# Available from

GPO Sales Program

Division of Technical Information and Document Control

U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

and

National Technical Information Service Springfield, Virginia 22161

# Title List of Documents Made Publicly Available

December 1 - 31, 1979

Division of Technical Information and Document Control Office of Administration U.S. Nuclear Regulatory Commission Washington, D.C. 20555





# CONTENTS

Preface
Arrangement of Items by Docket Number ix
Arrangement of Docket 50 Items by Facility Name xix
Docketed Items 1
Low Level Radwaste Disposal Sites - Docket 27
Domestic Licensing of Source Material - Docket 40
Domestic Licensing of Production and Utilization Facilities - Docket 50
Domestic Licensing of Special Nuclear Material - Docket 70 311
Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions - Docket 71
Nondocketed Items 327
10CFR — Commission Meeting Records
ACRS — Advisory Committee on Reactor Safeguards
COMMISSION – NRC Commissioners
CONTRACT – NRC Contracts and Modifications
FOIA - Freedom of Information Act Requests and Releases 332
GEN TECH IS — Generic Technical Issues
I&E — Inspection and Enforcement
MISC Public Document Room Miscellaneous
NUREG NUREG Reports and Related Correspondence
ORG — Correspondence with Other Organizations
PR - Proposed Rule
PRM - Petition for Rulemaking351
PROJ – Projects-Predocket Licensing
PT21 — Noncompliance Reports and Related Correspondence 352
QA999 — Quality Assurance Inspections
REGGD - Regulatory Guides
RES - Research and Technical Assistance Reports
REVIEW GRP — NRC Research Review Groups
STATE PROG — State Programs
TOPREP — Vendor Reports and Related Correspondence
WASTE MGT — Nuclear Waste Management
XPORTLIC — Export and Import Licenses
Personal Author Index
Corporate Source Index
Report Number Index
Cross Reference of Enclosures to Principal Documents
Cross Reference of Enclosures to Findapar Documents
Appendix A - Definitions of Docket 50 Categories
Appendix B - Definitions of Nondocketed Categories



#### **PREFACE**

The Title List of Documents Made Publicly Available is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, docketed does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information includes the information formerly issued through the Department of Energy's Technical Information Center under the title Power Reactor Docket Information (PRDI) and, in addition, information received or generated on other uses of radioactive materials. The last issue of PRDI, published in January 1979, was an annual cumulation of the information for 1978. The Title List series initiated by this document replaces PRDI, which will no longer be prepared. Plans for providing microfiche of the docketed material will be announced in a future issue of the Title List and in other mailings and announcements.

We are making the monthly issues produced in 1979 available free to all who subscribed to PRDI in Calendar Year 1978. We are doing this to encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

#### DOCKETED ITEMS

Beginning with Vol. 1, No. 4, the listings within dockets are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:


- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence

- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences, LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters

Appendix A sets forth those categories and describes the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.


The principal elements of the entries in the list are:

1 P. Operating license stage documents & correspondence



7904170015 Forwards info on TMI: JM Hendrie 790410 testimony, preliminary chronology of NRC actions, description of events & generic consideration of incident.

REHM, T.A. Office of the Executive Director for Operations.



- 1. NRC/PDR Document category (see Appendix A).
- 2. NRC Accession Number
- 3. Description of information contained in the document
- 4. Personal author. An asterisk in this position indicates that there is no personal author.
- 5. Corporate, agency or nonindividual source
- 6. Date of document described
- 7. Pages in document
- 8. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

#### NONDOCKETED ITEMS

Beginning with Vol. 1, No. 6, the nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories and their symbols are:

10CFR -- Commission Meeting Records

ACRS - Advisory Committee on Reactor Safeguards

COMMISSION — NRC Commissioners

CONTRACT - NRC Contracts and Modifications

FOIA - Freedom of Information Act Requests and Releases

GEN TECH IS — Generic Technical Issues

I&E - Inspection and Enforcement

MISC - Public Document Room Miscellaneous

NUREG - NUREG Reports and Related Correspondence

ORG - Correspondence with other organizations

PR - Proposed Rule

PRM - Petition for Rulemaking

PROJ - Projects-Predocket Licensing

PT21 - Noncompliance Reports and Related Correspondence

OA999 - Quality Assurance Inspections REGGD - Regulatory Guides RES - Research and Technical Assistance Reports REVIEW GRP - NRC Research Review Groups RM - Rulemakings SECY - Position Papers Before the Commission STATE PROG - State Programs TOPREP - Vendor Reports and Related Correspondence WASTE MGT - Nuclear Waste Management XPORTLIC - Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:

(1) NUREG - NUREG Reports and Related Correspondence 7901060007 NUREG/CR-0161 "Dynamic Analysis to Establish Normal Shock & Vibration Environs Experienced by Radioactive National Shipping Package." Quarterly Progress Report 780101-780331. Identifies parameters which affect normal shock & vibration environs.1 FIELDS, S.R., MECH, S.J. Hanford Engineering Development Laboratory. FIN A-2093. 78/11/30. 26pp. Available at NTIS. (10)

- 1. Nondocketed category
- 2. NRC Accession Number
- 3. NRC Report Number
- 4. Title and description of information contained in the document
- 5. Personal author(s). An asterisk in this position indicates that there is no personal author
- 6. Corporate, agency or other nonindividual source
- 7. Contract or financial (FIN) number (if any). If the document has a secondary report number it will appear following this entry.
- 8. Date of document described
- 9. Pages in document
- 10. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or Available at GPO."

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

#### NOTES:

The address for NTIS is:
 National Technical Information Service

Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the charge-card number when placing your order.

2. The address for GPO is:

Superintendent of Documents Government Printing Office Washington, D.C. 20402

To place orders for or to obtain price information about NRC publications at GPO, either write to GPO or call the Inquiry Desk at (202) 783-3238. Publications can be charged to VISA or Mastercharge credit cards; supply the chargecard number when placing your order.

3. The address for the PDR is:

1717 H Street, N.W. Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: 8¢ per page for standard size paper; 11¢ per page for oversized paper (drawings); 25¢ per microfiche for 24x diazo duplicates. A minimum charge of \$2.00 plus postage is charged for mail orders.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Potomac Research, Inc.

# ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name	Page
27-010	Beatty, NV, Nuclear Engineering Co.	1	40-8636	Wold Nuclear Co.	5
27-039	Sheffield, IL, Nuclear Engineering Co.	1	40-8663	Nuclear Dynamics, Inc.	6
27-047	Barnwell, SC, Chem-Nuclear Systems, Inc.	1	40-8674	Piateau Resources, Ltd.	6
27-048	Richland, WA, Nuclear Engineering Co.	2	40-8675	Energy Fuels Nuclear, Inc.	6
40-0229	Union Carbide Corp.	2	40-8677	NL Industries, Inc., Bearings Division	6
40-0299	Union Carbide Corp.	2	40-8681	Energy Fuels Nuclear, Inc.	6
40-0341	General Services Administration	2	40-8692	Cotter Corp.	6
40-1162	Western Nuclear, Inc.	2	40-8698	Plateau Resources, Ltd.	6
40-1341	Edgemont Uranium Mine, TVA, and	2	40-8721	Rocky Mountain Energy Co.	6
	Mines Development, Inc.		40-8722	Brush-Wellman, Inc.	7
40-1386	Raytheon Co.	3	40-8725	Gulf Mineral Resources Co.	7
40-2061	West Chicago Facility, Kerr-McGee Corp.	3	40-8727	Kerr-McGee Nuclear Corp.	7
40-2259	Pathfinder Mines Corp.	3	40-8728	Teton Exploration Drilling Co., Inc.	7
40-3453	Atlas Minerals	3	40-8745	Ogle Petroleum	7
40-4492	Federal American Partners	4	40-8748	Cyprus Mines Corp., Uranium Division	7
40-6940	Kawecki Berylco Industries, Inc.	4	40-8751	Cotter Corp.	8
40-7344	General Electric Co.	4	50-2	Univ. of Michigan Research Reactor	8
40-7869	Plateau Resources, Ltd.	4	50-3	Indian Point Station, Unit 1	8
40-8027	Kerr-McGee Corp.	4	50-5	Pennsylvania State Univ. Research	9
40-8102	Exxon Minerals Co. USA, Exxon Corp.	4		Reactor	10
40-8200	Cleveland-Cliffs Iron Co.	5	50-10	Dresden Nuclear Power Station, Unit 1	
40-8304	Wyoming Mineral Corp.	. 5	50-13	Babcock & Wilcox Co. Critical Facility	11
40-8348	In Situ Uranium Leaching Project	5	50-20	Massachusetts Institute of Technology	11
40-8380	Rocky Mountain Energy Co.	5		Research Reactor	4.0
40-8452	Bear Creek Uranium Co.	- 5	50-27	Washington State Univ. Research Reactor	12
40-8502	Irigaray Mine, Wyoming Mining Corp.	5	50-29	Yankee-Rowe Nuclear Power Station	12
40-8584	Union 76 Minerals Exploration Co.	5	50-54	Union Carbide Research Reactor	14
<b>40-8631</b>	Army, Dept. of, Armament Materiel Readiness Command	5	50-57	State Univ. of New York Research Reactor	14

Docket	Name	Page	Docket	Name	Page
50-59	Texas A&M Univ. Research Reactor	14	50-150	Ohio State Univ. Research Reactor	20
50-62	Univ. of Virginia Research Reactor	15	50-151	Univ. of Illinois Research Reactor	20
50-70	General Electric Co. Test Reactor	15	50-155	Big Rock Point Nuclear Plant	20
50-72	Univ. of Utah Research Reactor	15	50-156	Univ. of Wisconsin Research Reactor	23
50-73	General Electric Nuclear Test	15	50-157	Cornell Univ. Research Reactor	23
50-77	Reactor  Catholic Univ. of America Research	15	50-160	Georgia Institute of Technology Research Reactor	23
	Reactor	4.44	50-163	General Atomic Co.	23
50-83	Univ. of Florida Training Reactor	15	50-166	Univ. of Maryland Research Reactor	23
50-87	Westinghouse Critical Experiment	16	50-170	National Naval Medical Center	23
50-89 50-54	General Atomic Co.  Rockwell International Research	16 16	50-171	Peach Bottom Atomic Power Station, Unit 1	24
	Reactor		50-182	Purdue Univ. Research Reactor	24
50-97	Cornell Univ. Zero Power Reactor	16	50-184	National Bureau of Standards Reactor	24
50-98	Univ. of Delaware Research Reactor	16	50-186	Univ. of Missouri Research Reactor	24
50.99	Babcock & Wilcox Test Reactor	16	50-187	Space Radiation Research Reactor	24
50-106	Oregon State Univ.	16	50-188	Kansas State Univ. Research Reactor	24
50-111	North Carolina State Univ. Research Reactor	16	50-192	Univ. of Texas Research Reactor	24
50-112	Univ. of Oklahoma Research Reactor	16	50-193	Rhode Island & Providence Plantations AEC	24
50-113	Univ, of Arizona Research Reactor	17	50-199	Manhattan College Research Reactor	25
50-116	Iowa State Univ. Research Reactor	17	50-201	West Valley Reprocessing Plant	25
50-123	Univ. of Missouri Research Reactor	17		San Onofre Nuclear Station, Unit 1	25
50-124		17	50-206 50-208	Columbia Univ. Research Reactor	27
-0.400	Reactor	17	50-210	NASA Critical Facility	27
50-128		17	50-213	Haddam Neck Plant	27
50-129				Oyster Creek Nuclear Power Plant	29
50-131	Omaha Veterans Administration Hospital Research Reactor	17	50-219	•	32
50-133	Humboldt Bay Power Plant, Unit 3	17	50-220	Nine Mile Point Nuclear Station, Unit 1	32
50-134		19	50-223	Univ. of Lowell Research Reactor	33
	Research Reactor		50-224	Univ. of California Research Reactor	33
	Research Reactor	19	50-225	RPI Critical Experiment	34
	tor Facility	19 19	50-228	Aerotest Radiography & Research Reactor	34
	ritical	19	50-237	Dresden Nuclear Power Station, Unit 2	34
		20	50-243	Oregon State Univ. Research Reactor	36

Docket	Name	Page	Docket	Name	Page
50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	36	50-278	Peach Bottom Atomic Power Station, Unit 3	81
50-245	Milistone Nuclear Power Station, Unit 1	39	50-280	Surry Power Station, Unit 1	83
50-246	Advanced Critical Reactor Experiment	40	50-281	Surry Power Station, Unit 2	86
50-247	Indian Point Station, Unit 2	40	50-282	Prairie Island Nuclear Station, Unit 1	88
50-249	Dresden Nuclear Power Station, Unit 3	43	50-284	Idaho State Univ. Research Reactor	90
50-250	Turkey Point Plant, Unit 3	45	50-285	Fort Calhoun Station, Unit 1	90
50-251	Turkey Point Plant, Unit 4	47	50-286	Indian Point Station, Unit 3	92
50-252	Univ. of New Mexico Research Reactor	49	50-287	Oconee Nuclear Station, Unit 3	95
50-254	Quad-Cities Station, Unit 1	49	50-288	Reed College Research Reactor	98
50-255	Palisades Nuclear Plant	50	50-289	Three Mile Island Nuclear Station, Unit 1	98
50-256	Univ. of Montevideo Research Reactor, Uruguay	53	50-293	Pilgrim Nuclear Power Station, Unit 1	103
50-259	Browns Ferry Nuclear Power Station,	53	50-294	Michigan State Univ. Research Reactor	106
3 U-23 J	Unit 1		50-295	Zion Nuclear Power Station, Unit 1	106
50-260	Browns Ferry Nuclear Power Station, Unit 2	55	50-296	Browns Ferry Nuclear Power Station, Unit 3	108
50-261	H. B. Robinson Plant, Unit 2	56	50-297	North Carolina State Univ. PULSTAR	110
50-262	Brigham Young Univ. Research Reactor	58		Reactor	
50-263	Monticello Nuclear Generating Plant	58	50-298	Cooper Nuclear Station	110
50-264	Dow Chemical Co.	60	50-301	Point Beach Nuclear Plant, Unit 2	111
50-265	Quad-Cities Station, Unit 2	60	50-302	Crystal River Nuclear Plant, Unit 3	112
50-266	Point Beach Nuclear Plant, Unit 1	62	50-304	Zion Nuclear Power Station, Unit 2	116
50-267	Fort St. Vrain Nuclear Generating	64	50-305	Kewaunce Nuclear Power Plant	118
	Station		50-306	Prairie Island Nuclear Station, Unit 2	120
50-269	Oconee Nuclear Station, Unit 1	66	50-309	Maine Yankee Atomic Power Plant	121
50-270	Oconee Nuclear Station, Unit 2	68	50-311	Salem Nuclear Generating Station, Unit 2	122
50-271 50-272	Vermont Yankee Nuclear Power Station Salem Nuclear Generating Station,	71 72	50-31?	Rancho Seco Nuclear Generating Station	125
	Unit 1		£0.010	Arkansas Nuclear One, Unit 1	129
50-274	U.S. Geological Survey Research Reactor	76	50-313	Donald C. Cook Nuclear Power Plant,	132
50-275	Diablo Canyon Nuclear Power Plant, Unit 1	76	50-315	Unit 1	134
50-276		79	50-316	Donald C. Cook Nuclear Power Plant, Unit 2	
50-277	Peach Bottom Atomic Power Station, Unit 2	79	50-317	Calvert Cliffs Nuclear Power Plant, Unit 1	130
			•		
		ix			
4					

Doct	ket	Name	Page	Docket	Name	Page
	50-318	Calvert Cliffs Nuclear Power Plant, Unit 2	138	50-358	William H. Zimmer Nuclear Station, Unit 1	197
	50-320	Three Mile Island Nuclear Station, Unit 2	140	50-360	Battelle Memorial Institute Critical Facility	198
	50-321	Edwin I. Hatch Nuclear Plant, Unit 1	147	50-361	San Onofre Nuclear Station, Unit 2	198
	50-322	Shoreham Nuclear Power Station	149	50-362	San Onofre Nuclear Station, Unit 3	200
	50-323	Diablo Canyon Nuclear Power Plant,	150	50-363	Forked River Nuclear Station, Unit 1	201
		Unit 2		50-364	Joseph M. Farley Nuclear Plant, Unit 2	201
	50-324	Brunswick Steam Electric Plant, Unit 2	153	50-366	Edwin I. Hatch Nuclear Plant, Unit 2	203
	50-325	Brunswick Steam Electric Plant, Unit 1	155	50-367	Bailly Generating Station	205
	50-326	Univ. of California at Irvine Research Reactor	157	50-368	Arkansas Nuclear One, Unit 2	206
	50-327	Sequoyah Nuclear Plant, Unit 1	157	50-369	William B. McGuire Nuclear Station, Unit 1	208
	50-328	Sequoyah Nuclear Plant, Unit 2	160	50-370	William B. McGuire Nuclear Station,	209
	50-329	Midland Plant, Unit 1	162		Unit 2	
	50-330	Midland Plant, Unit 2	164	50-3 <b>7</b> 3	LaSalle County Station, Unit 1	210
	50-331	Duane Arnold Energy Center	167	50-374	LaSalle County Station, Unit 2	212
	50-333	James A. Fitzpatrick Nuclear Power	168	50-375	Nuclear Examination Reactor	213
		Plant	1711	50-376	North Coast Nuclear Plant	213
	50-334	Beaver Valley Power Station, Unit 1	171	50-382	Waterford Generating Station, Unit 3	213
	50-335	St. Lucie Plant, Unit 1	173	50-387	Susquehanna Steam Electric Station,	215
	50-336	Millstone Nuclear Power Station, Unit 2	175		Unit 1	217
	50-338	North Anna Power Station, Unit 1	177	50-388	Susquehanna Steam Electric Station, Unit 2	21 (
	50-339	North Anna Power Station, Unit 2	180	50-389	St. Lucie Plant, Unit 2	219
	50-341	Enrico Fermi Atomic Power Plant,	184	50-390	Watts Bar Nuclear Plant, Unit 1	220
		Unit 2	40.5	50-391	Watts Bar Nuclear Plant, Unit 2	222
	50-344	Trojan Nuclear Plant	185	50-394	California State Polytechnic College	223
	50-346	Dayis-Besse Nuclear Power Station, Unit 1	188		Research Reactor	223
		iclear Plant, Unit 1	191	50-395	Virgil C. Summer Nuclear Station, Unit 1	243
		n, Unit 1	193	50-396	Univ. of Virginia Cavalier Reactor	225
		nit 2	194	50-397	WPPSS Nuclear Project, Unit 2	225
		r 3	195	50-399	Mendocino, Unit 2	226
			196	50-400	Shearon Harris Nuclear Power Plant, Unit 1	226
			197	50-401	Shearon Harris Nuclear Power Plant, Unit 2	227
			197		Oitte 2	.*

Dock	et	Name	Page	Docket	Name	Page
	50-402	Shearon Harris Nuclear Power Plant,	229	50-449	Douglas Point Nuclear Station, Unit 2	257
		Unit 3	220	50-452	Greenwood Energy Center, Unit 2	257
	50-403	Shearon Harris Nuclear Power Plant, Unit 4	230	50-453	Greenwood Energy Center, Unit 3	257
	50-404	North Anna Power Station, Unit 3	231	50-454	Byron Station, Unit 1	257
	50-405	North Anna Power Station, Unit 4	232	50-455	Byron Station, Unit 2	258
	50-406	Tuskegee Institute Research Reactor	233	50-456	Braidwood Station, Unit 1	259
	50-407	Univ. of Utah Research Reactor	233	50-457	Braidwood Station, Unit 2	260
	50-409	La Crosse Boiling Water Reactor	233	50-458	River Bend Station, Unit 1	261
	50-410	Nine Mile Point Nuclear Station,	235	50-459	River Bend Station, Unit 2	262
	-	Unit 2		50-460	WPPSS Nuclear Project, Unit 1	262
	50-412	Beaver Valley Power Station, Unit 2	235	50-461	Clinton Power Station, Unit 1	263
	50-413	Catawba Nuclear Station, Unit 1	236	50-462	Clinton Power Station, Unit 2	263
	50-414	Catawba Nuclear Station, Unit 2	237	50-463	Fulton Generating Station, Unit 1	264
	50-416	Grand Gulf Nuclear Station, Unit 1	238	50-466	Allens Creek Nuclear Station, Unit 1	264
	50-417	Grand Gulf Nuclear Station, Unit 2	239	50-467	Allens Creek Nuclear Station, Unit 2	266
	50-423	Milistone Nuclear Power Station, Unit 3	241	50-471	Pilgrim Nuclear Power Station, Unit 2	266
	50-424	Alvin W. Vogtle Nuclear Plant, Unit 1	241	STN-50-477	Atlantic Generating Station, Unit 1	267
	50-425	Alvin W. Vogtle Nuclear Plant, Unit 2	242	STN-50-478	Atlantic Generating Station, Unit 2	267
	50-426	Alvin W. Vogtle Nuclear Plant, Unit 3	243	STN-50-482	Wolf Creek Generating Station	267
	50-427	Alvin W. Vogtle Nuclear Plant, Unit 4	243	STN-50-483	Calloway Plant, Unit 1	269
	50-433	Univ. of California at Santa Barbara	243	STN-50-484	Tyrone Energy Park, Unit 1	270
		Research Reactor	242	STN-50-485	Sterling Power Project Nuclear, Unit 1	270
ST	N-50-437	Floating Nuclear Plant	243	OTEN CA AGE	Calloway Plant, Unit 2	271
	50-438	Bellefonte Nuclear Plant, Unit 1	244	STN-50-486		272
	50-439	Bellefonte Nuclear Plant, Unit 2	245	STN-50-488	Perkins Nuclear Station, Unit 1	272
	50-440	Perry Nuclear Power Plant, Unit 1	246	STN-50-489	Perkins Nuclear Station, Unit 2	
	50-441	Perry Nuclear Power Plant, Unit 2	247	STN-50-490	Perkins Nuclear Station, Unit 3	273
	50-443	Seabrook Nuclear Station, Unit 1	248	STN-50-491	Cherokee Nuclear Station, Unit 1	274
	50-444	Seabrook Nuclear Station, Unit 2	249	STN-50-492	Cherokee Nuclear Station, Unit 2	275
	50-445	Comanche Peak Steam Electric Station, Unit 1	250	STN-50-493	Cherokee Nuclear Station, Unit 3	275
	50-446	Comanche Peak Steam Electric	254	50 <del>-4</del> 96	Montague Nuclear Power Station, Unit 1	276
•	3V-440	Station, Unit 2		50-497	Montague Nuclear Power Station,	276
S	TN-50-447	GESSAR-238	257		Unit 2	
	50-448	Douglas Point Nuclear Station, Unit 1	257	STN-50-498	South Texas Project, Unit 1	276

Docket	Name	Page	Docket	Name	Page
STN-50-499	South Texas Project, Unit 2	280	STN-50-553	Phipps Bend Nuclear Plant, Unit 1	302
50-500	Davis-Besse Nuclear Power Station, Unit 2	284	STN-50-554	Phipps Bend Nuclear Plant, Unit 2	303
50-501	Davis-Besse Nuclear Power Station,	284	STN-50-556	Black Fox Station, Unit 1	304
36-041	Unit 3	AU'T	STN-50-557	Black Fox Station, Unit 2	304
STN-50-502	Haven Nuclear Plant, Unit 1	284	STN-50-566	Yellow Creek Nuclear Plant, Unit 1	305
STN-50-503	Haven Nuclear Plant, Unit 2	284	STN-50-567	Yellow Creek Nuclear Plant, Unit 2	306
STN-50-504	Koshkonong Nuclear Plant, Unit 1	284	STN-50-568	NEP Nuclear, Unit 1	307
STN-50-505	Koshkonong Nuclear Plant, Unit 2	285	STN-50-569	NEP Nuclear, Unit 2	307
STN-50-506	Koshkonong Nuclear Plant, Unit 3	285	STN-50-574	Bagnac Nuclear Power Project, Philippines	307
STN-50-507	Koshkonong Nuclear Plant, Unit 4	285	STN-50-580	Erie Nuclear Plant, Unit 1	308
STN-50-508	WPPSS Nuclear Project, Unit 3	285	STN-50-581	Erie Nuclear Plant, Unit 2	308
STN-50-509	WPPSS Nuclear Project, Unit 5	286	STN-50-584	GIBBSAR, Gibbs & Hill	309
50-513	WPPSS Nuclear Project, Unit 4	286	STN-50-584 STN-50-592	Palo Verde Nuclear Station, Unit 4	309
50-514	Pebble Springs Nuclear Plant, Unit 1	287	STN-50-592 STN-50-593	Palo Verde Nuclear Station, Unit 5	309
50-515	Pebble Springs Nuclear Plant, Unit 2	287	STN-50-596	New Haven, Unit 1	309
STN-50-516	Jamesport Nuclear Station, Unit 1	288	STN-50-596 STN-50-597	New Haven, Unit 2	309
STN-50-517	Jamesport Nuclear Station, Unit 2	288	50-598	Northwestern Univ.	309
STN-50-518	Hartsville Nuclear Plant, Unit 1	289	50-599	Carroll Facility I	310
STN-50-519	Hartsville Nuclear Plant, Unit 2	290	50-600	Carroli Facility II	310
STN-50-520	Hartsville Nuclear Plant, Unit 3	291	70-0008	Battelle Columbus Laboratories	31
STN-50-521	Hartsville Nuclear Plant, Unit 4	291		Rockwell International Corp.	31
STN-50-222	Skagit Nuclear Power Project, Unit 1	292	70-0025	Babcock & Wilcox Co.	31
STN-50-523	Skagit Nuclear Power Project, Unit 2	294	70-0027		31
50-525	Barton, Unit 2	295	70-0033	Texas Instruments, Inc.	
STN-50-528	Palo Verde Nuclear Station, Unit 1	295	70-0036	Combustion Engineering, Inc.	31
STN-50-529	Palo Verde Nuclear Station, Unit 2	296	70-0135	Babcock & Wilcox Co.	31
STN-50-530	Palo Verde Nuclear Station, Unit 3	298	70-0143	Nuclear Fuel Services, Inc.	31
50-537	Clinch River Breeder Reactor	299	70-0250	The Boeing Co.	31
50-538	Memphis State Univ. Research Reactor	299	70-0364	Parks Township Site, Babcock & Wilcox Co.	31
STN-50-545	RESAR-3S	299	70-0371	United Nuclear Corp.	31
STN-50-546	Marble Hill Nuclear Station, Unit 1	299	70-0687	Union Carbide Corp.	31
STN-50-547	Marble Hill Nuclear Station, Unit 2	300	70-0693	Nuclear Research Corp.	31
50-549	Greene County Nuclear Power Plant	302	70-0734	General Atomic Co.	3
•	•	•			
		xiv			

Doc	ket	Name	Page	Docket	Name	Page
	70-0754	Vallecitos Nuclear Center, General	314	71-0114	Colby-Thielmeier Testing Co.	319
		Electric Co.	214	71-0121	Neutron Products, Inc.	319
	70-0820	United Nuclear Corp.	314	71-0159	Lockheed Missile & Space	319
	70-0824	Babcock & Wilcox Co.	315	71-0160	Omaha Testing Laboratories, Inc.	319
	70-0903	Gulf United Nuclear Fuels Corp.	315	71-0193	Navy, Dept. of	319
	70-0925	Cimarron Facility, Kerr-McGee Corp.	316	71-0199	Navy, Dept. of	319
	70-1100	Combustion Engineering, Inc.	316	71-0206	Pryor Foundry, Inc.	319
	70-1113	General Electric Co.	316	71-0225	Navy, Dept. of	320
	70-1143	Westinghouse Electric Corp.	316	71-0239	Navy, Dept. of	320
	70-1151	Westinghouse Electric Corp.	316	71-0248	Monsanto Research Corp.	320
	70-1193	Cimarron Facility, Kerr-McGee Corp.	317	71-0250	Transnuclear, Inc.	320
	70-1201	UF-6 Conversion Facility, Babcock & Wilcox Co.	317	71-0258	Nuclear Engineering Co., Inc.	320
	50 1057	Mixed Oxide Fabrication Plant,	317	71-0345	Carolina Power & Light Co.	320
	70-1257	Exxon Nuclear Co., Inc.		71-0347	Stone & Webster Engineering Corp.	320
	70-1308	Morris Operations, General Electric Co.	317	71-0349	Caterpillar Tractor Co.	320
	70-1362	Hahnemann Medical College & Hospital, Philadelphia, PA	317	71-0352	Niles Steel Tank Co.	320
		Fuel Recovery & Storage Station, Allied	318	71-0355	Jersey Central Power & Light Co.	320
	70-1729	General Nuclear Services		71-0356	Navy, Dept. of, USS Picdmont	320
	70-2205	St. Luke's Hospital, Milwaukee, WI	318	71-0357	Navy, Dept. of, USS Vulcan	320
	70-2623	McGuire Spent Fuel Pool, Duke Power Co.	318	71-0358	Navy, Dept. of, USS Sierra	320
	70-2756	Transnuclear, Inc.	318	71-0359	Pick Instrument Products Co., Inc.	321
	70-2750	Transnuclear, Inc.	318	71-0360	Navy, Dept. of, USS Yosemite	321
	70-2776	Transnuclear, Inc.	318	71-0362	Wisconsin Public Service Corp.	321
		Exxon Nuclear Co., Inc.	318	71-0363	Briggs Engineering & Testing Co., Inc.	321
	71-0003 71-0006	United Nuclear Corp.	318	71-0364	Naval Nuclear Power Unit, Port Hueneme	, 321
		Hittman Nuclear & Development Corp.	319		CA	221
	71-0024 71-0026	Eastern Testing & Inspection	319	71-4949	Model: UNC-1484, Combustion Engineering, Inc.	321
	71-0020	Babcock & Wilcox Co.	319	71-5026	Model: BC-48-220, Atcor, Inc.	321
	71-0027	Morrison-Knudsen Co., Inc.	319	71-5059	Model: Urany Nit-Tnk, Nuclear Fuel	321
	71-0073	Morrison-Knudsen Co., Inc.	319	m4 5006	Services, Inc.  Model: UNC-2600, General Atomic Co.	321
	71-0079	Babcock & Wilcox Co.	319	71-5086	Model: CC, Westinghouse Electric Corp.	
	71-0088	Babcock & Wilcox Co.	319	71-5395	Model: RCC-1, -2, -3, Westinghouse	321
	71-0096	Pan American World Airways	319	71-5450	Electric Corp.	
	71-0090	I dil Allossoni il dano			·	
				xy :		
			÷			
		•				

D	ocket	Name	Page	Docket	Name	Page
	71-5467	Model: Mark VR, VE & Mark 15, Energy, Dept. of	321	71-9001	Model: IF-300, General Electric Co.	324
	71-5641	Model: UNC-2500	321	71-9006	Model: 500 SU, Argonne National Laboratory	324
	71-5768	Model: BB-250-2, Combustion Engineering Co., Inc.	321	71-9007	Model: 520, Argonne National Laboratory	324
	71-5796	Model: 181361, Picker Corp.	321	71-9009	Model: FL 10-1, General Electric Co.	324
	71-5805	Model: Atcor VNDB Cask, Atcor, Inc.	322	71-9010	Model: NLI-1/2, NL Industries, Inc.	324
	71-5939	Model: GE-1500, General Electric Co.	322	71-9011	Model: E-MEH-00-00004, Transporta-	324
-	71-5957	Model: BMI-1, Energy, Dept. of	322	71 0040	tion, Dept, of	
	71-5980	Model: GE-600, General Electric Co.	322	71-9019	Model: BU-7, General Electric Co.	324
	71-6058	Model: B3-1, Nuclear Engineering Co.	322	71-9027	Model: 741, Technical Operations, Inc.	324
	71-6078	Model: 927 Al & C1, Combustion	322	71-9028	Model: 684, Technical Operations, Inc.	324
	71 (144	Engineering, Inc.		71-9032	Model: 650, Technical Operations, Inc.	324
	71-6144	Model: 6144, Nuclear Engineering Co.	322	71-9033	Model: 660 & 660E, Technical Operations, Inc.	324
	71-6206	Model: B, Babcock & Wilcox Co.	322	71-9035	Model: 680, Technical Operations, Inc.	324
	71-6244	Model: 6244, Chem-Nuclear Systems, Inc.	322	71-9039	Model: 715, Technical Operations, Inc.	325
	71-6275	Model: LL-28-4, Chem-Nuclear Systems, Inc.	322	71-9044	Model: GE-1600, General Electric Co.	325
	71-6280	Model: A-0109	222	71-9070	Model: N-55, Energy, Dept. of	325
	71-6300	Model: UNC-1352, Combustion Engineering, Inc.	323 323	71-9079	Model: HN-100 Series 2, Hittman Nuclear & Development Corp.	325
	71-6345	Model: ANL-402-SPM,-403-SPM, E.I. du Pont de Nemours & Co., Inc.	323	71-9081	Model: CNSI-1600, Chem-Nuclear Systems, Inc.	325
	71-6357	Model: NNFD-10, Babcock & Wilcox Co.	323	71-9085	Model: Sentinel 85	325
	71-6375	Model: PB-1, Chem-Nuclear Systems,	323	71-9086	Model: HN-100 Series 1, Hittman Nuclear & Development Corp.	325
	71-6386	Model: 235R001, Energy, Dept. of	323	71-9089	Model: NH-100 S, Hittman Nuclear & Development Corp.	325
	71-6400	Model: Super Tiger, Westinghouse Electric Corp.	323	71-9094	Model: CNSI-14-195-H, Chem-Nuclear Systems, Inc.	325
	71-6568	Model: LL-60-150, TVA	323	71-9096	Model: CNSI-21-300, Chem-Nuclear	325
	71-6581	Model: 51032-1 & -1A, Exxon	323	•	Systems, Inc.	
		em-Nuclear	323	71-9105	Model: Rad-Waste CR.I, Chem-Nuclear Systems, Inc.	325
		CHILIANGIGHT	323	71-9107	Model: 771, Technical Operations, Inc.	326
			323	71-9108	Model: AL-33-90, Atcor, Inc.	326
			323	71-9111	Model: CN6-80A, Chem-Nuclear Systems, Inc.	326
			324	71-9113	Model: 7-100, Chem-Nuclear Systems, Inc.	326

Docket	Name	Page	Docket	Name	Page
71-9119	Model: BAPL 5910 BRDCG, Energy, Dept. of	326	71-9851	Model: Lithium Hydroxide Fire/ Impact Shield, Energy, Dept. of	326
71-9132	Model: T-3, Nuclear Packaging, Inc.	326	71-9853	Model: ORNL-BNL-NBS Unirradiated	326
71-9137	Model: 820	326	71-9932	Fuel Container, Energy, Dept. of Model: UC-609, Energy, Dept. of	326



# ALPHABETIC ARRANGEMENT OF DOCKET 50 ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Advanced Critical Reactor Experiment	50-246	40	Browns Ferry Nuclear Power Station, Unit 2	50-260	55
Aerotest Radiography & Research Reactor	50-228	34	Browns Ferry Nuclear Power Station, Unit 3	50-296	108
Allens Creek Nuclear Station, Unit 1	50-466	264	Brunswick Steam Electric Plant, Unit 1	50-325	155
Allens Creek Nuclear Station, Unit 2	50-467	266	Brunswick Steam Electric Plant, Unit 2	50-324	153
Arkansas Nuclear One, Unit 1	50-313	129	Byron Station, Unit 1	50-454	257
Arkansas Nuclear One, Unit 2	50-368	206	Byron Station, Unit 2	50-455	258
Duane Arnold Energy Center	50-331	167	California State Polytechnic College	50-394	223
Atlantic Generating Station, Unit 1	STN-50-477	267	Research Reactor		
Atlantic Generating Station, Unit 2	STN-50-478	267	Calloway Plant, Unit 1	STN-50-483	269
Babcock & Wilcox Co. Critical Facility	50-13	11	Calloway Plant, Unit 2	STN-50-486	271
Babcock & Wilcox Co. Test Reactor	50-99	16	Calvert Cliffs Nuclear Power Plant, Unit 1	50-317	136
Bagnac Nuclear Power Project, Philippines	STN-50-574	307	Calvert Cliffs Nuclear Power Plant,	50-318	138
Bailly Generating Station	50-367	205	Unit 2		
Barton, Unit 2	50-525	295	Carroll Facility I	50-599	310
Battelle Memorial Institute Critical	50-360	198	Carroll Facility II	50-600	310
Facility	50 224	171	Catawba Nuclear Station, Unit 1	50-413	236
Beaver Valley Power Station, Unit 1	50-334	171	Catawba Nuclear Station, Unit 2	50-414	237
Beaver Valley Power Station, Unit 2	50-412	235	Catholic Univ. of America Research	50-77	15
Bellefonte Nuclear Plant, Unit 1	50-438	244	Reactor	am. + 50 101	071
Bellefonte Nuclear Plant, Unit 2	50-439	245	Cherokee Nuclear Station, Unit 1	STN-50-491	274
Big Rock Point Nuclear Power Plant	50-155	20	Cherokee Nuclear Station, Unit 2	STN-50-492	275
Black Fox Station, Unit 1	STN-50-556	304	Cherokee Nuclear Station, Unit 3	STN-50-493	275
Black Fox Station, Unit 2	STN-50-557	304	Clinch River Breeder Reactor	50-537	299
Braidwood Station, Unit 1	50-456	259	Clinton Power Station, Unit 1	50-461	263
Braidwood Station, Unit 2	50-457	260	Clinton Power Station, Unit 2	50-462	263
Brigham Young Univ. Research	50-262	58	Columbia Univ. Research Reactor	50-208	27
Reactor  Browns Ferry Nuclear Power Station, Unit 1	50-259	53	Comanche Peak Steam Electric Station, Unit 1	50-445	250

Name	Docket	Page	Name	Docket	Pa
Comanche Peak Steam Electric Station, Unit 2	50-446	254	Fort St. Vrain Nuclear Generating Station	50-267	
Donald C. Cook Nuclear Power Plant, Unit 1	50-315	132	Fulton Generating Station, Unit 1	50-463	2
Donald C. Cook Nuclear Power Plant,	50-316	134	General Atomic Co.	50-89	
Unit 2	30 510	101	General Atomic Co.	50-163	
Cooper Nuclear Station	50-298	110	General Electric Test Reactor	50-70	
Cornell Univ. Research Reactor	50-157	23	General Electric Nuclear Test Reactor	50-73	
Cornell Univ. Zero Power Reactor	50-97	16	Georgia Institute of Technology Research Reactor	50-160	
Crystal River Nuclear Plant, Unit 3	50-302	112	Georgia Institute of Technology	50-276	
Davis-Besse Nuclear Power Station, Unit 1	50-346	188	Research Reactor		,
Davis-Besse Nuclear Power Station,	50-500	284	GESSAR-238	STN-50-447	1
Unit 2		40.4	GIBBSAR, Gibbs & Hill	STN-50-584	:
Davis-Besse Nuclear Power Station, Unit 3	50-501	284	Robert Emmet Ginna Nuclear Plant, Unit 1	50-244	
Diablo Canyon Nuclear Power Plant, Unit 1	50-275	76	Grand Gulf Nuclear Station, Unit 1	50-416	:
Diablo Canyon Nuclear Power Plant,	50-323	150	Grand Gulf Nuclear Station, Unit 2	50-417	;
Unit 2			Greene Country Nuclear Power Plant	50-549	:
Douglas Point Nuclear Station, Unit 1	50-448	257	Greenwood Energy Center, Unit 2	50-452	
Douglas Point Nuclear Station, Unit 2	50-449	257	Greenwood Energy Center, Unit 3	50-453	
Dow Chemical Co., Research Reactor	50-264	60	Haddam Neck Plant	50-213	
Dresden Nuclear Power Station, Unit 1	50-10	10	Shearon Harris Nuclear Power Plant, Unit 1	50-400	
Dresden Nuclear Power Station, Unit 2	50-237	34	Shearon Harris Nuclear Power Plant,	50-401	
Dresden Nuclear Power Station, Unit 3	50-249	43	Unit 2	50 101	
Erie Nuclear Plant, Unit 1	STN-50-580	308	Shearon Harris Nuclear Power Plant, Unit 3	50-402	:
Erie Nuclear Plant, Unit 2	STN-50-581	308	Shearon Harris Nuclear Power Plant,	50-403	
Joseph M. Farley Nuclear Plant, Unit 1	50-348	191	Unit 4	30-103	•
Joseph M. Farley Nuclear Plant,	50-364	201	Hartsville Nuclear Plant, Unit 1	STN-50-518	;
Unit 2	00-004	201	Hartsville Nuclear Plant, Unit 2	STN-50-519	
Enrico Fermi Atomic Power Plant, Unit 2	50-341	184	Hartsville Nuclear Plant, Unit 3	STN-50-520	. :
James A. Fitzpatrick Nuclear Power	50-333	168	Hartsville Nuclear Plant, Unit 4	STN-50-521	
Plant	00 000	100	Edwin I. Hatch Nuclear Plant, Unit 1	50-321	
Floating Nuclear Plant	STN-50-437	243	Edwin I. Hatch Nuclear Plant, Unit 2	50-366	
Forked River Nuclear Station, Unit 1	50-363	201	Haven Nuclear Plant, Unit 1	STN-50-502	- ;
Fort Calhoun Station, Unit 1	50-285	90	Haven Nuclear Plant, Unit 2	STN-50-503	
		<b>x</b> :			

Name	Docket	Page	Name	Docket	P
Hope Creek Nuclear Station, Unit 1	50-354	195	Midland Plant, Unit 1	50-329	
Iope Creek Nuclear Station, Unit 2	50-355	196	Midland Plant, Unit 2	50-330	
Humboldt Bay Power Plant, Unit 3	50-133	17	Millstone Nuclear Power Station, Unit 1	50-245	
daho State Univ. Research Reactor	50-284	90	Millstone Nuclear Power Station,	50-336	
ndian Point Station, Unit 1	50-3	8	Unit 2	50-250	
ndian Point Station, Unit 2	50-247	40	Millstone Nuclear Power Station, Unit 3	50-423	
ndian Point Station, Unit 3	50-286	92	Montague Nuclear Power Station, Unit 1	50-496	
owa State Univ. Research Reactor	50-116	17	Montague Nuclear Power Station, Unit 2	50-497	
lamesport Nuclear Station, Unit 1	STN-50-516	288	Monticello Nuclear Generating Plant	50-263	
Jamesport Nuclear Station, Unit 2	STN-50-517	288	NASA Critical Facility	50-210	
Kansas State Univ. Research Reactor	50-188	24	National Bureau of Standards Reactor	50-184	
Kewaunee Nuclear Power Plant	50-305	118	National Naval Medical Center	50-170	
Koshkonong Nuclear Plant, Unit 1	STN-50-504	284	NEP Nuclear, Unit 1	STN-50-568	
Koshkonong Nuclear Plant, Unit 2	STN-50-505	285	NEP Nuclear, Unit 2	STN-50-569	
Koshkonong Nuclear Plant, Unit 3	STN-50-506	285	New Haven, Unit 1	STN-50-596	
Koshkonong Nuclear Plant, Unit 4	STN-50-507	285	New Haven, Unit 2	STN-50-597	
La Crosse Boiling Water Reactor	50-409	233	Nine Mile Point Nuclear Station,	50-220	
LaSalle County Station, Unit 1	50-373	210	Unit 1		
LaSalle County Station, Unit 2	50-374	212	Nine Mile Point Nuclear Station, Unit 2	50-410	
Limerick Generating Station, Unit 1	50-352	193	North Anna Power Station, Unit 1	50-338	
Limerick Generating Station, Unit 2	50-353	194		50-339	
Maine Yankee Atomic Power Plant	50-309	121	North Anna Power Station, Unit 2	50-404	
Manhattan College Research Reactor	50-199	25	North Anna Power Station, Unit 3		
Marble Hill Nuclear Station, Unit 1	STN-50-546	299	North Anna Power Station, Unit 4	50-405	
Marble Hill Nuclear Station, Unit 2	STN-50-547	300	North Carolina State Univ. PULSTAR Reactor	50-297	
Massachusetts Institute of Technology Research Reactor	50-20	11	North Carolina State Univ. Research Reactor	50-111	
William B. McGulre Nuclear Station,	50-369	208	North Coast Nuclear Plant	50-376	
Unit 1	50-370	209	Northwestern Univ.	50-598	
William B. McGuire Nuclear Station, Unit 2			Nuclear Examination Reactor	50-375	
Memphis State Univ. Research Reactor	50-538	299	Oconee Nuclear Station, Unit 1	50-269	
Mendocino, Unit 2	50-399	226	Oconee Nuclear Station, Unit 2	50-270	
Michigan State Univ. Research Reactor	50-294	106	Oconee Nuclear Station, Unit 3	50-287	
			Ohio State Univ. Research Reactor	50-150	

Name	Docket	Page	Name	Docket	Page	
Omaha Veterans Administration	50-131	17	Quad-Cities Station, Unit 2	50-265	60	
Hospital Research Reactor	r0.107	16	Rancho Seco Nuclear Generating	50-312	125	
Oregon State Univ.	50-106	16	Station  Reed College Research Reactor	50-288	98	
Oregon State Univ. Research Reactor	50-243	36 29	RESAR-3S	STN-50-545	299	
Oyster Creek Nuclear Power Plant	50-219		Rhode Island & Providence	50-193	24	
Palisades Nuclear Plant	50-255	50 295	Plantations AEC	30 133		
Palo Verde Nuclear Station, Unit 1	STN-50-528	293	River Bend Station, Unit 1	50-458	261	
Palo Verde Nuclear Station, Unit 2	STN-50-529	298	River Bend Station, Unit 2	50-459	262	
Palo Verde Nuclear Station, Unit 3	STN-50-530	309	H.B. Robinson Plant, Unit 2	50-261	56	
Palo Verde Nuclear Station, Unit 4	STN-50-592	309	Rockwell International Corp. Critical Facility	50-147	19	
Palo Verde Nuclear Station, Unit 5	STN-50-593 50-171	24	Rockwell International Research Reactor	50-94	16	
Peach Bottom Atomic Power Station, Unit 1	30-171	24	RPI Critical Experiment	50-225	34	
Peach Bottom Atomic Power Station,	50-277	79	Salem Nuclear Generating Station,	50-272	72	
Unit 2	50 27P	0.1	Unit 1	00-272		
Peach Bottom Atomic Power Station, Unit 3	50-278	81	Salem Nuclear Generating Station, Unit 2	50-311	122	
Pebble Springs Nuclear Plant, Unit 1	50-514	287	San Onofre Nuclear Station, Unit 1	50-206	25	
Pebble Springs Nuclear Plant, Unit 2	50-515	287	San Onofre Nuclear Station, Unit 2	50-361	198	
Pennsylvania State Univ. Research Reactor	50-5	9	San Onofre Nuclear Station, Unit 3	50-362	200	
Perkins Nuclear Station, Unit 1	STN-50-488	272	Saxton Nuclear Experimental Facility	50-146	19	
Perkins Nuclear Station, Unit 2	STN-50-489	272	Scabrook Nuclear Station, Unit 1	50-443	248	
Perkins Nuclear Station, Unit 3	STN-50-490	273	Scabrook Nuclear Station, Unit 2	50-444	249	
Perry Nuclear Power Plant, Unit 1	50-440	246	Sequoyah Nuclear Plant, Unit 1	50-327	157	
Perry Nuclear Power Plant, Unit 2	50-441	247	Sequoyah Nuclear Plant, Unit 2	50-328	160	
Phipps Bend Nuclear Plant, Unit 1	STN-50-553	302	Shoreham Nuclear Power Station	50-322	149	
Phipps Bend Nuclear Plant, Unit 2	STN-50-554	303	Skagit Nuclear Power Project, Unit 1	STN-50-522	292	
Pilgrim Nuclear Power Station, Unit 1	50-293	103	Skagit Nuclear Power Project, Unit 2	STN-50-523	294	
Pilgrim Nuclear Power Station, Unit 2	50-471	266	South Texas Project, Unit 1	STN-50-498	276	
Point Beach Nuclear Plant, Unit 1	50-266	62	South Texas Project, Unit 2	STN-50-499	280	
Point Beach Nuclear Plant, Unit 2	50-301	111	Space Radiation Research Reactor	50-187	24	
Prairie Island Nuclear Station, Unit 1	50-282	88	State Univ. of New York Research	50-57	14	
Prairle Island Nuclear Station, Unit 2	50-306	120	Reactor			
Purdue Univ. Research Reactor	50-182	24	Sterling Power Project, Nuclear, Unit 1	STN-50-485	270	
Quad-Cities Station, Unit 1	50-254	49	St. Lucie Plant, Unit 1	50-335	173	
			$(A_{ij}, A_{ij}) = (A_{ij}, A_{ij}, A_{ij})$			
xxii						

Name	Docket	Page	Name	Docket	Page
St. Lucie Plant, Unit 2	50-389	219	Univ. of Michigan Research Reactor	50-2	8
Virgil C. Summer Nuclear Station,	50-395	223	Univ. of Missouri Research Reactor	50-123	17
Unit 1	F0 000	0.0	Univ. of Missouri Research Reactor	50-186	24
Surry Power Station, Unit 1	50-280	83	Univ. of Montevideo Research Reactor,	50-256	53
Surry Power Station, Unit 2	50-281	86	Uruguay	50.053	40
Susquehanna Steam Electric Station, Unit 1	50-387	215	Univ. of New Mexico Research Reactor	50-252	49
Susquehanna Steam Electric Station, Unit 2	50-388	217	Univ. of Oklahoma Research Reactor  Univ. of Texas Research Reactor	50-112 50-192	16 24
Texas A&M Univ. Research Reactor	50-59	14	Univ. of Utah Research Reactor	50-72	15
Texas A&M Univ. Research Reactor	50-128	17	Univ. of Utah Research Reactor	50-407	233
Three Mile Island Nuclear Station,	50-289	98	Univ. of Virginia Cavalier Reactor	50-396	225
Unit 1			Univ. of Virginia Research Reactor	50-62	15
Three Mile Island Nuclear Station, Unit 2	50-320	140	Univ. of Washington Research Reactor	50-139	19
Trojan Nuclear Plant	50-344	185	Univ. of Wisconsin Research Reactor	50-156	23
Turkey Point Plant, Unit 3	50-250	45	U.S. Geological Survey Research	50-274	76
Turkey Point Plant, Unit 4	50-251	47	Reactor	50-271	71
Tuskegce Institute Research Reactor	50-406	233	Vermont Yankee Nuclear Power Station	30-271	,,
Tyrone Energy Park, Unit 1	STN-50-484	270	Virginia Polytech Institute Training Reactor	50-124	17
UCLA Training Reactor	50-142	19	Alvin W. Vogtle Nuclear Plant, Unit 1	50-424	241
Univ. of California at Santa Barbara Research Reactor	50-433	243	Alvin W. Vogile Nuclear Plant, Unit 2	50-425	242
Union Carbide Research Reactor	50-54	14	Alvin W. Vogtle Nuclear Plant, Unit 3	50-426	243
Univ. of Airzona Research Reactor	50-113	17	Alvin W. Vogtle Nuclear Plant, Unit 4	50-427	243
Univ. of California	50-357	197	Washington State Univ. Research Reactor	50-27	12
Univ. of California at Irvine Research Reactor	50-326	157	Waterford Generating Station, Unit 3	50-382	213
Univ. of California Research Reactor	50-224	33	Watts Bar Nuclear Plant, Unit 1	50-390	220
Univ. of Delaware Research Reactor	50-98	16	Watts Bar Nuclear Plant, Unit 2	50-391	222
Univ. of Florida Training Reactor	50-83	15	Westinghouse Critical Experiment	50-87	16
Univ. of Illinois Research Reactor	50-151	20	-	50-201	25
Univ. of Illinois LOPRA Research	50-356	197	West Valley Reprocessing Plant  West Virginia Univ. Research Reactor	50-201	17
Reactor	-0	••		STN-50-482	267
Univ. of Kansas Research Reactor	50-148	20	Wolf Creek Generating Station		
Univ. of Lowell Research Reactor	50-223	33	Worcester Polytech Institute Research Reactor	50-134	19
Univ. of Maryland Research Reactor	50-166	23			

Name	Docket	Page	Name	Docket	Page
WPPSS Nuclear Project, Unit 1	50-460	262	Yellow Creek Nuclear Plant, Unit 1	STN-50-566	305
WPPSS Nuclear Project, Unit 2	50-397	225	Yellow Creek Nuclear Plant, Unit 2	STN-50-567	306
WPPSS Nuclear Project, Unit 3	STN-50-508	285	William H. Zimmer Nuclear Station, Unit 1	50-358	197
WPPSS Nuclear Project, Unit 4	50-513	286	Zion Nuclear Power Station, Unit 1	50-295	106
WPPSS Nuclear Project, Unit 5	STN-50-509	286	Zion Nuclear Power Station, Unit 2	50-304	116
Yankee-Rowe Nuclear Power Station	50-29	12			·

## DOCKETED ITEMS

#### LOW LEVEL RADWASTE DISPOSAL SITES

#### DOCKET 27-010 BEATTY, NV

- 7912280640 Forwards nonproprietary Insp Rept 76-02 for Nuclear Engineering Co & certification of document in response to 791101 ltr. COMER.O.C. Executive Officer for Operations Support. 79/11/14.
- --7912280645 Requests nonproprietary Insp Rept 76-02 & statement cartifying rapt as public record.

  BRYAN, R. H., NELSON, B. M. Nevada, State of. 79/11/01. 2pp.
- --7912280453 Nongropristary IE Insp Rept 79-02 on 740309-0415.

  Noncompliance noted: radwasts removed from shipping containers, radwasts not disposed of within six months from date of receipt & disposal of uncontained radwasts.

  MENSLAHSKI, F. A., PHILLIP, G. A. Region 5, San Francisco, Office of the Director. BOOK, H. E. Region 5, San Francisco, Fuel Facility & Materials Bafety Branch. 74/05/11. 88pp.
- --7912280658 Order suspending license for handling of nuclear matl due to violations noted in 760309 insp. DAVIS.J.O. Office of Inspection & Enforcement, Office of the Director. 76/03/11. 3pp.
- --7912280667 Ltr confirming allegations that employees had removed equipment & maths from site. Requests cooperation by local residents in continuing attempt to locate addl tanks. ENGELKEN.R.H. Region 5. San Francisco, Office of the Director. 76/03/31. 14pp.
- ---7912280676 "Radiation Survey in Beatty, NV & Surrounding Area (Mar 1976)." HENDRICKS, D. W., FORT, C. W. Environmental Protection Agency, 76/04/30. 47pp.

#### DOCKET 27-039 SHEFFIELD, IL., NUCLEAR ENGINEERING CO.

- 7912180444 Forwards quarterly monitoring data of piezometers & wells in vicinity of Trench 18 & Trench 18 sumps.per 790423 agreement w/NRC.

  BAER, T. S. Nuclear Engineering Co., Inc., (subs. of Teledyne, Inc.).
  79/11/06.
- --7912180448 Trench 18 munitaring record for Jul-Sept 1979.

  \* Nuclear Engineering Co., Inc., (subs. of Teledyne, Inc.).
  79/09/30. 1p.
- 7712130290 Order denying Chicago Section of ANS 770628 mution to compel NRC to file draft EIS & to compel study of reasonable alternatives for suspension of OL.No authorities cited which require or permit such action by ASLB, QOODHOPE, A. C. Atomic Safety and Licensing Spard Panel. 79/12/03.
- 7912260290 Motion for reconsideration of ASLS 791203 order holding that Nuclear Engineering is still in possession of existing license. Certificate of Svc seci.
  CONNER, T.B. Nuclear Engineering Co., Inc., (subs. of Teledyne, Inc.). CONNER, T.B. Conner, Moore & Corber. 79/12/13. App.

#### DOCKET 27-047 BARNWELL, SC., CHEM-NUCLEAR SYSTEMS

7912140114 Forwards Amend 19 to License 46-13536-01.
DRAGONETTE, K. S. Low Level Waste Licensing Branch. 79/11/07. 1p.

- 7912200001 Forwards Waste Pectaging Insp Rept 79-038 on 791017.
  BUTHERLAND. J. T. Region 2. Atlanta. Fuel Facility & Materials
  Bafety Branch. 79/11/07. 2pp.
- ---7912200002 Waste Packaging Insp Rept 79-038 on 791017. Noncompliance noted:improper blocking & bracing.
  FOTTER.J.P. MODDRUFF.R.L. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 79/11/07. Spp.
- 7912200344 Forwards waste packaging Insp Rept 79-02A on 790925-26. No noncompliance noted.
  BUTHERLAND.J.T. Region 2. Atlanta. Fuel Facility & Materials Bafety Branch. 79/11/07. 2pp.
- --7912200395 Waste packaging Insp Rept 79-02A. No noncompliance noted.
  Major areas inspected shipping paper & DOT placarding
  requirements, radiation levels, removable contamination, DOT &
  NRC package features.
  BROWN.R.A. Region 2. Atlanta, Office of the Director.
  POTTER.J.P. Region 2. Atlanta, Fuel Facility & Materials Safety
  Branch. 79/11/06. 69p.
- 7912260072 Corrects Maste Packaging Insp Rept 79-01C. Paragraphs 5 & 10 discuss drum shipped by B&M. containing liquid matls. Drum in fact shipped by Dmaha Public Power Co.
  BUTHERLAND. J. T. Region 2. Atlanta. Fuel Facility & Materials
  Bafety Branch. 79/11/08. 2pp.
- -7912260078 Forwards Maste Packaging Insp Rept 79-01C on 790911-13. SUTHERLAND.J.T. Region 2. Atlanta. Fuel Facility & Materials Safety Branch. 79/10/30. 2pp.
- ---7912260085 Waste Packaging Insp Rept 79-010 on 790911-13. Noncompliance noted: falsification of shipping papers. WOODRUFF.R.L., POTTER, J.P. Region 2. Atlanta, Fusi Facility & Haterials Sefety Branch. 79/10/19. Spp.
- 7912260142 Forwards Waste Packaging Insp Rept 79-028 on 790925. SUTHERLAND, J.T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/11/09. 2pp.
- -7912260145 Waste Packaging Insp Rept 79-028 on 790925 Noncompliance noted: excessive levels of contamination in licensee shipment vehicle.

  BROWN.R.A. Region 2. Atlanta, Office of the Director.

  POTTER.J.P. Region 2. Atlanta, fuel Facility & Materials Safety Branck. 79/11/06. 4pp.
- 7912310230 Forwards Waste Packaging Insp Rept 79-048 on 791031.
  SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials
  Safety Branch: 79/11/19. 2pp.
- -- 7912310238 Waste Pectaging Insp Rept 79-048 on 791031 Noncompliance noted: improper placarding of vehicles. POTTER.J.P. BROMM.R.A. Region 2. Atlanta, Fuel Facility & Materials Bafety Branch. 79/11/14. 4pp.
- 7912170381 Natifies of completed review of DO Eisenhut 791108 memb to HR Dentan re ltrs to licensees concerning solid radwests. Authors of ltr did not sufficiently consider technical & political problems associated w/approach. COLLINS.J.T. THI-2 Operations/Support. 79/11/26. 4pp.
- --- 7912170384 Ferwards itr to licensees on solid radwasts. In order to continue availability of waste burial facilities, action items in itr must be implemented by licensees.

  EIBENGUT.D. G. Division of Operating Reactors. 79/11/08. 18pp.

- --7912170389 Summary of 791017-19 menting w/State of SC policy & technical officials re low level raduaste. Itinerary & SC Dept of Health & Environ control draft ltrs to Chem-Nuclear Sys, Inc encl. \* Commission. 79/10/19. 9pp.
- 7912170226 Summary of 791030 meeting w/SC Eureau of Radiological Health, SC Oeological Survey, vendor & USOS in Columbia, SC regeologic & hydrologic aspects of facility & impact of reported fault on integrity of site.

  LEFEVRE, H. Geosciances Branch, 79/12/05. Spp.
- --7912170230 Summary of 791030 meeting with SC Dept of Health & Environ Control.USGS.BC Geological Survey & vendor in Columbia.SC re apparent fault at site.Faults at site should not have significant effect on radionuclide migration.
  TURI.O.P. Low Level Waste Licensing Branch. 79/11/07. Spp.

#### DOCKET 27-048 RICHLAND, WA., NUCLEAR ENGINEERING CO.

- 7912210108 Forwards SNM License 16-19204-01 authorizing receipt & disposal of GNM at low level waste burial ground at Hanford. HA. BMITH,R.D. Low Level Waste Licensing Branch. 79/12/04. 2pp.
- ---7912210110 GNM License 16-17204-01 for Nuclear Engineering Co. Incauthorizing receipt & disposal of SNM at low level waste burial ground at Hanford, WA.
  SMITH.R.D. Low Level Waste Licensing Branch. 79/11/30. 24pp.
- ---7912210114 "Low Level Waste Burial Ground Site Closure & Stabilization," Revision 1.

  \* Low Level Waste Licensing Branch. 79/05/17. 7pp.
- 7912310249 Forwards FR notice of issuance of renewal license for disposal of BNM.
  DRAGONETTE, K. S. Low Level Waste Licensing Branch. 79/12/1 Low Level Waste Licensing Branch. 79/12/13. 1p.
- -7912310259 Notice of issuance of renewal license for disposal of SNM.
  DRAGONETTE.K.B. Low Level Waste Licensing Branch. 79/12/12.
  4pp.
- 7912310271 Forwards FR notice of issuance of renewal license for disposal of BNM.Replaces Page 4 of notice sent w/791213 ltr. H/D enci. DRAGONETTE.K.8, Low Level Waste Licensing Branch. 79/12/14.
- 7912280672 Urges finalization of DOE plans for acceptance of commercial transurante waste. Nuclear Engineering Cowill not accept BMM at site.
  MARTINIJ.B. Division of Waste Management. 79/12/18. 1p.
- ---7912280674 Returns License 16-19204-01, due to alleged defects in licensing procedures No nuclear waste will be accepted at site. NEELIJ.N. Nuclear Engineering Co., Inc., (subs. of Taledyne, Inc.). 79/12/07. 2pp.

#### DOMESTIC LICENSING OF SOURCE MATERIAL

#### DOCKET 40-0229 UNION CARBIDE CORP.

7912120575 Bummary of 791016 meeting w/ANL in Bilver Spring,MD re Union Carbide Corp new proposed tailings disposal plan & FEB preparation. KOTSCHJ,L. Uranium Recovery Licensing Branch. 79/11/21. Spp.

#### DOCKET 40-0299 UNION CARBIDE CORP.

- 7912170286 Authorizes archeological survey on 3.5 sections of land & Site 48NA102. Forwards State of WY 791106 ltr describing REKEMEYER, P. C. Union Carbide Corp. 79/11/13. 2pp.
- 7712310158 Forwards 771130 permeability tests rept per License Amund 13.Condition 2.Tests indicate average permeability of 0.83 ft/gr for clay liner as installed. MONO.T. Union Carbide Corp. 79/12/05. 5pp.

## DOCKET 40-0341 GENERAL SERVICES ADMINISTRATION

- 7912040031 Ack receipt of 791018 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 40-0341/79-01.
  MCCLINTOCK.R.G. Region 1. Philadelphia. Office of the Director.
- -7912040036 Responds to NRC 790919 ltr re violations noted in IE Insp Rept 40-0341/79-01. Corrective actions: regional radiological survey & audit conducted & actions taken to ensure proper instrument calibr. PERRYMAN.O.I. General Services Administration. 79/10/19. 3pp.
- ---7912040038 Discusses IE Insp Rept 40+0341/79-01 on 790829 & forwards notice of violation. MCCLINTOCK, R. O. Region 1, Philadelphia, Dffice of the Director, 79/09/19. 2pp.
- --7912040045 Notice of violation from insp on 790829. Noncompliance noted:
  failure to conduct required insps of Curtis Bay depot.
  Region 1. Philadelphia, Office of the Director. 79/09/19.
- 7912280007 Responds to IE Bulletin 79-19. "Packaging of Low Level Radwaste for Transport & Burial." Radwaste generated occasionally upon repackaging of leaking containers or shipment/relocation of matls requiring decontain

#### DOCKET 40-1162 WESTERN NUCLEAR. INC.

- 7912110072 Notifies of issuance of License Amend 5, authorizing raise of util tallings dam to elevation 6410 & operating level of tailings pond to elevation 6400.

  SCARANDER.A. Uranium Recovery Licensing Branch. 79/10/11.
- 7912030032 Forwards results of analysis of nine samples of sediment collected between lowest settling pond & ore haul road within water drainage pathway, as directed by NRC BDODEM O. Western Nuclear, Inc. (subs. of Phelps Dodge Corp.). 79/10/29. 3pp.
- 7912110115 Notifies of amend fee overpayment per issuance of License Amend 4 on 790625 Refund will be made. MILLER.W.O. License Fee Management Branch. 79/11/02. 1p.
- 7912180073 Requests const insp of lift in tailings retention dam, authorized by Amend 5 to license. Insp is necessary within next two was, in light of Lessons Learned Task Force recommendations from Church Rock dam failure.

  BCARANG, R. A. Uranium Recovery Licensing Branch. 79/11/09. 1p.
- DOCKET 40-1341 EDGEMONT URANIUM MINE, TVA & MINES DEVELOPMENT, INC.
- 7912140255 Forwards conceptual decommissioning plan, in response to request to 0 Trager of NRC, W/o encl.
  MILLS.L.M. Tennessee Valley Authority. 79/10/03. ip.
- 7912190086 Responds to request for participation in EIS for Edgement U mill in SD. Preparation of entire EIS has been contracted to ORNL. SCARAND, R. A. Interior, Dept. of. 79/11/16. 2pp.
- 7912190725 Bummary of 790924-25 site visit & scoping meeting. Outling of scoping committee & list of attendees encl.
  TRAGER.E.A. Uranium Recovery Licensing Branch. 79/11/16. 11pp.
- 7912180085 Comments on decommissioning plan & environ rept.Rept procedurally adequate w/respect to description & avaluation of selected disposal site,millsite & fish & wildlife resources.
  TAUD, S. H. Interior, Dept. of, Fish & Wildlife Service. 79/11/19.
- 7912170069 Forwards comments re land use, surface water hydrology, geology & terrestrial biota required for review of environ rept for Edgemont U mill docommissioning. Requests response according to agreed timetable.

  BCARANG, R. A. Uranium Recovery Licensing Branch. 79/11/21. 18pp.

#### DOCKET 40-1386 RAYTHEON CO.

- 7912030221 Ack receipt of 791022 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 40-1386/79-01.
  MCCLINTOCK, R. D. Region 1, Philadelphia, Office of the Director. 79/11/01. ip.
- --7912030222 Responds to NRC 790918 ltr re violations noted in IE Insp Rept 40-1386/79-01. Corrective actions: breathing zone sampling to be initiated for determination of thorium contamination in work areas. MERROW.R.J. Raytheon Co. 79/10/22. 3pp.
- --7912030224 Discusses IE Insp Rept 40-1386/79-01 on 790816-17 & forwards notice of violation.

  MCCLINTOCK.R.O. Region 1, Philadelphia, Office of the Director 79/09/18. 20p.
- DOCKET 40-2061 WEST CHICAGO FACILITY, KERR-MCGEE CORP.
- 7912070009 "Stabilization Plan."

  # Kerr-McGee Chemical Corp. (subs. of Kerr-McGee Corp.). 79/08/15. 274pp.
- 7912030019 Summary of 790919 meeting w/state.local & federal representatives in Region 3 ofcs re Kerr-McGee stabilization plan for site.

  NIXON,W.A. Uranium Fuel Licensing Branch. 79/09/25. 2pp.
- 791203000B Bubmits demands for inclusion in 791106 meeting between NRC & Kerr-McGee in Rockville, MD re decommissioning of West Chicago facility, Urges future nontechnical meetings be held in Chicago area.

  RENNELS, A. E. West Chicago, IL. 79/10/31. 1p.
- 7912030024 Confirms 791101 telcon re matls taken from factory site & installed elsewhere. Ofc of Atty General requests radiological measurements on all matl taken from site. MANBELL.D. Illinois, State of. 79/11/02, 2pp.
- 7912190217 Requests thorough analysis of Kerr-McGea lab, converted into ofcs in Chicago, IL, in which excess levels of radiation have been detected. Also requests identification of other Kerr-McGee bidgs.

  HANSELL.D. Illinois, Stata of. 79/11/19. 1p.
- 7912170177 Forwards comments from various organizations, re proposed stabilization plan & IE study on airborne risks posed by thorium-bearing residues found at various places in West Chicago IL.
  NIXUN.W.A. Uranium Fuel Licensing Branch. 79/11/21. 10pp.
- --7912170180 Submits comments on Kerr-McCee Chemical Corp proposed stabilization plan re activities in West Chicago, IL. EPA comments encl. HANSELL.D. Illinois, State of. 79/10/19. 28pp.
- --7912170185 Forwards results of experiment conducted on West Chicago soil samples re airborne thorium risk experiment. GRANT.W.B. Region 3. Chicago, Office of the Director. 79/10/24.
- 7912050041 Summary of 791113 meeting w/Kerr-McGee re comments prepared by various organizations on proposed stabilization plan for facility. Vendor agreed to provide changed or addl pages for stabilization plan to reflect answers. NIXON.W. A. Uranium Fuel Licensing Branch. 79/11/27. 2pp.
- 7912200450 PNO-III-79-049; on 791126, radioactivity detected in bldg purchased several years earlier from vendor. No radiation levels likely to cause exposures in excess of NRC limits. PAPERIELLO, C. J., RDY, G. Region 3, Chicago, Office of the Director. 79/11/28. ip.
- 7712260103 Forwards FR notice re vendor decommission plans for rare earth facility & NRC intent to prepare E18.
  CROW.W.T. Uranium Fuel Licensing Branch. 79/12/11. 1p.
- ---7912260106 Notice of availability of stabilization plan & intent to prepare DEB re approval of plan to decommission rare earth facility. Stabilization plan & racipient address list encl. CROM. H. T. Uranium Fuel Licensing Branch. 79/12/11, 3pp.

#### DOCKET 40-2259 PATHFINDER MINES CORP.

- 7912170143 "Ground Hater Hydrology Adjacent to Pathfinder Gas Hills Tailings Reservoirs." HOWLETT, L., HOFFMAN, G. L. Hydro-Engineering, 79/07/31, 122pp.
- 7912170282 Notifies of error in 790302 semiannual effluent monitoring rept. Topsoil sample analyses presented as "soluble" should be identified as "total" concentrations. Std rept form corrected to eliminate further problems.

  NUGENT, E. L. Pathfinder Mines Corp. 79/10/31. 19.
- 7912170284 Forwards data accumulated 790708-14 on in vivo lung analysis re 791029 request.
  NUOENT.E.i. Pathfinder Mines Corp. 79/11/14. 1p.
- ---7912170285 "Rept of In Vivo Counting for Pathfinder Mines Corp." HELGESON, O. L. Helgeson Nuclear Services. Inc. 79/08/24. 5pp.
- 7912190400 Amends Source Matl License SUA-672, authorizing use of new solvent extraction circuit Installation & maint of fire protection sys required for solvent extraction bldg.

  BCARANO, R. A. Uranium Recovery Licensing Branch. 79/11/14. 2pp.
- 7912190612 Amend 6 to License SUA-672, authorizing replacement of solvent extraction circuit Licensee must maintain Halon 1301 fire protection sys in bldg. OILLEN, D.M. Uranium Recovery Licensing Branch. 79/11/14. 2pp.
- 7912280285 Ack receipt of 790822.0917 & 1026 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 40-2259/79-01. EVERETT.R.J. Region 4, Dallas, Fuel Facility & Materials Safety Branch. 79/11/19. 10pp.
- --7912280295 Responds to NRC 790926 ltr re violations noted in IE Insp Rept 40-2299/79-01. Corrective actions: will improve mgt control by direct access to mgt level personnel during entry & exit interviews. NUGENT.E. L. Pathfinder Mines Corp. 79/10/26. 10pp.
- --7912280303 Act receipt of 790822 & 0917 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 40-2289/79-01. Requests addl info. SEYFRIT.K.V. Region 4. Dallas, Office of the Director. 79/09/26. ip.
- --79122803ii Responds to NRC 790906 ltr re violations noted in IE Insp Rept 40-2259/79-01.Corrective actions:radiation health physicist will audit performance of radiation dept every 30 days for six months. NUOENT, E. L. Pathfinder Mines Corp. 79/09/17. 3pp.
- ---7912280325 Ack receipt of 790822 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 40-2259/79-01. Requests addl info. BEYFRIT.K.V. Region 4: Dallas, Office of the Director. 79/09/04. lp.
- ---7912280331 Responds to NRC 790731 ltr re violations noted in IE Insp Rept 40--2299/79-01.Corrective actions:personnel in radiation dept will inspect equipment before operating equipment. NUGENT.E.L. Pathfinder Mines Corp. 79/08/22. 8pp.
- ---7912280339 Forwards IE Insp Rept 40-2259/79-01 on 790625-26 & notice of violation. SEYFRIT.K.V. Region 4, Dallas, Office of the Director. 79/07/31. 2pp.
- --7912280346 Notice of violation from insp 790625-26.
  \* Region 4, Dallae, Office of the Director. 79/07/24. 2pp.
- --7912280360 IE Insp Rept 40-2259/79-01 on 790625-26. Noncompliance noted: failure to perform monthly contamination surveys & scrubber operational checks & failure to post license & regulations. BROWN, O. D. Region 4. Dallas, Fuel Facility & Materials Safety Branch. CAIN.C.L., HARRISDN.H.C. Region 4. Dallas, Office of the Director. 79/07/24. 9pp.

#### DDCKET 40-3453 ATLAB MINERALS

7712170241 Advises of deferral of Yuba City project due to cost, procedures & concerns re efficiency of recovery sys. Requests response to 770829 ltr.
SWANSY, Q. T. Atlas Minerals. 79/10/10. ip.

- 7912030035 Declines 790924 offer to participate in ALARA study. SMANRY, Q. T. Atlas Minerals. 79/10/15. ip.
- 7912030229 Ack receipt of 790914 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 40-3453/79-01.
  Requests further info.
  EVERETT.R.J. Region 4. Dallas, Fuel Facility & Haterials Safety Branch. 79/10/29. 1p.
- --7912030330 Responds to NRC 790820 ltr re violations noted in IE Insp. Rept 40-3453/79-01. Corrective actions: constant flow respirometer purchased to be worn by maint personnel. BWANBY, C. T. Atlas Minerals. 79/09/14. 4pp.
- ---7912030231 Forwards IE Insp Rept 40-3453/79-01 on 790717-19 & notice of violation.
  RRGWN. 9.D. Region 4. Dallas, Fuel Facility & Naterials Bafety Branch. 79/08/20. 2pp.
- --7912030232 Notice of violation from insp on 790717-19.
  Region 4. Dallas. Office of the Director. 79/08/17. 2pp.
- ---7912030234 IE Insp Rept 40-3453/79-01 on 790717-19. Noncompliance noted: improper selection of respirator equipment & failure to conduct biweskly surface contamination surveys of change rooms.

  \*\*\*Region 4, Dallas, Office of the Director. 79/08/17. 6pp.
- 7912200137 Notifies that Source Hatl License SUA-917 is amended revising Condition 19.authorizing elevation increase of tailings impoundment & tailings pond.
  BCARANG.R.A. Uranium Recovery Licensing Branch. 79/10/29. 2pp.
- 7912200162 Forwards "Rept of In Vivo Counting, 790711-13." SWANBY, Q. T. Atlas Minerals. 79/11/15. ip.
- --7912200165 "Rept of In Vivo Counting, 790711-13."

  \* Helgsson Nuclear Services. Inc. 79/07/13. 14pp.
- 7912280638 Discusses 791113 insp of const of 18-ft rise to tailings pond. Testing procedures & const activities adequate. Nat1 meets design space for soils.
  HOWARD, T. R. Atlas Hinerals. 79/11/30. 2pp.
- 7912310162 Forwards design criteria, gradation curve & hydrologic & const data design drawing per 791220 assting, BNANBY, Q. T. Atlas Hinerals, 79/12/03, Spp.

#### DOCKET 40-4492 FEDERAL AMERICAN PARTNERS (MINING)

- 7912180179 Requests permission to construct & operate major mod & expansion of facility under Licness SUA-667. Forwards supportive documentation, "Major Mod (2000 Tons per Day Mill Addition) to Source Matts License SUA-667 Application." HRIGHT, K. H. Federal American Partners (Mining). 79/11/14. 1p.
- --7912180184 "Major Hod (2000 Tons Per Day Mill Addition) to Bource Matls License SUA-667 Application," Seven oversize drawings enci. \* Federal American Partners (Mining). 79/11/14. 53pp.
- 7912170093 Bummary of 791009 meeting w/TVA & Federal American Partners in Bilver Spring, MD re license renewal request.

  GILLEN, D. M. Uranium Recovery Licensing Branch. 79/10/26. 2pp.
- 7912030012 Forwards results of in vivo body scans representing data taken from 38 employees over 3-yr period, performed per NRC request.
  BPIBAK.J.F. Federal American Partners. 79/11/01, 3pp.
- 7912170114 Forwards projected schedule for Federal American Partners environ rept review based on receipt of rept by 791207.
  LINEHAN, J. J. Uraniwa Recovery Licensing Branch. 79/11/20. 2pp.
- 7912310375 Confirms adding discussion re moving existing tailings pond to agenda of 791218 meeting w/NRC in Silver Spring. ND. SPIBAK. J. F. Federal American Partners (Mining). 79/11/21. ip.
- 7912310445 Forwards Region 4 791113 rept re survey of former US Energy Corp metal bidg decontaminated by Federal American Partners, Bldg meets unrestricted use criteria. LINEHAN, J. J. Uranium Recovery Licensing Branch. 79/11/29, 1p.

---7912310449 Submits results of 791030 rediction survey of former US Energy Corp metal bldg located at Federal American Partners U milling site. Contamination levels acceptable for unrestricted use.
CAIN.C.L. Region 4. Dellas, Fuel Facility & Materials Safety Branch. 79/11/13. 1p.

#### DOCKET 40-6940 KAWECKI BERYLCO INDUSTRIES, INC.

- 7912170075 Porwards notice to be published in FR, listing major proposed licensing actions filed w/Div of Fuel Cycle & Matl Safety not previously listed in FR. CUNNINNHAM.R.E. Division of Fuel Cycle & Material Safety. 79/11/19. 1p.
- --7912170078 Natice of receipt of applications for licenses amends & licenses renewals.

  CUNNINGHAM.R. E. Division of Fuel Cycle & Material Safety.
  79/1/159. 500.

#### BBCKET 40-7344 GENERAL ELECTRIC CO.

- 7912110157 Ack receipt of 791101 ltr informing NRC of steps taken in response to IE Insp Repts 30-06047/79-01 & 40-7344/79-01.9E interpretation of 10GFR20 correct re access. Interlock control not required. HCCLINTOCK,R. D. Region 1, Philadelphia, Office of the Diractor. 79/11/14. ip.
- --7912110167 Responds to NRC 791026 ltr re IE Insp Repts 30-06047/79-01 & 40-7344/79-01. Corrective actions: compliance w/10CFR20 achieved re control of nosetip line scanner in Bldg 100. Requests NRC advice re need for interlock control. HCFADDEN, J.R. General Electric Co. 79/11/01. 1p.
- --7912110175 Discusses IE Insp Repts 30-06047/79-01 & 40-7344/79-01. No noncompliance noted. Major areas inspected: licenses actions re radiation safety, license & NRC rules. NRC understands Bldg 100 will be equipped w/interlocks per 10CFR20. MCCLINTOCK, R. O. Region i, Philadelphia, Office of the Director, 79/10/R6. Rpp.

## DOCKET 40-7869 PLATEAU REEDURCES, LTD.

- 7912130360 Discusses decommissioning plans for facility Monitoring under way, Mill startup planned for first quarter of 1981.

  Transfer of wet tailings will begin by 810301 & be completed by 810431.

  NEWMAN,P. Plateau Resources, Ltd. 79/11/12, 2pp.
- 7912170099 Confirms 791105 telcon w/R Cooperstein re decommissioning of Shootering Canyon RAD site. Updated proposed decommissioning plans due by 791231.

  LINEHAN, J. J. Uranium Recovery Licensing Branch. 79/11/20. ip.

#### DOCKET 40-8027 KERR-HCGEE CORP.

- 7912260352 Requests exemption from licensing fees. Amends will be issued to licensees to incorporate decommissioning & emergency plans as conditions of licenses.
  ROMBE, L. C. Probabilistic Analysis Branch (Pre 791030). 78/07/13. Spp.
- 7912030017 Responds to NRC 791018 telcon re addl info to support 791005 request for exception to Reg Guide 3.13.Discusses pond fill schedule & above- & below-grade pond failures. HKELLEY&M.J. Kerr-McGee Corp. 79/10/31. Spp.
- DOCKET 40-8102 EXXON MINERALS CO. USA, EXXON CORP.
- 7912040029 Responds to 790730 request for info re in situ U solution extraction technology & specific projects utilizing sodium carbonate-bicarbonate as lixiviant Forwards NUREG/CR-0311 & NUREG-0499 N/o encl.

  MILLER, H. J. Uranium Recovery Licensing Branch. 79/08/28. 1p.
- 7912310190 Advises of planned program to improve ventilation in mill yellowcate work areas Alterations do not change operation mode significantly, as discussed in 791026 telcon. Description of proposed alterations encl.
  ORTLOFFIG.D. Etxon Minerals Co., USA. 79/10/30. App.

- 7912200169 Forwards rept "In Vivo Lung Counting Data, Highland U Operations: 1978-1979."
  SALMONSON, B. J. Exxon Minerals Co., USA. 79/11/09. 1p.
- --7912200173 "In Vivo Lung Counting Data, Highland U Operations, 1978-1979."

   Exten Hinerals Co., USA, 79/11/09, 4pp.
- 7912190780 Requests confirmation that amend to license is not necessary to allow acceptance & processing of U solutions & slurries at facility.

  ORTLOFF, Q. D. Exxon Minerals Co., USA. 79/11/12. ip.

#### DOCKET 40-8200 CLEVELAND-CLIFFS IRON CO.

- 7912190275 Requests license cancellation. Forwards "North Rolling Pin in Situ Bolution Mine Test & Restoration Summary," giving post-operational findings. BDMERVILLE.K.Q. Cleveland-Cliffs Iron Co. 79/10/26. ip.
- ---7912190280 "North Rolling Pin In Situ Solution Mine Test & Restoration Summary." WATKING.D. In-Situ Consulting. 79/01/31. 95pp.

#### DOCKET 40-8304 WYOMING MINERAL CORP.

- 7912110092 Responds to 790816 ltr re license renewal Advises that 790726 ltr was in error Requests proposed plans for R&D activities prior to license renewal Addl site info necessary.

  SCARAND R. A. Uranium Recovery Licensing Branch. 79/10/24. 2pp.
- 7912190788 Hithdraws request for hearing re renewal of license Requests postponement until 800111 for providing planning info re R&D activities.

  8CHENDEL, K. R. Hyoming Mineral Corp. 79/11/13. 1p.
- 7912120093 Summary of 791102 meeting w/vendor in Bilver Spring, MD restatus of license renewal request, lixiviant excursion at commercial in situ site & status of amend application to authories increase in flow rate capacity.

  COOPERSTEIN,R. Uranium Recovery Licensing Branch. 79/11/19.
- 7912180100 Bummary of 791101 meeting w/HY Mineral Corp in Bilver Spring, HD re in situ U solution extraction activities at Irigarey site, COOPERSTEIN, R. Uranium Recovery Licensing Branch. 79/11/19. 300.

#### DOCKET 40-8348 IN SITU URANIUM LEACHING PROJECT

7912170243 "Addendum to Sunopsis of Research In Situ U Leaching Project, Results of Aquifer Stabilization Observation & Other Surveys." Drawing encl.

\* Minerals Exploration Co. (subs. of Union Dil Co. of California).
79/10/24. 37pp.

#### DOCKET 40-8380 ROCKY MOUNTAIN ENERGY CO.

7912170172 Notifies of excursion in Pattern 3 Nine Hile Lake in situ leach test operation. Discovered during routine check of pH & conductivity of monitor well sample.

ROTHFLEISCH, J. E Uranium Recovery Licensing Branch. 79/11/21.
19.

#### DOCKET 40-8452 BEAR CREEK URANIUM CD.

- 7912200604 Requests written confirmation of 790824 telcon authorizing increase in sampling frequency for grizzly source term acutioring.
  MEDLOCK.R.L. Bear Creek Uranium Co. 79/11/07. 2pp.
- 7912270252 Forwards in vivo counting data for each employes at Bear Creek. HERSLOFT, L. W. Rocky Mountain Energy Co. 79/11/26. 3pp.

- DOCKET 40-8502 IRIGARAY MINE, WYOMING MINING CORP.
- 7912310193 Forwards status rept in form of 790917 & 21 communications between Irigary Pacility & State of MY. Includes water quality analyses, static water levels & piezometric contours. SCHENDEL, K.R. Westinghouse Electric Corp., Myoming Mineral Gorp. 79/09/26. 13pp.
- 7912310197 Forwards status rept in form of 790926 & 1012 communications between Irigary facility & State of MY. Includes addit water quality analysis results from shallow monitor & shallow research well samples.

  80HENDEL, K.R. Westinghouse Electric Corp., Wyoming Mineral Corp., 79/10/16. 24pp.
- 7912170170 Forwards change request & latest communications between Irigary facility & State of WY.
  SCHENDEL.K.R. Wyoming Mineral Corp. 79/11/12. Spp.
- 7912200014 Forwards update of Inigarary 517 ammunia transport & conversion monitoring program re requirements of license Condition 38.
  FORD-W. Wyoming Mineral Corp. 79/11/16. 9pp.
- 7912120093 Summary of 791102 meeting w/vendor in Silver Spring, MD restatus of license renewal request lixiviant excursion at commercial in situ site & status of amend application to authorize increase in flow rate capacity.

  CDOPERSTEIN.R. Uranium Recovery Licensing Branch. 79/11/17.
- 7912180100 Summary of 791101 meeting w/WY Mineral Corp in Bilver Bpring,MD rs in situ U solution extraction activities at Irigaray sita. COOPERSTEIN,R. Uranium Recovery Licensing Branch, 79/11/19.
- 7912130011 Provides written summary of verbal update given at 791102 maeting re excursion cleanup procedures required for Irigaray mine by HY Dept Environ Quality, FORD, W.H. Hyoming Mineral Corp. 79/11/26. 2pp.
- 7912210042 Forwards notice of violation from State of HY Dept of Environmental Grality re topsoil waste noted during 791018 insp. Cease & desist order issued 791031 Supporting documents encl.

  SCHENDEL, K. R. 'Hyoming Mineral Corp. 79/11/26. 26pp.
- 79122B0106 Forwards 791116 ltr from WY Mineral Corp to State of WY Dept of Environ Quality. Weekly water quality analyses for shallow monitor & shallow research wells encl. WICHERS, D. L. Wyoming Mineral Corp. 79/11/26, 13pp.
- 7912310203 Forwards latest communications between Irigary mine site & WY Dept of Environ Quality. Includes weekly water quality analyses for shallow monitor rone.

  WIGHERS, D. L. Wyoming Mineral Corp. 79/11/28. 9pp.
- 7912270047 Forwards 791029 itr from HY Mineral Irigary facility to State of HY re operations under Mining Permit 478. Two oversize drawings enci.

  SCHENDEL.K.R. Wyoming Mineral Corp. 79/11/30. 22pp.

#### DOCKET 40-8584 UNION 76 MINERALS EXPLORATION CO.

7912170283 Informs that on 791114.smbankment fill placement on Cell C of tailings impoundment was suspended for duration of winter months. Final fill placement will commence in Spring 1980. ACOSTA.A.P. Union 76 Minerals Exploration Co. 79/11/19. 1p.

#### DOCKET 40-8431 ARMY, DEPT. OF, ARMAMENT MATERIEL READINESS COMMAND

7912110182 Discusses IE Insp Repts 30-06068/79-01.30-08867/79-01.
40-8621/79-01 & 70-0693/79-01 on 791003.No noncompliance noted. Major areas inspected: radiation safety & compliance w/NRC regulations.
MCCLINTOCK.R.O. Region 1, Philadelphia, Office of the Director. 79/10/18. 2pp.

#### DOCKET 40-8636 WOLD NUCLEAR CO.

7912130002 Notifies of termination of License 8UA-1329, in accordance w/790816 ltr.
8CARAND.R.A. Uranium Recovery Licensing Branch. 79/10/18. lp.

7912170113 Recommends termination of License SUA-1329, per Wold Nuclear Co 790816 request. Field investigation reveals that no U solution extraction has occurred. Final surveillance for decommissioning unnecessary.
COUPERSTEIN, R. Uranium Recovery Licensing Branch. 79/10/18.

#### DOCKET 40-8663 NUCLEAR DYNAMICS, INC.

- 7912120135 Forwards "Restoration Summary Rept on In Situ Solution Mining Test Bitt."
  STOICK.A.F. Noclear Dynamics. 79/10/19. 1p.
- --7912120137 "Restoration Summary Rept on In Situ Solution Mining Test Site." GANNADY:F. X. Nuclear Dynamics. 79/10/19. 40pp.
- ---7912120150 Forwards ltr of notification of restoration activities, prepared by FX Connady, project engineer. STOICK, A. F. Nuclear Dynamics. 79/07/13. 1p.
- ---7912120153 Ltr of notification of restoration activities. Qutlines transition from end of leaching to restoration proper. CANNADY, F. X. Nuclear Dynamics. 79/07/09. 3pp.
- 7912210112 Advises that data for sixth quarterly rept under License BUA-1331 can be found in "Restoration Summary Rept on In Bito Mining Test Bite Sundance Proj. Crook County, WY." STOICK.A.F. Nuclear Dynamics. 79/11/26. 1p.

#### DOCKET 40-8674 PLATEAU RESOURCE

- 7912280082 Forwards request to amend License SUA-1326. Also discusses compliance w/other conditions of license re radiation sefety officer, earthen berm around ore storage pad, dust control, reclamation plans & equipment for in vivo lung counts.

  SEWELL, R. D. Plateau Resources, Ltd. 79/10/31. 3pp.
- --7912280089 Requests amend of License SUA-1326 including changes to address amount, mgt control program & area for decommissioning.
  SEWELL,R.B. Plateau Resources, Ltd. 79/10/31. Spp.
- --7912280102 Requests submission of fee to amend License 8UA-1326. JACKSON.O. License Fee Management Branch. 79/11/29. 1p.
- --7912280108 Forwards fee for amend to License SUA-1326. NEWHAN, P. Plateau Resources, Ltd. 79/12/03. lp.

#### DOCKET 40-8675 ENERGY FUELS NUCLEAR, INC.

- 7712180260 Forwards Source Matl License SUA-1325.A)1 administrative, operating & monitoring procedures must be implemented at least 30 days from license issuance date.

  SCARAND, R. A. Uranium Recovery Licensing Branch. 79/09/29. ip.
- --7912180264 Bource Matl License SUA-1325 for Energy Fuels Nuclear, Inc authorizing use of crushed natural U ore at one buying station mear Hanksville, UT. BCARAND, R. A. Division of Fuel Cycle & Material Bafety. 79/09/28. 12pp.

#### DOCKET 40-8677 NL INDUSTRIES, INC., BEARINGS DIV.

7912030120 Bubmits application for Amend 2 to NL Bearings/NL Industries export license increasing amount of U to &0.000 lb & extending expiration date to 820101.

CIANI,F. NL Industries, Inc. 79/10/30. lp.

#### DOCKET 40-8681 ENERGY FUELS NUCLEAR. INC.

- 7912120011 Amend 1 to Source Matl License SUA-1358 re Conditions 25 & 26 authorling first stage of const of enbankments & liner sys of tailings retention sys.

  SCARAND.R.A. Uranium Recovery Licensing Branch. 79/10/12. 4pp.
- 7912130167 Confirms 791016 talcon itemizing specific concerns about memorandum of agreement re mitigation of adverse effect at mill site. Licensee will avoid project design within 100 ft of project design within 100 ft of perimeter of reclaims tailings impoundment area. SCARAND.R. A. Uranium Recovery Licensing Branch. 79/10/19. Spp.

- 7912190010 Forwards documentation of ownership or control of land to be used for tailings disposal in accordance w/Condition 2B of License SUA-1358 Includes warranty deeds & mill site claims.

  BAKER, C. E. Energy Fuels Nuclear, Inc. 79/11/12, 51pp.
- 7912310169 Discusses 791109 const insp of embantments on Cells 1,2 & 3. Const procedures appear adequate. Memo documenting 791018 site visit enclosed.

  NELSON, J. D. Colorado State Univ. 79/11/12. 3pp.

#### DOCKET 40-BA92 COTTER CORP.

7912190638 Lists contract costs incurred & manhours expended in reviewing 780324 application. Approved by RA Scarano. ROTHFLEISCH, J.E. Uranium Recovery Licensing Branch. 79/11/04.

#### DOCKET 40-8698 PLATEAU RESOURCES, LTD.

- 7912130192 Amend 1 to License SUA-1371, authorizing const of embankment for tailings impoundment by adding Condition 40-43 k modifying Condition 19, Paragraph C. SCARANO, R. A. Uranium Recovery Licensing Branch. 79/09/28.
- DOCKET 40-8721 ROCKY MOUNTAIN ENERGY CO.
- 7912130702 Requests listed or proposed threatened endangered species within proposed U recovery project area. Map of U project site plan enci.
  ROTHFLEISCH, J. E. Uranium Recovery Licensing Branch. 79/06/15.
- 7912130084 Requests supplemental info on surface water features, seepage recovery & pipeline failure for review of 790212 environ info re source matl license application. Requests info re endangered species for biological assessment.
  ROTHFLEISCH. J. E. Uranium Recovery Licensing Branch. 79/10/12.
- --7912130091 Requests identification of listed or proposed endangered species within area of proposed project location.
  ROTHFLEISCH, J. E Uranium Recovery Licensing Branch. 79/06/15.
- --7912130133 Notifies of concerns re project in Natrona County, WY. Public lands within project not identified. Environ rept did not specify occupation of public land. Location of federal whereals not identified.

  BAKER. D. P. Interior, Dept. of. Bureau of Land Management. 79/09/19.
- 7912260250 Confirms 791004 rept re status of Rocky Mountain Energy Co Nine Mile Lake commercial solution mining project. ROTHFLEISCH. J. E Uranium Recovery Licensing Branch. 79/10/22.
- 7912170267 Forwards response to NRC 791012 questions re environ rept & source matt license Requests comments.W/o encl.
  NEUMANN.M.R. Rocky Mountain Energy Co. 79/11/09. 3pp.
- 7912180088 Forwards revised environ rept. "Prinicipal Parameters for Radiological Assessment." NEUMANN.M.R. Rocky Mountain Energy Co. 79/11/14. ip.
- 7912180093 Revised environ rept. "Principle Parameters for Radiological Assessment."

  \* Rocky Mountain Energy Co. 79/11/14. 18pp.
- 7912310200 Submits formal written notification of excursion at facility. Forwards chronology of excursion verification for Well M-40, corrective actions & drawing of Pattern III well layout Progress repts forthcoming.
  BOLBER, C. M. Rocky Mountain Energy Co. 79/11/16, 19pp.
- 7912190484 Advises that Board of Natrona County Commissioners has no questions or comments on environ rept or source matl license application.
  ECHULTE, F. L. Natrona County, WY. 79/11/19. lp.
- 7912310372 Comments on Rocky Mountain Energy response to questions re proposed in situ U operation at Nine Mile Lake, Casper, MY. Buggests response to question re examination of groundwater rights & supplies is speculative.

  BEDONT, N. E. Wyoming, State of. 79/11/26, 3pp.

#### DOCKET 40-8722 BRUSH-WELLMAN, INC.

7912200588 Forwards plan for future decontamination & reclamation of recovery operation, as required by Condition 27 of source matl license.

ZUEHLKE.J.R. Brush-Wellman, Inc. 79/11/15. 2pp.

#### DOCKET 40-8725 GULF MINERAL RESOURCES CO.

- 7912050443 Offers no comment re Gulf Resources Co project.Requests Requests relevant mati as available.
  CARTER.D. McKinley Area Council of Govts, Gallup.NM. 79/10/04. 1p.
- 7912190642 Summary of 791022-23 site visit & scoping meeting. Outline of scoping meeting & list of attendees encl.
  TRAGER, E. A. Uranium Recovery Licensing Branch. 79/11/16. 12pp.

#### DOCKET 40-8727 KERR-MCGEE NUCLEAR CORP.

- 7912190131 Forwards add1 info re application for source mat1 license covering U recovery activities from minewater per 791003 request Includes map & organization description.
  SHELLEY, W. J. Kerr-McGee Corp. 79/11/07. 10pp.
- --7912190136 NPDE8 Permit WY-0022411,issued to Kerr-McGee Nuclear Corp. \* Environmental Protection Agency, 78/05/08, 10pp.
- --7912190144 NPDES Permit WY-0026221, issued to Kerr-McGee Nuclear Crop. \* Environmental Protection Agency. 78/04/10. 11pp.
- --7912190148 NPDES Permit WY-0026212,issued to Kerr-McOse Nuclear Corp. \* Environmental Protection Agency. 78/08/08. 10pp.

#### DOCKET 40-8728 TETON EXPLORATION DRILLING CO., INC.

- 7912180394 Accepts application request for source matl license to conduct U solution mining R&D operation Addl environ repts needed. Forwards request for addl info.
  MILLER, H. J. Uranium Recovery Licensing Branch. 79/10/22. 4pp.
- 7912200293 Advises that permission to install equipment does not constitute NRC approval of application. Permission granted due to R&D nature of facility.

  MILLER, H. J. Uranium Recovery Licensing Branch. 79/11/09. lp.

#### DOCKET 40-8745 DOLE PETROLEUM

- 7912210186 Application for source matl license authorizing extraction of 180,000 kg U-308 in wet slurry form.Resumes for QJ Hartman.QJ Catchpole & JQ Vialpando encl., CATCHPOLE.Q.J. Ogle Petroleum.Inc. 79/08/01. 6pp.
- 7912130402 Forwards transmittal ltrs for anviron rept, per list provided by BJ Fisher. Ltrs also notify of 791101 public meeting in Riverton, WY to discuss scaling for Bison Basin Project. CATCHPOLE. O. J. Ogle Petroleum, Inc. 79/10/19. 2pp.
- 7912210300 Forwards notice of intent to prepare DES & scoping meeting.

  \* Uranium Recovery Licensing Branch. 79/10/26. 1p.
- --7912210312 Notice of availability of environ rept & intent to prepare DES re issuance of source matl license.

  BCARANO.R.A. Uranium Recovery Licensing Branch. 79/10/09.

  Rpp.
- 7912210317 Forwards notice of intent to prepare draft environ impact statement & notice of scoping meeting, W/o encl. Division of Waste Management, 79/10/26. 1p.
- --7912210323 Forwards notice of intent to prepare draft environ impact statement & notice of scoping meeting. W/o encl.

  \* Division of Waste Management. 79/10/26, 1p.
- --7912210328 Forwards notice of intent to prepare draft environ impact statement & notice of scoping meeting, W/d encl.

  \* Division of Waste Management. 79/10/26. ip.

- 7912170129 Discusses Ogle Petroleum application for license to extract in situ U from site in Fremont County, WY. Requests info re endangered or threatened species in area. MILLER, H. J. Uranium Recovery Licensing Branch. 79/11/07. 3pp.
- 7912310515 Provides comments re environ rept on production-scale in situ U mine in Bison Basin.WY. Eventual disposal of evaporities should be further discussed to assure hazardous math will not be abandoned at site.

  MENARD, H. W. Interior, Dept. of. Geological Survey. 79/11/15. 1p.
- 7912200616 Forwards transcript of 791101 meeting w/NRC re environ scoping. CATCHPOLE.O.J. Ogle Petroleum, Inc. 79/11/16. 21pp.
- 7912190212 Discusses & submits comments on review of Ogle Petroleum Environ Rept for proposed Bison Basin in situ U leach mine in Fremont County, HV. Section re solid effluents requires clarification concerning low level radioactive solids. LARSON. H. C. Interior, Dept. of, Bureau of Mines. 79/11/21. 1p.
- 7912310165 Responds to NRC 791107 ltr rs U extraction from ore body in Framont County, MY. Biological assessment required to determine if proposed project will affect endangered species.

  5TILES, H. E. Interior, Dept. of, Fish & Wildlife Service. 79/11/23. io.
- 7912310212 Comments by State of HY Executive Dapt on environ rept for proposed production-scale in situ mine:NRC should more fully scrutinize potential surface & groundwater impacts.

  Supporting documentation encl.

  HERBCHLER, E. Wyoming, State of. 79/11/23. 12pp.
- 7912270067 Notifies of completion of acceptance review of 790810 BNM license application & supporting environ rept Documents are acceptable. Dimonthly repts re review schedule will be provided.

  MILLER, H. J. Uranium Recovery Licensing Branch. 79/11/26. 5pp.
- ~~7912270069 Notice of availability of environ rept & intent to prepare draft EIB re issuance of source matl license for Dison Basin project in Frémont County, WY. Questions, comments & requests for addl info encl, BCARANO, R. A. Uranium Recovery Licensing Branch, 79/10/09.
- 7912190208 Commants on environ rept for Olge Petroleum, Inc. in situ U Mine, Framont County, WY. Requests to review environ statement, when prepared to ascertain any adverse impacts to Indian land & people of Wind River Indian Reservation.

  \* Interior, Dept. of, Dureau of Indian Affairs. 79/11/28. 1p.

#### DOCKET 40-8748 CYPRUS MINES CORP. . URANIUM DIV.

- 7912130318 Responds to 790912 request for placement on mailing list for receipt of metl re environ impact of area. Two license applications for mills in areas are under review. DEB will be sent when available.

  BCARAND.R.A. Uranium Recovery Licensing Branch. 79/10/16. lp.
- 7912110272 Notifies of completion of acceptance review of byproduct matl license application & supporting environ rept re proposed Hansen project Document acceptable for detailed review.

  SCARAND.R.A. Uranium Recovery Licensing Branch, 79/10/23. ip.
- 7912210272 Forwards notice of availability of environ rept & notice of 791106 scoping meeting. W/o encl.

  \* Office of Nuclear Material Safety & Safeguards. 79/10/26. 1p.
- --7912210277 Forwards notice of availability of environ rapt & notice of 791106 scoping meeting. W/o encl.

  \* Office of Nuclear Material Safety & Safeguards. 79/10/26. ip.
- --7912210286 Forwards notice of availability of environ rept & notice of 791106 scoping meeting. H/o encl.

  \* Office of Nuclear Material Eafety & Safeguards. 79/10/26. lp.
- --7912210290 Forwards notice of availability of environ rept & notice of 791106 scoping meeting.

  \* Office of Nuclear Material Bafety & Bafeguards. 79/10/26. 1p.
- --7912210295 Notice of availability of environ rept & intent to prepare draft environ impact statement re issuance of source matl licensee.

  BCARANO, R. A. Uranium Recovery Licensing Branch. 79/10/22.

  Zpp.

### DOCKET 40-8751 COTTER CORP.

77:12:303:18 Responds to 77:07:12 request for placement on mailing list for receipt of mail re environ impact of area. Two license applications for mills in areas are under review. DES will be sent when available.

SCARANO, R. A. Uranium Recovery Licensing Branch. 79/10/16. 1p.

# DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

# DOCKET 50-2 UNIV. OF MICHIGAN RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

7912120206 Forwards draft Reg Guide S.XX. "Std Forest & Content for Licensee Physical Security Plan for Protection of SMM of Moderate or Low Strategic Significance." W/O encl. REID.R.W. Operating Sysectors Strench 4 (Pre 791030). 79/08/22.

# DOCKET 50-3 INDIAN POINT STATION, UNIT 1

- F. Security, medical, emergency & fire protection plans
- 7912200022 Discusses NRC 791109 mesting re sarrgancy preparedness team review objectives. Provides guidance for improving licenses energency preparedness & assuring capability of offsite agencies to take appropriate management actions.

  ORIMER, B.K., CULLING.H., SNIEZEK.J. Emergancy Preparedness Task Force. 79/11/23, 30pp.
- 7912200122 Notification of 791205 meeting w/util in Bethesda.MD, to review eargency preparedness capabilities.List of NRC considerations encl. EISENHUT.D.Q. Division of Operating Reactors. 79/11/29. 3pp.
- 7912240003 Notification of 791218 meeting w/util in Ossining.NY ra emergency planning. OLSHAN, L. N. Operating Reactors Branch 1. 79/12/07. 3pp.

#### O. Adjudicatory correspondence

- 7912060644 Btatement in support of UCS 790917 patition for decommissioning of Unit 1 & suspension of Units 2 & 3 Ots. Requests institution of proceeding per IOCFR2.202.Affidavit, Certificate of Svc & supporting documentation encl. ABRAMS.R., BIALIK.E.I. New York, State of. 79/11/16, 15pp.
- 7912110038 Confirms receipt of encl 790329 petition to suspend OLs for all PWRs. Forwards FR notice indicating that petition will be treated in accordance w/10GFR2.206.

  DENTON-H.R. Office of Nuclear Reactor Regulation. 79/11/23. 19.
- --7912110126 Notice of request for action pursuant to 10CFR2.206 re Environ Coalition on Nuclear Power 790329 petition requesting suspension of all OLs for PARS. MULLER D.R. Office of Nuclear Reactor Regulation. 79/11/23.
- 7912200270 Forwards statement made in support of UCS patition for decommissioning of Unit 1 & suspension of operation at Units 2 & 3.

  BROWN.P. D. G. Mid-Hudson Nuclear Opponents, Inc. 79/11/27. 1p.
- --7912200274 Statement of PDC Brown in support of UCS patition for proceeding to institute decommissioning of Unit 1 & suspension of operation at Units 2 & 3 pending safety review.
  BROWN.P.D.O. Mid-Hudson Nuclear Opposents, Inc. 79/11/26. Spp.
- 7912040074 Notice of withdrawal from proceedings effective 791130. BHITH B.H. Hearing Branch 2. 79/11/29. 15.
- .79:2040078 Notice of appearance on behalf of MRC.Cartificate of Svc encl. HODRE, J. E. Hearing Branch 2. 79/11/29. Upp.
- 791226036B Requests extension until B0020B to respond to interveners NY State Energy Ofc & Citizens' Committee for Protection of Environ petitions for review of ALAB-436 & ALAB-561 re seismic issues. Certificate of Evc encl. HOORE, J. E. Hearing Branch 2. 79/12/07. App.

- 7912180410 Requests confirmation of 800126 desdiine for NRC response to intervenor UCS 791115 request for action under 10CFR2.206.Also requests meeting to discuss lasues to be used to formulate response.

  WEISS, E. R. Sheldon, Harmon & Weiss. 79/12/10. 1p.
- —79121B0422 Requests that Commission reconsider 770425 decision to refer intervenor UCS 790328 seismic reanalysis petition to staff. Commission must assume jurisdiction since staff has issued no reply to UCS in six months. WEISS.E.R. Union of Concerned Scientists. MEISS.E.R. Bheldon, Harmon & Weiss. 79/12/10. 3pp.
- 7912310078 Three ltrs requesting favorable action on patition to shut down facility.
  ESTEROMITZ.R., KAMIAN.L., BRODESKY.N. Affiliation Unknown.
  79/12/10. 389.
- 7912190239 Order granting extension until B00208 for NRC to respond to NY State Energy Ofc & Citizens Committee for Protection of Environ petitions for review.
  CHILK.S.J. Office of the Secretary of the Commission. 79/12/14.
- 7912310109 Two ltrs requesting favorable action on patition to suspend operations at facility.
  CHINDER.J., KANZAN.L. Affiliation Unknown. 79/12/15. 3pp.
- 7912190107 Forwards 791217 1tr to Commissioner Ahearne re UCS peition on safety & site location issues. FISH.H. Heuse of Rép. 79/12/17. 1p.
- ---7912190114 Requests quict response to UCS petition re resolution of site location & safety issues.
  FIRM.H. House of Rep. 79/12/17. ip.

#### H. General correspondence

- 7912140158 Requests that EJ Sack be deleted from employee list & that JP Davis be added as replacement.
  DAVIS.J.P. Consolidated Edison Co. of New York. 79/11/27. ip.
- P. Operating license stage documents & correspondence
- 7911090248 "Bummary of Operating Experience W/Recirculating Steam Generators." EISEMANT-D.G. Division of Operating Reactors. NUREO-0523. 79/01/31. 69pp.
- 7912050163 Discusses NRC review of LERs & Tech Spec requirements recontrol RPI sys at Westinghouse PMRs. Requests Tech Specs review to ensure requirement for red maint to within +/~ 12 steps indicated & RPI sys verified accurate within 12 steps. SCHEMENCER. A. Deprating Reactors Branch 1. 79/10/29. 7pp.
- 791119014B Forwards "Discussion of TMI Lessons Learned Short-Term Requirements." Revisions to encl implementation schedule for MMREG-057B requirements should be submitted w/justification within 15 days, if schedule requirements cannot be met. DENTON. H. R. Office of Nuclear Reactor Regulation. 79/10/30. 2pp.
- 7912100187 Discusses NRC 791101 meeting w/representatives of N868 vendors & fuel suppliers re discussion of respective partions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. ELBCMMUT.D.G. Division of Operating Resctors. 79/11/09. 65pp.
- -7912100255 Responds to NRC 791101 request re noncompliance of Heatinghouse ECCB evaluation model under requirements of 10CFRSO App K. Evaluation of three fuel rod models indicates no safety problems for Heatinghouse plants. ANDERSON.T. M. Westinghouse Electric Corp. 79/11/02. App.
- ---7912100330 Responds to NRC 791101 request re DRM. cladding swelling & rupture data. Revisu of analytical models & tests indicates compliance w/10CFRSO App K. All GE space for calculated peak cladding tesp remain unchanged.

  BUCHROLZ, R. H. General Electric Co. 79/12/07, 2pp.
- -7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of IOCFR50, 46 satisfied.

  OHSELY, 0.F. Exxon Nuclear Co., Inc., (subs. of Exxon Corp.).
  79/11/02. 5ps.

- --7912100456 Forwards add1 info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results.

  GMBLEY. 0. F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/11/04. 22pp.
- 7912070263 Partially responds to FDIA request for document re Pawling, NY site. Forwards requested info. Submits addl info: sodium deuterium reactor never built at site. no matl ever used at site & no radioactive matl disposed of in lake.

  CARR. J. C. Division of Rules and Records. 79/11/16. 3pp.
- 7912070291 Submits partial response to FDIA request for documents re Nuclear Development Association, United Nuclear Corp. Gulf United Nuclear Corp & ATCOR. Inc. concerning facility site. Forwards requested info. Provides addl info re site. CARR. J. C. Division of Rules and Records. 79/11/16. Spp.
- 7912130284 Forwards epplication for amend to OL changing ETS & required fee. Fee paid under protest.
  CAHILL.H.'J. Consolidated Edison Co. of New York. 79/12/03. 1p.
- --7912130291 Application to amend ETS distinguishing limiting conditions & monitoring requirements, eliminating repetitive specs, reporting requirements & bases & updating ETS rept to reflect present technology.

  CAHILL, M. J. Consolidated Edison Co. of Naw York. EARLY, A. E. Power Authority of the State of New York. 79/12/03. 25pp.
- --7912130306 Revised Pages 1-1 through 5.6-1 of ETB re limiting conditions & monitoring requirements, annual environ operating rept & nonroutine reportable environ occurrences. Affidavit of sec encl.

  \* Consolidated Edison Co. of New York. 79/12/03. 46pp.
- 7912180561 Responds to NRC 791029 ltr re control rod position indication sys. Tech Specs revised to limit rod miselignment & Unit 1 shutdown awaiting decision on ECCS.
  CAHILL, M. J. Consolidated Edison Co. of New York. 79/12/07. ip.
- 7912200415 Notifies of 791218 site visit of NRC Emergency Planning Task Force to evaluate upgrading of emergency planning since TMI accident, Requests participation of NY State Energy Ofc. COLLING. H. E. Assistant Director for Emergency Preparedness, 79/12/07. ip.
- 7912270339 Forwards "Program Plan for Performance Verification of PWR Bafety/Relief Valves & Bys" & supplemental info in response to TMI Lessons Learned Task Force Recommendations 2.1.2. CAHILL, W. J. Consolidated Edison Co. of New York. 79/12/17. 7pp.
- --7912270373 "Program Plan for Performance Verification of PWR Safety/ Relief Valves & Sys." \* Electric Power Research Institute. 79/12/13. 62pp.
- 7912270267 Forwards 791220 conference paper re Indian Point/Zion near site studies. Requests paper be made part of public record. PEOPLES D. L. Commonwealth Edison Co. \* Consolidated Edison Co. of New York. \* Power Authority of the State of New York. 79/12/21. ip.
- ~-7912270275 "Indian Point/Zion Near Bite Studies," presentation to NRC.

  \* Commonwealth Edison Co. \* Consolidated Edison Co. of New York.

  \* Power Authority of the State of New York. 79/12/20. Sipp.
- 7912310181 Informs that no response to NRC 791030 ltr can be provided for Unit 1 since unit shut down in 1974. Presently awaiting decision by company re installation of ECCS. If unit returned to syc.util will respond to NUREO-0578.

  CAHILL.W. J. Consolidated Edison Co. of New York. 79/12/21. ip.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912130215 Responds to IE Bulletin 79-18 Evacuation announcement systems in Dec 1978 reveal several deficiencies which were corrected Audibility testing will be continued annually. CAHILL, M. J. Commonwealth Edison Co. 79/10/15. 2pp.
- 7912170186 Responds to IE Bullatin 79-23, "Potential Failure of Emergency Dissel Generator Field Exciter Transformer."
  Described conditions re connections neutral of generator & neutral of primary windings of EPT not applicable,
  GAHILL, M. J. Consolidated Edison Co. of New York. 79/10/29, 2pp.
- 7912050023 Forwards IE Circular 79-22, "Strake Times for Power Operated Relief Valves," No response required, ORIER, B.H. Region 1, Philadelphia, Office of the Director. 79/11/16, 1p.

- 7912050234 Forwards IE Info Notice 79-27, "Steam Generator Tube Ruptures at Two PMR Plants." No response required. GRIER, B. H. Region 1, Philadelphia. Office of the Director. 79/11/16. 1p.
- 7912100113 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/11/16, 1p.
- 7712110396 Forwards IE Info Notics 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/11/19. 1p.
- 7912050221 Forwards IE Bulletin 79-26, "Boron Loss From BHR Control Blades." No response required. ORIER.B.H. Region 1, Philadelphia, Office of the Director. 79/11/20.
- 7912060966 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No response required.

  ORIER.B.H. Region i, Philadelphia, Office of the Director.
  79/11/26. 10.
- 7912110031 Forwards IE Circular 79-23. "Motor Starters & Contactors Failed to Operata." No response required.
  ORIER.B.H. Region 1. Philadelphia. Office of the Director.
  79/11/26. 1p.
- 7912190018 Forwards IE Builetin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation," Written response required. GRIER, B. H. Region 1, Philadelphia, Office of the Director, 79/11/30. 1p.
- 7912310209 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action required. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/12/06. 1p.
- 7912190734 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Written response required. ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/12/07. 1p.
- 7912280188 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required. GRIER, B.H. Region i, Philadelphia, Office of the Director. 79/12/13. ip.
- R. Periodic operating reports & related correspondence
- 79:12140333 Forwards Nov 1979 data re fish species specified in Section 401 certification to NY State Dept of Environ Conservation. MONTI, M. A. Consolidated Edison Co. of New York. 79/12/10. 17pp.
- 7912170302 Forwards daily records of fish collection for Nov 1979. CAHILL.H.J. Consolidated Edison Co. of New York. 79/12/14. ip.
- ---7912170307 Tabulation of daily records of fish collection for Nov 1979, \* Consolidated Edison Co. of New York. 79/11/30. 5pp.
- U. Congressional/Executive Correspondence
- 7912140528 Concurs w/Kemeny Commission recommendation re emergency evacuation plans for power plant areas. NRC should rule directly on UCB patition to shut down plant. BINGHAM, J. House of Rep. 79/11/14. 1p.
- DOCKET 50-5 PENNSYLVANIA STATE UNIV. RESEARCH REACTOR
  F. Security, medical, emergency & firs protection plans
- 7912120206 Forwards draft Reg Quide 5.XX. "Std Format & Content for Licensee Physical Security Plan for Protection of SNN of Moderate or Low Strategic Significance." W/o encl. REID, R. M. Operating Reactors Branch 4 (Pre 791030). 79/08/22. Zpp.

- DOCKET 50-10 DRESDEN NUCLEAR POWER STATION, UNIT 1

  F. Security, medical, emergency & fire protection plans
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives. Provides guidance for improving licensee emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.

  ORIMES, B.K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- 7912270063 Forwards list of specific items requiring updating in emergency plans. Emergency plans were evaluated using code requirements. Reg. Guide 1.101 & Emergency Planning Review Guidelines Number 1. Revision 1. IPFOLITO.T.A. Operating Reactors Branch 3. 79/11/30. 7pp.
- 7912270088 Ack receipt of 790816 ltr transmitting security personnel training & qualification plan. Requests submittal of Class I & III fees totaling \$4,000.

  MILLER, W. O. License Fee Management Branch. 79/12/10. 1p.

#### H. General correspondence

- 7912280405 Discusses 791204 title change of manager of nuclear operations to vice president Organization structure not altered. Mo revision will be made to GA program topical rept CE-1-A until organization structure is delineated. JAMECEK, R.F. Commonwealth Edison Co. 79/12/19. 1p.
- P. Operating license stage documents & correspondence
- 7912100189 Discusses NRC 791101 meeting w/representatives of NSSS vanders & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EISENAUT.D. 9. Division of Operating Reactors. 79/11/09. 65pp.
- --7912100255 Responds to NRC 791101 request re noncompliance of Westinghouse ECCS evaluation model under requirements of IOCFR50 App K. Evaluation of three fuel rod models indicates no safety problems for Hestinghouse plants.
  ANDERSON, T. M. Westinghouse Electric Corp. 79/11/02. 4pp.
- --7912100330 Responds to NRC 791101 request re GRML cladding swelling & rupture data. Review of analytical models & tests indicates compliance w/iOCFRSO App K. All GE specs for calculated peak cladding tem remain unchanged.

  BUCHHOLZ.R.H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50. 46 satisfied.

  GHGLEY.O.F. Excon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/11/02. 5pp.
- --7912100455 Forwards add1 info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation adde1. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. DMSLEY-G.F. Exion Nuclear Co., Inc. (subs. of Exxon Corp.), 79/11/04, 22pp.
- 7912040261 Forwards plant steam bypass capacity sheets, percent rated. Into provided to GE for incorporation into NEDD-24708. PEOPLES.D.L. Commonwealth Edison Co. 79/11/16. 200pp.
- 7712110017 Forwards updated lists of SEP topics not requiring site review due to ongoing generic licensing activities outside SEP or because of inapplicability to facility.

  ZIEMANN. D. L. Operating Reactors Branch 2. 79/11/16. Opp.
- 7912170157 Forwards evaluation of SEP Topic XVII "Operational GA Program." Naview completed.Assessment incorporates util 781023 suggested mods. ZIEHAMA.D.L. Operating Reactors Branch 2. 79/11/20. 4pp.
- 7912050322 Discusses 791113 & 14 site visit re solid radwaste processing & temporary storage. Facilities have instituted improved waste minimization programs.

  GRANT,P., LD.R. Environmental Evaluation Branch. 79/11/23, 2pp.
- 7912120323 Forwards "Integrated Sphere Loak Rate Test" procedure & "Unit 1 Integrated Leak Rate Test Rept 1977."

  JANECEK, R. F. Commonwealth Edison Co. 79/11/28. 1p.
- ---7912120327 "Integrated Sphere Leak Rate Test" procedure.

  # Commonwealth Edison Co. 77/08/31. 61sp.

- --7912120330 "Unit 1 Leak Rate Test Rept 1977." \* Communuealth Edison Co. 77/12/31. 49pp.
- 7912070417 Comments on encl Fugro. Inc review of LLL/TERA rept re seismic hazard analysis. Variance in export opinion suggests that program output is inaccurate. Questionable areas must be resolved in order for methodology to be useful.

  JANECEK.R.F. Commonwealth Edison Co. 79/11/29, 2pp.
- ---7912070420 "Critique of LLL/TERA Repts on Beismic Hazard Analysis," prepared for Nuclear Sycs Corp. + FURGO Consulting Engineers & Geologists. 79/10/26. 7pp.
- 7912110395 Summary of 791011 meeting w/util re BEP seismic review. iEVIN.H.A. Systematic Evaluation Program Branch. 79/11/29. Bpp.
- 7912310361 Submits requested info on SEP Topic IX-3. "Station Svc & Cooling Water Sys." Total residual heat released during cool down from normal operating temp to 212 F approx 475.3 million BTU.

  JANECEK, R. F. Commonwealth Edison Co. 79/11/29. 6pp.
- 7912040297 Forwards supplementary response to be incorporated into 791018 ltr re lessons learned commitments to meet near-term requirements.
  REED.C. Commonwealth Edison Co. 79/11/30. 7pp.
- 7912040485 Bubmits updated schedules for installation of recirculation pump trip mods per 790329 ltr.
  FEOPLES.D.L. Commonwealth Edison Co. 79/11/30. 2pp.
- 7912070475 Notification of 791206 meeting w/util & Dow Chemical in Bethesda.MD to discuss disposal of solidified wastes in low level waste burial sites.

  O'CONNOR.P. W. Operating Reactors Branch 2. 79/11/30. ip.
- 7712120411 Forwards supplementary response re commitment to meet short-term requirements of Lessons Loarned Task Force. REED.C. Commonwealth Edison Co. 77/11/30. 7pp.
- 7912120425 Forwards supplemental response to 791018 ltr re commitments to Lessons Learned Task Force recommendations. PEOPLES D. L. Commonwealth Edison Co. 79/12/03. 2pp.
- 7912140266 Forwards design drawings re water suppression sys, detection sys & Unit 1 fire pump. Drawings available in Central Files only. Hydraulic calculation info & Fairbanks morse manual describing fire pump oncl.

  JANECEK.R. F. Commonwealth Edison Co. 79/12/04. 2pp.
- 7712210349 Forwards cover sheet for CE-1-A.Revision 10, inadvertently cmitted from 791116 transmittal. NAUGHTON,W.F. Commonwealth Edison Co. 79/12/13. 2pp.
- 7912270469 Forwards response to NRC request for add1 info on THI Lessons Learned Task Force Recommendations 2.1.7a & 2.1.7b. FEOPLES, D. L. Commonwealth Edison Co. 79/12/14. Bpp.
- 7912310348 Forwards revised pages to CE-1-A, "Comm Ed GA Program for Nuclear Generating Stations," Revision 11.
  JANECEK,R.F. Commonwealth Edison Co. 79/12/20. ip.
- --7912310359 Revised pages to CE-1-A, "Comm Ed GA Program for Nucleur Generating Stations," Revision 11, \* Commonwealth Edison Co. CE-1-A, 79/11/21, Jopp.
- G. Inspection reports, IE Bulletins & correspondence
- 7912050013 Forwards IE Insp Repts 50-010/79-19,50-237/79-23 & 50-249/79-21 on 790904-28 & notice of violation, HEISHMANN.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/10/18. 2p.
- ---7912050020 Notice of violation from insp on 790904-28.

  Region 3, Chicago, Office of the Director. 79/10/15. 2pp.
- --7912050037 IE Insp Repts 50-010/79-19.50-237/79-23 & 50-249/79-21 on 790904-28 Noncompliance noted: failure to control access to high radiation areas & failure to follow procedures. BARKER, J. L. MALKER, R. D., SPESBARD, R. L. Region 3, Chicago, Office of the Director. 79/10/15. 9pp.
- 7912050204 Notice of violation from insp on 790904-28.
  \* Region 3. Chicago. Office of the Director. 79/10/15. 2pp.

- 7912070264 Forwards IE Insp Ropt 50-010/79-20 on 791016.No noncompliance noted.

  DAVIS,A.B. Region 3. Chicago. Fuel Facility & Materials Safety Branch. 79/10/25. 2pp.
- --7912070270 IE Insp Rept 50-010/79-20 on 791016.No noncompliance noted. Major areas inspected radwaste mgt & radiation protection for Unit 1 decontamination. FISHER.N.L. HIATT.J.W. Region 3. Chicago, Office of the Director. 79/10/23. 3pp.
- 7912200344 Forwards waste packaging Insp Rept 79-02A on 790925-26. No noncompliance noted.
  SUTHERLAND.J.T. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 79/11/07. 2pp.
- 7912130679 Forwards IE Insp Repts 50-010/79-21,50-237/79-24 & 50-249/79-22 on 791009-12 & 15-18 & notice of violation.
  Insp repts & notice of violation withheld (ref 10CFR2.790).
  HIND, J. A. Region 3, Chicago, Safeguards Branch. 79/11/09, 2pp.
- 7912030106 Forwards IE Circular 79-22. "Stroke Times for Power Operated Relief Valves." No response required. KEPFLER, J. O. Region 3, Chicago, Office of the Director. 79/11/16, io.
- 7912100213 Forwards IE Info Notice 79-28, "Overloading of Structural Elemants Due to Pipe Support Loads." No response required.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912110557 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required.

  KEPPLER. J. C. Region 3. Chicago. Office of the Director. 79/11/16.
- 7912190013 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No written response required. PAPPAS.H. Region 3. Chicago. Office of the Director. 79/11/19. 3pp.
- 791R050350 Forwards IE Bulletin 79-26, "Boron Loss From BWR Control Blades." Response required.

  KEPPLER, J. Q. Region 3, Chicago, Defice of the Director. 79/11/20.
- 7912040009 Ack receipt of 791108 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/79-19, 50-237/79-23 & 50-249/79-21. IESEMMAN.R.F. Region 3. Chicago. Reactor Operations Nuclear Support Branch. 79/11/21. 1p.
- ---7912040011 Responds to NRC 791018 ltr re violations noted in IE Insp Rapts 50-010/79-17,30-237/79-23 & 50-249/79-21. Corrective actions: personnel instructed to lock door to high radiation area. PEOPLES, D. L. Commonwealth Edison Co. 79/11/08. Spp.
- 77:2100417 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on 2HRs." Now itten response required.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/26.
- 7912140187 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No written response required. KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/26.
- 7912110395 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sent by NRC to licensees.

  KEPPLER, J. O. Region 3, Chicago. Office of the Director. 79/11/28.
- 7912190199 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Weitten response required. KEPPLER, J. 9. Region 3, Chicago, Office of the Director. 79/11/30. ip.
- 791214D056 Forwards IE Info Notice 79-30, "Reporting of Defects & Nancompliances, 10CFR21." No action or response required.

  KEPPLER, J. O. Region 3. Chicago, Office of the Director. 79/12/06.

- 7912200086 Forwards IE Bulletin 79-20, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/12/10. ip.
- 7912200443 Notification of 791213 meeting w/util to discuss IE Bulletin 79~02 anchor bolt & base plate analysis.

  JORDAN E. L. Division of Reactor Operations Inspections. 79/12/11.
- R. Pariodic operating reports & related correspondence
- 7912180377 Forwards munthly operating repts for Nov 1979. STEPHENSON.B.B. Commonwealth Edison Co. 79/12/07. 1p.
- --7912180386 Monthly operating repts for Nov 1979. CIESZKIEWICZ.S. Commonwealth Edison Co. 79/12/03. 19pp.
- S. Reportable occurrences, LERs & related correspondence
- 7912120068 PNG-III-79-025: on 791025, essential eves motor generator set tripped, resulting in tripping of Unit 3 reactor Caused by slamming of essential eves electrical panel door. CREED.J. DINAHUE.J.F., HIND.J.A. Region 3. Chicago, Diffice of the Director. 79/10/26. 2pp.
- 7912170166 PNO-III-79-25A: threatening telephone calls came from court-committed patient. All affected licensees notified.
  BELANGER, J., DONAHUE, J. F., HIND, J. A. Region 3, Chicago, Office of the Director. 79/10/29. ip.
- 7912030088 PNO-III-79-031:on 791023.Federal Highway Administration Bureau of Motor Carrier Safety issued notice of shipping violation for improper packaging of low specific activity radioactive matl. Util-fined.
  BARKER, J. L., SPESSARD, R., HEISHMAN, R. F. Region 3, Chicago, Office of the Director. 79/11/01. 1p.
- 7912170390 PND-III-79-038:on 791113; contractor working dutside facility sphere fell 30 ft from scaffolding. Broke back & neck. SPEBSARD.R., HEISHMAN.R.F. Region 3, Chicago, Office of the Director. 79/11/14. 1p.
- 7912270345 Responds to NRC requests for info re loss of offsite power events at facility. Forwards answers to questions re 651112 & 780122 events. LER 78-005/03L-0.780122 deviation rept & list of 345 kV & 138 kV line failures during 1974-1979. JANECEK, R. F. Commonwealth Edison Co. 79/12/19. 21pp.
- BOCKET 50-13 BABCOCK & WILCOX CO. CRITICAL FACILITY

  F. Security, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Guide 5.XX. "Btd Format & Content for Licensee Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance." W/o encl. REID.R.W. Operating Reactors Branch 4 (Pre 791030), 79/08/22, 2pp.
- P. Operating license stage documents & correspondence
- 7912070456 Submits add1 info in support of request for amend to Licenso GX-10. Discusses probability of max credible accident & need for amend to Tech Specs.

  OLSEN.A.F. Babcock & Wilcox Co. 79/12/03. 1p.
- DOCKET 50-20 MASSACHUSETTS INST. OF TECH. RES. REACTOR
  F. Security, medical, emergency & fire protection plans
- 7912120206 Forwards draft Rog Guide 5.XX, "Btd Format & Content for Licensee Physical Becurity Plan for Protection of SNM of Moderate or Low Strategic Significance." W/o encl. REID, R.W. Operating Reactors Branch 4 (Pre 791030), 79/08/22. 2pp.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912040131 Ack receipt of 791015 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-020/79-02.
  GRIER, B. H. Region 1, Philadelphia, Office of the Director, 79/11/06. 1p.

- --7912060146 Responds to NRC 790925 ltr re violations noted in IE Inso Rept 50-020/79-02. Corrective actions: changes will be presented to committee by 791130 & senior review board will conduct overall review. CLARK.L. Massachusetts Institute of Technology. 79/10/15. 2pp.
- --7912060153 Forwards IE Insp Rept 50-020/79-02 on 790829-31 & notice of violation. ORIER.B.H. Region 1. Philadelphia. Office of the Director. 79/09/25. 2pp.
- --7912080161 Notice of violation from insp on 790829-31.

  \* Region 1, Philadelphia, Office of the Director. 79/09/20.
- ---7912060171 IE insp Rept 50-020/79-02 on 790829-31. Noncompliance noted: failure to adhere to radiation protection procedures, to review procedures re requalification & to annually review operator exam results.

  BTETMA.T.F., FOLEY.Y. Region 1. Philadelphia, Office of the Director. MCCABE.E.C. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch. 79/09/20. 9pp.

#### DOCKET 50-27 WASHINGTON STATE UNIV. RESEARCH REACTOR

- F. Security, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Guide 5.XX. "Btd Format & Contant for Licensee Physical Security Plan for Protection of SNH of Moderate or Low Strategic Significance." W/o encl. REID.R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22.
- 7912100267 Forwards changes to security plan. Changes withhold (ref 10CFR2. 790). BRANDS.F. M. Washington State Univ. 79/10/19. 2pp.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912:10095 Forwards IE Insp Rept 50-027/79-02.No noncompliance noted.
  Insp rept withheld tref 100FR2.790).
  NORDERHAUG, L. R. Region 5. San Francisco, Safeguards Branch.
  79/11/13; 2pp.

## DOCKET 50-29 YANKEE-ROME MUCLEAR POWER STATION

- F. Security, medical, emergency & fire protection plans
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives. Provides guidance for improving licensee emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions. ORIMES.B.K., COLLINS.H., SNIEZEK.J. Emergency Preparedness Task Force. 79/11/23. 30pp.
- Q. Adjudicatory correspondence
- 7912110038 Confirms receipt of encl 790329 patition to suspend OLs for all PHRs.Forwards FR notice indicating that patition will be treated in accordance w/10CFR2 206. DENTON.H.R. Office of Nuclear Reactor Regulation. 79/11/23. ip.
- --7912110126 Notice of request for action pursuant to 10CFR2.206 re Environ Costition on Nuclear Power 790329 petition requesting suspension of all OLs for PHRs. MALLER, D. R. Office of Nuclear Reactor Regulation. 79/11/23. 30pp.
- P. Operating license stage documents & correspondence
- 7708010337 Notifies of status of rept on reactor cavity annulus seal. Most PMR users remove ring during normal operation. Others store seal ring in raised position during normal operation. LAINAS, C. Plant Systems Branch (Pre 791030). 79/07/05. 7pp.
- 7912050201 Discusses NRC review of LERs & Tech Spec requirements recontrol RPI sys at Mestinghouse PWRs. Requests Tech Specs review to ensure requirement for red saint & RPI sys varified accurate within 12 steps.

  ZIEMANN.D.L. Operating Reactors Branch 1, 79/10/29, 7pp.
- 7912140370 Provides info on adequacy of electric distribution sysvoltage Discusses mature of potential problem. GROCE:R.H. Yankee Atomic Electric Co. 79/11/01. 3pp.

- 79:2100:189 Discusses NRC 79:101 meeting w/representatives of NSSS vendors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. RIBENHUT.D.O. Division of Operating Reactors. 79/11/09. 65pp.
- --7912100295 Responds to NRC 791101 request re noncompliance of Westinghouse ECCB evaluation model under requirements of 10CFRSO App K. Evaluation of three fuel rod models indicates no aafety problems for Westinghouse plants. ANDERSON. T. M. Westinghouse Electric Corp. 79/11/02. 4pp.
- ---7912100330 Responds to NRC 791101 request re DRNL cladding swelling & rupture data. Review of analytical models & tests indicates compliance w/1002R50 App K.All QE specs for calculated peak cladding temp remain unchanged.
  RUCHROLZ.R.H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod hurst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of iOCFR50.46 satisfied.
  DMELEY,0.F. Exzon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/02. Spp.
- --7912100456 Forwards add1 info re evaluation of impact of NRC proposed rupture/blockage model used in vandor evaluation model. No advarse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. OMSLEY.Q.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/04. 22pp.
- 7912170084 Forwards requirements for auxiliary feedwater sys. EIBEMHUT, D.C. Assistant Director for Operating Reactor Projects (Pre 791030). 79/11/09. 3pp.
- ---7912170087 Operating procedure for auxiliary feedwater sys.

  \* Assistant Director for Operating Reactor Projects (Pre 791030).
  79/11/09. 22pp.
- 7912030098 Notification of 791115 meeting w/util in Bethesda, MD to discuss asymmetric LOCA loads issue. MDSFORD, 8. B. Division of Operating Reactors. 79/11/14. ip.
- 7912110033 Forwards updated lists of SEP topics not requiring site review due to ongoing generic licensing activities outside SEP or because of inapplicability to facility.

  ZIEMANN, D. L. Operating Reactors Branch 2. 79/11/16. Bpp.
- 7912030175 Requests that NRC provide requirements for cost burden comparison of proposed asymmetric LOCA loads. Util will institute inservice insp program to minimize time required to reach decision re plant mod implementation.

  ORDCE.R.H. Yankee Atomic Electric Co. 79/11/19. 2pp.
- 7912170192 Forwards evaluation of SEP Topic XVII "Operational QA Program." Review completed Assessment incoporates util 781020 suggested mods. ZIEMANN.D.L. Operating Reactors Branch 2. 79/11/20. 2pp.
- 7912060175 Bummary of 791108 meeting w/util in Bethesda.MD re adequacy of electric distribution sys voltages.
  BURGER.A. Operating Reactors Branch 2. 79/11/21. 4pp.
- 7912170411 Bummary of 790920 meeting w/util in Bethesda, MD re BEP review topics concerning hydrologic description, flooding patential & protection requirements, safety-related water supply & dam integrity.

  LEVIN, H. A. Bystomatic Evaluation Program Branch. 79/11/27. 4pp.
- 79(2040208 Forwards Figure 1 as horizontal seismic response spectra. Datailed rept for site dependent response spectra will be forwarded suon.

  GROCE-R.H. Vankes Atomic Electric Co. 79/11/29. 6pp.
- 7912040348 Comments on NUREQ-0577. "Potential for Low Fracture Toughness & Lamellar Testing on PHR Steam Generator & Reactor Coolant Pump Supports." Hatt test rapts for steam generator base matl encl.

  200-HOFFMAN.J.R. Yankes Atomic Electric Co. 79/11/29. 1p.
- --7912040352 Matl test rapt for steam generator base matl. # Goslin-Birmingham Mfg. Go. 70/05/01. ip.
- 7912110314 Informs of voltage regulators to be installed by 791208 to correct potential undervoltage problem. Requests extension until mid-Jan 1980 to make voltage regulator final ties to avoid outage k minimize thermal stresses.

  MOGDY, D. E. Vankee Atomic Electric Co. 79/12/03. 2pp.

- 7912190783 Summarizes NRC Lessons Learned Implementation Team 791018 telcon w/util re response to NRC 790913 ltr.Forwards list of items not meeting schedule & list of items needing clarification.

  BURDER, A. Operating Reactors Branch 2. 79/12/03. Sop.
- BURGENIA. Operating Reactors Branch 2. 79/12/03. Opp
- 791221015B Forwards loss of offsite power survey.Response requested within 90 days.

  ZIEMANN.D.i.. Operating Reactors Branch 2. 79/12/04. 3pp.
- 7912120299 Changes util 791203 ltr re installation of voltage regulators by removing 24-h requirement for plant trip. MODDY.D.E. Vankee Atomic Electric Co. 79/12/06. 1p.
- 7912130230 Responds to 791206 telcon to clarify util 791119 ltr which included addl NRC requirement. Attachment reaffirms commitment to increased scope of short-term requirements of Lessons Learned Task Force.

  HOODY.D.E. Yankee Atomic Electric Co. 79/12/07. 3pp.
- 7912180611 Clarifies 791107 response to NRC 790912 ltr re steam generator water hammers No water hammer experience since plant 1966 mod. MODDY.D.E. Yankee Atomic Electric Co. 79/12/07. lp.
- 7912270030 Discusses future info needs to facilitate epidemiologic studies of health effects of low level exposure to ionizing radiation. Contractor is Equifax.

  ZIEMANN.D.L. Operating Reactors Branch 2, 79/12/07. 2pp.
- 7912200551 Forwards evaluation of draft NUREG 0.630, "Cladding, Bwelling & Rupture Models for LOCA Analysis." Recommends experimental program not be limited in scope of temp & pressure conditions, but focus on test matrix for LOCA model. VANDENBURGH. D. Yankee Atomic Electric Co. 79/12/10. Spp.
- ---7912200856 "Technical Evaluation of Draft NURE9-0630."
  \* Yankee Atomic Electric Co. 79/12/10. 16pp.
- 7912180150 Notifies that util no longer takes exception to Item 2.2.2b in util 791207 ltr. Description of on-site technical support ctr will be submitted by 800301.

  KAY. J. A. Yankee Atomic Electric Co. 79/12/14. ip.
- 7912180155 Commits to full requirements & schedules of Lessons Learned Task Force short-term requirements w/exception of items having difficulty w/equipment procurement Provides schedule for implementing exception items. Shutdown commencing 800119. KAY, J. A. Yankes Atomic Electric Co. 79/12/14. 2pp.
- 7912270454 Bubmits info re THI Lessons Learned Task Force short-term requirements, in response to NRC 791210 request Bracifically discusses auxiliary feedwater flow indication, testability, power supply & indication accuracy.

  KAY, J. A. Yankee Atomic Electric Co. 79/12/14. 5pp.
- 7912270203 Discusses review of waste gas/cover gas sys ability to limit noble gas release w/o use of three gas decay drums. Noble gases have not exceeded dose objectives of 10CFR50. App I. Bys can keep offsite doses within objectives.

  KAY, J. A. Yankes Atomic Electric Co. 79/12/17. 5pp.
- 7912270532 Forwards response to NRC requirements for auxiliary feedwater sys re NUREO-0578 & NUREO-0585. Intent of NRC requirements are met or exceeded by design changes at facility.

  MODDY, D. E. Yankee Atomic Electric Co: 79/12/21. 15pp.
- 7912310556 Reiterates that steam generator water hammer not experienced at facility subsequent to 1966 mods.; HOODY, D. E. Yankee Atomic Electric Co. 79/12/21. 1p.
- 4. Inspection reports, IE Bulletins & correspondence
- 7912120218 Responds to IE Bulletin 79-24 Facility uses electrical heat trace, steam heating or flow & insulation to prevent lines from freezing.

  ORDGE,R.H. Vankee Atomic Electric Co. 79/10/10. 1p.
- 7912140252 Responds to IE Bulletin 79-02. "Pips Support Rase Plate Designs Using Concrete Expansion Anchor Boits." Test progrem instituted to assure proper installation of expansion anchor buits.

  GRACE.R.H. Yankee Atomic Electric Co. 79/10/31. 2pp.
- 7912060177 Ack receipt of 791016 lir informing NRC of steps taken to correct violations noted in IE Insp Ript 50-029/79-08. SMITH.0.H. Region 1. Philadelphia, Fuel Facility & Materials Safety Branch. 79/11/06, ip.

- --7912050185 Responds to NRC 790920 Itr re violations noted in IE Insp Rept 50-029/79-08. Corrective actions: individuals reinstructed in proper wearing of dosimetry & extensive review begun. HODDY.D.E. Yankee Atomic Electric Co. 79/10/16. 4pp.
- ---7912060189 Forwards IE Insp Rept 50-029/79-08 on 790709-12 & notice of violation. BMITH.G.H. Region 1. Philadelphia. Fuel Facility & Materials Bafety Branch. 79/09/20. 2pp.
- --7912060193 Notice of violation from insp on 790709-12.

  \* Region i, Philadelphia, Office of the Director. 79/09/17.
  2pp.
- --7912060201 IE Insp Rept 50-029/79-0B on 790709-12. Noncompliance noted: improper wearing of dosimeters, errors in dosimetry records & radwaste transfer in unauthorized form.
  PLUMLEC.K. Region 1. Philadelphia, Office of the Director.
  BTOMR.J.P. Region 1. Philadelphia, Fuel Facility & Materials Bafety Branch. 79/09/17. 10pp.
- 7912260301 Forwards IE Insp Rept 50-029/79-11 on 791017-19.No noncompliance noted. BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/11/08. 2pp.
- --7912260302 IE Insp Rept 50-029/79-11 on 791017-19. No noncompliance noted Major areas inspected plant operations & areas applicable to selected LERs & IE bulletins.

  KEIMIQ.R.R. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch LAZARUS.W.J. Region 1, Philadelphia, Office of the Director. 79/11/07. 7pp.
- 7712130076 Provides supplemental response to IE Bulletin 79-14.
  "Beismic Analysis For As-Built Safety-Related Piping."
  Program initiated to assure that all 2.5 inch & larger
  pipes meet deskyn requirements.
  GROCE,R.H. Yankee Atomic Electric Co. 79/11/14. 2pp.
- 7912050067 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required.
  ORIER.B.H. Region 1. Philadelphia, Office of the Director.
  79/11/16. 1p.
- 7912050311 Forwards IE Info Notice 79-27, "Staum Generator Tube Ruptures at Two PHR Plants." No response required. ORIER.8.H. Region 1, Philadelphia. Office of the Director. 79/11/16. 1p.
- 7912100157 Formards IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads." No response required. ORIER.8.H. Region 1. Philadelphia. Office of the Director. 79/11/16. 1p.
- 7912200474 Ack receipt of 791015 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-029/79-07.
  MARTIN.W.O. Region 1. Philadelphia, Safeguarda Branch. 79/11/16.
- --7912200475 Forwards IE Inap Rept 50-029/79-07 on 790709-13 & notice of violation. Notice of violation withheld (ref 10CFR2, 790.) MARTIN. H. O. Region 1. Philadelphia. Safeguards Branch. 79/09/20. 2pp.
- ---7912200478 IE Insp Rept 50-029/77-07 on 790709-13. Noncompliance noted: infraction to communication & deficiency in records & repts. Details withheld (ref 10CFR2.790.)

  DEVLIN.J. Region 1. Philadelphia. Safeguards Branch.
  BAILEY.R.J., JONES.E.N. Region 1. Philadelphia, Office of the Director. 79/09/07. 1p.
- 7912110490 Forwards IE Info Notice 79-29. "Loss of Nonsafety-Related Reactor Coulant Bys Instrumentation During Operation." No specific action or response required. ORIER, B.H. Region 1. Philadalphia. Office of the Director. 79/11/19. 1p.
- 7912050337 Forwards IE Bulletin 79-26, "Boron Loss From BMR Control Blades." No response required. ORIER, B.H. Region 1, Philadelphia, Office of the Director. 79/11/20, ip.
- 7912060600 Forwards IE Circular 79-24, "Proper Installation & Calibr of Gore Spray Pipe Break Detection Equipment on BHRs." No response required.
  ORIER, B.H. Region 1, Philadelphia, Office of the Director.
  79/11/26. 1p.

- 7912110096 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Dperate." No response required. CRIER, B.H. Region 1. Philadelphia, Office of the Director. 79/11/26. 1p.
- 7912210022 Outlines NRC understanding of status of IE Bulletin 79-14 re seismic analysis for as-built safety-related piping. Requests prompt notification if situation differs. CRIER, D. H. Region 1. Philadelphia. Office of the Director. 79/11/28. 2pp.
- 7912170097 Forwards IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Gys Bus During Operation." Written response required. GRIER.D.H. Region 1. Philadelphia. Office of the Director. 79/11/30. ip.
- 7912310254 Forwards IE Info Notice 79-30, "Reporting of Defects & Moncompliances, 10CFR21." No action required.
  GRIER/B.H. Region i, Philadelphia, Office of the Director.
  79/12/06. 4pp.
- 7912190772 Forwards IE Bulletin 79-28. "Possible Halfunction of Namco Mudel EA180 Limit Switches at Elevated Temps." Written response required. GRIER.B.H. Region 1. Philadelphia. Office of the Director. 79/12/07. ip.
- 7912280282 Forwards IE info Notice 79-31. "Use of Incorrect Amplified Response Spectra." No written response required. GRIER.B.H. Region i, Philadelphia. Office of the Director. 79/12/13. ip.
- H. Periodic operating reports & related correspondence
- 7912180341 Forwards monthly operating rept for Nov 1979. MODDY, D. E. Yantee Atomic Electric Co. 79/12/12. 1p.
- --7912180345 Monthly operating rept for Nov 1979. SUCOREN, R. M. Yankee Atomic Electric Go. 79/12/12. Spp.
- 6. Reportable occurrences, LERs & related correspondence
- 7912060662 PND-I-79-013: on 791026, computer study indicated that if LOCA occurs during startup mode, w/four main coolant pumps operating, possibility of safeguards bus voltage degradation exists. Interim corrective actions under review.

  LAZARUS, M. . MARTIN, T. T. BRUNNER, E. J. Region 1, Philadelphia, Office of the Director. 79/10/26. ip.
- 7912070437 Forwards LER 79-027/03L-0. AUTIO.H.A. Yantes Atomic Electric Co. 79/12/04. lp.
- --7912070444 LER 79-027/03L-0: on 791105, during plant stortup in Hode 3, post-accident hydrogen control sys HV-80V-1 & 2 failed to seat properly, Caused by oil & dirt buildup on valva internals, Valves cleaned, retested & returned to svc. FRENCH, L. D. Yankee Atomic Electric Co. 79/12/05. ip.
- 7912100292 Forwards LER 79-028/03L-0.
  AUTIO, H. A. Yankse Atomic Electric Co. 79/12/05. ip.
- --- 7912100296 LER 79-028/03L-0: on 791103, timing test not performed after repair of containment isolation valve. Caused by personnel error. Importance of using proper procedures pointed out to appropriate personnel.

  MAY.E.L. Yankes Atomic Electric Co. 79/12/05. ip.
- 7912110287 Forwards LER 79-029/03L-0. AUTIO.H. A. Yankeo Atomic Electric Co. 79/12/06. ip.
- --7912110290 LER 79-029/03L-0: on 791106 during testing of gost-accident hydrogen venting sqs:NV-80V-1 & 2 failed to meat properly. Caused by oil & dirt buildup on valve internals. Valves cleaned, imapected & returned to svc. FRENCH, L. D. Yankee Atomic Electric Co. 79/12/06. 1p.
- 7912110291 Forwards LER 79-030/03L-0.
  AUT10.H.A. Yankee Atomic Electric Co. 79/12/07. 1p.
- --7912110293 LER 79-030/03L-0; an 791109, during safety injection accumulator time delay verification procedure OP-4630, TDC4 setpoint discovered to be beyond Tech Spec Limit Cause under investigation. Temporarily replaced time delay relay.

  HAY, E. L. Yankee Atomic Electric Cd. 79/12/07. 1s.

- DOCKET 50-54 UNION CARBIDE RESEARCH REACTOR
- F. Security, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Quide 5.XX. "Std Format & Content For Licensee Physical Security Plan for Protection of SNN of Moderate or Low Strategic Significance." W/o encl. REID.R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22.
- G. Inspection reports, IE Bulletins & correspondence
- 7912260084 Ack receipt of 791025 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-054/79-03 & 70-0687/79-01.
  MARTIN.W. Q. Region 1. Philadelphia. Safeguards Branch. 79/11/19.
- --79122600hi Responds to NRC 790919 ltr re violations noted in IE Insp Repts 50-054/79-03 & 70-0687/79-01. Corrective actions: increasing mpt control of training program & schedule of audits promitgated. MCODVERN.J.J. Union Carbide Corp. 79/10/25. 1p.
- --7912260068 Forwards IE Insp Repts 50-054/79-03 & 70-0687/79-01 on 790424-27 & notice of violation. Notice of violation withheld (ref 10CFR2.790).
  MARTIN.W. Q. Region i, Philadelphia, Safeguards Branch. 79/09/19. 2pp.
- --7912260074 IE Insp Repts 50-054/79-03 & 70-0687/79-01 on 790424-27. Noncompliance noted:failure to perform required training of personnel Details of insp withheld (ref 100FR2.790). HOLDDY, D.J., ZIBULSKY, H. Region 1. Philadelphia, Diffice of the Director. JOYNER, J. H. Region i, Philadelphia, Safeguards Branch. 79/08/20. ip.
- DOCKET 50-57 STATE UNIV. OF NEW YORK RESEARCH REACTOR
- F. Becurity, medical, emergency & fire protection plans
- 7912120204 Forwards droft Reg Guide 5.XX. "Btd Format & Content for Licensee Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance." W/o encl. REID.R.W. Operating Reactors Granch 4 (Pre 791030). 79/08/22.
- Q. Inspection reports. IE Dulletins & correspondence
- 7912120141 Ack receipt of 790924 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-057/79-01.
  GMTTH.O.H. Region i, Philadelphia, Fuel Fecility & Materials Safety Branch. 79/10/17. ip.
- ---7912120144 Responds to NRC 790612 ltr re violations noted in IE Insp Rept 50-057/79-01. Corrective actions: campus security police instructed in safety procedures & copy of 100FR20 posted at reactor bridge access. CHON.W.Y. New York, State Univ. of, Buffalo. 79/09/24. 2pp.
- --7912120147 Forwards IE Insp Rept 30-057/79-01 on 790226-28 % notice of violation.
  SMITH-9. H. Region 1. Philadelphia, Fuel Fecility & Materials Safety Branch. 79/06/12. 2pp.
- --7912120149 Notice of violation from insp on 790224-28.

  \* Region i, Philadelphia, Office of the Director. 79/06/06.

  1p.
- ---7912120158 IE Insp Rept 50-057/79-01 on 790226-28 Noncompliance noted; failure to provide notice to radiation workers & to post radiation areas.

  DONALDSON, D. . STOMR, J. P. Region 1, Philadelphia, Office of the Director. 79/06/06, 10pp.
- DOCKET 50-59 TEXAS ASM UNIV. RESEARCH REACTOR
- F. Becurity, medical, pmorgoncy & fire protection plans
- 7912120306 Forwards draft Rag Quido 5.XX, "9td Forsat & Content for Licensee Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance." W/o encl. REID.R.W. Operating Roactors Branch 4 (Pre 791030). 79/08/22, 200.

## J. Insurance & indomnity information

7912100303 Forwards executed Amend 15 to Indomnity Agreement E-12 modifying prefatory language, "in course of transportation." FENNER, E. H. Texas A & M Univ. 79/12/03. 2pp.

## DOCKET 50-62 UNIV. OF VIRGINIA RESEARCH REACTOR

- F. Security, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Quide 5.XX. "Std Format & Content for Licensee Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance." W/o encl. REID.R. H. Operating Reactors Branch 4 (Pre 791030). 79/08/22. 2pp.

## G. Inspection reports, IE Bulletins & correspondence

- 7912210034 Ack receipt of 791116 ltr informing NRC of steps taken to correct violation & deviation noted in IE Insp Rept 50-062/79-02.
  SUTHERLAND, J.T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/12/12
- ---7912210038 Responds to NRC 791024 ltr re violations noted in IE Insp Rept 30-062/79-02, Corrective actions: door to possible high radiation area locked. Pocket dosimeters response & leak tested. BHRIVER.B.N. Virginia, Univ. of. 79/11/16. Rpp.
- ---7912210043 Forwards IE Insp Rept 50-062/79-02 on 790910-21 & notices of violation & deviation.
  BUTHERLAND.J.T. Region 2. Atlants. Fuel Facility & Materials Bafety Branch. 79/10/24. 2pp.
- --7912210046 Notice of violation from insp on 790918-21.

  \* Region 2, Atlanta, Office of the Director. 79/10/24. 1p.
- --7912210048 Notice of deviation from insp on 790918-21,
  w Region 2, Atlanta, Office of the Director. 79/12/04. ip.
- ---7912210191 IE Insp Rept 50-062/79-02 on 790918-21. Noncompliance noted: failure to lock high radiation area & failure to source & leak test pocket dosimetero.

  EWALD.B.C., WRAY.J.R. Region 2, Atlanta, Office of the Director.
  OISBON.A.F. Region 2, Atlanta; Fuel Facility & Materials
  Bafety Branch. 79/10/23. 7pp.

## DOCKET 50-70 GENERAL ELECTRIC TEST REACTOR

- F. Becurity, medical, emergency & fire protection plans
- 7912120205 Forwards draft Reg Guide 5, XX. "Std Format & Content for Licensee Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance." W/o encl. REID.R.W. Operating Resctore Branch 4 (Pre 791090). 79/08/22. 2pp.

## 9. Adjudicatory correspondence

- 7912170004 Forwards NRC reply to GE request for expeditious review of EIS for GETS.
  HENDRIE, J. M. Commission. 79/09/07. 3pp.
- ---7912170007 Huggests NRC ignore OE request that EIS be expedited OE info re GETR is unroliable Hafety evaluation should be carefully considered. BALDWIN M.A. Friends of the Earth. 79/06/06. Upp.
- 7912170013 Forwards order to show cause for shutdown & schedule for completion of OETR seismic review ASLB ruling expected 791024.
  HENDRIE J. M. Commission. 79/09/07. 7pp.
- ---7912170017 Requests expeditious review of facility & issuance of safety avaluation. Mads made according to more conservative design bases. Bafety evaluation completion dates have repeatedly slipped.

  BEATON, R. H. General Electric Cn. 79/05/31. 3pp.
- 7912070236 Request for interlocutory appeal from ASLE 791010 memorandum torder re denial of RV Dellums request to participate in proceedings to be represented by staff members not admitted to practice before federal or state bers. DELLUMB.R.V. House of Rep. 79/10/R6. 3gp.

- 7912130103 Smets denial of intervenor RV Bellums 791026 request to certify interlocutory appeal re portions of ABLB 791009 order. Intervenor failed to show rulings are adverse to public interest or create unsural delay or expense.
  BHANBON.D.T. Heering Branch 1. 79/11/16. 9pp.
- P. Operating license stage documents & correspondence
- 7912140243 Forwards info in response to NRC 790214 request for add1 info re request for rovision to Tech Specs for Licenso TR+1. Tech Specs mods encl. CUMNINGHAM.G.E. General Electric Co. 79/12/10. ip.
- --7912140365 Forwards supplemental info to 780116 application re License TR-1. Revisions to Tech Specs included.

  DARMITZEL, R. W. General Electric Co. 79/12/11. ilpp.
- Q. Inspection reports. IE Bulletins & correspondence
- 7912280375 Forwards IE Insp Repts 50-070/79-03 & 50-073/79-02 on 791107-09 & notice of deviation. Encls withheld (ref 10CFR2.790).

  NORDERHAUG, L. R. Region 5. San Francisco. Safeguards Branch. 79/12/12. 200.

## DOCKET 50-72 UNIV. OF UTAH RESEARCH REACTOR

- F. Security, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Quide 5.XX, "Btd Format & Content for Liconsee Physical Security Plan for Protection of SNM of Moderate or Low Strategic Bignificance." W/a encl. REID.R.W. Operating Reactors Branch 4 (Pre 771030). 79/08/22. Rpp.

#### DOGKET 50-73 GENERAL ELECTRIC NUCLEAR TEST REACTOR

- F. Security, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Quide 5.XX. "Btd Format & Content for Licensee Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance." W/o encl. REID, R. W. Operating Reactors Branch 4 (Pre 791030). 79/08/22.
- P. Operating license stage documents & correspondence
- 7912R70017 Ack receipt of 79060B ltr transmitting revised requalification program for GETR Program approved. COLLINS.P.F. Operator Licensing Branch. 79/12/10. 2pp.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912280375 Forwards IE Insp Repts 50-070/79-03 & 50-073/79-02 on 791107-09 & notice of deviation Encls withheld (ref 10CFR2.790).
  NRNDERHAUGL. R. Region 5, San Francisco, Safeguards Branch.
  79/12/12. 2pp.
- DOCKET 50-77 CATHOLIC UNIV. OF AMERICA RESEARCH SEACTOR
  F. Security, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Guide 5.XX. "Std Format & Content for Licenses Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance." W/o encl. REID, R. W. Operating Reactors Stanch 4 (Pre 791030). 79/08/22.

## DOCKET 50-89 UNIV. OF FLORIDA TRAINING REACTOR

- F. Security, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Guide 5, XX. "Btd Format & Content for Licensee Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance." W/o ancl. REID.R.W. Operating Reactors Stranch 4 (Pr

- P. Operating license stage documents & correspondence
- 7912260188 Discusses review of revised requalification program.
  Provision should be included for operator avaluation.
  COLLINS.F.F. Operator Licensing Branch. 79/11/26. 1p.
- Q. Inspection reports. IE Bulletins & correspondence
- 7912210052 Ack receipt of 791130 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-083/79-02.
  LENIS.R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/12/11. lp.
- --791221003B Responds to NRC 791120 ltr re violations noted in IE Insp. Rept 80-083/79-02. Corrective actions: started meeting agenda & approval of minutes of previous meeting & in-depth review performed for 1978.

  DIAZ.N. J. Florida, Univ. of. Qainesville. 79/11/30. 2pp.
- --7912210061 Forwards IE Insp Rept 50-083/79-02 on 791022-25 & notice of violation. LEMIB.R.C. Region 2, Atlanta. Reactor Operations Nuclear Bupport Branch. 79/11/20. 2pp.
- --7912210063 Natice of violation from insp on 791022-25.
  \* Region 2. Atlanta. Office of the Director. 79/11/20. ip.
- --7912210069 IE Insp Rept 50-083/79-02 on 791022-25. Noncompliance noted: failure to make written records of monthly meetings & failure to make intensive review of facility operations during 1977.

  JULIAN.C. Region 2, Atlanta, Office of the Director.

  BURNETT.P.T. Region 2, Atlanta, Reactor Operations Nuclear Gupport Branch. 79/11/20. App.

## DUCKET SO-07 WESTINGHOUSE CRITICAL EXPERIMENT

- F. Becurity, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Guide 5.XX, "Std Format & Content for Licenses Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance." W/o encl. REID:R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22. Zon.
- P. Operating license stage documents & correspondence
- 7912070341 Requests 2-yr deferral for nonpower reactor licensees to comply w/upgrade rule. Training reactor will not operate as Category i safeguards facility. Description & Functions of training reactor & upgrade rule options entl.
  ROTH, J. M. Hestinghouse Electric Corp. 79/11/19. 5pp.

## DOCKET 50-89 GENERAL ATOMIC CO.

- F. Security, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Guide 5.XX. "Bid Format'& Content for Licensee Physical Security Plan for Protection of SNM of Moderate or Lou Strategic Significance." W/o encl. REID:R. W. Operating Reactors Branch 4 (Pre 791030). 79/08/22. 2pp.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912070179 Forwards IE Insp Repts 50-089/79-02 & 50-163/79-02 on 790912-14. No noncompliance noted. OREMS, J. L. Region 5. San Francisco, Reactor Operations Nuclear Support Branch. 79/10/19. 2pp.
- --7912070198 IE Insp. Repts 50-089/79-02 & 50-163/79-02 on 790912-14. No noncompliance noted Major areas inspected organization.logs & records.review & audit, procedures & reportable events. FAULKENBERRY, D. Region 5, Ban Francisco. Reactor Operations Nuclear Support Branch. JOHNSON, A. D., MORRILL, P. J. Region 5, San Francisco, Office of the Director. 79/10/19. App.
- DOCKET 50-94 ROCKHELL INTERNATIONAL REBEARCH REACTOR
- Q. Inspection reports, IE Bulletins & correspondence
- 7912050691 Forwards 1E Insp Rept 50-074/79-01 on 790904-06.No noncompliance noted. BOOK.H.E. Region 5. San Francisco. Fuel Facility & Materials Safety Branch. 79/10/16. 2pp.

--7912050693 IE Insp Rept 50-094/79-01 on 790904-06.No noncompliance noted Major areas inspected physical status & timetable redismantling plan for reactor.

SOOK.H.E. Region 5, San Francisco, Fuel Facility & Materials Safety Branch. CURTIS.J.R. Region 5, San Francisco, Office of the Director. 79/10/16. 2pp.

## DOCKET 50-97 CORNELL UNIV. ZERO POWER REACTOR

- F. Becurity, medical, emergency & fire protection plans
- 79:2120204 Forwards draft Reg Ouide 5.XX. "Std Format & Content for Licensee Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance." W/o encl. REID.R.M. Operating Reactors Branch 4 (Pre 791030). 79/08/22. 200.
- J. Insurance & indemnity information
- 79:12:100:335 Forwards executed Amend 12 to Indemnity Agreement E-4 to modify prefatory language. "in course of transportation." VERBAGE.P. A. Cornell Univ. 79/12/03. 2pp.

## DOCKET 50-98 UNIV. OF DELAWARE RESEARCH REACTOR

- F. Security, medical, emergency & fire protection plans
- 7712120206 Forwards draft Reg Quide 5. XX. "Std Format & Content for Licensee Physical Security Plan for Protection of BNH of Moderate or Low Strategic Significance." W/o encl. REID.R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22. 2pp.

## DOCKET 50-99 BABCOCK & WILCOX TEST REACTOR

- F. Security, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Quide S.XX. "8td Format & Content for Licensee Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance." W/o encl. REID:R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22. 20p.

## DOCKET 50-106 DREGON BYATE UNIV.

- F. Security, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Quide 5.XX. "Btd Format & Content for Licensee Physical Security Plan for Protection of BNM of Moderate or Low Strategic Significance." W/a encl. REID.R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22. 2pp.
- DOCKET 50-111 NORTH GAROLINA STATE UNIV. RESEARCH REACTOR
- F. Security, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Ouide 5.XX, "Btd Format & Content for Licenses Physical Security Plan for Protection of SNM of Moderate or Low Strategic Bignificance." W/o encl. REID.R.W. Decrating Reactors Branch 4 (Fre 791030). 79/08/22. Zpp.
- P. Operating license stage documents & correspondence
- 7912130432 Modifies request for extension of License R-63 to change expiration date to B30219 & to discontinue area & stack monitors, daily air samples & weekly smear survey. BAXE.R.F. North Carolina State Univ. 79/12/07.
- DOCKET 50-112 UNIV. OF DKLAHOMA RESEARCH REACTOR
- F. Becurity, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Quide 5.XX, "Btd Format & Content for Licensee Physical Becurity Plan for Protection of SNM of Moderate or Low Strategic Significance." W/o encl. REID,R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22.

## DOCKET 50-119 UNIV. OF ARIZONA RESEARCH REACTOR

## F. Becurity, medical, emergency & fire protection plans

7912120206 Forwards draft Reg Guide 5.XX, "Btd Format & Content for Licensee Physical Security Plan for Protection of BNM of Moderate or Low Btrategic Bignificance." W/o encl. REID.R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22.

## DOCKET 50-114 IOWA STATE UNIV. RESEARCH REACTOR

## F. Security, medical, emergency & fire protection plans

7912120206 Forwards draft Reg Ouide 5.XX. "8td Format & Content for Licensee Physical Becurity Plan for Protection of SNM of Moderate or Low Strategic Significance." W/o encl. REID.R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22.

#### DOCKET 50-123 UNIV. OF MISSOURI RESEARCH REACTOR

## F. Security, medical, emergency & fire protection plans

79:2120206 Forwards draft Reg Quide 5.XX, "Btd Format & Content for Licensee Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance." W/o encl. REID:R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22.

7912200364 Forwards Physical Security plan. Plan withheld (ref 10GFR2.790). EDMARDS: D. R. Missouri, Univ. of, Rolla, 79/12/14. 1p.

## P. Operating license stage documents & correspondence

7912070459 Application for renewal of License R-79 for 10 yrs. Complete set of supporting documentation will be forwarded by 791220.

MARCHELLO, J. M. Missouri, Univ. of, Rolla, 79/10/15. 2pp.

79:2040267 Confirms that license renewal application will be completed by 79:217.All documentation is complete except for revision of Tech Specs.
EDWARDS,D.R. Missouri, Univ. of, Rolla. 79/11/27. ip.

7912200452 Forwards Tech Specs, hexard analysis, emergency preparedness plans, financial liability statement & EIA in support of license ranswal application for License R-79. Becurity plan withheld (ref 10CFR2. 790).
EDMARDS, D. R. Missouri, Univ. of, Rolla. 79/12/14. 1p.

--7912200458 Forwards financial statement in support of renswal of License R-79, Current operating budget for FY79-80 encl. MARCHELLO, J. M. Missouri, Univ. of, Rolla. 79/12/14. 11pp.

--7912200460 Emergency Preparedness Plans. # Missouri, Univ. of Rolls. 79/10/31. 48pp.

\* Missoury, Oliv. Ot. Kolia. /7/10/01. 4044.

---7912200463 Tech Specs.

\* Missouri, Univ. of, Rolla. 79/12/11. 22pp.

---7912200465 Hazard Analysis Bummary Rept. \* Missouri, Univ. of, Rolla: 79/12/11. 87pp.

--7912200449 EIA supporting renewal application for license R-79. \* Missouri, Univ. of, Rolla, 79/12/11. 13pp.

DOCKET 50-124 VIROINIA POLYTECH INST. TRAINING REACTOR
F. Security, medical, emergency & fire protection plans

7912120206 Forwards draft Reg Guide 5.XX. "Btd Format & Content for Licensee Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance." W/o encl. REID.R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22, 2pp. DOCKET 50-128 TEXAS AMM UNIV. RESEARCH REACTOR

## F. Security, medical, emergency & fire protection plans

7912120206 Forwards draft Reg Ouide 5.XX. "Std Format & Content for Licensee Physical Security Plan for Protection of BNM of Moderate or Low Strategic Significance." W/o encl. REID.R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22.

#### G. Inspection reports, IE Bullatins & correspondence

7912030675 Forward's IE Insp Rept 50-128/79-03 on 791101-02.No noncompliance noted.

MADBEN, Q. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch, 79/11/14, 2pp.

--7912050660 IE Insp Rept 50-128/79-03 on 791101-02 No noncompliance noted Major areas inspected: security plan, SNM protection, security organization, access control alarm sus, communications & surveillance.

MADSEN, O. L. Region 4, Dallas, Reactor Operations Nuclear Support Brench. CALDHELL, R.A. Region 4, Dallas, Office of the Director. 79/11/13. 1p.

DOCKET 50-129 WEST VIRGINIA UNIV. RESEARCH REACTOR

## F. Security, medical, emergency & fire protection plans

7912120206 Forwards draft Reg Quide 5.XX. "Btd Format & Content for Licensae Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance." W/o encl. REID.R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22. Znb.

#### P. Operating license stage documents & correspondence

7912040449 Bubmits info requested by P Erickson telcon re 790927 request to dismantle & dispose of AQN-2117 reactor Outlines plans for handling irradiated reactor components & storage of source.

BLACKSHAW.O.L. West Virginia Univ. 79/11/30. 2pp.

DOCKET 50-131 DMAHA VET. ADMIN. HOSP. RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

7912120206 Forwards draft Reg Guide 5.XX. "Btd Format & Content for Licensee Physical Becurity Plan for Protection of SNM of Moderate or Low Strategic Significance." W/a encl. REID.R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22.

## G. Inspection reports. IE Bulletins & correspondence

7912130354 Forwards IE Insp Rept 50-131/79-01 on 791015-16. No noncompliance noted.

MADBEN, O.L. Region 4. Dallas, Reactor Operations Nuclear Support Branch. 79/10/29. 2pp.

---7912130359 IE Inap Rept 50-131/79-01 on 791015-16. No noncompliance noted Major areas inspected; organization reactor logs & records; audits, requalification training, procedures, surveillance tests, experiments & radiation control. MADHEN, Q.L. Region 4, Dallas, Reactor Operations Nuclear Bupport Branch. KELLEY, D.L. Region 4, Dallas, Office of the Director. 79/10/25. App.

DOCKET 50-133 HUMBOLDT BAY POWER PLANT, UNIT 3 ...

F. Security, medical, emergency & fire protection plans

7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives. Provides guidance for improving licensee emergency preparedness & assuring capability of offsite agarcies to take appropriate emergency actions.

ORIMES, B. K. Emergency Preparedness Task Force. 79/11/23. 30pp.

## O. Adjudicatory correspondence

7912030347 Request for leave to reply to intervenors' 791016 Memorandum in support of answer in opposition to licensee request to hold proceedings in absyance.

LOCKE, R. F. Pacific Gas & Electric Co. 79/10/31. 1p.

- --79120503Bi Reply to intervenors' 791016 memorandum in support of answer in opposition to licensee request to hold proceedings in abeyance. Proceedings must be delayed 12 months to allow completion of geological studies. LOCKE.R.F. Pacific Gas & Electric Co. 79/10/31. 4pp.
- --7912050354 Forwards annual statistical rept of recorded personnel whole body exposure for CY77.
  CRAME.P.A. Virginia Electric & Power Co. 78/03/14. 2pp.
- --7912050360 Forwards tabulation of personnel exposure to radiation by work & job function for 1977. CRANE.P.A. Pacific Gas & Electric Co. 78/03/14. 3pp.
- --7912050364 Forwards annual statistical rept of recorded personnel whole body atposure for CY78.
  CRANE.F.A. Pacific Gas & Electric Co. 79/03/27. 2pp.
- --7912050349 Forwards tabulation of personnel exposure to radiation by Mork & Job function for 1978 Certificate of Svc ancl. GRANE, P. A. Pacific Gas & Electric Co. 79/03/27. 4pp.
- 7912060251 Forwards Hoodward Clyde Consultants 791026 ltr outlining status of geologic & seismic investigations involving plant. Certificate of Svc encl.
  LUCKE,R.F. Pacific Cas & Electric Co. 79/11/09. 6pp.
- 79122A0097 Requests that A Baldwin, counsel for Friends of the Earth, bo placed on mailing list for all correspondence re util. BROWN, L. J. Jones, Brown & Clifford. 79/12/03. ip.
- 7912280574 Requests immediate closing of facility due to proximity of earthquake faults.
  WHEELER, R. A. Affiliation Unknown. 79/12/22. 2pp.
- 7912310510 Response to applicant 790927 motion to hold proceedings in abeyance until 801001. Applicant request preserves stakes quo w/o prejudice to rights of parties. NRC has no objections to granting motion until seismic & geologic studies conducted. GOLDBERG, S. C. Hearing Branch 2. 79/12/26. 5pp.
- --7912310512 Affidavit attesting that delay in resumption of util activities until B01001 will preserve status que. Prof qualifications & Certificate of Sx encl. QAMMILL.W.P. Division of Operating Reactors. 79/18/20. 7pp.
- P. Operating license stage documents & correspondence
- 77:2100:89 Discusses NRC 79:101 meeting w/representatives of NSSS vendors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding smalling & incidence of rupture. Vendor responses onci. EISENRUT.D.Q. Division of Operating Reactors. 79/11/09. 63pp.
- ---7912100253 Responds to NRC 791101 request re noncompliance of Mestinghouse ECCB evaluation model under requirements of 10CFR30 App K. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants. ANDERSON. T.M. Westinghouse Electric Corg. 79/11/02. App.
- --7912100330 Responds to NRC 791101 request to CIANL cladding swelling & rupture data Ravies of analytical models & tests indicates compilance w/10CFR80 App N. All GE specs for calculated peak cladding temp remain unchanged.

  SUCHHOLZ, R. H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re not burst test data. Concludes that data properly represented by fuol models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50. 46 satisfied.

  DUSLEY, Q.P. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/11/02. 5pp.
- -79:2:00456 Forwards addi info re evaluation of impact of NRC proposed repture/blockage model used in vandor evaluation model.

  No adverse impact from new repture burst data or use of NRC repture/blockage model on licensing calculation results. OMSLEY.0 F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/11/04. 22pp.
- 7912200439 Notification of cancelled 7912ti-13 meeting w/util & Woodward & Clyde in Eureka CA to discuss proposed continuation of seismic & geologic investigation. RODNEY, V. L. Operating Reactors Branch 3. 79/12/06. 2pp.

- G. Inspection reports: IE Bullstins & correspondence
- 7912100273 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/11/16. lp.
- 7912110510 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. ENGELKEN.R. Region 5, Ban Francisco, Office of the Director. 790/11/16. 10.
- 7912070022 Forwards IE Circular 79-24, "Proper Installation & Calibr of Cora Spray Pipe Break Detection Equipment on BHRs." No response required.
  ENGELKEN.R.H. Region 5, San Francisco, Office of the Director.
  79/11/26. 1p.
- 7712110268 Forwards IE Carcular 79-23, "Motor Startors & Contactors Failed to Operate." No response required. EMPELMEN.R.H. Region 5, San Francisco, Office of the Director. 79/11/26. 1p.
- 7912110A94 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofce copies of escalated enforcement correspondence sent by NRC to licensees.
  ENGELHEN.R.H. Region 5, San Francisco, Office of the Director. 79/11/26. 1p.
- 7912190143 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation." Written response required. ENDELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/11/30. 1p.
- 7912310269 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, iOCFR21." No action required. ENGELMEN.R.H. Region 5, San Francisco, Office of the Director. 79/12/06. 4pp.
- 7912190001 Forwards licensee responses to IE Bulletin 79-23, "Potential Failure of Emergancy Diesel Generator Field Exciter Transformer."
  CRENB, J. L. Region 5, San Francisco, Reactor Operations Nuclear Bupport Branch. 79/12/07. 1p.
- --7912190002 Responds to IE Bulletin 79-23. "Potential Failure of Emergency Diesel Generator Field Exciter Transformer." Facility will conduct required systemed full load operation test of emergency generator prior to startup. CRANE, P. A. Facific Gas & Electric Co. 79/10/26. 1p.
- ---7912190003 Responds to IE Dulietin 79-23, "Potential Failure of Emergency Diesel Generator Field Exciter Transformer." Facility will conduct load test of emergency diesel generator prior to recovery from refueling shutdown. GGODHIN. C. Portland General Electric Co. 79/10/11, 1p.
- --7912190006 Responds to IE Bulletin 79-23, "Potential Failure of Emergency Diesel Generator Field Exciter Transformer." Facility will conduct test of emergency diesel generators praceeding Mar 1980 refueling outage.
  BEAD, J. D. Bouthern California Edison Co. 79/10/22, 2pp.
- 7918200236 Forwards IE Bulletin 79-28. "Possible Malfunction of Namco Model Eal80 Limit Switches at Elevated Temps." Action required. ENGELMEN R. H. Region 5, San Francisco, Office of the Director.
- 7912280619 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required. ENGELKEN.R.H. Region 5, Ban Francisco, Office of the Director. 79/12/13. 1p.
- A. Periodic operating reports & related correspondence
- 7712120346 Forwards monthly operating rept for Nov 1977. WEEKB.E.D. Pacific Oas & Electric Co. 79/12/04. ip.
- ---7912120350 Honthly operating rapt for Nov 1979. OETTY, B. C. Pacific Gas & Electric Co. 79/12/03. App.

- DOCKET 50-134 WORGESTER POLYTECH INST. RESEARCH REACTOR F. Security, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Guide 5.XX, "8td Format & Content for Licensee Physical Security Plan for Protection of BNM of Moderate or Low Strategic Significance." W/o encl. REID.R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22. 2pp.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912260330 Forwards IE Insp Rept 50-134/79-01 on 790905.No noncompliance noted.
  MARTIN, H. G. Region 1. Philadelphia, Safeguards Branch. 79/11/02.
- ---7912260331 IE Insp Rept 50-134/79-01 on 790905. No noncompliance noted. Major areas inspected matl control & accounting. JOYNER, J. H. Region 1, Philadelphia, Bafeguards Branch. BUPMERB, R. T. Region 1, Philadelphia, Office of the Director, 79/10/23. 3pp.

## DOCKET 50-139 UNIV. OF WASHINGTON RESEARCH REACTOR

- F. Becurity, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Quide 5.XX. "Btd Format & Content for Licenses Physical Security Plan for Protection of SNN of Moderate or Low Strategic Significance." W/o encl. REID.R.N. Querating Reactors Branch 4 (Pre 791030). 79/08/22.
- 8. Reportable occurrences. LERs & related correspondence
- 7912280608 AD: on 791211, while reactor shut down, graduate student spilled five gallons of water on reactor top. Hater absorbed by graphite moderator resulted in magative reactivity. Facility currently resolving problem. CHALK. H. B. Washington, Univ. of. 79/12/21. 2pp.

## DOCKET 80-142 UCLA TRAINING REACTOR

- F. Security, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Quide 5.XX. "Std Format & Content for Licensee Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance." W/o encl. REID.R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22.
- Q. Adjudicatory correspondence
- 7912190091 Act receipt of 791003 request to shut down facility. Request being treated as request for action under 10CFR2, 206. FR notice encl. office of inspection & Enforcement, Office of the Director. 79/11/30. 1p.
- --7912190098 Notice of request for action under 10CFR2, 206. BTELLO, V. Office of Inspection & Enforcement, Office of the Director, 79/11/30. 2pp.
- ---7912170105 Requests shutdown of facility & public hearings rarelicensing & intervenor status. Newspaper articles re-safety question encl. HIRBCH.D.O. Committee to Dridge the Gap. 79/10/03. App.
- --7912190119 "UCLA Nuclear Reactor Is It Safe." \* Committee to Bridge the 9ap. 79/10/03. 39pp.
- --7912190125 IE Insp Rept 30-142/78-01 on 750123-24. Noncompliance noted: error in calibr curve of gaseous effluent monitor & ventilation exhaust air not properly diluted or released. MCNBLAMBKI.F.A., BODN.H.E. Region 5. San Francisco, Office of the Director. 75/02/11. 11pp.
- P. Operating license stage documents & correspondence
- 7912080635 Responds to FOIA request for UCLA Nuclear Energy Lab Facility License R-71,9AR & application for licensee Amond 10.Furwards info listed in App A. CARR, J. C. Division of Rules and Records. 79/11/16. 2pp.

- --7912050637 Forwards Amend 10 to License R-71, negative declaration, ElA & safety evaluation. No significant environ impact associated w/operation. No EIS needed.

  LEAR. 0. Decrating Reactors Branch 3 (Pre 791030). 76/02/05.
- --7912050646 Negative declaration re issuance of EIS. No significant environ impact associated w/proposed license amend. EIS not warranted.

  REGON.W. H. Assistant Director for Environmental Projects.
  78/12/19. 1p.
- --7912050647 EIA supporting nagative declaration re need for separate EIB.

  \* Assistant Director for Environmental Projects. 75/12/19.
  3pp.
- --7912050651 Bafety evaluation supporting Amend 10 to License R-71.

  Assistant Director for Environmental Projects. 76/02/05.

  4pp.
- ---7912050660 Forwards responses to questions raised by D Jaffe & Black in 750922 telcon re univ & Nuclear Energy Lab commitment to two-yr environ TLD program & radiation exposures to personnel within meteorological lab.

  KASTENBERO, H. E. California, Univ. of, Los Angelos. 75/11/05.
- --7912030661 Forwards application for amend of License R-71.TE Hicks ltr to UCLA environ health & safety officer encl. HUBSON, J. H. California, Univ. of, Los Angeles. 75/05/22. 2pp.
- --7912050664 Proposed Amend 10 to License R-71. Util safety analysis encl.

  # California, Univ. of, Los Angeles. 75/05/16. 12pp.
- ---7912050665 Amend 9 to License R-71, incorporating encl Tech Opecs into Itemse. SKDVHOLT, D. J. Atomic Energy Commission. Directorate of Licensing. 71/03/01. 3pp.
- --7912080668 Revised Tech Specs transmitted w/Amend 9, reflecting Amend 10 changes. \* California, Univ. of, Los Angelss. 71/03/01. 14pp.
- G. Inapection reports: IE Dullstins & correspondence
- 7912050346 Forwards IE Insp Rept 50-142/79-04 on 790927-28.No noncompliance noted. BOOK.H.E. Ragion 5, Ban Francisco, Fuel Facility & Materials Bafety Branch. 79/10/22. 2pp.
- --7912030335 IE Insp Rept 50-142/79-04 on 790927-28. No nencompliance noted, Major areas inspected: UCLA-based group concerns reexcessive Ar-41 exposure from stack effluent.
  BOOK: H. E. Region 5. Ban Francisco, Fuel Facility & Materials Bafety Branch. MAIRD. J. Region 5. Ban Francisco, Office of the Director. 79/10/19. Spp.
- DOCKET 50-146 BAXTON NUCLEAR EXPERIMENTAL FACILITY
- S. Reportable occurrences. LERs & related correspondence
- 7912260008 PND-I-79-002A: on 7910022, followup survey was performed by inspector to verify cleanup of unrestricted area where contaminated soil was discovered on 790920. Identified small radioactive area, approx two ft in diameter. Monitor planned. PLUMLEE, K., SMITH, B. H. Office of Inspection & Enforcement, Office of the Director, 79/10/22. 2pp.
- DUCKET 50-147 ROCKHELL INTL. COMP. GRITICAL FACILITY
  Q. Inspection reports, IE Bulletins & correspondence
- 7912060021 Forwards IE Insp Rept 50-147/79-01 on 790904-06. No noncompliance noted. BOOK.H.E. Region 9, San Francisco: Fuel Facility & Materials Bafety Branch. 79/10/17. Rpp.

--7912060031 IE Insp Rept 50-147/79-01 on 790904-06. No noncompliance noted. Hajor areas inspected: physical status of facility, surveillance program & timetable re dismantling plan. BOOK. H.E. Region 5. Ban Francisco, Fuel Facility & Materials Safety Branch. CURTIS. J. R. Region 5. San Francisco. Office of the Director. 79/10/16. 3pp.

#### DOCKET 50-149, UNIV. OF KANSAS RESEARCH REACTOR

- F. Becurity, medical, emergency & fire protection plans
- 7912120205 Forwards draft Reg Quide 3. XX, "Std Format & Content for Licenses Physical Security Plan for Protection of SNN of Moderate or Low Strategic Significance." W/g encl. REID, R. W. Operating Reactors Branch 4 (Pre 791030). 79/08/22.
- G. Inspection reports. IE Bullatins & correspondence
- 7912120229 Forwards IE Insp Rept 90-148/79-02 on 791022-24 & notice of violation. MADEEN,O.L. Region 4. Dellas. Reactor Operations Nuclear Support Branch, 79/11/07. 2pp.
- --7912120235 Notice of violation from insp on 791022-24.

  \* Region 4. Dallas, Office of the Director. 79/11/05. 1p.
- ---7912120239 IE Insp Rept 50-148/79-02 on 791022-24. Noncompliance noted: failure to implement design change properly. SPANGLER,R. G., RUCKER,M.J. Region 4. Dallas, Office of the Director. MADSEN.G.L. Region 4. Dallas, Reactor Operations Nuclear Support Branch. 79/11/05. Spp.

## DOCKET 50-150 OHIO STATE UNIV. RESEARCH REACTOR

- F. Security, medical, emergency & fire protection plans
- 7912120205 Forwards draft Reg Quide 5.XX. "Btd Format & Content for Licensee Physical Security Plan for Protection of SNM of Koderate or Low Strategic Significance." W/o encl. REID.R. W. Operating Reactors Branch 4 (Pre 791030). 79/08/22. Pdp.

## DOCKET 50-151 UNIV. OF ILLINGIS RESEARCH REACTOR

- F. Security, medical, emergency & fire protection plans
- 7912120205 Forwards draft Reg Quide 5.XX. "Btd Format & Content for Licensee Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance." W/o encl. REID.R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22.

## DOCKET 50-155 BIG ROCK POINT NUCLEAR PLANT

- F. Security, medical, emergency & fire protection plans
- 79:2:180335 Notifies of delay in Plant Bys Branch Team 1 evaluations of facility fire protection sys. Outlines of assistance needed encl.

  LAINAS.G. Plant Bystems Branch. 79/11/16. Spp.
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives. Provides guidance for improving licensee amergency preparedness & assuring capability of offeite agencies to take appropriate emergency actions.

  ORIMES, B. K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- 7912200125 Notifies of completion of design detail review of fire protection sys re util 790831 response to NRC 790404 safety . evaluation. Design criteria for mods are acceptable. LAINAS. Q. Plant Systems Branch. 79/11/23, Spp.
- 7912310092 Requests installation of backup gower for red emergency telephones as discussed in 791116 telcon.
  KEPPLER J. G. Region 3. Chicago, Office of the Director. 79/11/30.
- 7912180604 Natifies that plant red emergency telephone has emergency backup power in response to NRC 791130 request. HOFFMAN.D.P. Consumers Fower Co. 79/12/13. ip.

#### 9. Adjudicatory correspondence

- 7912170415 Agraes w/J Bui 791030 1tr re nuclear power plant. \* Christa-Maria. 79/10/31. lp.
- --7912170418 Requests that NRC demand plant maintain shutdown condition to protect citizens.
  BUI.J. Affiliation Unknown. 79/10/30. 2pp.
- 7912130193 Comments on intervenors charges that plant is unsafe. Allegations are inaccurate & w/o merit.as evidenced by recent insp & return to operation.
  YOUNGDAL.R.C. Consumers Power Co. 79/11/14. lp.
- 7912070470 Requests to make limited appearance statement at special prehability conference.

  JADMIN.D. Affiliation Unknown. 79/11/15. 1p.
- 7912050135 Requests to make limited appearance statement at licensing prehearing.
  (ETARF. H. Affiliation Unknown. 79/11/17. 1p.
- 7912060640 Restatement of contentions. Alleges that NRC cannot allow spent fuel pool expansion until storage & personent disposal problems solved Urges review of possibility of Class 9 accident Certificate of Byc encl.
  SHELDON, K.P. Christa-Maria. SHELDON, K.P. Sheldon, Harmon & Heiss. 79/11/20. Spp.
- 7912110374 Contentions questioning whether Big Rock old pool meets present requirements for spent fuel pool. Urges postponement of licensing until long-term waste disposal problem is solved.

  O'NEILL, J. P. Affiliation Unknown. 79/11/20. 10pp.
- 7912070008 Motion for approval of NRC Christa-Maria & CPC stipulation re Christa-Maria 791030 contentions. Restatement of contentions filed on 791120. NRC & CPC objections will be filed on 791129. MOORE J. E. Hearing Branch 3. 79/11/26. 2pp.
- ---7912070344 Stipulation of contentions re Christa-Maria patition to intervene as member of 24 citizens associations in area. Etatement re consolidation w/Crista-Maria will be filed at 791205 prehearing conference.W/Centificate of Svc. MODRE.J.E. Hearing Branch 2. GALD.J. Consumers Power Co. SHELDON.K.P. Christa-Maria. 79/11/26. Spp.
- 7912100319 Order shifting site of 791205 prehearing conference to Holiday Inn.US Route 131 South Petoskey, MI. OROSSMAN.H. Atomic Safety and Licensing Soard Panel. 79/11/28, 1p.
- 7912070076 Response to Christa-Maria & JP D'Neill 791120 contentions. Christa-Mería Contentions 1 & 7-9 are inadmissible & Contentions 2-6 are subj to 791126 stipulation. JP D'Neill Contentions 1.8.5, 2.8.2.E.3, 2.F. & 4 admissible. HOORE.J.E. Hearing Branch 2. 79/11/29. 32pp.
- ---7912070102 Forwards response to ABLB question.TMI occurence was Class 9 accident from possible standpoint rather than actual.Two Gertificates of Bvc encl. HATTECH.R.J. THI-2 Lessons Learned Task Force. 79/08/16. Bpp.
- 7912100322 Notice of appearance in proceeding Certificate of Svc encl. OCLDBERG.B.C. Antitrust Division. 79/11/29. 3pp.
- 7912170179 Response objecting to Christa-Haria 791030 Contentions 1 & 7-9. Contention 1.re stay of proceeding pending rulemening, contradicts NRC 791025 notice. Contentions 7 & 8 imprecise & lack bases for assertion. Contention 9 is outside proceeding. MILLER.M. I., QALLG.J., BTEPTOE.P. Consumers Power Co. 79/11/29. 11pp.
- 79:2170008 Request for order granting extension until 79:203 to respond to intervenor JP 0'Neill 79:120 restatement of contentions. Restatement has caused MRC to completely rewrite draft response.

  GALLO J. Consumers Power Co. GALLO J. Iskem, Lincoln & Beals. 79/12/01. 3pp.
- 7912170038 Response to intervenor JP 0'Neill 791030 & 1120 contentions. No objection to Contentions I. 5 & II.C. Contentions II.E. 3 & II. B will be accepted if addl info provided. All other contentions should be rejected as too general or irrelevant. GALLO, J., MILLER, M. I., STEPTOE, P. Consumers Power Co., 79/12/01.

- --7912170063 Forwards request for add1 info re SEP Topic IX-1. "Fuel Storage." Certificate of Svc encl. ZIEMANN.D.L. Operating Reactors Branch 2. 79/11/27. Spp.
- 7912190206 Forwards proposed prehearing conference agenda & hearing schedule. Requests determination on how prehearing conference will proceed & formulation of schedule for parties to follow.

  MODRE J. E. Hearing Branch 2. 79/12/03. 3pp.
- 7912190310 Forwards "Rept on Systematic Evaluation of Operating Facilities." as possible background info re spent fuel pool proceeding.

  MDDREJ.E. Hearing Branch 2. 79/12/03. 1p.
- --7912170316 "Rept on Bystematic Evaluation of Operating Facilities."

   Office of Nuclear Reactor Regulation, 79/11/25. 38pp.
- 7912210438 Ack receipt of 791104 petition to delay facility restart, panding resolution of seven identified issues. Request was not received before restart. Petition will be treated under 10CFR2.206.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/12/04. 2pp.
- ---7912210441 Notice of request for action under 10CFR2.206 re delay in facility restart.
  DENTON.H.R. Office of Nuclear Reactor Regulation, 79/12/04. ipp.
- ---7912210443 Patition to intervens. Identifies seven issues that must be resolved prior to facility restart. School sys should have workable avacuation plans. All NRC requirements should be implemented by changes.

  BIER, J., JOHNS, S. J. Affiliation Unknown. 79/11/04. 2pp.

## H. Constal correspondence

- 7912060508 Notifies that offsite radiation protection training course for NRC inspectors B satisfactory. Requests advance notification of arrival of NRC personnel.

  LOUDENBLAGER, T. Consumers Power Co. 79/12/03. 1p.
- J. Insurance & indemnity information
- 7712040447 Forwards Amends 9 & 17 to Indeanity Agreements 8-40 & E-22. respectively, modifying prefatory language re course of transportation.

  IRELAND. J. H. Consumers Power Co. 79/11/29. 3pp.
- P. Operating license stage documents & correspondence
- 7912100189 Discusses NRC 791101 meating w/representatives of NBSS vendors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swelling & indidence of rupture. Vandor responses encl. EISENHUT.D.Q. Division of Operating Reactors. 79/11/09. 65pp.
- --7912100255 Responds to NRC 791101 request re noncompliance of Westinghouse ECCS svaluation model under requirements of 10CFRSO App K. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants.
  ANDERSON.T.M. Westinghouse Electric Corp. 79/11/02. App.
- ---7912100330 Responds to NRC 791101 request re ORNL cladding swelling & rupture data. Review of analytical models & tests indicates compliance w/100FR30 App K.All GE specs for calculates peak cladding team remain unchanged.
  BUCHHOLZ.R.H. General Electric Co. 79/12/07. 2pp.
- ---7912100407 Forwards response to NRC 791101 request re rod burst test date. Concludes that date properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50. 46 satisfied.

  ONDLEY. 0. F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/11/02. 5pp.
- --7912100456 Forwards addl info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model.

  No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results.

  DRSLEFY.G.F. Exzon Nuclear Co., Inc. (subs. of Exxon Corp.).

  79/11/04. 22pp.
- 7912110018 Forwards updated lists of SEP topics not requiring site review due to ongoing generic licensing activities outside HEP or because of inapplicability to facility.

  ZIEMAND.D.L. Operating Reactors Branch 2. 79/11/16. Upp.

- 7912130082 Forwards request for add1 info re SEP Topic IX-1.Fuel Storage.
  71EMANN.D.L. Operating Reactors Branch 2. 79/11/27. 3pp.
- 7912170042 Requests Class III fee to review & approval of radiological effluent Tech Spec changes. Fee for 790927 request due 15 days upon receipt of ltr.
  MILLER, H. D. License Fee Management Branch. 79/11/27. 1p.
- 7912130112 Forwards request for add1 info re proposed expansion of spent fuel pool storage capacity.
  ZIEMANN.D.L. Operating Reactors Branch 2. 79/11/28. 3pp.
- 7912140107 Forwards assessment of repair of reactor vessel control rod drive penetration. Repair acceptable.

  ZIEMANN, D. L. Uperating Reactors Branch 2. 79/11/30. 2pp.
- 7912050497 Responds to NRC 791016 ltr re 781129 & 1228 submittals re fuel handling accidents in containment purge sys. Final solution on containment isolation sys will be submitted by 800201. HOFFMAN, D. P. Consumers Power Co. 79/12/03. 1p.
- 7912060621 Requests NRC review of encl draft matts re proposed Tech Bpsc change concerning radiological effluents.Draft Dose Calculation Manuals.draft process control programs & radiological effluent Tach Specs encl. HOFFMAN.D.F. Consumers Power Co. 79/12/03. 2pp.
- ---7912060622 Draft radiological affluent Tach Space for Palisades. \* Consumers Power Co. 79/11/30. 9pp.
- --7912060623 Palisades draft Offsite Dose Calculation Manual.

  \* Consumers Power Co. 79/11/30. 50pp.
- --7912060624 Palisades health physics procedure for laundry radwaste batch calculation & release authorization. \*\* Consumers Power Co. 79/10/08. 11pp.
- --7912060625 Palisades health physics procedure for modified radwasts calculation & release authorization. \* Consumers Fower Co. 79/10/09. 9pp.
- --7912060626 Palisades health physics procedure for sampling waste gas decay tank.
  \*\* Consumers Power Co. 79/04/18. 2pp.
- --7912060627 Palisades health physics procedure for analysis of waste gas decay tank samples.

  \*\* Consumers Power Co. 79/04/18. 1p.
- ---7912060628 Palisades health physics procedure for calculation of waste gas decay tank.

  > Consumers Power Co. 79/10/10. 13pp.
- ---7912080629 Palisades health physics procedure for stack gas particulate & indine sampling. \*\* Consumers Power Co. 79/10/10. 2pp.
- --- 7912060630 Palisades health physics procedures for stack gas sample
- -7712000630 Palisages sealth physics proceeds a counting.
  4 Consumers Power Co. 79/10/10. 1p.
- ---7912060631 Palisades health physics procedures for authorization of containment purge.

  \* Consummers Power Co. 78/03/30. 4pp.
- --7912060632 Palisades health physics procedure for calculation of condenser offgas offluents.

   Consumers Power Co. 79/10/10. 1p.
- --7912060633 Palisades health physics procedure for turbine & dirty wasta sump calculations. \* Consumers Power Co. 79/10/06. 1p.
- ---7912060634 Palisadas draft process control program, Nov 1979. \*\* Consumers Power Co. 79/11/30. 3pp.
- ---7912060636 Palisades operating procedures for gaseous radwaste sys. \* Consumers Power Co. 79/10/18. 17pp.
- --7912060637 Palisades operating procedures for solid radwaste sys. \*\* Consumers Power Go. 79/10/18. 25pp.

- -7912060641 Palisades operating procedures for spent resin handling ys. - Consumers Power Co. 79/10/18. 18pp.
- --7912070413 Operating procedures for liquid radwaste sys. \* Consumers Power Co. 79/10/23. 34pp.
- --7912070414 Handling procedure for radioactive mat1 shipment.
  4 Consumers Power Co. 79/08/30. 17pp.
- --7912070419 Draft process control program for packaging of dry solid
  - sto. Consumers Power Co. 79/12/03, App.
- --7912070421 Radiochemistry procedure for sampling.
  \* Consumers Power Co. 79/12/03. 5pp.
- ~-7912070425 Radiochemistry procedure for changing stack gas sampling
  - filters. \* Consumers Power Co. 77/06/27. App.
- -7912070429 Radiochemistry procedure for sampling & analysis: lake water daily & monthly composite samples. # Consumers Power Co. 76/10/16. 4pp.
- --7912070432 Radiochemistry procedure for offgas composition analysis. \* Consumers Power Co. 76/05/20. 5pp.
- --7912070435 Radiochemistry procedure for analysis of offgas. \* Consumers Power Co. 77/01/12. Spp.
- --7912070441 Radiochemistry proceduro for analysis of liquid radioactive
  - Consumers Power Co. 79/12/03. 16pp.
- --7912070449 Radiochemistry procedure for analysis of stack gas filters. \* Consumers Power Co. 77/05/02. 15pp.
- ---7912070458 Draft Offsite Dose Calculation Manual. \* Consumers Power Co. 79/11/30. 29pp.
- --7912070465 Draft radiological effluent Fach Specs.
   Consumers Power Co. 79/11/30. 14pp.
- --7912070467 Health physics procedure for stack gas calculations & effluent records at Palisades.

  \* Consumers Power Co. 79/12/03, 7pp.
- 7912070125 Forwards license fee for review of Age I submittal re radiological effluent Tech Spec changes. F000, H. G. Consumers Power Co. 79/12/04, 1g.
- 7912100374 Responds to NRC 791009 request for clarification of limit switch development for valves shown on util Drawing 0740030103. Forwards info re limit switch development. Torque switches will be verified during outage.

  MDFFNAN. D. P. Consumers Power Co. 79/12/04. 2pp.
- 7912210153 Continuing review of proposed spent feel pool storage capacity expansion. Requests add1 info re SEP Topic IX-1, info on proposed expansion insp & test procedures for rack lifting & transporting devices.

  ZIEMANN, D. L. Operating Reactors Branch 2, 79/12/07, 2pp.
- 7912170235 Notifies that response to NRC 791023 ltr re operation w/open purge & vent valvos during normal operation is delayed pending receipt of info from Allis-Chalmers. Response will be forwarded by 791221.

  NOFFMAN. D. P. Consumers Power Co. 79/12/13. ip.
- 7912210146 Responds to NRC 791030 ltr re THI-2 Lessons Learned Task Force Status rept & short-term recommendations. & provides implementation schedule. HUSTON, R. N. Consumers Power Co. 79/12/17. 2pp.
- 7912210182 Forwards response to NRC ltr re interim position for containment purge & vent valve operation pending resolution of isolation valve operability. Final data received & operations in compliance.

  HUSTON, R. W. Consumers Power Co. 79/12/17. App.
- 7912310438 Forwards tabulation of actions addressing requirements resulting from NRC review of THI-2 incident. Buparsedes 791030 ltr. HOFFMAN, D. P. Consumers Power Co. 79/12/27, 64pp.

- -7912310464 "Project Requirements for Steam Drum Safety Relief Valve Position Indicators PRD-CPR-001," controlled copy. Supporting documentation encl. \* Energy Incorporated. 79/12/06. 18pp.
- --7912310465 Const specs for inside containment portion of steam drum safety relief valve position indication sys. TROHKIMDINEN.G. Energy Intorporated. 79/12/06. 28pp.
- --7912310469 Const space for outside containment portion of steam drum safety relief valve position indication sys. TROHKIMGINEN.G. Energy Incorporated. 13090-000. 79/12/14. 17pp.
- --7912310473 Test spec for pressurizer relief valve position indication sys. GREEN:W.W. Energy Incorporated. 79/12/14. 47pp.
- 7912310355 Responds to 791128 request for addl info re proposed expansion of spent fuel storage. New spent fuel racks will be installed per detailed procedures re specific transit paths & installation sequences.

  HOFFMAN. D. P. Consumers Power Co. 79/12/28. 5pp.
- G. Inspection reports, IE Bulletins & correspondence
- 7912050118 Forwards IE Circular 79-22, "Stroke Times for Power Operated Reliaf Valves." No response required.

  KEPPLER.J.G. Region 3. Chicago, Office of the Director. 79/11/16.
- 7912100226 Forwards IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Bupport Loads." No response required. KEPPLER, J. G. Region 3. Chicago. Office of the Director. 79/11/16.
- 79:2:1057: Forwards IE Info Notice 79-29, "Loss of Nonsefety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required, KEPFLER. J. O. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912260140 Forwards IE Insp Rept 50-195/79-13 on 791024-26 & 29-31. No noncompliance noted.
  HEIGHMAN.R.F. Ragion 3: Chicago, Reactor Operations Nuclear Support Branch. 79/11/16. 2pp.
- ---7912260144 IE Insp Rept 50-155/79-13 on 791024-26 & 29-31. No noncompliance noted. Major areas inspected: completion of insp requirement of IE Bulletin 79-08 & followup actions relative to LERs. IE bulletins & open insp items. RIOSMAY. M. R. BOVD. D. C. Region 3. Chicago, Office of the Director. 79/11/16. 6pg.
- 7912080363 Forwards IE Bulletin 79-26. "Boron Loss From BWR Control Blades." Response required. KEPPLER, J. O. Region 3. Chicago. Office of the Director. 79/11/20.
- 791210042B Forwards 1E Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on DHRs." No written response required. KEPPLER.J.Q. Region 3. Chicago, Office of the Director. 79/11/24.
- 7912110252 Ferwards IE Circular 79-23. "Motor Starters & Contactors Failed to Operate." No response required, KEFPLER, J. G. Region 3. Chicago. Office of the Director. 79/11/26.
- 7912110403 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sent by NRC to licensees.

  KEPPLER. J. G. Region 3, Chicago, Office of the Director. 79/11/28.
- 7912190216 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation." Hritten response required. KEPPLER.J. 9. Region 3. Chicago, Office of the Director. 79/11/30.
- 7912140079 Forwards IE Info Notice 79-30. "Reporting of Defects & Noncompliances, IOCFR21." No action or response required.
  KEFPLER, J. G. Region G. Chicago, Office of the Director. 79/12/06.

- 7912120432 Forwards revision to 790201 inservice test program for pumps & valves incorporating changes resulting from 790516 & 17 site meeting w/NRC. Requests comments. FIELDB.H. Consumers Power Co. 79/12/07. 1p.
- --7912120436 "Description of Inservice Test Program for Pumps & Valves & Requests for Relief from Specific ABME Code Requirements." \* Consumers Power Co. 79/12/07. 4ipp.
- 7912200106 Forwards IE Bullstin 79~28, "Possible Malfunction of Namco Model EALBO Limit Bwitches at Elevated Temps." Action required. KEPPLER, J. O. Region S, Chicago, Office of the Director. 79/12/10.
- S. Reportable occurrences, LERs & related correspondence
- 7912070070 PNO-III-79-34: on 791104, util achieved criticality following refueling & maint outage. Caused by leakage in control rod drive F-2 & loose inlet diffuser plats. Repairs required removal of core & vessel internals.
  RIDOWAY.K.R., BOYD.D.C. Region 3, Chicago, Office of the Director. 79/11/05. 1p.
- 7912060446 Forwards LER 79-026/03L-0. HOFFHAN, D. P. Consumers Power Co. 79/12/03. 1p.
- ---7912060450 LER 79-026/03L-0: on 791101. during monthly specific gravity checks on reactor depressurizing sys. battery C, cell 48 read below Tech Spec limit. Plant in shutdown stage. Cause undetermined. Cell replaced on 791103 prior to plant startup. # Consumers Power Co. 79/12/03. 1p.
- 7912140407 Forwards LER 79-027/03L-0. HUBTON, R. W. Consumers Power Co. 79/12/11. 1p.
- --7912140409 LER 79-027/03L-0: on 791115 during power operation emergency condensor sys temps indicated leakage at outlet valve. Cause will be investigated at future shutdown. No leakage from primary sys occurred.

  \*\* Consumers Power Co. 79/12/11. ip.
- 7912140412 Forwards updated LER 78-048/03X-1. HUBTON.R.W. Consumers Power Co. 79/12/11. 1p.
- --7912140413 Updated LER 78-04B/03X-1: an 78i10B during power operation, noted amergoncy condenser shell side temp was 205 F. Temp returned to normal levels when inlet valve in loop 2 closed. Caused by improperly fitted gate valve disc.
  # Consumers Fower Co. 79/12/11. 1p.
- 7912310483 Forwards LER 79-020/01T-0. FIELDB.H. Consumers Power Co. 79/12/26. 1p.
- ---7912310492 LER 79-028/01T-0: on 791213 design review of CV4097 & CV4095 containment isolation valves indicated valves might not close under worst LOCA pressure conditions unless already partially closed. Caveed by inadequate specs.

  + Consumers Power Co. 79/12/26. 2pp.
- T. Hearing transcripts on non-antitrust matters
- 791R190344 Transcript of ASLB 791R05 prehearing conference in Patoskey, MI re spent fuel expansion. Pp 1-254.
  OROGBHAN, H., SHON, F.J., PARIS, O. H. Atomic Bafety and Licensing Board Panel. 79/12/05. 255pp.
- U. Congressional/Executive Correspondence
- 7912120570 Respunds to 790714 1tr re facility restart.Leak was found in reactor coolant pressure boundary. Facility shut down to correct problems. Technical review & onsite insp provide adequate assurance of safe operation. 008810K.L.V. Office of the Executive Director for Operations. 79710/12. ip.
- --7912120874 Forwards R Bayer 790912 itr opposing reopening of facility. Requests comment.
  ALBOSTA.D. House of Rep. 79/09/14. 2pp.
- 7912140530 Forwards M Drake & B&C Wright ltrs of concurn for plant operations. Requests response to issues reised. LEVIN.C. Sanate. 79/11/09. 4pp.

- DUCKET 50-156 UNIV. OF WISCONSIN RESEARCH REACTOR
- F. Security, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Quide 5.XX. "Std Format & Content for Licensee Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance." W/o encl. REID.R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22.
- DOCKET 50-157 CORNELL UNIV. RESEARCH REACTOR
- F. Becurity, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Quide 5.XX. "Btd Format & Content for Licensee Physical Security Plan for Protection of BNM of Moderate or Low Strategic Significance." H/o encl. REID.R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22.
- J. Insurance & indemnity information
- 7912100335 Forwards executed Amond 12 to Indemnity Agraement E-4 to modify prefatory language. "In course of transportation." VERBAGE, P. A. Cornell Univ. 79/12/03. 2pp.
- DOCKET 50-140 GEORGIA INST. OF TECH. RESEARCH REACTOR
- F. Security, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Guide 5.XX, "Std Format & Content for Licensee Physical Security Plan for Protection of BNM of Moderate or Low Strategic Bignificance." M/n encl. REID.R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22.
- DOCKET 50-163 GENERAL ATOMIC COMPANY
- F. Security, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Guide 5.XX. "Std Format & Content for Licensee Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance." #/o encl. REID:R.W. Operating Reactors Branch 4 (Prs 791030). 79/08/22.
- O. Inspection reports, IE Bulletins & correspondence
- 7912070179 Forwards IE Insp Repts 50-089/79-02 & 50-163/79-02 on 790912-14. No noncompliance noted. CREMS.J.L. Region 5. San Francisco, Reactor Operations Nuclear Support Branch. 79/10/19. 2pp.
- ---7912070198 IE Insp Repts 50-089/79-02 & 50-163/79-02 on 790912-14.No noncompliance noted Major areas inspected organization.logs & records.review & audit.procedures & reportable events.
  FAULKENBERRY.D. Region 5. San Francisco, Reactor Operations Nuclear Support Branch. JOHNSON,A.D., MORRILL.P.J. Region 5. San Francisco, Office of the Director. 79/10/19. 4pp.
- DOCKET 50-166 UNIV. OF MARYLAND RESEARCH REACTOR
- F. Becurity, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Guide 5.XX, "Std Format & Content for Licensee Physical Becurity Plan for Protection of SNM of Modsmate or Low Strategic Significance." #Vo encl. REID, R. M. Operating Reactors Branch 4 (Pre 791030). 79/08/22.2nc.
- DOCKET 50-170 NATIONAL NAVAL MEDICAL CENTER
- F. Security, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Quide 5.XX. "Std Format & Content for Licensee Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance." W/O encl. REID.R.H. Operating Reactors Branch 4 (Pre 791030). 79/08/22.

DOCKET 50-171 PEACH BOTTOM ATCHIC POHER STATION, UNIT 1
P. Operating license stage documents & correspondence

791119014B Forwards "Discussion of TMI Lessons Learned Short-Term Requirements." Revisions to encl implementation schedule for NMREG-037B requirements should be submitted wjustification within 15 days if schedule requirements cannot be met. DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/30. 2pp.

DOCKET 50-162 PURDUE UNIV. RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

7912120206 Forwards draft Reg Quide 5.XX. "Std Format & Content for Licensee Physical Sacurity Plan for Protection of SNM of Moderate or Low Strategic Significance." W/w encl. REID.R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22.

## J. Insurance & indeanity information

7912050583 Forwards esecuted Amend 10 to Indemnity Agreement E-6, modifying prefatory language re "course of transportation," BERTRAM, K. D. Purdue Univ. 79/11/21. 2pp.

DOCKET 50-184 NATIONAL BUREAU OF STANDARDS REACTOR

F. Security, medical, emergency & fire protection plans

7912120206 Forwards draft Reg Quide 5.XX. "Btd Format & Content for Licensee Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance." W/o encl. REID.R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22. 286.

7912100262 Forwards amend to security & safeguards plan. Amend withheld (ref 10cFR2.790).
CARTER.R. S. Commerce. Dept. of, National Bureau of Standards,
79/12/05. 1p.

Q. Inspection reports, IE Bulletins & correspondence

7912030079 Forwards IE Insp Rept 50-184/79-04 on 790829-31 No noncompliance noted.

MARTIN.W.O. Region 1, Philadelphia, Safeguards Branch. 79/10/05.

--7912050086 IE Insp Rept 50-184/79-04 on 790829-31. No noncompliance noted Hajor areas inspected security plan, protection of SNM, security organization, access control alarm sys & surveillance. Details withheld (ref iOCFR2. 790).

LADUM, R. H. MCKEOMN, L. M. Region i. Philadelphia, Office of the Director. DEVLIN, J. W. Region i. Philadelphia, Safeguards Branch. 79/10/03. ip.

DOCKET 50-196 UNIV. OF MISSOURI RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

79:2120206 Forwards draft Reg Quide 5.XX. "8td Format & Content For Licensee Physical Becurity Plan for Protection of SNM of Moderate or Low Strategic Significance." W/o encl. REID, R. W. Operating Reactors Branch 4 (Pre 791030). 79/08/22. 2pp.

G. Inspection reports, IE Bulletins & correspondence

7912030219 Act receipt of 791023 ltr informing NRC of steps taken to correct violations noted in IE Inep Rept 50-186/79-06.

DAVIS,A.B. Region 3, Chicage, Fuel Facility & Materials Bafety Branch. 79/11/07. 1p.

--7912030220 Responds to MRC 791005 ltr re violations noted in IE Insp. Rept 50-186/79-06. Corrective actions; individuals informed to use check-off sheet for shipments included in scope of 10CFR71. 54.

OLSON, O. L. . BRUGGER, A. M. Missouri, Univ. of, Columbia, 79/10/23.

DOCKET 50-187 SPACE RADIATION RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

7912120206 Forwards draft Reg Quide 5.XX. "Std Format & Content for Licensee Physical Security Plan for Protection of SNM of Moderate or Low Strategic Bignificance." W/o encl. REID.R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22.

Q. Inspection reports. IE Bulletins & correspondence

7912050312 Forwards IE Insp Rept 50-187/79-02 on 791016-18.No noncompilance noted. CREMB.J.L. Region 5: San Francisco: Reactor Operations Nuclear Bupport Branch. 79/10/30. 2pp.

--7912050316 IE Insp Rept 50-187/79-02 on 791016-18. No noncompliance noted Major areas inspected: operating & maint procedures, review & audit.
STERNBERGO.D.M. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. CARLSON, J. D., MORRILL, P. J. Region 5, San Francisco, Office of the Director. 79/10/29. Spp.

DOCKET 50-188 KANSAS STATE UNIV. RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

7912120206 Forwards draft Reg Guide 5.XX. "Std Format & Content for Licensee Physical Becurity Plan for Protection of SNM of Moderate or Low Strategic Significance." W/o encl. REID.R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22. 2pp.

DOCKET 50-192 UNIV. OF TEXAS RESEARCH REACTOR

F. Security, medical, emergancy & fire protection plans

7912120206 Forwards draft Reg Quide 5.XX. "Btd Format & Content for Licenses Physical Security Plan for Protection of ENM of Moderate or Low Strategic Significance." W/o encl. REID.R.H. Operating Reactors Branch 4 (Pre 791030). 79/08/22. 200.

DOCKET 50-193 RHODE ISLAND & PROVIDENCE PLANTATIONS AEC F. Security, medical, emergency & fire protection plans

7912120206 Forwards draft Reg Guide 5.XX, "Btd Format & Content for Licenses Physical Becurity Plan for Protection of BNM of Moderate or Low Strategic Significance," W/o encl. REID.R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22.

P. Operating license stage documents & correspondence

7912190060 Discusses Reactor Bafety Branch review of science ctr request to amend Tech Specs for utilization of aluminide & oxide fuel Proposed mods are acceptable. CHECK.P.S. Reactor Bafety Branch. 79/11/27. 2pp.

R. Periodic operating reports & related correspondence

7912280657 Responds to FOIA request for access to info re nuclear facilities in RI, Forwards documents listed in App A. W/o encl.
CARR, J. C. Division of Rules and Records, 79/12/18, 2pp.

S. Reportable occurrences, LERs & related correspondence

7912130522 RD: on 791127, pH of secondary water sample exceeded Tech Speciamit. Caused by failure to initiate automatic blowdown of secondary water sample. Importance of procedure stressed to operators.

DIMEQLIQ, A. F. Rhode Island, State of. 79/11/28. 1p.

7912130531 RO: on 791121, decrease in negative differential pressure discovered between inside & outside of Nuclear Science Ctr bidg. Caused by loose fitting gasket on truck door. Casket adjusted. Maint schedule will be implemented.

DIMEQLID, A. F. Rhode Island, State of. 79/12/03. 1p.

7912190590 Notifies of error in 791203 ltr re RD 50-193/79-03. Date in first line of second paragraph should read 791129. DIMEQLID.A.F. Rhode Island, State of. 79/12/07. 1p.

DOCKET 50-199 MANHATTAN COLLEGE RESEARCH REACTOR
F. Security, medical, smergency & fire protection plans

7912120206 Forwards draft Reg Quide 5.XX. "Btd Format & Content for Licensee Physical Decurity Plan for Protection of SNM of Moderate or Low Strategic Significance." W/o encl. REID, R. W. Operating Reactors Branch 4 (Pre 791030). 79/08/22, 200

DOCKET 50-201 WEST VALLEY REPROCESSING PLANT

- F. Security, medical, emergency & fire protection plans
- 7912040022 Requests submittal of category F fee for safeguards contingency piec & security personnel training & qualification plan approved 790814.
  MILLER, H. O. License Fee Management Branch. 79/11/05. 1p.
- G. Inspection reports, IE Bulletins & correspondence
- 7712060208 Ack receipt 791005 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-201/79-02. SMITH.O.H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 79/11/06. ip.
- --7912060213 Responds to NRC 790913 ltr re violations noted in IE Insp Rept 50-201/79-02. Corrective actions: requirements for hand & foot counter posted, radiation area sign posted & proper labeling emphasized. DUCKHORTH.U.P. Nuclear Fuel Barvices. Inc. (subs. of Getty Dil Co.). 79/10/05. 3pp.
- ---7912060233 Forwards IE Insp Rept 50-201/79-02 on 790606-08 & notice of violation. SHITH.O.H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 79/09/13. 2pp.
- --7912060237 Notice of violation from insp on 790606-08.

  \* Region 1, Philadelphia, Office of the Director. 79/09/11.
  2pp.
- --7912060240 IE Insp Rept 50-201/79-02 on 790606-08. Noncompliance noted: failure to follow procedures in use of hand & foot counter, to post radiation area & to label container.

  CLEMONS.P.E. Region 1, Philadelphia, Défice of the Director.

  STDHR.J.P. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 79/09/ii. Spp.

DOCKET 50-204 SAN ONOFRE NUCLEAR STATION, UNIT 1

- F. Security, medical, emergency & fire protection plans
- 7912200022 Discusses NRC 791109 meeting re emergancy preparedness tram review objectives. Provides guidance for improving licensee emergency preparedness & assuring capability of offsite agencies to take appropriate emergency ections.

  ORIMES. B. K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- 7912120443 Responds to NRC 791002 ltr re radiation safety certification of NRC personnel NRC radiation safety course meets requirements of util training program & is acceptable. MAYNES.J. 9. Southern California Edison Co. 79712/05. 1p.
- 7912180572 Forwards add1 info re emergency plenning in response to NRC 791031 request, Add1 copies of responses re Units 2 & 3 will be transmitted w/Amend 17 of FBAR. Info is responsive to specific questions & NRC overall action plen. BASKIN.K.P. Southern California Edison Co. 79/12/10. 23pp.
- 7912310009 Forwards proprietary request for add1 info to complete review of safeguards contingency plan. Details withheld (ref 10GFR2.790).

  ZIEMANN.D.L. Derating Reactors Branch 2. 79/12/11. 2pp.
- Q. Adjudicatory correspondence
- 7912110038 Confirms receipt of encl 790329 petition to suspend OLs for all PMRs. Forwards FR notice indicating that petition will be treated in accordance w/10CFR2 206.

  DENTON: H. R. Office of Nuclear Reactor Regulation. 79/11/23. ip.

- --7912110126 Notice of request for action pursuant to 10CFR2.206 re Environ Coalition on Nuclear Power 790327 patition requesting suspension of all GLs for PARs. HULLER, D. R. Office of Nuclear Reactor Regulation. 79/11/23. 38pp.
- 7712310002 Ltr to all CA residents Notifies that petitions to suspend or revoke OL will be treated as requests for action under 10CFR2.206 FR notice encl.
  DENTON.H.R. Office of Nuclear Reactor Regulation. 77/12/13. 2pp.
- --7912310004 Notice of receipt of identical petitions submitted by GA residents requesting action under 10CFR2.206.
  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/12/13. 1p.
- I. Financial information
- 7712270361 Forwards SEC Form 10-K & 1977 internal cash flow projection in compliance w/lockRi40, 21.
  HUGHES, N. O. Southern California Edison Co. 79/12/18. 2pp.
- P. Operating license stage documents & correspondence
- 7911070248 "Summary of Operating Experience H/Recirculating Steam Ownerators." EISENHUT, D. Q. Division of Operating Reactors. NUREO-0523. 79/01/31. 89pp.
- 7908010339 Notifies of status of rept on reactor cavity annulus seal.
  Most PMR users remove ring during normal operation. Others
  store seal ring in reised position during normal operation.
  LAINAG. Plant Systems Branch (Fre 791030). 79707705. 7pp.
- 7912050187 Discusses NRC review of LERs & Tech Spec requirements re control RPI sys at Westinghouse PWRs Requests Tech Specs review to ensure requirement for rod maint to within +/- 12 steps indicated & RPI sys verified accurate within 12 steps. SCHMENCER.A. Operating Reactors Branch 1. 79/10/29. 7pp.
- 7912100189 Discusses NRC 791101 meeting w/representatives of NBSS vendors & fuel suppliers or discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EISENHUT, D. Q. Division of Operating Reactors. 79/11/09. 45pp.
- ---7912100255 Responds to NRC 791101 request re noncompliance of Mestinghouse ECCS avaluation model under requirements of 10CFR50 App N. Evaluation of three fuel rod models indicates no safety problems for Mestinghouse plants.

  ANDERSON.T.M. Westinghouse Electric Corp. 79/11/02. 4pp.
- --7912100330 Responds to NRC 791101 request re ORNL cladding swelling & rupture data.Review of analytical models & tests indicates compliance w/10CR30 App K. All OE specs for calculated poak cladding temp remain unchanged.

  BUCHHOLZ.R. H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50. 46 satisfied.
  OHSLEY.O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/11/02. Spp.
- --7912100456 Forwards add1 info re evaluation of impact of NRC proposed rupture/blockage model used in vandor evaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. DMSLEY,G.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.), 79/11/04. 22pp.
- 7912200065 Forwards NRC generic & plant-specific requirements for auxiliary feedwater sys. Designs & procedures of facility should be evaluated against requirements to determine dagree of conformity.

  EISENHUT, D. O. Division of Operating Reactors. 79/11/15. Sipp.
- 7912110032 Forwards updated lists of SEP topics not requiring site review due to ongoing generic licensing activities outside SEP or because of inapplicability to facility, ZIEMANN, D. L. Operating Reactors Brench 2. 79/11/16. Spp.

- 7912060170 Summary of 791024-25 meeting w/util in Bathesda. Md re util response to lessons learned from TMI.
  SHEA. J. J. Operating Reactors Branch 2. 79/11/18. 13pp.
- 7912110412 Bummary of 790918 meeting w/util & consultants in Bethosda, MD re details of specific earthquake study. LEVIN.H.A. Systematic Evaluation Program Branch. 79/11/19. 82pp.
- 7912170198 Forwards evaluation of SEP Topic XVII "Operational OA Program." Assessment incorporates util 781003 suggested mods.

mods.
ZIEMANN.B.L. Operating Reactors Branch 2. 79/11/20. 4pp.

- 7912170189 Forwards evaluation of SEP Topic XVII "Operational QA Program," Review completed Assessment incorporates util 781207 suggested mode.
  ZIEMANN.D.L. Deprating Reactors Branch 2. 79/11/27. Spp.
- 7912100306 Forwards corrected Page 2 of 791116 response to NRC 790921 Itr re-policies & procedures for surveillance tests of reactor safeguards sys. BASKIN-M.F. Southern California Edison Co. 79/12/03. 2pp.
- 7912210332 Forwards "Review of Repts on Simulation of Ground Motions." DERNREUTER, D. L., TOKARZ, F. J. Laurence Livermore Laboratory, 79/12/06. 1p.
- --7912210343 "Review of Repts on Simulation of Ground Motions."

  BERNREUTER, D. L. Lawrence Livermore Laboratory, 79/12/04. 16pp.
- 7912140340 Notifies of change in exclusion area boundary distance from containment. List of SEP topic assessments referring to exclusion area boundary distance encl.
  HAYNES.J.O. Southern California Edison Co. 79/12/07. 2pp.
- 7912190791 Forwards quastions re study, "Hept of Evaluation of Max Earthquake & Site Oround Motion Parameters Associated w/ Offshore Jone of Deformation Facility."

  DEVINE, J. F. Interior. Dept. of, Ocological Survey, 79/12/07. App.
- 7912180515 Notifies of completed review of Yech Specs re control rod position indication sys. Control rod misalignment limitations not included in Tach Specs. Evaluations w/Hestinghouse re corrective actions underway. Details available by 791228.

  BASKIN.K.P. Southern California Edison Co. 79/12/10. 2pp.
- 7912210369 Responds to NRC 791023 ltr re operation of containment purge & vent valves pending resolution of isolation valve operability. Purge valves closed during reactor operation until operability under design basis LDCA is proven.

  BASKIN-K.P. Southern California Edison Co. 79/12/14. 2pp.
- 7912270504 Forwards revisions to util 790713 commitments re compliance w/short-term TMI Lessons Learned Task Force requirements per NUREG-0578.
  BASKIN.K.P. Southern California Edison Co. 79/12/14. 2pp.

## O, Inspection reports. IE Bulletins & correspondence

- 7912050094 Forwards IE Insp Rept 50-206/79-14 on 790907-08 & 10-13.No noncompliance noted. CREMS.J.L. Region 5. San Francisco. Reactor Operations Nuclear Support Branch. 79/10/26. 2pp.
- --7912050096 IE Insp Rept 50-206/79-14 on 790907-08 & 10-13 No noncompliance noted Major areas inspected GA/GC, administration, procurements, receipt, storage & handling of equipment & matis.

  MILLER.L.F., HORN.A. Region B, San Francisco, Office of the Birector. FAULKENBERRY, 8. Region B, San Francisco, Reactor Operations Nuclear Support Branch. 79/10/26, 7pp.
- 7912100280 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads," No response required. ENGELKEN,R.H. Region 5, San Francisco, Office of the Director, 79/11/16. ip.
- 7912110317 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required. EMPELENIR.H. Region 5. Ban Francisco. Office of the Director. 79/11/16. ip.
- 7912070023 Forwards IS Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on SWRs." No response required. EMPELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/11/26. ip.

- 7912110272 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. ENGELMEN.R.H. Region 5, San Francisco, Office of the Director. 79/11/26. 1p.
- 7912110496 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sent by NRC to licensees.
  ENGELMEN.R.H. Region 5, San Francisco, Office of the Director. 79/11/276 1e.
- 7912190153 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Written response required. ENGELKEN.R.H. Region 5, Ban Francisco, Office of the Director. 79/11/30.
- 7912310273 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21," No action required. EMBELKEN,R.H. Region 5, San Francisco, Office of the Director. 79/12/06. 4pp.
- 7912180479 Forwards util 790911 & 1005 replies to IE Bulletin 79-17. CREMB.J. L. Region 5. San Francisco, Reactor Operations Nuclear Support Branch. 79/12/07. 1p.
- 7912190001 Forwards licensee responses to IE Bulletin 79-23, "Potential Failure of Emergency Diesel Cenerator Field Exciter Transformer."
  CREMES.L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 79/12/07. ip.
- --7912190006 Responds to IE Bulletin 79-23, "Potential Failure of Emergency Diesel Generator Field Exciter Transformer." Facility will conduct test of amergency diesel generators preceeding Mar 1980 refueling outage.
  BEAD.J.O. Bouthern Celifornia Edison Co. 79/10/22. 2pp.
- 7912200244 Forwards IE Bulletin 79-28, "Possible Halfunction of Namco Model EAIBO Limit Buitches at Elevated Temps." Action regulated. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/12/07 18.
- 7912210132 Forwards responses to IE Bulletin 79-21, "Temp Effects on Layel Measurements." CREMS.J.C. Region 5, San Francisco, Office of the Director. 79/12/07. 1p.
- --7912210136 Responds to IE Bulletin 79-21, "Temp Effects on Level ... Heasurements." Corrects identification of six liquid level measurement instruments inside conbetament.

  BRAKE, J. H. Southern California Edison Co. 79/09/28. ip.
- --7912210195 Responds to IE Bulletin 79-21, "Temp Effects on Level Instrumentation." Evaluated liquid level measurement syspost-accident ambient temp on indicated water level, safety & control setpoints & emergency procedures, HATTINGE, J. J. Sacramento Municipal Utility District. 79/09/14.
- --7912210162 Responds to IE Bulletin 79-21, "Temp Effects on Level Instrumentation." Discusses liquid level measurement syspost-accident ambient temp on indicated water, safety & control setpoints & emergency procedures.

  GOODHIN.C. Portland General Electric Co. 79/09/14. 15pp.
- 791R210142 Responds to IE Bulletin 79-21 "Temp Effects on Level Measurements." re liquid level measurement sys.post-accident ambient temp on indicated water level.safety & control setpoints & emergancy procedures.
  HEAD.J.T. Southern California Edison Co. 79/09/14. 5pp.
- 7912240162 Ack receipt of 791120 ltr informing NRC of steps taken to correct violations noted in 791105 notice of violation rephysical protection insp.
  NRDREHHAUG.L.R. Region 5. San Francisco: Safeguards Branch.
  79/12/10.
- 7912280625 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/12/13. ip.
- R. Pariodic operating reports & related correspondence
- 7912110212 Forwards monthly operating rept for Nov 1979. CURRAN.J.M. Bouthern California Edison Co. 79/12/05. 1p.

- ---7912110215 Monthly operating rept for Nov 1979. MORAN,R. Q. Bouthern California Edison Co. 79/12/05. Spp.
- 8. Reportable occurrences. LERs & related correspondence
- 7912060506 PNO-V-79-009: on 791107, manual shutdown of unit occurred. Caused by electrical fault on 480-volt bus 1. Smoke & odor of burning insulation detected. Licensee inspection affected switchgear for damages.
  FAULKENBERRY, B. Office of Inspection & Enforcement, Office of the Director. 79/11/07. 2pp.
- 791204046B Forwards LER 79-018/01T-0. HEAD, J. T. Bouthern California Edison Co. 79/11/26. 2pp.
- --7912040473 LER 79-018/01T-0: on 791109, support discovered missing on liquid radwaste disposal sys piping outside containment. Caused by failure to install support during fistd const. New support installsd during 79110 unrelated outsgs. CURRAN, J. M. Bouthern California Edison Co. 79/11/26, 1p.
- 7912030176 RO: on 791127, as result of insp per IE Bulletin 79-14, missing valve operator support & incorrectly installed valve operator support identified for valve CV-528 on line 2014 3-inch 151R Seal water return line, Problem corrected.

  CURRAN, J. M. Bouthern California Edison Co. 79/11/27. 1p.
- 7912040397 Forwards LER-79-017/017-1. HEAD.J.T. Bouthern California Edison Co. 79/11/29. App.
- ---7912040408 LER 79-017/01T-1: on 791107, following loss of power to several electrical sys & 4 kV room fire alarm, 480-volt bus supply breaker 1 automatically tripped. Caused by rodent bridging two energized phases, short-circuiting bus.

  CURRAN, J. H. Southern California Edison Co. 79/11/29. 7pp.
- 7912180528 Forwards LER 79-019/01T-0. HEAD, J. T. Southern California Edison Co. 79/11/29. 2pp.
- ---7912180532 LER 79-019/01T-0: on 791116, during field verification/insp. three supports were missing on piping used to transfer fuel to diesel generator. Supports were not installed during const. New supports installed on 791166, CURRAN, J. M. Southern Celifornia Edison Co. 79/11/30, ip.
- 7912170292 Forwards LER 79-020/011-0.
  HEAD, J. T. Bouthern California Edison Co. 79/12/07. 2pp.
- ---7912170293 LER 79-020/01T-0: on 791126.missing valve operator support & incorrectly welded valve operator support discovered during inspection. Caused by poor const. New support configuration conforms piping sys to seismic input info.

  CURRAN.J. M. Bouthern California Edison Co. 79/12/07. ip.
- 7912170311 Forwards LER 79-023/03L-0. HEAD, J. T. Bouthern California Edison Co. 79/12/11. 2pp.
- --7912170314 LER 79-023/03L-0: on 791010, during GA audit, variable low pressure trip setting on pressure channel not equal to prescribed computed trip value, Caused by test procedure not containing acceptance criteria. Procedure revised, CURRAN, J. M. Southern California Edison Co. 79/12/11. ip.
- 7912180609 Forwards LER 79-021/017-0. HEAD, J. T. Southern California Edison Co. 79/12/12. 2pp.
- --7912180617 LER 79-021/01T-0: on 791114. while making routine rounds, operator found it volt do power supply on Y subchannel of load sequencer Number 2 had tripped off, Cause unknown, Power supply reset & sequencer sucesfully tested.

  CURRAN, J. M. Bouthern California Edison Co. 79/12/12. ip.
- 7912270881 Forwards LER 79-022/017-0.
  ENGELKEN,R.H. Southern California Edison Co. 79/12/17, 2pp.
- ---7912270587 LER 79-022/01T-0: on 791130: supports on component cooling water sys supply header found missing. Supports not installed during field const. New supports installed 791202: conforming piping sys to seismic analysis input info.

  \* Bouthern California Edison Co. 79/12/17. 1p.

- DOCKET 50-208 COLUMBIA UNIV. RESEARCH REACTOR

  F. Security, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Quide 5.XX, "Std Format & Content for Licensee Physical Security Plan for Protection of 8NM of Moderate or Low Strategic Significance." W/o encl. REID.R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22.
- J. Insurance & indemnity information
- 7912180544 Executed Amend 3 to Indemnity Agreement E-60, modifying prefatory language re "course of transportation." SALTZMAN.J. Antitrust & Indemnity Group. CARTER.P.D. Columbia Univ. 79/12/11. 1p.
- DOCKET 50-210 NASA CRITICAL FACILITY
- G. Inspection reports, IE Bulletins & correspondence
- 7912200395 Maste packaging Insp Rept 79-02A. No noncompliance noted.
  Major areas inspected: shipping paper & DOT placarding
  requirements, radiation levels, removable contamination, DOT &
  NRC package features.
  BROWN, R. A. Region 2, Atlanta, Office of the Director, POTTER, J. P.
  Region 2, Atlanta, Fuel Facility & Materials Safety Branch.
  79/11/06. 6pp.
- DOCKET 50-219 HADDAM NECK PLANT
- F. Security, medical, emergency & fire protection plans
- 7912180167 Forwards request for addl info re safeguards contingency plan submitted 790329. Request withheld (ref 10CFR2. 790).
  ZIEMANN, D. L. Operating Reactors Branch 2. 79/11/20. 2pp.
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives. Provides guidance for improving licensee meergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.

  ORIMES, B. K. Emergency Preparedness Task Force, 79/11/23. 30pp.
- 7912130455 Forwards add1 response to NRC 790913 & 1030 ltrs re improved in-plant iodine instrumentation under accident conditions. Air monitors in control room area at each site will be installed by 800101. Improved portable sys will be developed. COUNBIL.W.G. Northeast Utilities. 79/12/07. ip.
- G. Adjudicatory correspondence
- 7912110038 Confirms receipt of encl 790327 petition to suspend DLs for all PNRs. Forwards FR notice indicating that petition will be treated in accordance w/10CFR2.206.

  DENTON, H. R. Office of Nuclear Reactor Regulation, 79/11/23. ip.
- --7912110126 Notice of request for action pursuant to 100FR2.206 re Environ Coalition on Nuclear Power 790329 patition requesting suspension of all OLs for PMRs. MULLER, D.R. Office of Nuclear Reactor Regulation. 79/11/23. 38pp.
- P. Operating license stage documents & correspondence
- 791109024B "Summary of Operating Experience W/Recirculating Steam Generators." EISENHUT, D. G. Division of Operating Reactors. NUREG-0523. 79/01/31. 89ep.
- 7912030167 Discusses MRC review of LERs & Tech Spec requirements recontrol RPI sys at Westinghouse PWRs. Requests Tech Specs review to ensure requirement for rod maint to within +/- 12 steps indicated & RPI say verified accurate within 12 steps. SCHMENCER.A. Operating Reactors Branch 1. 79/10/29. 7pp.
- 7912100189 Discusses NRC 791101 maeting w/representatives of NSSS vendors & fuel suppliers re discussion of respective portions of ECCB evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses ancl. EIBENHUT.D.O. Division of Operating Reactors, 79/11/09. 65pp.
- --7912100255 Responds to NRC 791101 request re noncompliance of Westinghouse ECCB evaluation model under requirements of 10GFR50 App K. Evaluation of three fuel rod models indicates no safety problems for Hestinghouse plants.
  ANDERBON, T. M. Hestinghouse Electric Corp. 79/11/02. 4pp.

- --7912100330 Responds to NRC 791101 request re ORNL cladding swelling & rupture data. Review of analytical models & tests indicates compliance w/10CFR50 App K.All GE specs for calculated peak cladding temp remain unchanged.
  BUCHHOLZ.R.H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fue) models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50. 46 satisfied.

  OMSELEY.O.F. Exzon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/11/02. Spp.
- --7912100486 Forwards addl info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. OMBLEY, G.F. Exion Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/04. 22pp.
- 7912110023 Forwards updated lists of SEP topics not requiring site rayiew due to engoing generic licensing activities outside SEP or because of inapplicability to facility.

  ZIEMANN.D.L. Operating Reactors Branch 2. 79/11/16. Spp.
- 7912030173 Forwards add1 info re steam generator water hammer.Present design & operating procedures found adequate to preclude steam generator water hammer events.
  COUNBIL.W.O. Connecticut Yankse Atomic Power Co. 79/11/26. 29pp.
- 79:2040306 Forwards addl info re steam generator water hammer. Includes info re feedring. No occurrences of steam generator water hammers noted beyond instances discussed in DC Switzer 790715 ltr to RA Purple.

  COUNSIL. W. 9. Connecticut Vantee Atomic Power Co. 79/11/26. 29pp.
- 7912060505 Forwards calculations re automatic initiation of auxiliary feeduater & supporting statement that longer time is available for Haddem Neck steam generator dryout than for Hillstone-2. COWNSILM. G. Northeast Utilities. 79/11/30. 15pp.
- 7912190261 Discusses commitment made by CT Yankee Atomic Power Co & Northwast Nuclear Energy Co to implement automatic imitiation of auxiliary feedwater. Addresses util conclusion that implementation not necessary for safe operation. CDUNGIL. W. Q. Northeast Utilities. 79/11/30. Opp.
- 7912190782 Summarizes NRC Lessons Learned Implementation Team 791119 talcon w/usil re response to NRC 790913 ltr. Forwards list of items for which util schedule not acceptable, items in noncompliance & requiring clarification.

  SILVER.R.O. Operating Reactors Branch 2. 79/12/03. 7pp.
- 7912070400 Responds to request for review of auxiliary feedwater sysper NRC requirements. Mods completed eliminating need for svc water turbine driven pump lube oil coolers.

  CDUNSIL.W. O. Connecticut Yankee Atomic Power Co. 79/12/04. 6pp.
- 7912100284 Forwards "Proposed Automatic Initiation Echeme for Auxiliary Feedwater Sys." in response to NRC request for specific design details & demonstration of compliance w/HR Denton 791030 ltr.
  CDUNSIL.W.Q. Northeast Utilities. 79/12/06. 2pp.
- --7912100294 "Proposed Automatic Initiation Scheme for Auxiliary Feedwater Sys." \* Northeast Utilities, 79/12/31, 7pp.
- 7912120370 Forwards rept re proposed automatic initiation of auxiliary fastwater sys in response to NRC request for seperific design details & for demonstration of compliance w/NRC 791030 ltr to all operating nuclear youer plants.

  COUNBIL. W. G. Northeast Utilities. 79/12/06. 18pp.
- 7912130321 Discusses interim procedures for Recommendation 2.1.8.b. until high-range capability is available re increased range of radiation monitors requirement.
  COUNSIL.W.C. Northeast Utilities. 79/12/07. 4pp.
- 791218024B Responds to 791023 Interim Position 2.5 requiring containment gurge & vent isolation valves to be closed when reactor not in cold shutdown mode. Util cannot block valve automatic closure operations.
  COUNSIL.H.G., FEE.W.F. Connecticut Yankee Atomic Power Co. 79/12/10. 2pp.

- 7912180279 Provides commitment to implement Recommendation 2.2.1.b reshift technical advisor in compliance w/short-term Lessons Learned Task Force requirements. Will submit compliance for containment pressure indications & RCS venting by 810101. COUNSIL.W.O. Rortheast Utilities. 79/12/10. 2pp.
- 7912180A78 Responds to request for info re control rod position indication sys & rod misalignment for safety analysis assumptions. Tech Specs do not permit comparison to guidance provided in NRC 791105 ltr. COUNGILM, 0, . LEE, W. F. Connecticut Yankee Atomic Power Co. 79/12/10. 2pp.
- 79:2170294 Formally documents 79:21: verbal commitments to develop procedures for Item 2.1.8.b re increased range of radiation monitors in accordance w/criteria delineated in NRC 79:030 ltr to all operating nuclear power plants. COUNDIL.W. Q., FEE.W.F. Connecticut Yankse Atomic Power Co. 79/12/12. 2pp.
- 7912180476 Provides partial response to HR Denton 791030 ltr.Prevention of loss of containment isolation upon reset of containment isolation signal will be achieved by nods to valve switches. Completion expected 800101. Valve list oncl. CDUN811.W. Q., FEE.W. F. Connecticut Yankee Atomic Power Co. 79/12/13. 7pp.
- 79:2210288 Notifies of commitment to comply w/Lessons Learned Task Force requirements of Item 2.1, 4 re containment isolation. Reactor operation will continue until hardware mode can be designed & implemented.

  COUNSIL, H. G. Connecticut Yankse Atomic Power Co. 79/12/14. 1p.
- 7912270318 Provides info on compliance w/TMI Lessons Learned Task Force short-term item re auxiliary feedwater sys flow indication, in response to NRC 791211 request. Util installing single control grade flow indication channel per feedline. COUNSIL. M. O. Northeast Utilities. 79/12/18. 3pp.
- 7912270403 Forwards drawings re automatic initiation of auxiliary feedwater. Drawings to Central Files only.
  COUNSIL.W. 6. Connecticut Yankee Atomic Power Co. 79/12/18. 2pp.
- 7912270589 Responds to NRC 791113 1tr re SEP Topic III-8.C.
  "Irradiation Damago.Use of Bensitized Steel & Fatigue
  Resistance." Portion of evaluation.re brazes on control rod
  spider.requires revision to maintain factual accuracy.
  COUNSIL, W. O. Connecticut Yankee Atomic Power Co. 79/12/18. 2pp.
- Q. Inspection reports: IE Bulletins & correspondence
- 7912100193 Ack receipt of 791002 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-213/79-15.
  BRUNNER.E.J. Region 1, Philadelphia. Reactor Operations Nuclear Support Branch. 79/10/18. 1p.
- --7912100196 Responds to NRC 790913 ltr re violation noted in IE Insp Rept 50-213/79-15. Corrective actions: surveillance procedure revised. COUNSTL.N.O. Connecticut Vankee Atomic Power Co. 79/10/02. 3pp.
- --7912100197 Forwards IE Insp Rept 50-213/79-15 on 790814-16. BRUNNER, E. J. Region i, Philadelphia, Reactor Operations Nuclear Bugport Branch. 79/09/13. Spp.
- --7912100199 IE Insp Rept 50-213/79-15 on 790814-16. Noncompliance noted: failure to perform required surveillance tests.

  LAZARUS, W. Region i. Philadelphia. Office of the Director.

  KEINIO, R. R. Region i. Philadelphia, Ranctor Operations Nuclear Support Branch. 79/09/12. App.
- 7912190787 Forwards IE Insp Rept 50-213/79-16 on 791002-05. No noncompliance noted.
  BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/10/26. 2pp.
- --7912190797 IE Insp Rept 80-213/79-16 on 791002-05. No noncompliance noted. Major areas inspected: licensee actions concerning several IE bulletins, plant conditions & licensee activities, KEIMIG.R.R. Region 1. Philadelphia, Reactor Operations Muclear Bupport Branch. LAZARUS. M. Region 1. Philadelphia, Office of the Director. 79/10/25. Spp.
- 7912140285 Responds to IE Bulletin 79-24, "Frozen Lines." Present measures considered adequate to assure freeze protection of safety-related lines.
  COUNBIL.W. C. Connecticut Yankee Atomic Power Co. 79/10/31. 2pp.

- 7912210109 Forwards response to IE Bulletin 79-14. "Beismic Analysis for As-Built Bafety-Related Piping Bys." List encl of nonconformance repts for which sys repairs were recommended after engineering review.

  COUNBIL. H. O. Connecticut Yankee Atomic Power Co. 79/11/01. Spp.
- 7912170244 Forwards response to IE Bulletin 79-13, "Cracking in Feedwater Sys Piping." Summary of insp results encl. No unacceptable components identified.
  COUNBILL W.O., FEE. W. F. Connecticut Yankee Atomic Power Co. 79/11/05. Spp.
- 7912200344 Forwards wasts packaging Insp Rept 79-02A on 790925-26. No noncompliance noted.
  BUTHERLAND.U.T. Region 2. Atlanta. Fuel Facility & Materials
  Bafaty Branch. 79/11/07. 2pp.
- --7912200395 Waste packaging Insp Rept 79-02A.No noncompliance noted, Hajor areas inspected; shipping paper & DDT placarding requirements; radiation levels; removable contamination; DDT & NRC package features.

  9809N,R.A. Region 2, Atlanta, Office of the Director. 79/11/06.
- 7912050024 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required. Office of the Director. 79711/16. 1p.
- 7912050239 Forwards IE Info Notice 79-27. "Bteam Generator Tube Ruptures at Two PHR Plants." No response required. QRIER.B.H. Region i. Philadelphia. Office of the Director. 79/11/16. ip.
- 7912100115 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Bupport Loads." No response required. GRIER.B.H. Region 1. Philadelphia. Dffice of the Director. 79/11/16. 1p.
- 79:2110400 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required. ORIES, B.H. Region 1. Philadelphia. Office of the Director. 79/11/19. 1p.
- 7912050226 Forwards IE Bulletin 79-26, "Boron Loss From BWR Control Biades," No response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director. 79/11/20. 1p.
- 7912060567 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BHRs." No response required.

  ORIER, B. H. Region 1, Philadeiphia, Office of the Director.
  79/11/26. 19.
- 7912110035 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. ORIER, B. H. Region 1, Philadelphia, Office of the Director, 79/11/26. 1p.
- 7912170020 Forwards IE Bulletin 77-27. "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation." Written response required. ORIER. B. H. Region 1. Philadelphia. Office of the Director, 79/11/30. 1p.
- 7912260113 Ack receipt of 791010 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-213/79-11.
  BRUNNER, E. J. Region i, Philadelphia, Reactor Operations Nuclear Support Branch. 79/11/30. ip.
- --7912260116 Responds to NRC 790918 ltr re violations noted in IE Insp. Rept 30-213/79-11. Corrective actions: surveillance procedures BURS, 3-6 being revised to insure recording of all required plant parameters on data reduction sheets.

  COUNSIL, M. O. Connecticut Yankee Atomic Power Co. 79/10/10. 3pp.
- --7912260118 Forwards IE Insp Rept 50-213/79-11 on 790717-20 & notice of violation.

  BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/09/18. 2pp.
- --7912260120 Natice of violation from insp on 790717-20.

  \* Region i, Philadelphia, Reactor Operations Nuclear Support
  Branch. 79/09/17. ip.

- --7912260122 IE Insp Rept 50-213/79-11 on 790717-20. Noncompliance noted: failure to implement plant procedures & failure to review temporary procedure change prior to implementation. CAPHTON.D.L. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch. BETTENHAUSEN.L., GRAHAM.P.D. Region 1. Philadelphia. Office of the Director. 79/09/13. 13pp.
- 7912200637 Notifies of proposed imposition of civil penalties for violations identified in 790214-16,26-28 & 0305-09 insps of radiation protection program.
  STELLO, V. Office of Inspection & Enforcement, Office of the Director. 79/12/06. 2pp.
- --7912200641 Notice of violation from insp on 790214-16.26-28 & 0305-09. \* Region i, Philadelphia, Office of the Director. 79/12/06. 9pp.
- --7912200446 Notice of proposed imposition of civil penalties for violations identified in 790214-16, 26-28 & 0305-09 insps of radiation protection program.

  \* Office of Inspection & Enforcement, Office of the Director, 79/12/06. In.
- 7912310210 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action required.
  ORIER, B.H. Region i, Philadelphia, Office of the Director, 79/12/06. 1p.
- 7912190736 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Written response required. ORIER.B.H. Region 1, Philadelphia, Office of the Director. 79/12/07. ip.
- 7912280190 Forwards IE Info Notice 79-31. "Use of Incorrect Amplified Response Spectra." No written response required. GRIER.B.H. Region i, Philadelphia, Office of the Director. 79/12/13. ip.
- R. Periodic operating reports & related correspondence
- 7912180437 Forwards monthly operating rept for Nov 1979. ORAVES, R. H. Connecticut Yankse Atomic Power Co. 79/12/12. 1p.
- --7912180441 Monthly operating rept for Nov 1979.
  \* Connecticut Yankes Atomic Power Co. 79/12/12. Epp.
- S. Reportable occurrences, LERs & related correspondence
- 7912180041 PNS-I-79-08: on 791115, during main gate search of tractor trailer. O. 22 caliber handgun & ammunition discovered under seat of cab. Truck owned by Holmes Transport Co. Darnwell. SC, picking up low level waste shipment. Driver arrested. HADDEN, M., DEVLIN, J., MARTIN, M. Q. Region 1, Philadelphia. Office of the Director. 79/11/16; ip.
- 7912040501 Advises that on 791116 approx 460 galtons of 12% sodium hypochlorits were released to river Release exceeded total allowable chlorine concentration. Detailed rept fo follow. GRAVES R. B. Connecticut Vankes Atomic Power Co. 79/11/26. 2pp.
- 7912260262 RG 50-213/79-06: on 791216, unplanned release of radioactive gas. Caused by control valve relay failure which increased level in degasifier & activated rupture diaphragm. Rept will be submitted within 10 days.

  ORAVES, R. H. Connecticut Yankse Atomic Power Co. 79/12/17. 1p.
- DOCKET 50-219 DYSTER CREEK NUCLEAR POWER PLANT
- F. Security, medical, emergency & fire protection plans
- 7912200030 Forwards Suppl 2 to 780303 fire protection safety evaluation in response to 790918 & 1012 requests that installation of remote shutdown station be deferred. NRC position paper "Bafe Shutdown Capacity" encl.
  ZIEHANN, D. L. Operating Reactors Branch 2. 79/11/13, 2pp.
- --7912200056 Suppl 2 to 780303 fire protection safety evaluation.

  \* Operating Reactors Branch 2. 79/11/13. 4pp.
- ---7912200059 "Bafe Shutdown Capacity."

  a Office of Nuclear Reactor Regulation. 79/11/13. 7pp.
- 7912180289 Approves 790831 ltr containing design mods for fire protection sys.in response to 780303 safety evaluation. Raview status encl. LAIMAG. 9. Plant Bystems Branch. 79/11/16. 3pp.

- 7912180335 Notifies of delay in Plant Sys Branch Team 1 evaluations of facility fire protection sys. Outlines of assistance needed encl.

  LAINAS.O. Plant Systems Branch. 79/11/16. 5pp.
- LAINAS, G. Plant Systems Branch. 79/11/16. Spp.
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives. Provides guidance for improving licenses emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.

  ORIMES, B. K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- P. Operating license stage documents & correspondence
- 7912130008 Forwards summary of methodology & parameters for SEP seismic reviews. Summary is interim guide for use in review of facilities. Requests comments. HOFMAYER.C.H. Bystematic Evaluation Program Branch, 79/11/08.
- 7912100189 Discusses NRC 791101 meeting w/representatives of NSSS vandors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EIGENHUT, D. O. Division of Operating Reactors. 79/11/09. 65pp.
- --79:2100255 Responds to NRC 79:10\$ request re noncompliance of Mestinghouse ECCS evaluation model under requirements of 10CFR50 App K. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants.
  ANDERSON, T. M. Hestinghouse Electric Corp. 79/11/02. 4pp.
- --7912100330 Responds to NRC 791101 request re URNL cladding swelling & rupture data Review of analytical models & tests indicates compliance w/10CFR50 App K. All GE specs for calculated peak cladding temp remain unchanged.

  BUCHHCLI.R. H. General Electric Co. 79/12/07. 2pp.
- ---7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFRSO. 46 satisfied.

  ONSLEY.C.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/11/02. Spp.
- --7912100456 Forwards add1 info re evaluation of impact of NRC proposed repture/blockage model used in vendor evaluation model. No adverse impact from new repture burst date or use of NRC repture/blockage model on licensing calculation results. DM9LEY.G.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/04. 22pp.
- 7911200385 Forwards Tech Spec Change Request 78, applying Amend 23 to Octo all refueling cycles. FINFROCK, I.R. Jersey Central Power & Light Co. 79/11/16. 1p.
- --7912070404 Bafety evaluation supporting Tech Bpec Change Request 78, which provides for single & multiple control red removals.

  \* Jersey Central Power & Light Co. 79/11/16. 3pp.
- 7912110026 Forwards updated lists of SEP topics not requiring site review due to ongoing generic licensing activities outside SEP or because of imapplicability to facility.

  ZIEHANN.D.L. Operating Reactors Branch 2. 79/11/16. Bpp.
- 7912050132 Summary of 791113 telcon w/util in re lessons learned implementation.
  NOWICKI, S. J. Operating Reactors Branch 2. 79/11/20. 3pp.
- 7912040358 Forwards Drawings 4037, Sheets 1 & 2,4303-4507 & 4110 for input to seismic analysis. Lists equipment weights used in devaloping dynamic model of reactor bidg. Equipment weights used in turbine bidg model encl. W/o drawings.

  NAGALY. Jorsey Central Power & Light Co. 79/11/27. 6pp.
- 7912170077 Approves 790831 design criteria for mod resulting from fire protection review Evaluation of incomplete items 3.2.1 through 3.2.4 forthcoming.

  ZIEMANN.D.L. Operating Reactors Branch 2. 79/11/27. 2pp.
- 7912040327 Forwards responses to NRC 790713 Itr re BEP Topic IX-3, "Station Svc & Cooling Water Sys." Also forwards operating procedures re svc water failure & cooling water sys failure. Three drawings.available in Central Files only. NAOAI.Y. Jersey Central Power & Light Co. 79/11/28, 3pp.
- --7912040331 Operating Procedure 504 Revision G. "Svc Water Failure."

  \* Jersey Central Power & Light Co. 79/09/18. Spp.

- --7912040334 Operating Procedure 507. 1. Revision 3, "Reactor Bldg Closed Cooling Water Sys Failure." \* Jersey Central Power & Light Co. 79/07/11. 4pp.
- --7912040336 Operating Procedure 507. 2. Revision 3. "Turbine Bldg Closed Cooling Water Bys Failure."

  \* January Central Power & Light Co. 79/06/13. 4pp.
- 7912040506 Forwards new schedule for completion of proposed mods for torus & load definitions.Long-term program plant unique analysis should be completed by fourth quarter,1980.

  FINFROCK.I. R. Jersey Central Power & Light Co. 79/11/30. 3pp.
- 7912070327 Informs NRC that revised radiological effluent Tech Specs will be submitted Mar 1980, prior to planned 1980 outage.
  FINFROCK, I. R. Jarsey Central Power & Light Co. 79/12/03. ip.
- 7912110260 Forwards response to NRC questions re Tech Bpec Change Request 74. Requests prompt consideration. FINFROCK, I.R. Jersey Central Power & Light Co. 79/12/06, 6pp.
- 7912140209 Responds to 791109 telcon re communications between control room & safety-related plant areas. Repeater/base station communications sys will be installed by 800930.
  FINFROCK. I. R. Jersey Central Power & Light Co. 79/12/07. 1p.
- 7912190631 Forwards response to NRC 790716 request for add1 info re BEP Structurel Topic III-2. Topic III-3A, Topic III-7B & Topic III-7D. FINFROCK, I. R. Jersey Central Power & Light Co. 79/12/07. 18pp.
- --7912190559 "Flood Level Btudies Hurricane Tide Estimate."
  MAEUBENER, T. E. Haeusener, T. E. 70/04/27. Spp.
- --7912190664 "Rept on Probable Max Hurricane Flood Layel," HAEUSSNER, T. E. Haeussner, T. E. 70/04/25. 52pp.
- --7912190471 "Circulating Water Bys Environ Considerations." EATON, R. D. Eaton, R. O., P. E. 70/06/22, Spp.
- --7912190678 "Rept, Probable Max Hurricans Flood Analysis." GHERLOCK, P. Dames & Muore. 79/12/19. 36pp.
- --7912190683 "Expansion of Drywell Containment Vessel,"

  \* Jersey Central Power & Light Co. 79/12/31, 41pp.
- --7912190703 "Loads on Spherical Shells."
  THULLEN.P. Chicago Bridge & Iron Co. 44/08/31. 35pp.
- ---7912190707 "Rept of Initial Overload Tests of Leakage Rate Determination of Pressure Suppression Vassels," prepared for Burns & Roe, Inc. & Chicago Bridge & Iron Co. 46/03/31. 22pp.
- 79:2140417 Forwards Tech Spec Change Request 76 for License DPR-16. Change removes nondestructive examination requirements for reactor coolant sys due to revised inservice insp program. FINFROCK. I.R. Jersey Central Power & Light Co. 79/12/11, ip.
- --7912140419 Tech Spec Change Request 76 re surveillance requirements in Section 4.3 re revised inservice insp program. Certificate of Svc ancl.
  FINFROGK.I.R. Jersey Central Power & Light Co. 79/12/11. 2pp.
- 7912190364 Forwards primary containment isolation sys data in response to NRC request Request for long-term sys info now complete. FINFROCK, I.R. Jersey Central Power & Light Co. 79/12/14. Sipp.
- 7912270544 Forwards response to NRC 790810 request for info re possible draining of spent fuel storage pool following pipe failure, per SEP Topic IX-1. "Fuel Storage."
  NAOAI, Y. Jersey Central Power & Light Co. 79/12/14, 5pp.
- 7912270384 Discusses intent to initiate valve qualification program for containment vent & purge valves & to follow interim position for containment purge & vent valve operation. Testing of valves will commence Apr or May 1980.

  FINFROCK, I. R. Jersey Central Power & Light Co. 79/12/17, ip.
- O. Inspection reports, IE Bulletins & correspondence
- 7912030245 Ack receipt of 790917 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-219/79-10.
  BRUNNER.E.J. Region 1. Philadelphia. Reactor Operations Nuclear Bupport Branch. 79/10/24. ip.

- --7912030248 Responds to NRC 790828 ltr re violations noted in IE Insp Rept 30-219/79-10. Corrective actions: revised Plant Emergency Procedures 511.1, 514 & 532 to include restrictions re open valves. RD88, D. A. Jersey Central Power & Light Co. 79/09/17. 4pp.
- ---7912030251 Forwards IE Insp Rept 50-219/79-10 on 790503-04 & notice of violation.

  ORIER, B. H. Region i, Philadelphia, Office of the Director.

  79/08/28. 2pp.
- ---7912030252 Notice of violation from insp on 790503-04.
  Region 1, Philadelphia, Office of the Director. 79/08/22.
- --7912030256 IE Insp Rept 50-219/79-10 on 790503-04. Noncompliance noted: deficient procedural controls which resulted in isolation of all recirculations loops w/consequent dropping of core water level below safety limit.

  BRIO08.L., MEELY.D.R. Region 1, Philadelphia, Office of the Diractor. 79/08/22, 20pp.
- 7912200206 Forwards IE Insp Rept 50-219/79-19 on 791009-11. No noncompliance noted.
  BRUNNER: E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/10/31. 2pp.
- --7912200213 IE Insp Rept 50-219/79-19 on 791009-11. No noncompliance noted Major areas inspected: independent effort, organization & administration, office review & LER followup. BRIOOS, L. Region 1. Philadelphia, Office of the Director. MCCABE, E. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch. 79/10/30. 7pp.
- 7912310060 Forwards IE Insp Rept 50-219/79-13 on 790803-04. No noncompliance noted. BMITH, 9.H. Region 1. Philadelphia. Fuel Facility & Materials Bafety Branch. 79/11/06. 2pp.
- ---7912310065 IE Insp Rept 50-219/79-13 on 790503-04. No noncompliance noted. Hajor areas inspected: radiological conditions associated w/low-low-water level incident after 790502 reactor trip.

  NEELY, D. R. Region 1, Philadelphia, Office of the Director. STOMR, J. P. Region i, Philadelphia, Fuel Facility & Materials Safety Branch. 79/11/02. 3pp.
- 7912200344 Forwards wasts packaging Insp Rept 79-02A on 790925-26.No nuncompliance noted.

  SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Bafety Branch. 79/11/07. 2pp.
- --7912200395 Waste packaging Insp Rept 79-02A No noncompliance noted.
  Major areas inspected; shipping paper & DDT placarding requirements, radiation levels, removable contamination, DDT & NRC package features.

  #RDMN,R.A. Region 2, Atlanta, Office of the Director. 79/11/06.
- 7912050032 Forwards IE Circular 79-22, "Btroke Times for Power Operated Relief Velves." No response required. ORIER, B. H. Region i, Philadelphia, Office of the Director. 79/11/16. ip.
- 7912030253 Forwards IE Info Notice 79-27, "Steam Generator Tube Ruptures at Two PHR Plants." No response required. ORIER.B.H. Region 1, Philadelphia, Office of the Director. 79/11/16, ip.
- 7912100120 Forwards IE info Notice 79-28, "Overloading of Structural Elements Due to Pipe Bupport Loads." No response required. ORIER.B.H. Region 1, Philadelphia, Office of the Director. 79/11/16. ip.
- 7912110409 Forwards IE Info Notice 77-29, "Loss of Nonsefety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required. OffER.B.H. Region 1, Philadelphia, Office of the Director. 79/11/19. 1p.
- 7912050237 Forwards IE Bulletin 79-26, "Boron Loss From BHR Control Blades," Response required.
  GRIER, B.H. Region 1, Philadelphia, Office of the Director, 79/11/RO. ip.
- 7912060573 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No response required.
  ORIER, B. H. Region 1, Philadelphia, Office of the Director, 79/11/26. ip.

- 791211004B Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required.
  ORIER,B.H. Region I. Philadelphia, Office of the Director.
  79/11/26. 1p.
- 7912190027 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Written response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director. 79/11/30. 1p.
- 7912280015 Updates 790921 response to IE Bullstin 79-18, "Audibility Problem Encountered on Evacuation of Personnel from High Noise Areas." Btrobe lits devices used for visual alarm in high noise areas.

  ROSS, D. A. Jersey Central Power & Light Co. 79/12/06. 2pp.
- 7712310216 Forwards IE Info Notice 77-30, "Reporting of Defects & Noncompliances, 10CFR21," No action required.

  QRIER, B. H. Region 1, Philadelphia, Office of the Director.
  79/12/06. 4pp.
- 7912190748 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Written response required. QRIER, B. H. Region i, Philadelphia, Office of the Director. 79/12/07. 1p.
- 7912280199 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required. ORIER, B.H. Region 1, Philadelphia, Office of the Director. 79/12/13. 1p.
- R. Pariodic operating reports & related correspondence
- 7912210306 Forwards monthly operating rept for Nov 1979. ROSE, D. A. Jersey Central Power & Light Co. 79/12/14. 1p.
- ---7912210310 Monthly operating rept for Nov 1979. MCCLAIN, C. M. Jersey Central Power & Light Co. 79/12/14. 8pp.
- S. Reportable occurrences, LERs & related correspondence
- 7912070323 Forwards LER 79-040/03L-0. ROBB.D.A. Jersey Central Power & Light Co. 79/11/30. 3pp.
- --7912070328 LER 79-040/031-0: on 791102,NRC audit noted standby gos treatment sys charcoal filters not tested por Tech Epec. Caused by not including methyl iodide removal efficiency test on master test schedule & in-plant procedure. ROSS.D.A. Jersey Central Power & Light Co. 79/11/30. 1p.
- 7912070334 Forwards LER 79-037/03L-0.
  ROSB.D.A. Jersey Central Power & Light Co. 79/11/30. 1p.
- ---7912070340 LER 79-037/03L-0: on 791103, during monthly surveillance test, core spray booster pump NZO3B failed to start. Pump breaker control power fuse checked. Caused by loose fuse. Fuse clip tightness checked & fus
- 7912070359 Forwards LER 79-038/03L-0.
  ROSS.D.A. Jersey Central Power & Light Co. 79/11/30, ip.
- ---7912070365 LER 77-038/03L-0: on 791105, diesel generator i failed to start during diesel generator 20% plus load test. Causad by component failure. Breaker position switch readjusted. ROSB, D. A. Jersey Central Power & Light Co. 79/11/30. App.
- 7912070333 Forwards LER 79-041/03L-0.
  ROBS, D. A. Jersey Central Power & Light Co. 79/12/03. 1p.
- ---7912070345 LER 79-041/03L-0: on 791102 noted that no effluent data reported for radwaste bidg ventilation monitoring sys since Oct 1978. Caused by inadequate design of effluent monitoring sys. Mods made to enable calibr of detectors.

  RUSS, D. A. Jersey Central Power & Light Co. 79/12/03, 3pp.
- 7912070350 Forwards LER 79-039/03L-0.
  ROSS.D. A. Jarsey Central Power & Light Co. 79/12/03. ip.
- --7912070364 LER 79-039/03L-0: on 791105, while performing average power range monitor surveillance test & celibr, 100% flow rod block setpoint on Channel i found to be 107% of rated neutron flux. Caused by instrument drift, Channel i readjusted, ROSS, D. A. Jersey Central Power & Light Co. 79/12/03. Spp.

- 7912110315 Forwards LER 79-042/03L-0. R05s.D.A. Jersey Central Power & Light Co. 79/12/06. 1p.
- --7912110317 LER 79-042/03L-0: on 791106, valve ERV NR 10BA opened during operation for no reason. After calibr, valve malfunctioned within 1-h. Caused by component failure. Pressure switch replaced.
  ROSS, D. A. Jersey Central Power & Light Co. 79/12/06. 3pp.
- 7912210338 Forwards RO 79-38/03L. ROSS D. A. Jarsey Central Power & Light Co. 79/12/14. ip.
- --7912210354 RO 79-38/03L: on 791105, during degraded mode operation & surveillance test, dissel generator failed to start. Caused by diesel generator breaker position switch being out of adjustment. Switch readjusted.

  \* Jersey Central Power & Light Co. 79/12/14. 2pp.

## U. Congressional/Erecutive Correspondence

- 7912210183 Forwards NRC response to Ocean County Board of Chosen Freeholders 790816 resolution re Congressional action to establish independent agency for continuous radiological monitoring of facility, AP King 790821 ltr & resolution encl. ODSSICK.4. V. Office of the Executive Director for Operations, 79/10/24. Spp.
- 7912210190 Forwards NRC response to Board of Chosen Fresholders resolution re Congressional action to establish independent agency for continuous radiological monitoring of facility. OBSECKIL V. Office of the Executive Director for Operations. 79/10/24. ip.
- --7912210197 Forwards AP King 790821 Itr & Ocean County Board of Chosen Fresholders 790816 resolution concerning facility radioactive discharges Requests comment. WILLIAMS.H.A. Benate. 79/09/04. 3pp.
- 7912210237 Forwards NRC response to resolution re Congressional action to establish independent agency for continuous radiological monitoring of facility.

  GUSBICK.i.v. Office of the Executive Director for Operations.

  79/10/24. ip.

# DOCKET 50-220 NINE HILE POINT NUCLEAR STATION, UNIT 1 F. Security, medical, emergency & fire protection plans

- 7912200022 Discusses NRC 791109 meeting re emergency preparadness team review objectives. Provides guidance for improving licensee emergency preparadness & assuring capability of offsite agencies to take appropriate emergency actions.

  GRIMES.B.K. Emergency Preparadness Task Forcs. 79/11/23. SOpp.
- 7912180839 Requests NRC approval by 800131 to modify fire protection sys mod included in Amend 33 to DFR-63.Plans to install automatic 6% Halon sys.u/manual carbon dioxide sys as backup.

  DISE.D.P. Niagara Hohauk Power Corp. 79/12/11. 1p.
- 7912210179 Forwards changes to util security plan.Plan withheld fref 10CFR2.790). BARTLETT.J. Niagera Mohewi Pawer Corp. 79/12/11. ip.

## P. Operating license stage documents & correspondence

- 7912200411 Notifies that response to 791018 request for info rerefusling outage forthcoming. DENION.H.R. Office of Nuclear Reactor Regulation. 79/11/05. 2pp.
- 7912100187 Discusses NRC 791101 meeting w/representatives of NSSS vendors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EIBENAUT.D. 0. Division of Operating Reactors. 79/11/09. 65pp.
- --7912100255 Responds to NRC 791101 request re noncompliance of Wastinghouse ECCS evaluation model under requirements of 10CFR50 App K. Evaluation of three fuel rod models indicates no safety problems for Wastinghouse plants. ANDERBON, T. M. Wastinghouse Electric Corp. 79/11/02. App.
- ---7912100330 Responds to NRC 791101 request re ORNL cladding swelling & rupture data Review of analytical models & tests indicates compliance w/10CFR50 App % All GE specs for calculated peak cladding temp remain unchanged.

  BUCHHOLZ, R. H. General Electric Co. 79/12/07, 2pp.

- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50.46 satisfied.
  OMSLEY.O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/11/02. Bpp.
- --7912100456 Forwards addl info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model. No adverse inpact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. OMSLEY.O.F. Exton Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/04. 22pp.
- 7912040462 Responds to NRC 791107 ltr & forwards fee for review & approval of request to amend Tech Specs to operate two recirculation loops isolated W/o encl.

  DISE-D.P. Niagara Hohauk Power Corp. 79/11/21. 2pp.
- 7912040469 Forwards info re containment isolation barriers in response to NRC 770713 ltr. Fourteen oversize drawings, available in Central Fites only.

  DISE.D.P. Niegara Mohawk Power Corp. 79/11/28. 42pp.
- 7912050492 Notifies NRC that due to delays in const of administration bldg extension, installation of breathing air compressor will be delayed until 800131.

  DIBE, D. P. Niagara Mohawk Power Corp. 79/11/28. ip.
- 7912040315 Submits addl into re 790913 ltr on corrosion analysis results Results transmitted by 791231.
  DISE, D. P. Niagara Mohawt Power Corp. 79/11/30. 1p.
- 7912040346 Requests consideration of new acceptance criteria for condensation oscillation loads, including margin added to pool swell net vertical upload, pool swell impact "Sweep" time on structures above pool & vent h
- 7912180547 Forwards addl info re station electrical distribution sys, per NRC 791015 request.Addl deviations from NRC guidelines have not bean found.Onsite distribution sys test should not be necessary.

  DISE.D.P. Niagara Mohawk Power Corp. 79/12/07. 2pp.
- 7912210377 Forwards interim position on containment vant & purge valves, in response to NRC 791022 ltr. Presently verifying operability for containment vent & purge valves, DISE, D. P. Niagara Mohawk Power Corp. 79/12/17.
- 7912270379 Changes 791126 commitment to install relief & safety valve position indication seven days after equipment delivery. Relocation of charge amplifiers outside drywell is required due to operating & accident environ conditions.

  DISE, D.P. Niagera Mohawk Power Corp. 79/12/19. 2pp.
- 7912270330 Forwards requested clarification of NUREQ-0578 commitments in util 791126 ltr. Facility relief valves not air operated. Control room staff to be augmented by addition of assistant supervisor by 800101.
  RHODE, O. K. Niagara Mohawk Power Corp. 79/12/20. 2pp.
- 7912270507 Commits to install recirculation pump trip by 801231. BARTLETT.J. Niagara Mohawk Power Corp. 79/12/21. 1p.

## Q. Inspection reports, IE Bulletine & correspondence

- 7912100205 Ack receipt of 790920 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-220/79-15.
  MARTIN.W. 0. Region i. Philadelphia. Safeguards Branch. 79/10/23.
- --7912100208 Responds to NRC 790912 ltr re violations noted in IE Insp. Rept 30-220/79-15. Corrective actions withheld (ref. 10CFR2, 790).
  BARTLETT, J. Niagara Mohawk Power Corp. 79/09/20. 1p.
- --7912100211 Forwards IE Insp Rept 50-220/79-15 on 790508-11.Notice of violation withheld (ref 10CFR2.790).

  HARTIN H.O. Region 1. Philadelphia, Bafaguards Branch.
  79/09/12. 3pp.
- --7912100215 IE Insp Rept 50-220/79-15 on 790508-11.Noncompliance noted; regulatory requirements re alarm response procedures & recordkeeping. Details withheld (ref 10CFR2, 790).

  SHEPHERD, R. E. Region 1, Philadelphia, Office of the Director. DEVLIN.J.W. Region 1, Philadelphia, Bafeguards Branch. 79/08/23. 1p.

- 7912170168 Responds to IE Bulletin 79-24, "Frozen Lines." Safety related process instrument & sampling lines do not freeze during cold weather.

  BCHNEIDER.R.R. Niegara Hohawk Power Corp. 79/10/24. 1p.
- 7912260050 Forwards IE Insp Rept 50-220/79-24 on 790914 & 26-27. No noncompliance noted Insp rept withheld (ref 100FR2. 790).

  MARTIN.W. 0. Region 1. Philadelphia. Safeguards Branch. 79/11/02.
- 7912310427 Responds to IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Forwards suggesty of work performed to date & updated schedule for completion of remaining items per 790817 ltr. BCHNEIDER, R. R. Niagara Mohaws Power Corp. 79/11/07. 4pp.
- 7912140157 Responds to IE Bulletin 79-01. "Environ Qualification of Class IE Equipment." Electrical penetration connectors presently being tested.
  SCHWEIDER R. R. Niagara Mohawk Power Corp. 79/11/07. 1p.
- 7912050040 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required. Office of the Director. 79/11/16. 1p.
- 7912050274 Forwards IE Info Notice 79-27, "Steam Generator Tube Ruptures at Two PWR Plants." No response required. ORIEM, B.H. Region 1, Philadelphia, Office of the Director. 79/11/16. 1p.
- 7912100134 Forwards IE Info Notice 79-28, "Overloading of Structural Elaments Due to Pipe Support Loads." No response required. ORIER, B.H. Region i, Philadelphia, Office of the Director. 79/11/16. 1p.
- 7912110449 Forwards IE Info Notice 79-29. "Loss of Nonsefety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required. ORIER, H. Region 1. Philadelphia, Office of the Director. 79/11/19. ip.
- 7912030243 Forwards IE Bulletin 79-26, "Boron Loss From BHR Control Blades." Response required. ORIER.B.H. Region 1, Philadelphia, Office of the Director. 79/11/20. 1p.
- 7912200303 Ack receipt of 791105 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-220/79-23.

  RENAMER.E.J. Region 1: Philadelphia: Reactor Operations Nuclear Support Branch. 79/11/21: 1p.
- --7912200313 Responds to NRC 791015 ltr re violations noted in IE Insp Rapt 50-220/79-23. Corrective actions: reactor enalysis personnel will provide closer supervisory review. BCHNEIDER, R. R. Niegara Mohawk Power Corp. 79/11/05. 2pp.
- --7912200318 Forwards IE Insp Rept 50-220/79-23 on 790918-20 & notice of violation.

  BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/10/15. 2pp.
- ---7912200324 Notice of violation from insp on 790918-20.

  Region 1, Philadelphia, Office of the Director. 79/10/11.
  1p.
- --7912200332 IE Insp Rept 50-220/79-23 on 790918-20. Noncompliance noted: failure to properly document & review plant testing procedures.

  GRAMAN, P. D., BETTENHAUSEN, L. Region 1, Philadelphia, Office of the Director. CAPHTON, D. L. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch, 79/10/11, 10pp.
- 7918060580 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BMRs," No response required.
  ORIER, B. H. Region 1, Philadelphia, Office of the Director.
  79/11/26. 1p.
- 7712110066 Forwards IE Circular 77-23, "Motor Starters & Contactors Failed to Operate." No response required. ORIER.B.H. Region 1. Philadelphia, Dffice of the Director. 79/11/26, 1p.
- 7912040277 Forwards results of feedwater & control rod drive nozzle insps performed during Spring 1979 refueling nutage, No reportsates indications of creating found.

  DISE, D. P. Niegera Mohawk Power Corp. 79/11/28. 15

- 7912190044 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation." Hritten response requires. GRIER.B.H. Region 1. Philadelphia, Office of the Director. 1n.
- 7912310228 Forwards IE Info Notice 79~30, "Reporting of Defects & Noncompliances, IOCFR21." No action required. GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/12/06. 4pp.
- .7912190757 Forwards IE Bulletin 79-28, "Possible Malfünction of Namco Model EA180 Limit Switches at Elevated Temps." Hritten response required.
  ORIER, B. H. Region 1, Philadelphia, Office of the Director.
  79/12/07. ip.
- 7912280019 Revises 791107 response to IE Bulletin 79-14, "Beismic Analysis for As-Built Bafaty-Related Piping Bys." Util will inspect piping sys within drywell & verify restraint location & design for sys where GA documentation exists, BCHNEIDER, R. R. Niagara Mohawk Power Corp. 79/12/07, 2pp.
- 7912280215 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra," No written response required. GRIER, D. H. Region 1. Philadelphia. Office of the Director. 79/12/13. 1p.
- R. Periodic operating reports & related correspondence
- 7912260267 Forwards monthly operating rept for Nov 1979. SCHNEIDER.R. R. Niagara Mohawk Power Corp. 79/12/10. 1p.
- -7912260268 Monthly operating rept for Nov 1979. PERKINS.T.J. Niagara Mohawk Power Corp. 79/12/10. App.
- 9. Reportable occurrences, LERs & related correspondence
- 7912270259 Responds to NRC 790918 1tr re loss of offsits power events. One event occurred on 731117 during which all power lost causing failure of one 115 kV line. BARTLETT, J. Niagara Hohawk Power Corp. 79/12/21. 3pp.

## DOCKET 50-223 UNIV. OF LOWELL RESEARCH REACTOR

- F. Security, medical, emergency & fire protection plans
- 7912120204 Forwards draft Reg Quide 5.XX, "Btd Format & Content for Licenses Physical Security Plan for Protection of SNM of Moderate or Low Btrategic Significance." W/o encl. REID:R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22.
- J. Insurance & indemnity information
- 7912180579 Executed Amend 9 to Indomnity Agreement E-54, modifying prefatory language re "course of transportation." BALTMAN, J. Antitrust & Indomnity Orang. DUFF, J. B. Lowell, Univ. of. 79/11/30. ip.
- DOCKET 50-224 UNIV. OF CALIFORNIA REBEARCH REACTOR
- F. Security, medical, emergency & fire protection plans
- 7912120206 Forwards draft Rag Quide 5.XX, "Btd Format & Content for Licensee Physical Security Plan for Protection of SNM of Møderate or Low Strategic Significance." M/o encl. REID, R. W. Operating Reactors Branch 4 (Fre 791030), 79/08/22.
- 9. Adjudicatory correspondence
- 7912180612 Endorses Friends of the Earth request for action asking parameter revocation of Regents of Univ of CA DL. OEUROE, J. Alexeds County, CA. 79/10/30. 1p.
- 7912140425 Requests suspension of all activities of TRIOA reactor, removal of all Pu & other radioactive matl, permanent revocation of OL & holding of public hearings in Berkeley, CA, before any resumption of reactor operations, HARTINO, I., BALDHIN, M. A. Friends of the Earth. 79/12/11. 2ipp.

## rating license stage documents & correspondence

0616 Enderses Friends of the Earth request that reactor activity tchaverry Hall.Univ of CA.be suspended.CA Assembly 11 endorsament encl. ON.H. Berkeley, CA. 79/08/01. 2pp.

#### 50-225 RPI CRITICAL EXPERIMENT

urity, medical, emergency & fire protection plans

0206 Forwards draft Rag Quide 5.XX. "Std Format & Content for name Physical Security Plan for Protection of SNM of rate or Low Strategic Significance." W/o anci. NR.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22.

50-228 AERDTEST RADIDORAPHY & RESEARCH REACTOR urity, medical, emergency & fire protection plans

20205 Forwards draft Reg Ouide 5.XX. "Std Format & Content for Insee Physical Security Plan for Protection of SNM of Frate or Low Strategic Significance." W/o encl. 15.R.M. Operating Reactors Branch 4 (Pre 791030). 79/08/22.

## pection reports, IE Bulletins & correspondence

0132 Ack receipt of 791203 ltr informing NRC of staps taken to ect violations noted in IE Insp Rept 50-228/79-02. (.H.E. Region 5, San Francisco, Fuel Facility & Moterials ty Branch. 79/12/11. ip.

2260134 Responds to NRC 791113 ltr re violations noted in IE Insp pt 50-228/79-02 Corrective actions: evalution of meutron name for personnel in GA lab & reactor console completed by D0115. EMACHECK.R.L. Aerotest Operations. 79/12/03. 2pp.

2260135 Forwards IE Insp Rept 50-228/79-02 on 791015-17 & notice of clastion. ONATH.E. Region 5, San Francisco, Fuel Facility & Materials ofety Branch. 79/11/13. 2pp.

2260136 Notice of violation from insp on 791015-17. Region 5, Ban Francisco, Office of the Director. 79/11/13.

2260137 IE Insp Rapt 50-228/79-02 on 791015-17.Noncompliance noted: kiled to adequately evaluate neutron exposures. ATRD.J.B. Region 5. Ban Francisco, Office of the Director. DOK.M.E. Region 5. Ban Francisco, Fuel Facility & Materials afety Branch. 79/11/13. Bpp.

# T 50-237 DREGDEN NUCLEAR POWER STATION, UNIT 2

curity, medical, emergency & fire protection plans

00022 Discusses NRC 791109 meeting we emergency preparadness team low objectives.Provides guidance for improving licensee rgency preparedness & assuring capability of offsite ncies to take appropriate emergency actions. MEB.B.K. Emergency Preparedness Task Force. 79/11/23. 30pp.

70063 Forwards list of specific items requiring updating in rgoncy plans. Emergency plans were evaluated using code uirements, Reg Guide 1.101 & Emergency Planning Review delines Numbor 1. Revision 1. ULITO.T.A. Operating Reactors Branch 3. 79/11/30. 7pp.

70089 Act receipt of 770816 ltr transmitting security personnel ining & qualification plan Requests submittal of Class I II fees totalling \$4.000. License Fee Management Branch. 79/12/10. ip.

## naral correspondence

80405 Discusses 791204 title change of manager of nuclear rations to vice president Organization structure not area No revision will be made to GA program topical rapt in-1-A until organization structure is delineated.

EGEK,R.F. Commonwealth Edison Co. 79/12/19. 1p.

## P. Operating license stage documents & correspondence

- 7912100189 Discusses NRC 791101 meeting w/representatives of N888 vendors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing wifuel cladding swelling & incidence of rupture. Vendor responses encl. EISENHUT, D.Q. Division of Operating Reactors. 79/11/09. 65pp.
- --7912100255 Responds to NRC 791101 request re noncompliance of Westinghouse ECCS evaluation model under requirements of 10CFR50 App M. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants. ANDERSON, T. M. Wastinghouse Electric Corp. 79/11/02. 4pp.
- --7912100330 Responds to NRC 791101 request re ORNL cladding swelling & rupture data. Review of analytical models & tests indicates compliance w/10CFR50 App K. All GE specs for calculated peak cladding tempremain unchanged.

  BUCHHOLZ, R. H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR30.46 satisfied.

  GMBLEF, 0.F. Expon Nuclear Co., Inc. (subs. of Exxon Corp.).

  79/11/02. 5pp.
- --7912100456 Forwards add1 info re evaluation of impact of NRC proposed rupture/blockage model used in vandor evaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. OMSLEY.0.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.), 79/11/04. 28pp.
- 7912180172 Responds to 790313 ltr re completion of draft evaluation of SEP TOPIC IV-1. A. Review complete & evaluation will be basic input into integrated safety assessment.

  ZIEMANN. D. L. Operating Reactors Stanch 2. 79/11/13. 2pp.
- 7912040261 Forwards plant steam bypass capacity sheets, percent rated.
  Info provided to OE for incorporation into NEDO-24708.
  PEOPLES D.L. Commonwealth Edison Co. 79/11/16. 200pp.
- 7912110015 Forwards updated lists of BEP topics not requiring site review due to ongoing generic licensing activities outside SEP or because of inapplicability to facility.

  ZIEMANN, D. L. Operating Reactors Branch 2. 79/11/16. Spp.
- 7912170204 Forwards evaluation of BEP Topic XVII "Operational GA Program." Review completed Assessment incorporates util 781023 suggested mods. ZIEMANN.D.L. Operating Reactors Branch 2. 79/11/20. 4pp.
- 7912050322 Discusses 791113 & 14 site visit re solid radwasts processing & temporary storage Facilities have instituted improved wasts minimization programs. ORANT, P., LO.R. Environmental Evaluation Branch, 79/11/23, 2pp.
- 7912070417 Comments on encl Fugro. Inc review of LLL/TERA rept resismic herard analysis. Variance in expert opinion suggests that program output is inaccurate. Questionable areas must be resolved in order for methodology to be useful.

  JANECEK.R.F. Commonwealth Edison Co. 79/11/29, 2pp.
- --7912070420 "Critique of LLL/TERA Repts on Seismic Hazard Analysis," prepared for Nuclear Sycs Corp. \* FURGO Consulting Engineers & Osologists, 79/10/26. 7pp.
- 771211037B Summary of 791011 meeting w/util re SEP seismic review. LEVIN.H.A. Systematic Evaluation Program Branch. 79/11/29. Spp.
- 7712310361 Bubmits requested info on SEP Topic IX-3, "Station Svc & Cooling Water Bys." Total residual heat released during cool down from normal operating temp to 212 F approx 475. 3 million BTU.

  JANECEK, R. F. Commonwealth Edison Co. 79/11/29. App.
- 7912040297 Forwards supplementary response to be incorporated into 791018 ltr re lessons learned commitments to meet near-term requirements.

  REED, C. Commonwealth Edison Co. 79/11/30. 7pp.
- 7912040485 Submits updated schedules for installation of recirculation pump trip mods per 790329 ltr. PEOPLES.D.L. Commonwealth Edison Co. 79/11/30. 2pp.
- 7912120411 Forwards supplementary response re commitment to mest short-term requirements of Lessons Learned Task Force. REED, C. Commonwealth Edison Co. 79/11/30. 7pp.

- 7912120425 Forwards supplemental response to 791018 ltr re commitments to Lessons Learned Task Force recommendations. PEOPLES, D. L. Commonwealth Edison Co. 79/12/03. 2pp.
- 7912110380 Proposes to amend Tech Specs, extending max average planar linear heat generation rate to larger exposure values. Erreta & addenda sheets for "LOCA Analysis Rept," Tech Specs page changes & Class III fees encl.
  PEOPLES D. L. Commonwealth Edison Co. 79/12/04. 2pp.
- --7912110386 Errata & addenda sheets for "LOCA Analysis Rept."
  \* General Electric Co. NEDO-24146. 79/10/31. 3pp.
- --7912110391 Tech Spac page changes:Page BiC-1 for Dresden-2 & Figure 3.5-1 for Quad-Cities-1.

  \* Commonwealth Edison Co. 79/10/31. Spp.
- 7912140266 Forwards design drawings re water suppression sys, detection sys & Unit 1 fire pump. Drawings available in Central Files only. Hydraulic calculation info & Fairbanks morse manual describing fire pump enci.

  JANECEK, R. F. Commonwealth Edison Co. 79/12/04. 2pp.
- 7912270006 Requests that any info re loss of offsite power at facility be forwarded. Info should be submitted within 90 days of 1tr receipt.

  ZIEMANN.D.L. Operating Reactors Branch 2, 79/12/04, 3pp.
- 7912210349 Forwards cover sheet for CE-1-A, Revision 10, inadvertently omitted from 791116 transmittal.

  NAUGHTON, M. F. Gommonwealth Edison Co. 79/12/13. 2pp.
- 7912180531 Forwards info documenting evaluation of purge & vent valve operability verification. Util committed to purge & vent sus in conformance w/ARC interim position. Complete confirmatory analyses not available for 30-40 wk. PEOPLES, D. L. Commonwealth Edison Co. 79/12/14. 6pp.
- 7912190542 Forwards "Adequacy of Station Electric Distribution Bys Voltages," addressing 480-volt undervoltage conditions. JANECEK.R.F. Commonwealth Edison Co. 79/12/14, 1p.
- --7912190545 "Adequacy of Station Electric Distribution Sys Voltages." \* Commonwealth Edison Co. 79/12/14. Spp.
- 7912270469 Forwards response to NRC request for add1 info on TMI Lessons Learned Task Force Recommendations 2.1.7a & 2.1.7b. PEOPLES, D. L. Commonwealth Edison Co. 79/12/14. App.
- 7912270470 Advises that qualification program for remaining purge & vent containment valves is in progress Drasden & Quad-Cities butterfly valves will close, regardless of degree of opening. Response to NRC interim position encl.
  PEOPLES, D. L. Commonwealth Edison Co. 79/12/14. 6pp.
- 7912270597 Advises of compliance w/Catagory A THI Lessons Learned Task Force items identified in NRC 790913 & 1030 ltrs. Compliance will be achieved by 800101, or prior to return to power for units in outages on 800101.
  PEOPLES, D. L. Commonwealth Edison Co. 79/12/17. 1p.
- 7912310370 Forwards Sargent & Lundy rept indicating sufficiency of torus sway rods. Rubber mats are glued to steel bettery rack & glass battery cells sit on rubber mats, providing factor of 3 conservation in coefficient of friction.

  JANECEK.R. F. Commonwealth Edison Co. 79/12/18, 2pp.
- 7912270459 Confirms discussions re proposed Tach Epec amend to extend max average planar linear heat-generation rate curves. No fuel type is expected to exceed peak pellet exposure above 40,000 MHD/BT.

  JANECEK, R. F. Commonwealth Edison Co. 79/12/20. ip.
- 79i2280533 Responds to NRC 79i03i request for plant-unique implementation schedule for additional condensation tests re Mark I full scale test facility. Analysis dependent on final resolution of acceptance criteria.
  PEOPLES.D.L. Commonwealth Edison Co. 79/12/20. 2pp.
- 7912310348 Forwards revised pages to CE-1-A, "Comm Ed GA Program for Nuclear Generating Stations:" Revision 11.

  JANECEK.R.F. Commonwealth Edison Co. 79/12/20. 1p.
- ---7912310359 Revised pages to CE-1-A, "Comm Ed GA Program for Nuclear Generating Stations," Revision 11. \* Commonwealth Edison Co. CE-1-A, 79/11/21, 16pp.

- G. Inspection reports, IE Bulletins & correspondence
- 7912050013 Forwards IE Insp Repts 50-010/79-19,50-237/79-23 & 50-249/79-21 on 790904-28 & notice of violation. HEISHMAN,R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/10/18. 2pp.
- --7912050020 Notice of violation from insp on 790904-28.

  \* Region 3, Chicago, Office of the Director. 79/10/15. 2pp.
- --7912050037 IE Insp Repts 50-010/79-19,50-237/79-23 & BO-249/79-21 on 790704-28. Noncompliance noted: failure to control access to high radiation areas & failure to follow procedures. BARKER, J. L. NALKER, R. D. SPEBRARD, R. L. Region 3: Chicago, Office of the Director. 79/10/15. 9pp.
- 7912050204 Notice of violation from insp on 790904-28.
  \* Region 3, Chicago, Office of the Director. 79/10/15. 2pp.
- 7912200344 Forwards waste packaging Insp Rept 79-02A on 790925-26. No noncompliance noted.
  SUTHERLAND, J. T. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 79/11/07. 2pp.
- --7912200395 Waste packaging Insp Rept 79-02A. No noncompliance noted.
  Major areas inspected: shipping paper & DOT placarding
  requirements, radiation levels, removable contamination, DQT &
  NRC package features.
  BROHN.R.A. Region 2, Atlanta, Office of the Director. 79/11/06.
- 7912130679 Forwards IE Insp Repts 50-010/79-21,50-237/79-24 & 50-247/79-22 on 791009-12 & 15-18 & notice of violation, Insp repts & notice of violation withheld (ref 10CFR2,790), HIND, J.A. Region 3, Chicago, Bafeguards Branch. 79/11/09, 2pp.
- 7912050106 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required.
  KEPPLER.J.G. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912100213 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required.
  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912110597 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required.

  KEPPLER, J. C. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912210025 Forwards IE Insp Repts 50-237/79-25 & 50-249/79-23 on 790917-18 & 24-27. No noncompliance noted.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director, 79/11/16, 2pp.
- --7912210031 IE Insp Repts 50-237/79-25 & 50-249/79-23 on 790917-18 & 24-27. No noncompliance noted, Mejor areas inspected; cooling lake const, sail borings on north dike & review of monthly surveillance repts on dike structure.

  QALLACHER.E. J., DEBTMANN.M.J. Region 3, Chicago, Office of the Director, HAYES.D.W. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/11/14. 26pp.
- 7912180013 Notifies of delay in implementation of IE Bulletin 79-14 re accessible areas comparison & evaluation phase. Current program provides for earliest detection & evaluation of significant discrepancies. PEOPLES: D. L. Commonwealth Edison Co. 79/11/19. 2pp.
- 7912050350 Forwards IE Bulletin 79-26, "Boron Loss From BHR Control Slades." Response required.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/20.

  1p.
- 7912040009 Ack receipt of 79110B ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/79-19, 50-237/79-23 & 50-247/79-21.
  HEISHMAN.R.F. Region 3. Chicago, Reactor Operations Nuclear Bupport Branch. 79/11/21. 1p.
- --7912040011 Responds to NRC 791018 ltr re violations noted in IE Insp Repts 50-010/79-19,50-237/79-23 & 50-249/79-21. Corrective actions: parsonnel instructed to lock door to high radiation area. PEOPLES, D. L. Commonwealth Edison Co. 79/11/08. 5pp.

- 7912100417 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Sreak Detection Equipment on BMRs." No written response raquired.

  KEPPLER. J. G. Region 3, Chicago. Office of the Director. 79/11/26.
- 7912140187 Forwards IE Circular 79-23. "Motor Starters & Contactors Failed to Operate." No written response required. KEPPLER.J. G. Region 3. Chicago. Office of the Director. 79/11/26.
- 7912110395 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sent by NRC to licensees.

  KEPPLER, J. G. Region 3, Chicago. Office of the Director. 79/11/28.
- 7912190199 Forwards IE Bulistin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Written response required.
  KEPPLER.J. Q. Region 3. Chicago, Office of the Director. 79/11/30.
- 7912140056 Forwards IE info Notice 79-30, "Reporting of Defects & Noncompliances: 10CFR21." No action or response required.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/12/06.
- 7912200086 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. KEPPLER.J. 9. Region 3, Chicago, Office of the Director. 79/12/10. 1s.
- 79:12200443 Notification of 79:233 meeting w/util to discuss IE Builetin 79-02 anchor bolt & base plate analysis.

  JORDAN.E.L. Division of Reactor Operations Inspections. 79/12/11.
- R. Periodic operating reports & related correspondence
- 7912180377 Forwards monthly operating repts for Nov 1979. STEPHENSON B. B. Commonwealth Edison Co. 79/12/07. 1p.
- --7912180386 Monthly operating rapts for Nov 1979. CIESZKIENICZ. S. Commonwealth Edison Co. 79/12/03. 19pp.
- 8. Reportable occurrences, LERs & related correspondence
- 791212006B PND-III-79-025; on 791025, essential eves motor generator set tripped resulting in tripping of Unit 3 reactor. Caused by slamming of essential eves electrical panel door. CREED.J. DONAHUE.J.F., HND, J.A. Region 3, Chicago, Office of the Director. 79/10/26. 2pp.
- 7912170166 PNO-III-79-25A: threatening telephone calls came from courtcommitted patient. All affected licensees notified. BELANGER, J. DONANUE. J. F. , HIND, J. A. Region 3. Chicago, Office of the Director. 79/10/29. 1p.
- 7912030008 PNO-III-79-031: on 791023, Federal Highway Administration Bureau of Motor Carrier Bafety issued notice of shipping violation for improper packaging of low specific activity radioactive matl. Util fined.

  BARKER, J.L., SPESSARD, R., HEISHMAN, R.F., Region 3, Chicago, Office of the Director. 79/11/01. 1p.
- 7912200546 PNO-III-79-036: on 791110.Unit 3 tripped while performance of low vacuum trip surveillance in progress.Unit 2 tripped when instrument mechanic isolated feedwater pump suction transmitter resulting in feedwater pump tripping.

  BARKER.J. : SPESSARD.R. Region 3. Chicago. Office of the Director. 79/11/13. 2pp.
- 7912030192 Forwards LER 79-060/03L-0. BTEPHENSON, B. B. Commonwealth Edison Co. 79/11/28. 1p.
- --7912030196 LER 79-060/03L-0: on 791030, while Units 2 & 3 were at steady power discovered that annual requirement to cycle testable valves in flow seth for fire water supply had not been performed Coursed by failure to identify existing procedure. HERBERT, B. Commonwealth Edison Co. 79/11/28. ip.
- 7912140462 Forwards LER 79-063/03L-0. BTEPHENSON, B. B. Commonwealth Edison Co. 79/11/30. 1p.

- --7912140469 LER 79-063/03L-O: on 791114, during weekly surveillance, source range monitor calibr initiated rod block at 10265 counts per second. Caused by electronic instrument drift. Bource range monitor readjusted & will be tested weekly.

  KURCHYNSKY, M. Commonwealth Edison Co. 79/11/30. 2pp.
- 7912140378 Forwards LER 79-061/03L-0. STEPHENSON, B. B. Commonwealth Edison Co. 79/12/05. 1p.
- --7912140404 LER 79-061/03L-O:on 791109, during normal operation, found Cardox storage tank below Tech Spac limit, Caused by drift in spring setpoint of pilot valve 2009197. Spring was adjusted. HOLLAND.P. Commonwealth Edison Co. 79/12/06. Spp.
- 7912140459 Forwards LER 79-062/03L-0. BTEPHENSON.B.B. Commonwealth Edison Co. 79/12/06. 1p.
- 7912270345 Responds to NRC requises for info re loss of offsite power events at facility. Forwards answers to questions re 651112 t 780122 events.LER 78-003/03L-0.780122 deviation rept t list of 345 kV & 138 kV line failures during 1974-1979. JANECEK.R.F. Commonwealth Edison Co. 79/12/19. 21sp.
- 7912270254 Forwards LER 79-064/03L-0. STEPHENSON, B. B. Commonwealth Edison Co. 79/12/21. 1p.
- --7912270265 LER 79-064/03L-0: on 791124, torus-to-drywell vacuum breaker found inoperable. Caused by swollen teflon shaft bushings. Bushings machined to required clearance & study initiated reapplicability of teflon as bushing material. DUNBAR, J. Commonwealth Edison Co. 79/12/21. 2pp.
- DOCKET 50-243 OREODN STATE UNIV. RESEARCH REACTOR
  F. Security, medical, emergency & fire protection plans
- 7912120205 Forwards draft Reg Quids 5. XX. "Std Format & Content for Licenses Physical Security Plan for Protection of SNM of Moderate or Low Strategic Bignificance." W/o encl. REID.R. W. Operating Reactors Branch 4 (Pre 791030). 79/08/22.
- P. Operating license stage documents & correspondence
- 7912260227 Forwards safety evaluation on mode to TRIGA reactor console electronics.

  LATNAB. G. Plant Bystems Branch. 79/11/19. ip.
- --7912260233 Bafety evaluation re proposed mods to TRIQA reactor console electronics.

  \* Plant Bustems Branch. 79/11/19. 6PP.
- Q. Inspection reports. IE Bulletins & correspondence
- 7912110100 Forwards IE Insp. Rept 50-243/79-02 No noncompliance noted. Insp. rept withheld (ref. 100FR2.790). NORDERHAUD, L. R. Region 5. Ban Francisco. Bafaguards Branch. 79/11/13, 2pp.
- DUCKET 50-244 ROBERT EMMET GINNA NUCLEAR PLANT, UNIT 1
  F. Security, medical, emergency & fire protection plane
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team raview objectives.Provides guidance for improving licensee surgency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.

  ORIMES, B.K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- 7912270392 Responds to NRC 790214 fire protection safety evaluation rept requirements for addl info re doors, piping & duct penstrations, prafire strategies & exposed structural steel. WHITE, L. D. Rochester Que & Electric Corp. 79/12/18. 2pp.
- 7912310391 Forwards "Bare Bhutdown Fire Study."
  WHITE, L. D. Ruchester Gas & Electric Corp. 79/12/28. 1p.
- --7912310394 "Bafe Shutdown Fire Study."

  \* Rochester Oas & Electric Corp. 79/12/31. 60pp.

## O. Adjudicatory correspondence

- 791211003B Confirms receipt of encl 790329 petition to suspend OLs for all PWRs. Forwards FR notice indicating that petition will be treated in accordance w/10CFR2.206.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/23. ip.
- ---7912110126 Notice of request for action pursuant to 10CFR2.206 re Environ Coalition on Nuclear Power 790327 patition requesting suspension of all DLs for PWRs. HULLER, D.R. Office of Nuclear Reactor Regulation. 79/11/23, 38pp.
- 7912200522 Bipulation terminating proceeding as to Rochester Committee for Scientific Info.Inc.RCBI agrees that applicant has fulfilled Paragraphs 1 & 4 requirements of 740312 stipulation. Gertificate of Bvc encl.
  ROBENSAUM.M.E. Rochester Committee for Bcientific Information.
  VOIGT.M.H. Rochester Committee for Bcientific Information.
  Lamb, Leiby & MacRae. 79/12/10. 4pp.

## H. General correspondence

- 7912140167 Concurs w/updated Certificate of Bvc. Requests that RN Pinkney of Ontario.NY be added to svc list & served copies of all applications for licenses & amend. FARON.R. 8. LeBoeuf, Lamb. Leiby & MacRae. 79/11/20. 1p.
- 7912270012 Responds to ltr re impact of TMI incident on facility. Forwards NURE9-0878.W/o encl. DENTON, H. R. Office of Nuclear Reactor Regulation. 79/12/06. 2pp.
- 7912270068 Responds to ltr re impact of TMI incident on facility.
  Forwards NUREO-0578 W/o encl.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/12/06. 2pp.
- 7912270365 Forwards Certificate of Svc omitted from time stamped 1tr noting filing for util. Certificate of Svc should be placed w/filing.

  ANDRAS, R. F. LeBoeuf, Lamb, Leiby & MacRae. 79/12/20. 3pp.

## J. Insurance & indomnity information

e e tiv⊈ a Compositorio

- 7912180580 Bubmits list of complainants re Dec 1973-Feb 1974 overexposure allegation.
  ALTON: C. O. American Nuclear Insurers. 79/12/12. 1p.
- P. Operating license stage documents & correspondence
- 7911090248 "Summary of Operating Experience U/Recirculating Steam Generators." EISENHUT, D. C. Division of Operating Reactors. NUREG-0523, 79/01/31. 89pp.
- 7908030878 Forwards list of seismic projects. Reviews findings re safety-related piping sys reamslysis for plants w/algebraically combined earthquake components discussed. HERRING, K. B. Engineering Branch (Pre 791030), 79/06/15. 6pp.
- 7912080178 Discusses NRC review of LERs & Tech Spec requirements recontrol RPI sys at Westinghouse PWRs. Requests Tech Specs review to ensure requirement for rod maint to within +/- 12 steps indicated & RPI sys verified accurate within 12 steps. SCHMENCER, A. Operating Reactors Branch 1. 79/10/29. 7pp.
- 7912100189 Discusses NRC 791101 meeting w/representatives of N898 vendors & fuel suppliers re discussion of respective portions of ECCB evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EISENHUT, D. Q. Division of Operating Reactors. 79/11/09. 65pp.
- --7912100285 Responds to NRC 791101 request re noncompliance of Westinghouse ECCS evaluation model under requirements of 10CFR80 App K. Evaluation of three fuel rod models indicates no safety problems for Hestinghouse plants.

  ANDERSON, T. M. Westinghouse Electric Corp. 79/11/02. 4pp.
- --79:2:00330 Responds to NRC 79:101 request re CRNL cladding swelling & rupture data. Review of analytical models & tests indicates compliance w/10CFR50 App K. All GE space for calculated yeak cladding temp remain unchanged.

  BUCHHOLZ, R. H. General Electric Co. 79/12/07. 2pp.

- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of iOCFR30. 46 satisfied.

  DMBLEY, G.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/11/02. Spp.
- --7912100456 Forwards addl info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model.

  No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results.

  DMBLEV,O.F. Exxon Nuclear Co., Inc. (subs. of.Exxon Corp.).

  79/11/04. 22pp.
- 7912040144 Summary of 791101 meeting w/util in Bethesda.HD re plans to insert mixed oxide fuel assemblies into plant core during Mar 1980 refueling outage. SHEA.J.J. Dpsrating Reactors Branch 2. 79/11/16. 17pp.
- 7912110030 Forwards updated lists of SEP topics not requiring site review due to engoing generic licensing activities outside SEP or because of inapplicability to facility. ZIEMANN.D.L. Operating Reactors Branch 2, 79/11/16. Opp.
- 7912170079 Requests add1 info rs review of 791018 submittal on tendon surveillance program,
  ZIEMANN.D.L. Operating Reactors Branch 2, 79/11/20, 3pp.
- 7912060117 Summary of 791109 telcon w/util re lessons learned implementation.
  SHEA, J. J. Operating Reactors Branch 2. 79/11/21. 6pp.
- 7912050494 Forwards response to NRC 791022 request for evaluation of auxiliary feedwater sys & informs that addl info reauxiliary feedwater sys flow requirements will be forwarded in seven months.

  WHITE: L. D. Rochester Gas & Electric Corp. 79/11/2B. 2ipp.
- 7912120447 Responds to NRG request for structural model of containment structure & internals for use in BEP seismic analysis.
  Advises that appropriate sketches & models have been sent to LLL. Application for withholding info encl.
  WHITE, L. D. Rochester Oas & Electric Corp. 79/11/30. 6pp.
- 7912190057 Forwards safety evaluation re potential for water hammer in feedwater piping & technical evaluation by EG&O.

  LAINAS.O. Flant Systems Branch. 79/12/03. 2pp.
- --7912190062 Safety evaluation re-potential for water hammer in feedwater piping. Acceptable precautions taken to minimize water hammer occurrence. \* Office of Nuclear Reactor Regulation. 79/11/30. 3pp.
- --7912190066 "Steam Generator Water Hummer Technical Evaluation." \* E0 & G. Inc. 79/10/31. 15pp.
- 7912120450 Forwards "Design Analysis Adequacy of Station Electric Distribution Sys Voltages." Some operating conditions have potential to cause spurious separations of safety buses from offsite power source. Available in Central Files.
  WHITE.L.D. Rochester Ges & Electric Corp. 79/12/06. 2pp.
- 7912120289 Responds to 791105 ltr re control rod position indication. Present Teck Bpec definition of inoperable control rod includes statement re misalignment by more than 15 inches w/bank.

  WHITE.L.D. Baltimore Gas & Electric Co. 79/12/07. ip.
- 79:2120445 Notifies that util concurs w/NRC 79:113 draft evaluation of SEP Topic III-B.C. "Irradiation Damage:Use of Sensitized Stainless Steel & Fatigue Resistance.
  WHITE.L.D. Rochester Gas & Electric Corp. 79/12/07. 1p.
- 7912180418 Forwards evaluation of prestressed tendon forces, in response to NRC 791120 ltr.
  WHITE, L. D. Rochester Gas & Electric Corp. 79/12/12, 2pp.
- ~-7912180426 "Evaluation of Prestressed Tendon Forces."

  \* Gilbert/Commonwealth Cos. GAI-2074. 79/11/20. 300pp.
- 7912180516 Responds to NRC request for info re auxiliary feedwater sys & TM1 short-term Lessons Learned Task Force requirements. Existing auxiliary feedwater flow indication complies w/clarification C. i.Drawing available in Central Files only. WHITE.L.D. Rochester Qas & Electric Corp. 79/12/14. 2pp.

- 7912180527 Responds to NRC 791023 ltr re containment purging during normal plant operations. Purping done to improve working or environ conditions. Valve openings restricted. Ventilation isolation sys modified requiring valve reset individually. HHITE.L. D. Rochester Gas & Electric Corp. 79/12/14. 29p.
- 7912210380 Forwards Dilbert Associates Drawings D-001.012, Revision 1. D-001-022, Revision 13. D-002-004. Revision 6 & D-001-032. Revision 7 in response to NRC request for containment drawings. W/e encl. Rochester Gas & Electric Corp. 79/12/14.
- 79122B0147 Advises of waiver of Class III license amend fee on 791114 application for Tech Spec change re fire protection. Refund being processed.
  MILLER, W.D. License Fee Management Branch. 79/12/14. 1p.
- 7912280501 Forwards three addl copies & one aperture card for Drawing 33013-544, Revision 4. WHITE, L. D. Rochester Gas & Electric Corp. 79/12/19. 1p.
- 7912280198 Forwards application to amend License DPR-18.
  VOIGT, H. H. LeBosuf, Lamb, Leiby & MacRae. 79/12/20. 2pp.
- --7912280206 Application to amend License DPR-18, changing Tech Spers remixed oxide fuel assemblies in fuel to be loaded for Cycle NHITE, L. D. Rochester Gas & Electric Corp. 79/12/14. 17pp.
- ---7912280213 "Fuel & LOCA Evaluation of Mixed Oxide Fuel Assemblies." SKARITKA, J. Wastinghouse Electric Corp. 79/12/31. 10pp.
- --7912280222 "Plant Transient Analysis," Revision 1.
  MARDOMSKI,F.J., KAHN.J.D., LEACH,C.E. Exxon Nuclear Co., Inc.
  (subs. of Exxon Corp.), XN-NF-77-40, 79/07/03, 21pp.
- --7912280232 "Addendum to Criticality Analysis for Fuel Storage Racks to Address Storage of Mixed Oride Fuel Assemblies." SCHHARTZ, M. H. Pickard Lowe & Carrick, Inc. 79/11/28. 18pp.
- --79122B0240 "Cycle 10 SAR W/Mixed Oxide Assemblies."

  JOHNBON, B. L., BUSSELHAN, O. J., SOFER, O. A. Exxon Nuclear Co., Inc.
  (subs. of Exxon Corp.), XN-NF-79-103, 79/12/14, 32pp.
- G. Inspection reports. IE Bulletins & correspondence
- 7912140047 Responds to IE Bulletin 79-23.No connection exists between kVA generator & low kVA rated transformers. Potential for emergency generator failure will be determined by 24-h load test before end of next refueling outage.

  HHITE, L. D. Rochester Oas & Electric Corp. 79/10/19. 54pp.
- 7912170247 Responds to IE Bulletin 79-17, "Pipe Gracks in Stagnant Borated Water Sys at PWR Plants." Examination of stagnant portions of sys not previously performed were completed on 791010. WHITE, L. D. Rockester Gas & Electric Corp. 79/10/24. 2pp.
- 7912040048 Forwards response to 1E Bulletin 79-14, "Seismic Analyses for As-Built Safety-Related Piping Sys." Plans to defer inspuntil resins are removed.

  WHITE, L. D. Rochester Gas & Electric Corp. 79/10/30. 20pp.
- 7912210357 Forwards IE Insp Rept 50-244/79-13 on 790917-20. No noncompliance noted.
  BRUNNER.E.J. Region i, Philadelphia, Reactor Operations Nuclear Support Branch. 79/11/01. 2pp.
- --7912210363 IE Insp Rept 50-244/79-13 on 790917-20 No noncompliance noted Major areas inspected; plant operations, nonroutine event reporting program & potential failure mechanism of pressurizer power operated relief valve yoke.

  MARKOMSKI.R.S. Region i. Philadelphia, Office of the Director.

  KEIMIG.R.R. Region i. Philadelphia, Reactor Operations Nuclear Support Branch. 79/10/24. Spp.
- 7912050061 Forwards 1E Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required.

  ORIER. B. H. Region 1, Philadelphia, Office of the Director, 79/11/16. 1p.
- 7912030304 Forwards IE Info Notice 79-27, "Steam Cenerator Tube Ruptures at Two PWR Plants." No response required. CRIER.B.H. Region i, Philadelphia, Office of the Director. 79/11/16. ip.

- 7912100155 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Bupport Loads." No response required. GRIER, B.H. Region 1. Philadelphia, Office of the Director. 79/11/16. ip.
- 7912110473 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required.
  ORIER, B. H. Region i, Philadelphia, Office of the Director.
  79/11/19. ip.
- 79:2050330 Forwards IE Bulletin 79-26, "Boron Loss From BMR Control Blades." No response required.

  ORIER, B. H. Region i, Philadelphia, Office of the Director.
  79/11/20. ip.
- 7912060597 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BMRs." No response required.
  ORIGR.B.H. Region i. Philadelphia. Office of the Director.
  79/11/26. ip.
- 7912110091 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/11/26. ip.
- 7912260033 Responds to IE Bulletin 79-17, Revision 1 re pipe cracks in stagnant borated water sys. Will inspect seven add1 welds during next annual refueling outage. During interim monthly inspect will be conducted.
  WHITE, L. D. Rochester Gas & Electric Corp. 79/11/26. 2pp.
- 7912190094 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation." Written response required. ORIER, B. H. Region 1, Philadelphia, Office of the Birector. 79/11/30. ip.
- 7912310280 Forwards IE Info Notice 79-30. "Reporting of Defects & Noncompliances, 10CFR21." No action required.
  GRIER, B. H. Region i, Philadelphia, Office of the Director.
  79/12/06. 4pp.
- 7912190769 Forwards IE Bulletin 79-28, "Possible Helfunction of Namco Model EA180 Limit Switches at Elevated Temps." Written response required. GRIER, B. H. Region 1. Philadelphia, Office of the Director. 79/12/07. 1p.
- 7912280022 Forwards response to IE Bulletin 79-02, Revision 2. "Pipe Bupport Base Plate Designs Using Concrete Expansion Anchor Bolts." Testing program initiated for supports using structural steel shapes.

  WHITE, L. D. Rochester Gas & Electric Corp. 79/12/07. Spp.
- 79:12280244 Forwards IE Info Notice 79-3:. "Use of Incorrect Amplified Response Spectra." No written response required. ORIER, B. H. Region i. Philadelphia. Office of the Director. 79/12/13. 1.
- R. Periodic operating reports & related correspondence
- 7912180348 Forwards monthly operating rept for Nov 1979. SNOW.B.A. Rochester Gas & Electric Corp. 79/12/11. 1p.
- --7912180351 Monthly operating rept for Nov 1979. MCNAMARA, A. E. Rochester Oas & Electric Corp. 79/12/11. 5pp.
- 8. Reportable occurrences, LERs & related correspondence
- 7912130526 RO: on 791201. air ejector radiation monitor was detected trending upwards on radiation monitoring recorder. Leak test measured approx 0.007 gallons/minute. Facility shut down on 791203. SNOW, B. A. Rochaster Que & Electric Corp. 79/12/03. ip.
- 7912270603 RO 79-023: on 791207, liquid penetrant examination of safe-end of 4-inch relief nozzle adjacent to nozzle to safe-end weld revealed 6-inch long indication. Further analysis required to determine cause.

  BNOW, B. A. Rochester Ose & Electric Corp. 79/12/11. 2pp.
- 7912190515 Forwards LER 79-022/01T-0.
  WHITE, L. D. Rochester Gas & Electric Corp. 79/12/14. 1p.

- -791219052: LER 79-022/01T-0: on 791201, during normal operations, found two leaking tubes & eleven other tubes w/pluggable defects.

  Caused by possible thermal, hydraulic & mechanical loading in wadge area & by possible residuel caustics concentration.

  CURTIS, A. E. Baltimore Gas & Electric Co. 79/12/14. 2pp.
- 7912270434 Forwards LER 79-023/017-0.
  WHITE, L. D. Rochester Gas & Electric Corp. 79/12/21. 15.
- DOCKET 50-245 MILLSTONE NUCLEAR POWER STATION, UNIT 1 F. Socurity, medical, emergency & fire protection plans
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team raview objectives. Provides guidance for improving licensee emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions, ORIMES.B.K. Emergency Preparedness Task Force. 79/11/23, 30pp.
- 7912130455 Forwards add1 response to NRC 790913 & 1030 ltrs re improved in-plant iodine instrumentation under accident conditions. Air monitors in control room area at each site will be installed by BOO101. Improved portable sys will be developed. COUNBIL. M. O. Northeast Utilities. 79/12/07. 1p.
- 7912310392 Forwards results of review of util 790731 mesponse re incomplete Item 3.2.2 of fire protection mafety evaluation, LAINAS, 0. Plant Systems Branch. 79/12/17, 4pp.
- P. Operating license stage documents & correspondence
- 7908030578 Forwards list of seismic projects Reviews findings re safety-related piping sys reenelysis for plants w/algebraically combined earthquake components discussed. HERRING, K. S. Engineering Branch (Pre 791030). 79/06/15. App.
- 7912100189 Discusses NRC 791101 meeting w/representatives of NBSS vandors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EIBENHUT, D. Q. Division of Operating Reactors, 79/11/09. 65pp.
- -7912100255 Responds to NRC 791101 request re noncompliance of Westinghouse ECCB evaluation model under requirements of 100FR30 App K. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants. ANDERBON, T. M. Westinghouse Electric Corp. 79/11/02, App.
- --7912100330 Responds to NRC 791101 request re ORNL cladding swelling & rupture data. Review of analytical models & tests indicates compilance w/100FR50 App K. All QE specs for calculated peak cladding temp remain unchanged.

  BUCHHOLZ, R. H. General Electric Co. 79/12/07. 2pp.
- ---7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of iOCFR50.46 satisfied.

  OMBLEY, O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.), 79/11/02. 5pp.
- ---7912100456 Forwards addl info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. DMSLEY.0.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/04. 22pp.
- 7912110029 Forwards updated lists of BEP topics not requiring site review due to ongoing generic licensing activities outside BEP or because of inapplicability to facility.

  ZIEMANN, D. L. Uperating Reactors Branch 2, 79/11/16, 8pp.
- 7912050504 Bubmits corrected info submitted in 79091B ltr concerning Tech Specs shutdown margin in startup physics testing program for Cycle 7 rept.

  COUNBIL. N. G. Northeast Utilities, 79/11/20, 1p.
- 7912030206 Forwards seismic design info in response to NRC 790828-29 meeting request re BEP seismic review Seventy-seven oversize drawings encl. Drawings available in Central Files only. COUNSIL, W. G. Northeast Utilities, 79/11/26, 320pp.

- 7912040225 Forwards response to NRC questions re SEP Topic VI-5 re combustible gas control. Two drawings encl. available in Central Files only. COUNBIL. N. O. Northeast Utilities. 79/11/28. 5pp.
- 7912190261 Discusses commitment made by CT Yankee Atomic Power Co & Northwest Nuclear Energy Co to implement automatic initiation of auxiliary feedwater. Addresses util conclusion that implementation not necessary for safe operation. COUNSIL.W.Q. Northwast Utilities. 79/11/30. 6pp.
- 7912130321 Discusses interim procedures for Recommendation 2.1.8.b. until high-range capability is available re increased range of radiation monitors requirement. COUNSIL.W. Q. Northeast Utilities. 79/12/07. 4pp.
- 7712180279 Provides commitment to implement Recommendation 2.2.1.b re shift technical advisor in compliance w/short-term Lessons Learned Tesk Force requirements. Hill submit compliance for containment pressure indications & RGB venting by 810101. CDUNBIL. N. O. Northeast Utilities. 79/12/10. 2pp.
- 7912170294 Formally documents 791211 verbal commitments to develop procedures for Item 2.i.8.b re increased range of radiation monitors in accordance w/rriteria delineated in NRC 791030 ltr to all operating nuclear power plants. COUNBIL, H. G., FEE, H. F. Connecticut Yankee Atomic Power Co. 79/12/12. 2pp.
- 7912260276 Reaffirms util commitment to implement short-term recommendations of TMI Lessons Learned Task Force by 800101, except for Item 2.1.9. Commitment contingent upon external vendors supplying equipment on schedule.

  GOUNSIL, W. Q. Northeast Utilities. 79/12/17. Spp.
- 7912270293 Discusses acceptance criteria for Mark I long-term program. Elaborates on LQ Sobon 791130 ltr to DQ Eisenhot by providing plant-unique info on program & by listing areas of concern which leopardize compliance w/criteria. COUNBIL, H. Q. Northeast Utilities. 79/12/17. 3pp.
- 79;23:0376 Provides add1 info for NRC safety evaluation of Amend 64 to provisional OL. Inservice insp & testing program for Class 1,2 & 3 components will be revised. Diagram snc1. COUNBIL.M.O. Northeast Utilities. 79/12/19, Spp.
- Q. Imagection reports, IE Bulletine & correspondence
- 7912170228 Responds to IE Bullstin 79-24, "Frozen Lines." Review of freeze protection of safety-related sys indicates existing measures adequate.

  COUNBIL, M. C. Northeast Utilities. 79/10/31. ip.
- 7912130383 Forwards response to IE Bulletin 79-14. "Seismic Analysis for As-Built Safety-Related Piping Sys." Updated rept of progress in verifying seismic analysis input for safety-related piping sys encl.
  COUNSIL.M.C. Northeast Utilities. 79/11/08. 9pp.
- 7912030039 Forwards IE Circular 79-22, "Stroke Times for Power Operated Reilef Valves." No response required.
  ORIER, B.H. Region 1, Philadelphia, Office of the Director.
  79/11/16. ip.
- 7912050266 Forwards IE Info Notice 79-27, "Steam Cenerator Tube Ruptures at Two PMR Plants." No response required. ORIER, B.H. Region 1. Philadelphia, Office of the Director. 79/11/16. 1p.
- 7912100131 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pips Support Loads," No response required. GRIER, B. H. Region i, Philadelphia, Office of the Director. 79/11/16, ip.
- 7912110422 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required. GRIER, B. H. Region i, Philadelphia, Office of the Director. 79/11/19, 1p.
- 7912050258 Forwards IE Bullstin 79-26, "Boron Loss From BWR Control Blades." Response required.
  ORIER.B.H. Region I. Philadelphia. Office of the Director.
  79/11/20. ip.
- 7912060879 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BHRs." No response required.

  ORIER, B. H. Region 1, Philadelphia, Office of the Director.

  79/11/26, 1p.

- 12110060 Forwards IE Circular 79-23. "Motor Starters & Contactors Failed to Operate." No response required. ORIER.B.M. Region i, Philadelphia. Office of the Director. 79/11/26. 1p.
- 12190039 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Written response required. ORIER.B.H. Region 1. Philadelphia, Office of the Director. 79/11/30. 1p.
- 12310226 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances:10CFH21." No action required. ORIER.B.M. Region i, Philadelphia, Office of the Director. 79/12/06. 4pp.
- 012190754 Forwards IE Bulletin 79-20, "Possible Malfunction of Namco Model EAIGO Limit Switches at Elevated Temps." Written response required. ORIER.B.H. 'Region 1, Philadelphia. Office of the Director. 79/12/07. 1p.
- P12280207 Forwards IE Info Notice 79-31. "Use of Incorrect Amplified Response Egectra." No written response required. GRIER.B. H. Region 1, Philadelphia. Office of the Director. 79/12/13. 1p.
- Periodic operating reports & related correspondence
- 952180363 Forwards sonthly operating rept for Nov 1979. OPEKA, J. F. Northeast Utilities. 79/12/07. ip.
- -7912180365 Monthly operating rept for Nov 1979. YOUNG.R. Northeast Utilities. 79/12/04. 61
- Reportable occurrences, LERs & related correspondence
- P12030104 PNS-I-79-007: on 791108, forcer contractor employee was arrested after making threats against former supervisors in facility parking lot Shotyon found in car of employee. BHODLOSKY, T. Office of Inspection & Enforcement, Diffice of the Director, XEIMIO, R., BRUNNER, E. J. Region I, Philadelphia, Office of the Director, 79/11/08, ip.
- 912180309 PNG-I-79-022:on 791128, const worker injured in fall from scaffold at plant site. Extent of injuries unknown. No radioactive satl involved.
  ZIHHERNAN.R.P., KEIMIG.R.R., BRUNNER, E. J. Region i, Philadelphia, Office of the Director. 79/11/29. ip.
- 912070343 Forwards LER 79-032/03L-0. DPEKA,J.F. Northeast Utilities. 79/12/03. ip.
- -7912070346 LER 79-032/03L-0: on 791106, during routine monthly surveillance on reactor protection sys drywell pressure switches, discovered PS 2305-16218 & PS 2205-16216 tripped at values outside Tech Specs. Caused by setpoint drift. YOUNG, R. H. Northeast Utilities. 79/12/03. 3pp.
- 912100299 Forward: LER 79-033/03L-0. OPEKA,J.F. Northeast Utilities. 79/12/04. 3pp.
- -7912100304 LER 79-033/03L-0:on 791113, while performing routine survoillance, main steam line P switch failed to trip at proper setpoint Caused by setpoint drift. Switch adjusted & satisfacturily tested.
  YOUNG, R. H. Northeast Utilities. 79/12/04. ip.
- 912270515 Forwards LER 79-034/03L-0. OPEXA.J.F. Northeast Utilities. 79/12/14. 3pp.
- -7912270542 LER 79-034L-0: on 791115, while performing routine surveillance, electrical fault in motor controller rendered LCPI inboard isolation stop valve inoperable. Caused by contactor arcing. YOUNG,R.H. Northeast Utilities. 79/12/14. 1p.
- OCKET 50-246 ADVANCED CRITICAL REACTOR EXPERIMENT . Operating license stage documents & correspondence
- 912270469 Forwards response to NRC request for addI info on TMI Lessons Learned Task Force Recommendations 2.1,7a & 2.1.7b. PEOPLES.D.L. Commonwealth Edison Co. 79/12/14. Spp.

- 7912270597 Advises of compliance w/Catagory A THI Lessons Learned Task Force items (dentified in NRC 770713 & 1030 ltrs. Compliance will be achieved by 800101, or prior to return to power for units in outages on 800101.
  PEOPLES, D. L. Commonwealth Edison Co. 79/12/17. ip.
- DOCKET 50-247 INDIAN POINT STATION, UNIT 2
- F. Security, medical, emergency & fire protection plans
- 7912180335 Notifies of delay in Plant Bys Branch Team i evaluations of facility fire protection sys. Outlines of assistance needed encl. LAINAB, Q. Plant Systems Branch. 79/11/16. Spp.
- 7912170241 Discusses proposed task force review of emergency preparadness. Task force should study alternatives for reduction of probability & consequences of severe accident. EISEMANT, D. G. Division of Operating Reactors, 79/11/21.
- 7912200022 Discusses NRC 791109 meeting re emergency preparadness team review objectives. Provides guidance for improving licenses emergency preparadness & assuring capability of offsite agencies to take appropriate emergency actions. GRINES, B.K., COLLINS, H., SNIEZEK, J. Emergency Preparadness Task Force. 79/11/23. 30pp.
- 7912200122 Notification of 791205 meeting w/util in Hethesda, MD, to review emergency preparedness capabilities. List of NRC considerations encl. EISENHUT, D. G. Blvision of Operating Reactors. 79/11/29. 3pp.
- 7912260003 Notification of 791218 menting w/util in Ossining.NY re emergency planning. OLSHAN.L.N. Operating Reactors Branch 1. 79/12/07. 3pp.
- G. Adjudicatory correspondence
- 7912060644 Statement in support of UCS 790917 petition for decommissioning of Unit 1 & suspension of Units 2 & 3 OLs. Requests institution of proceeding per 105Re2 202. Affidavit, Certificate of Svc & supporting documentation sect. ADRAMS, R., BIALIK, E. I. New York, State of. 79/11/16, 13pp.
- 7912110038 Confirms receipt of encl 790329 petition to suspend OLs for all PURS. Forwards FR notice indicating that potition will be treated in accordance w/10CFRZ 204.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/23. ip.
- ---791211012A Notice of request for action pursuent to 10CFR2.20A re Environ Coslition on Nuclear Power 790329 petition requesting suspension of all OLs for PMRs. RMLER, D.R. Office of Nuclear Reactor Regulation. 79/11/23.
- 7912200270 Forwards statement made in support of UCB petition for decommissioning of Unit 1 & suspension of operation at Units 2 & 3.
  BROWN, P. D. Q. Mid-Hudson Nuclear Opponents. Inc. 79/11/27. 1p.
- --7912200276 Statement of PDO Brown in support of UCS petition for proceeding to institute decommissioning of Unit 1 & suspension of operation at Units 2 & 3 pending safety review. BROWN, P. D. G. Mid-Hudson Nuclear Opponents, Inc. 79/11/26, Spp.
- 7912040074 Notice of withdrawal from proceedings effective 791130. SNITH.B.H. Hearing Branch 2. 79/11/29. 1p.
- 7912040078 Notice of appearance on behalf of NRC. Certificate of Svc encl. MOORE, J. E. Hearing Branch 2. 79/11/29. Spp.
- 7912260368 Requests extension until B00208 to respond to intervenors NY BEAte Energy Ofc & Citizens' Committee for Protection of Environ petitions for review of ALAB-435 & ALAB-561 re neismic issues. Cartificate of Svc encl.

  MODRE J. E. Hearing Branch 2. 79/12/07. 4pp.
- 7912180410 Requests confirmation of 800126 deadline for NRC response to intervenor UCB 791115 request for action under 10CFR2.206.Also requests meeting to discuss issues to be used to formulate response.
  HEISG.E.R. Sheldon, Harmon & Heise. 79/12/10. 1p.

- --7912180422 Requests that Commission reconsider 790425 decision to refer intervenor UCB 79032B seismic reanalysis petition to staff. Commission must assume jurisdiction since staff has issued no reply to UCB in six months. WEISB.E.R. Union of Concerned Scientists, WEISB.E.R. Bheidon, Harmon & Weiss. 79/12/10. 3pp.
- 7912310078 Three ltrs requesting favorable action on patition to shut down facility.
  ESTEROWITZ, R., KAMZAN, L., BRODESKY, N. Affiliation Unknown.
  79/12/10. 3pp.
- 7912190239 Order granting extension until 800208 for NRC to respond to NY Btate Energy Ofc & Citizens Committee for Protection of Environ petitions for review.
  CHILK.S. J. Office of the Secretary of the Commission. 79/12/14.
- 7912310109 Two itrs requesting favorable action on petition to suspend operations at facility.

  OHINGER.J.: KAMZAN.L. Affiliation Unknown. 79/12/15. 3pp.
- 7912190107 Forwards 791217 ltr to Commissioner Ahearne re UCS peition on wafety & site location issues. FISH.H. House of Rep. 79/12/17. 1p.
- --7912190114 Requests quick response to UCS petition re resolution of site location & safety issues.
  FISH.H. House of Rep. 79/12/17. ip.

#### H. General correspondence

- 791214015B Requests that EJ Back be deleted from employee list & that JP Davis be added as replacement. DAVIS.J.P. Consolidated Edison Co. of New York. 79/11/27. 1p.
- P. Operating license stage documents & correspondence
- 7912050163 Discusses NRC review of LERs & Tech Spec requirements recontrol RPI sys at Westinghouse PWRs. Requests Tech Spacs review to ensure requirement for rod maint to within +/- 12 steps indicated & RPI sys verified accurate within 12 steps. SCHWENCER.A. Operating Reactors Branch 1. 79/10/29. 7pp.
- 7912100189 Discusses NRC 791101 meeting w/representatives of N888 vendors & fuel suppliers re discussion of respective portions of ECGS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EISENHUT.D.O. Division of Operating Reactors. 79/11/09. 65pp.
- --7912100255 Responds to NRC 791101 request re noncompliance of Hestinghouse ECCB evaluation model under requirements of 10CFR50 App K. Evaluation of three fuel rod models indicates no safety problems for Hestinghouse plants.

  ANDERSON, T. M. Wastinghouse Electric Corp. 79/11/02. 4pp.
- ~-7912100330 Responds to NRC 791101 request re ORNL cladding swelling & rupture data, Review of analytical models & tests indicates compliance w/iOCFR30 App K.All GE specs for calculated peak cladding temp remain unchanged.

  BUCHHOLZ, R. H. General Electric Co. 79/12/07. Rpp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50. 46 satisfied.

  OHBLEY, G.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  797/11/02. 5pp.
- --7912100456 Forwards add1 info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. OMSLEY, Q.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/04. 22pp.
- 7912070263 Partially responds to FOIA request for document re Pawling, NY site. Forwards requested info. Submits addl info: sodium deuterium reactor never built at site, no matl ever used at site & no radioactive matl disposed of in lake.

  CARR. J. C. Division of Rules and Records. 79/11/16. 3pp.
- 7912070291 Bubmits partial response to FOIA request for documents re Nuclear Development Association, United Nuclear Corp, Gulf United Nuclear Corp & ATODR Inc. concerning facility site. Forwards requested info, Provides add1 info re site. CARR. J. C. Division of Rules and Records, 79/11/16. 3pp.

- 7912060126 Bummary of 791114 telcon w/util re lessons learned implementation.
  OLSHAN, L. N. Operating Reactors Branch 1. 79/11/21. 6pp.
- 7912040470 Notifies NRC that turbine manufacturer has reported stress corresion cracking in keyway areas of some low pressure discs of turbines at other plants. Current missile generation probability within guidelines of Reg Guide 1, 115.
  CAHILLIM. J. Consolidated Edison Co. of New York. 79/11/27. ip.
- 7912040466 Notifies NRC of current development of safety analysis capability using reactor sys transient analysis code RETRAN.
  Currently using code to perform in-house plant specific analysis to better understand reactor transients.
  CAHILL.W. J. Consolidated Edison Co. of New York. 79/11/29. ip.
- 7912000649 Notification of 791205 meeting w/utils in Bethesda.MD to discuss alternatives to reduce probability & consequences of severe reactor accident.

  ZECH.G. Division of Operating Reactors. 79/11/29. App.
- 7912130284 Forwards application for amend to OL changing ETS & required fee. Fee paid under protest. CAMILL, M. J. Consolidated Edison Co. of New York. 79/12/03. Ip.
- --7912130291 Application to amend ETS distinguishing limiting conditions & manitoring requirements, eliminating repetitive specs, reporting requirements & bases & updating ETS rept to reflect present technology.

  CAHILL, W. J. Consolidated Edison Co. of New York. EARLY, A. E. Power Authority of the State of New York. 79/12/03. 25pp.
- ---7912130306 Revised Pages 1-1 through 5.6-1 of ETS re limiting conditions & monitoring requirements, annual environ operating rept & nonroutine reportable environ occurrences. Affidavit of svc encl.

  \* Consolidated Edison Co. of New York. 79/12/03. 46pp.
- 7912130667 Forwards revisions to util schedule for implementing TMI-2 Lessons Learned Task Force short term requirements described in NUREO-0378. GAMILL.M.J. Consolidated Edison Co. of New York. 79/12/07. 2pp.
- --7912130684 Provides add1 info re draft NUREO-0630 data. Westinghouse fuel rod model used in App K.ECCB evaluation model & interim & long term recommendations for resolution of noncompliance. ANDERSON.T.M. Westinghouse Electric Corp. 79/12/07. 7pp.
- 7912180561 Responds to NRC 791029 ltr re control rod position indication sys. Tech Specs revised to limit rod misalignment & Unit 1 shutdown awaiting decision on ECCS.
  CAHILL. N. Consolidated Edison Co. of New York. 79/12/07. 1p.
- 7912200415 Notifies of 791218 site visit of NRC Emergency Planning Task Force to evaluate upgrading of emergency planning since TMI accident Requests participation of NY State Energy Ofc. COLLING.H.E. Assistant Director for Emergency Preparedness. 79/12/07. ip.
- 7912270232 Forwards response to NRC 791210 request for add1 detailed info re responses to TMI Lessons Learned Task Force recommendations. Oversize drawings available in Central Files only.

  CAHILL. H. J. Consolidated Edison Co. of New York. 79/12/14. 28pp.
- --7912270236 "Spec for Flow Transmitters," prepared for Westinghouse & Con Ed.

  \* United Engineers & Constructors, Inc. (subs. of Raytheon Co.), 67/06/15. Spp.
- --7912270243 "Spec for Indicators Panel Mounted," prepared for Mestinghouse & Con Ed. \* United Engineers & Constructors, Inc. (subs. of Maytheon Co.), 67/04/06. 4pp.
- 7912280060 Requests submittal of Class III amend fee re 790907 application concerning recarking of spent fuel pool NRC 791015 ltr requesting fee has not been answered. MILLER.W.O. License Fee Management Branch. 79/12/14. Ip.
- 7912270312 Discusses implementation of NRC Category A Lessons Learned requirements Requirements will be implemented or facility will be shut down until completion of implementation. ZARAKAB.P. Consolidated Edison Co. of New York. 79/12/17. 1p.
- 7712270339 Forwards "Program Plan for Performance Verification of PWR Safety/Relief Valves & Sys" & supplemental info in response to TMI Lessons Learned Task Force Recommendations 2.1. 2. CAHILL. W. J. Consolidated Edison Co. of New York. 79/12/17. 7pp.

- -7912270373 "Program Plan for Performance Verification of PWR Safety/ Relief Valves & Sys." a Electric Power Research Institute. 79/12/13. 62pp.
- 7912270188 Forwards "NRC Requirements for Auxiliary Feedwater Sys," in response to NRC Bulletins & Ordors Task Force review of operating reactors.

  CAHILL.W. J. Consolidated Edison Co. of New York. 79/12/17. 1p.
- --7912270190 "NRC Requirements for Auriliary Feeduator Sys." \* Consolidated Edison Co. of New York. 79/11/07. 19pp.
- 7912310303 Forwards response to 791023 ltr per iOCFR®O.54(f).Valve qualification program for containment purge & pressure relief valves initiated on expedited basis.Valves will perform satisfactorily after LOCA.
  CAHILL.W. J. Consolidated Edison Co. of New York. 79/12/19. Hpp.
- 7912270267 Forwards 791220 conference paper re Indian Point/Zion near site studies Requests paper be made part of public record. PEOPLES D. L. Commonwealth Edison Co. \* Consolidated Edison Co. of New York. \* Power Authority of the State of New York. 79/12/21. I۵.
- --7912270275 "Indian Point/Zion Near Site Studies." presentation to NRC.

  s Commonwealth Edison Co. + Consolidated Edison Co. of New York.

   Power Authority of the State of New York. 79/12/20. Sipp.
- Q. Inspection reports, 1E Bulletins & correspondence
- 7912130213 Responds to IE Builetin 79-18 Evacuation announcement systems in Dec 1978 reveal several deficiencies which were corrected Audibility testing will be continued annually. CAHILL.W. J. Commonwealth Edison Co. 79/10/15. 2pp.
- 7912170186 Responds to IE Mulletin 79-23. "Potential Failure of Emergency Diesel Generator Field Exciter Transformer."
  Described canditions re connections meutral of generator & neutral of primary windings of EFT not applicable.
  CAHILL, W. J. Consolidated Edison Co. of New York. 79/10/29. 2pp.
- 7912200054 Forwards 1E Insp Rept 50-247/79-12 on 790819-0915.No nancomplianco noted. BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/10/30. 2pp.
- --7912200067 IE Insp Rept 50-247/79-12 on 790819-0915. No noncompliance noted major areas inspected; whift logs & records, tours of facility & stagmant borated water sys.
  REDELONSKI,T., JCHNSON,R. Region 1. Philadelphia, Office of the Director. KEIMIO,R.R. Region 1. Philadelphia, Reactor Operations Nuclear Support Granch. 79/10/29, 11pp.
- 7912200159 Forwards IE Insp Rept 50-247/79-19 on 790904-11 No noncompliance noted. CARLSON.R.T. Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 79/11/01. 2pp.
- -7912200167 IE Insp Rent 50-247/79-19 on 790704-11. No noncompliance noted Major areas inspected review of adequacey of licensee response to IE Bulletin "Seismic Analysis for As-Built Bafety-Related Piping Sys."
  FEIL.R. FOLEY.T. Region 1, Philadelphia, Office of the Director. TRIPP.L Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/10/24. 10pp.
- 7912050164 Act receipt of 791024 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-247//7-16.
  BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/11/06. 1p.
- --7912050172 Responds to NBC 790926 ltr re violations noted in IE Insp Rept 50-247/79-16. Corrective actions: responsible personnel reinstructed in proper procedures & test procedures revised. CAHILL.W.J. Consolidated Edison Co. of New York. 79/10/24. ip.
- --7912050179 Forwards IE Insp Rest 50-247/79-16 on 790800-10 & notice of violation. BRUNNER, E. J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 79/09/26. 2pp.
- -7912050185 Natice of violation from insp on 770808-10.

  \* Region I. Philadelphia. Office of the Director. 79/09/23. \* 2pp.

- --7912050192 IE Insp Rept 50-247/79-16 on 790808-10 Noncompliance noted; improper annotation of PI-VI (A) data sheet. CAPHTON,D.L. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. FDLEY,T. Region 1, Philadelphia, Office of the Director. 79/09/25, App.
- 7912200344 Forwards waste packaging Insp Rept 79-02A on 790925-26. No noncompliance noted.
  SUTHERLAND, J. T. Region 2, Atlanta, Funl Facility & Materials Safety Branch. 79/11/07. 2pp.
- --7912200393 Waste packaging Insp Rept 79-02A. No noncompliance noted.
  Major areas inspected: shipping paper & DOT placarding
  requirements, rediation levels, removable contamination, DDT &
  NRC package features.
  DROWN, R. A. Region 2, Atlanta, Office of the Director. 79/11/06.
- 7912050023 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/11/16. 1p.
- 7912050234 Forwards IE Info Notice 79-27, "Steam Generator Tube Ruptures at Two PUR Plants." No response required. GRIER, B.H. Region i, Philadelphia, Office of the Director, 79/11/16. ip.
- 7912100113 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/11/16. 1p.
- 7912110396 Forwards IE Info Notice 79-29, "Loss of Nonsefety-Related Reactor Coolent Sys Instrumentation During Operation." No specific action or response required. GRIER, B. H. ... Region 1, Philadelphia, Office of the Director. 79/11/19. 1p.
- 7912080221 Forwards IE Bulletin 79-26, "Boron Loss from BWR Control Dlades." No response required.
  GRIER, B. H. Region i, Philadelphia, Office of the Director.
  79/11/20. 1p.
- 7912040856 Forwards IE Circular 77-24. "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on DWRs." No response required. GRIER, D. H. Region 1, Philadelphia, Office of the Director. 79/11/26. ip.
- 7912110031 Forwards IE Circular 79-23, "Motor Starters & Contactors failed to Operate." No response required.
  ORIER, P. M. Region i, Philadelphia, Office of the Director.
  79/11/26. 1p.
- 7912040465 Provides supplmental response to IE Bulletins 79-02 & 79-07. Bafety-related pipelines seismically reanalyzed w/dynamic computer stress code & considered in evaluating adequacy of pipe supports using expansion anchor bolts.

  CAHILL.W. J. Consolidated Edison Co. of New York. 79/11/27. Spp.
- 791219001B Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation." Written response required. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/11/30. lp.
- 7912310209 Forwards 1E Info Notice 79-30, "Reporting of Defects & Moncompliances, 10CFR21." No action required. eRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/12/06. (p.
- 7912190734 Forwards IE Sulletin 79-28, "Possible Melfunction of Namco Model EA180 Limit Switches at Elevated Temps." Written money that the control of the Director. Office of the Director. Office of the Director. 79/12/07. 1p.
- 791228018B Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra," No written response required. GRIER.B. H. Region 1, Philadelphia, Défice of the Director. 79/12/13. ip.
- R. Periodic operating reports & related correspondence
- 7912140333 Forwards Nov 1979 data re fish epecies specified in Section 401 certification to NY State Dept of Environ Conservation. MONTI.W. A. Consolidated Edison Co. of New York. 79/12/10. 17pp.

- 7912170245 Forwards monthly operating rept for Nov 1979.
  CAHILL, W. J. Consolidated Edison Co. of New York. 79/12/14. 1p.
- --7912170299 Monthly operating rept for Nov 1979. KAWULALL. Consolidated Edison Co. of New York. 79/12/04. App.
- 7912170302 Forwards daily records of fish collection for Nov 1979.
  CAHILLIM.J. Consolidated Edison Co. of New York. 79/12/14. 1p.
- --7912170307 Tabulation of daily records of fish collection for New 1979.
- 8. Reportable occurrences, LERs & related correspondence
- 7912200575 PNS-I-79-002:R Pienciak, Associated Press reporter interviewed 20 to 30 guards at facilities & plans to write article describing guard force performance, util physical security programs & weaknesses in programs.

  DEVLIN, J. H., NARTIN, M. G., ALLAN, J. Office of Inspection & Enforcement, Office of the Director. 79/10/05. ip.
- 7912200490 PNB-I-79-004: on 791016, licensee received notification via telcon w/NY State Police of bomb threat against facility. State Police assisting in bomb search. No evacuation of facilities.

  DEVLIN. J. M., MARTIN, W. Q., ALLAN, J. Office of Inspection & Enforcement, Office of the Director. 79/10/16. ip.
- 7912200444 PNS-I-79-004A: on 791017.Peekskill Evaning Btar,Peekskill,NV. states receiving bomb threat extortion ltr re facilities & three phone calls on 791016 re same bomb threat. Search of facilities revealed no bomb.

  DEVLIN.J.W., MARTIN,W.C., ALLAN.J. Office of Inspection & Enforcement. Office of the Director. 79/10/17. 2pp.
- 7912200073 PNB-I-79-0048: on 791021, bomb threat received by NY Telephone Co operator from unidentified male who said bomb would go off in 1-h at plant. Search conducted at Units 2 % 3.No bomb found.

  SHEPHERD, R. E., DEVLIN.J. W., HARTIN, W.O. Office of Inspection & Enforcement, Office of the Director. 79/10/22. ip.
- 7912120465 Forwards LER 78-009/01X-1.
  CAHILL, W. J. Consolidated Edison Co. of New York. 79/12/07. 1p.
- --7912120469 LER 78-009/01X-1:on 78030i.one-third of hydraulic snubbers tested were below functional test acceptance criteria. Caused by mechanical defects & wear in Bergen-Patterson Models H88A-3, 10,20 & 50. Defective snubbers replaced.

  MAKEPEACE, J. M. Consolidated Edison Co. of New York, 79/12/07.
- 7912140410 Forwards LER 79-023/03L-0. CAHILL, W. J. Consolidated Edison Co. of New York. 79/12/07. 1p.
- --7912140411 LER 79-023/03L-0: on 791109, during normal operation, when terminating blowdown from steam generator 24, one series isolation valve. PCV-1217, in blowdown line, would not close. Caused by operator closure spring bearing plate dislodging. MAKEPEACE, J. M. Consolidated Edison Co. of New York. 79/12/07. 1p.
- 7912310403 Forwards updated LERs 78-022/01X-1 & 79-013/03X-1. CAHILL-W.J. Consolidated Edison Co. of New York. 79/12/21. 1p.
- ---7912310406 Updated LER 78-022/01X-1: on 78U817, confirmed discrepancy between specified & as supplied value of reliof valves. Cause not stated. Valves removed & replaced during 1979 refueling outage.

  MAKEPEACE, J. M. Consolidated Edison Co. of New York. 79/12/21.
- ---7912310410 Updated LER 79-013/03X-1: on 790329, visual insp revealed pinhole leak at socket weld connections on seal injection header downstream of filters. Cause not stated. Permanent repair accomplished during 1979 refueling outage.

  MAREFEAGE, J. M. Consolidated Edison Co. of New York. 79/12/21.
  1p.
- U. Congressional/Executive Correspondence
- 7912140528 Concurs w/Kemeny Commission recommendation re emergancy evacuation plans for power plant areas NRC should rule directly on UCB petition to shut down plant.
  BINCHAM, J. House of Rep. 79/11/14. 1p.

- DOCKET 50-249 DRESDEN NUCLEAR POWER STATION, UNIT 3

  F. Security, medical, emergency & fire protection plans
- 7912200022 Discusses NRC 791109 meeting re energency preparedness team review objectives.Provides guidance for improving licensement emergency preparedness & assuring capability of affisite agencies to take appropriate emergency actions.

  GRIMES.B.K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- 7912270063 Forwards list of specific items requiring updating in emergency plans. Emergency plans were evaluated using code requirements, Reg Guide 1.101 & Emergency Planning Review Guidelines Number 1. Revision 1. IPPOLITO. T. A Operating Reactors Branch 3. 79/11/30. 7pp.
- 7712270089 Ack receipt of 790816 ltr transmitting security personnel training & qualification plan. Requests submittal of Class I & III fees totalling \$4,000.

  MILLER, W. D. License Fee Management Branch. 79/12/10. 1p.
- H. General correspondence
- 7912200605 Discusses 791204 title change of manager of nuclear operations to vice president.Organization structure not altered.No revision will be made to CA program topical rept CE-I-A until organization structure is delineated.

  JANECEK.R.F. Commonwealth Edison Co. 79/12/19. lp.
- P. Operating license stage documents & correspondence
- 7912100189 Discusses NRC 791101 meeting w/representatives of NSSS vendors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/representatives of respective portions of ECCS evaluation models dealing w/representatives of repture. Vendor responses enci. EISENHUT, D. O. Division of Operating Reactors. 79/11/09. 45pp.
- ---7912100255 Responds to NRC 791101 request re noncompliance of Hestinghouse ECC9 evaluation model under requirements of 10CFR50 App K. Evaluation of three fuel rod models indicates no safety problems for Hestinghouse plants.

  ANDERSON, T. M. Westinghouse Electric Corp. 79/11/02. 4pp.
- --7912100330 Responds to NRC 791101 request re ORNL cladding swelling & rupture data. Review of analytical models & tests indicates compliance w/locrR50 App K. All GE specs for calculated peak cladding temp remain unchanged.

  BUCHHOLZ,R.H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFRSO. 46 satisfied.
  OMSLEY,O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/11/02. Spp.
- --7912100456 Forwards addl info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model.

  No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results.

  DMSLEY. O. F. Exxon Nuclear Co. . Inc. (subs. of Exxon Corp.).

  79/11/04. 22pp.
- 7912040261 Forwards plant steam bypass capacity sheets,percent rated. Info provided to GE for incorporation into NEDO-24708. PEOPLES, D. L. Commonwealth Edison Co. 79/11/16. 200pp.
- 7712050322 Discusses 771113 & 14 site visit re solid radwaste processing & temporary storage.Facilities have instituted improved waste minimization programs.

  ORANT,P., LO.R. Environmental Evaluation Branch. 79/11/23. 2pp.
- 7912040297 Forwards supplementary response to be incorporated into 791018 ltr re lessons learned commitments to meet near-term requirements.
  REED.C. Commonwealth Edison Co. 79/11/30. 7ps.
- 7912040485 Submits updated schedules for installation of recirculation pump trip mods per 790329 ltr.
  PEOPLES, D. L. Commonwealth Edison Co. 79/11/30. 2pp.
- 7912120411 Forwards supplementary response re consitment to meet short-term requirements of Lessons Learned Task Force.
  REED,C. Commonwealth Edison Co. 79/11/30. 7pp.
- 7912120425 Forwards supplemental response to 791018 ltr re commitments to Lessons Learned Task Force recommendations. PEOPLES.D.L. Commonwealth Edison Co. 79/12/03. 2pp.

- 7712110380 Proposes to amend Tech Specs, extending man average glanar linear heat generation rate to larger exposure values. Errata & addenda sheets for "LOCA Analysis Rept." Tech Specs page changes & Class III fees entl. PEOPLES, D. L. Commonwealth Edison Co. 79/12/04. 2pp.
- ---7912110386 Errata & addenda shoets for "LOCA Analysis Rept." \* General Electric Co. NEDO-24146. 79/10/31. 3pp.
- 7912140266 Forwards design drawings re water suppression sys.detection sys & Unit 1 fire pump. Drawings available in Central Files only. Hydraulic calculation info & Fairbanks morse manual describing fire pump enci.

  JANECEK, R. F. Commonwealth Edison Co. 79/12/04. 2pp.
- 7912190622 Forwards proposed amend to License DPR-25 consisting of changes to Tech Specs App A to implement reload licensing. PECPLES D. L. Commonwealth Edison Co. 79/12/10. 5pp.
- ---7912190626 Proposed Tech Specs changes in support of reload licensing.
- 7912210349 Forwards cover sheet for CE-1-A.Revision 10.inadvertently amitted from 791116 transmittal.
  NAUGHTON.W.F. Communwealth Edison Co. 79/12/13. 2pp.
- 7912180531 Forwards info documenting evaluation of purge & vent valve operability verification. Util committed to purge & vent sys in conformance w/NRC interim position. Complete confirmatory analyses not available for 30-40 wk. PEOPLES. D.1. Commonwealth Edison Co. 79/12/14. 6pp.
- 7912190942 Forwards "Adequacy of Station Electric Distribution Sys Voltages." addressing 480-volt undervoltage conditions. JANECEK.R.F. Commonwealth Edison Co. 79/12/14. 1p.
- --7912190545 "Adequacy of Station Electric Distribution Sys Voltages." \* Commonwealth Edison Co. 79/12/14. Upp.
- 7912270470 Advises that qualification program for remaining purge & vent containment valves is in progress. Drosden & Guad-Cities butterfly valves will close-regardless of degree of opening. Response to NRC interim position encl. PEOPLES, D. L. Communwealth Edison Co. 79/12/14. Opp.
- 7912280533 Responds to NHC 791031 request for plant-unique implementation schedule for additional condensation tests we Hark I Full scale test facility. Analysis dependent on final resolution of acceptance criteria.

  PEOPLES.D.L. Commonwealth Edison Co. 79/12/20. 2pp.
- 7912310348 Forwards revised pages to CE-1-A. "Comm Ed GA Program for Nuclear Generating Stations:" Revision 11. JANECEK, R. F. Commonwealth Edison Co. 79/12/20. 1p.
- --7912310359 Revised pages to CE-1-A. "Comm Ed GA Program for Nuclear Generating Stations." Revision 11. # Commonwealth Edison Cd. CE-1-A. 79/11/21, 16pp.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912050013 Forwards IE Insp Repts 50-010/79-19,50-237/79-23 & 50-249/79-21 on 790904-28 & notice of violation. HEISHMAN.R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/10/18. 2pp.
- ---7912050037 IE Insp Repts 50-010/79-19,50-237/79-23 k 50-249/79-21 on 790904-29. Noncompliance noted: failure to control access to high radiation areas & failure to fallow procedures. BARKER.J.L. WALKER.R.D. SPESSARD.R.L. Region 3. Chicago, Office of the Director. 79/10/15. 9pp.
- 7912200344 Forwards waste packaging Insp Rept 79-02A on 790925-26.No noncompliance noted.

  SUTHERLAND.J.T. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 79/11/07. 2pp.
- ---7912200395 Waste packaging Insp Rept 79-02A.No noncompliance noted.
  Major areas inspected:shipping paper & DOT placarding
  requirements.radiation levels.removable contamination.DOT &
  NRC package features.
  BROWN.R.A. Region 2. Atlanta, Office of the Director. 79/11/06.

- 7912050106 Forwards IE Circular 79-22. "Stroke Times for Power Operated Relief Valves." No response required. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/16. ip.
- 7912100213 Forwards IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads." No response required. KEPPLER, J. G. Region 3. Chicago. Office of the Director. 79/11/14.
- 7912110557 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required.

  KEPPLER, J. G. Region 3. Chicago, Office of the Director. 79/11/16.
- 7912210025 Forwards IE Insp Repts 50-237/79-25 & 50-249/79-23 on 790917-18 & 24-27. No noncompliance noted.

  KEPPLER. J. G. Region 3, Chicago, Office of the Director. 79/11/16.
- --7912210031 IE Insp Repts 50-237/79-25 & 50-247/79-23 on 790917-18 & 24-27. No noncompliance noted. Major areas inspected; cooling lake constrail borings on north dike & review of monthly surveillance repts on dike structure.

  GALLACHER, E. J. DESTANN, H. J. Region 3, Chicago, Office of the Director. HAYES, D. H. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/11/14. 26pp.
- 7912180013 Notifies of delay in implementation of IE Bulletin 79-14 re accessible areas comparison & evaluation phase. Current program provides for earliest detection & evaluation of significant discrepancies.
  PEOPLES.D.L. Commonwealth Edison Co. 79/11/19. 2pp.
- 79:2050350 Forwards IE Bulletin 79-26, "Boron Loss From BWR Control Blades." Response required.
  KEPPLER.J.G. Region 3, Chicago, Office of the Director. 79/11/20.
- 7912040009 Ack receipt of 791108 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/79-19. 50-237/79-23 t 50-249/79-21. HEISHMAN.R.F. Region 3. Chicago. Reactor Operations Nuclear Support Branch. 79/11/21. lp.
- --7912040011 Responds to NRC 791018 ltr re violations noted in IE Insp Repts 50-010/79-19.50-237/79-23 & 50-249/79-21. Corrective actions: personnel instructed to lock door to high radiation area. PECPLES, D. L. Commonwealth Edison Co. 79/11/08. Spp.
- 79:2100417 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs. " No written response required.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/26.
- 7912140187 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No written response required.
  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/26.
- 7912110395 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sent by NRC to licensees.

  KEPPLER, J. O. Region 3. Chicago, Office of the Director. 79/11/28.

  10.
- 7912190199 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Written response required.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/30, in
- 7912140056 Forwards 1E 1nfo Notice 79-30, "Reporting of Defects & Noncompliances:10CFR21." No action or response required.

  KEPPLER, J. O. Region 3. Chicago, Office of the Director. 79/12/06,
- 7912200006 Forwards IE Sulletin 79-28, "Possible Halfunction of Nanco Hodel EA180 Limit Switches at Elevated Temps." Action required.
  KEPPLER. J. C. Region S. Chicago, Office of the Director. 79/12/10, in
- 7912200443 Notification of 791213 meeting w/util to discuss IE Bulletin 79-DZ anchor bolt & base plate analysis. JORDAN, E. L. Division of Heactor Operations In≤pections. 79/12/11. 3pp.

- R. Periodic operating reports & related correspondence
- 7912180377 Forwards monthly operating repts for Nov 1979. STEPHENBON, B. B. Commonwealth Edison Co. 79/12/07. ip.
- --7912180386 Monthly operating repts for Nov 1979. CIESZKIEWICZ, S. Commonwealth Edison Co. 79/12/03. 19pp.
- S. Reportable occurrences, LERs & related correspondence
- 7912070143 PNO-III-79-023:on 791025, spent fuel good overfilled. Caused by personnel valving error. Areas affected roped off & cleanup in progress.
  BARKER, J.L., PRESSARD, R.L., HEISHMAN, R.F. Region 3, Chicago, Office of the Director. 79/10/26. 1p.
- 791212006B PNO-III-79-025: on 791025, essential svcs motor generator set tripped, resulting in tripping of Unit 3 reactor. Caused by slamming of essential svcs electrical panel door.

  CREED.J. Region 3. Chicago, Office of the Director. 79/10/26.
- 7912170166 PNO-III-79-25A: threatening telephone calls came from courtcommitted patient. All affected licensess notified. 8ELANDER, J. Region 3, Chicago, Office of the Director. 79/10/29.
- 791203000B PNO-III-79-031: on 791023, Federal Highway Administration Bureau of Motor Carrier Bafety issued notice of shipping violation for improper packaging of low specific radioactive matl. Util fined.

  BARKER, J. L. Region 3, Chicago, Office of the Director. 79/11/01. 18.
- 7912200546 PNO-III-79-036: on 791110.Unit 3 tripped while performance of low vacuum trip surveillance in progress. Unit 2 tripped when instrument mechanic isolated feedwater pump suttion transmitter resulting in feedwater pump tripping.

  BARKER, J. SPESSARD.R. Region 3, Chicago, Office of the Director. 79/11/13. 2pp.
- 7912030162 Forwards LER 79-054/03L-0.
  STEPHENBON, B. B. Commonwealth Edison Co. 79/11/28. 1p.
- ---7912030166 LER 79-054/03L-0:on 791101, surveillance DOB 700-4 found intermediate range monitor to have rod block & hi hi half scram trips exceeding Tech Specs. Caused by dirty contacts on selector switch, Contacts cleaned.
  HOLLAND.P. Commonwealth Edison Co. 79/11/28. 1p.
- 7912140421 Forwards LER 79-030/03L-0. BTEPHENBON, B. B. Commonwealth Edison Co. 79/12/06. 1p.
- --7912140430 LER 79-030/03L-0: on 791110, during scram testing in refuel mode, substantial loss of position indication noted for control rod driveline H-9. Cause unknown. Buspect rod position indicator probe & cabling to be inspected at next outage.

  MAGROW, R. Commonwealth Edison Co. 79/12/06, 2pp.
- 7912180419 Forwards LER 79-031/03L-0. STEPHENSON, B. B. Commonwealth Edison Co. 79/12/06. 1p.
- 7912180376 Forwards LER 79-032/03L-0. BTEPHENSON, B. B. Commonwealth Edison Co. 79/12/10. 1p.
- ---7912180399 LER 79-032/03L-0:on 791120, pin hole leak found in Rx Feed pump min flow line. Caused by corrosion. Patch applied & permanent patch scheduled for next long outage. KDRCHYMEKY, M. Commonwealth Edison Co. 79/12/10. Ip.
- 7912270345 Responds to NRC requests for info re loss of offsite power events at facility. Forwards enswers to questions re 651112 & 780122 events. LER 78-005/03L-0.780122 deviation rest & list of 345 kV & 138 kV line failures during 1974-1979, JANECEK, R. F. Commonwealth Edison Co. 79/12/19. 21pp.

- DOCKET 50-250 TURKEY POINT PLANT, UNIT 3
- F. Security, medical, emergency & fire protection plans
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives. Provides guidance for improving licensee emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions. GRIMES, B. K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- 7912200618 Notifies of fee assessment for 790817 review of security training & qualification plan. Requests payment.
  DIGOS.R.M. License Fee Management Branch. 79/12/06. 1p.
- 7912270429 Forwards preliminary equipment descriptions & drawings re switchgear room & diesel generator room fire detection sys. Drawings available in Central Files only. UHRTO.R.E. Florida Fawer & Light Co. 79/12/20. 9pp.

## G. Adjudicatory correspondence

- 7912120125 Request for extension to respond to util objections to interrogatories. Opposes util attempt to dismiss intervenor interrogatories. Requests hearing to ensure that ASLB 790813 order is fairly executed.

  ROGOW, B. S. Oncavage, Mark. ROGOW, B. S. Rogow, B. 79/11/13. Bpp.
- 7912060203 Order cancelling 791130 deadline for responses to discovery requests. Directs parties to file responses within 30 days from date of order. Awalts parties' responses to intervenor MP Oncavage motion for extension received on 79113. BOMERS, E. B. Atomic Safety and Licensing Board Panel. 79/11/15. Son.
- 7912130050 No objection to intervenor M Oncavage motion for 10-day extension to respond to util objections to interrogatories.

  Certificate of Svc encl.

  COLL.N.A. Florida Power & Light Co. COLL.N.A. Steel, Hector & Davis. 79/11/19. Spp.
- 791211003B Confirms receipt of encl 770329 petition to suspend OLs for all PMRs. Forwards FR notice indicating that petition will be treated in accordance w/100FR2.206.
  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/11/23. 1p.
- --7912110126 Notice of request for action pursuant to 10CFR2.206 TE Environ Coalition on Nuclear Power 790329 petition requesting suspension of all OLs for PWRs. MULLER, D.R. Office of Nuclear Reactor Regulation, 79/11/29.38no.
- 7912070168 Response to intervenor 791107 motion for extension beyond time set in ASLB 791105 order re discovery. Has no objection to granting add1 ten days for intervenor to compel answers to outstanding objections. Certificate of Svc encl. QDLDBERG, S. C. Hearing Branch 2. 79/11/27. App.
- 7912140014 Suppl per ASLB 791115 order, to licensee 791107 objections to intervenor MP Oncavage 791029 interrogatories & request for production of documents. Urges ASLB to sustain objections if motion to compel filed. Certificate of Evc encl. CDLL, N. A. Florida Power & Light Co. CDLL, N. A. Steel, Hector & Davis. 79/11/27. 11pp.

## H. General correspondence

7912120015 Certifies that motion re proposed amend to facility DL to permit steam generator repair was served on 791109.
RDGOW, S. S. Oncavage, Mark. RDGOW, B. S. Rogow, B. 79/11/09. 2pp.

## M. Antitrust correspondence

- 7912060020 Motion to lodge FERC 791004 opinion & order denying prehearing Confirms reasons presented in FL Cities 790809 motion to lodge FERC 790803 opinion & order Affirmation of Byc & FERC 791004 order encl.

  JABLON,R.A. Florida Cities. 79/11/16. Bpp.
- 7912110438 Response in opposition to FL Cities 791116 motion to lodge FERC Opinion 57-A.No relation exists between FERC findings response the territy matters & findings in present proceeding response violations. Certificate of Svc encl. BCUMNIGHT, J. A. GRIBBON, D. H. Florida Power & Light Co. BOUNNIGHT, J. A. Lowenstein, Newman, Reis, Axelrad & Toll. 79/12/03. App.

- 7912110345 Answer to FL Cities 791116 ention to lodge FERC 790803 opinion re whether to conduct proceeding under Atomic Energy Act of 1954 Section 105(a). Boes not oppose lodging per NRC 790823 previous answer.

  DEMEY, L. S., CHANANIA, F. D. Antitrust Division. 79/12/06. 3pp.
- P. Operating license stage documents & correspondence
- 7911090248 "Summary of Operating Experience W/Recirculating Steam Generators." EISENBUT, D. G. Division of Operating Reactors. NUREG-0523. 79/01/31. 89pp.
- 7908010339 Notifies of status of rept on reactor cavity annulus seal.
  Host PWR users remove ring during normal operation. Others
  store seal ring in raised position during normal operation.
  LAINAS.O. Plant Systems Branch (Pre 791030). 79/07/03. 7pp.
- 7912050174 Discusses NRC review of LERs & Tech Spec requirements re control RPI sys at Westinghouse PWRs. Requests Tech Specs review to ensure requirement for rod maint to within +/- 12 steps indicated & RPI sys verified accurate within 12 steps. SCHMENCER, A. Operating Reactors Branch 1. 79/10/29. 7pp.
- 7912100187 Discusses NRC 791101 meeting w/representatives of NSSS vendors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EISENRUI.D.O. Division of Operating Reactors. 79/11/09. 45pp.
- --7912100255 Responds to NRC 791101 request re noncompliance of Westinghouse ECCS evaluation model under requirements of 10CFRSO App K. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants.
  ANDERSON, T. M. Nestinghouse Electric Corp. 79/11/02. App.
- --7912100330 Responds to MRC 791101 request re ORML cladding swelling & rupture data. Review of analytical models & tests indicates compliance windocrato App K.All GE specs for calculated peak cladding temp remain unchanged.
  BUCH#DL7.R.H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to ARC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of IOCFRSO. 45 satisfied.

  DMSLEY.G.F. Exon Nuclear Co., Inc. (subs. of Exxon Corp.).

  79/11/02. 5pp.
- --7912100456 Forwards add1 info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model. No adverse legact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. OWSLEY, G.F. Exton Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/04. 22pp.
- 7912100246 Informs that no further action is required to 790819 response to NRC 790818 request for info concerning reactor vossel atypical weld math. Safety evaluation encl. SCHMENCER.A. Operating Reactors Branch 1. 79/11/13. 2pp.
- --7912160254 Safety evaluation supporting use of atypical weld wire in reactor vessels.

   Office of Nuclear Reactor Regulation. 79/11/13. 6pp.
- 7912170015 Notifies that no further action required re 790818 response to 790819 requests for add1 info on possible use of atypical weld wire in reactor vessels.

  SCHMENCER.A. Operating Reactors Branch 1. 79/11/13. 2pp.
- 7912120070 Summary of 791114 telcon w/util re lessons learned implementation.
  OROTENBUIS.M. Operating Reactors Branch 1. 79/11/16. App.
- 7912100174 Forwards request for addl info re steam generator repair proposal & cost update of repair project. SCHWENCER, A. Operating Reactors Branch 1. 79/11/19. Spp.
- 7712040276 Plans to respond by 791221 to 770918 request for info re potential for steam generator water hapmer at PWRs w/ feedrings that discharge from bottom Manpower demands generated by MRGC-0578 prevent response at present. UHRIG.R.E. Florida Power & Light Co. 79/11/26. 1p.
- 7912070127 Notifies that info requested by NRC 790828,0927 & 1023 ltrs re containment venting & purge during normal operation will be submitted on 791213.

  UHRIG.R.E. Florida Power & Light Co. 79/11/29. 1p.

- 7912110304 Informs that NRC 791119 ltr not received until 791126. Will provide requested info by 791207. URIG.R.E. Florida Power & Light Co. 79/11/30. 1p.
- 7912180243 Urges expeditious review & safety evaluation of RETRAN reactor sys transient analysis code. List of intended uses of RETRAN encl.
  UNRIGATE. Florida Power & Light Co. 79/12/07. 3pp.
- 7912140246 Agrees to revise Tech Specs for control rod misalignment & position indication re NRC request. Tech Spec amend will be submitted by 800229.
  UHRTCA.R.E. Flarida Power & Light Co. 79/12/10. 1p.
- 7912200508 Forwards info requested by NRC 781128 ltr re analyses & evaluations performed to resolve containment purge issue.
  Results of valve integrity evaluation anticipated by June 1980.
  UHRIGOR.E. Florida Power & Light Co. 79/12/13. 9pp.
- 7912270391 Advises that proposed Tech Spec amends are being developed in response to NRC 790726 ltr. Proposal to be submitted 800331 will address undervoltage protection; proposal to be submitted 800131 will address diesel generator surveillance. UHRIO, R.E. Florida Power & Light Co. 79/12/18. 1p.
- 7912270524 Documents current status re implementation of short-term TMI Lessons Learned Task Force items. All mods will be completed by 800125. URRIG.R.E. Florida Power & Light Co. 79/12/19. 2pp.
- 7912270350 Responds to NRC 791017 ltr re auxiliary feedwater sys. Amend to Tech Specs covering auxiliary feedwater pumps scheduled for submittal on 800131. Sys operability verified monthly by starting pumps & establishing flow to steam generators. UHRTG, R. E. Florida Power & Light Co. 79/12/20. 9pp.
- 7912270513 Withdraws proposed Tech Spec changes re fuel rod bowing. UHRIG.R.E. Florida Power & Light Co. 79/12/20. 2pp.
- 7912280548 Notifies that 791213 rept. "Program Plan for Performance Verification of PUR Safety/Relief Valves & Sys." is responsive to requirements listed in NUREG-0578. UHRIG.R.C. Florida Power & Light Co. 79/12/21. 1p.
- G. Inspection reports, IE Bulletins & correspondence
- 7912060143 Forwards 1E Info Notice 79-12A, "Attempted Damage to New Fuel Assemblies." No specific action or response required.

  O'REILLY, J.P. Region 2, Atlanta, Office of the Director.

  79/11/09. 2pp.
- 7912100181 Forwards IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads." No response required. O'REILLY.J.P. Region 2. Atlanta. Office of the Director. 79/11/16. 1p.
- 7912110561 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required.
  O'REILLY.J.P. Region 2, Atlanta, Office of the Director.
  79/11/16. 2pp.
- 7912060616 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipa Break Detection Equipment on BWRs." No response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/26. 1p.
- 7912110147 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. O'REILLY,J.P. Region 2, Atlanta, Office of the Director. 79/11/26. 1p.
- 7912190442 Forwards IE Bullstin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation." Written response required.

  D'REILLY, J.P. Region 2. Atlanta. Diffice of the Director.
  79/11/30. 1p.
- 7912200004 Responds to IE Bulletin 79-17. Revision 1 re stagment borated water sys. Add1 drawings provided identifying safety-related Type 316 stainless steel pipe sys containing stagment oxygenated borated water M/o encl.
  UNRIG.R.E. Florida Power & Light Co. 79/11/30. ip.

- 7912310297 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/12/06. 5pp.
- 7912200033 Forwards IE Bulletin 79-28, "Possible Maifunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required.
  O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
  79/12/07. 20s.
- 7912280402 Forwards IE Info Notice 79-3i, "Use of Incorrect Amplified Response Spectra." No written response required. O'REILLY.J. P. Region 2. Atlanta. Office of the Director. 79/12/13. 2pp.
- 7912280136 Forwards IE Circular 79-25, "Shock Arrestor Strut Assembly Interference," No written response required. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 79/12/20. 4pp.
- 8. Reportable occurrences, LERs & related correspondence
- 7912180326 PND-II-79-006: on 791006, during planned maint on secondary steam sys, main steam valve to moisture separator reheater stuck open. Caused by stray hex nut from main steam line check valves. All check valves inspected.

  HARDIN.A.K., DYER.J.A. Region 2, Atlanta, Office of the Director. 79/10/09. ip.
- 7912140229 RO-250-79-33: on 791101, vendor discovered error in current ECCB analysis input data. Correction resulted in allowable Fq limit reduction of steam generator tube. Augmented surveillance or power limits applied.

  HAYES, J. K. Florida Power & Light Co. 79/11/02. 1p.
- 7912030152 Forwards LER 79-030/03L-0. ECHMIDT, A. D. Florida Power & Light Co. 79/11/05. 10.
- --79120301AO LER 79-030/03L-0; on 791004, radiation monitors R-II & R-I2 out of svc for approx 14-h during power operation. Caused by failurs of air sampling blower which supplies monitors. Blower replaced & monitors returned to svc. BCHOPPMAN.M.A. Florida Power & Light Co. 79/11/05. ip.
- 7912030211 RO 250-79-35: on 791109, during examination of large break enalysis, Westinghouse discovered clad heatup rates of less than 2 F per second were possible. Adjustments made to augmented surveillance program.

  MDDRE, J. E. Florida Power & Light Co. 79/11/13. ip.
- 7912130653 Forwards LER 79-033/017-0. SCHMIDT, A. D. Florida Power & Light Co. 79/11/15. 1p.
- --7912130658 LER 79-033/017-0: on 791101, vendor corrected input error in LOCA analyses for steam-generator-tub plugging lovels, which resulted in reduction of max allowable frequency. Caused by vendor error. Revised procedures.

  8CHOPPMAN, M.A. Florida Power & Light Co. 79/11/15. 2pp.
- 7912130632 Forwards LER 79-035/017-0, SCHMIDT.A.D. Florida Power & Light Co. 79/11/23. 1p.
- --7912130441 LER 79-038/OIT-O: on 791109, based on reanalyses prompted by vendor notification, earlier clad burst time & resulting change in calculated peak clad temp for LUCA transient indicated. Gause not stated. BCHOPPMAN, M. A. Florida Power & Light Co. 79/11/23. 2pp.
- 7912130534 Forwards LER 79-032/03L-0. SCHMIDT, A. D. Florida Power & Light Co. 79/11/30. ip.
- --7912130536 LER 79-032/03L-0: on 791031, periodic surveillance of control on valves, locks & switches revealed that circuit breakers 30532 & 30631 not locked Caused by personnel error Procedure revised & personnel reinstructed.

  8CHOPPMAN.M.A. Florida Power & Light Co. 79/11/30. 1p.
- 7912170520 Forwards LER 79-034/03L-0. SCHMIDT, A. D. Florida Power & Light Co. 79/12/05. 1p.
- --7912190522 LER 79-034/03L-0: on 791105, during power operation, auxiliary feedwater pumps tested & pump A failed to start. Caused by misalignment between connections to associated pneumatic controller resulting in inoperability of valve CV-3705.

  SCHOPPMAN.M.A. Florida Power & Light Co. 79/12/05. 2pp.

- U. Congressional/Executive Correspondence
- 7912170395 Forwards SW Meyerson 791107 ltr re problems at plant. Requests comment. CHILES, L. Senate. 79/11/19. 2pp.
- DOCKET 50-251 TURKEY POINT PLANT, UNIT 4
- F. Security, modical, emergency & fire protection plans
- 7912200022 Discusses NRC 791107 meeting re emergency preparedness team review objectives. Provides guidance for improving licensee emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.

  CRIMES, B. K. Emergoncy Preparedness Task Force. 79/11/23. 30pp.
- 791220061B Notifies of fee assessment for 790817 review of security training & qualification plan. Requests payment.
  DIGOS.R.M. License Fee Management Branch. 79/12/06. 1p.
- 7912270429 Forwards proliminary equipment descriptions & drawings re switchgear room & diesel generator room fire detection sys. Drawings available in Central Files only. UHRIG.R.E. Florida Power & Light Co. 79/12/20. 9pp.
- G. Adjudicatory correspondence
- 7912120125 Request for extension to respond to util objections to interrogatories. Opposes util attempt to dismiss intervenor interrogatories. Requests hearing to ensure that ABLN 770813 order is fairly executed.
  ROGOW, B. S. Oncavage, Mark. ROGOW, B. S. Rogow, B. 79/11/13. Bap.
- 7912060203 Order cancelling 791130 deadline for responses to discovery requests. Directs parties to file responses within 30 days from date of order Awaits parties' responses to intervenor MP Oncavage motion for extension received on 791113.

  RUMERS, E. S. Atomic Safety and Licensing Board Panel. 79/11/15.
- 7912130050 No objection to intervonor M Oncavage motion for 10-day extension to respond to util objections to interrogatories.

  Certificate of Svc encl.

  COLL, N. A. Florida Power & Light Co. COLL, N. A. Steel, Hector & Davis. 79/11/19. 5pp.
- 7912110038 Confirms receipt of encl 790329 petition to suspend OLs for all PHRs. Forwards FR notice indicating that petition will be treated in accordance w/10CFR2.206.
  DENTON: N. R. Office of Nuclear Reactor Regulation. 79/11/23. ip.
- ---7912110126 Notice of request for action pursuant to 10GFR2.206 re Environ Coalition on Nuclear Power 790327 petition requesting suspension of all OLs for PWRs. HULLER, D.R. Office of Nuclear Reactor Regulation. 79/11/23. 38pp.
- 7912070168 Response to intervenor 791109 motion for extension beyond time set in ASLB 791105 order re discovery. Has no objection to granting addl ten days for intervenor to compel answers to outstanding objections. Certificate of Svc encl.

  GOLDBERG. S. C. Hearing Branch 2. 79/11/27. 4pp.
- 7912140014 Suppl per ABLB 791115 order to licensee 791107 objections to intervener MP Oncavage 791029 interrogatories & request for production of documents. Urges ABLB to sustain objections if motion to compel filed. Certificato of Svc encl. COLL. N.A. Florida Power & Light Co. COLL. N.A. Steel, Hactor & Davis. 79/11/27, 11pp.
- H. General correspondence
- 7912120013 Certifies that motion re proposed amend to facility OL to permit steam generator repair was served on 791109.
  ROGOW, B. S. Oncavage, Mark. ROGOW, B. S. Rogow, B. 79/11/09. 2pp.
- M. Antitrust correspondence
- 7912060020 Motion to lodge FERC 791004 opinion & order denying prehearing. Confirms reasons presented in FL Cities 790809 motion to lodge FERC 790802 opinion & order. Affirmation of Svc & FERC 791004 order encl.
  JABLON.R. A. Florida Cities. 79/11/16. 8pp.

- 7912110438 Response in opposition to FL Cities 791116 motion to lodge FERC Opinion 57-A. No relation exists between FERC findings re tariff matters & findings in present proceeding reantitrust violations. Certificate of Svc encl. BDUKNICHT.J. A. GRIBBON.D. M. Florida Power & Light Co. BDUKNICHT.J. A. Lowenstein, Neuman, Reis, Azolrad & Toil. 79/12/03. 4pp.
- 7912110345 Answer to FL Cities 791116 motion to lodge FERC 790803 opinion re whether to conduct proceeding under Atomic Energy Act of 1954 Section 105(a). Does not oppose lodging per NRC 790823 previous answer.

  DEHEY, L. S., CHANANIA, F. D. Antitrust Division. 79/12/06. 3pp.
- P. Operating license stage documents & correspondence
- 7911090248 "Summary of Operating Experience W/Recirculating Steam Generators." EIBENHUT, D. G. Division of Operating Reactors. NUREG-0523. 79/01/31. 89pp.
- 7912050174 Discusses NRC review of LERS & Tech Spec requirements recontrol RPI sys at Westinghouse PWRs. Requests Tech Specs review to ensure requirement for rod maint to within +/- 12 steps indicated & RPI sys verified accurate within 12 steps. SCHWENCER.A. Operating Reactors Branch 1. 79/10/29. 7pp.
- 7912100189 Discusses NRC 791101 meeting w/representatives of NSSS vendors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EISENHUT.D.O. Division of Operating Reactors, 79/11/09. 65pp.
- --7912100255 Responds to NRC 791101 request re noncompliance of Hestinghouse ECCS evaluation model under requirements of 10CFR50 App K. Evaluation of three fuel rod models indicates no safety problems for Hestinghouse glants. ANDERSON.T.M. Hestinghouse Electric Corp. 79/11/02. App.
- --79:2100330 Responds to NRC 79:101 request re DRNL cladding swelling & rupture data. Review of analytical models & tests indicates compliance w/10CFR50 App K.All GE specs for calculated peak cladding temp remain unchanged.

  BUCHHOLZ, R. H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50, 46 satisfied.

  GMSLEV. 9. F. Exxon Nuclear Co. Inc. (subs. of Exxon Corp.).
  79/11/02. Spp.
- --79:2100456 Forwards add1 info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. DMSLEY.G.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.), 79/11/04. 22pp.
- 7912100246 Informs that no further action is required to 790819 response to NRC 790818 request for info concerning reactor vessel atypical weld math. Bafaty evaluation encl.

  SCHWENCER, A. Operating Reactors Branch 1, 79/11/13, 2pp.
- --7912100254 Safety evaluation supporting use of atypical weld wire in reactor vessels.

  \* Office of Nuclear Reactor Regulation. 79/11/13. 6pp.
- dirite di nociali necitor negulatium, 77/11/13. Opp.
- 7912170015 Notifies that no further action required re 790819 response to 790819 requests for add1 info on possible use of atypical weld wire in reactor vessels.

  SCHMENCER.A. Operating Reactors Branch 1. 79/11/13. 2pp.
- 7912120070 Summary of 791114 telcon w/util re lessons learned implementation. GROYENHUIS.M. Operating Reactors Branch 1, 79/11/16. 6pp.
- 7912100174 Forwards request for add1 info re steam generator repair proposal & cost update of repair project.
  8CHMENCER.A. Operating Reactors Branch 1. 79/11/19. Spp.
- 7912040276 Plans to respond by 791221 to 790918 request for info repotential for steam generator water hammer at PWRs w/feedrings that discharge from bottom Manpower demands generated by NURG-0578 prevent response at present. UHR10.R.E. Florida Power & Light Co. 79/11/26. ip.

- 7912180344 Forwards draft input for steam generator tube failure safety evaluations. Sections 2. 1. 3.2. 2.3.2.3.3 & 2.4.3. Input for Doel Unit 2 reactor in Belgium encl. SCHMENCER.A. Operating Reactors Branch 1. 79/11/28. 1p.
- --7912180350 Draft input for steam generator tube failure safety evaluation, Section 2.1.3.
  # Office of Nuclear Reactor Regulation. 79/11/28, 5pp.
- --7912180354 Draft input for steam generator tube safety evaluation, Section 2.2.3. \* Office of Nuclear Reactor Regulation, 79/11/28. 4pp.
- --7912180358 Draft input for steam generator tube failure safety evaluation, Section 2.4.3. # Office of Nuclear Reactor Regulation. 79/11/28. 3pp.
- 7912070127 Notifies that info requested by NRC 790828.0927 & 1023 ltrs re-containment venting & gurge during normal operation will be submitted on 791213.

  UHRIG.R.E. Florida Power & Light Co. 79/11/29. 1p.
- 7912110304 Informs that NRC 791119 ltr not received until 791126.Will provide requested info by 791207.
  UHRIG.R.E. Florida Power & Light Co. 79/11/30. ip.
- 7912180243 Urges expeditious review & safety evaluation of RETRAN reactor sys transient analysis code. List of intended uses of RETRAN encl.
  UHRIG.R.E. Florida Power & Light Co. 79/12/07. 3pp.
- 7912140246 Agrees to revise Tech Specs for control rod misalignment & position indication re NRC request. Tech Spec amend will be submitted by 800229.

  UHRIO.R.E. Florida Power & Light Co. 79/12/10. 1p.
- 7912200508 Forwards info requested by NRC 781128 ltr re analyses & evaluations performed to resolve containment purge issue.
  Results of valve integrity evaluation anticipated by June 1980.
  UHRIO,R.E. Florida Power & Light Co. 79/12/13. 9pp.
- 7912270391 Advises that proposed Tech Spec amends are being developed in response to NRC 790726 ltr. Proposal to be submitted 800331 will address undervoltage protection; proposal to be submitted 800131 will address diesel generator surveillance. UHRIO.R. E. Florida Power & Light Co. 79/12/18. 1p.
- 7912270350 Responds to NRC 791017 ltr re auxiliary feedwater sys. Amend to Tech Specs covering auxiliary feedwater pumps scheduled for submittal on 600131. Sys operability verified monthly by starting pumps & establishing flow to steam generators.

  UHRIO.R. E. Florida Power & Light Co. 79/12/20. 9pp.
- 7912270513 Withdraws proposed Tech Spac changes re fuel rod bowing. UHRIG.R.E. Florida Power & Light Co. 79/12/20. 2pp.
- 7912280548 Notifies that 791213 rept, "Program Plan for Performance Verification of PWR Bafety/Relief Valves & Sys," is responsive to requirements listed in NUREG-0378. UHRIG.R.E. Florida Power & Light Cd. 79/12/21. ip.
- G. Inspection reports. IE Bulletins & correspondence
- 7912060143 Forwards IE Info Notice 79-12A, "Attempted Damage to New Fuel Assemblies." No specific action or response required, O'REILLY, P. Region 2: Atlanta, Office of the Director. 79/11/09. 2pp.
- 7912100181 Forwards IE Info Notice 79-28. "Overloading of Structural Elements Dus to Pips Support Loads." No response required. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 79/11/16. ip.
- 7912110561 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required.

  O'REILLY, J.P. Region 2, Atlanta, Office of the Director.

  79/11/16. 2pp.
- 7912040616 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs," No response required.

  6'REILLY, J.P. Region 2: Atlanta, Office of the Director.
  79/11/26. ip.

- 7912110147 Forwards IE Circular 79-23. "Motor Starters & Contactors Falled to Operate." No response required.

  D'REILLY, J. P. Region 2. Atlanta. Office of the Director.
  79/11/24. 1n
- 7912190442 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Written response required. D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/30. 1p.
- 7912200004 Responds to IE Bulletin 79-17. Revision i re stagnant borated water sys. Addl drawings provided identifying safety-related Type 316 stainless steel pipe sys containing stagnant oxygenated borated water. W/o encl.
  UHRIG.R.E. Florida Power & Light Co. 79/11/30. ip.
- 7912310297 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action required.
  O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
  79/12/06. 5pp.
- 7912200033 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action regulared. O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
- 7912280402 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required. O'REILLY, J. P. Region 2, Atlanta, Dffice of the Director. 79/12/13. 2pp.
- 7912280136 Forwards IE Circular 79-25, "Shock Arrestor Strut Assembly Interference," No written response required. D'REILLY,J.P. Region 2, Atlanta, Office of the Director. 79/12/20, 4pp.
- 8. Reportable occurrences, LERs & related correspondence
- 7912030146 Forwards updated LER 79-011/03X-1. SCHMIDT, A. D. Florida Power & Light Co. 79/10/25. 1p.
- ---7912030149 Updated LER 79-100/03X-1:on 790622.charging sys performance noted to be degraded during routine startup operation. Caused by ruptured diaphram & damaged O-ring on valve. Valve repaired & pumps vented.

  SCHOPPMAN.M. A. Florida Power & Light Co. 79/10/25. ip.
- 7912140229. RO-250-79-33: an 791101, vendor discovered error in current ECCB analysis input data. Correction resulted in allowable Eq limit reduction of steam generator tube. Augmented surveillance or power limits applied.

  HAYES, J. K. Florida Power & Light Co. 79/11/02. 1p.
- U. Congressional/Executive Correspondence
- 7912170395 Forwards 8W Meyerson 791107 1tr re problems at plant. Requests comment. CHILES.L. Benate. 79/11/19. 2pp.
- DOCKET 50-252 UNIV. OF NEW MEXICO RESEARCH REACTOR
  F. Security, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Guide 5.XX, "Std Format & Content for Licensee Physical Security Plan for Protection of BNM of Moderate or Low Strategic Significance." W/o enci. REID, R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22.
- DOCKET 50-254 GUAD-CITIES STATION, UNIT 1
  F. Security, medical, emergency & fire protection plans
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives Provides guidence for improving licensee emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.

  ORIMES, B. K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- 7912270063 Forwards list of specific items requiring updating in smergency plans. Emergency plans were evaluated using code requirements, Reg Guide 1.101 & Emergency Planning Review Ouidelines Number 1.Revision 1.
  IPPOLITO, T. A. Operating Reactors Branch 3. 79/11/30. 7pp.

- 7912200672 Requests payment of Class III fees for review of 790816 nuclear security personnel training & qualification plans. DIGOS.R.M. License Fee Management Branch. 79/12/07. 1p.
- H. General correspondence
- 7912280605 Discusses 791204 title change of manager of nuclear operations to vice president Organization structure not altered. No revision will be made to GA program topical rept CE-1-4 until organization structure is delineated.

  JANECEK, R. F. Commonwealth Edison Co. 79/12/19. 1p.
- P. Operating license stage documents & correspondence
- 7912120088 Submits info re rolease rates of gaseous & particulate forms of radioactive matls during third quarter of 1979.
  KALIVIANAKIS.N. Commonwealth Edison Co. 79/10/25. 1p.
- 7912100187 Discusses NRC 791101 meeting w/representatives of NSSS vendors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EISENHUT.D.O. Division of Operating Reactors. 79/11/09. 65pp.
- --7912100255 Responds to NRC 791101 request re noncompliance of Westinghouse ECCB evaluation model under requirements of IOCFR30 App K. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants.

  ANDERSON, T. M. Westinghouse Electric Corp. 79/11/02. 4pp.
- --7912100330 Responds to NRC 791101 request re ORNL cladding swelling & rupture data.Review of analytical models & tests indicates compliance w/10CR50 App K. All GE specs for calculated peak cladding temp remain unchanged.

  DUCHHOLZ.R.H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50.46 satisfied.

  OMBLEV.O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/11/02. 5pp.
- --7912100456 Forwards addl info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model.

  No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results.

  OMSLEY.O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).

  79/11/04. 22pp.
- 7912040261 Forwards plant steam bypass capacity sheets.percent rated. Info provided to GE for incorporation into NEDO-2470B. PEOPLES.D.L. Commonwealth Edison Co. 79/11/16. 200pp.
- 7912040297 Forwards supplementary response to be incorporated into 791018 ltr re lessons learned commitments to meet near-term requirements.
  REED.C. Commonwealth Edison Co. 79/11/30. 7pp.
- 7912040485 Submits updated schedules for installation of recirculation pump trip mods per 790329 ltr. PEOPLES D.L. Commonwealth Edison Co. 79/11/30. Rpp.
- 7912120411 Forwards supplementary response re commitment to meet short-term requirements of Lessons Learned Task Force. REED, C. Commonwealth Edison Co. 79/11/30. 7pp.
- 79:2:20425 Forwards supplemental response to 79:0:8 ltr re commitments to Lessons Learned Task Force recommendations. PEOPLES: D. L. Commonwealth Edison Co. 79/12/03. 2pp.
- 79121103BO Proposes to amend Tech Specs, extending max average planar linear heat generation rate to larger exposure values. Errata & addenda sheets for "LOCA Analysis Ropt," Tech Specs page changes & Class III fees encl.
  PEDPLES.D.L. Commonwealth Edison Co. 79/12/04. Rpp.
- ---7912110384 Errata & addenda sheets for "LUCA Analysis Rept."

  \* General Electric Co. NEDD-24146. 79/10/31. 3pp.
- --7912110391 Tech Bpec page changes:Page B1C-1 for Dresden-2 & Figure 3.5-1 for Quad-Citles-1.

  \* Commonwealth Edison Co. 79/10/31. 5pp.
- 7912200672 Requests payment of Class III fees for review of 790816 nuclear security personnel training & qualification plans. DIGOS, R. M. License Fee Management Branch. 79/12/07. 1p.

- 7912210349 Forwards cover sheet for CE-1-A.Revision 10, inadvertently omitted from 791115 transmittal. NAUGHTON, W. F. Commonwealth Edison Co. 79/12/13. 2pp.
- 7912180831 Forwards info documenting evaluation of purge & vent valve operability verification. Util committed to purge & vent sys in conformance w/NRG interim position. Complete confirmatory analyses not available for 30-40 wk. PEOPLES.D.L. Commonwealth Edison Co. 79/12/14. 6pp.
- 7912190542 Forwards "Adequacy of Station Electric Distribution Bys Voltages," addressing 480-volt undervoltage conditions. JANECEK,R.F. Commonwealth Edison Co. 79/12/14, lp.
- --7912190545 "Adequacy of Station Electric Distribution Sys Voltages." \* Cammonwealth Edison Co. 79/12/14. Bpp.
- 7912270469 Forwards response to NRC request for add1 info on Lessons Learned Tack Force Recommendations 2.1.7a & 2.1.7b. PERPLES.D.L. Commonwealth Edison Co. 79/12/14. Bpp.
- 7912270597 Advises of compliance w/Category A TMI Lessons Learned Task Force items identified in NRC 770913 & 1030 ltrs. Compliance will be achieved by BO0101, or prior to return to power for units in outages on BO0101. PEOPLES.D.L. Commonwealth Edison Co. 79/12/17. lp.
- 7912270459 Confirms discussions re proposed Tech Spec Amend to extend max average planer linear heat-generation rate curves. No fuel type is expected to exceed peak poliet exposure above 40,000 MHD/ST.

  JANECEK, R. F. Commonwealth Edison Co. 79/12/20. ip.
- 7912280533 Responds to NRC 791031 request for plant-unique implementation schedule for additional condensation tests re Mark I full scale test facility Analysis dependent on final resolution of acceptance criteria.
  PEOPLES D. L. Commonwealth Edison Co. 79/12/20. 2pp.
- 7912310348 Forwards revised pages to CE-1-A. "Comm Ed GA Program for Nuclear Generating Stations." Revision 11.

  JANECER, R. F. Commonwealth Edison Co. 79/12/20. 1p.
- --7912310359 Revised pages to CE-1-A, "Comm Ed OA Program for Nuclear Generating Stations," Revision 18. \* Commonwealth Edison Co. CE-1-A. 79/11/21. 16pp.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912050106 Forwards IE Circular 79-22. "Stroke Times for Power Operated Relief Valves." No response required.
  KEPPLER, J. 6. Region 3. Chicago, Office of the Director. 79/11/16.
  1p.
- 7912100213 Forwards IE Info Notice 77-20, "Overloading of Structural Elements Due to Pipe Support Loads." No response required.

  KEPPLER, J. G. Region 3. Chicago, Office of the Director. 79/11/16.

  1p.
- 79:21:10597 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required.

  KEPPLER.J.Q. Region 3: Chicago: Office of the Director.
- 7912180013 Notifies of delay in implementation of IE Bullstin 79-14 re accessible areas comparison & evaluation phase Current program provides for earliest detection & evaluation of significant discrepancies. PEOPLES.D.L. Commonwealth Edison Co. 79/11/19, 2pp.
- 7912050330 Forwards IE Dulletin 79-25, "Boron Loss From BWR Control Blades." Response required.

  HEPPLER, J. 9. Region B, Chicago, Office of the Director. 79/11/20.

  1p.
- 7912100417 Forwards IE Circular 79-24. "Proper Installation & Calibr of Core Spray Ptps Break Detection Equipment on DWRs." No written response required KEPPLER.J. G. Region D. Chicago, Office of the Director. 79/11/26.
- 7912140187 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No written response required.
  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/26.

- 7912110395 Notifies that NRC intends to routinely forward to appropriate state public wtil regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sent by NRC to licensees.

  KEPPLER, J. 9. Region 3. Chicago, Office of the Director. 79/11/28.
- 7912190199 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Written response required. KEPPLER, J. O. Region J. Chicago, Office of the Director. 79/11/30.
- 79:2140036 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances: 10CFR21." No action or response required.

  KEPPLER, J. G. Region 3. Chicago, Office of the Director. 79/12/06.
- 7912200084 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/12/10.
- 7912200443 Notification of 791213 meeting w/util to discuss IE Bulletin 79-02 anchor bolt & base plate analysis.

  JORDAN, E. L. Division of Reactor Operations Inspections. 79/12/11.

  3pp.
- S. Reportable occurrences, LERs & related correspondence
- 7912180084 PNG-III-79-41A: on 791120, unit in cold shutdoun mode to repair small crack in feadwater line.Leakage being collected in drum.Leak in 14-inch long.3/4-inch drain line between weld & isolation velve.Licenses will cut line & cap it. CHRISSOTIMOB.N., BOYD.D.C. Region 3, Chicago, Office of the Director, 79/11/20. ip.
- 7912070443 Forwards LER 79-033/03L-0.
  KALIVIANAKIS.N. Commonwealth Edison Co. 79/11/27. ip.
- --7912070450 LER 79-033/03L-0: on 791030, suppression pool level discovered below Tech Epot limits. Caused by suppression chamber narrow range level instrumentation responding slowly to change in suppression pool level. Hore water added to suppression pool. Evel Hore water added to suppression pool. VAHRENHALD.U. Commonwealth Edison Co. 79/11/27. 2pp.
- 7412170410 PND-III-79-050: on 79112B, setpoint of ECCS instruments experienced 4-inch nonconformance. Caused by conservative setpoints from previous calibr. Calculations using new temp data revealed vessel level indications in 6-inch error. SPEBSARD, L. Region 3, Chicago, Office of the Director. 79/11/2B. ip.
- 7912180352 Forwards LER 79-035/03L-0.
  KALIVIANAKIS,N. Commonwealth Edison Co. 79/11/30. 1p.
- --7912180370 LER 79-035/03L-0: on 791107.RHR avc water line supports found W/safety factor less than two. Containment coaling loop declared inoperable. Caused by design deficiency. Supports modified for factor above four. loop returned to avc. LEECH.K. Commonwealth Edison Co. 79/11/30. ip.
- 7912270394 Forwards info ro 750806,771106 & 780213 loss of offsite power events, in response to 790918 request. JANECEK, R. F. Gammonwealth Edison Co. 79/12/20. App.
- DOCKET 50-255 PALISADES NUCLEAR PLANT
  F. Security, medical, emorgency & fire protection plans
- 7912180335 Notifies of delay in Plant Sys Branch Team 1 evaluations of facility fire protection sys. Butlines of assistance needed entl. LAINAG.G. Plant Systems Branch. 79/11/16. Spp.
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives Provides guidance for improving licenses emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.

  GRIMES, B. K. Emergency Preparedness Task Force. 79/11/23. GOpp.
- 9. Adjudicatory correspondence
- 7912110038 Confirms receipt of encl 790329 petition to suspend OLs for all PWRs. Forwards FR notice indicating that petition will be troated in accordance w/10CFR2.206.
  DENTON, H.R. Office of Nuclear Reactor Regulation. 79/11/23. ip.

- --7912110126 Notice of request for action pursuant to 10CFR2.206 re Environ Coalition on Nuclear Power 770329 petition requesting suspension of all OLs for PWRs. MULLER.D.R. Office of Nuclear Reactor Regulation. 79/11/23. 3800.
- 7912060834 Protests 791109 notice of proposed imposition of civil panalties re containment isolation noncompliance. Ramission or mitigation of civil penalties requested. Response to notice of violation submitted apparately.

  YOUNODAHL.R.C. Consumers Power Co. 79/11/29. 13pp.
- ---7912060535 Responds to 791109 notice of violation re containment isolation noncompliance. Disagrees w/noncompliances cited. Prompt & efficient actions taken to remody deficiencies. DEWITT, R. B. Consumers Power Co. 79/11/29. opp.
- --7912060537 "Independent Review of Containment Penetrations," Vols 1 & 2. \* MPR Associates, Inc. 79/11/15. 112pp.

- 791206050B Notifies that offsite radiation protection training course for NRC inspectors B satisfactory. Requests advance notification of arrival of NRC personnel.

  LDUBENSLAGER, T. Consumers Power Co. 79/12/03. 1p.
- J. Insurance & indemnity information
- 7912040447 Forwards Amends 9 & 17 to Indemnity Agreements D-40 & B-22. respectively, modifying prefetory language re course of transportation. IRELAND, J. H. Consumers Power Co. 79/11/29. Gpp.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 7912060519 Forwards FSAR, Revision 6. F000, W. O. Consumers Power Co. 79/12/04. 1p.
- --7912060520 Revision 6 to FSAR.updating Pages 8-20s. # Consumers Power Co. 79/12/04. 2pp.
- P. Operating license stage documents & correspondence
- 7911090248 "Bummary of Operating Experience W/Recirculating Steam Generators." EISENAUT, D. G. Division of Operating Reactors. NUREG-0523. 79/01/31. B9pp.
- 7912130008 Forwards summary of methodology & parameters for SEP seismic reviews. Summary is interim guide for use in review of facilities. Requests comments.

  HOFMAYER. C. H. Bystematic Evaluation Program Branch. 79/11/08.
- 7912100189 Discusses NRC 791101 meeting W/rapresentatives of NSSS vendors & fuel suppliers or discussion of respective portions of ECCS evaluation models dealing wifuel cladding smalling & incidence of rupture. Vendor responses encl. EISENMUT, D. Q. Division of Operating Reactors. 79/11/09. 65pp.
- ~-7912100255 Rasponds to NRC 791101 request re noncompliance of Westinghouse ECCS evaluation model under requirements of IOCFR50 App K. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants.

  ANDERSON.T.M. Hestinghouse Electric Corp. 79/11/02. 4pp.
- ---7912100330 Responds to NRC 791101 request re ORML cladding swelling & rupture data. Review of analytical models & tests indicates compilance w/10CFR50 App K. All GE specs for calculated peak cladding temp remain unchanged.

  BUCHHOLZ, R. H. General Electric Co. 79/12/07. Spp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50, 46 satisfied.

  GMSLEY, G.F. Exxon Nuclear Co.: Inc. (subs. of Exxon Corp.).
  79/11/02. 5pp.
- --7912100456 Forwards addl info re evaluation of impact of NRC proposed ruptura/blockage model used in vandor evaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. CHBLEY.6.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/04. 22pp.

- 7912110020 Forwards updated lists of SEP topics not requiring site review due to ongoing generic licensing activities outside SEP or because of inapplicability to facility.
  ZIEMANN, D. L. Operating Reactors Branch 2. 79/11/16. Bpp.
- 7912120262 Summary of 791025 meeting w/C-E owners group re asymmetric LOCA loads. HOSFORD, S. B. Engineering Branch. 79/11/20. 4pp.
- 7912170042 Requests Class III fee re review & approval of radiological effluent Tech Spec changes. Fee for 790927 request due 15 days upon receipt of ltr. MILLER. M. D. License Fee Management Branch. 79/11/27. lp.
- 7912180081 Forwards draft evaluation of SEP Topic II-1.A. "Exclusion Area Authority & Control." SEP Topic II-1.D. "Population Distribution" & SEP Topic II-1.C. "Potential Harards Due to Nasrby Industrial,Transportation & Military Facilities."

  ZIEMANN.D.L. Operating Reactors Branch 2. 79/11/27. 19pp.
- 7912180208 Notification of 791130 meeting w/util in Washington, DC to discuss util implementation of order requiring review of checklists & procedures to assure engineering safety features comply w/limiting conditions for operation stds. # Office of Inspection & Enforcement, Office of the Director. 79/11/28. 1p.
- 7912190202 Review of 791031 proposal re startup physics test program. Complete program acceptable. ZIEMANN, D.L. Operating Reactors Branch 2. 79/11/29. 2pp.,
- 7912060621 Requests NRC review of encl draft matts re proposed Tech Boet change concerning radiological effluents. Draft Dose Calculation Manuals, draft process control programs & radiological effluent Tech Specs encl. HDFFMAN, D. P. Consumers Power Co. 79/12/03. 2pp.
- --7912060622 Braft radiological effluent Tech Specs for Palisades. \* Consumers Power Co. 79/11/30. 9pp.
- --7912060623 Palicades draft Offsita Dose Calculation Manual. \* Consumers Power Co. 79/11/30. 50pp.
- --7912060624 Palisades health physics procedure for laundry radwaste batch calculation & release authorization. \* Consumers Power Co. 79/10/08. 11pp.
- --7912060629 Palisades health physics procedure for modified radwaste calculation & release authorization.

  3 Consumers Power Co. 79/10/09. 9ep.
- --7912060626 Palisades health physics procedure for sampling wasto gas decay tank.

  \* Consumers Power Co. 79/04/18. 2pp.
- --7912060627 Palisades health physics procedure for analysis of waste gas decay tank samples.
  # Consuders Power Co. 79/04/18. ip.
- ---7912060628 Palisades health physics procedure for calculation of waste
- gas decoy tank. \* Consumers Power Co. 79/10/10. 13pp.
- --7912060627 Palisades health physics procedure for stack gas particulate & lodine sampling.
  \*\* Consumers Power Co. 79/10/10. 2pp.
- --7912060630 Polisades health physics procedures for stock gas sample counting.

  \*\* Consumers Power Co. 79/10/10. 1p.
- ---7912060631 Palisedes health physics procedures for authorization of containment purge.

  \*\* Consumers Power Co. 78/03/30, 4pp.
- --7912080632 Palisades health physics procedure for calculation of condenser offgas effluents.
  \* Consumers Power Co. 79/10/10. 1p.
- --7912060633 Pelisades health physics procedure for turbine & dirty waste sump calculations.
  \* Consumers Power Co. 79/10/06. ip.
- --7912040434 Palisades draft process control program, Nov 1979. \* Consucers Power Go. 79/11/30. 3pp.

- --7912060636 Palisades operating procedures for gaseous radwaste sys. Consumers Power Co. 79/10/18. 17pp.
- --7912050537 Palisades operating procedures for solid radwaste sys. \* Consumers Power Co. 79/10/18. 25pp.
- --7912060641 Palisades operating procedures for spent resin handling
  - sys. Consumers Power Co. 79/10/18. 18pp.
- --7912070467 Health physics procedure for stack gas calculations & effluent records at Palisades.

  \* Consumers Power Co. 79/12/03, 7pp.
- 7912070125 Forwards license fee for review of App I submittal re radiological effluent Tech Spec changes. F000. W. C. Consumers Power Co. 79/12/04. 1p.
- 7912130239 Submits supplementary info on analysis of flow-rate & filter performance & structural integrity of purge bypass sys re containment isolation noncompliance. Proposed civil penalties are etcassive. YOUNGDAHL.R.C. Consumers Power Co. 79/12/06. 2pp.
- 7912110303 Submits response to NRC 791002 ltr re Oak Ridge Associated Univs radiation safety course Requests advance notification of personnel arrival to eliminate delay in site-specific training. FROST, S. R. Consumers Power Co. 79/12/07. 1p.
- 7912140415 Responds to NRC 791030 ltr re recommendations conterning auxiliary feedwater sys. Util will lock open valves in series in auxiliary feedwater sys pump suction piping as well as valves in series that could interrupt feedwater flow. HUSTON, R. W. Consumers Power Co. 79/12/11. 15pp.
- 7912190466 Submits response to NRC 791029 request for add1 info re SEP structural Topic III-2, Topic III-7. B. 1, Topic III-7. B. 2, Topic III-7. B. 3, Topic III-7. B. 4, Topic III-7. B. 5, Topic III-7. C & Topic III-7. D. HOFFMAN. D. P. Consumers Power Co. 79/12/14. 4pp.
- --7912190487 "Containment Bldg Structural Integrity Test." \* Bechtel Corp. 70/11/30. 129pp.
- --7912190496 "Deformation Heasurements During Containment Pressure Test."
  4 Miss. Janney, Elstner & Association, Inc. 70/10/05. 35pp.
- 7912210146 Responds to NRC 791030 ltr re TMI-2 Lessons Learned Task Force Status rept & short-term recommendations & provides implementation schedule.
  HUSTON, R. M. Consumers Power Co. 79/12/17. 2pp.
- 7912310344 Discusses revised portion of branch technical position re direct radiation measurementπ in radiological environ monitoring program Suppl to application for radiological effluent Tech Spocs unnecessary at present. FRDST.S.R. Consumers Power Co. 79/12/26. 19.
- 7912310373 Discusses use of Westinghouse BFD/NDFD relays in safety-related sys.Facility does not use or intend to use relays. FROST.B.R. Consumers Power Co. 79/12/26. 1p.
- 7912310476 Responds to NRC 790913 & 1030 ltrs relactions taken in response to TMI-2 accident Hill not start up from refueling outage until plant complies w/encl and commitment Revises & supersedes 791217 ltr re implementation criteria. HOFFHAN, D. P. Consumers Power Co. 79/12/27. 94pp.
- --7912310481 Draft "Input for Response to NRC Lessons Learned Requirements for C-E NSSS." \* Combustion Engineering, Inc. CEN-125, 79/12/31, 100pp.
- --7912310487 "Project Requirements for Plant Power Conversion Sys Relief Valve Position Indication." Supporting documentation encl. Energy Incorporated. 79/11/08. 37pp.
- --7912310475 Const specs for outside containment parties of pressurizer relief valve position indication sys. HENDERSON.S. A. TROUKINGINEN.G., SHANEL, H.H. Energy Incorporated, 79712705. http.
- --7912310501 Const specs for inside containment portion of pressurizer relief valve position indication sys. TROMEMOINEN.O. OREEN, H. W. , DIDESCH. T. E. Energy Incorporated. 79/11/13. 23pp.

- ---791231050B "Rept of Seismic Vibration Testing of Various Electrical Items for B&W Under Purchase Order 03378BLO." ESPOSITO.B., TOLF,M.L., GILFOY,R. Affiliation Unknown. 79/02/28.
- -7912310513 "Results from Charge Preamplifier Temp Test." BRAML, H. J., LEKA, A. F., COBB, J. H. Babcock & Wilcox Co. BAW-1590. 79/11/30. 18pp.
- -7912310517 "Installation & Checkout Procedures C-010-00 for Valve Monitoring Sys. "
  SPINSILL.D. J. Consumers Power Co. 79/11/12. 10pp.
- ~7912310523 "Post-TMI Evaluation Task 2.Conceptual Design for Reactor Vessel Level Monitoring Sys." Sixteen oversize drawings Combustion Engineering, Inc. 79/12/21. 102pp.
- O. Inspection reports. IE Bulletins & correspondence
- 7912050210 Responds to IE Bulletin 79-23.No connections exist between neutral of generator & neutral of primary winding of excitation power transformer. Test of emergency dissels will be performed prior to completion of next refueling outage. HOFFMAN.D.P. Consumers Power Co. 79/11/05. 2pp.
- 7912200678 Responds to IE Bulletin 79-23 re failure of emergency diesel generator field exciter transformer. No connections between neutral of generator & neutral of excitation power transformer. Plans full load test of both emergency diesels. HOFFHAN. D. P. Consumers Power Co. 79/11/05. 2pp.
- 7912190786 Forwards IE Insp Rept 50-255/79-16 on 790706,09,23-24, OBIG-14,0918,29-30 & 1001.
  KEPPLER, J. C. Region 3, Chicago, Office of the Director. 79/11/07.
- ---7912170792 Notice of violation from insp on 790706,09,23-24,0813-14, 0918,29-30 & 1001. # Region 3, Chicago, Office of the Director. 79/11/09. ip.
- --7912190799 IE Insp Rept 50-235/79-16 on 790706.09.23-24.0813-14.0918, 29-30 % 1001. Noncompliance noted: shipment of licensed matl to licensed burial facility in unauthorized form. COOLEY.M.J., DAVIS.A.B., FISHER.M.L. Region 3, Chicago, Office of the Director. 79/11/05. 45pp.
- 7912040217 Forwards response to IE Bulletin 79-14. "Baismic Analysis for Am-Built Bafety-Related Piping Sys." Heven evaluations of pipe stress rewealed no nonconformances. One revealed need for add pipe support.
  HOFFMAN.D.P. Consumers Power Co. 79/11/09. 3pp.
- 7912050118 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required. KEPPLER.J.C. Region 3. Chicago, Office of the Director. 79/11/16.
- 7912100226 Forwards IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads." No response required.

  KEPPLER. J. G. Region 3. Chicago, Office of the Director. 79/11/16.
- 7912110571 Formards IE Info Notice 79-29. "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. KEPPLER.J.O. Region 3. Chicago, Office of the Director. 79/11/16.
- 7912050027 Notification of 791121 menting w/util & Bechtel to discuss IE Bulletin 79-02 anchor bolt insp program at facility. JORDAN, E.L. Division of Reactor Operations Inspections. 79/11/20.
- 7912050367 Forwards IE Bulletin 79-26, "Bordn Loss From BiR Control Blades." No response required. KEPPLER.J.Q. Region S. Chicago, Office of the Director. 79/11/20.
- 7912180126 Responds to 790802 Itr re short-term Action Item 1 of IE Bullstin 79-06C Requests revision of LDCA procedures to conform more closely w/IE Bullstin 79-06C, EIBENHUT, D. Q. Division of Operating Reactors. 79/11/24. 3pp.
- 7912100428 Forwards IE Circular 79-24. "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BURS." No written response required.
  KEPPLER.J. C. Region 3. Chicago, Office of the Director. 79/11/26.

- 7912110252 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. KEPPLER.J. Q. Region 3. Chicago, Office of the Director. 79/11/26. 1p.
- 7912110403 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs cupies of escalated enforcement correspondence sent by NRC to licensees.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/28.
- 7912190216 Forwards IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Written response required.

  KEPPLER, J. G. Region 3. Chicago, Office of the Director. 79/11/30.
  in.
- 7912130158 Summary of 791121 meeting w/util in Bethesda. HD re anchor bolt insp program at facility in accordance w/IE Bulletin 79-02.

  JORDAN, E.L. Division of Reactor Operations Inspections. 79/12/06.
- 7912140079 Forwards IE Info Notice 79-30. "Reporting of Defects & Moncompliances, 10CFR21." No action or response required. KEPPLER, J. C. Region 3. Chicago. Office of the Director. 79/12/06.
- 791220010A Forwards IE Bulletin 79-28, "Possible Halfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/12/10.
  18.
- 7912280499 Responds to NRC 791121 ltr re violations noted in IE Insp Rept 50-235/79-17. Corrective actions: reviewed check sheets far 1979 refueling outage for verification that primary coolant sys beron concentration was within Tech Specs. FROST, B.R. Consumers Power Co. 79/12/22. 2pp.
- 7912310294 Responds to MRC 791121 ltr re violations noted in IE Insp Rept 50-255/79-17. Corrective actions: 1979 refueling outage check sheats examined & leaking steam generator dam & reactor cavity liner repaired. FROST, S. R. Consumers Power Co. 79/12/22. 2pp.
- R. Pariodic operating reports & related correspondence
- 7912130293 Forwards monthly operating rept for Nov 1979. ADAMS. M. E. Consumers Power Co. 79/12/07. 2pp.
- ---7912130297 Monthly rept operating rept for Nov 1979. BODTKE.P.J. Consumers Power Co. 79/12/05. 4pp.
- S. Reportable occurrences, LERs & related correspondence
- 7912210041 PNO-III-79-11: on 791009, licenses notified NRC of possible nonconservative safety analysis. Review of main stemm line break inside containment revealed informed: assumption retreduction of mainfeadwater flow to steam generator.
  BOYD, D. C. Region 3, Chicago, Office of the Director. 79/10/09.
- 7912180508 Forwards 791205 NPDES noncompliance notification. HOFFMAN, D.P. Consumers Power Co. 79/12/14. 1p.
- --7912180512 NPDES noncompliance notification:on 791031. Five oil & grease samples collected indicated daily average of 21.9 mg/1.
  Caused by probable failure of oil separator. Separator restored to proper operation.
  FOBES.R.L. Consumers Power Co. 79/12/05. 1p.
- ---7912180314 NPDEB noncompliance notification:on 791015,23 & 29,011 & grasse samples indicated 41,29 & 24.1 mg/l.respectively.

  Caused by probable failure of oil separator. Separator restored to proper operation.

  FOBEB, R. L. Cunsumers Power Co. 79/12/05. ip.
- --7912180517 NPDES noncompliance notification: on 791020, 5,000 mallens of laundry water containing 2.58 mg/i phosphorus was released. Caused by change in type & quantity of detergent. Adjusted quantity of detergent used & will avaluate testing reagents. FDSES,R.L. Consumers Power Co. 79/12/05. ip.
- 7912310417 Forwards NPDES nencompliance metification on 790930. FROST, S.R. Consumers Power Co. 79/12/26. 1p.

- --7912310425 NPDES noncompliance notification: on 790930 daily average for suspended solids for laundry waste was higher than limit for Sept 1979. Cause unknown but organic growth suspected in postfilter hold tank. Sys analyzed for filter failure. FOBES, R. L. Consumers Power Co. 79/10/25. 19.
- 7912310436 Forwards NPDES noncompliance notification on 790927. FRDST, S. R. Consumers Power Co. 79/12/26. 1p.
- --7912310441 NPDES nancompliance notification: on 790927, approx 2,500 gallons of laundry waste measuring 4,92 mg/l total phosphorous discharged. Caused by indiscriminate use of new laundry detergent.
  FOBES,R.L. Consumers Power Co. 79/10/25. ip.
- 7912310364 Responds to 791213 & 21 telcons re turbine disc cracking problem. Util instructed by Westinghouse to reassemble low pressure turbine, after cracks found on 791029. Reinspection of discs planned approx nine months after startup. HOFFMAN.D.P. Consumers Power Co. 79712/28. 2pp.
- DOCKET 50-256 UNIV. OF MONTEVIDED RESEARCH REACTOR
- P. Operating license stage documents & correspondence
- 7908010339 Notifies of status of rept on reactor cavity annulus seal.
  Most PNR users remove ring during normal operation. Others
  store seal ring in raised position during normal operation.
  LAIMAS.G. Plant Systems Branch (Pre 791030). 79/07/05. 7pp.
- DOCKET 50-259 BROWNS FERRY MUCLEAR POWER STATION. UNIT 1
- F. Security, medical, emergency & fire protection plans
- 7912200022 Discusses NRC 791107 meeting re emergency preparedness team review objectives. Provides guidance for improving licensee emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.

  ORIMES, B. K. Emergency Preparedness Task Force. 79/11/23. GOpp.
- P. Operating license stage documents & correspondence
- 7910010550 Notifies that HB Clayton will replace RJ McDermott as alternate on ASME Subcommittee on Performance Testing.
  MINDQUE,R.B. Office of Standards Development. 79/09/05. 1p.
- 7912100187 Discusses NRC 791101 meeting w/representatives of NSSS vendors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EISENRUT, D. Q. Division of Operating Reacture. 79/11/09. 65pp.
- ---7912100255 Responds to NRC 791101 request re noncompliance of Mestinghouse ECCS evaluation model under requirements of 10CFH50 App Kevaluation of three fuel rod models indicates no safety problems for Mestinghouse plants.

  ANDERSON.T.M. Hestinghouse Electric Corp. 79/11/02. 4pp.
- ---7912100330 Responds to NRC 791101 request re ORNL cladding swelling & rupture data. Review of analytical models & tests indicates compliance w/10CFR30 App K. All GE specs for calculated peak cladding temp rewain unchanged.

  BUCH-KOLZ. R. H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst tent data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR30.46 satisfied. OMSLEY.O.F. Expon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/02. 5pp.
- ---7912100456 Forwards add1 info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results.

  OMSLEY, 9. F. Exam Nuclear Co., Inc. (subs. of Exam Corp.).

  79/11/04. 22pp.
- 791226001B Responds to 790629 & 20 submittals re-proposed radiological seffluent Tech Specs. Requests 791206 seeting w/util in Bethasda-MD. Agenda items sncl.

  IPPOLITO.T.A. Operating Reactors Branch 3. 79/11/26. 4pp.
- 7912040435 Informs NRC that as member of BMR owners group, util commits to accept & implement owners group positions on NUREQ-0578, Items 2.1.3.6 & 2.1.9.
  HILLS, L. M. Tennessee Valley Authority. 79/11/29. 1p.

- 912050508 Forwards requested amend to Licenses DPR-33,DPR-52 & DPR-68, changing Tech Specs to reflect Nuclear Safety Review Board Class I & Class II fees forthcoming. MILLS.L.M. Tennessee Vailey Authority. 79/11/29. 2pp.
- --7912050510 Proposed changes to Tech Specs, reflecting Nuclear Safety Review Board charter. \* Tennessee Vailey Authority. 79/11/29. 24pp.
- 912130023 Notification of 800110 maeting b/util to discuss reporting level of util 8A & manager & QA review of documents. SPRAUL.J.G. Guality Assurance Branch. 79/12/05. 1p.
- 912130402 Forwards proposed amend to Licenses DPR-33,DPR-52 & DPR-68 to change Tech Specs re isolation of main steam lines following main steam line high temp logic actuation. MILLS.L.M. Tennessee Valley Authority. 79/12/05. 2pp.
- -791213050B Tech Specs revision for isolation of main steam lines. \* Tennessee Valley Authority. 79/12/05. 20pp.
- 912140273 Responds to 791022 ltr re containment purging & venting during normal operation. Forwards commitment to operate in conformance w/NRC interim position for containment purge & can valve operation.

  CROSS, J. L. Tennessee Valley Authority. 79/12/10. Spp.
- 912270251 Forwards amends to Licenses DPR-33.DPR-52 & DPR-58 changing Tech Specs re containment integrated leak rate test.
  MILLS.L.M. Tennessee Valley Authority. 79/12/17. 2pp.
- ~7912270256 Revised Pages 230 & 235 to Tech Specs re containment integrated loak rate test.
  \* Tennessee Valley Authority. 79/12/17. App.
- -7912270262 "Nuclear Containment Testing for TVA Nuclear Power Plants." presented at ANS 791111-16 winter meeting. CLARK.K.H.: WHITE.T.J. Tennessee Valley Authority. 79/11/16.
- 712270527 Notifies that Unit 2 will be in full compliance w/NUREG-C578 short-term requirements by 800101. MILLS-L.S. Tennessee Valley Authority. 79/12/19. 1p.
- Inspection reports, IE Bulletins & correspondence
- 712050366 Forwards IE Insp Repts 50-259/79-31.30-260/79-31 & 50-296/79-31 on 791002-05.No noncompliance noted. LEWIS.R.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 79/10/26. 2pp.
- -7912050379 IE Insy Repts 50-259/79-31 & 50-260/79-31 & 50-296/79-31 on 791002-05 No noncompliance noted, Major areas inspected:core thermal power calculations, core power limits, radioactive discharge & plant operations.

  DANCE H. C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. PRICE, D. S. Region 2. Atlanta, Office of the Director. 79/10/26. Spp.
- 712060163 Forwards IE Info Nutice 79-12A, "Attempted Damage to New Fuel Assemblies." No specific action or response required. O'REILLY,J.P. Region 2. Atlanta, Office of the Director. 79/11/09. Spp.
- 712210203 Forwards IE Insp Repts 50-259/79-32,50-260/79-32 & 50-296/79-32 on 791016-18.No noncompliance noted. MURPHY.C.E. Region 2. Atlanta, Reactor Construction & Engineering Busport Branch. 79/11/09. 2pp.
- -7912210210 IE Insp Repts SG-259/79-32, 50-240/79-32 & 50-294/79-32 on 791016-18 No nencoupliance noted Major areas inspected: thermal sleeve attachment wolds, feedwater pump shaft failures & observation of work activities.

  VAN DDORN, P. K. Region 2. Atlanta. Office of the Director. HERDIA. R. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/11/07. 3pp.
- 012070499 Forwards IE Info Notice 79-27, "Steam Cenerator Tube Ruptures at Two PMR Plants." O'REILLY.J.P. Region 2, Atlanta. Office of the Director 79/11/16. 14pp.
- Pi2100192 Forwards IE Info Notice 79-20. "Overloading of Structural Elements Due to Pipo Support Loads." No response required. O'MEILLY,J.P. Region 2. Atlanta. Office of the Director. 79/11/16. 1p.

- 7912110575 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/11/16. 2pp.
- 7912080620 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No response required.

  O'REILLY,J.F. Region 2. Atlanta, Office of the Director.
  79/11/26. 1p.
- 7912110157 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. O'REILLY,J.P. Region 2, Atlanta, Office of the Director. 79/11/26. 1p.
- 7912190472 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation," Written response required.
  O'REILLY,J.P. Region 2, Atlanta, Office of the Director.
  79/11/30. 1p.
- 7912210202 Forwards IE Insp Repts 50-259/79-40,50-260/79-40 & 50-296/79-40 on 791113-16. No noncompliance noted. Details withheld (ref 10CFR2. 790).

  KENNA. W. D. Region 2. Atlanta, Safeguards Branch. 79/12/05. 2pp.
- -7912210212 IE Insp repts 50-259/79-40.50-260/79-40.50-296/79-40 on 791113-16.No noncompliance noted.Major areas inspected: security organization.Details withheld (ref 10CFR2.790). TILLMAN.A. Region 2. Atlanta.Office of the Director. TDBIN.M.J. Ragion 2. Atlanta.Safeguards Branch. 79/12/04.
- 7912310316 Forwards 1E Info Notice 79-30, "Reporting of Defects & Noncompliances,10CFR21." No action required.

  O'REILLY,J.P. Region 2, Atlanta, Office of the Director.

  79/12/06. dpp.
- 7912200060 Forwards IE Bulletin 79-20, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. 0'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/12/07. 3pp.
- 7912280426 forwards IE Info Notice 79-31. "Use of Incorrect Amplified Response Spectra." No written response required. O'REILLY.J.P. Region 2. Atlanta. Office of the Director. 79/12/13. 3pp.
- 7912280150 Forwards IE Circular 79-25, "Shock Arrestor Strut Assembly Interference." No written response required. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 79/12/20. 4pp.
- R. Periodic operating reports & related correspondence
- 7912140384 Forwards monthly operating repts for Nov 1979. ABERCROMBIE, N. Tennessee Valley Authority. 79/12/10. 1p.
- ---7912140393 Monthly operating repts for Nov 1979. GREEN.D. Tennessee Valley Authority. 79/12/02. 33p.
- S. Reportable occurrences, LEAs & related correspondence
- 7912040301 Forwards updated LER 79-002/03L-1. CALHOUN.J.R. Tennessee Valley Authority. 79/11/23. 1p.
- --7912040303 Updated LER 79-002/03L-1.on 790127.SLC pump 18 relief valve opened prematurely. Caused by deterioration in valve seating surface which caused chattering. Replaced seating parts & verified proper pressure relief.

  4 Tennessee Valley Authority. 79/11/23. 1p.
- 7912180213 PND-II-77-034: on 791127.Revision 2 emergency responses ctr activated when notified by TVA of planned drill re transport of radwaste. Inspectors w/survey equipment dispatched to site of simulated accident. JONES.D., GILLESPIE, F. P. Region 2, Atlanta, Office of the Director. 79/11/27. 1p.
- 7912130438 RO-50-259/79-32: on 791128; during insp of restraints, typical hanger identified as possibly unacceptable. Caused by possible misapplication of hanger. Insp & analyses will be conducted to determine effect on sys.

  ADERCROMBIE, H. L. Tennessee Vallay Authority. 79/11/29, 1p.

- 7912180615 Forwards LER 79-032/01T-0. CALHOUN, J. R. Tennessee Valley Authority. 79/12/11. 1p.
- --7912180625 LER 79-032/01T-0: on 791129 residual heat removal supply to D heat exchanger restraint RI6 determined nonfunctional as installed Caused by erronous application of typical hanger design. Sys will function suring seismic event.

  \* Tennessee Valley Authority. 79/12/11. 2pp.
- 7912180623 Forwards LER 79-031/03L-0. CALHOUN, J. R. Tennesses Valley Authority. 79/12/12. 1p.
- --7912180629 LER 79-031/03L-0: on 791127, drywell air sampling monitor, RM 90-256, observed alarming downscale. Erratic indications recorded on previous occasions. Caused by failure of RAECO Hodel 1017 24-Volt transfer
- 7912280509 Forwards LER 79-034/03L-0.
  CALHOUN, J. R. Tennessee Valley Authority. 79/12/21. 1p.
- -7912280813 LER 79-034/03L-0: on 791126. while conducting relay testing on Unit 3 recirculation pump boards, relays inadvertently tested on Unit 1 pump boards shutting down both recirculation motor gamenator sets. Caused by personnel error.

  \* Tennessee Valley Authority. 79/12/21. 2pp.
- DOCKET 50-260 BROWNS FERRY NUCLEAR POWER STATION: UNIT 2
- F. Security, medical, emergency & fire protection plans
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives. Provides guidance for improving licensee amergency preparedness & assuring capability of official agencies to take appropriate emergency actions.

  ORIMES.B.K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- 9. Adjudicatory correspondence
- 791211003B Confirms receipt of encl 790329 petition to suspend CLs for all PWRs. Forwards FR notice indicating that petition will be treated in accordance w/10CFR2.206.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/23. ip.
- ~~7912110126 Notice of request for action pursuant to 10CFR2.206 re Environ Coalition on Nuclear Power 790327 petition requesting suspension of all OLs for PMRs. MULLER, D.R. Office of Nuclear Reactor Regulation. 79/11/23.
- P. Operating license stage documents & correspondence
- 7911090248 "Summary of Operating Experience W/Recirculating Steam Omerators."
  ElsEnHUT.D.O. Division of Operating Reactors. NUREG-0523.
  79/01/31. B7pp.
- 7912100169 Discusses NRC 791101 meeting w/representatives of NSSS vandors & fuel Suppliers re discussion of respective portions of ECCB evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EISENHUT. D. C. Division of Operating Reactors. 79/11/09. 65pp.
- -7912100285 Responds to NRC 791101 request re nuncompliance of Westinghouse ECCS evaluation model under requirements of 10CFR50 App K. Evaluation of three fuel rod models indicates no sefety problems for Wastinghouse plants.
  ANDERSON.T.M. Westinghouse Electric Corp. 79/11/02. 4pp.
- --7912100330 Responds to NRC 791101 request re CRNL cladding swelling & rupture data. Review of analytical models & tests indicates compliance w/10CFRSO App K.All GE specs for calculated peak cladding temp remain unchanged.

  BUCHHDLZ, R. H. General Electric Co. 79/12/07. 2pp.
- ~7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used, in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50.46 Eatisfied.
  OHBLEY, 0.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/02. 3pp. Ö,F. E.
- --7912100456 Forwards addl info re evaluation of impact of NRC proposed rupture/blockage model used in vandor evaluation model.

  No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results.

  OHBLEY, G. F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).

  79/11/04. 22pp.

- 791226001B Responds to 790629 & 20 submittals re proposed radiological effluent Tech Specs. Requests 791206 meeting w/util in Bethesda MD. Agenda items encl. Operating Reactors Branch 3. 79/11/26. 400. IPPOLITO, T. A.
- 7912040435 Informs NRC that as member of BWR owners group.util commits to accept & implement owners group positions on NUREG-0378, Items 2, 1, 3, b & 2, 1, 9.
  MILLS, L.M. Tennesses Vallay Authority, 79/11/29. ip.
- 7912030508 Forwards requested amend to Licenses DPR-33, DPR-52 & DPR-68, changing Tech Specs to reflect Nuclear Safety Review Board Class I & Class II fees forthcoming.
  MILLB, L. M. Tennessee Valley Authority. 79/11/29. 2pp.
- --7912050510 Proposed changes to Tech Specs, reflecting Nuclear Safety Review Board charter.
  \* Tennessee Valley Authority. 79/11/29. 24pp.
- 7912130023 Notification of 800110 meeting w/util to discuss reporting level of util GA & manager & GA review of documents.

  SPRAUL, J. G. Guality Assurance Branch. 79/12/05. 1p.
- 7912130482 Forwards proposed amend to Licenses DPR-33, DPR-52 & DPR-68 to change Tech Specs re isolation of main steam lines following main steam line high temp logic actuation.
  MILLS,L.M. Tennesses Valley Authority. 79/12/05. 2pp.
- --7912130308 Tech Spocs revision for isolation of main steam lines.
  \* Tennessee Valley Authority. 79/12/05. 20pp.
- 7912140273 Responds to 791022 ltr re containment purging & venting during normal operation. Forwards commitment to operate in conformance w/NIC interim position for containment purge & vent valve operation.

  CROSS.J.L. Tennessee Valley Authority. 79/12/10. Spp.
- 7912270251 Forwards amends to Licenses DPR-33:DPR-52 & DPR-60 changing Tech Specs re containment integrated loak rate test MILLB, L. M. Tennessee Valley Authority. 79/12/17. 2pp
- --7912270286 Revised Pages 230 & 235 to Tech Specs re containment integrated leak rate test. \* Tennesseo Vallay Authority. 79/12/17. 4pp.
- --7912270262 "Nuclear Containment Testing for TVA Nuclear Power Plants," presented at ANS 79111-16 winter meeting. CLARK, K. H. J. WHITE, T. J. Tennessee Valley Authority. 79/11/16.
- 7912270527 Notifies that Unit 2 will be in full compliance w/NUREG-0578 short-term requirements by 800101.
  MILLS.L.M. Tennessee Valley Authority, 79/12/19. 1p.
- O. Inspectium reports, IE Bulletins & correspondence
- 7912050366 Forwards IE Imsp Repts 50-259/79-31, 50-260/79-31 & 50-276/79-31 on 791002-09. No noncompliance noted. LEWIS,R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/10/26. 2pp.
- --7912050379 IE Insp Repts 50-289/79-31 & 50-260/79-31 & 50-296/79-31 on 791002-09. No noncompliance moted Major areas inspected:core thormal power calculations, core power limits, radioactive discharge & plant operations.

  DANCE, H. C. Region 2, Atlanta, Reactor Operations Nuclear Eupport Branch. PRICE, D. S. Region 2, Atlanta, Office of the Director. 79/10/24. Spp.
- 7912040163 Forwards IE Info Notice 79-12A, "Attempted Damage to New Fuel Assemblies." No specific action or response required. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 79/11/09. 3pp.
- 7912210203 Forwards IE Insp Repts 50-259/79-32,50-260/79-32 & 50-296/79-32 on 791016-18. No noncompliance noted. MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Eupport Branch. 79/11/09. 2pp.
- --7912210218 IE Insp Repts 50-259/79-32, 50-260/79-32 & 50-296/79-32 on 791016-18. No noncompliance noted. Major areas inspected: thermal sleeve attachment welds, feedwater pump shaft failures & observation of work activities.

  VAN DDGRN, P. K. Region 2. Atlanta, Office of the Director. HERDTA. R. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/11/07. 3pp.

- 7912070499 Forwards IE Info Notice 79-27, "Steam Concrator Tube Ruptures at Two PWR Plants." O'REILLY, P. Region 2, Atlanta, Office of the Director. 79711/16. 14pp.
- 7912100192 Forwards IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads." No response required. O'REILLY,J.P. Region 2. Atlanta. Office of the Director. 79/11/16. 1p.
- 7912110575 Forwards IE Info Notice 79-29. "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. 6'REILLTy.J.P. Region 2. Atlanta. Office of the Director. 79/11/16. 2pp.
- 79:2060620 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BMRs." No response required.

  0'REILLY.J.P. Region 2, Atlanta, Office of the Director.
  79/11/24. ip.
- 7912110157 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 79/11/24. ip.
- 7912190472 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation." Written response required. 0'REFLLYJ.P. Region 2, Atlanta, Office of the Director. 79/11/30. 1p.
- 7912210202 Forwards IE Insp Repts 50-259/79-40.50-260/79-40 & 50-276/79-40 on 791113-16.No noncompliance noted Details withheld (ref 100FR2.790).

  KENNA,M.B. Region 2, Atlanta, Safeguards Branch. 79/12/05. 2pp.
- --7912210212 IE Insp repts 50-259/79-40, 50-260/79-40, 50-296/79-40 on 791113-16. No noncompliance noted, Hajor areas inspected: security organization Details withheld (ref 10CFR2, 790), TILLHANA. Region 2, Atlanta, Office of the Director. TODIN.W.J. Region 2, Atlanta, Safeguards Branch, 79/12/04, 1p.
- 7912310316 Forwards IE Info Notice 77-30, "Reporting of Defects & Noncompliances: LOCFR21." No action required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/12/06. dpp.
- 7912200060 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. G\*REILLY, J. P. Region 2, Atlanta, Office of the Director, 79/12/07, 3pp.
- 7912280426 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required.
  0'RELLLY, J.P. Region 2, Atlanta, Office of the Director.
  79/12/13. 3pp.
- 79:12280:150 Forwards IE Circular 79-25, "Shock Arrestor Strut Assembly Interference." No written response required. O'RELLLY, J.P. Region 2, Atlanta: Office of the Director. 79/12/20, 4pp.
- R. Periodic operating reports & related correspondence
- 7912140384 Forwards monthly operating repts for Nov 1979, ADERCROMBIE, N. Tennesses Valley Authority. 79/12/10. 1p
- --7912140393 Honthly operating repts for Nov 1979. OREEN.D. Tennessee Valley Authority. 79/12/02. 33p.
- S. Reportable occurrences. LERs & related correspondence
- 7912180213 PNO-II-79-034: on 791127. Revision 2 emergency responses ctr activated when notified by TVA of planned drill retransport of radwaste. Inspectors w/survey equipment dispatched to site of simulated accident.

  JONES, D., OILLESPIE.F.P. Region 2. Atlanta. Office of the Director. 79/11/27. ip.
- 7912040477 Forwards LER 79-023/03L-0. CALHOUN J. R. Tennessee Valley Authority. 79/11/30. ip.

- --7912040483 LER 79-023/03L-0; on 791102, while performing surveillance test, torus hydrogen sensor gave high indication for 4% hydrogen calibr gas. Caused by model sensor failing in conservative directon. Design change planned to replace sys. \* Tennesses Vailey Authority. 79/11/30. 2pp.
- 7912270299 Forwards LER 79-024/03L-0.
  CALHOUN, J. R. Tennessee Valley Authority, 79/12/20. 1p.
- --7912270304 LER 79-024/03L-0: on 791121, while in hot standby, setpoint of pressure switch observed below Tech Spec limits, Caused by model R2T-A1288 switch drift. Switch recalibr & functionally tested satisfactorily.
  \* Tennessee Valley Authority. 79/12/20. 2pp.
- DOCKET 50-261 H. B. ROBINSON PLANT, UNIT 2
- F. Security, medical, emorgency & fire protection plans
- 7912200022 Discusses NRC 791109 meeting re amergency preparedness team review objectives. Provides guidance for improving licensee emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.

  ORIMES, B. K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- 7912170298 Forwards BNL design review & supplemental recommandations re fire protection. FERGUSON,R.L. Brookhaven National Laboratory. 79/12/11, App.
- G. Adjudicatory correspondence
- 791211003B Confirms receipt of encl 790329 patition to suspend OLs for all PWRs. Forwards FR notice indicating that petition will be treated in accordance w/10CFR2. 206.

  DENTON. H. R. Office of Nuclear Reactor Regulation. 79/11/23, ip.
- --7912110126 Notice of request for action pursuant to 10CFR2.206 re Environ Goalition on Nuclear Power 790329 petition requesting suspension of all OLs for PMRs. MULLER. D. R. Office of Nuclear Reactor Regulation. 79/11/23. 3Bps.
- J. Insurance & indemnity information
- 7912170254 Discusses 791220 transfer of funds to NRC constituting indemnity fee submitted for period 791204-801203.

  LANCASTER, J. L. Carolina Power & Light Co. 79/12/11. 1p.
- P. Operating license stage documents & correspondence
- 791109024B "Bummary of Operating Experience W/Recirculating Steam Generators." - EISENMUT.D.G. Division of Operating Reactors. NUREC-0523. 79/01/31. 89ap.
- 7912050145 Discusses NRC review of LERs & Tech Spec requirements recontrol RPI sys at Westinghouse PHRs. Requests Tech Epucs review to ensure requirement for rod maint to within +/- 12 steps indicated & RPI sys verified accurate within 12 steps. BCHWENCER.A. Operating Reactors Branch 1. 79/10/29. 7pp.
- 7912100189 Discusses NRC 791101 meeting w/representatives of NSSS vendors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swelling t incidence of rupture. Vendor responses encl. EISENRUT.D.Q. Division of Operating Reactors. 79/11/09. 65pp.
- --7912100295 Responds to NRC 791101 request re noncompliance of Mastinghouse ECCB evaluation model under requirements of 10CFRSO App K. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants.

  ANDERSON, T. M. Westinghouse Electric Corp. 79/11/02. 4pp.
- --7912100330 Responds to NRC 791101 request re ORNL cladding swelling & rupture data. Review of analytical models & tests indicates compliance w/100FR30 App K. All GE specs for calculated peak cladding temp remain unchanged.

  8UCHHGLZ, R. H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50. 46 satisfied.

  DM9LEY. G.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/11/02. Spp.

- --7912100456 Forwards addI info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model.

  No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results.

  OMSLEY.O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).

  79/11/04. 22pp.
- 791213006B Forwards Amend 44 to License DPR-23, safety evaluation & notice of issuance & availability.

  8CHMENCER, A. Operating Reactors Branch 1. 79/11/17. 2pp.
- --7912130071 Amend 44 to License DPR-23 establishing Tech Specs to assure insp & reporting requirements for inservice insp of steam generator tubing consistent w/Revision 1 of Reg Guide 1.83. BCHMERNER, A. Operating Reactors Branch 1. 79/11/17. 11pp.
- ---7912130076 Barety evaluation supporting Amend 44 to License DPR-23. \* Office of Nuclear Reactor Regulation. 79/11/17. 7pp.
- --7912130080 Notice of issuance & availability of Amend 44 to License DPR-23.

  8CHWENCER,A. Operating Reactors Branch 1. 79/11/17. 2pp.
- 7912040340 Forwards response to NRC 791002 ltr re Dak Ridge Associated Univs radiation safety training course. Requests 3-months notice prior to implementation so that site-specific orientation math can be prepared.

  UTLEY.E.E. Carolina Power & Light Co. 79/11/29. ip.
- 7912120305 Responds to inquiries by NRC re control rod guide tube wear measurements. Quide tube wear measurements in discharged assemblies are scheduled for Jan 1978.
  ORMLEY-O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/12/05. 1p.
- 7912120316 Submits supplementary response re revision to QA program. Indicated exceptions & provides alternatives to requirements. UTLEY, E. E. Garalina Power & Light Co. 79/12/Q6. 6pp.
- 7912200630 Notifies of fee assessment for review of 790817 security personnel training & qualification plan. Requests payment. DIQOS,R.M. License Fee Management Branch. 79/12/06. 1p.
- 7912120360 Responds to NRC 791022 itr re containment purge & vent valve operation pending resolution of isolation operability. Util commits to interim guidelines until testing & engineering analyses completed. Gualification review due by 800301.
  UTLEY.E.E. Carolina Power & Light Co. 79/12/07. 2pp.
- 7912130548 Forwards Offsite Dose Calculational Manual Manual should be used in conjunction w/radiological effluent Tech Specs.
  UTLEY.E. E. Carolina Power & Light Co. 79/12/10. ip.
- --7912130554 Offsite Dose Calculational Manual. \* Carolina Power & Light Co. 79/12/10. 50pp.
- 7912190589 Responds to NRC 791029 ltr re rod position indication sys.
  Tech Specs require that control rods remain within 15 inches
  of bank positions. Intends to perform addl analysis to
  support present Tech Specs.
  UTLEY, E. E. Carolina Power & Light Co. 79/12/14. 2pp.
- 7912270358 Reaffirms commitment to complete short-term TMI Lessons Learned Task Force requirements by 800101. Due to aquipment delivery delays, mod for automatic shadding of pressurizer heaters may not be completed until 800228.

  UTLEY, E. E. Caroline Power & Light Co. 79/12/17. 2pp.
- 7912270383 Confirms that mod allowing pressurizer heaters to shed automatically from emergency power sources upon safety injection initiation will be installed by 800101.
  UTLEY.E. E. Carolina Power & Light Co. 79/12/19. 2pp.
- 7912270534 Responds to NRC 791210 request for add1 info on short-term TMI Lessons Learned Task Force recommendations re auxiliary feedwater initiation & flow indication. Info to be transmitted by 791231.

  UTLEY, E. E. Carolina Power & Light Co. 79/12/19, 1p.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912050111 Forwards IE Rept 50-261/79-21 on 790918-21 No noncompliance noted. LEWIS,R.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 79/10/17: 2pp.

- --7912050119 IE Insp Rept 50-261/79-21 on 790918-21.No noncompliance noted. Major areas inspected: plant operations, periodic & special repts. LERs. IE bulletins & circulars & previous enforcement matters.

  MCHENRY.T.J. Region 2. Atlanta, Office of the Director.

  MCLLQGG.P.J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 79/10/16. 7pp.
- 7912060121 Forwards IE Insp Rept 50-261/79-24 on 791015-19. No noncompliance noted.
  SUTHERLAND, J. T. Region 2. Atlanta, Fuel Facility & Materials Gafety Branch. 79/10/31. 2pp.
- --7912060134 IE Insp Rept 50-261/79-24 on 791015-19 No noncompliance nored Major areas inspected: coordination w/offsite support agencies mergencies facilities equipment & procedures.

  TAYLOR, P. A., PERROTTI, D. J. Region 2. Atlanta. Office of the Director. HUFHAM. J. H. Region 2. Atlanta, Fuel Facility & Material's Bafety Branch. 79/10/31. 12pp.
- 7912180141 Forwards IE Insp Rept 50-261/79-23 on 791015-18.No noncompliance noted. MURPHY.C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/11/06. 2pp.
- ---7912180145 IE Insp Rept 50-261/79-23 on 791015-18 No noncompliance noted Major areas inspected: IE Bulletin 79-19 nondestructive examination insp & inservice insp documentation.

  BLAKE, J. Region 2. Atlanta. Office of the Director.

  HERDT, A. R. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 79/11/05. 4pp.
- 7912200344 Forwards waste packaging Insp Rept 79-02A on 790925-26 No noncompliance noted. SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/11/07. 2pp.
- --7912200395 Waste packaging Insp Rept 79-02A.No noncompliance noted.
  Major areas inspected: thipping paper & DOT placarding requirements radiation levels removable contamination. DOT & NRC package features.
  BROWN. R. A. Region 2, Atlanta, Office of the Director. 79/11/06.
- 7912060106 Forwards IE Info Notice 79-12A, "Attempted Damage to New Fuel Assemblies," No specific action or response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/09. 2pp.
- 791203006B Ack receipt of 791107 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-261/79-22. SUTHERLAND.J.T. Region 2. Atlanta. Fuel Facility & Materials Safety Branch. 79/11/16. lp.
- --7912030073 Responds to NRC 791019 ltr re violations noted in 1E Inap Rept 50-261/79-22. Corrective actions: implementation of written procedures for spent resin transfer & dewater & evaporator bottoms. BTARKEY, R. B. Caroline Power & Light Co. 79/11/07. 3pp.
- --7912030076 Forwards IE Insp Rept 50-261/79-22 on 790925-28 & untice of violation. O'REILLY.U.P. Region 2, Atlanta, Office of the Director. 79/10/19. 2pp.
- --7912030079 Natice of violation from insp un 790925-28. Region 2, Atianta, Office of the Director. 79/10/18. 1p.
- --79120300B3 IE Insp Rept 50-261/79-22 on 790925-28. Noncompliance noted: inadequate radwaste operating procedures. QIBEON.A.F. Region 2, Atlanta, Fuel Facility & Materials Bafaty Branch. JENKINS.O.R. Region 2, Atlanta, Office of the Director. 79/10/18. 7pp.
- 7912100160 Forwards IE info Notice 77-28. "Overloading of Structural Elements Due to Pipe Bupport Loads." No response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/16. 1p.
- 7912110540 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required.
  O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
  79/11/16. 2pp.
- 7912060609 Forwards IE Circular 79-24, "Proper Installation & Calibr of Care Spray Pips Break Detection Equipment on BWRs." No response required.

  O'REILLY,J.P. Region 2. Atlanta, Office of the Director.
  79/11/26. 1p.

- 7912110123 Forwards IE Circular 79-23, "Notor Starters & Contactors Failed to Operate." No response required.
  O'REILLY, J.P. Region 2. Atlanta, Office of the Director.
  799/11/26. 1p.
- 7712110486 Ack receipt of 771102 & 21 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-261/79-19. LEWIS.R.C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 79/11/30. 1p.
- --7912:10497 Responds to NRC 791012 ltr re violations noted in IE Insp Rept 50-261/79-19. Corrective actions:procedures will be revised or new procedures implemented to assure deviations properly evaluated. FURR. B. J. Carolina Power & Light Co. 79/11/02. Spp.
- --7912110502 Forwards IE Insp Rept 50-261/79-19 on 790910-14 & notice of violation. LEWIB.R.C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 79/10/12. 2pp.
- -7912110505 Notice of violation from insp on 790910-14. + Region 2, Atlanto, Office of the Director. 79/10/12. 2pp.
- -7912110514 IE Insp 50-261/79-19 on 790910-14.Noncompliance noted: jumper installed w/o tagging or bagging in shift foreman jumper & wire removal log & deviation evaluation procedures not developed or implemented.
  HESSMAN.R.H. Region 2. Atlanta. Reactor Operations Nuclear Bupport Branch. BROWNEE.V.L. ASSENDEN.M.C. Region 2. Atlanta. Office of the Director. 79/10/12. 18pp.
- 7912170383 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Written response required.
  O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
  79/11/30. 1p.
- 7912310053 Submits revised response to IE Bulletin 79-19 re packaging low level radwaste. All personnel involved in transfer, packaging & transport of radwaste to use agt-approved detailed instruction & operating procedures.
  FURR. 9. J. Carolina Power & Light Co. 79/12/04. 3pp.
- 7912280172 Updates 790906 response to 16 Bulletin 79-17. "Pipe Cracks in Stagmant Borated Water Sys at PWR Plants." Examinations completed 791105. No evidence of intergranular stress corresion cracking found.
  FURR.B.J. Carolina Power & Light Co. 79/12/06. 3pp.
- 7912310285 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 100FR21." No action required.
  1 "REXLLY, J. P. Region 2, Atlanta, Office of the Director.
  79/12706. Spp.
- 7912200006 Forwards IE Bulletin 79-28, "Possible Malfunction of Nanco Model EAIBO Limit Switches at Elevated Teaps," Action required. 0'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/12/07. 2pp.
- 79:2210195 Responds to IE Bulletin 79-02. Revision 2. Provides info retinsp & testing program of wax support design loads, anchor bolt insp & testing effect of preload on cyclic capacity & two uses of expansion anchor bolts.
  FURR. B. J. Carolina Power & Light Co. 79/12/10. 2pp.
- 7912280370 Forwards IE Info Notice 79-31. "Use of Incorrect Amplified Response Spectra." No written response required. O'REILLY.J.P. August 2. Atlanta, Office of the Director. 79/12/13. 2pp.
- 7912280119 Forwards IE Circular 79-25, "Ghock Arrestor Strut Assembly Interference." No written response required. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 79/12/20. 4pp.

.

- R. Periodic operating reports & related correspondence
- 7912130285 Forwards monthly operating rept for Nov 1979. STARKEY, R. B. Carmlina Power & Light Co. 79/12/10. 13
- ---7912130288 Monthly operating rept for Nov 1979.
  WATFORD, M. Carolina Power & Light Co. 79/12/06. Spg.

- S. Reportable occurrences, LERs & related correspondence
- 7912130596 Notifies NRC that final rept re deficiencies in procurement. fabrication & insp of engineered plates for concrete embedment & support of safety-related loads will be completed on 791231. Delays caused by extensive remork. CHIANOI, N. J. Carolina Power & Light Co. 79/11/02. 2ap.
- 7912040428 Forwards LER 79-041/03L-0. STARKEY, R.B. Carolina Power & Light Co. 79/11/29. Ip.
- --7912040432 LER 79-041/03L-0: on 791030, investigation revealed wrong class of insulating matt installed on containment for cooler unit motor leads to field cable connections. Caused by lack of awareness of specific insulating requirement. STARKEY.R.B. Carolina Power & Light Co. 79/11/29. 2pp.
- 7912050534 Forwards LER 79-040/03L-0. STARKEY, R.B. Carolina Power & Light Co. 79/11/29. 1p.
- --7912050549 LER 79-040/03L-0: on 791029.AE analysis for IE Bulletin 79-14 indicated pipes in auxilairy feedwater sys may be subj to excessive stress. Caused by restraint deviations. Restraints modified & piping reanalysed. STARKEY.R. &. Carolina Power & Light Co. 79/11/28. 3pp.
- 7912140445 Forwards tER 79-042/031-0. STARKEY.R.B. Carolina Power & Light Co. 79/12/12. 2pp.
- ---7912140451 LER 79-042/03L-0: on 791112 maint trouble tickets reviewed by OA: revealing that on 790731. w/plant at 100% power: safeguard test switch was replaced in B train w/o approved operating work procedure. Caused by failure to recognize need.

  BTARKEY, R. B. Carolina Power & Light Co. 79/12/12. 1p.
- 7912280529 Interim deficiency rept re defective Seismic Class I banger welds. Final rept will be forwarded on 800130. CHIANOI.N. J. Carolina Power & Light Co. 79/12/19. 2pp.

# DUCKET 50-262 BRIGHAM YOUNG UNIV. RESEARCH REACTOR

- F. Security, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Guide 5.XX, "Std Format & Content for Licensee Physical Becurity Plan for Protection of SMM of Moderate or Low Btrategic Bignificance." W/o encl. REID.R.W. Operating Reactors Branck 4 (Pre 791030). 79/08/22.

## DOCKET 50-263 MONTICELLO NUCLEAR GENERATING PLANT

- P. Security, medical, emergency & fire protection plans
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives Provides guidance for improving licenses emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions. GRIMER.B.K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- 7912070431 Discusses fire barrier installation required by fire protection safety evaluation. Proposes 3-br fire barriers for load ctrs. Bechtol drawings of add1 mods encl. MAYER-L. O. Horthern States Power Co. 79/11/30. 4pp.
- 7912310098 Requests installation of backup power for red emergency telephones, as discussed in 791115 telcon.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/30.
  is.
- 79:2190167 Advises that commitment to re-evaluate druwell erea for safe shutdown requirements, per 790829 fire protection safety evaluation, will be fulfilled during Feb 1980 refueling outage. Results by 800331.
  MAYER, L. O. Northern States Power Co. 79/12/12 1p.
- 79:2170304 Discusses results of evaluation of hose station flow rate calculations required by five protection safety evaluation, re 790829 consistent, All stations capable of accessing 100 gpm 65 psi residual pressure requirement. MAYER, L. O. Northern States Power Co. 79/12/13. 1p.

- 7912190354 Responds to NRC 790829 fire protection safety evaluation. No hose stations exist in vicinity of drywell. Approx 200-ft hase required to provide coverage for all drywell areas.

  Discusses proposed mods.

  MAYER.L.O. Northern States Power Co. 79/12/14. 2pp.
- 7912310365 Forwards design info re installation of fire detectors. Ionization-type detectors will be installed to detect fires in closed cabinets in control room. Brawing showing detector placement encl.

  MAYER, L. O. Northern States Power Co. 79/12/27. 4pp.

#### Q. Adjudicatory correspondence

- 7912110367 Order dismissing proceeding due to withdrawal of MN Pollution Control Agency as party. No items of controversy remain.

  LAZO, R.M. Atomic Bafety and Licensing Board Panel. 78/02/27. 4pp.
- P. Operating license stage documents & correspondence
- 7912100189 Discusses NRC 791101 meeting w/representatives of NSSS vandors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EIBENHUT, D. 0. Division of Operating Reactors. 79/11/09. 65pp.
- ---7912100255 Responds to NRC 791101 request re noncompliance of Westinghouse ECCB evaluation model under requirements of 10CFR50 App K. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants.
  ANDERSON, T.M. Westinghouse Electric Corp. 79/11/02. App.
- --7912100330 Responds to NRC 791101 request re ORNL cladding swelling & rupture data. Review of analytical models & tests indicates compliance w/iOCFR50 App K.All QE specs for calculated peak cladding temp remain unchanged.

  BUCHHOLZ, R., H. General Electric Co. 79/12/07. 2pp.
- ---7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50. 46 satisfied.

  OMBLEY.O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/11/02. Spp.
- --7912100454 Forwards add1 info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. DWBLEY, G.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/04. 22pp.
- 7912050146 Responds to technical assistance request TAC 6190. BER & technical avaluation of single loop operation encl.
  Proposed mods acceptable.
  LAINAB. Q. Plant Systems Branch. 79/11/14. 1p.
- ---7912050151 Safety evaluation of application of amend to DL to permit operation w/one recirculation loop out of svc. Amend acceptable, e Plant Systems Branch. 79/11/14. 2pp.
- ---7912050157 "Technical Evaluation of Electrical, Instrumentation & Control Design Aspects of Proposed License Amend for Bingle-Loop Operation." Amend acceptable.

  COOPER.J.H. EO & O. Inc. 79/11/14. 10pp.
- 7912040242 Forwards NEDO-24221, "Suppl Reload Licensing Submittal, Reload 7," in response to request by T Kevern.
  MAYER, L. O. Northern States Fower Co. 79/11/30. 1p.
- --7912040249 "Suppl Reload Licensing Submittal, Reload 7." HENRIKBON, P. H. Northern States Power Co. NEDG-24221. 79/11/30.
- 7912110310 Responds to NRC 791131 ltr requesting schedule for submittal of long-term plant-unique program analysis. Will provide schedule following final resolution of acceptance criteria. MAYER, L. D. Northern States Fower Co. 79/12/05. 1p.
- 7912120364 Requests encl revision to 770902 license smend requests correcting language of 770902 submittel re containment integrated lesk rate test duration.

  MAYER, L. D. Northern States Power Co. 79/12/06. 2pp.

- --7912120376 Revision 1 to 770902 license amend request, modifying App A Tech Specs, Sections 3.0 & 4.0 to incorporate containment integrated leak rate testing requirements of NUREG-0123. \* Northern States Power Co. 79/12/06. 8pp.
- 7912140259 Confirms 791129 telcon re 791120 response to NRC 791030 ltr concerning TMI Lessons Learned Task Force short-term requirements. Requests that exception for Item 2. I. 3.6 in Section B of Encl 1 of response be deleted. MAYER, L. O. Northern States Power Co. 79/12/07. lp.
- 7912200414 Discusses mod to turbine lube oil reservoir deluge sys, in response to NRC 790827 fire protection safety evaluation. Sys extended to provide complete coverage of Fire Zone 13-C. Improvements to hydraulic water supply sys made MAYER, L. D. Northern Btates Power Co. 79/12/11. 3pp.
- 7912200369 Submits design description of fire break installed between zones 48 & 4C as required by fire protection safety evaluation.

  MAYERIL. O. Northern States Power Co. 79/12/17. 1p.
- 7912270340 Submits fee determination for 791221 license amond request re change in max average planar linear heat generation rate limits for Cycle 7.Class II fee encl.

  \* Northern States Power Co. 79/12/21. lp.
- 7912270540 Forwards application for amend to Tech Specs.App A of License DPR-22 & amend fee. MAYER,L.O. Northern States Power Co. 79/12/21. ip.
- --7912270545 Application for amend to License DPR-22.extending table of max average planar linear heat generation rate limits for one fuel type to cover higher exposures during Cyclo 7.
  NACHIER,L. J. Northern States Power Co. 79/12/21. 2pp.
- ---7912270552 Revised Table 3.11.1 for proposed amend to Tech Specs re max average planar linear heat generation rate limits.

  \* Northern States Power Co. 79/12/21. 2pp.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912200189 Forwards IE Insp Rept 50-263/79-16 on 791015-17 No noncompilance noted. FIORELLI.9. Region 3. Chicago, Reactor Construction & Engineering Bupport Branch. 79/11/07. 2pp.
- --7912200194 IE Insp Rept 50-263/79-16 on 791015-17. No noncompliance noted Major areas inspected:licenses actions re IE Dulletin 79-14. "Beismic Analysis for As-Built Bafety-Related Piping Bys."

  YIN.I.T., DANIELSON, D. H. Region 3. Chicago. Office of the Director. 79/11/05. 7pp.
- 7912030144 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required. KEPPLER, J. 9. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912100239 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required.
  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912110385 Forwards IE Info Notice 79-29. "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required.

  KEPPLER, J. G. Region 3. Chicago. Office of the Director. 79/11/16.
- 7912080399 Forwards IE Bulletin 79-26, "Boron Loss From BWR Control Blades." Response required.

  KEPPLER, J. Q. Region 3, Chicago, Office of the Director. 79/11/20.
- 7912100440 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Datection Equipment on DWRs." No written response required.
  KEPPLER, J. Q. Region 3, Chicago, Office of the Director. 79/11/24.
- 7912140216 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No written response required.
  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/26.

- 7912110433 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofts topice of escalated enforcement correspondence sent by NRC to licensees.

  KEPPLER, J. G. Region 3. Chicago. Diffice of the Director. 79/11/28.
- 7912190231 Forwards IE Builetin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Whitten response required.

  KEPPLER, J. G. Region 3, Chicago, Office, of the Director. 79/11/30.
- 7912140093 Forwards IE Info Notice 79-30. "Reporting of Defects & Noncompliances.10CFR21." No action or response required.

  KEPPLER.J.G. Region 3. Chicago, Diffice of the Director. 79/12/06.

  io.
- 7912280046 Responds to IE Bulletin 79-25. "Failures of Westinghouse BFD Relays in Safety-Related Sys." No Westinghouse BFD relays used in safety-related sys. MACHTER.L.J. Northern States Power Co. 79/12/07. Ip.
- 7912280053 Responds to IE Bulletin 79-02.Revision 2, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts." Bechtel review shows support failure will not compromise structural integrity. WACHIER.L.J. Northern States Power Co. 79/12/07. 2pp.
- 7912200134 Forwards IE Oulletin 79-28, "Possible Halfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/12/10.
- R. Periodic operating reports & related correspondence
- 79:2:40367 Forwards monthly operating rept for Nov 1979. MAYER, L. O. Northern States Power Co. 79/12/07. 1p.
- --7912140374 Monthly operating rept for Nov 1979. MYRABO, A. L. Northern States Power Co. 79/12/04. App.
- S. Reportable occurrences. LERs & related correspondence
- 7912270444 RG: on 791214, current geak planar exposure determined to exceed Tech Spec limits. Calculations made to determine appropriate max average planar linear heat generation rate kH/Ft values for extended burnup program. ELIASON, L. R. Northern States Power Co. 79/12/17. lp.
- 791227056B Forwards LER 77-021/03L-0.
  MAYER.1. D. Northern States Fower Co. 79/12/19. 1p.
- --7912270580 LER 79-021/031-0. on 791119 during IR Bulletin 79-02 avaluation snubber \$9-31 base plate expansion anthor bolt safety factor found to be loss than one Caused by inadequate base plate & expansion anthor bolts.

  DAY.B. D. Northern States Power Co. 79/12/19. 1p.
- 7912270333 Forwards info in response to NRC 790918 itr re loss of offsite power events. Reactor experienced seven events between 710317 & 780616 info on voitage & frequency not available. Each event resulted from single event per error. MAYERJE. O. Northern States Power Co. 79/12/20. 2pp.
- --7912310428 LER 79-023/01T-0: pn 791214, during evaluation of fuel assembly exposures for next cycle, discovered that current cycle exposure of several nodes for one fuel type exceeded axposure values in Tech Spers. Caused by inadequate review. NEVINSKI, D. E. Northern States Power Co. 79/12/28. 3pp.
- DOCKET 50-264 DOW CHEMICAL CO.
- F. Socurity, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Guide S. XX. "Std Format & Content for Licenses Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance." W/o encl. REID, R. W. Operating Reactors Branch 4 (Pre 791030). 79/08/22. 2pp.

- Q. Inspection reports, IE Bulletins & correspondence
- 7912050073 Forwards IE Insp Rept 50-244/79-02 on 791002-03 & notice of violation. DAVIG.A.B. Region 3. Chicago. Fuel Facility & Materials Safety Branch. 79/10/22. 2pp.
- --7912050076 Notice of violation from insp on 791002-03.

  \* Region 3, Chicago, Reactor Construction & Engineering Bupport Branch. 79/10/22. 1p.
- --7912050315 IE Insp Rept 50-264/79-02 on 791002-03. Noncompliance moted: failure of reactor operations committee to meet quarterly.
  HIATT.J.W. Region 3. Chicago, Office of the Director.
  FISHER.W.L. Region 3. Chicago, Fuel Facility & Materials Safety Branch. 79/10/22. 6pp.
- 7912130346 Ack receipt of 791108 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-264/79-02.

  DAVIS.A.B. Region 3. Chicago, Fuel Facility & Materials Bafety Branch 79/11/28. ip.
- --7912[30350 Responds to 1E Insp Rept 50-264/79-02 Corrective actions: reactor operations committee met 790313,0802 & 1107 & will most on 791211.

  LANGNER,R.R., GILL,H.H. Dow Chemical Co. 79/11/08, ip.

# DOCKET 50-245 GUAD-CITIES STATION, UNIT 2

- F. Security, medical, emergency & fire protection plans
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives. Provides guidance for improving licenses emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.

  GRIMES.B.K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- 7912270063 Forwards list of specific items requiring updating in emergency plans. Emergency plans were evaluated using code requirements, Reg Guide 1.101 & Emergency Planning Review Guidelines Number 1.Revision 1. IPPOLITO.T.A. Operating Reactors Branch 3. 79/11/30. 7pp.
- 7912200672 Requests payment of Class III fees for review of 790816 nuclear security personnol training & qualification plans.

  DIGGS.R.M. License Fee Management Branch. 79/12/07. ip.
- H. General correspondence
- 7912280605 Discusses 791204 title change of manager of nuclear operations to vice president. Organization structure not altered. No revision will be made to GA progrem topical rept CE-1-A until organization structure is delimeated. JANECEK.R.F. Communwealth Edison Co. 79/12/19. 1p.
- P. Operating license stage documents & correspondence
- 7912120088 Submits info re release rates of gaseous & particulate forms of radioactive matls during third quarter of 1979, KALIVIANAKIS, N. Commonwealth Edison Co. 79/10/25. 1p.
- 7712100187 Discusses NRC 771101 meeting w/representatives of NSSS vendors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses enci.
  EISENHUT.D.G. Division of Operating Reactors. 79/11/09. 65pp.
- --7912100255 Responds to NRC 791101 request re noncompliance of Westinghouse ECCS evaluation model under requirements of 10CFREO App K. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants.

  ANDERSON.T. M. Westinghouse Electric Corp. 79/11/02. App.
- --7912100330 Responds to NRC 791101 request re ORNL cladding swelling & rupture data.Review of analytical models & tests indicates compliance w/iOCFA50 App K.All OE specs for calculated peak cladding temp remain unchanged.

  BUCHHOLZ.R.H. General Electric Co. 79/12/07, 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50.46 satisfied.

  CHELEY, G.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.), 79/11/02. Spp.

- --7912100456 Forwards add1 info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model.

  No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results.

  DMBLEPY, G.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).

  79/11/04. 22pp.
- 7912040261 Forwards plant steam bypass capacity shoots, percent rated. Info provided to 0E for incorporation into NEDO-24708. PEOPLES, D. L. Commonwealth Edison Co. 79/11/16. 200pp.
- 7912040297 Forwards supplementary response to be incorporated into 791018 ltr re lessons learned commitments to meet near-term requirements.
  REED.C. Commonwealth Edison Co. 79/11/30. 7pp.
- 7912040485 Submits updated schedules for installation of recirculation pump trip mods per 790329 ltr. PEOPLES, D. L. Commonwealth Edison Co. 79/11/30. 2pp.
- 7912120411 Forwards supplementary response re commitment to meet short-term requirements of Lessons Learned Task Force. REED.C. Commonwealth Edison Co. 79/11/30. 7pp.
- 7912120425 Forwards supplemental response to 791018 ltr re commitments to Lessons Learned Task Force recommendations. PEOPLES.D.L. Commonwealth Edison Co. 79/12/03. 2pp.
- 79121103BO Proposes to amend Tech Specs, extending max average planar linear heat generation rate to larger exposure values. Errata & addenda sheets for "LOGA Analysis Rept." Tech Specs page changes & Class III fees entl.
  PEOPLES.D.L. Commonwealth Edison Co. 79/12/04. 2pp.
- ---7912110386 Errata & addenda sheets for "LOCA Analysis Rept." \* General Electric Co. NEDD-24146. 79/10/31. 3pp.
- 7912210349 Forwards cover sheet for CE-1-A, Revision 10, inadvertently omitted from 791116 transmittal.
  NAUQHTON.W.F. Commonwealth Edison Co. 79/12/13. 2pp.
- 7912180531 Forwards info documenting evaluation of purge & vent valve operability verification. Util committed to purge & vent sys in conformance w/NRC interim position. Complete confirmatory analyses not available for 30-40 wk.
  PEOPLES, D. L. Commonwealth Edison Co. 79/12/14. 6pp.
- 7912190542 Forwards "Adequacy of Station Electric Distribution Sys Voltages," addressing 480-volt undervoltage conditions. JANECEK,R.F. Commonwealth Edison Co. 79/12/14. 1p.
- ---7912190545 "Adequacy of Station Electric Distribution Sys Voltages." \* Commonwealth Edison Co. 79/12/14. Spp.
- 7912270469 Forwards response to NRC request for add1 info on Leasons Learned Task Force Recommendations 2.1, 7a & 2.1,7b. PEOPLES.D.L. Commonwealth Edison Co. 79/12/14. Spp.
- 7912270470 Advises that qualification program for remaining purps & vent containment valves is in progress Dresden & Quad-Cities buttenfly valves will close, regardless of degree of opening. Response to NRC interim position encl.

  PEOPLES, D. L. Commonwealth Edison Co. 79/12/14. 6pp.
- 7912270897 Advises of compliance w/Category A TMI Lessons Learned Task Force items identified in NRC 790913 & 1030 ltrs. Compliance will be achieved by 800101, or prior to return to power for units in outages on 800101.

  PEOPLES, D. L. Commonwealth Edison Co. 79/12/17. ip.
- 7912280533 Responds to NRC 791031 request for plant-unique implementation schedule for additional condensation tests re Mark I full scale test facility. Analysis dependent on final resolution of acceptance criteria.

  PEOPLES, D. L. Commonwealth Edison Co. 79/12/20. 2pp.
- 7912310348 Forwards revised pages to CE-1-A, "Comm Ed GA Program for Nuclear Generating Stations," Revision 11, JANECEK, R. F. Commonwealth Edison Co. 79/12/20, ip.
- --7912310359 Revised pages to CE-1-A, "Comm Ed GA Program for Nuclear Generating Stations," Revision 11.

  \* Commonwealth Edison Co. CE-1-A. 79/11/21. 16pp.

en Allege Se

- Q. Inspection reports, IE Bulletins & correspondence
- 7912060190 Responds to IE Bulletins 79-02 & 79-14 re schedule for insp of hangers & anchor bolts. Inaccessible areas insp will be performed as required during refueling outage on 791125. PEOPLES, D. L. Commonwealth Edison Co. 79711/09. 28p.
- 7912200404 Plans to perform inaccessible areas insp required by IE Bulletins 79-02 & 79-14 during 791129 refueling outage. PEOPLEG.D.L. Commonwealth Edison Co. 79/11/09. 20p.
- 7912030106 Forwards 1E Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912100213 Forwards IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads." No response required. KEPPLER, J. G. Region 3. Chicago, Office of the Director. 79/11/16.
- 7912110357 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912180013 Notifies of delay in implementation of IE Bulletin 79-14 re accessible areas comparison & evaluation phase. Current program provides for earliest detection & evaluation of significant discrepancies. PEOPLEB, D. L. Commonwealth Edison Co. 79/11/19. 2pp.
- 7912090380 Forwards IE Bulletin 79-26, "Boron Loss From DWR Control Blades." Response required.
  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/20.
- 7912100417 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No written response required.

  KEPPLER, J. Q. Region 3, Chicago, Office of the Director. 79/11/26.
- 7912140187 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No written response required.
  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/24.
- 7912110395 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofts copies of escalated enforcement correspondence sent by NRC to licensees.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/28.
- 79;2190199 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Written response required.

  KEPPLER, J. Q. Region 3, Chicago, Office of the Director. 79/11/30.
  10.
- 7912140036 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action or response required.

  KEPPLER, J. C. Region 3, Chicago, Office of the Director. 79/12/06.
- 7912200086 Forwards IE Bulletin 79-28. "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. KEPPLER, J. C. Region 3. Chicago: Office of the Director. 79/12/10.
- 7912200443 Notification of 791213 meeting w/util to discuss IE Builetin 79-02 anchor bolt & base plate analysis.

  JORDAN: E. L. Division of Reactor Operations Inspections. 79/12/11.
- S. Reportable occurrences. LERs & related correspondence
- 7912270394 Forwards info re 750806,771106 & 780213 loss of offsite power events, in response to 790918 request.

  JANECEK, R. F. Commonwealth Edison Co. 79/12/20. 6pp.

- DUCKET 50-266 POINT BEACH NUCLEAR PLANT, UNIT 1
- F. Security, medical, emergency & fire protection plans
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives. Provides guidance for improving licenses emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions. GRIMES. B. K. Emergency Preparedness Task Force. 79/11/29. 30pp.
- 7912130295 Forwards Revision 11 to emergency plan manual, requiring that NRC be notified within 1-h of initiation of onsite evacuation plan & implementing temporary support ctrs w/dedicated phone line to NRC.
  FAY.C.W. Wisconsin Electric Power Co. 79/12/06. 3pp.
- --7912130303 Revision if to emergency plan manual. \* Wisconsin Electric Power Ca. 79/10/22. 100pp.
- 7912120230 Submits info re modified amended security plan. Info withheld tref 10CFR2.7901.

  DURSTEIN.S. Wisconsin Electric Power Co. 79/12/07. 1p.
- 7912270995 Forwards Revision 12 to emergency plan manual Page change instructions provided.
  FAY. C. W. Wisconsin Electric Power Co. 79/12/17. 2pp.
- ---7912270500 Revision 12 to emergency plan manual.Page change instruction & supporting ltr encl. # Wisconsin Electric Power Co. 79/12/17. 11ps.
- 7912310217 Discusses evaluation of incomplete items identified in 790802 fire protection safety evaluation.Licenses submitted info re brigade shift size on 791001 & basis for staff assignments on 790821. Proposed fire brigade acceptable. LAINAS, 0. Plant Systems Branch. 79/12/17. 4pp.
- 79:227019: Forwards rept. "Fire Detector Location Plan." mod to fire protection plan. Requests comment.
  FAY. C. H. Wisconsin Electric Power Co. 79/12/20. 2pp.
- --7912270194 "Fire Detector Location Plan," mod to fire protection plan.

  # Wisconsin Electric Power Co. 79/12/20. 55pp.

# 9. Adjudicatory correspondence

- 7912110038 Confirms receipt of encl 790327 petition to suspend OLs for all PWRs.Forwards FR notice indicating that petition will be treated in accordance w/100FRZ 206.

  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/11/23. 1p.
- --7912110126 Notice of request for action pursuant to 100FR2.206 re Environ Coalition on Nuclear Power 790329 petition requesting suspension of all ULs for PWRs. MULLER.D.R Office of Nuclear Reactor Regulation. 79/11/23.
- 7912050071 Petition to intervene. Urges Commission to hold adjudicatory hearing re hazards of stoam tube degradation. Certificate of Svc enci. FALK, M. M. Wisconsin's Environmental Decade. 79/11/26. 2pp.
- 7912100470 Forwards response to applicant 791123 ltr.Formal petition to intervene re GL amend will be filed on 791102. FALK.K.M. Wisconsin's Environmental Becade. 79/11/26. lp.
- --7912100472 Response supplementing 791114 patition in opposition to applicant ltr re steam generator tube degradation. Urges Commission commence investigative adjudicatory hearing on degradation safety problems. FALK.K.N. Mistonsin's Environmental Decade. 79/11/26. 12pp.
- 7912050087 Reply in opposition to WI Environ Decade 791114 petition requesting issuance of order to prevent reopening of facility after current refueling cycle. Petition presents no basis for safety risk allegation. Certificate of svc encl. CHARNOFF. 8. Wisconsin Electric Power Co. 79/11/27. 10pp.
- 79:2050003 Statement in support of HI Environ Decade petition objecting to startup of facility Degradation of steam generator tubes presents threat to public Urges Commission to grant hearing Centificate of Syc and.
  PDLLARD, R. D. WEISS, E. R. Union of Concerned Scientists. 79/11/28.

- 7912140535 Requests that future hearing re removal & storage of generators be held in Manitawor. WI. ESTES, J. Lakeshore Citizens for Safe Energy. 79/11/29. 1p.
- 7912200068 Denies 791114 & 26 petitions re prohibition against respening plant at end of refueling cycle.Director's decision entl. CASE.E.G. Office of Nuclear Reactor Regulation. 79/11/30. 2pp.
- --7912200072 Director's decision under 10CFR2 206 re denial of request to prohibit reopening of plant at end of refueling cycle. Order onc. 1.
  CASE, E. G. Diffice of Nuclear Reactor Regulation. 79/11/30. 5pp.
- --7912200074 Confirmatory order for mod of License DPR-24 re inservice of steam generators. CASE, E. G. Office of Nuclear Reactor Regulation. 79/11/30. 5pp.
- --7912200079 Safety evaluation re steam generator tube degradation due to deep crevice corresion. CASE.E.O. Office of Nuclear Reactor Regulation. 79/11/30. 3ipp.
- 7712280154 Opposition to WI Environ Decade Int 791126 petition to intervene & request for hearing. Request premature since proceeding not yet initiated. If hearing required re amend, ASLB must be appointed to rule on petition.

  O'NEILL.J.H. Wisconsin Electric Power Co. 79/12/07. 7pp.
- 7912170234 Response by WI Environ Decade in opposition to applicant 791207 objection to 791126 petition to Intervene & request for hearing Director's decision should be based on sworn discovery rather than pleadings. Certificate of Svc encl. FALK.K.M. Wisconsin's Environmental Decade. 79/12/12. App.

- 791213047B Requests ARC investigation of safety aspects of steam tube generator leaks. Meeting should be held to inform public of findings.
  EBTES.J. Lakeshore Citizens for Safe Energy. 79/11/07. lp.
- P. Operating license stage documents & correspondence
- 791109024B "Summary of Operating Experience W/Recirculating Steam Generators." EIBENMUT.D.G. Division of Operating Reactors. NUREO-0923. 79/01/31. B9pp.
- 7908010339 Notifies of status of rept on reactor cavity annulus seal.
  Host PWR users remove ring during normal operation Others
  store seal ring in raised position during normal operation.
  LAINAS.G. Plant Systems Branch (Pre 791030). 79/07/05. 7pp.
- 7912050193 Discusses NRC review of LERs & Tech Spec requirements recentral RPI sys of Westinghouse PWRs. Requests Tech Specs review to ensure requirement for rod maint to within +/- 12 steps indicated & RPI sys verified accurate within 12 steps. SCHWENCER.A. Operating Reactors Branch 1. 79/10/29. 7pp.
- 7912130608 Bubmits partial response to 790921 ltr re short-term & long-term requirements for auxiliary feedwater sys. Requests estension until 800131 for remaining requirements. FOX. C. W. Wisconsin Electric Power Co. 79/10/29. 4pp.
- 7912100189 Discusses NRC 791101 meeting w/representatives of N868 ventors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EIBENHUT, D. C. Division of Operating Reactors. 79/11/09. ASpp.
- --7912100255 Responds to MRC 791101 request re noncompliance of Westinghouse ECCS evaluation model under requirements of 10CFRSO App %. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants. ANDERSON, T. M. Westinghouse Electric Corp. 79/11/02. 4pp.
- --7912100330 Responds to NRC 791101 request re DRNL cladding swelling & rupture data. Review of analytical models & tests indicates compliance w/100FR50 App K.All GE specs for calculated peak cladding temp remain unchanged.
  BUCHHOLZ, R. H. Oeneral Eluctric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models is that analyses demonstrate all criteria of 10CFR50.46 satisfied.

  OHSLEY, Q. F. Exxon Nuclear Co. . Inc. (subs. of Exxon Corp.).
  79/11/02. Spp.

- ---7912100456 Forecards add1 info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model. No adverse impact from new rupture burst data or use of NRC yupture/blockage model on licensing calculation results. GMSLEY.o.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/04. 22pp.
- 7912050474 Advises that supplemental info re lessons learned info will be forwarded 791127.
  FAY.C.W. Hisconsin Electric Power Co. 79/11/20. ip.
- 7912030171 Ack receipt of MRC 791030 request for payment re approval of Tech Spec Change 61. No change occurred to reporting level for radiochemical engineer & health physicist to warrant 791030 reclassification as Class III fee.
  FAY.C.W. Wisconsin Electric Power Co. 79/11/21. 2pp.
- 7912040167 Summary of 791120 meeting w/util.Westinghouse & WI Environ Decade re plant steam generator tube degradation. TRAMPELL.C.M. Operating Reactors Branch 1, 79/11/23, 63pp.
- 7912030172 Responds to NRC 791123 telcon re revised ECCS reanalysis for steam generator tubes plugged up to 18%.
  BURSTEIN.S. Misconsin Electric Power Co. 79/11/26. 2pp.
- 7912180346 Forwards draft input for steam generator tube failure safety evaluations Hactions 2.1.3.2.2.3.2.3.3 & 2.4.3. Input for Dael Unit 2 reactor in Helgium encl. SCHMENGER.A. Operating Reactors Branch 1. 79/11/28. 1p.
- ---7912180350 Draft input for steam generator tube failure safety evaluation. Section 2.1.3.

  \* Office of Nuclear Reactor Regulation. 79/11/28. 5pp.
- 7912040486 Discusses commitment to certain programs upon return to power for Cycle 8:2. Primary-to-secondary hydrostatic tests & eddy current examination of steam generator tubes will be performed.

  BURSTEIN.S. 44isconsin Electric Power Co. 79/11/29. 3pp.
- 7912040247 Submits mod to 791129 ltr re operating conditions. Item 4.b should read. "Ang Two Identified Leaking Tubes in Any Twenty-Calendar-Bay Period."
  BURRHEIN-S. Wisconsin Electric Power Co. 79/11/30. ip.
- 7912190518 Requests payment of Class III for re 791119 request for ECCS reanalysis for 10% steam generator tube plugging limit.

  DIGOS, R. M. License Fee Management Branch. 79/12/03. Ip.
- 7912130012 Summary of 791119 telcon w/util re proposed schedule for implementations of Lessons Learned Task Force recommendations.
  TRANSCELL.C.M. Operating Reactors Branch 1. 79/12/06. Spp.
- 7912140369 Responds to 790917 ltr re commitment to EPA U fuel cycle std. Facility whready in compliance w/procedure comparing actual quantity of radioactive matt released w/dose design objectives of code.

  FAY. C. W. Wisconsin Electric Power Co. 79/12/06. 2pp.
- 7912180578 Notifies that NRC radiation safety certification is acceptable in lieu of util safety program. FAY.C.W. Wisconsin Electric Power Co. 79/12/06. ip.
- 7912140422 Discusses 791205 telcon w/Eisenhut & Trammell & 791206 telcon w/Trammell re methods of calculating & identifying primary-to-percondary leakage in steam generators. Understonds MRC 791130 order establishes max levels for leakage.
  BURSTEIN.S. Misconsin Electric Power Co. 79/12/09. Spp.
- 7912190562 Requests reconsideration of license fee applicability to 790710 Tech Spec change requested to qualification requirements for radiation safety manager. Change originally requested by SRC. No safety issue involved. FAY. C. W. Wisconsin Electric Power Co. 79/12/10. 289.
- 7912310171 Discusses plant shutdown due to steam generator tube leak.
  Imap on 7908231 & 1031 indicated extensive degradation No offsite radiation releases. MRC will send steam generator experts to review insps.
  DENTON, H. R. Diffice of Nuclear Reactor Regulation. 79/12/12. 2pp.
- 7912210143 Forecards response to NRC 791004 request for add1 info on inservice imag & testing progress Oversize drawing encl. FAY.C.M. Mimconsin Electric Power Co. 79/12/14. 6pp.
- 7912270300 Bubmits addition for NRC review of Tech Spec Change 60 for operation at reduced primary sys operating pressure. FAY.C.M. Wisconsin Electric Power Co. 79/12/14. Spp.

- 7912270209 Forwards review & approval fee for Commission action on 791119 ltr which provided revised ECCS reanalysis for up to 18% steam generator tube plugging.
  FAY.C.M. Misconsin Electric Power Co. 79/12/17. lp.
- 7912270430 Responds to NRC 791210 request for add1 info on TMI Lessons Learned Task Force recommendations re auxiliary feedwater sys. Oversize drawings available in Central Files. FAY.C.M. Wisconsin Electric Power Co. 79/12/17. 2pp.
- 7912280554 Forwards modified response to previous commitment to implement MREG-0578. Util will provide alarms in addition to existing position indication for power operated relief valves for both units.

  BURSTEIN.S. Wisconsin Electric Power Co. 79/12/17. 4pp.
- 7912270206 Requests amend to Licenses DPR-24 & DPR-27 incorporating changes in Tech Specs re rod bom & Section 15.3.10 clarification. Fee encl.
  BURSTEIN.S. Wisconsin Electric Power Co. 79/12/19. 4pp.
- ---7912270220 Revised Pages 15.1-4 through 15.3.10-16 for proposed amend to Tech Specs re control rod & power distribution limits.

  \* Wisconsin Electric Power Co. 79/12/19. 20pp.
- 7912280550 Forwards rapt re rod worth measurements, in response to MRC 790410 ltr. Measured data adheres to design predictions. All review & acceptance criteria satisfied.
  FAYs.C.M. Wisconsin Electric Power Co. 79/12/19. 2pp.
- 7912280601 Advises that seal ring should be removed following each refueling outage by raising ring more than 12 ft above cavity floor, in response to NRC 791002 request Util does not concur w/NRC belief that ring could become aissile.

  BURSTEIN.B. Wisconsin Electric Power Co. 79/12/20. 1p.
- 7912270492 Forwards mod to Tech Spec Change Request 60. BURSTEIN, S. Misconsin Electric Power Co. 79/12/21. 3pp.
- -7912270499 Proposed Tech Spec Page 15.2.9-2 reflecting mod to Tech Spec Change Request 60 Provides addl operating margin between proposed primary sys pressure & low pressurizer reactor trip setpoint.

  \* Wisconsin Electric Power Co. 79/12/21. ip.
- 7912280606 Submits add1 info re steam generator tube glugging history.
  Examination indicates intergranular attack is confined to
  tubesheet crevice area. Present eddy current techniques only
  capable of detecting tube cracts.
  BURSTEIN.S. Wisconsin Electric Power Co. 79/12/21. 6pp.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912260094 Forwards IE Insp Repts 50-266/79-15 & 50-301/79-17 on 791023-24.No noncompliance noted. DAVIS,A.B. Region 3, Chicago, Fuel Facility & Materials Safety Branch. 79/11/09. 2pp.
- --7912260098 IE Insp Repts 50-266/79-15 & 50-301/79-17 on 791023-24. No noncompliance noted. Major areas inspected: confirmatory measurements & radiological environ protection.
  EBSIG.T.H., DESTMANN.H.J., ROYTEK.C. Region 3, Chicago, Office of the Director. 79/11/08. 8pp.
- 7912030156 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912100249 Forwards IE Info Notice 79-28, "Dvarloading of Structural Elements Due to Pips Support Loads." No response required.
  KEPPLER, J. 9. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912110593 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required.

  KEPPLER, J. C. Region 3. Chicago, Office of the Director. 79/11/16.
- 7912310139 Responds to IE Bullatin 79-13. "Cracking in Feedwater Bys Piping." Outlines Unit 1 insp & repair. FAY.C.W. Wisconsin Electric Power Co. 79/11/19. 3pp.
- 7912030414 Forwards IE Bulletin 79-26, "Boron Loss From BWR Control Blades." No response required.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/20.

- 7912100447 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on EMRs." No written response required.

  KEPPLER. J. G. Region 3, Chicago. Office of the Director. 79/11/26.
- ko.
- 7912140245 Forwards IE Circular 79-23. "Motor Starters & Contactors Failed to Operate." No written response required. KEPPLER.J.O. Region 3. Chicago. Dffice of the Director. 79/11/26.
- 7912110448 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sent by NRC to licensees.

  KEPPLER. J. G. Region 3. Chicago. Office of the Director. 79/11/28
- 7912190235 Forwards IE Butletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Written response required. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/30.
- 7912200027 Responds to IE Bulletin 79-17. Required piping graminations completed 791012. No abnormalities found. Forwards final rept on piping examinations. W/o encl.
  FAY. C. N. Wisconsin Electric Power Co. 79/11/30. 2pp.
- 7912210144 Ack receipt of 791022 ltr re inspector access.Response will be forwarded upon completion of review. KEPPLER.J.O. Region 3. Chicago, Office of the Director. 79/12/05.
- 7912140106 Forwards IE Info Notice 77-30, "Reporting of Defacts & Nancompliances, 10CFR21," No action or response required.

  KEPPLER. J. G. Region 3, Chicago, Office of the Director. 79/12/06.
- 7912280650 Forwards 30-day response to IE Bulletin 79-02.Revision 2, "Pipe Support Dase Plate Designs Using Concrete Expansion Anchor Bolts." Accessible support testing complete Bample insport small pipe supports shows more testing not needed. FAY.C.W. Wisconsin Electric Power Co. 79/12/07. App.
- 7912200153 Forwards IE Bulletin 79-28. "Possible Malfunction of Namco Model EA180 Limit Guitches at Elevated Temps." Action required. KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/12/10. 1p.
- R. Periodic operating reports & related correspondence
- 7912180446 Forwards monthly operating rept for Nov 1979. DURSTEIN.S. Wisconsin Electric Power Co. 79/12/10. ip.
- --7912180449 Manthly operating rept for Nov 1979. BURSTEIN.S. Wisconsin Electric Power Co. 79/12/05. 10pp.
- S. Reportable occurrences, LERs & related correspondence
- 7912070412 Forwards LER 79-019/01T-0.
  FAY.C.W. Histonein Electric Power Co. 79/11/21. ip.
- --7912070416 LER 79-019/01T-0: on 791107.while filling steam generator A secondary side w/water to perform secondary-to-primary leak test.dilution of RCS occured Caused by leakage from open steam generator tube failing into primary outlet nozzle. FAY.C.W. Wisconsin Electric Power Ca. 79/11/21. 3pp.
- 7912070427 Forwards LER 79-020/01T-0. FAV.C.W. Wisconsin Electric Power Co. 79/11/27. Ip.
- --7912070433 LER 79-020/01T-0: on 791115, during refueling shutdown, enchor in steam generator A auxiliary feedwater line contained const deficiency. Caused by improper installation of three boits in anchor support plate. Anchor permanently modified. FAY.C.W. Wisconsin Electric Power Co. 79/11/27. 2pp.
- T. Hearing transcripts on non-antitrust matters
- 7912100210 Transcript of 791128 public meating in Washington DC. Pp 1-94. • Commission. 79/11/28, 95pp.

- ~-7912100217 Submits proposed schedule for 791128 briefing re steam generator tube degradation. Viewgraphs encl.
  BICKWIT-L. Office of the General Counsel. 79/11/20. 18pp.
- DDCKET 50-247 FORT ST. VRAIN NUCLEAR GENERATING STATION P. Operating license stage documents & correspondence
- 7912270003 Approves designated routes for shipment of spant nuclear fuel from Fort St Vrain Nuclear Generating Station; Platteville.Co to ID Chemical Processing Plant Arco, ID. Forwards data re arrangements w/low enforcement agencies.

  MCCORKLE.O.W. Physical Security Licensing Branch. 79/10/18.
- 791119014B Forwards "Discussion of TMI Lessons Learned Bhort-Term Requirements." Revisions to encl implementation schedule for NUREO-057B requirements should be submitted wjustification within 15 days, if schedule requirements cannot be met. DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/30. 2pp.
- 7912190580 Forwards "Investigations of Reactor Fluctuations, Vol 1" & "Investigations of Reactor Fluctuations, Vol 2." Rept available in Central Files only.
  SWART, F.E. Public Service Co. of Colorado. 79/11/28. ip.
- 7912040216 Forwards GA-D15474. "Nuclear Detector Decalibration, Cycle 2." in support of mods requested in 790011 ltr. FULLER, J. K. Public Service Co. of Colorado. 79/11/29. 3pp.
- -7912040221 "Nuclear Detector Decalibration.Cycle 2." HACKNEY.R. Public Service Co. of Colorado. OA-D15474. 79/07/31. 54pp.
- 7912120406 Requests waiver of Tech Specs SR NR 1.1 & 1.3 until 100% full power achieved or until 70% determined to be max attainable power lavel.

  HAREMODUROLD. Public Sprvice Co. of Colorado. 79/11/29. 2pp.
- 7912310074 Commants on NUREG-0610: Item 2 on Pages 4 t 5 should refuncentrolled or unplanned radiological releases below limits set by Alert Classification. Ref to radiological Tach Specs should be eliminated.

  WAREMBOURG. D. W. Public Service Co. of Colorado. 79/11/30. 4pp.
- 79:2110316 Summarizes fluctuation test program & plans for future testing Significant similarities in fluctuation data observed during Cycles i & 2.Rise-to-power program should begin 79:210.

  MAREMBOURG.D.W. Public Service Co. of Colorado. 79/12/04. 7pp.
- 791220004B Forwards safety evaluation re core region restraint devices. VARGA, B. A. Assistant Director for Light Water Reactors. 79/12/10.
- --7912200053 Bafsty evaluation re core region restraint devices.Reactor can be safely operated u/installed Luci locks up to 70% full powdr. \* Assistant Director for Light Water Reactors. 79/12/10. 10pp.
- P121B0995 Bubmits brief summary of position re items questioned in NRC 791030 ltr.Response will indicate implementation date of B00101. Detailed response will be forwarded not later than 771614. SWART, F. E. Public Service Co. of Colorado. 79/12/12. 3pp.
- 7912270233 Forwards response to NRC 791030 request for commitments to TMI Lessons Learned Task Force recommendations. Util not committed to all requirements due to NRC failure to include util in owners group meetings & on malling list. SWART.F. E. Public Service Co. of Colorado. 79/12/12. 54pp.
- 7912210373 Forwards "Initial Approach to Power Tests (B-Series), Interim Startup Rept 13," for 790823-1122. WAREMBOURG, D. Public Service Co. of Colorado, 79/12/13. ip.
- --7912210376 "Initial Approach to Power Tests (H-Beries), Interim Btartup Rept 13" for 790823-1122. \* Public Service Co. of Colorado. 79/11/22. 2pp.
- 7912280862 Forwards add1 info & justification re Item 2.2.1.b concerning shift technical advisor. Util commits to 1-h response time. WAREHBOURG.D.W. Public Service Co. of Colorado. 79/12/18. 12pp.

- 7912310175 Discusses issues unresolved after 790820 meeting.PCRV relief valve vent line & filter analyzed per Class I seismic criteria.False trips & moisture indications causes investigated & repaired.

  SWART.F.E. Public Service Co. of Colorado. 79/12/19. 4pp.
- Q. Inspection reports. IE Bulletins & correspondence
- 79:2210078 Responds to IE Bulletin 79-01A.ASCO solenoid valves w/
  safatu-related applications have been qualified for
  operability through exposure to worst postulated
  environmental accident conditions.
  FULLER, J. K. Public Service Co. of Colorado. 79/09/28. 3pp.
- 7912140094 Forwards IE Bulletin 79-17. Revision 1. "Pipe Cracks in Stagmant Borated Water Bys at PWR Plants." No written response required. SEYFRIT, K. V. Region 4. Dallas, Office of the Director. 79/10/29.
- 7912040028 Provides add1 info re admittance of NRC inspectors to facility. Requests inspectors be issued permanent nonemployees badges & be allowed to participate in site orientation program.

  BEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/10/30.
- 7912170206 Updates 791019 telcon response to IE Bulletin 79-01A.
  Initiating maint program to change resilient parts of
  safety-related environ-qualified ABGO valves within max svc
  life requirements.
  SWART.F.E. Public Service Co. of Colorado. 79/10/31. 2pp.
- 7912170201 Responds to IE Bulletin 79-23, "Potential Failure of Emergency Diesel Generator Field Exciter Transformer." No circuits between neutral of EPT or CPT to generator neutral. Testing to be completed by 800131.
  MILLEN.C.K. Public Service Co. of Colorado. 79/11/01. lp.
- 7912120566 Forwards IE Bulletin 79-25, "Failures of Westinghouse BFD Relays in Safety-Related Sys." Action required. SEYFRIT.K.V. Region 4, Dallas, Office of the Director. 79/11/02. 16.
- 7912120212 ForWards IE Insp Rept 50-267/79-18 on 791031.No noncompliance noted, MADBEN.O.L. Region 4, Dallas, Reactor Operations Nuclear Support Branch. 79/11/05. 2pp.
- --7912120223 IE Insp Rept 50-267/79-18 on 791031.No noncompliance noted.
  Major areas inspected:public officials of Grealey &
  Platteville.CO apprised of NRC mission & status of site.
  DICKERSON, M. W. HEBTERMAN, T. F. Region 4, Dallas, Office of the
  Director. MADSEN.O.L. Region 4, Dallas, Reactor Operations
  Nuclear Support Branch. 79/11/02. Spp.
- 7912190030 Forwards IE Circular 79-22. "Btroke Times for Power Operated Relief Valves." No written response required.
  SEYFRIT, K. V. Region 4. Dallas. Office of the Director. 79/11/16.
  ip.
- 7912120559 Forwards IE Bulletin 79-26, "Boron Loss From BWR Control Bladss." No response required. SEYFRIT, K.V. Region 4, Dallas, Office of the Director. 79/11/20. ip.
- 79:2110489 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sent by NRC to licensees.

  BEYFRIT, X. V. Region 4, Dallas, Office of the Director. 79/11/26.
- 7912180266 Discusses inservice insp & testing program re review & development of modified surveillance requirements. Util will provide development schedule by 791201 & proposed requirements for each sys or subsys as developed. FULLER, J. K. Public Bervice Co. of Colorado. 79/11/30. App.
- 79:2190189 Forwards IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Written response required.
  BEYFRIT.K.V. Region 4. Dallas, Office of the Director. 79/11/30. ip.
- R. Pariodic operating reports & related correspondence
- 7912180509 Forwards Monthly Operations Rept 68 for Aug 1979. WAREMBOURG, D. Public Service Co. of Colorado. 79/09/18. ip

- --7912180513 Monthly Operations Rept 68 for Aug 1979. \* Public Service Co. of Colorado, 79/09/18. 5pp.
- 7912180500 Forwards Monthly Operations Rept &9 for Sept 1979. WAREHBOURG.D. Public Service Co. of Colorado. 79/10/11. 1p.
- --7912180503 Honthly Operations Rept 69 for Bept 1979. \* Public Service Co. of Colorado. 79/10/11. 4pp.
- 7912140331 Forwards monthly operating rept for Nov 1979.
  WAREMBOURG.D. Public Service Co. of Colorado. 79/12/07. ip.
- --7912140335 Monthly operating rept for Nov 1979.
  GAHM.J.W. Public Service Co. of Colorado. 79/12/03. 5pp.
- 7912180413 Forwards Monthly Operations Rept 70 for Oct 1979. WAREMBOURG D. Public Service Co. of Colorado. 79/12/14. 1p.
- --7912180429 Monthly Operations Rept 70 for Oct 1979.

  OAHM. J. H. Public Bervice Co. of Colorado. 79/11/01. Spp.
- 7912310396 Forwards monthly operating rept for Nov 1979. WAREHODURG.D. Public Service Co. of Colorado. 79/12/21. 1p.
- ---7912310398 Monthly operating rept for Nov 1979. OAHM, J. W. Public Bervice Co. of Colorado. 79/12/03. 9pp.
- 8. Reportable occurrences, LERs & related correspondence
- 7912310055 PNO-IV-79-006: on 791014 inadvertent release of radioactivity occurred in reactor bldg. Caused by circulator helium buffer auxiliary sys upset. Bingle spike noted on plant stack monitor.
  MESTERMAN.T.F., MADBEN,O.L. Region 4, Dallas, Office of the Director. 79/10/15. 1p.
- 7912180062 Forwards Part 21, Rept 50-267/79-01 re full thread rods that did not meet reduction area spec.

  LEE, D. R. Public Service Co. of Colorado. 79/11/09. ip.
- --7912180065 Notifies that on 791106 full threaded rods found out of compliance w/reduction area specs.Remaining math in warehouse stock was replaced by US Steel Corp. \* Public Service Co. of Colorado. 79/11/09. 2pp.
- 7912040337 Forwards LER 79-051/03L-0.
  WAREMBOURD, D. Public Service Co. of Colorado. 79/11/16. 5pp.
- --7912040341 LER 79-051/03L-O: on 791017, at 5% power, sys 21 loop 1 surge tank level decreased to low level setpoint tripping loop 1 bearing water pumps & making circulators inspendie. Gaused by procedural inadequacy & operator error. QAHM, J. W. Public Service Co. of Colorado, 79/11/16. ip.
- 7912040296 Forwards LER 79-041/03X-1.
  WAREMBOURG, D. Public Service Co. of Colorado. 79/11/20. 3pp.
- --7912040298 LER 79-041/03X-1:on 791026, malfunctions in IC circulator speed measurement caused loss of circulator high speed signals. Caused by electronic circuit unbalance due to signal cable resistance change. Modifier adjusted & checked waekly. GAHM. J. H. Public Service Co. of Colorado. 79/11/19. ip.
- 7912040326 Forwards LER 79-052/03L-0.
  WAREHBOURG, D. Public Service Co. of Colorado. 79/11/20. App.
- --7912040330 LER 79-052/03L-0; on 791022, at 9% power B instrument air compressor found to have insufficient output while A compressor out of syc. Caused by bent piston rod & worn valves. Parts replaced or rebuilt.

  GAMM. J. W. Public Bervice Co. of Colorado. 79/11/20. 1p.
- 7912040332 Forwards LER 79-053/03L-0.
  WAREMBDURG, D. Public Service Co. of Colorado. 79/11/20. Spp.
- --7912040335 LER 79-053/03L-0:on 791024, total primary coolant exidents exceeded 10 parts per million. Caused by off-gassing of exidents due to reaction of moisture w/core graphite. Power decreased to initiate maint shutdown.

  GAMM. J. W. Public Service Co. of Colorado. 79/11/19. 1p.
- 7912040362 Forwards LER 79-055/03L-0.
  MAREMBDURG, D. Public Bervice Co. of Colorado. 79/11/26. 5pp.

- --7912040363 LER 79-055/03L-0: on 791026, during surveillance testing, check valve V-22370 was stuck open, making fire water booster pumps imperable for helium circulator drive. Cause unknown. Valve to be opened & inspected.

  GAHM, J. H. Public Service Co. of Colorado. 79/11/26. lp.
- 7912040429 Forwards LER 79-054/03L-0.

  MAREMBOURG.D. Public Service Co. of Colorado. 79/11/28. Spp.
- ---7912040433 LER 79-054/03L-0: on 791029, standby diesel engine 18 tripped on high cooling water temp during surveillance test. Caused by incorrect lineup of cooling water valves. Cooler isolated to repair cooling water tube leak. Operator reinstructes. GAHM, J. H. Public Service Co. of Colorado. 79/11/28. 1p.
- 7912040320 Forwards LER 79-057/03L-0.
  HAREMBOURG, D. Public Service Co. of Colorado. 79/11/29. Spp.
- --7912040323 LER 79-057/03L-0: on 791030 during surveillance testing one of three reactor pressure transmitters found out of calibr.
  Instrument settings less conservative than required Caused by instrument drift. Instrument recalibr.
  GANN.J. H. Public Service Co. of Colorado. 79/11/29. ip.
- 7912040400 Forwards LER 79-056/03L-0. WAREMEDURG, D. Public Service Co. of Colorado. 79/11/29. Spp.
- --7912040406 LER 79-056/03L-0: on 791030, seven of elevan helium circulator seal malfunction pressure differential switch units tripped outside Tech Specs. Caused by dirt accumulation in electrical suitches. Switches cleaned, randjusted & checked manthly. GAMM, J. B. Public Service Co. of Colorado. 79/11/29. 1p.
- 7912120324 Forwards LER 79-058/03L-0.
  WAREHEQUEG.D. Public Service Co. of Colorado. 79/12/04. 3pp.
- --7912120336 LER 79-058/O3L-0: on 791107.during reactor shutdown.line supplying backup bearing water to IA helium circulator determined to be impaired due to impaired hanger. Causad by missing anchor bolt & stripped anchor bolt shield.

  GAHH.J. W. Public Service Co. of Colorado. 79/12/06. ip.
- 7912120338 Forwards LER 79-059/03L-0. WAREMBOURG,D. Public Service Co. of Colorado. 79/12/06. 4pp.
- ---7912120341 LER 79-059/03L-0: on 791109, during reactor shutdown for maint, boiler feeder snubber BFS-412 observed inoperable. Caused by empty hydraulic oil reservoir Reservoir refilled. GAHM.J. W. Public Service Co. of Colorado. 79/12/06. 1p.
- 7912180596 Forwards LER 79-054/03X-1.
  WAREMBDURG.D. Public Service Co. of Colorado. 79/12/12. 5pp.
- --79:21806:0 LER 79-054/03X-1 on 79:029, standby diesel engine iB tripped on high cooling water temp during surveillance test Caused by cooling water valves lined up incorrectly, Cooling water restored & personnel instructed in proper methods, GANM. J. H. Public Service Co. of Colorado, 79/12/10. 5pp.
- 7912270424 Forwards LER 79-061/03L-0. WAREMBOURO,D. Public Service Co. of Colorado, 79/12/20. 4pp.
- --7912270493 LER 79-061/03L-0: on 791120.pH % total dissolved solid samples not collected for nine shifts. Caused by poor weather. High chloring residual discharge caused by low retention time due to alternate discharge flow path. GAHM, J. W. Public Service Co. of Colorado. 79/12/20. 1p.
- DOCKET 50-269 OCONEE NUCLEAR STATION, UNIT 1
- F. Security, medical, emergency & fire protection plans
- 7809290053 Summary of fire protection appeal meeting on 780414. Meeting inconclusive so official summary not prepared. BIRKEL R. Light Water Reactors Branch 2. 78/09/26. 2pp.
- 7809290054 Summary of fire protection appeal meeting on 780414. Meeting inconclusive, so official summary not prepared. BIRKEL R. Light Water Reactors Branch R. 78/09/25. 2pp.
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives. Provides guidance for improving licensee emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.

  ORIMES, D. K. Emergency Preparedness Task Force. 79/11/23. 30pp.

## C. Adjudicatory correspondence

- 791211003B Confirms receipt of encl 790329 petition to suspend OLs for all PWRs. Forwards FR notice indicating that petition will be treated in accordance w/10CFR2. 206. DENTON.H.R. Office of Nuclear Reactor Regulation. 79/11/23. ip.
- ~~7912110126 Notice of request for action pursuant to 10CFR2.206 re Environ Coalition on Nuclear Power 790329 petition requesting suspension of all OLs for PHRs. MULLER, D.R. Office of Nuclear Reactor Regulation. 79/11/23. 38pp.

#### I. Financial information

- 7912270577 Forwards duplicate copies of util 790321 guarantee of retrospective premiums. in response to NRC 791210 request. WHITLEY.H. D. Dute Power Co. 79/12/20. 1p.
- ~~7912270585 Requests approved guarantee of payment of deferred premiums for 1979. SALTHAN, J. Antitrust & Indemnity Group. 79/12/10. 1p.
- J. Insurance & indemnity information
- 7809190350 Informs recipient of Duke Power Co 780705 request to modify station Indemnity Agreement B-44 to permit receipt & possession of 4 fuel assemblies from Crystal River 3 facility.

  FAIRTLE-M.B. Operating Reactors Branch 4 (Pre 790625).

  78/09/14. 2pp.
- P. Operating license stage documents & correspondence
- 7809270093 Comments on seisoically induced floods at Oconde plants.
  Investigates potential failure of Jocassed Dam in relation
  to safety of units. Guestion is being addressed by
  Geosciances Branch.
  HRLMAN. L. G. Hydrology Meteorology Branch. 78/09/22. 1p.
- ---7809270104 Responds to 760115 memo re recent earthquake activity in vicinity of Jocossee Dam. Discusses bases of saismically induced flood analysis for facility DL. Reactor area could be vulnerable to flooding, but detailed info unavailable.

  HULMAN.L.O. Hydrology Meteorology Branch. 76/01/30. ip.
- 7911090248 "Swamary of Operating Experience W/Recirculating Steam Contrators." EISENHUT, D. 0. Division of Operating Reacture. NUMEC-0523. 79/01/31. 89pp.
- 790B010339 Notifies of status of rept on reactor cavity annulus seal.

  Most PWR users remove ring during normal operation. Others
  store seal ring in raised position during normal operation.

  LAINAB, Q. Plant Systems Branch (Pre 791030). 79/07/05. 7pp.
- 7912310070 Ack 790831 ltrs endorsing B&W generic rept BAW-1564. "Integrated Control Sys Reliability Analysis." & requests addl info.
  REID.R.W. Operating Reactors Branch 4. 79/11/07. 13pp.
- 7912120190 Forwards summary of Teknekron Research. Inc study of licensea regulatory performance evaluation & Teknekron draft rept reoperating reactors w/2&H nuclear steam supply sys. Requests commants. H/o encl.
  STELLO.V. Office of Inspection & Enforcement. Office of the Director. 79/11/08. 2pp.
- 7912100189 Discusses HRC 791101 meeting w/representatives of MSSS vendors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses enci.
  EISEM-NJ.D.O. Division of Decrating Reactors. 79/11/09. 65pp.
- --7912100255 Responds to NRC 791101 request re noncompliance of Westinghouse ECCB evaluation model under requirements of IOCFR30 App K. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants.
  ANDERSON, T. M. Westinghouse Electric Corp. 79/11/02, 4pp.
- --7912100330 Responds to NRC 791101 request re GRML cladding swelling & rupture data. Review of analytical models & tests indicates compliance w/iOCFRBO App K. All GE specs for calculated peak cladding temp remain unchanged.

  BUCHHOLZ.R.H. General Electric Co. 79/12/07, 2pp.

- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50, 46 satisfied.

  QHSLEY, Q.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/11/02. Spp.
- --7912100456 Forwards addl info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model.

  No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results.

  OMELEY, O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).

  79/11/04. 22pp.
- 7912180317 Forwards safety evaluation of proposed changes to Tech Bpecs re 780112,0201 & 790822 requests for amend to auxiliary electrical emergency power sys períodic testing. LAINAS.0. Plant Systems Brench. 79/11/13. 2pp.
- ---7912180324 Bafety evaluation supporting proposed changes to Tech Spacs re auxiliary electrical sys & emergency power sys surveillance periodic testing. \* Office of Nuclear Reactor Regulation. 79/11/13. App.
- 7912120092 Bummary of 791024 mesting w/B&W owners group re asymmetric LOCA loads evaluation Evaluation of B&W plants to be completed by Jul 1980. HOSFORD 8. B. Assistant Director for Engineering Programs. 79/11/20. 4pp.
- 7912100478 Forwards, to all B&W operating plants except TMI, request for add1 info re small break LOCA. Comments requested by 791203. REID.R.W. Operating Reactors Branch 4. 79/11/21. 3pp.
- 7912100414 Forwards concerns on control rod guide tube wear in B&Wdesigned facilities, to assist in planning surveyillance program Mesting scheduled 791220 in Bethesda, MD to discuss proposed program. REID, R. W. Operating Reactors Branch 4. 79/11/23. App.
- 7912040398 Forwards rept & errata sheat re power operated relief valva actuation & reactor trip frequency.
  PARKER.W.O. Duke Power Co. 79/11/26. 24pp.
- 7912040293 Forwards requests for relief from requirements of ASME Boiler & Pressure Vessel Code Section XI, due to impracticality of performing hydrostatic testing of portions of low pressure see water, chemical addition & nitrogen sys. PARKER, W. O. Duke Power Co. 79/11/27. Spp.
- 7912040415 Forwards correct commitment dates to 791121 response to NUREG-0378.
  PARKER, W. D. Duke Power Co. 79/11/27. 4pp.
- 7912110131 Denies 771113 request for extension of time in which to file upgraded emergency plan. Rept due 800101. REID.R.W. Operating Reactors Branch 4. 79/11/27. 2pp.
- 791204031å Forwards proposed Toch Spec revision, supplementing 790328 submittel re operability requirements of emstgency feedwater sys. PARKER, M. D. Duke Power Co. 79/11/28. 1p.
- --7912040518 Proposed Tech Spec revision re emergency feedwater sys. \* Duke Power Co. 79/11/28. 9pp.
- 7912060802 Requests add1 time to respond to NRC 791121 ltr re small break LDCA. Info re mechanical effects of induced elug flow on steam generator tubes will be provided by 800215. Pump scal cooling info will be submitted by 791231. PARKER, N.O. Duke Power Co. 79/12/03. 1p.
- 7912120434 Notifies that response to NRC 790821 ltr re Item 7-1A, benchmark analysis of sequential auxiliary feedwater flow to steam generators following loss of main feedwater will be provided by 791221.
  PARKER, H. D. Duke Power Co. 79/12/03. 1p.
- 7912190775 Forwards draft ltr to all licensees re diesal generator fuel all QA requirements.
  EIBENHUT.D.Q. Division of Operating Reactors. 79/12/11. 2pp.
- 7912270266 Provides status of NUREG-0578 Category A itoms which will not be implemented prior to 800101. Unit I currently in shutdown for refueling. All required items for Unit I will be completed before startup anticipated in early Feb 1980. PARKER, W. G. Duke Power Co. 79/12/17. 2pp.

- 7912270399 Advises that excessive downtime for remaining TMI Lessons Learned Task Force requirements during peak winter months is unnecessary. Sequential shutdown of Units 2 & 3 in Feb will be followed by shutdown of Unit 1 by 800531.

  THIES.A.C. Duke Power Co. 79/12/17. 3pp.
- 7912270451 Reaffirms util commitment to safe operation of facility. Claims significant progress in meeting virtually all Category A items in NVREG-0578.

  THIES,A.C. Duke Power Co. 79/12/17. 3pp.
- Q. Inspection reports, IE Bulletins & correspondence
- 7712170211 Forwards, "Revision 1.Summary Rept, Generic Response to US NRC IE Bulletin 79-02, Base Plate/Concrete Expansion Anchor Bolts." PARKER, W. D. Duke Power Co. 79/10/29. 1p.
- --7912170222 "Revision I, Summary Rept, Generic Response to US NRC IE Bulletin 79-02, Base Plate/Concrete Expansion Anchor Bolts." \* Duke Power Co. TR-3501-1. 79/08/30. 7pp.
- 7912200344 Forwards waste packaging Insp Rept 79-02A on 790925-26. No noncompliance noted. SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/11/07. 2pp.
- --7912200395 Waste packaging Insp Rept 79-02A.No noncompliance noted.
  Major areas inspected:shipping paper & DDT placarding
  requirements.radiation levels.removable contamination.DDT &
  NRC package features.
  BROWN.R.A. Region 2. Atlanta, Office of the Director. 79/11/06.
- 7912040128 Forwards IE Info Notice 79-12A, "Attempted Damage to New Fuel Assemblies," No specific action or response required. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 79/11/09. 2pp.
- 7912060549 Forwards response to Item 5 of IE Bulletin 79-09C re small break operating guidelines. Forwards "Analysis Bummary in Support Of Inadequate Core Cooling Guidelines for Loss of RCS Inventory." H/o encl. PARKER.W. O. Duke Power Co. 79/11/07. ip.
- 7912100154 Ack receipt of 791108 ltr in response to NRC 790607 ltr re items designated as C & D. Corrective actions will be examined during future insp. LEWIG.R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch, 79/11/16. 1p.
- --7912100165 Responds to NRC 790607 ltr re violations noted in IE Insp Ropts 50-269/79-10,50-270/79-10 & 50-287/79-10. Corrective actions: plans to amend GA program topical rept to reflect present mode of operation. PARKER.W. O. Duke Power Co. 79/11/08. lp.
- 7912100169 Forwards IE Info Notice 79-28. "Overloading of Structural Elements Due to Pige Support Loads." No response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 79/11/16. 1p.
- 7912110343 Forwards IE Info Notice 79-27, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required.
  O'REILLY.J.P. Region 2, Atlanta, Office of the Director.
  79/11/16, 2pp.
- 7912170127 Responds to IE Bullstin 79-01. "Environ Qualification of Class IE Equipment." Anticipates Unit 1 & 3 motor operators will be changed out during first cold shutdown after 800129. PARKER, N. D. Duke Power Co. 79/11/16. 1p.
- 7912060607 Forwards IE Circular 79-24, "Proper Installation & Galibr of Core Spray Pips Break Detection Equipment on BVRs." No response required.

  O'REILLY, J. P. Region 2, Atlanta, Office of the Director, 79/11/26. 1p.
- 7912110134 Forwards IE Circular 79-12, "Motor Starters & Contactors Failed to Dperate." No response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/26. 1p.
- 7912040434 Forwards requests for relief from inservice insprequirements of ABME Boiler & Pressure Code, Section XI due to impracticality of performing volumetric examinations on welds in several sys.

  PARKER, W. O. Duke Power Co. 79/11/27. 23pp.

- 7912190790 Responds to IE Bulletin 79-17. Revision 1 re stagnant borated water sys. Examination of normally inaccessible portions of Unit 1 for gipe cracks to be conducted during current refueling outage.
  PARKER.M. O. Duke Power Co. 79/11/28. ip.
- 7912190386 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Dus During Operation." Written response required. D'REILLY, J. P. Region 2. Atlanta, Office of the Director. 79/11/30. 1p.
- 7912140348 Provides supplemental info to 790824 response to IE Builetin 79-08C. "Nuclear Incident at TMI Suppl." re revision of emergency procedures requiring trip of reactor coolant pumps upon reactor trip.
  PARKER. W. O. Duke Power Co. 79/12/06. 2pp.
- 7912280017 Updates 790914 response to IE Bulletin 79-21, "Temp Effects on Level Heasurements." Completion date of Item 4 changed to no later than 800101. PARKER, M.O. Buke Power Co. 79/12/06. ip.
- 7912310293 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances: lOCFR21." No action required.
  D'REILLLY, P. Region 2, Atlanta, Office of the Director.
  77/12/06. 5pp.
- 7912200026 Forwards 1E Bulletin 79-29. "Possible Malfunction of Namto Model EA180 Limit Switches at Elevated Temps." Action required. D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/12/07. 2pp.
- 7912310008 Forwards third response to IE Bulletin 79-02, Revision 2, re pipe support base plate designs. Dase plate flexibility in calculation of expansion anchor bolt loads accounted for by conservative hand calculation method.
  PARKER, N. O. Duke Power Co. 79/12/07. 25pp.
- 7912310022 Forwards updates to 791029 & 1106 responses to IE Bulletin 79-14, "Beismic Analysis for As-Built Safety-Related Piping Sys." Provides summary of seismic input nonconformances through 791126. PARKER, H. O. Duke Power Co. 79/12/07. 11pp.
- 7912210075 Ack receipt of 1E Insp Repts 50-269/79-28,50-270/79-28 t 50-267/79-28 on 791024-26. No proprietary info.
  PARKER, W. O. Duke Power Co. 79/12/10. tp.
- --7912210080 Forwards IE Insp Repts 50-269/79-28,50-270/79-26 & 50-287/79-28 on 791024-26. No noncompliance noted. SUTHERLAND.J.T. Region 2. Atlanta. Fuel Facility & Materials Safety Branch. 79/11/15. 2pp.
- ~~7912210088 IE Insp Repts 50~269/79~28.50~270/79~26 & 50~287/79~28 on 791024~26. No noncompliance noted, Major areas inspected: App B Tech Specs annual reporting requirements & review of nonrouting reports & LERS.

  CUNNINGHAM.A. L. Region 2, Atlanta, Office of the Director. NUFIAM.J. W. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/11/14. 3pp.
- 7912210227 Ack receipt of 791109 & 30 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/79-24, S0-270/79-22 & 30-287/79-24.

  KENNA, H. B. Region 2, Atlanta, Safeguards Branch. 79/12/11. lp.
- --7912210238 Provides add1 info to 791109 response to NRC 790927 ltr re violations noted in IE Insp Repts 50-269/79-24, 50-270/79-22 & 50-287/79-24, Details withheld (ref 10CFR2.790). PARKER.W.O. Duke Power Co. 79/11/30.
- --7912210248 Responds to MRC 790927 ltr rè violations noted in IE Insp Repts 50-269/79-24,50-270/79-22 & 50-287/79-24. Details withheld (ref 10CFR2.790). PARKER, M. D. Dute Power Co. 79/11/09. lp.
- --7912210263 Forwards IE Insp Repts 50-269/79-24,50-270/79-22 & 50-287/79-24 on 790821-24 & 0905-07. Notice of violation withheld (ref 100FRZ,790).

  KENNA, W. B. Region 2, Atlanta, Safeguards Branch. 79/09/27.
- --7912210283 IE Insp Repts 50-249/79-24,50-270/79-22 & 50-287/79-24 on 790821-24 & 0905-07. Major areas inspected: security organization & physical barriers, Details withheld (ref 100FR2.790).
  ORE, D. E., JOHN, M. N. Region 2, Atlanta, Office of the Director, Meri J. C. NRC Regional Offices. 79/09/27. ip.

- 7912280377 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/12/13. 2pp.
- 7912280129 Forwards IE Circular 79-28, "Shock Arrestor Strut Assembly Interference." No written response required.
  O'REILLY.J. P. Region 2, Atlanta, Office of the Director.
  79/12/20. 4pp.
- R. Periodic operating reports & related correspondence
- 79121B0375 Forwards monthly operating repts for Nov 1979. PARKER, W. D. Duke Fower Co. 79/12/14. ip.
- ~~7912180384 Monthly operating repts for Nov 1979. REAVIS.J.A. Duke Power Co. 79/12/14. 14pp.
- S. Reportable occurrences. LERs & related correspondence
- 7912040474 Responds to NRC 790921 ltr transmitting NRC 790626 ltr remultiple equipment failures & surveillance testing errors.

  Discusses review of events described in NRC 790926 ltr.

  Existing procedures & policies address concerns.

  PARKER, M. O. Duke Power Co. 79/12/04. 2pp.
- --7912040476 Forwards RD-269/77-21. FARKER, W. D. Duke Fower Co. 77/07/13. 1p.
- --7912040479 R0-269/77-21: on 770628, during isolation of train A of penetration room ventilation to replace carbon filters, train A was inadvertently tagged out-resulting in filter change in train B instead of A. Caused by personnel arror.
  \* Duke Power Co. 77/07/13. 2pp.
- 7912120294 Notifies of failure to retain instructions to energize both 4160 volt standy buses w/Lee combustion turbine when Unit 2 was in svc. Caused by inadequate revision to operating procedure for 100 kV power supply on 791130.
  PARKER W.O. Duke Power Co. 79/12/05. 1p.
- 7912130411 RD: on 791126-30, only one standby bus had been energized by Lee Station gas turbine, although Tech Specs require both standby buses be energized during hydro outage. Caused by inadequately revised procedures.

  PARKER, H. O. Duke Power Co. 79/12/10. 2pp.
- DOCKET 50-270 DOONEE NUCLEAR STATION, UNIT 2
- F. Security, medical, emergency & fire protection plans
- 7809270053 Summary of fire protection appeal meeting on 780414. Meeting inconclusive, so official summary not prepared, BIRKEL, R. Light Hater Reactors Branch 2. 78/09/26. 2pp.
- 7912200022 Discusses NRC 791107 meeting re emergency preparedness team review objectives. Provides guidance for improving licensea emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.

  ORIMES, D. K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- O. Adjudicatory correspondence
- 7912110038 Confirms receipt of encl 770329 petition to suspend DLs for all PMRs.Forwards FR notice indicating that petition will be treated in accordance w/10CFR2.206.
  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/11/23. ip.
- --7912110126 Notice of request for action pursuant to 10CFR2, 206 re Environ Coalition on Nuclear Power 790329 petition requesting suspension of all OLs for PMRs. MULLER, D. R. Office of Nuclear Reactor Regulation. 79/11/23. 3800.
- I. Financial information
- 7912270577 Forwards duplicate capies of util 790321 guarantee of retrospective premiums in response to NRC 791210 request. WHITLEY.H.D. Duke Power Co. 79/12/20. 1p.
- --7912270585 Requests approved guarantee of payment of deferred premiums for 1979. BALTZHAN J. Antitrust & Indemnity Group. 79/12/10. 1p.

#### J. Insurance & indemnity information

- 7809190350 Informs recipient of Duke Power Co 780705 request to modify station indemnity Agreement 8-44 to permit receipt & possession of 4 fuel assemblies from Crystal River 3 .facility.
  FAIRTILE M.B. Operating Reactors Branch 4 (Pre 790625).
  78/09/14. 2pp.
- P. Operating license stage documents & correspondence
- 7809270093 Comments on seismically induced floods at Oconee plants. Investigates potential failure of Jocassee Dam in relation to safety of units Question is being addressed by Geosciences Branch.

  HULMAN.L.G. Hydrology Meteorology Branch. 78/09/22. ip.
- ---7809270104 Responds to 760115 memo re recent parthquake activity in vicinity of Jocassee Dam. Discusses bases of seismically induced flood analysis for facility DL. Reactor area could be vulnerable to flooding, but detailed info unavailable.
  HULMAN.L.G. Hydrology Meteorology Branch. 76/01/30. 1p.
- 7911090248 "Bummary of Operating Experience W/Recirculating Steam Generators." EISENHUT.D.Q. Division of Operating Reactors. NUREG-0523. 79/01/31. B9pp.
- 7912310070 Ack 790831 ltrs endorsing B&W generic rept BAW-1564. "Integrated Control Sys Reliability Analysis." & requests addl info. REID.R.M. Operating Reactors Branch 4. 79/11/07. 13pp.
- 7912130190 Forwards summary of Teknekron Research, Inc study of licensee regulatory performance evaluation & Teknekron draft rept reoperating reactors w/8&W nuclear steam supply sys. Requests comments. W/o encl.

  87ELLO, V. Office of Inspection & Enforcement. Office of the Director. 79/11/08. 2pp.
- 7912100187 Discusses NRC 791101 meeting w/representatives of NSSS vendors & fuel suppliers re discussion of respective portions of ECGB evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EISENHUT, D. Q. Division of Operating Reactors. 79/11/09. 65pp.
- ---7912100285 Responds to NRC 791101 request re noncompliance of Westinghouse ECCS evaluation model under requirements of iOCFR50 App K. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants.

  ANDERSON, T. M. Westinghouse Electric Corp. 79/11/02. App.
- --7912100330 Responds to NRC 791101 request re ORNL cladding swelling & rupture data. Review of analytical models & tests indicates compliance w/100FR50 App K. All GE specs for calculated peak cladding temp remain unchanged.

  BUCHHOLZ,R.H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50. 46 satisfied.

  OMBLEY, G.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/11/02. 5pp.
- --7912100486 Forwards addl info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. DMBLEY, 0.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.), 79/11/04. 22pp.
- 79121B0317 Forwards safety evaluation of proposed changes to Tech Specs re 780112,0201 & 790822 requests for amend to auxiliary alectrical emergency power sys periodic testing. LAINAS,6. Plant Systems Branch. 79/11/13. 2pp.
- --7912180324 Safety evaluation supporting proposed changes to Tech Specs re auxiliary electrical sys & emergency power sys surveillance periodic testing. & Office of Nuclear Reactor Regulation. 79/11/13. App.
- 7912120092 Summary of 791024 meeting w/BtW owners group re asymmetric LOCA loads evaluation. Evaluation of BtW plants to be completed by Jul 1980, HOSFORD, B.B. Assistant Director for Engineering Programs, 79/11/20, 4pp.

- 791210047B Forwards to all B&W operating plants except TMI request for addl info re small break LOCA Comments requested by 791203. REID.R.W. Operating Reactors Granch 4. 79/11/21. 3pp.
- 79:2100416 Forwards concerns on control rod guide tube wear in B&W-designed facilities.to assist in planning surveyillance program. Meeting scheduled 79:1220 in Bethesda. MD to discuss proposed program.
  REID,R.W. Operating Reactors Branch 4. 79/11/23. App.
- 79:2040355 Forwards rept & errata sheet re power operated relief valve actuation & reactor trip frequency.
  PARKER.W.O. Duke Power Co. 79/11/26. 24pp.
- 7912040273 Forwards requests for relief from requirements of ASME Boiler & Pressure Vessel Code Section XI, due to impracticality of performing hydrostatic testing of portions of low pressure svc water, chemical addition & nitrogen sys. PARKER, M. O. Duke Power Co. 79/11/27. App.
- 7912040415 Forwards correct commitment dates to 791121 response to NUREO-0578. PARKER, W. O. Duke Power Co. 79/11/27. 4pp.
- 7912110131 Denies 791113 request for extension of time in which to file upgraded emergency plan. Rept due 800101.
  REID.R.W. Operating Reactors Branch 4. 79/11/27. 2pp.
- 79:2040516 Forwards proposed Tech Spac revision, supplementing 790525 submitted re operability requirements of unergency feedwater sys. PARKER, H. O. Duke Power Co. 79/11/28. 1p.
- --7912040518 Proposed Tach Epec revision re emergency feedwater sys.
  \* Duke Power Co. 79/11/28. 9pp.
- 79120A0902 Requests add1 time to respond to NRC 791121 ltr re small break LOCA. Info re mechanical effects of induced slug flow on steam generator tubes will be provided by 800215. Pump seal cooling info will be submitted by 791231. PARKER. W. D. Duke Power Co. 79/12/03. ip.
- 7912120434 Notifies that response to NRC 790821 ltr re Item 7-1A, benchmark analysis of sequential auxiliary feedwater flow to steam generators following loss of main feedwater will be provided by 791221.
  PARKER, W. O. Duke Power Co. 79/12/03. 1p.
- 7912180160 Forwards proposed revision to Teth Specs to extend Cycle 4 to no more than 383 \*/~10 effective full power days.Forwards Class III amend fee.W/o oncl fee. PARKER.W.O. Dute Power Co. 79/12/13. 2pp.
- --7912180163 Proposed revision to Tech Space to extend Cycle 4 to no more than 353 +/-10 effective full power days. \* Duke Power Co. 79/12/13. 7pp.
- 7912270266 Provides status of NUREO-0578 Category A items which will not be implemented prior to 800101 Unit i currently in shutdown for refueling All required items for Unit i will be completed before startup anticipated in early Feb 1980. PARKER: W. O. Duke Power Co. 79712/17. Spp.
- 7912270399 Advises that excessive downtime for remaining TMI Leasung Learned Task Force requirements during peak winter months is unnecessary. Bequential shutdown of Units 2 & 3 in Feb will be followed by shutdown of Unit 1 by 800531.
  THIES, A.C. Duke Power Co. 79/12/17. 3pp.
- 7912270451 Reaffirms util commitment to safe operation of facility. Claims significant progress in meeting virtually all Category A items in NOREO-0578. THIER, A.C. Duke Power Co. 79/12/17. 3pp.
- Q. Inspection reports. IE Bulletins & carrespondence
- 7912170211 Forwards, "Revision 1, Summary Rept, Generic Response to US NRC IE Bulletin 79-02, Base Plate/Concrete Expansion Anchor Bolts." PARKER, W. C. Duke Power Co. 79/10/27. 1p.
- --7912170222 "Revision i Summary Rept. Generic Response to US NRC IE Bulletin 79-02, Base Plate/Concrete Expansion Anchor Bolts." \* Duke Power Co. 1R-3501-1. 79/08/30. 7pp.

- 7912200344 Forwards waste packaging Insp Rept 79-02A on 790925-26. No noncompliance noted.
  SUTHERLAND.J.T. Region 2, Atlanta, Fuel Facility & Materials
  Safety Branch. 79/11/07. 2pp.
- --7912200395 Waste packaging Insp Rept 79-02A No noncompliance noted.
  Major areas inspected: shipping paper & BOT placarding
  requirements, radiation levels, removable contamination, DOT &
  NRC package features.
  BROWN-R.A. Region 2, Atlanta, Office of the Director. 79/11/06.
  App.
- 7912040128 Forwards IE Info Notice 79-12A, "Attempted Damage to New Fuel Assemblies." No specific action or response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/09. 2pp.
- 7912060549 Forwards response to Item 5 of IE Bulletin 79-05C re small break operating guidelines. Forwards "Analysis Summary in Support Df Inadequate Core Cooling Guidelines for loss of RCS Inventory." W/o enci. PARKER.M.O. Duke Power Co. 79/11/09. ip.
- 7912100154 Ack receipt of 791108 ltr in response to NRC 790607 ltr re items designated as C & D. Corrective actions will be examined during future insp. LEHIS:R.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 79/11/14. 19.
- --7912100145 Responds to NRC 790607 ltr re violations noted in IE Insp Repts 50-269/79-10.50-270/79-10 & 50-287/79-10. Corrective actions: plans to amend GA program topical rept to reflect present mode of operation. PARKER.H.O. Duke Power Co. 79/11/08. ip.
- 7912100169 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/16. 1p.
- 7912110545 Forwards IE Info Notice 79-29. "Loss of Nonsefety-Related Reactor Goolant Sys Instrumentation During Operation." No specific action or response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/16. 2pp.
- 7912170127 Responds to IE Bulletin 79-01. "Environ Qualification of Class IE Equipment." Anticipates Unit 1 & 3 motor operators will be changed out during first cold shutdown after 800129. PARKER, W. O. Duke Power Co. 79/11/16. ip.
- 7912110134 Forwards IE Circular 79-12, "Motor Starters & Contactors Failed to Operate." No response required. O'RETILLY.J.P. Region 2, Atlanta, Office of the Director. 79/11/26. ip.
- 7912040434 Forwards requests for relief from inservice insprequirements of ABME Boiler & Pressure Code, Section XI due to impracticality of performing volumetric examinations on welds in several sys.

  PARKER, M. O. Duke Power Co. 79/11/27. 25pp.
- 7912190790 Responds to IE Bulletin 79-17. Revision i re stagmant borated water sys. Examination of normally inaccessible portions of Unit 1 for pipe cracks to be conducted during current refueling outage.

  PARKER, U. D. Duke Power Co. 79/11/28. 10.
- 7912190386 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation."
  Written response required.
  0/RELLLY.J.P. Region 2. Atlanta, Office of the Director.
  79/11/30. 1p.
- 7912140348 Provides supplemental info to 790824 response to IE Bulletin 79-036. "Nuclear Incident at TMI Suppl." re revision of sacrgency procedures requiring trip of reactor coolant sumps upon reactor trip.
  PARKER, W. O. Duke Power Co. 79/12/04. 2pp.
- 7912280017 Updates 790914 response to IE Bulletin 79-21, "Temp Effects on Level Measurements." Compistion date of Item 4 changed to no later than 800101.
  PARKER, M. G. Duke Power Co. 79/12/06. Ip.

- 7912310293 Forwards IE Info Notice 79-30, "Reporting of Defects & Nuncompliances, 10CFR21." No action required.
  D'REILLY, J.P. Region 2, Atlanta, Office of the Director.
  79/12/06. 5pp.
- 7912200026 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/12/07. 200.
- 7912310005 Forwards third response to IE Bulletin 79-02. Revision 2. re pipe support base plate designs. Base plate flexibility in calculation of expansion anchor bolt loads accounted for by conservative hand calculation method. PARKER, W. O. Duke Power Co. 79/12/07. 25pp.
- 7912310022 Forwards updates to 791029 & 1106 responses to IE Bulletin 79-14. "Seismic Analysis for As-Built Bafety-Related Piping Sys." Provides summary of seismic input nonconformances through 791126. PARKER, H. O. Duke Power Co. 79/12/07. 11pp.
- 7912210078 Ack receipt of IE Insp Repts 50-269/79-28,50-270/79-26 & 50-287/79-28 on 791024-26.No proprietary info. PARKER, W. C. Duke Power Co. 79/12/10, 1p.
- ---7912210080 Forwards IE Insp. Repts 50-269/79-28,50-270/79-26 & 50-287/79-28 on 791024-26. No noncompliance noted. BUTHERLAND.J. T. Region 2: Atlanta: Fuel Facility & Materials Safety Branch. 79/11/15. 2pp.
- --7912210088 IE Insp Repts 50-269/79-28,50-270/79-26 & 50-287/79-28 on 791024-26. No noncompliance noted Major areas inspected: App B Tech Specs annual reporting requirements & review of nonroutine reports & LERs.
  CUNNINGHAM.A. L. Region 2, Atlanta, Office of the Director. HUFHAM.J.W. Region 2, Atlanta, Fuel Facility & Materials Bafety Branch. 79/11/14. 3pp.
- 7912210227 Ack receipt of 791109 & 30 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/79-24, 50-220/79-22 & 50-287/79-24. RENNA,M.B. Region & Atlanta, Safeguards Branch. 79/12/ii. 1p.
- ---7912210238 Provides addl info to 791109 response to NRC 790927 ltr re violations noted in IE Insp Repts 50-269/79-24, 50-270/79-22 & 50-287/79-24. Details withheld (ref 10CFR2. 790). PARKER,W. D. Duks Power Co. 79/11/30. lp.
- --7912210248 Responds to NRC 790927 ltr re violations noted in IE Insp Repts 50-269/79-24,50-270/79-22 & 50-287/79-24.Details withheld (ref.10CFR2,790). PARKER,M.O. Duke Power Co. 79/11/09. ip.
- --7912210263 Forwards IE Insp Repts 50-269/79-24,50-270/79-22 & 50-287/79-24 on 790821-24 & 0905-07. Notice of violation withhold (ref 10CFR2.790).
  KENNA, H. B., Region 2. Atlanta, Bafaguards Branch. 79/09/27. 2pp.
- --7912210283 IE Insp Repts 50-269/79-24,50-270/79-22 & 50-287/79-24 on 790821-24 & 0905-07. Major areas inspected:security organization & physical barriers. Details withheld (ref 10CFR2. 790).
  MORE, D.E., JDHN, M. N. Region 2, Atlanta, Office of the Director. HOWELL, J. C. NRC Regional Offices. 79/09/27. 1p.
- 7912280377 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required. O'REILLY.J. P. Region 2, Atlanta, Office of the Director. 79/12/13. 2pp.
- 7912280129 Forwards IE Circular 79-28, "Shock Arrestor Btrut Assembly Interference." No written response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/12/20. 4pp.
- R. Periodic operating reports & related correspondence
- 7912180375 Forwards monthly operating repts for Nov 1977. PARKER, M. C. Duke Power Co. 79/12/14. 1p.
- --7912180384 Monthly operating repts for Nov 1979. REAVIS.J.A. Duke Power Go. 79/12/14. 16pp.

## S. Reportable occurrences, LERs & related correspondence

- 7912060553 PNO-II-79-016: on 791025, immediate action ltr issued requiring investigation of LPIB impairment & failure of personnel to notice incorrect control board indications. Special audit to be conducted by util.

  DYER.J.A. Region 2. Atlanta, Office of the Director. 79/10/26.
- 7912040474 Responds to NRC 790921 ltr transmitting NRC 790626 ltr re multiple equipment failures & surveillance testing errors. Discusses review of events described in NRC 790926 ltr. Existing procedures & policies address concerns. PARKER, M. D. Duke Power Co. 79/12/04. 2pp.
- 7912120294 Notifies of failure to retain instructions to energize both 4160 volt standy buses w/Lee combustion turbine when Unit 2 was in svc.Caused by inadequate revision to operating procedure for 100 bV power supply on 791130.
  PARKER.M.O. Duse Power Co. 79/12/05. 1p.
- 7912130411 RD: on 791126-30, only one standby bus had been energized by Lee Station gas turbine, although Tech Specs require both standby buses be energized during hydro outage. Caused by inadequately revised procedures.

  PARKER, M. O. Dute Power Co. 79/12/10. 2pp.
- 7912270503 Forwards LER 79-009/01T-0.
  PARKER, M. O. Duke Power Co. 79/12/21. 2pp.
- ----7912270509 LER 79-009/01T-0: on 791209, during annual maint of engineered safeguard valves, HFI suction valves from borated water storage tank rendered inoperable. Caused by inadvertent rendval & cleaning of limit switch assemblies. LEWIS.S. R. Duke Power Co. 79/12/21. 1p.
- 7912280497 Advises that RO-270/79-8 will be submitted by 800107. Investigation of accident involving reactor bldg penetration imperability is underway.

  PARNER, M. O. Duke Power Co. 79/12/21. ip.

#### DOCKET 50-271 VERHONT YANKEE NUCLEAR POWER STATION

- F. Becurity, medical, emergency & fire protection plans
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives. Provides guidance for improving licensee emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.

  ORIMES, B. K. Emergency Preparedness Task Force. 79/11/23. GOpp.
- P. Operating license stage documents & correspondence
- 7912100413 Discusses NRC concern re containment purging & venting during nermal operation. Includes licensee override of safety actuation isolation signals to containment isolation valves & valve ability to shut w/o degrading containment. SCHMENCER.A. Operating Reactors Branch 1. 79/10/09. Spp.
- 7912050279 Forwards Amend 55 to License DPR-28 safety evaluation & matics of issuance & availability.

  IPPOLITO, T. A. Operating Reactors Branch 3. 79/10/22. 3pp.
- ---7912050300 Safety evaluation supporting Amend 55 to License DFR-28. \* Office of Nuclear Reactor Regulation. 79/10/26. 7pp.
- ---7912050307 Notice of issuance of Amené 55 to License DPR-28.
  IPPOLITO.T.A. Operating Reactors Branch 3. 79/10/26. 2pp.
- 7912100189 Discusses NRC 791101 meeting w/representatives of NSSS vendors & fuel suppliers to discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rugture. Vendor responses encl. EISENHUT, D. Q. Division of Operating Reactors. 79/11/09. 65pp.

- --7912100330 Responds to NRC 791101 request re DRNL cladding swelling & rupture data.Review of analytical models & tests indicates compliance w/100FR50 App K. All GE specs for calculated peak cladding temp remain unchanged.

  BUCHHOLZIR.H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50. 46 satisfied.

  OMSLEY, 6. F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/11/02. 5pp.
- --7912100456 Forwards add1 info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model.

  No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results.

  DMSLEY. G.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).

  79/11/04. 22pp.
- 791213001B Reports faulty overcurrent trip devices in Westinghouse DB 50 circuit breakers. End cap replacement & calibr schedule for next outage of sufficient duration.

  MOODY, D. E. Vermont Yankee Nuclear Power Corp. 79/11/13. ip.
- 7912190123 Recommends rejection of licensee proposed changes to Tech Specs due to insufficient data.Licensee failed to provide addl info requested by NRC. LAINAB.G. Plant Systems Branch. 79/11/15. 2pp.
- 7912070087 Notification of 791211 meeting w/util & QE in Bethesda, MD to discuss fuel performance.
  ROWEY, U.L. Depating Reactors Branch 3. 79/11/27. 2pp.
- 7912180238 Ack receipt of NRC 791016 ltr re violation of General Dasign Criteria 17. Proposed alternative second level of undervoltage protection based on detection, alarm & operator action.

  MODDY, D. E. Vermont Yankee Nuclear Power Corp. 79/12/06. 7pp.
- 7912130353 Forwards proprietary slides for 791211 meeting w/NRC refacility Reload 3 fuel & water rod wear. Affidavit for withholding proprietary info encl. Blides withheld (ref 10CFR2.790). Copy encl for Central Fites only. CARNLEY, J. S. General Electric Co. 79/12/11. 5pp.
- 7912170310 Requests that 791130 ltr be placed on docket as response to NRC 791002 & 30 ltrs re acceptance criteria for Mark I containment program.

  8MITH.R.L. Vermont Yankee Nuclear Power Corp. 79/12/13. 2pp.
- 7912310341 Advises that 800101 date for compliance w/NUREG-0578 not feasible.Equipment delivery design review, safety evaluation & outage schedule will result in completion during wk of 800216.8 Schedule & ltr re requested outage and. HOODY.D.E. Vermont Yankse Nuclear Power Corp. 79/12/14. App.
- 7912310521 Responds to NRC 791114 ltr re mod & resubmission of generic positions on TMI Lessons Learned Task Force implementation. BHR relief & safety valves expected to experience liquid & two-phase flow under high & low pressure conditions. KEENAN.T.D. Babcock & Wilcox Operating Plants Owners Group. 79/12/14. 2pp.
- O. Inspection reports. IE Bulletins & correspondence
- 7912030080 Ack receipt of 791007 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-271/79-10.

  SMITH.O.H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 79/10/24. lp.
- ---7912030086 Responds to NRC 790913 ltr re violation noted in IE Insp Rept 30-271/79-10. Corrective action: stack gas samples will he analyzed every 96-h. HOODY, D.E. Vermont Yankee Nuclear Power Corp. 79/10/09. 2pp.
- --7912030089 Forwards IE Insp Rept 50-271/79-10 on 790710-13 & notice of violation.
  SMITH, C.H. Region 1. Philadelphia, Fuel Facility & Materials Safety Branch. 79/09/13. 2pp.
- --7912030096 IE Insp Rept 50-271/79-10 on 790710-13. Noncompliance noted: failure to sample stack gas at required frequency. THOMMS.L.H. Region i. Philadelphia. Office of the Director. STOMR.J.P. Region i. Philadelphia. Fuel Facility & Materials Safety Branch. 79/09/11. 7pp.

- 7912170365 Responds to LE Bulletin 79-02. Revision 1. Suppl 1. Facility continues program on anchor bolt replacement.
  HDODY, D. E. Vermont Yankee Nuclear Power Corp. 79/10/29. 2pp.
- 7912140260 Responds to IE Bulletin 79-24, "Frozen Lines." Adequate measures already taken to assure that safety-related process, instrument & sampling lines do not freeze.
  MDODY, D.E. Vermont Yankee Nuclear Power Corp. 79/10/30. ip.
- 7912180270 Forwards IE Insp Rept 50-271/79-16 on 791016-19. No noncompliance noted.
  BRUNNER.S.J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 79/10/31. 2pp.
- --7912180274 IE Inso Rept 50-271/79-16 on 791016-19.No noncompliance noted Major areas inspected surveillance callor of safety-related components & equipment required by Tech Specs.
  ZIMMERMAN.R.P. Region 1. Philadelphia, Office of the Director.
  KISTER.H.B. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch. 79/10/30. Spp.
- 7912180433 Responds to IE Bulletin 79-11. "Faulty Overcurrent Trip Device in Circuit Breaters for Engineered Safety Sys." End caps not changed & battery tie breakers not tested or calibr due to special test equipment failure. MOODY,D.E. Vermont Yankee Nuclear Power Corp. 79/11/13. 1p.
- 7912050065 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." Mo response required. ORIER.B.H. Region 1, Philadolphia, Office of the Director. 79/11/16. ip.
- 7912050309 Forwards IE Info Notice 79-27. "Steam Cenerator Tube Ruptures at Tuo PHR Plants." No response required. ORIER, D. H. . Region 1, Philadelphia, Office of the Director. 79/11/16. ip.
- 7912100156 Forwards IE Info Notice 79-26, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. GRIER.8.H. Region 1, Philadelphia, Office of the Director. 79/11/16. 1p.
- 7912110487 Forwards 1E Info Notice 79-29, "Loss of NonsoFety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required. CRIER.B.H. Region I. Philadelphia, Office of the Director. 79/11/19. ip.
- 7912050335 Forwards IE Dulletin 79-26, "Boron Loss From BWR Control Blades," Response required.
  GRIER, B. H. Region 1. Philadelphia, Office of the Director.
  79/11/20. 1p.
- 7912060599 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BMRs." No response required.
  GRIER, B. H. Region 1. Philadelphia, Office of the Director.
  79/11/26. 1p.
- 7912110074 Forwards IE Circular 79-23, "Notor Starters & Contactors Failed to Operate." No response required. GRIER, B.H. Region 1. Philadelphia, Office of the Director. 79/11/26. jp.
- 7912190095 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Written response required. GRIER, B.H. Region I, Philadelphia, Office of the Director. 79/11/30. 1p.
- 7912310253 Forwards IE Info Notice 79-30. "Reporting of Defects & Noncompliances, 100FR21." No action required. GRIER, B. H. Region 1, Philadelphia. Office of the Director. 79/12/06. 4pp.
- 79:2190770 Forwards IE Bulletin 79-28. "Possible Molfunction of Nameo Model EA180 Limit Switches at Elevated Tomps." Written nesponse required. GRIER, B.H. Region 1. Philadelphia, Office of the Director. 79/12/07. lp.

- A. Periodic operating reports & related correspondence
- 7912180402 Forwards monthly operating rept for Nov 1979. MDDDY, D. E. Vermont Yankee Nuclear Power Corp. 79/12/12. 1p.
- --7912180407 Monthly operating rept for Nov 1979. SUBGREN, R. H. Vermont Yankee Nuclear Power Corp. 79/12/12. 8pp.
- S. Reportable occurrences. LERs & related correspondence
- 7912110379 Forwards LER 79-029/031-0.
  CONHAY, W. F. Vermont Yankee Nuclear Power Corp. 79/12/04. 1p.
- --7912110402 LER 79-029/03L-0: on 791104, during survaillance testing, MSIV-BO B & B6 C closed in 2.5-s. Min closure time is 3-s. Caused by operator failure to recognize potentially degraded condition of MSIVs. Retimed within 3- to 5-s. CDNMAY.M.F. Vermont Yankee Nuclear Power Corp. 79/12/04. 2pp.
- 7912110382 Forwards LER 79-033/01P-0. CONWAY, W. F. Vermont Yankee Nuclear Power Corp. 79/12/04. 1p.
- --7912110385 LER 79-033/01P-0: on 791205, seismic analyses revealed that pipe supports in five sys may be inadequate to support seismic loads. Caused by incorrect design or application of pipe supports. Appropriate mods to sys will be performed. CONMAY.W.F. Vermont Yankee Nuclear Power Corp. 79/12/06. 2pp.
- 7912130379 Forwards LER 79-030/031-0.
  CDNWAY-W.F. Vermont Yankee Nuclear Power Corp. 79/12/10. 1p.
- --7912130385 LER 79-030/03L-0: on 791110, during steady state operation, increasing trend in torus water level observed. Caused by leaking bygass valve for torus level transmitters. Hater indication restored per Tech Specs.

  CONNAY, N.F. Vermont Yankee Nuclear Power Corp. 79/12/10. 2pp.
- 7912180486 Forwards LER 79-034/01P-0. CONMAY,W.F. Vermont Yankee Nuclear Power Corp. 79/12/12. 1p.
- --7912180489 LER 79-034/01P-0: on 791211. during seismic analyses of seismic Class 1 pipe supports, discovered that pipe supports in portion of two sys may not support seismic loads. Caused by incorrect design or application of supports. CONMAY.H.F. Vermant Yankee Nuclear Power Corp. 79/12/12. 2pp.
- 79121703R6 Forwards LER 79-031/03L-0. CONNAY, M. F. Vermont Yankee Nuclear Power Corp. 79/12/14. 1p.
- --7912170327 LER 79-031/03L-0: on 791110, during refueling/maint outage, hangers RCIC-H-82 & HPCI-HD-578 removed from svc. Removal unnoticed during review. Caused by personnel error. Hangers returned to svc.
  CONHAY, N.F. Vermont Yankeo Nuclear Power Corp. 79/12/14. 2pp.
- 7912270332 Forwards LERs 79-033/01T-0 & 79-034/01T-0. GUNMAY. H. F. Vermont Yankes Nuclear Power Corp. 79/12/19. 1p.
- --7912270338 LERs 79-033/01T-0 & 79-034/01T-0: on 791205, during seismic analysis required by IE Bulletin 79-14, pipe supports in five sys discovered to heve potontial stress in DBE. Caused by design deviation. Mod supports.

  CONHAY.H.F. Vermont Yankos Nuclear Power Corp. 79/12/19. 2pp.
- DOCKET 50-272 SALEM NUCLEAR GENERATING STATION, UNIT 1
  F. Security, medical, emergency & fire protection plans
- 7912050487 Forwards updated emergency plan. Submittal 1 in response to NRC 791010 ltr.
  LIBRIZZI.F.P. Public Service Electric & Gas Co. of New Jersey.
  79/11/19. 12pp.
- ---7912050488 Updated emergency plan. Submittal 1. \* Public Service Electric & Cas Co. of New Jersey. 79/11/19. 112pp.
- --7912050491 "Emergency Operations Plan." \* Delaware, State of, 72/01/31, 700pp.
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives. Provides guidance for improving licensee emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.

  ORIMES, B. K. Emergency Preparedness Task Force. 79/11/23. 30pp.

- 791212050B Notification of 791210 meeting w/util in Hancock's Bridge, NJ re audit implementation of guidelines for emergency operational procedures re small break LOCA. BOSS,W. Operating Reactors Branch 1. 79/12/07. 2pp.
- G. Adjudicatory correspondence
- 7912050177 Supplemental argument on behalf of intervenors Coleman to reopen Coleman Contention i3 re reracking of spent fuel pool. Actual figures of radiation exposure during reracking of Peach Bottom nuclear station never received.

  VAN NESS, S. C., ONSDORFF, K. A. New Jersey, State of. 79/10/30. Spp.
- 79:2140030 Response in apposition to Public Advocate of State of NJ 79:030 supplemental argument supporting motion for reconsideration of Colemans Contention 13. Colemans failed to demonstrate relevance of claim. Certificate of Svc encl. WETTERNANN.M. J. Public Service Electric & Gas Co. of New Jersey. 79/11/13. 7pp.
- 7912190085 Forwards RP Douglas affidavit re relative toxicity index resulting from replacement of spent fuel pool racks.
  Requests to include it & NRC 791015 affidavit in record.
  WETTERHANN.M. J. Conner, Moore & Corber. 79/11/14. 2pp.
- ---7912190092 Affidavit of RP Douglas on 791102 re relative toxicity index resulting from replacement of prosent spent fuel pool racks w/proposed racks.

  DOUGLABJR, P. Public Bervice Electric & Gas Co. of New Jersey.
  79/11/02. 20p.
- 7912130106 Beeks denial of intervenor Coleman supplemental argument in support of 790802 request for reconsideration of ASLB 790430 dismissal of Contention 13 Argument re transshipment is irrelevant to expansion of spent fuel storage.

  BMITH.B.H., MOORE,J.E. Hearing Branch 2. 79/11/19. 16pp.
- 791211003B Confirms receipt of entl 790329 petition to suspend DLs for all PMRs. Forwards FR notice indicating that petition will be treated in accordance w/10CFR2.204.
  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/11/23. 1p.
- --7912110126 Notice of request for action pursuant to 10CFR2.206 re Environ Coalition on Nuclear Power 790327 petition requesting suspension of all OLs for PWRs. MULLER, D. R. Office of Nuclear Reactor Regulation. 79/11/23. 38pp.
- 7912070076 Response to Christa-Maria & JP O'Neill 791120 contentions. Christa-Maria Contentions 1 & 7-9 are inadmissible & Contentions 2-6 are subj to 791126 stipulation. JP O'Neill Contentions 1. B. 5.2. B. 2. E. 3, 2. F. & 4 admissible. MODRE, J. E. Hearing Branch 2. 79/11/29. 32pp.
- --7912070093 Response to ASLB Question 4.TMI occurrence was Class 9 accident. BMITH.B.H. Hearing Branch 2. 79/08/24. 4pp.
- --7912070102 Forwards response to ABLB question.TMI occurence was Class 9 accident from possible standpoint rather than actual. Two Certificates of Svc encl.

  MATTSON.R. J. TMI-2 Lessons Learned Task Force. 79/08/16. Bpp.
- 7912100329 Notice of withdrawal from proceeding, effective 791130. Centificate of Bvc encl. SMITH.B.H. Hearing Branch 2. 79/11/29. 3pp.
- 7912310132 Response in apposition to intervenors Coleman motion for reconsideration of ASLB 770430 order dismissing Contention 9 as untimely Intervenors failed to meet stds for granting motion or respening record. W/Certificate of Svc. MOORE.J.E. Hearing Branch 2. 79/12/21. 10pp.
- H. General correspondence
- 7912190569 Responds to NRC 791002 Itr re acceptance of Oak Ridge Associated Unive radiation safety training of NRC personel. NRC personnel will need to take brief radiation safety quiz & attend plant specific indoctrination. LIBRIZZI,F.P. Public Service Electric & Oas Co. of New Jersey. 79/12/10. 1p.
- J. Insurance & indemnity information
- 7912040374 Forwards Amend 7 to Indemnity Agreement 8-74 modifying prefatory language re course of transportation. QRIFFITHB,R. Public Bervice Electric & Gas Co. of New Jersey. 79711/27. 2pr

- P. Operating license stage documents & correspondence
- 7911090248 "Summary of Operating Experience W/Recirculating Steam Operators." EISENNUT.D.G. Division of Operating Reactors. NUREO-0523. 79/01/31. 8900.
- 7908010339 Notifies of status of rept on reactor cavity annulus seal. Most PWR users remove ring during normal operation. Others store seal ring in raised position during normal operation. LAINAS, G. Plant Systems Branch (Pre 791030). 79/07/05. 7pp.
- 7912050184 Discusses NRC review of LERs & Tech Spec requirements recontrol RPI sys at Westinghouse PWRs Requests Tech Specs review to ensure requirement for rod maint to within +/- 12 steps indicated & RPI sys verified accurate within 12 steps. BCHWENCER.A. Operating Reactors Branch 1. 79/10/29. 7pp.
- 7912100410 Discusses NRC concern re containment purging & venting during normal operation. Includes licensee override of safety actuation isolation signals to containment isolation valves & valve ability to shut w/a dograding containment. 
  6CHWENCER, A. Operating Reactors Branch 1. 79/10/30. Spc.
- 7912100189 Discusses NRC 791101 meeting w/representatives of NSSS vendors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EISENHUT, D. O. Division of Operating Reactors. 79/11/09. 65pp.
- --7912100255 Responds to NRC 791101 request re noncompliance of Westinghouse ECCS evaluation model under requirements of 10CFR50 App K. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants.

  ANDERSON, T. M. Westinghouse Electric Corp. 79/11/02. App.
- --7912100330 Responds to NRC 791101 request re CRNL cladding swelling & rupture data. Review of analytical models & tests indicates compliance w/10CRSO App K. All GE specs for calculated peak cladding temp romain unchanged.

  BUCHHOLZ, R. H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50. 46 satisfied.

  OMSLEY.O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/11/02. Spp.
- --7912100454 Forwards addl info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model.

  No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results.

  OWSLEY, O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).

  79/11/04. 22pp.
- 7912100178 Forwards TMI Lossons Learned Task Force items for which further clarification is necessary for compliance w/requirements.

  8CHMENGER.A. Operating Roactors Branch 1. 79/11/13. 5pp.
- 7912060013 Notification of 791116 meeting w/util in Nothesda,MD redesign of containment sump pump effective operation in post-LOCA recirculation mode.
  ROBB,W.J. Operating Reactors Branch 1. 79/11/15. 29p.
- 7912190046 Forwards addl info required for completion of electrical override/bypass aspects of containment purge matter.

  LAINAS.C. Plant Systems Branch. 79/11/19. 2pp.
- 7912040108 Forwards Amend 22 to License DPR-70 safety evaluation & notice of issuance & availability.

  BCHWENGER.A. Operating Reactors Branch 1. 79/11/20. 2pp.
- --7912040124 Amend 22 to License DPR-70 lifting restriction on auxiliary feedwater level rise rate when secondary water level in steam generator is below level of feedwater sparger. SCHMENCER. A. Operating Reactors Branch 1. 79/11/20. 22p.
- --7912040128 Safety evaluation supporting Amend 22 to License DPR-70. \* Office of Nuclear Reactor Regulation. 79/11/20. 5pp.
- --7912040137 Notice of issuance & availability of Amend 22 to License DPR-70. BCHMENGER, A. Operating Reactors Branch 1. 79/11/20. Spp.

- 7912040410 Forwards info to Item 2 of interim position for containment purge & vent valve operation pending resolution of isolation valve operability.

  LIBRIZIEF.P. Public Service Electric & Gas Co. of New Jersey.

  79/11/21. 33pp.
- 7912060318 Forwards request for amend to License DPR-70. Request consists of proposed change to safety Tech Specs to incorporate requirements for radiological effluents. Fee & Offsite Dose Calculation Manual end.
  LIBRIZZI.F.P. Public Service Electric & Gas Co. of New Jersey.
  79/11/26. 2pp.
- ---7912060329 Application for amend of License DPR-70. Request consists of proposed change to safety Tech Specs to incorporate requirements for radiological effluents. BCNNEIDER, F. M. Public Service Electric & Gas Co. of New Jersey. 79/11/26. App.
- --7912060335 Proposed changes to Pages 1-1 through 12-3 of draft Tech Specs re radiological effluents. \* Public Service Electric & Gas Co. of New Jersey. 79/11/26.
- --7912060339 Offsite Dose Calculational Hanual. + Public Service Electric & Gas Co. of New Jersey. 79/12/31. 42pp.
- 7912040504 Advises that procedures for interim solution to potential dropped rod accidents were implemented on 791112. Confirms 791123 tolcon notification to E Reeves.
  LIBRIZZI.F.P. Public Service Electric & Gas Co. of New Jersey.
  79/11/27. 1p.
- 7912200509 Forwards request for add1 info in order to complete review of containment vent & purge isolation sys.
  SCHMENCER.A. Operating Reactors Branch 1. 79/12/05. 3pp.
- 7912140304 Forwards rept. "Installation Procedure (Underwater) for Increased Capacity Spent Fuel Storage Racts." LIBRIZZI,F.P. Public Service Electric & Gas Co. of New Jersey. 79/12/10. ip.
- --7912140318 "Installation Procedure (Underwater) for Increased Capacity Spent Fuel Storage Racks." \* Public Service Electric & Gas Co. of New Jersey. 79/12/10. 540p.
- 7912180525 Notifies that Con Ed will administer hot license certification examination to Public Svc Electric & Oas Co personnel in Jan 1980 following completion of certification program Results will be forwarded by end of Feb 1980.

  CURRY, J. J. Consolidated Edison Co. of New York, 79/12/11. ip
- 7912190452 Notifies of B00107 mosting of Salem Technical Advisory Group to introduce individuals unfamiliar w/facility to monitoring programs & to update members w/most rocent info & repts. ALLEN, H. E. Environmental Protection Agency. 79/12/13. 1p.
- 7912190577 Responds to NRC 791210 request for add1 info re auxiliary feedwater sys at Unit 1 "Controls & Electrical Drawings for Safety-Related Equipment." SER & FSAR should be consulted.

  Testing procedure revisions forthcoming.
  LIBRIZZI.F.R. Public Service Electric & Gas Co. of New Jersey.
  79/12/14 2pp
- 7912200527 Natifies NRC that util will implement all Lessons Learned Task Force items by 800101. Nonquisified valve position indicators will be installed by Jan 1980. Anticipates delivery of qualified indicators by Apr 1980. LIBRIZZI, F. P. Public Service Electric & Gas Co. of New Jersey. 79/12/14. 2pp.
- 7912280538 Submits followup to 790921 commitment to meet auxiliary feeduater pump test requirement by 800101. Commitment revised due to extended plant outage. Will perform test as soon as possible after return to power.

  LIBRI221.F.P. Public Service Electric & Gas Co. of New Jersey.
  79/12/19. ip.
- G. Inspection reports. IE Bulletins & correspondence
- 7912030059 Forwards IE Insp Repts 50-272/79-25 & 50-311/79-13 on 790805-0909 No noncompliance noted. BRUNNER.E.J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 79/09/27. 2pp.

- --7912030064 IE Insp Repts 50-272/79-25 & 50-311/79-13 on 790805-0909. No noncompliance nutrd Major areas inspected:plant layout,logs & records & followup on IE bulletins & on previously inspected items.

  NORRHOLM.L.J. Region i, Philadelphia, Office of the Director.

  KEIMIO.R.R. Region i, Philadelphia, Reactor Operations Nuclear Support Branch. 79/09/26. 14pp.
- 791206006B Forwards IE Insp Repts 50-272/79-25 & 50-311/79-13 on 790805-0909. No noncompliance noted.
  BRUNNER,E.J. Region I. Philadelphia, Reactor Operations Nuclear Support Branch. 79/09/27. 2pp.
- --7912060076 IE Insp Repts 50-272/79-25 & 50-311/79-13 on 790805-0909. No noncompliance noted. Major areas inspected: facility tour, log & record reviews, licensee event review. IE Bulletin followup, fire protection & QA.

  NORRHOLM.L. J. Region 1, Philadelphia, Office of the Director.

  KEIMIG.R.R. Region 1, Philadelphia, Reactor Operations Nuclear 77/09/26. 14pp.
- 7912030236 Ack receipt of 790921 ltr informing of steps taken to correct violations noted in IE Insp Rept 50-272/79-15. GRIER.B.H. Region 1. Philadelphia, Office of the Director. 79/10/15. 1p.
- --7912030239 Responds to NRC 790829 ltr re violations noted in IE Insp Rept 90-272/79-13. Corrective actions: identified fire hose stations inspected & stressed importance of submitting incident repts on time. SCHNEIDER, F. M. Public Service Electric & Cas Co. of New Jersey. 79/09/21. 4pp.
- --7912030241 Forwards IE Insp Rept 50-272/79-15 on 790422-0526 & notice of violation.
  BRUNNER,E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/08/29. 2pp.
- ---7912030242 Notice of violation from insp on 790422-0526. Portions withhold (ref 10CFR2,790).

  \* Region 1, Philadelphia, Office of the Director. 79/08/21. 3pp.
- 7912180472 Responds to IE Bulletin 79-23, "Potential Failure of Emergency Diesel Generator Field Exciter Transformer," Diesel generators tested in accordance w/IE Bulletin 79-23. No alarms or abnormal conditions recorded. SCHNEIDER, F. W. Public Service Electric & Gas Co. of New Jersey, 79/10/23, 2pp.
- 7912170170 Forwards response to IE Bulletin 79-14, Suppl 2, "Seismic Analysis for As-Built Safety-Related Piping Sys." As-built piping sys conform to stress isometrics used for performing seismic analyses. SCHNEIDER, F. W. Public Service Electric & Oas Co. of New Jersey. 79/10/30, App.
- 7912200043 Forwards IE Insp Ropts 50-272/79-27 & 50-311/79-34 on 79091-1006. No noncompliance noted.

  BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/11/01. 2pp.
- --7912200046 IE Insp Repts 50-272/79-27 & 50-311/79-34 on 790910-1006. No nancompliance noted. Major areas inspected: log & records review & review of licensee events.

  NORRHOLIMI. J. Region 1. Philadelphia, Office of the Director.

  KEIMIG.R.R. Region 1. Philadelphia, Reactor Operations Nuclear 5upport Branch. 79/10/31. 15pp.
- 7912100180 Forwards request for add1 info re inservice testing program. Notifies of 791205-05 site meeting to discuss inservice testing program. SCHWENCER.A. Operating Reactors Branch 1. 79/11/13. 9pp.
- 7912260032 Responds to Revision 2 of IE Bulletin 79-13 re cracks in feedwater sys piping. Insps at Unit 1 exceeded requirements. After piping support insp at Unit 2, util will be in full compliance w/Revision 2. SCHNEIDER.F.M. Public Service Electric & Gas Co. of New Jersey. 79/11/15. 2pp.
- 7912050095 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required. GRIER, D.H. Region 1. Philadelphia. Office of the Director. 79/11/16. 1p.
- 7912050297 Forwards IE Info Notice 79-27, "Steam Generator Tube Ruptures at Two PWR Plants," No response required. GRIER, B.H. Region 1. Philadelphia, Office of the Director. 79/11/16. 1p.

- 7912100148 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. ORIER.B.H. Region i, Philadelphia, Office of the Director. 79/11/16. 1p.
- 79:21:10468 Forwards IE Info Notice 77-29, "Loss of Nonsafety-Related Reacter Coolant Sys Instrumentation During Operation." No specific action or response required. GRIER.B.H. Region 1. Philadelphia. Office of the Director. 79/11/19. 1p.
- 7912050291 Forwards IE Bulletin 79-26, "Boron Loss From BWR Control Blades." No response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director. 79/11/20. 1p.
- 7912060588 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No response required.
  QRIER.B.H. Region 1, Philadelphia, Office of the Director.
  79/11/26. 1p.
- 7912070423 Responds to IE Bulletin 79-17, Revision i. "Pipe Cracks in Etagnant Borated Water Sys at PWR Plants." Review utilizing definition from bulletin in progress, Results & schedule of insp plans will be submitted by 800101.

  8CHNEIDER, F. W. Public Service Electric & Gas Co. of New Jersey.
  79/11/26. lp.
- 7912110079 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director. 79/11/26. 1p.
- 7912310007 Ack receipt of 791010 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-272/79-15.
  Util response to be withheld (ref 10CFR2.790).
  ORIER.B.H. Region 1. Philadelphia, Office of the Director.
  79/11/27. 2pp.
- 791219007B Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power 8ys Bus During Operation." Written response required. ORIER, B.H. Region 1. Philadelphia, Office of the Director. 79/11/30. 1p.
- 7912310246 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action required.
  GRIER, B. H. Region 1, Philadelphia, Office of the Director.
  79/12/06. 4pp.
- 7912190764 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Written response required.
  ORIER, B.H. Region I. Philadelphia. Office of the Director.
  79/12/07. 1p.
- 7912280234 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required.

  GRIER, B. H. Region 1, Philadelphia, Office of the Director.
  79/12/13. 1p.
- R. Periodic operating reports & related correspondence
- 7912040511 Industrial waste treatment operating rept for Oct 1979. MIDURA.H.J. Public Service Electric & Gas Co. of New Jersey. 79/11/08. 2pp.
- --7912040515 Industrial waste treatment operating rept for Oct 1979. \* Public Service Electric & Oas Co. of New Jursey. 79/10/31. lp.
- 7912040521 Forwards wastewater treatment rept for Oct 1979. MIDURA,H.J. Public Service Electric & Gas Co. of New Jersey. 79/11/13. 1p.
- --7912040524 Wastewater treatment rept for Oct 1979.

  \* Public Service Electric & Cas Co. of New Jersey. 79/11/13. 1p.
- 7912040493 Forwards "Discharge Monitoring Rept for Oct 1979." MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey. 79/11/26. 1p.
- --7912040495 "Discharge Monitoring Rept for Oct 1979."

  SCHNEIDER, F. W. Public Bervice Electric & Gas Co. of New Jersey.
  79/11/20. 12pp.

- 7912180379 Forwards monthly operating rept for Nov 1979. MIDURA.H. J. Public Service Electric & Gas Co. of New Jersey. 79/12/10. ip.
- --7912180383 Monthly operating rept for Nov 1979. MILLER, L. K. Public Service Electric & Gas Co. of New Jersey. 79/12/10. 16pp.
- 8. Reportable occurrences. LERs & related correspondence
- 7912200493 PNS-I-79-003: on 791010, bomb threat received. No bombs found or exploded in either unit.
  JONES, L. W., MARTIN, W. G., ALLAN, J. Office of Inspection & Enforcement, Office of the Director. 79/10/10. ip.
- 7912170421 PNO-I-79-009: on 791017, liquid waste holdup tank It collapsed. Caused by vent valve left closed during pump-down process. No liquid released from tank.
  BORES.R.J., STOHR.J.P. Office of Inspection & Enforcement, Defice of the Director. 79/10/17. 1p.
- 7912260013 PNO-1-79-010: on 791019, anti nuclear group filed under Endangered Spacies Act of 1973 action to suspend or revoke util license on bases that two endangered fish were killed after being caught on util traveling screens.

  SHANDAKY, M., BORES, R. J., SMITH, O. Office of Inspection & Enforcement, Office of the Director. 79/10/19. 1p.
- 7912240010 PNO-I-79-011: on 791023, six workers overcome by carbon dioxide in diesel generator room when fire suppression sys actuated. Caused by operator placing switch in automatic. Investigation continuing.
  KEIHTO,R.R. BRUNNER.E.J. Office of Inspection & Enforcement, Office of the Director. 79/10/23. 1p.
- 7912030190 Forwards updated LER 79-041/01X-1. LIBRIZZI,F.P. Public Service Electric & Gas Co. of New Jersey. 79/11/10. 3pp.
- ---7912030195 Updated LER 79-041/01X-1: on 790425, during refuling outage, eddy current testing of steam generator tubes 12 % 14 performed. After testing, one template plug lost in primary coplant sys. Caused by personnel error. KAPPLE, A.W. Public Bervice Electric & Oas Co. of New Jersey. 79/11/10. 1p.
- 7912040311 Forwards updated LER 79-056/01X-1. LIBRT271,F.P. Public Service Electric & Gas Co. of New Jersey. 79/11/10. 3pp.
- --7912040317 Updated LER 79-056/01X-1; on 790831, tests performed in response to NRC query re plant RHR pump NPSH during post LOCA operations indicated pump flow exceeded design runout flow. Caused by low sys resistance. Flow instruments recalibr. KAPPLE, A.W. Public Service Electric & Ops Co. of New Jersey. 79/11/10. 1p.
- 7912040338 Forwards updated LER 79-050/01X-1. LIBRIZZI,F.P. Public Service Electric & Cas Co. of New Jersey. 79/11/10. Spp.
- ---7912040343 Updated LER 79-050/01X-1: on 790710.Westinghouse notified util that heatup of S/G level measurement ref legs presents potential safety problem during accident conditions. Caused by design deficiency. Changed low-low setpoint. KAPPLE.A.W. Public Service Electric & Gas Co. of New Jersey. 79/11/10. lp.
- 7912040359 Forwards LER 79-055/01X-1. LIBRIZZI.F.P. Public Bervice Electric & Cos Co. of New Jersey. 79/11/10. 3pp.
- --7912040360 LER 79-055/01X-1: on 790830, in response to NRC query re torque valves required for closing containment ventilation isolation valves under incident conditions, actuator torque valves determined insufficient. Gaused by calculation error. KAPPLE.A. H. Public Service Electric & Gas Co. of New Jersey. 79/11/10. 1p.
- 7912040386 Forwards updated LER 79-054/01X-1. LIBRIZZI,F.P. Public Service Electric & Gas Co. of New Jersey. 79/11/10. 3pp.
- --7912040395 Updated LER 79-054/01X-1: on 790824, three snubbers on main feedwater 14 during refueling outage per followup to NRC Insp Rept 50-311/79-19. Caused by extreme shock load. Onubbers replaced. KAPPLE, A. W. Public Service Electric & Gas Co. of New Jersey. 79/11/10. 1p.

- 7912040402 Forwards LER 79-045/01X-1. LIBRIZZI,F.P. Public Service Electric & Gas Co. of New Jersey. 79/11/10. 3pp.
- ~~7912040409 LER 79-045/01X-1:on 79060; imperfections found in impeller of component cooling pump i3. Caused by mfg technique prior to ASME code examination requirements. Original impellers replaced.

  KAPPLE, A. M. Public Service Electric & Gas Co. of New Jersey.

  79/11/10. 1p.
- 7912040414 Forwards updated LER 79-046/01X-1. LIBRIZZI.F.P. Public Service Electric & Oas Co. of New Jersey. 79/11/10. 3pp.
- ~~7912040416 Updated LER 79-046/01x-1: on 790614. Linear indications in welf areas on steam generations 11, 12-13 & 14 discovered.

  Caused by correction Corrective action explained in response to 1E Bulletin 79-13.

  KAPPLE.A.W. Public Service Electric & Gas Co. of New Jersey.
  79/11/10. Lp.
- 7912050422 Forwards LER 79-071/03L-0. LIBRIZZEF, P. Public Service Electric & Gas Co. of New Jersey, 79/11/30. 3pp.
- --7912050429 LER 79-071/03L-0: on 791031, three emergency diesels became inoperable by tagging out diesel lockout switches. Caused by operator misunderstanding instructions & requirements. Reinstructed operator in dept requirements. KAPPLE.A.W. Public Service Electric & Gas Co. of New Jersey, 79/11/30. ip.
- 7912110296 Forwards LER 79-072/03L-0. LIBRIZZI,F.P. Public Service Electric & Gas Co. of New Jersey. 79/12/03. 2pp.
- --7912110298 LER 79-072/03L-0: on 791105 during cold shutdown operation.
  mateorological instruments were out of svc. Caused by power
  supply inverter failure due to couling fan motor being
  bound overloading & damaging inverter. Normal power restored.
  KAPPLE.A. W. Public Service Electric & Gas Co. of New Jersey.
  79/12/03. [p.
- 7912270R84 Forwards LER 79-075/03L-0. LIBRIZ21,F.P. Public Service Electric & Gas Co. of New Jersey, 79/12/20. 3pp.
- --7912270290 LER 79-075/03L-0: on 791123, overall air lock leak rate was found to be in excess of allowable limits. Caused by 100 elevation inner door seal & 130 elevation outer door seal gopping out of seating channel Beals were reseated. KAPPLE, A. M. Public Service Electric & Qas Co. of New Jersey, 79/12/20. 1p.
- 79122705B4 Forwards LER 79-069/03L-0. LIBRIZZI.F.P. Public Service Electric & Gas Co. of New Jersey. 79/12/20. 3pp.
- ~~7912270591 LER 79-069/O3L-0: on 791121, during refueling operations & containment purge, radiation monitors observed to be inoperable. Caused by circuit overload tripping air participate detector breaker.
  KAPPLE, A. W. Public Service Electric & Gas Co. of New Jersey. 79/12/20. 4pp.
- 7912270395 Forwards LER 79-068/03L-0. LIBRIZZI,F. P. Public Service Electric & Gas Co. of New Jersey, 79/12/20. 3pp.
- --7912270600 LER 79-068/OJL-0: on 791128, during Mode 5 operation, safety injection pump 12 started up to fill accumulators but breaker tripped Caused by loose radial & thrust locknuts. Rotating element of pump replaced & locknuts secured. KAPPLE, A. W. Public Service Electric & Ges Co. of New Jersey. 79/12/20. ip.
- U. Congressional/Executive Correspondence
- 7912040107 Responds to 790913 request for written explanation re classification of TMI 790329 accident as class 9 accident. Forwards NRC response to Balem 1 Board Question 4,FD Anderson 790824 memo & RJ Mattson 790830 memo. QOSSICK.L.V. Office of the Executive Director for Operations. 79/10/03. 4pp.
- --7912040118 Advises of Class 9 status of THI accident. SMITH.B.H. Hearing Branch 2. 79/09/EB. 1p.

- DOCKET 50-274 U.S. GEOLOGICAL SURVEY RESEARCH REACTOR
  F. Security, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Guide 5.XX, "Std Format & Content for Licensee Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance." W/o encl. REID.R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22.
- DOCKET 50-275 DIABLO CANYON NUCLEAR POHER PLANT, UNIT 1

  A. Application/construction stage documents & correspondence
- 7912110011 Forwards NRC position on status & applicability to pending OL applications of results of TMI followup actions. Outlines addl short-term actions to be taken.

  VABSALLO.D.B. Division of Project Management. 79/09/27. 41pp.
- 7912110264 Discusses NRC plans to use generic enalyses to develop early verification program to resolve ATWS issue for PWRs & BWRs. Success of program depends on industry response. Supports formation of owners groups to provide nacessary info.

  DENTON. H. R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.
- 7912100483 FOIA request for records re 791019 meeting at which JM Hendrie.D Hassell.L Bickwit & RT Kennedy were present. FLEIBCHAKER.D. Fleischaker.D. S. 79/10/26. 2pp.
- 7912070004 Requests distribution of encl memorandum to Board notification svc lists.

  VAROA.S.A. Assistant Director for Light Water Reactors. 79/11/08.
- --7912070030 Recommends that info on cracking in stagnant boron lines be provided to pertinent boards, in response to 790830 memorandum. KNIGHT,J.P. Assistant Director for Engineering. 79/10/24. 2pp.
- --7912070038 Submits Operating Experience Memo 17 re pipe cracks in borated water sys at TMI-1. Results of Met Ed ultrasonic examination of certain Type 304 stainless steel piping ancl, EIBENHUT, D. O. Division of Operating Reactors. 79/10/05. 4pp.
- 7911270467 Forwards "Discussions of TMI Lessons Learned Short-Term Requirements" providing addl clarifications of NRC requirements for pending OL applicants. VASSALLO.D.B. Division of Project Management. 79/11/09. 2pp.
- 79:2100484 Responds to FOIA request for records re 79:019 meeting at which JM Hendris, D Hassell, L Bickwit & RT Kennedy were present. Forwards J Stephens handwritten notes of RT Kennedy meeting.

  CARR, J. C. Division of Rules and Records. 79/11/23. 2pp.
- 7912180089 Forwards proposed Revision 2 to Reg Quide 1.97,
  "Instrumentation for Light Water Cooled Nuclear Power Plants
  to Assess Plant & Environs Conditions During & Following
  Accident: "Requests comments.
  VARGA: S.A. Assistant Director for Light Water Reactors. 79/11/23.
  4pp.
- 7912040498 Forwards fee for Class I & Class II amend re request for extension of const dates for CPPR-39 & CPPR-69.
  CRANE, P. A. Pacific Gas & Electric Co. 79/11/26. 1p.
- 7912190170 Ack RS Hime 791105 ltr re CA Commission on Agriculture views concerning New Melones dom & reservoir.Forwards 791031 news release.explaining transfer of facilities.W/o enci.Ltr being forwarded to NRC for consideration of Commission. NIELSEN.A.D. Interior.Dept.of. 79/11/26, 2pp.
- 7912040452 Notifies NRC of intentions re paving of certain roads at alant site & impact on archaeological resource area north of plant. Forwards 791112 ltr from Greenwood & Associates.
  PEYERB.R.J. Pacific Oas & Electric Co. 79/11/27. App.
- 791217003B Forwards HA Baldwin of Friends of the Earth 791024 request for preparation of addi environ statements re Class 9 accidents at facilities. Petition being handled as request for action under 10CFR2.206.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/27. 2pp.
- 7912170044 Forwards WA Baldwin of Friends of the Earth 791024 request for preparation of addl environ statements re Class 9 arcidents at facilities. Petition being handled as request for action under 100FR2.206.

  DENTON, H.R. Office of Nuclear Reactor Regulation, 79/11/27, 2pp.

- 7912110322 Forwards response to NRC 790802 ltr re secondary water chemistry control. CRANE, P. A. Pacific Gas & Electric Co. 79/12/05. 4pp.
- 7912120317 Bupplies schedule for providing info re environ qualification of Class IE instrumentation & electrical equipment, in response to 791102 ltr. CRANE, P. A. Pacific Gas & Electric Go. 79/12/05. ip.
- 7912130271 Forwards "Gualification of Control Sys," in response to NRC 790917 ltr requesting info for review of potential safety question detailed in IE Info Notice 79-22. CRANE,P.A. Parific Oas & Electric Co. 79/12/06. ip.
- --7912130280 "Gualification of Control Sys."
  \* Pacific Gas & Electric Co. 79/11/30. 50pp.
- 7912310356 Notification of 800108 meeting w/vtils in Bethesda, MD to discuss info request re adequacy of equipment qualification. UNOARO, A. R. Power Systems Branch. 79/12/11. 3pp.
- 7912310172 Notification of 800109 meeting w/util in Bathesda, MD to present info to util on methods & procedures used by Sandia Labs in study on sys interaction & how methods might be used for investigating effects of failures in sys & components.

  BUCKLEY, B. C. Light Water Reactors Branch 1. 79/12/17. 3pp.
- 7912310037 Confirms rescheduling of meeting re affect of nuclear plant on five endangered species to 800108. REOAN.H. Assistant Director for Environmental Technology. 79/12/19. 1p.
- D. NRC Draft/Final Environmental Statements, suppls & correspondence
- 79121300A3 Ack receipt of 791023 ltr re five endangered species near plant. Requests consultation meeting at future date. REGAN, M. H. Assistant Director for Environmental Projects. 79/11/30. 2pp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Ouide 1. 101.
  VASSALLO, D. D. Division of Project Management. 79/11/21. 4pp.
- Q. Adjudicatory correspondence
- 7912060109 Responds to Governor Brown 791015 request to participate as representative of State of CA.Request should be granted. Cartificate of Svc encl. DAVIS.L.D. Hearing Branch 4. 79/11/08. 5pp.
- 7912030038 Response in opposition to Joint Intervenors 791024.25 & 26 requests to institute proceedings on qualifications of Chairman JM Hendrie & Commissioner RT Kennedy. Ex parts communications took place. Certificate of Svc encl. GEHR. A. C. FURBUSH, M. H. , CRANE, P. A. Pacific Gas & Electric Co. 79/11/09. 22pp.
- 7912130160 Supports Obvernor EQ Brown petition to intervene for reasoning set forth in NRC response Certificate of Syc ancl. FLEISCHAKER, D. S. Affiliation Unknown. FLEISCHAKER, D. S. Fleischaker, D. S. 79/11/09. 3pp.
- 7912130276 Brief in support of exceptions to Part IV of ASLB 790927 partial initial decision. Urges revision of NASLP inference w/intervenor participation in security matters. Exclusion of experts prajudiced intervenor. W/Cartificate of Bvc. DALDHIN.M.A., JONES, V. I., VALENTINE, P. C. Ban Luis Obispo Mothers for Peace. 79/11/12. 24pp.
- 7912050161 Response to Joint Intervenors' 791024 & 26 requests to disquelify Commissioners Hendris & Kennedy. Request should be denied because Joint Intervenors failed to satisfy burden of proof as to bias.

  DAVIS.L.D. Hearing Branch 4, 79/11/13, 11pp.
- --7912050173 Note to all parties forwarding summary of 791019 meeting between JM Handrie & util representatives.

  # Docketing & Bervices Branch. 79/10/26. 3pp.
- 7912060229 Order granting extension until 791121 for all parties to file replies to applicant motion for OL. CHILK.S.J. Commission. 79/11/15. 1p.

- 7912070171 Response in opposition to PG&E 791105 objections to Governor Brown participation in proceeding Rights of interested state representatives established in NRC regulations.
  Timoliness requirement need not be applied to state.
  BROWN.H.H., KLINE.J.A. California, State of. 79/11/15. App.
- 79120A0139 Order admitting State of CA as interested state in proceeding Grants Governor Brown representative participant status. Requests identification of issues within 30 days from receipt.

  BOMERS, E. S. Atomic Safety and Licensing Board Panel. 79/11/16.
- 7912060541 Drder directing NRC to file response on intervenors' security plan contentions by 791218.
  BISHOP, C. J. Atomic Safety and Licensing Board Panel. 79/11/19.
- 7912050439 Order extending deadline to 791123 for Joint Intervenors response to util & NRC question re hearings to determine qualification of Commissioners Kennedy & Hendrie.
  CHILK, S. J. Office of the Secretary of the Commission. 79/11/20.
- 7912050025 Response in apposition to applicant 791026 motion requesting issuance of GL. Record incomplete re presence of reasonable assurance that activities may be conducted \( \omega \) on endangering public health \( \epsilon \) safety. Cortificate of Svc encl. DAVIS, L. D. Hearing Branch 4. 79/11/21. 9pp.
- 7912050046 Joint Intervenors' response opposing applicant 791026 motion requesting that ABLB be directed to issue decision on remaining issues Opportunity to develop argument re OL issuance should be granted Certificate of Byc encl. FLEISCHAKER, D. Fleischaker, D. S. PHILLIPS, J. R. Center for Law in the Public Interest. 79/11/21. Spp.
- 7912050117 Joint Intervenors' reply in opposition to NRC & applicant responses re qualifications of Chairman Hendrie & Commissioner Kennedy Available documents establish existence of ex parts communications. W/Certificate of Svc. FLEIBCHAKER, D. Fleischaker, D. S. PHILLIPS, J. R. Center for Law in the Public Interest. 79/11/23. 9pp.
- 7912130058 Forwards petition by WA Baldwin, requesting that NRC prepare supplemental environ statements re Class 9 accidents at facilities. Appropriate action will be taken.
  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/11/27. 3pp.
- --7912130070 Request for action under 10CFR2 206 for preparation of supplemental EIB concerning impact of Class 7 accidents at facilities.
  MULLER.D.R. Division of Site Safety & Environmental Analysis.
  79/11/23. ip.
- 7912130168 Request for extension until 791207 to file brief in support of exceptions taken to ASLB 770927 partial initial decision.
  Represents that neither NRC nor applicant oppose motion.
  Stamped "granted" on 791128 by ASLAB.
  FLEISCHAKER, D. S. Affiliation Unknown. FLEISCHAKER, D. S. Fleischaker, D. S. 79/11/27. 2pp.
- 7912140011 Request by Joint Intervenors for extension until 791207 to file brief in support of exceptions taken to ASLB 790927 partial initial decision. Voluminous transcript requires additime to assure quality of brief. Certificate of Svc encl. FLEIBCHAKER.D. Fleischaker, D. S. PHILLIPS.J.R. Center for Law in the Public Interest. 79/11/27. 4pp.
- 7912190230 Opposes private meeting held between util & NRC on 791019. Urges disqualification of JM Hendrie & RT Kennedy from participation in matters concerning facilities. Forwards DR Kirkpatrick 791106 lbt transmitting KB Coen 791207 ltr. LAURN, V. W. Affiliation Unknown. 79/11/27. lp.
- --7912190237 Opposes private meeting hald between util & NRC on 791019. KIRKPATRICK, D. Affiliation Unknown. 79/11/06. ip.
- --7912190245 Requests disqualification of JM Hendrie & RT Kennedy from licensing proceedings for facilities.

  COEN.K.S. Affiliation Unknown. 79/12/07. ip.
- 7912200158 Ack receipt of 791024 patition & forwards FR notice for request for action per 10CFR2 206.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/27. 3pp.
- --7912200168 Notice of issuance & availability of Friends of the Earth 791024 petition requesting that NRC prepare supplemental EIS re impact of Class 9 accident at facilities. MULLER, D.R. Division of Site Safety & Environmental Analysis. 79/11/23. 1p.

- 7912170012 Brief in support of Joint Intervenors exceptions to ASLD partial initial decision. Board failed to consider properly seismic focusing & high stress drop issue. Issue should be remanded for hearing. Certificate of Svc encl.
  KLINE.J.A. BROWN.H.H. California. State of. BROWN,H.H. Hill Christopher & Phillips. 79/12/07. IBpp.
- 7912310457 Brief in support of exceptions to ASLB 790927 partial initial decision which found that facility could withstand 7.5 magnitude marthquake on Hosgri fault Requests ASLAB hear oral argument Certificate of Svc encl. FLEISCHAKER, D. S. Fleischaker, D. S. 79/12/07. 89pp.
- 7912270064 Requests response to 791030 request for preservation of NRC apparanda re 791119 aceting between JM Hendric & Hielto Shackleford & Blanc. Forwards copy of 791030 Itr. H/n ancl. FLEISCHAMER.D. S Floischaler. D. S. 79/12/13. 2pp.
- 7912280512 Requests that OL not be granted to util.Cites inability of util.cities & county to preserve public health in event of nuclear mishap.

  HURTHAN.H. Affiliation Unknown. 79/12/14. 1p.
- 7912280508 Requests substantive response to 791024 request for NRC to supplement EIS to consider consequences of Class 9 nuclear accidents. Failure to respond by 800104 will indicate NRC does not plan to require suppl.

  8ALDWIN.W.A. Friends of the Earth. 79/12/21. 1p.

- 7912110371 Certifies that response to Ouvernor EG Brown petition to participate as representative of interested state was served on 791104.
  BISGNOFF, C. A. Pacific Cas & Electric Co. 79/11/16. 3pp.
- 791219000B Responds to request for renotice of license Task Force recommendations proceedings & full public hearings to THI Lessons Learned applicable to applicant. Evaluation of recommendations undurmay.

  ENCELHARDT, T. F. Deputy Executive Lugal Director. 79/11/27. 3pp.
- -7912190012 Advises that NRC has approved SECY 79-461: "Recommendations of NRC/EPA Task Force on Emergency Planning."
  CHILM.S.J. Office of the Secretary of the Commission. 79/10/05.
- --7912190035 Forwards interim guidence for upgrade of emergency plans per Reg Quide 1. 101. Comments requested. EISEMNUT.D.O. Assistant Director for Light Water Reactors. 79/10/10. 2pp.
- -7912190045 Requests full public hearings re THI Lessons Learned Task Force recommendations & renotice of ongoing licensing for public participation. CARR.H. League of Homen Voters of San Luis Obispo.CA. 79/10/29.
- 7912190220 Supports resumption of OL issuances. SHAH, H. E. Affiliation Unknown, 79/11/27. ip.
- 7912280600 Responds to 790926 ltr re power plant opening, waste disposal & safety precautions. NRC conducting thorough investigation of TMI accident. Recommendations will be applied to all nuclear facilities. Ltr encl. DENTON. H. R. Office of Nuclear Reactor Regulation. 79/12/07. Spp.
- K. Utility Final Gafety Analysis Report (FSAR) & amends
- 7912260280 Forwards Amend 81 to FBAR & Amend 82 to Hosgri Rapt. SHACKLEFORD B.W Pacific Sas & Electric Co. 79/12/18. 1p.
- --7912260284 Amené 81 to FSAR & Amené 82 to Hosgri Rept For Diablo Canyon, Provides add1 info re pressurization air flow conservative dumping value torsion calculation & polar crame stability. 5 Pacific Oas & Electric Co. 79/12/18. 9App.
- Q. Inspection reports. IE Bulletins & correspondence
- 7912060090 Forwards IE Jasp Repts 50-275/79-21 & 50-323/79-11 on 790821-24 & 0924-26. No noncompliance noted. CREMS, J.L. Region 5. San Francisco. Reactor Operations Nuclear Support Branch. 79/10/19. 2pp.

- --7912060104 IE Insp Repts 50-275/79-21 & 50-323/79-11 on 790821-24 & 0924-26. No noncompliance noted. Major areas inspected: preoperational testing evaluation verification of test results & IE circular followup.

  STERNBERO, D. M. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. MORRILL, P. J., HORN, A. J. Region 5, San Francisco, Office of the Director. 79/10/19. Spp.
- 7912060056 Forwards IE Insp Rept 50-275/79-23 on 790927 & 1003-05. No noncoapliance noted.

  SPENCER.G.S. Region 5. San Francisco, Reactor Construction & Engineering Support Branch. 79/11/01. 2pp.
- --7912060065 IE Insp Rept 50-275/79-23 on 790927 & 1003-05. No noncompliance noted Major ereas inspected action on IE Bulletin 79-14.ABME certificates of authorization & const activities.

  DDDDS,R.T. Region 5. Sam Francisco. Reactor Construction & Engineering Support Branch. HUTSON.T.W. Region 5. San Francisco. Office of the Director. 79/11/01. 4pp.
- 7912100273 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. ENGELKEN,R.H. Region S. San Francisco, Office of the Director. 79/11/16. 1p.
- 7912110510 Forwards IE Info Notice 79-29. "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. ENSELECT.R. N. Region 5, San Francisco, Office of the Director. 79/11/16. ip.
- 7912070022 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Byray Pipe Break Detection Equipment on BMRs." No response required.
  ENGELKEN.R.H. Region 5, San Francisco, Office of the Director.
  79/11/20
- 7912110268 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required.
  EMDELKEN,R.H. Region 5, San Francisco, Office of the Director.
  79/11/26. ip.
- 7912110494 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sent by NRC to licensees.
  ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/11/26. ip.
- 7912190121 Forwards IE Bulletin 79-27, "Loss of Non-Claus IE Instrumentation & Control Power Bys Bus During Operation." Written response required. EMBELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/11/30.
- 7912310269 Forwards IE Info Notice 79-30, "Reporting of Defects & Nancompliances, 10CFR21." No action required. EMCELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/12/06. 4pp.
- 7912140492 Forwards reply to IE Bullotin 79-02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts," SPENCER.G.S. Region 5, Ban Francisco, Reactor Construction & Engineering Support Branch, 79/12/07, Ip.
- --7912140497 Responds to IE Bulletin 79-02. Revision 2. "Pipe Supports Dase Flate Dosigns Using Concrete Expansion Anchor Bolts."
  Supports have stiffener plates added to assure baseplate rigidity & load distribution to bolts.
  CRANE.P. A. Pacific Das & Electric Co. 79/09/19. 4pp.
- 7912200237 Forwards IE Bulletin 79-29, "Possible Malfunction of Nomco Model EA1BO Limit Switches at Elevated Temps." Action required. ENSELKEN.R.H. Region 5, San Francisco. Office of the Director. 79/12/07. ip.
- 7912270072 Forwards PG&E response to IE Bulletin 79-04. SPENCER. C. S. Region 5: San Francisco. Reactor Construction & Engineering Support Branch. 79/12/07. 1p.
- --7912270079 Notifies that response to IE Bulletin 79-04 will be sent by 791101 gending receipt of calculated loads & hanger strength review from Westinghouse.
  CRANE.P. A. Pacific Gas & Electric Co. 79/10/16. 1p.

- 7912190614 Responds to IE Bulletin 78-12, 78-12A & 78-12B. Weld math heat & lot numbers tabulated in 790408 C-E generic rept.

  Gurveillance weldment consists of full thickness weldments using tandem arc welding process.

  CRANE.P. A. Pacific Oas & Electric Co. 79/12/12. ip.
- 7912280ái9 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required. ENGELMEN.R.H. Region 5, San Francisco, Office of the Director. 79/12/13. ip.

#### U. Congressional/Executive Correspondence

- 7912210216 Ack receipt of 790928 ltr re League of Women Voters of San Luis Obispo.CA comments on advance notice of rulemaking for emergency planning at Diablo Canyon. OOSSIGK.L.V. Office of the Executive Director for Operations. 79/10/29. ip.
- --7912210228 Forwards League of Nomen Voters of San Luis Obispo.CA 790920 comments on proposed regulations for nuclear emergency plans. Requests comment. LACOMARSIND.R. House of Rep. 79/09/28. 7pp.
- 7912210124 Responds to JH Alexander 790829 ltr re study of human factor of nuclear plant installation. Operating personnel receive addl training in plant transients & multiple accident conditions.
  ODBSIGK.L.V. Office of the Executive Director for Operations.
  79/10/31. 2pp.
- --7912210133 Forwards JH Alexander request for more study of human factor in operating & control sys of nuclear power plant installation. Requests comments. CRANSIDN.A. Senato. 79/08/29. 2pp.
- 7912210030 Requests info re effect licensing moratorium will have on facility.

  LAGOMARBINO,R.J House of Rep. 79/11/08. 1p.
- 7912130206 Advises that Commission move quickly to decide if 791019 meeting w/util disqualifies Commissioners Hendrie & Kennedy from licensing.
  LAGONARSIND.R. J. House of Rep. 79/11/15. 1p.
- 7912180460 Forwards ltrs from constituents re licensing of facilities. Requests Commissioners Hendrie & Kennedy be disqualified because of attendance at 791019 meeting w/util. LAGOMARBINO,R.J House of Rep. 79/11/15. 18pp.
- --7912180475 Urges Commission not to license nuclear reactor due to proximity to earthquake fault.

  JACKSON, O. M. Affiliation Unknown. 79/11/28. 1p.
- --7912180480 Urges resignation of Chairman Hondrie & Commissioner Konnedy for attending meeting w/PC&E. COOPER.P. Affiliation Unknown. 79/11/05. lp.
- --7912180484 Objects to secret 791019 meeting between Hendric-Kennedy & PO&E. Urges disqualification from further decisions on util. CUMMINGS.S.C. Affiliation Unknown. 79/11/06. 19.
- ---7912180488 Forwards copies of 791121 ltrs sent to Senator Cranston & Representative Panetta urging disqualification of Hendrie & Kennedy.
  TETER.H.M. Affiliation Unknown. 79/11/21. 4pp.
- ~-79;2180493 Forwards copy of 79;112 ltr to Senator Cranston objecting to meeting between HundrierKennedy & PO&E. Requests each commissioner receive copy. ERNST.T. Affiliation Unknown. 79/11/28. 2pp.
- --7912180502 Forwards copy of 1tr to Senator Cranston orging disqualification of Hendrie & Kennedy from further decisions on util.

  ZIMMERHAN, A. Affiliation Unknown, 79/11/28, 2pp.
- --7912180307 Forwards copies of 791116 ltrs to Senator Cranston & Regresentative Panetta urging disqualification of Hendrie & Kennedy from further decisions on POME. HANZEK.R. Affiliation Unknown. 79/11/16. Spp.
- --7912180510 Objects to meeting between Hendrie, Kennedy & PG&E. Urges disqualification from further decisions on util. MOODY, R., MOODY, D. Affiliation Unknown. 79/11/11. opp.

# V. Operator Examinations

7911020180 Notifies of status of operator licensing at facilities scheduled to receive OLs.
COLLING.P.F. Operator Licensing Branch. 79/10/19. 3pp.

#### DOCKET 50-276 GEORGIA TECH RESEARCH REACTOR

- F. Security, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Guide 5.XX, "Std Format & Content For Licensee Physical Security Plan for Protection of SNM of Hoderate or Low Strategic Significance." W/o encl. REID.R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22.

# DOCKET 50-277 PEACH BOTTOM ATCHIC POWER STATION, UNIT 2 F. Security, medical, emergency & fire protection plans

7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives. Provides guidance for improving licensee emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.
GRIMES, B. K. Emergency Proparedness Task Force. 79/11/23. 30pp.

#### G. Adjudicatory correspondence

7912110043 Forwards comments on NUREG-0511 Draft GEIS reflects conscious & deliberate NRC policy to jeopardize public health & safety & thwart objectives of NEPA.

KEPFORD, C. Environmental Coalition on Nuclear Power. 79/10/24.

- 7912180098 Ack receipt of 791118 ltr re concerns about application for early site review. Commission is reviewing application for docketing. Doard found intervenor motion to terminate review premature.

  OILINSKY.V. Commission. 79/11/30. 1p.
- --7912180107 Believes util application for early site review is futile gesture.NRC review of application will reinforce public image of inefficient & wasteful govt administration. Lancaster News 790920 article re early site review encl. SPACKHAN.T. Affiliation Unknown. 79/11/18. 3pp.
- P. Operating license stage documents & correspondence
- 7912100189 Discusses NRC 791101 meeting w/representatives of NSSS vendors & fuel suppliers re discussion of respective partions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EISENHUT.D.O. Division of Operating Reactors. 79/11/09.
- --7912100285 Responds to NRC 791101 request re noncompliance of Hestinghouse ECCB evaluation model under requirements of 10CFR50 App N. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants.

  ANDERSON, T. M. Hestinghouse Electric Corp. 79/11/02. 4pp.
- --79121000300 Responds to NRC 791101 request re ORNL cladding swelling & rupture data. Review of analytical models & tests indicates compliance w/1007850 App K. All GE specs for calculated peak cladding temp remain unchanged.

  BUCHHOLZ.R. H. General Electric Co. 79/12/07. Ppp.
- ---7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50. 46 satisfied.
  GMSLEY.O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/11/02. Spp.
- --7912100456 Forwards add1 info ro evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model.
  No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results.
  DWBLEFY.O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/11/04. 22pp.
- 7912140182 Notification of 791127 meeting u/util to discuss proposed design providing second lovel of undervoltage protection for safety related equipment at facility.

  CLARK, R. Operating Reactors Branch 3. 79/11/14. 2pp.

- 7912120325 Responds to NRC 791002 ltr re certification of NRC personnel in radiation safety by Oak Ridge Associated Univs.NRC personnel will attend site-specific training & submit annual confirmation of requalification.

  CLOUTIER.R. Philadelphia Electric Co. 79/12/03. 2pp.
- 7912180606 Responds to 791022 ltr re containment purging & venting during normal operation. Util will comply w/ "Interim Position for Containment Purge & Vent Valve Operation Pending Resolution of Isolation Valve Operability."

  DALTROFF, S. L. Philadeiphia Electric Co. 79/12/11. 2pp.
- 7912280561 Responds to NRC 791214 telcon requesting info re implementation of short-term Lessons Learned Task Forte requirements by 800101 Discusses proposed schedule & revisions.

  DALTROFF, S. L. Philadelphia Electric Co. 79/12/21. Spp.

# Q. Inspection reports, IE Bulletins & correspondence

- 7912060033 Ack receipt of 791009 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/79-13 & 50-278/79-15.

  ORIER.B.H. Region 1. Philadelphia. Office of the Director. 79/10/22. 1p.
- --7912060044 Responds to NRC 790917 ltr re violations noted in IE Insp. Repts 50-277/79-13 & 50-278/79-15. Corrective actions: personnel instructed in accurate signing off of surveillance tests & in timely responses to audit rept. DALTROFF,S.L. Philadelphia Electric Co. 79/10/09. 6pp.
- --7912060049 Forwards IE Insp Repts 50-277/79-13 & 50-278/79-15 on 790618-21 & 25-29 & notice of violation.
  GRIER,B.H. Region I, Philadelphia, Office of the Director. 79/09/17. 3pp.
- --7912060054 Notice of violation from insp on 790618-21 & 25-29.

  \* Region 1, Philadelphia, Office of the Director. 79/09/07.
  30p.
- ---7912060058 IE Insp Repts 50-277/79-13 & 50-278/79-15 on 790618-21 & 25-29. Noncompliance noted failure to identify post-valve replacement test results as unacceptable & to issue timely responses to audit repts.

  JORNSON. J. MARKOMSKI. R. & KISTER, H. B. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/09/07. 22pp.
- 7912170171 Responds to IE Bulletin 79-23. "Potential Failure of Emergency Diesel Generator Field Exciter Transformer." No connections found which could allow flow of high circulating currents exceeding transformer ratings.

  GALLAGHER.J.W. Philadelphia Electric Co. 77/10/25. 2pp.
- 7912170240 Updates review of seismit analyses for as-built safetyrelated piping per IE Bullotin 79-14, "Seismic Analysis for Safety-Related Piping Sys" " DALTROFF, S. L. Philadelphia Electric Co. 79/10/30. 2pp.
- 7912050101 Ack receipt of 791015 ltr informing NRC of steps taken to correct violations noted in TE Insp Repts 50-277/79-14 & 50-278/79-14. SMITH, G.H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 79/11/06. Ip.
- --7912050105 Responds to NRC 790924 ltr re violations noted in JE Insp Repts 50-277/79-14 & 50-278/79-16. Corrective actions: new shutdown procedure & removal of identified leaking fuel assemblies. DALTROFF, S. L. Philadeiphia Electric Co. 79/10/15. 3pp.
- --7912050107 Forwards IE Insp Repts 50-277/79-14 & 50-278/79-16 on 790622 & notice of violation.
  SMITH.Q.H. Region i. Philadelphia, Fuel Facility & Materials Safety Branch. 79/09/24. 2pp.
- --7912050110 Notice of violation from inep on 770622.

  \* Region i, Philadelphia. Office of the Director, 79/09/20.
  ip.
- --7912050116 JE Insp Repts 50-277/79-14 & 50-278/79-16 on 790622.
  Noncompliance noted: failure to adhere to Tech Spec
  release rates.
  SERABEAN J. A., JACKSON, T. J., STOHR, J. P. Region 1, Philadelphia,
  Office of the Director. 79/09/20. 4pp.
- 7912200344 Forwards waste packaging Insp Rept 79-02A on 790925-26.No noncompliance noted.

  SUTHERLAND.J.T. Region 2 Atlanta. Fuel Facility & Materials Safety Branch. 79/11/07. 2pp.

- --7912200395 Waste packaging Insp Rept 79-DEA No noncompliance noted.
  Major areas inspected:shipping paper & DDT placarding
  requirements:radiation levels,removable contamination,DDT &
  NRC package features.
  BROWN, R.A. Region 2, Atlanta, Office of the Director. 79/11/04.
- 7912050049 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director. 79/11/16. 1p.
- 7912050286 Forwards IE Info Notice 79-27, "Bteam Generator Tube Ruptures at Two PWR Plants." No response required. ORIER.D.H. Region 1. Philadelphia. Office of the Director. 79/11/16. 1p.
- 7912100144 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/11/16. 19.
- 791211045B Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. ORIER.B.H. Region 1, Philadelphia. Office of the Director. 79/11/19. 1p.
- 7912050277 Forwards IE Bulletin 79-26. "Boron Loss From BWR Control Blades." Response required.
  CRIER.B.H. Region 1, Philadelphia, Office of the Director.
  79/11/20. 1p.
- 7912260109 Ack receipt of 791004 ltr informing NRC of steps taken to correct violation nated in IE Insp Repts 50-277/79-08 & 50-278/79-09.
  MARTIN, H. O. Region 1, Philadelphia, Safeguards Branch. 79/11/21.
- --7912260115 Forwards IE Insp Repts 50-277/79-08 & 50-278/79-09 on 790226.28 & 70305-07 & notice of violation Notice of violation withheld (ref 10CFR2, 790).
  MARTIN.H.G. Region 1. Philadelphia, Safeguards Branch.
  79/09/14. 2pp.
- --7912260119 IE Insp Repts 50-277/79-08 & 50-278/79-09 on 790226,28 & 0305-07. Details withheld (ref 10CFR2. 790).

  BAILEY.R. J., LABUN.R. Region 1, Philadelphia, Office of the Director. DEV.IN.J.H. Region 1, Philadelphia, Safeguards Branch. 79/09/14. 2pp.
- 7912060584 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pips Break Detection Equipment on BMRs." No response required.
  ORIER, B. H. Region 1, Philadelphia. Office of the Director.
  79/11/26. 1p.
- 7912110073 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required.
  GRIER, B. M. Region 1, Philadelphia, Office of the Director.
  79/11/26. 1p.
- 7912210005 Prants extension until 800101 for placing plant in cold shutdown to complete mods to control rod drive sys small piping hangers as required by IE Bulletins 79-02 & 79-14. GRIER B.H. Region i, Philadelphia, Office of the Director. 79/11/26. Cop.
- 7912190063 Forwards IE Bulistin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation." Written response required. GRIER, B.H. Region i, Philadelphia, Office of the Director, 79/11/30. ip.
- 7912310237 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action required, ORIER, B. M. Region 1, Philadelphia, Office of the Director, 79/12/06. 4pp.
- 7912190761 Forwards IE Bulletin 79-28. "Possible Malfunction of Namco-Model EA180 Limit Switches at Elevated Temps." Written response required.

  ORIER, B. H. Region 1, Philadelphia, Office of the Director.
  79/12/07. 1p.
- 7912280031 Responds to IE Bulletin 79-02. Revision 2, "Pipe Bupport Base Plate Designs Using Concrete Expansion Anchor Bolts."
  Where safety factors less than required, supports will be modified.
  DALTROFF, S. L. Philadelphia Electric Co. 79/12/07. 4pp.

- 7912280227 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required.
  QRIER, B. H. Region i, Philadelphia, Office of the Director.
  79/12/13. ip.
- R. Periodic operating reports & related correspondence
- 7712140344 Forwards monthly operating repts for Nov 1979. COONEY, M. J. Philadelphia Electric Co. 79/12/10. 1p.
- --7912140359 Monthly operating repts for Nov 1979. ALDEN, W. M. Philadelphia Electric Co. 79/12/10. 9pp.
- S. Reportable occurrences, LERs & related correspondence
- 7912310322 RO-2-79-50/1P: on 791113 insp of vendor design per IE Bulletin 79-02 revealed trapeze-type hangers re i-inch control rod drive insert & withdraw piping not seismitcally qualified. Caused by design deficiency.

  ULLRICH.W.T. Philadelphia Electric Co. 79/11/14. 2pp.
- 7912310191 RD-2-79-51/IP: on 791121, both fire pumps out of svc for short period. Caused by installation of relief valve on fire header. Following completion of sys mod, sys will be tested & declared fully operable.

  ULLRICH, H. T. Philadelphia Electric Co. 79/11/21, ip.
- 7912070349 LER 79-047/03L-0: on 791029, valves SV2671A & SV2671B failed to close during surveillance testing of dioxide analyzer primary containment valves. Caused by piston binding in valve body. Valve internals rebuilt.

  CDONEY, M. J. Philadelphia Electric Co. 79/11/28. 1p.
- 7912120343 Forwards LER 79-048/03L-0. COONEY, M. J. Philadelphia Electric Co. 79/11/29. 4pp.
- --7912120347 LER 79-048/03L-0; on 791030; during relamping of main off gas stack, personnel discovered broken isokinetic sample line. Caused by crimp at U clamp support bracket & fatigue from expansion, contraction & wind loading. COONEY, M. J. Philadalphia Electric Co. 79/11/29. 1p.
- 7912120427 Forwards LER 79-050/017-0. CODNEY, M. J. Philadelphia Electric Co. 79/11/29. 2pp.
- --7912120435 LER 79-050/01T-O:on 791113, during insp in response to IE Bulletin 79-02, eight hangers for control rod drive insert/withdrawal piping found not qualified to withstand DBE. Caused by seismic, support design deficiency. GOONEY, M. J. Philadelphia Electric Co. 79/11/29. 1p.
- 7912140455 Forwards LER 79-051/01T-0. COGNEY, M. J. Philadelphia Electric Co. 79/12/05. 2pp.
- --7912140463 LER 79-051/OiT-O: on 791121, fire pump controls removed from syc to permit mod on fire header. Diesel pump found to be inoperable. Caused by dirty relay contacts in regulator circuit. Contacts cleaned & pump returned to syc. CODNEY, M. U. Philadelphia Electric Co. 79/12/05. 1p.
- 7912270393 RQ-2-79-52/iP: on 791127, seismic capabilities of concrete block walls on elevation i35 ft reanalyzed as less than required safety factor. Caused by engineering design deficiency. Mod of wall support will raise safety factor. ULLRICH.W.T. Philadelphia Electric Co. 79/12/06. 2pp.
- 7912190566 RO-2-79-53/1P: on 791207, recirculation sys sample line outer valves isolation function inoperable. Caused by improper testing of installed jumper. Jumper removed valves tested for manual & automatic isolation & found operable.

  ULLRICH. W. T. Philadelphia Electric Co. 79/12/10. 2pp.
- 7912270596 RO-2-79-53/IP: on 791207, recirculation sys sample line outer valve AO-2-2-40 isolation function failed Caused by improper testing after jumper installation. Jumper removed & log procedure will be reviewed.

  ULLRICH.W.T. Philadelphia Electric Co. 79/12/10. 2pp.
- 7912180644 Forwards LER 79-052/01T-0. CDONEY, M. J. Philadelphia Electric Co. 79/12/11. 2pp.
- --7912180647 LER 79-052/01T-0: on 791127, analysis per IE Info Notice 79-28 revealed four concrete expansion bolts in concrete block walls w/safety factors of less than four Caused by deficient design. Corrective actions to be completed by 8000101.

  CODNEY: M. J. Philadelphia Electric Co. 79/12/11. 1p.

- DOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3
  F. Security, medical, emergency & fire protection plans
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives. Provides guidance for improving licensee amergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.

  ORIMES, B. K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- Q. Adjudicatory correspondence
- 7912110043 Forwards comments on NUREG-0511. Draft GEIS reflects conscious & deliberate NRC policy to Jeopardize public health & safety & thwart objectives of NEPA.
  KEPFORD. C. Environmental Coalition on Nuclear Power. 79/10/24.
- H. General correspondence
- 7912180098 Ack receipt of 791118 ltr re concerns about application for early site review. Commission is reviewing application for docketing. Board found intervenor motion to terminate review premature.

  GTLINSKY, V. Commission. 79/11/30. 1p.
- --7912180107 Relieves util application for early site review is futile gesture.NRC review of application will reinforce public image of inefficient & wasteful govt administration. Lancaster News 790920 article re early site review encl. EPACKMAN.T. Affiliation Unknown. 79/11/18. 3pp.
- P. Operating license stage documents & correspondence
- 79121001B7 Discusses NRC 791101 meeting w/representatives of NSSS vendors & fuel suppliers re discussion of respective portions of ECGS evaluation models dealing w/fuel cladding swalling & incidence of rupture. Vendor responses encl. EIBENHUT.D. Q. Division of Operating Reactors. 79/11/09. 65pp.
- ---7912100255 Responds to NRC 791101 request re noncompliance of Westinghouse ECCS evaluation model under requirements of 10CFR50 App N. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants. ANDERSON, T. M. Westinghouse Electric Corp. 79/11/02. 4pp.
- --7912100330 Responds to NRC 791101 request re DRNL cladding swelling & rupture data.Review of analytical models & tests indicates compliance w/10CFR50 App K. All QE specs for calculated peak cladding temp remain unchanged.

  BUCHHOLZ, R. H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50. 46 satisfied. OMSLEY, G. F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/02. 5pp.
- --7912100456 Forwards addl info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model.

  No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results.

  OMSERY.O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).

  79/11/04. 22pp.
- 7912140182 Notification of 791127 meeting w/util to discuss proposed design providing second level of undervoltage protection for safety related equipment at facility.
  CLARK.R. Operating Reactors Branch 3. 79/i1/14. 2pp.
- 7912120325 Responds to NRC 791002 ltr re certification of NRC personnel in radiation safety by Oak Ridge Associated Univs.NRC personnel will attend site-specific training & submit annual confirmation of requalification.

  CLOUTIER.R. Philadelphia Electric Co. 79/12/03. 2pp.
- 7912180606 Responds to 791022 ltr re containment purging & venting during normal operation Util will comply w/ "Interim Position for Containment Purge & Vent Valve Operation Pending Resolution of Isolation Valve Operability."

  DALTROFF.S.L. Philadelphia Electric Co. 79/12/11. 2pp.
- 7912280561 Responds to NRC 791214 teicon requesting info re implementation of short-term Lessons Learned Task Force requirements by 800101 Discusses proposed schedule & revisions.
  DALTROFF, S. L. Philadelphia Electric Co. 79/12/21. Spp.

- Q. Inspection reports, IE Bulletins & correspondence
- 7912060033 Ack receipt of 791009 ltr informing NRC of steps taken to correct violations noted in CE Insp Repts 50-277/79-13 & 50-278/79-15. GRIER, D. H. Region 1, Philadelphia, Office of the Director. 79/10/22. 1p.
- --7912080044 Responds to NRC 790917 ltr re violations noted in IE Insp. Repts 50-277/79-13 & 50-278/79-15. Corrective actions: personnel instructed in accurate signing off of surveillance tests & in timely responses to audit rept. DALTROFF.S. L. Philadelphia Electric Co. 79/10/09. App.
- --7912060649 Forwards IE Insp Repts 50-277/79-13 & 50-278/79-15 on 790618-21 & 25-29 & notice of violation.
  GRIER.B.H. Region I. Philadelphia, Office of the Director.
  79/09/17. 3pp.
- --7912060054 Notice of violation from insp on 790618-21 & 25-29.

  \* Region 1. Philadelphia, Office of the Director. 79/09/07.
  3pp.
- ---7912060058 IE Insp Repts 50-277/79-13 & 50-278/79-15 on 790618-21 & 25-29. Noncompliance noted: failure to identify post-valve replacement tost results as unacceptable & to issue timely responses to audit repts.

  JOHNSON, J. MARKOMSKI R., KISTER H. B. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/09/07. 22pp.
- 7912170171 Responds to IE Bulletin 79-23, "Potential Failure of Emergency Diesel Generator Field Exciter Transformer." No connections found which could allow flow of high circulating currents exceeding transformer ratings.

  OALLAOHER.J.W. Philadelphia Electric Co. 79/10/25. 2pp.
- 7912170240 Updates review of seismic analyses for as-built safetyrelated piping per IE Bulletin 79-14, "Seismic Analysis for Safety-Related Piping Sys." DALTROFF, S. L. Philadelphia Electric Co. 79/10/30. 2pp.
- 79:2050:00 Ack receipt of 79:005 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/79-14 & 50-278/79-16. SMITH.G.H. Region 1, Philadelphia, Fuel Facility & Materials Safety Dranch. 79/11/06. 1p.
- ---7912050105 Responds to NRC 790924 itr re violations noted in IE insp Repts 50-277/79-14 & 50-278/79-16. Corrective actions: new shutdown procedure & removal of identified leaking fuel assemblies. DALTROFF: S. L. Philadelphia Electric Co. 79/10/15. 3pp.
- --7912050107 Forwards IE Insp Repts 50-277/79-14 & 50-278/79-14 on 790622 & notice of violation. SMITH O.H. Region 1. Philadelphia. Fuel Facility & Materials Safety Branch. 79/09/24. 2pp.
- --7912050110 Notice of violation from insp on 790622.

  Region 1, Philadelphia, Office of the Director. 79/09/20.
  1p.
- --7912050116 IE Insp Repts 50-277/79-14 & 50-278/79-16 on 790622.
  Noncompliance noted: failure to adhere to Tech Spec
  release rates.
  SERABIAN J. A. ( JACKSON, T. J., STONR, J.P. Region I, Philadelphia,
  Office of the Director. 79/09/20, 4pp.
- 7912200344 Forwards waste packaging Into Rept 79-02A on 790925-26.No noncompliance noted. SUTHERLAND, J. T. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 79/11/07. 2pp.
- ---7912200395 Waste packaging Insp Rept 79-02A No noncompliance noted.

  Major areas inspected:shipping paper & DOT placarding requirements, radiation levels, removable contamination, DOT & NRC package features.

  BROWN R.A. Region 2, Atlanta, Office of the Director. 79/11/06.
  6pp.
- 7912050049 Forwards IE Circular 79-82, "Stroke Times for Power Operated Reliof Valves." No response required. GRIER, 8.M. Region 1. Philadelphia, Office of the Director. 79/11/16. 1p.
- 7912050286 Forwards IE Info Notice 79-27, "Bteam Opperator Tube Ruptures at Two FWR Plants." No response required. ORIER.8.H. Region 1. Philadelphia. Office of the Director. 79/11/16. ip.

- 7912100144 Forwards IE Info Notice 79-28, "Overluading of Structural Elements Due to Pipe Support Loads." No response required. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/11/16. lp.
- 7912110458 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolent Sys Instrumentation During Operation." No specific action or response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director. 79/11/19. 1p.
- 7912050277 Forwards IE Bulietin 79-26, "Boron Loss From BWR Control Blades:" Response required. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/11/20, 1p.
- 7912260109 Ack receipt of 791004 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-277/79-08 & 50-278/79-09.

  MARTIN.W. G. Region 1, Philadelphia, Safeguards Branch. 79/11/21.

  Jp.
- --79122601i5 Forwards IE Insp Repts 50-277/79-08 \$ 50-278/79-09 on 790226.28 \$ 70305-07 & notice of violation. Notice of violation withheld (ref loCFR2. 790).
  HARTIN.W. G. Region 1, Philadelphia, Bafeguards Branch.
  79/09/14. 2pp.
- --7912260119 IE Insp Repts 50-277/79-08 & 50-278/79-09 on 790226,28 & O305-07. Details withheld (ref iOCFR2. 790).

  IAILEY,R. J. LADUN, R. Region 1, Philadelphia, Office of the Director. DEVLIN, J. W. Region 1, Philadelphia, Safeguards Branch. 79/09/14. 2pp.
- 7912060584 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No response required.
  GRIER, B. H. Region 1, Philadelphia, Office of the Director.
  79/11/26. 1p.
- 7912110073 Forwards IE Circular 79-23, "Motor Starters & Contactors failed to Operate." No response required. ORIGE, B.H. Region 1, Philadelphia, Office of the Director, 79/11/26. Ip.
- 7912190063 Forwards IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation." Written response required. ORIER.B.H. Aegion 1, Philadelphia, Office of the Director. 79/11/30. 1p.
- 7912310237 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action required. GRIER, B. H. Region 1. Philadelphia, Office of the Director, 79/12/06. 4pp.
- 7912190761 Forwards IE Oulietin 79-28. "Possible Malfunction of Namco Model EAIBO Limit Switches at Elevated Temps." Written response required. GRIER, B. H. Region 1. Philadelphia. Office of the Director. 79/12/07. 1p.
- 7912280001 Responds to IE Bulletin 79-02. Revision 2. "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts." Where safety factors less than required, supports will be modified.
  DALTROFF, S. L. Philadelphia Electric Co. 79/12/07. 4pp.
- 7912280227 Forwards IE Info Notice 79-31. "Use of Incorrect Amplified Response Spectra." Na written response required. ORIER, B.H. Region 1. Philadelphia, Office of the Director. 79/12/13. 1p.
- R. Periodic operating reports & related correspondence
- 7912140344 Forwards monthly operating repts for Nov 1979. CODNEY, M. J. Philadelphia Electric Co. 79/12/10. ip.
- --7912140359 Monthly operating rapts for Nov 1979. ALDEN, W. N. Philadelphia Electric Co. 79/12/10. 9pp.
- 8. Reportable occurrences, LERs & related correspondence
- 7912180010 RO 3-79-29/1P: on 791019, response to IE Bulletin 79-14 revealed damaged sway strut on C reactor fead pump discharge line. Cause under invastigation. New sway strut will arrive 791023.
  ULLNICH.W. T. Philadelphia Electric Co. 79/10/19. 2pp.

- 7912040295 LER 79-033/03L-0: on 791022. while in cold shutdown for refueling. 3D RHR pump tripped on overcurrent Caused by internal motor fan blade fatigue failure. Stator insulation repaired & hottom fan installed.
  COUNEY. M. J. Philadelphia Electric Co. 79/11/21. 1p.
- 79:2130180 RD-3-79-38/1P: on 79:121.review of 79:117 surveillance test revealed that two MSIVs in steamline A closed in shorter times than specified in Yech Specs. Caused by possible temp effects on hydraulic fluid viscosity.

  ULLRICH, W. T. Philadelphia Electric Co. 79/11/21. ip.
- 7912040405 LER 79-034/OGL-0: on 791101, during surveillance testing, standby liquid control pump relief valve operated below Tech Spec limit. Caused by setpoint drift on JMSK Crosby valve. Valve readjueted within Tech Spec limit. COONEY, M. J. Philadelphia Electric Co. 79/11/28. 1p.
- 7912180504 LER 79-035/03L-0; on 791102 during insp of traveling in core probe sys, whear valves in guide tube assemblies detected installed backwards. Caused by facility const error. Five shear valves removed & properly reinstalled. RODNEY.M. Philadelphia Electric Go. 79/12/03. ip.
- 7912130417 RD-3-79-39/1P, update: on 791130, eight seismic supports inside containment & supporting control rod drive piping line found not to be meismically qualified. Caused by design deficiency. Hods will be completed during outage beginning 791207.

  ULLRICH. W. T. Philadelphia Electric Co. 79/12/04. 2pp.
- 7912180546 LER 79-036/03L-0:on 791108, leak rates exceeded Tech Spec limits. Gaused by debris blocking valve closure. Sealing surfaces cleaned & polished. Valves retested & returned to svc. # Philadelphia Electric Co. 79/12/05. ip.
- 7912180586 Forwards LER 79-038/01T-0. COONEY, M. J. Philadelphia Electric Co. 79/12/06. 2pp.
- --7912180591 LER 79-030/01T-0:on 791120 during raview of surveillance test, two MSIVs in "A" steamline closed in times shorter than specified in Tech Specs. Caused by operator not recognizing fast MSIV closure time. Operator procedure revised.

  COUNEY, M. J. Philadelphia Electric Co. 79/12/06. 1p.
- 7912270393 RO-2-79-52/1P: on 791127, seismic capabilities of concrete block walls on olevation 135 ft reanalyzed as less than required safety factor. Caused by angineering design deficiency. Mod of wall support will raise safety factor. ULLRICH. W. T. Philadelphia Electric Co. 79/12/06. 2pp.
- 7912180644 Forwards LER 79-052/017-0. COONEY, H. J. Philadelphia Electric Co. 79/12/11. 2pp
- --7912180647 LER 79-052/01T-0: on 791127, analysis per IE Info Notice 79-28 revealed four concrete expansion bolts in concrete block walls w/eafety factors of less than four Caused by deficient design. Corrective actions to be completed by 800101. COONEY, M. J. Philadelphia Electric Co. 79/12/11. Ip.
- 7912180956 LER 79-037/03L-0: on 791113, during surveillance testing on red sequence control sys, sequence mode found inoperable. Caused by failure in integrated circuit chip on sequence logic board. Integrated circuit chip was replaced. COONEY, M. J. Philadelphia Electric Co. 79/12/13. 1p.
- 7912270497 Furwards LER 79-039/01T-0. COUNEY, N. J. Philadelphia Electric Co. 79/12/14. 3pp.
- --7912270510 LER 79-039/01T-0: on 791130 engineering review per IE Bullstin 79-02 identified 16 supports associated w/1-inch control rod driveline insert & withdrawal piping as not being seisatically qualified Caused by inadequate design. CODNEY, M. J. Philadelphio Electric Co. 79/12/14. 1p.
- DOCKET 50-280 SURRY FOWER STATION, UNIT 1
- F. Security, medical, emergency & fire protection plans
- 7912040399 Responds to NRC 791010 ltr requesting info re upgrading of sangancy planning. Proposes that response be contingent on NRC review of revised emergency plan. Completion planned prior to May 1980 insp.

  BTALLINGS.C.M. Virginia Electric & Power Co. 79/11/12. 1p.

- 7912200022 Discusses NRC 791109 mooting re emergency preparedness team review objectives. Provides guidance for improving licensee emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.
  GRIMEG.B.K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- 7912050576 Forwards license fee for review of security personnel training & qualification program, submitted in 790817 ltr.
  STALLINGS.C.M. Virginia Electric & Power Co. 79/11/29. 2pp.
- 7912030189 Forwards amended physical security program. Program withheld (ref 10CFR2, 790).
  STALLINGS,C,M. Virginia Electric & Power Co. 79/11/30. 4pp.
- 7912100250 Forwards project status summary re implementation of fire protection mods.
  STALLINOS.C.M. Virginia Electric & Power Co. 79/12/04 2pp.
- G. Adjudicatory correspondence
- 7911300062 Forwards util 791023 ltr & check re NRC 791001 order imposing civil penalties.W/o encl.
  STELLO,V. Office of Inspection & Enforcement, Office of the Director. 79/11/07. 1p.
- 791211003B Confirms receipt of encl 790329 petition to suspend OLs for all PWRs. Forwards FR notice indicating that petition will be treated in accordance w/100FR2. 206.
  DENTON, H.R. Office of Nuclear Reactor Regulation. 79/11/23. 1p.
- --7912110126 Notice of request for action pursuant to 10CFR2.206 re Environ Coalition on Nuclear Power 790329 petition requesting suspension of all OLs for PWRs. MULLER, D. R. Office of Nuclear Reactor Regulation. 79/11/23.
- 7912050069 Order granting extension until 791221 for Commission to determine whether to review 791024 denial of enforcement action.

  CHILK, S. J. Office of the Sacretary of the Commission. 79/11/27.
- 7912190082 Responds to 790911 itr requesting preparation of EIS & hearings re transport of steam generator parts to Richland, WA. DOE exempt from NRC regulation. Environ assessment will be prepared prior to transport.

  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/11/29. 2pp.
- ---7912190088 Requests public hearings & preparation of EIS re proposed transport of radioactive steem generator to Richland, WA. ALLEN, J. North Anna Environmental Coalition. 79/09/11. 1p.
- 7912180536 Discusses NRC 790822 show cause order reanalysis.Pipe support analysis will result in identification of mods & issuance of preliminary design drawings by 791223. School for installation of reasining mods will be submitted 791221. SPENCER, M. G. Virginia Electric & Power Co. 79/12/13. 2pp.
- 7912260367 Order granting extension until E00118 for Commission to elect to review 790201,0421 & 1024 denials of enforcement action.
  CHILK.B. J. Office of the Socretary of the Commission. 79/12/19.
- P. Operating license stage documents & correspondence
- 7911090248 "Summary of Operating Experience W/Recirculating Steam Generators." EIBENHUT.D.C. Division of Operating Reactors. NUREG-0523. 79701/31. 8900.
- 7908010329 Notifies of status of rept on reactor cavity annulus seal.
  Host PHR users romove ring during normal operation. Others
  store seal ring in reised position during normal operation.
  LAINAS, 9. Plant Systems Branch (Fre 791030). 79/07/05. 7pp.
- 77:2050179 Discusses NRC review of LERs & Tech Spec requirements re control RPI sys at Hestinghouse PMRs. Requests Tech Specs review to ensure requirement for rod maint to within +/- 12 steps indicated & RPI sys verified accurate within 12 steps. SCHHENCER. A. Operating Reactors Branch 1. 79/10/29. 7pp.
- 7912170029 Clarifies requirements re control rod position indication sys at Westinghouse PWR, due to existing wide variations of LERs received.

  SCHMENCER, A. Operating Reactors Branch 1. 79/10/29. 3pp.

- --7912170032 Tech Specs for reactivity control sys.

  \* Operating Reactors Branch 1, 79/10/01, 3pp
- --7912170037 Tech Spec for reactivity control sys position imdication
  - sys. \* Operating Reactors Branch 1. 79/03/15. 1p.
- 7912100189 Discusses NRC 791101 meeting w/representatives of NSSS vendors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EISENHUT, D. G. Division of Operating Reactors. 79/11/09. 65pp.
- --7912100255 Responds to NRC 791101 request re noncompliance of Wastinghouse ECCS evaluation model under requirements of 10CFR50 App K. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants.

  ANDERSON.T.M. Westinghouse Electric Corp. 79/(1/02. 4pp.
- ~-7912100330 Responds to NRC 791101 request re ORNL cladding swelling & rupture data. Review of analytical models & tests indicates compliance ω/10CFR50 App K.All GE specs for calculated peak cladding temp remain unchanged.
  BUCHHOLZ, R. H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50.46 satisfied.
  OMBLEY.O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/11/02. Spp.
- --7912100456 Forwards add) info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. OWSLEY, G. F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 22011040 2020. OWSLEY, G. F. Ext 79/11/04. 22pp.
- 7912100171 Ack receipt of 790913 ltr in response to NRC 790525 ltr re soil structure interaction. Bump factor of 1.25 is adequate for seismic stresses for DBE. Equation used to calculate new DBE level is acceptable. EISENHUT, D. G. Bffice of Nuclear Reactor Regulation. 79/11/15. 2pp.
- 7912170132 Requests Class I & II fees re review & approval of security personnel training & qualification plan. Fee for 791001 request due 15 days after receipt of ltr.
  MILLER, M. G. License Fee Management Branch. 79/11/26. 19.
- 7912190200 Summarises 791114 telcon w/util re implementation of Lessons Learned Task Force Licenses proposed schedule for pressurized beaters direct indication of valve position & leak reduction program found unacceptable. NEIGHBORS.D. Operating Reactors Branch 1. 79/11/28. 7pp.
- 7912030201 Requests detailed syllabus for Oak Ridge Associated Univ radiation safety seminar.Lists addl info required prior to reaching final determination of acceptance. STALLINGS, C. M. Virginia Electric & Power Co. 79/11/29. 1p.
- 7912100302 Discusses review of Tech Spec surveillance requirements recentral rad position indication sys. Compliance w/requirement for alignment within 15 inches maintained. Tech Spec change being prepared to ensure proper control of rad maint.

  STALLINGS. C. M. Virginia Electric & Power Co. 79/12/04. 1p.
- 7912180182 Commits to comply w/NRC interim position for containment purge & vent valve operation pending resolution of isolation valve operability, in response to NRC 791023 ltm.
  STALLINGB.C.M. Virginia Electric & Power Co. 79/12/13. 3pp.
- 7912200518 Commits to full implementation of all Category A requirements from TMI-2 Lessons Learned Task Force by 800131 PROFFITT, W. L. Virginia Electric & Power Co. 79/12/17. 1p.
- 7912310390 Responds to NRC 790822 show cause order for reanalysis of pipe supports outside containment structure. Identified 74 mods to be completed 800201 Preliminary design mod drawings issued to field.

  SPENCER, W. C. Virginia Electric & Power Co. 79/12/21. 2pp.
- 7912310499 Requests emend to OL in form of change to auxiliary feedwater sys. Class 1 & III fees encl. STALLINGS, C. M. Virginia Electric & Power Co. 79/12/28. 3pp.

- --7912310506 Revised Pages 3.6-1 through 3.6-3 & 4.8-1 through 4.8-2 to Tech Specs.providing further verification of auxiliary feedwater pumps. \* Virginia Electric & Power Co. 79/12/28. 6pp.
- G. Inspection reports, IE Bulletins & correspondence
- 7912060490 Forwards IE Insp Repts 50~280/79-54 & 50-281/79-76 on 790910-13 & 19-21. No noncompliance noted. MURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/10/23. 2pp.
- --7912060495 IE Insp Repts 50-280/79-54 & 50-281/79-76 on 790913 & 19-21.
  No noncompliance noted Major area inspected; pipe support
  base plate designs using concrete expansion anchor bolts.
  VALLISH.E. J. Region 2, Atlanta, Office of the Director.
  HERDT.A.R. Region 2, Atlanta, Reactor Construction &
  Engineering Support Branch. 79/10/18. App.
- 7912070108 Forwards IE Insp Repts 50~280/79-56 & 50-281/79-74 on 770913-14. No noncompliance noted, MURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/10/24. 2pp.
- --7912070112 IE Insp Repts 50-280/79-56 & 50-281/79-74 on 790913-14.

  No noncompliance noted Major areas inspected concrete expansion anchors & seismic analysis for as-built safety-related piping sys.

  COMPTON.R.M. Repion 2. Atlanta. Diffice of the Director.

  HERDI.A.R. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 79/10/12. App.
- 7912050621 Forwards IE Insp Rept 50-280/79-58 on 790926-28. No noncompliance noted.

  MURPHY.C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/10/25. 2pp.
- --7912050422 IE Insp Rept 50-280/79-38 on 790924-28 No noncompliance noted Major areas inspected: IE Bulletins 79-02 & 79-14, COMPTON.R.M., MODEROS.L. Region 2, Atlanta, Office of the Director. HERDT.A.R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/10/24. Spp.
- 7912060228 Forwards IE Insp Repts 50-280/79-57 & 50-281/79-75 on 790918-21. No noncompliance noted. LEWIS.R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/10/25. 2pp.
- --7912060235 IE Insp Repts 50-280/79-57 & 50-281/79-75 on 790918-21. No noncompliance nuted Major areas inspected: piping support & restraint sys & followup insp.
  WHITENER: H. L. Region 2. Atlanta, Office of the Director.
  BURNETT. P. T. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 79/10/24. App.
- 7912050623 Forwards IE Insp Repts 50-280/79-59 & 50-281/79-78 on 790910-28. No noncompliance noted. LEWIS.R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/10/26. 2pp.
- --7912050424 IE insp Repts 50-280/79-89 & 50-281/79-78 on 790910-28. No noncompliance noted Major areas inspected: plant operations, maint & plant security.

  BURKE, D. J. Region 2. Atlanta, Offics of the Director.

  KELLGOO, P. J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 79/10/25. App.
- 7912200344 Forwards waste packaging Insp Rept 79-02A on 790925-26. No noncompliance noted. SUTHERLAND.J.T. Region 2. Atlanta. Fuel Facility & Materials Bafety Branch. 79/11/07. 2pp.
- --7912200395 Waste packaging Insp Rept 79-02A. No nancompliance noted.
  Major areas inspected: shipping paper & DOT placarding
  requirements, radiation levels, removable contamination, DOT &
  NRC package features.
  BROWN, R. A. Region 2, Atlanta, Office of the Director. 79/11/06.
- 7912100201 Forwards IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads." No response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 79/11/16. ip.
- 7912110987 Forwards IE Info Notice 79-29. "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required. O'RELLLY.J.P. Rogion 2. Atlanta, Office of the Director. 79/11/16. 2pp.

- 7911300140 Forwards IE Bulletin 79-26, "Boron Loss From BWR Control Blades." No response required. D'REILLY.J.P. Region 2. Atlanta, Office of the Director. 79/11/20. 2pp.
- 7912050446 Ack receipt of 791025 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/79-55 & 50-281/79-73.
  LEWIS,R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/11/21. lp.
- --7912050452 Responds to NRC 790926 ltr re violations noted in IE Insp Rapts 50-280/79-55 & 50-281/79-73 Corrective actions:maint staff instructed to follow requirements of radiation work permit & all radiation workers required to sign in. STALLINGS.C.M. Virginia Electric & Power Co. 79/10/25. 2pp.
- --7912030456 Forwards IE Insp Repts 50-280/79-55 & 50-281/79-73 on 790820-0907 & notice of violation.
  LEMIS.R.C. Region 2. Atlanta, Reactor Operations Nuclear Bupport Branch. 79/09/26. 2pp.
- --7912050460 Notice of violation from insp on 770820-0707.

  \* Region 2, Atlanta, Office of the Director. 77/07/24. ip.
- --7912050467 IE Insp Repts 50-280/79-55 & 50-281/79-73 on 790820-0907.
  Noncompliance noted: two welders grinding & welding albow in feedwater line w/o respiratory protection.
  MELLOGO,P.J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. BURKE,D.J. Region 2. Atlanta, Office of the Director. 79/09/24. Spp.
- 7912070007 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No response required.

  0'REILLY,J.P. Region 2, Atlanta, Office of the Director.
  79/11/26. 1p.
- 7912110186 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/26. 1p.
- 7912140538 Responds to IE Bulletin 79-17, Revision I, "Pipe Cracks in Btagnant Borated Water Sys at PWR Plants." Completed special Insp drawings & began visual szamination of Unit 1 sys. STALLINOS.C.M. Virginia Electric & Power Co. 79/11/27. 2pp.
- 7912200097 Responds to IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas," Sound alarms inaudible in 50% of sound layel locations tested. STALLINOS.C.M. Virginia Electric & Power Co. 79/11/29. 3pp.
- 7912190492 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Written response required. O'REILLY.J.P. Region 2. Atlanta. Office of the Director. 79/11/30. ip.
- 7912310330 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/12/06. 5pp.
- 7912200070 Forwards IE Bulletin 79-28. "Possible Malfunction of Names Model EAIBO Limit Switches at Elevated Temps." Action required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/12/07 201
- 7912310280 Responds to IE Bulletin 79-02, Revision 2, "Pipe Bupport.

  Base Plate Designs Using Concrete Expansion Anchor Bolts."

  Five pipe supports on Beismic Category 1 sys in auxiliary

  hidg installed using expension anchor bolts.

  BPENCER.M.C. Virginia Electric & Power Co. 79/12/07. App.
- 7912280441 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required.
  O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
  79/12/13. 2pp.
- 7712240231 Responds to NRC 791126 ltr re violations noted in IE Insp Rept 50-280/79-60; Corrective actions: valves labeled & drawing change requests submitted. BTALLINGS, C.M. Virginia Electric & Power Co. 79/12/19. 3pp.

- 7912260244 Responds to NRC 791123 itr re violation noted in IE Imap Repts 50-280/79-43 & 50-281/79-83 Corrective action: design change on replacement starting contactors completed. BTALLINGS.C.M. Virginia Electric & Power Co. 79/12/19. 2pp.
- 7912260251 Forwards revised response to items of noncompliance identified in IE Insp Repts 50-280/79-08 & 50-281/79-09. STALLINGS.C.M. Virginia Electric & Power Co. 79/12/19. 4p.
- 7912270441 Forwards responses to infractions reported in IE lnsp Repts 50-280/79-61 & 50-281/79-80.

  STALLINGS.C.M. Virginia Electric & Power Co. 79/12/20. 4pp.
- 7912280161 Forwards IE Circular 79-25, "Shock Arrestor Strut Assembly Interference." No written response required.
  O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
  79/12/20, 4pp.
- 7912280494 Forwards response to NRC 791203 itr re violations noted in IE Insp Repts 50-280/79-62 & 50-281/79-82 on 791001-31. Annuciator log procedure established to document safety-related annuciator actuations & rossts.

  BTALLINOB.C.M. Virginia Electric & Power Co. 79/12/26. 4pp.
- R. Periodic operating reports & related correspondence
- 7912140324 Forwards monthly operating repts for Nov 1979. STALLINOS.C.M. Virginia Electric & Power Co. 79/12/12. lp.
- --791214033B Monthly operating repts for Nov 1979. COBTELLO.O.J. Virginia Electric & Power Co. 79/12/04. 45pp.
- 8. Reportable occurrences, LERs & related correspondence
- 7912200423 PNS-II-79-003: on 791010. criminal trial began on individuals who publicly admitted responsibility for damage of new fuel assemblies in storage at facilities. NRC unsuccessful at interviewing individuals re operational & security problems. ALDERSON.C.E., KELLOGO.P.J. Region 2. Atlanta. Office of the Director. 79/10/10. ip.
- 7912210045 PND-II-79-015: on 791024, facility achieved criticality & is at 50% power on 791025. Unit had been shut down for seismic reanalysis of safety related piping. ELROD. 8. A. . KELL000, P. J. Region 2, Atlanta. Office of the Director. 79/10/25. ip.
- 7912110387 Forwards updated LER 79-024/01X-1. STALLINGS, C.M. Virginia Electric & Power Co. 79/12/07. 1p.
- --7912110390 Updated LER 79-026/01X-1: on 790829. Westinghouse told util of possible failure of certain control sys, previously assumed to remain "as is." to fail under adverse environ conditions. FBAR reviewed. Present analyses unaffected.
  STEWART. W. L. Virginia Electric & Power Co. 79/12/07. App.
- 7912140432 Forwards LER 79-037/03L-0.
  BTALLINOS, C.M. Virginia Electric & Power Co. 79/12/11. 1p.
- --7912140442 LER 79-037/03L-0: on 791119, during normal operation, heat tracing circuit 13A (panels B & 9) I & 2 boron injection recirculation-to-boric acid tanks failed Caused by overheating of heat tracing tape. Tape replaced.

  BIEWART, M. J. Virginia Electric & Power Co. 79/12/11. 2pp.
- 7912140466 Forwards LER 79-031/03L-0. BTALLINGS.C.M. Virginia Electric & Power Co. 79/12/11. ip.
- --7912140477 LER 79-031/03L-0: on 791117; liquid wasts containing isotope greater than 1. 5E-03 UCi/cc was released. Caused by personnel error. Water releases for Nov were checked & verified.

  Personnel involved advised to fill out forms carefully.

  BTEWART, W. L. Virginia Electric & Power Co. 79/12/11. 2pp.
- 7912140386 Forwards LER 79-036/01T-0. STALLINGS, C. M. Virginia Electric & Power Co. 79/12/12. 1p.
- --7912140394 LER 79-036/017-0: on 791128 during unit operation util notified by engineer that error in current containment depressurization analysis assumed spray effectiveness values too high Caused by incorrect application of approved model.

  \* Virginia Electric & Power Co. 79/12/12. 2pp.
- 7912270307 Forwards LER 79-034/017-0. STALLINGS.C.M. Virginia Electric & Power Co. 79/12/20. ip.

- --7912270311 LER 79-034/01T-0: on 791207, during reanalysis, discovered that when radiation alarm setpoint is reached in discharge line of air ejectors of Units 1 & 2, trip valves divert air to containment. Caused by walve design contrary to FSAR.

   Virginia Electric & Power Co. 79/12/21. 2pp.
- 7912270847 Forwards LERS 79-033/03L-0 & 79-035/03L-0. STALLINGS.C.M. Virginia Electric & Power Co. 79/12/20. ip.
- --7912270560 LER 79-033/03L-0: on 791127, during normal operation, personnel observed reduction in flow & pressure in charging pump svc water subsys. Caused by broken stem on 1-SM-107, w/valve disc partially blocking pump supply. Valve replaced.

  \* Virginia Electric & Power Co. 79/12/21. 2PP.
- --7912270592 LER 79-035/03L; on 791127, during normal operation, routing surveillance revealed failure of heat tracing circuit 28 (panel 8). Unit I suction piping to boric acid transfer pump 1-CH-P-2A. Caused by water damage. Heat tape replaced.

   Virginia Electric & Power Co. 79/12/21. 2pp.

#### DOCKET 50-281 SURRY POWER STATION, UNIT 2

- F. Security, medical, emergency & fire protection plans
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives. Provides guidance for improving licensee emergency preparedness & assuring capability of office agencies to take appropriate emergency actions.
  GRIMES, B. K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- 79:2050576 Forwards license fee for review of security personnel training & qualification program, submitted in 790817 ltr. STALLINGS, C. M. Virginia Electric & Power Co. 79/11/29. 2pp.
- 7912030189 Forwards amended physical security program Program withheld (ref 10CFR2.790). STALLINGS.C.M. Virginia Electric & Power Co. 79/11/30. 4pp.
- 7912100250 Forwards project status summery re implementation of fire protection mode. STALLINGS.C.M. Virginia Electric & Power Co. 79/12/04. 2pp.

### Adjudicatory correspondence

- 7912110038 Confirms receipt of encl 790329 patition to suspend DLs for all PWRs. Forwards FR notice indicating that petition will be treated in accordance w/10CFR2.206. DENION.H.R. Office of Nuclear Reactor Regulation. 79/11/23. ip.
- --7912110126 Notice of request for action pursuant to 100FR2.206 re Environ Coalition on Nuclear Power 790329 petition requesting suspension of all OLs for PMRs. MULLER, D. R. Office of Nuclear Reactor Regulation. 79/11/23.
- 7912050069 Order granting extension until 791221 for Commission to determine whether to review 791024 denial of enforcement action.
  CHILA.S. J. Office of the Secretary of the Commission. 79/11/27.
- 79121900B2 Responds to 770911 ltr requesting preparation of EIS & hearings re transport of steam generator parts to Richland. WA. DCE exempt from NRC regulation. Environ assessment will be prepared prior to transport.

  DENTON. H. R. Office of Nuclear Reactor Regulation. 79/11/29, 2pp.
- --7912190088 Requests public hearings & preparation of EIS re proposed transport of radioactive steam generator to Richland, HA.
  ALLEN. J. North Anna Environmental Coalition. 79/09/11. lp.
- 79.12260367 Order granting extension until 800118 for Commission to elect to review 790201.0421 & 1024 denials of enforcement action. CHILM.S. J. Office of the Secretary of the Commission. 79/12/19:
- P. Operating license stage documents & correspondence
- 7911090248 "Summary of Operating Experience W/Recirculating Steam Generators." EISEMHUT.D.O. Division of Operating Reactors. NURE9-0923. 79/01/31. B7pp.

- 7912050199 Discusses NRC review of LERs & Tech Spec requirements re control RPI sys at Westinghouse PWRs. Requests Tech Specs review to ensure requirement for rod maint to within +/- 12 steps indicated & RPI sys verified accurate within 12 steps. SCHWENGER.A. Operating Reactors Branch 1. 79/10/29. 7pp.
- 7912170029 Clarifies requirements re control red position indication sys at Hestinghouse PMR, due to existing wide variations of LERs received.

  SCHMENCER, A. Deerating Reactors Branch 1, 79/10/29, 3pp.
- --7912170032 Tech Specs for reactivity control sys.

  \* Operating Reactors Branch 1, 79/10/01. 3pp.
- --7912170037 Tech Spec for reactivity control sys position indication sys.

  # Operating Reactors Branch 1. 79/03/15. ip.
- 7712100187 Discusses NRC 791101 meeting w/representatives of NSSS vendors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EISENHULD. G. Division of Operating Reactors. 79/11/09. 65pp.
- --7912100255 Responds to NRC 791101 request re noncompliance of Westinghouse ECCS evaluation model under requirements of IOCFR50 App K. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants.
  ANDERSON, T.M. Westinghouse Electric Corp. 79/11/02. App.
- --7912:100030 Responds to NRC 791101 request re DRNL cladding swelling & rupture data. Review of analytical models & tests indicates compliance w/10CFR50 App K.All GE specs for calculated peak cladding temp remain unchanged.

  BUCHHOLZ.R.H. General Electric Co. 79/12/07. 2pp.
- ---7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50. 46 satisfied.
  OMSERY.G.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/02. 5pp.
- --7912100496 Forwards add1 info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model.

  No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results.

  OMSELEY, O.F. Exxon Nuclear Co. . Inc. (subs. of Exxon Corp.).

  79/11/04. 22pp.
- 79:2100171 Ack receipt of 790913 ltr in response to NRC 790525 ltr resoil structure interaction. Bump factor of 1.25 is adequate for seismic stresses for GBE. Equation used to calculate new GBE level is acceptable.

  EISENHUT, D. Q. Office of Nuclear Reactor Regulation. 79/11/15. 2pp.
- 7912170132 Requests Class I & II fees re review & approval of security personnel training & qualification plan. Fee for 791001 request due 15 days after receipt of ltr.
  MILLER, H. D. License Fee Management Branch. 79/11/26. ip.
- 7912180346 Forwards draft input for steam generator tubs failure safety evaluations, Sections 2. 1.3.2.2.3, 2.3.3 & 2.4.3. Input for Doel Unit 2 reactor in Selgium enci.
  SCHWENCER, A. Operating Reactors Branch 1. 79/11/28. 1p.
- --7912180354 Draft input for steam generator tube safety evaluation. Section 2.2.3. \* Office of Nuclear Reactor Regulation. 79/11/28. 4pp.
- 7912190200 Summarizes 791116 telcon w/util re implementation of Lessons Learned Task Force.Liconsee proposed schedule for pressurized beaters, direct indication of valve position & leak reduction program found unacceptable. NEIGHBORS, D. Operating Reactors Branch 1, 79/11/28, 7pp.
- 7912030201 Requests detailed syllabus for Oak Ridge Associated Univradiation safety seminar.Lists addl info required prior to reaching final determination of acceptance.

  BTALLINGS, C.M. Virginia Electric & Power Co. 79/11/29. ip.
- 7912100302 Discusses review of Tech Spec surveillance requirements re control rod position indication sys. Compliance w/requirement for alignment within 15 inches maintained Tech Spec change being prepared to ensure proper control of rod maint. STALLINGS, C.M. Virginia Electric & Power Co. 79/12/04. ip.

- 7912:B0:62 Commits to comply w/NRC interim position for containment purge & vent valve operation pending resolution of isolation valve operability, in response to NRC 791023 itr.
  BTALLINGS,C.M. Virginia Electric & Power Co. 79/12/13. 3pp.
- 7912200518 Commits to full implementation of all Category A requirements from TMI-2 Lessons Learned Task Force by 800131. PROFFITT, W.L. Virginia Electric & Power Co. 79/12/17. 1p.
- 7912310499 Requests emend to OL in form of change to auxiliary feedwater sys.Class I & III fees enci. STALLINGS,C.M. Virginia Electric & Power Co. 79/12/28. 3pp.
- --7912310506 Revised Pages 3.6-1 through 3.6-3 & 4.8-1 through 4.8-2 to Toch Specs, providing further verification of auxiliary feedwater pumps. \* Virginia Electric & Power Co. 79/12/28. 6pp.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912060490 Forwards IE Insp Repts 50-280/79-54 & 50-281/79-76 on 790910-13 & 19-21. No noncompliance noted.
  MURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/10/23. 2pp.
- --7912060495 IE Insp Repts 50-280/79-54 & 50-281/79-76 on 790913 & 19-21.
  No noncompliance noted Major area inspected; pipe support base plate designs using concrete expansion anchor bolts.
  VALLISH, E. J. Region 2, Atlanta, Office of the Director.
  HERDT.A.R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/10/18. App.
- 7912070109 Forwards IE Insp Repts 50-280/79-56 & 50-281/79-74 on 790913-14.No noncompliance noted.
  MURPHY.C.E. Region 2. Atlenta, Reactor Construction & Engineering Support Branch. 79/10/24. 2pp.
- --7912070112 IE Insp Repts 50-280/79-56 & 50-281/79-74 on 790913-14.

  No noncompliance noted Major areas inspected:concrete expansion anchors & seismic analysis for as-built safety-related piping sys.

  CCMPTON,R.M. Region 2. Atlanta, Office of the Director.

  MERDI,A.R. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/10/12. 4pp.
- 7912050550 Forwards 1E Insp Rept 50-281/79-77 on 791002-05.No nancompliance noted, MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/10/25. 2pp.
- --7712050555 IE Insp Rept 50-281/79-77 on 791002-05. No noncompliance noted Major areas inspected auxiliary bldg, steam generator replacement & observation of welding.
  KLEINSCROE, W. P. Region 2. Atlanta, Office of the Director.
  HERDI, A. R. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/10/24. 6pp.
- 7912040228 Forwards IE Insp Repts 50-280/79-57 & 50-281/79-75 on 790918-21.No noncompliance noted. LEWIS.R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/10/25. 2pp.
- --7912060235 IE Insp Repts 50-280/79-57 & 50-281/79-75 on 790918-21.No noncompliance noted Major areas inspected piping support & restraint sys & followup insp.

  HHITENER, H. L. Region 2, Atlanta, Office of the Director.

  BURNETT, P. T. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/10/24. 4pp.
- 7912050623 Forwards IE Insp Repts 30-280/79-59 & 50-281/79-7B on 790910-28. No noncompliance noted. LENIB.R.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 79/10/26. 2pp.
- --7912050624 IE Insp Repts 50-280/79-59 & 50-281/79-78 on 790910-28 No nancompliance noted Major areas inspected plant operations, maint & plant security.
  BURKE.D. J. Region 2: Atlanta, Office of the Director.
  KELLOGO.P. J. Region 2, Atlanta, Reactor Operations Nuclear Bupport Branch. 79/10/25. App.
- 7912200344 Forwards waste packaging Insp Rept 79-02A on 790928-26. No noncompliance noted. BUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/11/07. 2pp.

- --7912200395 Waste packaging Insp Rept 79-02A No noncompliance noted.
  Major areas inspected:shipping paper & DOT placarding requirements:radiation levels:removable contamination.DDT & NRC package features.
  BROWN.R.A. Region 2. Atlanta, Diffice of the Director.
  POTTER, J.P. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 79/11/06. 4pp.
- 7912310107 Forwards IE Insp Rept 50-281/79-72 on 790827-30.No noncompliance noted. MURPHY.C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/11/08. 2pp.
- --7912310115 IE Insp Rept 50-281/79-72 on 790827-30. No noncompliance noted Major areas inspected: QC records for main steam elbows & modified steam water nozzles & welding & radiography of main steam piping.

  ERD, C. M. Region 2. Atlants. Office of the Director.

  DANIELSON, D. H., HERDI. A. R. Region 2. Atlants. Reactor Construction & Engineering Support Branch. 79/11/07. 4pp.
- 7912310349 Forwards IE Insp Rept 50-281/79-79 on 791015-19.No noncompliance noted. LEWIS.R.C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 79/11/14. ip.
- --7912310353 IE Insp Rept 50-281/79-79 on 791015-19. No noncompliance noted Major areas inspected: containment leakage rate tasting & pipe support & restraint sys.

  MHITENER.H.L., BRODKS.E.H. Region 2, Atlanta, Office of the Director. BURNETT.P.T. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/11/07. 4pp.
- 7912100201 Forwards 1E Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads," No response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/16. 1p.
- 7912110587 Forwards IE Info Notice 79-27, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/16. 2pp.
- 7912050446 Ack receipt of 791025 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/79-55 & 50-281/79-73. LENIS,R.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 79/11/21. 1p.
- ---7912050452 Responds to NRC 790926 ltr re violations noted in IE Insp Repts 50-280/79-55 & 50-281/79-73. Corrective actions: maint staff instructed to follow requirements of radiation work permit & all radiation workers required to sign in. BTALLINGS, C. M. Virginia Electric & Power Co. 79/10/25. 2pp.
- --7912050456 Forwards IE Insp Repts 50-280/79-55 & 50-281/79-73 on 790820-0907 & natice of violation. LEWIS.R.C. Region 2: Atlanta. Reactor Operations Nuclear Bupport Branch. 79/09/26. 2pp.
- --7912050440 Notice of violation from insp on 790820-0907.

  \* Region 2, Atlanta, Office of the Director. 79/09/24. 1p.
- --7912050467 IE Insp Repts 50-280/79-55 & 50-281/79-73 on 790820-0907.
  Noncompilance noted:two welders grinding & welding albow in feedwater line w/o respiratory protection.
  KELLOOG.P.J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. BURKE.D.J. Region 2. Atlanta, Office of the Director. 79/09/24. 5pp.
- 7912070007 Forwards IE Circular 79-24, "Proper Installation & Calibr of Gore Spray Pipe Break Detection Equipment on BMRs." No response required.

  O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
  79/11/26. ip.
- 7912110186 Forwards JE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. O'REILLYJ, P. Region 2, Atlanta, Office of the Director. 79/11/26. ip.
- 7912140530 Responds to IE Bulletin 79-17, Revision i. "Pipe Cracks in Stagnant Borated Water Sys at PMR Plants." Completed special insp drawings & began visual examination of Unit 1 sys. STALLINGS, C. M. Virginia Electric & Power Co. 79/11/27. 2pp.

- 7712200077 Responds to IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas," Sound alarms inaudible in 50% of sound level locations tested. STALLINGS.C.M. Virginia Electric & Power Co. 79/11/29. 3pp.
- 7712190492 Forwards 1E Bulletin 79-27, "Loss of Non-Class 1E Instrumentation & Control Power Bys Bus During Operation." Written response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Birector. 79/11/30. 1p.
- 7912310330 Forwards IE info Notice 79-30. "Reporting of Defects & Noncompliances:10CFR21." No action required. O'RETLLY.J.P. Region 2, Atlanta, Office of the Director. 79/12/06. Spp.
- 7912200070 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. 0'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/12/07. 2pp.
- 7912310280 Responds to IE Dulletin 79-02. Revision 2. "Pipe Support Dase Plate Designs Using Concrete Expansion Anchor Bolts."
  Five pipe supports on Seismic Category I sys in auxiliary bldg installed using expansion anchor bolts.

  SPENCER. W. C. Virginia Electric & Power Co. 79/12/07. App.
- 7912280441 Forwards IE info Natice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required, 0'AELLUTUP. Region 2, Atlanta, Office of the Director. 79/12/13. 2pp.
- 7912200378 Forwards results of feetwater sys piping insps.in response to IE Bulletin 79-13.Revision 2 re cracking in feedwater piping. STALLINGS.C.M. Virginia Electric & Power Co. 79/12/17. 4pp.
- 7912260244 Responds to NRC 791123 ltr re violation noted in 1E Insp Repts 50-280/79-63 & 50-281/79-83 Corrective action: design change on replacement starting contactors completed. STALLINGS.C.M. Virginia Electric & Power Co. 79/12/19. 2pp.
- 7912260251 Forwards revised response to items of nancompliance identified in IE Insp Repts 50-280/79-08 & 50-281/79-09. STALLINGS.C.M. Virginia Electric & Power Co. 79/12/19. 4p.
- 7912270441 Forwards responses to infractions reported in IE Insp Repts 50-280779-61 & 50-281779-80.
  STALLINGS.C.M. Virginia Electric & Power Co. 79/12/20. 4pp.
- 7912280661 Forwards 1E Circular 79-25, "Shock Arrestor Strut Assembly Interference." No written response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/12/20. 4pp.
- 7912280490 Forwards response to NRC 791205 ltr re IE Insp Rept 50-281/79-81 on 791031-1102.Feedwater & reactor coolant pumps inspected for damage. Employees Instructed in proper use of rigging operation.
  STALLINGS.C.M. Virginia Electric & Power Co. 79/12/26. 3pp.
- 7912280494 Forwards response to NRC 791203 itr re violations noted in IE Insp Repts 50-200/79-62 & 50-201/79-82 on 791001-31. Annuclator log procedure established to document safety-related annuclator activations & resots.

  STALLINGS.C.M. Virginia Electric & Power Co. 79/12/26. 4pp.
- R. Periodic operating reports & related correspondence
- 7912140324 Forwards monthly operating repts for Nov 1979. STALLINGS.C.M. Virginia Electric & Power Co. 79/12/12. ip.
- --7912140338 Monthly operating repts for Nov 1979. COBTELLO.O. J. Virginia Electric & Power Co. 79/12/04. 45pp.
- S. Reportable occurrences, LERs & related correspondence
- 7912200423 PNS-II-79-003: on 791010, criminal trial bugan on individuals who publicly admitted responsibility for damage of new fuel assemblies in storage at facilities. NRC unsuccessful at interviewing individuals re operational & security problems.
  ALDERSON, C. E., KELLOGG, P. J. Region 2, Atlanta, Office of the Director. 79/10/10, 1p.

- DOCKET 50-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT 1
  F. Security, medical, emergency & fire protection plans
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives. Provides guidance for improving licensee emergency preparedness & assuring capability of affeite agencies to take appropriate emergency actions.

  GRIMES, N. K. Emergency Preparedness Task Force. 79/11/23. 30pp-
- 7912120244 Forwards evaluation of electrical & mechanical penetration seals & fire detectors required by 790906 fire protection safety evaluation rept.

  MAYER.L.D. Northern States Power Co. 79/11/30. 54pp.
- Adjudicatory correspondence
- 791211003B Confirms receipt of encl 790329 petition to suspend OLs for all PWRs.Forwards FR notice indicating that petition will be treated in accordance w/10CFR2, 206.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/23. 1p.
- --7912110126 Notice of request for action pursuant to 10CFR2.206 re Environ Coalition on Nuclear Power 790329 patition requesting suspension of all OLs for PWRs. MULLER D.R. Office of Nuclear Reactor Regulation. 79/11/23.
- P. Operating license stage documents & correspondence
- 7911090248 "Summary of Operating Experience H/Recirculating Steam Generators." EIBENHUT.D.G. Division of Operating Reactors. NURE9-0523. 79/01/31. 874p.
- 7908010337 Notifies of status of rept on reactor cavity annulus smal.

  Most PMR users remove ring during normal operation. Others
  store smal ring in raised position during normal operation.

  LAINAS. Q. Plant Systems Branch (Pre 791030). 79/07/05. 7pp.
- 7912040164 Discusses NRC concerns re containment purging & venting during normal operations. Includes licenses override of safety actuation isolation signals to containment isolation valves & valve ability to shut u/a degrading containment. BCHMENCER.A. Operating Reactors Branch 1, 79/10/29, 5pp.
- 7912050176 Discusses NRC review of LERs & Tech Spec requirements recentral RPI sys at Westinghouse PMRs. Requests Tech Specs review to ensure requirement for rad maint to within +/- 12 steps indicated & RPI sys verified accurate within 12 steps. SCHMENCER, A. Operating Reactors Branch 1, 79/10/29, 7pp.
- 7912100189 Discusses NRC 791101 meeting w/representatives of NRSE vendors & fuel suppliers re discussion of respective portions of ECCE evaluation models dealing wfuel cladding swelling & incidence of rupture. Vendor responses encl. EISENHUT, D. Q. Division of Operating Reactors. 79/11/09. 65pp.
- --7912100255 Responds to NRC 791101 request re noncompliance of Wastinghouse ECCS evaluation model under requirements of 10CFR50 App K. Evaluation of three fuel rod models indicates no safety problems for Wastinghouse plants.
  ANDERSON, T. M. Westinghouse Electric Corp. 79/11/02. App.
- ---7912100330 Responds to NRC 791101 request re DRML cladding swelling & rupture data. Review of analytical models & tests indicates compilance w/100FR30 App K. All QE specs for calculated peak cladding temp remain unchanged.
  BUCHHOLZ.R.H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models t that analyses demonstrate all criteria of 10CFR50.46 satisfied.

  DMSLEY, 0.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/11/02. 5pp.
- ---7912100455 Forwards add1 info re evaluation of impact of NRC proposes rupture/blockage model used in vendor evaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. OBSECP.0.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/04. 22pp.
- 7912120103 Notification of 791126 meeting w/util in Betheeda.MD to discuss reactor vessel nozzle fabrication. GROTENHUIS.M. Operating Reactors Branch 1. 79/11/19. 2pp.

- 7912040201 Confirms implementation of interim procedural solution adopted at 791119 meeting w/NRC.Westinghouse & util repossible rod drop accident analysis for certain Westinghouse designed plants.

  MAYER.L.O. Northern States Power Co. 79/11/27. ip.
- 7912180346 Forwards draft input for steam generator tube failure safety evaluations, Sections 2.1, 3,2,2,3,2,3,8,2,4,3, Input for Doel Unit 2 reactor in Belgium encl.
  SCHMENGER, A. Operating Reactors Branch 1, 79/11/28, ip.
- --7912180358 Draft input for steam generator tube failure safety evaluation Section 2.4.3. \* Office of Nuclear Reactor Regulation. 79/11/28. 3pp.
- 7912110307 Responds to NRC 791029 ltr re control rod misalignment specs. License amend request re spec changes will be submitted by 800115.
  MAYER, L. O. Northern States Power Co. 79/12/05. ip.
- 7912200083 Forwards update to 790731 meteorological evaluation for fuel handling accident inside containment. Further changes may be necessary.
  HULMAN.L.G. Hydrology Meteorology Branch. 79/12/07. 2pp.
- 7912210008 Summary of 791124 meeting w/Westinghouse & util re-base metal cracking in reactor vessel nozzles under stainless steel ciadding.
  ORDTENHUIB.H. Operating Reactors Branch 1, 79/12/12. 4pp.
- --7912210013 Discusses pipe leak at TVD 1, in Finland, due to faulty fabrication process of components mfg in France & significance to US plants. DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/24.
- 7912200432 Notifies that util will be in comptiance by 800131 w/Lessons Learned Task Force recommendations re relief & safety valves direct position indication & inadequate core cooling detection instrumentation.

  MAYER.L.O. Northern States Power Co. 79/12/14. 2pp.
- 7912200385 Notifies NRC that util cannot meet 781025 schedule for resolving issue of asymmetric LOCA loads due to delays in matl procurement Pips restraints will be installed during refueling outage.

  MAYER.L.O. Northern States Power Co. 79/12/17. 1p.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912050401 Forwards IE Insp Repts 50-282/79-23 & 50-306/79-19 on 790917-30. No noncompliance noted. HEISHMAN.R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/10/26. 2pp.
- --7912050406 IE Insp Repts 50-282/79-23 & 50-306/79-19 on 790917-30. No noncompliance noted Major areas inspected maint, security, review, audit & radiation protection.
  FEIERABEND.C. D., WARNICK, R. F. Region 3, Chicago, Office of the Director, 79/10/22. 3pp.
- 7912260102 Forwards IE Insp Rept 50-282/79-26 on 791002-03.No noncompliance noted.
  HEIBHMAN.R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/11/06. 2pp.
- --7912260105 IE Insp Rept 50-282/79-26 on 791002-03 No noncompliance noted Major areas inspected: steam generator tube rupture. WARNICK.R.F., CHOULES, N.C., OESTMANN, M.J. Region 3, Chicago, Dffice of the Director, 79/11/05. Spp.
- 7912050144 Forwards IE Circular 79-22, "Stroke Times for Power Operated Reliaf Valves." No response required. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/16. ip.
- 7912100239 Forwards IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads." No response required. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912110585 Forwards IE Info Notice 77-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action on response required.

  KEPPLER, J. C. Region 3, Chicago, Office of the Director. 79/11/16.

- 7912210066 Forwards IE Insp Repts 50-202/79-27 & 50-306/79-21 on 791001-31.No noncompliance noted. HEISHMAN.R.F. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 79/11/16. 2pp.
- --7912210074 IE Insp Repts 50-282/79-27 & 50-306/79-21 un 791001-31 No noncompliance noted Major areas inspected plant operations, maint, security & observations of plant staff response to steam generator tube rupture. FEIERABEND.C.D., MARNICK.R.F. Region 3, Chicago, Office of the Director. 79/11/13. 9pp.
- 7912050404 Forwards IE Bulletin 79-26, "Boron Loss From BWR Control Blades." No response required. KEPPLER. J. O. Region 3, Chicago, Diffice of the Director. 79/11/20.
- 7912100440 Ferwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No written response required.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/26.
- 7912140216 Forwards IE Circulor 79-23. "Motor Starters & Contactors Failed to Operate." No written response required.
  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/26.
- 7912110433 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general afcs copies of escalated enforcement correspondence sent by NRC to licensees.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/28.
- 7912190801 Responds to IE Bulletin 79-17, Revision 1. Insp per Item 2 (b) to begin 791203 for Unit 2 & end in two wks. Unit 1 insp scheduled for Aug 1980.

  HACHTER, L. J. Northern States Power Co. 79/11/28. 1p.
- 7912050467 Ack receipt of 791031 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-282/79-21 & 50-306/79-18.
  HEISHMAN.R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/11/30. 1p.
- --7912050471 Responds to NRC 791009 ltr re violations noted in IE lnsp Repts 50-282/79-21 & 30-304/79-18. Corrective actions: Design Change 771397 Forms w/required initials completed WACHTER.L. J. Northern Etates Power Co. 79/10/31. 3pp.
- 7912190231 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Dus During Operation." Hritten response required. KEPPLER, J. C. Region 3, Chicago, Office of the Director. 79/11/30.
- 7912070434 Forwards "Inservice Insp.Examination Summary, 791003-14. Insp. Period 2. Steam Generator Tube Eddy Current Exam." MAYER. L. U. Northern States Power Co. 79/12/04. 1p.
- --7912070440 "Inservice Insp.Examination Summary,791003-16, lnsp Period 2, Steam Generator Tube Eddy Current Exam." HANSEN, D. B., DAHLMAN, L. Northern Btates Power Co. 79/11/07.
- 7912140093 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action or response required.

  KEPPLER, J. O. Region 3. Chicago, Office of the Director. 79/12/04.
- 7912280067 Responds to IE Bulletin 79-02. Revision 2. "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts." All Seismic Category I restraints that use concrete expansion anchors were field verified.
  WACHTER.L. J. Northern States Power Co. 79/12/07. 2pp.
- 7912200134 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/12/10.
- 7912280041 Responds to IE Bulletins 78-12.78-12A & 78-12B. "Short Period Scrams at DHR Facilities." No deviations found in welding math used in vessels. WACHTER.L.J. Northern States Power Co. 79/12/11. 2pp.

### R. Periodic operating reports & related correspondence

- 7912180620 Forwards monthly operating rept for Nov 1979 & corrections to wonthly operating repts for Aug. Sept & Oct 1979.
  MAYER.L.O. Northern States Power Co. 79/12/12. Ip.
- --7912180628 Monthly operating rept for Nov 1979. HUNSTAD A.A. Northern States Power Co. 79/12/01. Bpp.
- --7912180634 Revised page of conthly operating rept for Aug 1979. HAMSTAD.A.A. Northern States Fouer Co. 79/12/01. 1p.
- ---7912180636 Revised page of monthly operating rept for Sept 1979. HUNSTAD.A.A. Northern States Power Co. 79/12/01. 1p.
- ---7912180640 Revised page of wonthly operating rept for Oct 1979. HUNSTAD.A.A. Northern States Power Co. 79/12/01. lp.

## S. Reportable occurrences. LERs & related correspondence

- 7912070135 PNO-III-79-024: on 791026, Region 3 notified of chlorine treatment of cooling tower water containing annels encephalitis Licensee will monitor discharges & subsit environ event rept to NRC.
  DESITIANN.N.J., ESSIG.T.H. Region 3, Chicago, Office of the Director. 79/10/25. 2pp.
- 7912050593 PNO-III-79-035:on 791007, neutralizing tank batch released ph greater than Tech Spec limit Caused by improper eperation of ph monitor on tank effluent pipe. Hemo issued requiring reliable operation of monitor. DESIMANN. M. J. Region 3. Chicago, Effice of the Director. 79/11/05. 2pp.
- 7912170423 PNO-III-79-39: on 791115, reactor tripped. Caused by failure of feedwater puop 12 supplying water to steam generators. Puop 11 was shipped to vendor for rewinding due to similar failure Reactor in process of cold shutdown. WARNICK.R.F. HEISHMAN.R.F. Region 3, Chicago, Office of the Director. 79/11/15. 1p.
- 7912070332 Environ Event Rept 79-11 for 17 days in Nov. Blowdown flow in excess of Tech Specs required to complete special chlorination treatment authorized by 79102 FIS change. WARDLE C. Northern States Power Co. 79/12/03. lp.
- 7912280568 Forwards Westingbouse evaluation of 791002 tube rupture event. Concurs w/util recommendations in LER 79-027/017-0 re operation of turbine driven auxiliary feed pump & steam supply valve from faulted steam generator.

  ANDERSON T M. Westinghouse Electric Corp. 79/12/19. 17pp.
- 7912270491 Forwards LER 79-030/03L-0.
  MAYER, L. O. Northern States Power Co. 79/12/21. 1p.
- ---7912270498 LER 79-030/03L-0: on 791121; during insps per IE Bulletins 79-14 & 79-02; two snubbers in cooling water sys found incorrectly installed & one hanger in auxiliary feedwater sys found damaged. Repairs were made immediately. HARSTAD.A.A. Northern States Power Co. 79/12/21. 1p.
- 7912310475 Forwards LER 79-031/03L-0.
  MAYER, L. D. Northern States Fower Co. 79/12/26. 1p.
- --7912310478 LER 79-031/03.-0: on 791126 during periodic surveillance program review.discovered that SP1022 boric acid tank level test not performed within tolerance band. Caused by personnel oversight. Instrumentation & control schedule to be used. HARSTAD.A. A. Northern States Power Co. 79/12/26. lp.

### DOCKET 50-284 IDAHO STATE UNIV. RESEARCH REACTOR

# F. Security, medical, emergency & fire protection plans

7912120206 Forwards Graft Reg Guide 5.XX. "Std Format & Content for Licensee Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance." W/o encl. REID.R.H. Dperating Reactors Branch 4 (Pre 791030). 79/08/22.

#### DOCKET 50-285 FORT CALHOUN STATION, UNIT 1

- F. Security, medical, emergency & fire protection plans
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives. Provides guidance for improving licensee emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions. CRIMES, B.K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- 7912190588 Forwards quantitative repts re offects of fire water piping rupture on safety-related equipment. Description of water curtain for fire Areas 6 & 20 & drawings encl. Drawings available in Central Files only.

  JONES, M. C. Omaha Public Power District, 79/12/12. 13pp.

### C. Adjudicatory correspondence

- 7912050599 Reply by Metropolitan Area Planning Agency in opposition to applicant consolidated answer objecting to request for hearing. Public concerns re facility mods should be heard. Questions util credibility. Certificate of Svc encl. KINSHEN.A.H. Metropolitan Area Planning Agency Omaha.NE. AIRSHEN.A.H. Kirshen. A.H. 79/10/30. 9pp.
- 7912060612 Motion to strike applicant answer to Metropolitian Area Planning Agency request for hearing. Alleges that util failed to comply w/100FA2. 705. Questions LeBoeuf, Lamb. Limby & MacRae authority to resist hearing. Certificate of Svc encl. KIRSHEN. A. H. Hetropolitan Area Planning Agency Dmaha, NE. KIRSHEN. A. H. Kirshen, A. H. 79/10/30. 3pp.
- 79(2130074 Seeks denial of AH Kirshen & Metropolitan Area Planning Agency 791030 motion to strike applicant 791023 answer to hearing request Applicants response complies w/code requirements re determination of petitioners rights. ORAY, J.R. Hearing Branch 1. 79/11/19. Spp.
- 7912130081 Beeks denial of AH Hirshen & Metropolitan Area Planning Agency 791030 motion to strike applicant 791023 answer to hearing request Applicants response complies w/code requirements re determination of petitioners rights. GRAY, J. R. Hearing Branch 1. 79/11/20. 5pp.
- 791211003B Confirms receipt of encl 790329 petition to suspend OLs for all PMRs. Forwards FR notice indicating that petition will be treated in accordance w/10CFR2. 206.
  DENION.H.R. Diffice of Nuclear Reactor Regulation. 79/11/23. ip.
- ---7912110126 Notice of request for action pursuant to 10CFR2.206 re Environ Coalition on Nuclear Power 790329 petition requesting suspension of all OLs for PMRs. MULLER.D.R. Office of Nuclear Reactor Regulation. 79/11/23.

### H. Ceneral correspondence

- 7912190501 Responds to 791002 ltr outlining basic radiation safety course. Accepts certification program for admitting NRC personnel to radiation control areas. Addl training of approx D-h would be required.

  JONES.M. C. Dasha Public Power District. 79/12/13. 1p.
- P. Operating license stage documents & correspondence
- 7911090248 "Bummary of Operating Experience W/Recirculating Steam Generators." EISENAUT.D.O. Division of Operating Reactors. NUREO-0323. 79/01/31. 89pp.
- 7912100189 Discusses NRC 791101 meeting w/representatives of NBSS vendors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EISENNUT.D. Q. Division of Operating Reactors. 79/11/09. 65pp.
- --7912100330 Responds to NRC 791101 request re ORNL cladding swelling & rupture data.Review of analytical models & tests indicates compilance w/IOCFR50 App K. All GE specs for calculated peak cladding teap remain unchanged, BUCHMOLZ.R.H. General Electric Co. 79/12/07. 2pp.

- --7712100407 Forwards response to NRC 791101 request re rod hurst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 100FRSD. 46 satisfied. OHSLEY, C.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/02. Spp.
- --7912100496 Forwards addl info re evaluation of impact of NRC proposed repture/blockage model used in vendor svaluation model. No adverse impact from new repture berst data or use of NRC repture/blockage model on licensing calculation results. OWSLEY, 0. F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/04. 22pp.
- 7912030212 Forwards info repotential for steam generator water hammer, in response to NRC 790911 request.

  JONES, W. C. Omaha Public Power District. 79/11/12. App.
- 7912170039 Notification of meeting w/utils in Brownsville.NE & Omaha.NE to discuss NRC post-TMI emergency planning acceptance criteria.Agenda encl.
  IPPOLITO.T.A. Operating Reactors Branch 3. 79/11/16. Spp.
- 7912120262 Summary of 791025 meeting w/C-E owners group re asymmetric LOCA loads. HOSFORD.5.B. Engineering Branch, 79/11/20. 4pp.
- 7912120080 Bummary of 791116 meeting w/util,Exxon Nuclear & LeBoeuf, Lamb,Leiby & Macrae in Bethesda,MD re plant Cycle 6 reload & proposed power increase ERICKEDN.P. B. Operating Reactors Branch 4. 79/11/26. App.
- 7912130416 Responds to NRC 791030 ltr re implementation methods & schedules for NUREG-0578. Util will complete tasks according to schedule except those requiring cold shutdown. Pressurizer heaters & level mods scheduled for 1980 for 1981 outages. JONES, U. C. Omaha Public Power District. 79/11/27. 9pp.
- 7912050360 Notification of 791211 meeting w/util & Exxon re Exxon setpoint methodology to be used for Cycle 6 relaod & stretch power.

  ERICKEON, P. B. Operating Reactors Branch 4. 79/11/28. 2pp.
- 7912140012 Responds to 791115 ltr re rescheduling of 791116 meeting w/util to Omaha. NE. rather than Bilver Spring. MD. Due to technical nature of meeting number of NRC specialists required. Next meeting to be held 791211 in Domha. REID.R. M. Operating Reactors Branch 4. 79/11/29. lp.
- 7912190069 Forwards safety evaluation re-potential for water hammer in feedwater piping.
  LAINAS.G. Plant Systems Branch. 79/12/03. 2pp.
- ---7912190077 Bafety evaluation re-potential for water hammer in feedwater piping. Acceptable precautions taken to minimize water hammer occurrence.

  \*\*B Dffice of Nuclear Reactor Regulation. 79/12/03. 17pp.
- 791219015B Notifies that util not exempt from fee for review & approval of Tech Specs change Forwarding of Class II fee requested.
  MILLER, M. D. License Fee Management Branch. 79/12/03. 2pp.
- 79:2190337 Notifies of partial refund of Class III amend fer re 790919 application. Action required by application is in Class II fee category. MILLER, W. O. License Fee Management Branch. 79/12/03. 1p.
- 7912070463 Forwards "Loss of Load to Dne Steam Generator Incident Analysis." as supplemental info re application for amend to License DPR-40, permitting Cycle 6 operation following core reload.

  JDNES W.C. Omaha Public Power District. 79/12/04. 1p.
- --7912070464 "Loss of Load to One Steam Cenerator Incident Analysis." JUNES.W.C. Omaha Public Power District. 79/11/30. 28pp.
- 7912260207 Forwards safety evaluation re 780711 & 791106 proposed ands to chemical vol control sys & vibration dampaner sys. REID, R. W. Operating Reactors Branch 4. 79/12/04. 2pp.
- --7912260214 Bafety evaluation of proposed mods to chemical vol control sys & vibration dampener sys.

  \*\*Operating Reactors Branch 4, 79/12/04, ip.

- 7912140397 Responds to NRC 791023 ltr re purge & vent valve operability vorification. Util commits to operate in conformance \( \omega \) interim position. Unit containment ventilation isolation signals adequately segregated to ensure operability of one. JONES, H. C. Omaha Public Power District. 79/12/07. 3pp.
- 7912190565 Forwards proposal for implementing Section 2.1.7 a of NUREG-0378 re control grade automation of auxiliary feedwater sys. Mod schedule for early Jan 1980 refueling outage Oversize drawing of electrical sys enc! for Central Files only. JUNES.W. C. Omaha Public Power District. 79/12/13. 9pp.
- 7912270270 Forwards Class II fee for DL amend application in response to NRC 791203 ltr & IE Bulletin 79-06B.

  JONES, W. C. Omaha Public Power District. 79/12/13. 2pp.
- 7912270376 Discusses util commitment to implement NRC Category A NUREG-0578 requirements. Requirements will be implemented by 800131 or facility will be shut down until completion of implementation.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912190363 Responds to IE Bulletin 79-13, "Cracking in Feedwater Sys Piping." Facility will shut down on 791031 to perform ultrasonic insp of welds connecting saferend to downstream elbow & saferend to piping for both generators. JONES.W.C. Omaha Public Power District. 79/10/25. 1p.
- 7912210105 Responds to IE Bulletin 79-23 No connections exist between excitation transformer & generator at neutral on either diesel generator. No corrective action required. JONES, W. C. Omeha Public Power District. 79/10/26. 2pp.
- 7912140078 Forwards IE Bulletin 79-17. Revision 1. "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Written response required. SEYFRIT, K. V. Region 4. Dallas. Office of the Director. 79/10/29.
- 79:2170195 Updatos 79:1031 response to IE Bulletin 79-0&C Adequate instrumentation at facility exists to detect inadequate core cooling.Certain non-LDCA qualified instrumentation being replaced by LDCA qualified instrumentation.

  JONES.W.C. Omaha Public Power District. 79/11/01. Ip.
- 7912120565 Forwards IE Bulletin 79-25, "Failures of Westinghouse BFD Relays in Safety-Related Bys." Action required. BEYFRIT.K.V. Region 4, Dallas, Office of the Director. 79/11/02. 1p.
- 7912190028 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No written response required.

  BEYFRIT.K.V. Region 4, Dallas, Office of the Director. 79/11/16.
- 7912120555 Forwards IE Bulletin 79-26, "Boron Loss From BUR Control Blades." No response required.

  SEYFRIT.K.V. Ragion 4, Dallas, Office of the Director. 79/11/20.
- 7912110485 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sent by NRC to licensees.

  SEYFRIT, K. V. Region 4. Dallas, Office of the Director. 79/11/26.
- 7912190188 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Written response required SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/11/30.
- R. Periodic operating reports & related correspondence
- 7912140347 Forwards monthly operating rept for Nov 1979. JONES, W. C. Omaha Public Power District. 79/12/07. ip
- --7912140352 Monthly operating rept for Nav 1979. HICKLE, B. J. Omaha Public Power District. 79/12/07. 9pp.
- S. Reportable occurrences, LERs & related correspondence
- 7912070406 Forwards LER 79-021/21L-0. STEVENS, S. C. Omaha Public Power District. 79/11/19. 10pp.

- --7912070410 LER 79-021/21L-0: on 791106, during insp required by IE Bulletin 79-14 re safety-related piping sys. discrepancies found between design documents & as-bull t configuration of seismic restraints. Caused by probable QC installation error. RICHARD, A. W. Omaha Public Power District. 79/11/14. 1p.
- 7912110360 Forwards LER 79-020/03L-0. SIEVENS.S.C. Omaha Public Power District. 79/12/05. 1p.
- --7912110366 LER 79-020/03L-0: on 791031, during imaps of accessible piping, eight snubbers on safety injection sys piping found inoperable. Caused by improper installation of anchor bolts. Base plate redesigned & anchor bolts reinstalled. EIDEM.M.E., KUSEK.L.T. Omaha Public Power District. 79/12/05.
- DOCKET 50-286 INDIAN POINT STATION, UNIT 3

  F. Security, medical, emergency & fire protection plans
- 7912180335 Notifies of delay in Plant Sys Branch Team 1 evaluations of facility fire protection sys. Outlines of assistance needed encl.
  LAINAS.C. Plant Systems Branch. 79/11/16. Spp.
- 7912170261 Discusses proposed task force review of emergency preparedness. Task force should study alternatives for reduction of probability & consequences of severe accident. EISENHUT.B. G. Division of Operating Reactors. 79/11/21. Spp.
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives. Provides guidance for improving licensee emergency preparedness & assuring capability of affsite agencies to take appropriate emergency actions.

  ORIMES. B. K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- 7912030181 Forwards supplemental info to NRC requests of 780929 & 1128 re fire protection program. Will not install automatic, wet-pipe hydraulic sprinkler sys. Will provide total flooding carbon digride sys. EARLY, P. J. Power Authority of the State of New York. 79/11/26.
- 7912200122 Notification of 791205 meeting w/util in Dethesda.MD. to review emergency preparedness capabilities.List of NRC considerations encl. EIBENHUT, D. O. Division of Operating Reactors. 79/11/29. Spp.
- 7912260003 Notification of 791218 meeting w/util in Ossining, NY re emergency planning. OLSHAN, L. N. Operating Reactors Branch 1, 79/12/07, Upp.
- G. Adjudicatory correspondence
- 7912D&O&44 Statement in support of UCS 790917 petition for decommissioning of Unit ( & suspension of Units 2 & 3 DLs. Requests institution of proceeding per 10CFR2.202. Affidavit. Certificate of Syc & supporting documentation encl. ABRAMS.R., BIALIK.E.I. New York, State of. 79/11/16. 15pp.
- 7912110039 Confirms receipt of oncl 790329 patition to suspend OLs for all PWRs.Forwards FR notice indicating that patition will be treated in accordance w/10CFR2.206.
  DENTON-H.R. Office of Nuclear Reactor Regulation. 79/11/23. ip.
- --7912110126 Notice of request for action pursuant to 10CFR2, 206 re Environ Coalition on Nuclear Power 790327 petition requesting suspension of all DLs for PWRs. MULLER.D.R. Office of Nuclear Reactor Regulation. 79/11/23
- 7912200270 Forwards statement made in support of UCB petition for decommissioning of Unit 1 & suspension of operation at Units 2 & I BROWN,P.D.G. Hid-Hudson Nutlear Opponents, Inc. 79/11/27. 1p.
- --7912200275 Statement of PDG Brown in support of UCB petition for proceeding to institute decommissioning of Unit 1 & suspension of operation at Units 2 & 3 pending safety review BROWN P. D. 9. Mid-Hudson Nuclear Opponents, Inc. 79/11/26. Opp.
- 7912040074 Notice of withdrawal from proceedings effective 791130. SMITH, B. H. Hearing Branch 2 79/11/29. 1p.
- 791204007B Notice of appearance on behalf of NRC Certificate of Byc encl.
  MODRE, J.E. Hearing Branch 2. 79/11/29. Opp.

- 791226036B Requests extension until 800208 to respond to intervenors NY State Energy Ofc & Citizens' Committee for Protection of Environ petitions for review of ALAB-436 & ALAB-561 re seismic issues, Certificate of Evc encl. MODRE, J. E. Hearing Branch 2. 79/12/07. 4pp.
- 7912180410 Requests confirmation of 800126 deadline for NRC response to intervenor UCS 791115 request for action under 10CFR2.206.Also requests meeting to discuss issues to be used to formulate response.

  WEISS, E. R. Sheidon, Harmon & Weiss. 79/12/10. 1p.
- --7912180422 Requests that Commission reconsider 790425 decision to refer intervenor VCS 790328 seismic reanalysis petition to staff. Commission must assume jurisdiction since staff has issued no reply to UCS in six months. WEISS.E.R. Union of Concerned Scientists. WEISS.E.R. Sheldon, Harmon & Waiss. 79/12/10. Spp.
- 791231007B Three ltrs requesting favorable action on petition to shut down facility.
  ESTEROWITZ.R., KAMZAN,L., BRODESKY,N. Affiliation Unknown.
- 7912190239 Order granting extension until 800208 for NRC to respond to NY State Energy Ofc & Citizens Committee for Protection of Environ petitions for review.
  CHILK, S. J. Office of the Secretary of the Commission. 79/12/14.
- 7912310109 Two ltrs requesting favorable action on petition to sumpend operations at facility. GHINGER.J., KAMZAN,L. Affiliation Unknown. 79/12/15. 3pp.
- 7712170107 Forwards 771217 ltr to Commissioner Ahearne re UCB poition on safety & site location issues. FIBH.H. House of Rep. 79/12/17. lp.
- --7912190114 Requests quick response to UCS petition re resolution of site location & safety issues. FISH.H. House of Rep. 79/12/17. 1p.
- H. General correspondence
- 7912140127 Requests removal from svt list of EJ Back & addition of JP Davis. DAVIS.J.P. Consolidated Edison Co. of New York. 79/11/08. 1p.
- 7912170418 Requests update of NRC distribution list by deleting VJ Cassan as counsel & substituting CM Pratt. EARLY, P. J. Power Authority of the State of New York. 79/12/13. 1p.
- 791219D513 Advises that complotion of Oak Ridge Associate Univs radiation safety course is acceptable in lieu of first section of facility training program towards certification of individual for entry to restricted areas.

  EARLY, P. J. Power Authority of the State of New York. 79/12/13. Ip
- 7912280504 Requests update of distribution lists by replacing name of VJ Cassan w/CM Protties counsel for util.
  EARLY, P. J. Power Authority of the State of New York. 79/12/13. ip.
- J. Insurance & indemnity information
- 7912270609 Confirms that PASNY has loan commitment for \$10 million from Manufacturers Hanover Trust for retrospective insurance payment if necessary, in event of nuclear disaster Commitment expires 800630.

  MCCARTHY, R. H. Affiliation Unknown. 79/12/18, 1p.
- P. Operating license stage documents & correspondence
- 7911090248 "Summary of Operating Experience W/Recirculating Steam Cenerators." £18EN:WJ. DG. Division of Operating Reactors. NUREG~0523. 79/01/31. 87pp.
- 79:2050:8: Discusses NRC review of LERs & Tech Spec requirements re control RPI sys at Westinghouse PWRs Requests Tech Specs review to ensure requirement for rod maint to within +/- 12 steps indicated & RPI sys verified accurate within 12 steps. SCHWENCER.A. Gperating Reactors Branch 1. 79/10/29. 7pp.
- 7712100187 Discusses NRC 771101 meeting w/representatives of NBSS vendors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. ELBENHUT, D. G. Division of Operating Reactors. 77/11/09. 65pp.

- --7912100255 Responds to NRC 791101 request re noncompliance of Westinghouse ECC5 evaluation model under requirements of IOCFR80 App K. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants. ANDERSDN.T.M. Westinghouse Electric Corp. 79/11/02. App.
- --7912100330 Responds to NRC 791101 request re ORNL cladding swelling & rupture data. Review of analytical models & tests indicates compilance w/IOCFRSO App K.All OE specs for calculated peak cladding temp remain unchanged.

  BUCHHDLZ.R.H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50.46 satisfied.
  OMSLEV.O.F. Exxon Nuclear Co.: Inc. (subs. of Exxon Corp.).
  79/11/02. 5pp.
- -7912100456 Forwards addl info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model.

  No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results.

  OMBLEY, O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).

  79/11/04. 22pp.
- 7912100022 Discusses issuance of Amend 17 to License DPR-64, which authorized operation at 100% power, Max allowable fee already gaid by util No addl fee required.

  MILLER, W. O. License Fee Management Branch. 79/11/13, 1p.
- ~~7912100037 Forwards review summary of costs incurred by various program ofcs involved in OL issuing & processing No add1 license fee required because max fee allowed already paid Facility fee schedule encl.

  HOLLOWAY, C. J. License Fee Management Branch. 79/11/09. 2pp.
- --7912100043 Forwards assessment of review costs for CP & DL actions, to aid in fee determination. W/o encl. BERKOW.H.N. Office of Nuclear Reactor Regulation. 79/10/30. ip.
- --7912100051 Responds to 790910 memo requesting calculation of costs associated w/OL issuance. Since total cost exceeded fee limit no further action required.
  EISENHUT.D.G. Division of Operating Reactors. 79/10/19. lp.
- --7912100062 Forwards IE cost data rept of routine insp effort for 700701-760405. Data for 690813-700630 could not be reconstructed.

  CDBS.L. I. Executive Officer for Management & Analysis. 79/02/09.
- --7912100066 Provides ACRB prof manpower expenditure estimates for CP & OL reviews. FRALEY, R. F. ACRS - Advisory Committee on Reactor Safeguards. 78/11/01. 1p.
- --7912100079 Requests info re ACRS prof man-hrs expended on review of each reactor. Data for safety, environ & antitrust hearing concerns should be included. Associated travel should not be License Fee Management Branch. 79/10/02. 1p. MILLER, W. D.
- 7912070263 Particily responds to FDIA request for document re Pawling, NY site.Forwards requested info. Submits addl info: sodium deuterium reactor never built at site, no matl ever used at site & no radioactive matl disposed of in lake.

  CARR.J.C. Division of Rules and Records. 79/11/16. 3pp.
- 7912070291 Submits partial response to FOIA request for documents re Nuclear Development Association, United Nuclear Corp. Gulf United Nuclear Corp & ATCOR Inc. concerning facility site. Forwards requested info. Provides addl info re site. CARR.J.C. Division of Rules and Records. 79/11/16. 3pp.
- 7912060070 Summary of 791113 telcon w/util re util 791022 response to 790913 itr re lessons learned implementation.
  OLSHAN, L. N. Operating Reactors Branch 1. 79/11/23. 4pp.
- 7912120064 Hummary of 791113 telcon w/util re lessons learned implementation. OLSHAN.L.N. Operating Reactors Branch 1. 79/11/23. Spp.
- 7912040200 Forwards proposed Tech Specs changes re safety review committee, submitted as application for amend to OL. EARLY, P. J. Power Authority of the State of New York. 79/11/28. in the parameter against the second

The Special Section of the Section o

12 5006

- --79120402D6 Proposed Tech Specs changes re safety review committee Safety evaluation enci \* Power Authority of the State of New York. 79/11/28. Opp.
- 7912040649 Notification of 791205 meeting w/utils in Bethesda, MD to discuss alternatives to reduce probability & consequences of severe reactor accident.

  ZECH, Q. Division of Operating Reactors. 79/11/29. App.
- 7912210115 Notification of 791205 meeting w/Con Ed & Comm Ed in Bethesda.MD to discuss in-depth review of facility.NRC considerations encl. EISENHUT.D.C. Division of Operating Reactors. 79/11/29. App.
- 7912040526 Forwards application for amend to License DFR-64 to incorporate operating conditions for secondary water chemistry manitoring program.

  EARLY, P. J. Power Authority of the State of New York 79/12/03.
- --7912060528 Application for amend to License DPR-64 to incorporate conditions for secondary water chemistry monitoring program to inhibit steam generator tube degradation. Proposed addition % safety evaluation entl.

  EARLY, P. J. Power Authority of the State of New York. 79/11/30.
- 7912130284 Forwards application for amend to GL changing ETS & required fee.Fee paid under protest.
  CAHILL, W. J. Consolidated Edison Co. of New York. 79/12/03. 1p.
- --7912130271 Application to amend ETS distinguishing limiting conditions & monitoring requirements, oliminating repetitive specs, reporting requirements & bases & updating ETS rept to reflect present technology.

  CANTELL, M. J. Consolidated Edison Co. of New York. EARLY, A. E. Power Authority of the State of New York. 79/12/03. 25pp.
- --7912130306 Revised Pages 1-1 through 5.6-i of ETS re limiting conditions & monitoring requirements.annual environ operating rept & nonroutine reportable environ occurrences. Affidavit of svc encl.

  \* Consolidated Edison Co. of New York. 79/12/03. 46pp.
- 7912070397 Forwards revised TMI lessons learned commitment list, per 791130 & 1203 telcons.List supersedes encl to 791121 ltr. EARLY,P. J. Power Authority of the State of New York. 79/12/04.
- 7912200415 Notifies of 791218 site visit of NRC Emergency Planning Task Force to evaluate upgrading of emergency planning since TMI accident Requests participation of NY State Energy Dfc. COLLING.H.E. Assistant Director for Emergency Preparedness. 79/12/07. 1p.
- 7912170296 Forwards revised pages to 791204 ltr re short-term requirements of TMI Lessons Learned Task Force. Util will complete all required items prior to return to power. Items will be complete by 800201.

  EARLY, P. J. Power Authority of the State of New York. 79/12/10.
- 7912180843 Forwards payment for Class III fee for 791204 application. Fee paid under protest pending final determination of legality of fee schedule. EARLY.P.J. Power Authority of the State of New York. 79/12/11. 1p.
- . 7912180371 Supplies Tech Spec review results re accuracy of Westinghouse control RPI sys. Deviation of 13 steps permissible. Revised Tech Specs to be submitted to comply w/new 12 step accuracy limits.

  EARLY, P. J. Power Authority of the State of New York. 79/12/13. Ip.
- 7912190372 Ack receipt of 791206 telcon request re electrical drawings for valves of containment isolation sys. Drawings will be sent as encls to Ltr IUP-2282 on 791213.

  EARLY, P. J. Power Authority of the State of New York. 79/12/13. 1p.
- 7912190576 Forwards containment isolation valve drawings for NUREQ-0578, in response to NRC request Drawings available in Central Files only DUERR. R.F. United Engineers & Constructors, Inc. (subs. of Raytheon Co.). 79/12/13. ip.
- 7912270308 Forwards info & drawings or NUREO-0576, concerning auxiliary feedwater sys automatic initiation Drawings not encl. EARLY, P. J. Power Authority of the State of New York. 79/12/17.

- 7912270315 Discusses compliance w/requirements of NUREG-0578.
  Requirements will not be completed by 800101. Facility will
  not return to svc until requirements are complete. Completion
  anticipated by 800201.
  EARLY,P.J. Power Authority of the State of New York. 79/12/17. 1p.
- 7912270339 Forwards "Program Plan for Performance Verification of PWH Safety/Relief Valves & Sys" & supplemental info in response to TMI Lessons Learned Task Force Recommendations 2.1.2.
  CANILL, M. J. Consolidated Edison Co. of New York. 79/12/17. 7pp.
- --7912270373 "Program Plan for Performance Verification of PWR Safety/ Relief Valves & Sys." + Electric Power Research Institute. 79/12/13. 62pp.
- 7912270335 Forwards application for amend of License DPR-64, proposed Tech Spec change safety evaluation & Class III fee Payment made under protest.

  EARLY,P. J. Power Authority of the State of New York. 79/12/18. 1p.
- ---7912270447 Application for amend of License DPR-64,modifying Section 3.10.App A to reduce allowable misalignment of control rad indicated position to group step counter demand positions. EARLY,P. J. Power Authority of the State of New York. 79/12/18.
- --7912270455 Proposed Tech Spec change to Section 3.10.5 re control rod position indication misalignment. # Power Authority of the State of New York. 79/12/12. 4pp.
- --7912270460 Safety evaluation for proposed Tech Spec change re control rod position indication misalignment, Mod will not reduce margin of safety.

  \* Power Authority of the State of New York. 79/12/12. 2pp.
- 7912270267 Forwards 791220 conference paper re Indian Point/Zion near site studies Requests paper be made part of public record. PEOPLES.C.L. Commonwealth Edison Co. \* Consolidated Edison Co. of New York. \* Power Authority of the State of New York. 79/12/21.
- 7912270353 Forwards response to 791107 ltr re NRC requirements for auxiliary feedwater sys
  EARLY.P.J. Power Authority of the State of New York. 79/12/21.
- 7912280612 Informs of plans to perform hydrostatic test of RCS, followed by low power physics test, on or about 791226. Facility presently has acceptable App K ECCS analysis based on Mestinghouse Oct 1975 evaluation model. EARLY.P. J. Power Authority of the State of New York. 79/12/21.
- Q. Inspection reports, 1E Bulletins & correspondence
- 7912050001 Forwards IE Insp Rept S0-285/79-12 on 790820-22.No noncompliance noted

  CARLSON, R. T. Region 1. Philadelphia, Reactor Construction &
  Engineering Support Branch. 79/10/15. 2pp.
- --7912050004 IE Insp Rept 50-286/79-12 on 790820-22. No noncompliance noted hajor areas inspected underground fire makes fire water storage tanks fire pumps & fire pump house.

  KOLTAY, P. S. Region 1, Philadelphia, Office of the Director EDNETER, S.D. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/10/11. Spp.
- 7912170176 Responds to JE Bulletin 79-27, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No evidence of cracking. Visual insp of accessible welds will be performed & results sent when sys can be uperated to achieve required pressure. BAYNE.J.P. Power Authority of the State of New York. 79/10/24. 1p.
- 7912200466 Forwards IE Insp Rept 90-286/79-22 on 790913,19-21,25-27 & 1002-05 No noncompliance noted.
  CARLSON.R.T. Region I, Philadelphia, Reactor Construction & Engineering Support Branch, 79/11/01, 2pp.
- ---7912200472 IE insp Rept 50-286/79-22 on 790913, 19-21, 25-27 % 1002-09. No noncompliance noted Major areas inspected steam generator insp program & inservice insp activities including work in progress. TRIPP.L.E. Region I. Philadelphia. Reactor Construction & Engineering Support Branch. MCBREARTY,R.A. Region I. Philadelphia. Office of the Director. 79/10/30. 9pp.

- 7912130515 Forwards response to IE Bulletin 79-21. "Temp Effects on Level Measurement." Liquid level measuring sys & all safety & control setpoints reviewed. SCHMEIDER.J.R. Power Authority of the State of New York. 79/11/02. Han.
- 7912310125 Forwards IE Insp Rept 50-286/79-18 on 790902-29. No noncompliance noted.
  BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/11/05. 2pp.
- --7912310131 IE Insp Rept 50-286/79-18 on 790902-29 No noncompliance noted Major areas inspected: logs & records, physical security & periodic repts. REBELOWERI.T., JOHNBON.J. Region 1, Philadelphia, Office of th & periodic repts.
  REBELDWSKI.T., JDHNSON, J. Region 1. Philadelphia. Office of the Director. KEIMIG.R. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch. 79/11/02. 13pp.
- 7912140293 Responds to IE Bulletin 79-23 re potential failure of emergency diesel generator. Generator neutral floats & is not connected to ground, eliminating possibility of malfunction. BAYNE, J. P. Power Authority of the Stats of New York. 79/11/07.
- 7912200344 Forwards waste packaging Insp Rept 79-02A on 790725-26. No noncompliance noted. SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/11/07. 2pp.
- -7912200395 Waste packaging Insp Rept 79-02A. No noncompliance noted.
  Major areas inspected: shipping paper & DDT placarding
  requirements, radiation levels, removable contamination, DDT &
  NRC package features.
  BROWN, R. A. Region 2, Atlanta, Office of the Director. 79/11/04.
- 7912310367 Responds to IE Bulletin 79-13, "Indication of Low Water Level at Oyster Creek Reactor." Examined & evaluated steam generator feedwater norries-to-piping welds w/respect to ASME codes. No cracking noted. DAYNE,J.P. Power Authority of the State of New York. 79/11/15.
- 7912030047 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required.
  GRIER.B.H. Region 1, Philadelphia, Office of the Director.
  79/11/16. 1p.
- 7912050201 Forwards IE Info Notice 79-27, "Steam Cenerator Tube Ruptures at Two PWR Plants." No response required. CRIER.B.H. Region 1. Philadelphia, Office of the Director. 79/11/16. ip.
- 7912100138 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/11/16. ip.
- 7912110453 Forwards IE Info Notice 79-29. "Luss of Nonsafety-Related Reactor Conlant Sys Instrumentation During Operation." No specific action or response required. GRIER B. H. Region 1. Philadelphia, Office of the Director. 79/11/19. 1p.
- 7912050267 Forwards IE Bulletin 79-26, "Boron Loss From BUR Control Blades." No response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director. 79/11/20. ip.
- 7912060583 Forwards IE Circular 79-24, "Proper Installation & Calibr of Gare Upray Pipe Break Detection Equipment on SWRs." No response required.
  ORIER, B. H. Region 1, Philadelphia, Office of the Director.
  79/11/26. Ip.
- 7912110067 Forwards IE Circular 79-23, "Motor Starters & Contoctors Failed to Operate." No response required.
  ORIER.B. H. Region 1. Philadelphia. Office of the Director.
  79/11/26. ip.
- 7912210096 Ack receipt of 791012 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-286/79-09.
  BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/11/27. lp.
- --7912210103 Forwards IE Insp Rept 50-286/79-09 on 790415-0707 & notice of violation Encls withheld (ref 100FR2.790).

  BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/09/27. 2pp.

- 7912190049 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Written response required. ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/11/30. 10.
- 7912310234 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances: 10CFR21." No action required.

  ORIER.B.H. Region 1, Philadelphia, Office of the Director.
  77/12706. 4pp.
- 7912190758 Forwards IE Bulletin 79-28, "Possible Malfunction of Nasco Model EA180 Limit Switches at Elevated Temps." Written response required. QRIER.D.H. Region 1. Philadelphia. Office of the Director. 79/12/07. 1p.
- 7912280005 Responds to IE Bulletin 79-02.Revision 2.Verification that pipe support base plate flexibility was accounted for in calculation of anchor bolts loads will be completed by 800101.

  SCHMIEDER, J. R. Power Authority of the State of New York. 79/12/07.
- 7912280217 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required. GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/12/13. ip.
- R. Periodic operating reports & related currespondence
- 7912140333 Forwards Nov 1979 data re fish species specified in Section 401 certification to NY State Dept of Environ Conservation. HONTI.H.A. Consolidated Edison Co. of New York. 79/12/10. 17pp.
- 7912170302 Forwards daily records of fish collection for Nov 1979. CAHILLIN.J. Consolidated Edison Co. of New York. 79/12/14. 1p.
- --7912170307 Tabulation of daily records of fish collection for Nov 1979. + Consolidated Edison Co. of New York. 79/11/30. Spp.
- 7918200342 Forwards monthly operating rept for Nov 1979. BAYNE, J. P. Power Authority of the State of New York. 79/12/14. 1p.
- --7912200349 Monthly operating rept for Nov 1979.

  GONNELL, C. Power Authority of the State of New York. 79/12/03.

  Hop.
- 8. Reportable occurrences. LERs & related correspondence
- 7912200575 PNS-I-79-002:R Pienciak Associated Press reporter interviewed 20 to 30 guards at facilities & plans to write article describing guard force performence util physical socurity programs & weaknesses in programs.

  DEVLIN J. W., MARTIN W.G., ALLAN, J. Diffice of Inspection & Enforcement, Office of the Director. 79/10/05. 1p.
- 7912200490 PNS-I-79-004: on 791016. licensee received notification via telcon w/NY State Police of bomb threat against facility. State Police assisting in bomb search. No evacuation of facilities. DEVLIN, J. W., MARTIN, W. C., ALLAN, J. Office of Inspection & Enforcement, Office of the Director. 79/10/16. 1p.
- 7912200444 PNS-I-79-004A: on 791017, Peekskill Evening Star, Peekskill, NY, states receiving bomb threat extertion ltr re facilities & three phone calls on 791016 re same bomb threat Search of facilities revealed no bomb.
  DEVLIN, J. W. MARTIN, W. G., ALLAN, J. Office of Inspection & Enforcement, Office of the Director. 79/10/17. 2pp.
- 7912200073 PNS-I-79-0048: on 791021, book threat received by NY Telephone Co operator from unidentified male who said book would go off in 1-h at plant. Search conducted at Units 2 & 3. No book found.
  SHEPPHERD, R. E., DEVLIN, J. M., MARTIN, H. G. Office of Inspection & Enforcement, Office of the Director. 79/10/22. 1p.
- 7912030114 PNS-1-79-006: on 791103, extortion bomb threat against facility was received by local newspaper. Search conducted to no bomb found.

  JONES, L. M. Office of Inspection & Enforcement, Office of the Director. BRUNNER, E. J., ALLAN, J. Region 1. Philadelphia, Office of the Director. 79/11/06, 1p.
- 7912040319 Forwards LER 79-013/01T-0.
  BAYNE, J. P. Power Authority of the State of New York. 79/11/28. 1p.

- ---7912040321 LER 79-013/017-0:on 791127, setpoints for PCV-464.PCV-466 & PVC-468 below Tech Spec limit. Caused by mechanical valve drift. Valves reset to Tech Spec requirements.

  GUMBLE.F. W. Power Authority of the State of New York. 79/11/28.

  ip.
- 7712040367 Forwards LER 77-015/01T-0.

  BAYNE, J. P. Power Authority of the State of New York. 79/11/28. 1p.
- —7912040369 LER 79-015/01T-0: on 791127. accumulator 31 & 34 level transmitters out of spec. Caused by Rosemount Model 1151 DP level transmitter being outside of required tolerance. Transmitter recalibr.
  GWMSLE.F.W. Power Authority of the State of New York. 79/11/28.
- 7912040308 RD-016/01T-00: on 791127. evaluation revealed nontonservative feature could exist in App K LOCA analysis re fuel rod burst calculation. Analysis w/current model being performed. Results of analysis available before unit startup.

  BAYNE, J. P. Power Authority of the State of New York. 79/11/28.
- 7912040482 RO 79-013/01T-0 & 79-015/01T-0 on 791127, during cold shutdown, tests indicated that pressurizer valve settings & accumulator level transmitters below limits, Caused by mechanical drift. Valves & transmitters reset.

  BAYNE, J. P. Power Authority of the State of New York. 79/11/28.

  Zpp.
- 7912310328 RG-016/01T-00: on 791127. Westinghouse notified util that evaluation of current LOCA/ECCS evaluation model indicates nonconservative feature could exist in App K LOCA analysis w/respect to portion of calculation re fuel rod burst. BAYNE, J. P. Power Authority of the State of New York. 79/11/28. 2pp.
- 7912110332 Forwards LER 79-016/01T-0.

  BAYNE J. P. Power Authority of the State of New York. 79/12/07. Ip.
- ---79 12110303 LER 79-016/01T-0 on 791127 util notified by Mestinghouse that nonconservative feature could exist in fuel burst calculations of App K LOCA analysis. Analysis of possible adverse affects to sys underway.

  CMBLE.F.N. Power Authority of the State of New York. 79/12/07.
- 7912180569 Formards updated LER 79-016/01T-1, correcting c)exical error in first paragraph of Attachment 1 to LER. Ref to "hot shutdown" should read "cold shutdown."

  DAYNE, J. P. Power Authority of the State of New York. 79/12/14.

  Zpp.
- 79122/0553 Forwards LER 79-018/03L-0.
  BAYNE, J. P. Power Authority of the State of New York. 79/12/21. Ip.
- --7912270562 LER 79-018/03L-0:on 791123.during refueling shutdown, determined on completion of seismic restraint test 3PT-R38 that 35 snubbers out of spec Caused by defective snubbers. Snubbers repaired or replaced.

  GUMBLE.F.W. Power Authority of the State of New York. 79/12/21. 200.
- U. Congressional/Executive Correspondence
- 7912140528 Concurs w/Kemeny Commission recommendation re emergency evacuation plans for power plant areas NRC should rule directly on UCS setition to shut down plant. BINOMAM. J. House of Rep. 79/11/14. 1p.
- DOCKET 50-287 OCONEE MUCLEAR STATION, UNIT 3
- F. Security, medical, emergency & fire protection plans
- 7809290053 Summary of fire protection appeal meeting on 780414.
  Meeting inconclusive, so official summary not prepared.
  BIRKEL. R. Light Water Reactors Branch 2. 78/09/26. 2pp.

- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives Provides guidance for improving licensee omergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.

  GRIMES, B. K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- 0. Adjudicatory correspondence
- 7912110038 Confirms receipt of encl 790329 petition to suspend OLs for all PMRs. Forwards FR notice indicating that petition will be treated in accordance w/IOCFR2.206.
  DENTIN. H. R. Defice of Nuclear Reactor Regulation. 79/11/23. 1p.
- --7912110126 Notice of request for action pursuant to 10CFR2.206 re Environ Coalition on Nuclear Power 790329 petition requesting suspension of all CLs for PHRs. MULLER.D.R. Office of Nuclear Reactor Regulation. 79/11/23. 38pp.
- I. Financial information
- 7912270577 Forwards duplicate copies of util 790321 guarantee of retrospective premiums, in response to NRC 791210 request. WHITLEY, H. D. Ouke Power Co. 79/12/20. 1p.
- --7912270585 Requests approved guarantee of payment of deferred premiums for 1979. SALTZMAN J. Actitrost & Indemnity Group. 79/12/10. 1p.
- J. Insurance & indemnity information
- 780?190350 Informs recipient of Duke Power Co 780?05 request to modify station Indomnity Agreement 8-44 to permit receipt & possession of 4 fuel assemblies from Crystal River 3 facility.

  FAIRTILE, M. B. Operating Reactors Branch 4 (Pro 790625).
- P. Operating license stage documents & correspondence
- 7809270073 Comments on seismically induced floods at Oconee plants.
  Investigates potential failure of Jocassee Dam in relation
  to safety of units Guestion is being addressed by
  Ceosciences Branch,
  HULMAN.L.G. Hydrology Meteorology Branch. 78/09/22. ip.
- --7809270104 Responds to 760115 memo re recent earthquake activity in vicinity of Jocassee Dam. Discussos bases of seismically induced flood analysis for facility DL. Reactor area could be vulnerable to flooding but detailed info unavailable.

  HULMAN, L. O. Hydrology Meteorology Dranch. 76/01/30. Ip.
- 791109024B "Summary of Operating Experience W/Recirculating Steam Generators," EISENHUT. D.9. Division of Operating Reactors. NUREG-0523, 79/01/31. B9no.
- 7912310070 Ack 790831 Itrs endorsing 8&W generic rept DAW-1564, "Integrated Control Sys Reliability Analysis," & requests addl info.
  REID.R.W. Operating Reactors Branch 4. 79/11/07. 13pp.
- 7712130190 Forwards summary of Taknekron Research. Inc study of licensee regulatory performance evaluation & Toknekron draft rept re operating reactors w/D&W nuclear steam supply sys. Requests comments H/o encl.
  STELLO.V. Office of Inspection & Enforcement, Office of the Director. 79/11/08. 2pp.
- 7912100189 Discusses NRC 791101 meeting u/representatives of NSSS vandors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vondor responses encl. ETSENHUT, D. Q. Division of Operating Reactors. 79/11/09. 65pp.
- --7912100255 Responds to NRC 771101 request re noncompliance of Westinghouse ECCS evaluation model under requirements of 10CFR50 App N. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants. ANDERSON.T.M. Westinghouse Electric Corp. 79/11/02. 4pp.
- --7912100330 Responds to NRC 791101 request re DRNL cladding swelling & rupture data. Review of analytical models & tests indicates compliance w/10CFR50 App K. All GE specs for calculated peak cladding temp remain unchanged.

  BUCHHOLZ.R. H. General Electric Co. 79/12/07. 2pp.

- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 100FR50. 46 satisfied.

  DNSLEY.G.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/11/02. 5pg.
- --7912100456 Forwards add1 info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. GMSLEY.G.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/04. 22pp.
- 7912180317 Forwards safety evaluation of proposed changes to Tech Spits no 780112,0201 & 790822 requests for amend to auxiliary electrical emergency power sys periodic testing. LAIMAS. 9. Plant Systems Branch. 79711/13. 2pp.
- --7912180324 Safety evaluation supporting proposed changes to Tech Epecs ro auxiliary electrical sys & emergency power sys surveillance periodic testing.

  \* Office of Nuclear Reactor Regulation. 79/11/13. App.
- 7912120092 Summary of 791024 meeting w/B&W owners group re asymmetric LOCA loads evaluation. Evaluation of B&W plants to be completed by 1980.
  HOSFORD.8.B. Assistant Director for Engineering Programs, 79/11/20. 4pp.
- 7912100478 Forwards, to alk B&W operating plants except TMI, request for add1 info re small break LOCA. Comments requested by 791203. REID.R.W. Operating Reactors Branch 4. 79/11/21. 3pp.
- 7912100414 Forwards concerns on control rod guide tube wear in B&W-designed facilities, to assist in planning survavillance program. Meeting scheduled 791220 in Bethesda, MD to discuss proposed program.
  REID, R. W. Operating Reactors Branch 4. 79/11/23. App.
- 7912040355 Forwards rapt & errata sheet re power operated relief valve actuation & reactor trip frequency.
  PARKER, W. D. Duke Power Co. 79/11/25, 24pp.
- 7912040293 Forwards requests for relief from requirements of ABME Boiler & Pressure Vessel Code Bection XI.due to impracticality of performing hydrostatic testing of portions of low pressure syc water, chemical addition & nitrogen sys. PARKER, W. O. Duke Power Co. 79/11/27. Bpp.
- 7912040415 Forwards correct commitment dates to 791121 response to NOREO-0578.
  PARXER, N.O. Duke Power Co. 79/11/27. 4pp.
- 7912110131 Denies 791113 request for extension of time in which to file upgraded emergency plan. Rept due 800101.
  REID.R.W. Operating Reactors Branch 4. 79/11/27. 2pp.
- 7912040516 Forwards proposed Tech Spec revision, supplementing 770528 submittel re operability requirements of emergency feedwater sys.

  PARKER.W. D. Duke Power Co. 79/11/28, 1p.
- --7912040518 Proposed Tech Spec revision re emergency feedwater sys. \* Duke Power Co. 79/11/28. 9pp.
- 7912050302 Requests add1 time to respond to NRC 791121 ltr re small break LOCA Info re mechanical effects of induced slug flow on steam generator tubes will be provided by 800215. Pump seal cooling info will be submitted by 791231. PARKER, M. O. Duke Power Co. 79/12/03. 1p.
- 7912120434 Notifies that response to NRC 790821 ltr re Item 7-1A, benchmark analysis of sequential auxiliary feedwater flow to steam generators following loss of main feedwater will be gravided by 791221.
  PARKERAM.O. Duke Power Co. 79/12/03. 1p.
- 7912270266 Provides status of NUREG-0578 Category A items which will not be implemented prior to S00101. Unit i currently in shutdown for refueling All required items for Unit i will be completed before startup anticipated in early Feb 1980, PARKER. N. D. Duke Power Co. 79/12/17. 2pp.
- 7912270399 Advises that excessive downtime for remaining TMI Lessone Learned Task Force requirements during peak winter months is unnecessary Sequential shutdown of Units 2 & 3 in Feb will be followed by shutdown of Unit 1 by 800531. THIES A.C. Duke Power Co. 79/12/17. 3pp.

- 7912270431 Reaffirms util commitment to safe operation of facility. Claims significant progress in meeting virtually all Category A items in NUREG-0578.
  THIES: A.C. Duke Power Co. 79/12/17. 3pp.
- G. Inspection reports, IE Bulletins & correspondence
- 7912170211 Forwards, "Revision 1, Summary Rept. Generic Response to US NRC IE Bulletin 79-02. Base Plate/Concrete Expansion Anchor Bolts." PARKER, W. D. Duke Power Co. 79/10/29. 1p.
- --7912170222 "Revision 1.Summary Rept. Generic Response to US NRC IE Bullstin 79-02. Base Plate/Concrete Expansion Anchor Bolts." \* Duke Power Co. TR-3501-1. 79/08/30. 7pp.
- 7912200344 Forwards waste packaging Insp Rept 79-02A on 790925-26.No noncompliance noted. BUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/11/07. 2pp.
- --7912200395 Waste packaging Insp Rept 79-02A No noncompliance noted.

  Major areas inspected: shipping paper & DOT placarding
  requirements: radiation levels: removable contamination, DDT &
  NRC package features.

  BROWN,R.A. Region 2, Atlanta, Office of the Director. 79/11/04.
- 7912040128 Forwards IE Info Notice 79-12A. "Attempted Damage to New Fuel Assemblies." No specific action or response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/09. 2pp.
- 7912060049 Forwards response to Item 5 of IE Bulletin 79-050 re small break operating guidelines. Forwards "Analysis Summary in Support Of Inadequate Core Cooling Guidelines for Loss of RGB Inventory." W/o encl. PARKER, W. O. Duke Power Co. 79/11/09. 1p.
- 7912100134 Ack receipt of 791108 ltr in response to NRC 790607 ltr re items designated as C & D. Corrective actions will be examined during future insp. LEMIS.R.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 79/11/16. 1p.
- --7912100165 Responds to NRC 790607 ltr re violations noted in lE Insp Repts 50-269/79-10.50-270/79-10 & 50-287/79-10. Corrective actions: plans to amend GA program topical rept to reflect present mode of operation. PARKER, W. O. Duke Power Co. 79/11/08. 1p.
- 7912100169 Forwards IE Info Notice 79-28, "Overloading of Btructural Elements Due to Pipe Support Loads." No response required. O'REILLY, J.F. Region 2. Atlanta, Office of the Director. 79/11/16. ip.
- 7912110545 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/11/16. 2pp.
- 7912170127 Responds to IE Bulletin 79-01, "Environ Qualification of Class IE Equipment." Anticipates Unit i & 3 motor operators will be changed out during first cold shutdown after 800129, PARKER, H. D. Duke Power Co. 79/11/16. ip.
- 7912060607 Forwards IE Circular 79-24. "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No response required.

  O'REILLY.J.P. Region 2. Atlanta. Office of the Director.
  79/11/26. 1p.
- 7912110134 Forwards IE Circular 79-12, "Motor Starters & Contactors Failed to Operate." No response required. D'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/26. ip.
- 7912040434 Forwards requests for relief from inservice insprequirements of ASME Boiler & Pressure Code, Section XI due to impracticality of performing volumetric examinations on welds in several sys.

  PARKER, W. O. Duke Power Co. 79/11/27. 25pp.
- 7912190790 Responds to IE Bulletin 79-17. Revision 1 re stagnant borated water sys. Examination of normally inaccessible portions of Unit 1 for pipe cracks to be conducted during current refueling outage.
  PARKER. H. D. Duke Power Co. 79/11/28. ip.

- 7912190386 Forwards IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Written response required. G'REILLY, J. P. Region 2. Atlanta, Office of the Director. 79/11/30. 1p.
- 79:2140348 Provides supplemental info to 790824 response to IE Mulletin 79-05G. "Nuclear Incident at THI - Suppl." re revision of emergency procedures requiring trip of reactor coolant gumps upon reactor trip. PARKER, M. D. Duke Power Co. 79/12/06. 2pp.
- 7912280017 Updates 790914 response to IE Bulletin 79-21, "Temp Effects on Level Measurements." Completion date of Item 4 changed to no later than B00101.
  PARKER, W. O. Duke Power Co. 79/12/06. ip.
- 7912310293 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances,100FR21." No action required. U'REILLY,J.P. Region 2, Atlanta, Office of the Director. 79/12/06. Spp.
- 7912200026 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EAIBO Limit Switches at Elevated Temps." Action required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/12/07. 2pp.
- 7912310005 Forwards third response to IE Bulletin 79-02, Revision 2, re pipe support base plate designs. Base plate flexibility in calculation of expansion anchor bolt loads accounted for by conservative hand calculation method, PARKER, W. D. Duke Power Co. 79/12/07. 25pp.
- 7712310022 Forwards updates to 771027 & 1106 responses to IE Bulletin 70-14. "Beismic Analysis for As-Built Safety-Related Piping Sys." Provides summary of seismic input nonconformances through 771126.
  PARKER, W. O. Duke Power Co. 77/12/07. 11pp.
- 7912210075 Ack receipt of IE Insp Repts 50-269/79-28,50-270/79-26 & 50-267/79-28 on 791024-26. No proprietary info. PARKER, W. O. Duke Pauer Co. 79/12/10. ip.
- --7912210080 Forwards IE Insp Repts 50-269/79-28,50-270/79-26 & 50-287/79-28 on 791024-26. No noncompliance noted.
  BUTHERLAND.J.T. Region 2. Atlanta, Fuel Facility & Materials Bafety Branch. 79/11/15. 2pp.
- --7912210088 IE Insp Ropts 50-269/79-28, 50-270/79-26 & 50-287/79-28 on 791024-26. No noncompliance noted. Major areas inspected: App B Tech Specs annual reporting requirements & review of nonrouting reports & LERs.
  CUNNINGHAN. A.L. Region 2, Atlanta, Office of the Director.
  HUFHAM. J.W. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/11/14. 3pp.
- 7912210227 Ack receipt of 791109 & 30 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/79-24, 50-270/79-22 & 50-287/79-24.

  KENNA, W. B. Region 2, Atlanta, Bafeguards Branch. 79/12/11.
- --7912210238 Provides add1 info to 791109 response to NRC 790927 ltr rg violations noted in IE Insp Repts 50-269/79-24, BO-270/79-22 & SO-287/79-24. Details withheld (ref 10CFR2.790). PARKER W.O. Duke Power Co. 79/11/30. 1p.
- --7912210248 Responds to NRC 790927 ltr re violations noted in 1E Insp Repts 50-269/79-24, 50-270/79-22 & 50-287/79-24, Details withheld (ref 10CFR2, 790). PARKER, N. D. Duke Power Co. 79/11/09. ip.
- --7912210263 Forwards IE Insp Repts 50-269/79-24,50-270/79-22 & 50-287/79-24 on 790821-24 & 0903-07 Notice of violation withheld (ref 10CFR2 790).
  KENNA, H. B. Region 2. Atlanta, Bafeguards Branch. 79/09/27. 2pp.
- --7912210283 IE Insp Repts 50-269/79-24, 50-270/79-22 & 50-287/79-24 on 790821-24 & 0905-07, Major areas inspected: security organization & physical barriers. Details withheld (ref 100FR2, 790).
  MOORE, D. E., JUHN, W. N. Region 2, Atlanta, Office of the Director. HOMELL, J. C. NRC Regional Offices. 79/09/27. 1p.
- 7912280377 Forwards IE Info Notice 79~31. "Use of Incorrect Amplified Response Spectra." No written response required.
  O'REILLY.J.P. Region 2. Atlanta. Office of the Director.
  79/12/13. 2pp.

- 7912280127 Forwards IE Circular 79-25, "Shock Arrestor Strut Assembly Interference." No written response required.

  O'REILLY, J.P. Region 2, Atlanta, Office of the Director.

  77/12/20. 4pp.
- R. Periodic operating reports & related correspondence
- 7912180375 Forwards monthly operating repts for Nov 1979. PARKER, M. D. Dute Power Co. 79/12/14. 1p.
- --7912180384 Monthly operating repts for Nov 1979. REAVIS.J.A. Duke Power Co. 79/12/14. IApp.
- 5. Reportable occurrences. LERs & related correspondence
- 7912200012 PND-II-79-011: on 791016, while returning low pressure injection 8 train to svr. about 2000 gallons of reactor coulant spilled through partially opened vent valve into west penetration room Facility shut down for insp & repair. HOSEY.C.M., TROUP.G. Region 2, Atlanta, Office of the Director. 79/10/17. lp.
- 7912070103 PNO-II-79-18: on 791028, unit restarted after extended shutdown for refueling & installation of emergency feedwater sys. Increased insp program implemented until unit reaches 75% power.

  PYER, J. A. LEWIS, R. C. Region 2, Atlanta, Office of the Director. 79/10/29. 1p.
- 7912170402 PNO-II-79-031: on 791110, w/reactor at 100% power, main condensate pumps tripped. Caused by technician working on hotueil level control sys which reduced feedwater flow to steam generators.

  QUICK, D. R., MARTIN, R. Region 3. Atlanta, Office of the Director. 79/11/13. 2pp.
- 79121G0556 RD 79/14: on 79111G, during hot shutdown, reactor coolant sys cooldown rate was exceeded. Caused by steam generators being overfed. No immediate corrective action taken. Design & procedural changes currently under review.

  BOND, R. T. Duke Power Co. 79/11/16. Jp.
- 7912130430 Discusses loss of power to integrated control sys during which cooldown limits were exceeded Anticipates submission of RO-287/79-13 by 791130.
  PARKER, N. O. Duke Power Co. 79/11/23. 1p.
- 7912190704 Describes loss of power to nonsafety-related 120 volts ac single phase power panel & resultant sys malfunctions.
  Recommends issuance of encl proposed IE bulletin.
  EISENHUT.D.G. Division of Operating Reactors. 79/11/27. 4pp.
- 7912070439 Forwards LER 79-013/017-0.
  PARKER, W. O. Duke Power Co. 79/11/30. 3pp.
- ~-7912070442 LER 79-013/01T-0: on 791110, RCS cooldown rate exceeded Tech Specs limit after gower to intergrated control sys was lost for approx 2.5 minutes. Caused by blown inverter fuses & transfer switch failure. Redundant switch installed. LEWIS.S.R. Dute Power Co 79/11/30. 1p.
- 7912040474 Responds to NRC 790921 Itr transmitting NRC 790626 ltr re multiple equipment failures & surveillance testing errors. Discusses review of events described in NRC 790926 ltr. Existing procedures & policies address concerns. PARKER. N. O. Duke Power Co. 79/12/04. 2pp.
- 7912120294 Notifies of failure to retain instructions to energize both 4160 volt standy buses w/Lee combustion burbins when Unit 2 was in svc. Caused by inadequate revision to operating procedure for 100 kV power supply on 791130.
  PARKER.W. O. Duke Power Co. 79/12/05. 1p.
- 7912110362 Forwards LER 79-012/03L-0. PARKER, W. O. Duke Power Co. 79/12/07. 1p.
- ~-7912110388 LER 79-012/03L-0: on 791107, during routine insp of turbine bldg basement, excessive packing leakage from low pressure svc water pump 38 discovered. Caused by possible improper tightening of lock nut, Pump repaired & in svc. LEWIS, S. R. Duke Power Co. 79/12/07. 3pp.
- 7912130411 RO: on 791126-30, only one standby bus had been energized by Lee Station gas turbine, although Tech Spacs require both standby buses be energized during hydro outage. Caused by inadequately revised procedures.

  PARKER, W. D. Duke Power Co. 79/12/10. 2pp.

- DOCKET 50-288 REED COLLEGE RESEARCH REACTOR
- F. Security, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Guide 5.XX. "Std Format & Content for Licensee Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance." W/o encl. REID.R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22.
- a. Inspection reports, IE Bulletins & correspondence
- 7912110200 Forwards IE Insp Rept 50-288/79-01.No noncompliance noted. Insp rept withheld (ref 10CFR2.790). NORDERHAVO,L.R. Region 5, Ban Francisco, Bafeguards Branch. 79/11/13. 2pp.
- DOCKET 50-289 THREE MILE ISLAND NUCLEAR STATION, UNIT 1
  F. Security, medical, emergency & fire protection plans
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives. Provides guidance for improving licensee emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions. GRIMES.B.K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- 7912030170 Forwards physical security plan addendum Addendum withheld (ref 10CFR2.790). HERBEIN.J.G. Metropolitan Edison Co. 79/11/27. ip.
- 7912070136 Forwards Revision 6A to modified amended physical security plan. Revision withheld (ref 10CFR2, 790).
  HERBEIN.J.G. Metropolitan Edison Co. 79/11/30. 1p.
- 7912310382 Cites util 791016 commitment to submit design for alternate shutdown station by 791215. Increased workload due to restart has delayed completion of station design. Requests extension until 800315. HERBEIN, J. O. Hetropolitan Edison Co. 79/12/24. 1p.
- 0. Adjudicatory correspondence
- 7912040006 Requests that encl ltr be attached to petition & that citizens be provided w/funding to go through intervenor process.

  BERRYHILL, F. Coalition for Nuclear Power Plant Postponement.
  79/10/29. ip.
- --7912040008 Requests suspension of licensing nuclear power plants. BERRYHILL.F. Coalition for Nuclear Power Plant Postponement. 79/10/29. 2pp.
- 7912050232 Request for financial aid for intervenors to retain experts to submit studies & /or to testify re facility restart.NRC must fund intervenor participation if participation contributes substantially to issue determination.

  COHEN.W.W. Pennsylvania, State of. 79/11/06. 6pp.
- 7912030238 Proposed procedures in response to Mat Ed 791102 proposals. Supports schedule for revised contentions. Objects to consolidation of intervenors per issues interests not sufficiently common to permit cloims joinder. JORDAN. W. S., SHELDÜN, K. P. Feople Against Nuclear Energy. JORDAN. W. S. Sheldon, Harmon & Weiss. 79/11/07. 7pp.
- --7912060242 Reply brief in lieu of pleading on psychological distress issue. Alleges that Atomic Energy Act requires consideration of distress contentions & NEPA requires consideration of sacio-economic impacts. Contends irrelevancy of EIS.

  JORDAN, H. S. & SHELDON, K. P. Poople Against Nuclear Energy.

  JORDAN, M. S. & Sheldon, Harmon & Weiss. 79/11/07. i3pp.
- 7912050180 Notice of appearance of JD Cunningham on behalf of Newberry Township THI Steering Committee, M Minnich, RJ 21oger, LS Carlisla, V Phillips, CH Wolfe, LI Dominoski, PA Smith, DK Umholtz, CH CLark, MD Clark & ML Clock, Clock, CUNNINGHAM, J. D. Fox, Farr & Cunningham. 79/11/08, 1p.
- 7912060095 Submits & confirms licensee offer to produce & mail intervenor documents w/o charge on behalf of intervenors.

  Reserves right to withdraw offer in event of noncompliance w/terms. Certificate of Svc encl.

  TROMBRIDGE, G. F. Shaw, Pittman, Potts & Trowbridge. 79/11/13. 5pp.

- 7912130175 Notice of appearance on behalf of PA Public Util commission. Certificate of Svc encl. MCCLAREN.8.A, Pennsylvania, State of. 79/11/13. 4pp.
- 7912170066 Forwards TMI Alert Contention 4, redrafted to clarify intent. Meant to be security contention, not contention re psychological issues. ADLER, T. A. Widoff, Reager, Selkowitz & Adler. 79/11/13. 1p.
- --7912170070 Revised Contention 4 alleging licensee unreadiness to deal w/specialized nature of civil disruption that may occur due to restarting of facility Certificate of Svc encl.
  ADLER.T.A. Three Mile Island Alert. ADLER.T.A. Widoff, Reager, Belkowitz & Adler. 79/11/13. 2pp.
- 7912060066 Notifies of appearance at 791109 hearing Majority of hearing was directed to psychological distress issues & funding of intervenors, in which Dauphin County did not participate. KNUPP,R.L. Knupp & Andrews. 79/11/14. 1p.
- 7912130169 Notice of appearance in proceeding Certificate of Svc. PAYON.W.D. Hearing Branch 4. 79/11/14. 3pp.
- 7912120522 Discussion on effect of rulemakings upon issues of TMI-1 suspension proceeding. Two issues. Class 9 accidents & emergency planning do not proclude ABLB from considering appropriate contentions. Certificate of Svc sncl.
  SINGER.L.N. Hearing Branch 2. 79/11/16. 14pp.
- 7912170009 Forwards 790809 order & notice of hearing re 790926 ltr of concern on TMT restart.

  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/11/16. lp.
- --7912170019 Order & notice of hearing to examine & resolve safety concerns prior to restart.
  CHILK.S.J. Office of the Secretary of the Commission. 79/11/16.
- --7912170036 Expresses concerns over TMI restart. K19SEL, Q. J. Affiliation Unknown. 79/09/29. 1p.
- 7912030668 Memorandum assuring parties that decision will be based upon whole record including licensee position re placing short-term actions into contest for benefit of public.
  SMITH, I.W. Atomic Safety and Licensing Board Panel. 79/11/19. 2pp.
- 7912130085 Objection to intervenor TMI Alert 791113 revised Contention 4 re potential for civil disruptions following restant. Contention is beyond scope of proceeding. Certificate of Svc encl.

  TROWNRIBGE, O. F. Metropolitan Edison Co. TROWNRIBGE, G. F. Shaw, Pittman, Potts & Trowbridge. 79711/20. Spp.
- 7912050015 Response in opposition to Consumer Advarate of PA potition to seek NRC funding for witness expenses. Current policy does not favor intervenors' funding, per Commission 761112 statement. Certificate of Evc encl.

  SHANSUN, D. T. Hearing Branch 1. 79/11/21. 9pp.
- 7912110384 Response in apposition to UCS 791115 Amended Contention 13. Patitioner failed to identify accident or sequence of events for which intervention sought. Certificate of Svc ancl. YRCHERIDGE.O.F Metropolitan Edison Co. 79/11/21. 9pp.
- 7912140151 Statement of position re preparation of EIS prior to TMI-1 restart.EIB must be issued per MEPA since restart has potential for adversely affocting quality of environ. Certificate of Byc encl.

  SELKOWITZ.L. B.; ADLER.T.A. Three Mile Island Alert. SELKOWITZ.L.B. Hidoff. Reager, Selkowitz & Adler. 79/11/21. 19pp.
- 7912100459 Requests to make limited appearance statement at licensing prehearing.
  BIERNAN.C. Affiliation Unknown. 79/11/29. 1p.
- 791211003B Confirms receipt of encl 790329 petition to suspend OLs for all FMRs. Forwards FR natice indicating that petition will be treated in accordance w/10CFR2.206.
  DENTON, H.R. Office of Nuclear Reactor Regulation. 79/11/23. ip.
- --7912110126 Natice of request for action pursuant to 10CFR2.206 re Environ Coalition on Nuclear Power 790329 petition requesting suspension of all OLs for PWRs. MULLER.D.R. Office of Nuclear Reactor Regulation. 79/11/23.

- 791213030B Memorandum advising ASLB & parties of licensee arrangements for restart rept distribution. ASLB & petitioners will receive updated copy through Amend 9. Subsequent amends will be submitted. W/Certificate of Svc. TRDWBRIDGE, G. F. Metropolitan Edison Co. TRDWBRIDGE, G. F. Shaw, Pittman, Potts & Trowbridge. 79/11/28. App.
- 7912130026 Request for financial assistance to support intervention on psychological distress issues. Commission 761112 decision rejecting financial assistance to intervenors followed by legal opinions allowing aid Certificate of Svc enci. JORDAN. M. S., SHELDDN. K. P. People Against Nuclear Energy. JORDAN. M. S. Shaldon, Harmon & Weiss. 79/11/29. 33pp.
- 7912210422 Amend to petition to intervene in response to President's Commission repts on TMI accident Consequences of Class 9 accident should be evaluated & supplemented to EIS. Certificate of Svc encl.
  8HOLLY, S. C. Affiliation Unknown. 79/11/29. 14pp.
- 7912210423 Brief in lieu of pleading on necessity of new FEB prior to decision on whether to restart facility. Restoring confidence in regulatory agency & process necessary. Class 9 accident should be analyzed & reviewed. Certificate of Svc oncl. KENFORD. C. Environmental Coalition on Nuclear Power. 79/11/29.
- 7912130034 Response to NRC brief re effect of rulemakings on issues of plant suspension proceeding. Concurs w/NRC conclusion that proposed rulemakings have no effect on proprietary adjudicative issues. Certificate of Svc encl.
  TROWBRIDGE, G. F. Metropolitan Edison Co. TROWBRIDGE, G. F. Shaw, Pittman, Potts & Trowbridge. 79/11/30. 15pp.
- 7912130110 Opposition to intervenor S Sholly petition for exception to code re Contention 11. Hydrogen gas control issue is beyond scope of restart proceeding Certificate of Svc encl. TROMBRIDGE, G. F. Metropolitan Edison Co. TROMBRIDGE, G. F. Shaw, Pittman, Potts & Trowbridge, 79/11/30. 15pp.
- 7912180246 Argument for preparation of supplemental EI8 prior to TMI-1 restart. Restart is major federal action requiring E18 under NEPA, ASLB must consider psychological stress as issue affecting quality of human environ. Certificate of Svc encl. CUNNINGHAM, J. D. Newberry Township, York Haven, PA. CUNNINGHAM, J. D. Fox, Ferr & Cunningham. 79/11/30. 9pp.
- 7912200063 Forwards intervenor UCS 791130 reply brief on application of Nati Environ Policy Act. Certificate of Svc encl. WEISB. E. R. Sheldon, Harmon & Weiss. 79/11/30. 1p.
- --7912200066 Reply brist on application of Natl Environ Policy Act. ASL8 should permit UCB Contention 20 to be litigated in proceeding. Act applies to NRC restart decision & to consequences of Class 9 accident.
  WEISB.E.R. Union of Concerned Scientists. WEISB.E.R. Bheldon, Harmon & Waiss. 79/11/20. 27pp.
- --7912200071 Bubmits preliminary comments on NRC 790B13 ltr & draft NEPA regulations.CEG regulations are sufficiently flexible to avoid conflict w/NRC responsibility as independent regulatory agency.Certificate of Svc ancl.
  KNIGHT.C.F. Council on Environmental Quality. 79/09/26. App.
- 7912310142 Requests extension of time to respond to NRC brief on rulemakings, per 791114 prehoaring conference. Urges issuance of EIS containing study of Class 9 accident. Cartificate of Svc encl.
  AMMDDT. M. Affiliation Unknown. 79/11/30. 6pp.
- 7913130130 Opposes intervenor UCS amended Contention 13 re Class 9 accidents & intervenor TMI Alort amended Contention 4 re plant security plan. Supports certification of 8 Sholly petition. Certificate of 5vc encl.
  MULKEY, M. E. Hearing Branch 2. 79/12/03 7pp.
- 7912180162 Request to file brief addressing issues raised by NRC 791121 response to Consumer Advocate of State of PA request for NRC funding of intervener witnesses. Issues are novel & of first impression. Certificate of Evc encl. COHEN, W. W., KENNARD, N. J. Pennsylvania, State of. 79/12/03. Opp.
- 7912180193 Brief in lieu of pleading supporting intervanor patition for witness funding. Commission discretionary powers.congress intent & President Carter 790516 Executive Order allow financial grants to intervenors. President Order encl. COHEN. W. H. . KENNARD. N. J. Pennsylvania. State of. 79/12/03. 24pp.
- 7912180082 Requests submission of legible version of Contention 6.
  Excerpt from transcript containing illegible version encl.
  SMITH, I. W. Atomic Safety and Licensing Board Panel. 79/12/05. 6pp.

- 79:2270087 First set of interrogatories. Requests info re radiation releases into atmosphere & water & method of measurement, sorticeconomic consequences, plant security plans & util financial & plant physical history. Certificate of Svc encl. ADLER, T.A. Three Mile Island Alert. ADLER, T.A. Hidoff, Reager, Selkowitz & Adler. 79/12/06. 40pp.
- 7912130243 Forwards responses to NRC supplementary requests for financial info for restart proceeding.

  HAFER F. D. General Public Utilities GPU Service Corp. 79/12/07.
- 7912270082 Submits boliday schedule for licensee discovery reading room & observation ctr.
  TROUBENDOE, O.F. Metropolitan Edison Co. TROUBENDOE, G. F. Shaw,
  Pittman, Potts & Trowbridge. 79/12/07. 4pp.
- 7912310196 Supplements NRC 791031 brief re need for FES prior to TMI-1 restart Suggests ASLB reserve judgment pending release of EIA currently being prepared by NRC. Hearing re need for FES must not be allowed to develop into full OL hearing. TROMBRIDGE.G.F. Metropolitan Edison Co. TROMBRIDGE.G.F. Bhaw, Pittman, Potts & Trombridge. 79/12/07. 11pp.
- 7912270095 Comments on Kemeny Commission rept.Forwards supplementary arguments to Contentions i through 11. W/Certificate of Syr. LEWIB.M. 1. Affiliation Unknown. 79/12/10. 7pp.
- 7912260100 Response in opposition to SC Sholly 791129 contentions. Commission past policy that Class 9 environ consequences need be considered absent NRC recommendation, recently reaffirmed. Certificate of Svc encl.
  TROMBRIDGE.G.F. Metropolitan Edison Co. TROMBRIDGE.G.F. Bhaw. Pittman. Potts & Trowbridge. 79/12/11. 12sp.
- 7912260293 Opposes intervenor People Against Nuclear Energy 791129 request for financial assistance to support intervention on issue of psychological distress. ASLB should not be burdened w/add1 procedural responsibilities during course of hearing. TROMBRIDGE, G.F. Hetropolitan Edison Co. TROMBRIDGE, G.F. Shaw, Pittman. Potts & Trowbridge. 79/12/11. 7pp.
- 7912190806 Notifies that NRC will not supplement arguments advanced in 791031 briefs on psychological distress issues & 791031 brief in response to contentions.

  MULKEY.M.E. Hearing Branch i. 79/12/13. ip.
- 7912270111 First set of interrogatories. Requests info re state officers notified of TMI accident, radiation dose readings received by Commonwealth of PA & util accounts made to Commonwealth of PA. Certificate of Svc encl.
  ADLER.T.A. Three Mile Island Alert. ADLER.T.A. Widoff, Reager, Selkowitz & Adler. 79/12/13. 10pp.
- 7912260362 Motion to withdraw intervenor 791005 third contention re inadequacy of emergency planning Remaining contentions on psychological distress & threat to community health shall be pursued. Cartificate of Svc encl.
  JORDAN, M. S. People Against Nuclear Energy. JORDAN, W. S. Sheldon, Harmon & Weiss. 79/12/15. Rpp.
- 7912270011 First special prehearing conference order re scope of proceedings. Class 9 contentions ruling deferrals & contentions of UCS. TMS Alerts MM Aamodts Anti-Nuclear Group Representing York, B Sholly & Chesapeake Energy Alliance.

  JORDAN, W. B., LITTLE, L. W., SMITH, I. W. Atomic Safety and Licensing Board Panel, 79/12/18. 67pp.
- 7712310120 Supports S Shally 771130 Contention 16, sub, to provision of adequate specificity by discovery Opposes Contention 17 rs variations of 790328 accident Issue of variations need not be settled at prehearing.
  MULKEY, M. E. Hearing Branch 2, 79/12/20. 5pp.
- 7912310138 Response to MI Lewis 791210 discussion of interest & previous contentions. Urgas preservation of ASLB 791218 first special prehearing conference order ruling on MI Lewis interest & contentions. Certificate of Svc enci.
  MULKEY, M. E. Hearing Branch 2. 79/12/20. 3pp.

# H. General correspondence

- 7912120258 Responds to 790806 ltr re D Bmith concerns about facility restart Forwards MRC 770807 order specifying basis for shutdown, procedures for restart hearings & itoms which must be resolved prior to restart.
  608816K.L.V. Office of the Executive Director for Operations.
  79/10/04. 2pp.
- 79:2040063 Requests site access for representatives of IAEA COLLING.J.T. TMI-2 Operations/Support. 79/10/31: 2pp.

- 7912180660 Responds to concern re delay in restart of facility.
  Outlines facility history since 790702 NRC 790809 order
  specifying basis of shutdown order & procedures to govern
  restart hearings encl. W/o encl.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/28. 2pp.
- 7912190391 Responds to 791109 ltr re psychological stress & reactivation of facility. Psychological stress not statutory responsibility of NRC.
  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/11/30. 1p.
- 7912100341 Forwards updated svc distribution list for correspondence.
  Original copy of correspondence should be sent to new address.
  ARNOLD.R.C. Metropolitan Edison Co. 79/12/04. App.
- 7912180521 Forwards updated svc copy distribution list for facility. ARNOLD R. C. Metropolitan Edison Co. 79/12/04. 4pp.

#### I. Financial information

- 7912040349 Forwards supplementary response to initial financial info request & addi response to Supplementary Financial Request 9 requiring Net Ed to show cause why certificate of public convenience should not be revoked. HARER, F. D. General Public Utilities - GPU Service Corp. 79/11/27.
- 7912040087 Forwards 4ddl response to NRC Supplemental Financial Request 9 requiring Met Ed to show cause why certificate of public convenience should not be revoked. Requests acknowledgement of receipt of matl.

  MAFER.F. D. General Public Utilities CPU Service Corp. 79/11/29.
  148pp.
- 7912050511 Forwards info in response to NRC 791109 supplementary requests for financial info re restart proceeding.PA Public Util Commission 791127 prehearing conference transcript encl.
  HAFER.F.D. General Public Utilities GPU Service Corp. 79/12/03.
- 7912260219 Forwards addit response to Supplementary Financial Info Request 9 alternative means of supplying JC P&L svc territory, in response to NRC 791109 request for financial info.

  HAFER, F. D. General Public Utilities GPU Service Corp., 79/12/20.600no.
- P. Operating license stage documents & correspondence
- 7911090248 "Summary of Operating Experience W/Recirculating Steam Generators." EISENVALT, D. O. Division of Operating Reacturs. NUREG-0523. 79/01/31. 87pp.
- 7908010339 Notifies of status of rept on reactor cavity annulus seal.

  Most PHR users remove ring during normal operation. Others
  store seal ring in raised position during normal operation.

  LAINAG. Plant Systems Branch (Pre 791030) 7970705 7pp.
- 7912030174 "Recommended Requirements for Restart of TMI~1." Vol 1. Amends 1-5 have been incorporated w/original text. \* Metropolitan Edison Co. 79/09/12. 300pp.
- 7712040153 Forwards request for add1 info to supplement TMI-1 "Restart Rept;" per 791017 meeting in Middletown, PA. Response required by 791107. Submittal scheduled for wk of 791022 not yet received.

  VDLLMER.R.H. TMI-2 Operations/Support. 79/10/26. 22pp.
- 7911140314 Forwards matl presented at 791017 meeting w/util in Middletawn:PA re TMI-1 restart rept. VOGLEHEDS:J.C. Core Parformance Branch. 79/10/29. 7pp.
- 7912200233 Forwards index of B&N generic correspondence re resolution of issues associated w/177 Fuel Assembly plants including TFKF-1. Certificate of Svc encl.

  SQUDER, J. L. Division of Rules and Records. 79/11/05. 7pp.
- 7912070004 Requests distribution of encl memorandum to board notification svc lists.

  VARQA,S.A. Assistant Director for Light Water Reactors, 79/11/08.
- --7912070030 Recommends that info on cracking in stagmant boron lines are provided to pertinent boards, in response to 790830 memorandum.

  KNIOHT, J. P. Assistant Director for Engineering, 79/10/24, 2pp.

- ---7912070038 Submits Operating Experience Memo 17 re pipe cracks in borated water sup at TMI-1.Results of Met Ed ultrasonic examination of certain Type 304 stainless steel piping encl. EISENMUT.D.G. Division of Operating Reactors. 79/10/05. 4pp.
- 7912130184 Forwards summary of Teknekron Research. Inc study of licensee regulatory performance evaluation & Teknekron draft rept re operating reactors w/B&W nuclear steam supply sys. Requests comments. W/o encl.
  BTELLO, U. Office of Inspection & Enforcement, Office of the Directur. 79/11/08. 2pp.
- 7912100189 Discusses NRC '791101 meeting w/representatives of NSSS vendors & fuel suppliers re discussion of respective partions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EISENHUT.D.O. Division of Operating Reactors. 79/11/09. 65pp.
- --7912100285 Responds to NRC 791101 request re noncompliance of Westinghouse ECCS evaluation model under requirements of 10CFR50 App K. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants. ANDERSON, T. M. Westinghouse Electric Corp. 79/11/02. 4pp.
- --7912100330 Responds to NRC 791101 request re CRNL cladding swelling & rupture data. Review of analytical models & tests indicates compliance w/iOCFR50 App K. All OE specs for calculated peak cladding temp remain unchanged.

  BUCHHOLZ,R, H. General Electric Co. 79/12/07. 2pp.
- ---7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50.46 satisfied.

  ONSILEY.G.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/11/02. 5pp.
- --7912100456 Forwards add1 info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. GMSLEY.G.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/04. 22pp.
- 7912200336 Requests addl info to complete draft safety evaluation on TMI-1 restant. Addl info includes design features, solid radwaste & sump pumping & sampling procedure. LEE, J. T. TMI-2 Operations/Support. 79/11/14. 2pp.
- 7912110102 Forwards list of items for TMI-1 restart resulting from TMI-2 Lessons Loarned Task Force rept in response to 791017 request.

  VOLLMER.R.H. TMI-2 Operations/Support. 79/11/19. 7pp.
- 7912120092 Summary of 791024 meeting w/NEW owners group re asymmetric LOCA loads evaluation. Evaluation of B&W plants to be completed by Jul 1980. HOSFORD. S.B. Assistant Director for Engineering Programs. 79/11/20. App.
- 7912040440 Forwards request for addl info re lessons learned items. Response required by 79112B, VOLLMER.R.H. TMI-2 Operations/Support. 79/11/21. 19pp.
- 7912040100 Responds to telegram re release of Kr-85 NRC evaluation of environ impact will precede any radioactive release Forwards environ assessment of use of EPICOR-II. W/o encl. VOLLMER.R. H. Assistant Director for Systems & Projects. 79/11/23. 1p.
- 79120500B1 Requests detailed info on wear characteristics of control rods on fuel assembly guide tubes. Bignificant guide tube wear could impode control rod scram capability & affect coolable geometry of core. Meeting scheduled 791220.

  REID.R.W. Operating Reactors Branch 4. 79/11/23. 7pp.
- 7912030033 Notification of 791205 meeting w/util in Bethesda.MD to discuss any remaining questions in restart review.

  SILVER.H. NRC Three Mile Island Task Force. 79/11/26. 4pp.
- 7712200139 Forwards request for addl info re containment purge sys. LAINAS. G. Plant Systems Branch. 79/11/26. 4pp.
- 7912030320 Forwards Amend 7 to: "TMI-1 Restart Rept."
  HERBEIN, J. G. Metropolitan Edison Co. 79/12/03. 1p.
- --7912050325 "TMI-1 Restart Rept." Amend 7.
  \* Metropolitan Edison Co. 79/12/03: 100pp.

- 7912060340 Forwards Amend B to 790912 restart rept in response to NRC 791121 ltr. HERBERN J. G. Metropolitan Edison Co. 79/12/04. lp.
- --7912060349 Amend 8 tu 770912 restart rept providing addl info re solid waste disposal sys.mobile solidifation sys.plant sheilding & auxiliary bldy ventilation sys. \* Metropolitan Edison Co. 79/12/04. 5pp.
- 7912060346 Forwards revised Section 5.2 of TMI-1 restart rept. HERBEIN, J. G. Motropolitan Edison Co. 79/12/04. 1p.
- --7912060355 Revised Section 5 2 of TMI-1 restart rept re station organization.

  \* Metropolitan Edison Co. 79/12/04. 67pp.
- 7912120401 Forwards updated svc distribution list.Notifies of address change for original correspondence.
  ARNDLD, R. C. Metropolitan Edison Co. 79/12/04. 4pp.
- 7912190617 Notifies of Class III fee for review of 791101 application requesting extension of surveillance interval for reactor vessel internal vent valves.

  MILLER.W. O. License Fee Management Branch. 79/12/04. Jp.
- 7912100328 Responds to 791121 request for verification re moderator dilution accidents.All potential pathways for initiation of accident reviewed. Both manual valves closed prior to inservice insp of engineered safequards.

  HERDEIN.J. Q. Metropolitan Edison Cn. 79/12/05. ip.
- 7912260309 Requests info re sensitivity-to-feedwater transients be forwarded to TMI-1 Board.
  VULLMER.R.H. Assistant Director for Systematic Evaluation Program (Pre 791030). 79/12/05. 3pp.
- --7912260315 Responds to request re design adequacy of N&W NSSS utilizing once-through-steam generators (Bellefonte Nuclear Plant).
  Response requested by 791203 Necessary sys mods considered as part of post-TMI-2 effort.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/25. 4pp.
- --7912260346 "Primary Sys Perturbations Induced by Once-Through Steam Generators." Feedwater transient summary encl. \* Office of Nuclear Reactor Regulation. 79/10/25. Spp.
- --7912260348 "IREP Initial Plant Study." Attempts to develope assessment of B&W reactors to identify risk impacting sequences re reactor safety study & preliminarily identify possibly impacted by design changes.

  \* Office of Nuclear Reactor Regulation. 79/10/25. 4pp.
- 791221011B Forwards requests for additionacial & technical info. VOLLMER, R. H. TMI-2 Operations/Support. 79/12/06. 7pp.
- 7912120414 Responds to 790814 request for addl info re degraded grid voltage. Response to Items 1 & 2 entl Item 3 still being evaluated. Response will be sent by 791221. HERBEIN J. G. Metropolitan Edison Co. 79712/10. 3pp.
- 7912200513 Informs that mods are being made to auxiliary fuel handling bldg exhaust ventilation sys. Ruquests postponement of Tech Specs Change Request 7A submitted on 791028, pending completion of ventilation sys mods.

  HERSEIN, J. G. Motropolitan Edison Co. 79/12/12. ip.
- 7912180254 Forwards Amend 9 to 790912 startup rept. HERBEIN, J. C. Metropolitan Edison Co. 79/12/14. 1p.
- --7912180257 Amend 9 to 790912 startup rept. \* Metropolitan Edison Co. 79/12/14. 198pp.
- 7912270523 Forwards nuclear instrumentation data for Jan 1979, verifying that calibr moets specs. Once-per-shift calibr adequate.
  HERBEIN. J. G. Metropolitan Edison Co. 79/12/18. 3pp.
- 7912310378 Cites NRC 790921 ltr re inadvertent reactor scram & safety injection occurring during monthly surveillance testing of safeguards sys.Required reviews in response to ltr not complete since review parallels restart activity. HERBEIN J. G. Metropolitan Edison Co. 79/12/24. lp.

- Inspection reports, 1E Bulletins & correspondence
- 7912280286 Forwards combined IE Insp Repts 50-289/79-17 & 50-320/79-19 on 790717-19. No noncompliance noted. CARLSON.R.T. Region I. Philadelphia, Reactor Construction & Engineering Support Branch. 79/09/26. 2pp.
- --7912280301 IE Insp Repts 50-289/79-17 & 50-320/79-19 on 790717-19. No noncompliance noted Major areas inspected: fire prevention & protection program outstanding items in area of fire protection & control room panel electrical fire & Control room panel electrical fire & COLTAY,P., CHAUDHARY,S.M. Region 1, Philadelphia, Defice of the Director. EINSTER: S.D. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/09/26. 3pp.
- 7912040166 Forwards IE Insp Ropts 50-289/79-18 & 50-320/79-22 on 790718-0814. Region 1, Philadelphia, Office of the Director. 79/10/01. 2pp.
- --7912040179 IE Insp Repts 50-289/79-18 & 50-320/79-22. Noncompliance noted uncontrolled high radiation areas failure to use breathing air sys properly & improper calibr of equipment used to measure airborne concentrations.

  CROCKER.H.P.: HAVERKAMP.D.R.: NEELY.D.R. Region 1, Philadelphia, Dffice of the Director. 79/09/18. 38pp.
- 7912170220 Forwards response to IE Bulletin 79-24, "Frozen Lines." Safety-related lines subj to freezing temps identified & reviewed. Procedure developed to inspect lines to assure adequate protection during extremely cold weather. HERBEIN, J. G. Metropolitan Edison Co. 79/11/06. 2pp.
- 7912180496 Forwards response to IE Bulletin 79-15, "Deep Draft Pump Deficiencies." Util will make available on site detailed info on pump design, spec, history & procedures. Design specs for pumps being met, HERBEIN, J. G. Hetropolitan Edison Co. 79/11/06, 7pp.
- 7912260051 Farwards IE Insp Rept 50-289/79-15 on 790730-31 & 0814-15. No noncompliance noted CARLSNN.R.T. Region 1. Philadelphie: Reactor Construction & Engineering Support Branch. 79/11/07. 2pp.
- --7912260056 IE Insp Rept 50-289/79-15 on 790730-31 & OB14-15.No nancompliance noted. Major areas inspected: licensee examination program of stagnant piping sys.

  JERNIGAN. E.P., HALTON. G.A. Region 1, Philadelphia, Office of the Director. TRIPP.L.E. Region L. Philadelphia, Reactor Construction & Engineering Support Branch. 79/11/06. 4pp.
- 7912060643 Ack receipt of 791004 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-289/79-10.
  CARLSON.R.T. Region 1. Philadelphia. Reactor Construction & Engineering Support Branch. 79/11/09.
- --7712060633 Responds to NRC 790906 itr re violations noted in IE Insp. Rept 50-289/79-10 on 790419-0612 Currective actions:will monitor contractor performance in all inservice insps. including audit of Nuclear Energy Svcs.
  HERBEIN.J. G. Metropolitan Edison Co. 79/10/04. 3pp.
- --7912060656 Forwards IE Insp Rept 50-289/79-10 on 790417-0612 & notice of violation. CARLSDN.R.T. Region i, Philadelphia, Reactor Construction & Engineering Support Dranch. 79/09/06. 2pp.
- --7912060658 Notice of violation from insp on 790419-0612.

  Region 1. Philadelphia, Office of the Director, 79/08/28.
- --7912060664 IE Insp Rept 50-289/79-iD on 790419-0612 Noncompliance noted deficiencies in inservice insp on 790220-0310, similar to those found during previous inservice insps. EDNETER, B. D. CARLSIN, R. T. Region 1. Philadelphia, Reactor Construction & Engineering Support Branch. DEVLIN, J. W. Region 1, Philadelphia, Safeguards Branch. 79/08/28. 27pp.
- 7912050260 Forwards IE Info Notice 79-27. "Steam Generator Tube Ruptures at Tuo PWR Plants." No response required. GRIER, B.H... Region I. Philadelphia. Office of the Director. 79/11/16. 1p.
- 7912100127 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/11/16. ip.

- 7912280264 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valve." No written response required. GAIER.B.H. Region I, Philadelphia, Office of the Director. 79/11/16. ip.
- 7912i104i5 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required. ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/11/19. 1p.
- 7912050248 Forwards IE Bulletin 79-24, "Boron Loss From BHR Control Blades." No response required.
  GRIER,B.H. Region i, Philadelphia, Office of the Director.
  79/11/20, 1p.
- 7912060576 Furwards IE Circular 79-24. "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BMRs." No response required.

  GRIER, B. H. Region i. Philadelphia. Office of the Director.

  79/11/26. ip.
- 79:21:10054 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required.
  ORIER.B. H. Region 1, Philadelphia, Office of the Director.
  79/11/26. 1p.
- 7912190034 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Written response required.

  ORIER, B. M. Region 1, Philadelphia, Office of the Director. 79/11/30, 1p.
- 7912190752 Forwards IE Bulletin 79-28, "Possible Malfunction of Names Model EA180 Limit Switches at Elevated Temps." Written response required. ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/12/07. 1p.
- 7912280204 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra," No written response required.
  ORIER, B. H. Region 1, Philadelphia, Office of the Director.
  79/12/13. 1p.
- R. Periodic operating reports & related correspondence
- 7912040090 Orants request for extension to 800601 for submitting annual radiological environ operating rept for 1979. COLLING.J.T. TMI-2 Operations/Support. 79/11/13. 3pp.
- 7912200365 Forwards monthly operating rept for Nov 1979. HERBEIN, J. 9. Metropolitan Edison Co. 79/12/17. ip.
- --7912200368 Monthly operating rept for Nov 1979. STAIR, J. R. Metropolitan Edison Co. 79/12/17. Spp.
- S. Reportable occurrences. LERs & related correspondence
- 7912040043 RG 79-17/1P: on 79110B support boltings for rigid anchor DHH-127A found to be inadequate in design & installation. Details & corrective action will be addressed in followup rept.
  POITS, W. E. Metropolitan Edison Co. 79/11/08. lp.
- 7912180051 PNO-TMI-79-05: on 791121,RH Vollmer & JT Collins will attend briefing on current TMI activities in Annapolis.MD Briefing sponsored by State of MD & will include representatives from Met Ed.PA Dept of Environ Resources & NRC.
  CGLLINS.J.T. Office of Inspection & Enforcement, Office of the Director. 79/11/21. 1p.
- 7912130367 Forwards LER 79-017/01T-0.
  HERBEIN.J. G. Metropolitan Edison Co. 79/11/26. 1p.
- --7912130479 LER 79-017/01T-0: on 791108, during insp required by IE Bulletin 79-14, size of support bolting for rigid anchor DHH-127A found inadequate in design & installation, Caused by wrong size bolts. Redesigned support to be installed.
  MITCHELL, D. G. Metropolitan Edison Co. 79/11/26. 2pp.
- 7912120333 Requests extension until 800301 to submit analysis of loads & load height due to need to work on restart items. No plans to ship spent fuel prior to Mar 1980.

  HERBEIN.J. G. Metropolitan Edison Co. 79/12/05. Ip.

7912270323 Forwards LER 79-017/01T-1.
HERBEIN, J. O. Metropolitan Edison Co. 79/12/11. ip.

- T. Hearing transcripts on non-antitrust matters
- 7912030009 Transcript of 791108 restart proceeding in Harrisburg, PA. Pp 1-283.

  \* Commission. 79/11/08. 288pp.
- 7912280477 Transcript of Senate Committee on Environ & Public Works, Subcommittee on Nuclear Regulation 791108 hearing re TMI cleanup.Pp 1-97. DIECKAMP.H. Metropolitan Edison Co. THIESING.J.W. Bechtel Corp. HILSON.R. General Public Utilities - GPU Service Corp. 79/11/08.
- 7912280479 Transcript of Senate Committee on Environ & Public Horks, Subcommittee on Nuclear Regulation 791109 hearing re TMI cleanup.Pp 1-69. LOOMIS,P.A., LEVY.A. Securities & Exchange Commission. GRAHAM,J. General Public Utilities - GPU Service Corp. 79/11/09. 71pp.
- U. Congressional/Executive Correspondence
- 79:2120243 Responds to 7908:3 ltr re D Smith request for info concerning proposed 2-year delay for facility restart. Forwards NRC 790809 order specifying basis for shutdown, procedures for restart & items which must be resolved. GBSSICK.L.V. Office of the Executive Director for Operations. 79/10/04. 2pp.
- --7912120250 Forwards DW Smith 790731 request for info re proposed NRC 2-year delay for facility restart. SMUSTER.B. House of Rep. 79/08/13. 2pp.
- 7912120226 Responds to 790802 ltr re impact of facility shutdown on consumer prices of electricity. Forwards NRC 790809 order specifying basis for shutdown NRC does not have info needed to estimate impact of shutdown on consumer prices.

  OOSSICK.L.V. Office of the Executive Director for Operations, 79/10/12. 2pp.
- --7912120233 Request info re restart of facility & estimate of impact facility shutdown on consumer prices. MARKS.M.L. House of Rep. 79/08/02. 1p.
- 7912040081 Requests opportunity to express opinions re TMI-1 restart before subcommittee Requests assistance in suspending restart hearing until Kemeny rept recommendations implemented.
  ROTH.J.L. Three Mile Island Alert. 79/11/10. 2pp.
- 7912280471 Responds to 790516 ltr re constituent petitions requesting parmanent shutdown of facilities. NRC will conduct hearing prior to restart of Unit 1. Licensee has not submitted proposal for recovery of Unit 2. gossick.L.V. Office of the Executive Director for Operations. 79/11/29. 2pp.
- --7912280486 Notifies that Executive Board of East York Elementary School PTA 790430 resolution & York Committee for Sale Environ petition requesting plant shutdown have been forwarded to Director of Nuclear Reactor Regulation.

  BHAPAR, H. K. Office of the Executive Legal Director. 79/06/13.
- ---7912280489 Forwards Executive Board of East York Elementary School PTA 790430 resolution & York Committee for Safe Environ petition requesting plant shutdown Requests comment. KANMERER, C. Office of Congressional Affairs. 79/06/01. 1p.
- ---7912280493 Ack receipt of 790516 ltr forwarding Executive Board of East York Elementary School PTA 790430 resolution & York Committee for Safe Environ petition requesting plant shutdown. KAMMERER, C. Office of Congressional Affairs, 79/06/01. lp.

- DOCKET 50-293 PILORIM NUCLEAR POWER STATION, UNIT 1

  F. Security, medical, emergency & fire protection plans
- 7912110428 Summary of 790925 meeting w/util in Plymouth NA repreliminary review of emergency planning.
  HANNON, J. N. Operating Reactors Branch 3. 79/10/18. 4pp.
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives. Provides guidance for improving licenses emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions. GRIMES. B. K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- 7912190326 Requests Class lil fee re security force training & qualification plan for review approval. Fee first requested 790924. Fee required within 15 days of receipt of ltr. HILLER. W. O. License Fee Management Branch. 79/11/26. lp.
- 7912140007 Requests revisions & add1 info re safeguards contingency plan submitted by 790403 ltr.NRC comments on plan withheld (ref 10CFR2.790).

  1PPQLITO, T. A. Operating Reactors Branch 3. 79/11/28. 2pp.
- 7912120440 Conditionally accepts NRC personnel radiation braining certification program. Discusses needed restrictions re length of certification, site specific indoctrinations & presentation of certificates.

  ANDOGNINI. G. C. Boston Edison Co. 79/11/30. Ip.
- 7912310312 Forwards revised safeguards contingency plan.Plan withheld (ref 10CFR2.790).
  ANDOGNINI.G.C. Boston Edison Co. 79/12/20. 1p.
- O. Adjudicatory correspondence
- 7912270321 Forwards summons & complaint issued by State of MA against util, as result of excessive radiation exposure to plaintiffs. ANDODNINI, G. C. Boston Edison Co. 79/12/20. 14pp.
- P. Operating license stage documents & correspondence
- 7912170106 Requests addl info re 791019 request for deletion of FSAR Amend 35 concerning containment air dilution sys. Forwards GE Toch Spacs for use as models in propering appropriate specs. IPPOLITG, T. A. Operating Reactors Branch 3 (Pre 791030). 79/10/30.
- --791217010B Tech Specs for post-accident monitoring instrumentation, containment sys & special test exceptions.

  \* General Electric Co. 79/10/30. 10pp.
- 7912100189 Discusses NRC 791101 meeting w/representatives of NSSS vendors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture vendor responses encl. EISENHUT.D. G. Division of Operating Reactors. 79/11/09. 65pp.
- --7912100255 Responds to NRC 791101 request re noncompliance of Westinghouse ECCS evaluation model under requirements of IOCFR50 App K. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants.
  ANDERSON, T. M. Wostinghouse Electric Carp. 79/11/02. 4pp.
- --7912100330 Responds to NRC 791101 request re ORNL cladding swelling & rupture data Review of analytical models & tests indicates compliance w/1007830 App K. All GE specs for calculated peak cladding temp remain unchanged.
  BUCHHOLZ, R. H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50.46 satisfied.

  OMSELY, O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/11/02. Spp.
- --7912100456 Forwards addl info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. OWSLEY, O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/04. 22pp.
- 7912070476 Forwards Amend 38 to License DPR-35, safety evaluation & notice of issuance & availability.
  IPPOLITO, T. A. Operating Reactors Branch 3. 79/11/23. 2pp.

- --79:2070483 Amend 38 to License DPR-35 changing Tech Specs to relax pump operability requirements in sys where spare pumps are installed in occess of requirements.

  IPPOLITO.T A Operating Reactors Branch 3. 79/11/23. 7pp.
- --7912070405 Safety evaluation supporting Amend 38 to License DPR-35.

   Office of Nuclear Reactor Regulation. 79/11/23. 2pp.
- --7912070488 Notice of issuance & availability of Amend 38 to License DPR-35.
  IPPOLITO.T.A. Operating Reactors Branch 3. 79/11/23. 2pp.
- 7912040259 Forwards specific & comprehensive info per NRC 790713 request re BWR. Requests clarification on specific requirements re valve position.
  ANDOGNINI, G. C., MCGUIRE, P. J. Boston Edison Co. 79/11/26. 75pp.
- 7912280178 Advises of Equifar study re feasibility of performing epidemiologic studies on health effects of exposure to low level ionizing radiation. Requests cooperation. IPPOLITO. N. A Operating Reactors Branch 3. 79/11/27. 1p.
- 7912280189 Advises of Equifax study re feasibility of performing epidemiologic studies on health effects of exposure to low level ionizing radiation. Requests cooperation. 1PPOLITO.Y.A. Operating Reactors Branch 3. 79/11/27. 1p.
- 7912140250 Ack receipt of 790109 to 0821 ltrs recontainment purging.
  Util justified unlimited operation of valves involved only
  in containment differential pressure operation, Add info
  required recontainment purging in exchanical area.
  JPPOLITO.T.A. Operating Reactors Branch 3. 79/11/28. 4pp.
- 7912120419 Responds to 791031 ltr requesting util to submit schedule for plant unique analysis for Mark I containment long-term program. Refers to Mark I numers group 791130 ltr voicing concern on subj.
  ANDOGNINI.G.C. Boston Edison Co. 79/11/30. 1p.
- 7912310011 Requests cooperation in allowing some NRC TLD stations to co-locate w/util TLD stations. Advises of 791210 meeting w/MA Dept of Heelth re TLD stations. FMITH, G.H. Region 1. Philadelphia, Fuel Facility & Materials Safety Branch. 79/12/04 2pp.
- 7912120333 Forwards "Multiple Controlled Cell Ramoval," delineating of the methodology for determining that removal of one or multiple controlled cells during cald shutdown leads to less reactive state.
  ANDIGONINI.G.C. Boston Edison Co. 79/12/07. 1p.
- --7912120337 "Multiple Controlled Cell Removal." ANTONDEDULOS, P. Boston Edison Co. 79/11/30. 50pp.
- 7912260077 Notification of 791211 meeting w/util in Bethesda.MD re electrical design of engineered safety feature override circuitry.per criteria of NRC 791188 ltr. HANNON.J.N. Operating Reactors Branch 3. 79/12/07. 1p.
- 7912270144 Forwards util response w/o attachments to 791026 notice of violation & of proposed imposition of civil penalties in response to State of MA 791126 request Attachments withheld (ref 10CFH2.790) M/o encl.
  STELLO.V. Office of Inspection & Enforcement, Office of the Director. 79/12/07. 1p
- 7912260242 Forwards "Supplemental Reload Licensing Submittal Por Filgrin Nuclear Power Station Unit 1.Reload 4." & Class III fee.supporting request for changes to App A of lech Specs. HONARD.J. E. Boston Edison Co. 79/12/12. 39pp.
- ---7912260246 "Supplemental Reload Licensing Submittal for Pilgrim Nuclear Power Station Unit 1.Reload 4." supporting changes to App A of Tech Specs. RASH.J.L. Ogneral Electric Co. NEMD-24224. 79/11/30. 25pp.
- 7912280064 Request submittal of Class II amend for ro 790888 transmittal of simulator retraining program, NRC 791083 ltr requesting fee has not boen answered.
  MILLER, W. O. License Fee Management Branch. 79/12/14. 1p.
- 7919270320 Responds to 791022 ltr re review of interim positions for containment purge & vent valve operation & conformance of operation to positions. Furge isolation valves used for inerting 24th after startup.
  HOHARD.J.E. Boston Edison Co. 79/12/19. Jpp.

- 7712270419 Forwards complete offsite power outage history, containing responses to NRC 770718 questions. Description of intended transmission line mods to minimize frequency of simultaneous 345 tv line outages due to lightning encl.
  ANDOGNINI.G.C. Boston Edison Co. 77718720 43pp
- Q. Inspection reports, If Bulletins & correspondence
- 7912210011 Requests add1 info re Dergen-Patterson hydraulic shock suppressor accumulator spring cells to evaluate adequacy of util response to IE Bulletin 78-10. GRIER-B.H. Region L. Philadelphia, Office of the Director. 79/09/13. 2pp.
- 7912050252 Forwards IE Insp Rept 50-293/79-12 on 790705-06 No noncompliance noted. MARTIN.W.9. Region 1, Philadelphia, Bafeguards Dranch 79/10/04. 200.
- --7912080262 IE Insp Rept 50-293/79-12 an 790705-06. No noncompliance noted Major areas inspected verification & evaluation of actions re-physical protection program. Details withheld (ref 10CFR2 790).

  JONES E. M. Region 1. Philadelphia. Defice of the Birector DEVLING. M. Region 1. Philadelphia. Sefequends Branch, 79/09/27. 1p.
- 7912070123 Ack receipt of 791002 ltr informing NRC of steps taken to correct violation noted in IE lnsp Rept 50-293/79-09.
  BRUNNER, E. J. Region i, Philadelphia, Reactor Operations Muclear Bupport Branch. 79710/22. Ip.
- --7912070126 Responds to NRC 790910 ltr re violation inited in IE Image Rept 50-293/79-09 Corrective actions: procedures updated to specify coolant injection valve locking. ANDOGNINI.G.C. Bostom Edison Co. 79/10/02, Upp.
- ---7912070132 Forwards IE losp Rept 30-293/79-09 on 790514-11, 31-25, 27-31 & 0601 & notice of violation.
  BRUNNER, C. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79709/10. Spp.
- ~~7912070134 Notice of viniation from insp on 790514~18.21~요하.요약~31 및 0603. # Region 1, Philadelphia, Office of the Director. 74709707.
- ---7912070139 IE thep Rept 50-893779-09, Noncompliance noted procedures do not specify valve locking position & valve documented locked in wrong position and the state of the ARCHITECLUR, MARKONGKIR. Region 1. Philadelphia, iffice of the Director. MCCABE.E.C. Region 1. Philadelphia, Hearter liperations Nuclear Hupport Dranch. 79709707. 20pp.
- 7910140206 Responds to IC Bulletin 79-24, "Frozen Lines " Identifies stack sample line as only line to experience freezing at facility.
  ANDOONINI.6.C. Roston Edison Co. 79/10/24. 1p.
- 7912260065 Hasponds to 790913 request for add1 info needed to complete review of util response to 16 Bulletin 7B-10 or Hergen-Patterson hydraulic shack suppressor accumulator spring coils Refety-related hydraulic subbers inspected in 1979 ANDOGNINI.O.C. Boston Edison Co. 79710729. Spp.
- 7912180405 Update: 790801 response to IE Bulletin 79-14. Accessible safety-related sys inspectod-all deviations insignificant or ainur in offect on piping stress analysis. Asks extensions of 120-day deadline for inaccessible purtions of sys. AMBOGNINI.6.C. Doston Ediann Co. 79711702. Opp.
- 7912050017 Forwards IE Circular 79-22, "Biroke Times for Power Operated Relief Valves," No response required. ORIER.B.M. Region 1, Philadelphia, Office of the Direktor. 79711/16. 1p.
- 7912050225 Forwards IE Info Notice 79-27, "Steam Generator Tube Roptures at Tuo PHR Plants " No response required. GRIER, B.H. Region 1, Philadelphia, Office of the Nirector 79/11/16 1p.
- 7912100107 Forwards IE Info Notice 79-28. "Overloading of fittertural Elements Due to Pipa Support Luads." No response required ORIER.S.H. Region J. Philadelphia. Office of the Director. 79/11/16. ip.

- 79121103B9 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required. GRIER. B.H. Region i. Philadelphia. Office of the Director. 79/11/19. ip.
- 7912050213 Forwards IE Bulletin 79-26, "Boron Loss From BWR Control Blades." Response required.
  GRIER, B. H. Region i, Philadelphia, Office of the Director.
  79/11/20. ip.
- 7912060564 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Apray Pipe Break Detection Equipment on BWRs," No response required.
  GRIER. J. H. Region 1, Philadelphia, Office of the Director.
  79/11/26. 1p.
- 7912110022 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. ORIER.B.M. Region 1. Philadelphia, Office of the Director. 79/11/26. 1p.
- 7912190011 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation." Written response required. GRIER. B. H. Region 1, Philadelphia, Office of the Director. 79/11/30. ip.
- 7912310204 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 100FR21," No action required. ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/12/06. 1p.
- 7912190533 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EAIBO Limit Buitches at Elevated Temps." Written response required.
  ORIER, B. H. Region i, Philadelphia, Office of the Director.
  79712/07. ip.
- 7912280181 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required. GRIER B. H. Region 1, Philadelphia, Office of the Director. 79/12/13, Ip.
- R. Periodic operating reports & related correspondence
- 7912050448 Forwards revised monthly operating rept for Oct 1979. MCQUIRE P. J. Boston Edison Co. 79/11/29. 1p.
- --7912040375 Revised monthly operating rept for Oct 1979. WHITNEY, Q. Q. Boston Edison Co. 79/11/01. 2pp.
- 7912200372 Forwards monthly operating rept for Nov 1979. MCQUIRE, P. J. Boston Edison Co. 79/12/01. 1p.
- --7912200375 Honthly operating rapt for Nov 1979. QAFFNEY.C.M. Boston Edison Co. 79/12/07. App.
- 7912310413 Forwards revised monthly operating rept for Nov 1979. MCGUIRE, P. J. Hoston Edison Co. 79/12/21. 1p.
- --7912310414 Revised monthly operating rept for Nov 1979. \* Boston Edison Co. 79/12/21. 1p.
- B. Reportable occurrences, LERs & related correspondence
- 7912200476 EN-79-012: proposed imposition of civil penalty of \$5,000.00 to be issued 791026 to util based on item of noncompliance associated w/implementation of physical security program.
  BROCKETT.T.W., 90WER.O.C. Office of Inspection & Enforcement, Office of the Director. 79/10/24. 1p.
- 7912040387 Forwards LER 79-041/04T-0. HCGUIRE, P. J. Boston Edison Co. 79/11/28. ip.
- --7912040394 LER 79-041/04T-0: on 791119, Yankee Atomic Environ Lab notified util that quertarly composite sample of air particles from overlook area exceeded calculated lower limit of datection. Improved analysis instituted. WHITNEY, Q. Q. Boston Edison Co. 79/11/27. lp.
- 7912070390 Forwards LER 79-042/03L-0. HCQUIRE, P. J. Boston Edison Co. 79/11/30. ip.

- ---7912070393 LER 79-042/03L-0: on 791101, oxygen analyzer valves AO-5065-10, 12, 15, 16, 17, 23 & 26 did not meet primary containment isolation timing requirements. Caused by faulty position indication lights on AO-5045-12 & 15.

  MATHIS, C. J. Boston Edison Co. 79/11/30. ip.
- 7912110311 Forwards LER 79-043/03L-0. MCGUIRE, P. J. Boston Edison Co. 79/12/06. 1p.
- --7912110313 LER 79-043/03L-0:on 791108, drywell unidentified leakage rate exceeded Tech Specs. Caused by leakage passing inboard isolation valve MD-2301-4 on HPCI sys. Valve backseated & leakage reduced to less than that requiring sbutdown.

  WHITNEY, O. O. Boston Edison Co. 79/12/06. 1p.
- 7912110370 Forwards LER 79-044/03L-0. MCQUIRE,P. J. Boston Edison Co. 79/12/06. 1p.
- --7912110377 LER 79-044/03L-0: on 791109 reactor coolent leak detection air sampling sys indicated low flow. Sample lines filled w/condensate. Caused by packing on isolation valve of HPCI sys allowing steam to escape. Valve backseated & leak reduced. WHITNEY. O. O. Boston Edison Co. 79/12/06. 1p.
- 7912180630 Forwards LER 79-041/04T-1. MCGUIRE, P. J. Boston Edison Co. 79/12/12. 1p.
- --7912180637 LER 79-041/04T-1: on 791119, util notified by lab that quarterly composite sample of air particulates taken at overlook contained Co-60 in excess of Tech Specs. Caused by improved analytical techniques sensitive to more isotopes. WHITNEY, O. O. Boston Edison Co. 79/12/11. 2pp.
- 7912200353 Forwards LER 79-046/03L-0. MCGUIRE, P. J. Boston Edison Co. 79/12/14. ip.
- --7912200360 LER 79-046/03L-0: on 790812 position of Assistant Station Manager filled necessitating change to organizational chart. Operations Review Committee composition also changed to include Vice Chairman. Caused by increased work load. WHITNEY, G. O. Boston Edison Co. 79/12/14. 1p.
- 7912270182 Forwards LER 79-045/03L-0. MCGUIRE, P. J. Boston Edison Co. 79/12/14. 1p.
- --7912270204 LER 79-045/03L-0: on 791114, differential pressure between drywell & suppression chamber decreased to less than 1.50 psid. Caused by decrease in HPCI valve leakage. Nitrogen added & temp increased which increased differential to 1.50. GRAHAM.E.T. Boston Edison Co, 79/12/11. 1p.
- 7912260278 Forwards LER 79-047/03L-0. MCGUIRE, P. J. Boston Edison Co. 79/12/17. ip.
- --7912260281 LER 79-047/03L-0: on 791117 & 20. fire brigade reduced to less than required by Tech Spacs. Caused by security shift supervisory personnel changing priorities of assigned tasks & contradicting directives issued by chief of security. MATHIB: C. J. Boston Edison Co. 79/12/17. 1p.
- 7912270316 RD 79-01/DR:on 791217, while lowering new fuel assembly into fuel pool. Rice hook holding assembly failed, resulting in assembly falling onto spent fuel. Cause not get determined. Investigation underway re recovery of assembly. MATHIS.C. J. Boston Edison Co. 79/12/17. 1p.
- 7912280577 RC: on 791211, while transferring Fuel Assembly LTL-656, crane lifted assembly out of spent fuel pool. Caused by failure to monitor hook while withdrawing from pool Assembly returned to proper postion.

  MATHIS, C. J. Boston Edison Co. 79/12/20. 1p.
- 7912280475 RO-79-048 on 791224 backup battery charger, in use due to main battery charger 791223 failure, tripped & could not be reset. Cause under investigation. Spare battery charger will be in svc by 791224.

  ORAHAM, E. T. Boston Edison Co. 79/12/24. Ip.
- 7912310453 Forwards LER 79-049/03L-0. MCGUIRE, P. J. Boston Edison Co. 79/12/28. ip.
- --7912310454 LER 79-049/03L-0: on 791129, after completing surveillance testing of diesel generator A. auxiliary trip relay annunciator did not clear. Cause undetermined. Phase A target & differential lockout reset.
  MATHIB.C. J. Boston Edison Co. 79/12/28. 1p.

- --7912070483 Amend 38 to License DPR-35 changing Tech Specs to relax pump operability requirements in sys where space pumps are installed in excess of requirements.

  [PPOLITO.1 A Operating Reactors Branch 3. 79/61/23. 7pp.
- --7912070485 Safety evaluation supporting Amend 38 to License DPR-35.

  \* Office of Nuclear Reactor Regulation. 79/11/23. 2pp.
- --7912070488 Notice of issuance & availability of Amend 38 to License DPR-35. IPPOLITO T.A. Operating Reactors Branch 3. 79/11/23. 2pp.
- 7912040259 Forwards specifit & comprehensive info per NRC 790713 request re BHR.Requests clarification on specific requirements re valve position.

  ANDOGNINI.O.C., MCGUIRE.P.J. Boston Edison Co. 79/11/26. 75pp.
- 7912280178 Advises of Equifar study re feasibility of performing epidemiologic studies on health effects of exposure to low level toniting radiation. Requests cooperation.

  IPPOLITE T.A Operating Reactors Granch 3. 79/11/27. 1p.
- 7912280189 Advises of Equifax study re feasibility of performing epidemiologic studies on health effects of exposure to low level ionizing radiation. Requests cooperation.

  IPPOLITO.T.A. Operating Reactors Branch 3. 79/11/27. 1p.
- 7912140250 Ack receipt of 790109 to 0821 ltrs re-containment purging.
  Util justified unlimited operation of valves involved only
  in containment differential pressure operation. Add1 info
  required re-containment purging in mechanical area
  IPPOLITO.T.A. Operating Reactors Branch 3. 79/11/28. 4pp.
- 7912120419 Responds to 79103) Itr requesting util to submit schedule for plant unique analysis for Mark I containment long-term program. Refers to Mark I owners group 791130 Itr voicing concern on subj.

  ANDOGNINI.G.C Boston Edison Co. 79/11/30. 1p.
- 7912310011 Requests cooperation in allowing some NRC TLD stations to co-locate w/util TLD stations. Advises of 791210 meeting w/MA Dept of Health re TLD stations. SMITH-Q-H. Region f. Philadelphia. Fuel Facility & Materials Safety Branch. 79/12/04. 2pp.
- 7912120333 Forwards "Multiple Controlled Cell Removal." delineating util methodology for determining that removal of one or multiple controlled cells during cold shutdown leads to less reactive state.

  ANDDONINI.G.C. Boston Edison Co. 79/12/07. In.
- --7912120337 "Multiple Controlled Cell Removel." ANTONOPOULOS.P. Boston Edison Co. 79/11/30 50pp
- 7912240077 Notification of 791211 meeting w/util in Bethesda.MD re electrical design of engineered safety feature override circuitry.per criteria of NRC 79112H ltr. HANNON.J.N. Operating Reactors Branch 3. 79/12/07. ip.
- 7912270144 Forwards util response.w/o attachments.to 791026 notice of violation & of proposed imposition of civil penalties.in response to State of HA 79126 request. Attachments withheld (ref 10CFR2 790). H/o encl.
  STELLO.V. Office of Inspection & Enforcement, Defice of the Director. 79/12/07. 1p
- 7912250242 Forwards "Supplemental Reload Licensing Submittal for Pilgrim Nuclear Power Station Unit 1.Reload 4," & Class 111 fee.supporting request for changes to App A of Tech Specs. HOMARD, J. E. Boston Edison Co. 79/12/12. 39pp.
- --7912260246 "Supplemental Reload Excensing Submittal for Pilgrim Nuclear Power Station Unit 1.Reload 4." supporting changes to App A of Tech Specs RASH.J.L. General Electric Co. NEDO-24224. 79/11/30. 25pp.
- 7912280064 Request submittal of Class II amend fee re 790828 transmittal of simulator retraining program NRC 791023 ltr requesting fee has not been answered.

  MILLER-W.O. License Fee Managament Branch. 79/12/14. lp.
- 7912270320 Responds to 791022 ltr re review of interim positions for containment purge & vent valve operation & conformance of operation to positions. Purge isolation valves used for inerting 24th after startup.

  HOMARD. J. E. Boston Edison Co. 79/12/19. Opp.

- 7912270419 Forwards complete offsite power outage history.containing responses to NRC 790918 questions. Description of intended transmission line mods to minimize frequency of simultaneous 345 bV line outages due to lightning encl.

  ANDOGNINI.G.C. Boston Edison Co. 79/12/20. 43pp.
- G. Inspection reports, IE Bulletins & correspondence
- 7912210011 Requests add1 info re Bergen-Patterson hydraulic shock suppressor accumulator spring coils to evaluate adequacy of util response to IE Bulletin 78-10.

  ORIER, B.H. Region I, Philadelphia, Office of the Director, 79/09/13. 2pp.
- 7912050252 Forwards IE Insp Rept 50-293/79-12 on 790705-06. No noncompliance noted.
  MARTIN,W.G. Region 1, Philadelphia, Safaguards Branch. 79/10/04.
- --7912050262 IE Insp Rept 50-293/79-12 on 790705-06. No noncompliance noted Major areas inspected: verification & evaluation of actions re physical protection program. Details withheld (ref 10CFR2. 790).

  JONES.E. W. Region 1, Philadelphia, Office of the Director. DEVLIN.J. H. Region 1, Philadelphia, Safeguards Branch. 79/09/27. 1p.
- 7912070123 Ack receipt of 791002 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-293/79-09.
  BRUNNER.E.J. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch. 79/10/22. 1p.
- --7912070124 Responds to NRC 790910 ltr re violation noted in IE Insp Rept 50-293/79-09 Corrective actions: procedures updated to specify coalant injection valve locking. ANDOGNINI.6.C. Boston Edison Co. 79/10/02. 3pp.
- --7912070132 Forwards IE Insp Rept 50-293/79-09 on 790514-18,21-25, 27-31 & 0601 & notice of violation. BRUNNER, E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/09/10. 2pp.
- --7912070134 Notice of violation from insp on 790514-18,21-25,29-31 & O601.

  \* Region i. Philadelphia. Office of the Director. 79/09/07.
- --7912070139 IE Insp Rept 50-293/79-09. Noncompliance noted: procedures do not specify valve locking position & valve documented locked in wrong position.

  ARCHITZEL.R., MARKOMSKI.R. Region 1. Philadelphia. Office of the Director. MCCABE.E.C. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 79/09/07. 20pp.
- 79:2140286 Responds to IE Bulletin 79-24. "Frozen Lines." Identifies stack sample line as only line to experience freezing at facility.

  ANDOGNINI, C. C. Boston Edison Ca. 79/10/24. ip.
- 7912260065 Responds to 790913 request for add1 info needed to complete review of util response to IE Bulletin 78-10 re Bergen-Patterson hydraulic shack suppressor accumulator spring coils. Safety-related hydraulic snubbers inspected in 1979.

  ANDDGNINI.G.C. Boston Edison Co. 79/10/29. 2pp.
- 7912180485 Updates 790801 response to 1E Bulletin 79-14. Accessible safety-related sys inspected all deviations insignificant or minor in effect on piping stress analysis. Asks extension of 120-day deadline for inaccessible portions of sys. ANDOGNINI, C. C. Boston Edison Co. 79/11/02. 3pp.
- 7912050017 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required. GRIER, B.H. Region 1. Philadelphia, Office of the Director. 79/11/16. 1p.
- 7912050225 Forwards IE Info Notice 79-27, "Steam Generator Tube Ruptures at Tuo FWR Plants." No response required, GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/11/16 tp.
- 7912100107 Forwards IE Info Notice 79-2B, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. GRIER, B.H. Region J. Philadelphia. Office of the Director. 79/11/16. Lp.

- 7912110389 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. ORIER. B. H. Region i. Philadelphia. Office of the Director. 79/11/19. ip.
- 7912050213 Forwards IE Bulletin 79-26, "Boron Loss From BWR Control Blades." Response required.
  ORIER, B. H. Region 1. Philadelphia, Office of the Director.
  79/11/20. ip.
- 7912040864 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BMRs." No response required.
  ORIER, B. H. Region i, Philadelphia, Office of the Director.
  79/11/26. ip.
- 7912110022 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. ORIER, B. M. Ragion 1, Philadelphia, Office of the Director. 79/11/26. 1p.
- 7912190011 Forwards IE Builetin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Written response required. ORIER, B. H. Region i, Philadelphia, Office of the Director. 79/11/30, ip.
- 7912310204 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 100FR21." No action required. ORIER, B.H. Region 1, Philadelphia, Office of the Director. 79/12/06. 1p.
- 7912190833 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Written response required. GRIER, B. H. Region i, Philadelphia, Dffice of the Director. 79/12/07. 1p.
- 79:12280181 Forwards IE Info Notice 79-3:, "Use of Incorrect Amplified Response Spectra." No written response required. GRIER.B.H. Region 1, Philadelphia. Office of the Director. 79/12/13. 1p.
- 8. Periodic operating reports & related correspondence
- 791205044B Forwards revised monthly operating rept for Dct 1979. MCQUIRE, P. J. Boston Edison Co. 79/11/29. 1p.
- --7912040375 Revised monthly operating rept for Oct 1979. WHITNEY, Q. Q. Boston Edison Co. 79/11/01. 2pp.
- 7912200372 Forwards monthly operating rept for Nov 1979. MCGUIRE, P. J. Boston Edison Co. 79/12/01. 1p.
- --7912200375 Monthly operating rept for Nov 1979. OAFFNEY, C. M. Boston Edison Co. 79/12/07. App.
- 7912310413 Forwards revised monthly operating rept for Nov 1979. MCQUIRE P. J. Boston Edison Co. 79/12/21. 1p.
- --7912310414 Revised monthly operating rept for Nov 1979, \* Boston Edison Co. 79/12/21. ip.
- 8. Reportable occurrences, LERs & related correspondence
- 7912200476 EN-79-012: proposed imposition of civil penalty of \$5,000.00 to be issued 791026 to util, based on item of noncompliance associated w/implementation of physical security program. BROCKETT, T.M., GOMERIO, C. Office of Inspection & Enforcement, Office of the Director. 79/10/24. 1p.
- 7912040387 Forwards LER 79-041/04T-0. HCGUIRE, P. J. Boston Edison Co. 79/11/28. 1p.
- --7912040394 LER 79-041/04T-0: on 791119; Yankee Atomic Environ Lab notified util that quarterly composite sample of air particles from overlook area exceeded calculated lower limit of detection, Improved analysis instituted. HHITNEY, 9, 0. Boston Edison Co. 79/11/27. lp.
- 7912070390 Forwards LER 79-042/03L-0. MCQUIRE, P. J. Boston Edison Co. 79/11/30. 1p.

- --7912070393 LER 79-042/03L-0: on 791101; oxygen analyser valves A0-5065-10:12:15:16:17:23 & 26 did not meet primary containment isolation timing requirements. Caused by faulty position indication lights on A0-5045-12 & 15. MATHIB.C.J. Boston Edison Co. 79/11/30. 1p.
- 7912110311 Forwards LER 79-043/03L-0. MCGUIRE.P.J. Boston Edison Co. 79/12/06. 1p.
- ---7912110313 LER 79-043/03L-0: on 791108, drywell unidentified leakage rate exceeded Tech Specs. Caused by leakage passing inboard isolation valve MO-2301-4 on HPCI sys. Valve backseated & leakage reduced to less than that requiring shutdown.
  WHITNEY, Q. G. Boston Edison Co. 79/12/06. 1p.
- 7912110370 Forwards LER 79-044/03L-0. MCQUIRE, P. J. Boston Edison Co. 79/12/06. 1p.
- --7912110377 LER 79-044/03L-0: on 791109 reactor coolant leak detection air sampling sys indicated low flow. Sample lines filled w/ condensate. Caused by packing on isolation valve of HPCI sys allowing steam to escape. Valve backseated & leak reduced. WHITNEY, G. G. Boston Edison Co. 79/12/06. . ip.
- 7912180630 Forwards LER 79-041/04T-1.
  MCGUIRE.P.J. Boston Edison Co. 79/12/12. ip.
- --7912180637 LER 79-041/04T-1: on 791119, util notified by lab that quarterly composite sample of air particulates taken at overlook contained Co-60 in excess of Tech Specs. Causad by improved analytical techniques sensitive to more isotopes. WHITNEY, O. G. Boston Edison Co. 79/12/11. 2pp.
- 7912200353 Forwards LER 79-046/03L-0. MCQUIRE, P. J. Boston Edison Co. 79/12/14. 1p.
- --7912200360 LER 79-046/O3L-0 on 790Bi2 position of Assistant Station Manager filled necessitating change to organizational chart. Operations Review Committee composition also changed to include Vice Chairman Caused by increased work load. WHITNEY, O. O. Boston Edison Co. 79/12/14. 1p.
- 7912270182 Forwards LER 79-045/031-0. MCQUIRE, P. J. Boston Edison Co. 79/12/14. 1p.
- --7912270204 LER 79-045/O3L-0: on 791114, differential pressure between drywell & suppression chamber decreased to less than 1.50 psid. Caused by decrease in HPCI valve leakage. Nitrogen added & temp increased, which increased differential to 1.50. GRAHAM, E. T. Boston Edison Co. 79/12/11. 1p.
- 7912260278 Forwards LER 79-047/03L-0. MCQUIRE, P. J. Boston Edison Co. 79/12/17. 1p.
- --7912260281 LER 79-047/03L-0: on 791117 & 20, fire brigade reduced to less than required by Toch Space. Caused by socurity shift supervisory personnel changing priorities of assigned tasks & contradicting directives issued by chief of security. MATHIB, C. J. Boston Edison Co. 79/12/17. 1p.
- 7912270316 RD 79-01/OR: on 791217, while lowering new fuel assembly into fuel poul. Rice hook holding assembly failed, resulting in assembly falling onto spent fuel. Cause not yet determined. Investigation underway re recovery of assembly.

  MATHIB. G. J. Boston Edison Co. 79/12/17. ip.
- 7912280577 RD: on 791211, while transferring Fuel Assembly LTL-656, crane lifted assembly out of spent fuel pool. Caused by failure to monitor hook while withdrawing from pool. Assembly returned to proper position.

  MATHIB. C. J. Boston Edison Co. 79/12/20. 1p.
- 7912280475 RC-79-048 on 791224: backup battery charger in use due to main bettery charger 791223 failure, tripped & could not be reset. Cause under investigation, Spare battery charger will be in svc by 791224.

  GRAHAM, E. T. Boeton Edison Co. 79/12/24. ip.
- 7912310453 Forwards LER 79-049/03L-0. MCGUIRE, P. J. Boston Edison Co. 79/12/28. ip.
- ---7912310454 LER 79-049/03L-0:on 791129:after completing surveillance testing of diesel generator A:auxiliary trip relay annunciator did not clear. Cause undetermined. Phase A target & differential lockout reset.

  MATHIB:C.U. Boston Edison Co. 79/12/28. 1p.

DOCKET 50-294 MICHIGAN STATE UNIV. RESEARCH REACTOR

- F. Security, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Guide 5.XX. "Std Format & Content for Licensee Physical Security Plan For Protection of SMM of Moderate or Low Strategic Significance." W/o encl. REID,R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22.

### J. Insurance & indemnity information

7912140381 Forwards executed Amend 10 to Indomnity Agreement E-91 defining "in course of transportation." GRIDER, H. G. Michigan, Univ. of. 79/12/10. 2pp.

DOCKET 50-295 ZION NUCLEAR POWER STATION, UNIT 1

- F. Security, medical, emergency & fire protection plans
- 7912170261 Discusses proposed task force review of emergency preparedness. Task force should study alternatives for reduction of probability & consequences of severe accident. EIGENHUT.D. 0. Division of Operating Reactors. 79/11/21. 3pp.
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives. Provides guidance for improving licensee emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.

  ORIMES, B. K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- 7912200122 Notification of 791205 meeting w/util in Bethesda. HD, to review emergency preparedness capabilities. List of NRC considerations encl. EISEN-NUT.D. 6. Division of Operating Reactors. 79/11/29. 3pp.
- 7912270063 Forwards list of specific items requiring updating in emergency plans Emergency plans were evaluated using code requirements. Reg Guide 1. 101 & Emergency Planning Review Guidelines Number 1. Revision 1. IFPOLITO. T. A. Operating Reactors Branch 3. 79/11/30. 7pp.
- 7912210127 Responds to 791115 conversation re emergency telephones.
  Requests info indicating backup power supply to emergency
  telephones.
  KEPPLER.J. G. Region 3. Chicago. Office of the Director. 79/12/05.
  ip.
- 7912200672 Requests payment of Class III fees for review of 790816 nuclear security personnel training & qualification plans.

  DIGGS.R.M. License Fee Management Branch. 79/12/07. 1p.

## G. Adjudicatory correspondence

- 7912110503 Forwards licenses response to ASLB 790914 memorandum & order & 791029 IE Bulletin 79-17. Revision i.T Tramm, TW Lutens. B Clarks & P Staehle affidavits address technical safety problems re spent fuel storage. Cortificate of Svc encl. STEPTOE.P. Isham, Lincoln & Beale. 79/11/16. 4pp.
- --7912110513 Affidavit identifying type of stainless steel in liner, spent fuel assemblies & spent fuel goal cooling sys. Clarifies exposure condition of stainless steel & consequences of stainless steel sys failure. TRAMM.T.R. Communusaith Edison Co. 79/11/16. 10pp.
- --7912110518 Affidavit reporting spent fuel pool cooling sys inspresults. Identifies examination of spent fuel rack undertaken in respunse to IE Bulletin 79-17. LUKENS, T. W. Commonwealth Edison Co. 79/11/16. 5pp.
- --7912110925 Affidavit reporting spent fuel pool cooling sys insp results Identifies oxamination of spent fuel rack undertaken in response to IE Bullotin 79-17. SHANNON.R. Commonwealth Edison Co. 79/11/16. 4pp.
- ---7912110302 Affidavit giving essential performance requirements of sensitization tests results performed on TMI specimens.Prof qualifications & supporting documentation encl. CLARRE.W.L. General Electric Co. 79/11/16. 64pp.
- --7912110542 Affidavit stating reasons for believing that intergranular stress corrosion cracking does not present safety problem.

  Recommends weekly monitoring of pool water chemistry. Prof qualifications & supporting documentation encl.

  BTAEHLE.R. Hinnesota, Univ. of, Minneapolis. 79/11/16. 30pp.

- 79:2:1900:5 Forwards documents relevant to intergranular stress corrosion cracking issue.W/o enci.
  STEPTOE,P.P. Isham, Lincoln & Beale. 79/i1/19. 2pp.
- 771211003B Confirms receipt of encl 770329 petition to suspend DLs for all PWRs.Forwards FR notice indicating that petition will be treated in accordance w/IOCFR2.206.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/23. 1p.
- --7912110126 Notice of request for action pursuant to 10CFR2.206 re Environ Coalition on Nuclear Power 790329 petition requesting suspension of all QLs for PWRs. MULLER, D. R. Dffice of Nuclear Reactor Regulation. 79/11/23.
- 7912040455 Recommends closing plants due to proximity to population centers & lack of evacuation plans.

  \* Citizens Against Nuclear Power. 79/11/28. Spp.
- 7912100476 Motion for extension until 791214 for NRC to respond to ASLB order requesting info re intergranular stress corrosion cracking. Applicant submittal was not received until 791128. Certificate of Svc encl. GDDDARD.R.J. Hearing Branch 2. 79/11/29. 3pp.
- 791214004B Memorandum & order granting extension until 791214 for NRC to respond to ABLB 790914 order re possible intergranular stress corrosion cracking in proposed fuel storage racks to be used in spent fuel poul.

  WOLF, S. F. Atomic Bafety and Licensing Board Panel. 79/12/03. ip.
- 7912180230 Advises of errors in licensee 791116 submittal on intergranular stress corrosion cracking. Forwards missing pages.
  STEPTOE, P. P. Isham, Lincoln & Beale. 79/12/03. 3pp.
- 7912180178 Response to ASLB 790914 order that affidavits be provided stating extent to which Stainless Steel 304 would be used in spent fuel storage pool & effects from immersion in pool water. Forwards JR Weeks & A Tabo
- --7912180181 Affidavit of JR Weeks on 791206 re extent of presence of Stainless Steel 304 in spent fuel storage pool & affects of immersion in pool water. Statement of prof qualifications encl.
  WEEKS, J. R. Brockhaven National Laboratory. 79/12/06. 4pp.
- ---7912180186 Affidovit of A Taboada in 791207 re extent of presence of Stainless Btool 304 in spent fuel storage pool & effects of immersion in pool water. Statement of prof qualifications & Certificate of Svc encl.

  TABOADA.A. Diffice of Standards Devolopment. 79/12/07. 4pp.
- 7912210420 Response to intervenor State of H. 791210 request for extension until 791220 to respond to ASLB order requiring info re intergranular stress corresion cracking No objection to extention WcGreifficate of Svc. GODDARD, R. J. Hearing Branch 2. 79/12/12. 2pp.

# H. General correspondence

- 7912280605 Discusses 791204 title change of manager of nuclear operations to vice president Organization structure not altered. No revision will be made to GA program topical rupt CE-1-A until organization structure is delineated. JANECER, R. F. Commonwealth Edison Co. 79/12/19. 1p.
- P. Operating license stage documents & correspondence
- 77:1090248 "Summary of Operating Experience W/Recirculating Steam Generators." EISENHUT.D.C. Division of Operating Reactors. NUREO-0523. 79/01/31. 87pp.
- 790B010339 Notifies of status of rapt on reactor cavity annulus seal.
  Most PHR users remove ring during normal operation. Others
  store seal ring in raised position during normal operation.
  LAINAS.O. Plant Systems Branch (Pre 791030). 79/07/05, 7pp.
- 7912110011 Forwards NRC position on status & applicability to pending OL applications of results of TMT followup actions. Outlines addl short-term actions to be taken.
  VASSALLO, D. B. Division of Project Management. 79/09/27. 41pp.

- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATHE issue for PHRs & BHRs.
  Buccess of program depends on industry response. Supports formation of owners groups to provide necessary info.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912050162 Discusses NRC review of LERs & Tech Spec requirements recontrol RPI sys at Westinghouse PWRs. Requests Tech Specs review to ensure requirement for rod maint to within +/- 12 steps indicated & RPI sys verified accurate within 12 steps. SCHWENGER.A. Operating Reactors Branch 1. 79/10/29. 7pp.
- 7911270467 Forwards "Discussions of TMI Lessons Learned Short-Term Requirements" providing addl clarifications of NRC requirements for pending DL applicants. VASSALLO, D. B. Division of Project Management. 79/11/09. 2pp.
- 7912100189 Discusses NRC 791101 meeting w/representatives of NSSS vendors & fuel suppliers re discussion of respective portions of ECCB evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EIBENHUT.D.O. Division of Operating Reactors. 79/11/09. 45pp.
- --7912100255 Responds to NRC 791101 request re noncompliance of Westinghouse ECCB evaluation model under requirements of 10CFR50 App K. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants.

  ANDERSON, T. M. Westinghouse Electric Corp. 79/11/02. 4pp.
- --7912100330 Responds to NRC 791101 request re DRNL cladding swelling & rupture date, Review of analytical models & tests indicates compilance w/10CFRSO App K. All OE specs for calculated peak cladding temp remain unchanged.

  BUCHHOLZ.R.H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vandor evaluation models & that analyses demonstrate all criteria of 100FR50.46 satisfied.
  DMSLEY, O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.), 79/11/02. Spp.
- ---7912100456 Forwards add1 info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. OMSLEY.G.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.), 79/11/04. 22pp.
- 7712050322 Discusses 771113 & 14 site visit re solid radwaste processing & temporary storage. Facilities have instituted improved waste minimization programs...

  ORANT. P. Environmental Evaluation Branch. 77/11/23. 2pp.
- 7912060649 Notification of 791205 meeting w/utils in Bathesda, MD to discuss alternatives to reduce probability & consequences of severe reactor accident.

  ZECH, G. Division of Operating Reactors. 79/11/29. 4pp.
- 7912040297 Forwards supplementary response to be incorporated into 791018 ltr re lessons learned commitments to meet near-term requirements.

  REED.C. Commonwealth Edison Co. 79/11/30. 7pp.
- 7912120411 Forwards supplementary response re commitment to meet short-term requirements of Leasons Learned Task Force. REED.C. Commonwealth Edison Co. 79/11/30. 7pp.
- 7912120425 Forwards supplemental response to 791018 ltr re commitments to Lessons Learned Task Force recommendations. PEOPLES, D. L. Commonwealth Edison Co. 79/12/03. 2pp.
- 7912110309 Responds to NRC 791029 ltr re control RPI sys at Westinghouse PHRs. Resolution of RPI sys is +/-5% of span. When indicated misslignment of 12 steps exists misslignment could be 24 steps & control RPI should be monitored +/-12%. PEOPLES.D.L. Commonwealth Edison Co. 79/12/04. 2pp.
- 7912110318 Confirms 791119 notification of implemented mod. Automatic rod control operation prohibited above 90% of rated power W/Control Bank D balow 216 steps withdrawn. PEOPLES.D. L. Commonwealth Edison Co. 79/12/04, ip.
- 7912200041 Forwards request for add1 info re auxiliary feedwater sys automatic initiations & flow indications to steam generators.

  Generators Branch 1 (Pre 791030). 79/12/12.
  2pp.

- 7912210349 Forwards cover sheet for CE-1-A.Revision 10, inadvertently omitted from 791116 transmittal.
  NAUGHTON.W.F. Commonwealth Edison Co. 79/12/13. 2pp.
- 7712180531 Forwards info documenting evaluation of purge & vent valve operability verification. Util committed to purge & vent sys in conformance w/NRC interim position. Complete confirmatory analyses not available for 30-40 wt. PEOPLES, D. E. Commonwealth Edison Co. 79/12/14. 6pp.
- 7912190542 Forwards "Adequacy of Station Electric Distribution Sys-Voltages," addressing 480-volt undervoltage conditions. JANECEK, R. F. Commonwealth Edison Co. 79/12/14. 1p.
- --7912190545 "Adequacy of Station Electric Distribution Sys Voltages." \* Commonwealth Edison Co. 79/12/14. Spp.
- 7912270469 Forwards response to NRC request for add1 info on Lessons Learned Task Force Recommendations 2.1.7a & 2.1.7b. PEOPLES,D.L. Commonwealth Edison Co. 79/12/14. Bpp.
- 7912270470 Advises that qualification program for remaining purge & vent containment valves is in progress. Dresden & Quad-Cities butterfly valves will close regardless of degree of opening. Response to NRC interim position encl. PEOPLES, D. L. Commonwealth Edison Co. 79/12/14. 6pp.
- 7912270897 Advises of compliance w/Category A TMI Lessons Learned Task Force items identified in NRC 790913 & 1030 ltrs.Compliance will be achieved by B00101.or prior to return to power for units in outages on B00101. PEOPLES.D.L. Commonwealth Edison Co. 79/12/17. 1p.
- 7912270464 Forwards supplementary response on TMI Lessons Learned Task Force recommendations, in response to NRC request for info. Response should be incorporated into 791019 ltr reauxiliary feedwater sys requirements. PEOPLES, D. L. Commonwealth Edison Co. 79/12/18. 9pp.
- 7912310348 Forwards revised pages to CE-1-A, "Coam Ed GA Program for Nuclear Generating Stations," Revision 11.

  JANECEK, R. F. Commonwealth Edison Co. 79/12/20. 1p.
- --7912310359 Revised pages to CE-1-A. "Comm Ed GA Program for Nuclear Generating Stations." Revision 11. \* Commonwealth Edison Co. CE-1-A. 79/11/21. 16pp.
- 7912270267 Forwards 791220 conference paper re Indian Point/Zion near site studies. Requests paper be made part of public record. PEOPLES, D. L. Commonwealth Edison Co. 79/12/21, ip.
- --7912270275 "Indian Point/Zion Near Site Studies." presentation to NRC.
  \* Commonwealth Edison Co. 79/12/20. Sipp.
- G. Inspection reports, IE Bulletins & correspondence
- 7912030090 Forwards IE Insp Repts 50-279/79-20 & 50-304/79-19 on 790901-30. No noncompliance noted. HEIBIMAN.R.F. Region 3, Chicago, Reactor Operations Nuclear Bupport Branch. 79/10/17. 2pp.
- --7912050066 IE Insp Repts 50-295/79-20 & 50-304/79-19 on 790901-30 No noncompliance noted Major areas inspected reactor operation, maint IE bulletin followup, LERs, physical security, & changing pump shaft matl.

  KOHLER, J. E., SPEBSARD, R. L. Region 3, Chicago, Office of the Director. 79/10/17. 9pp.
- 7912180224 Forwards IE Imap Repts 50-295/79-23 & 50-304/79-21 on 790702 & 0925, No noncompliance noted. FIORELLIG. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 79/11/07. 2pp.
- --7912180234 IE Insp Repts 50-295/79-23 & 50-304/79-21 on 790702 & 0925.

  No noncompliance noted Major areas inspected: review procedures, mfg activities at Leckenby Co & review audits & surveillances performed by Comm ED.

  HAYES.D.N. Hegion 3. Chicago. Reactor Construction & Engineering Support Branch. NAIDU.K.R. Region 3. Chicago. Office of the Director. 79/11/05. Spp.
- 7912050106 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required.
  KEPPLER.J.O. Region 3. Chicago, Office of the Director. 79/11/16.

- 1100213 Forwards IE Info Notice 79-28, "Overloading of Structural ements Due to Pipo Support Loads: " No response required. PPLER. J. O. Region 3. Chicago. Office of the Director. 79/11/16.
- Elio557 Forwards IE Info Notice 79-29. "Loss of Nonsafety-Related factor Coolant Sys Instrumentation During Operation." No secific action or response required. EPPLER. J. C. Region 3. Chicago. Office of the Director. 79/11/16. lb.
- 3050344 Forwards IE Bulletin 79-26, "Boron Loss From BWR Control lades," No response required.

  IPPLER, J. G. Region 3, Chicago, Office of the Director. 77/11/20.
- 2100417 Forwards IE Circular 79-24, "Proper Installation & Calibr of pre Spray Pipe Break Detection Equipment on BWRs." No litten response required. 
  3PPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/26.
- 2140187 Forwards IE Circular 79-23, "Motor Starters & Contactors siled to Operate." No written response required.

  EPPLER.J. C. Region 3, Chicago, Office of the Director. 79/11/26.
- 2110395 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty meral ofcs copies of escalated enforcement correspondence int by NRC to licensees.

  PPLER.J. O. Region 3. Chicago. Office of the Director. 79/11/28.
- ?190199 Forwards IE Bulletin 79-27, "Loss of Non-Class IE strumentation & Control Fower Sys Bus During Operation." ritten response required. :PPLER.J. G. Region 3, Chicago. Office of the Director. 79/11/30.
- 2140056 Forwards IE Info Notice 77-30, "Reporting of Defects & Incompliances, 10CFR21." No action or response required.

  IPPLER, J. 9. Region 3. Chicago, Office of the Director. 79/12/06. .D.
- 22000B6 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco del EA180 Limit Switches at Elevated Temps." Action quired. PPLER, J. C. Region J. Chicago, Office of the Director. 79/12/10.
- 1200443 Notification of 791213 meeting w/util to discuss IE Bulletin 7-02 anchor bolt & base plate analysis. IRDAN, E. L. Division of Reactor Operations Inspections. 79/12/11.

## 'eriadic operating reports & related correspondence

- 2110219 Forwards monthly operating repts for Nov 1979. NDKE, N. E. Commonwealth Edison Co. 79/12/07. 1p.
- 712110223 Monthly operating repts for Nov 1979. COOK, J. M. Commonwealth Edison Co. 79/12/07. 11pp.
- reportable occurrences. LERs & related correspondence
- PIBO373 PND-III-79-018; on 791015, cracking in feedwater nozzle-to-tipe welds on steam generators A & D verified by radiographs iing H & AA film. Previous examination using different techniques & film found welds acceptable.

  NO.D. C., HEISHMAN.R.F. Region 3, Chicago, Office of the lrector. 79/10/15. ip.
- 2310045 PNO-III-79-018A: on 791017, insp & evaluation ongoing of inear indications in feedwater notife to pipe welds, Welds a each of four steam generators have been radiographed inear indications exist in feedwater notife.

  WESSARD, R.L., HEISHMAN, R.F., Region 3, Chicago, Office of the rector, 79/10/17, 2pp.
- C110099 PNO-III-79-018B: on 791023, licensee determined linear idications in feedwater no.11e pipe welds to be cracks, tacking estimated depth less than 0.170 inch. Meeting theduled 791025 to review matter.

  LLIAMS.C.C. STREETER.J.F. NEISHMAN.R.F. Region 3, Chicago, ifice of the Director. 79/10/23, 2pp.

- 7912120066 PNO-III-79-025: on 791025, assential svcs motor generator set tripped, resulting in tripping of Unit 3 reactor. Caused by slamming of essential svcs electrical panel door.

  CREED, J. Region 3, Chicago. Office of the Director. 79/10/26.
- 7912170166 PNO-III-79-25A: threatening telephone calls came from court-committed patient. All affected licensees notified. DELANGER.J. Region 3. Chicago, Office of the Director. 79/10/29.
- 7912040654 PND-III-79-18C: on 791023, based on metallurgical & volumetric examination, linear indications found in feedwater nozzle-to-pipe welds. Licensee will remove & replace defective welds & piping in feedwater loop.

  KOHLER, J. E., SPESSARD, R. L., HEISHMAN, R. F. Region 3, Chicago, Office of the Director. 79/11/01. 1p.
- 7912070418 Forwards LER 79-076/03L-0.
  WANDKE, N.E. Commonwealth Edison Co. 79/11/09. 1p.
- -7912070422 LER 79-076/03L-0: on 791010, while performing refueling surveillances, reactor coolant flow transmitter IFT-444 shifted high. Caused by zero shift. Transmitter recalibr using new technique to correct drift & zero shift problem. RODERS, C.L. Commonwealth Edison Co. 79/11/09. ip.
- 7912070453 Forwards LER 79-079/03L-0.
  WANDKE, N. E. Commonwealth Edison Co. 79/11/09. 1p.
- --7912070457 LER 79-079/03L-0: on 791023, during refueling, auxiliary bldg area radiation monitor repeatedly failed low. Caused by broken restraining clamp on photomultiplier tube. Clamp replaced. Monitor functionally tested & restored to svc. TRZYNA, O. Commonwealth Edison Co. 79/11/09. 1p.
- 7912180090 PND-III-79-43: on 791114, during overhaul of low pressure turbine, crack indications found in B section, Number 2 disks & on 791120, two cracks found in C section, Number 1 disks. New spindle required for permanent repair.

  KOHLER, J. E., BOYD, D. C. Region 3, Chicago, Office of the Director, 79/11/20. 1p.
- 7912180366 PND-III-79-052: on 791129, during routine surveillance, gland seals on three hydraulic snubbers observed w/excessive leaking. Gauges observed on piston rods where snubbers pass through housing at gland seal & on housing.

  DANIELSON, D. H., FIORELLI, G., Region 3, Chicago, Office of the Director. 79/11/29, 1p.
- DOCKET 50-296 BROWNS FERRY NUCLEAR POWER STATION, UNIT 3 F. Security, medical, emergency & fire protection plans
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team raview objectives. Provides guidance for improving licensee emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.

  ORIMES, B. K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- P. Operating license stage documents & correspondence
- 7912100189 Discusses NRC 791101 meeting w/representatives of NSBS vendors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding portions or ECGS evaluation moves useding write. Secondly swelling & incidence of rupture.Vendor responses entl. EIBENHUT.D.O. Division of Operating Reactors, 79/11/09. 65pp.
- --7912100255 Responds to NRC 791101 request re noncompliance of Westinghouse ECCS evaluation model under requirements of 10CFR50 App K. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants.

  ANDERSON, T. M. Westinghouse Electric Corp. 79/11/02. 4pp.
- --7912100330 Responds to NRC 791101 request re ORNL cladding swelling & rupture data. Review of analytical models & tests indicates compliance w/10CFR50 App K. All GE specs for calculated peak cladding temp remain unchanged.

  BUCHKOLZ, R. H. General Electric Co. 79/12/07. 2pp.
- ---7912100407 Forwards response to NRC 791101 request re rod burst test data Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50.46 satisfied.

  GMSLEY, O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).

  79/11/02. Spp.

- --7912100496 Forwards addl info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. OMBLEY.O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/04. 22pp.
- 791226001B Responds to 790629 & 20 submittals re proposed radiological effluent Tach Specs.Requests 791206 meeting w/util in Bathesde, MD. Agenda itsms encl.

  IPPOLITO, T. A. Operating Reactors Branch 3. 79/11/26. 4pp.
- 7912040435 Informs NRC that as member of BWR owners group, util commits to accept & implement owners group positions on NUREG-0578, Items 2. 1. 3. b & 2. 1. 9.

  MILLE, L. M. Tennessee Valley Authority. 79/11/29. ip.
- 791205050B Forwards requested amend to Licenses DPR-33, DPR-52 & DPR-68, changing Tech Specs to reflect Nuclear Safety Review Board Class I & Class II fees forthcoming.
  MILLS,L.M. Tennessee Valley Authority. 79/11/29. 2pp.
- --7912050510 Proposed changes to Tech Specs, reflecting Nuclear Safety Review Board charter. \* Tennessee Valley Authority. 79/11/29. 24pp.
- 7912130439 Fowards Amend 28 to License DPR-68, safety evaluation & notice of issuance & availability.
  IPPDLITO, T. A. Operating Reactors Branch 3. 79/11/30. 2pp.
- --7912130706 Amend 28 to License DPR-68, changing Tech Specs to incorporate limiting conditions for operation during third fuel cycle & to reflect facility mode during current refueling outage.

  IPPOLITO, T. A. Operating Reactors Branch 3. 79/11/30. 49pp.
- --7912130717 Safaty evaluation supporting Amend 28 to i.icanse DPR-68.
  \* Office of Nuclear Reactor Regulation. 79/11/30. 25pp.
- --7912130726 Notice of issuance & availability of Amend 28 to License DPR-68. IPPOLITO,T.A. Operating Reactors Branch 3. 79/11/30. 2pp.
- 7912130023 Notification of 800110 meeting w/util to discuss reporting level of util GA & manager & GA review of documents.

  BPRAUL.J.O. Quality Assurance Branch. 79/12/05. 1p.
- 7912130482 Forwards proposed amend to Licenses DPR-33.DPR-52 & DPR-68 to change Tech Specs re isolation of main steam lines following main steam line high temp logic actuation.

  MILLS.L.M. Tennesses Valley Authority. 79/12/05. 2pp.
- --7912130508 Tech Specs revision for isolation of main steam lines. \* Tannesses Valley Authority. 79/12/05. 20pp.
- 7912140273 Responds to 791022 ltr re containment purging & venting during normal operation. Forwards commitment to operate in conformance w/NRC interim position for containment purge & vent valve operation.

  CROSS, J. L. Tennessee Valley Authority. 79/12/10. 5pp.
- 7912270251 Forwards amends to Licenses DPR-33, DPR-52 & DPR-68 changing Tech Specs re containment integrated leak rate test.
  MILLS, L. M. Tennessee Valley Authority. 79/12/17. 2pp.
- --7912270256 Revised Pages 230 & 235 to Tech Specs re containment integrated leak rats test.

  \* Tennesses Valley Authority. 79/12/17. 4pp.
- ---7912270262 "Nuclear Containment Testing for TVA Nuclear Power Plants," presented at ANS 79111-16 winter meeting. CLARK, K. H., WHITE, T. J. Tennessee Valley Authority. 79/11/16. 50op.
- 7912270527 Notifies that Unit 2 will be in full compliance w/NUREG-0578 short-term requirements by 800101.
  MILLB.L.M. Tennessee Valley Authority. 79/12/19. ip.
- Q. Inspection reports. IE Bulletine & correspondence
- 7912030366 Forwards IE Insp Repts 50-259/79-31.50-260/79-31 & 50-296/79-31 on 791002-05.No noncompliance noted, LEWIS,R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/10/26. 2gp.

- --7912050379 IE Insp Repts 50-259/79-31 & 50-260/79-31 & 50-296/79-31 on 791002-05. No noncompliance noted Hajor areas inspected: core thermal power calculations, core power limits, radioactive discharge & plant operations.

  DANCE, H. C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. PRICE, D. S. Region 2. Atlanta, Office of the Director. 79/10/26. Spp.
- 7912040163 Forwards IE Info Notice 79-12A, "Attempted Damage to New Fuel Assemblies." No specific action or response required.

  O'REILLY J.P. Region 2, Atlanta, Office of the Director.

  79/11/09. 3pp.
- 7912210203 Forwards IE Insg Repts 50-259/79-32.50-260/79-32 & 50-296/79-32 on 791016-18 No noncompliance noted. MURPHY.C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/11/09. 2pp.
- ---7912210218 IE Insp Repts 50-259/79-32.50-260/79-32 & 50-296/79-32 on 791016-1B. No noncompliance noted Major areas inspected: thermal sleeve attachment welds, feedwater pump shaft failures & observation of work activities. VAN DODRN.P.K. Region 2. Atlanta. Office of the Director. HERDI.A.R. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/11/07. 3pp.
- 7912070499 Forwards IE Info Notice 79-27, "Steam Generator Tube Ruptures at Two PWR Plants." O'REILLLY, LP. Region 2, Atlanta, Office of the Director. 79/11/16. 149p.
- 7912100192 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/16. 1p.
- 7912110575 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/16. 2pp.
- 7912060620 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BMRs." No response required.

  O'REILLY.J.P. Region 2, Atlanta, Office of the Director.
  79/11/26. 1p.
- 7912190472 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation." Written response required.
  O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/30. ip.
- 7912210202 Forwards IE Insp Repts 50-259/79-40,50-260/79-40 & 50-296/79-40 on 791113-16. No noncompliance noted Details withheld (ref 10CFR2.790). KENNA, M. B. Region 2, Atlanta, Safeguards Branch. 79/12/05. 2pp.
- --7912210212 IE losp repts 50-289/79-40.50-260/79-40.50-294/79-40 on 791113-16. No noncompliance noted Hajor areas inspected: socurity organization. Details withheld (ref 100FR2.790). TILLMAN.A. Region 2. Atlanta. Defice of the Director. TOBIN.W.J. Region 2. Atlanta. Bafeguards Branch. 79/12/04.
- 7912310314 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action required.

  O'REILLY, J. P. Ragion 2. Atlanta, Office of the Director.

  79/12/06. 6pp.
- 7912200060 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps," Action required. C'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/12/07. 3pp.
- 7912280426 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required.
  O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
  79/12/19. 3pp.
- 7912280150 Forwards IE Circular 79-25, "Shock Arrestor Strut Assembly Interference;" No written response required.

  O'REILLY, J.P. Region 2, Atlanta, Office of the Director.

  79/12/20. 4pp.

O

Periodic operating reports & related correspondence

12140384 Forwards monthly operating repts for Nov 1979. ABERCROMBIE.H. Tennessee Valley Authority. 79/12/10. 1p.

7912140393 Honthly operating repts for Nov 1979. GREEN.D. Tennessee Valley Authority. 79/12/02. 33p.

Reportable occurrences. LERs & related correspondence

12180299 PNO-11-79-007: on 791007, supporting chain holding tube bundle from RHR sys heat exchanger broke, dropping bundle approx 20 ft back into shell of heat exchanger. RHR sys not required for operation prior to reactor startup.
PRICE D.S., DANCE, H.C. Region 2, Atlanta, Office of the Director.
79/10/09. 1p.

12:180213 PNO-11-79-034: on 791127. Revision 2 emergency responses ctr activated when notified by TVA of planned drill retransport of radwaste. Inspectors w/survey equipment dispatched to site of simulated accident. JUNES.D. Region 2. Atlanta. Office of the Director. 79/11/27.1p.

12190354 RD 50-296/79-19:on 791204, during augmented ultrasonic insp of core spray piping, indication located adjacent to safe-end to core spray pipe weld Caused by stress corrosion cracking.Piping replaced w/carbon steel. ABERCROMBIE.H. Tennessee Vailey Authority. 79/12/09. 1p.

12270475 Forwards LER 79-019/01T-0. CALHOUN J.R. Tennessee Valley Authority. 79/12/17. Lp.

7912270483 LER 79-019/01T-0:on 791204.while performing ultrasonic insp of core spray piping, indication found adjacent to safe-end-to-core spray pipe weld DQB-3-18.Possibly caused by stress corrosion cracking in obtainless steel pipe. \* Tennessee Valley Authority. 79/12/17. 2pp.

12270564 Forwards LER 79-020/03L-0. CALHOUN, J. R. Tennessee Valley Authority. 79/12/19. ip.

7912270574 LER 79-020/03L: on 791120 during refueling outage secondary containment integrity lost when both hatches in personnel air lock from turbine bldg to reactor bldg opened simultaneously for 15-s. Caused by bent door lock bolt.

\* Tennassee Valley Authority. 79/12/19. 2pp.

12280503 Forwards LER 79-021/01T-0. CALHOUN.J.R. Tennessee Valley Authority. 79/12/21. ip.

7912280507 LER 79-021/017-0:on 791208, following refueling outage & Unit 3 return to svc.escessive drywell laskage occurred. Caused by loose holts around hatch door. Bolts were retightened & administrative controls initiated to verify seal worthineds. \* Tonnessee Valley Authority. 79/12/21. 2pp.

CKET 50-297 NORTH CAROLINA STATE UNIV. PULSTAR REACTOR Security, medical, emergency & fire protection plans

12120206 Forwards draft Reg Quide 9.XX, "Btd Format & Cuntent for Licensee Physical Security Plan for Protection of SNH of Moderate or Low Strategic Significance." W/o encl. REID.R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22.

Inspection reports, IE Bulletias & correspondence

12310223 Responds to IE Bulletin 79-19. "Packaging of Low Level Radwaste for Transport & Murial." Bixtoon shipments made in Jam 1978-June 1979. HDRBAND.W. North Carolina State Univ. 79/12/06. 3pp.

CKET 50-298 COOPER NUCLEAR STATION

Security, medical, emergency & fire protection plans

12200022 Discusses NRC 791109 meeting re emergency gregaredness toam review objectives.Provides guidence for improving licensee emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions. ORIMES.B.K. Emergency Preparedness Task Force. 79/11/23. 30pp.

P. Operating license stage documents & correspondence

7912140233 Forwards response to IE Bulletin 79-14, "Beismic Analysis for As-Built Bafety-Related Piping Sys." Insp results for all safety-related sys not addressed in previous responses enci. PILANT,J.M. Nebraska Public Power District. 79/10/30. 3pp.

7912100189 Discusses NRC 791101 meeting w/representatives of NSSS vendors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EISENHUT, D. 0. Division of Operating Reacturs. 79/11/09. 65pp.

--7912100255 Responds to NRC 791101 request re noncompliance of Westinghouse ECCB evaluation model under requirements of 10CFR50 App K. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants. ANDERSON.T.M. Westinghouse Electric Corp. 79/11/02. 4pp.

--79:12100330 Responds to NRC 79:101 request re GRML cladding swelling & rupture data.Review of analytical models & tests indicates compliance w/10CFR50 App K.All GE specs for calculated peak cladding temp remain unchanged.

BUCHHDLZ.R.H. General Electric Co. 79/12/07. 2pp.

--7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50. 46 satisfied.

DUSLEY, G.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).

79/11/02. 5pp.

--7912100456 Forwards add1 info re evaluation of impact of NRC proposed rupture/blockage model used in vandor evaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. OMSLEY, O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.), 79/11/04. 22pp.

7712170039 Notification of meeting w/utils in Brownsville, NE & Omaha, NE to discuss NRC post-TMI emergency planning acceptance criteria. Agenda encl.
IPPOLITO, T. A. Operating Roactors Branch 3. 79/11/16. Spp.

7912040251 Forwards commitments to followup actions required by NRC as result of TMI-2 review. Justification for delay in direct indication of valve position schedule & description of degree of compliance included.
PILANT, J. M. Nebraska Public Power District. 79/11/20. 8pp.

7912070329 Forwards add1 info on short-term TMI Lessons Learned Task Force requirements, concerning emergency power, safety valves & diverse containment isolation. PILANT, J. M. Nebraska Public Power District. 79/12/03. 3pp.

7712120259 Concurs w/intent of GE 771130 ltr to NRC:formallzing commitment to perform limited number of addl confirmatory full scale condensation escillation tests.
PILANT., M. Nebraska Public Power District. 79/12/04. 1p.

7912190549 Responds to NRC 790918 request for add1 info re loss of offsite eys on 760222 Four lines lost feeding 345 kV switchyard ring bus connected to startup transformer Couse. Fault on 345 kV relay & felse relaying resulting from storm PILANT. J. M. Nebraska Public Power District. 79/12/14. 3pp.

7912280842 Commits to operate facility in accordance w/interim position provided in NUREG-0578 re containment purging & venting during normal operation. Echedule for required mode will be submitted approx 800101.

PILANT, J. N. Nebraska Public Power District. 79/12/18. 3pp.

Q. Inspection reports, IE Bulletins & correspondence

7912140248 Responds to IE Bulletin 79-23, "Potential Failure of Emergancy Dissal Consertor Field Exciter Transformer." No direct connection exists between neutrals of excitation power transformer & emergency dissel gonerator.
PILANT, J. N. Nabraska Public Power District. 79/09/28, 1p.

7912140133 Forwards IE Sulletin 79-17, Revision 1, "Pipe cracks in Biagnant Borated Water Bys at PWR Plants." No written response required SEYRIT, K. V. Region 4, Dallas, Office of the Director, 79/10/29.

- 7912120564 Forwards IE Bulletin 79-25, "Failures of Westinghouse BFD Relays in Safety-Related Sys." Action required. SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/11/02, in.
- 7912190026 Forwards IE Circular 79-22, "Stroke Times for Power Operated Reliaf Valves." No written response required. SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/11/16.
- 7912120553 Forwards IE Bulletin 79-26. "Boron Loss From BWR Control Blades." Response required.
  SEYFRIT.K.V. Region 4. Dallas. Office of the Director. 79/11/20.
- 7912110484 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general offcs copies of escalated enforcement correspondence sent by NRC to licensees.

  SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/11/26.
- 7912190141 Grants 791108 request for extension until mid-Mar 1980 to answer Item 3 of IE Bulletin 79-14. Grants extension until 800227 to complete AE assessment of isometric drawings resulting from past insps.

  EEYFRIT.K.V. Region 4, Dallas, Office of the Director. 79/11/26.
- --7912190180 Requests extension to mid-Mar 1980 to verify remaining isometric piping drawing to complete response to IE Bulletin 79-14, "Beismic Analysis for As-Built Bafety-Related Piping Bys." PILANT, J. H. Nebraska Public Power District. 79/11/08. 2pp.
- 7912190185 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation." Whitten response required.
  BEYFRIT.K.V. Region 4, Dallas, Office of the Director. 79/11/30.
- R. Periodic operating reports & related correspondence
- 7912140395 Forwards monthly operating rapt for Nov 1979. LEBBOR, L. C. Nabraska Public Fower District. 79/12/07. ip.
- --7912140399 Honthly operating rept for Nov 1979. BALLINGER, P. L. Nebraska Public Power District. 79/12/07. 4pp.
- S. Reportable occurrences, LERs & related correspondence
- 7912200019 PNO-IV-79-014: on 791114, reactor taken off line due to inability to determins cause of emergency diesel generator 2 malfunction.

  CONSTABLE, I., HESTERMAN, I.F. Office of Inspection & Enforcement, Office of the Director. 79/11/15, ip.
- 7912130387 Forwards LER 79-030/03L-0. LEBSOR, L. C. Nebraska Public Power District. 79/11/20. 2pp.
- --79:2:30:389 LER 79-030/03L-0: on 79:021, while pumping water from torus to radwaste; drywell-to-torus differential pressure dropped below Tech Space. Caused by nitrogen pressure forcing water from downcomers to flow to torus.
  PHILLIPS, D. L. Nabraska Public Power District, 79/11/20. ip.
- 7912130391 Forwards LER 79-032/03L-0. LEBBOR, L. C. Nebraska Public Power District. 79/11/21. 2pp.
- --7912130393 LER 79-032/03L-0: on 791026; during normal operation, doors to MPCI & RHR B&D pump rooms left open w/o fire watch, Causad by personnel error. Occurrence discussed w/personnel involved. Fire doors controlled by procedure posted w/signs.

  LAWRENCE.L. I. Nebraska Public Power District. 79/11/21. 3pp.
- 7912310435 Forwards LER 79-033/03L-0. LEBSOR, L. C. Nebreska Public Power District. 79/12/06. 3pp.
- ---7912310437 LER 79-033/03L-0: on 791109, surveillance procedure re diesel generator operability not performed on diesel generator 1, Perwonnel under impression diesel generator 2 would not be made operable. Test performed following day.
  WILLIAMS.M. 0. Nabraska Public Power District. 79/12/06. ip.
- 7912310447 Forwards LER 79-034/03L-0. LESBOR, L. C. Nebraska Public Power District. 79/12/06, 2pp.

- --7912310450 LER 79-034/03L-0: on 791107, base for diesel generator 2 lube oil header to cam chain tensioner broke. Caused by hose proximity to cam chain & tensioner sprocket. Hose replaced & clamped away from cam chain.

  DOAN, P. F. Nebraska Public Power District. 79/12/06. ip.
- 7912310459 Forwards LER 79-035/03L-0. LESSOR.L.C. Nebraska Public Power District. 79/12/07. 2pp.
- --7912310467 LER 79-035/03L-0: on 791109, during core spray operability surveillance procedure. CB-HD-12A valve would not open electrically. Caused by failure of axial movement on worm set clutch collar. Valva repaired.

  FLANNIGAN, R. D. Nebraska Public Power District. 79/12/07. 1p.
- 7912310442 Forwards LER 79-036/03L-0. LEBSOR, L. C. Nebraska Public Power District. 79/12/10. 2pp.
- --7912310444 LER 79-036/03L-0: on 791110, four cylinder sleeves in diesel generator 2 damaged during surveillance test. Cause under investigation. Damaged parts replaced & cylinders inspected. DDAN, P. F. Nebraska Public Power District. 79/12/10. ip.
- 7912310438 Forwards LER 79-037/03L-0. LE580R.L.C. Nebraska Public Power District. 79/12/12. 2pg.
- ---7912310440 LER 79-037/03L-0: on 791113 diesel Cenerator 1 failed to start, Caused by silencer bypass solenoid stopping in midposition due to insufficient air supply. Valve opened & air supply capped. Sys will be modified. PHILLIPB.D.L. Nebraska Public Power District. 79/12/12. 1p.
- DOCKET 50-301 POINT DEACH NUCLEAR PLANT, UNIT 2
  F. Becurity, medical, emergency & fire protection plans
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives. Provides guidance for improving licensee emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.

  ORIMEB.B.K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- 7912130295 Forwards Revision 11 to emergency plan manual requiring that NRC be notified within 1-h of initiation of onsite evacuation plan & implementing temporary support ctrs w/dedicated phone line to NRC.
  FAY.C.W. Wisconsin Electric Power Co. 79/12/06. 3pp.
- --7912130303 Revision il to emergency plan manual. \* Wisconsin Electric Power Co. 79/10/22. 100pp.
- 7912120230 Submits info re modified amended security plan. Info withheld (ref 10CFR2.790).
  BURBTEIN, S. Wisconsin Electric Power Co. 79/12/07. 1p.
- 7912270495 Forwards Revision 12 to omergency plan manual. Page change instructions provided.
  FAY.C.W. Wisconsin Electric Power Co. 79/12/17. 2pp.
- --7912270500 Revision 12 to emergency plan manual.Page change instruction & supporting ltr encl.

  \* Wisconsin Electric Power Co. 79/12/17. 11pp.
- 7912310217 Discusses evaluation of incomplete items identified in 790802 fire protection safety evaluation Licensee submitted info re brigade shift size on 791001 & basis for staff assignments on 790821 Proposed fire brigade acceptable. LAINAS. Q. Plant Systems Branch. 79/12/17. 4pp.
- 7912270191 Forwards rept, "Fire Detector Location Plan." mod to fire protection plan. Requests communt.
  FAY.C.W. Wisconsin Electric Power Co. 79/12/20. 2pp.
- --7912270196 "Fire Datector Location Plan." mod to fire protection plan.
  \* Wisconsin Electric Power Co. 79/12/20. 55pp.
- Q. Adjudicatory correspondence
- 7912110038 Confirms receipt of encl 790329 petition to suspend DLs for all PMRs. Forwards FR notice indicating that petition will be treated in accordance w/100FR2.206.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/23. ip.

712110126 Notice of request for action pursuant to 10CFR2 206 re Environ Coalition on Nuclear Power 790329 petition requesting suspension of all OLs for PWRs. MULLER, D. R. Office of Nuclear Reactor Regulation. 79/11/23.

2140838 Requests that future hearing re removal & storage of amerators be held in Manitowoc, WI. 3TES, J. Lakeshore Citizens for Safe Energy. 79/11/29. 1p.

2280154 Opposition to MI Environ Decade Inc 791126 petition to stervene & request for hearing.Request premature since societies on tyst initiated. If hearing required re amend, BLB must be appointed to rule on petition. 'NEILL, J. H. Wisconsin Electric Power Co. 79/12/07. 7pp.

### Jeneral correspondence

1:30478 Requests NRC investigation of safety aspects of steam tube merator leaks. Meeting should be held to inform public of Indings. Indings. 3TES.J. Lakeshore Citizens for Safe Energy. 79/11/07. 1p.

### Iperating license stage documents & correspondence

.070248 "Summary of Operating Experience W/Recirculating Steam nerators."
SECNIUT.D.Q. Division of Operating Reactors. NUREG-0523.
701/31. 89aa.

1050193 Discusses NRC review of LERs & Tech Spec requirements reintrol RPI sys at Westinghouse PHRs. Requests Tech Spacs view to ensure requirement for rod maint to within +/- 12 seps indicated & RPI sys verified accurate within 12 steps. HHENCER: A. Operating Reactors Branch 1. 79/10/29. 7pp.

#130608 Submits partial response to 790921 ltr re short-term & ng-term requirements for auxiliary feedwater sys. Requests tension until 800131 for remaining requirements.

|X.C.W. Wisconsin Electric Power Co. 79710729. 4pp.

100187 Discusses NRC 791101 meeting w/representatives of NSSS ndors & fuel suppliers re discussion of respective rtions of ECCS evaluation models dealing w/fuel cladding elling & incidence of rupture. Vendor responses and. SENHUT.D. G. Division of Operating Reactors. 79/11/09, 45pp.

12100255 Responds to NRC 791101 request re noncompliance of Westinghouse ECGS evaluation model under requirements of 100FR50 App K. Evaluation of three Fuel rod models indicates no safety problems for Westinghouse glants.
ANDERSON, T. M. Westinghouse Electric Corp. 79/11/02. App.

12100330 Responds to NRC 791101 request re ORNL cladding swelling & rupture data. Review of analytical models & tests indicates compliance w/10CFR50 App K. All 9E specs for calculated peak cladding temp remain unchanged.
BUCHHOLZ, R. H. General Electric Co. 79/12/07, 2pp.

12100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by Fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR90. 46 satisfied.

DMSLEY, O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). DHSLEY, 0. F. E: 79/11/02, 5pp.

12100456 Forwards add1 info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. IMBLEY, G.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.), 79/11/04. 22pp.

390474 Advises that supplemental info re lessons learned info will forwarded 791127. δ.C.W. Hisconsin Electric Power Co. 79/11/20. ip.

MO171 Ack receipt of NRC 791030 request for payment re approval of the Spec Change 61 No change occurred to reporting level radiochemical engineer & health physicist to warrant 0300 reclassification as Class III fee. C.C.W. Wisconsin Electric Power Co. 79/11/21. 2pp.

30172 Responds to NRC 791123 telcon re revised ECCB reanalysis for an generator tubes plugged up to 18%. STEIN.B. Wisconsin Electric Power Co. 79/11/26. 2pp.

- 7912130012 Summary of 791119 telcon w/util re proposed schedule for implementation of Lessons Learned Task Force recomendations.
  TRAMMELL.C.M. Operating Reactors Branch 1. 79/12/06. App.
- 7912140369 Responds to 790917 ltr re commitment to EPA U fuel cycle std. Facility already in compliance w/procedure comparing actual quantity of radioactive mati released w/dose design objectives of code.
  FAY. C. W. Wisconsin Electric Power Co. 79/12/06. 2pp.
- 79i2180578 Notifies that NRC radiation safety certification is acceptable in lieu of util safety program.
  FAY.C. H. Wisconsin Electric Power Co. 79/12/06. ip.
- 7912190562 Requests reconsideration of license fee applicability to 790710 Tech Baec change requested re qualification requirements for radiation safety manager Change originally requested by NRC. No safety issue involved.

  FAY.C.W. Wisconsin Electric Power Co. 79/12/10. 2pp.
- 7912210143 Forwards response to NRC 791004 request for addl info on inservice insp & testing program. Oversize drawing encl. FAY, C. W. Wisconsin Electric Power Co. 79/12/14. App.
- 7912270300 Submits add1 info for NRC review of Tech Spec Change 60 for operation at reduced primary sys operating pressure. PAY.C.M. Wisconsin Electric Power Co. 79/12/14. 5pp.
- 7912270430 Responds to NRC 791210 request for add1 info on TMI Lessons Learned Task Force recommendations re auxiliary feedwater sys. Oversize drawings available in Central Files. FAY.C.W. Wisconsin Electric Power Co. 79/12/17. 2pp.
- 7912280554 Forwards modified response to previous commitment to implement NUREG-0578. Util will provide alarms in addition to existing position indication for power operated relief valves for both units.

  BURSTEIN.S. Wisconsin Electric Power Co. 79/12/17. 4pp.
- 7912270206 Requests amend to Licenses DPR-24 & DPR-27 incorporating changes in Tech Specs re rod bow & Section 15.3.10 clarification. Fee encl.
  BURBTEIN 8. Wisconsin Electric Power Co. 79/12/19. 4pp.
- --7912270220 Revised Pages 15.1-4 through 19.3, 10-14 for proposed amend to Toch Speck re control rod & power distribution limits. \* Wisconsin Electric Power Co. 79/12/19. 20pp.
- 7912280601 Advises that seal ring should be removed following each refueling outage by raising ring more than 12 ft above cavity floor in response to NRC 791002 request. Util does not concur w/NRC belief that ring could become missile.

  BURSTEIN.S. Wisconsin Electric Power Co. 79/12/20. ip.
- 7912270492 Forwards mod to Tech Spec Change Request 60. BURSTEIN.B. Wisconsin Electric Power Co. 79/12/21. 3pp.
- -7912270499 Proposed Tech Spec Page 19.2.3-2 reflecting mod to Tech Spec Change Request 60.Provides addl operating margin between proposed primary sys pressure & low pressurizer reactor trip setpoint. Wisconsin Electric Power Co. 79/12/21. 1p.
- G. Inspection reports, IE Bulletins & correspondence
- 7912260094 Forwards IE Insp Repts 50-266/79-15 & 50-301/79-17 on 791023-24. No noncompliance noted. DAVIB.A.B. Region 3. Chicago, Fuel Facility & Materials Bapety Branch. 79/11/09. 2pp.
- --791226009B IE Insp Repts 50-266/79-15 & 50-301/79-17 on 791023-24. No noncompliance noted Major areas inspected:confirmatory measurements & radiological environ protection.
  ESBIG.T. H., OESTMANN. M. J., ROYTEK. C. Region 3, Chicago, Office of the Director. 79/11/08. Bpp.
- 79:2050156 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valvas." No response required.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912100249 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/16.

- 7912110593 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required.

  KEPPLER, J. Q. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912310139 Responds to IE Bulletin 79-13, "Cracking in Feedwater Sys Piping." Outlines Unit 1 insp & repair. FAY, C. W. Wisconsin Electric Power Co. 79/11/19. 3pp.
- 7912050414 Forwards IE Bulletin 79-26, "Boron Loss From BWR Control Blades." No response required.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/20.
- 7912100447 Forwards IE Circular 77-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BHRs." No written response required.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/26,
- 7912140245 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No written response required.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/26.
- 7912110448 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sent by NRC to licensees.

  KEPPLER, J. O. Region G. Chicago, Office of the Director. 79/11/28.
- 7912190235 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Written response required.
  KEPPLER. J. Q. Region 3. Chicago, Office of the Director. 79/11/30.
- 7912200027 Responds to IE Bulletin 79-17. Required piping examinations completed 791012. No abnormalities found. Forwards final rept on piping examinations. W/o encl. FAY, C. W. Wisconsin Electric Power Go. 79/11/30. 2pp.
- 7912210144 Ack receipt of 791022 ltr re inspector access Response will be forwarded upon completion of review.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/12/05.
- 7912140106 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action or response required.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/12/06.
- 7912280650 Forwards 30-day response to IE Bullstin 79-02, Revision 2, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts." Accessible support testing complets. Sample insp of small pipe supports shows more testing not needed, FAY, C. W. Wisconsin Electric Power Co. 79/12/07. 4pp.
- 7912200153 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. KEPPLER, J. O. Region 3, Chicago, Dffice of the Director. 79/12/10.
- R. Periodic operating reports & related correspondence
- 79:2:80444 Forwards monthly operating rept for Nov 197 BURSTEIN, S. Wisconsin Electric Fower Co. 79/12/10.
- --7912180449 Monthly operating rept for Nov 1979. BURSTEIN, 8. Wisconsin Electric Power Co. 79/12/05. 10pp.
- T. Hearing transcripts on non-antitrust matters
- 7912100210 Transcript of 791128 public meeting in Washington, DC. Pp 1-94. \* Commission. 79/11/20, 95pp.
- --7912100217 Submits proposed schedule for 791128 brisfing re steam generator tube degradation. Visugraphs encl.
  BICKHIT.L. Office of the General Counsel. 79/11/28. 18pp.

- DUCKET 50-302 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3 F. Security, medical, emergency & fire protection plans
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives Provides guidance for improving licensee emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.

  GRIMES.B.K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- 7912130201 Forwards add1 design drawings for fire protection mods, in response to NRC 790727 request per safety evaluation in Amend 23 of OL. Description of fire detection sys encl. Drawings available in Central Files only.

  BAYNARD, P. Y. Florida Power Corp. 79/12/06. Ilpp.
- 7912200094 Responds to 790B17 ltr re security training & qualification plan Approval or amend fee of \$4,000 required before final review of plan by NRC.

  DIGGS.R.M. License Fee Management Branch. 79/12/07. 1p.
- 7912260245 Forwards add1 info concerning fire program re alternate safe shutdown capability proposed mod.in response to NRC 790911 request.

  HANCOCK, J. A. Florida Power Corp. 79/12/17. 5pp.
- --7912260254 "Sys Instrumentation & Controls Required to Go to Shutdown from Outside Control Room." \* Florida Power Corg. 79/12/17. 19pp.
- 7912310533 Forwards draft version of upgraded emergency plan in accordance w/format of Reg Quide 1.101.in response to NRC 791010 request. Draft Procedure NSSD-17. "Dffsite Radiological Support Plan" encl.
  MDORE. G. C. Florida Power Corp. 79/12/27. 3pp.
- -7912310536 Draft Procedure 17, "Offsite Radiological Support Plan." \* Florida Power Corp. 79/12/20. 10pp.
- --7912310540 Draft "Emergency Procedure EM-100." \* Florida Power Corp. 79/12/27. 250pp.
- Q. Adjudicatory correspondence
- 7912180327 Requests that NRC take immediate action to shut down PUTNEY, L. W. Putney, L. W. 79/11/04. 2pp.
- 7912110038 Confirms receipt of encl 790329 petition to suspend DLs for all PWRs.Forwards FR notice indicating that petition will be treated in accordance w/10CFR2.206. DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/23. ip.
- --7912110126 Notice of request for action pursuant to 10CFR2.206 re Environ Coalition on Nuclear Power 790329 petition requesting suspension of all GLs for PWRs. MULLER, D. R. Office of Nuclear Reactor Regulation. 79/11/23. 38pp.
- H. General correspondence
- 7912200634 Responds to 791106 ltr re safety of nuclear power plants.
  Facility 36 miles from nearest population ctr of 25,000 or more. Lessons learned from TML accident will be reviewed & evaluated to assess need for new safety margins.

  DENTON: H.R. Office of Nuclear Reactor Regulation. 79/12/05. 2pp.
- J. Insurance & indemnity information
- 7809190350 Informs recipient of Duke Power Co 780705 request to modify station Indomnity Agreement B-44 to permit receipt & possession of 4 fuel assemblies from Crystal River 3 facility.
  FAIRTILE.M. B. Operating Reactors Branch 4 (Pre 790625).
  78/09/14. 2pp.
- 7912190629 Forwards executed Amend 7 to Indomnity Agreement 8-54, modifying prefatory language re transportation of radioactive matl.
  FREITAG, J. D. Florida Power Corp. 79/12/13. 3pp.

- P. Operating license stage documents & correspondence
- 7911090248 "Summary of Operating Experience W/Retirculating Steam Generators." Bivision of Operating Reactors. NUREG-0523. 79701731. B9pp.
- 7912190268 Forwards Revision 1 to 790802 submittal w/discussion of differences between Revisions 0 & 1. Also forwards Gilbert Associates 790924 ltr. All but four required insps conducted for safety-related piping listed in ltr. STEWART. W.P. Florida Power Corp. 79/10/30. 17pp.
- 7912310070 Ack 790831 Itrs endorsing B&W generic rept BAW~1864, "Integrated Control Sys Reliability Analysis," & requests addl info. REID,R.W. Operating Reactors Branch 4. 79/11/07. 13pp.
- 7912130181 Forwards summary of Teknekron Rossarch, Inc study of licenseo regulatory performance evaluation & Teknekron draft rept re operating reactors w/B&W nuclear steam supply sys.Roquests comments.W/o encl.
  STELLOV. Defice of Inspection & Enforcement, Office of the Director. 79/11/08. 2pp.
- 7912100187 Discusses NRC 791101 meeting w/representatives of NSSS vendors & fuel suppliers re discussion of respective partions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EISENHUT. D. O. Division of Operating Reactors. 79/11/09. 45pp.
- ---7912100255 Responds to NRC 791101 request re noncompliance of Westinghouse ECCS evaluation model under requirements of 10CFR50 App K. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants. ANDERSON.T. M. Westinghouse Electric Corp. 79/11/02. 4pp.
- --7912100330 Responds to NRC 791101 request re GRNL cladding swelling & rupture data. Review of analytical models & tests indicates compliance w/10CFR50 App K.All GE specs for calculated peak cladding temp remain unchanged.

  BUCHHOLZ,R.H. General Electric Co. 79/12/07. 2pp.
- ---7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50. 46 satisfied.

  OHELEY.O.F. Exton Nuclear Co., Inc. (subs. of Exton Corp.).
  79/11/02. 5pp.
- --7912100456 Forwards addl info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model.
  No advarse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results.
  DMELEY.O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/11/04. 229p.
- 7912120072 Summary of 791024 meeting w/B&W owners group re asymmetric LOCA loads evaluation. Evaluation of B&W plants to be completed by Jul 1780.
  HCSPCRD.8.B. Assistant Director for Engineering Programs.
  79/11/20. 4pp.
- 7912100478 Forwards, to all B&W operating plants except TMI, request for addl info re small break LGCA. Comments requested by 791203.
  REID,R,W. Operating Reactors Branch 4. 79/11/21. 3pp.
- 7912100222 Requests detailed info re wear characteristics of control rods on guide tubes in fuel assemblies. Info needed to verify that guide tube wear was not significant problem in IMM factilities. NRC concerns re tube wear enci. REID.R.H. Derating Reactors Branch 4. 79/11/23. 6pp.
- 7912040441 Bubmits confirmation of sotpoint derivation per Tech Spec Change Request 35. BRIGHT.R.M. Florida Power Corp. 79/11/27, 2pp.
- 7912040499 Forwards Section 2.20 of Cycle 1 refueling dutage rept in response to J Strosnider request for info re once-through steam generator B repairs.
  8810H1.RM. Florids Power Corp. 79/11/27. 1p.
- --7912040502 Cycle I refueling outage rept, Section 2.20. \* Florida Power Corp. 79/11/27, 27pp.
- 7912050042 Forwards Amend 26 to License DPR-72 & notice of issuance & availability.
  REID,R.W. Operating Reactors Branch & 79/11/27. Spp.

- --7912050048 Amend 26 to License DPR-72 modifying Tech Specs to require five-man fire brigade.
  REID.R.W. Operating Reactors Branch 4. 79/11/27. Spp.
- --7912050053 Notice of issuance & availability of Amend 26 to License DPR-72.
  REID.R.W. Operating Reactors Branch 4. 79/11/27. 2pp.
- 7912070460 Forwards response to NRC 791121 1tr requesting add1 info re small break LOCAs. HANCOCK.J.A. Florida Power Corp. 79/12/03. 3pp.
- 7912110410 Forwards revised Pages 5-1 through 5-5,6-2,6-7,6-11 & 6-12 for Proposed Change 55 to Tech Spucs requesting amend of Apps A & B re title of director of nuclear operations & offsite organizational figure.Fee & Certificate of Svc encl. HANCOCK.J.A. Florida Power Corp. 79/12/04. 3pp.
- --7912110417 Revised Pages 5-1 through 5-5,6-2,6-7,6-11 & 4-12 for Proposed Change 55 to Tech Specs requesting amend of Apps A & B re title of director of nuclear operations & offsite organizational figure.

  \*\* Florida Power Corp. 79/12/04. 9pp.
- 7912260025 Advises of NRC position, in response to 790725 submittal repump & valve inservice testing program. High & low pressure interfaces w/two or more valves shall be leak tested periodically Requests design provisions per encl. REID, R. W. Decrating Reactors Branch 4. 79/12/04. Spp.
- 7912280637 Requests design provisions &/or procedures to permit leak testing of valves in interfaces between high & low pressure sys. W/o encl.
  REID.R.W. Operating Reactors Branch 4. 79/12/04. ip.
- 7912110351 Submits addl info concerning response to Guestion 7 of NRC 770803 ltr. Addl nonlinear time history sliding enalysis performed. Max sliding distance for high density fuel storage racks not affected by time history motion beyond 1.2-w. MODRE, O.C. Florida Power Corp. 79/12/05. App.
- 7912120288 Responds to NRC 770808 ltr re electrical power sys review.

  Offsite power sys & onsite distribution sys in compliance w/NRC guidelines.

  MOURE, G. C. Florida Power Corp. 79/12/05. 3pp.
- 79122260307 Requests info re sensitivity-to-feedwater transients be forwarded to TMI-1 Board.
  VOLLMEN.R. H. Assistant Director for Systematic Evaluation Program (Pro 791030). 79/12/05. 3pp.
- --7912260348 "IREP Initial Plant Study." Attempts to develope assessment of D&H reactors to identify risk impacting sequences re reactor safety study & preliminarily identify possibly impacted by design changes.

  \* Office of Nuclear Reactor Regulation. 79/10/25. App.
- 7912180271 Forwards revised Pages 4 & 5 to Tech Specs re fire protection & secondary water chemistry monitoring program re 790724 Tech Spec change request, Number 50. Certificate of Svc encl.
  BAYNARD, P. V. Florida Power Corp. 79/12/07. 4pp.
- --7912180275 Revised Pages 4&5 to Tech Specs re fire protection & secondary water chemistry monitoring program. \* Florida Power Corp. 79/12/07. 2pp.
- 7912140922 Forwards response to 791121 Question 3 re small break LOCAs. Response to Question 1 will be submitted in mid-Jan 1980. HANCOCK, J. A. Florida Power Corp. 79/12/10. Spp.
- 7912140239 Notifies of one wk dolay in obtaining info re proposed alternate safe shutdown capability mod requested 790911.

  HANCOCK.J. A. Florida Power Corp. 79/12/10. 2pp.
- 7912270575 Provides info re new fuel cladding strain & fuel assembly flow blockago models in response to NRC 791109 ltr. Agrees w/results presented by BtW re calculated peak fuel clad temp. Compliance w/100FR90. 46 shown.
  HANCOCK. J. A. Florida Power Corp. 79/12/20. 2pp.
- O. Inspection reports. IE Bulletins & correspondence
- 7912050060 Forwards IE Inop Rept 50-302/79-42 on 791001-05. No noncompliance noted, LEWIS.R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/10/24. 2pp.

- --7912080068 IE Insp Rept 50-302/79-42 on 791001-05. No nencompliance noted Major areas inspected: review of LERs: followup on previously identified items & plant tour.
  GUICK, D.R. Region 2, Atlanta, Office of the Director. DYER, J. A. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/10/24. App.
- 7912180114 Forwards IE Insp rept 50-302/79-43 on 791009-12 No noncompliance noted. LEMIS.R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/11/07. 2pp.
- --7912180121 IE Insp Rept 50-302/79-43 on 791009-12. No noncompliance noted, Major areas inspected; containment integrated leak rate testing & plant operations.
  JOHNSON, A. H. Region 2. Atlanta, Office of the Director.
  BURNETT, P. T. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 79/11/07. 5pp.
- 7912040134 Forwards IE Info Notice 79-12A, "Attempted Damage to New Fuel Assemblies." No specific action or response required. O'REILLY, J. P. Region 2. Atlanta. Office of the Director. 79/11/09. 2pp.
- 7912100114 Respands to IE Bulletin 79-25 re failure of Westinghouse BFD relays. No Westinghouse BFD/NBFD relays used or planned for use in safety-related sys. HOORE, G. C. Florida Power Corp. 79/11/14. ip.
- 7912100207 Responds to IE Bulletin 79-05C, Item 5.88W operating guideline contains instructions for establishing & maintaining plant control during inadequate core cooling conditions.

  HANCOCK, J. A. Florida Power Corp. 79/11/14. 2pp.
- 7912100176 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. G'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/16. 1p.
- 7912110358 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/16. 2pp.
- 7912310336 Forwards IE Insp Rept 50-302/79-44 on 791015-19 & notice of violation. LEWIS.R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/11/16. 2pp.
- ---7912310338 Natice of violation from insp on 791015-19.
  Region 2. Atlanta, Office of the Director. 79/11/16. 1p.
- ---7912310346 IE Insp Rept 50-302/79-44 on 791015-19. Noncompliance noted: failure to submit prompt rapt when determined spray additive sys less conservative than less conservative aspect of Tach Specs.

  MCHENRY, T. J. Region 2, Atlanta, Office of the Director.

  MELLOGO, P. J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 79/11/16. Opp.
- 7912060561 Ack receipt of 791114 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 80-302/79-38.

  LEUIS,R.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 79/11/20. ip.
- --7912060666 Responds to NRC 791022 ltr re violation noted in IE Insuperty 50-302/79-38. Corrective action: procedure changes to demonstrate that isolation valves are operable following maint.

  HANCOCK, J. A. Florida Power Corp. 79/11/14. Rpp.
- ---7912060668 Forwards IE Insp Rept 50-302/79-38 on 790924-28 & notice of Violation.
  LEWIS, R.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 79/10/22. 2pp.
- --7912060671 Natice of violation from insp on 790924-28.

  \*\* Region 2, Atlanta, Office of the Director. 79/10/19. ip.
- ---7912060673 IE Insp Rept 50-302/79-38 on 790924-29. Noncompliance noted: failure to perform post-maint testing of containment isolation valves.

  BELISLE, O. A. Region 2. Atlanta, Office of the Director.

  BANCE, H. C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 79/10/19, 4pp.

- 7912060614 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Bpray Pipe Break Detection Equipment on BHRs." No response required.

  O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
- 7912i10i43 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/22. 1p.
- 79:12:190795 Forwards response to IE Bulletin 79-17.Revision i re stagnant borated water sys. Ultrasonic testing for pipe cracks not yet completed. Insp program for accessible & inaccessible welds in development by Gilbert Associates. BAYNARD, P. Y. Florida Power Corp. 79/11/29. 4pp.
- 7912190439 Forwards IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Written response required. D'REILIY, J.P. Region 2, Atlanta, Office of the Director. 79/11/30. ip.
- 7912310313 Forwards IE Info Notice 79-30. "Reporting of Defects & Noncompliances,10CFR21." No action requires.
  O'REILLY, J.P. Region 2. Atlanta, Office of the Director.
  79/12706. Spp.
- 7912200032 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. 0'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/12/07. 2pp.
- 791231001B Forwards response to IE Bulletin 79-02.Revision 2.re pipe support base plate designs. During field testing all wedge type concrete expansion anchors torqued per manufacturer recommendation for original installation.

  HANCOCK, J. A. Florida Power Corp. 79/12/10. 3pp.
- 7912280398 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Beectra." No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 79/12/13. 2pp.
- 7912310010 Updates 790921 response to IE Bulletin 79-18, "Audibility! Problem Encountered on Evacuation of Personnel from High Noise Areas." Engineering study complete & mod/installation of equipment to be completed by 800312.

  MDORE, D. C. Florida Power Corp. 79/12/13. 2pp.
- 7912310016 Forwards updated Table A-R. "Besign Documents Used for Analyses," in response to IE Bulletin 79-14 re seismic analyses for piping sys. W/a sncl. Updated table supersedes original submitted in 770912 ltr. HANGOCK, J. A. Floride Power Corp. 79/12/13. ip.
- 7912280134 Forwards IE Circular 79-25, "Shock Arrestor Strut Assembly Interferance." No written response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/12/20. App.
- R. Poriodic operating reports & related correspondence
- 7912180371 Forwards monthly operating rept for Nov 1979. HANCOCK, J. A. Florida Power Corp. 79/12/14. 1p.
- --7912180398 Monthly operating rept for Nov 1979. CULVER.M.W. Florida Power Corp. 79/12/10. Spp.
- 8. Reportable occurrances, LERs & related correspondence
- 7912030154 Forwards LER 79-087/01T-4.
  HANCOCK, J. A. Florida Power Corp. 79/11/27. 1p.
- --7912030157 LER 79-0B7/01T-4: on 791004, noted that seven closed cycle cooling sys hangers failed to meet safet requirements per IE Bulletin 79-02. Caused by Inadequa hanger design, Mod 79-6-86f initiated to rework hanger LANGASTER, K. F. Florida Power Corp. 79/11/20. 3pp.
- 7912100269 Forwards LER 79-106/03L-0, HANCOCK, J. A. Florida Power Corp. 79/12/04. 1p.

- --7912100275 LER 79-106/03L-0: on 79110B, during daily operating surveillance, concentrated boric acid flow path heat trace recorder HTRT-5 failed Caused by broken recorder drive cord. Drive cord & balance motor replaced. CDOPER, J. Flurida Power Corp. 79711/29. 2pp.
- 7912110330 Forwards LER 79-105/03L-0. HANCOCK, J. A. Florida Power Curp. 79/12/06. 1p.
- ---7912110331 LER 79-105/03L-0: on 791101, during sampling of RCS, chemical addition isolation valve CAV-2 would not close Cause unknown. Valve body of CAV-2 lubricated, satisfactorily tested & returned to svc on 791102.

  LANCASTER, K. F. Florida Power Corp. 79/11/23. 2pp.
- 7912260239 Forwards LER 79-107/03L-0. HANCOCK, J. A. Florida Power Corp. 79/12/18. 1p.
- --7912260243 LER 79-107/03L-0:on 791120, following routine pressurizer sampling, chemical addition isolation valve would not close. Caused by inadequate design. Installed Mod 79-11-81 providing pneumatic assist during valve closing.

  LANCASTER.K. F. Florida Power Corp. 79/12/12. 2pp.
- U. Congressional/Executive Correspondence
- 7912:30014 Responds to 790814 ltr re K Griffin concern about facility safety issues. Forwards NRC 790813 ltr to K Griffin NRC 790706 ltr to util facil fact sheet. GOSBICK.L.V. Office of the Executive Director for Operations. 79710704. ip.
- --7912130017 Responds to 790612 ltr re safety of facility.Forwards 790706 ltr to util authorizing restart of unit.Numerous regulations protect health & safety of public.

  EISENHUT.D.Q. Office of Nuclear Reactor Regulation. 79/08/13.
- --7912130020 Notifies of satisfactory completion of Section IV, Paragraph 1, Items A-G of NRC 790516 shut down order Facility may resume operation Facility fact sheet encl. DENTON, H. R. Office of Nuclear Reactor Regulation. 79/07/06. App.
- ---7912130022 Forwards K Griffin 790611 ltr re facility safety issues.
  Request comments.
  BTONE.R. Senate. 79/08/14. 3pp.
- DOCKET 50-304 ZION NUCLEAR POHER STATION, UNIT 2
- F. Security, medical, emergency & fire protection plans
- 7912170261 Discusses proposed task force review of emergency preparadness. Task force should study alternatives for raduction of probability & consequences of severe accident. EISENHUT, D. G. Division of Operating Reactors. 79/11/21. 3pp.
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives. Provides guidance for improving licensee emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions. ORIMES. B. K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- 7912200122 Notification of 791205 meeting w/util in Bethesda.MD, to review emergency preparedness capabilities.List of NRC considerations encl. EISEMHUT.D.O. Division of Operating Reactors. 79/11/29. Opp.
- 7912270063 Forwards list of specific items requiring updating in emergency plans. Emergency plans were evaluated using code requirements Reg Ouide 1. 101 & Emergency Planning Review Ouidelines Number in Revision 1.
  IPPOLITO.T.A. Operating Reactors Branch 3. 79/11/30. 7pp.
- 7912210127 Responds to 791115 conversation re emergency telephones.
  Requests info indicating backup power supply to emergency
  telephones.
  KEPPLER, J. C. Region 3. Chicago, Office of the Director. 79/12/05.
  1p.
  - udicatory correspondence
    - licensee response to ASLB 790914 memorandum & order tin 79-17. Revision 1. T Tramm. TW Lukens, B raffidavits address technical safety fuel storage. Certificate of Svc encl. Lincoln & Beals. 79/11/16. 4pp.

- --7912110513 Affidavit identifying type of stainless steel in liner, spent fuel assemblies & spent fuel pool cooling sys. Clarifies exposure condition of stainless steel & consequences of stainless steel sys failure. TRAMM.T.R. Commonwealth Edison Co. 79/11/16. 10pp.
- --79121105;B Affidavit reporting spent fuel pool cooling sys insp results. Identifies examination of spent fuel rack undertaken in response to IE Bulletin 79-17. LUKENS,T.W. Commonwealth Edison Co. 79/11/16. 5pp.
- --7912110525 Affidavit reporting spent fuel pool cooling sys insp results Identifies examination of spont fuel rack undertaken in response to IE Bulletin 79-17. BHANNON R. Commonwealth Edison Co. 79/11/16. 4pp.
- --7912110532 Affidavit giving essential performance requirements of sensitiration tests results performed on TMI specimens.Prof qualifications & supporting documentation encl. CLARKE,W.1. General Electric Co. 79/11/16. 64pp.
- --7912110542 Affidavit stating reasons for believing that intergranular stress corresion cracking does not present safety problem. Recommends weekly monitoring of pool water chemistry. Prof qualifications & supporting documentation encl.
  STAEHLE, R. Minnesota, Univ. of, Minneapolis, 79/11/16. 30pp.
- 7912190015 Forwards documents relevant to intergranular stress corrosion cracking issue. W/o encl. STEPTOE, P. P. Isham, Lincoln & Beale. 79/11/19. 2pp.
- 7912110038 Confirms receipt of encl 790329 petition to suspend OLs for all PMRs.Forwards FR notice indicating that petition will be treated in accordance w/10CFR2. 206.

  DENTON: H. R. Office of Nuclear Reactor Regulation. 79/11/23. 1p.
- --7912110126 Notice of request for action pursuant to 10CFR2.206 re Environ Coalition on Nuclear Power 790329 petition requesting suspension of all DLs for PWRs. MULLER.D.R. Office of Nuclear Reactor Regulation. 79/11/23.
- 7912040455 Recommends closing plants due to proximity to population centers & lack of evacuation plans.

  \* Citizens Against Nuclear Power. 79/11/28. 5pp.
- 7912100476 Motion for extension until 791214 for NRC to respond to ABLB order requesting info re intergranular stress corrosion cracking Applicant submittal was not received until 791128. Certificate of Box encl.

  GODDARD, R. J. Hearing Branch 2. 79/11/29. 3pp.
- 791214004B Memorandum & order granting extension until 791214 for NRC to respond to ASLB 790914 order re possible intergranular stress corrosion cracking in proposed fuel storage racks to be used in spent fuel pool.

  WDLF, S. F. Atomic Safety and Licensing Board Panel. 79/12/03. ip.
- 7912180230 Advises of errors in licensee 791116 submittal on intergranular stress corrosion cracking. Forwards missing pages. STEPTOE P. P. Isham. Lincoln & Beale. 79/12/03. 3pp.
- 7912180178 Response to ASLB 790914 order that affidavits be provided stating extent to which Stainless Steel 304 would be used in spent fuel storage pool & effects from immersion in pool water. Forwards JR Neeks & A Tabo
- --79121801B1 Affidavit of JR Weeks on 791206 re extent of presence of Stainless Steel 304 in spent feel storage pool & effects of immersion in pool water. Statement of prof qualifications encl.
  WEEKS.J.R. Brookhaven National Laboratory. 79/12/06. 4pp.
- ---7912180186 Affidavit of A Taboada in 791207 re extent of presence of Stainless Steel 304 in spent fuel storage pool & effects of immersion in pool water. Statement of prof qualifications & Certificate of Svc encl.

  TABOADA, A. Office of Standards Development. 79/12/07. App.
- 7912210420 Response to intervenor State of IL 791210 request for extension until 791228 to respond to ASLB order requiring info re intergranular stress corrosion cracking. No objection to estention W/Gertificate of Svc. OODDARD R. J. Hearing Branch 2. 79/12/12. 2pp.

### H. General correspondence

- 7912280605 Discusses 791204 title change of manager of nuclear operations to vice president Organization structure not altered No revision will be made to GA program topical rept CE-1-4 until organization structure is delineated.

  JANECEK, R. F. Commonwealth Edison Co. 79/12/19. 1p.
- P. Operating license stage documents & correspondence
- 7911090248 "Summary of Operating Experience W/Recirculating Steam Openators." EISENHUT.D.O. Division of Operating Reactors. NUREQ-0523. 79/01/31. 89pp.
- 7912110011 Forwards NRC position on status & applicability to pending OL applications of results of TMI followup actions. Outlines addl short-term actions to be taken.
  VASGALLO,D.B. Division of Project Management. 79/09/27. 41pp.
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATWB issue for PWRs & BWRs.
  Buccess of program depends on industry response. Bupports formation of owners groups to provide necessary info.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.
- 7912050162 Discusses NRC review of LERs & Tech Spec requirements re control RPI sys at Westinghouse PWRs. Requests Tech Specs rayiew to ensure requirement for rod maint to within +/- 12 steps indicated & RPI sys verified accurate within 12 steps. SCHWENGER.A. Operating Reactors Branch 1. 79/10/29. 7pp.
- 7911270467 Forwards "Discussions of TMI Lessons Learned Ehort-Term Requirements" providing addl clarifications of NRC requirements for pending OL applicants. VABSALLO, D. B. Division of Project Management. 79/11/09. 2pp.
- 7912100189 Discusses NRC 791101 meeting w/representatives of NSSS vandors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses oncl. EISENHUT.D.O. Division of Operating Reactors. 79/11/09. 45pp.
- --7912100330 Responds to NRC 791101 request re DRNL cladding swelling & rupture data Review of analytical models & tests indicates compliance w/iOCFRSO App K.All GE specs for calculated peak cladding temp remain unchanged.

  BUCHHOLZ.R.H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vandor evaluation models & that analyses demonstrate all criteria of 10CFR50. 46 satisfied.

  BMSLEY.O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/11/02. Spp.
- --7912100456 Forwards addl info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model.

  No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results.

  OHBLEY, O. F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).

  79/11/04. 22pp.
- 79120B0322 Discusses 791113 & 14 site visit me solid radwaste processing & temporary storage Facilities have instituted improved waste minimization programs.

  ORANT, P. Environmental Evaluation Branch. 79/11/23, 2pp.
- 7912060649 Notification of 791205 maeting w/utils in Bethesda.MD to discuss alternatives to reduce probability & consequences of savere reactor accident.

  ZECH.G. Division of Operating Reactors. 79/11/29, 4pp.
- 7912040297 Forwards supplementary response to be incorporated into 79101B ltr re lessons learned commitments to meet near-term requirements.
  REED.C. Commonwealth Edison Co. 79/11/30. 7pp.
- 7912120411 Forwards supplementary response re commitment to meet short-term requirements of Lessons Learned Task Force. REED.C. Commonwealth Edison Co. 79/11/30. 7pp.

- 7912120425 Forwards supplemental response to 791018 ltr re commitments to Lessons Learned Task Force recommendations. PEOPLES, D. L. Commonwealth Edison Co. 79/12/03. 2pp.
- 7912110309 Responds to NRC 791029 itr re control RPI sys at Westinghouse PWRs. Resolution of RPI sys is +/-5% of span. When indicated misalignment of 12 steps exists misalignment could be 24 steps & control RPI should be monitored +/-12%. PEOPLES, D. L. Commonwealth Edison Co. 79/12/04. 2pp.
- 7912110318 Confirms 791119 notification of implemented mod. Automatic rod control operation prohibited above 90% of rated power w/Control Bank D below 216 steps withdrawn. PEOPLEG.D.L. Commonwealth Edison Co. 79/12/04. ip.
- 791R200672 Requests payment of Class III fees for review of 790816 nuclear security personnel training & qualification plans.
  DIGOS,R.M. License Fee Management Branch. 79/12/07. 1p.
- 7912200041 Forwards request for add1 info re auxiliary feedwater sys automatic initiations & flow indications to steam generators.
  SCHMENGER.A. Operating Reactors Branch 1 (Pre 791030). 79/12/12.
  2pp.
- 7912210349 Forwards cover sheet for CE-i-A,Revision 10, inadvertently omitted from 791116 transmittal.
  NAUGHTON,W.F. Commonwealth Edison Co. 79/12/13. 2pp.
- 7912180331 Forwards info documenting evaluation of purge & vent valve operability verification. Util committed to purge & vent sys in conformance w/NRC interim position. Complete confirmatory analyses not available for 30-40 wk.
  PEOPLES.D.L. Commonwealth Edison Co. 79/12/14. App.
- 7912190542 Forwards "Adequacy of Station Electric Distribution Sys Voltages," addressing 480-volt undervoltage conditions. JANECEK,R.F. Commonwealth Edison Co. 79/12/14. ip.
- --7912190845 "Adequacy of Station Electric Distribution Sys Voltages." \* Commonwealth Edison Co. 79/12/14. Bpp.
- 7912270469 Forwards response to NRC request for add1 info on Lessons Learned Task Force Recommendations 2, 1, 7a & 2, 1,7b. PEOPLES, D. L. Commonwealth Edison Co. 79/12/14. Bpp.
- 7912270470 Advises that qualification program for remaining purge & vent containment valves is in progress Dresden & Gwad-Cities butterfly valves will close, regardless of degree of opening. Response to NRC interim position encl. PEOPLES, D. L. Commonwealth Edison Co. 79/12/14. 6pp.
- 7912270597 Advises of compliance w/Category A TMI Lessons Learned Task Force items identified in NRC 790913 & 1030 ltrs. Compliance will be achieved by 800101 or prior to return to power for units in outages on 800101. PEOPLES, D. L. Commonwealth Edison Co. 79/12/17. ip.
- 7912270464 Forwards supplementary response re TMI Lessons Learned Task Force recommendations, in response to NRC request for info. Response should be incorporated into 791017 ltr reauxiliary feedwater sys requirements. PEOPLEB, D. L. Commonwealth Edison Co. 79/12/18. 9pp.
- 7912310348 Forwards revised pages to CE-1-A, "Comm Ed GA Program for Nuclear Generating Stations," Revision 11.

  JANECEK, R. F. Commonwealth Edison Co. 79/12/20. ip.
- --7912310359 Revised pages to CE-1-A. "Comm Ed GA Program for Nuclear Generating Stations:" Revision il.
  \* Commonwealth Edison Co. CE-1-A. 79/11/21. 16pp.
- 7912270267 Forwards 791220 conference paper re Indian Point/Zion near site studies. Requests paper be made part of public record. PEOPLES.D.L. Commonwealth Edison Co. 79/12/21. 1p.
- --7912270275 "Indian Point/Zion Near Sits Studies," presentation to NRC.

  \* Communumenth Edison Co. 79/12/20. 31pp.
- G. Inspection reports, IE Bulletins & correspondence
- 79120B0050 Forwards IE Insp Repts 50-295/79-20 & 50-304/79-19 on 790901-30. No noncompliance noted, HEISHMAN.R.F. Region 3 Chicago, Reactor Operations Nuclear Support Branch. 79/10/17. 2pp.

# DOCKETED ITEMS

- 912030066 IE Insp Repts 50-295/79-20 & 50-304/79-19 on 790901-30. No noncompliance noted Major areas inspected reactor operation, maint, IE bullotin followup, LERs, physical security, & changing pump shaft matl.
  NCHLER, U.E.: SPESSARD, R.L. Region 3, Chicago, Office of the Director. 79/10/17, 9pp.
- 2180224 Forwards IE Insp Repts 50-295/79-23 & 50-304/79-21 on 790702 0925 No moncompliance noted. IORELLI.O. Region 3. Chicago, Reactor Construction & Engineering Upport Branch. 79/11/07. 2pp.
- 9121B0234 IE Imap Repts 50-295/79-23 & 50-304/79-21 on 790702 & 0925.
  No noncompliance noted Major areas inspected:review procedures, mfg activities at Lockenby Co & review audits & surveillances performed by Comm ED.
  HAYES, D. W. Region 3, Chicago, Reactor Construction & Englineering Support Branch, NAIBU.K.R. Region 3, Chicago, Office of the Director. 79/11/05. 5pp.
- 12050106 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No reaponse required. KEPPLER.J.G. Region J. Chicago. Office of the Director. 79/11/16.
- 12100213 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. KEPPLER.J.G. Region 3, Chicago, Office of the Director. 79/11/16.
- 12110557 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Eys Instrumentation During Operation." No specific action or response required, KEPPLER, J. G. Region 3. Chicago. Office of the Director. 79/11/16.
- 12050344 Forwards IE Bulletin 79-26. "Boron Loss From BWR Control Blades." No response required. KEPPLER.J.O. Region 3. Chicago. Office of the Director. 79/11/20.
- 12100417 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No written response required. KEPPLER.J. Q. Rugion G. Chicago, Office of the Director. 79/11/26.
- 212140187 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No written response required. KEPPLER, J. G. Region 3. Chicago, Office of the Director. 79/11/24.
- 212:10395 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofts copies of escalated enforcement correspondence sent by NRC to licensees.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/28.
- P12190197 Forwards IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Written response required. KEPPLER.J.G. Region 3. Chicago. Office of the Director. 79/11/30.
- 912140056 Forwards 1E Info Notice 79-30, "Reporting of Defects & Noncompliances,10CFR21." No action or response required. KEPPLER,J.C. Region 3, Chicago, Office of the Director. 79/12/06.
- 912200086 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action reguired. KEPPLER.J.O. Region 3, Chicago, Office of the Director. 79/12/1
- Region 3, Chicago, Office of the Director. 79/12/10
- 912200443 Notification of 791213 meeting w/stil to discuss IE Bulletin 79-02 anchor bolt & base plate analysis. JORDAN.E.L. Division of Reactor Operations Inspections. 79/12/11.
- t. Periodic operating reports & related correspondence
- 912110219 Forwards monthly operating repts for Nov 1979. WANDIKE, N. E. Commonwealth Edison Co. 79/12/07. 1p.
- ---7912110223 Henthly operating repts for Nov 1979. COCK, J. M. Commonwealth Edison Co. 79/12/07. iipp.

- S. Reportable occurrences. LERs & related correspondence
- 7912120068 PNO-III-79-025; on 791025; essential svcs motor generator set tripped, resulting in tripping of Unit 3 reactor. Caused by slamming of essential svcs electrical panel door.
  CREED.J. Region 3, Chicago, Dêfice of the Director. 79/10/26.
- 7912170166 PNO-III-79-25A: threatening telephone calls came from court-committed patient All affected licensess notified. DELANGER, J. Region G. Chicago, Office of the Director. 79/10/29.
- 7912050550 PND-III-79-29A: on 791101.volumetric examinations revealed cracking in steam generator-to-feedwater piping. Defective wolds & piping will be replaced.
  KGHLER,J.L., SPEESBARD, R.L., HEIBHMAN,R.F. Region 3, Chicago, Office of the Director. 79/11/02. ip.
- 7912180366 PND-III-79-052: on 791129, during routine surveillance, gland seals on three hydraulic anothers observed w/excessive leaking. Gauges observed on piston rods where snubbers pass through housing at gland seal & on housing. DANIELSON, D. H., FIDRELLI, G. Region 3, Chicago, Office of the Director. 79/11/29. 1p.
- DOCKET 50-305 KEWAUNEE NUCLEAR POWER PLANT
- F. Security, medical, emergency & fire protection plans
- 7912130415 Forwards request for add1 info re contingency plan. Request withheld (ref 10CFR2. 790).
  SCHWENCER.A. Operating Reactors Branch i. 79/11/13. 2pp.
- 7912200114 Forwards draft suppl to fire protection safety evaluation. LAINAS.O. Plant Bystems Branch. 79/11/20. 2pp.
- --7912200118 Draft suppl to fire protection safety evaluation. \* Office of Nuclear Reactor Regulation. 79/11/20. 10pp.
- 7912200022 Discusses NRC 791109 meeting re emergency preparadness tram review objectives. Provides guidance for improving licenses emergency preparadness & assuring capability of offsite agencies to take appropriate emergency actions. ORIMES, B.K. Emergency Preparadness Task Force. 79/11/R3. 30pp.
- 7912210129 Responds to 791115 conversation re emergency telephones.
  Requests info indicating backup power supply to emergency
  telephones.
  KEPPLER, J. Q. Region 3. Chicago. Office of the Director. 79/12 Region 3. Chicago, Office of the Director. 79/12/05.
- O. Adjudicatory correspondence
- 7912110038 Confirms receipt of encl 790329 petition to suspend OLs for all PURs.Forwards FR notice indicating that petition will be treated in accordance w/10GFR2.206.

  DENTON-H.R. Office of Nuclear Reactor Regulation. 79/11/23. ip.
- --7912110126 Notice of request for action pursuant to 10CFR2.206 re Environ Coalition on Nuclear Power 790329 petition requesting suspension of all DLs for PWRs. HULLER, D. R. Office of Nuclear Reactor Regulation. 79/11/23. 38pp.
- P. Operating license stage documents & correspondence
- 7911090248 "Summary of Operating Experience W/Recirculating Steam Generators. "
  EISENHUT, D. O. Division of Operating Reactors. NUREG-0523.
  79/01/31. 89pp.
- 7912050194 Discusses NRC review of LERs & Tech Spec requirements recontrol RPI sys at Mastinghouse PMRs. Requests Tech Specs review to ensure requirement for rod maint to within +/- 12 steps indicated & RPI sys verified accurate within 12 steps. SCHMENCER. A. Operating Reactors Branch 1. 79/10/29. 7pp.
- 7712100189 Discusses NRC 771101 meeting w/representatives of NSS8 vendors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EISENHUT.D. G. Division of Operating Reactors. 79/11/09. 63pp.

- --7912100255 Responds to NRC 791101 request re noncompliance of Westinghouse ECCB evaluation model under requirements of 10CFR50 App K. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants.
  ANDERSON.T.M. Westinghouse Electric Corp. 79/11/02. 4pp.
- --7912100330 Responds to NRC 791101 request re ORNL cladding swelling & rupture data. Review of analytical models & tests indicates compilance w/iOCFR50 App K. All GE specs for calculated peak cladding temp remain unchanged.

  BUCHHOLZ, R. H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50.46 satisfied.

  OHBLEY.O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/02. 5pp.
- ---7912100456 Forwards add1 info re evaluation of impact of NRC proposed rupture/blockage model used in vandor evaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. CHBLEY, O. F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/04, 22pp.
- 7912040102 Summary of 791115 telcon w/util re lessons learned implementation.
  OLSHAN, L. N. Operating Reactors Branch 1. 79/11/23. 7pp.
- 7912060029 Summary of 791115 telcon w/util re util 791019 response to 790913 ltr re lessons learned implementation.

  OLSHAN, L. N. Operating Reactors Branch 1, 79/11/23. 6pp.
- 7912210439 Notifies that radioactive math shipping activities to be performed per util GA program.780120 Revision 2,approved 790723.
  RICHMOND, J., LUOMA, C.R. Wisconsin Public Service Corp. 79/11/27.
- 7912120362 Responds to NRC 791029 ltr re Tech Specs on rod misslignment. Current util Tech Specs are consistent w/safety analysis & mode of operation based on approved physics methods.

  MATHEWS, E. R. Wisconsin Public Service Corp. 79/12/05. 2pp.
- 7912210121 Requests firm date for delivery of re-analysis at ECCS cooling performance using correct Hestinghouse evaluation model.

  8CHHENCER, A. Operating Reactors Branch 1, 79/12/07. 2pp.
- 7912180481 Submits interim position for containment purge during operation, in response to NRC 791023 ltr. Also submits addition for comparing Branch Technical Position 6-4 for Containment Bys Branch.

  MATHEWS, E. R. Wisconsin Public Service Corp. 79/12/10. 3pp.
- 7912180501 Forwards addl info re Lessons Learned Task Force Short-Term Requirements in response to 791207 telcon. No implementation schedule available due to uncertainty in delivery of equipment.

  MATHEMBIE. R. Wisconsin Public Bervice Corp. 79/12/10. 2pp.
- 7712180621 Responds to NRC 791019 ltr. Discusses overpressure protection sys & number of available electrical penetrations through containment. Mods to Class IE power sources planned for 1980 refueling outage.

  MATHEWS, E. R. Wisconsin Public Service Corp. 79/12/12. 1p.
- 79:2:190420 Forwards Westinghouse reanalysis description time sequence of events & generic sensitivity study results to document ECCB reanalysis re rirc/water reaction calculation.
  Calculated peak clad temp does not exceed 2,200 F.
  MATHEWB.E.R. Wisconsin Public Service Corp. 79/12/14. 36pp.
- 7912210325 Provides requested info re auxiliary feedwater sys. Existing dasign meets short-term criteria of NUREC-0578 & H Denton 791030 clarification ltr.
  MATHEMS.E.R. Wisconsin Public Service Corp. 79/12/14. 2pp.
- G. Inspection reports, IE Bulletins & correspondence
- 7912050028 Forwards IE Insp Rept 50-305/79-16 on 790925-28 No noncompliance noted. HEISHMAN.R.F. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 79/10/18. 2pp.

- --7912050035 IE Insp Rept 50-305/79-16 on 790925-28.Ng noncompliance noted Major areas inspected:core power distribution limits, in-core/ex-rore calibr & isothermal temp coefficient. CHOM.E.T. Region 3, Chicago. Office of the Director. STREETER.J.F. Region 3. Ghicago. Reactor Operations Nuclear Support Branch. 79/10/16. App.
- 7912050400 Forwards IE Insp Rept \$0-305/79-15 on 790910-14.No noncompliance noted. HEIBHMAN,R.F. Region 3. Chicage, Reactor Operations Nuclear Bupport Branch. 79/10/25. 2pp.
- --7912050412 IE Insp Rupt 50-305/77-15 on 790910-14. No noncompliance noted. Major areas inspected: safety-related components & equipment.implementation of ABME Code Section ii pump & valve test program & followup on IE Bulletin 79-06C.
  MCGREORR.L.G. Region 3. Chicago, Office of the Director.
  STREETER.J.E. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 79/10/24. Bp.
- 7912040211 Responds to IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas." Inadequate alarm sys identified in four areas. Bys will be improved by adjustment or installation of speakers. MATHEWS.E.R. Wisconsin Public Service Corp. 79/11/08. 1p.
- 7912050158 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required. KEPPLER, J. Q. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912100252 Forwards IE Info Notice 79-28, "Dverloading of Structural Elements Due to Pipe Support Loads." No response required, KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912120001 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coulant Sys Instrumentation During Operation." No specific action or response required.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912050416 Forwards IE Bulletin 79-26, "Boron Loss From BWR Control Blades." No response required.
  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/20.
- 7912120079 Forwards IE Insp Rept 50-305/79-18 on 791015-19 % notice of violation, Notice of violation withheld (ref 10CFR2, 790). HIND, J. A. Region 3, Chicago, Bafeguards Branch, 79/11/21. 2pp.
- --7912120085 IE Insp Rept 50-305/79-18 on 791015-19. Noncompliance noted: some guards not qualified in accordance w/commitments & some security-related equipment not tested in accordance w/commitments. Details withheld (ref lOCFR2.790).
  CREED.J.R., BCHWAN.C.A. Region 3, Chicago, Diffice of the Director. HIND.J.A. Region 3, Chicago, Safeguards Branch. 79/11/20. 2pp.
- 7912170210 Updates 791018 response to IE Bulletin 79-21. Brift on steam generator level transmitters may be 3.1% Potential level uncertainty is 11.8%. To assure compliance w/Tech Specs, setpoint will be raised to 17%.
  MATHEMB.E.R. Wisconsin Public Bervice Corp. 79/11/21. 2pp.
- 79:210044B Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Byray Pipe Broak Detection Equipment on BWRs." No written response required.

  KEPPLER.J. G. Region 3, Chicago, Office of the Director. 79/11/26.

  1p.
- 7912140249 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No written response required.

  KEPPLER. J. G. Region 3, Chicago, Office of the Director. 79/11/26.
- 7912110490 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sent by NRC to licensees.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/28.
- 791219023B Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Written response required.

  KEPPLER.J.O. Region 3. Chicago, Office of the Director. 79/11/30.

  1p.

- 7912200089 Responds to IE Bulletin 79-17.Revision 1 re stagnant borated water sys.Welds already inspected 4 will be revioued to ensure 10% of accessible welds inspected.Further insp if necessary to be completed within 12 months.

  MATHEWS.E.R. Wisconsin Public Service Corp. 79/11/30. 2pp.
- 7912140109 Forwards IE Info Notice 79-30. "Reporting of Defects & Noncompliances, 10CFR21." No action or response required. KEPPLER. J. G. Region 3. Chicago. Office of the Director. 79/12/06. 1p.
- 79:2200:35 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/12/10.
- R. Periodic operating reports & related correspondence
- 7912140357 Forwards monthly operating rept for Nov 1979.
  MATHENS, E. R. Washington Public Power Supply System. 79/12/10. 1p.
- --7912140362 Monthly operating rept for Nov 1979. WALLACE, J. J. Washington Public Power Supply System. 79/12/10.
- DDCKET 50-306 PRAIRIE ISLAND NUCLEAR STATION, UNIT 2

  F. Security, medical, emergency & fire protection plans
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives.Provides guidance for improving licenses emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.

  ORIMES.B.K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- 7912120244 Forwards evaluation of electrical & mechanical penetration seals & fire detectors required by 790904 fire protection safety evaluation rept.
  MAYER.L. D. Northern States Power Co. 79/11/30. 94pp.
- G. Adjudicatory correspondence
- 7912110038 Confirms receipt of encl 770329 petition to suspend OLs for all PWRs. Forwards FR notice indicating that petition will be treated in accordance w/10CFR2.204.
  DENTON, M. R. Office of Nuclear Reactor Regulation. 79/11/23. 1p.
- --7912110126 Notice of request for action pursuant to 10CFR2.206 re Environ Cealition on Nuclear Power 790329 petition requesting suspension of all CLs for PWRs. MULLER.D.R. Office of Nuclear Reactor Regulation. 79/11/23. 38pp.
- P. Operating license stage documents & correspondence
- 7911090248 "Summary of Operating Experience W/Recirculating Steam Openators." E18ENHUT, D.O. Division of Operating Reactors. NUREG-0523. 79/01/31. 87pp.
- 7912040164 Discusses NRC concerns re containment purging & venting during normal operations. Includes licensee override of safety actuation isolation signals to containment isolation valves & valve ability to shut w/o deprading containment.

  SCHMENCER.A. Operating Reactors Branch 1. 79/10/29. 5pp.
- 7912050176 Discusses NRC review of LERs & Tech Spec requirements re control RPI sys at Westinghouse PWRs. Requests Tech Specs review to ensure requirement for rod maint to within +/- i2 steps indicated & RPI sys verified accurate within 12 steps. SCHMENCER.A. Operating Reactors Branch 1. 79/10/29. 7pp.
- 79121001B9 Discusses NRC 791101 meeting w/representatives of NSSS vendors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EISENHUT.D.Q. Division of Operating Reactors. 79/11/09. 45pp.
- --7912100285 Responds to NRC 791101 request re noncompliance of Westinghouse ECC9 evaluation model under requirements of 10CFRBO App W. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants. ANDERSON.T.M. Westinghouse Electric Corp. 79/11/02. 4pp.

- --7912100330 Responds to NRC 791101 request re DRNL cladding swelling & rupture data. Review of analytical models & tests indicates compliance w/10CFR50 App K. All GE specs for calculated peak cladding temp remain unchanged.

  BUCHHOLZ, R. H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50.46 satisfied.

  CHELEV.G.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/02. 5pp.
- --7912100456 Forwards addl info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. OMBLEY.G.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/04. 22pp.
- 7912120103 Notification of 791126 meeting w/util in Bethesda.MD to discuss reactor vessel nozzle fabrication. GRDTENHUIS.M. Operating Reactors Branch 1. 79/11/19. 2pp.
- 7912040201 Confirms implementation of interim procedural solution adopted at 791119 meeting w/NRC. Westinghouse & util repossible rod drop accident analysis for certain Westinghouse designed plants.

  MAYER.L.O. Northern States Power Co. 79/11/27. ip.
- 7912110307 Responds to NRC 791027 1tr re control rod misalignment specs.License amend request re spec changes will be submitted by 800115.
  MAYER, L. D. Northern States Power Co. 79/12/05. 1p.
- 7912210008 Summary of 791126 meeting w/Westinghouse & util re base metal cracking in reactor vessel noizles under stainless steel cladding.
  ORDIENRUIS.M. Operating Reactors Branch 1, 79/12/12. App.
- --7912210013 Discusses pipe leak at TVO 1.in Finland, due to faulty fabrication process of components mfg in France & significance to US plants. DENTON.H.R. Office of Nuclear Reactor Regulation. 79/10/24. 14pp.
- 7912200432 Notifies that util will be in compliance by 800131 w/Lessons Learned Task Force recommendations re relief & safety valves direct position indication & inadequate core cooling detection instrumentation.
  MAYER.L.D. Northern States Power Co. 79/12/14. 2pp.
- 7912200385 Notifies NRC that util cannot meet 781025 schedule for resolving issue of asymmetric LOCA loads, due to delays in mat1 procurement. Pipe restraints will be installed during refueling outage.

  MAYER.L.O. Northern States Power Co. 79/12/17. 1p.
- Q. Inspection reports. IE Bulletins & correspondence
- 7912050401 Forwards IE Insp Repts 50-282/79-23 & 50-306/79-19 on 790917-30. No noncompliance noted.
  HEISHMAN,R.F. Region 3, Chicago, Reactor Operations Nuclear Bugport Branch. 79/10/26. 2pp.
- --7912050406 IE Insp Repts S0-282/79-23 & 50-306/79-19 on 790917-30. No noncompliance noted Major areas inspected maint, security, review, audit & radiation protection.
  FEIERABEND.C. D., MARNICK, R. F. Region 3, Chicago, Office of the Director. 79/10/22. 3pp.
- 7712030144 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912100239 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912110585 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required.

  KEPPLER. J. O. Region 3, Chicago, Office of the Director. 79/11/16.

  19.

- 7912210066 Forwards IE Insp Repts 50-282/79-27 & 50-306/79-21 on 791001-31. No noncompliance noted. HEISHMAN.R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/11/16. 2pp.
- --7912210074 IE Insp Repts 50-282/79-27 & 50-306/79-21 on 791001-31.No noncompliance noted Major areas inspected; plant operations, maints security & observations of plant staff response to steam generator tube rupture. FEIERABEND.C. D., WARNICK.R.F. Region 3, Chicago, Defice of the Director. 79/11/13. 9pp.
- 7912050404 Forwards IE Bulletin 79-26, "Boron Loss From BWR Control Blades." No response required.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/20.

  1p.
- 7912100440 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on SMRs." No written response required.

  KEPPLER.J.O. Region 3, Chicago. Office of the Director. 79/11/26,
- 7912140216 Forwards IE Circuler 79-23, "Motor Starters & Contactors Failed to Operats." No written response required.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/26.
- 7912110433 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofts copies of escalated enforcement correspondence sent by NRC to licensees.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/28.
- 7912190801 Responds to IE Bulletin 79-17. Revision 1. Insp per Item 2 (b) to begin 791203 for Unit 2 & end in two wks. Unit 1 insp schedulad for Aug 1980.

  WACHTER.L. J. Northern States Power Co. 79/11/28. 1p.
- 7912050667 Ack receipt of 791031 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-282/79-21 & 50-304/79-18.
  HEISHMAN,R.F. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 79/11/30. ip.
- ---7912050671 Responds to NRC 791009 ltr re violations noted in IE Insp. Repts 50-282/79-21 & 50-306/79-18. Corrective actions: Design Change 771397 forms w/required initials completed. HACHTER, L. J. Northern States Power Co. 79/10/31. 3pp.
- 7912190231 Forwards IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Written response required.

  KEPPLER, J. Q. Region 3, Chicago, Office of the Director. 79/11/30.
- 7912140093 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action or response required. KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/12/06.
- 7912280067 Responds to IE Bulletin 79-02. Revision 2, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts." All Seismic Category I restraints that use concrete expansion anchors were field verified.

  WACHTER, L. J. Northern States Power Co. 79/12/07. 2pp.
- 7912200134 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required.

  KEPPLER, J. 9. Region 3, Chicago, Office of the Director. 79/12/10.
- 7912280041 Responds to IE Bulletins 78-12, 78-12A & 78-12B, "Short Period Scrams at BWR Pacilities." No deviations found in welding matl used in vessels.

  WACHTER, L. J. Northern States Power Co. 79/12/11. 2pp.
- R. Periodic operating reports & related correspondence
- 7912180620 Forwards monthly operating rapt for Nov 1979 & corrections to monthly operating rapts for Aug. Gapt & Oct 1979.
  MAYER, L. O. Northern States Power Co. 79/12/12. ip.
- --7912180628 Monthly operating rept for Nov 1979. HUNBTAD, A.A. Northern States Power Co. 79/12/Q1. Bpp.

- S. Reportable occurrences. LERs & related correspondence
- 7912070135 PNO-III-79-024: on 791026, Region 3 natified of chlorine treatment of cooling tower water containing amouba encephalitis. Licensee will monitor discharges, & submit environ event rept to NRC.

  OESTMANN, M. J., ESSIG. T. H. Region 3, Chicago, Office of the Director. 79/10/25. 2pp.
- 7912060593 PNO-III-79-035: on 791007, neutralizing tank batch released ph greater than Tech Spec limit. Caused by improper operation of ph monitor on tank effluent pipe. Namo issued requiring reliable operation of monitor. DESITHANN. M. J. Region 3, Chicago, Office of the Director. 79/11/05. 2pp.
- 7912030197 Forwards LER 79-029/03L-0. MAYER, L. D. Northern States Power Co. 79/11/30. ip.
- --7912030202 LER 79-029/03L-0: on 791102, during surveillance test, turbin driven auxiliary feedwater pump did not start. Cause Unknown. Valves being checked for proper position every 4-h & design Change initiated.
  HUNSTAD.A.A. Northern States Power Co. 79/11/30. 1p.
- 7912070332 Environ Event Rept 79-ii for 17 days in Nov. Blowdown flow in excess of Tech Baecs required to complete special chlorination treatment authorized by 791102 ETB change. WARD, E. C. Northern Btates Power Co. 79/12/03. 1p.
- 79122B056B Forwards Westinghouse evaluation of 791002 tube rupture event. Concurs w/util recommendations in LER 79-027/01T-0 reoperation of turbine driven auxiliary feed pump & steam supply valve from faulted steam generator.

  ANDERSON, T. M. Westinghouse Electric Corp. 79/12/19. 17pp.
- 7912310475 Forwards LER 79-031/03L-0.
  MAYER, L. O. Northern States Power Co. 79/12/26. 1p.
- --7912310478 LER 79-031/03L-0: on 791126, during periodic surveillance program review, discovered that 8P1022 boric acid tank level test not performed within tolerance band. Caused by personnel oversight. Instrumentation & control schedule to be used. HUNBTAD, A. A. Northern States Power Co. 79/12/26. 1p.
- DOCKET 50-309 MAINE YANKEE ATOMIC POWER PLANT
  F. Becurity, medical, amergency & fire protection plans
- 7912200022 Discusses NRC 791109 menting re emergency preparedness team review objectives. Provides guidance for improving licensee emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.

  ORIMEB. B. K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- O. Adjudicatory correspondence
- 7912110038 Confirms receipt of encl 790329 petition to suspend OLs for all PMRs. Forwards FR notice indicating that petition will be treated in accordance w/100FR2, 206. DENTON.H.R. Office of Nuclear Reactor Regulation. 79/11/23. 1p.
- --7912110126 Notice of request for action pursuant to 10CFR2.206 re Environ Coalition on Nuclear Power 790327 petition requesting suspension of all OLs for PWRs. MULLER, D. R. Office of Nuclear Reactor Regulation. 79/11/23. 3Bpp.
- 791211040B Petition to intervene Urges Commission to schedule conferences, discovery & hearings. Certificate of Svc & supporting documentation encl.
  TUPPER, B. R., MILLTER, D. S. Sensible Maine Power. 79/11/29. 7pp.
- ---7912110418 Attachment 3 in support of petition to intervene. Identifies aspects of proceeding for which intervention sought Contends that applicant failed to implement protective measures is human & technical failures.

  MILLER, D. B. Sensible Maine Power. 79/11/29. 12gp.
- --7912110425 Errata to 791123 patition to intervene Corrects tupographical errors.
  MILLER D. S. Bensible Maine Power. 79/11/29. 2pp.
- 7912190005 Forwards State of ME notice of intent to participate.
  PATERBON, J. M. Maine, State of. 79/11/28. 1p.

- --7912190009 Notice of intent to participate in hearings re util application to espand spent fuel storage capacity. Certificate of Svc encl. PATERSON, J. M. R. Haine, State of. 79/11/28. 2pp.
- 7912130277 Establishes ASLB to preside in proceeding.per Commission 791024 order.RM Lazo appointed chairman & CH Hand & QA Linenberger members. LAZO.R.M. Atomic Safety and Licensing Board Panel. 79/12/03. 2pp.
- 7912:70053 Answer in support of Sansible ME Power petition to intervene. Requests appointment of ASLB to preside in proceeding. Urges holding of prehearing conference. Certificate of Svc encl.
  DIGNAN.T.O., QADJR.K. Maine Yanker Atomic Power Co. DIGNAN.T.O. Ropes & Gray, 79/12/07. 3pp.
- 7912170202 Notice of appearance in proceeding re spent fuel pool compaction. Certificate of Svc encl.
  OAD.R.K. Maine Yankse Atomic Power Co. GAD.R.K. Ropes & Gray. 79/12/07. 2pp.
- 7912180028 Notice of appearance Certificate of Svc encl.
  DIGNAN.T.O. Maine Yankee Atomic Power Co. DIGNAN.T.O. Ropes & Gray. 79/12/07. 2pp.
- 7912260006 Supports request by State of ME to participate as interested state if hearing held to consider licensee request to amend license to for expansion of spent fuel pool capacity. Cartificate of Svc enci.

  MCGURREN,H. J. Hearing Branch 1. 79/12/11. 2pp.
- 7912260292 Supports Sensible ME Power timely patition to intervene. Interest requirements satisfied Cartificate of Svc encl. MCGURREN, H. J. Hearing Branch 1. 79/12/13, 6pp.
- H. Caneral correspondence
- 7912200655 Forwards confirmation of responses given in 791116 telcon re 791031 questions concerning spent fuel pool. GAMMILL.W.P. Assistant Director for Operating Reactor Projects (Pre 791030). 79/11/04. 4pp.
- P. Operating license stage documents & correspondence
- 791109024B "Summary of Operating Experience M/Recirculating Steam Generators."
  EISENHUT,D. 0. Division of Operating Reactors. NURE9-0523.
  79/01/31. 89pp.
- 790B010339 Notifies of status of rept on reactor cavity annulus seal.

  Most PHR users remove ring during normal operation. Others
  store seal ring in raised position during normal operation.

  LAINAS.O. Plant Systems Branch (Pre 791030). 79/07/05. 7pp.
- 7912100187 Discusses NRC 791101 meeting W/representatives of NSS8 vendors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EISENHUT,D. G. Division of Operating Reactors. 79/11/09. 65pp.
- --7912100255 Responds to NRC 791101 request re noncompliance of Westinghouse ECCB evaluation model under requirements of 10CFR30 App N. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants. ANDERSON, T. M. Westinghouse Electric Corp. 79/11/02. 4pp.
- --7912100330 Responds to NRC 791101 request re DRNL cladding swelling & rupture date. Review of analytical models & tests indicates compliance w/10CFR50 App K. All QE specs for calculated peak cladding temp remain unchanged.
  BUCHHOLZ.R. H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models it that analyses demonstrate all criteria of 10CFR50. 46 satisfied.

  OMSLEY.G.F. Exxon Nuclear Co.: Inc. (subs. of Exxon Corp.).

  79/11/02. Spp.
- --7912100456 Forwards addl into re evaluation of impact of NRC proposed rupturs/blockage model used in vendor evaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. OMSLEY, U.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.), 79/1/04. 22pp.
- 7912170065 Requests add1 into within 90 days re loss of offsite power. REID.R.W. Operating Reactors Branch 4. 79/11/27. 3pp.

- 7912040348 Comments on NUREG-0577, "Potential for Low Fracture Toughness & Lamellar Testing on PMR Steam Cenerator & Reactor Coolant Pump Supports." Hatl test repts for steam generator base matl encl. HOFPMAN, J. R. Yankee Atomic Electric Co. 79/11/29. 1p.
- --7912040352 Matl test rept for steam generator base matl. • Ooslin-Birmingham Mfg. Co. 70/05/01. 1p.
- 7912180233 Responds to 790915 & 1122 ltrs re modified spant fuel rod storage. Forwards request fo addl info before completing, review & evaluation.
  REID.R.W. Operating Reactors Branch 4. 79/11/30. 4pp.
- 7912200180 Discusses review of pipe cracks in chemical vol control sys. Addition of horizontal multi-stage centrifugal charging pumps will not cause pressure fluctuations. Effects from one positive displacement auxiliary charging pump possible.
  REID.R.H. Operating Reactors Branch 4. 79/12/07. 2pp.
- 7912180470 Dutlines commitments & responses to Lessons Learned Task Force short-term requirements. EDMARDS: D. M. Maine Yankee Atomic Power Co. 79/12/10. 1p.
- 7912260222 Forwards addl info re containment purge & vant eys in response to NRC 791105 request. Two oversize drawings of ventilation arrangement encl.

  HOODY, D. E. Maine Yankee Atomic Power Co. 79/12/10. 14pp.
- 7912180950 Advises that encl addl precaution should be added to C-E post-LOCA guidelines for C-E plants w/high pressure safety injection pumps using shutoff heads of 2,400 psi. Precautionary measures sncl. LIEBLER, O. E. C-E Operating Plants Genera Group. 79/12/13. 3pp.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912060003 Forwards IE Insp Rept 50-309/79-13 on 790906-08. No noncompliance noted.
  BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/09/27. 2pp.
- --7912060017 IE Insp Rept 50-309/79-13 on 790906-08. No noncompliance noted Major areas inspected; containment integrated leak rate test & inspected; containment integrated leak rate test & inspected; containment for pumps & valves. SMITH, T. H., REKITO, H. A. Region i. Philadelphia, Ceffice of the Director. CAPHION, D. L. Region i. Philadelphia, Reactor Operations Nuclear Support Branch. 79/09/26. Spp.
- 7912050390 Forwards IE Insp Rept 30-309/79-12 on 790821-23. No noncompliance noted.
  BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/10/16. 2pp.
- --7912050395 IE Insp Rept 50-309/79-12 on 790821-23. No noncompliance noted Major areas inspected; operator requalification training, general employee training & craft & technician personnel training.
  BETTEMHAUSEN.L., GAPHTON.D.L. Region 1, Philadelphia, Office of the Director. 79/10/11. 6pp.
- 7912120536 Responds to IE Bulletin 79-18. Vol of speakers will be increased where evacuation alara was not clearly audible. Procurement of addl speakers for some areas underway. OROCE, R. H. Maine Yankee Atomic Power Co. 79/10/17. 1p.
- 7912040057 Discusses IE Bulletin 79-23 re potential failure of emergency diesel generator field exciter transformer. No connection exists between primary winding of transformer & generator. Test will be completed before 800101.

  QROCE, R. H. Maine Yankee Atomic Power Co. 79/10/29, 1p.
- 7912140016 Responds to IE Bulletin 79-24. "Frozen Lines." Present sys provides adequate protection against freezing of safety-related process, instrument & sampling lines. MODDY.D.E. Haine Yankee Atomic Power Co. 79/10/31, 1p.
- 7912040019 Second supplementary response to IE Bulletin 79-14. Commits to extensive seismic analysis of pipes & supports. Checks completed on supports 2.30 inches in diameter & larger. GROCE, R. H. Maine Yankae Atomic Power Co. 79/11/07. 2pp.
- 7912200344 Forwards waste packaging Insp Rept 79-02A on 790925-26. No noncompliance noted.
  SUTHERLAND.J.T. Region 2. Atlanta, Fuel Facility & Materials
  Safety Branch. 79/11/07. 2pp.

- --7912200395 Waste packaging Insp Rept 79-02A.No noncompliance noted.

  Major areas inspected; shipping paper & DDT placarding.

  requirements; radiation levels; removable contamination, DDT & NRC package features.

  BROWN R.A. Region 2, Atlanta, Office of the Director. 79/11/06.
- 7912130086 Provides second supplementary response to IE Bulletin 79-02, "Pipe Support Base Plate Design using Concrete Expansion Anchor Bults." Random sample of 75 anchor bults tested w/o failures.
  ORDGE, R. H. Heine Yankee Atomic Power Co. 79/11/14. 3pp.
- 7912030038 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required. ORIER, B.M. Region i, Philadelphia, Office of the Director. 79/11/16. ip.
- 7912050264 Forwards IE Info Notice 79-27, "Steam Generator Tuba Ruptures at Two PMR Plants." No response required. ORIER.B.H. Region i, Philadelphia, Office of the Director. 79/11/16. ip.
- 7912100129 Forwards IE Info Notice 77-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. ORIER, B.H. Region i, Philadelphia, Office of the Director. 79/11/16. ip.
- 7912110419 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required. ORIER.B.H. Region 1, Philadelphia, Office of the Director. 79/11/19. 1p.
- 7912130073 Requests verification of status of completion of insprequired by IE Bulletin 79-14.

  ORIER, B.H. Region I. Philadelphia, Office of the Director.
  79/11/19. 2pp.
- 7912080251 Forwards IE Bulletin 79-24, "Boron Loss From BWR Control Blades." No response required. ORIER, B.H. Region 1, Philadelphia, Office of the Director. 79/11/20. ip.
- 7912130036 Requests response to IE Bulletin 79-02 containing justification & description of sampling program used, BRUNNER.E.J. Region 1: Philadelphia: Reactor Operations Nuclear Bupport Branch. 79/11/21, ip.
- 7912310472 Hodifies response to NRC B01119 Itr re IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Bys." Verification completed on B0 supports for piping 2.5 inches in disameter & larger, GROCE, R. H. Meine Yankee Atomic Power Co. 79/11/23. 2pp.
- 7912060577 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Boray Pipe Break Detection Equipment on BMRs." No response required.

  ORIER, B. H. Region i, Philadelphia, Office of the Director.
  79/11/26. ip.
- 79:21:10056 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/11/26. ip.
- 7912190036 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Written response required. GRIER, H. Region i, Philadelphia, Office of the Director. 79/11/30. 1p.
- 79:23:0224 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, iOCFR21," No action required. ORIER, B.H. Region 1. Philadelphia, Office of the Director. 79/12/06. 4pp.
- 7912190753 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps," Written response required. ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/12/07. 1p.
- 7912280205 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required, GRIER, B. H. Region 1, Philadelphia, Office of the Director, 79/12/13. ip.

- R. Periodic operating reports & related correspondence
- 7912180387 Forwards monthly operating rept for Nov 1979. MODDY, D. E. Maine Yankee Atomic Power Co. 79/12/12. ip.
- --7912180389 Monthly operating rapt for Nov 1979. SJOGREN.R.M. Maine Yankee Atomic Power Co. 79/12/12. Spp.
- B. Reportable occurrences. LERs & related correspondence
- 7912200542 PNO-I-79-007: on 791016, while performing 24-h load test of iB amergency dissel generator, fire occurred in turbocharger exhaust piping. Diesel shut down on generator trip. Cause of trip unknown.

  JOHNSON, D., KEIMIG, R., BRUNNER, E. J. Region 1, Philadelphia, Office of the Director. 79/10/16. 1p.
- 7912040389 Forwards LER 79-027/03L-0. WODD, E. C. Yankee Atomic Electric Co. 79/11/21. 1p.
- --7912040398 LER 79-027/03L-0: on 791029, leakage near safety injection tank discharge check valve 1 exceeded Tech Spec limits. Caused by 0-ring failure on bearing cap of swing check valve.0-ring replaced & bearing cap seal welded, FRIZZLE.C.D. Yankee Atomic Electric Co. 79/11/21. 2pp.
- 7912040325 Forwards LER 79-028/03L-0. WOOD, E. C. Maine Yankee Atomic Power Co. 79/11/28, 1s.
- --7912040328 LER 79-028/03L-0: on 791031; one set of relay contacts on each of three separate reactor trip matrix relays were not opening reliably. Cause not stated. Three CP Clare, mercury watted relay modules, type H02X-1011, replaced.
  FRIZZLE, C. D. Maine Yankee Atomic Power Co. 79/11/28. 2pp.
- 7912140496 Forwards LER 79-030/99X-0. WOOD, E. C. Mainw Yankwa Atomic Power Co. 79/12/07. ip.
- --7912140501 LER 79-030/99X-0: on 791105, reactor coolant dose equivalent iodine exceeded Tech Spec limit. Caused by unscheduled plant trip. Monitoring program established to follow iodine trends. FRIZZLE, C. D. Maine Yankee Atomic Power Go. 79/12/07. 4pp.
- 7912180554 Forwards LER 79-029/99X-0.
  WOOD, E. C. Maine Yankee Atomic Power Co. 79/12/07. ip.
- ---7912180557 LER 79-029/99X-0: on 791025, during routine shutdown operations for repair of leaking valve, reactor coolant dose squivalent indine exceeded Tech Specs. Caused by minor fuel cladding degradation.
  FRIZZLE, C. D. Maine Yankse Atomic Power Co. 79/12/07. Spp.
- DOCKET 50-311 BALEM NUCLEAR GENERATING STATION, UNIT 2

  A. Application/construction stage documents & correspondence
- 7912110011 Forwards NRC position on status & applicability to pending OL applications of results of TMI followup actions. Outlines addl short-term actions to be taken.

  VASSALLO, D. B. Division of Project Management, 79/09/27. 41pp.
- 7912110264 Discusses NRC plans to use generic analyses to develop marly verification program to resolve ATME issue for PMRs & BMRs.

  Buccess of program depends on industry response, Supports formation of owners groups to provide necessary info, DENTON, H. R. Défice of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912190046 Forwards add1 info required for completion of electrical override/bupass aspects of containment purge makes. LAINAS, C. Plant Systems Branch. 79/11/19. 2pp.
- 7912060609 Forwards proposed Revision 2 to Reg Quide 1.97.
  "Instrumentation for Light Water Cooled Nuclear Power Plants to Assess Plant & Environs Conditions During & Following Accident." Requests comment, VAROA, B. A. Assistant Director for Light Water Reactors. 79/11/23.3pp.
- 7912060318 Forwards request for amend to License DPR-70. Request consists of proposed change to safety Tech Space to incorporate requirements for radiological effluents. Fee & Offsite Dose Calculation Menual end. LIBRIZZI.F.P. Public Bervice Electric & Gas Co. of New Jersey. 79/11/26. 2pp.

- --7912060337 Offsite Dose Calculational Manual. \* Public Service Electric & Oas Co. of New Jersey. 79/12/31. \*Zec.
- 79121B0071 Notification of 791211 meeting w/util to discuss matters re Lessons Learned Task Force recommendations. DROMERICK.A.W. Light Water Reactors Branch G. 79/12/06. 2pp.
- 7912180530 Responds to 790731 ltr requesting submittal of proposed secondary water chemistry control program & forwards proposal.
  MTTL.R.L. Public Service Electric & Gas Co. of New Jørsey.
  79/12/06. 5pp.
- 79:2180525 Notifies that Con Ed will administer hat license certification examination to Public Evc Electric & Oas Copersonnel in Jan 1980, following completion of certification program. Results will be forwarded by and of Feb 1980. CURRY.J.J. Consolidated Edison Co. of New York. 79/12/11. ip.
- 7912310356 Notification of 800108 meeting w/utils in Bethosda, MD to discuss info request re adequacy of equipment qualification.
  UNGARO, A. R. Power Systems Branch. 79/12/11. 3pp.
- 7912190452 Notifies of 800107 meeting of Balem Technical Advisory Group to introduce individuals unfamiliar w/facility to monitoring programs & to update members w/most recent info & repts.
  ALLEN.H.L. Environmental Protection Agency. 79/12/13. 1p.
- 7912190577 Responds to NRC 791210 request for addl info re auxiliary faedwater sys at Unit 1. "Controls & Electrical Drawings for Safety-Related Equipment," SER & FSAR should be consulted. Testing procedura revisions forthcoming.
  LIBRIZZI,F. R. Public Service Electric & Gas Co. of New Jersey. 79/12/14. 2pp.
- 7912280602 Forwards request for comment by 800131 on recommendations contained in NUREG-0660, "Enhancement of Chaite Emergency Dissel Concrator Reliability."

  PARR. O. D. Light Water Reactors Granch 3. 79/12/14. 19pp.
- F. Security, medical, emergency & fire protection plans
- 7912050487 Forwards updated emergency plan. Bubmittal 1 in response to NRC 791010 ltr. LIBRIZZI.F.P. Public Service Electric & Gas Co. of New Jersey. 79/11/19. 12pp.
- --7912050488 Updated emergency plan, Submittal 1.

  \* Public Service Electric & Oas Co. of New Jersey. 79/11/19.
  112pp.
- --7912050491 "Emergency Operations Flan." \* Delaware, State of, 72/01/31, 700pp.
- 7912040471 Forwards info to upgraded emergency plans to plants under const & DL review. Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Rog Guide 1.101.

  VASSALLO, D. B. Division of Project Management. 79/11/21. App.

### G. Adjudicatory correspondence

- 7912070076 Response to Christa-Maria & JP O'Neill 791120 contentions. Christa-Maria Contentions 1 & 7-9 are inadmissible & Contentions 2-6 are subj to 791126 stipulation. JP D'Neill Contentions 1.8, 5, 2, B. 2, E. 3, 2, F. & 4 admissible. MOGRE, J. E. Hearing Branch 2. 79/11/29, 32pp.
- --7912070093 Response to ASLB Question 4.TMI occurrence was Class 9 accident.
  ShiTH, B. H. Hearing Branch 2. 79/08/24. 4pp.
- ---7912070102 Forwards response to ABLB question. TMI occurance was Class 9 accident from possible standpoint rather than actual Two Certificates of Svc encl MATTSON, R. J. TMI-2 Lessons Learned Task Force. 79/08/14. App.
- 7912190530 Responds to 790726 ltr requesting deforment of all licensing of nuclear power plants until all facts known about TMI. New plants will not be licensed until criteria developed, implementing new safety objectives.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/12/03. ip.
- --7908080606 Oppuses proliferation of US nuclear power plants Requests that licensing be deferred until TMI studies are complete. MILNS-M.C. Affiliation Unknown. 79/07/29. ip.

- H. General correspondence
- 7912190567 Responds to NRC 791002 ltr re acceptance of Oak Ridge Associated Univs radiation safety training of NRC personel. NRC personnel will need to take brief radiation safety quit & attend plant specific indoctrination. LIBRIZILE, Public Service Electric & Gas Co. of New Jersey. 79/12/10. 1p.
- 6. Inspection reports, IE Bulletins & correspondence
- 7912030059 Forwards IE lnsp Repts 50-272/79-25 & 50-311/79-13 on 790805-0909. No noncompliance noted. BRUNNER.E.J. Region i. Philadelphia, Reactor Operations Nuclear Support Branch. 79/09/27. 2pp.
- --7912030064 IE Insp Repts 50-272/79-25 & 50-311/79-13 on 790805-0909. No noncompliance noted Major areas inspected: plant layout, logs & records & followsp on IE bulletins & on previously inspected items.

  NORRHOLM, L. J. Region 1, Philadelphia, Office of the Director.

  KEIM10,R.R. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 77/09/26. 14pp.
- 791204004B Forwards IE Insp Repts 50-272/79-25 & 50-3ii/79-13 on 790805-0909.No noncompliance noted.
  BRUNNER.E. J. Region I. Philadelphia, Reactor Operations Nuclear Support Branch. 79/09/27. 2pp.
- --7912060076 IE Insp Repts 50-272/79-25 & 50-311/79-13 on 790805-0909. No noncompliance noted Major areas inspected: facility bour, log & record reviews. It censee event review. IE Bulletin followup, fire protection & GA.
  NORRHOLM, L. J.
  Region i, Philadelphia, Defice of the Director.
  KEIMIO.R.R. Region i, Philadelphia, Reactor Operations Nuclear 579/09/26. 14pp.
- 7912030236 Ack receipt of 790921 ltr informing of steps taken to correct violations noted in IE Insp Rept 50-272/79-15.
  ORIER.B.H. Region i. Philadelphia. Office of the Director.
  79/10/15. 1p.
- 7912180472 Responds to IE Bulletin 79-23, "Potential Failure of Emergoncy Diosel Generator Field Exciter Transformer."
  Diesel generators tested in accordance w/IE Bulletin 79-23. No alarms or abnormal conditions recorded. Bulletin 79-23. BCHNEIDER F. W. Public Service Electric & Oas Co. of New Jersey. 79/10/23. 2pp.
- 7912170190 Forwards response to IE Bulletin 79-14, Buppl 2, "Seismic Analysis for As-Built Safety-Related Piping Sys." As-built piping sys conform to stress isometrics used for performing seismic analyses.
  SCHNEIDER, F. W. Public Bervice Electric & Gas Co. of New Jersey.
  79/10/30. 4pp.
- 7912200043 Forwards IE Insp Repts 50-272/79-27 & 50-311/79-34 on 79091-1006. No noncompliance noted.
  BRUNNER.E. J. Region i, Philadelphia, Reactor Operations Nuclear Support Branch. 79/11/01, 2pp.
- --7912200046 IE Insp Repts 50-272/79-27 & 50-311/79-34 on 790910-1006.No noncompliance noted Major areas inspected:log & records raview & review of licensee events.

  NORRHOLM, L. J. Region 1. Philadelphia. Office of the Director.

  KEIMIG.R.R. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 79/10/31. 15pp.
- 7912180435 Revises 791013 response to IE Bulletin 79-14, Suppl 2, "Seismic Analysis for As-Built Safety-Related Piping Sys." Changes last sentence on Page 2 re power ascension tests. MARTIN.T.J. Public Service Electric & Gas Co. of New Jersey. 79/11/06. ip.
- 771226032 Responds to Revision 2 of IE Bulletin 79-13 re cracks in feedwater sys piping. Insps at Unit 1 exceeded requirements. After piping support insp at Unit 2, util will be in full compliance w/Revision 2. SCHNEIDER, F. W. Public Bervice Electric & Gas Co. of New Jersey. 79/11/15. 2pp.
- 7912050057 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required. GRIER.B.H. Region 1. Philadelphia. Defice of the Director. 79/11/16. ip.
- 7912050298 Forwards IE Info Notice 79-27, "Btsam Osmerator Tube Ruptures at Two PMR Plants." No response required. ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/11/16. ip.

- 7912100146 Forwards IE Info Notice 79-28, "Overloading of Structural Elaments Due to Pipe Support Loads." No response required. ORIER.B.H. Region i, Philadelphia, Office of the Director. 79/11/16. 1p.
- 7912110466 Forwards IE Info.Notice 79-29. "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required.
  ORIER.B.H. Region i. Philadelphia, Office of the Director. 79/11/19. 1p.
- 7912050207 Forwards IE Bulletin 79-25, "Boron Loss From BWR Control Blades," No response required. ORIER, B. H. Region i, Philadelphia, Office of the Director. 79/11/20, ip.
- 7912060588 Forwards IE Circular 79-24, "Proper Installation & Calibr of Cors Spray Pipe Break Detection Equipment on BWRs." No response required.
  ORIER, B. H. Region i, Philadelphia, Office of the Director.
  79/11/26. ip.
- 7912110080 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required.
  ORIER.B.H. Region 1, Philadelphia, Diffice of the Director.
  79/11/26. ip.
- 7912190071 Forwards IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation." Written response required. ORIER, B.H. Region 1. Philadelphia, Offics of the Director. 79/11/30. 1
- 7912310244 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action required. GRIER, B. H. Region i, Philadelphia, Office of the Director. 79/12/06. 4pp.
- 7912190765 Forwards IE Bulletin 79-28, "Possible Melfunction of Namco Model EA180 Limit Switches at Elevated Temps." Written response required. ORIER, B.H. Region i, Philadelphia, Office of the Director. 79/12/07. ip.
- 79:12280236 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required.
  ORIER.B.H. Region 1, Philadelphia, Office of the Director.
  79/12/13. ip.

#### R. Periodic operating reports & related correspondence

- 7912040511 Industrial wasts treatment operating rept for Oct 1979. MIDURA, H. J. Public Barvice Electric & Oas Co. of New Jarsey. 79/11/08. 2pp.
- --7912040515 Industrial waste treatment operating rept for Dct 1979.

  \* Public Service Electric & Oas Co. of New Jersey. 79/10/31. ip.
- 7912040521 Forwards wastewater treatment rept for Oct 1979. MIDURA, H. J. Public Service Electric & Gas Co. of New Jarsey. 79/11/13. ip.
- --7912040524 Wastewater treatment rept for Oct 1979.
  \* Public Service Electric & Oas Co. of New Jersey. 79/11/13. ip.
- 7912040493 Forwards "Discharge Monitoring Rept for Oct 1979, " MIDURA.H.J. Public Bervice Electric & Gas Co. of New Jersey, 79/11/26. ip.
- --7912040495 "Discharge Monitoring Rept for Oct 1979."

  9CHNEIDER, F. H. Public Service Electric & Oas Co. of New Jersey, 79/11/20. 12pp.

# S. Reportable occurrences, LERs & related correspondence

- 7912120175 Ack receipt of 771005 ltr forwarding Significant Deficiency Evaluation Rept 79-06 re steam generator water level. CARLBON, R. T. Region i, Philadelphia, Reactor Construction & Engineering Support Branch. 79/10/15. ip.
- 7912140128 Ack receipt of enc1 791005 ltr forwarding final deficiency rept re containment purge & pressure vacuum relief valve. CARLSON.R.T. Region i, Philadelphia; Reactor Construction & Engineering Support Brench. 79/10/15. ip.

- 7912140533 Ack receipt of 791004 interim deficiency rept re max flow of RHR pump during post-LOCA recirculation mode.Rept encl. CARLEON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Brench. 79/10/15. 1p.
- --7912140537 Interim deficiency rept re max flow of RHR pump during post-LOCA mode. Caused by low sys resistance to pump runout conditions. Bys resistance increased by placement of resized orifices.

  MARTINIT.J. Public Service Electric & Oas Co. of New Jersey.
  79/10/04. 3pp.
- 791231010B Forwards WPPSG info indicating over 180 violations of separation criteria in control room Requires util audit of installed electric equipment to determine conformance.
  PARR. O. D. Light Water Reactors Branch 3. 79/11/29. 2pp.

# DOCKET 50-312 RANCHO SECO NUCLEAR GENERATING STATION

# A. Application/construction stage documents & correspondence

- 7912170038 Forwards MA Baldwin of Friends of the Earth 791024 request for preparation of add1 environ statements re Class 9 accidents at facilities. Petition being handled as request for action under 10CFR2. 206.

  DENTON
- 7912170064 Forwards HA Baldwin of Priends of the Earth 791024 request for preparation of addl environ statements re Class 9 accidents at facilities. Petition being handled as request for action under 10CFR2.206.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/27. 2pp.
- F. Becurity, medical, emergency & fire protection plans
- 7712180335 Notifies of delay in Plant Sys Branch Team 1 evaluations of facility fire protection sys. Outlines of assistance needed encl.

  LAINS-0. Plant Systems Branch. 79/11/14, 5pp.
- 791219073B Forwards input for answering two of GAD recommendations in rept, "Emergency Preparedness Around Facility:Case Study," RYAN.R.Q. Office of State Programs. 79/11/23. 3pp.
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives. Provides guidance for improving licensee emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.

  ORIMEB.B.K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- 7912240230 Forwards constr installation & testing schedule re physical protection sys. Schedule withheld (ref 100FR2.790).
  MAYTIMDE, J. J. Sacramento Municipal Utility District. 79/12/14. lp.
- 7712260226 Forwards Amend 7 of modified amended security plan. Amend withheld (ref 10CFRZ.790).
  MATTIMOE, J. J. Sacramento Municipal Utility District. 79/12/17. 1p.

### O. Adjudicatory correspondence

- 7912030107 Restatement of issues by CA Energy Commission. Withdraws previous issues, per NUREO-0578 recommendation to implement addl safety measures, Urges ABLB to clarify ruling on scope of hearing re offsite power loss. W/Certificate of Svc. ELLISON.C., BROWN, H. H. California, State of. 79/10/24, 3pp.
- --7912030112 Motion by CA Energy Commission for reconsideration of ASLI 791009 order excluding emergency response issue from proceeding. If affirmed, order should be certified to Commission for clarification of ASLB jurisdiction. ELLIBON.C., BROWN.H.H. California, Btate of. 79/10/24, 5pp.
- ---7912030117 Motion by CA Energy Commission for reconsideration of 791107 & 27 evidentiary hearings schedule. Requests delay of discovery until issuance of ruling on CA commission motion re-restatement of issues. Certificate of Byc and.

  ELLIBON.C., BROWN.H.H. California, State of. 79/10/24, 5pp.
- 7912030027 Answer in opposition to CA Energy Commission 791024 motion for reconsideration of ABLB 791009 order or for Commission certification. Urges exclusion of emergency planning issue or referral of order to ABLAB for review, BAXTER, T. A. LARSON, L. X. Bácramento Municipal Utility District. BAXTER, T. A. Shaw, Pittman, Potts & Trowbridge. 79/11/08. 7pp.

- --7912030034 Response to CA Energy Commission 791024 restatement of issues & request for clarification of offsite power issue.

  Issues may be admitted. Clarification not necessary, due to expected ruling on evidence. Certificate of Bvc encl.

  BAXTER.T.A., LARSON.L.K. Bacramento Hunicipal Utility District.

  BAXTER.T.A. Shaw, Pittman, Potts & Troubridge. 79/11/08. 4pp.
- 7912050242 Response to CA Energy Commission 791024 mation for reconsideration of schedule of discovery & hearings. Expidited schedule encl. Certificate of Suc encl. LEWIS,S.H. Hearing Branch 2. 79/11/08. 5pp.
- 7912100137 First set of interrogatories directed to 9 Hursh & R Castro. Requests bases for allegations that steam generator dosign results in unsafe facility. HDEFLING.R.K. Hearing Branch 4. 79/11/09. 12pp.
- --7912100143 Request for production of documents directed to 0 Hursh & R Castro. Damends insp & copying of all documents to be identified in responses to NRC 791109 first set of interrogatories.

  HOEFLING.R.K. Hearing Branch 4. 79/11/09. 1p.
- --7912100147 First set of interrogatories directed to CA Energy Commission (CEC). Questions meaning of "mechanics of facility," "basic reactor physics," "overpressurization protection" & other terms used in CEC queries.

  HOEFLING.R.K. Hearing Branch 4. 79/11/09. 7pp.
- --7912100153 Request for production of documents directed to CA Energy Commission. Demands insp & copying of all documents to be identified in responses to NRC 791109 first set of interrogatories.

  HOEFLING, R. K. Hearing Branch 4. 79/11/09. ip.
- ---7912100158 First set of interrogatories directed to Friends of the Earth. Requests reasons & bases re allegations of util failure to take procedures assuring Pacility act competence. HOEFLING.R.K. Hearing Branch 4. 79/11/09. 7pp.
- --79:2:10016: Request for production of documents directed to Friends of the Earth Demands insp & copying of all documents to be identified in responses to NRC 79:109 first set of interrogatories. Certificate of Euc encl.
  HOEFLING.R.K. Hearing Branch 4. 79/11/09. 3pp.
- 7912170072 Response to CA Energy Commission (CEC) 791024 request for reconsideration of schedule. Urges partial denial of motion re CEC burden of proving own issues & seeks clarification of CEC burden re ASLB issues W.Cartificate of Svc.
  LEHIS.8. H. Hearing Branch 2. 79/11/13. 6pp.
- 7912170082 Response to CA Energy Commission 791024 restatement of issues & to request for clarification re ASLB exclusion of offsite power loss. Issues 1-1 &1-12 should be admitted. Urges denial of clarification. Certificate of Svc encl. LEMIS, B. H. Hearing Branch 2. HOEFLING, R. K. Hearing Branch 4. 79/11/13. App.
- 7912170216 Response to CA Energy Commission 791024 motion for reconsideration of ASLB 791005 order ruling on scope of contentions. Urges inclusion of emergency planning issues & exclusion of offsite matters.

  LEWIS, S. H. Hearing Branch 2. 79/11/13. 7pp.
- --7912170236 "Modified Adjudicatory Procedures," 10CFR2.764 suspension & statement of policy on conduct of adjudicatory proceedings.

  Constitutes final action on petitions received in proceedings. SJ Chilk 797105 suppl & Certificate of Svc encl.

  Geffice of the Socretary of the Commission. 79/11/09. 12pp.
- 7912140054 Intervenor CA Energy Commission first set of interrogatories & request for documents Seeks info re small break analysis, plant transient conditions & safety precautions taken in light of TMI.

  ELLISON.C., LANPHER.L.C. Galifornia, State of. 79/11/15. 10pp.
- 7912170005 Intervenor CA Energy Commission first request to NRC production o documents. Requests all documents identified by NRC in 791115 response to first set of interrogatories. ELLIBON. C. . LANPHER. L. C. California, State of. 79/11/15. 2pp.
- 7912050433 Notice that ML Glase will be replaced by ES Bowers as chairperson for proceeding.

  LAZUR.M. Atomic Safety and Licensing Board Panel. 79/11/20. Ip.
- 771211003B Confirms receipt of encl 770329 petition to suspend OLs for all PHRs. Forwards FR notice indicating that petition will be treated in eccordance w/10CFR2. 206.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/23. 1p.

- --7912110126 Notice of request for action pursuent to 10CFR2.206 re Environ Coalition on Nuclear Power 790327 patition requesting suspension of all OLs for PWRs. MULLER.D.R. Office of Nuclear Reactor Regulation. 79/11/23. SBpp.
- 7912130058 Forwards petition by HA Baldwin requesting that NRC prepare supplemental environ statements re Class 9 accidents at facilities. Appropriate action will be taken.
  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/11/27. 3pp.
- ---7912130070 Request for action under iOCFR2. 206, for preparation of supplemental EIS concerning impact of Class 9 accidents at facilities.

  MULLER, D. R. Division of Site Bafaty & Environmental Analysis. 79/11/23 in.
- 791220015B Ack receipt of 791024 petition & forwards FR notice for request for action per 100FR2.205.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/27. Spp.
- --7912200168 Notice of issuance & availability of Friends of the Earth 791024 petition requesting that NRC prepare supplemental EIS re impact of Class 9 accident at facilities. MULLER.D.R. Division of Site Eafety & Environmental Analysis. 79/11/23. | p.
- 79:2060024 Confirms 79:128 telcon re exchange of discovery between GA Energy Commission (CEC) & NRC. Responses to NRC interrogatories will be merved on 79:203. Responses to CEC interrogatories will be served on 79:201.
- 7912140015 First set of interrogatories. Adopts NRC 791109 first set of interrogatories.
  LARBON.L.K. Secramento Municipal Utility District. LARBON.L.K. Shaw. Pittman, Potts & Trowbridge. 79/12/04. 2pp.
- --7912140023 First request for production of documents directed to intervenor Friends of the Earth Adopts 791109 request for documents. Certificate of Svc encl.
  LARSON.L.K. Bacramento Municipal Utility District. LARSON.L.K. Shaw, Pittman, Potts & Trowbridge. 79/12/04. 3pp.
- 7912140033 First set of interrogatories directed to intervenor CA Energy Commission. Requests info re increased challenges to safety sys, failure of safety & relief valves, low reliability of auxiliary feedwater sys & accumulation of gas.

  LARSON, L. K. Sacramento Municipal Utility District. LARSON, L. K. Shaw, Pittman, Potts & Troubridge, 79/12/04, 6pp.
- --7912140041 First request for production of documents directed to intervenor CA Energy Commission. Requests all documents used to respond to util 791204 first set of interrogatories to CA Energy Commission. Certificate of Svc encl. LARBON.L.K. Bacramento Municipal Utility District. LARBON.L.K. Shaw, Pittman, Potts & Troubridge. 79/12/04. App.
- 77:2140068 Order adopting parties' proposed schedule for prehearing activities. Parties' understanding re-schedule also adopted. Discovery will proceed on two issues resubmitted in intervenor CA Energy Commission 77:024 pleading. BOMERS, E. B. Atomic Safety and Licensing Board Panel. 77/12/04. 3pp.
- 7912140124 First set of interrogatories Beeks info on Contentions 22,25,30,32 & 34. LARBON,L.K. Sacramento Municipal Utility District. LARBON,L.K. Bhaw, Pittman, Potts & Troubridge. 79/12/04. 4pp.
- --79:2140159 First request for production of documents directed to intervenors R Castro & O Hursh. Seeks all documents used to respond to util 79:204 first set of interrogatories. Certificate of Evc encl.
  LARBON, L. K. Sacramento Municipal Utility District, LARBON, L. K. Shaw, Pittman, Potts & Trowbridge, 79/12/04, 4pp.
- 79:2170:50 Response to CA Energy Commission first request for production of documents identified in NRC 79:115 response to first set of interrogatories. Certain documents available through Board notifications. Certificate of Svc snc1.
  HOEFLING.R.K. Hearing Branch 4. 79/12/11. 5pp.
- 7912170266 Responses to CA Energy Commission 791115 first set of interrogatories. Includes listing of all documents related to TMI-2 & to effects of accident on B&W plants. Affidavits, prof qualifications & Certificate of Bvc encl. HOEFLING, R. K. Hearing Branch 4, LEWIS, S. H. Hearing Branch 2, 79/12/11, 74pp.

- 791218004B Request for finding re State of CA Energy Commission first set of interrogatories & for protective order Responses to Interrogatories 1, 2.5, 7, B. 11 & 14 not necessary to proper decisions &/or are obtainable from other sources.

  HOEFLING, R. K. Hearing Branch 4. LEWIS, S. H. Hearing Branch 2, 79/12/11, 7pp.
- 7912310278 Order affirming & referring ASLB 791007 ruling to ASLAB for consideration. Emergency plan issue within scope of proceeding, but berred by proposed rulemaking. W/RF Cole & FJ Shon separate opinion supporting referral. COLE.R.F., SHOW.F.J., BOWERB.E.S. Atomic Safety and Licensing Board Panel. 79/12/14. 12pp.
- 7912210431 Request for issuance of order compelling intervenor Friends of the Earth to respond to NRC 791107 Intervolvenors aust define terms used; state reasons for assertions & give opinion as to adequate safety level. LENIS, S. H. Hearing Branch 2. 79/12/17. 7pp.
- 7912260327 Requests that intervenors 0 Hursh & R Castro permit insp & copying of all documents identified in response to NRC second set of interrogatories.

  HOGFLING.R.K. Hearing Branch 4. 79/12/17. 1p.
- ---7912260329 Second set of interrogatories Requests clarification of responses to Interrogatories 2,4 & 5 of NRC first set of interrogatories.

  HOEFLING, R. K. Hearing Branch 4. 79/12/17. 3pp.
- --7912260344 Becond set of interrogatiories Requests further info re responses to NRC Interrogatories 2,7,20 & 21 of NRC first set of interrogatories. HQEFLING.R.K. Hearing Branch 4. 79/12/17. 3pp.
- ~~7912260345 Second set of interrogatories. Requests further info re intervenor contentions re NRC 790507 order.facility personnel competence & adequacy of emergency instructions. Certificate of Svc encl. HOEFLING, R. K. Hearing Branch 4. 79/12/17, 7pp.
- 7912270093 Natifies of error in ASLB 791005 order ruling on scape & contentions. List of accepted contentions do not contain those of G Hursh & R Castro.accepted by ASLB on Page 19. Text of contention & Cartificate of Buc encl.

  BAXTER.T.A. Shaw, Pittman, Potts & Trombridge. 79/12/17. 3pp.
- 7912270143 Order placing burden of proceeding w/Energy Commission contentions on CA Energy Commission.

  BOMERB.E.B. Atomic Safety and Licensing Board Panel. 79/12/17.

  2pp.
- 7912270347 Bubmits util response to intervenor Friends of the Earth 791024 request for preparation of supplemental EIB reserviron impact of Class 9 accident. Environ review closed in 1974. No indication of significant defect in assessment. BAXTER, T. A. Shaw, Pittmen, Potts & Trowbridge, 79/12/21. 7pp.
- 7912280508 Requests substantive response to 791024 request for NRC to supplement EI8 to consider consequences of Class 9 nuclear accidents. Failure to respond by 800104 will indicate NRC does not plan to require suppl.

  8ALDWIN.W.A. Friends of the Earth. 79/12/21. 1p.

- 7912280112 Responds to 791022 ltr to Chairman Hendrie expressing concerns re emergency evacuation plans & burden of shutdown. Emergency issue raceiving more attention after TMI-2 accident Efforts being made to avoid delays in operation. KANE, W. F. Standardization Branch. 79/12/13, 2pp.
- J. Insurance & indemnity information
- 7912080800 Forwards executed Amend 7 to Indemnity Agreement B-66, modifying prefetory language re definition of "in course of transportation."

  MATTIMOE, J. J. Sacramento Municipal Utility District. 79/11/29.

  2pp.
- 7912070462 Advises of JR Hicksy complaint contending bodily, mental & financial injuries suffered while employed by SMUD Filed before Superior Court Sacramento Gounty. CA. Chem-Nuclear & other SMUD contractors included as defendants.
  ALTON, C. C. American Nuclear Insurers. 79/12/04. 1p.

- P. Operating license stage documents & correspondence
- 791109024B "Summary of Operating Experience W/Recirculating Steam Generators." EISENHUT.D. O. Division of Operating Reactors. NUREG-0523. 79/01/31. 89pp.
- 790B010339 Notifies of status of rept on reactor cavity annulus seal.
  Most PMR users remove ring during normal operation. Others
  store seal ring in raised position during normal operation.
  LAINAB. 9. Plant Bystems Branch (Pre 791030). 79/07/05. 7pp.
- 7912200243 Forwards index of B&W generic correspondence re resolution of issues associated w/177 Fuel Assembly plants.
  SOUDER, J. L. Division of Rules and Records. 79/11/05. 7pp.
- 7912310070 Ack 790831 Itrs endorsing B&W generic rept BAW-1564, "Integrated Control Sys Reliability Analysis," & requests addl info.
  REID.R.W. Operating Reactors Branch 4, 79/11/07. 13pp.
- 7912130176 Forwards summary of Teknekron Research. Inc study re licensee regulatory performance evaluation & Teknekron draft rept re operating reactors w/8kW nuclear steam supply sys. Requests comments. W/o encl.

  STELLO.V. Office of Inspection & Enforcement, Office of the Director. BALDNIN.W.A. Baldwin, W. A. VALENTINE, P. C. Valentine, P. C. 79/11/08. 2pp.
- 7912100189 Discusses NRC 791101 meeting w/representatives of NBSS vendors & fuel suppliers re discussion of respective portions of ECGS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EISENHUT.D.Q. Division of Operating Reactors. 79/11/09. 65pp.
- --7912100285 Responds to NRC 791101 request re noncompliance of Westinghouse ECC8 evaluation model under requirements of 10CFR30 App K. Evaluation of three fuel rod models indicates no mafety problems for Westinghouse plants. ANDERBON, T. M. Westinghouse Electric Corp. 79/11/02. 4pp.
- --7912100330 Responds to NRC 791101 request re DRM. cladding swelling & rupture data. Review of analytical models & tests indicates compilance w/100FR50 App K. All GE specs for calculated peak cladding temp remain unchanged.

  BUCHHDLZ, R. H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation godels & that analyses demonstrate all criteria of 10CFR50.46 satisfied.

  OWBLEY.0.F. Exxon Nuclear Co.\* Inc. (subs. of Exxon Corp.).
  79711/02. 5pp.
- --7912100456 Forwards add1 info re evaluation of impact of NRC proposed ruptura/blockage model used in vandor evaluation model.

  No adverse impact from new rupture, burst date or use of NRC ruptures/blockage model on licensing calculation results.

  OWBLEY, G. F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).

  79/11/04. 22pp.
- 7912120092 Bummary of 791024 meeting w/B&W owners group to asymmetric LUCA loads evaluation Evaluation of B&W plants to be completed by Jul 1980.
  HOSFORD 8, B. Assistant Director for Engineering Programs.
  79/11/20. 4pp.
- 7912100478 Forwards, to all B&W operating plants except TMI, request for add1 info re small break LDCA, Comments requested by 791203.

  REID, R. W. Operating Reactors Branch 4, 79/11/21. Spp.
- 7912060591 Forwards NRC concerns on control rod guide tube wear in B&W facilities. Meeting scheduled 791220 to clarify & discuss concerns.
  REID. R. W. Operating Reactors Branch 4, 79/11/23, 7ep.
- 7912040392 Forwards response to NUREO-0978 Refueling 1980 & 81 chosen as implementation dates, rather than 800101 & 810101 Most 800101 tasks will be completed by return-to-power date & will be performed more efficiently.

  MATTIMOS, J. J. Sacramento Municipal Utility District. 79/11/26, 13as
- --7912040412 "Operating Quidelines for Small Breaks."
  BECKNER, D. A., HALLMAN, D., KAURANK, B. A. Babcock & Wilcox Co, BUNF-20004. 79/11/30. 49pp.
- --7912040417 "Analysis Summary in Support of Inadequate Core Cooling Quidelines for Loss of RCS Inventory." Babcock & Wilcox Co. 79/11/30. 30pp.

- 7912040478 Submits fallowup request for extension from 791105 to 791117 for completion of mode re degraded voltage conditions.

  MATTIMOE.J.J. Sacramento Municipal Utility District. 79/11/26. 1p.
- 7912110319 Submits design details on mods re containment penetration valve area & makeup pump room discussed in Paragraph 3.0 of safety evaluation for License Amend 19. Requests approval. MATTIMDE.J.J. Sacramento Municipal Utility District. 79/11/30. lp.
- 7912270462 Notifies of 2-wk delay in receipt of CRAFT analysis w/ saquential auxiliary feedwater flow performed by B&M, Analysis will not be forwarded to NRC until 79122B. MATIMOE.J.J. Bacramento Municipal Utility District. 79/12/05. ip.
- 7912180607 Corrects util 791017 ltr se max experience switchyard voltage. District changed setpoint of existing overvoltage to 241 kV during 791117 outage. Operation at 241 kV acceptable. MATTIMOE, J. J. Sacramento Municipal Utility District. 79/12/06.
- 7912190264 Forwards assessment of seismic design requirements for containment structure. EISENHUT.D.O. Division of Operating Reactors. 79/12/06. Spp.
- --7912190269 Assessment of saismic design requirements for containment structure in response to CA Div of Mines & Gaology. \* Division of Operating Reactors. 79/12/05. 54pp.
- 7912280575 Responds to NRC 791121 ltr requesting small break analysis info. B&H is working on analysis. Schedule indicates info renatural circulation slug flow will be submitted by 800131 & info re reactor coolant pump seals by 791219.
  MATTIMOE.J.J. Sacramento Municipal Utility District. 79/12/06. 1p.
- 7912190437 Responds to 791002 memo requesting feedback on seminar scheduls providing radiation safety training in lieu of util safety course. Proposes seam for staff requiring entry into restricted areas. Individuals who fail should take course. RODRIGUEZ.R.J. Sacramento Municipal Utility District. 79/12/12. 10.
- 7912310338 Forwards Revision 1 to proposed Amend 63 to Tech Specs Bections 3 & 4 re limiting conditions for operation & surveillance stds.respectively. MATTIMOE.J.J. Sacramento Municipal Utility District. 79/12/12. 1p.
- --7912310369 Revision 1 to proposed Amend 63 to Tech Spec Sections 3 & 4 re limiting conditions for operation & surveillance stds, respectively.
  \* Serramonto Municipal Utility District. 79/12/12. 26pp.
- 7912190853 Forwards billing authorization issued to Allis-Chalmers Corp demonstrating that util has initiated action to qualify operability of containment vent & purge valves. HALBRIDGE, N. C. Sacramento Municipal Utility District. 79/12/13.
- 7912200505 Forwards "Auxiliary Feedwater Bys Reliability Analysis."
  HATTIMOE, J. J. Sacramente Municipal Utility District. 79/12/17. lp.
- --7912200506 "Auxiliary Feedwater Sys Reliability Analysis."
  \* Sacramento Municipal Utility District. 79/12/31. 47pp.
- 7912280467 Notifies of error in 791031 rept justifying continued irradiation of reactor vessel surveillance specimens. Capsule withdrawn at end of First cycle is RSI-B, not RBI-E. MATTIMOS. J. J. Sacramento Municipal Viility District. 79/12/17. ip.
- 7912280496 Discusses NRC 791107 request for position on recommendations in B&W Rept 156, "Integrated Control Sys Reliability Analysis." Position re recommendations will be provided by 800108.
  MATTIMOE, J. J. Sacramento Municipal Utility District. 79/12/19. ip.
- Q. Inspection reports, IE Bullotins & correspondence
- 7912050272 Forwards IE Insp Rept 50-312/79-16 on 790713-0803. No noncompliance noted. CREMB.J.L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 79/08/20. 2pp.
- --7912030280 IE Insp Rept 50-312/79-16 on 790713-0803 No noncompliance noted Major areas inspected: insp of plant operation, fire protection program & independent effort. CARTER, H.L., JOHNSON, P. Region 5, 8an Francisco, Office of the Director. FAULKENBERRY, B. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 79/08/17. App.

- 7912100283 Forwards IE Info Notice 79-28, "Overloading of Structural Elaments Due to Pipe Support Loads." No response required. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/11/16. 1p.
- 7912110519 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/11/16. 1p.
- 7912180287 Forwards evaluation of util 790411,14,19,22 & 502,11,14,21 & 1026 responses to IE Bulletins 79-05A & 79-05B. "Nuclear Incident at TMI-Suppl." Licensee has taken appropriate actions to meet majority of requirements.
  REID.R. W. Operating Reactors Branch 4. 79/11/23. 17pp.
- 7912210072 Forwards rept, "Evaluation of Licensees Responses to IE Bulletins 79-05A & 75-05B." REID.R.W. Operating Reactors Branch 4. 79/11/23. 3pp.
- --791221007B "Evaluation of Licensess Responses To IE Bulletins 79-05A & 79-059.
  \* Operating Reactors Branch 4. 79/11/23. 29pp.
- 7912070028 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pips Break Detection Equipment on BWRs." No response required.
  ENDELKEN,R. H. Region S, San Francisco, Office of the Director.
  79/11/26, 1p.
- 7912110273 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required.
  ENGELKEN.R.H. Region 5, San Francisco, Office of the Director.
  79/11/26. ip.
- 7912110499 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence eent by NRC to licensees.
  ENGELKEN.R.H. Region 5, Ban Francisco, Office of the Director. 79/11/26. ip.
- 7912190151 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Written response required.
  ENGELKENIR. H. Region 5: San Francisco, Office of the Director. 79/11/30. ip.
- 7912200129 Forwards IE Rept 50-312/79-24 re enforcement conference on 791121. Details withheld (ref10CFR2.790). ENGELKEN.R.H. Region 5. San Francisco, Office of the Director. 79/12/06. 2pp.
- 7912310277 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action required. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/12/06. 4pp.
- 7912190042 Forwards licensee response to IE Bulletin 79-05A, Revision 1, "Nuclear Incident at TMI-Suppl."
  CREMB.J.L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 79/12/07. ip.
- --7912190052 Revised response to IE Bullstin 79-05A, Revision 1, "Nuclear Incident at TMI-Suppl." Standing order will be issued to operating personnel that NRC should be notified within 1-h from time reactor is not in controlled or expected condition NODRIQUEZ, R. J. Bacramento Municipal Utility District, 79/10/24.
- 7912200248 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. ENGELKEN.R.M. Region \$, Ban Francisco. Office of the Director. 79/12/07. 1p.
- 7912210132 Forwards responses to IE Bulletin 79-21, "Temp Effects on Level Measurements." CREMB.J.L. Region B. San Francisco: Office of the Director. 79/12/07. ip.
- --7912210155 Responds to IE Bulletin 79-21, "Temp Effects on Level Instrumentation." Evaluated liquid level measurement sys post-accident ambient temp on indicated water level, safety & control setpoints & emergency procedures, MATTIMOE. J. J. Sacramento Municipal Utility District. 79/09/14. Boo.

- 7912270246 Submits info requested by NRC 791017 ltr re insprvice insp & inservice testing program. Resolves & documents licensee open items.

  MATTIMDE, J. J. Sacramento Municipal Utility District. 79/12/10.
  48pp.
- 7912270327 Forwards Revision 1 to inservice insp program originally submitted 790718. In response to NRC request at 791003-04 insp program review meeting.
  MATTIMOE.J.J. Bacramento Municipal Utility District. 79/12/12. 1p.
- --7912270334 Revision 1 to inservice insp program originally submitted 790718, Sections 3-6 replaced in entirety.

  \* Secremento Municipal Utility District. 79/12/12. 300pp.
- 7912310452 Forwards corrected pages to implementation review of inservice insp testing program.

  MATTIMOE.J.J. Sacramento Municipal Utility District. 79/12/24. ip.
- --7912310455 Corrected Pages 4-4,4-11 through 4-13,4-16,4-45,4-47 & 4-56 to inservice testing program. Includes results from makeup/HPI sys.decay heat/core flood areas, raw water & cooling water & turbine sampling tests.

  \* Bacramento Municipal Utility District. 79/12/24. Opp.
- R. Periodic operating reports & related correspondence
- 7912170277 Forwards monthly operating rapt for Nov 1979. RODRIGUEZ,R,J. Sacramento Municipal Utility District. 79/12/07. 1p.
- ---791217027B Honthly operating rept for Nov 1979. COLOMBD.R.W. Secremento Hunicipal Utility District. 79/11/30. Spp.
- 8. Reportable occurrences, LERs & related correspondence
- 7912070426 Forwards LER 79-016/03L-0.
  MATTIMDE, J. J. Sacramento Municipal Utility District. 79/11/29.
  2pp.
- --7912070430 LER 79-016/OSL-0: on 791101, during periodic visual insp of accessible safety sys hydraulic snubbers; snubbers 12 & 14 determined inoperable. Cause unstated. Snubber 12 rebuilt & tested. Snubber 14 refulled to proper level.
  CDLOMBO, R. W. Sacramento Municipal Utility District. 79/11/29.
- 79i2i10325 Forwards LER 79-003/04T-0.
  MATTIMOE, J. J. Sacramento Municipal Utility District. 79/11/29.
  2pp.
- ---7912110327 LER 79-003/04T-0: on 791120, plant effluent sample exceeded Tech Spec limit of 0,2 mg/l chlorine. Caused by excessive flow in plant sewage sys. COLOMBO.R.W. Bacramento Municipal Utility District. 79/11/29.
- 7912180638 Unusual Event UE-79-D3: on 791120, plant affluent sample revealed chlorine concentration above Tech Specs limit. Caused by sanitary sewage sys. Flow-through sys will be reduced, Forwards LER 79-003/047-0.
  MATTIMDE. J. J. Bacramento Municipal Utility District. 79/11/29.
- ---7912180641 LER 79-003/04T-0: on 791120, plant effluent sample indicated chlorine concentration above Tech Spec limit. Probably caused by excessive flow of plant newage sys. Cause of excessive flow being investigated.

  COLOHBO, R. W. Sacramento Municipal Utility District. 79/11/29, ip.
- 7912140450 Forwards LER 79-017/03L-0.
  MATTIMDE, J. J. Bacramento Municipal Utility District. 79/12/04.
  2pp.
- --7912140457 LER 79-017/03L-0: on 791109, during routine operation, diesel generator A failed to start from control room. Cause undetermined because major factors affecting starting capabilities appeared normal. No recurrence of problem. CDLOMBO, R. M. Bacramento, Municipal Utility District. 79/12/04, ip.
- 7912180551 Forwards LER 79-018/03L-0.
  MATTIMOE.J.J. Bacramento Municipal Utility District. 79/12/06.
  2pp.

- --7912180555 LER 79-018/03L-0:on 791117.during periodic visual insp. snubber 129 found inoperable due to lack of oil.Caused by loose lock-nut which allowed unit to rotate.Unit will be modified during 1780 refueling outage to secure lock. COLOMBO.R.W. Sacramento Municipal Utility District. 79/12/06.
- 7912260228 Forwards LER 79-019/03L-0.
  WALBRIDGE W. C. Sacramento Municipal Utility District. 79/12/10.
- --7912260227 LER 79-019/03L-0: on 791125, furing routine plant equipment insp. discovered weld leak on seal injection line. Cause not stated. Defective portion of weld ground out & weld dya penetrant checked.

  COLOMBO, R. W. Sacramento Municipal Utility District. 79/12/10.
- 7912260215 Forwards LER 79-004/04T-0.
  MATTIMOE.J.J. Bacramento Municipal Utility District. 79/12/11.
  200.
- --7912260217 LER 79-004/04T-0: on 791203, plant effluent samples indicated chlorine levels exceeded Tech Spec limits. Caused by partial blockage of sewage sys inlast line. Dilution flow increased & sewage sys hypochlorite pump stroke reduced.

  COLOMIO, R. M. Sacramento Municipal Utility District. 79/12/11.
  1p.
- 7912260279 Forwards updated LER 79-003/04X-1. MATTIMOE, J. J. Bacramento Municipal Utility District. 79/12/12. 200.
- --7912260283 Updated LER 79-003/04X-i:on 791120, plant effluent sample indicated excess amount of chlorine at site boundary. Caused by partial blockage of sewage sys inlet line. Preventative maint under review.

  CDLOMBD. R. W. Sacramento Municipal Utility District. 79/12/12. ip.
- 7912260273 Forwards LER 79-005/04T-0.
  MATTIMOE.J.J. Sacramento Municipal Utility District. 79/12/13.
- --7912260277 LER 79-005/04T-0: on 791205, plant effluent sample indicated excess amount of chlorine at site boundary. Caused by misunderstanding between chemistry & operations personnel rechlorine specs. Recurring problems w/chlorine under review. COLOMBD. R. W. Sacramento Municipal Utility District. 79/12/13.
- DOCKET 50-919 ARKANSAS NUCLEAR ONE, UNIT 1
- F. Security, medical, emergency & fire protection plans
- 7912180335 Notifies of delay in Plant Sys Branch Team 1 evaluations of facility fire protection sys. Outlines of assistance needed encl.

  LAINAB. 6. Plant Systems Branch. 79/11/16. Spp.
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives. Provides guidance for improving licenses emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.

  ORIMES, B. K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- 7912270070 Forwards comments re revisions & add1 info needed re facility safeguards contingency plan.Plan withheld (ref 10CFR2.790).W/o enci. REID,R.W. Operating Reactors Branch 4. 79/12/10. 2pp.
- 7712310231 Forwards results of preliminary review of facility emergency plan. Encourages continued work w/state & local representatives to improve emergency preparedness. Emergency planning acceptance critaria encl. REID R. W. Operating Reactors Branch 4 (Pre 790625). 79/12/17. 12pp.
- 7912310471 Forwards draft emergency plan incorporating recommendations of NUREO-0578 & NUREO-0610, Emergency Planning Review Guidelines 1, Revision lire emergency planning acceptance criteria for licensed nuclear plants & Reg Guide 1, 101.
  TRIMBLE, D. C. Arkansas Power & Light Co. 79/12/28. 2pp.
- --7912310474 Draft emergency plan. \* Arkansas Power & Light Co. 79/12/26. 300pp.

### Q. Adjudicatory correspondence

- 791211003B Confirms receipt of enci 790329 petition to suspend DLs for all PNRs. Forwards FR notice indicating that petition will be treated in accordance w/10CFR2. 206.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/23. 1p.
- --7912110126 Notice of request for action pursuant to 10CFR2.206 re Environ Coalition on Nuclear Power 790329 patition requesting suspension of all OLs for PWRs. MULLER D. R. Office of Nuclear Reactor Regulation. 79/11/23.
- 7912120538 Responds to FDIA request for IE bulletins & circulars for 1975 & IE info notices for 1975-79. Forwards documents listed in App A. IE circulars not issued in 1976 & IE info notices not issued prior to 1979.

  CARR. J. C. Division of Rules and Records. 79/11/27. 3pp.
- --7912120554 Order requiring licensee to place facility in cold shutdown condition until plant operation & safety procedures are evaluated & until licenses has taken steps to assure that personnel adhere to procedures. DAVIE.J. 9. Office of Inspection & Enforcement, Office of the Director. 79/06/30. Spp.

- 7912310215 Ack receipt of 791105 ltr clarifying proposed Russellville AR Municipal airport classification. Comments on DES for airport being located in close proximity of facility. Assistant Director for Environmental Projects. 79/12/17. 2pp.
- I. Financial information
- 7912050469 Forwards util statement of source of funds.for Oct 1978-Oct 1979. LANOSTON.N. Arkansas Powar & Light Co. 79/11/29. 1p.
- J. Insurance & indemnity information
- 7912070387 Forwards surety bond to meet requirements re Price-Anderson Act. HARTON, J. J. Arkansas Power & Light Co. 79/12/03. 3pp.
- K. Utility Final Bafety Analysis Report (FSAR) & amends
- 7912200520 Forwards Amend 59 to FSAR.
  TRIMBLE D. C. Arkansas Power & Light Co. 79/12/11. 1p.
- --7912200525 Amend 59 to FBAR.
  TRIMBLE, D. C. Arkansas Power & Light Co. 79/12/11. 54pp.
- P. Operating license stage documents & correspondence
- 791109024B "Summary of Operating Experience H/Necirculating Steam Generators." E1BENHUT.D.G. Division of Operating Reactors. NUREG-0323. 79/01/31. B9pp.
- 7912310070 Ack 770831 ltrs endorsing 8&M generic rept 8AM-1964, "Integrated Control Sys Reliability Analysis," & requests addl info. REID,R.H. Operating Reactors Branch 4. 79/11/07, 13pp.
- 79:2100:89 Discusses NRC 79:1101 Meeting s/representatives of NSBS vendors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing s/fuel cladding swelling & incidence of rupture. Vendor responses onel. EISENHUT.D.O. Division of Operating Reactors. 79/11/09. 45pp.
- --7912100255 Responds to NRC 791101 request re noncompliance of Westinghouse ECCS evaluation model under requirements of 10CFRSO App M. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants. ANDERSON, T. M. Westinghouse Electric Corp. 79/11/02. App.
- --77i2100330 Responds to NRC 791101 request re DRNL cladding swelling & rupture data. Review of analytical models & tests indicates compilence w/100FR80 App K. All GE specs for calculated peak cladding team remain unchanged.

  BUCHHOLZ, R. H. General Electric Co. 79/12/07. Spp.

- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50.46 satisfied.

  OMBLEV.9.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/11/02. 5pp.
- --7912100456 Forwards add1 info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. GMSLEV.Q.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/04. 22pp.
- 7912180200 Forwards request for addl info to complete evaluation of electrical override/byposs aspects of containment purge sys. LAINAS.Q. Plant Systems Branch. 79/11/19. 2pp.
- 7912120092 Bummary of 791024 meeting w/B&W owners group re asymmetric LOCA loads evaluation. Evaluation of B&W plants to be completed by Jul 1980.
  HOSFORD.B.B. Assistant Director for Engineering Programs.
  79/11/20. 4pp.
- 79:2100478 Forwards, to all B&W operating plants except TMI, request for addl info re small break LUCA, Comments requested by 79:203. REID, R. W. Operating Reactors Branch 4, 79/11/21. 3pp.
- 7912100229 Requests detailed info re wear characteristics of control rods on guide tubes in fuel assemblies. Info needed to verify that guide tube wear not significant problem in B&W facilities. NRC concerns re guide tube wear encl.
  REID.R.W. Operating Reactors Branch 4. 79/11/23. App.
- 7912040459 Forwards plot of projected operating cycles, per NRC request. One oversized page available in Central Files only. TRIMBLE.D.C. Arkanses Power & Light Co. 79/11/25, 1p.
- 7912040191 Forwards revised pages to Startup Rept Cycle 4 submitted on 790925.
  TRINBLE.D.C. Arkensas Power & Light Co. 79/11/29, 1p.
- --7912040197 Revised pages to startup rept Cycle 4 correcting error in moderator coefficient extrapolated to 95% full power & indicating location of in-core instrumentation used to determine core power distribution.
  TRIMBLE, D.C. Arkenses Power & Light Co. 79/11/29. 3pp.
- 7912110158 Notification of 791206 meeting w/util to discuss util proposal for long term technical support ctr. to be implemented as followup to TMI Lessons Learned Task Force rept.
  LONO.C. TMI-2 Lessons Learned Task Force. 79/11/30. 2pp.
- 7912120356 Forwards core power maps required to calculate core power distribution for Cycle 4 startup rept.
  TRIMBLE.D.C. Arkansas Power & Light Co. 79/12/09, 13pp.
- 7912120203 Submits schedule of response for small break LOCA concerns requested in 791221 ltr.
  TRIMSLE.D.C. Arkansas Power & Light Co. 79/12/04. 1p.
- 7912120934 Forwards request for addl info to complete review of GA program.

  HAASS M.P. Quality Assurance Branch. 79/12/05. Spp.
- 7912130249 Forwards revision to 791120 ltr re implementation schedule for Leasons Learned Task Force short-term recommendations. Requests expedited concurrence w/mothod of compliance to NUREO-0578.

  CAVANAUGH, H. Arkansas Power & Light Co. 79/12/05. 22pp.
- 7912140327 Forwards revision of selected provisions of 791120 response to TMI Lessons Learned Task Force recommendations Sequential shutdowns preferred to concurrent implementation schedule entl.

  CAVANUOH, W. Arkansas Power & Light Co. 79/12/05. 21pp.
- 7912210131 Responds to 780719 ltr requesting cask handling changes for facility & permit for B4C test rud shipment.Requests addl sum to meet Class 4 fee requirements.
  MILLERS U. License Fee Managament Branch. 79/12/12. ip.
- 7912270407 Advises of committment to NRC interim position redemonstration of purge & vent valve operability. Purge isolation valves will ramain closed when reactor is not in cold shutdown or refueling mode.

  TRIMSLE, D. C. Arkansas Power & Light Co. 79/12/12. 1p.

- 7912190705 Forwards "Emergency Operating Spec.Operating Guidelines for Bmall Breaks," & "Analysis Summary in Support of Inadequate Core Cooling Guidelines for Loss of RCS Inventory." to be incorporated into "Small Break Operating Guidelines."
  TRIMBLE.D.C. Arkenses Power & Light Co. 79/12/13. ip.
- --7912190716 "Emergency Operating Specs:Operating Guidelines for Small Breaks." HEGKNER, D. A. Babcock & Wilcox Co. BWNP-20004. 79/11/01. 50pp.
- --7912190721 "Analysis Summary in Support of Inadequate Core Cooling Quidelines for Loss of RCB Inventory." BECKNER, D. A. Babcock & Hilcox Co. 79/11/01. Sipp.
- 7912280609 Requests commitment to facility mods to ensure control room habitability following toxic gos release Quick-response chlorine detectors should be installed in fresh air inlats & control room isolation air exchange rate reduced. REID.R.H. Operating Reactors Branch 4. 79/12/14. 3pp.
- 7912210342 Discusses proposed shutdown to implement short-term items of NUREQ-0576. Shutdown schedule undergoing mod. Units 1 & 2 will be shut down 791221 & 800131, respectively & will not be restarted until items are implemented.

  CAVANAUGH, M. Arkenses Power & Light Co. 79/12/17. 2pp.
- 7912310335 Forwards correction to conceptual design for initiation & control of emergency feedwater independent of integrated control sys.per NOREO-0578 Requests approval Eight oversize drawings encl.

  TRIMBLE.D.C. Arkans
- 7912270133 Forwards "Auxiliary Feedwater Sys Reliability Analyses," & "Emargency Feedwater Reliability Analysis for Unit 1," propared by B&W.
  TRIMBLE, D. C. Arkensas Power & Light Co. 79/12/20, ip.
- ---7912270156 "Auxiliary Feedwater Bys Reliability Analyses." | MEAVER.W. DORMAN.R.W., ENZINNA,R.S. Babcock & Hilcox Co. BAN-1584, 79/12/31. 32pp.
- --7912270161 "Emergency Feedwater Reliability Analysis for Unit 1." WEAVER.W.W., DORMAN.R.W., ENZINNA.R.S. Babcock & Wilcox Co. 79/12/31. 40pp.
- G. Inspection reports, IE Bulletins & correspondence
- 7912170134 Responds to IE Bulletin 79-23, "Potential Failure of Emergency Dissel Generator Field Exciter Transformer." Connections between low kVA rated transformers & high KVA rated emergency generators have not been meds. TRIMBLE.D.C. Arkansas Power & Light Co. 79/10/05. 2pp.
- 7912030326 Forwards IE Insp Repts 80-313/79-21 & 50-368/79-20 on 790909-1003 & notice of violation. MADSEN.6.L. Region 4. Dallas, Reactor Operations Nuclear Support Branch. 79/10/23. 2pp.
- --7912050333 Notice of violation from insp on 790909-1005.
  \* Region 4, Dallas, Office of the Director. 79/10/23, ip.
- --7912050342 IE Insp Repts 50-313/79-21 & 50-368/79-20 on 790909-1005. Noncompliance noted: outdated Q lists. JOHNSON, H. D., MESTERMAN, T. F. Region 4, Dallas, Office of the Director. 79/10/23. 11pp.
- 7912140103 Forwards IE Bulletin 79-17, Revision 1, "Pipe Cracks in Stagnant Boratad Mater Bys at PWR Plants," Written response required.

  8EYFRIT.K.V. Region 4, Dallas, Office of the Director, 79/10/29, ip.
- 7912120561 Forwards IE Bulletin 79-25, "Failures of Westinghouse BFD Relays in Safety-Related Sys." Action required, BEYFRIT.K.V. Region 4, Dallas, Office of the Director. 79/11/02.
- 7912190033 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No written response required.
  SEYFRIT, K. V. Region 4, Dellas, Office of the Director. 79/11/16.
- 7912120550 Forwards IE Bulletin 79-26, "Boron Loss From BHR Control Blades." No response required.

  8EYFRIT.K.V. Region 4, Dailas, Office of the Director. 79/11/20.

- 7912110467 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general oftc copies of escalated enforcement correspondence sent by NRC to licensees.

  EEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/11/26.
- 7912040305 Responds to IE Bulletin 79-14 Forwards submittal schedule for analysis of inaccessible piping, Schedule for response to remaining items has slipped due to impact of new IE Bulletin 79-02, Revision 2, requirements.
  TRIMBLE D. C. Arkansas Power & Light Co. 79/11/27. 3pp.
- 7912050684 Ack receipt of 791115 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-313/79-21.

  MADSEN, O. L. Region 4. Dallas, Reactor Operations Nuclear Support Branch. 79/11/27. jp.
- --7912050687 Responds to NRC 791023 ltr re violations noted in IE Insp Rept 50-313/79-21. Corrective actions: plant G-list & distribution list revised & circulated. TRIMBLE, D. C. Arkansas Power & Light Co. 79/11/15. 2pp.
- 7912190169 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Written response required.
  SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/11/30.
- R. Periodic operating reports & related correspondence
- 7912170331 Forwards monthly operating rept for Nov 1979.
  TRIMBLE, D. C. Arkansas Power & Light Co. 79/12/14. ip.
- --7912170335 Monthly operating rept for Nov 1979. BRAMLETT.L.S. Arkansas Power & Light Co. 79/12/14. Spp.
- 8. Reportable occurrences, LERs & related correspondence
- 7912310069 PNG-IV-79-009: on 791016; reporter interviewed plant manager re repts of radioactive leakage instances: 790926; leakage past packing on two primery sys valves into bldg & 791012; shutdown cooling heat exchanger leak to svc water sys. WESTERNAN.T.F. AMOSEN, Q.L. Region 4, Dallas, Office of the Director. 79/10/17. ip.
- 7912310073 PND-IV-79-010: on 791017, inadvertent release of radioactive gas. Air sample in makeup tank initiated stack monitor alarmed & sampling terminated. Rate of radioactive release exceeded Tach Spec limit by 2.36.

  WESTERMAN, T. F., MADSEN, O. L. Region 4, Dallas, Office of the Director. 79/10/18, ip.
- 7912170256 Forwards LER 79-021/03L-0 & updated LER 79-012/03X-1. TRIMBLE.D.C. Arkansas Power & Light Co. 79/12/06. ip.
- --7912170264 LER 79-021/03L-0: on 791115. while securing makeup & purification sys, inside containment isolation swal return valve failed to fully close on demand. Caused by valve operator torque switch feiling to make up. Buttch replaced. BHIVELY, C. N. Arkansas Power & Light Co. 79/12/06. 1p.
- --7912170269 Updated LER 79-012/03X-1: on 790810, leak rate testing of reactor bidg purge valves at penetration V-1 indicated leak rate in excess of Tech Spec limits. Gaused by maiadjusted valve seat shims. Leak rate test performed.

  SHIVELY, C. N. Arkansas Power & Light Co. 79/12/06, 1p.
- 7912260272 Forwards LER 79-022/03L-0. TRIMBLE.D.C. Arkansas Power & Light Co. 79/12/18. ip.
- ---7912260274 LER 79-022/03L-0: on 791119, during plant heatup to hot shutdown conditions, operational test of turbine driven swergency feedwater pump not performed Caused by scheduling mistake. Startup procedure revised.

  BRAMLETT.L.S. Arkensas Power & Light Co. 79/12/17. 1p.
- U. Congressional/Executive Correspondence
- 7912280261 Forwards B Peters 791108 ltr expressing concerns re NRC public meeting on emergency planning insp. Response requested.
  PRYOR.D. Senate. 79/11/29. Opp.

- OCKET 50-915 DONALD C. COOK NUCLEAR POWER PLANT, UNIT 1 F. Security, medical, emergency & fire protection plans
- 7912200022 Discusses NRC 791109 meeting re emargency preparedness team review objectives. Provides guidance for improving licensee emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.

  GRIMES, D. K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- 3. Adjudicatory correspondence
- 791211003B Confirms receipt of encl 790327 petition to suspend OLs for all PKRs.Forwards FR notice indicating that petition will be treated in accordance w/10CFA2.206.
  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/11/23. 1p.
- -7912110126 Notice of request for action pursuant to 100FR2.206 re Environ Coalition on Nuclear Power 790329 petition requesting suspension of all OLs for PWRs. MULLER, D.R. Office of Nuclear Reactor Repulation. 79/11/23.
- f. Financial information
- 7912270604 Forwards article of merger filed w/State of IN & certificate of merger filed w/State of HI. DDLAN.J.E. Indiana & Michigan Power Co. 79/12/17. 16pp.
- P. Operating license stage documents & correspondence
- 79:1090240 "Summary of Operating Experience H/Recirculating Steam Generators." EISENHUT.D.O. Division of Operating Reactors. NUREG-0523. 79/01/31. G9pp.
- 7908010339 Notifies of status of rept on reactor cavity annulus seal. Most PHR users remove ring during normal operation. Others store seal ring in raised position during normal operation. LAINAB.0. Plant Bystems Branch (Pre 791030). 79/07/05. 7pp.
- 7912050175 Discusses NRC review of LERs & Tech Spec requirements re control RPI sys at Westinghouse PWRs Requests Tech Specs review to ensure requirement for rod maint to within +/- 12 steps indicated & RPI sys verified accurate within 12 steps. SCHWENCER.A. Operating Reactors Branch 1. 79/10/29. 7pp.
- 7912100189 Discusses NRC 791101 meeting w/representatives of NSSS vendors & fuel suppliers re discussion of respective portions of ECCB evaluation models dealing w/fuel cladding suelling & incidence of rupture. Vendor responses enci. EIBENHUT, D. O. Division of Operating Reactors. 79/11/09. 65pp.
- ~-7912100255 Responds to NRC 791101 request re noncompliance of Westinghouse ECCS evaluation model under requirements of IOCFR50 App K. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants. ANDERSON.T.M. Westinghouse Electric Corp. 79/11/02. 4pp.
- --7912100330 Responds to NRC 791101 request re DRNL cladding swelling & rupture data. Review of analytical models & tests indicates compliance w/iOCFRSD App K. All GE specs for calculated peak cladding temp remain unchanged.

  BUCHHOLZ.R. H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of iOCFR50. 46 satisfied. DMSLEY.O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/02. 5pp.
- --7912100486 Forwards add1 info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. QMSLEY,0.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/04. 23pp.
- 7912040175 Summary of 791115 teleon w/util re implementation of Leasons Learned Task Force recommendations. WIGGINTON, D. Operating Reactors Branch i. 79/11/21. 4pp.
- 7912050054 Summary of 791115 telcon w/licenses re 791024 response to NRC 790913 ltr. Informed licenses of lessons learned items for which proposed schedule for implementation is unacceptable.

  HIGGINFON.D. Operating Reactors Branch 1. 79/11/21. 3pp.

- 79:2130409 Confirms 79:129 meeting to discuss NRC regulatory program for protection of public health & safety re plants.

  KEPPLER, J. 9. Region 3. Chicago, Office of the Director. 79/11/21.

  Zpp.
- 7912280632 Confirms 791127 meeting w/mayor of Bridgman, MI & staff to discuss regulatory program for public health & safety protection. Tentative agenda enci.

  KEPPLER, J. O. Region 3. Chicago. Office of the Director. 79/11/2i.
- 7912040489 Responds to NRC 791030 ltr re implementation of recommendations contained in NUREG-0578. Supplements previous responses re power operated relief valves, safety valves & instrumentation for inadequate core cooling. DOLAN, J. E. Indiana & Michigan Power Co. 79/11/26. Spp.
- 7912170018 Submits addl info re analysis,insp & mod of main feedwater sys at plant. DDLAN.J.E. Indians & Michigan Electric Co. 79/11/26. 31pp. Available at NTIS.
- 7912040257 Informs of changes in operating procedures for automatic rod control sys. Changes made to guarantee that plant transient behavior due to credible control rod drop event will be within plant safety criteria.

  DDLAN.J.E. Indiana & Michigan Power Co. 79/11/29. 3pp.
- 7912210134 Requests quarterly radiological assessments to NRC.if Tech Space 2.4.1.h & 2.4.3c of App B are exceeded or vary w/code. SCHWENCER.A. Operating Reactors Branch 1. 79/12/04. 2pp.
- 79:21:10308 Discusses monitoring of containment radiation in context of purge sys operation. Design justified in using control grade radiation monitoring equipment since containment ventilation isolation not relying solely on monitor initiating signals.

  DDLAN, J. E. Indiana & Michigan Electric Co. 79/12/05. 3pp.
- 7912110312 Submits revised scheduls for final repts on results of facility analytical evaluation.
  DOLAN.J.E. Indiana & Michigan Electric Co. 79/12/07. 3pp.
- 7912120404 Forwards add1 info for mods to auxiliary feedwater sys re 790809 amend request. DDLAN,J.E. Indiana & Michigan Electric Co. 79/12/07. 9pp.
- 7912270018 Forwards Amends 34 & 15 to Licenses DPR-58 & DPR-74, respectively, safety evaluation & notice of issuance & availability.
  SCHMENCER.A. Operating Reactors Dranch 1 (Pre 791030). 79/12/07.
- --7912270021 Amends 34 & 15 to Licenses DPR-58 & DPR-74, respectively, requiring max allowable containment purgs isolation valve closure times to be reduced from 10 to 5-s. SCHMENCER.A. Operating Reactors Branch 1 (Pre 791030). 79/12/07. 12pp.
- --7912270023 Safety evaluation supporting Amends 34 & 15 to Licenses DPR-58 & DPR-74: respectively. \* Office of Nuclear Reactor Regulation. 79/12/07. 6pp.
- --7912270024 Notice of issuance & availability of Amends 34 & 15 to Licenses DPR-58 & DPR-74, respectively. BCHWENCER.A. Operating Reactors Branch 1 (Pre 791030). 79712707. 2pp.
- 7912180390 Forwards response to 791030 ltr re requirements for auxiliary feedwater sys identified during Bulletins & Orders Task Force review of operating reactors. Valves locked or sealed & mod to feedpump train to be completed.

  DDLAN.J.E. Indiana & Michigan Electric Co. 79/12/11. 6pp.
- 7912190560 Provides plans for Cycle 2 refueling autage. New fuel batch will consist of 80 fuel assemblies mfg by Westinghouse. Fuel designated as Region 4 & enriched to 3.40 w/o U-235. Startup of Cycle 2 expected by mid-Dec 1979.

  DDLAN, J. E. Indiana & Michigan Electric Co. 79/12/11. 2pp.
- 7912270431 Forwards info re voltage level at safety buses, startup, shutdown & accident loading high & low voltage condition cases & transformers capacity.in response to 790808 ltr. W/oversize drawing of simplified offsite power sources. DDLAM. J. E. Indiana & Michigan Electric Co. 79/12/17. 40pp.
- 791227025B Forwards response to NRC 791210 request for info required for evaluation of licenses response to TMI Lessons Learned Task Force recommendations. Oversize drawings available in Central Files only.

  DDLAN, J. E. Indiana & Michigan Electric Co. 79/18/20. 8pp.

- Q. Inspection reports, IE Bulletins & correspondence
- 7912110257 Forwards IE Insp Repts 50-315/79-23 & 50-316/79-20 on 790903-1005 & notice of violation.
  HEISHMAN.R.F. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 79/10/24. 2pp.
- --7912110263 Notice of violation from insp on 790903-1005.

  \* Region 3, Chicago, Office of the Director. 79/10/22. ip.
- --7912110271 IE Insp Repts 50-315/79-23 & 50-316/79-20 on 790903-1005. Noncompliance noted active welding permit not signed by util const safety coordinator & insp repts not reviewed by plant nuclear & safety review committee. HASSE.R.E., BUYD.D.C. Region 3, Chicago, Office of the Director. 79/10/22. Spp.
- 7912070109 Responds to IE Bulletin 79-24, "Frozen Lines." Adequate measures taken to prevent frozen lines during extremely cold weather.
  DDLAN.J.E. Indiana & Michigan Power Co. 79/11/09. 2pp.
- 7912200687 Responds to IE Bulletin 79-24, "Frozen Lines." Adequate measures taken to prevent freezing during extremely cold
- weather.
  DOLAN, J. E. Indiane & Michigan Power Co. 79/11/09. 2pp.
- 7912050103 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required.

  KEPPLER, J. Q. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912050130 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required.

  KEPPLER.J.O. Region 3. Chicago, Office of the Director. 79/11/16.
  ip.
- 7912100209 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads," No response required.

  KEPPLER, J. O. Region G. Chicago, Office of the Director. 79/11/16.
- 7912110582 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. KEPPLER.J. G. Region 3. Chicago. Office of the Director. 79/11/16.
- 7912050340 Forwards IE Bulletin 79-R6. "Boron Loss From BWR Control Blades." No response required.

  KEPPLER, J. G. Region 3. Chicago, Office of the Director. 79/11/20.
- 7912100436 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BHRs." No written response required.
  KEPPLER.J.O. Region 3, Chicago, Office of the Director. 79/11/26.
- 79:21:0392 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs, copies of escalated unforcement correspondence sent by NRC to licanses.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/28.
- 7912190228 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Hritten response required. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/30. ip.
- 7912200036 Responds to IE Bulletin 79-17, Revision 1. Nondestructive examinations completed 791121. No stress corrusion cracking found, Forwards list of add1 piping runs falling under NRC definition of stagnant borated water lines.

  DOLAN, J. E. Indiana & Michigan Electric Co. 79/11/30. 5pp.
- 7912140043 Forwards flow diagrams for inservice insp program per NRC 791031 request Drawings available in Central Files only. MALONEY, O. P. Indiana & Michigan Electric Cq. 79/12/06. 3pp.
- 7912140089 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 100FR21." No action or response required. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/12/06, ip.

- 7912200127 Forwards IE Bulletin 79-28. "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required.

  XEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/12/10.
- R. Periodic operating reports & related correspondence
- 7912170270 Forwards monthly operating rept for Nev 1979. SHALLER, D. V. Indiana & Michigan Power Co. 79/12/13. 1p.
- --7912170274 Monthly operating rept for Nov 1979. GILLETT.W.T. Indiana & Michigan Power Co. 79/12/03. Spp.
- 7912280521 Forwards annual statistical rept of exposures for 1978. License SUB-1176 did not expire until 790930. Same rept being submitted for Licenses SUB-1176. DPR-58 & DPR-74. SHALLER, D. V. Indiana & Michigan Power Co. 79/12/20. 1p.
- --7912280524 Submits statistical rept of exposures for 1978 Errors discovered in 790305 submittal Data reanalysis has shown differences re number of individuals & distribution of doses.

  SHALLER, D. V. Indiana & Michigan Power Co. 79/09/21. ip.
- 8. Reportable occurrences, LERs & related correspondence
- 7912120061 PND-III-79-026: on 791027, unit shut down to investigate cause of excessive vibrations on Reactor Cociant Pump 2.
  Wastinghouse investigating.
  BOYD, D. C., HEISHMAN, R.F. Region 3. Chicago, Office of the Director. 79/10/29, 1p.
- 7912040384 Forwards LER 79-056/03L-0. SHALLER, D. V. Indiana & Michigan Power Co. 79/11/26. Ip.
- --7912040390 LER 79-056/03L-O on 791027, opening torque on two ice condenser lower inlet doors exceeded max Tech Beec limit. Caused by door springs slightly stiffer than doors on other bays. Spring tension boilts adjusted. DELONG, B. D. Indiana & Michigan Power Co. 79/11/26. 2pp.
- 7912040365 Forwards LER 79-057/03L-0.
  SHALLER, D. V. Indiana & Michigan Power Co. 79/11/28. 1p.
- --7912040371 LER 79-057/03L-0: on 791029, while shifting to RHR, motor-operated containment isolation valve failed to open completely & would not close. Caused by corrusion of valve operator torque switch due to condensation in conduit.
  WIZNER, D. G. Indiana & Michigan Power Co. 79/11/28. 1p.
- 7912070371 Forwards LER 79-058/017-0.
  8HALLER D. V. Indiana & Michigan Power Co. 79/11/30. Lp.
- --7912070377 LER 79-058/01T-0: on 791115, flow path from Unit 2 motor-driven AFP steam generators 1 & 4 was inoperable. Caused by power supsiy to motor operated valves FMQ-212 & FMO-242 being removed for routins insp. Power restored.

  CHADWELL, H. M. Indiana & Michigan Power Co. 79/11/29. 2pp.
- 7912130330 Forwards LERs 79-059/03L-0 & 79-060/03L-0.
  SHALLER D.V. Indiana & Michigan Power Co. 79/12/07. 1p.
- --7912130372 LER 79-059/03L-0 on 79110B during test containment air particulate detector isolation valve ECR-31 would not close. Caused by leaking ASCO solenoid air supply valve & vent port tube restriction. Valve cleaned & tube removed.

  DELONO.8.D. Indiana & Michigan Power Co. 79/12/07. 2pp.
- --7912130380 LER 79-060/03L-0; on 791116, intermediate deck door to ice condenser found frozen shut Caused by plugged air handling unit drain line & frozen drainage overflow. Ice removed & drain line cleared Mod initiated.

  BROWN M.S. Indiana & Michigan Power Co. 79/12/07. 1p.
- 7912170238 Forwards LERs 79-061/03L-0 & 79-062/03L-0. SHALLER, D. V. Indiana & Michigan Power Co. 79/12/11. Ip.
- --7912170252 LER 79-061/03L-0: on 791111.during startup.stram generator 4 steam flow channel 1 indicated 21% lower than redundant channel.Caused by ail leak from bellows to transmitter body causing drift out of spec.Transmitter replaced.

  DELONG.S.D. Indiana & Michigan Power Co. 79/12/11. 1p.

- ---7912170257 LER 79-062/03L-0; on 791111; inoperable steam flow channel 1 taken out of trip condition during investigation of channel spec reading. Caused by incorrect panel indicator labeling. Channel placed in trip mode & labeling corrected. DELONG. B. D. Indiana & Michigan Power Co. 79/12/11. 2pp.
- DOCKET 50-316 DONALD C. COOK NUCLEAR POWER PLANT, UNIT 2 F. Security, medical, emergency & fire protection plans
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives. Provides guidance for improving licensee emergency preparedness & assuring capability of offsite agencies to take appropriate amergency actions.

  CRIMES.B.K. Emergency Preparedness Task Force. 79/11/23. 30pp.

# G. Adjudicatory correspondence

- 7912110038 Confirms receipt of encl 790329 petition to suspend OLs for all PWRs. Forwards FR notice indicating that petition will be treated in accordance w/10CFR2.206.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/23. ip.
- --7912110126 Notice of request for action pursuant to 100FR2.206 re Environ Coalition on Nuclear Power 790329 petition requesting suspension of all OLs for PWRs. MULLER, D. R. Office of Nuclear Reactor Regulation. 79/11/23. 38pp.

## 1. Financial information

- 79:2270604 Forwards article of merger filed w/State of IN & certificate of merger filed w/State of MI.
  DOLAN, J. E. Indiana & Michigan Power Co. 79/12/17. 16pp.
- P. Operating license stage documents & correspondence
- 7911090248 "Summary of Operating Experience W/Recirculating Steam Comprators." EIBENNUT,D.G. Division of Operating Reactors. NUREG-0523. 79/01/31. 8900.
- 7912050175 Discusses NRC review of LERs & Tech Spec requirements re control RPI sys at Westinghouse PWRs. Requests Tech Specs review to ensure requirement for rod maint to within +/- 12 steps indicated & RPI sys verified accurate within 12 steps. BCHMENCER.A. Operating Reactors Branch 1. 79/10/29, 7pp.
- 7912100189 Discusses NRC 791101 meeting W/representatives of NSSS vendors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of ruptura. Vendor responses encl. EISENHUT.D.O. Division of Operating Reactors. 79/11/09. &5pp.
- --7912100255 Responds to NRC 791101 request re noncompliance of Westinghouse ECCB evaluation model under requirements of 10CFR50 App K. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants. ANDERBON.T.M. Westinghouse Electric Corp. 79/11/02. 4pp.
- ---7912100330 Responds to NRC 791101 request re ORNL cladding swelling & rupture data. Review of analytical models & tests indicates compilance w/10CFRSO App K. All QE specs for calculated peak cladding temp remain unchanged.

  BUCHROLZ.R.H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR30.46 satisfied.
  OMBLEY,G.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.), 79/11/02. Spp.
- --7912100454 Forwards add1 info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing celculation results. OMSLEY.O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/04. 22pp.
- 7912040176 Bummary of 791115 telcon w/util re implementation of Lessons Learned Task Force recommendations. WIGGINTON.D. Operating Reactors Branch 1. 79/11/21. 4pp.

- 7912080054 Summary of 791115 telcon w/licenses re 791024 response to NRC 790913 ltr. Informed licenses of lessons learned items for which proposed schedule for implementation is unacceptable. WIGGINTON, D. Uperating Reactors Branch 1. 79/11/21. 3pp.
- 7912130409 Confirms 791129 meeting to discuss NRC regulatory program for protection of public health & safety re plants.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/21.

  200.
- 7912280632 Confirms 791129 meeting w/mayor of Bridgman, MI & staff to discuss regulatory program for public health & safety protection. Tentative agenda encl.

  KEPPLER, J. G. Region 3. Chicago, Office of the Director. 79/11/21.
- 7912040489 Responds to NRC 791030 ltr re implementation of recommendations contained in NUREQ-0578. Bupplements previous responses re power operated relief valves safety valves sinstrumentation for inadequate core cooling.

  DDLAN, J. E. Indiana & Michigan Power Co. 79/11/26. Spp.
- 7912170018 Submits addl info re analysis, insp & mod of main feedwater sys at plant.
  DLAN, J.E. Indiana & Michigan Electric Co. 79/11/26. Sipp.
  Available at NTIS.
- 7912040257 Informs of changes in operating procedures for automatic rod control sys. Changes made to guarantee that plant transient behavior due to cradible control rod drop event will be within plant safety criteris.

  DOLAN, J. E. Indiene & Michigan Power Co. 79/11/29, 3pp.
- 7912040254 Forwards diagram of control logic for RHR sys low flow alarm.
  DDLAN.J.E. Indiana & Michigan Electric Co. 79/11/30. Spp.
- 7912040404 Withdraws 790216 ltr requesting relief from commitment to perform load rejection test. Full load rejection test performed on 790721. Test rept will be sent by 791231. DDLAN, J. E. Indiana & Michigan Electric Co. 79/11/30. 1p.
- 7912210134 Requests quarterly radiological assessments to NRC, if Tech Specs 2.4, i. h & 2.4.3c of App B are exceeded or vary w/code. SCHHENGER, A. Operating Reactors Branch 1. 79/12/04. 2pp.
- 7912110308 Discusses monitoring of containment radiation in context of purge sys operation. Design justified in using control grade radiation monitoring equipment since containment ventilation isolation not relying solaly on monitor initiating signals.

  DDLAN, J. E. Indiana & Michigan Electric Co. 79/12/05. 3pp.
- 7912110312 Bubmits revised schedule for final rapts on results of facility analytical evaluation. DDLAN, J. E. Indiana & Michigan Electric Co. 79/12/07. 3pp.
- 7912120404 Forwards addl info for mode to auxiliary feedwater sys re 790809 amend request. DDLAN,J.E. Indiana & Michigan Electric Co. 79/12/07. 9pp.
- 7912270018 Forwards Amends 34 & 15 to Licenses DPR-58 & DPR-74, respectively, safety evaluation & notice of issuance & availability.

  BCHHENCER, A. Operating Reactors Branch 1 (Pre 791030). 79/12/07.
- ---7912270021 Amends 34 & 15 to Licenses DPR-58 & DPR-74, respectively, requiring max allowable containment purga isolation valve closure times to be reduced from 10 to 5-s. SCHMENCER.A. Operating Reactors Branch 1 (Pre 791030). 79/12/07. 12pp.
- ---7912270023 Safety evaluation supporting Amands 34 k 15 to Licenses DPR-58 & DPR-74-respectively. \* Office of Nuclear Reactor Regulation, 79/12/07, App.
- --7912270024 Notice of issuance & availability of Amends 34 & 15 to Licenses DPR-58 & DPR-74, respectively. SCHMENCER.A. Operating Reactors Branch 1 (Pre 791030). 79/12/07. 2pp.
- 7912180390 Forwards response to 791030 ltr re requirements for auxiliary feedwater sys identified during Bulletins & Orders Task Force review of operating reactors Velves locked or scaled & mod to feedpump train to be completed.

  DOLAN, J. F. Indiana & Michigan Electric Co. 79/12/11. 6pp.

- 79:2180436 Forwards add1 info for 79:102 Tech Spec change requests, including description of FSAR analyses results. Also includes MGAP-98:66, "Nuclear Dasign & Core Mgt of DC Cook Unit 2. Cycle 2." Rept withheld (ref 10CFR2.790).

  DOLAN.J.E. Indiana & Michigan Electric Co. 79/12/11. 38pp.
- 7912270431 Forwards info re voltage level at safety buses, startup, shutdown & accident loading high & low voltage condition cases & transformers capacity in response to 79080B ltr. H/oversize drawing of simplified offsite power sources. BOLAN. J. E. Indiana & Michigan Electric Co. 79/12/17. 40pp.
- 7912200509 Requests deletion of License Conditions 3.A & 3.8 of OL Amend, 6. Requirements for Apastat 7000 series relays & pressure switches fulfilled per encl test results. DOLAN.J.E. Indiana & Michigan Electric Co. 79/12/18. App.
- ---7912200512 "Dynamic Evaluation Test Program on Safety Injection Sys Pamel. Auxiliary Relay Pamel & Hot Shutdown Pamel." FDMLER.B.Q. Wyls Laboratories. 79/11/19. 117pp.
- ---7912200515 "Seismic Simulation & Radiation Test Program on Seven Pressure Switches." THORNEERRY, R. Wyle Laboratories, 78/10/26, 29pp.
- 7912270284 Submits add1 info re current status of four requirements of NUMES-0578 concerning direct indication of saféty valve position subcooling mater, sys integrity for high radioactivity & post-accident sampling.
  HUNTER, R. S. Indiana & Michigan Electric Co. 79/12/17. Opp.
- 7912270258 Forwards response to NRC 791210 request for info required for evaluation of licensee response to TNI Lessons Learned Task Force recommendations. Oversize drawings available in Central Files only.
  BOLAN.J.E. Indiana & Michigan Electric Co. 79/12/20, Spp.
- Q. Inspection reports. IE Bulletins & correspondence
- 7912110257 Forwards IE Insp Repts 50-315/79-23 & 50-316/79-20 on 790903-1005 & notice of violation.
  HEISHMAN.R.F. Region 3 Chicago, Reactor Operations Nuclear Support Branch. 79/10/24. 2pp.
- --7912110263 Notice of violation from insp on 790903-1005.

  \* Region 3. Chicago, Office of the Director. 79/10/22. ip.
- --7912110271 IE Insp Repts 50-315/79-23 & 50-316/79-20 on 790903-1005. Noncompliance noted; active welding permit not signed by util const safety coordinator & insp repts not reviewed by plant nuclear & safety review committee. HASSE.R.E., BDVD.D.C. Region 3, Chicago, Office of the Director. 79/10/22. Spp.
- 7912070109 Responds to IE Bulletin 79-24, "Frazen Lines." Adequate measures taken to prevent frozen lines during extremely cold weather.
  DOLANJE, Indiana & Michigan Power Co. 79/11/09, 2pp.
- 7912200687 Responds to IE Bulletin 79-24. "Frozen Lines." Adequate measures taken to prevent freezing during extremely cold meather.

  DOLAN.J.E. Indiana & Hichigan Power Co. 79/11/09. 2pp.
- 7912050103 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required.
  KEPPLER.J.G. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912050130 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Velves." No response required.

  MEPPLER, J. C. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912100209 Forwards IE Info Notice 79-28, "Overloading of Btructural Elements Due to Pipe Bupport Loads." No response required." MEPPLER, J. 9. Region 9, Chicago, Office of the Director. 79/11/16. io.
- 7912110582 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation," No specific action or response required.

  KEPPLER.J. 9. Region 3. Chicago, Office of the Director. 79/11/16.
- 7912050340 Formards IE Builetin 79-26, "Boron Loss From BWR Control Blades," No response required.
  KEPPLER, J. 9. Region 3, Chicago, Office of the Director. 79/11/20.

- 7912100436 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Opray Pipe Break Detection Equipment on BHRs." No written response required.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/26.
- 79:21402:3 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No written response required.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/25.
- 79:21:10392 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs.copies of escalated enforcement correspondence sent by NRC to licensees.

  KEPPLER, J. Q. Region 3. Chicago, Office of the Director. 79/11/2B.
- 7912190228 Forwards IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Written response required.

  KEPPLER. J. Q. Region 3. Chicago, Office of the Director. 79/11/30. ip.
- 7912200036 Responds to IE Bullstin 79-17. Revision I. Nondestructive examinations completed 791121. No stress corrosion cracking found. Forwards list of add1 piping runs falling under NRC definition of stagment beneated water lines.

  DDLAN, J. E. Indiana & Michigan Electric Co. 79/11/30. Spp.
- 7912140043 Forwards flow diagrams for inservice insp program per NRC 791031 request Drawings available in Central Files only.
  MALUNEY, Q. P. Indiana & Michigan Electric Co. 79/12/06. 3pp.
- 7912140089 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, iOCFR21." No action or response required.
  KEPPLER. J. O. Region 3. Chicago, Diffice of the Director. 79/12/06.
- 79:2200127 Forwards IE Bulletin 79-28. "Possible Halfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required.

  KEPPLER, J. Q. Region 3. Chicago, Dffice of the Director. 79/12/10.
- 7912270337 Confirms 791219 verbal rapt to RE Masse re nonconformance in small piping sys. Analysis indicated that 1-inch pipe between primary piping & sxcess let-down heat axchanger would be stressed above yield limit in event of earthquake.
  BHALLER, D. V. Indiana & Michigan Power Co. 79/12/20. ip.
- R. Periodic operating reports & related correspondence
- 7912280821 Forwards annual statistical rept of exposures for 1978. License SUB-1175 did not expire until 790930. Same rept being submitted for Licenses SUB-1176, DPR-58 & DPR-74. SHALLER, D. V. Indiana & Michigan Power Co. 79/12/20. lp.
- --7912280524 Bubmits statistical rapt of exposures for 1978 Errors discovered in 790305 submittel. Data reanalysis has shown differences re number of individuals & distribution of doses.

  BHALLER, D. V. Indiana & Michigan Power Co. 79/09/21. 1p.
- 8. Reportable occurrences, LERs & related correspondence
- 7912040375 Forwards LER 79-039/03L-0.
  8HALLER, D. V. Indiana & Michigan Power Co. 79/11/28. 1p.
- 7912040424 Forwards LER 79-038/017-0.
  BHALLER, D. V. Indiana & Michigan Power Co. 79/11/28. 1p.
- ---7912040430 LER 79-038/01T-0:on 791114.boron injection flow path was inadvertantly made inoperable to perform surveillance testing. Caused by charging line being out of svc for sys mod. Fuel element altered.

  CHADMELL.H.M. Indiana & Michigan Power Co. 79/11/28. 2pp.
- 7912070351 Forwards LER 79-040/03L-0.

  SHALLER.D.V. Indiana & Michigan Power Co. 79/11/30. 1p.

- --7912070356 LER 79-040/03L-0: on 791(0), during refueling operations, reactor vessel head unbolted w/one source range neutron flux monitor inoperable. Caused by deficient refueling protedure. Procedure to be revised.

  CHADWELL: H. M. Indiana & Michigan Power Co. 79/11/29. 1p.
- 7912070378 Forwards LER 79-041/03L-0. SHALLER.D.V. Indiana & Michigan Power Co. 79/11/30. 1p.
- ---7912070379 LER 79-041/03L-0: on 791101, during surveillance testing, hydrogen recombiner 1 failed to increase temp as required by Tech Specs. Cause unknown. Troubleshooting in progress, repairs to follow. WIZNER, D. G. Indiana & Michigan Power Co. 79/11/30. 1p.
- 7912100277 Forwards LERs 79-042/03L-0 & 79-043/03L-0. SHALLER, D. V. Indiana & Michigan Power Co. 79/12/03. ip.
- --7912100286 LER 79-042/03L-0:on 791101, while in Mode 6, w/one diesel generator out of svc.kV inverter blew fuse. Caused by loose bus feed cable short circuiting inverter while contractor personnel worked on inoperable generator.

  # Indiana & Michigan Power Co. 79/12/03. 2pp.
- ---7912100291 LER 79-043/03L-0:on 791102, during surveillance imsp, cracks discovered in rubber of ice condenser divider barrier seal. Cause & corrective action under study.
  WIZNER, D. G. Indiana & Michigan Power Co. 79/12/03. ip.
- 7912130312 Forwards LER 79-044/03L-0. SHALLER, D. V. Indiana & Michigan Power Co. 79/12/07. 1p.
- --7912130322 LER 79-044/03L-0: on 791025, during transfer of fuel, surveillance requirement for potential impact energy of crane load was not completed. Caused by misunderstanding of new Tech Spec. Refueling procedure change initiated.
  WIZNER, D. G. Indians & Michigan Power Co. 79/12/07. 1p.
- 7912170260 Forwards LER 79-045/03L-0. SHALLER, D. V. Indiana & Michigan Power Co. 79/12/12. 1p.
- --7912170271 LER 79-045/03L-0: on 791113, penetration provided access from containment to auxiliary bldg atmosphere contrary to Tech Specs. Caused by repair of bonnet removed from hand valve, Valve work suspended.
  LEASE, R. S. Indiana & Michigan Power Co. 79/12/12. 2pp.
- 7912270590 Forwards LER 79-046/03L-0 & LER 79-047/03L-0. SHALLER, D. V. Indiana & Michigan Power Co. 79/12/19. 1p.
- --7912270598 LER 79-046/03L-0: on 791119, during refushing, source range neutron flux manitor N-31 failed, Caused by excessive moisture in detector wells. Detectors replaced & dried. RISCHLING, J. L. Indiana & Michigan Power Co. 79/12/19. 2pp.
- --7912270602 LER 79-047/OSL-0: on 791124; during grid degraded voltage relay calibr, relay 27-1-201-A9 drapped out at nonconservative value. Caused by lener diade failure. Diode replaced & relay recalibr. RISCHLING, J. L. Indiana & Nichigan Power Co. 79/12/19. lp.
- 7912310345 Forwards LER 79-043/03X-1. SMALLER,D.V. Indiana & Michigan Power Co. 79/12/24. 1p.
- --7912310350 LER 79-043/03X-1:on 791102, during surveillance insp.ice condenser divider barrier seal found to have cracks in rubber.Caused by excessive compression during installation. Seal ring replaced in manner limiting compression. WINER.D.O. Indiana & Michigan Power Co. 79/12/21. lp.
- DOCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT. UNIT 1 F. Security, medical, emergency & fire protection plans
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness toam review objectives. Provides guidance for improving licensee emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.
  GRINES.B.K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- 7912040463 Notifies of delay in responding to request re ASTM E-119 test procedure. New drawings & room-by-room documentation to reflect fire safety actions underway. Revised submittals will be completed by 791221.

  LUNDVALL. A. E. Baltimore Oas & Electric Co. 79/11/29. 1p.

- 7712200062 Discusses fire protection test procedures to qualify cable & pipe genetrations. Lists issues that will not be resolved by test. No objection to use of test to obtain addl info on capability of cable.

  LAINAS.O. Plant Systems Branch. 77/11/29. 2pp.
- 7912260220 Forwards responses to Paragraphs 3.19,3.1,20,3,2.1,3.2.2, 3.2.8 & 3.2.9 re fire protection SER & amends to DL. Balance of response to Paragraph 3.2.1 delayed due to manpower commitments of TMI requirements.

  LUNDVALL, A. E. Baltimore Gas & Electric Co. 79/12/21. 350pp.
- 7912310388 Forwards oversize drawings of Figures 1-11 for fire hazards analysis of fire protection safety evaluation. Remaining item will be completed by 800111. LUNDVALL, A. E. Baltimore Gas & Electric Co. 79/12/27. 1p.
- --7912310431 "Fire Hazards Analysis: Auxiliary Bldg, Elevation (-)8 ft-0 inches, (-)10 ft-0 inches & (-)15 ft-0 inches, Safe Bhutdown Equipments & Raceway Locations." Figure 1.

  \* Baltimore Oas & Electric Co. 79/12/27. 1p.
- --7912310482 "Fire Hazards Analysis: Containment & Auxiliary Bldg, Unit i, Elevation 5 ft-0 inches & 10 ft-0 inches. Bafe Shutdown Equipments & Raceway Locations." Figure 2. \* Baltimore Gas & Electric Co. 79/12/27. 1p.
- ---7912310490 "Fire Hazards Analysis: Containment & Auxiliary Bldg. Unit i, Elevation 27 ft-0 inches. Bafa Shutdown Equipments & Raceway Locations." Figure 3. \* Baltimore Gas & Flectric Co. 79/12/27. ip.
- --7912310496 "Fire Hazards Analysis: Containment & Auxiliary Bldg, Unit i. Elevation 45 ft-0 inches, Safe Shutdown Equipment & Raceway Locations. " Figure 4. \* Baltimore Gas & Electric Co. 79/12/27. ip.
- --7912310502 "Fire Hazards Analysis: Containment & Auxiliry Bldg, Unit i, Elevation 69 ft-0 inches, Safe Shutdown Equipment & Raceway Locations." Figure 5. \* Baltimore Oas & Electric Co. 79/12/27. 1p.
- --7912310511 "Fire Hazards Analysis: Containment & Auxiliary Bldg, Unit 2, Elevation 5 ft-0 inches & 10 ft-0 inches, Bafe Shutdown Equipment & Racoway Locations," Figure 6. a Baltimore Qas & Electric Co. 79/12/27. 1p.
- ---7912310525 "Fire Hazards Analysis: Containment & Auxiliary Bldg. Unit 2. Elevation 27 ft-O inches. Bafe Bhutdown Equipments & Raceway Locations. " Figure 7. \* Baltimore Gas & Electric Co. 79/12/27. ip.
- ---7912310530 "Fire Hazards Analysis: Containment & Auxiliary Bldg, Unit 2, Elevation 45 ft-O inches, Safe Shutdown Equipment & Raceway Locations." Figure 8. \* Baltimore Gas & Electric Co. 79/12/27. ip.
- ---7912310534 "Fire Hazards Analysis: Containment & Auxiliary Bldg, Unit 2, Elevation 69 ft-0 inches, Safe Shutdown Equipment & Raceway Locations." Figure 9. \* Baltimore 9as & Electric Co. 79/12/27. 1p.
- --7912310541 "Fire Hazards Analysis: Water Treatment Area, Warehouse & Intake Btructure, Unit 1, Safe Shutdown Equipment & Raceway Locations." Figure 10.

  \*\*Baltimore Gas & Electric Co. 79/12/27. ip.
- --7912310544 "Fire Hazards Analysis: Water Treatment Area, Warehouse & Intake Btructure, Unit 2. Bafe Bhutdown Equipments & Raceway Locations." Figure 11. \* Baltimore Gas & Electric Co. 79/12/27. Ip.
- G. Adjudicatory correspondence
- 7912110038 Confirms receipt of encl 790329 petition to suspend DLs for all PWRs. Forwards FR notice indicating that petition will be treated in accordance w/10CFR2.206.
  DENTEN.H.R. Office of Nuclear Reactor Regulation. 79/11/23. ip.
- --7912110126 Notice of request for action pursuant to 10CFR2.206 re Environ Coalition on Nuclear Power 790329 petition requesting suspension of all OLs for PWRs. MULLER, D.R. Office of Nuclear Reactor Regulation. 79/11/23.

- F. Operating license stage documents & correspondence
- 7911090248 "Summary of Operating Experience W/Recirculating Steam Generators." EISENHUT.D. Q. Division of Operating Reactors. NUREG-0523. 79/01/31. 89pp.
- 7908010337 Notifies of status of rept on reactor cavity annulus seal.

  Most PHR users remove ring during normal operation. Others

  store seal ring in raised position during normal operation.

  LAINAS. Q. Plant Systems Branch (Pre 791030). 79/07/05. 7pp.
- 7912120301 Informs of error in Figure 3.2-4 of Tech Specs issued as License Amend 39. Corrected copy enci.
  REID.R.W. Operating Reactors Branch 4 (Pre 791030). 79/10/11.
- ---7912120307 Revised Pages 3/4 2-11 & 2-12 for Tech Specs re DNB axial flux offset control limit. saved w/License Amend 39.

  \*\* Operating Reactors Branch 4 (Pre 791030). 79/10/11. 2pp.
- 7912170116 Forwards findings from Nov 1978 "Power Plant Cumulative Environ Impact Rept." List of 12 questions re radicative affluents & spent fuel storage pools enci.
  WINEGRAD, O. H. Maryland, State of. 79/11/06. 27pp.
- 7912180057 Notifies of completion of review of steam generator water hammer. Approves proposed changes accompanying installation of L tubes. Tubes can effectively minimize likelihood of water hammer events. Safety evaluation encl. LAINAS, Q. Plant Systems Branch, 79/11/07. 2pp.
- ---7912180063 Bafety evaluation re steam generator water hammer in feedwater sys supporting proposed procedural changes. # Office of Nuclear Reactor Regulation. 79/11/07. Spp.
- 7912100189 Discusses NRC 791101 meeting w/representatives of N888 vendors & fuel suppliers re discussion of respective pertions of ECCB evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EIBENHUT, D. Q. Division of Operating Reactors. 79/11/09, 65pp.
- ---7912100255 Responds to NRC 791101 request re noncompliance of Westinghouse ECCS evaluation model under requirements of 10CFR50 App K.Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants.

  ANDERSON.T.M. Westinghouse Electric Corp. 79/11/02. App.
- ---7912100330 Responds to NRC 791101 request re ORNL cladding swelling & rupture data. Review of analytical models & tests indicates compliance w/100FR50 App K. All QE specs for calculated peak cladding temp remain unchanged.

  BUCHHOLZ.R.H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50.46 satisfied.
  OWBLEY.O.F. Exxon Nuclear Co.: Inc. (subs. of Exxon Corp.), 79/11/02. 5pp.
- ---7912100456 Forwards add1 info re svaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. OMBLEY, 0.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/04. 22pp.
- 7912120262 Bunmary of 791025 marting w/C-E owners group re asymmetric LOCA loads. HOSFORD, S. B. Engineering Branch. 79/11/20, 4pp.
- 7912120274 Forwards supplementary response to followup actions resulting. From TMI-2 incident re short-term lessons learned requirements. Provides implementation schedule.

  LUNDVALL.A. E. Baitimore Gas & Electric Co. 79/12/05. Opp.
- 7912310470 Forwards request for add1 info re containment purge sys to complete evaluation of electrical override/bypass aspects. LAINAG.0. Plant Bystems Brench. 79/12/06. 3pp.
- 7912120269 Discusses hydraulic snubbers w/common reservoirs. Replacement of common reservoirs w/individual reservoirs in progress. Remaining replacements will be completed during next refueling outsign.

  LUNDVALL, A. E. Baltimore Gus & Electric Co. 79/12/07. 3pp.

134

- 7912170364 Responds to NRC 791107 ltr re requirements for auxiliary faedwater sys. Third pump train will be added to enhance sys reliability. Project cannot be completed within 1 yr. LUNDVALL.A.E. Baltimore Gas & Electric Co. 79/12/13. 3pp.
- 7912190403 Submits responses to specific items re containment purging & venting in response to NRC 790927 & 1023 ltrs. Util commits to operation in conformance w/interim position in NRC 791023 ltr. Design review of purge & vent valves performed. LUNDVALL.A. E. Baltimore Gas & Electric Co. 79/12/14. 3pp.
- 7912190497 Responds to followup actions re TMI-2 Lessons Learned Task Force recommendations. Provides interim commitment for coverage of accident assessment function, pending upgrading of operators. Licanse holders to senior operators. LUNDVALL.A.E. Baltimore Gas & Electric Co. 79/12/14. 2pp.
- 7912270404 Supplements response to TMI Lessons Learned Task Force requirements Add1 info re operator license holders will be added to each shift to provide coverage of accident assessment function.

  LUNDVALL.A.E. Baltimore Gas & Electric Co. 79/12/14. 2pp.
- 7912270416 Provides committment to NRC interim position for purge & vent valve operation pending verification of valve operability under DBA-LOCA loadings. Design review indicates valve operation w/adequate shutting torque.

  LUNDVALL.A.E. Baltimore Gas & Electric Co. 79/12/14. Opp.
- 7912280634 Responds to 791106 ltr re affects of radioactive releases into Chamapeake Bay & stmosphere. Releases within Tech Spec limit. Specific answers to 12 questions encl.

  DENTON. H. R. Office of Nuclear Reactor Regulation. 79/12/17. 7pp.
- --7912280641 Forwards safety evaluation documenting analysis of potential risks associated w/LNO ship traffic in Chesapeake Bay. Likelihood of LNO accident resulting in significant radioactive release acceptably low. REID, R. W. Operating Reactors Branch 4 (Pre 791030). 78/06/13. 3pp.
- --7912280646 Safety evaluation re likelihood of LNG accident resulting in significant redicactive release.

  \* Office of Nuclear Reactor Regulation. 78/06/13. 16pp.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912060022 Forwards IE Insp Rept 50-317/79-09 on 790618-21.No noncompliance noted.
  CARLSUN.R.T. Region i, Philadelphia, Reactor Construction & Engineering Support Branch. 79/09/25, 2pp.
- --7912060026 IE Insp Rept 50-317/79-09 on 790618-21 No noncompliance noted. Major areas inspected; activities re IE Bulletin 79-02, DURR. J. P. Region i, Philadelphia. Office of the Director. TRIPP.L. E. Region i, Philadelphia. Reactor Construction & Engineering Support Branch. 79/09/21. 3pp.
- 7912050021 Forwards IE Circular 79-22. "Stroke Times for Power Operated Relief Valves." No response required. ORIER. B. H. Region 1. Philadelphia, Office of the Director. 79/11/16. 1p.
- 7912050230 Forwards IE Info Notice 79-27, "Steam Generator Tube Ruptures at Two PWR Plants." No response required. GRIER.B.H. Region 1. Philadelphia, Office of the Director. 79/11/16. 1p.
- 7912100109 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads," No response required. ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/11/16. 1p.
- 7912110394 Forwards IE Info Notice 79-29. "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required.

  GRIER, B. H. Region 1, Philadelphia, Office of the Director.
  79/11/19. 1p.
- 7912050217 Forwards IE Bulletin 79-26, "Boron Loss From BUR Control Blades." No response required. ORIER, B.H. Region i, Philadelphia, Office of the Director. 79/11/20, ip.
- 7912060565 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pips Break Detection Equipment on BHRs." No response required.
  QRIER, B. M. Ragion 1, Philadelphia, Office of the Director.
  79/11/26, 1p.

- 79:21:10027 Forwards IE Circular 79-23. "Motor Starters & Contactors Failed to Operate." No response required. ORIER.B. M. Region 1. Philadelphia, Office of the Director. 79/11/26. 1p.
- 79:2140213 Forwards IE Circular 79-23. "Motor Starters & Contactors Failed to Operate." No written response required.

  KEPPLER.J.G. Region 3. Chicago, Office of the Director. 79/11/26.
- 7912190017 Forwards IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Gys Bus During Operation." Written response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director. 79/11/30. 1p.
- 7912060358 Submits add1 response to IE Bulletin 79-01A. Cails in solenoid actuated unloader valves for MSIV hydraulic sys of both units observed to be environmentally unqualified for existing temp ambient. No safety hazard involved. ASH.R.F. Baltimore Gas & Electric Co. 79/12/01. 3pp.
- 79:2310205 Ferwards lE info Notice 79-30. "Reporting of Defects & Noncompliances, 10CFR21." No action required. ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/12/06. 1p.
- 7912190731 Forwards IE Bulletin 79-20, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Written response required. ORIER.B.H. Region i, Philadelphia. Office of the Director. 79/12/07. jp.
- 7912280D10 Responds to IE Bulletin 79-02 Revision 2, "Pipe Support Base Plate Designs Using Concrete Expansion Anthor Bolts."
  Supports using structural shapes attached directly to concrete w/expansion anchors were reviewed & repaired.
  LUNDVALL.A. E. Baltimore Gas & Electric Co. 79/12/07. 2pp.
- 7912280183 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required. GRIER, B.H. Region 1, Philadelphia. Office of the Director. 79/12/13. 1p.
- 7912190571 Submits 14-day followup required by IE Bulletins 79-01/01A re nonqualified electrical component Solenoid valves mfg by Skinner Frecision Industries, Electric Valve Div can satisfy pressure flow & environ requirements. Valves on order. LUNDVALL.A.E: Daltimore Gas & Electric Co. 79/12/14. 2pp.
- R. Periodic operating reports & related correspondence
- 7912310416 Forwards monthly operating repts for Nov 1979. MERSON. B. D. Baltimore Gas & Electric Co. 79/12/13. 1p.
- --7912310418 Monthly operating repts for Nov 1979. MERSON.S.D. Daltimore Gas & Electric Co. 79/12/13. 15pp
- S. Reportable occurrences. LERs & related correspondence
- 7912200456 PNB-I-79-018: on 791107, reactor power was reduced to 50% as result of observed axial power imbalance & increased differential pressure of 1.7 psi across reactor core. Caused by air introduced into reactor coalant sys.

  JOHNSON. D. Defice of Inspection & Enforcement, Office of the Director. KEIMIG.R. & BRUNNER, E. J. NRC Regional Defices. 79/11/09. ip.
- 7912260062 Forwards rept, "Cycle 4.Preliminary Rept of Power Distribution Episode." RUSSELL.L.B. Baltimore Gas & Electric Co. 79/11/13. 1p.
- --7912260064 "Cycle 4.Preliminary Rept of Power Distribution Episode." LIPPOLD.W.J. Baltimore Gas & Electric Co. 79/11/12. 11pp.
- 7912060453 Forwards LER 79-065/03L-0. RUSSEL,L.B. Baltimore Gas & Electric Co. 79/12/04. 1p.
- ---7912050494 LER 79-065/03L-0: on 791113, diesel generator 12 taken out of syc to inspect & correct governor operation. Caused by sludge deposits in governor assembly, Covernor cleaned.
  HEIBEL, R. P., HUSEBY, D. E. Baltimore Gas & Electric Co. 79/12/04.
  1p.
- 7912060469 Forwards LER 79-071/03L-0. RUBSELL, L.B. Baltimere Gas & Electric Co. 79/12/04. ip.

- --7912060485 LER 79-071/03L-0. on 791111, reactor tripped due to 500 kV breakers opening & causing loss of 500 kV transmission line 5052 & Unit 1 500 kV bus. Caused by malfunctioning solid state relay card in breaker 952-43 panel replaced. HEIBEL,R.P. Baltimore Gas & Electric Co. 79/12/04. 2pp.
- 7912060494 Forwards LER 79-072/03L-0. RUSSELL/L.B. Baltimore Oas & Electric Co. 79/12/04. 1p.
- --7912060499 LER 79-072/03L-0: on 791114, breaker 552-43 tripped & transmission line 5052 de-energized while breaker 552-41 was open. Possibly caused by personnel working on relay panel. HEIBEL,R.P. Baltimore Gas & Electric Co. 79/12/04. ip.
- 7912130541 Forwards LER 79-066/03L-0.
  RUSSELL,L.B. Baltimore Gas & Electric Co. 79/12/10. 1p.
- --7912130543 LER 79-066/031-0: on 791120, containment cooler 12 taken out of svc to repair sticking fan motor controller handswitch. Cause not stated Spring tension on switch handle adjusted. HEIDEL:R.P.: BAUER.E.R. Baltimore Gas & Electric Co. 79/12/10.
- 7912180456 Forwards LER 79-075/04T-0. RUSEELL L. B. Baltimore Gas & Electric Co. 79/12/13. ip.
- --7912180469 LER 79-075/04T-0:on 791129, waste neutralizing tank overflowed to ground in unmonitored discharge against environ Tech Baces. Caused by operator error in reading tank level. Procedures revised.

  EHERTS,R.F. Baltimore Gas & Electric Co. 79/12/13. 2pp.
- 7912180597 Forwards LER 79-069/03L-0. RUSSELL,L.B. Baltimore Gas & Electric Co. 79/12/13. 1p.
- --7912180502 LER 79-059/03L-0: on 791127; during steady state operation, diesel generator il was removed form svc. Caused by noed to repair generator fuel oil injector supply line. Line replaced & diesel returned to svc. Leak marked for future ref. LAGIEMBKI, J. S., HUSEBY, D. E. Baltimore Oas & Electric Co. 79/12/13. 2pp.
- 7912180408 Forwards LER 79-048/03L-0. RUSSELL.L.S. Baltimore Gas & Electric Co. 79/12/13. 1p.
- --7912180619 LER 79-068/03L-0: on 791127, during normal steady state operation, emergency diesel generator placed out of svc. Caused by need to replace Hoffman air vent float valve which failed due to normal wear. LAOIEMBKI, J. S., HUSEBY, D. E. Baltimore Gas & Electric Co. 79/12/13. 2pp.
- 7912210274 Submits nonroutine radiological environ operating rept re analysis of oyster samples for gamma-omitting radionuclides. Samples showed vory small fractions of allowable doses. STOUT, J. W. Baltimore Gas & Electric Co. 79/12/18. Ip.
- 7912310354 Forwards LER 79-074/03L-0.
  RUSSELL, L. B. Baltimore Gas & Electric Co. 79/12/20. 1p.
- ~~7912310387 LER 79~074/03L-0: on 791204, during steady state operation, diesel generator 12 placed out of svc for repair of oil leaks. Caused by flare & ferrule fittings coming loose due to diesel vibration. Fittings tightened & tubing replaced. LAGIEMSKI, J. S., HUSEBY, D. E. Baltimore Gas & Electric Co.
- DOCKET 50-318 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2 F. Security, medical, emergency & fire protection plans
- 7912200022 Discusses NRC 791109 meeting re emergancy preparadness team review objectives. Provides guidance for improving licensee emergency preparadness & assoring capability of offsite agencies to take appropriate emergency actions.

  GRIMEB, B. K. Emergency Preparadness Task Force. 79/11/23. 30pp.
- 7912040463 Notifies of delay in responding to request re ASTM E-119 test procedure. New drawings & room-by-room documentation to reflect fire safety actions underway. Revised submittals will be completed by 791221.

  LUNDVALL. A. E. Baltimore Gas & Electric Co. 79/11/29. 1p.
- 7912200062 Discusses fire protection test procedures to qualify cable & pipe penetrations. Lists issues that will not be resolved by test. No objection to use of test to obtain addl info on capability of cable.

  LAINAS.O. Plant Systems Branch. 79/11/29. 2pp.

- 7912260220 Forwards responses to Paragraphs 3, 19, 3, 1, 20, 3, 2, 1, 3, 2, 2, 3, 2, 8 & 3, 2, 9 re fire protection SER & amends to GL. Balance of response to Paragraph 3, 2, 1 delayed due to manpower commitments of TMI requirements.

  LUNDVALL, A. E. Baltimore Gas & Electric Co. 79/12/21. 350pp.
- 7912310388 Forwards oversize drawings of Figures 1-11 for fire hazards analysis of fire protoction safety evaluation. Remaining item will be completed by 800111.

  LUNDVALL.A.E. Baltimore Gas & Electric Co. 79/12/27. ip.
- ---7912310431 "Fire Hazards Analysis: Auxiliary Bldg. Elevation (-)8 ft-0 inches, (-)10 ft-0 inches, (-)15 ft-0 inches, Bafe Shutdown Equipments & Raceway Locations." Figure 1.

  \* Baltimore Gas & Electric Co. 79/12/27. 1p.
- --79123;0511 "Fire Hazards Analysis: Containment & Auxiliary Bldg, Unit 2, Elevation 5 ft-0 inches & 10 ft-0 inches, Bafe Shutdown Equipment & Raceway Locations." Figure 4. \* Baltimore Gas & Electric Co. 79/12/27. ip.
- --7912310525 "Fire Hazards Analysis: Containment & Auxiliary Bldg, Unit 2, Elevation 27 ft-0 inches, Safe Shutdown Equipments & Raceway Locations. " Figure 7. \* Baltimore Oas & Electric Co. 79/12/27. ip.
- --7912310530 "Fire Hazards Analysis: Containment & Auxiliary Bldg, Unit 2, Elevation 45 ft-O inches, Safe Shutdown Equipment & Raceway Locations." Figure 8. \* Baltimore Gas & Electric Co. 79/12/27. ip.
- --7912310534 "Fire Hazards Analysis:Containment & Auxiliary Oldg.Unit 2, Elevation 69 ft-O inches.Safe Shutdown Equipment & Raceway Locations." Figure 9. \* Baltimore Gas & Electric Co. 79/12/27. ip.
- --7912310544 "Fire Hazards Analysis: Water Treatment Area, Warehouse & Intake Structure, Unit 2, Safe Shutdown Equipments & Raceway Locations." Figure 11.

  \* Baltimore Oas & Electric Co. 79/12/27. 1p.
- G. Adjudicatory correspondence
- 7912110038 Confirms receipt of encl 790329 petition to suspend OLs for all PWRs. Forwards FR notice indicating that petition will be treated in accordance w/10CFR2.206.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/23. ip.
- ---7912110126 Notice of request for action pursuant to 10CFR2.206 re Environ Coalition on Nuclear Power 790329 petition requesting suspension of all OLs for PMRs. MULER, D. R. Office of Nuclear Reactor Regulation. 79/11/23. 38pp.
- P. Operating license stage documents & correspondence
- 7911090248 "Bummary of Operating Experience W/Recirculating Steam Generators." EISENHUT, D. G. Division of Operating Reactors. NUREO-0523. 79/01/31. 89pp.
- 7912170116 Forwards findings from Nov 1978 "Power Plant Cumulative Environ Impact Rept." List of 12 questions re radicative effluents & spant fuel storage pools encl. WINEGRAD.Q.W. Maryland, State of. 79/11/06. 27pp.
- 7912180057 Notifies of completion of review of steam generator water hammer Approves proposed changes accompanying installation of L tubes. Tubes can effectively minimize likelihood of water hammer events, Safety evaluation encl. LAINAB, Q. Plant Systems Branch. 79/11/07. 2pp.
- --7912180063 Safety evaluation re steam generator water hammer in feedwater sys supporting proposed procedural changes. \* Office of Nuclear Reactor Regulation. 79/11/07. Bpp.
- 7912100189 Discusses NRC 791101 meeting w/representatives of NSSS vendors & fuel suppliers re discussion of respective portions of ECCB evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EISENHUT.D.Q. Division of Operating Reactors. 79/11/09. 65pp.
- --7912100255 Responds to NRC 791101 request re noncompliance of Westinghouse ECCB evaluation model under requirements of 10CFR50 App. K. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants. ANDERBON, T. M. Westinghouse Electric Corp. 79/11/02. 4pp.

- --7912100330 Responds to NRC /91101 request re QRNL cladding swelling & rupture data Review of analytical models & tests indicates compliance w/10CFR30 App K.All GE specs for calculated peak cladding temp remain unchanged.

  BUCHHGLZ.R.H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50. 46 satisfied.

  OMSLEV.G.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/11/02. 5pp.
- --7912100456 Forwards addl info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. OWSLEY. G.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/04. 22pp.
- 7912100422 Forwards safety evaluation re control element assembly guide tube integrity for Cycle 3 operation.
  REID,R. W. Operating Reactors Branch 4, 79/11/19, 2pp.
- --7912100427 Safety evaluation re control element assembly guide tube integrity for Cycle 3 operation. Facility may be operated at licensed power level through Cycle 3.

  # Office of Nuclear Reactor Regulation. 79/11/19. 2pp.
- 7912120262 Summary of 791025 meeting w/C-E owners group re asymmetric LOGA loads. HOSFORD.S.B. Engineering Branch. 79/11/20. 4sp.
- 7912170071 Requests Class III fee re review & approval of Cycle 3 operation w/sleaved guide tubes in fuel assemblies under control element assemblies.
  MILLER.W.O. License Fee Management Branch. 79/11/27. 1p.
- 7912120274 Forwards supplementary response to followup actions resulting from TMI-2 incident re short-term lessons learned regularements. Provides implementation schedule.

  LUNDVALL, A. E. Baltimore Gas & Electric Co. 79/12/05. 3pp.
- 7912310470 Forwards request for add1 info re containment purge sys to complete evaluation of electrical override/bypass aspects.

  LAINAS. 0. Plant Systems Branch. 79/12/04. 3pp.
- 7912120269 Discusses hydraulic snubbers w/common reservairs Replacement of common reservairs w/individual reservairs in progress. Ramaining replacements will be completed during next refueling autage.

  LUNDVALL, A. E. Baltimore Gas & Electric Co. 79/12/07. 3pp.
- 7912190364 Responds to NRC 791107 ltr re requirements for auxiliary feedwater sys. Third pump train will be added to enhance sys. reliability, Project cannot be completed within 1 yr. LUNDVALL.A.E. Baltimore Gas & Electric Cb. 79/12/13. 3pp.
- 7912190403 Bubmits responses to specific items ro containment purging & venting in response to NRC 790927 & 1023 ltrs.Util commits to operation in conformance w/interim position in NRC 791023 ltr. Design review of purge & vent valves performed. LUNDVALL.A.E. Baltimore Gas & Electric Co. 79/12/14. 3pp.
- 7912190497 Responds to followup actions re TMI-2 Lessons Learned Task Force recommendations.Provides interim commitment for coverage of accident assessment function, pending upgrading of operators license holders to senior operators.

  LUNDVALL, A. E. Baltimore Gas & Electric Co. 79/12/14. 2pp.
- 7912270404 Supplements response to TMI Lessons Learned Tosk Force requirements. Add1 info re operator license holders will be added to each shift to provide coverage of accident assessment function.

  LUNDVALL.A. E. Baltimore Gas & Electric Co. 79/12/14. 2pp.
- 7912270416 Provides committment to NRC interim position for purge & vant valve operation pending varification of valve operability under DBA-LOCA loadings Design review indicates valve operation w/adequate shutting torque.

  LUNDVALL, A. E. Baltimore Qas & Electric Co. 79/12/14. Opp.
- 7912280634 Responds to 791106 ltr re effects of radioactive releases into Chesapeake Boy & atmosphere Releases within Tech Specilimit. Specific answers to 12 questions encl.

  DENTON. H. R. Office of Nuclear Reactor Regulation, 79/12/17, 7pp.

- --7912280641 Forwards safety evaluation documenting analysis of potential risks associated w/LNO ship traffic in Chesapeake Bay. Litelihood of LNO accident resulting in significant radioactive release acceptably low.
  REID.R.W. Operating Reactors Branch 4 (Pre 791030). 78/06/13.
  3pp.
- --7912280644 Safety evaluation re likelihood of LNO accident resulting in significant radioactive release.

  # Office of Nuclear Reactor Regulation, 78/06/13, 16pp.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912210319 Forwards IE lnsp Rept 50-318/79-12 on 790924-26. No noncompliance noted. CARLSON.R.T. Region t. Philadelphia, Reactor Construction & Engineering Support Branch. 79/11/01. 2pp.
- --7912210331 IE Insp Rept 50-318/79-12 on 790924-26. No noncompliance noted Major areas inspected:inservice insp activities.

  MALTON.O.A. Region 1. Philadelphia. Office of the Director. TRIPP.L.E. Region 1. Philadelphia. Reactor Construction & Engineering Support Branch. 79/10/31. 3pp.
- 7912310041 Forwards IE Insp Rept 50-318/79-16 on 791015-17 & 23-26. No noncompliance noted.
  BRUNNER.E.J. Region 1, Philadelphia, Roactor Operations Nuclear Support Branch. 79/11/09. 2pp.
- --7912310047 IE Insp Rept 50-318/79-16 on 791015-17 & 23-26. No noncompliance noted Major areas inspected: refueling activities, refueling outage related meint & surveillance activities & surveillance of pipe support & restraint sys. XALMAN.O. Region 1, Philadelphia. Office of the Director. CAPHTON.D. L. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/11/07. Spp.
- 7912050021 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required. ORIER, B.H. Region 1, Philadelphia, Office of the Director. 79/11/14. 1p.
- 7912050230 Forwards IE Info Notice 79-27. "Bteam Generator Tube Ruptures at Two PWR Plants." No response required. ORIER.B.H. Region i, Philadelphia, Office of the Director. 79/11/16. 1p.
- 7912100109 Forwards IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads." No response required. ORIER.B.H. Region i. Philadelphia. Office of the Director. 79/ii/16. ip.
- 7912110394 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Godlant Bys Instrumentation During Operation." No specific action or response required. ORIER.B.H. Region 1, Philadelphia, Office of the Director. 79/11/19. 1p.
- 7912050217 Forwards IE Bulletin 79-26, "Boron Loss From BWR Control Blades." No response required.
  ORIER.B.K. Region i, Philadelphia, Office of the Director.
  79/11/20. ip.
- 7912060365 Forwards IE Circuler 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BHRs." No response required.
  ORIER, B.H. Region i. Philadelphia. Office of the Director.
  79/11/26. 1p.
- 7912110027 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required.
  GRIER.B.H. Region i. Philadelphia. Office of the Director.
  79/11/26. 1p.
- 7912190017 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Written response required. ORIER, B.H. Region i, Philadelphia. Office of the Director. 79/11/30. ip.
- 7912050358 Submits add1 response to IE Bulletin 79-01A.Coils in solenoid actuated unloader valves for MSIV hydraulic sys of both units observed to be environmentally unqualified for existing temp ambient. No safety hazard involved.

  ASH.R.F. Baltimore Gas & Electric Co. 79/12/01. 3pp.
- 7912310205 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, IOCFR21." No action required. ORIER, B.H. Region 1. Philadelphia. Office of the Director. 79/12/06. 1p.

- 7912190731 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Written response required. CRIER, B.M. Region i, Philadelphia, Office of the Director. 79/12/07. ip.
- 7912280010 Responds to IE Bullstin 79-02, Revision 2. "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts."
  Supports using structural shapes attached directly to concrete w/expansion anchors were revis
- 7912280183 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required.
  ORIER.B.H. Region 1, Philadelphia, Office of the Director.
  79/12/13. 1p.
- 7912190571 Bubmits 14-day followup required by IE Bulletins 79-01/01A re nonquelified electrical component. Solenoid valves mfg by Skinner Pracision Industries, Electric Valve Div can satisfy pressure flow & environ requirements, Valves on order. LUNDVALL.A.E. Baltimore Oas & Electric Co. 79/12/14. 2pp.
- 7912260300 Forwards fee for 790711 submittals re control element assembly tube insp program, in response to NRC 791127 ltr. OLBON:R.C.L. Baltimore Oas & Electric Co. 79/12/19. ip.
- R. Periodic operating reports & related correspondence
- 7912310416 Forwards monthly operating repts for Nov 1979. MERSON.S.D. Baltimore Gas & Electric Co. 79/12/13. 1p.
- --7912310418 Monthly operating repts for Nov 1979. MERSON, B. D. Baltimore Cas & Electric Co. 79/12/13. 15pp.
- 7912280523 Forwards monthly operating rept for Nov 1979. MERSON B. D. Baltimore Gas & Electric Co. 79/12/19. ip.
- --7912280527 Monthly operating rept for Nov 1979.
  MERSON, B. D. Baltimore Gas & Electric Co. 79/12/19. 1p.
- 8. Reportable occurrences, LERs & related correspondence
- 7912210276 Submits nonroutine radiological environ operating rept re analysis of dyster samples for gamma-omitting radionuclides. Samples showed very small fractions of allowable doses. BTOUT.J.W. Baltimore Gas & Electric Co. 79/12/18, 1p.
- DOCKET 50-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2 F. Security, medical, emergency & fire protection plant
- 791228041B Informs that measures needed to reduce amount of slippage in schedule re fire door mod. Requests that schedule be implemented no later than mid-Dec 1979. COLLING. J. T. THI-2 Operations/Support. 79/11/21. 2pp.
- 7712200022 Discusses NRC 771109 meeting re emergency preparedness team review objectives. Provides guidance for improving licensee emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.

  QRIMES, B. K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- 7912030170 Forwards physical security plan addendum Addendum withheld (ref 10CFR2, 790).

  HERBEIN, J. G. Metropolitan Edison Co. 79/11/27. 1p.
- 7912070136 Forwards Revision 6A to modified amended physical security plan Revision withheld (ref 100FR2,790).
  HERBEIN, J. G. Metropolitan Edison Co. 79/11/30. ip.
- Q. Adjudicatory correspondence
- 7912110043 Forwards comments on NUREG-0511. Draft 9E18 reflects conscious & deliberate NRC policy to jeopardize public health & safety & thwart objectives of NEPA. KEPFORD, C. Environmental Coalition on Nuclear Power. 79/10/24. 22pp.
- 7912280463 Requests granting of Busquehanna Vailey Alliance 791105 patition to intervene & request for hearing Patitioners must demonstrate requisite interest & effect of proceedings on interest Cerbificate of Svc encl.

  CHANDLER, L. J. Hearing Branch 1. 79/11/14. 5pp.

- 7912040075 Notice of special prehearing conference on Busquehanna Valley Alliance 791105 petition to intervene & request for hearing. Conference will commence 791206 in Harrisburg. PA. Precise location to be announced.
  MILLER. M. E. Atomic Safety and Licensing Board Panel. 79/11/15. 4pg.
- 7912040079 Suppl to 791115 notice of special prehearing conference on Busquehanna Vallay Alliance 791105 petition to intervene & request for hearing. Conference will take place in Hearing Room 1 of State North DFC Bldg in Harrisburg.Pa.

  MILLER, M. E. Atomic Bafety and Licensing Board Penel. 79/11/20. ip.
- 7912110038 Confirms receipt of encl 790329 petition to suspend OLs for all PMRs. Forwards FR notice indicating that petition will be treated in accordance w/100FR2.206.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/23. 1p.
- --7912110126 Notice of request for action pursuant to 10CFR2.206 re Environ Coalition on Nuclear Power 790329 petition requesting suspension of all OLs for PHRs. HULLER, D.R. Office of Nuclear Reactor Regulation. 79/11/23, 38pp.
- 7912070170 Joint motion to indefinitely postpone 791206 special prehearing conference scheduled in ASLB 791115 notice. Efforts to reach agreement are underway. Certificate of sycenci.
  CHANDLER, L. J. Hearing Branch 1. 79/11/28. 2pp.
- 7912280310 Order denying NRC 791128 joint motion to postpone 791206 special prehearing conference. Public interest & interest of parties will be served by expeditious hearing. HILLER, M.E. Atomic Safety and Licensing Board Panel. 79/11/29. 368.
- 7912280456 Joint motion for order terminating proceedings, Susquehanna Valley Alliance withdraws 791105 patition to intervene & request for hearing. No other party requested hearing.
  BELKOWITZ.L. B. Susquehanna Alliance. SELKOWITZ.L.B. Widoff, Reager, Selkowitz & Adler. BAXTER.T.A. Metropolitan Edison Co. 79/11/30. 2pp.
- --7912280459 Agreement that NRC 791016 memorandum & order is final for purposes of judicial review & that order is reviewable by Busquehanna Valley Alliance. Certificate of Svc encl. SLAP.A. Busquehanna Alliance. SLAP.A. Public Interest Law Center of Philadelphia. CHARNOFF. 9. Metropolitan Edison Co. 79/11/29. 3pp.
- 7912280537 Opposes nuclear power, Suggests use of coal & U for energy, MLIE,T. Affiliation Unknown. 79/11/30. 2pp.
- 7912190530 Responds to 790726 ltr requesting deferment of all licensing of nuclear power plants until all facts known about TMI. New plants will not be licensed until criteria developed, implementing new safety objectives.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/12/03. Ip.
- ---79080606 Opposes proliferation of US nuclear power plants. Requests that licensing be deferred until TMI studies are complete. MILNS.M.C. Affiliation Unknown. 79/07/29.
- 7912190393 Submits testicies of ringnack pheasant to support concerns that radiation from TMI affected wildlife reproductive organs & vegstation in valley. Nuclear activity must cease immediately regardless of need for power, HOLOHKRA.P. Affiliation Unknown. 79/12/14. 2pp.

- 7909180006 Responds to 790417 ltr. Suggests combining nuclear plants w/other energy sys. Combined sys are not currently practical for nuclear power plants.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/08/20. 1p.
- ~~7909180007 Suggests combining nuclear plants w/other energy sys, HAIG, D. A. Affiliation Unknown. 79/04/17, 1p.
- 7912280466 Forwards Commission 790815 info paper describing TMI-2 program for shipments of radioactive solid waste, H/o and, COLLINS, J. T. TMI-2 Operations/Support, 79/10/22, 3pp.
- 7912040060 Responds to request for water chamistry analysis. Analysis will be sant upon completion by licenses. GOLLING. J. T. THI-2 Operations/Support, 79/10/23. ip.

- 7912040101 Provides designations for NRC trailers Bnly one box needed. Bhould be attached to Trailer 1 & designated NRC. COLLINS.J.T. TMI-2 Operations/Support. 79/10/23. 1p.
- 7912040063 Requests site access for representatives of IAEA. COLLING.J.T. TMI-2 Operations/Support. 79/10/31. 2pp.
- 7912140534 Requests info re release of radwaste water into Susquehanna River & comments on dangers of possible radwaste pollution. BEYER, J. M. New Jersey, State of. 79/11/06. 1p.
- 7912040094 Comments by Mental Health Association in PA on encl news article: area residents' mental health should be primary consideration in decision to restart TML Supporting articles encl. THOMAS.C.D. Affiliation Unknown. 79/11/09. 9pp.
- 7912040099 Comments by Tri-County Mental Health Association on encl news articls. "Psychological distress" issue should be considered before TMI-1 reactivation. TURNER, J. A. Affiliation Unknown. 79/11/09. 3pp.
- 7912040151 Expresses appreciation for compliments on presentation at PA Obvernor safety conference. Will make presentation at Dec tri-section meeting of American Industrial Hygiene Association.

  VDLLMER, R. H. TMI-2 Operations/Bupport. 79/11/14. ip.
- --7912040158 Requests participation in 791207 tri-section meeting of American Industrial Hygiene Association. Presentation of problem associated w/low level radiation exposure would be appropriate.

  BTRINGER, B. M. American Industrial Hygiene Association. 79/10/02.
- 7912310554 Responds to 791109 request on behalf of League of Women Voters for documents re NRC & TMI location description of NRC TLDs.including approx bearings & distance from TMI. W/o encl.

  COLLINS.J.T. TMI-2 Operations/Support. 79/11/16. 1p.
- 7912310555 Responds to 791109 request on behalf of League of Women Voters for documents re NRC & TMI-2 Forwards location description of NRC TLDs including approx bearings & distance from TMI. W/o encl.

  COLLING. J. T. TMI-2 Operations/Support. 79/11/16. 1p.
- 7912280344 Expresses concern on behalf on Lancaster Branch of American Association of Univ Women.re ramifications of TMI accident on health & safety of community Urges NRC to keep informed of issues & consider public concerns. JCHNBTON.P.Q. Affiliation Unknown. 79/11/20. ip.
- 7912040085 Forwards response to 790527 questions re TMI leak rates, internal temps & iddine concentrations.

  VOLLMER, R. H. TMI-2 Operations/Support. 79/11/23, 3pp.
- --7912040092 Requests info re TMI leak rates, internal temps & iodine concentrations.

  LEWIS, M. I. Affiliation Unknown. 79/05/27. 1p.
- 7912170094 Comments on 791005 ltr re nuclear facility accidents. Suggests changes to encl.NRC proposing regulatory changes in planning requirements. Suggests no action re ltr be taken until proposed changes acted upon. COLLINS.H.E. Office of State Programs. 79/11/23. ip.
- 7912280359 Requests meeting in MD w/selected officials & citizens refuture disposal of decontaminated water Origining decontamination of TMI water is concern of people who reside downstream from facility.
  RILEY.C. I. Maryland, State of 79/11/23. 2pp.
- 7912040334 Expresses concern re request to vent radioactive kypton into atmosphere. Urges NRC to stop permitting release of hazardous metls into atmosphere & consider burial. STEVENBON, A. C. Affiliation Unknown. 79/11/30. 1p.
- 7912280244 Ack receipt of remarks re accident at TMI-2. Forwards info re events that occurred at TMI-2.

  DENTON, H. R., Office of Nuclear Reactor Regulation. 79/11/30. 2pp.
- --7912280268 Comments on TMI-2 accident adventages of nuclear power exceed risks.
  KANNAZZIOI, N. Affiliation Unknown. 79/11/30. 2pp.
- 7912280274 Ack receipt of remarks re-accident at TMI-2. Forwards info reevents that occurred at TMI-2. H/o encl. DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/30. 2pp.

- --7912280279 Comments on TMI-2 accident: organized plan for evacuation is needed.
  CALCAGNO.L. Affiliation Unknown. 79/11/30. 2pp.
- 791228028B Ack receipt of remarks re accident at TMI-2. Forwards info re events that occurred at TMI-2. W/o encl.
  DENTON.H. R. Office of Nuclear Reactor Regulation. 79/11/30. 2pp.
- ---7012280293 Comments on TMI-2 accident: radiation leak at facility imperiled lives of local citizens.
  DICA:F. Affiliation Unknown. 79/11/30. 3pp.
- 7912280278 Ack receipt of remarks re accident at TMI-2. Forwards info re events that occurred at TMI-2. W/o encl.
  DENTON. H. R. Office of Nuclear Reactor Regulation. 79/11/30. 2pp.
- --7912280304 Comments on TMI+2 accident: federal reactor inspectors must be placed permanently at all plants. Safety equipment key stoom valve settings & ECCS operation must be checked. CROKE.D. Affiliation Unknown. 79/11/30. 3pp.
- 7912280309 Ack receipt of remarks relatcident at TMI-2. Forwards info relevents that occurred at TMI-2. W/o encl.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/30. 2pp.
- ---7912280316 Comments on TMI-2 accident: nuclear power is only way to ensure economic future.
  BRODMAN, R. Affiliation Unknown. 79/11/30. 2pp.
- 7912280320 Act receipt of remarks re accident at TMI-2. Forwards info re events that occurred at TMI-2. W/o encl. DENTON.H.R. Office of Nuclear Reactor Regulation. 79/11/30. 2pp.
- --79122B0321 Comments on TMI-2 accident: nuclear plants are dangerous. Local citizens need prompt notification of potential nuclear incident. KUMP.R. Affiliation Unknown. 79/11/30. 2pp.
- 7912280326 Ack receipt of remarks re accident at TMI-2. Forwards info re events that occurred at TMI-2. N/o encl.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/30. 2pp.
- --7912280328 Comments on TMI-2 accident: NRC should supervise plante more carefully Supports use of nuclear energy.
  DRUMMOND, L. Affiliation Uninown. 79/11/30. 2pp.
- 7912280332 Ack receipt of remarks re accident at TMI-2. Forwards info re events that occurred at TMI-2. W/o encl.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/30. 2pp.
- ---7912280337 Comments on TMI-2 accident:close nuclear plants in PA. Nuclear energy is dangerous & threatens lives of local citizens. BETRLACOUE, A.M. Affiliation Unknown. 79/11/30. 2pp.
- 7912280340 Ack receipt of remarks re accident at TMI-2. Forwards info re events that occurred at TMI-2. W/o encl. DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/30. 2pp.
- --7912280348 Comments on TMI-2 accident: nuclear energy answers important part of matl energy needs, until alternate means of energy production can be utilized.
  ROLTE.B. Affiliation Unknown. 79/11/30. lp.
- 7912280353 Ack receipt of remarks re accident at TMI-2. Forwards info re events that occurred at TMI-2. W/o encl.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/30. 1p.
- --7912280361 Comments on TMI-2 accident radiation release contaminated food & milk in area of facility Citizens experienced psychological distress Citizens require prompt notification of potential nuclear incident.

  SEILLA: A. Affiliation Unknown. 79/11/30. 3pp.
- 7912280367 Act receipt of remarks re accident at TMI-2.Forwards info re events that occurred at TMI-2.W/o encl. DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/30. 2pp.
- --7912280373 Commants on TMI-2 accident radioactive chemicals released from facility frightened & endangered lives of citizens. CALVARUSO, G. Affiliation Unknown, 79/11/30. 29p.
- 7912280378 Ack receipt of remarks re accident at TMI-2. Forwards info re events that occurred at TMI-2. M/o encl.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/30. Epp.

- --7912280385 Comments on TMI-2 accident: close TMI-2 until offects of 790328 incident are thoroughly understood.

  DUMBLETON.D. Affiliation Unknown. 79/11/30. 2pp.
- 7912280388 Ack receipt of remarks to accident at TM1-2.Forwards info re events that occurred at TM1-2.W/o encl. DENTON.H.R. Office of Nuclear Reactor Regulation. 79/i1/30. 2pp.
- --7912200393 Comments on TMI-2 accident: requests accurate info re effects of radiation released during 790320 incident. ABUILA, N. M. Affiliation Unknown. 79/11/30. 4pp.
- 7912280399 Ack receipt of remarks re accident at TMI-2. Forwards info re events that occurred at TMI-2. W/o encl.
  DENFON, H. R. Office of Nuclear Reactor Regulation. 79/11/30. 2pp.
- --7912280410 Comments on TMI-2 accident shut down nuclear plants. GERDLD.C. Affiliation Unknown. 79/11/30. 5pp.
- 7912280415 Ack receipt of remarks re-accident at TMI-2. Forwards info reevents that occurred at TMI-2. W/o encl. DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/30. 1p.
- --7912280422 Comments on nuclear power: local citizens should be promptly notified of potential nuclear incident.
  VIZZINI.J. Affiliation Unknown. 79/11/30. 3pp.
- 7912280433 Ack receipt of remarks re accident at TMI-2. Forwards info re events that occurred at TMI-2.W/o encl.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/30. 2pp.
- --7912280439 Comments on TMI accident: all plants w/similar design defects should be closed. RUPPE, L. Affiliation Unknown. 79/11/30. 2pp.
- 7912280845 Ack receipt of remarks re accident at TMI-2. Forwards info re events that occurred at TMI-2. W/o encl. DENTON.H.R. Office of Nuclear Reactor Regulation. 79/11/30. 2pp.
- --79122B0449 Comments on nuclear energy:important to determine sequence of events at TMI-2.
  BCIRTING.A. Affiliation Unknown. 79/11/30. 2pp.
- 7912280492 Ack receipt of remarks re accident at TMI-2. Forwards info re events that occurred at TMI-2. W/o encl. DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/30. ip.
- --7912280454 Comments on nuclear power: essential part of energy, Local citizens require prompt notification of nuclear incident. FITZSIMMONS, K. Affiliation Unknown. 79/11/30. 2pp.
- 7912280457 Ack receipt of remarks re accident at TMI-2. Forwards info re events that occurred at TMI-2. W/o encl. BENTON. H. R. Office of Nuclear Reactor Regulation. 79/11/30. lp.
- --7912280458 Comments on nuclear power:complex & dangerous technology whose full implications are unknown.

  BAUMANN.C. Affiliation Unknown. 79/11/30. 2pp.
- 7912280460 Ack receipt of remarks re-accident at TMI-2. Forwards info re events that occurred at TMI-2. W/o encl. DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/30. 2pp.
- ---7912280461 Comments on 790328 incident: facility should be shut down-Local citizens require prompt notification of nuclear incident. DUSCEMI.O. Affiliation Unknown. 79/11/30. 3pp.
- 7912280462 Ack receipt of remarks re accident at TMI-2. Forwards info re events that occurred at TMI-2. W/o encl.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/30. 2pp.
- ---7912280465 Comments on nuclear power: major source of energy for world.

  Nuclear energy has caused no loss of life & little
  damage to environ.

  HLOWATY.R. Affillation Unknown. 79/11/30. 2pp.
- 7912280468 Ack receipt of remarks re accident at TMI-2. Forwards info reevents that occurred at TMI-2. DENTON.H.R. Office of Nuclear Reactor Regulation. 79/11/30. ip.
- ---79122B0470 Comments on nuclear power: nuclear plants can be safe. Design criteria must be thoroughly evaluated & operators properly trained.
  CAMPBELL, P. Affiliation Unknown. 79/11/30. 3pp.

- 7912280472 Ack receipt of remarks re accident at TMI-2.Forwards info re events that occurred at TMI-2.W/o encl.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/30. 1p.
- --7912280476 Discusses good & bad points of nuclear power. Suggests shutdown & inap of all plants designed like TMI.
  RAMA,E. Affiliation Unknown. 79/04/09. 1p.
- 7912280478 Ack receipt of remarks re accident at TMI-2.Forwards info re events that occurred at TMI-2.W/o encl.
  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/11/30. 2pp.
- --7912280480 Discusses Senate Health Subcommittee attempts to determine radiation levels from 790328 incident Requests info re NRC attempt to determine radiation levels & views on safety of nuclear energy.

  QAZDAO,L. Affiliation Unknown. 79/11/30. 3pp.
- 7912280481 Ack receipt of remarks re accident at TMI-2. Forwards info re events that occurred at TMI-2. W/o encl.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/30. 2pp.
- --7912280482 Bupports use & development of nuclear energy.NRC must issue stricter regulations re design & siting criteria of nuclear facilities.

  GANNON.J. Affiliation Unknown. 79/11/30. 2pp.
- 7912280484 Ack receipt of remarks re accident at TMI-2. Forwards info re syents that occurred at TMI-2. W/o encl.
  DENTON: H. R. Office of Nuclear Reactor Regulation. 79/11/30. ip.
- --79122804B7 Suggests that nuclear power be used until more efficient & less expensive method of harnessing power for electricity is developed.

  LIOTTAIR. Affiliation Unknown. 79/11/30. 2pp.
- 79122B05iO Ack receipt of remarks re accident at TMI-2.Forwards info re events that occurred at TMI-2.W/o encl.
  DENTON,H.R. Office of Nuclear Reactor Regulation. 79/11/30. 2pp.
- --7912280314 Suggests that safer & more reliable source of energy be found. RAUSCHENBACH.P. Affiliation Unknown. 79/11/30, 3pp.
- 7912280514 Ack receipt of remarks re accident at TMI-2 Forwards info re events that occurred at TMI-2.

  DENTON, H. R. Diffice of Nuclear Reactor Regulation. 79/11/30. App.
- --7912280530 Approves of nuclear power Recommends that nuclear power be regulated in stringent manner & numerous safeguards be required. BCHAEFER K. Affiliation Unknown. 79/11/30. 4pp.
- 7712280534 Ack receipt of remarks re accident at TMI-2. Forwards info re events that occurred at TMI-2.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/30. 2pp.
- 7912280543 Ack receipt of remarks re accident at TMI-2.Forwards info re events that occurred at TMI-2.W/o encl. DENTON, H. R. Diffice of Nuclear Reactor Regulation. 79/11/30. 2pp.
- --7912280951 Believes that nuclear energy exposes citizens to unnecessary risks. Oovt not capable of using nuclear energy in safe way.

  KNOLL.M. Affiliation Unknown. 79/11/30. 1p.
- 7912280553 Ack receipt of remarks re accident at TMI-2. Forwards info re events that occurred at TMI-2. W/o encl.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/30. 2pp.
- ---7912280958 Comments on accident at TMI-2: other plants should take precautions to prevent similar occurrences.

  GANDER.S. Affiliation Unknown, 79/11/30. 2pp.
- 7912100341 Forwards updated avc distribution list for correspondence. Original copy of correspondence should be sent to new address.

  ARNOLD, R. C. Metropolitan Edison Co. 79/12/04. App.
- 7912180521 Forwards updated svc copy distribution list for facility. ARNOLD, R. C. Metropolitan Edison Co. 79/12/04. 4pp.
- 7912210035 Requests that no radioactive gases be released from facility. Radioactivity will lower productivity of farmland & contaminate produce.

  EWINGS.J. Affiliation Unknown. 79/12/05. 1p.

- 7912200406 Notifies that 790907 draft rept prepared for CEG circulated to federal officials & within NRC.HR Denton ltr to CEO encl. M/o encl. RYAN.R.O. Office of State Programs. 79/12/07. Ip.
- 7912200061 Responds to 790411 ltr re TMI.Discusses availability of NRC repts re TMI.Forwards summaries of NUREO-0600 & NUREO-0558.

  DENTON,H.R. Office of Nuclear Reactor Regulation. 79/12/10. 2pp.
- --7912200064 Requests info re TMI & safety of nuclear energy. KOCH.W. Affiliation Unknown. 79/04/11. 1p.
- 7912310240 Forwards documents re changes in regulation of nuclear power plants resulting from studies of TMI incident in response to 791008 ltr. H/a encl.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/12/14. 1p.
- --7912310247 Ack receipt of 791008 ltr re nuclear gower regulation & control. Nuclear power environmentally acceptable & among safest methods available to generate large amounts of electrical energy. Ltr to President Carter encl.
  PREGSEGKY, A. J. Energy, Dapt of 79/11/23. App.
- 7912310234 Discusses questions raised by TMI-2 accident re adequacy of GA requirements for design, const & operation of plants.
  Requests first & second tier documents that describe overall philosophy & requirements for agency GA program.
  HAAGS, M. P. Quality Assurance Branch. 79/12/18. ig.
- --7912310243 Discusses questions raised by TMI-2 accident re adequacy of OA requirements for design, const & operation of plants.
  Requests first & second tier documents describing overall philosophy & requirements for agency OA program.
  HAASS.W.P. Quality Assurance Branch. 79/12/18. ip.
- --7912310261 Discusses questions raised by TMI-2 accident re adequacy of OA requirements for design, const & operation of plants.
  Requests first & second tier documents that describe overall philosophy & requirements for agency OA program.
  HAASS,W.P. Quality Assurance Branch. 79/12/18. 1g.
- --7912310257 Discusses questions raised by TM1-2 accident re adequacy of GA requirements for design const & operation of plants.
  Requests first & second tier documents that describe overall philosophy & requirements for agency GA program.
  HAASS.W.P. Quality Assurance Branch. 79/12/18. 1p.
- ---7912310258 Discusses questions raised by TMI-2 accident re adequacy of GA requirements for design const & operation of plants.

  Requests first & second tier documents that describe overall philosophy & requirements for agency GA program.

  HANSG.W.P. Quality Assurance Branch. 79/12/18. 1p.
- J. Insurance & indomnity information
- 7908290534 Forwards summary of paid loss & loss expense as described in telcon.
  MARRANE J. American Nuclear Insurers. 79/08/23, 4pp.
- P. Operating license stage documents & correspondence
- 7911090248 "Summary of Operating Experience W/Recirculating Steam Generators." EISENHUT.D.O. Division of Operating Reactors. NUREG-0523, 79/01/31. 89pp.
- 7908220421 Forwards info fulfilling requirements described in 790725 deposition.
  NOVAK.T.M. Reactor Sustems Branch. 79/08/06. ip.
- 7912040084 Forwards SECY-79-490. COLLINS.J.T. TMI-2 Operations/Support. 79/10/82. 1p.
- --7912040086 Informs Commission of planned shipments of solid radwasts.
  Program procedures & checklist for shipments encl.
  DENTON.H.R. Office of Nuclear Reactor Regulation, SECY-79-490, 79/08/15. 13pp.
- 7912040095 Requests detailed analysis for justification of averaging technique for in-core thermocouples temps.
  CDLLING.J. T. TMI-2 Operations/Bupport. 79/10/22. 1p.
- 7912040122 Forwards NUREO-0585, "TMI-2 Lessons Learned Task Force, Final Rept."
  MATTSON, R. J. TMI-2 Lessons Learned Task Force. 79/10/22, ip.

- 7912040077 Responds to 791009 request for comments on design criteria for evaporator solidification facility. Inquires why sys is limited to use only 55-gallon drums.
  COLLING. J. T. THI-2 Operations/Support. 79/10/23. 2pp.
- 79:2040116 Discusses meeting on review & approval of TMI recovery operation procedures. No further meetings on topic required. NRC inspectors will monitor progress on resolution of outstanding items.
  CDLLING.J.T. TMI-2 Operations/Support. 79/10/23. 2pp.
- 7911160314 Forwards math presented at 791017 meeting w/util in Middletown.PA re TMI-1 restart rept. VDGLEWEDE, J. C. Core Performance Branch. 79/10/29. 7pp.
- 7912040096 Notification of 791108 meeting w/Met Ed & General Public
  Utils Svc Corp in Bethesda.MD to discuss proposed plans for
  disposal of Kr-85.
  VDLLMER, R. H. TMI-2 Operations/Support. 79/10/29. 3pp.
- 7912040107 Forwards printout from which most probable cumulative dose was derived. Input TLD data for upper & lower bound calculations enci. EISENHAUER,C. Commerce, Dept. of, National Bureau of Standards. 79/10/29. 50pp.
- 7912070006 "Rept of The President's Commission on The Accident At THI: The Newd for Change The Legacy of TMI." KEMENY, J. C. President's Commission on the Accident at Three Mile Island. 79/10/30. 209pp.
- 7912040073 Requests engineering evaluation of once-through steam generator level due to 791012 RCS & steam plant parameter deviations. Transient effects on RCS loop flow & differential temp should also be evaluated.

  COLLING.J.T. TMI-2 Operations/Support. 79/11/05. 2pp.
- 7912040056 Requests engineering evaluation of once through steam generator level due to 791012 RCS & steam plant parameter deviations. Transfent effects on RCB loop flow & differential tamp should also be evaluated.

  CDLLINS.J.T. TMI-2 Operations/Support. 79/11/08. 2pp.
- 7912130184 Forwards summary of Teknekron Research, Inc study of licenses regulatory performance evaluation to Teknekron draft rept resperating reactors w/B&W nuclear steam supply sys. Requests comments. W/o enci.
  STELLO, Office of Inspection & Enforcement, Office of the Director. 79/11/08. 2pp.
- 7912030067 Requests documentation identified in Items 1-6 of 790822 memo committing to extensive QA & QC of MDHR sys.Also requests notification when welds have been finished & hydrostatic & startup test procedures have been submitted. COLLINS, J. T. TMI-2 Operations/Support. 79/11/09, 2pp.
- 7912100189 Discusses NRC 791101 meeting w/representatives of NSSS vendors & fuel suppliers re-discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EISENHUT. D. G., Division of Operating Reactors. 79/11/09. 60pp.
- --7912100255 Responds to NRC 791101 request re noncompliance of Wastinghouse ECCS evaluation model under requirements of 10CFR50 App K. Evaluation of three fuel rod models indicates no safety problems for Wastinghouse plants. ANDERSON. T.M. Westinghouse Electric Corp. 79/11/02. App.
- --7912100330 Responds to NRC 791101 request re DRNL cladding swelling & rupture data. Review of analytical models & tests indicates compilance w/1005R50 App K. All GE specs for calculated peak cladding temp remain unchanged.
  BUCHHOLZ.R.H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of IOCFE50. 46 satisfied.
  OMELEY.Q.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/11/02. 5pp.
- --79:2100456 Forwards addl info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. OHBLEY, G.F. Exxon Nuclear Go., Inc. (subs. of Exxon Corp.). 79/11/04. 22pp.
- 79:2280380 "Preliminary Analysis & Views of NRC on Recommendations of President's Communission on Accident at TMI."

  \* Commission. 79/11/09. 33pp.

- ---7912280397 Responds to request for reaction to Kemeny rept.Rept does not stress enough that equipment could have been designed to avoid trouble.Rept is helpful on general level & less helpful on specific issues.

  GILINSKY.V. Commission. 79/11/09. 3pp.
- --7912280406 Concurs w/NRC response to 791106 request for views on recommendations of President's Commission on Accident at THI. Separate views encl. BRADFORD, P. A. Commission. 79/11/09. 9pp.
- 7912280336 Requests addl info to complete draft safety evaluation on TMI-1 restart. Addl info includes design features, solid radwaste & sump pumping & sampling procedure.

  LEE.J. T. TMI-2 Operations/Support. 79/11/14. 2pp.
- 7912280351 Requests util plans for accurately quantifying oxygen concentration of RCS within 15 days. Info needed to varify chemistry control program will accurately predict corrosive activity of primary coolant.

  CDLLINS.J. T. TMI-2 Operations/Support. 79/11/15. 3pp.
- 7712280362 Discusses timeliness of opening Dacay Heat Valves (DHV) 1 & 171. Premature opening of DHV 1 & DHV 171 would not be consistent w/ALARA principles re maint being performed in DHV 3 area.

  COLLING. J. T. TMI-2 Operations/Support. 79/11/18. App.
- 7912040104 Forwards technical evaluation summary of winterization requirements for temporary solid waste staging facility. External heat source for liners unnecessary. DEVINE, J. C., WILSON.R.F. General Public Utilities OPU Service Corp. 79/11/17. 14pp.
- 7912040136 Forwards NRC 791018 order for mod of license, Tech Specs & negative declaration re use of EPICOR-II sys for decontamination of intermediate level radwaste water at TMI-2.
  VDLLMER.R. H. TMI-2 Operations/Support. 79/11/19. 1p.
- --7912040148 Order for mod of license to add EPICOR-II discharge paths to Tach Specs Hearing may be requested within 20 days.
  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/10/18. Spp.
- --7912040150 Tech Specs amending DL for EPICOR-II & wastewater storage. \* Metropolitan Edison Co. 79/10/18. Spp.
- 7912280369 Notifies that no longer necessary to make redundant notifications due to realignment of NRC personnel. Organizational chart and COLLING.J.T. TMI-2 Operations/Support. 79/11/19. App.
- 7912280453 Ack receipt of 791107 ltr reaffirming that all HEPA filters go to DDE filter testing station prior to use in facilities. Recognizes that vendors test filters in accordance w/MIL-F-51068 & MIL 8TD-282. COLLINS, J. T. THI-2 Operations/Support. 79/11/19. 1p.
- 7912040083 Statement of policy & notice of intent to prepare programmatic EIS Statement will provide overall study of decontamination disposel process. CHILK.S. J. Office of the Secretary of the Commission. 79/11/21.
- 7912040100 Responds to telegram re release of Kr-B5.NRC evaluation of anviron impact will precede any radioactive release. Forwards environ assessment of use of EPICOR-II. W/o encl. VOLLMER.R. H. Assistant Director for Bystems & Projects. 79/11/23.
- 7912280430 Ack receipt of draft radiation protection plan for TMI-2. Comments withheld panding 791128 final rept. Assumes that document addressing TMI-1 will also be submitted on 791129. COLLING.J.T. TMI-2 Operations/Support. 79/11/23. ip.
- --7912280437 Forwards draft radiation protection plan vs 791119 discussion. Requests comments. Final document will be submitted on 791128. HEWARD, R. W. Metropolitan Edison Co. 79/11/21. 22pp.
- 7912280444 Forwards evaluation of consequences of depressurizing RCS, using hydrogen gas vol that exists in control rod drive mechanism region of reactor vessel.

  COLLINS.J.T. THI-2 Operations/Support. 79/11/23. ip.

- 7912310446 Responds to NRC 791012 ltr to JQ Herbein re natural circulation operation procedures. Agrees that 20 gpm fill rate limit inadequate & will add section to Procedure R-2-79-045. Hemo will be issued on turbine bypass valve.
  WILBON.R.F. General Public Utilities QPU Service Corp. 79/11/27.499.
- 7912280324 Requests approved version of "Technical Plan for THI-2 Recovery" & estimated schedule for decontamination effort up to & including fuel removal & RCS decontamination.
  VOLLMER.R. H. TMI-2 Operations/Support. 79711729. Spp.
- 7912120401 Forwards updated svc distribution list.Notifies of address change for original correspondence.
  ARNOLD, R. C. Metropolitan Edison Co. 79/12/04, 4pp.
- 7912130435 Forwards radiation protection plan.Plan will be Chapter 1 of Radiological Controls Procedure Manual.Radiation plan for Unit 1 will be part of restart submittal.
  ARNOLD:R.C. Metropolitan Edison Co. 79/12/07. lp.
- ---7912130441 Radiation protection plan. HEWARD, R. H. i ARNOLD, R. G. Matropolitan Edison Co. 79/12/07. 18pp.
- 7912180483 Forwards draft "Organization Plan," as discussed 791210 w/ D Brinkman. Also forwards suggested change page to proposed recovery Tech Specs, Section 6.0, WILBON, R. F. Metropolitan Edison Co. 79/12/11. 1p.
- --7912180491 "Organization Plan." \* Metropolitan Edison Co. 79/12/11. 4pp.
- --7912180492 Buggested change page to proposed recovery Tech Specs. Bection 6.0. # Metropolitan Edison Co. 79/12/11. ip.
- 7912270202 "Summary Technical Plan for TMI-2 Decontamination & Defueling."

  \* Metropolitan Edison Co. 79/12/12. Dipp.
- 7912180428 Forwards justification for reducing min borsted water storage tank vol from 350,000 to 100,00 gallons. Requests that tank be drained to within allowable limits & that EPICOR-II processed & borated water be used to fill tank. WILSON, R. F. Hetropolitan Edison Co. 79/12/19. 4pp.
- 7912270249 Forwards mode to proposed Tech Specs re efficient operation of plant operations review committee during recovery.
  WILBON, R. F. Metropolitan Edison Co. 79/12/20. 1p.
- --7912270253 Mode to Section 6 of proposed Tech Spece for plant operations review committee.

   Metropolitan Edison Co. 79/12/20. 3pp.
- 7912270343 States intention of releasing six storage cells on 791221 to hold anticipated EPICOR-II resin. Conditions outlined: cell drains & drain sys line into sump to be plugged & Rm-16 portable radiation alara unit to be installed in sump. WILBON, R. F. Metropolitan Edison Co. 79/12/20. 4pp.
- 7912280599 Forwards schedule info for recovery program repts requested by NRC 791203 ltr.
  WILBON, R. F. Metropolitan Edison Co. 79/12/21. 4pp.
- G. Inspection reports. IE Bulletins & correspondence
- 7912280284 Forwards combined IE Insp Repts 50-289/79-17 & 50-320/79-19 on 790747-19. No noncompliance noted.

  CARLEON.R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Stanch. 79709/26. 2pp.
- ---7912260301 IE Insp Repts 30-289/79-17 & 50-320/79-19 on 790717-19. No noncompliance noted Major areas inspected: fire prevention & protection program, outstanding items in area of fire protection & control room panel electrical fire. KOLTAY.P. CHAUDHARY.S.K. Region i, Philadelphia, Office of the Director. EDNETER.S.D. Region i, Philadelphia, Reactor Construction & Engineering Support Branch. 79/09/26. 3pp.
- 7912040166 Forwards IE Insp Repts 50-289/79-18 & 50-220/79-22 on 790718-0814. GRIER, B. H. Region 1, Philadelphia, Office of the Director, 79/10/01, 2pp.

- --7912040179 IE Insp Repts 50-289/79-18 & 50-320/79-22. Noncompliance noted: uncontrolled high radiation areas, failure to use breathing air sys properly & improper calibr of equipment used to measure airborne concentrations.

  CHOCKER, H. W., HAVERKAMP, D. R., NEELY, D. R. Region 1, Philadelphia, Office of the Director. 79/09/18. 38pp.
- 7912280330 Forwards IE Insp Rapt 50-320/79-24 on 790905-06. No noncompliance noted. CARLSON.R.T. Region i. Philadelphia, Reactor Construction & Engineering Support Branch. 79/10/12. 2pp.
- --7912280342 IE Insp Rept 50-320/79-24 on 790905-06. No noncompliance note. Major area inspected: fabrication & testing of mini-decay heat removal sys.
  WALTON: G. Region 1. Philadelphia. Office of the Director.
  TRIPP.L. Region 1. Philadelphia. Reactor Construction & Engineering Support Branch. 79/10/09. 3pp.
- 7918280379 Forwards IE Insp Rept 50-320/79-18 on 790705-06 & i1-13. No noncompliance noted. CARLSON.R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/10/19. 2pp.
- --7912280392 IE Insp Rept 50-320/79-18 on 790705-06 & 11-13. No noncompliance noted Major areas inspected:mods of various sys to provide long-term cooling of reactor core & activities re mods under emergency conditions.

  JERNIGAN.E.P. Region 1, Philadelphia, Diffice of the Director. TRIPP, L. E. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/10/18. 5pp.
- 7912040131 Forwards special insprepts to SC Dept of Health. Aug 1979, NRC conducted special insprept Nuclear Engineering Coburial sites in States of HA & NV to observe arrivals of raduaste shipments from THI-2. W/o enci. KERR. C. W. Assistant Director for State Agreements Programs. 79/11/08. 1p.
- 7912040140 Forwards special insprepts to NV Dept of Human Resources. In Aug 1979, NRC conducted special inspector Nuclear Engineering Co burial sites in States of MA & NV to observe arrivals of radwaste shipments from TMI-2, W/o encl. KERR. G. M. Assistant Director for State Agreements Programs. 79/11/08. ip.
- 7712100402 Forwards IE Bulletin 77-02, Revision 2, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts." No written response required.
  ORIER, B.H. Region 1, Philadelphia, Office of the Director.
  79/i1/08. ip.
- 7912050260 Forwards IE Info Notice 79-27. "Bteam Generator Tube Ruptures at Two PHR Plants." No response required. GRIER.B. M. Region 1. Philadelphia, Office of the Director, 79/11/16. 1p.
- 7912100127 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Dus to Pipe Support Loads," No response required. GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/11/16. ip.
- 7912280266 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valve." No written response required. ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/11/16. 1p.
- 791211041D Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required. ORIER, B. H. Region 1. Philadelphia, Office of the Director, 79/11/19. 1p.
- 7912050248 Forwards IE Bulletin 79-26, "Boron Loss From DWR Control Blades." No response required. ORIER, B. H. Hegion 1, Philadelphia, Office of the Director. 79/11/20, ip.
- 79:2060876 Forwards IE Circular 79-24, "Proper Installation & Calibr of Cors Spray Pipe Break Detection Equipment on BMRs." No response required.

  ORIER, B. H. Region 1. Philadelphia. Offics of the Director.

  79/11/26. 1p.
- 7912110054 Forwards IE Circular 79-23, "Motor Btarters & Contactore Falled to Operata." No response required. GRIER. B. H. Region 1, Philadelphia, Office of the Director. 79/11/26. 1p.

- 7912280204 Forwards IE Info Notice 79-31. "Use of Incorrect Amplified Response Spectra." No written response required. GRIER.B.H. Region L. Philadelphia, Office of the Director. 79/12/13. 1p.
- R Pariadic operating reports & related correspondence
- 7912040090 Grants request for extension to 800601 for submitting annual radiological environ operating rept for 1979. COLLINS J. T. THI-2 Operations/Support. 79/11/13. 3pp.
- S. Reportable occurrences, LERs & related correspondence
- 7912040082 PNG-79-003: on 791027; fire deluge sys in B natural draft cooling tower actuated. Actuation of all three power fire pumps resulted in overheating of fire pump B. Due to cooling water supply line rupture. CONTE, R. J., MCCAUSHY, R. W., COLLING, J. T. Office of Inspection & Enforcement, Office of the Director. 79/10/29, 1p.
- 7912180051 PNO-TMI-79-05; on 79121.RH Vollmer & JT Collins will attend briefing on current TMI activities in Annapolis.MD. Briefing appnsored by State of HD & will include representatives from Met Ed.PA Dept of Environ Resources & NRC. COLLING.J.T. Office of Inspection & Enforcement, Office of the Director. 79/11/21. ip.
- 7912310337 Forwards duse assessment from 790828 entry into TMI-2 fuel handling bldg north makeup valve room to examine & tighten leaking makeup valves. Detailed reviews conducted by radiological engineering personnel.

  WILSON. R. F. Metropolitan Edison Co. 79/12/05. 60pp.
- T. Hearing transcripts on non-antitrust matters
- 7912040189 Transcript of 791030 proceeding of ACRS Subcommittee on TNI-2 Accident Implications to review NUREQ-0600 in Washington DC Pp 1-175.

  \* ACRS Advisory Committee on Reactor Sofeguards. 79/10/30. 176pp.
- 7912040182 Transcript of 791105 meeting of ACRS Subcommittee on TMI-2 Accident Implications in Washington DC Pp 1-269. \* ACRS - Advisory Committee on Reactor Safeguards. 79/11/05.
- 7912280477 Transcript of Senate Committee on Environ & Public Works, Subcommittee on Nuclear Regulation 791108 hearing Te TMI cleanup. Pp 1-97.
  DIECKAMP, H. Metropulitan Edison Co. THIESING, J. W. Bechtel Corp. MILSON, R. General Public Utilities GPU Service Corp. 79/11/08.
- 79122B0479 Transcript of Benate Committee on Environ & Public Works, Subcommittee on Nuclear Regulation 791109 Amering to TMI cleanup.Pp 1-69.

  LOCHIS,P.A., LEVY.A. Spourities & Exchange Commission. GRAHAN, J. General Public Utilities GPU Service Corp. 79/11/09. 71pp.
- 7912280474 Transcript of NRC 791121 hearing in Harrisburg.PA to receive testimony on classification of TMI 790328 accident as extraordinary nuclear occurrence.Pp 1-109.
  MINDOUE,R.B. Office of Standards Bevelopment. SALTZMAN.J.
  Antitrust & Indeanity Gruup. SHAPAR.H. Office of the Executive Legal Director. 79/11/21. 110pp.
- 7912260319 Forwards Page 15 of transcript of BO Eisenhut testimony at Dec 1978 hearing re aircraft crash probability issue. CHANDLER, L. J. Hearing Branch 1. 79/11/28. 2pp.
- 7912280080 Forwards corrections to transcript of 791108 hearings before Subcommittee on Nuclear Reactor Regulation.W/c ancl. VOLLMER.R.H. TNI-2 Operations/Support. 79/12/05. 1p.
- U. Congressional/Executive Correspondence
- 7912120155 Forwards RT Cole 790822 request for info re venting of radioactive gases & water from facility. Requests comment. ROTH, N. Benate. 79709722. 2pp.
- 7912040107 Responds to 790913 request for written explanation re classification of TMI 770329 accident as Class 9 accident. Forwards NRC response to Salem 1 Board Question 4,FD Anderson 790824 memo & RJ Mattson 790830 memo. GOSSICK.L.V. Office of the Executive Director for Operations. 79/10/03. 4pp.

- --7912040118 Advises of Class 9 status of TMI accident. SMITH.B.R. Hearing Branch 2. 79/09/18. 1p.
- --7912040126 Requests written explanation for reclassification of TMI accident as Class 7 occurrence.
  LAGOMARSING.R. House of Rep. 79/04/13. 1p.
- 7912120528 Responds to 791005 ltr re AD Hotham request for improvement in operator trashing. Forwards NRC 790917 & 27 responses to AD Hotham.

  QCSSICK, L. V. Office of the Executive Director for Operations.

  79/10/31. lp.
- --7912120532 Bubmits list of studies underway re improvements in licensing process. Fundamental role of human element not overlooked. COLLINS,P.F. Operator Licensing Branch. 79/09/17. 2pp.
- ~-7912120535 Forwards AD Hotham 770B31 ltr re training & performance of plant workers. Ltr outlines ideas & suggestions for training nuclear plant workers. Requests comment. BYRON.B. B. House of Rep. 79/10/08. 7pp.
- 7912040081 Requests opportunity to express opinions re TMI-1 restart before subcommittee. Requests assistance in suspending restart hearing until Kemeny rept recommendations implemented.

  ROTH. J. E. Three Mile Island Alert. 79/11/10. 2pp.
- 7712280253 Responds to 771001 ltr concerning releases of radioactivity to atmosphere & Sucquehanna River.NRC had authorized use of EPICOR-II to clean up contaminated water in auxiliary bldg tanks.
  GDSSICK.L.V. Office of the Executive Director for Operations.
  79/11/15. 7pp.
- --7912280287 Request response to questions re proposed radioactive releases into atmosphere & Susquehanna River in connection w/cleanup of contaminated water from 790328 accident. BIDEN, J. R. Benate. 79/10/01. 2pp.
- 7912280279 Responds to 790925 ltr concerning comments of two geologists from Franklin & Marshall College re NRC environ assessment on use of EPICOR-II. NRC has authorized use of EPICOR-II. Forwards NRC response to public comments. GD851CK.L.V. Defice of the Executive Director for Operations. 79/11/15. 57pp.
- --7912280313 Forwards comments prepared by two geologists from Franklin & Marshall College re NRC environ assessment on use of EPICOR-II. Requests response. WALKER.R. S. House of Rep. 77/09/25. ip.
- 7912130241 Responds to Subcommittee on Energy & Environ 790713 request for info re release of radioactive matls to environ from 790328-0407. Iodine & noble gases were only radioactive matls of any consequence that were released.

  HENDRIE, J. M. Commission. 79/11/21. 3pp.
- --7912130314 Responds to 790713 request for info re release of radioactive matls to environ from 790328-0407. Indine & noble gases were only radioactive matls of any consequence that were released.

  HENDRIE J. M. Commission. 79/11/21. 3pp.
- ---7912130338 "Summary of Gaseous Releases to Environ at TMI During Period of 790328-0531."

  \* Porter-Gartz Consultants, Inc. 79/11/21, 2pp.
- --7912130353 Draft "Release of Radionuclides into Susquehanna River from TMI Durling Period of 790328-0511, Data & Analysis, " PASCIAK.W., CONGEL.F.J., BRANAGAN,D.R. Radiological Assessment Branch. NUREG-059B. 79/11/21. 78pp.
- ---7912130363 Draft rept "Method for Calculating Doses to Population from Xe-133 Releases During TMI Accident." PABCIAN, W. BRANAGAN, E.F., CONGEL, F. J. Radiological Assessment Branch, 79/11/21. 23pp.
- --7912130377 Requests info re radioligical releases from THI from 790328-0447 UDALL, M.K., WEAVER, J. House of Rep., Interior & Insular Affairs, 79/07/13, ip.

- 7912280411 Responds to 790821 ltr re WA Arsenault 790815 questions. Approx 14 mCi of noble gases & 15 Ci of I-131 released into atmosphere in first month following accident. Xe-133 was detected in NY several days after accident. ODBSICK.L.V. Office of the Executive Director for Operations. 79/11/21. 4pp.
- 7912280471 Responds to 790516 ltr re constituent petitions requesting permanent shutdown of facilities. NRC will conduct hearing prior to restart of Unit 1. Licensee has not submitted proposal for recovery of Unit 2.

  ORSICK.L.V. Office of the Executive Director for Operations.
  79/11/29. 2pp.
- --7912280486 Notifies that Executive Board of East York Elementary School PTA 790430 resolution & York Committee for Sale Environ petition requesting plant shutdown have been forwarded to Director of Nuclear Reactor Regulation.

  8HAPAR, H. K. Office of the Executive Legal Director. 79/06/13.
- --7912280489 Forwards Executive Board of East York Elementary School PTA 790430 resolution & York Committee for Safe Environ petition requesting plant shutdown Requests comment. KAMMERER, C. Office of Congressional Affairs. 79/06/01. 1p.
- --7912280492 Raquests that NRC parmanently shut down & decommission TMI facilities. Risks of catestrophic accident from facilities unacceptable. YOUNG, J. B., BANDAB, B. M., HANKEY, D. Affiliation Unknown. 79/05/14. 142pp.
- --7912280493 Ack receipt of 790516 ltr forwarding Executive Board of East York Elementary School PTA 790430 resolution & York Committee for Safe Environ petition requesting plant shutdown.
  KAMMERER, C. Office of Congressional Affairs. 79/06/01. ip.
- DOCKET 50-321 EDWIN I. HATCH NUCLEAR PLANT, UNIT 1
- F. Security, medical, emergency & fire protection plans
- 7912280559 Notifies that NRC guides & criteria cannot be adequately incorporated into site emergency plan before 800i01. Requests delay in submittal data for revised emergency plan until 800i01. KELLY, R. J. Georgia Power Co. 79/10/20. 1p.
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives. Provides guidance for improving licenses emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.

  GRIMES, B.K. Emergancy Preparedness Task Force. 79/11/23, 30pp.
- Q. Adjudicatory correspondence
- 7912060120 Order dismissing proceeding Interenor Georgians Against Nuclear Energy participation in proceeding terminated. GROBEMAN, H. Atomic Safety and Licensing Board Panel. 79/11/16. 200.
- 7912110038 Confirms receipt of encl 790329 petition to suspend OLs for all PMRs. Forwards FR notice indicating that petition will be treated in accordance w/10CFR2. 206.
  DENTON M.R. Office of Nuclear Reactor Regulation. 79/11/23. 1p.
- --7912110126 Notice of request for action pursuant to 100FR2.206 re Environ Coalition on Nuclear Power 790329 petition requesting suspension of all DLs for PHRs. MULLER.D.R. Office of Nuclear Reactor Regulation, 79/11/23. 38pp.
- H. General correspondence
- 7912100137 Requests that RJ Welly replace CF Whitmer as addresses for all correspondence. EMPREMERRORS N. Ocorgia Power Co. 79/08/22, ip.
- P. Operating license stage documents & correspondence
- 7911090248 "Bummary of Operating Experience W/Redirculating Steam Opnerators." EISENHUT, D. O. Division of Operating Reactors. NUREQ-0523. 79/01/31. 89pp.
- 7912180083 Forwards request for addl info about containment purge & vent sys re util plans for unlimited purging.

  LAINAS, O. Plant Systems Branch. 79/11/04. 3pp.

- 7912100189 Discusses NRC 791101 meeting w/representatives of NSSS vendors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EISENHUT, D.O. Division of Operating Reacturs. 79/11/09. 65pp.
- --7912100255 Responds to NRC 791101 request re noncompliance of Westinghouse ECCS evaluation model under requirements of 10CFR50 App K. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants.

  ANDERSON, T. M. Westinghouse Electric Corp. 79/11/02. App.
- --7912100330 Responds to NRC 791101 request re ORNL cladding swelling & rupture data. Review of analytical models & tests indicates compliance w/iOCFR50 App K. All GE specs for calculated peak cladding temp remain unchanged.

  BUCHROLZ.R. H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50.46 satisfied. DHSLEYs G.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/02. 5pp.
- --7912100456 Forwards add1 info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. OWSLEY.O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/04. 22pp.
- 7912260131 Forwards safety evaluation of util request for change in Tech Spacs re adjustment of average power range monitor satpoints. LAINAG.O. Plant Systems Branch. 79/11/27. 2pp.
- ---7912260164 Safety evalution limiting util Tech Spec change request.

  Deviation from average power range monitor calibr procedures
  during full power inconsistent w/IEEE 279.

  \* Plant Systems Branch. 79/11/27. 2pp.
- 7912050150 Forwards Amend 4 to "Spent Fuel Pool Mod," included as part of 790709 application for expansion of spent fuel storage.
  Propared in response to NRC 791101 request.
  KELLY.R.J. Georgia Power Co. 797/11/30. 2pp.
- --7912050155 Amend 4 to "Spent Fuel Pool Mod," design rept & safety evaluation. \* Georgia Power Co. 79/11/30. 14pp.
- 7912050533 Commits to add1 confirmatory condensation oscillation tests in full-scale test facility, outlined in OE 791330 ltr re Mark I containment program. Schedule for submittal of plant unique analysis will be provided following NRC resolution. KELLY,R. J. Georgia Power Co. 79/11/30. 2pp.
- 79:R190164 Requests payment of Class I & III amend fees for review of 790B17 security personnel training & qualification plan.

  DIGOS,R.M. License Fee Management Branch, 79/12/06. ip.
- 7912140321 Forwards rept "Adequacy of Station Electric Distribution Sys Voltage." KELLY,R. J. Georgia Power Co. 79/12/07. 2pp.
- --7912140326 "Adequacy of Station Electric Distribution Bys Voltage." \* Opengia Power Co. 79/12/07, 87pp.
- 7912270517 Confirms commitments in response to short-term recommendations of TMI-2 Lessons Learned Task Force on mod of automatic valve reopening circuit Mod to be completed by BOO101 or prior to critical operation.

  KELLY,R.J. Georgia Power Co. 79/12/20. ip.
- Q. Inspection reports. IE Bulletins & correspondence
- 7912040007 Forwards response to 790702 ltr & IE Bulletin 78-14 reverification of seismic analysis as modified by 790727,0815 & 0907 ltrs. Rept describes resolution of items in Unit 2 program, Verification of unit analysis delayed M/o encl. WIDNER, W. A. Georgia Power Co. 79/11/08. 2pp.
- 7912110055 Forwards 790921 response to IE Dulletin 79-19, "Packaging of Low-Level Radwaste for Transport & Burial." WIDNER, W. A. Georgia Power Co. 79/11/08. ip.

- 7912060148 Forwards IE Info Notice 79-12A, "Attempted Damage to New Fuel Assemblies." No specific action or response required. D'HELLLY.J.P. Region 2, Atlanta, Office of the Director. 79/11/09. 2pp.
- 7912100184 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/11/16. lp.
- 7912110962 Forwards IE Info Notice 79-29. "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required. O'REILLY.J.P. , Region 2. Atlanta, Office of the Director. 79/11/16. 2pp.
- 7912040617 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pips Break Detection Equipment on BMRs." No response required.

  0/REILLYJ.P. Region 2: Atlanta: Office of the Director.
  79/11/26. ip.
- 7912110149 Forwards IE Circular 79-23, "Motor Starters & Contectors Failed to Dperate." No response required. O'REILLY, J. P. Region 2. Atlanta. Office of the Director. 79/11/26. 1p.
- 7912190454 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Written response required. 0'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/11/30. 1p.
- 7912210177 Forwards corrected copy of 791130 ltr responding to IE Bulletin 79-18. "Audibility Problems Encountered on Evacuation of Personnel from High-Noise Areas." WIDNER. M. A. Occupia Power Co. 79712/05. ip.
- --7912210181 Corrected copy of response to IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High-Noise Areas." Requests addl 90 days to complete installation of addl visual evacuation signals in identified areas. WIDNER, W. A. Georgia Power Co. 79/11/30. 1p.
- 7912310301 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncospliances, 10CFR21." No action required.

  0/REILLY,J.P. Region 2, Atlanta, Office of the Director.

  79/12/06. Spp.
- 79:2200038 Forwards IE Bulletin 79-28. "Possible Malfunction of Namco Model EAIRO Limit Switches at Elevated Temps." Action regulated.
  O'REILLY, J.P. Region 2. Atlanta, Office of the Director.
  79/12/07. 200.
- 7912280404 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra," No written response required.

  O'REILLY, J. P. Region 2, Atlanta, Office of the Director.

  79/12/13, 2pp.
- 7912280141 Forwards IE Circular 79-25, "Bhock Arrestor Strut Assembly Interference." No written response required. C'REILLY.J.P. Region 2. Atlanta, Office of the Director. 79/12/20. 4pp.
- R. Periodic operating reports & related correspondence
- 7912180430 Forwards monthly operating rept for Nov 1979. MANRY, M. Georgia Power Co. 79/12/10. 1p.
- ---7912180434 Monthly operating rept for Nov 1979, JOHNSON O. L. Georgia Power Co. 79/12/10. Spp.
- 8. Reportable occurrences. LERs & related correspondence
- 7912130426 RO-79-089: on 791106, while evaluating as-built seismic piping a supports head vent line portion of RHR head spray piping by bypass to condenser valve chest found unsupported Caused by omission of supports from design.

  HANRY.M. Georgia Power Co. 79/11/06. 2pp.
- 7912050450 Forwards LER 79-093/03L-0. MANRY, M. Georgia Power Co. 79/11/27. 1p.

- --7912050457 LER 79-093/03L-0: on 791112 monthly tests on Units 1 & 2 liquid radwaste radiation moniters not performed Caused by training class in progress during scheduled test time, leaving insufficient time to complete tests.

  ROGERS.H. H. Georgia Power Co. 79/11/27. 2pp.
- 7912110320 Ferwards LER 79-091/03L-0. MANRY, M. Qeorgia Power Co. 79/11/27. ip.
- ---7912110323 LER 79-091/03L-0: on 791106 insurance investigation revealed required penetration seal not installed in 2-inch penetration in control/syc bldg firewall. Caused by misinterpreted drawings. Seal installed.

  CO901N.C.L. Georgia Power Co. 79/11/27. 2pp.
- 7912130424 Forwards LER 79-092/03L-0. MANRY.N. Osorgia Power Co. 79/12/05. ip.
- —7912130436 LER 79-092/03L-0: on 791107.prompt notification telegram for LER 79-089 was not transmitted as required. Caused by broken telecopy machine & failure to advise mgt. Procedures changed. CDOOIN.C.L. Georgia Power Co. 79/12/09. 2pp.
- 7912140429 Forwards LER 79-094/03L-0. MANRY, M. Gaorgia Power Co. 79/12/07. 1p.
- --7912140436 LER 79-094/03L-0: on 791121, while reactor in run mode, discovered B pump running w/o discharge pressure or flow on local gauges. Caused by breaking of pump line bottom shaft, Shaft & suction bell replaced.

  NIX.R. T. Georgia Power Co. 79/12/07. 3pp.
- 7912170306 Forwards LER 79-097/03L-0. MANRY.M. Georgia Power Co. 79/12/11. ip.
- --7912170316 LER 79-097/03L-0: on 791128; after recalibr of P33-P001A & B during steady state power operation; drywell torus dihydrogen & diuxide analyzers A & B indicated more than 4% oxygen concentration. Caused by leakage of air into analyzer.

  NIX.R. T. Georgia Power Co. 79/12/11. 2pp.
- 7912170319 Forwards LER 79-096/03L-0. MANRY.M. 9sorgia Power Co. 79/12/11. 1p.
- --7912170321 LER 79-095/03L-0: on 791127, while performing dihydrogen k dioxygen analyzer instrument calibroxygen analyzers on P33-P001A k B found out of tolerance. Caused by instrument drift. Analyzers recalibr.
  NIX.R. T. Georgia Power Co. 79/12/11, 2pp.
- 7912260247 Forwards LER 79-095/03L-0. MANRY.M. Quorgia Power Co. 79/12/14. 1p.
- ---7912260249 LER 79-095/03L-0: on 791126, during normal plant operation, discovered that 791126 battery individual cell surveillance procedure not performed. Caused by personnel oversight. Procedure performed on 791127.

  NIX.R.T. Georgia Power Co. 79/12/14. 3pp.
- 7912270472 Forwards updated LER 78-027/03X-1. MANRY, M. Georgie Power Co. 79/12/17. 1p.
- --7912270477 Updated LER 78-027/03X-1: on 780502, hanger E11-RHR-H97 on RHR evc water dutlet from heat exchanger found broken.

  Caused by sheared support rod & disengaged saddle bolt.

  Saitch replaced.

  CU001N.C.L. Georgie Power Co. 79/12/17. 2pp.
- 7912270482 Forwards LER 79-098/01T-0. MANRY.H. Georgia Power Co. 79/12/17. ip.
- ---7912270489 LER 79-098/01T-0:on 791210.HPCI sys not proven inoperable as required by Tech Space. Caused by failure of personnel to consider reactor core isolation cooling sys inoperable after trip on high turbine exhaust pressure.

  BAXLEY. B. X. Georgia Power Co. 79/12/19. 3pp.
- 7912310429 Forwards LER 79-100/03L-0. HANRY.H. Georgia Power Co. 779/12/20. 1p.
- ---7912310430 LER 79-100/03L-0:on 791211.during steady state power operation, LPCI containment isolation valve Eii-F0158 determined to be leaking. Caused by valve seat being galled. Corrective action not complete. COOGIN.C.L. Georgia Power Co. 79/12/19. Spp.

- 7912310415 Forwards LER 79-099/03L-0.
  MANRY, M. Georgia Power Co. 79/12/27. 1p.
- --7912310420 LER 79-099/03L-0:on 791206.while performing Procedure HNP-1-3605 w/reactor in run mode.stack inlet valve failed in closed position. Caused by limit switch in control circuit not making proper contact. Limit switch adjusted.

  NIX.R.T. Georgia Power Co. 79/12/27. 2pp.

#### DOCKET 50-322 SHOREHAM NUCLEAR POWER STATION

- A. Application/construction stage documents & correspondence
- 790B070310 Forwards NUREO/CR-0660, "Enhancement of Dosite Emergency Dissel Generator Reliability," Requests comments W/o ehcl. VABSALLO, B. Assistant Director for Light Water Reactors, 79/04/18, 3pp.
- 7912i10011 Forwards NRC position on status & applicability to pending OL applications of results of TMI followup actions, Outlines addl short-term actions to be taken.
  VASSALLO, D. B. Division of Project Management. 79/09/27. 41pp.
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMB issue for PMRs & BMRs.
  Buccess of program depends on industry response. Supports formation of owners groups to provide necessary info.
  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912130125 Forwards proposed Revision 2 to Reg Guida 1.97.
  "Instrumentation for Light Water Cooled Nuclear Power Plants to Assess Plant & Environs Conditions During & Following Accident." Requests comments.
  VAROALS.A. Assistant Director for Light Water Reactors. 79/11/23.3pp.
- 7912270167 Forwards proposed Revision 2 to Reg Quide 1.97,
  "Instrumentation for Light Water Cooled Power Plants to
  Assess Plant & Environs Conditions During & Following
  Accident." Comments should be filed before 791214 meeting.
  VARQA: B.A. Assistant Director for Light Water Reactors. 79/11/23.
  3pp.
- ---7912270178 Notification of 791214 meeting w/applicants to discuss proposed Ravision 2 to Reg Guide 1.97, "Instrumentation for Light Water Cooled Nuclear Plants to Assess Plant & Environs Conditions During & Following Accident."

  KINTNER.L.L Light Water Reactors Branch 1. 79/11/19. 1p.
- 7912070084 Summary of 791108 meeting w/Naval Research Lab.util.0E & SEM in Bethesda,MD re status of seismic qualification review of facility.

  WILEON.J.N. Light Water Reactors Branch 4. 79/11/30, 11pp.
- 7912140053 Bummary of 791017 meeting w/util,84W & Hunton & Williams in Bethesda,MD re review of application for facility DL. WILBON,J.N. Light Water Reactors Branch 4. 79/11/30, 10pp.
- C. Utility Environmental Report (ER), amands & correspondence
- 7912200104 Forwards updated distribution list for environ rept suppls & amends for facility.

  DUNCAN, M. Environmental Projects Branch 2. 79/12/07. 4pp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards into re upgraded emergency plans to plants under const & OL review Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Guide i. 101.

  VASBALLO, D. B. Division of Project Management. 79/11/21. App.
- Q. Adjudicatory correspondence
- 7911190528 Testimony re intervenor Miami Valley Power Project Contention 17 on use of Kápusol as fire barrier for cable trays. Centificate of 80c encl. HARRISON.O.A. Division of Systems Safety. 79/10/30. 15pp.
- ---7911190530 Forwards June 1979 "Fire Protective Cable Tray Fire Test" by MS Abrams witnessed by NB Cohn on 790606. CDHN.N.B. Gage-Babcock Associates. Inc. 79/06/12. 6pp.
- 7912060074 Forwards 791102 second stipulation resulting from applicant. NRC & Suffolk County negotiations on latter contentions. REVELY, M. T. Hunton & Hilliams. 79/11/05, ip.

- ---7912060079 Second stipulation re Suffolk County contentions. Contains applicant agreement to meet certain conditions on RCS leakage. Nill particularize unresolved contentions.
  REVELY.W.T. Long Island Lighting Co. LIKE.I. Suffolk County. NY. HOEFLING.R.K. Hearing Branch 4. 79/11/02. 4pp.
- 7912060050 Hemorandum seeking explanation by parties of 791105 second stipulation re Suffolk County contentions. Guestions whether Footnote 2.Page 2. should be incorporated in Tech Specs & whether first paragraph of footnote is NRC disclaimer. BOWERS, E. S. Atomic Safety and Licensing Buard Panel. 79/11/16. 1p.
- 7912170227 Notice by NY State Board on Electric Generation Siting & Environ. Replies to utils' application for rehearing of ASLB order dismissing application for certificate of environ compatibility will be accepted if filed by 791203.

  MADISON, S. R. New York, State of, 79/11/20. 1p.
- 791213003B Response to ASLB 791116 memorandum re NRC & intervenor Suffolk County 791102 second stipulation re certain intervenor contentions. Footnote 2 re RCB leakage may be incorporated into Tech Specs. Certificate of Svc encl. HOEFLING.R.K. Hearing Branch 4, 79/12/04. Upp.
- 7912190178 Forwards ASLB "Hemorandum Concerning Second Stipulation Re Certain Suffolk County Contentions." HOEFLING.R.K. Hearing Branch 4. 79/12/04. 1p.
- ---7912190191 "Memorandum Concerning Second Stipulation Re Certain Suffolk County Contentions." Util should specify if page two single spaced paragraph will be included in Tech Space. First sentence of footnote appears to be disclaimer. BOWERS, E. S. Atomic Safety and Licensing Board Panel. 79/11/16.
- G. Inspection reports, IE Bulletins & correspondence
- 7912070200 Forwards IE Insp Rept 50-322/79-14 on 790827-30.No noncompliance noted, BRUNNER.E.J. Region 1. Philadelphia, Offics of the Director. 79/09/26. 2pp.
- ---7912070202 IE Insp Rept 50-322/79-14 on 790827-30. No noncompliance noted. He for areas inspected: overall preoperational test program, pipe supports, chlorination sys. load ctr transformers & emergency standby power sys.
  NICHOLAS-H. H., HIGOINS. J. C. Region 1, Philadelphia, Office of the Director CAPHTON. D. L. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch, 79/09/25, 9pp.
- 7912120181 Supplements 790911 response to IE Bulletin 79-15. No unusual wear found during hydraulic testing of deep draft pumps.
  Startup test planned for svc water pumps.
  NOVARRO, J. P. Long Island Lighting Co. 79/10/09. 2pp.
- 79:2:304Bi Responds to IE Bulletin 79-14 re saismic analysis for safety-related piping sys. Heismic analysis of safety-related piping 2 1/2-inch diameter & greater accurately reflects actual installation.

  NOVARRO, J. P. Long Island Lighting Co. 79/10/30. 2pp.
- 7912130015 Responds to IE Bulletin 79-23, "Potential Failure of EDG Field Exciter Transformer." Each transformer to be inspected for direct or indirect grounding condition. NOVARRO.J.P. Long Island Lighting Co. 79/11/01. 2pp.
- 7912310054 Forwards IE Insp Rept 50-322/79-15 on 790921-22, No noncompliance noted.
  BRUNNER, E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/11/09. 2pp.
- ---7912310058 IE Insp Rept 50-322/79-15 on 790921-22. No nuncompliance noted, Major areas inspected reactor pressure vessel & main steam line hydrostatic test.
  NICHOLAS.H.H. Region 1. Philadelphia, Office of the Director.
  CAPHTON.D.L. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch. 79/11/07. 9pp.
- 79:2050036 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required.
  GRIER.B. H. Region 1. Philadelphia. Office of the Director.
  79/11/16. 1p.
- 7912050236 Forwards IE Info Notice 79-27. "Steam Generator Tube Ruptures at Two PMR Plants." No response required. GRIER, B. H. Region 1. Philadelphia. Office of the Director. 79/11/16. ip.

- 7912100124 Forwards lE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. GRIER, B.H. Region 1. Philadelphia. Office of the Director. 79/11/16. Ip
- 7712110413 Forwards [E Info Notice 77-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. GRIER.B.H. Region i. Philadelphia. Office of the Director. 77/11/19. 1p
- 7912050243 Forwards IE Bulletin 79-26, "Boron Lass From BWR Control Blades." No response required.
  GRIER, B. H. Region I. Philadelphia. Diffice of the Director.
  79/11/20. 1p.
- 7912060574 Forwards IE Circular 79-24. "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BUNs." No response required.
  ORIER, D. H. Region, i. Philadelphia, Office of the Director.
  79/11/26. 1p.
- 7912110051 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required.
  GRIER.B.H. Region 1, Philadelphia, Office of the Director.
  79/11/26. 1p.
- 7912:90031 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." No written response required.
  GRIER B. H. Region 1, Philadelphia, Office of the Diroctor.
  79/11/30.
- 7912310220 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, IOCFR21." No action required. ORIER.D.H. Region I, Philadelphia, Office of the Director. 79/12/06. 4pp.
- 7912190750 Forwards IE Bulletin 79-20, "Possible Malfunction of Namco Model EAIRO Limit Switches at Elevated Temps." Written response required ORIER.B.H. Region 1, Philadelphia, Office of the Director. 79/12/07. 1p.
- 7912270517 Forwards revised preservice insp program for facility re general magnetic particle eramination & program plan. NAVARRO, J. P. Long Island Lighting Co. 79/12/13. 23pp.
- 7912280200 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required.
  ORIER, D. H. Region 1. Philadelphia. Office of the Director.
  79/12/13. 1p.
- DOCKET 50-323 DIAGLO CANYON NUCLEAR POWER PLANT, UNIT 2
- 79:2050117 Joint Intervenors' reply in opposition to NRC & applicant responses re qualifications of Chairman Hendrie & Commissioner Kennody Available documents establish existence of ex parte communications. W/Certificate of Svc. FLEISCHAKER.D. Fleischaker. D. S. PHILLIPS J.R. Center for Law in the Public Interest. 79/11/23. 7pp.
- A Application/construction stage documents & correspondence
- 7912110011 Forwards NRC position on status & applicability to pending OL applications of results of TMI followup actions. Outlines add1 short-term actions to be taken.

  VASSALLO, D. B. Division of Project Management. 79/09/27. 41pp.
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATWB issue for PWRs & BWRs. Success of program depends on industry response. Supports furmation of owners groups to provide necessary info.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.
- 7412100483 FOIA request for records to 771019 maching at which JM Handrie, D Hassell, L Bickwit & RT Kennedy were present. FLEISCHAKER, D. Fleischaker, D. S. 79/10/26. 2pp.
- 7912070004 Requests distribution of encl memorandum to Board notification svc lists. VAROA,S.A. Assistant Director for Light Water Reactors. 79/11/08. 3pp.

- 7912100484 Responds to FOIA request for records re 791019 meeting at which UM Rendrie, D Hassell, L Bickwit & RT Kennedy were present. Forwards J Stephens handwritten notes of RT Kennedy meeting.

  CARR, J. C. Division of Rules and Records. 79/11/23. 2pp.
- 7912180089 Forwards proposed Revision 2 to Reg Guide 1.97, "Instrumentation for Light Water Cooled Nuclear Power Plants to Assess Plant & Environs Conditions During & Following Accident." Requests comments. VAROA.B. A. Assistant Director for Light Water Reactors. 79/11/23.
- 7912040498 Forwards fee for Class I & Class II amend re request for extension of const dates for CPPR-d9 & CPPR-69.
  CRANE.P.A. Pacific Gas & Electric Co. 79/11/26. 1p.
- 7912190170 Ack RS Hime 791105 ltr re CA Commission on Agriculture views concerning New Helanes dam & reservoir Forwards 791031 news release explaining transfer of facilities W/o encl. Ltr being forwarded to NRC for consideration of Commission. NIELSEN.A. D. Interior Dept. of. 79/11/26. 2pp.
- 7912040452 Notifies NRC of intentions re paving of certain roads at plant site & impact on archaeological resource area north of plant.Forwards 791112 itr from Greenwood & Associates. PETERS.R.J. Pacific Gas & Electric Co. 79/11/27. App.
- 7912170038 Forwards WA Baldwin of Friends of the Earth 791024 request for preparation of add1 environ statements re Class 9 accidents at facilities. Petition being handled as request for action under 10CFR2.206.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/27. 2pp.
- 7912170064 Forwards WA Baldwin of Friends of the Earth 791024 request for preparation of addl environ statements re Class 9 accidents at facilities.Petition being handled as request for action under 10CFR2.206.
  DENTON, H.R. Office of Nuclear Reactor Regulation. 79/11/27. 2pp.
- 7912110322 Forwards response to NRC 790802 ltr ro secondary water chemistry control.
  CRANE,P.A. Pacific Gas & Electric Co. 79/12/05. 4pp.
- 7912120317 Supplies schedule for providing info to environ qualification of Class IE instrumentation & electrical equipment, in response to 791102 ltr. CRANE.P.A. Pacific Gas & Electric Co. 79/12/09. lp.
- 7912130271 Forwards "Qualification of Control Sys," in response to NRC 790917 ltr requesting info for review of potential safety question detailed in IE Info Notice 79-22.
  CRANE,P.A. Pacific Oas & Electric Co. 79/12/06. 1p.
- --7912130280 "Qualification of Control Sys." \* Pacific Gas & Electric Co. 79/11/30. 50pp.
- 7912310172 Notification of B00109 meeting w/util in Bethesda.MD to present info to util on methods & procedures used by Sandia Labs in study on sys interaction & how methods might be used for investigating effects of failures in sys & components.

  BUCKLEY.B.C. Light Water Reactors Branch 1. 79/12/17, 3pp.
- 7912310037 Confirms rescheduling of meeting re effect of nuclear plant on five endangered species to 900108.
  REGAN W.H. Assistant Director for Environmental Technology.
  79/12/19. 1p.
- D. NRC Draft/Final Environmental Statements, suppls & correspondence
- 7912:30063 Ack receipt of 791023 ltr re five endangered species near plant.Requests consultation meeting at future date.
  REGAN, M. M. Assistant Director for Environmental Projects.
  79/11/30. 2pp.
- F. Security, medical, emergency & fire protection plans
- 7912040474 Forwards info re upgraded emergency plans to plants under const & OL review Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Quide 1.101.

  VASSALLO, D. B. Division of Project Management. 79/11/21. 6pp.

#### G. Adjudicatory correspondence

- 7912040107 Responds to Governor Brown 791015 request to participate as representative of State of CA. Request should be granted.

  Certificate of Svc encl.

  DAVIS, L. D. Hearing Branch 4. 79/11/05. 5pp.
- 791203003B Response in opposition to Joint Intervenors 791024.25 & 26 requests to institute proceedings on qualifications of Chairman JM Hendrie & Commissioner RT Kennedy Ex parte communications took place. Certificate of Svc encl. OEHR.A.C., FURBUSH.M.H., CRANE.P.A. Pacific Gas & Electric Co. 79/11/09. 22pp.
- 7912130160 Supports Covernor EC Brown petition to intervene for reasoning set forth in NRC response Certificate of Bvc encl. FLEIBCHAKER, D. S Affiliation Unknown. FLEIGCHAKER, D. S Fleischaker, D. S. 79711/09. 3pp.
- 7912130276 Brief in support of exceptions to Part IV of ASLB 790927 partial initial decision. Urges revision of NASLP inference w/intervenor participation in security matters. Exclusion of experts prejudiced intervenor WCertificate of Bvc.

  BALDHIN.M.A., JUNEB, Y. I., VALENTINE, P. C. San Luis Obispo Mothers for Peace. 79/11/12. 26pp.
- 7912050161 Response to Joint Intervenors' 791024 & 26 requests to disqualify Commissioners Hendrie & Kannedy. Request should be denied because Joint Intervenors failed to satisfy burden of proof as to bias.

  DAVIS, L. D. Hearing Branch 4. 79/11/13. Lipp.
- --7912050173 Note to all parties forwarding summary of 791019 meeting between JH Hendrig & util representatives. \* Docketing & Services Branch. 79/10/26. 3pp.
- 7912060229 Order granting extension until 791121 for all parties to file replies to applicant motion for OL. CHILK, S. J. Commission. 79/11/15. 1p.
- 7912070171 Response in opposition to PORE 791105 objections to Governor Brown participation in proceeding Rights of interested state representatives established in NRC regulations.
  Timeliness requirement need not be applied to state.
  BROWN.H.H., KLINE.J.A. California, State of. 79/11/15. App.
- 7912060139 Order admitting State of CA as interested state in proceeding Grants Governor Brown representative participant status. Requests identification of issues within 30 days from receipt.

  BOMERS, E. S. Atomic Safety and Licensing Board Panel. 79/11/16.
- 7912060541 Order directing NRC to file response on intervenors' security plan contentions by 791218.
  BISHOP, C. J. Atomic Safety and Licensing Board Panel. 79/11/19.
- 7912030439 Order extending deadline to 791123 for Joint Intervenors response to util & NRC question re hearings to determine qualification of Commissioners Kennedy & Hendrie.
  CHILK.S.J. Office of the Secretary of the Commission. 79/11/20.
- 7712050025 Response in opposition to applicant 771026 motion requesting issuance of OL.Record incomplete re presence of reasonable assurance that activities may be conducted w/o endangering public health & safety. Certificate of Svc encl.

  NAVIS.L.D. Hearing Branch 4. 79/11/21. 9pp.
- 7912050046 Joint Intervenors' response opposing applicant 791026 motion requesting that ABLB be directed to issue decision on remaining issues. Opportunity to develop argument ve OL issuance should be granted. Certificate of Svc encl. FLEISCHAMER.D. Fleischaker. D. B. PHILLIPS, J.R. Center for Law in the Public Interest. 79/11/21. Spp.
- 7912130058 Forwards putition by WA Baldwin requesting that NRC prepare supplemental environ statements re Class 9 accidents at facilities Appropriate action will be taken.

  DENTON, M.R. Office of Nuclear Reactor Regulation. 79/11/27. Spp.
- --7912130070 Request for action under lOCFR2.206, for preparation of supplemental EIS concerning impact of Class 9 accidents at facilities.
  HULLER, D.R. Division of Site Safety & Environmental Analysis.
  79/11/23. 1p.

- 7912130168 Request for extension until 791207 to file brief in support of exceptions taken to ASLB 790927 partial initial decision. Represents that neither NRC nor applicant oppose motion. Stamped "granted" on 791128 by ASLAU. FLEISCHAKER, D. S. Affiliation Unknown. FLEISCHAKER, D. S. Fleischaker, D. S. 79/11/27. 2pp.
- 79:12:14001: Request by Joint Intervenors for extension until 79:207 to file brief in support of exceptions taken to ASLB 79:09:27 partial initial decision. Voluminous transcript requires addl time to assure quality of brief. Certificate of Syc encl. FLE:ISCHAXER, D. Flaischaker, D. S. PHILLIPS, J. R. Center for Law in the Public Interest. 79/11/27. 4ρμ.
- 79:2190230 Opposes private meeting held between util & NRC on 79:019. Urges disqualification of JM Hendrie & RT Kennedy From participation in matters concerning facilities. Forwards DR Kirkpatrick 79:106 ltr transmitting KB Coen 79:207 ltr. LAURN. V. W. Affiliation Unknown. 79/11/27. ip.
- ---7912190237 Opposes private meeting held between util & NRC on 791019 KIRKPATRICK D. Affiliation Unknown. 79/11/06. ip.
- --7912190245 Requests disqualification of JM Hendrie & RT Kennedy from licensing proceedings for facilities. COEN.K. S. Affiliation Unknown. 79/12/07. 1p.
- 7912200158 Ack receipt of 791024 petition & forwards FR notice for request for action per 10CFR2.206.
  DENTON:H.R. Office of Nuclear Reactor Regulation. 79/11/27. 3pp.
- ~-7912200168 Notice of issuance & availability of Friends of the Earth 791024 petition requesting that NRC prepare supplemental EIS re impact of Class 9 accident at facilities. MULLER.D.R. Division of Site Safety & Environmental Analysis. 79/11/23. lp.
- 7912170012 Brief in support of Joint Intervenors exceptions to ASLB partial initial decision. Board failed to consider properly setsmic focusing & high stress drop issue. Issue should be remanded for hearing Certificate of Svc encl. RCINE, J. A. J. BROWN, H. H. California, State of BROWN, H. H. Hill Christopher & Phillips. 79/12/07. 18pp.
- 7912310457 Brief in support of exceptions to ASLB 790927 partial initial decision which found that facility could withstand 7.5 magnitude earthquake on Hosgri fault Requests ASLAB hear onal argument. Certificate of Svc encl.
  FLEISCHAKER, D. S Fleischaker, D. S. 79/12/07. B9pp.
- 7912270064 Requests response to 791030 request for preservation of NRC memoranda re 791119 meeting between JM Hendrie & Mielke, Shackleford & Blanc, Forwards copy of 791030 ltr. W/o encl. FLEISCHAKER, D. S. Fleischaker, D. S. 79/12/13. 2pp.
- 7912280512 Requests that OL not be granted to util.Cities inability of util.cities & county to preserve public health in event of nuclear mishap.

  HOFFNAN. H. Affiliation Unknown 79/12/14. lp.
- 771228050B Requests substantive response to 771024 request for NRC to supplement EIS to consider consequences of Class 9 nuclear accidents. Failure to respond by 800104 will indicate NRC does not plan to require suppl.

  BALDWIN.W.A. Friends of the Earth. 79/12/21. tp.

- 7912110371 Certifies that response to Governor EG Brown petition to participate as representative of interested state was served on 791106.
  BIBCHOFF, C. A. Pacific Gas & Electric Co. 79/11/16. Opp.
- 791219000B Responds to request for renotice of license Task Force recommendations proceedings & Full public hearings re TMI Lessons Learned applicable to applicant. Evaluation of recommendations underway.

  ENGELHARDT, T. F. Deputy Executive Legal Director. 79/11/27. Opp.
- --7912190035 Forwards interim guidance for upgrade of emorgency plans per Reg Quide 1.101. Comments requested. E18ENHUT.D.Q. Assistant Director for Light Water Reactors. 79710710. 2pp.
- --7912170045 Requests full public hearings re THI Lessons Learned Task Force recommendations & renotice of ongoing licensing for public participation. CARR, H. League of Women Voters of San Luis Obispo CA. 79/10/29.

- 7912190220 Supports resumption of OL issuances. SHAW.H.E. Affiliation Unknown. 79/11/27. 1p.
- 7912280600 Responds to 790926 ltr re power plant opening,waste disposal & safety precautions. NRC conducting thorough investigation of TM1 accident. Recommendations will be applied to all nuclear facilities. Ltr ent. .

  DENTON, H.R. Office of Nuclear Reactor Regulation. 79/12/07. Spp.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 7912260280 Forwards Amend 81 to FSAR & Amend 82 to Hosgri Rept. SHACKLEFORD, B. W. Pacific Oas & Electric Co. 79/12/18. ip.
- --7912260284 Amend 81 to FSAR & Amend 82 to Hosgri Rept for Diable Cangon.Provides addl info re pressurization air flow conservative dumping value, torsion calculation & polar crane stability.

  \* Pacific Gas & Electric Co. 79/12/18. 96pp.
- Q. Inspection reports, IE Dulletins & correspondence
- 7912040090 Forwards IE Insp Repts 50-275/79-21 & 50-323/79-11 on 790821-24 & 0924-26 No noncompliance noted. CREMS, J. L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 79/10/19. 2pp.
- --7912060104 IE Insp Repts 50-275/79-21 & 50-323/79-11 on 790821-24 & 0924-26. No noncompliance noted Major areas inspected: presperational testing evaluation verification of test results & IE circular fullows.

  BTERNBERO, D. M. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. MORRILL, P. J., HORN, A. J. Region 5, San Francisco, Office of the Director. 79/10/19. 5pp.
- 7912100273 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. ENDELKEN.R.H. Region 5, San Francisco. Office of the Director. 79/11/16. ip.
- 7912110510 Forwards IE Info Notice 77-29, "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/11/16. 1p.
- 7912070022 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BMRs." No response required.
  ENGELKEN,R. H. Region 5, San Francisco, Office of the Director.
- 7912110268 Forwards IE Circular 79-23, "Motor Btarters & Contactors Failed to Operato." No response required.
  ENGELKEN, R. H. Region 5, San Francisco, Office of the Director.
  79/11/26. 1p.
- 7912110494 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sent by NRC to licensees.
  ENGELMENTR. H. Region 5, San Francisco, Office of the Director. 79/11/26. ip.
- 7912190121 Forwards IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Written response required. ENDELKEN.R.H. Region 5. San Francisco, Office of the Director. 79/11/30. Ip.
- 7912310269 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action required. ENGELBEN, R. H. Region 5, San Francisco, Office of the Director. 79/12/06. 4pp.
- 7912140492 Forwards reply to IE Bulletin 79-02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bults." SPENCER.G.S. Region 5, San Francisco. Reactor Construction & Engineering Support Branch. 79/12/07. 1p.
- --7912140497 Responds to IE Bulletin 79-02.Revision 2, "Pipe Bupports Base Plate Designs Using Concrete Expansion Anchor Bolts." Supports have stiffener plates added to assure baseplate rigidity & load distribution to bolts. CRANE.P.A. Pacific Gas & Electric Co. 79/09/19. App.

- 7712200237 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. ENGLKEN.R.H. Region 5, San Francisco, Office of the Director. 79/12/07. 1c.
- 7912270072 Forwards POLE response to IE Bulletin 79-04. SPENCER. G. S. Region 5. San Francisco. Reactor Construction & Engineering Support Branch. 79/12/07. 1p.
- --7912270078 Notifies that response to IE Bulletin 79-04 will be sent by 791101 pending receipt of calculated loads & hanger strength review from Westinghouse.

  CRANE, P. A. Pacific Gas & Electric Co. 79/10/16. 1p.
- 7912190614 Responds to IE Bulletin 78-12.78-12A & 78-12B Weld metl heat & lot numbers tabulated in 790608 C-E generic rept. Surveillance weldment consists of full thickness weldments using tandem are welding process. CRANE, P. A. Patific Gas & Electric Co. 79/12/12. 1p.
- 7912280619 Forwards IE Info Notice 79-31. "Use of Incorrect Amplified Response Spectra." No written response required. ENGELKEN, R.H. Region 5, San Francisco. Office of the Director. 79/12/13. 1p.
- U. Congressional/Executive Correspondence
- 7912210216 Ack receipt of 790928 itr re Lwague of Women Voters of Ban Luis Obispo.CA comments on advance notice of rulemaking for emergency planning at Diablo Canyon. QDSSICK-L.V. Office of the Executive Director for Operations. 79/10/29. 1p.
- ---791221022B Forwards League of Homen Voters of Ban Luis Obispo.CA 790920 comments on proposed regulations for nuclear emergency plans. Requests comment. LAGGMARBING.R. House of Rep. 79/09/28. 7pp.
- 7912210124 Responds to JH Alexander 790827 ltr re study of human factor of nuclear plant installation. Operating personnel receive additraining in plant transients & multiple accident conditions.

  GOMBICK.L.V. Office of the Executive Director for Operations.

  79/10/31. 2pp.
- ---7912210133 Forwards JH Alexander request for more study of human factor in operating & control sys of nuclear power plant installation Requests comments. CRANSTON. A. Benate. 79/08/29. 2pp.
- 7712210030 Requests info re effect licensing moratorium will have on facility.
  LAGOMARBIND.R.J House of Rep. 79/11/08. ip.
- 7912130206 Advises that Commission move quickly to decide if 791019 meeting w/util disqualifies Commissioners Hendrie & Kennedy from 11censing.
  LAGUMARSIND.R. J House of Rep. 79/11/15. 1p.
- 7912180468 Forwards ltrs from constituents re licensing of facilities. Requests Commissioners Handrie & Kennedy be disqualified because of attendance at 791019 meeting w/util. LAQUMARSING.R. J House of Rep. 79/11/15. 15pp.
- --7912180475 Urges Commission not to license nuclear reactor due to proximity to earthquake fault.
  JACKBUN.D.M. Affiliation Unknown. 79/11/28. 1p.
- --7912180480 Urges resignation of Chairman Handrie & Commissioner Kannady for attending meeting w/PokE. CDOPER.P. Affiliation Unknown. 79/11/05. ip.
- --7912180484 Objects to secret 791019 maeting between Hendrie Kennede & POLE. Urges disqualification from further decisions on util. CUMMINGS 8.C. Affiliation Unknown, 79/11/06, 1p.
- --7912180488 Forwards copies of 791121 ltrs sent to Senator Cranston & Representative Penetta urging disqualification of Hendrie & Kennedy, TETER.H.M. Affiliation Unknown. 79/11/21. 4pp.
- --7912180493 Forwards copy of 791112 ltr to Senator Cranston objecting to meeting between Hendrie-Kennedy & PG&E Requests each commissioner receive copy. ERNST.7. Affiliation Unknown. 79/11/28. 2pp.

- --7912180302 Forwards copy of ltr to Senator Cranaton urging disqualification of Hendrie & Kennedy from further decisions on with.
  - on util. ZIMMERMAN:A. Affiliation Unknown, 79/11/28. 2pp.
- ---7912180507 Forwards copies of 791116 ltrs to Benator Cranston & Representative Penetta urging disqualification of Hendrie & Kennedy from further decisions on PO&E.

  MANZER.R. Affiliation Unknown. 79/11/16. 3pp.
- ---7912180510 Objects to meeting between Hendrie-Kennedy & PQ&E. Urgas disqualification from further decisions on util, MOODY, R., MOODY, D. Affiliation Unknown, 79/11/11. App.
- DOCKET 50-324 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2
- F. Security, medical, emergency & fire protection plans
- 7912200022 Discusses NRC 791109 meeting re amargancy preparadness team review objectives. Provides guidance for improving licensee emergency preparadness & assuring capability of offsite agencies to take appropriate emergency actions.

  ORIMES. B. K. Emergency Preparadness Task Force. 79/11/23. SOpp.
- P. Operating license stage documents & correspondence
- 7912100189 Discusses NRC 791101 meeting w/representatives of N888 vendors & fuel suppliers re discussion of respective partions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EISENHUT. D. G. Division of Operating Reactors. 79/11/09. 65pp.
- --79121002B5 Responds to NRC 791101 request re noncompliance of Hestinghouse ECCS evaluation model under requirements of 10CFR50 App K. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants.
  ANDERSON.T.M. Hestinghouse Electric Corp. 79/11/02. App.
- --7912100330 Responds to NRC 791101 request re ORNL cladding swelling & rupture data. Review of analytical models & tests indicates compliance w/10CFR30 App K. All GE specs for calculated peak cladding temp remain unchanged.

  BUCHHOLZ.R. H. Ganeral Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFRSO. 46 setisfied.

  OHBLEY. O. F. Exxon Nuclear Co.: Inc. (subs. of Exxon Corp.). OHBLEY 0.F. Ex 79/11/02. 5pp
- --7912100455 Forwards addl info re evaluation of impact of NRC proposed rupture/blockage model used in vendor avaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. OMSLEY. 2.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/04. 22pp.
- 7912180319 Forwards safety evaluation for single loop operation. LAINAB.G. Plant Systems Branch. 79/11714. 1p.
- --7912180330 Bafety evaluation supporting license amend for single loop operation. EORO technical evaluation encl. # Office of Nuclear Reactor Regulation. 79/11/14. 13pp.
- 7912040270 Bummarizes revised Cycle 3 startup test rept.Corrects util 79110B submittal. FURR.B.J. Caroline Power & Light Co. 79/11/21. 4pp.
- 7912040505 Forwards revised Cycle 3 summary startup test rept. W/o FURR, B. J. Carolina Power & Light Co. 79/11/21. 4pp.
- 7912040340 Forwards response to NRC 791002 ltr re Dak Ridge Associated Univs radiation eafety training course Requests 3-months notice prior to implementation so that site-specific orientation matt can be prepared.

  UTLEY. E. E. Carolina Power & Light Co. 79/11/29. 1p.
- 7912200630 Notifies of fee assessment for review of 790817 security parsonnel training & qualification plan. Requests payment. D1998, R.M. License Fee Hanagement Branch. 79/12/06. 1p.
- 7912120409 Responds to 791022 ltr by stating interim position for containment purge & vent valve operation pending resolution of isolation valve operability. Verfictation of valve operability will be available by 800107.

  UTLEY, E. E. Carolina Power & Light Co. 79/12/07. 2pp.

- 7912270380 Confirms discussion w/NRC re completion of mods for safety-relief valve indication containment isolation & high-range radiation monitoring. All TMI Lessons Learned Task Force short-term requirements will be completed by 800101. UTLEY.E.E. Carolina Power & Light Co. 79/12/17. 2pp.
- Q. Inspection reports. IE Bulletins & correspondence
- 7910040479 Forwards rept of May 1979 insp by Performance Appraisal Team, Issues in compliance section should be resolved. THORNBURG.H.P. Division of Reactor Construction Inspection. 79/08/29
- --7910040491 Notice of violation from mgt insp on 790514-25.

  \* Region 2, Atlanta, Office of the Director. 79/08/29. 2pp.
- 7912180337 Forwards IE Insp Repts 50-324/79-36 & 50-325/79-37 on 790831-0928 No noncompliance noted. LEWIS.R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/11/06. 2pp.
- --7912180343 IE Insp Repts 50-324/79-36 & 50-325/79-37 on 790831-0928. No noncompliance noted Major areas inspected plant operations, radiation protection OA program organization & administration & core power distribution.

  OUZTB.J. E. Region 2. Atlanta, Office of the Director.

  KELLOGO.P.J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 79/11/06. 6pp.
- 7912060106 Forwards IE Info Notice 79-12A, "Attempted Damage to New Fuel Assemblies." No specific action or response required, O'REILLY, U.P. Region 2, Atlanta, Office of the Director, 79/11/09. 2pp.
- 7912030223 Ack receipt of 791005 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/79-19 t 50-325/79-19.

  0'REILLY, J. P. Region 2, Atlanta, Office of the Director.
  79/11/14. lp.
- ---7912030225 Responds to NRC 790913 ltr re violations noted in IE Insp Repts 50-324/79-19 & 50-325/79-19. Corrective actions: all questionable limiting conditions for operations will be treated as reportable. BANKS.H.R. Carolina Power & Light Co. 79/10/05. Spp.
- --7912030227 Forwards IE Insp Repts 50-324/79-19 & 50-325/79-19 on 790914-23 & notices of violation & deviation. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/09/13. 2pp.
- 7912100160 Forwards IE Info Notice 77-28, "Overloading of Structural Elements Due to Pipe Support Loads," No response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/16. ip.
- 7912110540 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required.
  O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
  '79/11/16. 2pp.
- 7912050626 Ack receipt of 791016 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/79-29 & 50-328/79-30.
  LEWIS,R.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 79/11/20. 1p.
- --7912050629 Responds to NRC 790924 ltr re violations noted in IE Insp Repts 50-324/79-29 & 50-323/79-30, Corrective actions: Operating Procedure 2 revised re reactor recirculation sys. BANKB.H.R. Carolina Power & Light Co. 79/10/16. 2pp.
- --7912030632 forwards IE Insp Repts 50-324/79-29 & 50-328/79-30 on 790702-27 & notice of violation. LEWIB.R.C. Region 2. Atlanta, Reactor Operations Nuclear Bupport Branch. 79/09/24. 2pp.
- --7912050634 Notice of violation from insp on 790702-27.

  \* Region 2, Atlanta, Office of the Director. 79/09/18. ip.
- -7912050641 IE Insp Repts 50-324/79-29 & 50-325/79-30 on 790702-27, Noncompliance noted: failure to have adequate procedure to return recirculation loop to syc. Umission resulted in Unit 1 trip. vrip. OUZTS, J.E. Region 2, Atlanta, Office of the Director. KELLOOG, P. J. Region 2, Atlanta, Reactor Operations Nuclear Bupport Branch. 79/09/18. App.

- 7912070158 Act receipt of 790919 ltm informing NRC of steps taken to correct violations noted in IE Insp Hepts 50-024/79-25 & 50-025/79-26.
  LEWIB.R.C. Region 2. Atlanta, Reactor Operations Nuclear Support
  - 79/11/20
- --7912070160 Responds to NRC 79082B ltr re violations noted in IE Insp Repts 50-324/79-25 & 50-325/79-26. Corrective actions: informed personnel of requirements & cautions to be followed before entering posted area. BANKS-H.R. Carolina Power & Light Co. 79/09/19. 2pp.
- --7912070163 Forwards IE Insp Repts 50-324/79-25 & 50-325/79-26 on 790724-25 & notice of violation.
  LEWIS.R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/08/28. 2pp.
- --7912070166 Notice of violation from insp on 790724-25.

  \* Region 2, Atlanta, Office of the Director, 79/08/16. 1p.
- --7912070167 IE Insp Repts 50-324/79-25 % 50-325/79-26 on 790724-25.
  Noncompliance noted: failure to follow radiation control entry requirements & failure of surveillance procedure to direct sys restoration.

  SKOLDS, J. L. Region 2, Atlanta, Office of the Director.

  KELLOOG, P. J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/08/14. 7pp.
- 7912060609 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on DHRs." No response required. B'REILLY-U.P. Region 2. Atlanta, Office of the Director. 79/11/26. 1p.
- 7912110123 Forwards IE Circular 79-23. "Motor Starters & Contactors Failed to Operate." No response required.
  O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
  79/11/26. [p.
- 7912310507 Notifies of delay in completion of Plant Mod 77-269 revised prints until 800101 & of Plant Mod 77-370 prints until 800501.per IE Insp Repts 50-324/79-02 & 50-324/79-02 & TOLLISON.A.C. Carolina Power & Light Co. 79/11/28. ip.
- 7912040283 Responds to 1E Bulletin 79-01. Util commits to install environmentally qualified limit switches on MSIVs during Spring 1980 refueling outages. New switches are NAMCO Model 740-50100 & meet IEEE criteria.

  UTLEY, E. E. Carolina Power & Light Co. 79/11/29. lp.
- 7912190383 Forwards IE Builetin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Dus During Operation." Written response required. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 79/11/30. 1p.
- 7912310053 Submits revised response to IE Bulletin 79-19 re packaging low level radwaste. All personnel involved in transfer, packaging & transport of radwaste to use mgt-approved detailed instruction & operating procedures.
  FURR.B. J. Carolina Power & Light Co. 79/12/04. 3pp.
- 7912310500 Responds to 1E Bulletin 79-25. "Failures of Westinghouse BFD Relays in Safety-Related Sys." Westinghouse BFD relays not used to not maintained in stock as spares. FURR.B.J. Carolina Power & Light Co. 79/12/05. 1p.
- 7912310264 Responds to IE Bulletin 79-02 Revision 2. "Pipe Bupport Base Plate Designs Using Concrete Expansion Anchor Bolts." Expansion anchors not used in concrete block walls to attach pipe supports in safety-related sys.

  FURR-B. J. Carolina Power & Light Cn. 79/12/06. ip.
- 7912310265 Forwards IE Info Notice 79-30. "Reporting of Defects & Noncompliances, 10CFR21." No action required. O'REILLY,J.P. Region 2. Atlanta, Office of the Director, 79/12/06. 5pp.
- 7912200006 Forwards 1E Bulletin 79-28. "Possible Malfunction of Namto Model EA180 Limit Switches at Elevated Temps." Action required.

  O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
  79/12/07. 2pp.
- 7912310282 Forwards revised response to IE Bulletin 79-01. "Environ Qualification of Class IE Equipment." W/o encl. FURR.B.J. Carolina Power & Light Co. 79/12/12. 2pp.

- 7912280370 Forwards IE Info Notice 79-31. "Use of Incorrect Amplified Rasponse Spectra." No written response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/12/13. 2pp.
- 79[2280119 Forwards IE Circular 79-25, "Shock Arrestor Strut Assembly Interference." No written response required.
  O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
  79/12/20. App.
- R. Periodic operating reports & related correspondence
- 7912130354 Forwards monthly operating rept for Nov 1979. FURR.B. J. Carolina Power & Light Co. 79/12/10. 1p.
- --7912130358 Monthly operating rapt for Nov 1979. WILLIS.E. Carolina Power & Light Co. 79/12/05. 12pp.
- 5. Reportable occurrences, LERs & related correspondence
- 7912130586 Notifies NRC that final rept re deficiencies in procurement, fabrication & insp of engineered plates for concrete embedment & support of safety-related loads will be completed on 791231, Delays caused by extensive rework. CHIANGI,N.J. Carolina Power & Light Co. 79/11/02. 2pp.
- 7912030177 RO: on 791111, during seal replacement of reactor recirculation gump A, nonisolable weld on pump A suction line test connection leaked Line removed & capped Pump test connection B will be modified.

  TOLLISON, A. C. Garolina Power & Light Co. 79/11/12. 1p.
- 7912180477 Forwards LER 79-099/03L-0.
  TOLLISON.A.C. Carolina Power & Light Co. 79/12/06. ip.
- -7912180482 LER 79-099/03L-0: on 791120.coolant iodine activity exceeded Tech Spec limit Caused by two reactor scrams & increase in fission product inventory in coolant from fuel element leak. Fuel bundles to be sipped & leaking bundles to be removed. TDLLISON.A.C. Carolina Power & Light Co. 79/12/04. 1p.
- 7912180533 Forwards LER 79-096/03L-0.
  TOLLISDN, A. C. Carolina Power & Light Co. 79/12/07. 1p.
- --7912180537 LER 79-096/03L-0: on 791115, during reactor low pressure channel calibr & function test, switches 1 & 2 of 2-821-PS-NO21D were out of talerance. Caused by loose actuating cam. Cam set screw tightened & instrument calibr. TOLLISON, A. C. Carolina Power & Light Co. 79/12/07. 1p.
- 7912270279 Forwards LER 79-093/03L-0.
  TOLLISON, A. C. Carolina Power & Light Co. 79/12/07, ip.
- --7912270301 LER 79-093/03L-0: on 791120 during startup, rod 42-33 gave overtravel alarm at notch 48. Apparently caused by loosσ inner filter on σγίνε. Rods will only be pulled to notch 46 until drive unit overhaul during 1980 refueling outage. TOLLISON. A. C. Carolina Power & Light Co. 79/12/07. ip.
- 7912120298 Forwards LER 79-095/03L-0.
  TOLLISON, A.C. Carolina Power & Light Co. 79/12/10. 10.
- --7912120303 LER 79-095/03L-0: on 791110, during relief valve test, pump relief valve lifted at 1,250 psig. Caused by scuffing on stem guide bushing ID & on stem OD. Scuffing cleaned & surfaces polished smooth. TOLLIBON, A. C. Carolina Power & Light Co. 79/12/10. 2pp.
- 7912180494 Forwards LER 79-100/03L-0.
  TOLLISON, A. C. Carolina Power & Light Co. 79/12/13. 1p.
- -7912180498 LER 79-100/03L-0: on 791120, during normal reactor startup, full out indication not received by reactor sequence control ups from control rod 06-27. Caused by defective optical isolator. Isolator replaced, TOLLISON,A.C. Carolina Power & Light Co. 79/12/13. 1p.
- 7912270526 Forwards LER 79-105/03L-0.
  TOLLISON, A. C. Carolina Power & Light Co. 79/12/14. ip.
- --7912270536 LER 79-105/03L-0: on 791201. while replacing indicating light bulb during rod block monitor rod block test, bulb broke & rod block monitor B tripped Caused by base of broken bulb coming in contact tw/ground, Bulb replaced.

  TOLLISON.A.C. Carolina Power & Light Co. 79/12/14. 19.

- 7912270549 Forwards LER 79-101/03L-0.
  TOLLISON, A. C. Carolina Power & Light Co. 79/12/14. 1p.
- --7912270561 LER 79-101/O3L-0:on 791120.during normal reactor startup, intermediate range monitor D did not indicate proper overlap on Range 7.Caused by preamplifier maladjustment Preamplifier adjusted per Maint Instruction 3-15J.
  TOLLISON, A. C. Carolina Power & Light Co. 79/12/14. ip.
- 7912270325 Responds to 790918 ltr requesting addi info on 750326 loss of offsite power at unit.Normal power was off for approx four minutes & restored manually. Unit in cold shutdown. Oscillograph at Castle Hayne road 50% voltage loss.
  UTLEY,E.E. Carolina Power & Light Co. 79/12/18. 2pp.
- 7912270406 Forwards LER 79-103/03L-0.
  TOLL180N,A.C. Carolina Power & Light Co. 79/12/19. ip.
- --7912270414 LER 79-103/03L-0: on 791126, plant chlorine source (railroad tank car) was located in exclusion area while control bldg chlorine detectors out of svc. Caused by shift foreman assumption that detectors were operational.

  TOLLISON, A. C. Carolina Power & Light Co. 79/12/19. 2pp.
- 7912280529 Interim deficiency rept re defective Seismic Class I hanger welds. Final rept will be forwarded on 800130.
  CHIANGI,N, J. Carolina Power & Light Co. 79/12/19. 2pp.
- 7912270559 Forwards LER 79-091/03L-0.
  TOLLISON, A. C. Carolina Power & Light Co. 79/12/20, ip.
- --7912270570 LER 79-091/03L-0: on 791126, during normal plant operation, operator noticed containment atmospheric monitor CAC-AR-1259 was reading upscale on oxygen channel. Caused by blocked sample flow while monitor was sampling torus, TOLLIBON.A, C. Carolina Power & Light Co. 79/12/20. 1p.
- 7912270548 Forwards LER 79-078/03L-0.
  TOLLIBON, A. C. Carolina Power & Light Co. 79/12/21. 1p.
- --7912270558 LER 79-09B/03L-0: on 791129, while replacing section of flex conduit luading to flow switch one lead came in contact w/case. shorting itself & causing RHR logic A power failure.
  Caused by blown F-1 fuse. Fuse replaced.
  TOLLISON, A.C. Carolina Power & Light Co. 79/12/21. 1p.

# DOCKET 50-325 BRUNSHICK STEAM ELECTRIC PLANT, UNIT 1 F. Security, medical, emergency & fire protection plans

- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives. Provides guidance for improving licensee amergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.

  ORIMES, B. K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- P. Operating license stage documents & correspondence
- 7912100189 Discusses NRC 791101 meeting w/representatives of NBSB vandors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses enci.
  EISENHUT, D. G. Division of Operating Reactors. 79/11/09. 65pp.
- ~-7912100255 Responds to NRC 791101 request re noncompliance of Westinghouse ECCS evaluation model under requirements of 10CFR50 App K. Evaluation of three fuel rad models indicates no safety problems for Westinghouse plants.

  ANDERSON.T.M. Westinghouse Electric Corp. 79/11/02. 4pp.
- --7912100330 Responds to NRC 791101 request re DRNL cladding swelling & rupture data.Review of analytical models & tests indicates compliance w/10CFR80 App K. All GE specs for calculated peak cladding temp remain unchanged.

  BUCHHOLZ, R. H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50.46 satisfied.

  OMBLEV.O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/02. 5pp.

- --7912100456 Forwards add) info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. OMBLEY, G.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/04. 22pp
- 7912040340 Forwards response to NRC 791002 ltr re Oak Ridge Associated Univs radiation safety training course Requests 3-months notice prior to implementation, so that site-specific orientation math can be prepared UTLEY, E. E. Carolina Power & Light Co. 79/11/29. 1p.
- 7912200630 Notifies of fee assessment for roview of 790817 security personnel training & qualification plan. Requests payment.

  DIGOS.R.M. License Fee Management Branch. 79712706. Ip.
- 7912120409 Responds to 791022 ltr by stating interim position for containment purge & vent valve operation pending resolution of isolation valve operability. Verfification of valve operability will be available by 800107.

  UTLEY.E.E. Carolina Power & Light Co. 79/12/07. 2pp.
- 7912270380 Confirms discussion w/NRC re completion of mods for safetyrelief valve indication, containment isolation & high-range radiation monitoring. All TMI Lessons Learned Task Force short-term requirements will be completed by 800101. UTLEY, E. E. Carolina Power & Light Co. 79/12/17. 2pp.
- O. Inspection reports. IE Bulletins & correspondence
- 7910040479 Forwards rept of May 1979 insp by Performance Appraisal Team Issues in compliance section should be resolved. THORNBURG.H.P. Division of Reactor Construction Inspection. 79/08/29. 1p.
- --7910040491 Notice of violation from mgt insp on 790514-25.

  \* Region 2, Atlanta, Office of the Director, 79/08/29, 2pg.
- 7912180337 Forwards IE lnsp Repts 50-324/79-36 & 50-325/79-37 on 790831-0928 No noncompliance noted.
  LEHIS.R.C. Region 2, Atlanta. Reactor Operations Nuclear Support Branch. 79/11/06. 2pp.
- --7912180343 IE Insp Repts 50-324/79-36 & 50-325/79-37 on 790831-0928.Nu noncompliance noted. Major areas inspected: plant operations, radiation protection GA programs organization & administration & core power distribution.

  OUZTS.J.E. Region 2. Atlanta, Office of the Director.

  KELLOGO.P.J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 79/11/04. 6pp.
- 7912060106 Forwards IE Info Notice 79-12A, "Attempted Damage to New Fuel Assemblies." No specific action or response required. D'AELLLY, J.P. Region 2. Atlanta, Office of the Director. 79/11/09. 2pp.
- 7912030223 Ack receipt of 791005 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/79-19 & 50-323/79-19.
  O'REILLY, J. P. Region 2. Atlanta, Office of the Director.
- --7912030225 Responds to NRC 790913 ltr re violations noted in IE Insp Repts 50-324/79-19 & 50-325/79-19 Corrective actions: all questionable limiting conditions for operations will be treated as reportable. BANKS,H.R. Carolina Power & Light Co. 79/10/05. Spp.
- --7912030227 Forwards IE Insp Repts 50-324/79-19 & 50-325/79-19 on 790514-25 & notices of violation & deviation. O'REILLY,J.P. Region 2. Atlanta, Office of the Director. 79/09/13. 2pp.
- 79:2100160 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads," No response required. D'REILLY, J.P. Region 2. Atlanta, Office of the Director. 79/11/16. ip.
- 7912110540 Forwards IE Info Notice 79-29. "Less of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required.

  O'REILLY, J.P. Region 2. Atlanta: Office of the Director.
  79/11/16. 2pp.
- 7912050626 Ack receipt of 791016 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/79-29 & 50-323/79-30.
  LEMIS.R.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 79/11/20. 1p.

- --7912050629 Responds to NRC 790924 ltr re violations noted in IE Insp Repts 50-324/79-29 % 50-329/79-30 Corrective actions: Operating Procedure 2 revised re reactor recirculation sys. BANKS:H.R. Carolina Power & Light Co. 79/10/16. 2pp.
- --7912050432 Forwards IE Insp Repts 50-324/79-29 & 50-325/79-30 on 790702-27 & notice of violation.

  LEWIS,R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/09/24. 2pp.
- --7912050634 Notice of violation from insp on 790702-27.

  Region 2, Atlanta, Office of the Director. 79/09/18. 1p.
- --7912050641 IE Insp Repts 50-324/79-29 % 50-325/79-30 on 790702-27.
  Noncompliance nuted: failure to have adequate procedure to return recirculation loop to svc. Umission resulted in Unit 1 trip.
  OUZTS, J. E. Region 2, Atlanta, Office of the Director, KELLOGO, P. J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/09/18. 6pp.
- 7912070158 Ack receipt of 790919 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/79-25 & 50-325/79-26.
  LEWIS,R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/11/20. ip.
- ---7912070160 Responds to NRC 790828 ltr re violations noted in IE Insp Repts 50-324/79-29 & 50-325/79-26. Corrective actions: informed personnel of requirements & cautions to be followed before entering postud area. BANKG.H.R. Carolina Power & Light Co. 79/09/19. 2pp.
- --7912070163 Forwards IE Insp Repts 50-324/79-25 & 50-325/79-26 on 790724-25 & notice of violation. LEHIS.R.C. Region 2: Atlanta, Reactor Operations Nuclear Bupport Branch. 79/08/28. 2pp.
- --7912070166 Notice of violation from insp on 790724-25. \* Region 2, Atlanta, Office of the Director. 79/08/16. ip.
- --7912070167 IE Insp Repts 50-324/79-25 & 50-325/79-26 on 790724-25.
  Noncompliance noted: failure to follow radiation control entry requirements & failure of surveillance procedure to direct sys restoration.
  SKOLDS,J.L. Region 2. Atlanta. Office of the Director.
  MELLOGOP. J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 79/08/16. 7pp.
- 7912080805 Forwards JE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs," No response required.

  O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
  79/11/26. 10.
- 79:2110123 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required.
  O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
  79/11/26. 1p.
- 7912060142 Forwards 1E 1nsp Rept 50-325/79-41 on 791022.No noncompliance noted. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/11/27. 2pp.
- --7912060152 IE Insp Ropt 50-325/79-41 on 791022.No noncompliance noted. Major areas intracted:cause & corrective actions re 791019 trip.
  BILEY, B.M., KELLOGG, P.J. Region 2. Atlanta, Office of the Director. 79/11/21. 2pp.
- 7912310507 Notifies of delay in completion of Plant Mod 79-269 revised prints until 800101 & of Plant Mod 77-370 prints until 800501, per 1E Insp Repts 50-324/79-02 & 50-325/79-02. TOLLISON, A. C. Carolina Power & Light Co. 79/11/28. 1p.
- 7912040283 Responds to IE Bulletin 79-01. Util commits to install environmentally qualified limit switches on MSIVs during Spring 1980 refueling outages. New switches are NAMCO Model 740-50100 & meet IEEE criteria.

  UTLEY.E.E. Carolina Power & Light Co. 79/11/29. 1p.
- 7912190383 Forwards IE Bolletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Hritten response required. D'RETLLY.J.P. Region 2. Atlanta, Office of the Director. 79/11/30. (p.

- 7912310053 Submits revised response to IE Bulletin 79-19 re packaging low level radwaste. All personnel involved in transfer, packaging & transpart of radwaste to use mgt-approved detailed instruction & operating procedures.
  FURR.B.J. Carolina Power & Light Co. 79/12/04. 3pp.
- 7912310500 Responds to IE Bulletin 79-25, "Failures of Westinghouse BFD Relays in Bafety-Related Sys." Westinghouse BFD relays not used & not maintained in stock as spares. FURR.B.J. Carolina Power & Light Co. 79/12/05. 1p.
- 7912310266 Responds to IE Bulletin 79-02, Revision 2. "Pipe Buppart Base Plate Designs Using Concrete Expansion Anchor Bolts." Expansion anchors not used in concrete block walls to attach pipe supports in safety-related sys. FURR.B.U. Carolina Power & Light Co. 79/12/06. 1p.
- 7912310285 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances,10CFR21." No action required.
  0'REILLY, J.P. Region 2, Atlanta, Office of the Director.
  79/12/06. 3pp.
- 7912200006 Forwards IE Bulletin 79-28. "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Tamps." Action required. D'REILLY.J.P. Region 2. Atlanta. Office of the Director. 79/12/07. 2pp.
- 7712310282 Forwards revised response to IE Bulletin 79-01, "Environ Gualification of Class IE Equipment." W/o encl. FURR,B.J. Carolina Power & Light Co. 79/12/12. 2pp.
- 7912280370 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." Να written response required. O'REILLY,J.P. Region 2, Atlanta, Office of the Director. 79/12/13. 2pp.
- 7912280119 Forwards IE Circular 79-25, "Shock Arrestor Strut Assembly Interference." No written response required.
  O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
  79/12/20. 4pp.
- R. Periodic operating reports & related correspondence
- 7912130354 Forwards monthly operating rept for Nov 1979. FURR.B.J. Carolina Power & Light Co. 79/12/10. 1p.
- ---7912130358 Monthly operating rept for Nov 1979. WILLIB.E. Caroline Power & Light Co. 79/12/05. 12pp.
- 8. Reportable occurrences, LERs & related correspondence
- 7912210060 PNO-II-79-012A: on 791019, reactor shut down & coded at 20 F per hour via reactor core isolation cooling sys. Reactor bldg evacuated w/gross beta gamma airborne activities about 30% of may permissible concentration. DANCE, H. C., KELLOGO, P. M. Region 2, Atlanta, Office of the Director. 79/10/19. 1p.
- 7912260019 PNO-II-79-012: on 791019, high steam line radiation signal was received, closing main steam isolation valves & shutting down reactor. Low level airborne radioactivity datected in bidg. Reactor is combing down for investigation.

  DANCE, H. C., KELLDOG, P. J. Region 2, Atlanta, Dffice of the Director. 79/10/19. 1p.
- 79121305B6 Notifies NRC that final rapt re daficiencies in procurement, fabrication & insp of engineered plates for concrete embedment & support of safety-related loads will be completed on 791231. Delays caused by extensive remork. CHIANGI.N. J. Carolina Power & Light Co. 79/11/02. 2pp.
- 7912030177 RO: on 791111, during seal replacement of reactor recirculation pump A, nonisolable weld on pump A suction line test connection leaked. Line removed & capped Pump test connection 8 will be modified.
  TOLLISON, A. C. Carolina Power & Light Co. 79/11/12. 1p.
- 7912200467 PNO-11-79-030: on 791110, during shutdown, water discovered dripping from through mat pipe crack in 0.75-inch test connection from 28-inch reactor collant pump section line. RILEY, B. W., KELLOGO, P. J. Region 2, Atlanta, Office of the Director, 79/11/13. 1p.
- 7912130539 RO-1-79-98: on 791019, reactor core isolation cooling turbine failed to start Caused by sheared bolt on steam exhaust check valve FO40. Unit resumed power valve repaired & leak test satisfactorily completed.

  TOLLISON, A.C. Carolina Power & Light Co. 79/11/15. ip.

- 79:2050432 Forwards LER 79-09B/01T-0.
  TOLLIBON, A. C. Cardina Power & Light Co. 79/11/28. 1p.
- --7912050438 LER 79-098/01T-0:on 791i15, steam exhaust check valve FO40 failed leak test. Caused by sheared bolt & nut lodged in seat of reactor core isolation cooling steam exhaust isolation valve F001. Bolt & nut removed. Leak test successful.
  TGLLISON, A. C. Carolina Power & Light Co. 79/11/28. 2pp.
- 7912080462 Forwards LER 79-099/03L-0.
  TOLLISON, A. C. Carolina Power & Light Co. 79/11/28. ip.
- --7912050470 LER 79-095/OSL-0: on 791106. Units 1 & 2 chloring detectors failed to respond to test solution. Cause not known. Plant chloring source moved outside exclusion area until detectors repaired.

  TOLLISON. A. C. Caroling Power & Light Co. 79/11/28, ip.
- 7912030475 Forwards LER 79-084/03L-0.
  TOLLISON, A. G. Carolina Power & Light Co. 79/11/28. ip.
- --79120504B0 LER 79-084/03L-0:on 791101.FHR flow indicator 1E11-FI-933B indicated 2.500 gpm w/sys not in operation. Cause not etated. Indicator FI333B & transmitter FI 333B calibr & sys returned to svc.
  TOLLIBON.A.C. Carolina Power & Light Co. 79/11/28. 1p.
- 7912110378 Forwards LER 79-097/03L-0. FURR.B.J. Garolina Power & Light Co. 79/12/04. 1p.
- --7912110381 LER 79-097/O3L-0: on 791108, during normal operation, circulating water pump motor feiled & caused diesel generator output breaker to reclose on bus. Caused by locking out of close signal by antipump feature. Plant mods planned. TOLLIBON. A. C. Garolina Power & Light Co. 79/12/Ob. 2pp.
- 7912180603 Forwards LER 79-099/03L-0.
  TOLLISON, A. C. Carolina Power & Light Co. 79/12/07. ip.
- --7912180613 LER 79-099/03L-0: on 791115, during normal reactor stortup, "full in" lights remained lit on control rode 18-11 & 26-11 when rods removed from "full in" position, Caused by short & defective gate on buffer probe cards.

  TOLLISON, A. C. Caroline Power & Light Co. 79/12/07, 1p.
- 7912180549 Forwards LER 79-086/03L-0. TOLLISON, A. G. Carolina Power & Light Co. 79/12/11, ip.
- ---7912180552 LER 79-086/03L-0: on 791119, during normal operation, containment atmospheric monitor CAC-AGH-1263 failed downscale on oxygen channel. Cause unknown, Instrument recalibr. Investigating other monitoring sys.

  TOLLIBON.A.C. Carolina Power & Light Co. 79/12/11. 1p.
- 7912180540 Forwards LER 79-094/03L-0.
  TOLLISON, A. C. Carolina Fower & Light Co. 79/12/14. ip.
- --7912180545 LER 79-094/03L-0: on 791116, during normal operation, broken drive belt was found on containment atmospheric monitor CAC-AGH-1259, Caused by normal wear. Belt added to periodic maint program to detect worn belts in future.

  TOLLISON, A. C. Carolina Power & Light Co. 79/12/14. 1p.
- 7912270306 Forwards LER 79-089/03L-0. TOLLISON A.C. Carolina Power & Light Co. 79/12/17. ip.
- ---7912270317 LER 79-089/03L-0: on 791120, reactor core isolation cooling turbine tripped on mechanical overspeed during scram. Caused by crack in amphenol connector to tachometer pickup. Connector replaced.

  TOLLIBON, A. C. Carolina Power & Light Co. 79/12/17. 2pp.
- 7912270522 Forwards LER 79-103/03L-0, TOLLIBON, A. C. Carolina Power & Light Co. 79/12/19. 1p.
- ---7912270535 LER 79-103/03L-0: on 791205, root valve to Instruments i-E81-P8-N0128 & D found closed Cause unknown, Penstrant test completed successfully & valves left in proper position, TOLLISON, A. C. Carolina Power & Light Co. 79/12/19. 2pp.
- 7912270529 Forwards LER 79-093/03L-0.
  TOLLIBON, A. C. Carolina Power & Light Co. 79/12/19, 1p.

- --7912270541 LER 79-093/03L-0: on 791127, while performing high steamline radiation channel alignment & functional test, main steamline drawer B was out of specs. Caused by instrument drift. Drawer recalibr.
  TOLLISON, A. C. Carolina Power & Light Co. 79/12/19. 2pp.
- 7912270843 Forwards LER 79-104/03L-0.
  TOLLISON, A.C. Carolina Power & Light Co. 79/12/19. 1p.
- --7912270571 LER 79-106/03L-0:on 791207.during core spray sys.component test. "core spray/RHR pump running" annunciator not received.Caused by shut root valves not returned to normal position after testing on 79130.

  \* Carolina Power & Light Co. 79/12/14. 2pp.
- 7912280529 Interim deficiency rept re defective Seismic Class I hanger welds. Final rept will be forwarded on 800130. CHIANGL.N. J. Carolina Power & Light Co. 79/12/19. 2pp.
- 7912270487 Forwards LER 79-102/03L-0.
  TOLLISON, A. C. Carolina Power & Light Co. 79/12/20. ip.
- --7912270490 LER 79-102/O3L-O: on 791129, during normal operation containment atmospheric monitor tripped & could not be restarted. Caused by seized pump bearings. Pump replaced & preventative maint procedure established.
  TGLLISDN.A.C. Carolina Power & Light Co. 79/12/20. 1p.
- 7912270518 Forwards LER 79-092/03L-0.
  TOLLIBON, A. C. Carolina Power & Light Co. 79/12/20. 1p.
- --7912270328 LER 79-092/03L-0: on 791204, during normal plant operation, operator noticed containment atmospheric monitor CAC-ATH-1263 was reading downscale. Caused by blown power supply fuse & shift in instrument zero. Fuse replaced. TOLLISON, A. C. Carolina Power & Light Co. 79/12/20, 2pp.
- 7912270537 Forwards LER 79-091/03L-0, TOLLISON,A.C. Carolina Power & Light Co. 79/12/20. 1p.
- --7912270551 LER 79-091/OSL-0: on 791201, seal staging flow high annunciator was received on recirculation pump 18 & drywell floor drain pump started pumping. Caused by excessive packing leakage of recirculation pump 18 suction.
  TOLLISON, A. C. Carolina Power & Light Co. 79/12/20. 1p.
- 7912270856 RC:on 791129, pressure switch FP-PSL-3963 shorted out, creating short on annunciator card covering Reactor Bldg Zones 13-15. Cause not stated Short at pressure switch removed for repair. New annunciator card ordered.

  TOLLISON.A.C. Carolina Power & Light Co. 79/12/20. 1p.
- 7912270572 Forwards LER 79-107/017-0.
  TOLLIBON, A.C. Carolina Power & Light Co. 79/12/20. 1b.
- --7912270583 LER 79-107/01T-0: on 791212; while performing visual insp of inaccessible anubbers, several snubbers found on safety relief valve F019H tailpipe. Caused by reactor screw when safety relief valves F019F, 0 & H automatically lifted. TOLLIBON: A. C. Carolina Power & Light Co. 79/12/20. 2pp.
- DOCKET 50-326 UNIV. OF CALIFORNIA AT IRVINE RES. REACTOR F. Security, medical, emergency & fire protection plans
- 7912120204 Forwards draft Reg Quide 5.XX, "Std Format & Content for Licensee Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance," W/o encl. REID.R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22. 20n.
- 0. Inspection reports, IE Bulletins & correspondence
- 79:2280207 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Blectra." No written response required.

  GRIER, B. H.

  79/12/13. 1p.
- DOCKET 50-327 SEGUDYAH NUCLEAR PLANT: UNIT 1
- A. Application/construction stage documents & correspondence
- 7712110011 Forwards NRC position on status & applicability to pending OL applications of results of TMT followup actions Outlines add1 short-term actions to be taken.
  VASSALLO.D.B. Division of Project Management. 79/09/27. 41pp.

- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRs & BMRs. Success of program depends on industry response. Supports formation of comers groups to provide necessary info.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912040143 Discusses NRC requirements re operator & senior operator licenses.
  VASALLD, D. B. Division of Project Management. 79/11/01. 2pp.
- 7912060525 Forwards responses to NRC 791004 questions on water level measurement sys inside containment. Responses based on mode to steam generator ref leg design which will be completed before initial criticality.

  MILLS,L.M. Tennessee Valley Authority. 79/12/03. 8pp.
- 7912130001 Forwards request for add1 info re instrumentation & control sys of facility RUBENSTEIN.L.S. Light Water Reactors Branch 4. 79/12/03. 9pp.
- 7912060522 Forwards response to 791026 request for add1 info re review of MCAP-91-57. Includes info re qualification of resistance temp detectors & remote bellows sensing containment pressure transmitters.
  MILLS.L.M. Tonnessee Valley Authority. 79/12/04. 7pp.
- 7912110369 Forwards responses to J Bury 791130 telcon quastions.FSAR will be revised by Amend 64 in accordance w/responses.
  MILLS.L.H. Tennessee Valley Authority. 79/12/05. 33pp.
- 7912130023 Notification of 800110 meeting w/util to discuss reporting level of util GA & manager & GA review of documents.

  SPRAUL, J. G. Guality Assurance Branch. 79/12/05, 1p.
- 7912180074 Notification of ACRS 791207 meeting re plant & low power tests. RUBENSTEIN.L.S. Light Water Reactors Branch 4. 79/12/06. 2pp.
- 7912310396 Notification of 800108 meeting w/utils in Bethesda MD to discuss info request re adequacy of equipment qualification.
  UNDARO, A.R. Power Systems Branch, 79/12/11. 3pp.
- 7912210003 Notification of 791218 meeting w/util in Bethesda.MD to discuss risk assessments. STAHLE.C.B. Light Water Reactors Branch 4. 79/12/13. 3pp.
- 7912210348 Forwards 760329 ltr & drawings re interim auxiliary bldg secondary containment enclosure. Test description excerpts of preoperational test IVA-9A encl. Drawings available in Contral Files only.

  MILLS.L.M. Tempessee Valley Authority. 79/12/13. 39pp.
- --7912210356 Forwards proposal for interim auxiliary bldg secondary containment enclusure.
  GILLELAND.J.E. Tennessee Valley Authority. 76/03/29. 3pp.
- 7912200503 Forwards responses to NUREG-0578, "TMI-2 Lessons tearned Task Force Final Rept."
  MILLS.L.M. Tennessee Valley Authority. 79/12/14, 39pp.
- 7912270363 Forwards affidavit certifying that Amend 63 to util FSAR served on 791221 to parties listed in affidavit.
  MILLS.L.M. Tennessee Valley Authority. 79/12/21. 2pp.
- 7712310352 Discusses Preoperational Test TVA-13, "Onsite AC Distribution Sys." Lists procedures to be followed to ensure safe operation of Unit I. MILLS.L.M. Tennessee Valley Authority. 79/12/21. 2pp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review. Applicants required to make cortain emergency arrangements w/state & local organizations & submit emergency plans per Reg Quide 1. 101.
  VASSALLO. D. D. Division of Project Management. 79/11/21. 6pp.
- и. Utility Final Safety Analysis Report (FSAR) & amends
- 7912100359 Forwards Amend 63 to FSAR, submitted to amend DL application. MILLS, L. M. Tennessee Valley Authority. 79/12/07. 1p.
- --7912100361 Amend 63 to FSAR, submitted to amend OL application. MILLS:L.M. Tennessee Valley Authority. 79/12/07. 16pp.

- 7912270289 Forwards proposed revisions to FSAR Sections 13.2 % 13.5 to be incorporated into Amend 64.in response to 791130 questions by OL reviewer J Buzy.
  MILLS.L.M. Tennessee Valley Authority. 79/12/13. ip.
- --7912270295 Proposed revisions to FSAR Sections 13.2 & 13.5. \* Tennessee Valley Authority. 79/12/13. 10pp.
- 7912270533 Forwards proposed FSAR revisions to be incorporated in Amend 64. Revisions required to resolve inconsistencies between draft Tech Specs & FSAR. Marked-up pages encl. MILLS.L.M. Tennessee Valley Authority. 79/12/19. 12pp.
- G. Inspection reports. IE Bulletins & correspondence
- 7912030061 Forwards IE Insp Rept 30-327/79-49 on 790917-21.No noncompliance noted. LEW18.R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/10/19. 2p.
- --7912030065 IE Insp Rept 50-327/79-49 on 790917-21. No noncompliance noted Major areas inspected startup procedure review, closeout of previous insp item & review of completed preoperational test packages.
  BURNETT, P. T. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. DDNAT, T. J. Region 2. Atlanta, Office of the Director. 79/10/10. 5pp.
- 791206045B Forwards IE Insp Repts 50-327/79-58 & 50-328/79-30 on 791001-05.No noncompliance noted.
  SUTHERLAND.J.T. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 79/10/23. 2pp.
- --7912040447 IE Insp Repts 50-327/79-58 & 50-328/79-30 on 791001-05 No noncompliance noted Major areas inspected preoperational testing of radwaste sys & review of procedures for implementing radiological Tech Specs.

  JACKSON, L. L. Region 2, Atlanta, Office of the Director.

  GIBSON, A.F. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/10/23. 4pp.
- 7912060479 Forwards 1E Insp Rept 50-327/79-54 on 791003.No nencompliance noted. MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 79/10/23. 2pp.
- --7912060486 IE Insp Rept 50-327/79-54 on 791003.No noncompliance noted.
  Major areas inspected: steam generator feedwater line
  radiography.
  CROWLEY.B.R. Region 2. Atlanta, Office of the Director.
  HERDT.A.R. Region 2. Atlanta, Reactor Construction &
  Engineering Support Branch. 79/10/22. 3pp.
- 7912050380 Forwards IE Insp Rept 50-327/79-52 on 791002-04.No noncompliance noted. HURPHY:C.E. Region 2: Atlanta, Reactor Construction & Engineering Support Branch. 79/10/24. 2pp.
- --7912050385 IE Insp Rept 50-327/79-52 on 791002-04, No noncompliance noted Major areas inspected:concrete expansion anchors & setsmic analysis for as-built safety-related piping sys. MDDENOS, L. Region 2. Atlanta. Office of the Director. HERDT.A.R. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 79/10/23. 4pp.
- 7912050486 Forwards IE Insp Repts 90-327/79-53 & 50-328/79-28 on 791002-05. No noncompliance noted. MURPHY.C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/10/25. 2pp.
- --7912050489 IE Insp Repts 50-327/79-53 & 50-328/79-28 on 791002-05.No noncompliance noted Major areas inspected:10CFR50, 55(e) items & inspector followup items onsite & at design ofcs. CANTRELL,F.S. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. ODUGE,M.J. Region 2, Atlanta, Office of the Director. 79/10/25. Spp.
- 7912090627 Forwards IE Insp Rept 50-327/79-57 on 791010-11.No noncompliance noted. LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/10/25. 2pp.
- --7912050631 IE Insp Rept 50-327/79-57 on 791009-11. No noncompliance noted Major areas inspected: review of inspector-identified items, followup on IE circulars & plant tour.
  DANCE, H. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/10/24. Spp.

- 7912040448 Forwards suppl response to IE Bulletins 78-12.78-12A & 78-12B re atypical weld matl in reactor pressure vessel welds. Westinghouse generic rept submitted 791029 covers plants: Final response by 800125.

  MILLB.L.M. Tennessee Valley Authority. 79/10/28. 2pp.
- 7912120248 Forwards IE Insp Rept 50-327/79-62 on 790920-21.No noncompliance noted. SUTHERLAND.J.T. Region 2. Atlanta. Fuel Facility & Materials Safety Branch. 79/11/02. 2pp.
- --7912120255 IE Insp Rept 50-327/79-62 on 790920-21. No noncompliance noted. Major areas inspected: coordination w/offsite support agencies.
  TROJANOMSKI,R.E. Region 2, Atlanta, Office of the Director, HUFHAM, J. W. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/11/01. 3pp.
- 7912180149 Forwards Insp Rept 50-327/79-59 on 791017-18.No noncompliance noted. LEWIB, R.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 79/11/06. 2pp.
- --7912180154 IE Insp Rept 50-327/79-59 on 791017-18. No noncompliance noted. Major areas inspected:completed preoperational test package reviews & review of revised engineer & safety feature survoillance instructions.

  DUNAT.T.J. Region 2. Atlanta, Office of the Director. DYER, J. A. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 79/11/02. App.
- 7912180125 Forwards IE Insp Rept 80-327/79-56 on 790901-30.No noncompliance noted. LEWIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/11/07. 2pp.
- --7912180130 IE Insp Rept 50-327/79-56 on 790901-30. No noncompliance noted. Major areas inspected: movement of SNM, readiness of facility for OL & followup of previously identified items. COTTLE, H. T. Region 2. Atlanta, Office of the Director. DANCE, H. C. Region 2. Atlanta, Reactor Operations Nuclear Bupport Branch. 79/11/07. Δρp.
- 7912040163 Forwards IE Info Notice 79-12A, "Attempted Damage to New Fuel Assembles." No specific action or response required. D'REILLY, P. Region 2, Atlanta, Office of the Director. 79/11/09. 3pp.
- 7912110202 Forwards response to 790330 ltr & IE Bulletin 79-04 re Velan valves. Correct weight valves installed Piping & supports reviewed using correct valve weights.
  MILLS, L. M. Tennessee Valley Authority. 79/11/09. 20pp.
- 7912070499 Forwards IE Info Notice 79-27. "Steam Generator Tube Ruptures at Two PWR Plants." O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 79/11/16. 14pp.
- 7912100192 Forwards IE Info Notice 79-28, "Overloading of Btructural Elements Due to Pipe Support Loads." No response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/16, ip.
- 7912110575 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required.

  O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
  79711146 200
- 7912260147 Forwards IE Insp Rept 50-327/79-61 on 791025.No noncompliance noted.

  MURPHY, C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/11/16. 2pp.
- ~-7912240151 IE Insp Rept 50-327/79-61 on 791115. No noncompliance noted.

  Major areas inspected steam generator feedwater line insp.
  per IE Bulletin 79-13, "Cracking in Feedwater Sys Piping."

  GROWLEY, B. R. Region 2, Atlanta, Office of the Director.

  HERDTIAR. Region 2. Atlanta. Reactor Construction &
  Engineering Support Branch. 79/11/15. 3pp.
- 7912240303 Forwards IE Insp Repts 50-327/79-63 & 50-328/79-31 on 791030-1101. No noncompliance nated. MRFHV.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 79/11/16. 2pp.

- --7912260306 IE Insp Repts 50-327/79-63 & 50-328/79-31 on 791030-1101. No noncompliance noted Major areas inspected: 10CFR50, 55(e) items, noncomformance rept control & safety-related work activities.

  CANTRELL, F.B. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. GOUGE.M.J. Region 2, Atlanta, Office of the Director. 79/11/15. 5pp.
- 7912310326 Forwards IE Insp Repts 50-327/79-60 & 50-328/79-29 on 791009-12. No noncompliance noted.
  MURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/11/16. 2pp.
- --7912310333 IE Insp Repts 50-327/79-60 & 50-328/79-29 on 791009-12.No noncompliance noted. Major areas inspected: fire protection review circuit relocations instrumentation work & work activities.

  GIBBONS.T.D. Region 2. Atlanta, Diffice of the Director. CONLON, T. E. Region 2. Atlanta, Reactor Construction & Engineering Bupport Branch. 79/11/16. 4pp.
- 7912050597 Ack receipt of 791107 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-327/79-46.
  LEWIS,R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/11/20. 1p.
- --7912050&02 Responds to NRC 79101& ltr re violations noted in IE Insp Rept 50-327/79-4A.Corrective actions:engineer placed control switch in normal position & informed persons involved. MILLS.L.M. Tennessee Valley Authority. 79/11/07. 2pp.
- --7912050605 Forwards IE Insp Rept 50-327/79-46 on 790806-31 & netice of violation.

  LENIS.R.C. Region 2. Atlanta, Reactor Operations Nuclear Bupport Branch. 79/10/16. 2pp.
- --7912050628 IE Insp Rept 50-327/79-46 on 790806-31. Noncompliance noted: failure to follow procedure for making temporary alteration on safety-related sys.

  COTTLE, M. T. Region 2. Atlanta, Office of the Director.

  DANCE, H. C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 79/10/02. 7pp.
- 7912050425 Notice of violation from insp on 790806-31.
  \* Region 2, Atlanta, Office of the Director. 79/10/02. ip.
- 7912050307 Forwards responses to deficiences noted in NRC 791031 ltr re IE Insp. Repts 50-327/79-34 & 50-328/79-19. Documentation for hydrostatic testing & flushing of fire protection sys piping now available. MILLS.L.M. Tennessee Valley Authority. 79/11/21. App.
- 7912040620 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No response required.

  O'REILLY,J.P. Region 2, Atlanta, Office of the Director.
  79/11/26. 1p.
- 7912110157 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/26. 1p.
- 7912190472 Forwards IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Written response required. Brightly J.P. Region 2. Atlanta, Office of the Director. 79/11/30. 1p.
- 7912310316 Forwards IE Info Notice 79-30. "Reporting of Defects & Noncompliances,100FR21." No action required.

  D'REILLY, J. P. Region 2. Atlanta, Office of the Director.

  79/12/06. 6pp.
- 7912200060 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EAIBO Limit Switches at Elevated Temps." Action required. 0'REFLLY, J. P. Region 2, Atlanta, Office of the Director. 79/12/07. 3pp.
- 7912310008 Forwards final response to 1E Bulletin 78-120, "Atypical Weld Matl in Reactor Pressure Vessel Welds." Util has reviewed 791029 Westinghouse rept & is satisfied that all specific vessel info required by bulletin included.

  MILLB.L.M. Tennessee Valley Authority. 79/12/11. 2pp.
- 7912280426 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra," No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/12/13. 3pp.

- 7912280190 Forwards IE Circular 79-25, "Shock Arrestor Strut Assembly Interference." No written response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/12/20. 4pp.
- S. Reportable occurrences, LERs & related correspondence
- 7910310325 Forwards final deficiency rept re inadequate lower reactor vessel insulation support.
  MILLS.L.M. Tennessee Valley Authority. 79/10/26, ip.
- --7910310359 Final deficiency rept:as result of IE Info Notice 79-11 review insulation support discovered inadequate to prevent guide tube loading during seismic event. Restraint sys designed to prevent excessive insulation movement.

  \* Tennessee Valley Authority. 79/10/26. 1p.
- 7912120005 PNB-II-79-017: on 791028, conducted emergency drill at plant to test state response in conjunction w/NRC concurrence w/ state emergency plan. Insp team dispatched to site to observe licensee actions.

  JENMINS.O.R. Region 2, Atlanta, Office of the Director. 79/10/29.
- 7912130520 Forwards final deficiency rept re Penn Ventilator Co GA Program.
  MILLS.L.M. Tennessee Valley Authority. 79/11/19. ip.
- 7912050524 Forwards first interim deficiency rept re damaged tubes in containment spray heat exchanger. MILLS.L.M. Tennessee Valley Authority. 79/11/23. 1p.
- --7912050530 First interim deficiency rept re damaged tubes in containment spray heat exchanger. Caused by improper design of tube bundle supports resulting in flow induced vibration. Full flow vibration test scheduled. w Tennessee Valley Authority. 79/11/23. Ip.
- 7912120422 Forwards final deficiency rept re flood area partitions. MILLS.L.M. Tennessee Valley Authority, 79/12/05, 1p.
- --7912120428 Final deficiency rept re flood area partitions not installed in accordance w/design requirements. Design drawings did not consider carbon dioxide pressures. Damaged partitions replaced by panels w/min of 1.5-h barrier rating.

  w Tennessee Valley Authority. 79/12/05. ip.
- 7912120477 Forwards final deficiency rept re fire extinguishers not seismically supported.
  MILLE.L.M. Tennessee Valley Authority. 79/12/05. 1g.
- --79121204Bi Final deficiency rept re fire extinguishers not seismically supported Caused by design oversight Qualified mounting brackets will be installed to secure extinguishers by 800530.

  \*\*Tennessee Valley Authority.
- 7912190574 Forwards final deficiency rept to RCB exceeding heatup & cooldown rates.
  MILES, L. M. Tennessee Valley Authority. 79/12/12. 1p.
- --7912190979 Final deficiency rept to RCS exceeding heatup & cooldown rates. Physical locations of temp elements subject them to localized transient temp changes not indicative of RCB as whole. No corrective action necessary.

  + Tennessee Valley Authority. 79/12/12. 2pp.
- 7912280544 Forwards final deficiency rept re defective design of charcoal adeorber trays.
  HILLS:1..M. Tennessee Valley Authority. 79/12/14. ip.
- --7912280552 Final deficiency rept: on 791116.charcoal absorber trays were found to leak charcoal between frame & perforated plats.
  Caused by design defect due to poorly pop-riveted joint.
  Trays will be removed & replaced.
  \* Tennessee Valley Authority. 79/12/14. ip.
- 7912280591 Forwards first interim deficiency rept re control rod drop events.
  MELLB.L.M. Tennesses Valley Authority. 79/12/17. 1p.
- ---7912280390 First interim deficiency. Dropped rod accident analyses methodology affected nonconservatively by power distribution & reactivity insertion profiles. Extensive evaluation required to establish analytical safety margins.

  \*\*Tennessee Valley Authority. 79/12/17. 1p.

- 7912270473 Forwards final rept on diesel generator field relay coil failures.
  MILLS, L.M. Tennessee Valley Authority. 79/12/18. 1p.
- --7912270476 Final rept on field relay coil failures. Field relay coils replaced & penerators back in svc. # Tennessee Valley Authority. 79/12/18. 2pp.
- DOCKET 50-328 SEGUDYAH NUCLEAR PLANT, UNIT 2

  A. Application/construction stage documents & correspondence
- 7912110011 Forwards NRC position on status & applicability to panding DL applications of results of TMI followup actions. Dutlines addl short-term actions to be taken.
  VASBALLO, D. B. Division of Project Management. 79/09/27. 41pp.
- 79:21:10264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRs & BMRs. Success of program depends on industry response. Supports formation of owners groups to provide necessary info.

  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912060525 Forwards responses to NRC 791004 questions on water level measurement sys inside containment. Responses hased on mods to steam generator ref leg design which will be completed before initial criticality.

  MILLB.L.M. Tennessee Valley Authority. 79/12/03. App.
- 77:213:0001 Forwards request for add1 info re instrumentation & control sys of facility. RUDENSYEIN.L.S. Light Water Reactore Branch 4. 79/12/03. 9pp.
- 7912060322 Forwards response to 791026 request for addl info re review of MCAP-91-57. Includes info re qualification of resistance tamp detectors & remote beliews sensing containment pressure transmitters.

  HILLS,L.M. Tennessee Valley Authority. 79/12/04. 7pp.
- 7912110369 Forwards responses to J Buzy 791130 telcon questions.FBAR will be revised by Amend 64. in accordance w/responses.
  HILLS, L. M. Tennessee Valley Authority. 79/12/05. 33pp.
- 7912130023 Notification of 800110 meeting w/util to discuss reporting level of util GA & manager & GA review of documents.
  SPRAUL, J. Q. Guality Assurance Branch. 79/12/05. 1p.
- 7912180074 Notification of ACRS 791207 meeting re plant & low power tasts.
  RUBENSTEIN, L. S. Light Water Reactors Branch 4. 79/12/05, 20p.
- 7912210003 Notification of 791218 meeting w/util in Bethesda, MD to discuss risk assessments.
  STAHLE, C. B. Light Water Reactors Branch 4. 79/12/13. 3pp.
- 7712210348 Forwards 760329 ltr & drawings re interim auxiliary bldg secondary containment enclosure. Test description excerpts of preoperational test TVA-9A encl. Drawings available in Central Files only.
  MILLS, L. M. Tennesses Valley Authority. 79/12/13. 39pp.
- --7912210356 Forwards proposal for interim auxiliary bldg secondary containment enclosure.
  GILLELAND, J. E. Tennessee Valley Authority. 76/03/29. Gpp.
- 7912200503 Forwards responses to NUREG-0578, "TMI-2 Lessons Learned Task Force Final Rept."
  MILLO,L.M. Tennessee Valley Authority. 79/12/14. 39pp.
- 7912270363 Forwards affidavit cartifying that Amend 63 to util FSAR served on 791221 to parties listed in affidavit.
  MILLS.L.M. Tennessee Valley Authority. 79/12/21. 2pp.
- 7912310352 Discusses Preoperational Test TVA-13, "Onsite AC Distribution Sys." Lists procedures to be followed to ensure safe operation of Unit 1.
  MILLS,L.M. Tennessee Valley Authority. 79/12/21. 2pp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded smergency plans to plants under const & DL review. Applicants required to make certain smergency arrangements w/state & local organizations & submit emergency plans per Reg Quide 1.101.
  VABBALLO, D. B. Division of Project Management, 79/11/21, 6pp.

- K. Utility Final Safety Analysis Report (FSAR) & amends
- 7912100359 Forwards Amend 63 to FBAR, submitted to amend OL application. MILLB.L.M. Tennessee Valley Authority. 79/12/07. 1p.
- --7912100361 Amend 63 to FSAR, submitted to amend OL application.
  MILLS, L.M. Tennessee Valley Authority. 79/12/07. 16pp.
- 7912270289 Forwards proposed revisions to FBAR Bactions 13.2 % 13.5 to be incorporated into Amend 64.in response to 791130 questions by OL reviewer J Buzy.
  MILLG.L.M. Tennessee Valley Authority. 79/12/13. 1p.
- --7912270295 Proposed revisions to FSAR Sections 13.2 & 13.5. \* Tennessee Valley Authority. 79/12/13. 10pp.
- 7912270533 Forwards proposed FBAR revisions to be incorporated in Amend 64. Revisions required to resolve inconsistencies between draft Tech Specs & FSAR. Marked-up pages encl.

  'MILLE.L.M. Tennessee Valley Authority. 79/12/19. 12pp.
- Q. Inspection reports: IE Bulletins & correspondence
- 7912040458 Forwards IE Insp Repts 50-327/79-58 & 50-328/79-30 on 791301-03. No noncompliance noted.

  SUTHERLAND, J. T. Region 2. Atlanta. Fuel Facility & Materials Safety Branch. 79/10/23. 2pp.
- ---79120A0467 IE Insp Repts 50-327/79-58 & 50-328/79-30 on 791001-03. No nancompliance noted Major areas inspected; presperational testing of radwaste sys & review of procedures for implementing radiological Tech Specs.

  JACKBON, L. L. Region 2, Atlanta, Office of the Director.

  91880N.A.F. Region 2, Atlanta, Fuel Facility & Materials Safety Branch, 79/10/23. App.
- 7912050486 Forwards IE Insp Repts 50-327/79-53 & 50-328/79-28 on 791002-05, No noncompliance noted.
  MURPHY.C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/10/25. 2pp.
- --7912050489 IE Insp Repts 50-327/79-53 & 50-328/79-28 on 791002-05. No noncompliance noted Major areas inspected:10CFR50, 55(e) items & inspector followsp items onsite & at design ofcs.
  CANTRELL,F.B. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. ODUDE:M.J. Region 2. Atlanta. Office of the Director. 79/10/25, 5pp.
- 7912040448 Forwards suppl response to IE Bulletins 78-12.78-12A & 78-12B re atypical weld matl in reactor pressure vessel welds. Westinghouse generic rept submitted 791029 covers plants. Final response by 800125.
  MILLS.L.M. Tennessee Valley Authority. 79/10/28. 2pp.
- 7912060163 Forwards IE Info Notice 79-12A, "Attempted Damage to New Fuel Assemblies." No specific action or response required. D'REILLY, J.P. Region 2. Atlanta, Office of the Director, 79/11/09. 3pp.
- 7912110202 Forwards response to 790330 itr & IE Bulletin 79-04 re Velan valves. Correct weight valves installed. Piping & supports reviewed using correct valve weights.

  MILLG.L.M. Tennesses Valley Authority. 79/11/09. 20pp.
- 7912070499 Forwards IE Info Notice 79-27. "Bteam Generator Yube Ruptures at Two PMR Plants." O'REILLY,J.P. Region 2. Atlants. Office of the Director. 79/11/16. 14pp.
- 7912100192 Forwards IE Info Notice 79-20, "Overloading of Structural Elements Dus to Pipe Support Loads." No response required. U'REILLY, U.P. Region 2. Atlanta, Office of the Director. 79/11/16. ip.
- 7912110375 Forwards IE Info Notice 79-29. "Loss of Nonsafaty-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required. O'REILLY.J.P. Region 2. Atlanta. Office of the Director. 79/11/16. 2pp.
- 7912260303 Forwards IE Insp Repts 50-327/79-63 & 50-328/79-31 on 791030-1101. No noncompliance noted. MRRPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 79/11/16, 2pp.

- --7912260306 IE Insp Repts 50-327/79-63 & 50-328/79-31 on 791030-1101. No noncompliance moted. Major areas inspected: 10CFR50. 55(e) items. noncomformance rept control & safety-related work activities.

  CANTRELL,F. 6. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. OUVGE.M. J. Region 2. Atlanta. Office of the Director. 79/11/15. Spp.
- 7912310326 Forwards IE Insp Repts 50-327/79-60 & 50-328/79-29 on 791009-12 No moncompliance noted.
  MURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/11/16. 2pp.
- --7912310333 IE Insp Repts 50-327/79-60 & 50-328/79-29 on 791009-i2. No noncompliance noted. Major areas inspected: fire protection review circuit relocations instrumentation work & work activities.

  918BGNS.T.D. Region 2. Atlanta, Office of the Director. CONLON.T.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/11/16. 4pp.
- 7912050507 Forwards responses to deficiences noted in NRC 791031 ltr re IE Insp Repts 50-327/79-34 & 50-328/79-19. Documentation for hydrostatic testing & flushing of fire protection sys piping now available. MILL8, L. M. Tennessee Valley Authority. 79/11/21. App.
- 7912060620 Forwards IE Circular 79-24. "Proper Installation & Calibr of Care Spray Pipe Break Detection Equipment on DMRs." No response required.
  0'RELLLY.J.P. Region 2. Atlanta. Office of the Director.
  79/11/26. 1p.
- 7912110157 Forwards IE Circular 79-23, "Notor Starters & Contactors Failed to Operate." No response required. D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/26. ip.
- 7912190478 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation." No written response required.

  O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
  79/11/30.
- 7912310316 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action required.
  D'REILLY, J.P. Region 2, Atlanta, Office of the Director.
  779/12/06. dpp.
- 7912200060 Forwards IE Bulletin 79-28, "Possible Halfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required.
  O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
  79/12/07. 30a.
- 791231000B Forwards final response to IE Bulletin 78-128. "Atypical Wold Matl in Reactor Pressure Vessel Welds." Util has reviewed 791029 Westinghouse rept & is satisfied that all specific vessel info required by bulletin included. MILLB.L.M. Tennessee Vailey Authority. 79/12/11. 2pp.
- 7912280426 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra," No written response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/12/13. 3pp.
- 7912280150 Forwards IE Circular 79-25, "Bhock Arrestor Strut Assembly Interference," No written response required.
  O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
  79/12/20. 4pp.
- S. Reportable occurrences. LERs & related correspondence
- 7912130520 Forwards final deficiency rept re Penn Ventilator Co GA Program.
  MILLS, E. M. Tennessee Valley Authority. 79/11/19. 1p.
- 7912050524 Forwards first interim deficiency rept re damaged tubes in containment spray heat exchanger.
  MILLS.L.M. Tennesses Valley Authority. 79/11/23. ip.
- --7912030530 First interim deficiency rept re damaged tubes in containment spray heat exchanger. Gaused by improper design of tube bundle supports resulting in flow induced vibration. Full flow vibration test scheduled.

  \* Tennessee Valley Authority. 79/11/23. ip.
- 7912120422 Forwards final deficiency rept re flood area partitions. MILLB.L.M. Tennessee Valley Authority. 79/12/05. ip.

- --7912120428 Final deficiency rept re flood area partitions not installed in accordance w/design requirements. Design drawings did not consider carbon digride pressures. Damaged partitions replaced by panels w/min of 1 5-h barrier rating.

   Tannessee Valley Authority. 79/12/05. lp.
- 7912120477 Forwards final deficiency rept re fire extinguishers not seismically supported.
  MILLS.L.M. Tennessee Valley Authority. 79/12/05. ip.
- --7912120481 Final deficiency rept re fire extinguishers not seismically supported. Caused by design oversight. Qualified mounting brackets will be installed to secure extinguishers by 800530.
  - \* Tennessee Valley Authority. 79/12/05. 1p
- 7912190974 Forwards final deficiency rept re RCS exceeding heatup & cooldown rates.
  MILLS:L.M. Tennessee Valley Authority. 79712/12. 1p.
- --7912190575 Final deficiency rept re RCS exceeding heatup & cooldown rates. Physical locations of temp elements subject them to localized transient temp changes not indicative of RCS as whole. No corrective action necessary.

  \* Tennessee Valley Authority. 79/12/12. 2pp.
- 7912280544 forwards final deficiency rept re defective design of charcoal adsorber trays.
  MILLS.L.M. Tennessee Valley Authority. 79/12/14. 1p.
- --7912280552 Final deficiency rept: on 791116, charcoal absorber trays were found to leak charcoal between frame & perforated plate, Caused by design defect due to poorly pap-riveted joint. Trays will be removed & replaced.
  \* Tennessee Valley Authority. 79/12/14. lp.
- 791228098: Forwards first interim deficiency rept re control rod drop events. MILLS.L.M. Tennessee Valley Authority. 79/12/17. 1p.
- --7912280590 First interim deficiency. Dropped rod accident analyses methodology affected nonconservatively by power distribution & reactivity insertion grofiles Extensive evaluation required to establish analytical safety wargins.

  \* Tonnessee Valley Authority. 79/12/17. 1p.
- 7912270473 Forwards final rept on diesel generator field relay coil failures. MILLB.L.M. Tennessee Valley Authority. 79/12/18. 1p.
- ---7912270476 Final rept on field relay coil failures.Field relay coils replaced & generators back in svc.
  \* Tennessee Valley Authority. 79/12/18. 2pp.

### DOCKET 50-329 MIDLAND PLANT, UNIT 1

- A. Application/construction stage documents & correspondence
- 7912110011 Forwards NRC position on status & applicability to pending OL applications of results of TMT followup actions, Dutlines add1 short-term actions to be taken.

  VASSALLO.D.B. Division of Project Management. 79/09/27. 41pp.
- 7912140175 Summary of 790718 meeting w/otil Bechtel Corp & ACRS in Bethesda.HD re soil deficiencies at facility site. HODD, D. Light Water Reactors Branch 4. 79/10/16. Spp.
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMB issue for PMRs & DMRs.
  Success of program depends on industry response Supports formation of cumers groups to provide necessary info.
  DENTON.H.R. Office of Nuclear Reactur Regulation. 79/10/17. Spp.
- 7912050294 Forwards D Hood 791002 memo re revised estimate of const completion date for distribution according to board notification svc lists.

  VARGA.S.A. Assistant Director for Light Water Reactors. 79/11/08.
- --7912090305 Discusses 790918-19 site visit re revised estimate of const completion date of June 1982 Heeting summary forthcoming. HOOD, D. Light Water Reactors Branch 4. 79/10/02. 1p.
- 7912100272 Notifies of review of response to NRC 790321 request replant fill settlement & effects at site. Forwards addit questions & positions. Requests response.

  RUBENSTEIN.L.S. Light Water Reactors Branch 4. 79/11/19. 7pp.

- 7912040286 Forwards response to NRC 791025 request re design adequaty of B&W NSSS utilizing once-through steam generators.

  Necessary mods do not require const halt.

  HOMELLS.H. Consumers Power Co. 79/11/30. 141pp.
- 7912070511 Summary of 790904 meeting w/util & Bechtel Corp in BethesdarMD re load sequencing & design stds for diesel generator. HODD,D.S. Light Water Reactors Branch 4. 79/11/30. 18pp.
- 7912110406 Summary of 790927 meeting w/util in Bethesda, MD reactivities undertaken by util to consolidate continuing safety review of plant & concerning implication of TMI-2 accident.

  MODD, D. S. Light Water Reactors Branch 4. 79/11/30. 750.
- 7912120257 Summary of 791114 meeting w/US Corps of Engineers & util re observation of soil settlement at plant sites. HODD.D. Light Water Reactors Branch 4. 79/12/03. 4pp.
- 7912070451 Forwards revised response to NRC 791025 request re design adequacy of B&H sys sensitivity. Utilizing once-through steam generators. Revision provides replacement of preliminary graphs & tables & corrects minor errors.

  HOHELL, S. H. Consumers Power Co. 79/12/04. 150pp.
- 7912120397 Forwards affidavit of svc of Amend 21 issued as Revision 10 to OL environ rept,re util application for CPs & OLs for facilities.

  BACON,J.L. Consumers Power Co. 79/12/07. 4pp.
- 7912270193 Forwards Amend 72 to application for CPs & QLs. HOMELL, S. H. Consumers Fower Co. 79/12/19. ip.
- --7912270197 Amend 72 to application for CPs & QLs, implementing remodial actions re-soil activities for safety-related structures & sys founded in & on plant fill matl.

  HOWELL, S. H. Gonsumers Power Co. 79/12/19, ip.
- C. Utility Environmental Report (ER), amends & correspondence
- 7912030155 Responds partially to NRC request for addl info required to complete environ ropt Forwards applications for discharge & waste water discharge permits & "Rept of Preliminary Archaeological Survey of Transmission Right-of-Way..."
  HONELL, S. H. Consumers Power Co. 79/11/29, 100pp.
- --7912030158 "Rept of Preliminary Archaeological Survey of Transmission Right-of-Way From Midland Plant to Tittabawassem Substation of CPC." TAGGART, D. Michigan, Univ. of. 79/07/31. 14pp.
- 7912030188 Forwards Amend 71 to application for CF & Oi. Submitted as Revision 10 to environ rept.

  HOWELL, S. H. Consumers Power Co. 79/11/30. 2pp.
- --7912030191 Revision 10 to environ rept. \* Consumers Power Co. 79/11/30. 169pp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & DL review. Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Quide 1. 101.

  VASSALLQ, D. B. Division of Project Management. 79/11/21. app.
- G. Adjudicatory correspondence

- 7912060061 Bubmits typographical corrections to CPC post-hearing brief & proposed findings of fact & conclusions of law,Page 31, Footnote 21. Line 9 & Page 94,Line 5. REYNOLDS,W.B. Shaw, Pittman, Potts & Trowbridge. 79/11/08. 1p.
- 7912190029 Responds to 791114 ltr to ASLB re lack of support in record for two comments in util reply brief. Issues before ASLB fully briefed. No further elaboration by parties would serve any useful purpose. REYNOLDS, W. B. Shaw, Pittman, Potts & Troubridge. 79/11/20. 2pp.
- 7912190162 Notifies that fuel loading date for Unit 2 could be delayed until 1983. Definitive revised fuel loading schedule will be campleted in first quarter of 1980. MILLER. M. I. Isham. Lincoln & Beals. 79/11/26. 1p.

- 7912200642 Forwards NRC 791206 order modifying CPs re soil foundation
- nazis onsite. BTELLO,V. Office of Inspection & Enforcement, Office of the Director. CASE,E.G. Office of Nuclear Reactor Regulation. 79/12/06. 1p. STELLO, V.
- ---7912200645 Order modifying CPs by prohibiting excavation, const work or remedial action in soil matts around safety-related structures & sys.

  STELLO,V. Office of Inspection & Enforcement, Office of the Director. CASE.E. Q. Office of Nuclear Reactor Regulation.
  79/12/06. 6pp.
- --7912200448 Notice of violation from insp on 781211-790125.

  # Office of Inspection & Enforcement, Office of the Director. 79/12/06. 4pp.
- --7912200651 Notice of violation from insp on 781211-790125. \* Office of Inspection & Enforcement, Office of the Director. 79/12/06. 2pp.
- 7912270004 Forwards order modifying CPs CPPR-81 & CPPR-82 & notice of violation. CASE.E.O. Office of Nuclear Reactor Regulation. STELLD.V. Office of Inspection & Enforcement. Office of the Director. 79/12/06. ip
- -7912270008 Order modifying CPs CPPR-81 & CPPR-82 re soil activities for safety-related structures & sys. CABE.E.Q. Office of Nuclear Reactor Regulation. STELLO,V. Office of Inspection & Enforcement, Office of the Director. 79/12/06.
- --7912270009 Notice of violation from insp on 781211-790125.
  Noncompliances noted:inconsistencies in license application & design basis documents & failure to provide insp hold points to verify soil work.

  \* Office of Nuclear Reactor Regulation. 79/12/06. 4pp.
- 7912140100 Forwards order modifying CPs & two notices of violation describing items of noncompliance re soil settlement matter. Wo encl.

  OLMSTEAD, W. J. Hearing Branch 4. 79/12/07. ip.
- 7912280083 Forwards NRC 791206 order modifying CPs issued to CPC. W/s encl. STELLO.V. Office of Inspection & Enforcement, Office of the Director. 79/12/17. 1p.
- 7912290086 Forwards NRC 791206 order modifying CPs issued to CPC. W/o encl. BTELLO.Y. Office of Inspection & Enforcement, Office of the Director. 79/12/17. ip.
- 7912310337 Requests hearing on behalf of utilire Amend 72 to application for CPs & OLs.
  MILLER,M.I. Isham, Lincoln & Beale. 79/12/26. 3pp.

# H. General correspondence

7912060508 Notifies that offsite radiation protection training course for NRC inspectors B satisfactory, Requests advance notification of arrival of NRC personnel.

LOUDENSLAGER.T. Consumers Power Co. 79/12/03. lp.

### M. Antitrust correspondence

- 7912070120 Errata to proposed liconse conditions filed w/CPC & intervenors joint 790925 motion supporting license conditions. Intervenors. DDJ & NRC concur w/corrections. Certificate of 8vc encl. ROSS, W. W., WATSON, K. S. Consumers Power Co. 79/11/28. 22pp.
- 7912180212 Errata to proposed antitrust license conditions contained in 790925 joint motion, NRC intervenors & DOI concur in corrections, Complete set of proposed license contitions, reflecting corrections, encl. Certificate of Svc encl. ROSS, W.W. Consumers Power Co., ROSS, W.W. Wald, Herkrader & Ross, 79/11/28. 22pp.
- G. Inspection reports, IE Bulletins & correspondence
- 7912030260 Forwards IE Insp Repts 50-329/79-20 & 50-330/79-20 on 790918-20 & notice of violation. FIORELLIG. Region 3. Chicago. Reactor Construction & Engineering Support Branch. 77/10/10. 2pp.

- --7912030262 Notice of violation from insp on 790918-20.

  \* Region 3, Chicago, Reactor Construction & Engineering Support Branch, 79/10/09, ip.
- --7912030263 IE Insp Repts 50-329/79-20 & 50-330/79-20 on 790918-20. Noncompliance noted: failure to control special processes. NAIDU.K.R., HAYEG.D.W. Region 3, Chicago, Office of the Director: 79/10/09. Bpg.
- 7912030249 Forwards IE Insp Repts 50-329/79-21 & 50-330/79-21 on 790925-27. No noncompliance noted. FIDRELLI, G. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 79/10/11. 2pp.
- ---7912030257 IE Insp Repts 50-329/79-21 & 50-330/79-21 on 790925-27.No noncompliance noted Major areas inspected preservice inspects work activities & nondestructive examination data & repts.
  WARD.K.D. Region 3, Chicago, Office of the Director.
  DANIELSON.D.H. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/10/10. Spp.
- 7912260129 Forwards IE Insp Repts 50-329/79-22 & 50-330/79-22 on 791010-12 & notice of violation. FIDRELLI,0 Region 3. Chicago, Reactur Construction & Engineering Support Branch. 79/10/30. 2pp.
- ---7912260133 Notice of violation from insp on 791010-12.
  \* Region 3, Chicago, Office of the Director. 79/ 79/10/29. In.
- -7912240137 iE Insp Repts 50-329/79-22 & 50-330/79-22 on 791010-12. Noncompliance noted: lack of weld & rod control. VANDEL.T.E., NAIDU.K.R. & KNOP.R.C. Region 3, Chicago, Office of the Director. 79/10/29. 18pp.
- 7912200128 Forwards IE Insp Repts 50-329/79-23 & 50-330/79-23 on 791025. No noncompliance noted.

  KEPPLER.J.G. Region 3. Chicago. Office of the Director. 79/11/08.
- 7912050122 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required. KEPPLER.J.G. Region 3. Chicago. Office of the Director. 79/11/16.
- 7912100223 Forwards TE Info Notice 79-28, "Gverloading of Structural Elements Due to Pipe Support Loads." No response required. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/14.
- 79:21:0574 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required KEPPLER.J. G. Region 3. Chicago, Office of the Director. 79/11/14.
- 79:2050370 Forwards IE Bulletin 79-24, "Boron Loss From BWR Control Blades." No response required.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/20.
- 7912100425 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BMRs." No written response required.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/26.
- 7912110249 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. KEPPLER, J. G. Region 3. Chicago, Office of the Director. 79/11/26.
- 7912120172 Ack receipt of 791031 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-329/79-19 & 50-330/79-19.
  KEPPLER.J.O. Region 3. Chicago. Defice of the Director. 79/11/26.
- --7912120180 Responds to NRC 791010 ltr re violations noted in IE Insp Hepts 50-329/79-19 & 50-330/79-19 Corrective actions: training records for const GC personnel updated to accurately reflect actual training. HOWELL, S. H. Consumers Power Co. 79/11/26. Bpp.
- 7912110420 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs cupies of escalated enforcement correspondence sent by NRC to licensees.

  KEPPLER.J.O. Region 3. Chicago. Office of the Director. Region 3. Chicago. Office of the Director. 79/11/28.

- 7912060012 Ack receipt of 791106 ltr informing NRC of eteps taken to correct violations noted in IE Insp Repts 50-329/79-20 & 50-330/79-20. PluRELI.0. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 79/11/30. ip.
- --7912040015 Responds to NRC 791010 ltr re violations noted in IE lasp Repts 50-329/79-20 & 50-330/79-20. Corrective actions: procedures re formal design changes revised by Bechtel. HOHELL.S.H. Consumers Power Co. 79/11/04. 3pp.
- 7912190218 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation."
  No written response required.
  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/30.
- 7912140077 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances: 10CFR21." No action or response required. KEPPLER. J. O. Region 3. Chicago, Office of the Director. 79/12/06.
  - 7912200108 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. KEPPLER, J. G. Region 3, Chicago, Dffice of the Director. 79/12/10.
  - R. Periodic operating reports & related correspondence
  - 7912040110 Forwards Bechtel nonconformance repts, logs, quality audit findings, action requests, BAN nonconformance repts, inservice insp nonconformance repts & util nonconformance repts, audit findings & corrected action repts for Dct 1979.
    HOWELLS.H. Consumers Power Co. 79/11/21. 450pp.
  - 7912280522 Forwards quarterly rept for period 800101-0331 re Bechtel supervisors & engineers expected to be on const site. HDMELL.8.H. Consumers Power Co. 79/12/21. 34pp.
  - S. Reportable occurrences, LERs & related correspondence
  - 7912130418 Ack receipt of 791026 interim deficiency rept re terminal blocks & cracked disconnect links.
    FIORELLI, 0. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 79/11/14. ip.
  - 7912170059 Ack receipt of 791026 interim deficiency rept re feedwater piping impact qualities.
    FIORELLI, 0. Division of Reactor Construction Inspection. 79/11/15.
    1p.
  - 7912170103 Ack receipt of 791025 interim deficiency rept re terminal black disconnect links. FIDRELLI, 0. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 79/11/15. 1p.
  - 7912170416 PNO-III-79-048: on 791127, electrician received shock from energized circuit breaker cabinet. Caused by electrican, unaware breaker was energized hiding tool box in breaker cabinet so he could go to lunch.
    KNOP.R.C., FIGRELLI.C. Region 3, Chicago, Office of the Director, 79/11/28. 10.
  - 7912110358 Interim deficiency rept re safe shutdown buration capability. Bechtel preparing sys design to increase safety-grade boration capability. Finalization of sys design estimated by end of Mar 1980. Next rept by 800411.
    HOWELL, S. H. Consumers Power Co. 79/12/06. 2pp.
  - 7912130219 Forwards final deficiency rept re main feed pipe spools. HDNELL.S.R. Consumers Power Co. 79/12/10. 2pp.
  - --7912130224 Final deficiency rept re main feed pipe spools NRC found nine pipes not in compliance w/ASME code physical impact requirements. One hot bend spool being replaced others nearth articles of the second temp of 70 F. vional Corp. 79/11/19. App.

; of diesel

. Engineering

- 7912180176 Interim deficiency rept re containment internal structures coatings w/loss of adhesion. Evaluation of corrective action being undertaken by Bechtel. Next rept will be submitted by 800215. Mgt correction action rept encl.
  HDWELL G. H. Consumers Power Co. 79/12/13. Opp.
- 79)2180826 Interim deficiency rept re in-containment coatings which have loss of adhesion between successive layers of coating sys. Approx 600 square ft of surface under investigation. MOMELL, S.H. Consumers Power Co. 79/12/13. 6pp.
- 7912110365 Forwards interim deficiency rept re broken anchor bolt in reactor vessel support skirt flange. HOWELL, S. H. Consumers Power Co. 79/12/14. 1p.
- --7912110373 Interim deficiency rept re broken anchor bolt in reactor vessel support skirt flange. Anchor stud purchased from MB Valley Btructural Stoel Co. who procured matl from Bouthern Bolt & Fastner Corp.

  \*\* Consumers Power Co. 79/12/05. 2pp.
- 7912130544 Interim deficiency rept re broken reactor vessel anchor stud. Vessel support skirt flange anchor bolt broke. Testing for cause of break will be completed by mid Jan 1980, W/results available by mid Feb 1980.
  HO
- 7912280483 Final deficiency rept re reactor bidg spray piping supports. Stresses are within code allowables Grinnell analysis & plant drawings reconciled w/actual hardware. Plant is in conformance w/design requirements.

  HDWELL, B. H. Consumers Power Co. 79/12/21. ip.
- 7912280560 Forwards final deficiency rept re failure of Hilti drap-in anchors to meet tension testing requirements.
  HOWELL, S. H. Consumers Power Co. 79/12/21. ip.
- --7912280565 Final deficiency rept me failure of Hilti drop-in anchors to meet tension testing criteria. Testing program will devalop ultimate loads for drop-in anchors which are not completely set. HORK, J.O. BAILEY, K. Bechtel Associates Professional Corp. 79/11/30. Spp.

### DOCKET SO-330 HIDLAND PLANT, UNIT 2

- A. Application/construction stage documents & correspondence
- 7912110011 Forwards NRC position on status & applicability to pending OL applications of results of TMI followup actions. Outlines addl short-term actions to be taken.
  VASBALLD, D. B. Division of Project Management. 79/09/27. 4ipp.
- 7912140175 Summary of 790718 meeting w/util.Bechtel Corp & ACRB in Bethesda,MD re soil deficiencies at facility site.

  HOOD,D. Light Water Reactors Branch 4. 79/10/16. App.
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRs & BMRs. Buccess of program depends on industry response. Supports formation of owners groups to provide necessary info. DENTON, M.R. Office of Nuclear Reactor Regulation. 79/10/17. Gpp.
- 7912050294 Forwards D Hood 791002 memo re revised estimate of const completion date for distribution according to board notification syc lists.
  VAROA.B.A. Assistant Director for Light Water Reactors. 79/11/08, 2pp.
- --7912050305 Discusses .790918-19 site visit re revised estimate of const completion date of June 1982. Meeting summary forthcoming. HOOD, D. Light Water Reactors Branch 4. 79/10/02. ip.
- 7912100272 Notifies of review of response to NRC 790321 request replant fill settlement & effects at site. Forwards addit questions & positions. Requests response.

  RUBENSTEIN.L. B. Light Water Reactors Branch 4, 79/11/19. 7pp.
- 7912040286 Forwards response to NRC 791025 request re design adequacy of B&W NBSB utilizing once-through steam generators.

  Necessary mode do not require const halt.

  HOWELL, B. H. Consumers Power Co. 79/11/30. 141pp.
- 7912070511 Summary of 790906 meating w/util & Bechtal Corp in Bethesda.MD re load sequencing & design stds for dissel generator. HOOD.D.B. Light Water Reactors Branch 4. 79/11/30. 18pp.

- 7912110406 Bummary of 790927 meeting w/util in Bethesda,MD reactivities undertaken by util to consolidate continuing safety review of plant & concerning implication of TMI-2 accident.

  HOOD, D. B. Light Water Reactors Branch 4. 79/11/30. 700.
- 7912120257 Summary of 791114 menting w/US Corps of Engineers & util re observation of soil settlement at plant sites. HOOD, D. Light Water Reactors Branch 4. 79/12/03. 4pp.
- 7912070451 Forwards revised response to NRC 791025 request re design adequacy of B&H sys sensitivity. Utilizing once-through steam generators. Revision provides replacement of preliminary graphs & tables & corrects minor errors.

  HOWELL, B. H. Consumers Power Co. 79/12/04. 150pp.
- 7912120397 Forwards affidevit of svc of Amend 21, issued as Revision 10 to DL environ rept, re util application for CPs & OLs for facilities.

  BACON, J. L. Consumers Power Co. 79/12/07. 4pp.
- 7912270193 Forwards Amend 72 to application for CPs & OLs. HOWELL, B. H. Consumers Power Co. 79/12/19. ip.
- ---7912270197 Amend 72 to application for CPs & OLs, implementing remedial actions re soil activities for safety-related structures & sys founded in & on plant fill matl.
  HUMELL,S.H. Consumers Power Co. 79/12/19. 1p.
- C. Utility Environmental Report (ER), amends & correspondence
- 7712030165 Responds partially to NRC request for addl info required to complete environ rept. Forwards applications for discharge & waste water discharge permits & "Rept of Preliminary Archaeclogical Burvey of Transmission Right-of-May..."

  HOWELL, B. H. Consumers Power Co. 79/11/29. 100pp.
- --7912030158 "Rept of Preliminary Archaeological Survey of Transmission Right-of-Way From Midland Plant to Tittabawassoe Substation of CPC." TAGGART.D. Michigan Univ. of. 79/07/31. 14pp.
- 7912030168 Forwards Amend 71 to application for CP & OL. Submitted as Revision 10 to environ rept. HOWELL: S. H. Consumers Power Co. 79/11/30. 2pp.
- --7912030191 Revision 10 to environ rept. \* Consumers Power Co. 79/11/30. 169pp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & DL review Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Quide 1.101.
  VABBALLO.D.B. Division of Project Management. 79/11/21. App.
- O. Adjudicatory correspondence
- 7912060061 Submits typographical corrections to CPC post-hearing brisf & proposed findings of fact & conclusions of law, Page 31, Fontnote 21, Line 9 & Page 94. Line 5. REYNOLDS, W. D. Bhaw, Pittman, Potts & Trowbridge, 79/11/08. 1p.
- 7912190029 Responds to 791114 ltr to ASLB re lack of support in record for two comments in util reply brief. Issues before ASLB fully briefed. No further elaboration by parties would serve any useful purpose.
  REYNOLDS.W.B. Shaw, Pittman, Potts & Trowbridge. 79/11/20. 2pp.
- 7912190162 Notifies that fuel loading date for Unit 2 could be delayed until 1983 Definitive revised fuel loading schedule will be completed in first quarter of 1980.
  MILLER,M.I. Isham, Lincoln & Beale. 79/11/26. ip.
- 7912200642 Forwards NRC 791206 order modifying CPs re soil foundation matls onsite.
  BYELLO.V. Office of Inspection & Enforcement, Office of the Director. CARE, E. Q. Office of Nuclear Reactor Regulation.
  79/12/06. ip.
- --7912200645 Order modifying CPs by prohibiting excavation, const work or remedial action in soil matls around safety-related structures & sys.

  BTELLO, V. Office of Inspection & Enforcement, Office of the Director, CABE, E, 9. Office of Nuclear Reactor Regulation. 79/12/06. 6pp.

- --7912200648 Notice of violation from insp on 781211-790125.

  \* Office of Inspection & Enforcement, Office of the Director.
  79/12/06. 4pg.
- --7912200651 Notice of violation from insp on 781211-790125.

  \* Office of Inspection & Enforcement, Office of the Director.
  79/12/06. 2pp.
- 7912270004 Forwards order modifying CPs CPPR-81 & CPPR-82 & notice of violation.
  CASE.E.G. Diffice of Nuclear Reactor Regulation. STELLB,V. Office of Inspection & Enforcement, Office of the Director. 79/12/06. 1p.
- --791227000B Order modifying CPs CPPR-B1 & CPPR-B2 rs soil activities for safety-related structures & sys.

  CASE,E. G. Office of Nuclear Reactor Regulation. BIELLO,V. Office of Inspection & Enforcement, Office of the Director. 79/12/04.
- --7912270009 Notice of violation from insp on 781211-790125.

  Noncompliances noted: inconsistencies in license application & design basis documents & failure to provide insp hold points to verify soil work.

  \* Office of Nuclear Reactor Regulation. 79/12/06. 4pp.
- 7912140100 Forwards order modifying CPs & two notices of violation describing items of noncompliance re soil settlement matter. M/o encl.

  OLMSTEAD. W. J. Hearing Branch 4. 79/12/07. 1p.
- 7912280083 Forwards NRC 791206 order modifying CPs issued to CPC. W/o encl.

  8TELLO,V. Office of Inspection & Enforcement, Office of the Director. 79/12/17. ip.
- 79122B0086 Forwards NRC 791206 order modifying CPs issued to CPC.W/o encl.
  STELLO,V. Office of Inspection & Enforcement, Office of the Director. 79/12/17. ip.
- 7912310339 Requests hearing on behalf of utilize Amend 72 to application for CPs & OLs.
  MILLER, M. I. Isham, Lincoln & Beale. 79/12/26. 3pp.
- H. General correspondence
- 791206050B Notifies that offsite radiation protection training course for NRC inspectors B satisfactory. Requests advance notification of arrival of NRC personnel. LOUDENSLAGER, T. Consumers Power Co. 79/12/03. 1p.
- M. Antitrust correspondence
- 7912070120 Errata to proposed license conditions filed u/CPC & intervenors joint 790925 motion supporting license conditions. Intervenors. DBJ & NRC concur u/corrections. Cartificate of Svc encl.
  RDSG.M.W. WATSON.K.S. Consumers Power Co. 79/11/28. 22pp.
- 7912180212 Errata to proposed antitrust license conditions contained in 790925 joint motion.NRC.intervenors & DDI concur in corrections. Complete set of proposed license contitions, reflection corrections, encl. Certificate of Svc encl. ROSS. W. W. Consumers Power Co. ROSS. W. W. Wald, Harkrader & Ross. 79/11/28. 22pp.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912030260 Forwards IE Insp Repts 50-329/79-20 & 30-330/79-20 on 790918-20 & notice of violation.
  FIORELLI, 0. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 79/10/10. 2pp.
- --7912030262 Notice of violation from insp on 790918-20.

  \* Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/10/09. 1p.
- --7912030263 IE Insp Repts 50-329/77-20 & 50-330/79-20 on 790918-20. Noncompliance noted: failure to control special processes. NAIDU, K. R. , HAYES, D. H. Region 3, Chicago, Office of the Director, 79/10/09. Spp.
- 7912030249 Forwards IE Insp Repts 50-327/79-21 & 50-330/79-21 on 790925-27. No noncompliance noted. FIGRELLIG. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/10/11. 2pp.

- --7912030257 IE lisp Repts 50-329/79-21 & 50-330/79-21 on 790925-27. No nancompliance noted Major areas inspected preservice inspure activities & nondestructive elamination data & repts. WARD.K.D. Region 3, Chicago. Office of the Director. DANIELEGUN.D H. Region 3, Chicago. Reactor Construction & Engineering Support Branch. 79/10/10. Spp.
- 7912260129 Forwards LE Insp Repts 50-329/79-22 & 50-330/79-22 on 791010-12 & notice of violation. FIDRELLIO. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 79/10/30. 2pp.
- --7912260133 Notice of violation from insp on 791010-12. \* Region 3, Chicago, Office of the Director. 79/10/29. ip.
- --7912240137 IE insp Repts 50-329/79-22 & 50-330/79-22 on 791010-12.
  Noncompliance noted: lack of weld & rod control.
  VANDELIT.E., NAIDULK.R., KNDP.R.C. Region 3, Chicago, Office of the Director. 79/10/29. 18pp.
- 7912200128 Forwards IE Insp Repts 50-329/79-23 & 50-330/79-23 on 791025.No noncompliance noted.

  KEPPLER.J.O. Region 3. Chicago, Office of the Director. 79/11/08.
- 7912050122 Forwards IE Circular 79-22. "Stroke Times for Power Operated Relief Valves." No response required. KEPPLER.J.G. Region 3. Chicago, Office of the Director. 79/11/16.
- 79:2100223 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required KEPPLER.J.C. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912110574 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required.

  KEPPLER.J. G. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912050370 Forwards IE Bulletin 79-24, "Boron Loss From BWR Control Blades." No response required. KEPPLER.J.O. Region 3. Chicago, Office of the Director. 79/11/20.
- 7912100425 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on DWRs." No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/26.
- 7912110249 Forwards IE Circular 79-23. "Motor Starters & Contactors Failed to Operate." No response required. KEPPLER, J. G. Region 3. Chicago. Office of the Director. 79/11/26. Ip.
- 7912120172 Ack receipt of 791031 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-329/79-19 % 50-329/79-19 % KEPPLER, J. G. Region 3. Chicago. Office of the Director. 79/11/24.
- --7912120180 Responds to NRC 791010 ltr re violations noted in IE Insp Repts 30-329779-19 & 50-330/79-19. Corrective actions: training records for const GC personnel updated to accurately reflect actual training. HOWELL, S. H. Consumers Power Co. 79/11/26. Opp.
- 7912110420 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofts copies of escalated enforcement correspondence sent by NRC to licensees
  KEPPLER, J. 9. Region 3: Chicago, Office of the Director. 79/11/28.
- 7912060012 Ack receipt of 791106 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-329/79-20 & 50-330/79-20.
  FIGRELLI G. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 79/11/30. ip.
- --7912060015 Responds to NRC 791010 ltr re violations noted in IE Insp Repts 50-329/79-20 & 50-330/79-20 Corrective actions; procedures re formal design changes revised by Bechtel. HOHELL, S. H. Consumers Power Co. 79/11/06. 3pp.

- 7912190218 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." No written response required. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/30, ip.
- 7912140077 Forwards IE Info Notice 79-30. "Reporting of Defects & Noncompliances, iOCFR21." No action or response required.
  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/12/06.
- 791220010B Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. KEPPLER.J.G. Region 3. Chicago, Office of the Director. 79/12/10.
- A. Periodic operating reports & related correspondence
- 7912040110 Forwards Bechtel nonconformance repts, logs, quality audit findings, action requests, B&H nonconformance repts, inservice insp nonconformance repts & util nonconformance repts, audit findings & corrected action repts for Oct 1979, HOWELL, S. H. Consumers Power Co. 79/11/21. 450pp.
- 7912280822 Forwards quarterly rept for pariod 800101-0331 rs Bachtel supervisors & engineers expected to be on const site. HOHELL, S. H. Consumers Power Co. 79/12/21. 34pp.
- S. Reportable occurrences, LERs & related correspondence
- 7912130418 Ack receipt of 791026 interim deficiency rept re terminal blocks & cracked disconnect links. FIORELLI, 9. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 79/11/14. 1p.
- 7912170059 Ack receipt of 791026 interim deficiency rept re feedwater piping impact qualities. FIORELLI.G. Division of Reactor Construction Inspection. 79/11/15.
- 7912170105 Ack receipt of 791026 interim deficiency rept re terminal block disconnect links.
  FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/11/15. 1p.
- 7912170416 PNO-III-79-048: on 791127, electrician received shock from emergized circuit breaker cabinet. Caused by electrican, unaware breaker was emergized, hidding tool hox in breaker cabinet so he could go to lunch.

  KNOP.R.C., FICRELLI.C. Region 3, Chicago, Office of the Director. 79/11/28. lp.
- 79:211035B Interim deficiency rept re safe shutdown boration capability. Bechtel preparing sys design to increase safety-grade boration capability. Finalization of sys design estimated by end of Mar 1980. Next rept by 800411.

  HOWELL, S. H. Consumers Power Co. 79/12/06. 2pp.
- 7912130219 Forwards final deficiency rept re main feed pipe spools. HOMELL, B. H. Consumers Power Co. 79/12/10. 2pp.
- --7912:130224 Final deficiency rept re main faed pipe spools. NRC found nine pipes not in compliance w/ABME code physical impact requirements. One hot bend spool being replaced. Others operate satisfactorily at min syc temp of 70 F. ANDERSON. D. Dechtel Associates Professional Corp. 79/11/19. App.
- 7912170062 Ack receipt of 791102 interim rept re settlement of diesel generator foundations & bldg. Completed review will be performed upon receipt of final rept. FIORELLI, 0. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 79/12/12. ip.
- 7912180176 Interim deficiency rept re containment internal structures coatings w/loss of adhesion. Evaluation of corrective action being undertaken by Bechtel. Next rept will be submitted by 800215. Mgt correction action rept encl.
  HOWELL.S.H. Consumers Power Co. 79/12/13. App.
- 7912180524 Interim deficiency rept re in-containment coatings which have loss of adhesion between successive layers of coating sys. Approx 600 square ft of surface under investigation. HOMELLE.B.H. Consumers Power Co. 79/12/13. 6pp.
- 7912110365 Farwards interim deficiency rept re broken anchor bolt in reactor vessel support skirt flange. HOHELL, B. H. Consumers Power Co. 79/12/14. ip.

- --7912110373 Interim deficiency rept re broken anchor boilt in reactor vessel support skirt flange. Anchor stud purchased from MB Valley Structural Steel Co, who procured matl from Southern Bolt & Fastner Corp.

  \*\* Consumers Power Co. 79/12/05. 2pp.
- 7912130544 Interim deficiency rept to broken reactor vessel anchor stud. Vessel support skirt flange anchor bolt broke. Testing for cause of break will be completed by mid Jan 1980, w/results available by mid Feb 1980.

  HOHELL, S. H. Consumers Power Co. 79/12/14. 2pp.
- 7912280483 Final deficiency rept re reactor bidg spray piping supports. Stresses are within code allowables Grinnell analysis & plant drawings reconciled w/actual hardware Plant is in conformance w/design requirements.

  HDHELL, S. H. Consumers Power Co. 79/12/21. ip.
- 7912280560 Forwards final deficiency rept re failure of Hilti drop-in anchors to meet tension testing requirements.
  HQWELL.S.H. Consumers Power Co. 79/12/21. 1p.
- --7912280565 Final deficiency rept re failure of Hilti drop-in anchors to meet tension testing criteria. Testing program will develop ultimate loads for drop-in anchors which are not completely set.

  HOOK, J. G. BAILEY, K. Bechtel Associates Professional Corp.
  79/11/30, 5pp.

### DOCKET 50-331 DUANE ARNOLD ENERGY CENTER

- F. Security, medical, emergency & fire protection plans
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives. Provides guidance for improving licensee emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.

  ORIMES, B. X. Emergency Preparedness Task Force. 79/11/23, 30pp.
- 7912040350 Forwards responses to questions raised re fire protection analysis. Diesel generator room drawings encl.
  ROOT. L. D. Iowa Electric Light & Power Co. 79/11/29. 10pp.
- J. Insurance & indemnity information
- 7912190507 Responds to 791210 ltr requesting approved guarantee of payment of deferred premiums for each operating reactor over 100 Mw(e), owned in whole or part Advises that info was filed 791120 w/util.
  TOYNE, O. W. Corn Belt Power Cooperative. 79/12/14. 1p.
- P. Operating license stage documents & correspondence
- 7912100189 Discusses NRC 791101 meeting w/representatives of NSSS vendors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EISENHUT.D.O. Division of Operating Reactors. 79/11/09, 65pp.
- --7912100255 Responds to NRC 791101 request re noncompliance of Westinghouse ECCS evaluation model under requirements of iOCFR50 App K. Evaluation of three fuel rad models indicates no safety problems for Westinghouse plants.

  ANDERSON, T. M. Westinghouse Electric Corp. 79/11/02. 4pp.
- ---7912100330 Responds to NRC 791101 request re ORNL cladding swelling & rugture data. Review of analytical models & tests indicates compliance w/loCFR50 App K.All GE specs for calculated peak cladding temp remain unchanged.

  BUCHHOLZ,R.H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50. 44 satisfied.

  OMBLEY.O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/02. 5pp.
- -7912100456 Forwards addl info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. OMSLEY, O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/04. 22pp.
- 7912030233 Forwards Amend 55 to License DPR-49, notice of issuance & awailability & EIA.

  1PPOLITO, T.A. Operating Reactors Branch 3. 79/11/19. 2pp.

- --7912030235 Amend 55 to License DPR-49, replacing requirement for repeated manual sampling & analysis for chlorine at plant discharge w/requirement for automatic recording/control equipment. IPPOLITO.T.A. Operating Reactors Branch 3. 79/11/19. 7pp.
- --791203023B EIA supporting Amend 55 to License DPR-49.
  \* Office of Nuclear Reactor Regulation. 79/11/19. 4pp.
- --7912030240 Notice of issuance & availability of Amend 55 to License DPR-49. IPPOLITO, T. A. Operating Reactors Branch 3. 79/11/19. 2pp.
- 7912050472 Ack receipt of NRC 791026 & 30 ltrs re containment purging & venting. Will respond by 791214. ROOT, L.D. Jowa Electric Light & Power Co. 79/11/27. Ip.
- 7912180044 Forwards corrected Tech Specs re 790111 & 0705.Ltrs containing Amends 48 & 52 respectively to License DPR-49. IPPOLITO T.A. Operating Reactors Branch 3. 79/11/27. 2pp.
- --7912180070 Submits revised Page 6.9-1 to Tech Specs re radiological procedures, issued as supplemental Amend 48 to License DPR-49.
  - 17. Operating Reactors Branch 3. 79/11/27. 2pp.
- --7912180077 Submits revised Pages VI,3.6-9 & 3.6-10a to Tech Specs re surveillance requirements, issued as supplemental Amend 62 to License DPR-49.
  - Operating Reactors Branch 3. 79/11/27. App.
- 7912070141 Requests that GE 791130 ltr re Mark I containment program & NRC acceptance criteria be made official part of facility docket file. ROOT.L.D. Iowa Electric Light & Power Co. 79/11/30. lp.
- 7912310369 Provides response to NRC 791022 ltr re operability of containment purge valves Present purge & vent valve design adequate for all normal & accident conditions.

  ROOT. L. D. Jowa Electric Light & Power Co. 79/12/14. 3pp.
- 7912270189 Discusses util 791205 ltr.in response to NRC 791210 ltr re failure to report approved guarantee of payment for deferred premiums for each operating nuclear reactor over 100 MW. Info filed through IA Electric Light & Power Co. WILLIAMS, E. H. Central Iowa Power Cooperative. 79/12/17. 1p.
- O. Inspection reports, IE Bulletins & correspondence
- 7912130064 Forwards IE Insp Rept 90-331/79-26 on 791024-25.No noncompliance noted. FIORELLI,G. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 79/11/05. 2pp.
- --7912130067 IE Insp Rept 50-331/79-26 on 791024-25. No noncompliance nated Major areas inspected: actions re IE Bulletins 79-14 & 79-Q4. 79-04.

  DANIELSON, D. H., YIN, I. T. Region 3, Chicago, Office of the Director. 79/11/02. 3pp.
- 7912060364 Forwards response to IE Bulletin 79-23 Generator grounded wye configured source, w/no circuit connecting ground & transformer, will pass only low frequencies. Special lest Procedure 38 completed on 791103 indicating normality.

  RDOT, L. D. lowa Electric Light & Power Co. 79/11/08. 3pp.
- 7912200683 Forwards response to IE Bulletin 79-23 re failure of emergency diesel generator field exciter transformer. No circuit connecting generator ground & exciter primary transformer. Special Test Procedure 5B completed 791103.

  ROOT, L. D. lowa Electric Light & Power Co. 79/11/08. 3pp.
- 7912130229 Supplements 791030 response to IE Julietin 79-14. Insp during 1980 first quarter refueling shutdown will include normally inaccessible piping.
  ROOT, L. D. Iowa Electric Light & Power Co. 79/11/15. 1p.
- 7912050126 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required.

  KEPPLER.J. G. Region 3, Chicago. Office of the Director. 79/11/16.
- 7912100232 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Bupport Loads," No response required.
  KEPPLER.J. G. Region 3. Chicago. Office of the Director. 79/11/16.

- 7912110579 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required.

  KEPPLER. J. O. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912050377 Forwards IE Builetin 79-26, "Boron Loss From BWR Control Blades," Response required. KEPPLER, J. Q. Region 3, Chicago, Office of the Director. 79/11/20. Lo.
- 7912100434 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pige Break Datection Equipment on DWRs." No written response required.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/26.

  ib.
- 7912110259 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. KEPPLER.J.O. Region J. Chicago, Office of the Director. 79/11/26.
- 7912110427 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sent by NRC to licensees.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/28.

  10.
- 7912190223 Forwards IE Bulletin 77-27. "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation." Hritten response required. KEPPLER.J.O. Region 3, Chicago, Office of the Director. 79/11/30. ip.
- 7912200117 Forwards IE Bulletin 79-28. "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/12/10.
- 7912280611 Forwards response to IE Bulletin 79-02.Revision 2.re pipe support base plates w/concrete expansion anchor bolts. Analyzed pipe anchor & support base plates w/expansion anchor bolts. ROOT.L.D. Idwa Electric Light & Power Co. 79/12/10. 14pp.
- R. Periodic operating reports & related correspondence
- 7912190398 Forwards monthly operating rept for Nov 1979. MINECK D. L. Towa Electric Light & Power Co. 79/12/14. 1g.
- --7912190405 Monthly operating rept for Nov 1979. VAN SICKEL J. Inwa Electric Light & Power Co. 79/12/14. 7pp.
- S. Reportable occurrences, LERs & related correspondence
- 7912260364 PNC-III-79-020: on 791023, unit saut down to repair leaking elbow in feedwater pump seal water discharge line to feedwater heater 49. MRIGHT, O. C., SPEESBARD, R. L., HEISHMAN, R. F. Office of Inspection & Enforcement, Office of the Director. 79/10/23. 1p.
- 7912050505 Submits ETB Violation Rept 79-2: on 79110B.plant cooling tower basins overflowed. Analysis indicated probable excessive chlorine concentration. Caused by plant design. Design change for dechlorination being tested.

  MANHOND.E.L. Iowa Electric Light & Power Co. 79/11/26. Pap.
- 7912110340 RO: during normal operation, cad sys oxygon analyzer B found inoperable. Daygen analyzer A not indicating suppression chamber oxygen concentration. Caused by test Jack short in analyzer B. Test Jack repaired tested & returned to SVC. HAMMOND, E. L. Towa Electric Light & Power Co. 79/11/30. 1p.
- 7912180614 RD:during normal operation,D cad sys oxygen analyser was imperable during surveillance test. Analyser satisfactorily tostes & aligned.
  HAMMOND,E.L. Iowa Electric Light & Power Co. 79/11/30. ip.
- 7912140470 Forwards LER 79-031/03L-0. MINECK,D.L. Iowa Electric Light & Power Co. 79/12/10. 1p.
- --7912140482 LER 79-031/031-0: on 791110, during power ascension following reactor screw.channel 8 rod black monitor failed causing control rod black.Caused by drifted count trip level setpoint adjusted.

  ZIMMERMAN.J.C. lawa Electric Light & Power Co. 79/12/10. ip.

- 7912140479 Forwards LER 79-030/031-0. MINECK.D.L. Idwa Electric Light & Power Co. 79/12/10. 1p.
- --79121404B9 LER 79-030/03L-0: on 791112. during surveillance testing, differential pressure switch PDIS 2442 trip setpoint found out of tolerance. Caused by instrument drift, Ewitch calibr & tested, Design review continuing.
  ZIMMERMAN, J. C. I lowa Electric Light & Power Co. 79/12/10. 2pp.
- 7912170213 Forwards LER 79-032/03L-0. MINECK,D.L. Iowa Electric Light & Power Co. 79/12/12. ip.
- --7912170219 LER 79-032/03L-0: on 791116, during surveillance testing, high drywell pressure switch PS-4311C trip setpoint found out of tolerance. Caused by instrument drift. Switch recalibr & functionally tested.
  ZIMMERMAN.J. C. Iowa Electric Light & Power Co. 79/12/12. ip.
- 7912170224 Forwards LER 79-033/017-0.
  MINECK, D. L. lawa Electric Light & Power Co. 79/12/12. ip.
- --7912170231 LER 79-033/01T-0: on 791128, during surveillance testing. B primary containment oxygen analyser ANB1818 Found inoperable. Caused by short circuit in test jack. Analyser repaired, tested & returned to svc.
  ZIMMERMAN, J. C. Iowa Electric Light & Power Co. 79/12/12. 2pp.
- 7912180518 RD-79-3: on 791202 off gas stack flow recorder indicated downscale. Caused by failure of associated transmitter. Recorder disassembled inspected reassembled tested & reinstalled. Cause of transmitter failure unknown. MINECK.D. L. I lowa Electric Light & Power Co. 79/12/12. 2pp.
- DOCKET 50-333 JAMES A. FITZPATRICK NUCLEAR POWER PLANT F. Security, medical, emergency & fire protection plans
- 7912200022 Discusses NRC 791109 meeting re emergency preparations team review objectives. Provides guidance for improving licensee emergency preparationss & assuring capability of offsite agencies to take appropriate emergency actions. GRIMES, B. K. Emergency Preparadness Task Force. 79/11/23. 30pp.
- H. General correspondence
- 7912190418 Requests update of NRC distribution list by deleting VJ Cassam as counsel & substituting GM Fratt. EARLY, P. J. Power Authority of the State of New York. 79/12/13. 1p.
- 7912280504 Requests update of distribution lists by replacing name of VJ Cassan W/CM Pratt, as counsel for util. EARLY, P. J. Power Authority of the State of New York. 79/12/13. Ip.
- J. Insurance & indemnity information
- 7912270609 Confirms that PASNY has loan commitment for \$10 million from Hanufacturers Hanover Trust for retrospective insurance payment, if necessary, in event of nuclear disaster, Commitment sypires 800630.

  MCCARTHY.R. H. Affiliation Unknown. 79/12/18. 1p.
- P. Operating license stage documents & correspondence
- 7912100189 Diacusses NRC 791101 meeting w/representatives of N8S9 vendors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/ruel cladding awelling & incidence of rupture. Vendor responses encl. EISENHUT. D. O. Division of Operating Reactors. 79/11/09. 65pp.
- --7912100255 Responds to NRC 791101 request re noncompliance of Westinghouse ECCS evaluation model under requirements of 10CFR30 App K. Evaluation of three fuel rod models indicates no safety problems for Wastinghouse plants. ANDERSON, T. M. Westinghouse Electric Corp. 79/11/02. App.
- --7912100330 Responds to NRC 791101 request re ORNL cladding swelling & rupture data Review of analytical models & tests indicates compliance w/100FR50 App K. All OE specs for calculated peak cladding temp remain unchanged.
  BUCHHOLZ,R.H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of IOCRESO. 46 satisfied.

  OMSELSY, G.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/11/02. 5pp.

- --7912100456 Forwards add1 info re evaluation of impact of NRC proposed rupture/blockage model used in vandor avaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. OMSLEY.Q.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/04. 22pp.
- 7912180117 Forwards safety evaluation re degraded grind voltage protection sys LAINAS, 0. Plant Systems Branch. 79/11/13. 1p.
- --7912180120 Bafety evaluation re degraded grind protection for safetyrelated ac power sys. Technical evaluation rept ancl. \* Office of Nuclear Reactor Regulation. 79/11/13. 11pp.
- 7912030168 Commits to expedited implementation of valve qualification program for containment purge & vent valves. Provided operability assessment of purge & vent valves on 790815. EARLY, P. J. Power Authority of the State of New York. 79/11/26. 1p.
- 7912040500 Requests immediate approval for installation of increased capacity fuel racks. Prompt installation will provide capability of full core unload.

  BERRY, G. T. Power Authority of the State of New York. 79/11/29.
- 7912120421 Forwards add1 info re safety evaluation in support of Amend 47 to License DPR-59. Encl responds to Paragraph 3.2.1, reffra hazard analysis.
  EARLY, P. J. Power Authority of the State of New York. 79/12/06.
- 7912120457 Forwards application for amend to License DPR-59 rs changes in Tach Specs related to spiral loading/unloading of reactor core. Safaty evaluation encl. Class III fam paid under protest.

  EARLY, P. J. Power Authority of the State of New York. 79/12/06.
- ---7912120460 Application for Amend to License DPR-59, changing Tech Specs to provide for spiral loading/unloading of core, reloading w/o full control rod blade insertion & redefinition of source range monitor operablity during reload.

  \* Power Authority of the State of New York. 79/12/06. 11pp.
- --7912120461 Bafaty evaluation supporting change in Tach Specs ra spiral loading/unloading of reactor core.

  \* Power Authority of the State of New York. 79/12/06. 2pp.
- 7912130545 Forwards application for amend to OL re expanded membership for safety review committee & inclusion into Tech Specs.

  EARLY, P. J. Power Authority of the State of New York. 79/12/06. 1p.
- ---7912130547 Application for amend to License DPR-59. EARLY, P. J. Power Authority of the State of New York. 79/12/06.
- ---7912130550 Proposed Tech Speca changes re safety review committee.

  \*\* Power Authority of the State of New York. 79/12/06. Spp.
- 7912180573 Notifies of primary containment integrated leak rate test scheduled for facility.

  LEONARD, J. D. Power Authority of the State of New York. 79/12/10.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912030045 Forwards IE Insp Rept 50-333/79-12 on 790827-30.No noncompliance noted, CARLEON.R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/09/26. 2pp.
- ---7912030048 IE Insp Rept 50-333/79-12 on 790827-30. No noncompliance noted, Major areas inspected: Inservice insp data & license documentation associated w/LER 79-018/03L-0.
  HOBREARTY.R.A. Region 1, Philadelphia, Office of the Director.
  TRIPP: L.E. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/09/20, opp.
- 7912120003 Forwards mgt review in response to NRC Immediate Action Ltr 79-15 re omission of certain instrument root valves from Ilneug checklist. LEONARD, J. D. Power Authority of the State of New York. 79/69/26.
- 7912000007 Forwards IE Insp Rept 50-333/79-10 on 790730-0803 & 20-24. No noncompliance noted.

  CARLSON, R. T. Region 1: Philadelphia: Reactor Construction & Engineering Support Branch. 79/10/16. 2pp.

- --7912050010 IE Insp Rept 50-333/79-10 on 790730-0803 & 20-24. No noncompliance noted Major areas inspected: spent fuel rack mod & action on previous insp findings.

  FEIL.R. Region i. Philadelphia. Office of the Director.

  TRIPP.L.E. Region I. Philadelphia, Reactor Construction & Engineering Support Branch. 79/10/09. 5pp.
- 7912130200 Responds to IE Bulletin 79-18. Eleven areas were found w/o adequate audio or visual alarm capabilities. Areas will be re-evaluated following installation of add1 elect devices. LEONARD, J. D. Power Authority of the State of New York. 79/10/17.
- 7912050074 Ack receipt of 790718 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-333/79-07.
  ORIER. B. H. Region 1, Philadelphia, Office of the Director.
  79/10/18. 1p.
- --7912050084 Responds to NRC 790824 ltr re violations noted in IE Insp Rept 50-333/79-07. Corrective actions: instrument surveillance procedure revised & permanent scale placed on indicator. LEONARD, J. D. Power Authority of the State of New York. 79/09/18.
- ---7912050088 Forwards IE Insp Rept 50-333/79-07 on 790529-0601 & notice of violation.
  BRUNNER, E. J. Region I. Philadelphia, Reactor Operations Nuclear Support Branch. 79/08/24. 2pp.
- --7912050090 Notice of violation from insp on 790529-0601.

  \* Region 1, Philadelphia, Office of the Director. 79/08/21.
  ip.
- --7912050131 IE Insp Rept 50-333/79-07 on 790529-0601 Noncompliance noted: failure to include acceptance criteria in Tech Spec surveillance calibr & subsequent review & approval of erroneous results.

  ZIMMERMAN, R. P., KIBTER, H. B. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch. 79/08/21. Spp.
- 7912120504 Responds to IE Bulletin 79-14. A/E piping stress analysis program will address bulletin concerns. Program rept forthcoming. LEDNARD, J. D. Power Authority of the State of New York. 79/10/18. 3pg.
- 7912260092 Forwards IE Insp Rept 50-333/79-15 on 790911-13.No noncompliance noted. MARTIN, W. 9. Region 1, Philadelphia, Safeguards Branch. 79/10/26.
- --7912260095 IE insp Rapt 50-333/79-15 on 790911-13. No noncompliance noted. Major ereas inspected: organization & operation, measurement & controls & shipping & receiving Details withheld (ref 10CFR2.790).
  BISBETT.P. H., SHAUB.E.T. Region 1, Philadelphia, Office of the Director. JOYNER, J. H. Region 1, Philadelphia, Safeguards Branch. 79/10/23. 1p.
- 7912140278 Responds to IE Bulletin 79-24, "Frozen Lines." Adequate protective measures already taken to produce freezing of lines during extreme cold.

  LEONARD. J. D. Power Authority of the State of New York. 79/10/31.
- 7912170214 Updates response to IE Bulletin 79-01 as requested by 791002 ltr. Encl table summarizes & supplements previous responses re environ qualification of Class IE electrical equipment.

  LEONARD, J. D. Power Authority of the State of New York. 79/11/02.
- 7912050045 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Volves." No response required.
  GRIER, B.H. Region 1, Fhiladelphia, Office of the Director.
  79/11/16. 1p.
- 7912030278 Forwards IE Info Notice 79-27, "Steam Generator Tube Ruptures at Two PMR Plants." No response required. QRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/11/16. 1p.
- 7912100136 Forwards IE Info Notice 79-28, "Dwarloading of Structural Elements Due to Pipe Support Loads." No response required. ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/11/16. ip.

- 7912110452 Forwards IE info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Gys Instrumentation During Operation." No specific action or response required. GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/11/19. 1p.
- 7912050269 Forwards IE Bulletin 79-26. "Boron Loss From BWR Control Blades." Response required. ORICE, B. H. Region 1. Philadelphia. Office of the Director. 79/11/20. 1p.
- 79122A00b3 Responds to IE Bulletin 79-25 re failures of BFD relays in safety-related sys. Relays not used at facility.
  LEDNARD, J. D. Power Authority of the State of New York. 79/11/20.
- 7912260057 Responds to Revision 2 of IE Builetin 77-02 re pipe supports using concrete expansion anchor bolts. No expansion anchors used in masonry-type walls.

  LEGNARD, J. D. Power Authority of the State of New York. 79/11/21.
- 7912060582 Forwards IE Circular 79~24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BHRs." No response required. GRIER.B.H. Region 1. Philadelphia, Office of the Director. 79/11/26. 1p.
- 79121100A9 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. GRIER, B. H. Region i. Philadelphia, Office of the Director. 79/11/26. 1p.
- 7912190055 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Fower Sys Bus During Operation." Written response required.

  ORIER, D. H. Region 1, Philadelphia, Dffice of the Director. 79/11/30. 1p.
- 7912100314 Provides status of program re requirements of IE Bulletin 79-14. Forwards schedule for insp of sofety-related pipe lines 2 1/2 inches & larger List does not include pipe lines analyzed for 790313 show cause order. EARLY.P. J. Power Authority of the State of New York. 79/12/03.
- 7912310235 Forwards 1E Info Notice 79-30, "Reporting of Defects & Nancompliances, 10CFR21." No action required. ORIER B.H. Region I. Philadelphia, Office of the Director, 79/12/06. 4pp.
- 7912190760 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Written response required.
  GRIER, B. H. Region 1, Philadelphia, Office of the Director.
  79/12/07. ip.
- 7912280220 Forwards IE Info Notice 79-31. "Use of Incorrect Amplified Response Spectra." No written response required. GRIER, B.H. Region I. Philadelphia. Office of the Director. 79/12/13. ip.
- R. Periodic operating reports & related correspondence
- 7912110250 Forwards monthly operating mept for Nov 1979. LEONARD, J. D. Power Authority of the State of New York. 79/12/07. lp.
- --7912110256 Monthly operating rept for Nov 1979.

  ZUFELT.E. Power Authority of the State of New York. 79/12/07.

  1100.
- S. Reportable occurrences, LERs & related correspondence
- 791212012B RO: on 791024.A/E informed util that pipe stress reanalysis indicated pipe support to be inoperative per NRC guidelines. Support will be upgraded to accept increased loads from SHOCK-III analysis.
  LEGNARD, J. D. Power Authority of the State of New York. 79/10/24.
- 7912130449 Forwards LER 79-083/03X-2.
  LEONARD, J. D. Power Authority of the State of New York. 79/11/28.

- --7912130454 LER 79-093/03x-2: on 791008, during normal operation, routing computer printout of core performance log indicated that max fraction of limiting pawer density was above Tech Spec limits. Reactor power reduced approx 3% to Tech Spec limits. CHILDS.W. V. Power Authority of the State of New York. 79/11/28. 20p.
- 791204D3DB Forwards LER 79-095/03X-1. LEGNARD, J. D. Power Authority of the State of New York. 79/11/30, 2pp.
- --7912040313 LER 79-095/03X-1: on 791025, drywell-to-suppression chamber differential pressure transmitter 27-PT-102B was found out of tolerance. Caused by improper testing procedure. Procedure corrected & proper calibr verified.

  CHILDS, W. V. Power Authority of the State of New York. 79/11/30.
- 7912110277 Forwards LER 79-101/03L-0. LEGNARD, J. D. Power Authority of the State of New York. 79/12/04.
- --7912110282 LER 79-101/OGL-O: on 791108, during operations surveillance test F-8T-76L, six penetrations discovered not sealed during plant const. Cause not stated. Penetrations sealed w/3-h rated mati & performed fire watch.

  CHILDS, H. V. Power Authority of the State of New York. 79/12/04.
- 7912110328 Forwards LER 79-100/03L-0. LEGNARD, J. D. Power Authority of the State of New York. 79/12/04.
- --7912110329 LER 79-100/03L-0: on 791108, during normal operation to complete corrective maint HPCI sys unintentionally made inoperable. Caused by need to replace leaking gasket associated w/sys hydraulic control valve seat drain. CHILDS.H.V. Power Authority of the State of New York. 79/12/04.
- 7912110343 Forwards LER 79-099/03L-0. LEGNARD, J. D. Power Authority of the State of New York. 79/12/04.
- --7912110347 LER 79-099/03L-0: on 79110B. leaking access plug on hydraulic control unit for control rod i8-35 required unit to be isolated.making control rod inquerable. Caused by failed O-ring. Ring replaced.
  CHILDS: W. V. Power Authority of the State of New York. 79/12/04.
- 7912110355 Forwards LER 79-102/03L-0. LEONARD, J. D. Power Authority of the State of New York. 79/12/05. 10.
- --7912110359 LER 79-102/03L-0: an 79110B; reactor water conductivity exceeded Tech Spec limit. Caused by decomposition of ion exchange resins which altered ph level. Eight condenser tubes plugged & one condensate demineralizer removed. CHILDS.M.V. Power Authority of the State of New York. 79/12/05. 4pp.
- 791214043B Forwards LER 79-104/03L-0. LEONARD, J. D. Power Authority of the State of New York. 79/12/10.
- --7912140449 LER 79-104/OSL-0: on 791110, during instrument survaillance procedure F-ISP-72, source range monitor A exhibited erratic operation. Cause unknown. During troubleshooting, instrument operation returned to normal. CHILDS W. V. Power Authority of the State of New York. 79/12/10.
- 7912180594 Forwards LER 79-105/03L-0. LEONARD.J.D. Power Authority of the State of New York. 79/12/13.
- --7912:80599 LER 79-105/03L-0: on 791114, during normal operation, noisy lubricating oil recirculating pump associated w/emergency diesel generator C noted Caused by bad bearing in pump motor. Notor replaced.

  CHILDS W. V. Power Authority of the State of New York. 79/12/13.
- 7912210316 Forwards LER 79-106/03L-0. LEGNARD, J. D. Power Authority of the State of New York. 79/12/17. 1p.

- ~~7912210322 LER 79-106/03L-0; on 791118 during normal steady state operation while conducting operations surveillance test F-ET-LJ, MBIV 29-A0V-BOA did not provide half scram signal equal to or less than 10% closurs Cause undatermined. CHILDS, W. V. Power Authority of the State of New York. 79/12/17. 200.
- 7912210327 Forwards LER 79-103/01T-0. LEONARD, J. D. Power Authority of the State of New York. 79/12/17.
- --7912210336 LER 79-103/01T-0: on 791205 due to IE Bulletin 79-14 reanalysis, pipe hanger H10-539 in B RHR sys considered inoperable due to thermal growth. Caused by hold down clips & guides restraining pipe movement. Clips & guides removed. CHILDS. W. V. Power Authority of the State of New York. 79/12/17. 2pp.

# DOCKET 50-334 BEAVER VALLEY POWER STATION, UNIT 1

- f. Security, medical, emergency & fire protection plans
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives. Provides guidance for improving licensee emergency preparedness & assuring capability of offsite agencies to take appropriate where

#### Q. Adjudicatory correspondence

- 7912110038 Confirms receipt of encl 790327 petition to suspend OLs for all PMRs. Forwards FR notice indicating that petition will be treated in accordance w/10CFR2.206.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/23. ip.
- --7912110126 Notice of request for action pursuant to 10CFR2.206 re Environ Coalition on Nuclear Power 790329 petition requesting suspension of all QLs for PWRs. MULLER.D.R. Office of Nuclear Reactor Regulation. 79/11/23.

## I. Financial information

- 7912310343 Responds to NRC 791210 ltr requesting util guarantee of 1979 retrospective premiums.Forwards 790327 ltr w/internal cash flow projection for 1979.
  CHRISTNER,R.S. Duquesne Light Co. 79/12/26. 2pp.
- P. Operating license stage documents & correspondence
- 7911090248 "Summary of Operating Experience W/Recirculating Steam Generators." EISENHUT.D.O. Division of Operating Reactors. NUREO-0523. 79/01/31. 89pp.
- 7708010339 Notifies of status of rept on reactor cavity annulus seal.
  Most PHR users remove ring during normal operation. Others
  store seal ring in reised position during normal operation.
  LAINAB. 0. Plant Bystems Branch (Pre 791030). 79/07/05. 7pp.
- 7712050170 Discusses NRC review of LERs & Tech Spec requirements re control RPI sys at Westinghouse PWRs. Requests Tech Specs review to ensure requirement for rod maint to within +/- 12 steps indicated & RPI sys verified accurate within 12 steps. SCHWENCER. A. Operating Reactors Branch 1. 79/10/29. 7pp.
- 791210040B Discusses NRC concern re containment purging & venting during normal operation. Includes licensee override of safety actuation isolation signals to containment isolation valves & valve ability to shut w/o degrading containment. BCHWENCER.A. Operating Reactors Branch 1, 79/10/29. Spp.
- 7712100189 Discusses NRC 771101 meeting w/representatives of NSSS vandors & fuel suppliers re discussion of respective partions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EISENHUT. D. 0. Division of Operating Reactors. 79/11/09. 65pp.
- ---7912100285 Responds to NRC 791101 request re noncompliance of Westinghouse ECCS evaluation model under requirements of iOCFR50 App K. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants.
  ANDERSON, T. M. Westinghouse Electric Corp. 79/11/02. 4pp.

- --79:2100330 Responds to NRC 79:101 request re ORNL cladding swelling & rupture data. Review of analytical models & tests indicates compliance w/10CFR50 App K. All GE specs for calculated peak cladding temp remain unchanged.

  BUCHHGLZ.R.H. General Electric Cu. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request me nod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50.46 satisfied.

  OMBLEY. G. F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/11/02. Spp.
- --7912100456 Forwards add1 info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model.

  No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results.

  OMBLEY, G.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).

  79/11/04. 22pp.
- 7912060038 Summary of 791116 telcon w/util re util 791022 response to 790913 ltr re implementation of "TMI Lessons Learned Task Force" recommendations. Wigginton, D. Operating Reactors Branch 1. 79/11/23. 5pp.
- 7912190007 Summary of 791116 telcon w/licenses re lessons learned implementation. Lists of items not meeting lessons learned implementation not conforming to lessons learned requirements & needing further clarification encl. WIGGINTON, D. Operating Reactors Branch 1. 79/11/23. Spp.
- 7912040289 Notifies of completed actions re rod drop analysis problems reported by Westinghouse & discussed at 791119 meeting.
  Actions completed 791122. Restrictions will remain in effect until problems resolved.
  DUNN.C.N. Duquesne Light Co. 79/11/27. 1p.
- 7912040379 Discusses implementation & review schedule for TMI-2 Lessons Learned Task Force short-term requirements. DUNN.C.N. Duquesne light Co. 79/11/30. Epp.
- 7912050465 Forwards results of analysis & info re response of containment pressure to steam break accident inside containment w/extended auxiliary feedwater flow to affected steam generator.

  DUNN, C. N. Duquesne Light Co. 79/11/30. 18pp.
- 7912210126 Notifies that rept required by Tech Specs 2.4.1.8 & 2.4.3.9 App B should include dose assessment w/respect to conformance w/code. SCHWENCER, A. Operating Reactors Branch 1. 79/12/04. 2pp.
- 7912100305 Forwards proposed Tech Spec 3/4.6.5, deleting option to utilize steam jet air ejector during Mode 4, Class II amend fae ancl.
  DUNN.C.N. Duquesne Light Co. 79/12/05. 3pp.
- ---7912100311 Proposed Tech Spec 3/4.6.5, eliminating uption to utilize steam jet ejector during Mode 4. Addl conservatism eliminates potential short-term containment leakage path.

  \* Duquesne Light Co. 79712705. 3pp.
- 7912270354 Discusses review of NRC 791213 request re commitment to implement TMI Lessons Learned Task Force Category A requirements by 800101. Intends to implement recommendations during current refueling outage.

  DUNN, C. N. Duquesne Light Co. 79/12/17. 1p.
- 7912270456 Notifies that requested info re auxiliary feedwater sys automatic initiations & flow indications to steam generators was provided during 791213 site visit. DUNN, C. N. Duquesne Light Co. 79/12/18. 1p.
- 7912270370 Responds to 791218 request re procedures for small break LOCA. Westinghouse owners group procedures adequate for facility. Site-specific procedures do not deviate significantly from ref procedure.

  DUNN.C.N. Duquesne Light Co. 79/12/21. 3pp.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912040097 Ack receipt of 790918 ltr imforming NRC of steps taken to correct violations noted in IE Insp Rept 50-334/79-11 MARTIN.W. G. Region 1, Philadelphia, Safeguards Branch. 79/10/12.
- ---7912040105 Responds to NRC 770828 itr re violations noted in 1E Insp Rept 30-334/79-11 Corrective actions details withheld (ref 10CFR2.770). DUNN, C. N. Duquesne Light Co. 79/09/18. 1p.

- ---7912040121 Forwards IE Insp Rept 50-334/79-11 on 790307-11 & notice of violation.Notice of violation withheld (ref 10CFR2.790).

  MARTIN.W.G. Region 1. Philadelphia. Safeguards Branch.
  77708/28. 2pp.
- ---7912040129 IE Insp Rept 50-334/79-11 on 790507-11. Noncompliance noted: socurity organization, access control & keys.locks.& combinations. Details withheld (ref 100FR2.790).

  BAILEY,R. J. MCKEONN,L. M. Region 1, Philadelphia, Office of the Director. DEVLIN.J. Region 1, Philadelphia, Safeguards Branch. 79/08/22. 1p.
- 7912040191 Ack receipt of 791005 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-334/79-13.

  BRUNNER.E.J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 79/10/18. 1p.
- --7912060205 Responds to NRC 790912 ltr re violation noted in IE Insp Rept 50-334/79-13. Corrective actions: temporary test circuit remounted on fireproof matl & installation checked for secure mounting. DUNN.C.N. Duquesne Light Co. 79/10/05. 3pp.
- --7912060214 Forwards IE Insp Rept 50-334/79-13 on 790529-0601 & 11-13 & notice of violation.
  BRUNNER, E. J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 79/09/12. 2pp.
- --7912060218 Nutice of violation from insp on 790529-0401 & 11-13.

  + Region 1, Philadelphia, Office of the Director. 79/09/ii.
  ip.
- --7912060221 IE Insp Rept 50-834/79-13 on 790529-0601 & 11-13.

  Noncompliance noted: inadequate implementation of design control measures resulting in faulty mounting of temporary test circuit.

  HCNATT.T. FINKEL.A. Region 1. Philadelphia. Office of the Director. KEINIG.R.R. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 79/09/11. 13pp.
- 7912170164 Responds to 1E Bulletin 79-23, "Potential Failure of Emergency Diesel Generator Field Exciter Transformer." Froblem not applicable to facility. Flow of high circulating current cannot exist at plant.

  BURN.C.N. Duquesne Light Co. 79/10/24. 2pp.
- 79121701B2 Updates 790B2G response to IE Bulletin 79-17, "Pipe Cracks in Stagnant Borated Hater Sys at PUR Plants." Insp of welds will not be completed within required 90-day period due to difficulty in removing concrete slabs.

  WERLING. J. A. Duquesne Light Co. 79/10/29. 2pp.
- 7912200530 Forwards IE Insp Rept 50-334/79-19 on 790927-28.No noncompliance noted.

  MARTIN, M. 9. Region 1, Philadelphia, Safeguards Branch. 79/10/29.
- --7912200534 IE Insp Rept 50-334/79-19 on 790827-28. No noncompliance noted Hajor areas inspected satt control & accounting.
  JOYNER, J. H. Region i, Philadelphia, Eafeguards Branch.
  SMITH. O., SUMMERS, R. Region i, Philadelphia, Office of the Director. 79/10/25. 5pp.
- 79:2170232 Responds to IE Bulletin 79-24, "Frozen Lines." All lines are protected or will be protected through use of cold weather log, heat trace thermocouples & controllers & slectric heater in trench adjacent to cooling tower.
  HDQLEVER.E.J. Duquesne Light Co. 79/11/01. 2pp.
- 7912100219 Ack receipt of 791029 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-334/79-17. GRIER.B.H. Region 1. Philadelphia. Office of the Director. 79/11/06. 1p.
- --7912100224 Responds to NRC 791001 ltr re violations noted in IE Insp Rept 90-334/79-17. Corrective actions: startup forms reviewed, evaluation rept issued & vibration instrument shipped to vendor for recalibr. DUNN, C. N. Duquesne Light Co. 79/10/29. 7pp.
- ---7912100236 Forwards IE Insp Rept 50-334/79-17 on 790820-24 & notice of violation. ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/10/01. 2pp.
- ---7912100245 Notice of violation from insp on 790820-24.

  # Region 1, Philadelphia, Office of the Director. 79/09/21.

  App.

- --7912100253 IE Insp Rept 50-334/79-17. Noncompliance noted: failure to follow procedures, use of heating torch w/o approved procedure & use of vibration measurement equipment w/expired calibr.

  BEKKHAN, D. A., KEIMIG, R. R. Region 1, Philadelphia, Office of the Director, 79/09/21, 20pp.
- 7912030026 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required. ORIER, D.H. Region 1, Philadelphia, Office of the Director. 79/11/16. 1p.
- 7912050245 Forwards IE Info Notice 79-27, "Steam Generator Tube Ruptures at Two PWR Plants." No response required. GRIER, B. H. Region i, Philadelphia, Office of the Director. 79/11/16. 1p.
- 7912100118 Forwards IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads." No response required. ORIER.B.H. Region 1. Philadelphia, Office of the Director. 79/11/16. 1p.
- 7912110404 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Gys Instrumentation During Operation." No specific action or response required. ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/11/19, ip.
- 7912050228 Forwards IE Bulletin 79-26, "Boron Loss From BWR Control Blades." No response required. GRIER.B.H. Region 1. Philadelphia, Office of the Director. 79/11/20. 1p.
- 7912060570 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Sprey Pipe Break Detection Equipment on BWRs." No response required.
  ORIER. B. H. Region 1. Philadelphia, Office of the Director.
  79/11/26. 1p.
- 7912110037 Forwards IE Circular 79-23, "Motor Btarters & Contactors Failed to Operate." No response required. GRIER.B.H. Region 1, Philadelphia. Office of the Director. 79/11/26. 1p.
- 79:2190021 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation," Written response required.
  ORIER.B.H. Region 1, Philadelphia, Office of the Director.
  79/11/30. ip.
- 7712200652 Forwards notices of violation & of intent to impose civil penalties for violations identified during 771127 insp.
  BTELLO.V. Office of Inspection & Enforcement, Office of the Director. 77/12/05. 2pp.
- --7912200657 Notice of violation from insp on 791127.

  Region i, Philadelphia. Office of the Director. 79/12/05.
- --7912200660 Notice of proposed imposition of civil penalties from violations noted in 791127 insp.

  \*\* Office of Inspection & Enforcement, Office of the Director. 79/12/05. 1p.
- --7912200667 Order modifying license requiring redundant & independent varification of angineered safety features operability & review of controls to assure limiting conditions for operation not defeated by maint & other activities.

  STELLO.V. Office of Inspection & Enforcement, Office of the Birector. 79/12/05. App.
- 7912120312 Corrects 781214 ltr re reactor vessel overprotection sys. Relief valves certified by seismic analysis. Vendor analysis complies w/seismic design requirements of facility. DUNN.C.N. Duquesne Light Co. 79/12/06. ip.
- 7912280002 Responds to IE Bulletin 79-02. Revision 2. "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts."
  Testing & insp procedures & documentation of testing & insp performed available at site.
  DUNN.C.N. Duquesne Light Co. 79/12/06. Spp.
- 7912310213 Forwards IE Info Notice 77-30, "Reporting of Defects & Noncompliances, 100FR21." No action required.

  GRIER, B. H. Region 1, Philadelphis, Office of the Director.
  79/12/06. 4pp.

- 7912190739 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Written response required.

  ORIER, B. H. Region 1, Philadelphia, Office of the Director.
  79/12/07. 1p.
- 7912280194 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Rasponse Spectra." No written response required.
  GRIER, B.H. Region 1, Philadelphia, Office of the Director.
  79/12/13. 1p.
- R. Periodic operating reports & related correspondence
- 7912040439 Forwards NPDES monthly rept for Nov. MCCRE. G. W. Duquesne Light Co. 79/11/29. 1
- --7912040443 NPDES monthly rept for Nov. MOORE, Q. M., STEED, L. S. Duquesne Light Co. 79/11/30. 12pp.
- 7912180362 Forwards monthly operating rept for Nov 1979. DUNN.C.N. Duquesne Light Co. 79/12/12. ip.
- ---7912180368 Monthly operating rept for Nov 1979. BP17ZNOGLE, A. Duquesne Light Co. 79/12/06. 4pp.
- B. Reportable occurrences, LERs & related correspondence
- 7912200552 PNB-I-79-001: on 791005, Intl Brotherhood of Electrical Workers will strike facility if new contract voted down. Becurity organization not affacted. DEVLIN, J.W., MARTIN, V.O. Office of Inspection & Enforcement, Office of the Director. 79/10/05. 1p.
- 7912200567 PNS-1-79-001A: on 791008, tentative agreement reached on new contract between util & Intl Brotherhood of Electrical Workers, Util believes contract will be ratified avoiding threat of strike.

  DEVLIN.J.W., ALLAN.J. Office of Inspection & Enforcement, Office of the Director. 79/10/09. 1p.
- 7912040522 RO 79-46/01P: on 791127 flowpath to charging pumps closed due to planned removal of emergency diesel generator. High head injection would have not been available if needed Error corrected when valve opened to intrease flow path to pumps. WERLING, J. A. Duquesna Light Co. 79/11/28. 2pp.
- 7912310385 RO-79-46/01F: on 791127; redundant motor operated isolation valve CH-i15D placed on clearance, in closed position, following emargency diesel generator maint shutdown Caused by operator error.

  WERLING, J. A. Duquesna Light Co. 79/11/28. 2pp.
- 7912130627 Forwards LER 79-045/03L-0, WERLING, J. A. Duquesna Light Co. 79/12/07. 2pp.
- ~~7912130634 LER 79-045/03L-0: on 79110B, during startup of horic acid cleanup sys, deborating demineralizer was filled w/primary grade water. When cut into svc boron in tank diluted to less than Tech Specs. Caused by inadequate startup procedure. WERLING, J. A. Duquesne Light Co. 79/12/07. ip.
- 7912180633 Forwards LER 79-046/01T-0, WERLING, J. A. Duquesne Light Co. 79/12/11, 2pp.
- --7912180639 LER 79-046/01T-0: on 791127, while generator which provides emergency power to motor operated valve CH-115D was removed from svc.valve was placed on clearance in closed position for saint. Caused by operator error.

  WERLING, J. A. Duquesna Light Co. 79/12/11, 2pp.
- 7912270502 Forwards LERs 79-039/99X-0 & 79-040/99X-0. WERLING.J.A. Duquesna Light Co. 79/12/19. 2pp.
- --7912270506 LER 79-039/99X-0: on 790920, vital bus inverter 4 Failed, causing reactor trip & high steam flow safety injection actuation. Caused by failure of vital bus inverter & transfer of vital bus to auxiliary power supply.

  MERCINO, J. A. Duquesne Light Co. 79/12/19, ip.
- -7912270520 LER 79-040/99X-0: on 790920, during operational Mode 3, vital bus invertor 4 transferred from auxiliary power source to inverter. Inverter was inoperable & safety injection occured. Caused by operator error. Personnel reprimended. MERLING, J.A. Duquesne Light Co. 79/12/19, 1p.

- DOCKET 50-335 ST. LUCIE PLANT, UNIT 1
- F. Security, medical, emergency & fire protection plans
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives. Provides guidance for improving licensee emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.

  ORIMES, B.K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- 7912200618 Notifies of fee assessment for 790817 review of security training & qualification plan. Requests payment.
  DIGOS.R.M. License Fee Management Branch. 79712/06. 1p.
- G. Adjudicatory correspondence
- 7912110038 Confirms receipt of encl 790329 petition to suspend OLs for all PMRs. Forwards FR notice indicating that petition will be treated in accordance w/10CFR2. 206.
  DENTON, H.R. Office of Nuclear Reactor Regulation. 79/11/23. ip.
- --7912110126 Notice of request for action pursuant to 10CFR2.206 re Environ Coalition on Nuclear Power 790329 petition requesting suspension of all OLs for PWRs. HULLER, D.R. Office of Nuclear Reactor Regulation. 79/11/23.
- M. Antitrust correspondence
- 7912060020 Motion to lodge FERC 791004 opinion & order denying prehearing Confirms reasons presented in FL Cities 790809 motion to lodge FERC 790803 opinion & order Affirmation of Byc & FERC 791004 order encl.

  JABLON, R. A. Florida Cities. 79/11/16, Bpp.
- 7912110438 Response in opposition to FL Cities 791114 motion to lodge FERC Optnion 57-A.No relation exists between FERC findings re tariff matters & findings in present proceeding re antifrust violations. Certificate of Svc encl. BOUKNIGHT. J. A. ORISBON. D. M. Florida Power & Light Co. BOUKNIGHT. J. A. Lowenstein, Newman, Reis, Azelrad & Toll. 79/12/03. 48p.
- 7912110345 Answer to FL Cities 791116 motion to lodge FERC 790803 opinion re whether to conduct proceeding under Atomic Energy Act of 1954 Section 105(a). Does not oppose lodging per NRC 790823 previous answer.

  DEMEY, L. B., CHANANIA, F. D. Antitrust Division. 79/12/06. 3pp.
- P. Operating license stage documents & correspondence
- 7911090248 "Bummary of Operating Experience W/Recirculating Steam Oemerators." EISENHUT.D.O. Division of Operating Reactors. NUREQ-0523. 79/01/31. 89pp.
- 7912100189 Discusses NRC 791101 meeting w/representatives of NSSS vandors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swalling & incidence of rupture. Vendor responses encl. EIBENHUT.D.Q. Division of Operating Reactors. 79/11/09. 65pp.
- ---7912100255 Responds to NRC 791101 request re noncompliance of Hestinghouse ECCS evaluation model under requirements of 10CFR50 App K.Evaluation of three fuel rod models indicates no safety problems for Hestinghouse plants, ANDERSON.T.M. Westinghouse Electric Corp. 79/11/02. App.
- -7912100330 Responds to NRC 791101 request to DRNL cladding swelling & rupture data. Review of analytical models & tests indicates compliance w/10CFR30 App K. All QE space for calculated peak cladding temp remain unchanged.

  BUCHMOLZ.R.H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50.46 satisfied.

  OMRLEY.O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/11/02. Spp.
- --7912100456 Forwards add1 info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model.

  No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results.

  DMBLEY.O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).

  79/11/04. 22pp.

- 7912060492 Act receipt of NRC 790927 & 1023 ltrs re containment purging & venting during normal operation. Response will be submitted by 791213.
  UMRIG.R.E. Florida Power & Light Co. 79/11/29. 1p.
- 7912110324 Forwards "Time Response Testing of Resistance Temp Detectors." Confirms acceptability of use of ensite loop current step response technique for measuring resistance temp detectors response time. UHRIG.R.E. Florida Power & Light Co. 79/12/04. 1p.
- --7912110326 "Time Response Testing of Resistance Temp Detectors." MOTT, J. E., HERRELL, D. C., ROBINSON, J. C. Technology for Energy Corp. 79/12/04. 15pp.
- 7712260328 No objection to licenses proposed changes to NPDES permit. Requests comments on changes to ETS necessary to accommodate revision in NPDES permit. REID.R.W. Operating Reactors Branch 4. 79/12/04. 3pp.
- 7912130259 Forwards revised pump & valve test program, in response to NRC 790716 ltr re test cycling of check valves.
  UHRIG.R.E. Florida Power & Light Co. 79/12/07. 1p.
- --7912130264 Revised pump & valve test program. \* Florida Power & Light Co. 79/12/07. 175pp
- 7912180243 Urges expeditious review & safety evaluation of RETRAN reactor sys transient analysis code. List of intended uses of RETRAN encl.
  UMRIG.R.E. Florida Pawer & Light Co. 79/12/07. 3pp.
- 791231014B Forwards SER opposing porposed Tech Spec changes that remove requirement for 8-h ac power source surveillance when limiting conditions for operation are not met Changes do not conform to Reg Guide 1.93 or Tech Specs.

  LAINAS.G. Plant Systems Branch. 79/12/07. 1p.
- ---7912310152 SER opposing proposed Tech Spec changes that remove requirement for 8-5 ac power source surveillance when Italians conditions for operation are not met. Changes do not conform to Reg Quide 1.93 or Tech Specs.

  \* Plant Systems Branch. 79/09/30. 2pp.
- --7912310154 Technical evaluation opposing proposed Tech Spec changes that remove requirement for B-h ac power source surveillance when limiting conditions for operation are not met Changes do not conform to Reg Guide 1.93 or Tech Specs.

  EG & O. Inc. 79/09/30. 4pp.
- 7912140290 Forwards evaluation of design & performance of ref core configuration utilizing higher enrichment fuel. Requests NRC approval by 800114 of proposed amend to revise max enrichment permitted by Tech Specs 5.3.1.

  UHRIG.R.E. Florida Power & Light Co. 79/12/12. 36pp.
- 791220040B Responds to 781129 ltr re containment purge issue. Forwards C-E ECCS performance evaluation assessment of radiological release from containment & discussion of containment purge isolation instrumentation & control circuit designs.

  UHRIG.R.E. Florida Power & Light Co. 79/12/13. 2pp.
- 7912270357 Advises that end-of-yr schedule manpower constraints & work associated w/TMI-2 Lessons Learned Task Force recommendations will delay response to request for info re containment purpe, Response will be submitted by B00215. UHRIO.R.E. Florida Power & Light Co. 79/12/21. 1p.
- 7912280548 Notifies that 791213 rept. "Program Plan for Performance Verification of PUR Sefety/Relief Valves & Sys." is responsive to requirements listed in NUREG-0578. UHR10.R. E. Florida Power & Light Co. 79/12/21. ip.
- Q. Inspection reports. IE Bulletins & correspondence
- 7912180355 Forwards IE Insp Rept 50-335/79-23 on 790910-14 & notice of SUTHERLAND, J. T. 79/10/15. 2pp. Region 2, Atlanta, Office of the Director.
- --79:2180364 IE Insp Rept 50-335/79-23 on 790910-14. Noncompliance noted: inventory of emergency items listed on Inventory Record Sheet 2 of 2 not performed for Jam.Feb & May 1979. ANDREMS, D.L., TAYLOR, P.A. Region 2, Atlanta, Office of the Director. HUFHAM, J. M. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 79/10/10. 14pp.

- 7912100260 Forwards IE Insp Ropts 50-335/79-27 & 50-389/79-17 on 791002-04. No noncompliance noted.
  SUTHERLAND.J.T. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 79/10/22. 2pp.
- --7912100274 IE Insp Repts 50-335/79-27 & 50-389/79-17 on 791002-04. No noncompliance noted Major areas inspected: mpt controls, environ monitoring stations & analytical measurements. PEERY, W. Region 2. Atlanta. Office of the Director. MUFHAM, J. W. Region 2. Atlanta. Fuel Facility & Materials Bafety Branch. 79/10/19. 3pp.
- 7912060249 Forwards IE Insp Rept 50-335/79-26 on 791009-12.No noncompliance noted.
  LEWIS.R.C. Region 2. Atlanta, Reactor Operations Nuclear Support
  Branch. 79/10/31. 2pp.
- --7912060254 IE Insp Rept 50-335/79-26 on 791009-12. No noncompliance noted Major areas inspected post-refueling zero power testing & power escalation testing preceding Cycle 3 operation. operation.
  JULIAN.C. Region 2, Atlanta, Reactor Operations Nuclear Bupport
  Branch, LEWIS.R.C. Region 2, Atlanta, Office of the Director.
  79/10/31. Spp.
- 7912060143 Forwards IE Info Notice 79-12A, "Attempted Damage to New Fuel Assemblies." No specific action or response required. D'REILLY, J.P. Region 2, Atlanta, Défice of the Director. 79/11/09. 2pp.
- 7912030050 Forwards IE Insp Rept 50-335/79-29 on 791022-25.No noncompliance noted.
  KENNA, M. B. Region 2, Atlanta, Bafaguards Branch. 79/11/13, 2pp.
- -7912030053 IE Insp Rept 50-335/79-29 on 791022-25. No noncompliance noted Major areas inspected: access control testing/maint, power supply locks & keys & licenses action on previous insp findings. Details withheld (ref 10CFR2. 790).

  MDDRE, D. E. Region 2. Atlanta, Office of the Director.

  TOBIN.W. J. Region 2. Atlanta, Safeguards Branch. 79/11/13.
- 7912110561 Forwards IE Info Notice 79-29, "Loss of Nonsefety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response roquired.

  O'REILLY.J.P. Region 2. Atlanta, Office of the Director.

  79/11/16. 2pp.
- 7912050616 Forwards IE Circular 79-24. "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No response required. O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 79/11/26. ip.
- 7912110147 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operato." No response required.

  0/REILLY.J.P. Region 2, Atlanta, Office of the Director.
  79/11/24. 1p.
- 7912100451 Ack receipt of 791108 ltr informing NRC of steps taken to correct violaton noted in IE Insp Rept 50-335/79-23.

  SUTHERLAND, J. T. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 79/11/27. 1p.
- --7912100453 Responds to NRC 791018 ltr ra violation noted in IE In\*p Rept 50-335/79-23. Corrective actions: recorded Oct 1979 inventory of emergency equipment & supplies, Procedure HP90 revised tembining Record Sheets i & 2. UHRIG.R. E. Florida Power & Light Co. 79/11/0H. 2pp.
- --7912100455 Forwards 1E Insp Rept 50-335/79-23 on 790910-14 & notice of violation.
  SUTHERLAND, J. T. Region 2: Atlanta: Fuel Facility & Materials
  Bafety Branch. 79/10/15. 2pp.
- --791210048B Notice of violation from insp on 790910-14.
  \* Region 2, Atlanta, Office of the Director. 79/10/11. ip.
- --7912100461 IE Insp Rept 50-335/79-23 on 790910-14. Noncompliance noted; Inventory Record Sheet 2 of emergency items not completed for Jan.Fab or May 1979.
  HUFTHAM, J. W. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. PERROTTI, D. J., TROJANOMSKI.R. E Region 2. Atlanta, Office of the Director. 79/10/11. 2p.

- 7912190442 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation." Written response required.
  D'RECILLY.J.P. Region 2, Atlanta, Office of the Director.
  79/11/30. 1p.
- 7912310297 Forwards IE Info Notice 79-30. "Reporting of Defects & Noncompliances, 10CFR21." No action required.
  O'REILLY, J.P. Region 2. Atlanta, Office of the Director.
  79/12/06. 5pp.
- 7912200033 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elovated Temps." Action required.
  0'RELLY.J.P. Region 2, Atlanta, Office of the Director.
  79/12/07. 2pp.
- 7912280402 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required.

  0'REILLY.J.P. Region 2, Atlanta, Office of the Director.
  79/12/13, 2pp.
- 7912280136 Forwards IE Circular 79-25, "Shock Arrestor Strut Assembly Interference," No written response required.
  O'REILLY,J.P. Region 2, Atlanta, Office of the Director.
  79/12/20. 4pp.
- 8. Reportable occurrences, LERs & related correspondence
- 7912180291 PNO-II-79-009: on 791008, high differential pressure observed on lower scal of reactor coolant pump 12B. Caused by defective pump seal. Pump seal replacement underway.

  DYER. J. A. HARDIN, A. K. Region 2, Atlanta, Office of the Director. 79/10/10. 1p.
- 7912040438 Forwards LER 79-031/01T-0. SCHMIDT, A.D. Florida Power & Light Co. 79/10/11, 1p.
- --7912040444 LER 79-031/01T-0: on 790927, during planned shutdown, GC check of installation of safety injection tank sample lines showed four raceway clips welded to vessel wall. Caused by contractor.

  SCHOPPMAN.M.A. Florida Power & Light Co. 79/10/11, 1p.
- 7912040422 Forwards LER 79-029/03L-0. SGHMIDT.A.D. Florida Power & Light Co. 79/10/17. ip.
- --7912040425 LER 79-029/03L-0:on 790917, level transmitter on 1B1 SIT drifted out of calibrilowering tank level below Tech Spec limit. Cause not determined. Transmitter recalibr. BCHO9PMAN.M.A. Florida Power & Light Co. 79/10/17. 1p.
- 7712130440 Forwards updated LER 79-015/03L-1.
  SCHMIDT.A.D. Florida Power & Light Co. 79/10/22. 1p.
- --7912130457 LER 79-015/O3L-1: on 790507.RCS boron concentration was below Tech Spec limit.Caused by vendor workers unknowingly cutting steam generator during rim cut mods. Tubes plugged & concentration restored.

  BCHOPPMAN.H.A. Florida Power & Light Co. 79/10/22. 1p.
- 7912130639 Forwards LER 79-032/03L-0. SCHMIDT.A.D. Florida Power & Light Co. 79/11/15. 1p.
- --7912130647 LER 79-032/03L-0:on 791016, during plant test of emergency diesel generator 1A, generator failed to indicate voltage or frequency after engine started. Caused by failed voltage repulator surge suppressor FP-3. Suppressor FP-1aced. SCHOPPMAN, M. A. Florida Pawer & Light Co. 79/11/15. 1p.
- DOCKET 50-334 MILLSTONE NUCLEAR POWER STATION, UNIT 2

  F. Security, medical, emergency & fire protection plans
- 7912200022 Discusses NRC 791107 meeting re emergency preparedness team review objectives. Provides guidance for improving licensee emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.

  GRIMES. B. K. Emergency Preparedness Task Force. 79/11/23. GOpp.
- 7912110305 Forwards add1 info re silicone from penetration seals for Unit 2. Original 791007 ltr erroneously addressed Unit 1. COUNSIL. M. G. Northeast Utilities. 79/12/04. 3pp.

- 7912130455 Forwards add1 response to NRC 790913 & 1030 ltrs re improved in-plant iodine instrumentation under accident conditions. Air monitors in control room area at each site will be installed by BOOIOI. Improved portable sys will be developed. COUNBIL. W. Q. Northeast Utilities. 79/12/07. lp.
- 7912210148 Submits add1 response to NRC ltr re fire protection & safe shutdown capability. Requests clarification of requests & previous negotiated agreements.
  COUNSIL.W.O. Northeast Utilities. 79/12/12. 2pp.
- Q. Adjudicatory correspondence
- 791211003B Confirms receipt of encl 790329 petition to suspend OLs for all PMRs. Forwards FR notice indicating that petition will be treated in accordance w/10CFR2. 206.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/23. 1p.
- --7912110126 Notice of request for action pursuant to 10CFR2.206 re Environ Coalition on Nuclear Power 790329 potition requesting suspension of all OLs for PWRs. MULLER, D. R. Office of Nuclear Reactor Regulation. 79/11/23. 30pp.
- P. Operating license stage documents & correspondence
- 7911090248 "Summary of Operating Experience W/Recirculating Steam Generators," EIBENHUT.D.O. Division of Operating Reactors. NUREG-0523. 79/01/31. 89pp.
- 7708010339 Notifies of status of rept on reactor cavity annulus seal.

  Most PWR users remove ring during normal operation. Others
  store seal ring in raised position during normal operation.

  LAINAS.O. Plant Systems Branch (Pre 791030). 79/07/05. 7pp.
- 7912100189 Discusses NRC 791101 meeting w/representatives of NBSS vendors & fuel suppliers re discussion of respective portions of ECCB evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vandor responses encl. EISENHUT.D. O. Division of Operating Reactors. 79/11/09. 65pp.
- --7912100255 Responds to NRC 791101 request re noncompliance of Westinghouse ECCB evaluation model under requirements of 10CFR50 App W. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants.
  ANDERSON, T. M. Westinghouse Electric Corp. 79/11/02. App.
- ---7912100330 Responds to NRC 791101 request re DRNL cladding swelling & rupture data. Review of analytical models & tests indicates compliance w/1005R50 App K. All GE specs for calculated peak cladding temp remain unchanged.

  BUCHHOLZ, R. H. General Electric Co. 79/12/07. 2pp.
- ~~7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50. 46 satisfied.

  GMSLEY, G. F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).

  79/11/02. Spp.
- --7912100486 Forwards add1 info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model.

  No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results.

  CHBLEY.G.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).

  79/11/04. 22pp.
- 771219D163 Forwards add1 info required for completion of NRC evolution of electrical override/bypass aspects of containment isolation matter. Criteria encl. LAINAB.0. Plant Bystems Branch. 79/11/19. 1p.
- 7912120262 Bummary of 791025 meeting w/C-E owners group re asymmetric LOCA loads. HOSFORD.8.B. Engineering Branch. 79/11/20. 4pp.
- 7912130005 Forwards request for addl info re loss of offsite power avents at facility Requests response within 90 days.
  REID, R. W. Operating Reactors Branch 4. 79/11/27. 3pp.
- 7912050502 Responds to NRC 791018.22 & 1121 requests re short— & long-term recommendations for auxiliary feedwater systements.

  COUNSIL.W.O. Northeast Utilities. 79/11/28. 3pc.

- 7912060505 Forwards calculations re automatic initiation of auxiliary foodwater & supporting statement that longer time is available for Haddem Neck steam generator dryout than for Millstone-R. COMPSELL.W.O. Northwast Utilities. 79/11/30. 19pp.
- 7912190261 Discusses commitment made by CT Yankee Atomic Power Co & Northeast Nuclear Energy Co to implement automatic initiation of auxiliary feedwater. Addresses util conclusion that implementation not necessary for safe operation. COUNSIL.W. Q. Northeast Utilities. 79/11/30. 6pp.
- 7912100284 Forwards "Proposed Automatic Initiation Scheme for Auxiliary Feedwater Sys," in response to NRC request for specific design details & demonstration of compliance w/HR Denton 791030 ltr.
  COUNSIL.W.O. Northeast Utilities. 79/12/06. 2pp.
- ---7912100294 "Proposed Automatic Initiation Scheme for Auxiliary Feedwater Sys." \* Northeast Utilities. 79/12/31. 7pp.
- 7912120390 Forwards rept re proposed automatic initiation of auxiliary feedwater sys in response to NRC request for sepcific design details & for demonstration of compliance w/NRC 791030 ltr to all operating nuclear power plants, COUNSIL.M.O. Northeast Utilities. 79/12/06. 18pp.
- 7912130321 Discusses interim procedures for Recommendation 2.1.8.5. until high-range capability is available re increased range of radiation monitors requirement.

  CDUNGIL.M.G. Northeast Utilities. 79/12/07. 4pp.
- 7912190409 Forwards "Summary Rept of Feedwater Piping Repsir Program & Associated Observations & Findings," re NRC 790928 request. COUNSIL, M. C. Northeast Utilities. 79/12/07. 2pp.
- --7912190414 "Summary Rept of Feedwater Piping Repair Program & Associated Observations & Findings."

  \* Northeast Utilities. 79/12/31. 10pp.
- 7912180279 Provides commitment to implement Recommendation 2, 2, 1, b reshift technical advisor in compliance w/short-term Lessons Learned Task Force requirements. Will submit compliance for containment pressure indications & RGS venting by 810101. COUNSIL.W.O. Northeast Utilities. 79/12/10. 2pp.
- 7912170294 Formally documents 791211 verbal commitments to develop procedures for Item 2.1.8.6 re increased range of radiation manisors in accordance w/criteria delineated in NRC 791030 ltr to all operating nuclear power plants.

  COUNSIL.W.O., FEE.W.F. Connecticut Yankee Atomic Power Co. 79/12/12. 2pp.
- 7912210187 Notifies of util commitment to fully implement all Category A short-term Lessons Learned Task Force requirements by BO0101 w/exception of Items 2.1.7. & 2.1.9, COUNSIL.W.O. Northeast Utilities. 79/12/17. 3pp.
- 7912210282 Forwards design drawings re automatic initiation of auxiliary feedwater in response to NRC request. W/o encl. List of drawings encl. COUNSIL. W. G. Northeast Utilities. 79/12/17. 2pp.
- 7912280004 Forwards drawings re automatic initiation of auxiliary feedwater sys. Drawings available in Central Files only. COUNSIL. W. G. Northeast Utilities, 79/12/17. 2pp.
- 7912270318 Provides info on compliance w/TMI Lessons Learned Task Force short-term item re-auxiliary feedwater sys flow indication, in response to NRC 79121; request Util installing single control grade flow indication channel per feedline.
  COUNSIL.W.Q. Northeast Utilities. 79/12/18. 3pp.
- 7912310543 Discusses review of fuel cladding strain & assembly flow blockage models in ECCS calculations to confirm conservation. Hodels in analysis are less conservative than new NRC models. Addi calculations to be campleted by 804212. COUNSIL. W. G.; SWITZER, D. C. Northeast Utilities. 79/12/27. 2pp.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912030054 Forwards IE Insp Rept 50-336/79-21 on 790814-17 & 0910-12, No noncompliance noted. CARLSON.R.T. Region i, Philadelphia, Reactor Construction & Engineering Bupport Branch. 79/09/26. 2pp.

- ---7912030054 IE Insp Rept 50-334/79-21 on 770814-17 & 0910-12 No noncompliance noted Major areas inspected: QC activities re repair of steam line to awilliary feedwater pumps & nondestructive examinations of feedwater nozzles.

  BANDERS.W.F. Region 1. Philadelphia. Office of the Director. TRIPP.L.E. Region 1. Philadelphia, Reactor Construction & Engineering Support Branch. 79/09/24. 7pp.
- 7912140287 Responds to IE Bulletin 79-24, "Frozen Lines." Dec 1975 review of all freeze protection for safety-related piping & instrumentation led to freeze protection improvements. COUNSIL, N. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 79/10/31. 2pp.
- 79:2:30:13 Forwards results of insp & analysis performed in response to IE Bulletin 79-14. "Seismic Analysis for As-Built Safety-Related Piping Bys."
  COUNSIL-#.0. Northeast Utilities. 79/11/07. 13pp.
- 7912180487 Advises that info in C-E Rept CEN-117 is applicable to facility, thereby fulfilling requirements contained in Bulletin 79-06C which requested info re inadequate core cooling.

  COUNSIL-4.9. Northeast Utilities. 79/11/09. in.
- 7912050039 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required. GRIER.B.H. Region 1, Philadelphia, Dffice of the Director. 79/11/16. 1p.
- 7912000266 Forwards IE Info Notice 79-27, "Steam Generator Tube Ruptures at Two PWR Plants." No response required. ORIER, B. H. Region 1. Philadelphia, Office of the Director. 79/11/16. 1p.
- 7912100131 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads," No response required. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/11/16. ip.
- 7912110422 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required. ORIER.B. H. Region 1, Philadelphia, Office of the Director. 79/11/19. ip.
- 7912050255 Forwards IE Bulletin 79-26. "Boron Loss From HWR Control Blades." No response required. GRIER, B. H. Region i, Philadelphia, Office of the Director. 79/11/20. ip.
- 7912060579 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No response required.

  ORIER, B. H. Region 1, Philadelphia, Office of the Director.
  79/11/26. 1p.
- 7912110060 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. GRIER, B. H. Region 1. Philadelphia, Défice of the Director. 79/11/26. 1p.
- 7912190039 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation." Written response required. GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/11/30. ip.
- 7712310226 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action required.

  ORIER, B. H. Region i, Philadelphia, Office of the Director, 79/12/06. 4pp.
- 7912190754 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Written response required. GRIER.8. H. Region 1. Philadelphia. Office of the Director. 79/12/07. ip.
- R. Pariodic operating reports & related correspondence
- 7912180392 Forwards monthly operating rept for Nov 1979. OPEKA, J. F. Northeast Utilities. 79/12/12. ip.
- ---7912180403 Monthly operating rept for Nov 1979. HGHLETT.Q.H. Northeast Utilities. 79/12/05. Spp.

- S. Reportable occurrences, LERs & related correspondence
- 7912030104 PNS-I-79-007: on 79110B, former contractor employee was arrested after making threats against former supervisors in facility parking lot Shotgun found in car of employee.

  BMODLOBKYT. Deffice of Inspection & Enforcement, Office of the Director, KEINTO.R., BRUNNER,E.J. Region i, Philadelphia, Office of the Director. 79/11/0B. ip.
- 7912040396 Forwards updated LER 79-016/03X-1.
  DPEKA, J. F. Northeast Utilities. 79/11/27. 2pp.
- ---7912040401 Updated LER 79-016/03X-1: on 790611, during plant cooldown, pressuriser pressure channel read lower than actual gressure. Caused by shift of zero point on transmitter. Boundon tube replaced & transmitter restored to svc. BATES.R.W. Northwast Utilities. 79/11/27. 1p.
- 7912040421 Forwards LER 79-035/03L-0. OPEKA.J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 79/11/28. 1p.
- --7912040426 LER 79-035/03L-0: on 791102, reactor protection sys, channel A high power level min trip setpoint exceeded Tech Spec limit. Caused by instrument drift. Setpoint potentiometer was readjusted & min high power trip setpoint restored to spec. BATEB.R.M. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 79/11/28. ip.
- 7912130459 Forwards LER 79-035/03L-0.
  DPEXA, J. F. Northwast Utilities, 79/11/28. 1p.
- --7912130468 LER 79-035/03L-0: on 791102, during surveillance testing in cold shutdown, reactor protection sys Channel A high power level min trip satpoint exceeded Tech Spec limit. Caused by instrument for let. Setpoint readjusted.

  BATES, R. W. Northeast Utilities. 79/11/28, 1p.
- 7912040407 Forwards Updated LER 79-013/03X-1. OPEKA.J.F. Northeast Utilities, 79/11/29, 1p.
- --7912040413 Updated LER 79-013/03X-1:on 790525, periodic check of control room chlorine detection sys revealed inoperable detectors. Gaused by low drip rates of detector solution onto sensor asseably, Clogged dispenses cleaned.

  BATES, R. H. Northeast Utilities. 79/11/29, 2pp.
- 7912180309 PNO-1-79-022: on 791128, const worker injured in fall from scaffold at plant site. Extent of injuries unknown. No radioactive matl involved.
  ZIPMERMAN, R.P., KEIMIOR, R., BRUNNER, E. J. Region i, Philadelphia, Office of the Director. 79/11/29. ip.
- 7912070301 Forwards LER 79-034/03L-0.
  OPEKA.J.F. Northeast Utilities. 79/11/30. ip.
- --7912070385 LER 79-034/03L-0: on 791101, during cold shutdown, containment personnel air lock inner & outer doors opened at same time for 30-s. Caused by bent operating shaft Shaft straigtened & lock operable.

  CLEMENT, C. H. Northeast Utilities. 79/11/30. ip.
- 7912180589 Forwards LER 79-037/03L-0. OPEKA, J. F. Northeast Utilities. 79/12/10. 1p.
- --7912180601 LER 79-037/03L-0: on 791114 during routine maint, leakage discovered on boric acid evaporator B concentrates pump discharge line, due to hairline crack in Type 304 stainless steel pipe. Caused by chloride stress corrosion cracking. HARRIS, J. B. Northeast Utilities. 79/12/07. 1p.
- 7712180575 Forwards LER 79-038/03L-0. OPEKA, J. F. Northeast Utilities. 79/12/13. ip.
- ---7912180881 LER 79-038/03L-0: on 791113; leakage discovered on acrated radwasta drain line, Caused by wall pitting or cracking. Failed pips section will be replaced when math is available & further investigation will be conducted. HARRIS. J. B. Northeast Utilities. 79/12/13. ip.

- DOCKET 50-338 NORTH ANNA POWER STATION, UNIT 1
- F. Security, medical, emergency & fire protection plans
- 7912200022 Discusses NRC 791109 meeting re emergency preparadness team raview objectives. Provides guidance for improving licenses emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.

  ORIMES, B. K. Emergency Preparedness Task Force. 79/11/23, 30pp.
- 7912040374 Responds to NRC 791010 ltr requesting info re upgrading of emergency planning. Responses will be submitted by 791207.
  STALLINGS, C. M. Virginia Electric & Power Co. 79/11/29. 1p.
- 7912050570 Forwards license fee for review of security personnel training & qualification program submitted in 790817 ltr.
  STALLINGS.C.M. Virginia Electric & Power Co. 79/11/29. 2pp.
- 7912070131 Forwards amended pages to approved security plan. Changes withheld (ref 10CFR2.790).

  8TALLINGS, C. M. Virginia Electric & Power Co. 79/12/03. ip.
- 7912130327 Forwards proposed revision to emergency plan, in response to NRC 791010 ltr.Plan designed for compatibility w/NRC concurred state & county radiological response plans, to provide for overall response effort.

  BTALLINOS, C. M. Virginia Electric & Power Co. 79/12/10. 1p.
- --7912130341 Proposed revision to emergency plan.
  \* Virginia Electric & Power Co. 79/12/10. 200mp.
- G. Adjudicatory correspondence
- 79:21:10043 Forwards comments on NUREQ-051: Draft QEIS reflects conscious & deliberate NRC policy to jeopardize public health & safety & thwart objectives of NEPA, KEPFORD. C. Environmental Coalition on Nuclear Power. 79/10/24. 22pp.
- 79:2050481 Ack receipt of 79:106 ltr re errors in certain pipe stress analyses. Requests full rept on nature & scope of errors, focusing on relation between errors & settlement issue.

  BISHOP, G. J. Atomic Safety and Licensing Appeal Panel. 79/11/08.
- 7912140148 Confirms 791108 ltr re VEPCO rept on analytical errors in pipe stress analyses. Rept will be submitted by 791210.
  CHRISTMAN, J. N. Hunton & Williams, 79/11/15, 1p.
- 7912060239 Ack receipt of 791115 ltr re pumphouse settlement issue. Requested rept should be filed no later than 791210 in order to expedite ASLB decision. Awaits NRC & parties comments. BISHOP, C. J. Atomic Sefety and Licensing Appeal Panel. 79/11/16. ip.
- 79:21:10038 Confirms receipt of encl 790329 petition to suspend OLs for all PMRs. Forwards FR notice indicating that petition will be treated in accordance w/i0CFR2. 206.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/23. Ip.
- --7912110126 Notice of request for action pursuant to 10CFR2,206 ra Environ Coalition on Nuclear Power 790329 petition requesting suspension of all OLs for PMRs. MULLER, D.R. Office of Nuclear Reactor Regulation. 79/11/23. 38pp.
- 7912120169 Brief in apposition to intervenors 791026 exceptions on ASLB 790824 order granting VEPCO motion for summary disposition. If not affirmed, urges ASLAB permit use of high density racks pending conclusion of praceeding Certificate of Byr encl. CHRISTMAN, J. N., MAUPIN, M. W. Virginia Electric & Power Co. 79/11/30, 58pc.
- --7912120174 Answer in opposition to VEPCO 790505 motion for summary disposition Full exploration of issues needed for appropriate relief.
  DUUGHERTY, J. B. Potomac Allience, 79/06/05, Spp.
- --7912120178 Statement of matl facts as to which there is no genuine issue to be heard re VEPCO motion for summary disposition. Affidavit & Cartificate of Svc encl.
  DOUGHERTY, J. B. Potomac Alliance. 79/06/05. 4pp.
- ---7912120184 Supplemental answer in opposition to VEPCO 790505 motion for summary disposition Urges ABLE to apply stds encouraging courts to be liberal re opportunity for full development of factual bases & arguments. Certificate of Svc encl. DOUGHERTY, J. B. Potomac Alliance. 79/06/25. Spp.

- --7912120189 Second supplemental answer in opposition to VEPCO 790505 motion for summary disposition. Radioactive emission.missile accidents & other issues are subj to major factual gaps. W/pleading pages on mat integrity & other related matters. DOUGHERTY. J. B. Potomac Alliance. 79/07/23. 45pp.
- --7912120193 Affidavit attesting that no credible analysis of Potomac Alliance alternatives may be undertaken w/o examination of greater body of facts. Prof qualifications encl. WEITZMAN.P.M. Affiliation Unknown. 79707/23. 9pp.
- --7912120197 Notion to amend petition to intervene Facility svc water cooling sys will not support spent fuel pool component cooling sys if mod permitted Formal discovery pages & informal discovery ltrs encl. DOUGHERTY, J. B. Potomac Alliance. 79/05/09. 14pp.
- 7912140002 Order scheduling 800103 oral argument for intervenors' appeal re storage pool mod. Parties must inform ASLB by 791221 of names of counsel.
  BISHOP.C. J. Atomic Safety and Licensing Appeal Panel. 79/12/05, 200
- 7912140172 Responds to ASLAP 79110B request Forwards "Rept on Effect of Outdated Amplified Response Spectrum Curves on Bvc Water Pumphouse Settlement," which details errors in stress analysis.

  CHRISTMAN, J. N. Hunton & Williams, 79/12/05, App.
- 7912180168 Opposition to intervenors Potomac Alliance & Citizens Energy Forum 791026 amended statement of erceptions. Intervenors were given ample opportunity to respond to NRC 790625 request for summary judgment Certificate of Sive encl. GOLDBERG. 8. C. Hearing Branch 2. 79/12/10. 26pp.
- 7912310366 Recommends forwarding encl addl info re Hostinghouse turbine disk matl to ABLAB.
  PAWLICKI.S.S. Materials Engineering Branch. 79/12/12. ip.
- --7912310377 Recommends notifying ASLAB of Wastinghouse turbine disk cracking, based on info in 791105 anonymous ltr, 791120 telcon w/Westinghouse & PNO-III-79-43 re low pressure disk cracks at Zion Unit 1.

  BOYLE M.L. Materials Engineering Branch. 79/12/12. 3pp.
- ---7912310386 Notifies that Westinghouse briefed utils re problems w/ stress corresion cracking in Westinghouse low pressure rotors & problems w/i.800 rpm low pressure turbines, reportable per 10CFR50.55(e) or 10CFR51.W/lists of plants. \* Westinghouse Electric Corp. 79/11/05. 4pp.
- 7912200636 Notifies that SC Goldberg will present oral argument on behalf of NRC per ABLAB 791205 order. GOLDBERG.S.C. Hearing Branch 2. 79/12/17. ip.

# H. General correspondence

- 7912100419 Summarizes procedures used in approving emergency response plan, in response to 790927 ltr re 790925 event.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/21. 3pp.
- 7912180332 Requests that all facility correspondence be forwarded to new address in Boulder.CO.
  FOSTER.B. M. Musick.Willamson.Schwartz.Leavenworth & Cope, P. C.
  79/11/27. ip.
- P. Operating license stage documents & correspondence
- 7911070248 "Summary of Operating Experience M/Recirculating Steam Generators." EISENHUT.D.G. Division of Operating Reactors. NUREO-0523. 79/01/31. 89pp.
- 7908010339 Notifies of status of ropt on reactor cavity annulus sual. Most PHR Users ranove ring during normal operation. Dehers store seal ring in relased position during normal operation. LAINAG. G. Plant Bystems Branch (Pre 791030). 79707/05. 7pp.
- 7912120449 Forwards modified Tuch Spec Change 20, changing Table 3.6-1 list of automatic isolation valves inside & outside of containment.

  BTALLINGS, C. M. Virginia Electric & Power Co. 79/10/10. 3pp.
- --7912120452 Modified Tech Space Change 23, changing Table 3.6-1 to add automatic valves 1-14-55 & TV-14-1028 & deleting valve TV-1024. \* Virginia Electric & Power Co. 79/10/10. 2pp.

- 7712100411 Discusses NRC concern re containment purging & venting during normal operation. Includes licensee override of safety actuation isolation signals to containment isolation valves & valve ability to shut w/o degrading containment. SCHWENCER, A. Operating Reactors Branch 1. 77/10/30. Bpp.
- 7912100189 Discusses NRC 791101 meeting w/representatives of NBS8 vendors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swalling & incidence of rupture. Vendor responses encl. EISENHUT.D.G. Division of Operating Reactors, 79/11/09. 65pp.
- --7912100255 Responds to NRC 791101 request re noncompliance of Hestinghouse ECC9 evaluation model under requirements of 10CFR50 App K. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants.

  ANDERSON, T. M. Westinghouse Electric Corp. 79/11/02. App.
- --7912100330 Responds to NRC 791101 request re ORNL cladding swelling & rupture data. Review of analytical models & tests indicates compliance w/100FR50 App K.All OE specs for calculated peak cladding temp remain unchanged.

  BUCHHOLZ, R. H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50.46 satisfied.

  DWSLEY, G.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.), 79/11/02. Spp.
- --7912100456 Forwards add1 info re evaluation of impact of NRC proposes rupture/blockage model used in vendor evaluation model.

  No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results.

  OMSLEV. 9. F. Exxon Nuclear Co., Inc. (subs. of Exxon Gorp.).

  79/11/04. 22pp.
- 7912100022 Discusses issuance of Amend 17 to License DPR-64, which authorized operation at 100% power. Max allowable fee already paid by util. No addl fee required.

  MILLER, W. D. License Fee Management Branch. 79/11/13. 1p.
- --7912100066 Provides ACRS prof manpower expanditure estimates for CP k GL reviews. FRALEY.R.F. ACRS - Advisory Committee on Reactor Safeguards. 78/11/01, 1p.
- --7912100079 Requests info re ACRB prof man-hrs expended on review of each reactor. Data for safety, environ & antitrust hearing concerns should be included. Associated trayel should not be shown.
  MILLER, W.O. License Fee Management Branch. 78/10/02. 1a.
- 7912040496 Submits Final General Design Critaria-17 compliance review results. Minor mods to switchyard to meet intent of NRC 790808 requirements. Operator procedures revised to eliminate loss of both offsito sources due to tie breaker failure. STALLINGS, C. M. Virginia Electric & Power Co. 79/11/28. 3pp.
- 79;2030201 Requests detailed syllabus for Oak Ridge Associated Univ radiation safety seminar.Lists addl info required prior to reaching final determination of acceptance. BTALLINOS.C.M. Virginia Electric & Power Co. 79/11/29. ip.
- 7912030209 Requests amend to License NPF-4. Forwards Proposed Tech Spec Change 27 re power distribution limits, Safety analysis & Class 111 fee encl. STALLINGS.C.M. Virginia Electric & Power Co. 79/11/29. G9pp.
- --7912030210 Proposed Tech Specs 3/4, 2 re power distribution limits.
  \* Virginia Electric & Power Co. 79/11/29, 5pp.
- 7912140134 Notification of 791129 meeting w/util & Westinghouse re inservice of steam generator at facility.
  ENGLE.L. Operating Reactors Branch 1. 79/11/29. 2pg.
- 7912200047 Summarizes 791116 telcon w/util re implementation schedule of Lessons Loarned Task Force recommendations. Forwards list of items for which proposed schedule is unaceptable & list of items for which proposed action does not comply w/stds. ENGLE, L. Operating Reactors Branch 1. 79/11/29. 7pp.
- 7912070325 Requests amend to License NPF-4 & forwards Tech Spec Change 25.adding & deleting safaty-related hydraulic snubbers listed in Table 3.7-4.

  BTALLINOB.C.M. Virginia Electric & Power Co. 79/12/06. 3pp.

- ---7912070326 Tech Spec Change 25, adding & deleting safety-related hydraulic snubbers listed in Table 3, 7-4.

  \* Virginia Electric & Power Co. 79/12/06. 2pp.
- 7912100364 Requests change to Tech Specs, substituting nongapped restraint for existing gapped restraint/stop for main steam line support Mod will redistribute piping sys loads, ensuring lavels are within original allowances. Class II fee encl.

  BTALLINGS, C. M. Virginia Electric & Power Co. 79/12/06. 3pp.
- --7912100377 Tech Spec 3/4 7-53a, Table 3, 7-4 for safety-related hydraulic shubbers.

  \* Virginia Electric & Power Co. 79/12/06. 2pp.
- 7912270089 Responds to 791107 ltr re delays in facility licensing. Policy statement re adaptation of licensing procedures to include recommendations of TMI task forces will be issued shortly.

  MENDRIE, J. M. Commission. 79/12/07. ip.
- 7912270092 Responds to 791108 ltr expressing concern re delays in licensing of facilities. Policy statement re adaptation of licensing procedures to include recommendations of TMI task forces will be issued shortly.

  HENDRIE, J. M. Commission. 79/12/07. 1p.
- 7912310199 Forwards request for add1 info re facility Cycle 2 raload amend to complete review of 791102 submittal, SCHMENCER, A. Operating Reactors Branch 1. 79/12/07. 3pp.
- 7912310109 Forwards request for info needed for review of util 781102 response to auxiliary feedwater sus requirements. Answer should be submitted by 791217.

  BCHWENCER, A. Operating Reactors Branch 1. 79/12/14. 5pp.
- 7912200518 Commits to full implementation of all Category A requirements from TMI-2 Lessons Learned Task Force by BO0151.

  PROFFITT.W.L. Virginia Electric & Power Co. 79/12/17. 1p.
- 7912200562 Forwards procedural changes required to address control rod drop analysis concerns & withdraws 790706 proposed Tech Spec Change 21 re control red insertion limits. BTALLINOS,C.M. Virginia Electric & Power Co. 79/12/17. 2pp.
- 79122701B7 Forwards proprietary response to NRC 791207 request for info re Cycle 2 reload as suppl to util 791102 ltr. Affidavit for withholding proprietary info sent to PDR. Rosponse withheld (ref 10CFR2. 790).
  BTALLINGB.C.M. Virginia Electric & Power Co. 79/12/17. 5pp.
- 7912280209 Bubmits addl info for proposed Tech Bpec Amend 27 re LOCA-ECGS calculation for small break using nonheatup rate dependent burst curve.

  STALLINGS, C. M. Virginia Electric & Power Co. 79/12/19. 2pp.
- 7912260211 Notifies of util intent to plug more steam generator tubes in Unit 1. Program will not impact or invalidate non-LDCA safety analysis in FBAR.

  STALLINGS.C.M. Virginia Electric & Power Co. 79/12/19. ip.
- 7912260216 Forwards rept, "Rosemount Model 1182 Severe Environ Teat," in response to NRC 791120 request for add1 info.
  BROWN, S. C. Virginia Electric & Power Co. 79/12/19. ip.
- --7912260218 "Rosemount Model 1152 Bavere Environ Test."

  \* Virginia Electric & Power Co. 79/12/19. 31pp.
- 7912270494 Advises that operation under Tech Specs 3.6.1.1 & 3.6.1.4 conforms w/MRC interim position re qualification of containment purging & venting valves.

  BTALLINGS.C.H. Virginia Electric & Power Co. 79/12/20. 2pp.
- 7912270349 Advises that info re separation of electrical equipment & sys was submitted Jul 1975, during electrical installation.
  Similar problems reported by MPPSS were covered in IE Insp.
  Rapts 50-338/75-9,75-11 & 75-16 & 50-339/75-9,75-10 & 75-11,
  BROWN, S. C. Virginia Electric & Power Co. 79/12/21, 2pp.
- 7912310371 Forwards revised Pages 3/4 7-5 & 7-6 for proposed Change 26to Tach Space re requirements for auxiliary feedwater sys. Fab enci. BTALLINGS.C.M. Virginia Electric & Power Co. 79/12/29. 3pp.
- --7912310374 Revised Pages 3/4 7-9 & 7-6 for proposed Change 26 to Yech Space to auxiliary feedwater sys requirements. Change will assure flow path varification during startup. • Virginia Electric & Power Co. 79/12/28. 2pp.

- O. Inspection reports, IE Bulletins & correspondence
- 7912060100 Forwards IE Insp Repts 50-338/79-38 & 50-339/79-44 on 790904-14 & 20-25. No noncompliance noted. LEWIS.R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/10/30. 2pp.
- --7912060114 IE Inap Repts 50-339/79-38 & 50-339/79-44 on 790904-14 & 20-25. No noncompliance noted Major areas inspected: LER, plant tours new fuel storage & licensee insp of certain induction disc relays.

  XELLOGO, P.J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. KIDD.M.S. Region 2, Atlanta, Office of the Director. 79/10/25. 7pp.
- 7912120264 Forwards IE Insp Repts 50-338/79-37 & 50-339/79-51 on 790924-27. No noncompliance noted. LEHIG.R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/11/01. 2pp.
- --7912120275 IE Insp Repts 50-338/79-37 & 50-339/79-51 on 790924-27. No noncompliance noted Major areas inspected significant event followup, LERs & fire protection program.

  WEBSTER, E. H. Region 2. Atlanta, Office of the Director.

  RELLOGO, P. J. Region 2. Atlanta, Reactor Operations Nuclear 39/11/01. App.
- 7912030070 Forwards 1E Insp Rept 50-338/79-44 on 791023-26. No noncompliance noted.

  KENNA, H. B. Region 2, Atlanta, Safeguards Branch. 79/11/13. 2pp.
- --7912030074 IE insp Rept 50-338/79-44 on 791023-26.No noncompliance noted Major areas inspected; review of security organization, protected area, physical barriers & vital area access control Details withheld (ref 10CFR2, 790).

  HOWELL, J. C., TILLMAN, A., TOBIN, W. J. Region 2, Atlanta, Diffice of the Director. 79/11/09. ip.
- 7912100201 Forwards IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads." No response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/16. 1p.
- 7912110BB7 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required.
  D'REILLY, J. P. Region 2. Atlante, Diffice of the Director.
- 79120700D7 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BMRs." No response required.

  D'REILLY.J.P. Region 2. Atlanta. Office of the Director.
  79/11/26. ip.
- 7912110186 Forwards IE Circular 79-23, "Motor Btarters & Contactors Failed to Operate." No response required.
  O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
  79/11/26. 1p.
- 79:2200:07 Responds to IE Bulletin 79-17.Revision 1 re stagnant borated water sys. Ultrasonic examinations for pipe cracks to be conducted in May 1980 following procedure approval.

  STALLINGS.C.M. Virginia Ejectric & Power Co. 79/11/29. 2pp.
- 7912190492 Forwards IE Bulletin 79-27, "Loss of Non-Class, IE Instrumentation & Control Power Sys Bus During Operation." Written response required.

  O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/30. io.
- 7912310330 Forwards IE Info Notice 79-30: "Reporting of Defects & Noncompliances: 100FR21." No action required. D'REILLIV.J.P. Region 2: Atlanta, Office of the Director. 79/12/04. Spp.
- 7912200070 Forwards IE Bulletin 79-20, "Possible Halfunction of Nemco Hodel EA180 Limit Switches at Elevated Temps." Action required. 0 /REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/12/07. 2pp.
- 7912310255 Responds to IE Bulletin 79-02, Revision 2. "Pipe Support Bass Plate Designs Using Concrete Expansion Anchor Boits."
  No pipe supports for Seismic Category 1 sus attached to concrete block walls w/anchor bolts at facilities.
  BROWN. S. C. Virginia Electric & Power Co. 79/12/07. Opp.
- 791212043B Forwards refueling steam generator inservice insp rept. STALLINGS.C.M. Virginia Electric & Power Co. 79/12/10. 1p.

- --7912120441 Inservice insp rept describing examination of steam generator during first refueling.
  \* Virginia Electric & Power Co. 79/12/10. 46pp.
- 7912280441 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required.
  O'REILLY, P. Region 2, Atlanta, Office of the Director.
  79/12/13. 2pp.
- 7912200378 Forwards results of feedwater sys piping insps.in response to IE Bulletin 79-13. Revision 2 recracking in feedwater piping.
  BTALLINGS.C.M. Virginia Electric & Power Co. 79/12/17. 4pp.
- 7912270421 Ack receipt of 791107 & 1207 ltrs re IE Insp Rept 50-338/79-40 & forwards revision to corrective actions. Welds satisfactorily re-examined on 791012. Contractor cautioned requality of liquid penetrant testing.

  STALLINOS.C.M. Virginia Electric & Power Co. 79/12/20. 2pp.
- 7912280161 Forwards IE Circular 79-25, "Shock Arrestor Etrut Assembly Interference." No written response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/12/20. 4pp.
- 791231054B Forwards response to violation noted in IE Insp Rept 50-338/79-45 & 50-339/79-54, Corrective actions: records of training & qualification for current employees will be maintened as lifetime records.

  STALLINOS
- R. Periodic operating reports & related correspondence
- 7912140377 Forwards monthly operating rept for Nov 1979. STALLINGS, C. M. Virginia Electric & Power Co. 79/12/12. 1p.
- --7912140390 Monthly operating rept for Nov 1979. MADISON, W. R. Virginia Electric & Power Co. 79/12/06. App.
- 8. Reportable occurrences, LERs & related correspondence
- 7912190751 PNO-II-79-001C: on 791005, completed investigation into cause of overpressurization of vol control tank & release of radioactive gases into bldg. Caused by high influx of water from primary sys.
  ALDERBON, G., KELLOOG, P. J. Region 2, Atlanta, Office of the Director. 79/10/10. lp.
- 7912120059 Submits potential significant deficiency rept re partially exposed wire in areas of insulation splice in control cable bundle.Faulty splice removed & cable properly terminated.
  STALLINGS,C.M. Virginia Electric & Power Co. 79/10/26. 2pp.
- 7912070046 PNO-II-79-24: on 791105, error found in analysis of piping sys seismic response. Error discovered during reanalysis of piping sys in response to IE Bullatin 79-14. Reanalysis & corrective action estimated to require eight wis. HEBSTER.E.H., KELLOGO, P.J., Region 2, Atlanta, Office of the Director, 79/11/05. ip.
- 7912080646 PNO-II-79-029: on 791107, control room & safeguards area schaust ventilation damper functions occurred w/o separate operator action, Caused by design error. Generic vendor considerations & plant desings under review.

  MEBSTER.E.H., KELLOGO, P.J., Region 2, Atlanta, Office of the Director. 79/11/07. 1p.
- 7912040377 Notifies of delay in completion of valve & operator weight verification program as identified in IE Bulletin 79-14, due to deficiency re amplified response spectrum curves in pipe stress analyses for sefety-related sys.

  BROWN.8.C. Virginia Electric & Power Co. 79/11/09. Rpp.
- 7912130519 Submits 24-h reportable event written followup re undetscable failure of P-4 contacts in engineered safety features actuation sys. Caused by Heatinghouse design error. Procedures for testing P-4 contacts being evaluated, \* Virginia Electric & Power Co. 79/11/14. ip.
- 7912170407 PNG-II-79-25A: on 791115, further review of safety function resot design errors revealed recirculation spray pumps, svc water radiation monitor pumps, casing cooling pumps & four save water valves affected by actuation signal reset.
  WEBSTER, E. H., KELLOGO, P. J. Region 2, Atlanta, Office of the Director. 79/11/15. 1p.

- 7912190668 Submits Part 21 rept re potential nonconservative feature of Westinghouse large break LOCA-ECCS evaluation model.
  Defect could affect peak clad temp calculated for LOCA transient. Analysis will be completed by early Dec 1979.
  STALLINOS.C.M. Virginia Electric & Power Co. 79/11/28. 2pp.
- 7912040312 Forwards LER 79-150/03L-D. BTALLINGS.C.M. Virginia Electric & Power Co. 79/11/29. 1p.
- --7912040316 LER 79-150/03L-0; on 791101. during refueling shutdown, discovered failure to perform required weakly surveillance of dc distribution sys. Caused by loss of administrative control. Bys tested & personnel notified of error.

  CARTHRIGHT, M. R. Virginia Electric & Power Co. 79/11/28. 2pp.
- 7912070380 Forwards LERs 79-152/01T-0 & 79-153/01T-0. STALLINGS.C.M. Virginia Electric & Power Co. 79/12/04. 1p.
- ---7912070386 LER 79-152/01T-0: on 791116, nonconservatism found in error analysis of nuclear instrumentation reactor rate trip circuit. Caused by improper treatment of factors affecting accuracy of reactor protection rate trip circuitry.

  CARTWRIGHT, W. R. Virginia Electric & Power Co. 79/11/30. 2pp.
- —7912070388 LER 79-153/01T-0: on 791116, nunconservatism found in method used to generate power distributions & rod worths for dropped rod events, Caused by improper analysis of reactivity distributions & rod worths.
  CARTHRIGHT.M.R. Virginia Electric & Power Co. 79/11/30, 2pp.
- 7912070407 Forwards LER 79-145/03L-0. BTALLINGS,C.M. Virginia Electric & Power Co. 79/12/04. ip.
- ---7912070409 LER 79-145/03L-0: on 791106.RHR sys removed from svc when sys inlet valve MOV-1701 closed. Caused by installation of jumper in solid state protection sys to allow performance of time response testing Jumper removed immediately.

  CARTURIGHT.W.R. Virginia Electric & Power Co. 79/12/04. 2pp.
- 7912120306 Forwards LER 79-141/01X-1. STALLINGS.C.M. Virginia Electric & Power Co. 79/12/10. 1p.
- ---7912120311 LER 79-141/01X-1: on 791106, sys operation review revealed design deficiencies in engineered safety feature equipment. Deficiencies could result in less conservative operation than assumed in FSAR Cause unknown.

  CARTWRIGHT, H. R. Virginia Electric & Power Co. 79/12/10. 3pp.
- 7912180564 Forwards LER 79-146/03L-0. STALLINOS.C.M. Virginia Electric & Power Co. 79/12/12. 2pp.
- -7912180570 LER 79-146/03L-0; on 791116, w/unit in refueling shutdown, pressurizer level protection channel III found to be reading erratic & inconsistent w/actual level Caused by defective andule amplifier in transmitter LT-1461.

  CARTHRIGHT, W. R. Virginia Electric & Power Co. 79/12/14. ip.
- 7912270468 Submits add1 info rs LER 79-151/017-0. During review of IE Bullatin 79-14 re seismic analysis discovered that amplified response spectrum curves had two or more values of acceleration for same period, Tables snc1.

  STALLINGS.C.M. Virginia Electric & Power Co. 79/12/19, 11pp.
- 7912270582 Forwards LER 79-158/017-0. STALLINGS.C. M. Virginia Electric & Power Co. 79/12/20. ip.
- ---7912270588 LER 79-158/01T-0: on 791211. during Mode 5,86M notified util that nonseismically qualified pressure differential switch (PDB-HV1228A & B) had been used in condenser water controls in control room air conditioners.

   Virginia Electric & Power Co. 79/12/21. 2pp.
- DOCKET 50-339 NORTH ANNA POWER STATION, UNIT 2
- A. Application/construction stage documents & correspondence
- 7912110011 Forwards NRC position on status & applicability to paneling DL applications of results of TMI followup actions. Dutlines add abort-term actions to be taken.
  VASSALLO, D. B. Bivision of Project Management. 79/09/27. 41pp.
- 7912110264 Discusses NRC plans to use generic analyses to devalup early verification program to resolve ATMS issue for PMRs & BMRs.
  Success of program depends on industry response. Supports formation of owners groups to provide nacessary info.
  DENTON.H.R. Defice of Nuclear Reactor Regulation. 79/10/17. 3pp.

- 7911270467 Forwards "Discussions of TMI Lessons Learned Short-Term Requirements" providing addl clamifications of NRC requirements for pending OL applicants. VASSALLO, D. B. Division of Project Management. 79/11/09. 2pp.
- 7912100022 Discusses issuance of Amend 17 to License DPR-64. which authorized operation at 100% power. Max allowable fee already paid by util. No addl fee required.
  MILLER. M. D. License Fee Management Branch. 79/11/13. 1p.
- --7912100066 Provides ACRB prof manpower expenditure estimates for CP & OL reviews.
  FRALEY, R. F. ACRB Advisory Committee on Reactor Safeguards.
  79711/01. 1p.
- 7912200312 Bupports C Horne 791107 request that NRC expedite licensing of facility to ease dependency on foreign oil Nuclear facility would lower prices for eastern NC electric customers.

  MOROANIR. Senate. 79/11/20. ip.
- ---7912200316 Requests that NRC expedite licensing of facilty to ease dependency on foreign oil.
  HORNErC, D. Affiliation Unknown. 79/11/07. 1p.
- ---7912200322 Requests that NRC expedite licensing of facility. Delay results in unjustifiable financial burden on citizens of VA. COLEMAN. M. Veterans Administration. 79/11/23. 3pp.
- --7912200328 Discusses NRC moretorium on licensing of operating reactors.
  Delay in licensing of facility will have severe financial impact on citizens of VA.Util is committed to implementing all NRC recommendations.
  TRIBLE.P.S., BATTERFIELD.D.E, DANIEL.H.C. House of Rep. 79/11/08, 28
- --7912200334 Responds to 791105 request that Commission reconsider decision to delay licensing & rescind licensing moratorium. Policy statement addressing question of resumption of licensing of completed plants forthcoming. HENDRIE, J. M. Commission. 79/12/03. 1p.
- --7912200345 Ack receipt of 791123 ltr re concern over delays in licensing Policy statement addressing question of resumption of licensing of completed plants forthcoming. HENDRIE.J.H. Commission. 79/12/03. 1p.
- --7912200351 Requests that Commission reply to Oovernor Dalton 791105 request for reconsideration of NRC decision to delay licensing of plant.

  DANIEL,K.W. House of Rep. 79/11/06. 1p.
- --7912200357 Notifies that NRC moratorium on licensing of nuclear power stations causes economic hardship on citizens of VA. Util has set all NRC criteria resulting from TMI. ROBB.C.E. Virginia. State of. 79/11/07. 2pp.
- ---7912200362 Submits concern re announced general moratorium on licensing of new nuclear generating facilities & potential cost impact of delay in startup of plant.

  HUNT.J.B. North Carolina. State of. 79/11/08. 2pp.
- --- 7912200370 Discusses economic consequences re NRC decision to postpone licensing proceedings. Urges reconsideration of plant licensing.

  BRADSHAH, J. L., SHANNON, P. C., HARWOOD, T. P. Virginia, State of. 79/11/08. is.
- --7912200376 Requests, on behalf of Board of Directors of Williamston Area Chamber of Commerce, that NRC issue OL to facility. Decision will lower energy bills of citizens of northeastern NC & reduce US dependence on for
- ---7912200382 Discusses disappointment re moratorium on issuance of new licenses & resulting economic impact.
  RAGONE.S. Virginia Electric & Power Co. 79/11/08. 2pp.
- ---7912200388 Discusses concerns re moratorium on issuance of new licensing & economic impact of delaying unit. HELMS.J., FOUNTAIN.L.H., HORGAN.R. Senate. 79/11/08. 2pp.
- ---7912200393 Discusses concerns re moratorium on issuance of new licensing & economic impact of delaying unit. FLOWERS.M.R. Affiliation Unknown, 79/11/13, 2pp.
- ---7912200399 Requests reconsideration of moratorium on licensing of plant due to economic impact of delay & oil shortage.
  RANDOL.A. 9., RANDOL.O.K. Affiliation Uninoum. 79/11/13. 1p.

- --7912200403 Requests exception be made for plant re moratorium on new licensing. KEPHART, C. O. Affiliation Unknown. 79/11/14. 1p.
- ---7912200410 Requests info on closing of plant due to proximity to large population ctrs.
  GLASBERGO, M. Hirschkop & Orad P.C. 79/11/14. 1p.
- --7912200413 Requests that Commission re-examins decision to impose moratorium on licensing new nuclear units. Increased cost of electricity will pose serious hardship on members, POLAND.C.P. Affiliation Unknown. 79/11/14. 1p.
- ---791220041B Submits concerns re decision to delay licensing of plant.
  Delay in licensing imposes economic hardship on people
  residing in northeastern NC.
  TAYLOR, D. R. Affiliation Unknown. 79/11/15. ip.
- --7912200422 Discusses concerns re moratorium on new licensing & economic impact of delay on public.
  TRIPP.R.W. Affiliation Unknown. 79/11/15. 2pp.
- --7912200424 Requests continued moratorium on all nuclear plants until compliance is made w/all existing safety stds. FIRCH.R.H. Affiliation Unknown. 79/11/29. 1p.
- 7912110010 Forwards proposed Revision 2 to Reg Guide 1.97.

  "Instrumentation for Light Water Cooled Nuclear Power Plants to Assess Plant & Environs Conditions During & Following Accident." Requests comment.

  VARGA.S. A. Assistant Director for Light Water Reactors. 79/11/23.
- 7912060186 Bummary of 791120 meeting w/util at facility re environ qualifications of Rosemount Model 1152 differential pressure transmitters.
  DROMERICK.A.W. Light Water Reactors Branch 3. 79/11/27. App.
- 7912040494 Submits Final General Design Criteria-17 compliance review results. Minor mods to switchyard to meet intent of NRC 790808 requirements. Operator procedures revised to eliminate loss of both offsite sources due to tie breaker failure. STALLINGS.C.M. Virginia Electric & Power Co. 79/11/28. 3pp.
- 7912030209 Requests amend to License NPF-4. Forwards Proposed Tech Spec Change 27 re-power distribution limits. Safety analysis & Class III fee encl. BTALLINGS.C.M. Virginia Electric & Power Co. 79/11/29. 39pp.
- ---7912030210 Proposed Tech Specs 3/4.2 re power distribution limits.

  \* Virginia Electric & Power Co. 79/11/29. 5pp.
- 7912100212 Notification of 791130 meeting w/util re TMI Lessons Learned Task Force recommendations.

  DROMERICK.A.W. Light Mater Reactors Branch 3. 79/11/29. 3pp.
- 7912310114 Forwards WPPBS 790816 ltr indicating over 150 violations of separation criteria in control room.Requires audit of installed electric equipment to determine conformance. PARR, O. D. Light Water Reactors Branch 3. 79/11/29. 3pp.
- 7912180122 Requests amond of FBAR to state intent re compliance w/NRC position on electrical protection of containment panetrations.

  PARR.O. D. Light Water Reactors Branch 3. 79/11/30. 5pp.
- 7912110289 Summary of 791130 meeting w/util re THI Lessons Learned Task Force recommendations.
  DROMERICK.A.W. Light Water Reactors Branch 3. 79/12/04. 4pp.
- 7912070338 Discusses summary of special tests designed to verify establishment of natural circulation in primary sys. Test grogram has considerable merit & will emblie plant staff to verify procedures & design predictions. Summary of test encl. STALLINGS, C. M. Virginia Electric & Power Co. 79/12/05. 11pp.
- 7912140046 Notification of 791212 & 13 meeting w/util in Louise.VA to discuss radiological shielding around pressure vessel & fuel transfer tubs.

  DROMERICK.A. M. Light Water Reactors Branch 3. 79/12/07. 3pp.
- 79122700B9 Responds to 791107 ltr re delays in facility licensing. Policy statement re adaptation of licensing procedures to include recommendations of TMI task forces will be issued shortly.

  HENORIE, J. M. Commission. 79/12/07. 1p.

- 7912270092 Responds to 791108 ltr expressing concern re delays in licensing of facilities. Policy statement re adaptation of licensing procedures to include recommendations of TMI task forces will be issued shortly.

  HENDRIE, J. M. Commission. 79/12/07. 1p.
- 7912310145 Forwards resolution Howard County Board of Supervisors supports licensing.
  LONGMIRE.J.E. Virginia, State of. 79/12/07. 3pp.
- 7912270007 Notification of 791219-20 site visit to discuss TMI Lessons Learned Task Force recommendations. DROMERICK, A. H. Light Water Reactors Branch 3. 79/12/14. 3pp.
- 7912260207 Submits addl info for proposed Teth Spec Amend 27 re LOCA-ECCS calculation for small break using nonheatup rate dependent burst curve. STALLINGS.C.M. Virginia Electric & Power Co. 79/12/19. 2pp.
- 7912260211 Notifies of util intent to plug more steam generator tubes in Unit 1. Program will not impact or invalidate non-LOCA safety analysis in FSAR. STALLINGS.C.M. Virginia Electric & Power Co. 79/12/19. ip.
- 7912260216 Forwards rept. "Rosemount Model 1152 Severe Environ Test." in response to NRC 791120 request for addl info. BROWN.S.C. Virginia Electric & Fower Co. 79/12/19. ip.
- --7912240218 "Rosemount Model 1152 Severe Environ Test."

  \* Virginia Electric & Power Co. 79/12/19. 31pp.
- 7912260259 Ack receipt of NRC 791130 request for addl info re electrical protection of containment penetrations. Schedule for providing info will be submitted by 791221. BROWN S. C. Virginia Electric & Power Co. 79712/19. ip.
- 7912270348 Advises that info re separation of electrical equipment & sys was submitted Jul 1975, during electrical installation. Similar problems reported by WPPSS were covered in LE Insp. Repts 50-338/75-9,75-11 & 75-16 & 50-339/75-8,75-10 & 75-11. BROWN,S.C. Virginia Electric & Power Co. 79/12/21. 2pp.
- 7912270366 Advises that info re electrical protection of containment penetration will be submitted between BOD115 & 0215.
  BROHN, B. C. Virginia Electric & Power Co. 79/12/21. ip.
- F. Becurity, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded omergency plans to plants under const & OL review. Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Guide 1.101.
  VASSALLO, D. B. Division of Project Management. 79/11/21. App.
- 7912070131 Forwards amended pages to approved security plan. Changes withheld (ref 10GFR2.790).
  STALLINGS.C.M. Virginia Electric & Power Co. 79/12/03. ip.
- 7912100329 Forwards proposed revision to emergency plan.in response to NRC 791010 ltr.Plan designed for compatibility w/NRC concurred state & county radiological response plans, to provide for overall response effort.

  STALLINGS.C.M. Virginia Electric & Power Co. 79/12/10, ip.
- --7912130341 Proposed revision to emergency plan.

  \* Virginia Electric & Power Co. 79/12/10. 200pp.

# G. Adjudicatory correspondence

- 7912110043 Forwards comments on NUREG-0511. Draft GEIS reflects conscious & deliberate NRC policy to jeopardize public health & safety & thwart objectives of NEPA.
  KEPFORD, C. Environmental Coalition on Nuclear Power. 79/10/24.
  22an
- 7912050481 Ack receipt of 791106 ltr re errors in certain pipe stress analyses Requests full rept on nature & scope of errors, focusing on relation between errors & settlement issue.

  BISHOP, C. J. Atomic Bafety and Licensing Appeal Panel. 79/11/08.

  1p.
- 7912140148 Confirms 791108 ltr re VEPCO rept on analytical errors in pipe stross analyses. Rept will be submitted by 791210. CHRISTMAN. J. N. Hunton & Williams, 79/11/15. 1p.

- 7912060239 Ack receipt of 791115 ltr re pumphouse settlement issue. Requested rept should be filed no later than 791210 in order to expedite ASLB decision Awaits NRC & parties comments. BISHOP.C.J. Atomic Safety and Licensing Appeal Panel. 79/11/16. 1c.
- 7912120169 Brief in opposition to intervenors 791026 exceptions on AGLB 790824 order granting VEPCO motion for summary disposition. If not affirmed, urges AGLAB permit use of high density racks pending conclusion of proceeding. Certificate of Svc encl. CHRISTMAN. J. N., MAUPIN. M. W. Virginia Electric & Power Co. 79/11/30, 58pp.
- ---7912120174 Answer in opposition to VEPCO 790505 motion for summary disposition. Full exploration of issues needed for appropriate relief.

  DUUGHENTY, J. B. Potomac Alliance. 79/06/05. 5pp.
- --7912120178 Statement of mati facts as to which there is no genuine issue to be heard re VEPCO motion for summary disposition. Affidavit & Certificate of Svc encl. DCUOMERTY, J. B. Potonac Alliance. 79/06/05. 4pp.
- ---79121201B4 Bupplemental answer in opposition to VEPCO 790505 motion for summary disposition. Urges ABLB to apply atds encouraging courts to be liberal re-opportunity for full development of factual bases & arguments. Certificate of Svc enc.

  DDUGHERTY, J. D. Potomac Alliance. 79/06/25, Spp.
- --79121201B9 Second supplemental answer in opposition to VEPCO 790505 motion for summary disposition. Radioactive emission, missile accidents & other issues are subj to major factual gaps. Hypleading pages on matl integrity & other related matters. DDUOHERTY, J. B. Potomac Alliance. 79/07/25. 45pp.
- --7912120173 Affidavit attesting that no credible analysis of Potomac Alliance alternatives may be undertaken w/o examination of greater body of facts. Prof qualifications encl. NETTZMAN.P.M. Affiliation Unknown. 79/07/23.
- --7912120197 Motion to amend petition to intervene Facility svc water cooling sys will not support spent fuel pool component cooling sys if mod permitted Formal discovery pages & informal discovery ltre encl.

  DOUGHERTY, J. B. Potomac Alliance. 79/05/09. 14pp.
- 7912140002 Order scheduling 800103 oral argument for intervenors' appeal re storage pool mod. Parties must inform ASLB by 791221 of names of counsel.
  BISHOP, C. J. Atomic Safety and Licensing Appeal Panel. 79/12/05.
- 7912140172 Responds to ASLAP 791108 request. Forwards "Rept on Effsct of Outdated Amplified Response Spectrum Curves on Bvc Water Pumphouse Settlement," which details errors in stress analysis.

  CHRISTMAN, J. N. Hunton & Williams. 79/12/05. 4pp.
- 7912180168 Opposition to intervenors Potomac Alliance & Citizens Energy Forum 791026 amended statement of exceptions, Intervenors were given ample opportunity to respond to NRC 790625 request for summary judgment. Centificate of 8vc encl. GOLDBERO, S. C. Hearing Branch 2. 79/12/10. 24pp.
- 7912310366 Recommends forwarding encl addl info re Westinghouse turbine disk matl to ABLAB.
  PANLICKI's S. Materials Engineering Branch. 79/12/12. 1p.
- --7912310377 Recommends notifying ASLAB of Westinghouse turbine disk cracking, based on info in 791105 anonymous ltr.791120 telcon w/Westinghouse & PNO-III-79-43 re low pressure disk cracks at Zion Unit i.
  BDYLE,M.L. Materials Engineering Branch. 79/12/12. 3pp.
- 7912200635 Notifies that BC Coldberg will present oral argument on behalf of NRC per ASLAS 791205 order.
  GOLDBERG, B. C. Hearing Branch 2. 79/12/17. 1p.

### H. General correspondence

- 7912130410 Comments on behalf of State Corp Commission of VA on NRC licensing moratorium: delay in VEPCO license application will result in grave economic losses for state residents. BRADSHAWLJ.L. SHANNON.P.C., HARWDOD,T.P. Virginia, State of, 79/11/08. 2pp.
- 7912180301 Urges chairman to issue licenso to facility immediately. SEXTON.R. Edgecomb-Martin County Electric Membership Corp. 79/11/20. 2pp.

- 7912200586 Requests that NRC reverse decision on moratorium of licensing nuclear units.

  MCNIEL. M. Shenandoah Valley Electric Cooperative, Inc. 79/11/26, 1p.
- 7912160332 Requests that all facility correspondence be forwarded to new address in Doulder,CO.
  FOSTER,R.M. Musick,Willamson,Schwartz,Leavenworth & Cope, P.C.
  79/11/27. ip.
- P. Operating license stage documents & correspondence
- 7912030201 Requests detailed syllabus for Dak Ridge Associated Universalistion safety seminar. Certain addl info required prior to reaching final determination of acceptance.

  BTALLINGS.C.M. Virginia Electric & Power Co. 79/11/29, ip.
- 7912200518 Commits to full implementation of all Category A requirements from TMI-2 Lessons Learned Task Force by 800131.
  PROFFITT. H. L. Virginia Electric & Power Co. 79/12/17. ip.
- 7912200562 Forwards procedural changes required to address control rod drop analysis concerns & withdraws 790706 proposed Tech Bpec Change 21 re control rod insertion limits.
  BTALLINGS.C.H. Virginia Electric & Power Co. 79/12/17. 2pp.
- Q. Inspection reports, IE Bulletins & correspondence
- 791205055 Forwards IE Insp Repts 50-339/79-41,50-404/79-07 & 50-405/79-07 on 790918-21. No noncompliance noted. MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 79/10/22. 2pp.
- --7912060657 IE Insp Repts 50-339/79-41.50-404/79-07 & 50-405/79-07 on 790918-21.No noncompliance noted Major areas inspected: nonconformance re concrete operations & activities reextended const delay.

  MCFARLAND.C.R. Region 2. Atlanta, Defice of the Director.

  BRYMAT.J.C. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/10/19. Spp.
- 7912060100 Forwards IE Insp Repts 50-338/79-38 & 50-339/79-44 on 790904-14 & 20-25 No noncompliance noted. LEHIS.R. C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 79/10/30. 2pp.
- --7912060114 IE Insp Repts 50-338/79-38 & 50-339/79-44 on 790904-14 & 20-25. No noncompliance noted Major areas inspected: LER, plant tours new fuel storage & licensee insp of certain induction disc relays.

  KELLOGO, P.J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. KIDD, M.S. Region 2, Atlanta, Office of the Director. 79/10/25. 7pp.
- 7912120264 Forwards IE Insp Repts 50-338/79-37 & 50-339/79-51 on 790924-27. No noncompliance noted. LEWISR. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/11/01. 2pp.
- --7912120275 IE Insp Repts 50-338/79-37 t 50-339/79-51 on 790924-27 No noncompliance noted Major areas inspected significant event followup.LERs three protection program.

  KEBSTER.E.H. Region 2, Atlanta, Deffice of the Director.

  KELLOGO.P.J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/11/01. Δpp.
- 7912100201 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. D'REILLY, J. P. Region 2. Atlanta, Office of the Director. 79/11/16. 1p.
- 7912110507 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Rolated Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. O'REILLYJ,P. Region 2, Atlanta, Office of the Director. 79/11/16. 2pp.
- 7912070007 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pips Break Detection Equipment on BWRs." No response required.

  O'REILLY.J.P. Region 2, Atlanta, Office of the Director.

  79/11/26. 1p.
- 7912110186 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required.
  O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
  79/11/26. 1p.

- 7912170492 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Written response required.

  O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/30. 1p.
- 7912310330 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/12/06. 5pp.
- 7912200070 Forwards IE Bulletin 79-28. "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 79/12/07. 2pp.
- 7912310255 Responds to 1E Bulletin 79-02. Revision 2: "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bults."
  No pipe supports for Beismic Category I sys attached to concrete block walls w/anchor bolts at facilities.
  BROWN.S. C. Virginia Electric & Power Co. 79/12/07. 3pp.
- 7912280441 forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required. O'REILLY, J. P. Region 2, Atlanta, Defice of the Director. 79/12/13. 2pp.
- 7912280161 Forwards IE Circular 79-25, "Shock Arrestor Btrut Assembly Interference." No written response required. D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/12/20. 4pp.
- 7912310548 Forwards response to violation noted in IE Insp Rept 50-338/79-45 & 50-339/79-54. Corrective actions records of training & qualification for current employees will be maintained as lifetime records.

  STALLINGS, C. M. Virginia Electric & Power Co. 79/12/27. 3pp.
- Reportable occurrences, LERs & related correspondence
- 7912070046 PNO-II-79-24: on 791105, error found in analysis of piping sys seismic response. Error discovered during reanalysis of piping sys in response to IE Bulletin 79-14. Reanalysis & corrective action estimated to require eight wks.
  WEBSTER, E. H., KELLOGO, P. J. Region 2, Atlanta, Office of the Director. 79/11/05, 1p.
- 7912060646 PNO-II-79-025: on 791107, control room & safeguards area exhaust ventilation damper functions occurred w/o separate operator action. Caused by design error. Generic vendor considerations & plant desings under review.

  WEBSTER.E.H., KELLOGG, P.J. Region 2, Atlanta, Office of the Director. 79/11/07. ip.
- 7912060377 Notifies of delay in completion of valve & operator weight varification program as identified in IE Bulletin 79-14, due to deficiency re amplified response spectrum curves in pipe strose analyses for safety-related sys.

  BROWN-S.C. Virginia Electric & Power Co. 79/11/09. 2pp.
- 7912170407 PND-II-79-25A: on 791115, further review of safety function reset design errors revealed recirculation spray pumps, svc water radiaton monitor pumps, casing cooling pumps & four svc water valves affected by actuation signal reset.

  WEBSTER.E.H., KELLDOG.P.J. Region 2, Atlanta, Office of the Director. 79/11/15, 1p.
- 7912130434 Interim deficiency rept re containment depressurization actuation & safety injection actuation circuitry. Safety circuits being redesigned to comply w/FSAR commitments. BROHN.S.C. Virginia Electric & Power Co. 79/11/21, 3pp.
- 7912040487 Interim deficiency rept on safoguards area exhaust sys.
  Evaluation revealed only safeguards & central area exhaust
  sys must be operational after seismic event.Final rept.
  forthcoming.
  BROWN.S.C. Virginia Electric & Power Co. 79/11/30. ip.
- 7912070398 Interim deficiency rapt re inconsistencies in use of seismic amplified response spectrum curves for pipe stress analyses. Pipe stress reanalyses & corrective actions still in progress. Final rapt to follow.

  BROWN.B. C. Virginia Electric & Power Co. 79/12/04. 2pp.
- 7912190663 Interim deficiency rept re seismic response spectrum curves in pipe stress analyses. Three inconsistencies discovered in amplified response spectrum curves used as input data to pipe stress analyses. Analyses repun using proper input. BROWN, S. C. Virginia Electric & Power Co. 79/12/04, 2pp.

- 7912070395 Interim deficiency rept re certain seismic amplified response spectrum curves used as input data to pipe stress analyses. Corrective action in progress using proper input data. Two pipes required mods.

  BROWN.S.C. Virginia Electric & Power Co. 79/12/07. 2pp.
- 7912180538 Final deficiency rept re ambient temp ranges exceeding design limits for emergency diesel generator fan cooling sys. Mods to current fan drive shaft & seasonal fluid changes corrected deficiency.

  BROWN, S. C. Virginia Electric & Power Co. 79/12/14. ip.
- 7912180560 Final deficiency rept re containment depressurization actuation is safety injection actuation circultry. Indicates resolution of revisions to previously reported circuits not complying w/FSAR. rigar. Virginia Electric & Power Co. 79/12/14. 200.
- 7912200391 Final deficiency rept re emergency diesel generator fan cooling sys. Ambient temp ranges sxist exceeding original design limits of sys. Manufacturer engineered mod to current fan drive shaft to allow operation w/o overloading. BROWN.S.C. Virginia Electric & Power Co. 79/12/14. ip.
- 7912280541 Interim deficiency rept concerning significant breakdown in QC program re verification of calibr of Formey compression testing machine. Attempting to calibr Formey compression testing machine in range of 0 to 25.000 lbs.

  BROWN.S.C. Virginia Electric & Power Co. 79/12/20. 3pp.
- DOCKET 50-341 ENRICO FERMI ATOMIC POWER PLANT, UNIT 2
- A. Application/construction stage documents & correspondence
- 7908070310 Forwards NUREO/CR-0660, "Enhancement of Onsite Emergency Diesel Generator Reliability." Requests commonts W/o encl. VABBALLO.D.D. Assistant Director for Light Water Reactors. 79/04/18. 3pp.
- 7912110011 Forwards NRC position on status & applicability to pending GL applications of results of TMI followop actions. Outlines add1 short-term actions to be taken.
  VASSALLO,D.B. Division of Project Management. 79/09/27. 41pp.
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMB issue for PMRs & BMRs. Success of program depends on industry response. Supports formation of owners groups to provide necessary info. DENTON.H.R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 791213007B Forwards request for add1 info re FBAR from Hydrology-Meteorology-Hydrologic Engineering & Structural Engineering Branches.

  STOLZ.U.F. Light Water Reactors Branch 1. 79/11/23. opp.
- 7912180314 Forwards proposed Revision 2 to Reg Guide 1.97.
  "Instrumentation for Light-Water-Cooled Nuclear Power Plants to Assess Plant & Environs Conditions During & Following Accident." Requests comments.
  VAROA, S. A. Assistant Director for Light Water Reactors. 79/11/23.
- 7912270167 Forwards proposed Revision 2 to Reg Guide 1.97.
  "Instrumentation for Light Water Cooled Power Plants to
  Assess Plant & Environs Conditions During & Following
  Accident." Comments should be filed before 791214 meeting.
  VARQA.S.A. Assistant Director for Light Water Reactors. 79/11/23.
- --791227017B Notification of 791214 meeting w/applicants to discuss proposed Revision 2 to Reg Guide 1.97. "Instrumentation for Light Water Cooled Nuclear Plants to Assess Plant & Environs Conditions During & Following Accident." KINTNER,L.L. Light Water Reactors Branch 1. 79/11/19. 1p.
- 7912D40364 Forwards electrical schematic Drawings 61721-2098-17 & 18, in response to N Treehan questions re wiring for MBIV loop control sys. Drawings available in Central Files only. SCHNERMAN,L. E. Detroit Edison Co. 79/11/26. ip.
- 791204030B Informs that final plant-unique analysis will be provided following final resolution between NRC & Mark I owners group of concerns re acceptance criteria for Mark I long-tarm program, as identified in GE 79130
- 7912270035 Notification of 790110-11 meeting w/Detroit Edison Co & GE at 0E:San Jose, CA to discuss analyses of asymmetric pressure forces due to LDCA on reactor pressure vessel.

  KINTMER, L. L. Light Water Reactors Branch 1. 79/12/07. 2pp.

- 7912140428 Discusses impact on facility of proposed revision to Reg Guide 1.97. Impact would be great & require replacement of all post-accident monitoring instruments & many non-qualified instruments. Estimated direct cost \$10 million. JENS.W.H. Detroit Edison Co. 79/12/12. 2pp.
- 7912270448 Certifies that const & operation of plant will conform to MI Coastal Zone Mgt program.

  HEIDEL.C.M. Detroit Edison Co. 79/12/14. 1p.
- 7912270555 Discusses demographic data errors re NUREO-0345, "Demographic Statistics Pertaining to Nuclear Power Reactor Sites." Text of NUREO document not self-explanatory reoriginal data source. Population data encl. JENB, N.H. Detroit Edison Co. 79/12/18. 3pp.
- --7912270569 Discusses demographic errors re NUREO-0553. "Beyond Defense In-Depth." Population within ten miles of facility considered lower than published data. Growth rate indicated by State of MI in 1978 is lower than 1974 projected figure. JENS.W.H. Detroit Edison Co. 79/12/20. 1p.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & DL review. Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Quide 1.101.
  VASSALLO.D.B. Division of Project Management. 79/11/21. App.
- H. General correspondence
- 7912180820 Forwards Certificate of Svc indicating svc of Amend 27 to amended & substituted application for licenses.

  MAYERS.B.R. Detroit Edison Co. 79/12/12. 3pp.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 7912030198 Forwards Amend 27 to OL application & FBAR. THOMAS.E.B. LeBosuf, Lamb, Leiby & MacRae. 79/11/30. 2pp.
- --7912030200 Amend 27 to FSAR, submitted as Amend 27 to DL application. \* Detroit Edison Co. 79/11/30. 99pp.
- M. Antitrust correspondence -
- 7912060406 Requests update of antitrust info in accordance w/encl AEC Reg Guide 9.3. Significant antitrust-related changes should be provided for OL review completion.

  TOALSTON, A. Antitrust & Indemnity Group. 79/11/21. ip.
- -7912060415 Reg Quide 9, 3, "Info Needed by AEC Regulatory Staff in Connection w/Antitrust Review of OL Applications for Nuclear Power Plants." \* Atomic Energy Commission. 74/10/31. 1p.
- G. Inspection reports, IE Bulletins & correspondence
- 7912070049 Forwards IE Insp Rept 50-341/79-18 on 790911-14 & notice of violation.
  KEPPLER, J. C. Region 3, Chicago, Office of the Director, ,79/10/16. 2рр.
- --7912070035 Notice of violation from insp on 790911-14.

  # Region J. Chicago. Office of the Director. 79/10/16. 1p.
- --7912070062 IE Insp Rept 50-341/79-18 on 790911-14. Noncompliance noted: failure to assure that purchased matl conformed to procurement document through examination of matl upon delivery.
  PHILLIP, O. A., WARD, K. D., NDRELIUS, C. E. Region 3, Chicago, Office of the Director. 79/10/16. 11pp.
- 7912050016 Forwards IE Insp Rept 50-341/79-21 on 791004-05.No noncompliance noted. FIDRELLI.O. Region 3. Chicago. Reactor Construction & Engineering Support Branch. 79/10/18. 2pp.
- --7912050022 IE Insp Rept 50-341/79-21 on 791004-05. No noncompliance noted Hajor areas inspected: welding repair of torus, reactor vessel nozzel mod & storage of reactor pressure vessel. ERB, C, M. Region 3, Chicago, Office of the Director. DANIELSON, D. H. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/10/16. 4pp.

- 7912050124 Forwards IE Circular 79-22, "Btroke Times for Power Operated Relief Valves." No response required.
  REPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912100230 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. REPPLER, J. 9. Region 3, Chicago, Office of the Director. 79/11/16. is.
- 7912110578 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolent Sys Instrumentation During Operation." No specific action or response required.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/16. in.
- 7912050375 Forwards IE Byllstin 79-24, "Boron Loss From BWR Control Blades." No response required.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director, 79/11/20.
- 7912100430 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BMRs." No written response required.
  KEPPLER. J. O. Region 3. Chicago. Office of the Director. 79/11/26.
- 79:2110258 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required.

  KEPPLER, J. 9. Region 3, Chicago, Office of the Director. 79/11/26.
- 7912110426 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general offs copies of socalated enforcement correspondence sent by NRC to licensees.

  KEPPLER, J. 9. Region 3. Chicago, Office of the Director, 79/11/28.
  is.
- 7912190221 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation."
  No written response required.
  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/30, is.
- 7912120556 Ack receipt of 791121 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-341/79-18. FIDRELLI.0. Region 3. Chicago. Reactor Construction & Engineering Support Branch. 79/12/03. 1p.
- ---7912120362 Responds to NRC 791016 ltr re violations noted in 1E Insp Rept 50-341/79-18. Corrective actions: certification for heat numbers located, reviewed, found acceptable & placed in appropriate file. HINES, E. Detroit Edison Co. 79/11/21. 4pp.
- 7912140086 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action or response required.

  KEPPLER, J. 9. Region 3, Chicago, Office of the Director. 79/12/06.
- 7912200115 Forwards IE Bullotin 79-28. "Possible Malfunction of Namco Model EALBO Limit Switches at Elevated Temps." Action required.

  KEPPLER, J. G. Region 3. Chicago, Office of the Director. 79/12/10.
- 8. Reportable occurrences, LERs & related correspondence
- 7912120382 Confirms 791109 telcon re problems w/Agastat relay assemblies in primary containment monitoring sys. Util will feteraine whether other equipment contains Agastat relay assemblies & will procure new relay bases. FAHRNER, M. J. Detroit Edison Co. 79/12/07. ip.
- 7912120437 Interim deficiency rept re failure of closure springs for fire dampers installed in reactor bldg. Research dept is conducting metallurgical tests to determine reason for failures. Final rept on 800407.
  FAHRNER
- 79:2280038 Ack receipt of 79:120 interior rept re receway hanger support limitations. Final rept will be reviewed upon receipt. FIGRELIT. 9. Region 3. Chicago. Reactor Construction & Engineering Support Branch. 79/12/12.

DOCKET 50-344 TROJAN NUCLEAR PLANT, PORTLAND GENERAL ELECTRIC

- F. Security, medical, emergency & fire protection plans
- 7912180335 Notifies of delay in Plant Sys Branch Team 1 evaluations of facility fire protection sys. Outlines of assistance needed encl.

  LAINAS.O. Plant Systems Branch. 79/11/16. Spp.
- 7912200022 Discusses NRC 791109 menting re emergency preparedness team review objectives. Provides guidance for improving licensme emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions. CRIMES, B. K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- 7912060476 Requests NRC schedule for comments re Revisions 4.4a & 5 to security plan. GOOBMIN.C. Portland General Electric Co. 79/11/30. 3pp.
- 7912270269 Forwards draft of revised 791204 "Radiological Emergency Plan." incorporating corrections & additions. GOODWIN.C. Portland General Electric Co. 79/12/19. 2pp.
- --7912270276 Draft of revised 791204 "Radiological Emergency Plan." incorporating corrections & additions. \* Pacific Gas & Electric Co. 79/12/19, 78pp.
- 7912070405 Braft radiological emergency plan. COODWIN.C. Portland General Electric Co. 79/12/31. 600pp.
- Q. Adjudicatory correspondence
- 7912040074 Submits status rept for whending 791107 re resolution of open items & completion of NRC SER. Review re continues effects of proposed mods on safety-related sys & plant operation. Block wall problem evaluated.

  CRAY, J. R. Hearing Branch 1. 79/11/09. 2pp.
- 7912170272 Intervenors Coalition for Safe Power & Consolidated Intervenors first set of interrogatories. Requests info reutil response to IE Bulletin 79-14, seismic qualification & drug charges against guards. Certificate of Svc encl. BELL.N. Affiliation Unknown. RDSOLJE, E. Coalition for Bafe Power. 79/11/14. 5pp.
- 791219016B Notifies that on 791219 NRC staff response to motion to strike applicants answer inadvertently served on ajudicatory boards of wrong party. Pleading should be ignored.

  ORAY, J. R. Hearing Branch 1. 79/11/20. 2pp.
- 7912050142 Submits rept re status of unresolved items & SER for week ending 791123 & Structural review of proposed mods.Plant Bys Branch awaiting licensee replies to NRC 790914 Guestion 3 & Question 790928 Questions 3 & 7.

  GRAY.J.R. Hearing Branch 1. 79/11/23. 1p.
- 791211003B Confirms receipt of encl 790329 patition to suspend DLs for all PMRs. Forwards FR notice indicating that patition will be treated in accordance w/10CFR2.206.

  DENTON, H. R. Uffice of Nuclear Reactor Regulation. 79/11/23. lp.
- --7912110126 Notice of request for action pursuant to 100FR2.206 re Environ Coalition on Nuclear Power 790329 patition requesting suspension of all OLs for PWRs. MULIER, D.R. Office of Nuclear Reactor Regulation. 79/11/23.
- 7912100126 Bubmits status rept for wk ending 791130 re resolution of open items & completion of SER.Licensee final responses, re and work on concurrent operation safety, were accepted & resolved. Structural questions unresolved. ORAY, J. R. Hearing Branch 1. 79/11/30. 2pp.
- 7912120030 Modifies ASLB partial initial decision permitting interim operation of facility. Operation will not resume pending further order NRC shall inform ASLB of unresolved items reseases to seven in face and Licensing Board Panel. 79/11/30.
- 7912120302 Add1 info for facility control bldg we block wall reaction force found to be inadequate to resist earthquake-generated reaction forces. Util will conduct evaluation. Results of 791206 meeting will be provided. Certificate of Svc encl. ORAY.J.R. Hearing Branch 1. 79/11/30. Spp.

- --7912120321 Responds to ASLB 791113 notification of LER 79-15 info.
  Status rept on evaluation of control bldg seismic resistance
  capability already provided in LER Suppl 1. Problem has no
  connection w/design deficiencies. Review cantinuong.
  BROEHL.D.J. Portland General Electric Co. 79/11/19. 4pp.
- 7912130257 Response to E Rosolie, Cualition for Safe Power, N Bell & Consolidated Intervenors 791114 interrogatories, Guestions 1, 2 & 3 out of scope of contentions admitted in ASLB 791017 order, Question 4 not relevant Certificate of Svc encl. AXELRAD.M. Portland General Electric Co. AXELRAD.M. Lowenstein, Neuman, Reis, Axelrad & Toll. 79/12/03. 7pp.
- 7912140542 Informs that comprehensive update of currently unresolved problems in lieu of status rept for wk ending 791207 is being prepared & will be filed by 791207.

  ORAY, J. R. Hearing Branch 1. 79/12/07. 1p.
- 7912170218 Responds to ASLB 791130 order directing NRC to inform ASLB of unresolved problems w/hearing on seismic issues, Forwards KS Herring, Cm Trammell, F Clemeson & JE Knight affidavits. ORAY, J. R. Hearing Branch i. 79/12/07. 3pp.
- --7912170223 Affidavit of KS Herring on unsolved problems, viewed from safety standpointine adequacy of control bldg mods to bring facility into substantial compliance w/license. Statement of professional qualifications ent.
- --7912170229 Affidavit of KS Herring re effects of mod work on plant safety Statement of prof qualifications encl. HERRING.K.S. Engineering Branch, 79/12/07. Spp.
- --7912170293 Affidavit of CM Trammell re ability of control room ventilation sys to maintain control room at positive pressure of 0.125-inch water column relative to outside atmosphere. Prof qualifications encl.
  TRANMELL.C.M. Office of Nuclear Reactor Regulation. 79/12/07.
- --7912170237 Affidavit of F Clemenson re control of const-generated dust & const work involved in floor slab & wall removal.Prof qualifications encl. CLEMENSON.F. Plant Systems Branch. 79/12/07. 7pp.
- --7912170242 Affidavit of JE Knight re fire protection for wood framing & other combustible matts protection of cables from dropped objects & effects of drilling through control bldg west wall from qualifications encl.

  KNIGHT. J. E. Systematic Evaluation Program Branch. 79/12/07.
- --7912170248 Affidavits of CM Trammell & KS Herring re piping & equipment supports & walls & seismic designs. Prof qualifications encl. TRANNELL.C.M. Office of Nuclear Reactor Regulation. HERRING, K. S. Engineering Branch. 79/12/07. App.
- 7912180113 Forwards affidavits of RH Short & DJ Broehl, president & vice president of util, respectively, in response to ASLB 791120 order, Certificate of Svc encl, AXELRAD, M. Lowenstein, Newman, Reis, Axelrad & Toll, 79/12/08. 7pp.
- --7912180120 Affidavit by president of util explaining unique circumstances facing region & affecting public need. SHORT,R.H. Portland General Electric Co. 79/12/07. App.
- --7912180127 Affidavit by vice president of util reporting status of responses to NRC questions to control bldg proceeding. Provides background of LER 77-15 issues Reported wall problems will not affect interim operation. BROCHL.D.J. Portland General Electric Co. 79/12/08. 13pp.
- 7912270091 Submits licensee views as to bow long facility should be permitted to operate absent firm plans for control room mods to bring facility in compliance w/license.Length of operation has no effect on public health & safety.

  AXELRAD.M. Lowenstein.Newman.Reis.Axelrad & Toll. 79/12/11. 9pp.
- 7912190488 Submits rept for mix ending 791214 re resolution of open items & completion of SER. Fire protection measures re mood framing of mod work evaluated & accepted Measures for cable protection from dropped objects accepted. CRAY. J. R. Hearing Branch 1. 79/12/14. 2pp.
- 7912280130 Bubmits responses to ASLE 791130 order, Paragraphs 4 & 5. Completion & filing of safety evaluation for proposed control bldg mod anticipated on 800214. Time limit on length of interim operation not needed. Prof qualifications encl. GRAY, J. R. Hearing Branch 1. 79/12/19. Spp.

- ---7912280137 Joint affidavit on length of interim operation for as-built control bldg. Evidence should be presented on required length of time to complete mods. Licensee should adhere to schedule.

  HERRING.K.S., TRAMMELL.C.M. Engineering Branch. 79/12/19. App.
- P. Operating license stage documents.& correspondence
- 79:1090248 "Summary of Operating Experience W/Recirculating Steam Generators." EISENHUT.D.C. Division of Operating Reactors. NUREG-0523, 79/01/31, 89pp.
- 790BD10337 Notifies of status of rept on reactor cavity annulus seal.
  Most PUR users remove ring during normal operation. Others
  store seal ring in raised position during normal operation.
  LAINAG. 0. Plant Systems Branch (Pre 791030). 79/07/05. 7pp.
- 7912050183 Discusses NRC review of LERs & Tech Spec requirements recontrol RPI sys at Hestinghouse PHRs. Requests Tech Bpecs review to ensure requirement for rod maint to within +/- 12 steps indicated & RPI sys verified accurate within 12 eteps. SCHHENGER.A. Operating Reactors Branch 1. 79/10/29. 7pp.
- 7912050523 Requests info re pipe support & wall, reviews & insps, structural adequacy reviews & insps, unreviewed aspects of pipe supports for safety-related piping & schedule for planned addl reviews & insps.
  FRANK, L. Gregon, State of. 79/11/01. 2pp.
- 7912100163 Amend 42 to License NPF-1, revising administrative controls section of Tech Specs re both onsite & offsite organizational structure.
  SCHMENCER.A. Operating Reactors Branch 1. 79/11/09. 11pp.
- 79121001B9 Discusses NRC 791101 meeting w/representatives of NBSS vendors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EISENHUT.D.Q. Division of Operating Reactors. 79/11/09. 65pp.
- --7912100255 Responds to NRC 791101 request rs noncompliance of Westinghouse ECCS evaluation model under requirements of 10CFR50 App M. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants.

  ANDERSON.T.M. Westinghouse Electric Corp. 79/11/02. App.
- --7912100330 Responds to NRC 791101 request re ORNL cladding swelling & rupture data. Review of analytical models & tests indicates compliance w/IOCFR50 App K. All GE specs for calculated peak cladding temp remain unchanged.

  BUCHHOLZ.R. H. General Electric Co. 79/12/07, 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vandor evaluation models & that analyses demonstrate all criteria of 10CFRSO. 46 satisfied.

  OWSLEY.O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/02. 5pp.
- --7912100436 Forwards add1 info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. OHSLEY.O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/04. 22pp.
- 7912050478 Forwards agenda of 791208 meeting w/D Dixon in response to NRC request for history & status of pipe support & structural insps. Requests notification if addl info is required.

  LENTSCH. J. W. Portland General Electric Co. 79/11/19. Spp.
- 7912070096 Summary of 791114 telcon w/util re implementation of TMI Lessons Learned Task Force. TRAMMELL.C.M. Operating Reactors Branch 1. 79/11/26. 6pp.
- 7912170123 Advises that Ofc of Nuclear Reactor Regulation review of plume study summary rept is subj to Class III fee provisions, due to environ issue.

  MILLER, W. O. License Fee Management Branch. 79/11/27. ip.
- 7912040380 Informs that milk samples from Kalso (Dudonaki Dairy) are no longer being taken. Sampling program from suitable site will be initiated.

  GOODWIN. C. Portland General Electric Co. 79/ii/30. ip.

- 7712070452 Accepts proposed Oak Ridge Associated Univ radiation safety course certification re 791002 request for substitute training program. Comments on concerns re adequacy of program requested.

  GOODHIN.C. Portland General Electric Co. 79/11/30. 2pp.
- 7912120319 Forwards response to NRC request for info re loss of offsite power. Outline of pertinent events encl. 900DMIN, C. Portland General Electric Co. 79/11/30. 5pp.
- 7912140353 Forwards supplemental commitments for implementation of TMI Lessons Learned Task Force recommendations in response to 791207 telcon, Info resolves remaining items of disagreement secept mod of containment isolation valves.

  9000BMIN.C. Portland General Electric Co. 79/12/07. 3pp.
- 7912180549 Requests addl 30-day extension to respond to NRC 791001 request for addl info re generic issue of degraded grid voltage.

  9000DHIM.C. Portland General Electric Co. 79/12/11. ip.
- 7912180622 Commits to implement proposed changes in Westinghouse 791128 ltr.Bank D control rods will be withdrawn equal to or greater than 215 steps when RCS is in automatic mode at more than 90% of rated power.

  COODWIN.C. Portland General Electric Co. 79/12/11. 1p.
- 7912210366 Forwards add1 info in response to NRC 791210 request re automatic initiation of auxiliary feedwater sys & auxiliary feedwater flow indication to steam generator. Thirteen oversized frawings available in Central Files encl. QDDDWIN.C. Portland General Electric Co. 79/12/14. 18pp.
- 7912190379 Forwards response to NRC 790914.20,28 & 1002 questions. Includes into re-safety-related cables & equipment, use of grout for installation of rebar into walls & rock.

  BRDEHL, D. J. Portland General Electric Co. 79/12/17. 16pp.
- --7912190390 "Miscellaneous Paper C-74-12.Pullout Resistance of Reinforcing Bars Embedded in Hardened Concrete." prepared by Engineer Materways Experiment Station. BTOHE.R.L. Army. Dept. of. 74/06/30. 48PP.
- 7912280491 Discusses 791207 supplementary info re implementation of short-term actions required by TMI Lessons Learned Task Force. One outstanding item remains re control circuit for 23 containment isolation valves. Mod completed by 800101. GEODMIN.C. Portland General Electric Co. 79/12/20. lp.
- 7912270183 Forwards response to NRC 770914,20,1002 & 18 questions recontrol blog mods. Cartificate of Byc encl.
  BRDEHL, D. J. Portland General Electric Co. 79/12/21. 194pp.
- 7912270181 Forwards final response to NRC 790914.20 & 1002 requests for info re control bldg mods.
  BROCHL.D.J. Portland General Electric Co. 79/12/22. 118pp.
- 7912280518 Forwards Change Application 56 requesting amend to License NPF-1. QCODHIN.C. Portland General Electric Co. 79/12/24. 1p.
- --7912280525 License Change Application 86 for License NPF-1, revising rod insertion limit Tech Specs to permit unrestricted operation during Cycle 3.

  QUDDWIN, C. Portland General Electric Co. 79/12/24. 3pp.
- --7912280535 Revised Pages 3/4 2-6a,2-88 3/4 205 for proposed Change 56 to Tech Specs re revision to rod insertion limits to permit Unrestricted operation during Cycle 3, \* Portland General Electric Co. 79/12/24, 3pp.
- 7912310516 Forwards License Change Application 57 requesting amend of License NPF-1 Certificate of Svc & Class II fee encl. OCCOMIN.C. Portland General Electric Co. 79/12/28. 2pp.
- --7912310520 License Change Application 57 to amend License NPF-1, revising Tech Specs re method of transferring diesel fuel oil from storage to equipment, min vol of borated water storage, sys actuation terminology & fire protection.

  \* Portland General Electric Co. 79/12/28. 7pp.
- --7912310327 Revised Tech Specs 3.1.2.7,4.1.2.7,3.7.8.2.4.7.8.2 & 3/4.1.2 & 3/4.1.3 re method of transferring diesel fuel oil from storage to equipment min vol of borated water storage, sys actuation terminology & fire protection equipment.

  \* Portland General Electric Co. 79/12/28. 11pp.

- G. Inspection reports, JE Bulletins & correspondence
- 7912060112 Forwards IE Insp Rept 50-334/79-17 on 790904-28.No noncompliance noted. CREWS,J.L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 79/10/15. 2pp.
- ---7912060123 IE Insp Rept 50-344/79-17 on 790904-28. No noncompliance noted Major areas inspected operations maintiphysical security & followup on IE bulletins & LERs. STERNBERG, D. M. Region 5. San Francisco, Reactor Operations Nuclear Support Branch. MALMROS, M. H. Region 5. San Francisco, Office of the Director. 79/10/12. 6pp.
- 79:2100278 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. ENGELKEN,R.H. Region 5, San Francisco, Office of the Director. 79/11/16. | 1p.
- 791207001B Forwards IE Circular 79~24. "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No response required.
  ENGELKEN,R.H. Region S. San Francisco, Office of the Director. 79/11/26. 10.
- 7912110269 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/11/26, 1p.
- 7912110495 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs, copies of escalated enforcement correspondence sent by NRC to licensees.

  ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/11/26. 10.
- 7912130150 Forwards Insp Rept 50-344/79-18 on 791107-09. No items of noncompliance found Rept withheld (ref 10CFR2. 790). Copy to Central Files only.
  NORDERHAUGL. R. Region 5. San Francisco. Safeguards Branch.
  79/11/26.
- 7912190147 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Dus During Operation." Written response required. ENGELKEN.R.H. Region 5, Ban Francisco, Office of the Director. 79/11/30. 1p.
- 7912310272 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances 10CFR21." No action required. ENGELKEN,R.H. Region 5, San Francisco, Office of the Director. 79/12706. 4pp.
- 7912190001 Forwards licensee responses to IE Bulletin 79-23, "Potential Failure of Emergency Diesel Generator Field Exciter Transformer."
  CREMB.J.L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 79/12/07. ip.
- --7912190003 Responds to IE Bulletin 79-23, "Potential Failure of Emergency Diesel Generator Field Exciter Transformer." Facility will conduct load test of emergency diesel generator prior to recovery from refueling shutdown. GODDHIN.C. Portland General Electric Co. 79/10/11. 1p.
- 7912200240 Forwards IE Bulletin 79-28, "Possible Malfunction of Named Model EA180 Limit Switches at Elevated Temps." Action required. ENGELKEN, R. H. Region 5, Ban Francisco, Office of the Director. 79/12/07. 10.
- 7912210132 Forwards responses to IE Bulletin 79-21, "Temp Effects on Level Measurements." CREMB.J.L. Region 5, San Francisco. Office of the Director. 79/12/07. ip.
- ---7912210162 Responds to IE Bulletin 79-21, "Temp Effects on Level Instrumentation." Discusses liquid level measurement sys, post-accident ambient temp on indicated water, safety & control setpoints & emergency procedures.

  GOODHIN, C. Portland General Electric Co. 79/09/14. 15pp.
- 7912280671 Forwards util response to IE Bulletin 79-04, "Incorrect Weights for Swing Check Valves Mfg by Velan Engineering Corp."
  CREMS, J. L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 79/12/07. 1p.

ı

- --7912280578 Forwards response to IE Bulletin 79-04. "Incorrect Weights for Swing Check Valves Mfg by Volan Engineering Corp." Valves identified & verified. No plant mods needed. GDODMIN.C. Portland General Electric Co. 79/09/14. Jpp.
- 7912280623 Forwards IE Info Notice 79-31. "Use of Incorrect Amplified Response Spectra." No written response required. ENGELKEN.R.H. Region 5. San Francisco, Office of the Director. 79/12/13. ip.
- A. Periodic operating reports & related correspondence
- 7912140361 Forwards monthly operating rept for Nov 1979. YUNDT.C.P. Portland General Electric Co. 79/12/08. 1p.
- --7912140387 Monthly operating rept for Nov 1979. BLAIR,G.G. Portland General Electric Co. 79/12/08. 4pp.
- S. Reportable occurrences, LERs & related correspondence
- 7912310066 PND-V-79-006: on 791019, facility notified NRC of tritium found in samples from onsite recreation lake. Caused by leating steam generator tubes.
  WENSLAMERI, F. A. Region 5, San Francisco, Office of the Director. 79/10/19, 2pp.
- 7912310104 PNG-V-79-005: on 791019, preliminary analysis indicated wall used to anchor restraint for RHR pump suction line may not have necessary structural capability. Analysis should be completed by 791022: Plant currently shut down.

  CREUS, J. L., STERNBERO, D. Region S. San Francisco, Office of the Director. 79/10/19. 1p.
- 7912260016 PNO-V-79-007:on 791025, emergency plan exercise will be conducted at facility.
  WENSLAUSKI.F. Office of Inspection & Enforcement, Office of the Director. 79/10/25. 1p.
- 7912080665 PNO-V-79-008: on 791029, util reported exposure of 3.7 rems to eye lans of contractor employee while testing steam generator A. Investigation underway, work temporarily stopped. FISH.R., HENSLAWERI,F. Region 5, San Francisco, Office of the Director. 79/10/27. 3pp.
- 7912030101 PNS-V-79-001: on 791108, ten off-duty & former guards arrested for narcotics traffic Individuals relieved from duty & inspectors are onsite to assure NRC security, NORDERMAND, E. R. Region 5, San Francisco, Office of the Director. 79/11/08. tp.
- 7912200572 PNS-V-79-001A: on 791126, liconsee notified Region 5 that continuing investigation into drug use at Facility resulted in termination of auxiliary operator for uncooperative attitude due to offsite use of cotains.

  \* Office of inspection & Enforcement, Office of the Director. 79/11/26. 1p.
- 7912120099 Notification of 791205-06 meeting w/util in Bethesda.HD to discuss LER 79-15 re masonry block wall & support reaction problem.
  TRAMMELL.C.M. Operating Reactors Branch 1, 79/12/01, 2pp.
- 7912110302 Forwards special rept re 770906 actuation of ECCS safety injection during turbine generator control circuit investigation. Caused by Faulty GE troubleshooting procedure. Procedure changed by GE.
  VUNDT, C. P. Portland General Electric Co. 79/12/03. 1p.
- 7912180427 Forwards special rept re ECCB octuation. YUNDT.C.P. Portland General Electric Co. 79/12/03. 1p.
- --79;2:180632 Special rept on 790906.ECCS safety injection was actuated. Caused by foulty troubleshooting procedure.GE has changed procedure. \* Portland General Electric Co. 79/12/03. Ip.
- 7912110341 Forwards Suppl 2 to LER 79-15 Review of masonry structures supporting safety-related piptng revealed 20 walls conductive to overstress Discusses corrective actions. FRANK.L. Portland General Electric Co. 79/12/04. 33pp.
- --7912110342 "Rept on Testing of Composite Masonry Walls." \* Portland General Electric Co. 79/11/30. 14pp.
- --7912110344 Special plant procedure for "Test of Masonry Bond Tensionto-Concrete Core in Masonry Block Walls." YUNDT.C.P Portland General Electric Co. 79/11/13. 10pp.

- --7912i10346 "Evaluation of Tests of Tensile Bond Strength of Concesta Block-to-Fill in Trajan Nuclear Power Plant Near Portland, CR. " Supporting documentation encl. \* Miss, Janney, Elsther & Association, Inc. 79/11/24. 20pp
- 7912180618 Forwards supplemental info to LER 79-15 providing results of evaluations of single & double-wythe masonry walls supporting safety-related piping Results of masonry bond tension tests & composite masonry wall tests encl. IROEHL.D. J. Portland General Electric Co. 79/12/04. 74pp.
- 7912270439 Forwards add1 info re LER 79-15, requested in 791202 joins affidavit of KB Herring & CM Trammell on status of Trojan wall problem.

  BDEML.D.J. Portland General Electric Co. 79/12/22. 71sp.
- DBCKET 50-346 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1 F. Security, medical, emergency & fire protection plans
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness took review objectives. Provides guidance for improving licenses emergency preparedness & assuring capability of offsite agencies to tate appropriate emergency actions. GRIMES. B. K. Emergency Preparedness Task Force. 79/11/23. 30pp
- 7912310103 Requests installation of backup power for rad emergency telephones.as discussed in 791115 telcon.
  KEPPLER.J. G. Region 3, Chicago, Office of the Director. 79/11/32
- O. Adjudicatory correspondence
- 7912/10038 Confirms receipt of encl 790329 petition to suspend DLs for all PMRs. Forwards FR notice indicating that petition will be treated in accordance w/100FR2. 206.
  DENTON, R. Bffice of Nuclear Reactor Regulation. 79/11/23.
- --7912110126 Notice of request for action pursuant to 100FR2.206 re Environ Coalition on Nuclear Power 790327 patition requesting suspension of all CLs for PMRs. MULLER, D. R. Office of Nuclear Reactor Regulation. 79/11/23. 3800.
- H. General correspondence
- 7712100334 Informs that all activities re nuclear program will be consolidated under one corporate officer.RP Grouse License amend request will be submitted in near future.

  JDHNSON.W.A. Toledo Edison Co. 79/11/28. ip.
- M. Antitrust correspondence
- 7912050098 Consolidated answer in opposition to Cleveland Electric Illuminating Co. Toledo Edison & Chio Edison petitions for ALAN-560 review. Petitioners failed to seek Commission review on issue of monopoly existence. Certificate of Svc encl. LEGBY, R. P. Antitrust Division. 79/11/21. 32pp.
- 7912110344 Informs of address change as of 791201. HJELMFELT, D. C. Hjelmfelt, D. C. 79/11/26. Spp.
- 7712110356 Orders extension until 800115 for Commission to review ALAB-560.
  CHILK.S.J. Office of the Secretary of the Commission. 79/12/07
- P. Operating license stage documents & correspondence
- 7911090248 "Summary of Operating Experience W/Recirculating Steam Generators." EISENHUT, D. O. Division of Operating Reactors. NUREG-0523. 79/01/31. BPpp.
- 7912310070 Ack 790B31 ltrs endorsing B&W generic rept BAW-1364. "Integrated Control Bys Reliability Analysis," & requests addl info. REID,R.W. Operating Reactors Brench 4. 79/11/07. 13pp.
- 7712130187 Forwards summary of Taknekron Research, Inc study of licembee regulatory performance evaluation & Teknekron draft rept reoperating reactors w/B&H nuclear steam supply sys.Requests comments.Wo encl.
  STELLO,V. Office of Inspection & Enforcement, Office of the Director. 79/11/08. 2pp.

- 7912100389 Discusses NRC 791101 meeting w/representatives of NSSS vandors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl.
  EISENHUT, D.Q. Division of Operating Reactors. 79/11/09. 45pp.
- --7912100255 Responds to NRC 791101 request re noncompliance of Hestinghouse ECCS evaluation model under requirements of 10CFR50 App K. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants. ANDERSON, T. M. Westinghouse Electric Corp. 79/11/02. 4pp.
- --7912100330 Responds to NRC 791101 request re ORNL cladding swelling & rupture data. Review of analytical models & tests indicates compliance w/IOCFR50 App K. All GE specs for calculated peak cladding temp remain unchanged.

  BUCHHOLZ, R. H. General Elactric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in veridor evaluation models & that analyses demonstrate all criteria of 10CFR50, 46 satisfied.

  OMBLEY, G.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/02. 5pp.
- --7912100456 Forwards addi info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model.

  No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results.

  OMBLEY, G. F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).

  79/11/04. 22pp.
- 7912280633 Forwards trip rept of 791018 & 19 visit to plant. SCHOLL, R. Plant Systems Branch. 79/11/15. 13pp.
- 7912180283 Notifies of partial refund of Class IV amend fee for 790713 application for change to Tech Specs.
  HILLER.W.C. License Fee Management Brench. 79/11/16. ip.
- 7912120092 Summary of 791024 meeting w/B&W owners group re asymmetric LOCA loads svaluation. Evaluation of B&W plants to be completed by Jul 1980.
  HOSFORD.9. B. Assistant Director for Engineering Programs.
  79/11/20. 4pp.
- 7912100478 Forwards, to all B&W operating plants except TMI, request for add1 info re small break LOCA. Comments requested by 791203.
  REID.R.H. Operating Reactors Branch 4. 79/11/21. Spp.
- 7912100237 Requests detailed info re wear characteristics of control rods on guide tube assemblies. Info needed to verify that guide tube wear not significant problem in BtW facilities. NRC concerns re tube wear encl.

  REID, R. M. Operating Reactors Branch 4. 79/11/23. App.
- 7912180118 Forwards request for add1 info re Tech Spec changes covering anticipated reactor trip, auxiliary feedwater survoillance & makeup gump termination.
  REID.W.R. Operating Reactors Branch 4. 79/11/28. 3pp.
- 7912190327 Notifies of partial refund of Class III amend fee re 791003 application. Action required by application is in Class II fee category.
  MILLER.M.D. License Fee Management Branch. 79/12/03. ip.
- 7912190402 Forwards revised Tech Space, Apps A & B re administrative controls, reflecting changes requested in 791188 application to amend CL. Requests Class II fee classification. CROUSE, R. P. Toledo Edison Co. 79/12/06. 2pp.
- ---7912190532 Revised pages 6-2.6-7 through 6-9 & 6-11 through 6-13 to Tech Specs.App A re administrative controls & revised Page 5-1-1 of Tech Specs.App B re organizational changes. \* Toledo Edison Co. 79/12/06. 9pp.
- 7912180584 Bupplements 791009 response to NRC 790808 inquiry re hus voltages. Bummarizes scope & schedule for proposed test program. CROUBE, R. P. Toledo Edison Co. 79/12/07, 1p.
- 7912190433 Forwards fee for 791206 amend to OL. CROUBE, R. P. Toledo Edison Co. 79/12/12. ip.
- 7912280275 Forwards Amend 22 to License NPF-3 & notice of lesuance & availability.
  REID, R. W. Operating Reactors Branch 4. 79/12/12. 3pp.

- ---7912280281 Amená 22 to License NPF-3, modifying antitrust license conditions. REID.R.W. Operating Reactors Branch 4. 79/12/12. 5pp.
- ---7912280290 Notice of issuance & availability of Amend 22 to License
- NPF-3. R£ID,R.W. Operating Reactors Branch 4. 79/12/12. 1p.
- 7912180505 Submits commitment of compliance to NRC 791023 interim position re-containment purgs & vent valve operation.

  Commitment is adequate for NRC determination that OL need not to be modified, suspended or revoked.

  CROUSE, R. P. Toledo Edison Co. 79/12/13. 3pp.
- 7912310463 Supplements application for amend to OL re revision to Condition 2.0(3)h.delaying completion schedule of fire protection mode until 800930. Class III fee.summary schedule, identification of proposed change & addl design mod encl. CROUSE.R.P. Toledo Edison Co. 79/12/22. Spp.
- 7912310480 Forwards BEW rept. "Small Break Operating Quidelines." incorporating core cooling guides in response to NUREG-0578. CROUSE.R.P. Toledo Edison Co. 79/12/27. 1p.
- --7912310486 "Small Break Operating Guidelines."

  \* Babcock & Wilcox Co. BNNP-20004. 79/11/20. 50pp.
- Q. Inspection reports. IE Bulletins & correspondence
- 7912050014 Forwards IE Insp Rept 50-346/79-26 on 790919 No noncompliance noted. XEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/10/15.
- --7912050018 IE Insp Rept 50-346/79-26 on 790919.No noncompliance noted. Hajor areas inspected:meeting was held to discuss status of licensee actions taken to address specific Region 3 concerns.

  REYEB: L.A., TAMBLING.T.N., WARNICK.R.F. Region 3, Chicago. Office of the Director. 79/10/09. Epp.
- 7912070066 Forwards IE Insp Rept 50-346/79-28 on 790819-17.27-31. 0910-14 & 24-28 & notice of violation. HEIBHMAN.R.F. Region 3. Chicago, Office of the Director. 79/10/26. 2pp.
- --7912070072 Notice of violation from insp on 790813-17.27-31.0910-14 & 24-28.

  \* Region 3: Chicago, Office of the Director. 79/10/25. lp.
- --7912070079 IE Insp Rept 50-346/79-28 on 790813-17,27-31,0910-14 & 24-28. Noncompliance noted: disabling of undervoltage sensing relays & failure of station review board to review violations of Tach Specs.

  STREETER,J.F., BAKER,K.R. Region 3, Chicago, Office of the Director. HEISHMAN.R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/10/29. 12pp.
- 7912050348 Forwards IE Insp Rept 50-346/79-25 on 790820-24.31.0904-07. 10-14.17-21 & 24-28 & notice of violation. HEISHMAN.R.F. Region 3. Chicago. Reactor Operations Nuclear Support Branch. 79/10/31. 2pp.
- ---7912050354 Notice of violation from insp on 790820-24.31,0904-07.14-14. 17-21 & 24-28. \* Region 3. Chicago. Office of the Director. 79/10/30. 1p.
- --7912050365 IE Insp Rept 50-346/79-25 on 790620-24.31.0904-07.10-14. 17-21 & 24-28.Noncompliance noted: Failure to establish fire watch. REVES, L.A., HARNICK.R.F. Region 3. Chicago. Office of the Director. 79/10/30. 6pp.
- 7912130210 Informs of delay in submitting rept re primary coolant sys pipe whip restraint design verification per IE Insp Rept 30-346/79-23. Delay in receipt of background info from D&W will result in 791207 submittal date.
  CROUSE.R.P. Toledo Edison Co. 79/11/05. 1p.
- 7912260082 Forwards draft IE bulletin concerning potential generic defect re failure of pins on control relays to make proper contact w/sockets.

  LAINAS.9. Plant Systems Branch. 79/11/06. ip.
- 7912200242 Forwards IE Insp Rept 50-346/79-27 on 791009-12.15-20,22.25, 26 & 29-31 No noncompliance noted. HEISKMAN.R.F. Region 3. Chicago, Reactor Operations Nuclear Bupport Branch. 79/11/13. 2pp.

- --7912200250 IE Insp Rept 50-346/79-27 on 791009-12.15-20.22.25.24 & 29-31.No noncompliance noted. Major areas inspected: plant operations, procedures, physical protection & surveillance of safety-related sys required by Tech Specs. REVES.L.A.. WARNICK.R.F. Region 3. Chicago, Office of the Director. 79/11/09. 5pp.
- 7912050192 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required.

  KEPPLER.J.G. Region 3. Chicago. Office of the Director. 79/11/16.
- 7912100244 Forwards IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads." No response required.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912110589 Forwards IE Info Notice 79-29, "Loss of NonsaPety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required.

  KEPPLER, J. O. Region G. Chicago, Diffice of the Director. 79/11/16.
- 7912050410 Forwards IE Bulletin 79-26, "Boron Loss From BWR Control Blades." No response required. KEPPLER, J. G. Rogion 3, Chicago, Office of the Director. 79/11/20. 1p.
- 7912040135 Notification of 791121 meeting w/util to discuss IE Bulletin 79-02 re anchor bolt inspection program.

  JORDAN.E.L. Division of Reactor Operations Inspections. 79/11/21.
  3ab.
- 7912100444 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Bpray Pipe Break Detection Equipment on BWRs." No written response required.

  KEPPLER. J. G. Region G. Chicago, Office of the Director. 79/11/26.
- 7912140237 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operato." No written response required.

  KEPPLER.J. G. Region 3, Chicago, Office of the Director. 79/11/26.
  1p.
- 7912110443 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sent by NRC to licensees.

  XEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/28.
- 7912190127 Forwards 30-day response to LE Bulletin 79-17.Revision 1, "Pipo Cracks in Stagnated Borated Water Sys at PWR Plants."

  Describes welds to be examined & welds selected for ultrasonic testing.

  CROUSE,R.P. Toledo Edison Co. 79/11/28. 24pp.
- 7712140375 Informs util of requirement to install emergency phone lines in operations & health physics dept.

  KEPPLER, J. O. Region 3. Chicago, Office of the Director. 79/11/30.
- 79:2190233 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus Buring Operation." Written response required. KEPPLER, J. C. Region 3. Chicago, Office of the Director. 79/11/30, 10.
- 7912210140 Act receipt of 791119 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 90-346/79-04.
  HEISHMAN.R.F. Region 3. Chicogo. Reactor Operations Nuclear Support Branch. 79/12/05. 1p.
- --7912210147 Responds to NRC 791020 ltr re violations noted in IE Insp Rept 50-346/79-04. Corrective actions: prepared deviation rept for violation of Tech Spec 6.8.1. GROUSE, R. P. Toledo Edison Co. 79/11/19, 2pp.
- 7912140099 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 100FR21." No action or response required.
  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/12/06.
  1p.
- 7912200144 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Tamps." Action required, KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/12/10, in.

- 7912280643 Forwards 30-day response to IE Bulletin 79-02, Revision 2, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts." Pipe support design calculations & drawings reviewed. Completion of work scheduled for 800401 & 0701. CROUSE, R. P. Toledo Edison Co. 79/12/10. 9pp.
- R. Periodic operating reports & related correspondence
- 7912130373 Forwards monthly operating rept for Nov 1979. MURRAY, T. D. Toledo Edison Co. 79/12/07. ip.
- ~-7912130375 Monthly operating rept for Nov 1979. CABA/E. Toledo Edison Co. 79/12/07. 13pp.
- S. Reportable occurrences, LERs & related correspondence
- 7912210081 PNO-III-79-14: on 791011, approx 100 gallons of reactor coolant were released to auxiliary bldg due to incorrect valve lineup during letdown filter changeout No personnel contaminated. Review will be made during future insp. GREGER, L. R., FISHER, W. L. Region 3, Chicago, Office of the Director. 79/10/11. 2pp.
- 7912200564 PND-111-79-017: on 791015; reactor tripped from 60% power on high reactor flux. Subsequently, offsite power lost to unit when circuit breaker malfunctioned. Cause unknown. REYES.L.A.; WARNICK, R.F., HEISHMAN, R.F., Region 3, Chicago, Office of the Director. 79/10/15. 1p.
- 7912200445 PNO-III-77-017A: un 791015, reactor tripped. Caused by capacitor failure in integrated control sys pulser circuit to turbine elector hydraulic control sys. Failed capacitor replaced.

  \*\* Office of Inspection & Enforcement, Office of the Director. 79/10/17. 20n.
- 7912200435 PND-III-79-178:on 791015, reactor tripped with subsequent loss of offsite power, Cause unknown.
  REYES, L. A., WARNICK, R. F., HEISHMAN, R. F. Office of Inspection & Enforcement, Office of the Director, 79/10/18, 2pp.
- 7912310088 PNO-III-79-019: on 791023 reduced power in preparation of tripping reactor coolant pump 1-1. Apparently caused by failure of two of three shaft seals.

  TAMBLING.T.N., WARNICK, R.F., HEISHMAN.R.F. Office of Inspection & Enforcement, Office of the Director, 79/10/23, 2pp.
- 7912190465 PNO-79-434: on 791015, facility had reactor trip w/loss of offsite power indicated in PNG-III-79-17. Licensee lost internal phone sys. Determined that NRC hotline required 110 volt ac power not available at site. WEISS. D. Office of Inspection & Enforcement, Office of the Director. 79/10/25. 1p.
- 7912180094 PNG-III-79-42: on 791120, unit critical after 26 day maint & mod outage caused by reactor trip on 791025. Caused by lost of reactor roolant pump during switching of emergency lighting buses. When anchor bolt penetrated buried conduit. REYEG, L. A., TAMBLINO, T. N., WARNICK, R. F. Region 3, Chicago, Office of the Director. 79/11/20. 2pp.
- 7912180221 PND-III-79-045: on 791122, while operating at 93% power, discovered RCS flow w/flour reactor coolent pumps in svc below Tech Spacs. Caused by instrumentation problem in Loop 2. Power to be limited to 72% during 18-months calibr test. REYES, L. A., WARNICK, S. F., TRAMBLING, T. N. Region 3, Chicago, Office of the Director, 79/11/26. 1p.
- 7912200028 PNG-III-79-045A: on 791106, reactor coolant sys flow discovered below min Tech Spec requirement. Util plans shutdown to add oil on weekend. REYES, L.A., WARNICK, R.F., TAMBLING, T.N. Region 3, Chicago, Office of the Director. 79/11/27. 1p.
- 7912100279 Forwards LER 79-107/03L-0. MURRAY, T. D. Folsdo Edison Co. 79/12/04. ip.
- --7912100288 LER 79-107/03L-O: on 791105, unit experienced loss of essential instrumentation distribution panel Y2 % did not enter action statement in Mode 5. Caused by blown greinverter YV2 output fuse. Repaired inverter. NAYLOR.R. W. Toledo Edison Co. 79/12/04, 2pp.
- 7912130476 Forwards LER 79-109/03L-0. MURRAY, J. G. Toledo Edison Co. 79/12/06. ip.

- --7912130486 LER 79-10B/O3L-0:on 791108, during normal plant evaluation of switching decay heat removal pumps, pump i failed to start remotely & locally at breaker. Caused by faulty cutout switch. Switch assembly replaced.

  NAYLOR, R. W. Toledo Edison Co. 79/12/06. 2pp.
- 7912170295 Forwards LER 79-111/03L-0. HURRAY, T. D. Toledo Edison Co. 79/12/11. ip.
- --79:2170297 LER 79-111/03L-0: on 79:114, during surveillance testing, accelerometer tracer could not be discerned due to excessive noise. Caused by component failure. Source of noise being investigated, possibly caused by battery charger.
  AEBIE.K. Toledo Edison Co. 79/12/11. 2pp.
- 7912170300 Forwards LER 79-109/03L-0. MURRAY, T.D. Toledo Edison Co. 79/12/11. ip
- --7912170303 LER 79-109/03L-0: on 791113; discovered Couch (Deutsch) relay contacts were driving high inductive loads in 26 nuclear safety-related circuits. Caused by inductive surge when contacts open. Arc suppression diades added to circuits. BEELER, T. P. Toledo Edison Co. 79/12/11. 2pp.
- 7912170305 Forwards LER 79-110/03L-0. HURRAY, T. D. Toledo Edison Co. 79/12/11. 1p.
- --7912170309 LER 79-i10/03L-0: on 791i12, while testing HPI pump i-1 in Mode 5. pump failed to start. Caused by improperly terminated tug in breaker control wiring. Lead properly terminated & reinstalled.

  NAYLOR, R. W. Toledo Edison Co. 79/12/11. 2pp.
- 7912260234 Forwards revised LER 79-105/01T-1. HURRAY.T.D. Toledo Edison Co. 79/12/15. 1p.
- 7912260237 Revised LER 79-105/01T-1: on 791109, during review of IE Bullstin 79-21 response, noted steam generator low level trip setpoints to steam & feedwater rupture control sys Channels 1 & 2 were below Tech Bpccs. Caused by error in points. TRAUTMAN.D. Toledo Edison Co. 79/11/21. 2pp.
- 7912260253 Forwards LER 79-112/03L-0. MURRAY-T.D. Toledo Edison Co. 79/12/18. 1p.
- --79:226025B LER 79-1:2/O3L-0: on 79:1:19, valve MB:06 failed to open during surveillance testing. Caused by improper installation of worm gear spacer. Drive sleeve machined & worm gear spacer reinstalled.

  D'NEILL, J. Toledo Edison Co. 79/12/18. 2pp.
- 7912270594 Forwards LER 79-113/03L-0. HURRAY.T.D. Toledo Edison Co. 79/12/18. 1p.
- --7912270599 LER 79-113/03L-0: on 791121, hourly surveillance requirements not performed for 5.5-h while incure instrumentation was inoperable. Caused by procedural deficiency. Equipment status board not updated. Procedure PP 1102.02 revised. BROWN, D. H. Toledo Edison Co. 79/12/18. 2pp.
- 7912270395 Forwards LER 79-114/03L-0.

  NURSAY.T.D. Toledo Edison Co. 79/12/20. 1p.
- --7912270398 LER 79-114/03L-0: on 791122.RCS indicated flow below Tech Spec requirements. Cause undetermined. Flow transmitter signal output circuits operating normally, Actual RCS flow & transmitter calibr will be checked & tubing backfilled. WERNER.J. Toledo Edison Co. 79/12/20. 3pp.
- 7912270402 Forwards LER 79-115/03L-0.

  MURRAY, T. D. Toledo Edison Co. 79/12/20. ip.
- --7912270407 LER 79-115/03L-0: on 791122, remote contact data typer became inoperable. Caused by procedural deficiency. Surveillance requirements inadequately specified on log sheet Log sheet will be modified to specify Tech Spec requirements. ROHRER, E. Toledo Edison Co. 79/12/20. 2pp.
- 7912270413 Forwards LER 79-116/03L-0. HURRAY: T. D. Toledo Edison Co. 79/12/20. ip.
- --7912270420 LER 79-116/O3L-0: on 791123.Control Rod Group 5 Rod ii absolute position indication declared inoperable.Caused by position indication assembly & cabling between electrical penetration & rod investigation continues.
  WERNER, J. Toledo Edison Co. 79/12/20. 3pp.

- U. Congressional/Executive Correspondence
- 7912120552 Responds to 791003 communication re N Masucci request for info concerning plant automatic shutdown & radwaste disposal. Shutdown caused by turbine trip resulting in equipment problems & loss of offsite power.
  FOUCHARD. J. J. Office of Public Affairs. 79/10/23. 2pp.
- --7912120563 Requests NRC comments re N Masucci request for info Concerning facility & nuclear waste disposal in DH METZENBAUM, H. M. Senate. 79/10/03. 1p.
- DOCKET 50-348 JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 1
  F. Security, medical, emergency & fire protection plans
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives. Provides guidance for improving licenses emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.

  ORIMES, B. K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- 7912190550 Forwards updated schedule for fire protection mods. CLAYTON, F. L. Alabama Power Co. 79/12/12. 3pp.
- Q. Adjudicatory correspondence
- 791211003B Confirms receipt of enc1 790329 petition to suspend the for all PMRs. Forwards FR notice indicating that petition will be treated in accordance w/10CFR2. 206.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/23. ip.
- --7912110126 Notice of request for action pursuant to 10CFR2.204 re Environ Coalition on Nuclear Power 790329 petition requesting suspension of all OLs for PMRs. MULLER, D. R. Dffice of Nuclear Reactor Regulation, 79/11/23.
- H. General correspondence
- 7912280401 Comments on NUREO-0610:list of reportable unusual events should be reduced in scope to include only events consequential to public & should be clearly defined.
  THRASH.H.Q. Alabama Power Co. 79/11/30. 2pp.
- M. Antitrust correspondence
- 7912190232 Forwards change of address for correspondence dealing w/util. New address: 1967 Sandalwood, Fort Collins, CD, 80826.
  HJELMFELT, D, C. Goldberg, Fieldman & Letham, P, C. 79/11/26. 2pp.
- P. Operating license stage documents & correspondence
- 7911090240 "Summary of Operating Experience W/Recirculating Steam Generators." EISENHUT.D.G. Division of Operating Reactors. NUREG-0523, 79701/31. B9pp.
- 7912050157 Discusses NRC review of LERs & Tech Spec requirements re control RPI sys at Westinghouse PWRs. Requests Tech Specs review to ensure requirement for rod maint to within +/- I2 steps indicated & RPI sys verified accurate within 12 steps. SCHMENGER; A. Operating Reactors Branch 1. 79/10/29, 7pp.
- 7912110977 Forwards request for add1 info re containment purgs & vent sys.Purge sys should only be used for cold shutdown & refueling reactor operational modes. LAINAS.G. Plant Systems Branch. 79/11/O2. 4pp.
- 7912100189 Discusses NRC 791101 meeting w/representatives of NSSS vendors & fuel suppliers re discussion of respective portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EISENHUT, D. O. Division of Operating Reactors. 79/11/09. 65pp.
- --7912100255 Responds to NRC 791101 request re nancompliance of Westinghouse ECCS evaluation model under requirements of 100FR50 App K. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants.

  ANDERSON, T. M. Westinghouse Electric Corp. 79/11/02. 4pp.
- --7912100330 Responds to NRC 791101 request re DRNL cladding swelling & rupture data, Review of analytical models & tests indicates compliance w/100FRSO App K. All OE specs for calculated peak cladding temp remain unchanged.
  BUCHHOLZ, R. M. General Electric Co. 79/12/07. 2pp.

- -7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of 10CFR50. 46 satisfied.

  DMSLEY.O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/11/02. 5pp.
- --7912100456 Forwards add1 info re evaluation of impact of NRC proposed rupture/blockage model used in vendor avaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. OMSLEY, 0.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/04. 22pp.
- 7912100266 Approves of 790501 proposed second 20-month inservice testing program description Grants interim relief from selected ASME code requirements. When detailed review complete, NRC will issue final approval.

  SCHWENCER, A. Operating Reactors Branch 1, 79/11/16, 3pp.
- --7912100268 Notice of granting of interim relief from ASME Section XI re inservice testing requirements.

  SCHMENCER.A. Operating Reactors Branch 1. 79/11/16, 2pp.
- 791204021B Summary of 791116 telcon w/util re lessons learned items for which licensee proposed schedule for implementation is unacceptable.
  REEVES.E.A. Operating Reactors Branch 1. 79/11/21. 6pp.
- 7912040141 Summary of 791116 telcon w/util re 791024 response to NRC 790913 ltr.Informed licensee of lessons learned items for which proposed implementation schedule is unacceptable. REEVES.E. A. Operating Reactors Branch 1. 79/11/21. Opp.
- 7912310505 Forwards request for addl info re containment purge sys to continue review of util lung-term proposals.

  SCHMENCER.A. Operating Reactors Branch 1. 79/12/04. 3pp.
- 7912180397 Forwards info re loss of offsite power.in response to 791002 ltr to AR Barton. CLAYTON.F.L. Alabama Power Co. 79/12/07. 3pp.
- 7912180405 Responds to NRC 791023 ltr. Discusses analysis performed by Henry Pratt Co.demonstrating that Bettis valve operators are capable of closure under LDCA conditions. Purging during operation w/18-incb valves safe under accident conditions. CLAYTON.F.L. Alabama Power Co. 79/12/10. 3pp.
- 7912180542 Forwards review & analysis of station electrical distribution sys. Review & analysis confirmed adequacy of offsite gower sys & onsite distribution sys. CLAYTON.F.L. Alabama Power Co. 79/12/11. 8pp.
- 7912190556 Forwards add1 info re description of auto initiation of auxiliary feedwater sys.in response to NRC 791210 request re Lessons Learned Task Force recommendations.

  CLAYTON.F.L. Alabama Power Co. 79/12/14. 7pp.
- O. Inspection reports, IE Bulletins & correspondence
- 7912070089 Forwards IE Insp Repts 50-348/79-32 & 50-364/79-14 on 790925-28 No noncompliance noted. LEMIS.R.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 79/10/22. 2pp.
- -7912070097 IE Insp Repts 50-348/79-32 & 364/79-14 on 790925-28 No noncompliance noted. Major areas inspected operations review. LERs. open items. IE circulars & agt meeting on Unit 2. HARDIN.A.K., DRADFORD, H. H. Region 2. Atlanta, Office of the Director. MARTIN.R.D. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 79/10/19. 4pp.
- 7912060097 Forwards IE Info Notice 79-12A. "Attempted Damage to New Fuel Assemblies." No specific action or response required. O'REILLY.J.P. Region 2. Atlanta. Office of the Director. 79/11/09. 2pp.
- 7912310292 Forwards IE Insp Rept 50-348/79-33 on 791010-12 & 19. No noncompliance noted. MRPHY, C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/11/15. 2pp.
- ---7912310300 IE Insp Rept 50-348/79-33 on 791010-12 & 19. No noncompliance noted. Major areas inspected: as-built safety-related piping sys insp procedures work activities & records & concrete majorsion anchor repair procedure.

  ANO.M.P., MERDITA.R. Region 2, Atlanta, Office of the Director, 79/11/08. 5pp.

- 7912100159 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/16. 1p.
- 7912110538 Forwards IE Info Notice 79-29. "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. O'REILLY,J.P. Region 2, Atlanta, Office of the Director. 79/11/16. 2pp.
- 7912060604 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BMTs." No response required.
  0'REILLY,J.P. Region 2, Atlanta, Office of the Director.
  79/11/26. 1p.
- 7912110113 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/26. ip.
- 7912140473 Responds to IE Bulletin 79-17.Revision 1. "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." Will conduct monthly visual examinations as requested. CLAYTON.F.L. Alabama Power Co. 79/11/27. 6pp.
- 7912140531 Ack receipt of 791102 ltr indicating no record of util response to IE Bulletin 79-19. "Fackaging of Low Level Radwaste for Transport & Burial." Util responded 790917 & NRC verified response by telcon 791108. CLAYTON.F.L. Alabama Power Co. 79/11/27. 1p.
- 7912190374 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Written response required.
  0'REILLY,J.P. Region 2. Atlanta, Office of the Director. 79/11/30. 1p.
- 7912310025 Forwards add1 response to IE Bulletin 79-01A. "Environ Qualification of Class IE Equipment." Solenoid valvas on valvas HV-8047.HV-8871.HV-7126 & LCV-1003 replaced w/ solenoid valves not containing acetal plastic. CLAYTON,F.L. Alabama Power Co. 79/12/04. 4pp.
- 7912310284 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances. 10CFR21." No action required.
  D'REILLY, J. P. Region 2. Atlanta, Office of the Director.
  79/12/06. 5pp.
- 7912200005 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required.

  O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
  79/12/07. 200.
- 7912210170 Responds to IE Bulletin 79-25 re failure of Westinghouse BFD relays in safety-related sys. Westinghouse SFD/NBFD relays not used or planned for use.

  CLAYTON F. L. Alabama Power Co. 79/12/07. 1p.
- 7912310274 Responds to IE Bulletin 79-02. Revision 2. "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts."

  No Seisaic Class 1 pipe supports found attached to concrete block walls during Nov 1979 facility walkdown.

  CLAYTON.F. L. Alabama Power Co. 79/12/07. 2pp.
- 7912210010 Ack receipt of IE Insp Repts 50-348/79-38 & 50-364/79-18 on 791106-09 No proprietary info. CLAYTON-F.L. Alabama Power Co. 79/12/10. 1p.
- ---7912210016 Forwards IE Insp Repts 50-348/79-38 & 50-364/79-18 on 791106-09, No noncompliance noted.
  NURPHY.C. E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 79/11/29. 2pp.
- --7912210021 IE Insp Repts 50-34B/79-38 & 50-364/79-18 on 791104-09. No noncompliance noted Major areas inspected electrical cable & terminations work & work activities & employee concerns. GIBBONG.T.D. Region 2. Atlanta, Diffice of the Director. COMLON.T.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/11/28. App.
- 7912280365 Forwards IE Info Notice 79-31. "Use of Incorrect Amplified Response Spectra." No written response required, O'fELLLY.J.P. Region 2. Atlanta, Office of the Director, 79/12/13. 2pp.

- 7912280115 Forwards IE Circular 79-25, "Shock Arrestor Strut Assembly Interference." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/12/20. 4pp.
- R. Periodic operating reports & related correspondence
- 7912270384 Forwards monthly operating rept for Nov 1979. CLAYTON.F.L. Alabama Power Co. 79/12/17. 1p.
- ---7912270389 Monthly operating rept for Nov 1979, HAIRSTON.M.O. Alabama Power Co. 79/12/01. 29pp.
- 7912310424 Forwards monthly operating rept for Nov 1979. CLAYTON, F. L. Alabama Power Co. 79/12/17. 3pp.
- ---7912310426 Monthly operating rept for Nov 1979. HAIRSTON, W. G. Alebama Power Co. 79/12/01. 7pp.
- B. Reportable occurrences. LERs & related correspondence
- 7912180286 PND-II-79-005: on 791008,120 cubic ft of gas containing 17 aCi of Kr-85 leaked from maste gas sys valve into auxiliary bldg. Oas released into environ via auxiliary bldg ventilation sys. Caused by maint work on valve. BRADFORD B., CIBBON, A.F. Region 2, Atlanta, Office of the Director. 79/10/09. ip.
- 7912070020 PNO-II-79-020: on 791031. Unit 1 achieved criticality following refueling outage which began on 790308. Zero power physics testing planned. BRADFORD, M.H., DYER.J. Region 2, Atlanta, Office of the Director. 79/10/31. 1p.
- 7912070050 PND-II-79-27: on 791107, fire occurred in cooling tower. Cause of fire unknown & under investigation. Fire extinguished in 30 minutes.

  BRADFORD W. H., MARTIN. R. D. Region 2. Atlanta, Office of the Director. 79/11/07. ip.
- 7912130422 RO: on 791107. cooling tower B fire resulted in reduction of fire protection tank levels. Tanks A & B fell to 120.000 gallons. Tank levels will be returned to min acceptable levels on 791107.

  HAIRSTON.W.O. Alabama Power Co. 79/11/07. 1p.
- 7912070063 PRO-II-79-29: un 791108, variations in leakeff rate noted from seal 2 on pump B. Facility shut down to repair pump seals on reactor collant pump. Licensee plans news release.

  RADFORD. U. H., MARTIN. R. D. Region 2. Atlanta. Office of the Director. 79/11/08. 1p.
- 7912130821 RO: Westinghouse notified util of potential for P-4 permissive failures to remain unidentified during parformance of surveillance tests. All info not evaluated. Datails will as provided in followup rept. HAIRBTON. W. O. Alabama Power Co. 79/11/08. 2pp.
- 7912030183 Forwards LER 79-049/03L-0. CLAYTON, F. L. Alabama Power Co. 79/11/27, 1p.
- -- 7912030187 LER 79-049/03L-0: on 791027, letdown erifice isolation valve 1-CVC-HV-Bi49A had not been tested prior to plant entering Hode 4. Caused by personnel seron. Personnel reinstructed in proper decuentation procedures.

  HAIRSTON.W. 0. Alabama Power Co. 79/11/27. 3pp.
- 7912040368 Forwards LER 79-053/03L-0. CLAYTON,F.L. Alabama Power Co. 79/11/30. 1p.
- ---7912040381 LER 79-033/03L-0: on 791101. rod K-14 in control bank A declared inoperable due to failure to move in or out during manual bank movement Caused by open control rod drive mechanism cable making power unavailable to K-14 lift coil. HAIRSTON M.O. Alabama Power Co. 79/11/29, ip.
- 7912110335 Forwards LERs 79-050/03L-0,79-051/03L-0,79-052/03L-0 & 79-054/01T-0, CLAYTON,F.L. Alabasa Power Co. 79/12/03. 1p.
- --7912110336 LER 79-050/03L-0: on 791107; trip bistables for pressurizer pressure transmitter PT455 not tripped before pressurizer level transmitter 459 root valves closed Caused by personnel error. Matter to be discussed w/operations personnel. HAIRBTON, M. O. Alabama Power Co. 79/12/03. 3pp.

- —7912110338 (.ER 79-052/03L-0: on 791106, refueling water storage tank declared inoperable when water vol fell below Tech Spacs. Caused by drift problems on level transmitters. Transmitters undergoing repairs. HAIRSTON.W.O. Alabama Power Co. 79/12/03. 1p.
- ---7912110339 LER 79-054/01T-0: on 791119, notified by Hestinghouse that possibility exists that current negative rate trip setpoints may not provide reactor trip during single or multiple rod drop events. Caused by designer calculation errors.

  HAIRSTON. H. O. Alabama Power Co. 79/12/03. ip.
- 7912120426 Forwards LERs 79-055/03L-0 & 79-056/03L-0. CLAYTON, F. L. Alabaga Power Co. 79/12/07. 1s.
- ~-7912120433 LER 79-055/03L-0: on 791108, borated water vol in boric acid storage tank fell below Tech Spec limit due to reactor cooldown. Boric acid tank concentration was returned to less than 7-700 pps, by 771109.

  HAIRSTON, N. O. Alabama Power Co. 79/12/07. 2pp.
- ---7912120459 LER 79-056/03L-0: on 791108,20 dysfunctional fire barrier penetrations found during GA audit Caused by misinterpretation of Tech Specs by plant personnel. Inoperable penetrations repaired. HAIRSTON.W. O. Alabama Power Co. 79/12/07. 2pp.
- 7912270212 Forwards LERs 79-057/03L-0 & 79-058/03L-0. CLAYTON, F. L. Alabama Power Co. 79/12/19. 1p.
- ---7912270228 LER 79-057/03L-0: on 791122, steam generator B level channel 486 declared inoperable due to high reading. Caused by instruments equalizing valve leaking. Valve tightened, tested & returned to operation.

  HAIRSTON.W. O. Alabama Power Co. 79/12/19. 1p.
- ----7912270238 LER 79-058/03L-0: on 791121. boron injection tank declared inoperable due to low concentration. Caused by inadvertant safety injection. Concentration increased by batching. HAIRSTON.M.G. Alabama Power Co. 79/12/19. 1p.
- 7912310448 Forwards LER 79-060/03L-0. CLAYTON: F. L. Alabama Power Co. 79/12/28, 1p.
- ---7912310451 LER 79-060/03L-0: on 791202, while moving from Mode 1 to 2, containment pressure Hi-1 & Hi-2 trip status lights for one channel energized on MCB w/normal readings on containment pressure indicators. Caused by comparator card failure. HARBTON, M. Q. Alabama Power Co. 79/12/29. ip.

## DOCKET 50-352 LIMERICK GENERATING STATION, UNIT 1

- A. Application/construction stage documents & correspondence
- 7911280133 Discusses mods to NRC position re status & applicability of TMI-2 accident review & NAREG-0578 to facilities under const. Forwards add info to be considered in development of final plant design & procedures. VASSALLO, D.B. Division of Project Hanagement. 79/10/10. 4pp.
- 7912110264 Discusses NRC plans to use generic analyses to develop sarly verification program to resolve ATHS issue for PMRs & BMRs.
  Success of program depends on industry response. Supports formation of owners groups to provide necessary info.
  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912280312 Advises of recently amended NRC regulations implementing suisting authority to require ensite ofc space & immediate facility access. FR notice dtd 790816 ancl. STELLO, V. Office of Inspection & Enforcement, Office of the Director. 79/11/28. 3pp.
- 7912190779 Notification of 791218 site visit to discuss effects of meanby blasting on facility.
  TIBBITTS.D.L. Light Water Reactors Branch 2. 79/12/04, 3pp.

- F. Becurity, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review. Applicants required to make certain emergency arrangements u/state & local organizations & submit emergency plans per Reg Quide 1.101.
  VABSALLO.D.B. Division of Project Management. 79/11/21. 6pp.
- H. General correspondence
- 7912260468 Requests all available info re emergency planning at facility including NUREGs, meeting minutes & committee scope.

  LEWIS, M. J. Affiliation Unknown. 79/12/21. ip.
- G. Inspection reports, 1E Bulletins & correspondence
- 7912120511 Responds to IE Bulletin 79-23 Exciter power transformer neutral is not connected to generator neutral Generator failure described in bulletin will not occur. BOYER, V. S. Philadelphia Electric Co. 79/10/22. 1p.
- 7912260296 Forwards IE Insp Repts 50-352/79-10 & 50-353/79-09 on 790924-25. No noncompliance noted. CARLSON,R.T. Region 1: Philadelphia, Reactor Construction & Engineering Support Branch. 79/11/06. 20p.
- --7912260298 IE Insp Repts 50-352/79-10 & 50-353/79-09 on 790924-25. No noncompliance noted. Hayar areas inspected: work activities a records re concreting & ASME code programs.

  HCGAUGHY, R. M. Region i. Philadelphia, Reactor Construction & Engineering Support Branch. MATTIA.J. Region i. Philadelphia. Office of the Director. 79/11/09. 4pp.
- 7912070144 Ack receipt of 791031 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-332/79-07 & 50-352/79-07 CAHLBON, R. T. Region I, Philadelphia, Reactor Construction & Engineering Support Branch. 79/11/15. 1p.
- ---7912070151 Responds to NRC 790927 ltr re violations noted in IE Insp. Repts 50-352/79-07 & 50-353/79-07. Corrective actions: specified repair procedure to meet pipe restraint spec & structural design requirements.

  BOYER. V. B. Philadelphia Electric Co. 79/10/31. Spp.
- 7912050289 Forwards IE Info Notice 79-27, "Steam Concrator Tube Ruptures at Two PNR Plants." No response required. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/11/14.
- 7912100140 Forwards IE Info Notice 79-28. "Overloading of Structural Elements Due to Pips Support Loads." No response required. GRIER. B. H. Region 1. Philadelphia. Diffice of the Director. 79/11/16. 1p.
- 7912100405 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No written response required, ORIER.B.H. Region 1, Philadelphia, Office of the Director. 79/11/16. ip.
- 7912110454 Forwards IE Info Notice 79-29. "Loss of Nonsafety-Related Reactor Coplant Bys Instrumentation During Operation." No specific action or response required. GRIER, B.H. Region i, Philadelphia, Office of the Director. 79/11/19. 1p.
- 7912050273 Forwards 1E Bulletin 79-26, "Boron Loss From BNR Control Bladge." No response required.
  GRIER.B.H. Region 1, Philadelphia, Office of the Director.
  79/11/20. ip.
- 7912060584 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BMRs." No response required. ORIER, B.H. Region 1, Philadelphia, Office of the Director. 79/11/26. 1p.
- 7912110075 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. Region 1, Philadelphia, Office of the Director. 79/11/24, ip.
- 79:2190089 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." No written response required. ORIER, B.H. Region 1, Philadelphia. Office of the Director. 79/11/30.

- 7912310241 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CfR21." No action required. ORIER, B. H. Region 1. Philadelphia. Office of the Director. 79/12/06. 4pp.
- 7912190762 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Written response required. ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/12/07. 1p.
- 7912280224 Forwards IE Info Notice 79-3i, "Use of Incorrect Amplified Response Spectra." No written response required. ORIER, B.H. Region I, Philadelphia, Office of the Director. 79/12/13. ip.
- U. Congressional/Executive Correspondence
- .7912210095 Responds to 790817 ltr re MC Seidts 790810 concern about siting of facility.NRC encourages power reactor siting in law population areas. Second NRC review of reactor before OLis granted to address safety & environ concerns. ODSSICK.L.V. Office of the Executive Director for Operations. 79/10/12. 3pp.
- 7912210253 Responds to 790807 ltr re FR Romano 790723 concern about blasting at rock quarry near facilities. Request being treated per 100FR2. 206. Effects of blasting at nearby quarry must be carefully evaluated. OBSICK. L. V. Office of the Executive Director for Operations. 79/10/12. 1p.
- --7912210266 Forwards FR Romano 790723 ltr re blasting operation at rock quarry near facilities. Requests comments.

  SCHWEIKER, R. S. Senate. 79/08/07. 2pp.
- DOCKET 50-353 LIMERICK GENERATING STATION, UNIT 2

  A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRs & BMRs. Success of program depends on industry response. Supports formation of owners groups to provide necessary info. DENTON.M.R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 79122B0312 Advises of recently amended NRC regulations implementing existing authority to require onsite of space & immediate facility access. FR notice dtd 790B16 encl.

  STELLOV. Office of Inspection & Enforcement, Office of the Director. 79/11/2B. 3pp.
- 7912190779 Notification of 791218 site visit to discuss affects of nearby blasting on facility. TIBBITTS, D.L. Light Water Reactors Branch 2, 79/12/04. Spp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review Applicants required to make certain emergency arrangements wistate & local organizations & submit emergency plans per Reg Guide 1.101.
  VASSALLO, D. B. Division of Project Management. 79/11/21. App.
- H. General correspondence
- 7912280488 Requests all available info re emergency planning at facility including NUREOs, meeting minutes & committee scope.

  LEWIS.M.J. Affiliation Unknown. 79/12/21, ip.
- G. Inspection reports. IE Bulletine & correspondence
- 7912120511 Responds to IE Bulletin 79-23. Exciter power transformer neutral is not connected to gonerator neutral Generator failure described in bulletin will not occur.
  BDYER. V. S. Philadelphia Electric Co. 79/10/22. 1p.
- 7912260296 Forwards IE Insp Repts 50-352/79-10 & 50-353/79-09 on 790924-25. No noncompliance noted. CARLEON.R. T. Region 1. Philadelphia, Reactor Construction & Engineering Support Branch. 79/11/06. 2pp.

- --7912260298 IE Insp Repts 50-352/79-10 & 50-353/79-09 on 790924-25.No noncompliance noted Major areas in≤pected; work activities & records re concreting & ASME code programs.
  MCOAUDHY,R.W. Region i, Philadelphia, Reactor Construction & Engineering Support Branch. MATTIA.J. Region i, Philadelphia, Office of the Director. 79/11/09. 4pp.
- 7912070144 Ack receipt of 791031 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-352/79-07 & 50-352/79-07. CARLEGON.R.T. Region i, Philadelphia, Reactor Construction & Engineering Support Branch. 79/11/15. 1p.
- --7912070151 Responds to NRC 790927 ltr re violations noted in IE Insp Repts 50-352/79-07 & 50-353/79-07. Corrective actions: specified repair procedure to meet pipe restraint spec & structural design requirements. BOYER, V. B. Philadelphia Electric Co. 79/10/31. 3pp.
- 7912050289 Forwards IE Info Notice 79-27, "Steam Generator Tube Ruptures at Two PWR Plants." No response required. ORIER.B.H. Region i, Philadelphia, Office of the Director. 79/11/14. ip.
- 7912100140 Forwards IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads." No response required. ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/11/16. 1p.
- 7912100405 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No written response required. GRIER, B. H. Region i, Philadelphia, Office of the Director. 79/11/16. 1p.
- 7912110456 Forwards IE Info Notice 79-29. "Loss of Nonsefety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director. 79/11/19. 1p.
- 7912050273 Forwards IE Bulletin 79-24, "Boron Loss From BWR Control Blades." No response required.

  QRIER.B.H. Region 1, Philadelphia, Office of the Director.
  79/11/20. 1p.
- 7912060584 Forwards IE Circular 79-24. "Proper Installation & Calibr of Gore Spray Pipe Break Detection Equipment on BURs." No response required.

  GRIES, B.H. Region 1. Philadelphia, Office of the Director. 79/11/26. 1p.
- 7912110075 Forwards IE Circular 79-23, "Motor Starters & Contactors Falled to Operate." No response required.

  ORIER.B.H. Region 1, Philadelphia, Office of the Director.
  79/11/26. 1p.
- 791219039 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation."
  No written response required.
  GRIER, B. H. Region 1, Philadelphia, Office of the Director.
  79/11/30. ip.
- 7912310241 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action required. GRIER, B.H. Region 1, Philadelphia, Office of the Director, 79/12/06. 4pp.
- 7912190762 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps," Written response required. ORIER, B. H. Region 1, Philadelphia, Diffice of the Director, 79/12/07. ip.
- 7912280224 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required.

  QRIER.B. H. Region 1, Philadelphia, Office of the Director.
  79/12/13. 1p.
- U. Congressional/Executive Correspondence
- 7712210075 Responds to 770817 itr re MC Seidts 770810 concorn about eiting of facility.NRC encourages power reactor siting in law papulation areas. Second NRC review of reactor before GL is granted to address safety & environ concerns. ODBRICK, L. V. Office of the Executive Director for Operations. 79/10/12. Spp.

- 7912210253 Responds to 790807 itr re FR Romano 790723 concern about blasting at rock quarry near facilities. Request being treated per 10CFR2, 206. Effects of blasting at nearby quarry must be carefully evaluated.

  QUSBICK.L.V. Office of the Executive Director for Operations.
  79/10/12. 1p.
- ~~7912210266 Forwards FR Romano 790723 ltr re blasting operation at rock quarry near factlities. Requests comments. SCHWEIKER.R. S. Senate. 79/08/07. 2pp.
- DOCKET SO-354 HOPE CREEK NUCLEAR STATION: UNIT 1
- A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATWB issue for PWRs & BWRs.
  Success of program depends on industry response Supports formation of owners groups to provide necessary info.
  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.
- 7912270567 Responds to NRC 791106 itr transmitting acceptance criteria for Mark I long-term grogram. Limited additesting will be conducted & schedule for containment analysis will be provided after final resolution of criteria.

  MITTL.R.L. Public Service Electric & Gas Co. of New Jersey.
  79/12/14. 2pp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review. Applicants required to make certain emergency arrangements wistate & local organizations & submit emergency plans per Reg Guide 1.101.
  VASSALLO, D. B. Division of Project Management. 79/11/21. App.
- G. Adjudicatory correspondence
- 7912110043 Forwards comments on NUREG-0511. Draft 0EIS reflects conscious & deliberate NRC policy to jeopardite public health & safety & thwart objectives of NEPA.
  KEPFORD, C. Environmental Coalition on Nuclear Power. 79/10/24.
- H. General correspondence
- 7912310245 Notifies of amonded regulations implementing existing authority requiring CP holders to provide onsite rent-free exclusive use of ofc space & immediate facility access to NRC insp personnel. FR notice dtd 790816 encl. STELLO.V. Office of Inspection & Enforcement, Office of the Director. 79/11/20. 4pp.
- Q. Inspection reports. IE Bulletins & correspondence
- 7912140267 Responds to IE Bulletin 79-23 ro putential failure of amorgancy diesel generator. Full load test of amorgancy diesel generator to be carried out for not less than 24-h. MARTEN, T. J. Public Service Electric & Gas Co. of New Jersey. 79/10/31. 1p.
- 7912170234 Responds to IE Bulletin 79-14. "Beismic Analysis for As-Built Safety-Related Piping Sys." Special insp for as-built configuration inappropriate due to early stages of const. In-process & final insp & review methods will be used. MARIIN.T.J. Public Service Electric & Gas Co. of New Jersey. 79/11/01. 2pp.
- 7912140287 Responds to IE Bulletin 79-14 re seismic analysis for safety-related piping sys. Insp for as-built configurations inappropriate until sys piping completed. MARTIN, T.J. Public Service Electric & Gas Co. of New Jarsey. 79/11/05. 1p.
- 7912050057 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves," No response required.
  GRIER, B. H. Region I, Philadelphia, Office of the Director.
  79/11/16, 1p.
- 7912050298 Forwards IE Info Notice 79~27, "Steam Generator Tube Ruptures at Two PWR Plants." No response required. QRIER.B.H. Region 1, Philadelphia, Office of the Director. 79/11/16. 1p.
- 79:2100:144 Forwards IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads." No response required. GRIER.B.H. Region 1. Philadelphia, Office of the Director. 79/11/16. 1p.

- 7912110466 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. ORIER.B.H. Region 1, Philadelphia, Office of the Director. 79/11/19. ip.
- 7912090287 Forwards IE Bulletin 79-26, "Boron Loss From BWR Control Blades." No response required. ORIER.B.H. Region 1, Philadelphia, Office of the Director. 79/11/20. tp.
- 7912080588 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on DWRs." No response required. GRIER, B. H. Region 1. Philadelphia. Office of the Director. 79/11/26. 1p.
- 7912110080 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. GRIER, B. H. Region 1. Philadelphia, Office of the Director. 79711/26. 1p.
- 7912190075 Forwards IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation." No written response required. ORIER, B. H. Region 1. Philadelphia. Office of the Director. 79/11/30. ip.
- 7912310244 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action required. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/12/06. 4pp.
- 79:2190765 Forwards IE Bulletin 79-20, "Possible Malfunction of Namco Model EAHO Limit Switches at Elevated Temps," Written response required.
  ORIER, B.H. Region 1, Philadelphia. Office of the Director.
  79/12/07. 1p.
- 7912280236 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/12/13. 1p.
- S. Reportable occurrences, LERs & related correspondence
- 7912130486 Ack receipt of 790926 interim deficiency rept re weld wire documentation.

  CARLSON.R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/10/17. 1p.
- --7912130464 Interim significant deficiency rept re weld wire documentation Electrodes used in post-weld heat treated condition were not properly tested. Caused by discrepancy in procedures. Procedures will be revised by BOOLIB. HARTIN.T.J. Public Service Electric & Gas Co. of New Jersey. 79/09/26. 3pp.
- DOCKET 50-355 HOPE CREEK NUCLEAR STATION, UNIT 2
- A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRs & BMRs. Success of program depends on industry response. Bugports formation of owners groups to provide necessary info.

  BENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 791R270567 Responds to NRC 791106 ltr transmitting acceptance criteria for Mark I long-term program. Limited additesting will be conducted & schedule for containment analysis will be provided after final resolution of criteria.
  MITTL.R.L. Public Service Electric & Gas Co. of New Jarsey.
  79/12/14. 2pp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to glants under const & DL review. Applicants required to make cortain emergency arrangements w/state & local organizations & submit emergency plans per Reg Guide 1.101.
  VASSALLO.D. B. Division of Project Management. 79/11/21. 6pp.

#### G. Adjudicatory correspondence

7912110043 Forwards comments on NUREO-0511. Draft GEIB reflects conscious & deliberate NRC policy to jeopardize public health & safety & thwart objectives of NEPA.

KEPFORD C. Environmental Coalition on Nuclear Power. 79/10/24, 22an

#### H. Qeneral correspondence

- 7912310245 Notifies of amended regulations implementing existing authority requiring CP holders to provide onsite.rent-free, exclusive use of ofc space & immediate facility access to NRC insp personnel.FR notice dtd 790816 encl. STELLGV. Office of Inspection & Enforcement, Office of the Director. 79/11/28. 4pp.
- 0. Inspection reports, IE Bulletins & correspondence
- 7912140247 Responds to IE Bulletin 79-23 re potential failure of emergoncy diesel generator. Full load test of emergency diesel generator to be carried out for not less than 24-h. HARTIN.T.J. Public Service Electric & Gas Co. of New Jersey. 79/10/31. ip.
- 79:2170234 Responds to IE Bulletin 79-14. "Beismic Analysis for As-Built Safety-Related Piping Sys." Special insp for as-built configuration inappropriate due to early stages of const. In-process & final insp & review methods will be used, MARTIN.T. J. Public Barvice Electric & Qas Co. of New Jersey. 79/11/01. 2pp.
- 79121402B9 Responds to IE Bulletin 79-14 re seismic analysis for safety-related piping sys. Insp for as-built configurations inappropriate until sys piping completed. HARTIN T. J. Public Bervice Electric & Gas Co. of New Jersey. 79/11/05. 1p.
- 7912050057 Forwards IE Circular 79-22. "Stroke Times for Power Operated Relief Valves." No response required. Office of the Director. 79/11/16. 1p.
- 7912050298 Forwards IE Info Notice 79-27. "Steam Generator Tube Ruptures at Two PMR Plants." No response required. GRIER.B.H. Region 1. Philadelphia. Office of the Director. 79/11/16. ip.
- 7712100146 Forwards IE Info Notice 77-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. ORIER. B. H. Region 1. Philadelphia, Office of the Director. 79/11/16. 1p.
- 7912110466 Forwards IE Info Notice 79-29. "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. ORIER, B. H. Region 1. Philadelphia. Office of the Director. 79/11/19. 1p.
- 7912050287 Forwards IE Bulletin 79-24, "Boron Loss From BWR Control Blades." No response required.
  ORIER.B.H. Region i, Philadelphia, Office of the Director.
  79/11/20. 1p.
- 7912060388 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Byray Pipe Break Detection Equipment on SWRs." No response required.
  ORIGE, B. H. Region i, Philadelphia, Office of the Director.
  79/11/26. 1p.
- 7912110080 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. GRIER.B.H. Region 1. Philadelphia, Office of the Director. 79/11/26. ip.
- 7912190075 Forwards IE Bullstin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." No written response required. ORIER, B. H. Region i, Philadelphis, Office of the Director. 79/11/30.
- 7712310244 Forwards IE Info Notice 79-30. "Reporting of Defects & Noncompliances, 10CFR21." No action required. GRIER, B. H. Region i, Philadelphia. Office of the Director. 79/12/06. 4pp.

- 79;2190765 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Written response required.

  ORIER, B. H. Region 1, Philadelphia, Office of the Director.
  79/12/07. | Ip.
- 79(2280236 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required.
  CRIER.8. H. Region 1, Philadelphia, Office of the Director.
  79/12/13. 1p.
- 8. Reportable occurrences. LERs & related correspondence
- 7912130456 Ack receipt of 790926 interim deficiency rept re weld wire documentation.
  CARLEON.R.T. Region i. Philadelphia. Reactor Construction & Engineering Support Branch. 79710/17. ip.
- ---7912130464 Interim significant deficiency rept re weld wire documentation. Electrodes used in post-weld heat treated condition were not properly tested. Caused by discrepancy in procedures. Procedures will be revised by 800118. HARTIN-T.J. Public Service Electric & Gas Co. of New Jersey. 79/09/26. Spp.
- DOCKET 50-356 UNIV. OF ILLINOIS LOPRA RESEARCH REACTOR
  F. Security, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Guide 5.XX, "Std Format & Content for Licensee Physical Security Plan for Protection of BNM of Moderate or Low Strategic Significance," W/o encl. REID, R. H. Operating Reactors Branch 4 (Pre 791030). 79/08/22, 2pp.

#### DOCKET 50-357 UNIV, OF CALIFORNIA

- F. Security, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Quide 5, XX, "Std Format & Content for Licenses Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance." W/o encl. REID.R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22. 2pp.

# DOCKET 50-358 WILLIAM H. ZIMMER NUCLEAR STATION, UNIT 1

### A. Application/construction stage documents & correspondence

- 7912110011 Forwards NRC position on status & applicability to pending OL applications of results of TMI followup actions. Outlines addl short-term actions to be taken.

  VABSALLO.D.B. Division of Project Management. 79/09/27. 41pp.
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMB issue for PMRs & BMRs.
  Buccess of program depends on industry response. Bupports formation of owners groups to provide necessary info.
  DENTON; H. R. Diffice of Nuclear Reactor Regulation. 79/10/17. 3pp.
- 7912100418 Forwards request for add1 info for environ qualification of Class IE instrumentation & electrical equipment. Requests schedule for response within seven days. Draft NRC interim position re snviron qualifications encl.

  STOLZ, J. F. Light Water Reactors Branch 1. 79/11/09. App.
- 7912180323 Forwards proposed Revision 2 to Reg Guide 1.97.
  "Instrumentation for Light-Mater-Coaled Nuclear Power Plants
  to Assess Plant & Environs Conditions During & Following
  Accident." Requests comments.
  VAR9A.8.A. Assistant Director for Light Water Reactors. 79/11/23.
  380.
- 79:2270178 Notification of 79:214 meeting w/applicants to discuss proposed Revision 2 to Reg Guide 1.97. "Instrumentation for Light Water Cooled Nuclear Plants to Assess Plant & Environs Conditions During & Following Accident."

  KINTNER.L.L. Light Water Reactors Branch 1. 79/11/19. 1p.
- 7912190534 Requests plant-wide field audit of installed electrical equipment & sys to determine conformance to separation criteria. Requests response in IS days.

  STOLL, J. F. Light Water Reactors Branch 1. 79/11/30. 2pp.
- 7912210007 Summary of 791205 meeting w/util in Bethesda. MD re addl margin in facility to acommodate pool dynamic loads.
  PELTIER, I. A. Light Water Reactors Branch 1. 79/12/07. 5pp.

- 7912310356 Notification of 800108 meeting w/utils in Bethesda,MD to discuss info request re adequacy of equipment qualification.
  UNGARO,A.R. Power Systems Branch. 79/12/11. 3pp.
- 7912310262 Forwards request for add1 info to continue review of application for OL. Includes request for info on second round questions & inservice pump & valve testing. Requests response by 800228.

  STOLZ, J. F. Light Water Reactors Branch 1. 79/12/12. 18pp.
- 7912170308 Forwards comments on proposed Revision 2 to Reg Quide 1.97.
  Quide should allow ex-containment post-accident monitors on
  plants having secondary containment bidgs. Util will attend
  791214 meeting.
  FLYNN, J. D. Cincinnati Gas & Electric Co. 79/12/13, App.
- .
- 7912270336 Responds to NRC 791130 ltr re separation of electrical equipment & sys. Util commits to complying w/requirements. FLYNN, J. D. Cincinnati Gas & Electric Co. 79/12/21. 1p.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & DL review. Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Guide 1.101.
  VASSALLO, D. B. Division of Project Management. 79/11/21. 6pp.
- 7912050391 Forwards Amend 101.Revision 8 to Industrial Security Plan. Plan withheld (ref 10CFR2.790). BORGMANN, E. A. Cincinnati Gas & Electric Co. 79/11/29. 2pp.
- 7712200438 Forwards draft emergency plan requested by NRC on 791106-08 visit.
  BURGMANN, E. A. Cincinnati Gas & Electric Co. 79/12/17. 2pp.
- --7912200440 Draft emergency plan. \* Cincinnati Gas & Electric Co. 79/12/17. 156pp.

#### G. Adjudicatory correspondence

- 7912120002 Interrogatories re Contention 13.Certificate of Svc encl. FELDMAN, J. H. Miami Valley Power Project. 79/11/08. 4pp.
- 7912130033 Memorandum & motion to continue evidentiary hearings until Congress either affirms status of NRC or creates new regulatory agency charged w/granting OLs. Certificate of Svc encl. FELDMAN, J. H. Miami Valley Power Project. 79/11/10. 3pp.
- 7912110361 Seventh set of interrogatories re intervenor Contention 13. Certificate of Svc encl. WETTERHAHN, M. J. Cincinnati Gas & Electric Co. WETTERHAHN, M. J. Conner, Moore & Corber. 79/11/21. Spp.
- 7912110376 Response to intervenor Miami Valley Power Project interrogatories re Contention 13, concerning delay in fuel loading date. Certificate of Svc encl.
  BDRGFANN.E.A. Cincinnati Cas & Electric Co. 79/11/27. 24pp.
- 7912130090 Objection to intervenor Miami Valley Power Project 791109 interrogatories re Contention 13 & request for protective order. Requested info outside scope of issues determined by ABLB. Certificate of Syc encl.
  HETTERHAHN.M.J. Cincinnati Cas & Electric Co. WETTERHAHN.M.J. Conner, Moore & Corber. 79/11/27. 4pp.
- 7912030426 Response to intervenor Miami Valley Power Project interrogatory re Contention 13 Interrogatory beyond 791001 ABLB order. Certificate of Svc and I. BARTH.C.A. Hearing Branch J. 79/11/28. 5pp.
- 7912280685 Responds to FDIA request for Sargent & Lundy 1969 rept, "Economic Evaluation of Alternatives," w/transmittal ltr & summary rept. Info withheld (ref FOIA Exemption 4). CARR, J. C. Division of Rules and Records. 79/12/21. 2pp.

### H. General correspondence

7912170135 Responds to 790426 ltr re radiation exposure resulting from nuclear accidents. Increase in radiation doses to persons living within 50-mile radius of TMI-1 was 1% of that received from background sources.

VAROA.S.A. Assistant Director for Light Water Reactors. 79/11/26.
28pg.

- --7912170140 Requests info re radiation doses in event of nuclear accident Guestions ability at procedural & equipment change to correct TMI-type problems.

  WEINER, M. Affiliation Unknown. 79/04/26. 2pp.
- 7912170145 Responds to 790417 itr re radiation exposure resulting from TM1-2. Increase in radiation doses to persons living within 50-mile radius was 1% of that received from background sources. Ltr to President Carter encl. VAR9A. S. Assistant Director for Light Hater Reactors. 79/11/26.
- 7912190076 Responds to inquiry re safety of facility & disclosure of Reed rept & hearings on NV 1954 nuclear testings. Reviews & hearings re non-TMI safety questions underway. TMI-related issues will be addressed in future hearings. Inquiry encl. VAROA. B. A. Assistant Director for Light Mater Reactors. 79/11/2
- Q. Inspection reports, IE Bulletins & correspondence
- 7912110439 Responds to IE Bulletin 79-23. Will perform 24 load tests during preoperational testing of emergency load generators. Problem described in Item 1 not applicable.

  BGROMANN.E.A. Cincinnati Gas & Electric Co. 79/10/25. 1p.
- 7912050113 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912100218 Forwards IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads." No response required.

  KEPPLER, J. G. Region 3. Chicago. Office of the Director. 79/11/16.
- 7912110567 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required.

  KEPPLER.J.C. Region J. Chicago. Office of the Director. 79/11/16.
- 7912050338 Forwards IE Bulletin 79-26, "Boron Loss From BHR Control Blades." No response required.

  KEPPLER. J. G. Region 3, Chicago, Uffice of the Director. 79/11/20.
- 7912100423 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No written response required.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/26.
- 7912140203 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No written response required.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/26.
- 7912110397 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sent by NRC to licensees.

  KEPPLER, J. O. Region 3. Chicago, Office of the Director. 79/11/28.
- 7912190211 Forwards IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Dus During Operation." Written response required. KEPPLER, J. O. Region 3. Chicago. Office of the Director. 79/11/30.
- 7912140069 Forwards IE Info Notice 79-30. "Reporting of Defects & Noncompliances, 10CFR21." No action or response required. KEPPLER, J. C. Region 3, Chicago, Office of the Director. 79/12/06.
- 7912200099 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps," Action required. KEPPLER: J. G. Region 3: Chicago, Defice of the Director. 79/12/10.
- S. Reportable occurrences. LERs & related correspondence
- 7912180045 PNS-III-79-04: on 791119, New Richmond, OH, police dispatcher received bomb threat from male caller. Plant evacuated. No device found & no explosion occurred. CREED, J.R., DOMAHUE, J.F. Office of Inspection & Enforcement, Office of the Director. 79/11/20. 1p.

- U. Congressional/Executive Correspondence
- 7912210071 Responds to V Dierig inquiry re transportation of fuel. Nuclear fuel arrives at facility in line w/earliest date of const completion.ASLB 790809 hearing determined no undue safety risk.

  OOSBICK.L.V. Office of the Executive Director for Operations.
  79/10/31. 3pp.
- --7912210089 Notifies of V Dieríg request for info re transportation of U-235 to facility Requests comment. HUDDLESTON, W. D. Senata. 79/08/27. lp.
- DOCKET 50-360 BATTELLE MEMORIAL INST. CRITICAL FACILITY F. Security, medical, emergency & fire protection plans
- 7912)20204 Forwards draft Reg Guide 5. XX, "Btd Format & Content for Licensee Physical Security Plan for Protection of SNM of Moderate or Low Btrategic Significance." W/o encl. REID.R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22.
- DOCKET 50-361 BAN ONOFRE NUCLEAR STATION, UNIT 2
- A. Application/construction stage documents & correspondence
- 7912110011 Forwards NRC position on status & applicability to pending OL applications of results of TMI followup actions. Gutlines add1 short-term actions to be taken.
  VASSALLO.D.B. Division of Project Management. 79/09/27. 41pp.
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATWS issue for PWRs & BWRs. Success of program depends on industry response. Supports formation of owners groups to provide necessary info. DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912110070 Forwards proposed Revision 2 to Reg Quide 1.97,
  "Instrumentation for Light Water Cooled Nuclear Power Plants
  to Assess Plant & Environs Conditions During & Following
  Accident." Requests comment.
  VAROA.S.A. Assistant Director for Light Water Reactors. 79/11/23.
- 7912190215 Ack receipt of 770628 & 0827 ltrs requesting withholding of slides of fuel structure design from public disclosure. Request granted (ref 10CFR2, 790). BAER,R.L. Light Water Reactors Branch 2, 79/12/05, 2pp.
- 7912190791 Forwards questions re study, "Rept of Evaluation of Max Earthquake & Bite Ground Motion Paramaters Associated w/ Offshore Zone of Deformation Facility." DEVINE, J. F. Interior, Dept. of, Geological Survey. 79/12/07. 4pp.
- 7912270390 Forwards "Status Rept on Followup Actions Resulting From NRC Reviews re TMI-2 Incident" to comply w/NUREO-0578 & to respond to NRC 790927 & 1109 ltrs.
  BASKIN.K.P. Southern California Edison Co. 79/12/19, 2pp.
- --7912270397 "Status Rept on Followup Actions Resulting From NRC Reviews ra TMI-2 Incident."

  # Southern California Edison Co. # San Diego Cas & Electric Co. 79712/31. 79pp.
- 7912280502 Advises that applicants are not willing to sign proposed mamorandum of agreement re potential impact of transmission lines on cultural resources.

  BASKIN, K. P. Southern California Edison Co. 79/12/21. ip.
- C. Utility Environmental Report (ER), amends & correspondence
- 7912200109 Forwards updated distribution list for environ rept suppls & amends for facility.

  DUNCAN.M. Environmental Projects Branch 2. 79/12/06. 5pp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded smargency plans to plants under const & OL review. Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Guide i. 101. VASSALLO, D. B. Division of Project Management. 79/11/21. App.

- 7912180572 Forwards addl info re emergency planning in response to NRC 791031 request. Addl copies of responses re Units 2 k 3 will be transmitted w/Amend 17 of FBAR. Info is responsive to specific questions & NRC overall action plan.

  BAGKIN.K.P. Southern California Edison Co. 79/12/10. 23pp.
- 7912310007 Forwards proprietary request for add1 info to complete review of safeguards contingency plan. Details withheld (ref 10CFR2. 790).

  ZIEMANN.D.L. Operating Reactors Branch 2. 79/12/11. 2pp.

## Q. Adjudicatory correspondence

- 7912100352 Stipulation allowing extension until 791103 for applicant to respond to intervenors Friends of the Earth et al. 791018 second set of interrogatories. Certificate of Svc ancl. Plo0TT.D.R. Southern California Edison Co. WHARTON.R.J. Friends of the Earth. Pl00TT.D.R. Chickering & Gregory. 79/11/04. 4pp.
- 7712130061 Stipulation re extension until 791203 for applicant to answer intervenor second set of interrogatories. Certificate of Svc enci. PIGOTT, D. R. Southern California Edison Co. PIGOTT, D. R. Chickering & Gregory. WHARTON, R. J. Friends of the Earth. 79/11/06. 4pp.
- 7912050189 Notice of appearance of L Thorton on behalf of util. Certificate of Svc encl. THORTON L. Affiliation Unknown. 79/11/08. 4pp.
- 7912100314 Order approving applicants & intervenors Friends of the Earth, et al. stipulation for extension until 791203 to answer intervenors' interrogatories.

  SNITH.I.H. Atomic Sefety and Licensing Board Panel. 79/11/26. ip.
- 7912140142 Response & objections to 791018 second set of interrogatories, Answers Interrogatories i-84. Verification of DR Pigott & Certificate of 8vc encl. PIGOTT, D. R. Southern California Edison Co. PIGOTT, D. R. San Diego Gas & Electric Co. PIGOTT, D. R. Chickering & Gregory, 79/12/03.

#### G. Inspection reports, IE Bulletins & correspondence

- 7912060018 Forwards IE Insp Repts 50-361/79-25 & 50-362/79-24 on 790904-07 & 24-28. No noncompliance noted: BPENCER.0.8. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/10/31. 2pp.
- --7912050025 IE Insp Rept 50-361/79-25 % 50-362/79-24 on 790904-08 & 24-28. No moncompliance noted Major areas inspected:const activities, reactor pressure vessel & internals, installation & protection of stainless steel piping.
  DDDDS:R.T. Region 5, Ban Francisco, Reactor Construction & Engineering Support Branch. PATE.R.J. Region 5, San Francisco Office of the Director. 79/10/26. 4pp.
- 7912100280 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/11/16. 1p.
- 7912110517 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Codlant Sys Instrumentation During Operation." No specific action or response required. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/11/16. 1p.
- 7712070023 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pips Break Detection Equipment on BWRs." No response required.
  EMPELWENTR H. Region 5, Ban Francisco, Office of the Director. 79/11/26. ip.
- 79:2110272 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. EMOELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/11/26. 1p.
- 7912110496 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sent by NRC to licensees.

  ENDELKEN.R.H. Region 5. Ban Francisco, Office of the Director. 79/11/26. ip.
- 7912130700 Ack receipt of 791031 ltr informing NRC of steps taken to correct violation noted in IE Insp. Repts 50-361/79-22 & 50-362/79-21.
  SPENCER.G. B. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/11/29. 1p.

- --7912130704 Responds to NRC 791002 Itr re violations noted in IE Insp. Repts 50-361/79-22 & 50-362/79-21. Corrective actions: detailed review of all safety-related cable pulling calculations conducted.

  ARENAL A. Southern California Edison Co. 79/10/31. 3pp.
- --7912130707 Forwards IE Insp Repts 50-361/79-22 & 362/79-21 on 790813-31 & notice of violation.

  8FENCER, G. S. Region S. San Francisco, Reactor Construction & Engineering Support Branch. 79/10/02. 2pp.
- --7912130713 Notice of violation from insp on 790813-31.

  \* Region 5, San Francisco, Dffice of the Director. 79/10/01.
  io.
- --7912130723 IE Insp Repts 50-361/79-22 & 50-362/79-21 on 790813-31.

  Noncompliance noted cable tension calculations for cable
  pull reviewed & found in error.

  PATE.R. J. Region 5, Sam Francisco, Office of the Director.

  DDDDBS.R.T. Region 5, San Francisco, Reactor Construction &
  Engineering Support Branch. 79/10/01. 5pp.
- 7912190156 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." No written response required. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/11/30
- 7712310273 Forwards IE Info Notice 79-30. "Reporting of Defects & Noncompliances, IOCFR21." No action required. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/12/04. 4pp.
- 7912140476 Forwards reply to IE Bulletin 79-13 Revision 1, "Cracking in Feedwater Bys Piping." SPENCER,O.S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/12/07. ip.
- --79121404B4 Responds to IE Bulletin 79-13. Revision 1. "Cracking in Feedwater Sys Piping." Radiographic examinations performed on feedwater nozzle-to-pips wolds in accordance w/ABME Code. Examinations revealed no cracking.

  BABKIN.K.P. Bouthern California Edison Co. 79/09/19. 4pp.
- 7912200247 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/12/07. ip.
- 7912280625 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required. ENGELKEN, R.H. Region 5, San Francisco, Office of the Director. 79/12/13. 1p.
- S. Reportable occurrences, LERs & related correspondence
- 7912180524 Forwards final deficiency rept re lack of qualification testing documentation for repaired power cable.
  ARENALIA. Southern California Edison Co. 79/12/12. 1p.
- ---7912180529 Final deficiency rept re lack of qualification testing documentation for repaired power cable. Discusses LOCA qualification testing of safety-related cable supplied by numerous vendors.

  \* Southern California Edison Co. 79/12/12. App.
- 7912190602 Forwards final deficiency rept re use of incorrect matl for retaining clip in thermal pressure relief devices on certain safety-related gate valves.

  ARENAL, A. Bouthern California Edison Co. 79/12/12. lp.
- --7912190615 Final deficiency rept:carbon steel retaining clip was substituted for stainless steel clip in thermal pressure relief valves. Corrosion of clip could cause poppet stem to be expelled. Cause unstated, Pipe plug installed in bore.

  \* Southern California Edison Co. 79/12/11. 3pp.
- 7912200541 Forwards interim deficiency rept re lack of documentation for measuring & testing equipment.
  ARENAL.A. Southern California Edison Co. 79/12/14. ip.
- --7912200544 Interim deficiency rept re lack of "as received" documentation for measuring & testing equipment recalibrated at vendor facilities. Procedures revised to strengthen control of vendors performing calibr svs.

  \* Southern California Edison Co. 79/12/14. 3pp.

- DOCKET 50-362 SAN ONOFRE NUCLEAR STATION, UNIT 3
- A. Application/construction stage documents & correspondence
- 7912110011 Forwards NRC position on status & applicability to pending OL applications of results of TMI followup actions. Outlines addl short-term actions to be talen.
  VASSALLO, B. B. Division of Project Management. 79/09/27. 41pp.
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRs & BURS. Buccess of gragram depends on industry response Supports furnation of owners graups to provide necessary info. DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.
- 7912190215 Ack receipt of 790628 & 0827 ltrs requesting withholding of slides of fuel structure design from public disclosure.
  Request granted (ref 10CFR2.790).
  BAER.R.L. Light Water Reactors Branch 2. 79/12/05. 2pp.
- 7912190791 Forwards questions re study, "Rept of Evaluation of Max Earthquake & Site Ground Motion Paraseters Associated w/ Offshore Jone of Deformation Facility." DEVINE, J. F. Interior, Dept. of, Geological Survey. 79/12/07. App.
- 7912270390 Forwards "Status Rept on Followup Actions Resulting From NRC Reviews re THI-2 Incident" to comply w/MUREG-0578 & to respond to NRC 790927 & 1109 ltrs.
  BASKIN.K.P. Southern California Edison Co. 79/12/19. 2pp.
- --7912270397 "Status Rept on Followup Actions Resulting From NRC Reviews re TMI-2 Incident."

  \* Southern California Edison Co. \* San Diego Gas & Electric Co. 79/12/31. 79pp.
- 7912280502 Advises that applicants are not willing to sign proposed magorandum of agreement re potential impact of transmission lines on cultural resources.

  NAEKIN, K. P. Southern California Edison Co. 79/12/21. ip.
- C. Utility Environmental Report (ER), amends & correspondence
- 7912200109 Forwards updated distribution list for environ rept suppls & anends for facility.

  DUNCAN.M. Environmental Projects Branch 2. 79/12/06. Spp.
- F. Security, medical, emorgency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review. Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Guide 1.101. VASSALLO, D. D. Division of Project Hanagement. 79/11/21. 6pp.
- 7912180572 Forwards add1 info re emergency planning in response to NRC 791031 request. Add1 copies of responses re Units 2 & 3 will be transmitted w/Amend 17 of FEAR. Info is responsive to specific questions & NRC overall action plan.

  BASKIN, K. P. Southern California Edison Co. 79/12/10. 23pp.
- 7912310007 Forwards proprietary request for add1 info to complete review of safeguards contingency plan. Details withheld (ref 10CFR2.790). ZIEMAND.D.L. Operating Reactors Branch 2. 79/12/11. 2pp.
- G. Adjudicatory correspondence
- 7912100352 Stipulation allowing extension until 791103 for applicant to respond to intervenors Friends of the Earth, et al.791018 second set of intervogatories. Certificate of Svc ancl. PloOTT.D.R. Southern California Edison Co. MHARTON.R.J. Friends of the Earth. PICOTT.D.R. Chickering & Gregory. 79/11/06. 4pp.
- 7912130061 Stipulation re extension until 791203 for applicant to answer intervenor second set of interrogatories Certificate of Svc encl. PIGOTT, D. R. Southern California Edicon Co. PIGOTT, D. R. Chickering & Gregory, WHARTON, R. J. Friends of the Earth. 79/11/06. 4pp.
- 7912050189 Notice of appearance of L Thorton on behalf of util. Cortificate of Svc oncl. THORTON, L. Affiliation Unknown. 79/11/08. 4pp.
- 7912100314 Order approving applicants & intervenors Friends of the Earth, et al. stipulation for extension until 791203 to answer intervenors' interrogatories.

  SMITH, I. W. Atomic Safety and Licensing Board Panel. 79/11/26. 1p.

- 7912140142 Response & objections to 791018 second set of interrogatories. Answers Interrogatories 1-84. Verification of DR Pigott & Certificate of Svc encl. P100TT.D.R. Southern California Edison Co. P100TT.D.R. San Diego Oas & Electric Co. P100TT.D.R. Chickering & Gregory. 79/12/03. 54pp.
- G. Inspection reports, IE Bulletins & correspondence
- 7912060018 Forwards IE Imsp Repts S0-361/79-25 & 50-362/79-24 on 790904-07 & 24-28 No noncompliance noted.

  SPENCER. 0. S. Ragion 5. San Francisco. Reactor Construction & Engineering Support Branch. 79/10/31. 2pp.
- --7912060025 IE Insp Rept 50-361/79-25 % 50-362/79-24 on 790904-00 % 24-26. No noncompliance noted Major areas inspected const activities, reactor pressure versel & internals, installation & protection of stainless steel piping.

  DUDDS.R.T. Region 5. San Francisco, Reactor Construction & Engineering Support Branch. PATER.J., Region 5. San Francisco Office of the Director. 79/10/26. 4pp.
- 7912100280 Forwards IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads." No response required. ENGELKEN.R.H. Region 5. San Francisco. Office of the Director. 79/11/16. 1p.
- 7912110517 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. ENGELKEN.R. H. Region 5, San Francisco, Office of the Director. 79/11/16. 1p.
- 7912070023 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Epray Pipe Break Detection Equipment on BWRs." No response required.
  ENGLIKEN.R.H. Region 9, San Francisco, Office of the Director. 79/11/26. 1p.
- 7912110272 Forwards IE Circular 79-23, "Motor Blarters & Contactors Failed to Operate." No response required. ENGELKEN.R.H. Region S. San Francisco. Diffice of the Director. 79711/26. 1p.
- 7912110476 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofts copies of escalated enforcement correspondence sent by NRC to licensees.

  ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/11/26. 1e.
- 7912130700 Ack receipt of 791031 Itr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-361/79-22 & 50-362/79-21.

  SPENCER. 9. S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/11/29, ip.
- --7912130704 Responds to NRC 791002 ltr re violations noted in IE Insp Repts 50-361/79-22 & 50-362/79-21.Corrective actions: detailed review of all safety-related cable pulling calculations conducted. ARENAL.A. Southern California Edison Co. 79/10/31. 3pp.
- --7912130707 Forwards IE Insp Reptx 50-361/79-22 & 362/79-21 on 790813-31 & notice of violation.

  SPENCER, O. S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/10/02. 2pp.
- ---7912130713 Notice of violation from insp on 790813-31,

  \* Region 5. San Francisco. Office of the Director. 79/10/01.
- ---7912130723 IE Insp Reptw 50-361/79-22 & 50-362/79-21 on 790813-31.

  Noncompliance noted:cable tension calculations for cable pull reviewed & found in error.

  PATE.R.J. Region 5. San Francisco. Office of the Director.

  DODDS.R.T. Region 5. San Francisco. Reactor Construction & Engineering Support Branch. 79/10/01. 5pp.
- 7912190196 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." No written response required. ENGELKEN.R.H. Region S. San Francisco, Office of the Director. 79/11/30.
- 7912310273 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompilances, 100FR21." No action required. ENGLKEN.R.H. Region 5, Ban Francisco, Office of the Director. 79/12/06. 4pp.

- 7912140476 Forwards reply to IE Bulletin 79-13 Revision i. "Cracking in Feedwater Sys Piping."

  SPENCER.O. S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/12/07. ip.
- --7912140484 Responds to IE Bulletin 79-13, Revision 1. "Cracking in Feedwater Sys Piping." Radiographic examinations performed on feedwater nozzle-to-pipe welds in accordance w/ASME Code. Examinations revealed no cracking.

  BASKIN.H.P., Southern California Edison Co. 79/09/19. 4pp.
- 7912200247 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. ENGELKEN.R. M. Region 5, San Francisco, Office of the Director. 79/12/07. ip.
- 7912280625 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required. EMDELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/12/13. ip.
- S. Reportable occurrences, LERs & related correspondence
- 7912180324 Forwards final deficiency rept re lack of qualification testing documentation for repaired power cable.

  ARENAL, A. Southern California Edison Co. 79/12/12. ip.
- --7912180529 Final deficiency rept re lack of qualification testing documentation for repaired power cable Discusses LOCA qualification testing of safety-related cable supplied by numerous vendors.

  \* Bouthern California Edison Co. 79/12/12. 4pp.
- 7912190602 Forwards final deficiency rapt re use of incorrect math for retaining city in thermal pressure relief devices on certain safety-related gate valves.

  ARENAL: A. Southern California Edison Co. 79/12/12. 1p.
- --79:2190615 Final deficiency rept:carbon steel retaining clip was substituted for stainless steel clip in thermal pressure reitef valves. Corrosion of clip could cause poppet stem to be expelled. Cause unstated. Pipe plug installed in bore.

  \* Southern California Edison Co. 79/12/11. 3pp.
- 79:2200541 Forwards interim deficiency rept re lack of documentation for measuring & testing equipment.

  ARENAL.A. Southern California Edison Co. 79/12/14. ip.
- ---7912200544 Interim deficiency rept re lack of "as received" documentation for measuring & testing equipment recalibrated at vendor facilities. Procedures revised to strengthen control of vendors performing calibr svts.

  \* Southern California Edison Co. 79/12/14. 3pp.
- DOCKET 50-363 FORKED RIVER NUCLEAR STATION, UNIT 1
- A. Application/construction stage documents & correspondence
- 7982110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PWRs & BWRs. Success of program depends on industry response. Supports formation of owners groups to provide necessary info.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. Opp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review Applicants required to make certain amargency arrangements wistate & local organizations & subsit emergency plans per Reg Quide 1,101.

  VABSALLO, D. B. Division of Project Management. 79/11/21. App.
- H. General correspondence
- 7912190102 Responds to 790409 itr re continued const.Lessons learned from TMI will be incorporated into design.Const suspended temperatily by util & will not resume for at least one yr. DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/28. 2pp.
- --7912190109 Notifies of concern over use of nuclear generation & operating similarities in design of TMI-2 & other nuclear units. Requests meeting w/RRC to identify strategy to reduce probability of TMI-incident at facility.

  BARBOUR. C. H. New Jersey, State of, 79/04/09, 1p.

- G. Inspection reports, IE Bulletins & correspondence
- 7912180401 Responds to IE Bulletin 79-25, "Reactor Trips at Turkey Point Units 3 & 4." No electrical equipment purchased w/installed Westinghouse BFD relays. Will request AE to identify type relays if BFD relays selected. FINFROCK. I.R. Jersey Central Power & Light Co. 79/11/14. 1p.
- 7912050030 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required.
  ORIER, B.M. Region 1. Philadelphia, Office of the Director.
  79/11/16. ip.
- 7912050250 Forwards IE Info Notice 79-27, "Steam Generator Tube Ruptures at Two PMR Plants." No response required. ORIER, B.H. Region 1, Philadelphia, Office of the Director. 79/11/16. 1p.
- 791210b122 Forwards IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Bupport Loads." No response required. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/13/16. 1p.
- 791211D411 Forwards IE Info Notice 79-29. "Loss of Nonsafety-Related Reackor Coolant Bys Instrumentation During Operation." No specific action or response required. ORIER.B.H. Region 1. Philadelphia. Office of the Director. 79/11/19. 1p.
- 7912050235 Forwards IE Bulletin 79-24, "Boron Loss From BWR Control Blades," No response required.

  ORIER, B. H. Region i. Philadelphia, Office of the Director, 79/11/20.
- 7912060573 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BMRs." No response required.
  GRIER, B. H. Region i, Philadelphia, Office of the Director.
  79/11/26. ip.
- 7912110047 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate," No response required. GRIER, B.H. Region 1, Philadelphia, Office of the Director, 79/11/26. 1p.
- 7912310219 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances: 100FR21." No action required. GRIER, B.H. Region 1. Philadelphia. Office of the Director. 79/{2/06. 4pp.
- 7912190747 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Ewitches at Elevated Temps." Written response required. ORIGE, B. M. Region 1. Philadelphia, Office of the Director. 79/12/07. 1p.
- 7912280196 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Resgonse Spectra." No written response required.
  ORIER, B. H. Region 1, Philadelphia, Office of the Director.
  79/12/13, 1p.
- DOCKET 50-364 JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 2
- A. Application/construction stage documents & correspondence
- 7912110011 Forwards NRC position on status & applicability to pending OL applications of results of TMT followup actions. Outlines addl short-term actions to be taken.
  VASSALLO, D. B. Division of Project Management. 79/09/27, 41pp.
- 7912110264 Discusses NRC plans to use generic analyses to develop sarly varification program to resolve ATMS issue for PMRs & BMRs. Buccess of program depends on industry response. Supports formation of owners groups to provide necessary info.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912270167 Forwards proposed Revision 2 to Reg Guide 1.97, "Instrumentation for Light Water Cooled Power Plants to Assess Plant & Environs Conditions During & Following Accident." Comments should be filed before 791214 meeting. VAROA, S. A. Assistant Director for Light Water Reactors, 79/11/23.
- --7912270172 Value/impact statement of proposed Revision 2 to Reg Guide 1.97, "Instrumentation for Light Water Cooled Nuclear Power Flants to Assess Plant & Environs Conditions During & Following Accident." Revision should be issued. # Assistant Director for Light Water Reactors. 79/10/15. 5pp.

- --791227017B Notification of 791214 meeting w/applicants to discuss proposed Rovision 2 to Reg Guide 1 97. "Instrumentation for Light Water Cooled Hurlear Plants to Assess Plant & Environs Conditions During & Following Accident." KINTNER.L.L. Light Water Reactors Branch 3. 79/11/19. 1p.
- C. Utility Environmental Report (ER), amends & correspondence
- 7912200095 Forwards IE Insp Repts 70-0135/79-06 & 70-0364/79-09 on 790305-0427 & notice of violation, Notice of violation withheld (ref 10CFR2, 790) MARTIN, M. G. Region 1. Philodeiphia. Safeguards Branch. 79/10/01.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & DL review Applicants required to make certain emergency arrangements w/state & local organizations & subnit emergency plans pur Reg Guide I. 101. VASSALLO, D. D. Division of Project Management. 79/11/21. App.
- 7912190550 Forwards updated schedulo for fire protection mods. CLAYTON.F. L. Alabama Power Co. 79/12/12. 3pp.
- H. General correspondence
- 7912280401 Comments on NUREG-0610: list of reportable unusual events should be reduced in scape to include only events consequential to public 2 should be clearly defined. THRASH.M. D. Alabama Power Co. 79/11/30. 2pp.
- M. Antitrust correspondence
- 79(2)90232 Forwards change of address for correspondence dealing w/util New address:1967 Sandalwood.Fort Collins.CO.80526.
  HJELMFELT.D.C. Goldberg.Fieldman & Letham.P.C. 79/11/26. 2pp.
- P. Operating license stage documents & correspondence
- 7912190556 Forwards addl info re description of auto initiation of auxiliary feedwater systim response to NRC 791210 request to Lessons Learned Task Force recommendations.

  CLAYTON,F. L. Alabama Power Co. 79/12/14. 7pp.
- G. Inspection reports. IE Bulletins & currespondence
- 7912070089 Forwards IE Insp Repts 90-349/79-32 & 50-344/79-14 on 790925-28. No noncompliance noted LENIS, R.C. Region 2. Atlanta. Reactur Operations Nuclear Support Branch 79/10/22. 2pp
- ---7912070097 IE Insp Hepts 90-348779-12 % 364779-14 on 790929-28 No noncompliance noted Major areas inspected operations review. LERs.open items (E circulars & mgt meeting on Unit 2. HARDIN A. K. DRADFORD) W Region 2. Atlanta. Office of the Director. MARTIN R. D Region 2. Atlanta. Reactor Operations Nuclear Support Branch 79/10/19 App
- 7912060097 Forwards IE Info Notice 79-12A. "Attempted Damage to New Fuel Assemblies." No specific action or response required. O'REILLY, J. P. Region 2. Atlanta. Office of the Director. 79/11/09. 2pp
- 7912100159 Forwards IE Info Natice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads " No response required. O'REILLY-J 9. Region 2. Atlanta, Office of the Director. 79/11/16. 1p
- 7912060604 Forwards LE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Dreak Detection Equipment on IMRs." No response required.

  O'REILLY.J.P. Region 2, Atlanta, Uffice of the Director.

  79/11/26. 1p.
- 7912110113 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. D'REILLY, J. P. Region 2. Atlanta. Office of the Director. 79/11/26. 1p

- 7912170006 Ack receipt of IE Insp Rept 50-364/79-16 on 791023-26.No proprietary info. CLAYTON, F. L. Alabama Power Co. 71/11/27. 1p.
- --7912170010 Forwards IE Insp Rept 50-364/79-16 on 791023-26.No noncompliance noted. MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/11/15. 2pp.
- --7912170016 IE Insp Rept 50-364/79-16 on 791023-26. No noncompliance noted Major areas inspected fire stop installations & case load forecast panel meeting.
  HUNT.M.D. Region 2. Atlanta, Office of the Director.
  BRYANT.J.C. Region 2. Atlanta Reactor Construction & Engineering Support Branch. 79/11/15. 3pp.
- 7912190371 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Dus During Operation." No written response required. O'REILLY.J.P. Region 2. Atlanta. Office of the Director. 79/11/30. 1p.
- 7912310284 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances: lOCFR21." No action required. BYREILLY.J.P. Region 2, Atlanta, Office of the Director. 79/12/06. 5pp.
- 7912200005 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. O'REILLY, J. P. Region 2. Atlanta, Office of the Birector. 79/12/07. 2pp.
- 7912210170 Responds to IE Bullotin 79-25 re failure of Wostinghouse BFD relays in safety-related sys. Westinghouse BFD/NBFD relays not used or planned for use. CLAYION, F. L. Alabama Fower Co. 79/12/07. 1p.
- 7912210010 Ack receipt of IE Insp Repts 50-348/79-38 & 50-364/79-10 on 791106-09. No proprietary info. CLAYTON, F. L. Alabama Power Co. 79/12/10. 1p.
- --7912210016 Forwards IE Insp Repts 50-348/79-38 & 50-364/79-18 on 791106-09 No noncompliance noted. MURPHY.C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/11/29. 2pp.
- --7912210021 IE Insp Repts 50-348/79-38 & 50-344/79-18 on 791106-09. No noncompliance noted Major areas inspected electrical cable & terminations work & work activities & employee concerns. GIBBONS, T. D. Region 2, Atlanta, Office of the Director. CONLON, T. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/11/28. App.
- 7912310015 Forwards response to IE Bulletin 79-IB. "Audibility Problems Encountered on Evacuation of Personnal from High Noise Areas." Audibility check of plant emergency evacuation alarm revealed numerous areas where alarm could not be heard. CLAYTON, F. L. Alabama Power Co. 79/12/12. 2pp.
- 7912280365 Forwards IE Info Notice 79-31, "Use of Incorrect Amplifited Response Spectra." No written response required.
  O'REILLY, J.P. Region 2: Atlanta, Office of the Director.
  79/12/13. 2pp.
- 7912280115 Forwards IE Circular 79-25, "Shock Arrestor Strut Assembly Interference," No written response required.
  O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
  79/12/20, 4pp.
- S. Reportable occurrences. LERs & related correspondence
- 7912130422 RD: on 791107.cooling towar B fire resulted in reduction of Pire protection tank levels. Tanks A & B fell to 120.000 gallons. Tank levels will be returned to min acceptable levels on 791107.
  HAIRSTON. W. G. Alabama Power Co. 79/11/07. 1p.
- 7912130621 RG: Westinghouse notified util of potential for P-4 permissive fattures to remain unidentified during performance of surveillance tests. All info not ovaluated. Details will be provided in followup rept. HAIRSTON.W.G. Alabama Power Co. 79/11/08. 2pp.

- DOCKET 50-366 EDWIN I. HATCH NUCLEAR PLANT, UNIT 2
  F. Security, medical, emergency & fire protection plans
- 7912280559 Notifies that NRC guides & criteria cannot be adequately incorporated into site emergency plan before 800101. Requests delay in submittal data for revised emergency plan until 800101. KELLY.R.J. Georgia Power Co. 79/10/20. 1p.
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives. Provides guidance for improving licensee emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.

  GRIMES, B. K. Emergency Preparedness Task Force. 79/11/23. 30pp.

#### Q. Adjudicatory correspondence

- 7912060120 Order dismissing proceeding. Intevenor Ceorgians Against Aucieur Energy participation in proceeding terminated. QRUBSHAN.H. Atomic Safety and Licensing Board Panel. 79/11/16. 2pp.
- H. General correspondence
- 7912100139 Requests that RJ Kelly replace CF Whitmer as addressee for all correspondence.
  EMRENGPERGER, W. Georgia Power Co. 79/08/22. ip.
- P. Operating license stage documents & correspondence
- 7912180083 Forwards request for addl info about containment purge & vent sys re util plans for unlimited purging.

  LAINAB.9. Plant Systems Branch. 79/11/06. Spp.
- 7912100189 Discusses NRC 791101 meeting w/representatives of N885 vendors & fuel suppliers re discussion of respective portions of ECCB evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl.
  EIBENHUT, D. O. Division of Operating Reactors. 79/11/09. 65pp.
- --7912100255 Responds to NRC 791101 request re noncompliance of Mestinghouse ECCS evaluation model under requirements of 10CFRSO App K. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants.
  ANDERSON, T. M. Westinghouse Electric Corp. 79/11/02. 4pp.
- --7912100330 Responds to NRC 791101 request re ORNL cladding swelling & rupture data. Review of analytical models & tests indicates compilance w/1005RBO App K. All GE specs for calculated peak cladding temp remain unchanged.

  EUCHHOLZ, R. H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data Concludes that data properly represented by fuel models used in vendor evaluation models t that analyses demonstrate all criteria of 10CFR50.46 satisfied.
  OHSCEY, O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/02. 5pp.
- --7912100456 Forwards addl info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. OMBLEY, 0.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/04. 22pp.
- 79:2100022 Discusses issuance of Amend 17 to License DPR-64.which authorized operation at 100% power.Max allowable fee already paid by util No addl fee required.
  MILLER.M.O. License Fee Management Branch. 79:11/13. ip.
- --7912100043 Forwards assessment of review costs for CP & OL actions, to aid in fee determination. W/o encl.
  3ERKOH.H.N. Office of Nuclear Reactor Regulation. 79/10/30. ip.
- --7912100004 Provides ACRB prof manpower expenditure estimates for CP & OL reviews. FRALEY.R.F. ACRB - Advisory Committee on Reactor Bafeguards. 78711701. 1p.
- --7912100079 Requests info re ACRS prof manthrs expended on review of each reactor Data for safety, environ & antitrust hearing concerns should be included Associated travel should not be shown.

  MILLER, W. O. License Fee Management Branch, 78/10/02. ip.

- 7912070497 Forwards Amend 13 to Liconse NPF-5, safety evaluation & notice of issuance & availability.
  IPPOLITO, T. A. Operating Reactors Branch 3. 79/11/23. 2pp.
- --7912070501 Amend 13 to License NPF-5, permitting continued operation & startup w/up to two vacuum breakers inoperable & w/three breakers inoperable if remaining breakers are operable at increased frequency IPPOLITO, T.A. Operating Reactors Branch 3. 79/11/23. 5pp.
- --7912070505 Safety evaluation supporting Amend 13 to License NPF-5.
  \* Office of Nuclear Reactor Regulation. 79/11/23. 1p.
- --7912070508 Notice of issuance & availability of Amend 13 to License NPF-5. 1PPOLITO.T.A. Operating Reactors Branch 3. 79/11/23. 2pp.
- 7912180661 Forwards FR notice of issuance of Amend 13 to License NPF-5.

  \* Operating Reactors Branch 3. 79/11/23. 1p.
- 7912190343 Forwards request for addl info to complete review of 781201, 790814 & 0908 requests for proposed lech Specs changes resettlement of Class I structures.

  1PPOLITO, T. A. Operating Reactors Branch 3. 79/11/27. App.
- 7912260131 Forwards safety evaluation of util request for change in Tuch Specs re adjustment of average power range monitor setpoints. LAINAG.O. Plant Systems Branch. 79/11/27. 2pp.
- ---7912260164 Safety evalution limiting util Tech Spec change request.

  Deviation from average power range monitor calibr procedures
  during full power inconsistent w/IEEE 279.

  \* Plant Systems Oranch 79/11/27. 2pp.
- 7912050150 Forwards Amend 4 to "Spent Fuel Pool Mod." included as part of 790709 application for expansion of spent fuel storage. Prepared in response to NRC 791101 request. KELLY.R.J. Georgia Power Co 79/11/30. 2pp.
- --7912050155 Amend 4 to "Spent Fuel Pool Mod." design rept & safety evaluation. \* Georgia Power Co. 79/11/30. 14pp
- 7912050533 Commits to addl confirmatory condensation oscillation tests in full-scale test facility, outlined in GE 79130 ltr re Mark I containment program Schudule for submittal of plant unique analysis will be provided following NRC resolution.

  KELLY,R. J. Georgia Power Co. 79/11/30. 2pp.
- 7912190164 Requests payment of Class I & Ill amend fees for review of 790817 security personnel training & qualification plan.
  DIGGS.R.M. License Fee Management Branch. 79/12/06. ip.
- 7912140321 Forwards rept "Adequacy of Station Electric Distribution Sys Voltage " KELLY,R.J. Georgia Power Co. 79/12/07. 2pp.
- --7912140326 "Adequacy of Station Electric Distribution Sys Voltage." \* Georgia Power Co 79/12/07. 87pp.
- 7912260083 Forwards criteria re electrical override/bypass for use in review of operating reactors. Naintaining purge valves closed does not resolve NRC concern w/purge valve circuitry. REID.R.W. Operating Reactors Branch 4. 79/12/11. 5pp.
- Q. Inspection reports: IE Bulletins & correspondence
- 7912040007 Forwards response to 790702 ltr & IE Bulletin 7B-14 reverification of selsmic analysis as modified by 790727.0815 & 0907 ltrs. Rept describes resolution of items in Unit 2 program. Verification of unit analysis delayed. Wo encl. WIDNER, N. A. Georgia Power Co. 797/11/08. 2pp.
- 7912110055 Forwards 790921 response to IE Bulletin 79-19, "Packaging of Low-Level Radwaste for Transport & Burial." WIDNER.W. A. Georgia Power Co. 79/11/08. ip.
- 7912060148 Forwards IE Info Notice 79-12A. "Attempted Damage to New Fuel Assemblies." No specific action or response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 79/11/09. 2pp.
- 7912100184 Forwards IE Info Notice 79-28, "Dverleading of Structural Elements Due to Pige Support Loads." No response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/16. lp.

- 7912110562 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required.
  O'REILLY, J. P. Region 2, Atlanta, Office of the Director, 79/11/16. 2pp.
- 79120A0617 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BURS." No response required.

  O'REILLY.J.P. Region 2. Atlanta, Office of the Director.
  79/11/26. 10.
- 7912110149 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/26. ip.
- 7912190454 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Hritten response required.
  0'AETLLYJ.P. Region 2, Atlanta, Office of the Director.
  79/11/30. 1p.
- 7912210177 Forwards corrected copy of 791130 ltr responding to IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High-Noise Areas." HIDNER.W.A. Georgia Power Co. 79/12/05. ip.
- --7912210181 Corrected copy of response to IE Bulletin 79-16. "Audibility Problems Encountered on Evacuation of Personnel from High-Noise Areas." Requests addl 90 days to complete installation of addl visual evacuation signals in identified areas. WIDNER, W. A. Georgia Power Co. 79/11/30. lp.
- 7912310301 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances.10CFR21." No action required.
  D'REILLY, J.P. Region 2. Atlanta, Office of the Director.
  79/12/06. 3pp.
- 7912200038 Forwards 1E Bulletin 79-28. "Possible Halfunction of Namco Model EAIBO Limit Switches at Elevated Temps." Action required. O'REILLY, J. P. Region 2. Atlanta. Diffice of the Birector. 79/12/07. 2pp.
- 7912280404 Forwards IE Info Notice 79-31. "Use of Incorrect Amplified Response Spectre." No written response required. O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 79/12/13. 2pp.
- 7912280141 Forwards IE Circular 79-25, "Shock Arrestor Strut Assembly Interference." No written response required. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 79/12/20. 4pp.
- R. Periodic operating reports & related correspondence
- 7912310432 Revised monthly operating rept for Jul 1979. ALLEN, P. B. Georgia Power Co. 79/08/08. 1p.
- --7912310433 Revised monthly operating rept for Aug 1979. ALLEN.P.B. Georgia Power Co. 79/08/08. ip.
- --7912310434 Revised monthly operating rept for Sept 1979. JOHNSON, G. L. Georgia Power Co. 79/10/24. 1p.
- 7912180438 Forwards monthly operating rept for Nov 1979. MANRY, W. Occresia Power Co. 79/12/10. 1p.
- ---7912180443 Monthly operating rept for Nov 1979. JOHNSON 9. L. Georgia Power Co. 79/12/10. 7pp.
- S. Reportable occurrences. LERs & related correspondence
- 7912050440 Forwards LER 79-119/03L-0. MANRY.M. Georgia Power Co. 79/11/28. 1p.
- --7912050445 LER 79-119/03L-0: on 791113, during surveillance procedurs HPN-2-3504, average power range monitor "F" insperable w/nine law power range monitor inputs. Caused by setpoint drift, Calibr performed.

  NIX:R.T. Georgia Power Co. 79/11/28. lp.
- 7912070445 Ferwards LER 79-120/03L-0. MANRY.M. Georgia Power Co. 79/11/29. 1p.

- --7912070448 LER 79-120/O3L-0: on 791113.emergency diesel generator tripped while performing manual start. Caused by high engine crankcase pressure due to ejector failure. Engine ejector cleaned & reinstalled. NIX.R.T. Georgia Power Co. 79/11/29. 2pp.
- 7912110368 Forwards LER 79-121/03L-0. MANRY, M. Georgia Power Co. 79/11/30. 1p.
- --7912110372 LER 79-121/O3L-0: on 791117, during return to full power, as average planar linear heat generation rate of 11.96 noted. Rapid increase in local thermal parameters caused by burnup of local Xenon produced by rod withdrawals. COOOIN.C.L. Georgia Power Co. 79/11/30. 2pp.
- 7912130384 Forwards LER 79-128/03L-0. KANRY,M. Georgia Power Co. 79/12/04. 1p.
- --7912130392 LER 79-128/03L-0: on 791128, drywell H & O concentration recorder became insperative. Caused by broken recorder drive string. String replaced & recorder returned to svc. NIX,R.T. Georgia Power Co. 79/12/06. 2pp.
- 7912130394 Forwards LER 79-127/03L-0. HANRY, M. Georgia Power Co. 79/12/06. 1p.
- --7912130400 LER 77-127/03L-0: on 791127, during HPCI steam line instrument functional test & calibr, low side setpoint found above Tach Spec max. Caused by setpoint drift. Instrument calibr & replaced on 791205 due to regular drift problems.
  NIX.R.T. Georgia Power Co. 79/12/06. 2pp.
- 7912130404 Forwards LER 79-124/03L-0.
  MANRY, M. Georgia Power Co. 79/12/06. 1p.
- --7912130408 LER 79-124/03L-0: on 791120, torus-drywell vacuum breaker valve 2748-F323E would not open Cause unknown due to inaccessibility of valve. Valve will be inspected & repaired as necessary during next cold shutdown.

  NIX.R.T. Georgia Power Co. 79/12/06. 2pp.
- 7912130412 Forwards LER 79-123/03L-0. MANRY, M. Georgia Power Co. 79/12/06. 1p.
- --7912130421 LER 79-123/03L-0: on 791117, plant svc water pump 2P41-C00H did not meet required flow. Pump declared inoperable, limiting condition for operation established Caused by normal wear on impeliers & seal rings. Pump rebuilt & returned to svc. NIX, R.T. Georgia Power Co. 79/12/06. 2pp.
- 7912140441 Forwards LER 79-122/03L-0. MANRY, M. Georgia Power Co. 79/12/07. 1p.
- ---7912140448 LER 79-122/03L-0: on 791117. while reactor at steady state of operation, do input breaker to 2R44-8003 tripped. Caused by failure of small control relay at LPCI converter. Relay replaced.
  NIX.R.T. Georgia Power Co. 79/12/07. 2pp.
- 7912180635 Forwards LER 79-125/03L-0.
  HANRY, M. Georgia Power Co. 79/12/12. Ip.
- --7912180642 LER 79-123/03L-0: on 791114, during routine review of previous radwaste discharges, discovered that on 791107, while at 0 MHt power-min required recirculation time not met on chemical waste sample tank A. Gaused by clogged inlet strainer. RODERS, W. H. Georgia Power Co. 79/12/11. Spp.
- 7912260221 Forwards LER 79-126/03L-0.
  MANRY, M. Georgia Power Co. 79/12/14. 1p.
- --7912260224 LER 79-126/O3L-O: on 791121, during plant svc water pump operability test, svc water pump failed to meet ABME Section II requirements. Caused by distortion of impeller by metal foreign object. Pump rebuilt.

  NIX,R.T. Georgia Power Co. 79/12/14. Gpp.
- 7912260265 Forwards LER 79+129/03L-0. MANRY.H. Georgia Fower Co. 79/12/14. ip.
- --7912260269 LER 79-129/03L-0: on 791129, while performing procedure HNP-2-3003, HPCI pump rated flow, thermal overloads of HPCI auxiliary oil pump breaker tripped while HPCI turbine being decreased. Caused by personnel error. Thermal overloads reset. NIX.R.T. Georgia Power Co. 79/12/14. 3pp.

- 7912310462 Forwards LER 79-130/03L-0.
  HANRY, M. Georgia Power Co. 79/12/26. ip.
- --7912310468 LER 79-130/03L-0: on 791205, during reactor water level instrument functional test & calibr, switch 2821-ND42A found out of Tech Spec limit Caused by instrument drift. Instrument calibr & tested.
  NIX:R.T. Georgia Power Co. 79/12/26. 2pp.

#### DOCKET 50-367 BAILLY GENERATING STATION

- A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATWS issue for PWRs & BWRs. Success of program depends on industry response. Supports forsætion of owners groups to provide necessary info. DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912170347 Forwards cooperative agreement between NRC & US Army Corps of Engineers re foundation review.
  GOLDBERG.S.C. Haaring Branch 2. FIN 8-6826. 79/11/15. ip.
- 7912190205 Lists documents provided to J Kubinski, US Army Corps of Engineers: re review of gile foundation.

  HELLER, L. M. Division of Site Sefety & Environmental Analysis.

  79/12/04. 2pp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review Applicants required to make certain emergency arrangements wistate & local organizations & submit emergency plans per Reg Quide 1, 101.

  VABSALLO, D. B. Division of Project Management. 79/11/21. App.
- 9. Adjudicatory correspondence
- 7912060028 Requests halt of facility const due to location in urban area. Certificate of Bvc encl. SCOTT. W. J. Illinois, State of. 79/11/13, 4pp.
- 7912130159 Forwards FR notice of opportunity for hearing on CP estension & newspaper advertisement re notice of opportunity for public participation in proposed NRC licensing action. RUBENBTEIN.L.S. Operating Reactors Branch 4. 79/11/21. 3pp.
- --7912130163 Notice of opportunity for hearing on CP extension Newspaper advantisements renotice of opportunity for public participation encl. RUBENSTEIN.L.S. Operating Reactors Branch 4. 79/11/26. 6pp.
- G. Inspection reports: IE Bulletins & correspondence
- 7912260167 Forwards IE Insp Rept 50-367/79-04 on 791015.No moncompilance noted, FIORELLI.0. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/11/15. 2pp.
- --7952260169 IE Insp Rept 50-367/79-04 on 791015 No noncompliance noted. Major areas inspected; project turnover. JABLONSKI, F. J., PHILLIPS, H. S., KNOP, R. C. Region 3, Chicago, Office of the Director. 79/11/07. 3pp.
- 7912050140 Forwards IE Circular 79-22: "Stroke Times for Power Operated Relief Valves." No response required.
  KEPPLER.J. 9. Region 3. Chicago. Office of the Director. 79/11/16.
- 7912100235 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. KEPPLER, J. 9. Region 3, Chicago, Office of the Director. 79/11/16, in.
- 7912110583 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coelant Sys Instrumentation During Operation." No specific action or response required.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912030308 Forwards IE Bulletin 79-26, "Boron Loss From BMR Control Blades." No response required.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/20.

- 791210043B Forwards IE Circular 79-24. "Proper Installation & Calibr of Core Byray Pipe Break Detection Equipment on BHRs." No written response required.

  KEPPLER.J. C. Region 3. Chicago. Office of the Director. 79/11/26.

  1p.
- 7912110265 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. KEPPLER, J. G. Region 3, Chicago: Office of the Director. 79/11/26.
- 7912110431 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofts copies of escalated enforcement correspondence sent by NRC to licensees.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/28.
- 7912190229 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation."
  No written response required.
  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/30.
  1p.
- 7912140090 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action or response required.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/12/06.
- 7912200130 Forwards IE Bulletin 79-28, "Possible Malfunction of Nanco Model EALBO Limit Switches at Elevated Temps." Action required. KEPPLER, J. G. Region 3, Chicago. Office of the Director. 79/12/10.
- R. Periodic operating reports & related correspondence
- 7912030186 Forwards well charts for 791031-1107, Bailly wells w/o recorders, pond lawels, pneumatic pressure transducers, water meter readings & USOB wells for 791107.

  BOHN, R. J. Northern Indiana Public Service Co. 79/11/16. 33pp.
- 7912030184 Forwards well charts for 791024-31, Bailly wells w/o recorders, pond levels, pneumatic pressure transducers & water meter readings for 791031. BOHN,R.J., Northern Indiana Public Service Co. 79/11/21. 31pp.
- 7912110364 Forwards well charts for 791107-15.Bailly wells w/o recorders for 791114, pand levels for 791114, pneumatic pressure tranducers for 791114 & water mater readings for 791115. BOHN, R. J. Northern Indiana Public Service Co. 79/11/26. 32pp.
- 7912110254 Forwards well charts for 791115-23. Bailly wells w/o recorders for 791123, pand levels for 791123, pneumatic pressure tranducers for 791121 & water meter readings for 791121.

  BOHN, R. J. Northern Indiana Public Service Co. 79/11/30. 32pp.
- 7912140234 Forwards 791123-28 well charts & 791128 facility wells w/o recorders, pand levels, pneumatic pressure transducers & water meter readings.

  BOHN, R. J. Northern Indiana Public Service Co. 79/12/07. 32pp.
- 7912310466 Forwards well charts for 791128-1205,8ailly wells w/o recorders, pond levels, pneumatic pressure transducers, water mater readings & USOB wells for 791205. BDHN,R.J. Northern Indiana Public Service Co. 79/12/14. 36pp.
- S. Reportable occurrences, LERs & related correspondence
- 7912140385 Ack receipt of 791105 ltr re possible multiple consecutive actuation of safety-relief valves. Will review final rept on matter upon receipt. FIORELI.0. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 79/11/27. 1p.
- U. Congressional/Executive Correspondence
- 7912200677 Responds to 791022 request for NRC views & opinions re proposed legislation to acquire add1 lands for IN Dunes Natl Lakeshore Park. Proposed acquisition has no effect on issuance or granting of facility parmits or licenses, QOBSICK/L.V. Office of the Executive Director for Operations, 79/10/25. 2pp.

- --7912200686 Responds to 791022 request for NRC views & opinions re proposed legislation to acquire addl lands for IN Dunes Natl Lakeshore Park.Proposed acquisition has no effect on issuance or granting of facility permits or licenses. 60891CK.L.V. Office of the Executive Director for Operations. 79/10/25. Spp.
- --7912200692 Requests NRC views & opinions re proposed legislation to acquire addl lands for IN Dunes Natl Lakeshore Park, FITHIAN F.J., BENJAHIN, A. House of Rep. 79/10/22. 3pp.
- 7912210002 Responds to 790809 ltr re alleged failure of util to comply w/federal regulations on plant siting General criterion re population levels were met Regulations were not violated by facility siting near Bethlehem Steel plant. GDSSICKLLV. Dffice of the Executive Director for Operations. 79/10/29. 3pp.

#### DOCKET 50-369 ARKANSAS NUCLEAR ONE. UNIT 2

- F. Security, medical, emergency & fire protection plans
- 7912180333 Notifies of delay in Plant Sys Branch Team 1 evaluations of facility fire protection sys. Outlines of assistance needed encl.

  LAINAS. G. Plant Systems Branch. 79/11/16. Spp.
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives Provides guidance for improving licensee emergency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.

  GRIMES, B. K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- 7912270070 Forwards comments re revisions & add1 info needed re facility safeguards contingency plan.Plan withheld (ref 100FR2.790).Wo encl. REID.R.W. Operating Reactors Branch 4. 79/12/10, 2pp.
- 7912310231 Forwards results of preliminary review of facility emergency plan. Encourages continued work w/state & local representatives to improve emergency preparedness. Emergency planning acceptance criteria encl. REID.R.W. Operating Reactors Branch 4 (Pre 790625). 79/12/17. 1200.
- 7912310471 Forwards draft emergency plansincorporating recommendations of NUREO-0578 & NUREO-0610 Emergency Planning Review Guidelines 1.Revision 1.re emergency planning acceptance criteria for licensed nuclear plants & Reg Quide 1.101.
  TRIMBLE, D. C. Arkansas Power & Light Co. 79/12/28. 2pp.

# G. Adjudicatory correspondence

- 791211003B Confirms receipt of encl 790329 petition to suspend GLs for all PMRs.Forwards FR notice indicating that petition will be treated in accordance w/10CFR2.206.

  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/11/23. 1p.
- --7912110126 Notice of request for action pursuant to 100FR2.206 re Environ Coalition on Nuclear Power 790329 petition requesting suspension of all OLs for PMRs. MULLER.D.R. Office of Nuclear Reactor Regulation, 79/11/23.

#### I. Financial information

- 7912050449 Forwards util statement of source of funds.for Oct 1978-Oct 1979.

  LANGSTON, N. Arkansas Power & Light Co. 79/11/29. 1p.
- J. Insurance & indemnity information
- 7912070387 Forwards surety bond to meet requirements re Price-Anderson Act. HARTON: J. J. Arkansas Power & Light Co. 79/12/03. 3pp.
- P. Operating license stage documents & correspondence
- 7911090248 "Summary of Operating Experience W/Recirculating Steam Cemerators." EISERMUT, D. Q. Division of Operating Reactors. NUREG-0523. 79/01/31. 89pp.

- 7912100187 Discusses NRC 791101 meeting w/representatives of NBSS vendors & fuel suppliers re discussion of respective partions of ECCS sealuation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EISENHUT.D.O. Division of Operating Reactors. 79/11/09. 45pp.
- ~-7912100295 Responds to NRC 791101 request re noncompliance of Westinghouse ECCS evaluation model under requirements of 10CFR50 App K. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants.

  ANDERSON T. M. Westinghouse Electric Corp. 79/11/02. 4pp.
- --7912100330 Responds to NRC 791101 request re ORNL cladding swelling & rupture data. Review of analytical models & tests indicates compliance w/10CFR50 App K. All GE specs for calculated peak cladding temp remain unchanged.

  BUCHHOLZ, R. H. General Electric Co. 79/12/07. 2pp.
- --7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of iOCFR50.46 satisfied.

  CMSLEY,0.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/02. 5pp.
- --7912100496 Forwards addl info re evaluation of impact of NRC proposed rupture/blockage model used in vendor evaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. DMSLEY.6.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/04. 22pp.
- 7912100022 Discusses issuance of Amend 17 to License DPR-64, which authorized operation at 100% power, Max allowable fee already paid by util No addl fee required.

  MILLER, W. O. License Fee Management Branch. 79/11/13. 1p.
- --7912100043 Forwards assessment of review costs for CP & OL actions, to aid in fee dotermination. W/o encl. BERKOW, H. N. Office of Nuclear Reactor Regulation. 79/10/30. 1p.
- --7912100064 Provides ACRS prof manpower expenditure estimates for CP & OL reviews. FRALEY.R.F. ACRS - Advisory Committee on Reactor Safeguards. 78/11/01. 1p.
- ---7912100079 Requests info re ACRS prof man-hrs expended on review of each reactor. Data for safety, environ & antitrust hearing concerns should be included. Associated travel should not be shown.

  MILLER, M. D. License Fee Management Branch, 78/10/02. ip.
- 7912040187 Requests Tech Specs change re inadvertent actuation of containment spray, submitted as Class III amend.
  CAVANAUGH.W. Arkansas Power & Light Co. 79/11/19. 2pg.
- --7912040195 Tech Spots Figure 3.6-1 re containment internal pressure vs containment average air temp. \* Arkansas Power & Light Co. 79/11/19. ip.
- 7912180198 Forwards request for add1 info to complete evaluation of electrical override/bypass aspects of containment purge sys.

  LAINAB.O. Plant Systems Branch. 79/11/19. 2pp.
- 7912040181 Responds to NRC 791004 itr re schedules for completing licensing conditions. Tech Specs revision submitted 791127.

  Description of long-term mods & Tach Specs for surveillance requirements due 90 days before refueling outage.

  TRIMBLE, D. C. Arkansas Power & Light Co. 79/11/27. 2pp.
- 7912070424 Requests change to License NPF-6 Tech Specs increasing trip setpoint by 23 psi.Class III amend fee & affidavit encl. CAVANAUOH, W. Arkansas Power & Light Co. 79/11/27, 2pp.
- --7912070428 Proposed Tech Spec Table 2.2-1 for License NPF-6, increasing trip setpoint by 23 psi.

  \* Arkansas Power & Light Co. 79/11/27. 2pp.
- 7912040459 Forwards plot of projected operating cycles per NRC request. One oversized page available in Central Files only, TRIMBLE.D.C. Arkansas Power & Light Co. 79/11/28. 1p.
- 7912120534 Forwards request for add1 info to complete review of GA program.
  HAMSS,W.P. Guality Assurance Branch. 79/12/05. 3pp.

- 7912130249 Forwards revision to 791120 ltr re implementation schedule for Lessons Learned Task Force short-term recommendations. Requests expedited concurrence w/method of compliance to NUREQ-0578.
  CAYANAUOH, W. Arkansas Power & Light Co. 79/12/05. 22pp.
- 7912140327 Forwards revision of selected provisions of 791120 response to TMI Lessons Learned Task Force recommendations. Sequential shutdowns proferred to concurrent. Implementation schedule encl.

  CAVANAUGH. W. Arkansas Power & Light Co. 79/12/05. 21pp.
- 7912200574 Notifies that processing & issuance of OL exceeded required fee. Since max fee paid no other charges are forthcoming.
  MILLER, H. D. License Fee Management Branch. 79/12/06. 1p.
- 7912270119 Notifies of completion of util evaluation re mod to hot leg temp measuring instrumentation to accommodate anomalous hot leg temp indications. Mod not unreviewed safety question as defined in 10CFR30. 39. W/791120 ltr re program criteria. 0AMHILL.W.P. Assistant Director for Operating Reactor Projects (Pre 791030). 79/12/07. 1p.
- 7912170312 Forwards Suppl 1 to startup rept for period ending 791031. TRIMBLE.D.C. Arkansas Power & Light Co. 79/12/11. 1p.
- --7912170315 Suppl 1 to startup rept for period ending 791031. \* Arlansas Power & Light Co. 79/10/31. 49pp.
- 7912280616 Forwards revision to NRC 791106 Additional Short-Term Recommendation 2.Endurance tests for auxiliary feedwater pumps are shortened from 72-h to 48-h. REID.R.W. Operating Reactors Branch 4, 79/12/13, 4pp.
- 7912210342 Discusses proposed shutdown to implement short-term items of NUREO-0378. Shutdown schedule undergoing mod. Units 1 & 2 will be shut down 791231 & 800131. respectively & will not be restarted until items are implemented.

  CAYANAUQH, W. Arkansas Power & Light Co. 79/12/17. 2pp.
- 7912260239 Forwards Pages S1-47,81-48,81-A1 & S1-A2 to 791211 suppl to startup rapt. TRIMBLE,D.C. Arkansas Power & Light Co. 79/12/17, 1p.
- --7912260241 Pages 61-47,81-48,81-A1 & 81-A2 to 791211 suppl to startup rept. \* Arkenses Power & Light Co. 79/12/17. 4pp.
- 7912310456 Forwards Pour pages omitted from 791211 submittal of Suppl 1 to 790713 startup rept.
  TRIMBLE.D.C. Arkansas Power & Light Co. 79/12/17. 1p.
- --7912310461 Four pages omitted from 791211 submittal of Suppl 1 to 790913 startup rept.

   Arkansas Power & Light Co. 79/12/17. 4pp.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912170134 Responds to IE Bulletin 79-23. "Potential Failure of Emergency Diesel Generator Field Exciter Transformer."
  Connections between low kVA rated transformers & high KVA rated emergency generators have not been made.
  TRIMBLE.D.C. Arkenses Power & Light Co. 79/10/03. 2pp.
- 7712140233 Responds to IE Bulletin 79-13. "Cracking in Feedwater Sys-Piping." Completed volumetric examination of nozzle-to-transition piece & transition piece-to-piping welds on steam generators. No cracks or code discontinuities identified. TRIMBLE.D. C. Arkansas Power & Light Co. 79/10/18. ip.
- 7912050326 Forwards IE Insp Repts 50-313/79-21 & 50-368/79-20 on 790909-1005 & notice of violation.

  MADBEN.O.L. Region 4. Dallas, Reactor Operations Nuclear Support Branch. 79/10/23. 2pp.
- --7912050333 Notice of violation from insp on 790909-1005.

  \* Region 4. Dallas, Office of the Director. 79/10/23. ip.
- --7912030342 IE Insp Repts 50-313/79-21 & 50-368/79-20 on 790909-1005. Noncompliance noted: outdated G lists. JOHNSON, W. D., WEBTERMAN, T. F. Region 4, Dallas, Defice of the Director. 79/10/23. 11pp.
- 7912140103 Forwards IE Bulletin 79-17, Revision 1, "Pipe Cracks in Stagmant Borated Water Sys at PWR Plants," Written response required.

  SEYFRIT. K. V. Region 4, Dailas, Office of the Director. 79/10/29.

- 7912120561 Forwards IE Bulletin 79-25, "Failures of Westinghouse BFD Relays in Safety-Related Sys." Action required.
  SEYFRIT.K.V. Region 4, Dallas. Office of the Director. 79/11/02.
- 7912190033 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No written response required.
  SEYFRIT.K.V. Region 4, Dallas. Office of the Director. 79/11/16 ib.
- 7912120550 Forwards IE Bulletin 79-24, "Horon Loss From BWR Control Blades." No response required. SEYFRIT.K.V. Region 4, Dallas, Office of the Director. 79/11/20.
- 7912110467 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sent by NRC to licensees.

  SEYFRIY.K. V. Region 4, Dallas, Office of the Director. 79/11/26.
- 7912190169 Forwards IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Written response required.

  SEYFRIT,K. V. Region 4, Dallas. Office of the Director. 79/11/30.
- 7912070446 Responds to NRC ltr re hot leg temp anomaly.Reactor vessel internals inspected on 791017 did not reveal cause of effect of temp switching anomaly.Describes actions planned if test program results call for action criteria.

  TRIMBLE.D.C. Arkansas Power & Light Co. 79/12/03. 13pp.
- --7912070447 Post-insp restart testing program.
  \* Arkansas Power & Light Co. 79/12/03. 7pp.
- R. Periodic operating reports & related correspondence
- 7912170196 Forwards monthly operating rept for Nov 1979. TRIMBLE.D.C. Arkensas Power & Light Co. 79/12/14. ip.
- --7912170203 Monthly operating rept for Nov 1979. PENDERGRAFT.R. Arkansas Pawer & Light Co. 79/12/14. 1ipp.
- 7912270278 Forwards monthly operating rept correction for Nov 1979. TRIMBLE.D.C. Arkansas Power & Light Co. 79/12/17. lp.
- --7912270282 Monthly operating rept correction for Nov 1979. PENDERGRAFT, R. Arkansas Power & Light Co. 79/12/14. ip.
- S. Reportable occurrences, LERs & related correspondence
- 7912310069 PNO-IV-79-009: on 791016, reporter interviewed plant manager re repts of radioactive leakage instances: 790926; leakage past packing on two primary sys valves into bldg & 791012, shutdown cooling heat exchanger leak to svc water sys. WEGTERMAN, T. F., MADEEN, O.L. Region 4, Dallas, Office of the Director. 79/10/17. 1p.
- 7912310084 FNO-IV-79-011: on 791018, during surveillance testing, major bearing damage encountered in emergency diesel generator 2.
  Reactor shut down for examination of core internals.
  Repairs will extend outage for undetermined period.
  WEBTERMAN.T.F., MADSEN.G.L.
  Director, 79/10/18. 1p.
- 7912170275 Forwards LER 79-087/03L-0 & updated LER 79-039/03X-1. TRIMBLE, D. C. Arkansas Power & Light Co. 79/12/04. 1p.
- --7912170279 LER 79-087/03L-0:on 791114, during Mode 5 operation, leakage discovered in socket weld on low pressure safety injection flow orifice valve. Caused by mechanical fatigue failure at weld. Injection sys out of svc 3-h during repair. PENDERGRAFT.R. Arkansas Power & Light Co. 79/12/06. lp.
- --7912170281 LER 79-039/03X-1:on 790527, during NRC audit of category E valve positions in Mode 3 operation, low pressure safety injection discharge header valve 281-5091-3 found closed. Caused by operator error. Valve modified.

  BHIVELY, C. N. Arkansas Power & Light Co. 79/12/06. ip.
- 7912310383 Forwards LERs 79-088/03L-0,79-089/03L-0,79-090/03L-0,79-091/03L-0 & 79-092/03L-0.
  TRIMBLE D. C. Arkansas Power & Light Co. 79/12/21. 1p.

- --7912310384 LER 79-088/03L-0: on 791122 during Mode 3 operation, emergency feedwater flow control valve 2CV-1025-1 failed to close on demand from control room. Caused by valve operator hydraulic pressure being low. Sys vented.

  SHIVELY.C.N. Arkansas Power & Light Co. 79/12/21. 1p.
- ---7912310393 LER 79-089/03L-0: on 791124, during Mode 3 operation, emergency feedwater flow control valve 2CV-1025-1 failed to close on demand from control room. Caused by trash in valve operator hydraulic says & hydraulic snubber out of adjustment.

  SHIVELY.C.N. Arkansas Power & Light Co. 79/12/21. 1p.
- ---7912310399 LER 79-090/03L-0: on 791125, during Mode 3 operation, emergency feedwater flow control valve 2CV-1025-1 failed to close on demand from control room. Caused by valve operator hydraulic sys being low on fluid Sys filled.

  SHIVELY, C. N. Arkansas Power & Light Co. 79/12/21. 1p.
- --7912310404 LER 79-091/03L-0: on 791126, during Mode 3 operation, dissolved oxygen concentration of reactor coolant sys found greater than 0.1 ppm but less than 0.2 ppm. Caused by large RCS deboration.
  PENDERORAFT, R. Arkansas Power & Light Co. 79/12/21. 1p.
- --7912310409 LER 79-092/03L-0: on 791201, during Mode 2 operation, emergancy faudwater flow control valve 2CV-1025-1 failed to close on demand from control room. Caused by lack of hydraulic pressure due to low fluid level in accumulator.

  SHIVELY, C. N. Arkansas Power & Light Co. 79/12/21. Ip.
- DOCKET 50-349 WILLIAM B. MCGUIRE NUCLEAR STATION, UNIT 1

  A. Application/construction stage documents & correspondence
- 790B010339 Notifies of status of rept on reactor cavity annulus seal.
  Most PHR users remove ring during normal operation. Others
  store seal ring in raised position during normal operation.
  LAINAS.G. Plant Systems Branch (Pre 791030). 79/07/05. 7pp.
- 7912110011 Forwards NRC position on status & applicability to pending OL applications of results of TMI followup actions. Dutlines addl short-term actions to be taken.
  VASSALLO.D. D. Division of Project Management. 79/09/27. 41pp.
- 7912110264 Discusses NRC plans to use generic analyses to develop early varification program to resolve ATMS issue for PMRs & BMRs.
  Success of program depends on industry response. Supports formation of owners groups to provide necessary info.
  DENTON. H. R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.
- 7912070004 Requests distribution of encl memorandum to board notification svc lists.

  VARGA B. A. Assistant Director for Light Water Reactors. 79/11/08.
  3pp.
- 7912110007 Forwards proposed Revision 2 to Reg Quide 1.97.
  "Instrumentation for Light Water Cooled Nuclear Power Plants
  to Assess Plant & Environ Conditions During & Following
  Accident." Requests comment.
  VARGA: S.A. Assistant Director for Light Water Reactors. 79/11/23.
  Jpp.
- 7912040512 Requests that completion dates specified for CPPR-83 be extended to 801231 & CPPR-04 to 820731.
  THIES,A.C. Duke Power Co. 79/11/30. 5pp.
- 7912270092 Responds to 791108 ltr expressing concern re delays in licensing of facilities. Policy statement re adaptation of licensing procedures to include recommendations of TMI task forces will be issued shortly.

  HENDRIE, J. M. Commission. 79/12/07. 1p.
- 7912310356 Notification of 800108 meeting w/utils in Bethesda,MD to discuss info request re adequacy of equipment qualification.
  UNGARD,A.R. Power Systems Branch. 79/12/11. 3pp.
- 7912210151 Forwards proprietary & nonproprietary response to NRC 790911 ltr re fuel assembly guide thimble tuke wear. Application & affidavit for withholding proprietary info encl. Document withheld (ref 10CFR2. 790).
  PARKER, W. D. Duke Power Co. 79/12/14. 34pp.
- 7912270352 Forwards add1 info re steam generator level measurement errors in response to NRC 791015 request. Info pertains to measuring system led heatup water density changes, steam generator narrow range level & emergency procedures. PARKER, W. D. Dute Power Co. 79/12/18. 7pp.

- 7912270327 Forwards response to NRC 791112 ltr re environ qualification of reactor coulant temp detectors & containment pressure transmitters. Calculation results encl.
  PARKER.H.O. Duke Power Co. 79/12/19. 4pp.
- 7912310460 Notifies of completion of review of procedures & mechanisms for routing & installing safety-related cables in response to NRC 791130 request Cables are installed according to FBAR separation criteria.
  PARKER. H. O. Duke Power Co. 79/12/26. 2pp.
- F. Security, medical, emergency & fire protection plans
- 7809290054 Summary of fire protection appeal meeting on 780414.

  Meeting inconclusive, so official summary not prepared.

  BIRKEL.R. Light Water Reactors Branch 2. 78/09/26. 2pp.
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review. Applicants required to make certain umergency arrangements w/state & local organizations & submit emergency plans per Reg Guide i. 101. VASSALLG, D.B. Division of Project Management. 79/11/21. App.
- 7912210171 Forwards final version of "Fire Gualification Test on Bilicone Foam Floor Penetrating Seals." PARKER.H.O. Duke Power Co. 79/12/14. 1p.
- I. Financial information
- 7912270577 Forwards duplicate copies of util 790321 guarantee of retrospective premiums in response to NRC 791210 request. WHITLEY.H.D. Duke Power Co. 79/12/20, 1p.
- ~~7912270585 Requests approved guarantee of payment of deferred premiuss for 1979. SALTHAN.J. Antitrust & Indomnity Group. 79/12/10. 15.
- P. Operating license stage documents & correspondence
- 7912200574 Discusses separation of electrical equipment & sys at plants.Forwards procedures for conducting electrical separation field audit.

  BAER.R.L. Light Water Reactors Branch 2. 79/11/30. 4pp.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912040010 Responds to IE Bulletins 78-12,78-12A & 78-12B re weld eatl documentation. Info pertinent to McQuire Unit 2 reactor vessel included in RDM rept which was submitted on 791029. Hestinghouse transmittal ltr encl. PARKER.H.O. Duke Power Co. 79/11/07. 2pp.
- --7912040014 Forwards rept "Weld Matl Documentation of Eleven Reactor Pressure Vessels Fabricated by RDM for Mestinghouse." in response to IE Dulletin 78-12. Complete records search made & no atypical weld matl found. W/o encl.
  ANDERBON. T. M. Westinghouse Electric Corp., PWR Systems Div. 79/10/29. ip.
- 7912060128 Forwards IE Info Notice 79-12A, "Attempted Damage to New Fuel Assemblies." No specific action or response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director, 79/11/09. 2pp.
- 7912100149 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. O'REILLY.J.P. Region R. Atlanta, Office of the Director. 79/11/16. 1p.
- 7912110345 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. O'RETLLV.J.P. Region 2, Atlanta, Office of the Director. 79/11/16. 2pp.
- 7912050518 Ack receipt of 1E Insp Rept 50-369/79-38 on 791022-23, No proprietary info.
  PARKER, N. O. Duke Power Go. 79/11/23, 1p.
- --7912050528 Forwards 1E Insp Rept 50-369/79-38 on 791022-23.No noncompliance noted. MURPHY.C.E. Region 2, Atlanta. Reactor Construction & Engineering Support Branch. 79/11/05. 2pp.

- --7912050532 IE Insp Rept 50-369/79-38 on 791022-23. No noncompliance noted. Major area inspected; steam generator feedwater line radiography.

  GROWLEY, B. R. Region 2. Atlanta. Office of the Director. HERDI.A.R. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 79/11/01. 3pp.
- 7912060607 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No response required.
  0'REILLY.J.P. Region 2, Atlanta, Office of the Director.
  79/11/26. ip.
- 7912:10:34 Forwards IE Circular 79-23. "Motor Starters & Contactors Failed to Operate." No response required. O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 79/11/26. 1p.
- 7912050182 Ack receipt of 791109 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-369/79-29.
  LEWIS.R.C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 79/11/28. 1p.
- ---791205018B Responds to NRC 791019 ltr re violations noted in IE Insp Rept 30-259/79-29. Corrective actions: re-examined valve lineup & verified that remaining valves correctly aligned. No proprietary info. PARKER, M. D. Duke Power Co. 79/11/09. 2pp.
- --7912060192 Forwards IE Insp Rept 50-369/79-29 on 790816-23 & notice of violation.
  LEHIB.R.C. Region 2, Atlanta: Reactor Operations Nuclear Support Branch. 79/10/19. 2pp.
- --7912060197 Notice of violation from insp on 790816-23.

  Region 2, Atlanta, Office of the Director. 79/10/10. ip.
- --7912060215 IE Insp Rept 50-369/79-29 on 790816-23.Noncompliance noted: failure to follow valve alignment procedure.
  WHITENER, H. L., JOHNBON, A. H. Region 2, Atlanta, Office of the Director. BURNETT, P. T. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/10/18, 5pp.
- 79:2190386 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation." Written response required. 0.4EILLY.J.P. Region 2, Atlanta, Office of the Director. 79/11/30. 1p.
- 7912310293 Forwards IE Info Notice 79-30. "Reporting of Defects & Noncompliances, 100FR21." No action required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 79/12/06. Spp.
- 7912200026 Forwards IE Bulletin 79-28, "Possible Halfunction of Namco Model EAIBO Limit Switches at Elevated Temps." Action required. 8/REILLYJ.P. Region 2, Atlanta, Office of the Director. 79/12/07. 2pp.
- 7912280159 Ack receipt of IE Insp Rept 50-369/79-36 on 791009-11. No proprietary info. PARMER. H. D. Duke Power Go. 79/12/13. 1p.
- ---7912280163 Forwards IE Insp Rept 50-369/79-36 on 791009-11.No noncompliance noted. LEWIG.R.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 79/11/23. 2pp.
- --7912280174 IE Insp Rept 50-369/79-36 on 791009-11 No noncompliance noted Major areas inspected preoperational test procedures, completed preoperational test package raview & followup on previous insp findings, DYER, J. A. Region 2, Atlanta, Reactor Operations Nuclear Support Branch, DONAT, T. J., MOON, B. T. Region 2, Atlanta, Office of the Director, 79/11/23, 7gp.
- 7912280377 Forwards IE Into Notice 79-31. "Use of Incorrect Amplified Response Spectra." No written response required. O'REILLY, P. Region 2, Atlanta, Dffice of the Director. 79/12/13. 2pp.
- 7912280129 Forwards IE Circular 79-25, "Bhock Arrestor Strut Assembly Interference." No written response required.

  O'REILLY, J. P. Region 2, Atlanta, Office of the Director.

  79/12/20. 4pp.

- S. Reportable occurrences. LERs & related correspondence
- 7911160464 Forwards Significant Deficiency Rept 369-370/79-10. PARKER, W. O. Duke Power Co. 79/11/08. 1p.
- 7912050592 Forwards deficiency rept SD 349-370/79-11 re Westinghouse 7300 Series process I & C card technical problems. PARKER, W. O. Duke Power Co. 79/11/29. 1p.
- --7912030594 Deficiency rept. SD 369-370/79-11 re Westinghouse 7300 Beries process comparator card technical problems. Caused by design deficiencies. Insp of cards conducted & cards being repaired. Corrective actions to be completed by 800430.

  \* Duka Power Co. 79/11/29. 7pp.
- 7912050503 Suppl 1 to Deficiency Rept 369-370/79-06 re personnel air lock door seal problem. Submits details on corrective actions taken. Actions for Unit 1 will be completed a personnel air lock door seals reinstalled by 800130. PARKER, W. D. Duke Power Co. 79/11/30. 10pp.
- 7912190710 Significant Deficiency Rept 369-370/79-06, suppl re personnel air lock door seals. All penetrating bolt holes & holes deviating from perpendicular re more than 3 degrees were plugged drilled & tapped. Action completed by 800131. PARKER, H. O. Duke Power Co. 79/11/30. 2pp.
- --7912190713 Shop insp procedure for air lock doors, Revision O. \* W. J. Woolley Co. 79/10/10. Bpp.
- POCKET 50-370 WILLIAM B. MCOUIRE NUCLEAR STATION, UNIT 2

  A. Application/construction stage documents & correspondence
- 7912110011 Forwards NRC position on status & applicability to pending OL applications of results of TMI followup actions. Gutlines addl short-term actions to be taken.

  VABBALLO, D. B. Division of Project Management. 79/09/27. 41pp.
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATHB issue for PHRs & BHRs. Buccess of program depends on industry response. Bupports formation of owners groups to provide necessary info. DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.
- 7912070004 Requests distribution of encl memorandum to board notification svc lists.
  VAROA, B. A. Assistant Director for Light Water Reactors. 79/11/08.
- 7912110007 Forwards proposed Revision 2 to Reg Guide 1.97.
  "Instrumentation for Light Water Cooled Nuclear Power Plants to Assess Plant & Environ Conditions During & Following Accident." Requests comment.
  VAROA:B.A. Assistant Director for Light Water Reactors. 79/11/23.
- 7912040512 Requests that completion dates specified for CPPR-83 be extended to 801231 & CPPR-84 to 820731.
  THIES, A. C. Duke Power Co. 79/11/30. 5pp.
- 7912200874 Discusses separation of electrical equipment & sys at plants. Forwards procedures for conducting electrical separation field audit.

  BAER.R.L. Light Water Reactors Branch 2. 79/11/30. App.
- 7912270092 Responds to 791108 ltr expressing concern re delays in licensing of facilities. Policy statement re adaptation of licensing procedures to include recommendations of TMI task forces will be issued shortly.

  HENDRIE, J. M. Commission. 79/12/07. 1p.
- 7912210151 Forwards proprietary & nonproprietary response to NRC 790911 ltr rs fuel assembly guide thimble tube wear. Application & affidavit for withholding proprietary info enci. Document withheld (ref 10CFR2. 790). PARKER, M. C. Duke Power Co. 79/12/14. 34pp.
- 7912270352 Forwards add1 info re steam generator level measurement errors, in response to NRC 791015 request. Info pertains to measuring sys, ref leg heatup, water density changes, steam generator narrow range level & emergency procedures. PARKER, W. O. Duke Power Co. 79/12/18. 7pp.
- 7912270327 Forwards response to NRC 791112 ltr re environ qualification of reactor collent temp detectors & containment pressure transmitters. Calculation results encl. PARKER, M. C. Duke Power Co. 79/12/19. App.

- 79(23)0460 Notifies of completion of review of procedures & mechanisms for routing & installing safety-related cables, in response to NRC 791(30 request Cables are installed according to FSAR separation criteria.

  PARKER, W. O. Duke Power Co. 79/12/26. 2pp.
- F. Security, medical, emergency & fire protection plans
- 7807290054 Summary of fire protection appeal meeting on 780414. Meeting inconclusive so official summary not prepared. BIRKELAR. Light Water Reactors Dranch 2. 78/09/26. 2pp.
- 7912040471 Forwards info re upgraded emergency plans to plants under const & DL review. Applicants required to make cortain emergency arrangements w/state & local organizations & submit emergency plans per Reg Quido 1.101. VASSALLO, D. D. Division of Project Management. 79/11/21. App.
- 7912210171 Forwards final version of "Fire Qualification Test on Silicone Foam"Floor Penetrating Seals."
  PARKER, W. G. Duke Power Co. 79/12/14. lp.
- I. Financial information
- 7912270577 Forwards duplicate copies of util 790321 guarantee of retrospective premiums. In response to NRC 791210 request. WHITLEY, H. D. Duke Power Co. 79/12/20. 1p.
- ---79122705B5 Requests approved guarantee of payment of deferred premiums for 1979. SALTZHAN.J. Antitrust & Indemnity Group. 79/12/10. 1p.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912040010 Responds to IE Bulletins 78-12.78-12A & 78-12B re weld math documentation. Info pertinent to McGuire Unit 2 reactor vessel included in RDM rept which was submitted on 791029. Westinghouse transmittal itr encl. PARKER.W. O. Duke Power Co. 79/11/07. 2pp.
- --7912040014 Forwards rept "Weld Matl Documentation of Eleven Reactor Pressure Vessels Fabricated by RDM for Westinghouse." in response to IE Bulletin 78-12. Complete records search made & no atypical weld matl found. W/o encl. ANDERSON, T. M. Westinghouse Electric Corp., PWR Systems Div. 79/10/29. 1p.
- 7912050128 Forwards IE Info Notico 79-12A, "Attempted Damage to New Fuel Assemblies." No specific action or response required. D'REILLY, J.P. Rogion 2, Atlanta, Office of the Director. 79/11/09. 2pp.
- 7912100169 Forwards IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads." No response required. G'RESLLY, J.P. Region 2. Atlanta. Office of the Director. 79/11/16. 1p.
- 7912110545 Forwards IE Info Notice 79-29. "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 79/11/16. 2pp.
- 7912110220 Ack receipt of 791019 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-370/79-18.

  MURPHY.C.E. Region 2. Atlanta, Reactor Construction & Engineering Eupport Branch. 79/11/23. ip.
- ---7912110229 Responds to NRC 790928 ltr re violation noted in IE Insp Rept 50-370/79-18 Corrective actions: sketches made of electrical bracing on safety-related motors & will be reviewed to assure adequacy. PARKER.W.O. Duke Power Co. 79/10/19. 2pp.
- ---7912110233 Forwards IE Insp Rept 50-370/79-18 on 790904-07 & notice of violation. MURPHY,C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/09/28. 2pp.
- --7912110238 Notice of violation from insp on 790904-07.

  \* Region 2. Atlanta, Office of the Director. 79/09/27. 1p.
- --7912110247 IE Insp Rept 50-370/79-18 on 790904-07 Noncompliance noted: mod to safety-related motors w/o approved drawing.
  OIBBENS.T.D., CONLON.T.E. Region 2. Atlanta, Office of the Director. 79/09/27. 3pp.

- 7912060607 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/11/26. ip.
- 7912110134 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/26. 1p.
- 7912190392 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Dus During Operation." No written response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/11/30. 1p.
- 7912310293 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances,10CfR21." No action required.
  D'REILLY, J. P. Region 2, Atlanta, Office of the Director.
  79/12/06. 5pp.
- 7912200026 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. 0'REILLY, J. P. Region 2, Atlanta, Office of the Director, 79/12/07. 2pp.
- 7912280377 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required. D'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/12/13. 2pp.
- 7912280129 Forwards IE Circular 79-25, "Shock Arrestor Strut Assembly Interference." No written response required.
  O'REILLY,J.P. Region 2, Atlanta, Office of the Director.
  79/12/20. 4pp.
- S. Reportable occurrences: LERs & related correspondence
- 7912050592 Forwards deficiency rept 8D 369-370/79-11 re Westinghouse 7300 Series process I & C card technical problems. PARKER, M.D. Duke Power Co. 79/11/29. 1p.
- --7912050594 Deficiency rept. 8D 369-370/79-11 re Westinghouse 7300 Series process comparator card technical problems. Caused by design deficiencies. Insp of cards conducted & cards being repaired. Corrective actions to be completed by 800430.

  \* Duke Power Co. 79/11/29. 7pp.
- 7912050503 Suppl 1 to Deficiency Rept 3A9-370/79-06 re personnel air lock door seal problem Submits details on corrective actions taken. Actions for Unit 1 will be completed & personnel air lock door seals reinstalled by 800130. PARKER.W. D. Duke Power Go. 79/11/30. 10pp.
- 7912190710 Significant Deficiency Rept 369-370/79-06. suppl re personnel air lack door seals All penetrating balt hales & hales deviating from perpendicular re more than 3 degrees were plugged, drilled & tapped, Action completed by 800131. PARKER, W. D. Duke Power Co. 79/11/30. 2pp.
- ~~7912190713 Shop insp procedure for air lock doors.Revision 0. \* W. J. Waolley Co. 79/10/10. Spp.
- DOCKET 50-373 LABALLE COUNTY STATION, UNIT 1
- A. Application/construction stage documents & correspondence
- 7912110011 Forwards NRC position on status & applicability to pending DL applications of results of TMI followup actions Outlines addl short-term actions to be taken.
  VASSALLD, D. D. Division of Project Management. 79/09/27. 41pp.
- 7912110224 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRs & BMRs. Success of program depends on industry response. Supports formation of ouners groups to provide necessary info. DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912070212 Forwards proposed Revision 2 to Reg Guide 1.97.
  "Instrumentation for Light Water Cooled Nuclear Power Plants to Assess Plant & Environs Conditions During & Following Accident." Requests comment.
  VARGA.B.A. Assistant Director for Light Water Reactors. 79/10/23.
  3pp.

- 7912190417 Requests add1 info for as-built piping analysis. Site visit planned for discussion of review w/engineers. URNL will perform LaSalle review.
  PARR. G. D. Light Water Reactors Branch 3. 79/11/15. Spp.
- 7912040261 Forwards plant steam bypass capacity sheets percent rated. Info provided to SE for incorporation into NEDD-2470E. PEOPLES, D. L. Commonwealth Edison Co. 79/11/16. 200pp.
- 7912270178 Notification of 791214 meeting w/applicants to discuss proposed Revision 2 to Reg Quide 1.97. "Instrumentation for Light Water Cooled Nuclear Plants to Assess Plant & Environs Conditions During & Following Accident."

  KINTNER, L. Light Water Reactors Branch 1. 79/11/19. 1p.
- 7912100313 Responds to NRC 791115 request re confirmatory piping analysis for facility. Forwards info for RHR pipe line. Time history responses for relative anchor motion to OBE response spectra will be forwarded. W/o encl.

  DELOEORGE. L. D. Commonwealth Edison Co. 79/12/05. 2pp.
- 7912310498 Notification of 791219 meeting & site visit w/util to orient ORNL & Battelle-Columbus personnel w/facility & to discuss NRC confirmatory piping analysis.
  BOURNIA: A. Light Water Reactors Branch 3. 79/12/07. 3pp.
- 7912210349 Forwards cover sheet for CE-1-A.Revision 10.inadvertently omitted from 791116 transmittal.
  NAUDHTON.W.F. Commonwealth Edison Co. 79/12/13. 2pp.
- 7712310348 Forwards revised pages to CE-1-A, "Comm Ed GA Program for Nuclear Generating Stations," Revision 11.

  JANECEK, R. F. Commonwealth Edison Co. 79/12/20. 1p.
- --7912310359 Revised pages to CE-1-A, "Comm Ed OA Program for Nuclear Generating Stations," Revision 11.

  \* Commonwealth Edison Co. CE-1-A, 79/11/21, 16pp.
- F. Security, medical, emergency & fire protection plans
- 7712040471 Forwards info re upgraded emergency plans to plants under const & OL review. Applicants required to make certain exergency arrangements w/state & local organizations & submit emergency plans per Reg Ouide 1. 101.
  VASSALLO. D. B. Division of Project Management. 79/11/21. Opp.
- 7912270060 Forwards request for add1 info re emergency planning. Revised emergency plans incorporating new requirements due within five wks.
  PARR.D.D. Light Water Reactors Branch 3. 79/12/07. 7pp.

# Q. Adjudicatory correspondence

- 7912260347 Denies 790821 request to institute proceedings to suspend or revoke CPs.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/12/04. 2pp.
- --7912260350 Director's deniel of Citizens Against Nuclear Power 790821 request under 10CFR2.206 to suspend or revoks CPs. Sufficient info exists to establish conservative hydrodynamic loads & to evaluate facility response.

  DENTON:H.R. Office of Nuclear Reactor Regulation. 79/12/04. Opp.
- --7912260351 Denial of Citizens Against Nuclear Power 790821 request for suspension or revocation of CP. Sufficient info exists to establish criteria for design to evaluation of Mark II containment sys.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/12/04. ip.
- --7912260394 Forwards 790821 petition to institute proceeding to suspend or revoke CP. KODNER, J.L. Committee for Application of Nuremberg Principles to US Nuclear Power Production. 79/08/21. ip.
- --7912260355 Petition to institute proceedings to suspend or ravoke CP.
  Util did not consider hydrodynamic loads that result from
  dynamic effects of druwell air & stream forced into
  suppression pool during LGCA.
  GOOGL, E. Committee for Application of Nuremberg Principles to US
  Nuclear Power Production. CAMPBELL, S. E. Sinnissippi Alliance for
  the Environment (SAFE). NAUMAN, Q. Citizens United for Responsible
  Energy. 79/08/21. Spp.

And the second of the second of

#### H. General correspondence

- 7912280605 Discusses 791204 title change of manager of nuclear operations to vice president. Dryanization structure not altered. No revision will be made to QA program topical rept CE-1-4 until organization structure is delineated.

  JANECEK, R. F. Commonwealth Edison Co. 79/12/19. ip.
- G. Inspection reports, IE Bullotins & correspondence
- 7912070155 Forwards IE Insp Repts 50-373/79-34 & 50~374/79-23 on 791002-04. No noncompliance noted. FIORELLI,G. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 79/10/26. 2pp.
- ---7912070162 IE insp Repts 50-373/79-34 & 50-374/79-34 on 791002-04. Nancompliance noted Major areas inspected nandestructive examinations on RHR pipe welds of Unit 1 & work activities re recirculation sys safe-end thermal sleeve mod. WILLIAMS.C.C., BARRETT.P.A., NEISLER.J.H. Region 3, Chicago, Office of the Director. 79/10/24. 7pp.
- 7912180333 Forwards IE Insp Repts 50-373/79-35 & 50-374/79-24 on 791016-17. No moncompliance noted. FIORELLI,G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/11/06. 2pp.
- --7912180342 IE Insp Repts 50-373/79-35 & 50-374/79-24 on 791014-17. No noncompliance noted Major areas inspected: verified ASME certificates of authorization held by licensee & contractors & conducted review of previously reported itams.

  LEE.E. M. K., NEISLER, J. H., WILLIAMS, C. C. Region 3, Chicago.

  Office of the Director. 79/11/05. Spp.
- 7912210150 Forwards IE Insp Rept 50-373/79-37 on 791017-19.No noncompliance noted. HEISHMAN.R.F. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 79/11/08. 2pp.
- --7912210154 IE Insp Rupt 50-373/79-37 on 791017-19 No noncompliance noted Major areas inspected: prooperational test program & followup on items of noncompliance.
  MANRA:F.A.: STREETER.J.F. Rugion 3, Chicago, Office of the Director. 79/11/08. 4pp.
- 7912090106 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required. KEPPLER, J. G. Region J. Chicago, Office of the Director. 79/11/16.
- 7912100213 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912110557 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required.

  KEPPLER. J. G. Region 3, Chicago. Office of the Director. 79/11/16.
- 7912050344 Forwards IE Bulletin 79-26, "Boron Loss From BWR Control Blades," No response required.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/20.
- 7912100417 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on INRs." No written response required.

  KEPPLER, J. O. Region 3. Chicago, Office of the Director. 79/11/24.
- 7912140187 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No written response required. KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/26. is.
- 7912110395 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs capies of escalated enforcement correspondence sent by NRC to licensees.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/28.
- 7912190207 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." No written response required. KEPPLER, J. Q. Region 3, Chicago, Office of the Director. 79/11/30.

- 7912140036 Forwards IE Info Notice 79-30. "Reporting of Defects & Nancompliances, IOCFR21." No action or response required.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/12/06.
- 7912210169 Responds to IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Fine sample problems, defined by NRC, completed, verifying SAP-PIYBIS code. Frequency & modal participation factors agree w/NRC definitions.
  PEOPLES, D. L. Commonwealth Edison Co. 79/12/06. 1p.
- 7912200086 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. KEPPLER.J.O. Region 3. Chicago, Office of the Director. 79/12/10.
- S. Reportable occurrences, LERs & related correspondence
- 79:12050501 Forwards supplemental info to deficiency rept re defects in ventilation stack. Meekly insp program initiated to ensure safety of structure. Transfer of fuel from current location not prodent.

  DELGEORGE, L. D. Commonwealth Edison Co. 79/11/28. 39p.
- 7912240079 Ack receipt of 791128 interim deficiency rept re vent stack. FIGRELLI, G. Region G. Chicago, Reactor Construction & Engineering Support Branch. 79/12/07. 1p.
- DOCKET 50-374 LASALLE COUNTY STATION, UNIT 2
- A. Application/construction stage documents & correspondence
- 7912110011 Forwards NRC position on status & applicability to pending OL applications of results of THI followup actions. Dutlines addl short-term actions to be taken.
  VASSALLO, D. B. Division of Project Management. 79/09/27. 41pp.
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRs & BMRs. Success of program depends on industry response. Supports formation of owners groups to provide nacessary info. DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912070212 Forwards proposed Revision 2 to Reg Quide 1.97,
  "Instrumentation for Light Water Cooled Nuclear Power Plants
  to Assess Plant & Environs Conditions During & Following
  Accident." Requests comment.
  VARGA.S.A. Assistant Director for Light Water Reactors, 79/10/23.
  3pp.
- 7912190417 Requests add1 info for as-built piping analysis. Site visit planned for discussion of review w/engineers. CRNL will perform LaSalla review.
  PARR.O.D. Light Water Reactors Branch 3. 79/L1/15. 3pp.
- 7912040261 Forwards plant steam bypass capacity sheets, percent rated, info provided to GE for incorporation into NEDO-24708. PEOPLEH.D.L. Commonwealth Edison Co. 79/11/16. 200pp.
- 7912100313 Responds to NRC 791115 request re confirmatory piping analysis for facility. Forwards info for RHR pipe line. Time history responses for relative anchor motion & OBE response spectra will be forwarded. W/o encl. DELGEORGE. L. O. Commonwealth Edison Co. 79/12/05. 2pp.
- 7912310498 Notification of 791219 meeting & sits visit w/util to orient GRML & Battells-Columbus personnel w/facility & to discuss NRC confirmatory piping analysis.
  BOURNIA.A. Light Water Reactors Branch 3. 79/12/07. Spp.
- 7912210349 Forwards cover sheet for CE-1-A.Revision 10.inadvertently omitted from 791116 transmittal.
  NAUGHTON, N. F. Commonwealth Edison Co. 79/12/13. 2pp.
- 7912310348 Forwards revised pages to CE-1-A. "Comm Ed GA Program for Nuclear Generating Stations," Revision 11. JANECEK.R.F. Commonwealth Edison Co. 79/12/20. 1p.
- ---7912310339 Revised pages to CE-1-A. "Comm Ed GA Program for Nuclear Concreting Stations: " Revision 11. \* Commonwealth Edison Co. CE-1-A. 79/11/21. 16pp.

- F. Security, medical, emergency & fire protection plans
- 7912040471 forwards info re upgraded emergency plans to plants under const & OL review Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Ouide 1.101.
  VASSALLD.D.B. Division of Project Management. 79/11/21. 6pp.
- 7912270040 Forwards request for add1 info re emergency planning. Revised emergency plans incorporating new requirements due within five wks. PARR.O.D. Light Water Reactors Branch 3. 79/12/07. 7pp.
- Adjudicatory correspondence
- 7911190528 Testimony re intervenor Miami Valley Power Project Contention 17 on use of Kaowool as fire barrier for cable trays.Certificate of Svc encl. HARRISON.O.A. Division of Systems Bafety. 79/10/30. 15pp.
- ---7911190530 Forwards June 1979 "Fire Protective Cable Tray Fire Test" by MS Abrams, witnessed by NB Cohn on 790606. COHN.N.B. Cage-Babcock Associates, Inc. 79/06/12. App.
- 7912260347 Denies 790821 request to institute proceedings to suspend or revoke CPs.

  DENION.H.R. Office of Nuclear Reactor Regulation. 79/12/04. 2pp.
- --7912260350 Director's denial of Citizens Against Nuclear Power 790821 request under 10CFR2, 204 to suspend or revoke CPs. Sufficient info exists to establish conservative hydrodynamic loads & to evaluate facility response.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/12/04. App.
- --7912260351 Denial of Citizens Against Nuclear Power 790821 request for suspension or revocation of CP. Bufficient info exists to establish criteria for design & evaluation of Mark II containment sys.

  DENTON. H. R. Office of Nuclear Reactor Regulation. 79/12/04. is.
- ---7912260334 Forwards 790821 petition to institute proceeding to sumpend or revoke CP. KODNER,J.L. Committee for Application of Nuremberg Principles to US Nuclear Power Production. 79708/21. ip.
- --7912260355 Patition to institute proceedings to suspend or revoke CP.

  Util did not consider hydrodynamic loads that result from
  dynamic effects of drywell air & stream forced into
  suppression pool during LOGA.

  GUODL, E. Committee for Application of Nuremberg Principles to US
  Nuclear Power Production. CAMPBELL, S.E., Sinnissippi Alliance for
  the Environment (BAFE). NAUMAN, G. Citizens United for Responsible
  Energy. 79/08/21, Spp.
- H. General correspondence
- 7912280605 Discusses 791204 title change of manager of nuclear operations to vice president. Organization structure not altered. No revision will be made to GA program topical rept CE-1-A until organization structure is delineated. JANECEK, R. F. Commonwealth Edison Co. 79/12/19. 1p.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912070155 Forwards IE Insp Repts 50-373/79-34 & 50-374/79-23 on 791002-04. No noncompliance noted. FIORELLI,0. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 79/10/26. 2pp.
- --7912070162 IE Insp Repts 50-373/79-34 & 50-374/79-34 on 791002-04. Noncompliance noted Hajor areas inspected:nondeatructive examinations on RHR pipe welds of Unit 1 & work activities representation systafa-and thermal sleeve mod. WILLIAMB.C.C., BARRETT.P.A., NEIBLER.J.H. Region 3. Chicago. Office of the Director. 79/10/24. 7pp.
- 7912180333 Forwards IE Insp Repts 50-373/79-35 & 50-374/79-24 on 791016-17. No noncompliance noted.
  FIDRELLI, G. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 79/11/06. 2pp.
- --7912180342 IE Insp Repts 50-373/79-35 & 50-374/79-24 on 791014-17.No noncompliance noted Major areas inspected verified ASME certificates of authorization held by licanses & contractors & conducted review of previously reported items.

  LEE, E. W. K., NEISLER J. H., WILLIAMS, C. C. Region 3, Chicago, Office of the Director. 79/11/05. 5pp.

- 7912050106 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required. KEPPLER, J. G. Region 3. Chicago. Office of the Director. 79/11/16. is.
- 79:21002:3 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Bupport Loads." No response required.

  KEPPLER, J. 9. Region 3, Chicago, Office of the Director. 79/11/16.
- 79:21:10357 Forwards IE Info Notice 79-29. "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required.

  KEPPLER, J. Q. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912050344 Forwards IE Bulletin 79-26, "Boron Loss From BWR Control Blades." No response required.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/20.
- 7912100417 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No written response required.

  KEPPLER, J. 9. Region 3. Chicago, Office of the Director. 79/11/26.
- 79:2140:87 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No written response required.

  KEPPLER.J. 9. Region S. Chicago, Office of the Director. 79/11/26.

  1p.
- 7912110395 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sent by NRC to licensess.

  KEPPLER.J.O. Region 3, Chicago, Dffice of the Director. 79/11/28.

  18.
- 7912190207 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation."
  No written response required.
  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/30.
  ip.
- 77:2140056 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action or response required. KEPPLER, J. Q. Region 3, Chicago, Office of the Director. 79/12/06.
- 7912210169 Responds to IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Fine sample problems, defined by NRC, completed, varifying SAP-PIYSIB code, Frequency & model participation factors agree w/NRC definitions.
  PEOPLES, D. L. Commonwealth Edison Co. 79/12/06. 1p.
- 7912200086 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action regulared. KEPPLER, J. C. Region 3, Chicago, Office of the Director. 79/12/10.
- S. Reportable occurrences, LERs & related correspondence
- 7912050501 Forwards supplemental info to deficiency mept me defects in ventilation stack. Weekly insp program initiated to ensure safety of structure. Transfer of fuel from current location not prudent.

  DELGEORGE, L. O. Commonwealth Edison Co. 79/11/28. 3pp.
- 7912260075 Notifies that NRC will review final deficiency rept repossible deficiency in reactor containment structural steel. FIDRELLI.O. Region 3, Chicago, Reactor Construction & Engineering Bupport Branch. 79/12/07. 1p.
- 79122A0079 Ack receipt of 791128 interim deficiency rept re vant stack. FIDRELLI, G. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 79/12/07. 1p.
- DOCKET 50-375 NUCLEAR EXAMINATION REACTOR
- F. Security, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Quide 5.XX, "Btd Format & Content for Licensee Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance." W/o encl. REED,R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22.

- DOCKET 50-376 NORTH COAST NUC PLANT
- A. Application/construction stage documents & correspondence
- 7912310356 Notification of 800108 meeting w/utils in Bathesda.ND to discuss info request re adequacy of equipment qualification.
  UNCARO, A. R. Power Systems Branch. 79/12/11. 3pp.
- DOCKET 50-382 WATERFORD GENERATING STATION, UNIT 3
- A. Application/construction stage documents & correspondence
- 7912110011 Forwards NRC position on status & applicability to pending OL applications of results of TMI followup actions Dutlines addl short-term actions to be taken.
  VASSALLO, D. B. Division of Project Management. 79/09/27. 41pp.
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRs & BMRs.
  Success of program depends on industry response Supports formation of owners groups to provide necessary info.
  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.
- 7912120072 Notification of 791128 meeting w/util & ANL in Taft.LA to discuss plant OL review & visit site.
  COTA.P. C. Environmental Projects Branch 1. 79/11/19. 4pp.
- 7912210107 Summary of NRC Caseload Forecast Panel 790925 sits visit re const progress.List of attendees encl. BENEDICT, R. A. Light Water Reactors Branch 2, 79/11/30. Upp.
- 7912190079 Requests survey of historic & cultural properties Figure 2.1-3 of environ rept indicating applicants portion of property & sections of environ rept re cultural resource investigation encl.

  REGAN.W. H. Assistant Director for Environmental Projects.
  79/12/06. 15pp.
- 7912270274 Requests that action items submitted by util on 791109 be given immediate attention. Also requests specific date for receipt of OL review schedule. ASMCLL, D. L. Louisiana Power & Light Co. 79/12/27. lp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & DL review Applicants required to make certain emergency arrangements wistate & local organizations & submit emergency plans per Reg Quide 1.101.
  VABSALLO.D.B. Division of Project Management. 79/11/21. App.
- Q. Adjudicatory correspondence
- 7912100326 Notice of appearance in proceeding Certificate of Svc encl. OLASSFIEGEL.H. Louisiana Power & Light Co. GLASSFIEGEL.H. Shaw. Pittman. Potts & Trowbridge. 79/11/12. 3pp.
- 7912170209 First interrogatories directed to intervenor LA Consumers Lague, Inc., per 790925 stipulation. Requests identification of statutes by title & citations to judicial decisions forming basis for Contention 3(d). Certificate of Svc encl. TROMBRIDGE, O. F., QLASSPIEGEL, H. Louisiana Power & Light Co. TROMBRIDGE, O. F., Shaw, Pittman, Potts & Trowbridge, 77/11/12. 4pp.
- 7912170217 First interrugatories directed to joint intervenors, per 790928 stipulation. Requests identification of geologic activities raised in Contention 23, as discussed in Saucier rept. Certificate of Byc encl.
  TROWREIDGE, O. F., GLASSPIEGEL, H. Louisiana Power & Light Co.
  TROWRIDGE, O. F., Shaw, Pittman, Potts & Trowbridge. 79/11/12. App
- 7912070243 Interrogatories & requests for production of documents, directed to joint intervenors Save Dur Wetlands, Inc & Dystershell Alliance, Inc. Requests basis supporting alleged design inefficiencies.

  MCOURREN, H. J. Hearing Branch 1. 79/11/13. 24pp.
- ---7912070248 Interrogatories & requests for production of documents directed to LA Consumer LeaguerInc. Requests basis supporting allaged inadequacy of applicant emergency plan. Certificate of Byc encl.

  MCGURREN.H. J. Hearing Branch 1. 79/11/13. 10pp.

- 7912200025 Submits interrogatories prepared for util Requests info re transmission lines draft emergency plan & evaluation of impact of gasoline shortage Forwarding ltr encl. IRVINO.S M. Louisiana Consumer's League. Inc. IAVINO.S.M. Public Law Utilities Group 79/11/13. 4pp.
- 7912260210 Forwards interrogatories of LA Consumer's teague for response by util. IRVING.B.M. Louisiana Consumer's League: Inc. 79/11/13. 1p.
- --7912260213 Interrogatories of LA Consumer's League for response by util.
  IRVING.S.M. Louisiana Consumer's League, Inc. 77/11/19. App.
- 79[2]20345 Request for delayed filing of first set of interrogatories for applicant.Interrogatories not processed due to severe illness & huspitalization.Certificate of Svc encl. JONES, L. L. Ogstershell Alliance, Inc. JONES, L. Gillespie & Jones. 79/11/23 App.
- ~-7912120352 First set of interrogatories. Seeks info re Contentions 1, 2, 8, 9, 12, 17 & 19-22. JUNES, L. L. Ogsterthell Alliance, Inc. JUNES, L. L. Gillespie & Junes. 79/11/23. 39pp.
- 7912280105 Confirms 791129 telcon conveying licensee agreement not to object to LL Jones 791123 motion requesting delayed filing of interrogatories. Jones time for filing addl TMI-related contentions extended to 791210.
- 7912130042 No objection to Joint Intervenors, Oystershell Alliance, Inc & Save Our Hetlands, Inc 791123 request for delayed filing of interrogatories. Certificate of Svc encl.
  TROUBRIDGE.G.F. Arkansas Power & Light Co. TROUBRIDGE, O. F. Shaw, Pittman, Potts & Troubridge. 79/11/30. 3pp.
- 7912190396 Grants Joint Intervenors, Gystershell Alliance, Inc & Savo Our Wetlands Inc, 791123 request for delayed filing of first set of interrogatories.

  WOLFE'S, J. Atomic Safety and Licensing Board Panel. 79/12/05. ip.
- 7912280140 Dbjections to joint intervenors' 791123 interrogatories re Contentions 6.9.21 & 22. Interrogatories vague. Info is equally accessible to intervenors. Info requested outside scope of contentions. Certificate of Svc encl. TROMBRIDGE.6.F. Louisiana Power & Light Co. TROMBRIDGE.6.F. Shaw, Pittman, Potts & Trowbridge. 79/12/06. 4pp.

#### H. General correspondence

- 7912260086 Responds to 790402 request that const be halted in view of TMI accident. Forwards NUREG-0578, NURG-0585 & NURG-0632, W/s encl.
  VAROA, S.A. Assistant Director for Light Water Reactors. 79/12/12.
  388.
- Q. Inspection reports: IE Bulletins & correspondence
- 7912060561 Responds to 790830 ltr re IE Insp Rept 30-382/79-09 concerning allegations of former util employee.Rept contains no proprietary info.
  ASWELL.D.L. Louisiana Power & Light Co. 79/09/04. 1p.
- 7912170362 Responds to IE Rulletin 79-14. Istallation of various safetyrelated/selemically supported piping sys in progress. ASWELL, D. L. Louisiana Power & Light Co. 79/10/16. tp.
- 7912120196 Forwards IE Insp Rept 50-382/79-15 on 791010-12.No noncompliance noted. MADSEN.O.L. Region 4. Dallas, Reactor Operations Nuclear Support Branch. 79/10/29. 2pg.
- --7912120204 IE Insp Rept 50-382/79-15 on 791010-12.No noncompliance noted Major areas inspected second corporate mpt meeting & related preoperational activities.
  CONSTACLE, C.L., STEMART.R.C., MESTERMAN.T.F. Region 4, Dallas, Office of the Director, 79/10/24, App.
- 7912030226 Forwards IE Insp Rept 50-382/79-12 on 790926-29. No noncompliance noted.
  SEIDLE:N.C. Region 4. Dallas, Reactor Construction & Engineering Support Branch. 79/10/26. 2pp.

- --7912030228 IE Insp Rept 50-382/79-12 on 790926-28. No noncompliance noted. Major areas inspected: const phase environ protection programs, audits, implementation of CP requirements & environ studies.

  EVERETT, R. J. Region 4, Dallas, Fuel Facility & Materials Safety Branch. WILBORN.L., SPITZBERG, D. B. Region 4, Dallas, Office of the Director. 79/10/22. 6pp.
- 7912050526 Forwards IE Insp Rept 50-382/79-11 on 790917-21 & 24-25.No nancompliance noted.
  SEIDLE.M.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/10/26. 2pp.
- --7912050531 IE Insp Rept 50~382/79-11 on 790917-21 & 24-25.No noncompliance noted Major areas inspected:const activities re previous stop work order on concrete placement for dome of containment bidg.

  HALL, R.E. Region 4, Dallas, Reactor Construction & Engineering Support Branch. CROSSMAN.W.A., TAPIA, J. I. Region 4, Dallas, Office of the Director. 79/10/24. App.
- 7912170357 Responds to IE Bulletin 79-23 Generator & excitation transformer do not have common neutral Required testing will be conducted prior to hot functional testing.
  ASMELL.D.L. Louisiana Power & Light Co. 79/11/06. ip.
- 7912100264 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. SEYFRIT.K.V. Region 4, Dallas, Office of the Director. 79/11/16.
- 7912110535 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Conlant Bys Instrumentation During Operation." No specific action or response required.

  SEYFRIT.K.V. Region 4, Dallas, Office of the Director. 79/11/16.
- 7912110283 Forwards IE Circular 79-23. "Motor Starters & Contactors Failed to Operato." No response required. SEYFRIT.K.V. Region 4. Dallas, Office of the Director. 79/11/26. 10.
- 7912110483 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general afcs copies of escalated enforcement correspondence sent by NRC to licensees.

  EEYFRIT.K.V. Region 4. Dallas, Office of the Director. 79/11/26.
- 7912180055 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No written response required. SEYFRIT,K.V. Region 4, Dallas, Office of the Director. 79/11/26.
- 7912190181 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation." No written response required. GEYFRIT,K.V. Region 4, Dailas. Office of the Birector. 79/11/30.
- 7912310265 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21," No action required, SEYFRIT,K,V, Region 4, Dallas, Office of the Director, 79/12/06.
- 7912200219 Forwards IE Bulletin 79-28. "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required.

  SEYPRIT, K. V. Region 4. Dallas, Office of the Director. 79/12/07.
- 7912280589 Forwards IE Info Notice 79-31. "Use of Incorrect Amplified Response Spectra." No written response required. SEYFRIT.K.V. Region 4. Dallas. Office of the Director. 79/12/13.
- 5. Reportable accurrences, LERs & related correspondence
- 7912070150 Responds to 790820 ltr re 790808 deficiencies in concrete placement by Fegles Power Svc. Stop work order issued 790817. Util will correct deficiencies to comply w/requirements. ASWELL, D. L. Louisiana Power & Light Co. 79/08/22. 1p.
- 7912070145 Notifies of delay in final deficiency repts re emergency diesel generators defective shaft springs & roller pins. Manufacturer has ordered new mod assemblies for roller pins. Final rept submitted by 800315.
  ASWELL, D. L. Louisiana Power & Light Co. 79/10/31. 2pp.

- 7912070392 Deficiency Rept 11 re switchgear breaker position switch operator defect Replacement installation expected in Dec. Final rept to be submitted by 800331.
  ASWELL,D.L. Lautsians Power & Light Co. 79/11/30. lp.
- 7912070455 Discusses Ban Onofre Units 2 & 3 deficiency rept re use of high pressure injection pump vendor acceptance test results in small break LOCA analysis. Currently conducting small break analysis at facility. FSAR amend forthcoming.

  ASWELL, D. L. Louisiana Power & Light Co. 79/12/03. 1p.
- DOCKET 50-387 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1

  A. Application/construction stage documents & correspondence
- 7912110011 Forwards NRC position on status & applicability to pending .QL applications of results of TMI followup actions.Outlines addl short-term actions to be taken VASSALLD, D.B. Division of Project Management. 79/09/27. 41pp.
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATWS issue for PWRs & BWRs.
  Success of program depends on industry response. Supports formation of dumers groups to provide necessary info.
  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.
- 7912050520 Forwards request for addl info for completion of OL application Includes question originated by DRNL.
  PARR.O.D. Light Water Reactors Branch 3. 79/11/23. 21pp.
- 7912060563 Forwards proposed Revision 2 to Reg Guide 1.97,
  "Instrumentation for Light Water Cooled Nuclear Power Plants
  to Assess Plant & Environs Conditions During & Following
  Accident," & value impact statement.
  VARGA.S.A. Assistant Director for Light Water Reactors. 79/11/23.
  3pp.
- --7912060569 Draft 1 of Revision 2 to Reg Guide 1.97. "Instrumentation For Light-Mater-Cooled Nuclear Power Plants to Assess Plant & Environs Conditions During & Following Accident." Draft 3 of ANS-4.5 encl. \* Office of Standards Development. 79/10/15. 55pp.
- 791227017B Notification of 791214 meeting w/applicants to discuss proposed Revision 2 to Reg Guide 1.97. "Instrumentation for Light Water Cooled Nuclear Plants to Assess Plant & Environs Conditions During & Following Accident."

  KINTNER, L. L. Light Water Reactors Branch 1. 79/11/19. 1p.
- 7912280318 Advises of recently amended NRC regulations implementing existing authority to require onsite ofc space & immediate facility access. Requests addl ofc space. FR notice dtd 790816 encl.

  BTELLO, V. Region 1, Philadelphia, Office of the Director.
  79/11/28. 4pp.
- 7912180009 Forwards supplemental hydrologic engineering questions re Fond Hill Reservoir evaluation. BIVINS.W.S. Hydrology Mateorology Branch. 79/11/30. 2pp.
- 7912200649 Forwards request for add1 info needed to prepare draft environ statement re Pond Hill reservoir.

  SELLS.D.E. Environmental Projects Branch 2. 79/12/05. 3pp.
- 7912280597 Forwards request for addl info re instrumentation & control sys to complete OL review.

  PARR.D.D. Light Water Reactors Branch 3. 79/12/11. 5pp.
- 7912270245 Forwards response to NRC 791205 request for add1 info re Pond Hill reservoir Oversize drawings available in Central Files only. CURTIS N. M. Pennsylvania Power & Light Co. 79/12/17. i3pp.
- £. Utility Environmental Report (ER), amends & correspondence
- 7912190777 Forwards updated distribution list for environ rept supple & amends for facility.

  DUNCAN.M. Environmental Projects Branch 2. 79/12/06. Spp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review Applicants required to make cortain emergency arrangements w/state & local organizations & submit emergency plans per Reg Quide 1.101.
  VABSALLO,D.B. Division of Project Management. 79/11/21. Opp.

#### G. Adjudicatory correspondence

- 7912050207 Requests portions of past ABLB orders restricting intervenor discovery access scheduling of prehearing conference within 60 days to establish new discovery timetable & denial of NRC motion for intervenor dismissal.

  HALLIGAN, T. J. Citizens Against Nuclear Dangers. 79/10/24. 5pp.
- 7912:80056 Requests to make limited appearance statement at licensing prekearing.
  CSALA.O.P. Affiliation Unknown. 79/11/14. 1p.
- --7912180058 Requests to make limited appearance statement at licensing prehearing. MITCHELL.R. Affiliation Unknown. 79/11/13. 1p.
- 7912060475 Requests to make limited appearance statement at licensing hearings.
  PULABKILL J. Affiliation Unknown. 79/11/19. lp.
- 7912170095 Response to ASLB 791030 order & memorandum.Requests issuance of protective order to relieve burden on intervenors & certification of questions re util abuse of discovery. Certificate of Svc encl.

  KEPFORD, C. Environmental Coalition on Nuclear Power. 79/11/19.
- 7912060470 Requests to make appearance statement at licensing hearings.
  THOM.W.T. Affiliation Unknown. 79/11/20. 1p.
- 7912180214 Requests to make limited appearance statement at licensing prehearing. SPALLONE, D. Affiliation Unknown. 79/11/24. 1p.
- 7912190129 Forwards extra copies of NUREG-0322, draft NUREG-0584, NUREG/CR-0456, 0573 & 0597. Environ Coalition on Nuclear Power will be added to mailing list for propased rules & monthly title list.

  CUTCHIN, J. M. Hearing Branch 3. 79/11/26. 3pp.
- 7912110]61 Requests to make limited appearance statement at licensing prehearing. SHULTZ.O.R., SHULTZ.L.B. Affiliation Unknown. 79/11/27. 2pp.
- 7912130246 Answer in opposition to intervener Environ Coalition on Nuclear Power motion for protective under contained in response to ASLB 791030 memorandum & order. Urgos rejection, per reasons set forth in order. Contificate of Sive encl.

  BILBERG, J. E. Pennsylvania Power & Light Co. 79/11/27. 3pp.
- 7912140539 Notifies that final EIS will not be published until Apr 1980. REIS.E.J. Hearing Branch 3 79/12/05 1p.
- 7912180173 Response to intervenor Environ Coalition on Nuclear Power 791119 request for protective order & certification of questions. All requests should be denied for lack of avidence of bias Certificate of Svc onc 1.

  REIS.E.J. Hearing Branch 3 79712705. 9pp.
- 7912180201 Responds to ASLB 791030 memorandum & order on discovery motions requesting permission to borrow documents from PDR.

  Necessary actions would not be appropriate. Other steps have been taken to make info available to intervenors.

  REIS.E.J. Hearing Branch 3 79/12/05. 2pp.
- 7912190157 Responds to 790731 itr re cuntinuing const of facility
  Before releases of radioactive liquids, impact will be
  evaluated & review made available to public.
  VARGA, B. A. Assistant Director for Light Water Reactors. 79/12/05.
  2np.
- 7912170262 Order denying intervenor Environ Coalition on Nuclear Power 791119 requests for protective order & for reconsideration of ASLB 791030 memorandum & order No basis for certification shown. Answers to discovery requests due 800118.

  BECHIDEFER.C. Atomic Safety and Licensing Board Panel. 79/12/06.
  7pp.
- 7912270096 Apposes extension to BOOMAB for intervenor Environ Coalition on Nuclear Power to respond to applicant discovery requests.

  Will cause risk of delays in hearing schedule Dutline of discovery history & Certificate of Svc encl.

  SILBERG. J. E. Shaw, Pittman. Potts & Trowbridge. 79/12/14. Spp.

- 7912210014 Notifies that IE completed insp of MK Creasy allegations re GA deficiencies & found no substantiating evidence.Matter need not be examined in OL procedure. CUTCHIN, J. M. Hearing Branch 3. 79/12/17. 4pp.
- --7912210017 Forwards IE Insp Repts 50-387/79-06 & 50-388/79-05 on 790221-23 & 0227-0302.No noncompliance noted. CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/12/07. 2pp.
- --7912210024 IE Insp Repts 50-387/79-06 & 50-388/79-05 on 790221-23 & 0227-0302. No noncompliance noted Major areas inspected: allegations re GA program made during 790129-31 prehearing conference.

  OALLO,R.M., SHITM,B.H. Region 1. Philadelphia, Office of the Director. MCGAUGHY,R.U. Region 1. Philadelphia, Reactor Construction & Engineering Support Branch. 79/12/07. 11pp.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 79121203B4 Forwards Revision 13 to F9AR, submitted as Amend 18 to GL application.
  CURTIS.N.M. Pennsylvania Power & Light Co. 79/12/12. 2pp.
- --79121203B7 Revision 13 to FSAR, submitted as Amend 1B to DL application. \* Pennsylvania Power & Light Co. 79/12/12. 400pp.
- P. Operating license stage documents & correspondence
- 7912140057 Notification of 791212 meeting w/util & Pacific Northwest Labs to discuss NRC confirmatory piping analysis. PARR.O.D. Light Water Reactors Branch 3. 79/12/03. 2pp.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912060194 Forwards IE Insp Repts 50-387/79-26 & 50-388/79-14 on 790730-0891 No noncompliance noted. CARLSDN.R.T. Region 1. Philadelphia, Reactor Construction & Engineering Support Dranch. 79/10/12. 2pp.
- --7912060200 IE Insp Repts 50-387/79-26 & 50-388/79-14 on 790730-0831.No noncompliance noted Major areas inspected:RCPB installation & storage of safety-related components & reactor pressure vessel recirculation sys mod.

  QALLO, R. M. Region i. Philadelphia, Office of the Director. MCGMUBHY, R. W. Region i. Philadelphia, Reactor Construction & Engineering Support Branch. 79/10/11. 12pp.
- 7912050331 Forwards IE Insp Rept 50-387/79-27 on 790926-28 No noncompliance noted. BRUNNER.E.J. Region 1. Philadelphia, Reactor Construction & Engineering Support Branch. 79/10/24. 2pp.
- --7912050341 IE Insp Rept 50-387/79-27 on 790926-28. No nuncompliance noted Hajor areas inspected properational test program. exergency standby power sys & followup on previous inspitems.
  NICHOLAS. H. H. , CAPHTON. B. L. Region 1, Philadelphia, Office of the Director. 79/10/22. 7pp.
- 7912140275 Respands to LE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Considers it inappropriate to perform insp required on sys still under const.

  CURTIS N. H. Pannsylvania Power & Light Co. 79/11/02. 1p.
- 7912050051 Forwards IE Circular 79-22. "Stroke Times for Power Operated Relief Valves." No response required. ORIER, B.H. Region i, Philadelphia, Office of the Director. 79/11/16. 1p.
- 7912030295 Forwards IE Info Notice 79-27, "Steam Generator Tube Huptures at Two PWR Plants." No response required. ORIER,B.H. Region 1, Philadelphia, Office of the Director. 79/11/16. 1p.
- 7912100145 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. GRIER, B. H. Region 1. Philadelphia, Office of the Director, 79/11/16. 1p.
- 7912110461 Forwards IE info Notice 79-29. "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required.

  GRIER, B.H. Region i. Philadelphia. Office of the Director.
  79/11/19. 1p.

- 7912050282 Forwards IE Bullstin 79-24, "Boron Loss From RWR Control Blades." No response required. ORIER,B.H. Region 1, Philadelphia, Office of the Director. 79/11/20. 1p.
- 7912260332 Ack receipt of 791102 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-387/79-25 & 90-388/79-13.
  ORIER, B. H. Region 1, Philadelphia, Office of the Director, 79/11/23. 1p.
- --7912260333 Responds to NRC 791012 ltr re violations noted in IE Insp. Repts 50-387/79-25 & 50-388/79-13. Corrective actions: regrading batch plant wash down area & rerouting effluents to controlled pathway where treated.

  CURTIS.N. M. Pennsylvania Power & Light Co. 79/11/02. 2pp.
- --7912260335 Forwards IE Insp Repts 50-387/79-25 & 50-388/79-13 on 790806-08 & notice of violation. SMITH.G.H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 79/10/12. 3pp
- --7912260337 Nutice of violation from insp on 790806-08.

  \* Region 1. Philadelphia. Office of the Director. 79/09/21.
  1p.
- --7912260339 IE Insp Repts 50-387/79-25 & 50-388/79-13 on 790806-08.
  Noncompliance noted: failure to follow procedures re dusting & failure to control erosion/sedimentation.
  SHANDRAKY, M. M., BORES, J., TERC, N. M. Region 1, Philadelphia,
  Office of the Director. 79/09/21. 7pp.
- 7912060586 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No response required.

  ORIER, B.H. Region i, Philadelphia, Office of the Director.

  79/11/26. 1p.
- 7912110077 Forwards IE Circular 79~23, "Motor Starters & Contactors Failed to Operate." No response required.

  ORIER.D.M. Region 1, Philadelphia, Office of the Director.
  79/11/26, 1p.
- 7912190065 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation."
  No written response required.
  ORIER.B.H. Region 1, Philadelphia, Office of the Director.
  79/11/30. 1p.
- 7912310242 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action required. ORIER, B.H. Region 1, Philadelphia, Defice of the Director. 79/12/06. 4pp.
- 7912190763 Forwards IE Bulletin 79-28, "Possible Malfunction of Namca Model EA180 Limit Switches at Elevated Temps," Written response required. ORIER.B.H. Region 1, Philadelphia, Office of the Director. 79/12/07. 1p.
- 7912280230 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required.
  ORIER.B.H. Region 1, Philadelphia, Office of the Director.
  79/12/13. 1p.
- S. Reportable occurrences. LERs & related correspondence
- 7912130335 Ack receipt of 791011 interim rept re potential deficiency in Amphenol connectors & Cutler Hammer E-30 switches.
  CARLBON.R.T. Region 1. Philadelphia. Reactor Construction & Engineering Support Branch. 79/10/22. 43pp.
- --7912130347 Interim deficiency rapt re Amphanol connectors & Cutler Hammer E-30 switches. Evaluation of faulty switch mechanisms will be submitted subsequent to GE & Bechtel evaluations. CURTIS. N. W. Pennsylvania Power & Light Co. 79/10/11. Epp.
- 7912040351 Forwards final deficiency rept re connector pin crimping defects on control panel insert.
  CURTIE:N.W. Pennsylvania Power & Light Gc. 79/11/28. 2pp.
- --7912040353 Final deficiency rept re panel inserts wiring & device damage. Caused by manufacturing personnel error & crimping tool malfunction resulting from inadequate GA. Connector pins repaired, reworked & tested.

  BIEESTA. J., HDLLINDSHAW.H. Bechtel Power Corp. (subs. of Bechtel Corp.). 79/10/30. 40pp.

- 7 Interim deficiency rept re violation of separation criteria 6 kV switchgear. Problem may be generic. Followup rept sw.
- ow. N.W. Pennsylvania Power & Light Co. 79/11/29. 2pp.
- 6 Interim deficiency rept re violation of separation criteria 6 kV switchgear. Caused by failure to delineate or rate separation requirements re project specs ng vendor wiring. Problem under review.
  N. M. Pennsylvania Power & Light Co. 79/11/29. 2pp.
- 5 Interim deficiency rept re cable pulling activities.Requests on until 800301 to file final definitive rept. N. W. Pennsylvania Power & Light Co. 79/12/10. 2pp.
- B Forwards final deficiency rept re insulation damage to in Control Room Inserts 72C & 73C which are part of standby diesel generator controls.GE evaluation
- N. W. Pennsylvania Power & Light Co. 79/12/17. ip.
- 308 Final deficiency rept re insulation damage to wiring in place of the state of t
- -398 BUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2
- ation/construction stage documents & correspondence
- i Forwards NRC position on status & applicability to pending ications of results of TMI followup actions. Outlines ort-term actions to be taken.

  D.D. B. Division of Project Management. 79/07/27. 41pp.
- 4 Discusses NRC plans to use generic analyses to develop early ation program to resolve ATMS issue for PMRs & BWRs. of program depends on industry response. Supports on of owners groups to provide necessary info. H.R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- D Forwards request for add1 info for completion of DL tion. Includes question originated by ORNL. D. Light Water Reactors Brench 3, 79/11/23. 2ipp.
- 3 Forwards proposed Revision 2 to Reg Guide 1.97, mentation for Light Water Cooled Nuclear Power Plants as Plant & Environs Conditions During & Following t," & value impact statement.

  Assistant Director for Light Water Reactors. 79/11/23.
- B Advises of recently amended NRC regulations implementing g authority to require onsite ofc space & immediate y access Requests addl ofc space.FR notice dtd 790816
- V. Region 1, Philadelphia, Office of the Director. B. 400.
- 5 Forwards supplemental hydrologic engineering questions re 11 Reservoir evaluation. H.B. Hydrology Meteorology Branch. 79/11/30. 2pp.
- 9 Forwards request for add1 info needed to prepare draft statement re Pond Hill reservoir. .E. Environmental Projects Branch 2, 79/12/05. 3pp.
- 7 Forwards request for add1 info re instrumentation & control complete OL review.
  D. Light Water Reactors Branch 3. 79/12/11. 5pp.
- 5 Forwards response to NRC 791205 request for addl info re 11 reservoir. Oversize drawings available in Central nly.
  N.W. Pennsylvania Power & Light Co. 79/12/17. 13pp.
- y Environmental Report (ER), amends & correspondence

enganing pada separah di didah Sebagai Sebagai Sebagai Sebagai

7 Forwards updated distribution list for environ rept suppls & for facility.

H. Environmental Projects Branch 2. 79/12/06. 5pp.

- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded omergency plans to plants under const & OL review. Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans por Reg Guide 1. 101.
  VASSALLO, D. D. Division of Project Management. 79/11/21. 6pp.
- O. Adjudicatory correspondence
- 7912050207 Requests portions of past ASLB orders restricting intervenor discovery access, scheduling of prehearing conference within 60 days to establish new discovery timetable & denial of NRC motion for intervenor dismissal. HALLIGAN, T. J. Citizens Against Nuclear Dangers. 79/10/24. Spp.
- 7912180056 Requests to make limited appearance statement at licensing prebearing.
  CBALA, 6.P. Affiliation Unknown. 79/11/14. 1p.
- --7912180058 Requests to make limited appearance statement at licensing prehearing. Affiltation Unknown. 79/11/13. 1p.
- 7912040475 Requests to make limited appearance statement at licensing hearings. PULASKILL J. Affiliation Unknown. 79/11/19. 1p.
- 7912170095 Response to ASLB 791030 order & momorandum. Requests issuance of protective order to relieve burden on intervenors & certification of questions re util abuse of discovery. Certificate of Svc encl. KEPFORD. C. Environmental Coalition on Nuclear Power. 79/11/19. 14pp.
- 7912040470 Requests to make appearance statement at licensing hearings.
  THOM, W. T. Affiliation Unknown. 79/11/20. ip.
- 79121802)4 Requests to make limited appearance statement at licensing prehearing.
  SPALLONE, K., SPALLONE, D. Affiliation Unknown, 79/11/26. ip.
- 7912190129 Forwards extra copies of NUREG-0322, draft NUREG-0584, NUREG/CR-0456, 0573 & 0597. Environ Coalition on Nuclear Power will be added to mailing list for groposed rules & monthly title list.

  CUTCHIN, J. M. . Hearing Branch 3. 79/11/26. Spp.
- 7912110161 Requests to make limited appearance statement at licensing prehearing. SHULTZ, O. R., SHULTZ, L. B. Affikiation Unknown. 79/11/27. 2pp.
- 7912130246 Answer in opposition to intervenor Environ Coalition on Nuclear Power motion for protective order, contained in response to ABLB 791030 memorandum & order Urges rejection, per reasons set forth in order. Certificate of Byc encl.
  BILBERO, J. E. Pennsylvania Power & Light Co. 79/11/27. 3pp.
- 7912140539 Notifies that final EIS will not be published until Apr 1980. REIS.E.J. Hearing Branch 3. 79/12/05. ip.
- 7912180173 Response to intervenor Environ Coalition on Nuclear Power 791119 request for protective order & certification of questions. All requests should be denied for lack of evidence of blas. Certificate of Svc encl.

  REIS.E.J. Hearing Branch 3. 79/12/05. 9pp.
- 7912180201 Responds to ASLB 791030 memorandum & order on discovery motions requesting permission to borrow documents from PDR. Necessary actions would not be appropriate. Other steps have been taken to make info available to intervenors. REIS, E. J. Hearing Branch 3. 79/12/05. 2pp.
- 7912190157 Responds to 790731 ltr re continuing const of facility.
  Refore releases of radioactive liquids, impact will be
  evaluated & review mode available to public.
  VARQA B. A. Assistant Director for Light Water Reactors. 79/12/05.
  Rec.
- 7712170262 Order denying intervenor Environ Coalition on Nuclear Power 791119 requests for protective order & for reconsideration of ABLB 791030 memorandum & order. No basis for certification shown. Answers to discovery requests due 800110.

  BECHHOEFER.C. Atomic Safety and Licensing Board Panel. 79/12/06.
  9pp.

- 7912270096 Opposes extension to 800118 for intervenor Environ Coalition on Nuclear Power to respond to applicant discovery requests.
  Will cause risk of orlays in hearing schedule Outline of discovery history & Certificate of Svc encl.
  SILBERGJE Shaw, Pittman, Ports & Prowbridge 79/12/14. Spp.
- 7912210014 Nutifies that IE completed insp of MK Creasy allegations re GA deficiencies & Found no substantiating evidence.Matter need not be examined in OL procedure. CUTCHIN.J.M. Hearing Branch 3. 79/12/17. App.
- --7912210019 Forwards IE Insp Repts 50-387/79-06 & 50-388/79-05 on 790221-23 & 0227-0302 No noncompliance noted. CARL90N.R.T. Region 1. Philadelphia, Reactor Construction & Engineering Support Branch. 79/12/07. 2pp.
- --7912210024 IE Insp Repts 50-387/79-06 to 50-388/79-05 on 790221-23 to 0227-0302. No noncompliance noted Major areas inspected: allegations of GA program made during 790129-31 prehearing conference GALLO.R.M., SMITH.B.H. Region 1. Philadelphia. Diffice of the Director. MCGAUGHY.R.H. Region 1. Philadelphia. Reactor Construction to Engineering Support Branch. 79/12/07. 11pp.
- K. Utility Final Safety Analysis Report (FBAR) & amends
- 7912120384 Forwards Revision 13 to FSAR, submitted as Amend 18 to OL application.
  CURTIS, N. W. Pennsylvania Power & Light Co. 79/12/12. 2pp.
- --7912120387 Revision 13 to FSAR, submitted as Amend 18 to OL application. \* Pennsylvania Power & Light Co. 79/12/12. 400pp.
- P. Operating license stage documents & correspondence
- 7912140057 Notification of 791212 meeting w/util & Pacific Northwest Labs to discuss NRC confirmatory piping analysis. PARR, O. D. Light Water Reactors Branch 3. 79/12/03. 2pp.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912060194 Forwards IE Insp Repts 50-387/79-26 & 50-388/79-14 on 790730-0831 No noncompliance noted. CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/10/32. 2pp
- ---7912060200 IE Insp Repts 50-387/79-26 & 50-388/79-14 on 790730-0831.No noncompliance noted Major areas inspected: RCPB, installation & storage of safety-related components & reactor pressure vassel recirculation sys mod. GALLO, R. M. Region 1, Philadelphia, Office of the Director, MCGAUGHY, R. W. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/10/11, 12pp.
- 7912140275 Responds to IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Considers it inappropriate to perform insp required on sys still under const.

  CURTIS.N. W. Pennsylvania Power & Light Co. 79/11/02. 1p.
- 7912050051 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves," No response required. ORIER.B.H. Region 1: Philadelphia, Office of the Director. 79/11/16. 1p.
- 7912050295 Forwards IE Info Notice 79-27, "Stoam Opnerator Tube Ruptures at Two PNR Plants " No response required. GRIER/B.H. Region I. Philadelphia. Office of the Director. 79/11/16. ip.
- 7912100145 Forwards IE Info Notice 79-28. "Dverloading of Structural Elements Due to Pipe Eupport Loads." No response required. GRIER, B.H. Region 1. Philadalphia, Office of the Director. 79/11/16. ip.
- 7912110461 Forwards IE Info Notice 79-29. "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. ORIER, B. H. Reginn 1. Philadelphia, Office of the Director. 79/11/19. 1p.
- 7912050282 Forwards IE Bullebin 79-26, "Boron Loss From BWR Control Blades." No response required. GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/11/20. ip.

- 7912260332 Ack receipt of 791102 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-387/79-25 & 50-388/79-13.

  ORIER.B.H. Region 1. Philadelphia, Office of the Director. 79/11/23. 1p.
- --7912260333 Responds to NRC 791012 ltr re violations noted in IE Insp. Repts 50-387/79-25 % 50-388/79-13. Corrective actions: regrading batch plant wash down area & rerouting effluents to controlled pathway where treated. CURTIS, N. M. Pennsylvania Power & Light Co. 79/11/02. 2pp.
- --7912260335 Forwards IE Insp Repts 50-387/79-25 & 50-388/79-13 on 790806-08 & notice of violation.
  SMITH.O.H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 79/10/12. 3pp.
- --7912260337 Notice of violation from insp on 790806-08.

  \* Region 1, Philadelphia, Office of the Director. 79/09/21.
  ip.
- --7912R&0339 IE Insp Repts 50-387/79-25 & 50-388/79-13 on 790806-08. Noncompliance noted:failure to follow procedures re dusting & failure to control erosion/sedimentation. SHANBAKY,M.M. BORES,R.J., TERC.N.M. Region i, Philadelphia, Office of the Director. 79/09/21. 7pp.
- 7912060586 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BMRs." No response required. GRIER, B.H. Region 1. Philadelphia, Office of the Director. 79/11/26. 1p.
- 7912110077 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director. 79/11/26. 1p.
- 7912190065 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Dus During Operation." No written response required. GRIER B.H. Region 1, Philadelphia, Office of the Director. 79/11/30. 1
- 7912310242 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, lOCFR21." No action required. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/12/06. 4pp.
- 7912190763 Forwards IE Bulletin 79-28, "Possible Malfunction of Nance Model EA180 Limit Suitches at Elevated Temps," Written response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director. 79/12/07. 1p.
- 7912280230 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required.
  GRIER.B.H. Region 1, Philadelphia, Office of the Director.
  79/12/13. ip.
- S. Reportable occurrences, LERs & related correspondence
- 7912130335 Ack receipt of 791011 interim rept re potential deficiency in Amphenol connectors & Gutler Hammer E-30 switches.
  CARLSON.R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/10/22.
- --7912130347 Interim deficiency rept re Amphenol connectors & Cutler Hammer E-30 switches Evaluation of faulty switch mechanisms will be submitted subsequent to GE & Bechtol evaluations. CURIIS.N.W. Pennsylvania Power & Light Co. 79/10/11. 2pp.
- 7912040351 Forwards final deficiency rept re connector pin crimping defects on control panel insert.

  CURTIS,N.W. Pennsylvania Power & Light Co. 79/11/28. 2pp.
- --7912040353 Final deficiency rept re panel inserts wiring & device damage. Caused by manufacturing personnel error & crimping tool malfunction resulting from inadequate QA. Connector pins repaired, reworked & tested.
  SISESTA.J., HOLLINGSHAW.H. Bechtel Power Corp. (subs. of Bechtel Corp.). 79/10/30. 40pp.
- 7912040507 Interim deficiency rept re violation of separation criteria for 4.14 kV switchgear. Problem may be generic. Followup rept to follow. CURTIS.N.M. Pennsylvania Power & Light Co. 79/11/29. 2pp.

- 7912050506 Interim deficiency rept re violation of separation criteria for 4, 16 kV switchgear. Caused by failure to delineate or incorporate separation requirements re project specs governing vendor wiring. Problem under review.

  CURTIS.N.W. Pennsylvania Power & Light Co. 79/11/29. 2pp.
- 7912140265 Interim deficiency rept re cable pulling activities. Requests extension until 800301 to file final definitive rept.
  CURTIS, N. W. Pennsylvania Power & Light Co. 79/12/10. 2pp.
- 7912270298 Forwards final deficiency rept re insulation damage to wiring in Control Room Inserts 72C & 73C which are part of offsite standby diesel generator controls GE evaluation encl.

  CURTIS, N. W. Pennsylvania Power & Light Co. 79/12/17. 1p.
- --7912270308 Final deficiency rept re insulation damage to wiring in control room inserts 72C & 73C which are part of defaite standby diesel generator controls. Caused by wire routing over steel barrier severing conductor insulation.
  \* Pennsylvania Power & Light Co. 79/12/17. 3pp.
- DOCKET 50-389 BT. LUCIE PLANT, UNIT 2
- A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PWRs & BMRs.
  Buccess of program depends on industry response Supports formation of owners groups to provide necessary info.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & DL review Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Quide 1. 101.
  VABBALLO.D.B. Division of Project Management. 79/11/21. 6pp.
- Q. Adjudicatory correspondence
- 7912110043 Forwards comments on NUREO-D511. Draft GEIS reflects conscious & deliberate NRC policy to joopardize public health & safety & thwart objectives of NEPA.

  MEPFORD: C. Environmental Coalition on Nuclear Power. 79/10/24.
  22aa.
- 7912140177 Requests name & affiliation of each individual visiting sys control ctr on 791211. Info should be received by 791206. Cartificate of Syc encl. BAUSER, M. A. Lowenstein, Newman, Reis, Axelrad & Toll. 79/11/21. 4pp.
- 7912270147 Notifies that intervenors will not present testimony of R Pollard of UCB at 791211 hearing. Forwards newspaper article treating D Bridenbaugh views re safety implications of gower failures, since prefiling testimony infeasible. HODDER, M. H. Hodder, M. H. 79/11/27. 2pp.
- --7912270150 First set of interrogatories. Requests info re sys-wide power failures, offsite power failures, failure to provide intertie w/OA Power Corp, test results & performance records. Cestificate of Eve encl. HODBER.M.H. Hodder,M.H. 79/11/27. App.
- 7912140062 Memorandum & order specifying Coral Gables.FL as location of evidentiary hearing re stability of applicant electrical grid & adequacy of plant emergency power supplies.
  BISHOP. C. J. Atomic Safety and Licensing Appeal Panel. 79/11/29.
  200.
- 7912190120 Responds to 791121 request for names & positions of ASLAB personnel intending to visit applicant sys control ctr on 791211. HC Ferrar, RB Salzman & WR Johnson will visit ctr. BISHOP, C. J. Atomic Bafety and Licensing Appeal Panel. 79/12/04. 1p.
- 7912180393 Responds to NRC 791105 ltr re violations noted in IE Insp Rapt 50-389/79-18 Corrective actions: initiated QC receipt insp. UMRIG.R.E. Florida Power & Light Co. 79/11/21. 3pp.
- 791227009B Response to intervenor interrogatories.Lists sys-wide & offsite power disturbances occurring within past 10 yrs.
  States reasoning for not interconnecting w/GA Power Co.
  Certificate of Svc encl.
  PEARSON.O.F. Florida Power & Light Co. 79/12/07. 12pp.

- M. Antitrust correspondence
- 7912200287 Discovery rept for intervenor FL Cities Intensive settlement negotiations conducted w/otil/DOJ.NRC & Orlando Util Commission. Sufficient likelihood of settlement w/Orlando to justify suspension of discovery JABLON.R.A. Florida Cities. JABLON.R.A. Spiegel & McDiarmid. 79/11/20. 1p
- 7912110345 Answer to FL Cities 791116 motion to lodge FERC 790803 opinion re whether to conduct proceeding under Atomic Energy Act Section 105(a) Does not appose lodging per NRC 790823 previous answer.

  DEWEY, L. S. Antitrust Division 79/12/06 3pp
- P. Operating license stage documents & correspondence
- 7912180243 Urges expeditious review & safety evaluation of RETRAN reactor sys transient analysis code List of intended uses of RETRAN enct.

  UHRIG, R.E. Florida Power & Light Co. 79/12/07. 3pp.
- G. Inspection reports, IE Builetins & correspondence
- 7912100260 Forwards IE Insp Repts 50-333/79-27 & 50-389/79-17 on 791002-04. No noncompliance noted.

  SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Naterials Safety Branch. 79/10/22. 2pp.
- --7912100274 IE Insp Repts 50-335/79-27 & 50-389/79-17 on 791002-04. No noncompliance noted Major areas inspected mgt controls, environ monitoring stations & analytical measurements. PEERY, M. M. Region 2. Atlanta. Office of the Director. RUFHAM, J. W. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 79/10/19. 3pp.
- 7912060143 Forwards IE Info Notice 79-12A, "Attempted Damage to New Fuel Assemblies." No specific action or response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/11/09. 2pp.
- 7912310281 Forwards IE Insp Rept 50-389/79-19 on 791022-25.No noncompliance noted. MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 79/11/09 2pp
- --7912310288 IE Insp Rept 50-389/79-19 on 791022-25. No moncompliance noted Major areas inspected action on previous insp findings, independent insp of const activities & inspector followup items.

  BURDETTE, T.E. Region 1. Philadelphia, Office of the Director.

  BRYANT, J. C. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/11/08. App.
- 7912140527 Responds to IE Bulletin 79-23. Failure of emergency diesel generator field excitor transformer precluded by absence of direct circuit between transformer & generator neutral FSAR re preoperational testing scheduled for Mar 1980.

  UHRIGER, E. Florida Power & Light Co. 79/11/13. 1p.
- 7912100181 Forwards IE Info Notice 79-28, "Uverloading of Structural Elements Due to Pipe Bupport Loads." No response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/16. ip.
- 7912110561 Forwards IE Info Notice 79-29. "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required. O'RETLLY.U.P. Region 2. Atlanta, Office of the Director. 79/11/16. 2pp.
- 7912060616 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No response required.

  O'REILLYJJ.P. Region 2. Atlanta. Office of the Director.
  79/11/26. ip.
- 79:2110147 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required.

  O'REILLY,J.P. Region 2, Atlanta, Office of the Director.
  79/11/26. 1p.
- 7912110193 Ack receipt of 791101 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-389/79-14. MURPHY.C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/11/26. 1p.

- --79]2110199 Responds to NRC 791012 ltr re violations noted in IE Insp Rept 50-389/79-14 Corrective actions: weld rod near base of safety injection pump supports gathered & dispused of & not used in fabrication. UHRIO,R.E. Florida Power & Light Co. 79/11/01. 3pp.
- --7912110203 Forwards IE Insp Rept 50-389/79-14 on 790911-14 & notice of violation. HURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 79/10/12. 2pp.
- --7912110210 Notice of violation from insp on 790911-14, \* Region 2, Atlanta, Office of the Director. 79/10/12. 1p.
- --7912110214 IE Insp Rept 50-389/79-14 on 790911-14. Noncompliance noted: control of weld electrodes. ECONOMUS.N. Region 2. Atlanta. Office of the Director. HERDT, A.R. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 79/10/12. 7pp.
- 7912190447 Forwards IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." No written response required. G'REILLY.J.P. Region 2. Atlanta, Office of the Director. 79/11/30. 1p.
- 7912180347 Ack receipt of 791121 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-389779-18.

  MMRPNY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/12/05. lp.
- --7912180357 Forwards IE Insp Rept 50-389/79-18 on 791009-12 & notice of violation MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 79/11/05. 3pp.
- --7912180351 Notice of vicilation from insp on 791009-12.

  Region 2. Atlanta, Office of the Director. 79/10/31. 1p.
- --7912180367 IE Insp Rept 50-389/79-18 on 791007-12.Noncompliance noted: failure to procure protective coating maths as safety-related items & failure to initiate nonconformance rept & place discrepant math in hold area.

  LEMAHAN.J.J. Region 2. Atlanta, Office of the Director.

  CONLON.T.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/10/31. 5pp.
- 7912310297 Forwards IE Info Notice 79-30. "Reporting of Defects & Moncompliances, 10CFR21." No action required. O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 79/12/06. Spp.
- 7912200033 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Hodel EA180 Limit Switches at Elevated Temps." Action required. D'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/12/07. 200.
- 7912310067 Ack receipt of 791203 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-389/79-20.
  SUTHERLAND.J.T. Region 2. Atlanta. Fuel Facility & Materials
  Safety Branch. 79/12/07. lp.
- --7912310072 Responds to NRC 791123 ltr re violations noted in IE losg Rept 30-389/79-20. Corrective actions: qualified person assigned to maintain daily log when environ control engineer not on site. UHR10, R. E. Florida Power & Light Co. 79/12/03. 2pp.
- ---7912310076 Forwards IE Insp Rept 50-389/79-20 on 791101-02 & notice of violation. SUTHERLAND.J.T. Region 2: Atlanta: Fuel Facility & Materials Safety Branch. 79/11/23. 2gp.
- --7912310081 Notice of violation from insp on 791101-02.
  \* Region 2. Atlanta. Office of the Director. 79/11/23. 1p.
- ---7912310086 IE Insp Rept 50-389/79-20 on 791101-02. Noncompliance noted: failure to maintain daily log of site surveillance, findings & environ protection activities.

  CUNNINGHAM.A.L. Region 2. Atlanta, Office of the Director.

  JENKINS.G.R. Region 2. Atlanta, Fuel Facility & Materials

  Bafety Branch. 79/11/23. 3pp.
- 7912280402 Forwards IE Info Notice 79-31, "Uso of Incorrect Amplified Response Spectra." No written response required.
  O'REILLY,J.P. Region 2, Atlanta, Office of the Director.
  79/12/13. 2pp.

- 7912280136 Forwards IE Circular 77-25, "Shock Arrestor Strut Assembly Interference." No written response required. O'RETLLY, J. P. Region 2, Atlanta, Office of the Director. 79/12/20. 4pp.
- T. Hearing transcripts on non-antitrust matters
- 7912210314 Forwards testimony of PW Baranowsky in response to ASLAB Question I re station blackout PW Baranowsky will be available as witness at hearings commencing on 791211. GLMSTEAD.W.J. Hearing Branch 4. 79/11/09. 1p.
- --7912210324 Testimony of PW Baranowsky in rusponse to ABLAB Question By re station blackout Statement of professional qualifications encl.

  BRANOWSKY, P. W. Probabilistic Analysis Staff. 79/11/09. 9pp.
- 7912200601 Transcript of 791211 bearing in Coral Gables, Ft. Pp 1-142. FARRAR, M., SALZMAN, R., JOHNSON, R. Commission. 79/12/11. 143pp.
- 7912200613 Transcript of 791212 hearing in Coral Gables,FL.Pp 143-394. FARRAR.M., SALZMAN,R., JOHNSON,R. Commission. 79/12/12. 252pp.
- 7912200625 Transcript of 791213 hearing in Coral Gables, FL. Pp 375-744. FARRAR, M., BALZMAN, R., JOHNSBN, R., Commission. 79/12/13. 360pp.
- 7912200587 Transcript of 791214 hearing in Coral Gables, FL. Pp 745-886. FARRAR, M., BALZMAN, R., JOHNSON, R. Commission. 79/12/14. 141pp.
- DOCKET 50-390 WATTS BAR NUCLEAR PLANT, UNIT 1
- A. Application/construction stage documents & correspondence
- 7912110Dii Forwards NRC position on status & applicability to pending GL applications of results of TMI followup actions. Outlines addl short-term actions to be taken.
  VASBALLO.D.B. Division of Project Management. 79/09/27.
- 7912110264 Discusses NRC plans to use generic analyses to develop early varification program to resolve ATMS issue for PMRs & BMRs.
  Success of program depends on industry response. Supports formation of comers groups to provide necessary info.
  DENTON, M. R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.
- 7712110005 Forwards proposed Revision 2 to Reg Ouide 1.97.
  "Instrumentation for Light Water Cooled Nuclear Pawer Plants to Assess Plant & Environs Conditions During & Following Accident." Requests comment.
  VANDA.S.A. Assistant Director for Light Water Reactors. 79/11/23.
- 7912130023 Notification of 800110 meeting w/util to discuss raporting level of util GA & manæger & GA review of documents.
  SPRAUL, J. O. Quality Assurance Branch. 79/12/05. ip.
- 7912270356 Forwards addl info requested in 791029 ltr re qualification of resistance temp detectors field connections & remote bellows sensing containment pressure transmitters. Info to be incorporated into Amend 42 of FSAR.

  MILLS, L. M. Tennessee Valley Authority. 79/12/19. 7pp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Guide 1.101.
  VASSALLO, D. B. Division of Project Management. 79/11/21. 6pp.
- G. Inspection reports. 1E Bulletins & correspondence
- 7912070056 Forwards IE Insp Repts 50-390/79-34 & 50-391/79-29 on 790919-21. No noncompliance noted. MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/10/22. 2pp.
- --7912070067 IE Insp Repts 50-390/79-34 & 50-391/79-29 on 790919-21 No noncompliance noted Major areas inspected conditions adverse to quality reporting & implementation of nonconformance repts.
  WRIGHT: R. M. NRC Regional Offices. CANTRELL, F. B. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/10/19. 3pp.

- 7912040448 Forwards suppl response to IE Bulletins 78-12.78-12A & 78-12B re attpical weld math in reactor pressure vessol usids. Hestinghouse generic rept submitted 791027 covers plants. Final response by 800125.
  HILLB.L.M. Tennessee Valley Authority. 79/10/28. 2pp.
- 7712310093 Forwards IE Insp Repts 50-390/79-38 & 50-391/79-32 on 791016-19. No noncompliance noted.
  NURPHY, C. E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/11/08. 2pp.
- --7912310100 IE Insp Repts 50-390/79-38 & 50-391/79-32 on 791016-19. No noncompliance noted Major areas inspected: pipe support base plate designs using concrete expansion anchor bolts & licensee identified items.
  VALLISH, E. J. Region 2. Atlanta, Office of the Director.
  HERDY, A. R. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/11/08. 3pp.
- 7912060163 Forwards IE Info Notice 79-12A, "Attempted Damage to New Fuel Assemblies." No specific action or response required. O'REILLY,J.P. Region R, Atlanta, Office of the Director, 79/11/09. 3pp.
- 7912110202 Forwards response to 790330 ltr & IE Bulletin 79-04 re Velan valves.Correct weight valves installed Piping & supports reviewed using correct valve weights.

  HILLE, L. H. Tennessee Valley Authority. 79/11/09. 20pp.
- 7912070499 Forwards IE Info Notice 79-27, "Bteam Generator Tube Ruptures at Two PWR Plants." O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/16. 14pp.
- 7912100192 Forwards IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads." No response required. O'REILLYs J.P. Region 2, Atlanta, Office of the Director. 79/11/16. 1p.
- 79:12:10875 Forwards IE Info Notice 79-29. "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required. O'REILLY-J.P. Region 2. Atlanta. Office of the Director. 79/11/16. 2pp.
- 7912310307 Forwards IE Insp Rept 50-390/79-46 on 791031-1102.No noncompliance noted. LEWIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/11/16. 2pp.
- --7912310318 IE Insp Rept 50-390/79-46 on 791031-i102. No noncompliance noted Major areas inspected: review of preoperational test procedures review of new fuel receipt & insp & storage dacumentation.

  BELIBLE, O. A., DONAT. T. J. Region 2, Atlanta, Office of the Director. DANCE M. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/11/16. Spp.
- 7912060620 Forwards IE Circular 79-24, "Proper Installation & Calibr of Cora Boray Pipe Break Datection Equipment on BHRs," No response required.
  0'RELLLYJJ.P. Region 2, Atlanta, Office of the Director.
  79711726. ip.
- 7912110157 Forwards IE Circular 79-23, "Hotor Btarters & Contactors Failed to Operate." No response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/11/26. 1p.
- 7912050265 Ack receipt of 791023 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/79-33 & 50-391/79-28.
  HURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch. 79/11/29. 2pp.
- --79120602B7 Forwards IE Insp Rept 30-370/79-33 & 50-391/79-28 on 790801-0907 & notice of violation. MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 79/10/01. 2pp.
- --7912060291 Notice of violation from insp on 790801-0907.

  \* Region 2, Atlanta, Office of the Director. 79/09/30. ip.
- --7912060299 IE Insp Repts 50-390/79-33 & 50-391/79-28 on 790801-0907.
  Noncompliance noted: failure to follow procedures for use of dynamometer in cable pulling.
  COCHRAN. 8. J., THOMAS.M. Region 2, Atlanta, Office of the Director. CANTRELL, F. S. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/09/30, 5pp.

- 7912200003 Supplements 790514 initial response to IE Bullotin 79-03 roughld defects in pipe spools. M/o encl.
  MILLS, L. M. Tennessae Valley Authority, 79/11/29, 1p.
- 7912190472 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation." Written response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/30. 1p.
- 7912310316 Forwards IE Info Notice 79-30. "Reporting of Defects & Noncompliances, 10CFR21." No action required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/12/06. 6pp.
- 7912200060 Forwards IE Bulletin 79-28, "Possible Halfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. D'REILLY.J.P. Region 2. Atlanta, Office of the Director. 79/12/07. 3pp.
- 7912310008 Forwards final response to IE Bulletin 78-128. "Atypical Weld Matl in Reactor Pressure Vessel Welds." Util has reviewed 791029 Westinghouse rept & is satisfied that all specific vessel info required by bulletin included. MILLS.L.M. Tennessee Valley Authority. 79/12/11. 2pp.
- 7912280426 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Epectra." No written response required. O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 79/12/13. 3pp.
- 79:12280150 Forwards IE Circular 79-25, "Shock Arrestor Strut Assembly Interference." No written response required. D'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/12/20. 4pp.
- R. Periodic operating reports & related correspondence
- 7912130258 Forwards "Environ Radioactivity Levels, 1978." MILLS, L. M. Tennessee Valley Authority. 79/12/05. 1p
- --7912130268 "Environ Radioactivity Lovels, 1978." \* Tennesses Valley Authority. 79/11/30. 50pp.
- 8. Reportable occurrences. LERs & related correspondence
- 7912200488 PNS-II-79-004: on 791016, licenses discovered that unknown individual glaced 3/16-inch iron wire around 480 volt ac bus to power distribution power in plant auxiliary bldg. Touching wire could have damaged board & caused injury. BESECHER, K. CANTRELL, F. S. Region 2, Atlanta, Office of the Director. 79/10/17. lp.
- 7912050513 Forwards first interim deficiency rept re surface cracks in Loop 1 steam generator. MILLS.4. M. Tennessee Valley Authority. 79/11/23. lp.
- --7912050516 Interim deficiency ropt re surface cracks in Loop 1 steam generator. Cause not stated. Util & Westinghouse evaluating scope of required repair work. Westinghouse requested to determine cause of cracks.

  \* Tennessee Valley Authority. 79/11/23. 1p.
- 7912050477 Third interim deficiency rept re diesel generator turbocharger lubrication. Insp of trubocharger on emergency diesel generators incomplete. Following completion of alignment & mods, insp will be conducted. MILLS.L.M. Tennessee Valley Authority. 79/11/28. ip.
- 7912050484 Second interim deficiency rept re refueling water storage tank overflow line not fabricated to ASME code. Following receipt & evaluation of repair procedures, corrective action statement will be prepared.

  MILLS, L. M. Tennessee Valley Authority. 79/11/29. ip.
- 7912190620 Second interim deficiency rept re piles supporting essential raw cooling water pipe slab not driven to drawing specs. Pile load test will be conducted on existing piling. Next rept will be submitted by 80041.

  HILLS.L.M. Tennessee Valley Authority. 79/11/30. ip.
- 7912170313 Forwards final deficiency rept re incorrectly performed pressurizer safety & relief line blowdown analysis.
  HILLB.L.M. Tennessee Valley Authority. 79/12/07. ip.

- 7912170317 Forwards final deficiency rept re RHR pump motor svc factor. MILLS,L.M. Tennessae Valley Authority. 79/12/07. 1p.
- --7912170323 Final deficiency rept re excessive svc factor on RHR pump motors. Flow restrictions added in HHR pump hot leg & cold leg injection headers to provide pressure drop necessary to prevent pump motor overloading.
  MiLts.L.M. Tennessee Valley Authority. 79/12/07. 1p.
- 79(2)70324 Supplemental info re ROs-50-390/79-25-01 & 50-391/79-21-01 re alignment bead welds. Unauthorized or undocumented alignment bead welds will be nonconformed & depositioned in accordance w/approved procedures.

  MILLS.L.M. Tennessee Valley Authority. 79/12/07. ip.
- 7912280581 Forwards first interim deficiency rept re control rod drop events. MILLS, L.M. Tennessee Valley Authority. 79/12/17. 1p.
- --7912280990 First interim deficiency. Dropped rod accident analyses methodology affected nonconsprvatively by power distribution & reactivity insertion profiles. Extensive evaluation required to establish analytical safety margins.

  # Tennessee Valley Authority. 79/12/17. ip.
- 7912270480 Forwards supplemental response re cable terminations in junction boses inside containment.
  MiLLS.L.M. Tennessee Valley Authority. 79/12/18. ip.
- ---7912270484 Supplemental response to deficiency rept re exception to commitment to replace cable terminations in junctions boxes inside containment w/splices for Class IE circuits.

  Terminations preferable for resistance temp detectors.

  \* Tennessee Valley Authority. 79/12/18. 1p.
- DOCKET 50-391 WATTS DAR NUCLEAR PLANT, UNIT 2

  A. Application/construction stage documents & correspondence
- 7912110011 Forwards NRC position on status & applicability to pending OL applications of results of TMI followup actions Outlines add1 short-term actions to be taken. VASSALLO,D.B. Division of Project Management. 79/09/27. 41pp.
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATWS issue for PWRs & BWRs.
  Success of program depends on industry response. Supports formation of numers groups to growide necessary info.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.
- 7912110005 Forwards proposed Revision 2 to Reg Guide 1.97,
  "Instrumentation for Light Mater Cooled Nuclear Power Plants
  to Assess Plant & Environs Conditions During & Following
  Accidant." Requests commont.
  VARGA.S.A. Assistant Director for Light Water Reactors. 79/11/23.
- 7912130023 Notification of 800110 meeting w/util to discuss reporting level of util 8A & manager & 8A review of documents.

  SPRAUL, J. G. Guality Assurance Branch. 79/12/05. 1p.
- 7912270356 Forwards addl info requested in 791029 ltr re qualification of resistance temp detectors field connections & remote bellows sensing containment pressure transmitters. Info to be incorporated into Amend 42 of FSAR.
  MILLS.L.B. Tennessee Valley Authority. 79/12/19. 7pp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Guide 1. 101. VABSALLO, D.B. Division of Project Management. 79/11/21. App.
- Q. Inspection reports. IE Bulletins & correspondence
- 7912070056 Forwards IE lnsp Repts 50-390/79-34 & 50-391/79-29 on 790919-21. No noncompliance note6. MRPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 79/10/22. 2pp.

- --7912070067 IE Insp Repts 50-390/79-34 & 50-391/79-29 on 790919-21.No nancompliance noted Major areas inspected:conditions adverse to quality reporting & implementation of nanconformance repts.
  WRIGHT, R. W. NRC Regional Offices. CANTRELL, F. S. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/10/19. 3pp.
- 7912040448 Forwards suppl response to IE Bulletins 78-12,78-12A & 78-12B re atypical weld matl in reactor pressure vessel welds. Westinghouse generic rept submitted 791029 covers plants. Final response by 800125.

  MILLS,L.M. Tennessee Valley Authority. 79/10/28. 2pp.
- 7912310093 Forwards IE Insp Repts 50-390/79-38 & 50-391/79-32 on 791016-19 No noncompliance noted. MURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/11/08. 2pp.
- --7912310100 le Insp Repts 50-370/79-38 & 50-391/79-32 on 791016-19.No noncompliance noted Major areas inspected: pipe support base plate designs using concrete expansion anchor bolts & litensee identified items.

  VALLISH E. J. Region 2. Atlanta, Office of the Director, HERDT.A.R. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/11/08. 3pp.
- 7912060163 Forwards IE Info Notice 79-12A. "Attempted Damage to New Fuel Assemblies." No specific action or response required. O'REILLY,J.P. Region 2, Atlanta, Office of the Director. 79/11/09. 3pp.
- 7912110202 Forwards response to 790330 itr & IE Bulletin 79-04 re Velan valves. Correct weight valves installed Piping & supports reviewed using correct valve weights.

  MILLS.L.M. Tennessee Valley Authority. 79/11/09. 20pp.
- 7912070499 Forwards IE Info Notice 79-27, "Steam Generator Tube Ruptures at Two PMR Plants." O'REILLY,J.P. Region 2, Atlanta, Office of the Director. 79/11/16. 14pp.
- 7912100192 Forwards IE Info Notice 79-28, "Overloading of Btructural Elements Due to Pipe Support Loads," No response required. D'REILLY,J.P. Region 2, Atlanta, Office of the Director. 79/11/16. ip.
- 7912110575 Forwards IE Info Notice 79-29. "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation Ouring Operation." No specific action or response required. O'REFLLY,J.P. Region 2, Atlanta, Office of the Director. 79/11/14. 2pp.
- 7912060620 Forwards IE Circular 79~24, "Proper Installation & Calibr of Care Spray Pips Break Detection Equipment on BWRs." No response required.
  0/REILLY,J.P. Hegion 2, Atlanta, Office of the Director.
  79/11/26. ip.
- 7912110157 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. D'REILLY,J.P. Region 2, Atlanta, Office of the Director. 79/11/26. jp.
- 7912060266 Ack receipt of 791023 ltr informing NRC of steps taken to correct violations noted in IE Inep Repts 50-390/79-33 & 50-391/79-28.

  MURPHY, C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/11/29. 2pp.
- ---7912060287 Forwards IE Insp Rept 50-390/79-33 & 50-391/79-28 on 790801-0907 & notice of violation.
  MURPHY.C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/10/01. Spp.
- --7912060291 Notice of violation from insp on 790801-0907.

  \*\* Region 2, Atlanta, Office of the Director. 79/09/30. | Ip.
- --7912060299 IE Insp Repts 50-390/79-33 & 50-391/79-28 on 790801-0907.
  Noncompliance noted: Pailure to follow procedures for use of dynamometer in cable pulling.
  COCHRAN, B. J., THOMAS, M. Region 2. Atlanta, Office of the Director. CANTRELL.F.S. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/09/30. Spp.
- 7912200003 Supplements 790514 initial response to IE Sulletin 79-03 re weld defects in pipe spools. W/o encl.
  MILLS.L.M. Tennessee Valley Authority. 79/11/29. ip.

- 7912190478 Forwards IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." No written response required. O'REILLY J.P. Region 2. Atlanta, Office of the Director. 79/11/30. 19.
- 7912310316 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action required.
  O'RRILLY, J.P. Region 2, Atlanta, Office of the Director.
  79/12/06. 6pp.
- 7912200060 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Buitches at Elevated Temps." Action required.

  D'REILLY, J.P. Region 2, Atlanta, Office of the Director.
  79/12/07. 3pp.
- 791231000B Forwards final response to IE Bulletin 78-12B, "Atypical Weld Matl in Reactor Pressure Vessel Welds." Util has revisued 791029 Westinghouse rept & is satisfied that all specific vessel info required by bulletin included.
  MILLB.L.M. Tennessee Valley Authority. 79/12/11. 2pp.
- 7912280426 Forwards IE Info Notice 79-3i, "Use of Incorrect Amplified Response Spectra." No written response required.
  D'REILLY, J.P. Region 2, Atlanta, Office of the Director.
  79/12/19. 3pp.
- 7912280150 Forwards IE Circular 79-29. "Shock Arrestor Strut Assembly interference." No written response required. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 79/12/20. 4pp.
- A. Periodic operating reports & related correspondence
- 7912130258 Forwards "Environ Radioactivity Levels.1978." HILLS, L. M. Tennessee Valley Authority. 79/12/05. ip.
- ---7912130268 "Environ Radioactivity Levels,1978." \* Tennessee Valley Authority, 79/11/30. Sopp.
- 8. Reportable occurrences, LERs & related correspondence
- 7912050513 Forwards first interim deficiency rept re surface cracks in toop 1 steam generator.

  HILLS.L.M. Tennessee Valley Authority. 79/11/23. 1p.
- --7912050515 Interim deficiency rept re surface cracks in Loop i steam generator Cause not stated Util & Westinghouse evaluating scope of required repair work Westinghouse requested to detarmine cause of cracks.

  \* Tennessee Valley Authority. 79/11/23. ip.
- 7912050477 Third interim deficiency rept re diesel generator turbocharger lubrication. Insp of trubocharger on emergency diesel generators incomplets. Following completion of alignment & mods, insp will be conducted.

  MILLS, L. M. Tennessee Valley Authority. 79/11/28. 1p.
- 7912050484 Second interim deficiency rept re refueling water storage tank overflow line not fabricated to ASME code.Following receipt & evaluation of repair procedures, corrective action statement will be prepared.

  NILLS, L. M. Tannesse Valley Authority. 79/11/29. 1p.
- 7912190620 Second interim deficiency rept re piles supporting essential rew cooling water pipe slab not driven to drawing specs. Pile load test will be conducted on existing piling. Next rept will be submitted by 800411.

  HILLS, L. M. Tennessee Valley Authority. 79/11/30. ip.
- 7912170313 Forwards final deficiency rept re incorrectly performed pressurizer safety & relief line bloudown analysis.
  HFLLS.L.M. Tennessee Valley Authority. 79/12/07. 1p.
- --7912170318 Final deficiency rept re incorrectly performed pressurizer safety & relief line blowdown analysis. Reanalysis revealed 10 supports needing redesign one support needing relocation & need for add1 supports.

  \* Tennessee Valley Authority. 79/12/07. 1p.
- 7912170317 Forwards final deficiency rept re RHR pump motor svc factor. MILLS, L. M. Tennessee Valley Authority. 79/12/07. 1p.

- --7912170323 Final deficiency rupt re excessive svc factor on NHR pump motors. Flow restrictions added in NHR pump hat leg & cold leg injection headers to provide pressure drap necessary to provent pump motor overloading MILLS.L.M. Tennessee Valley Authority. 79/12/07. 1p.
- 7912170324 Supplemental info re ROs-50-390/79-29-01 & 50-391/79-21-01 re alignment bead welds. Unauthorized or undocumented alignment bead welds will be nonconformed & depositioned in accordance w/approved procedures.

  MILLS, L. M. Tennessee Valley Authority. 79/12/07. 1p.
- 7912280581 Forwards first interim deficiency rept re control rod drop events. MILLS, L.M. Tennessee Valley Authority. 79/12/17. 1p.
- --7912280590 First interim deficiency Dropped rod accident analyses methodology affected Approach and provided by power distribution & reactivity insortion profiles. Extensive evaluation required to establish analysical safety margins.

  8 Tennessee Valley Authority. 79/12/17. Ip.
- 7912270480 Forwards supplemental response re cable terminations in junction boyes inside containment.
  MILLS, L. M. Tennessee Valley Authority. 79/12/18. 1p.
- --7912270484 Supplemental response to deficiency rept re asception to commitment to replace cable terminations in junctions boxes inside containment w/splices for Class IE circuits. Terminations preferable for resistance temp detectors.

  \* Tennessee Valley Authority. 79/12/18. 1p.
- DOCKET 50-394 CALIFORNIA STATE POLYTECH COLLEGE RES. REACTOR

  F. Security, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Guide 5.XX. "Std Format & Content for Licensee Physical Security Plan for Protection of ENM of Hoderate or Low Strategic Significance." W/s encl. REID.R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22.
- DOCKET 50-395 VIROLL C. SUMMER NUCLEAR STATION, UNIT 1

  A. Application/construction stage documents & correspondence
- 7912110011 Forwards NRC position on status & applicability to pending OL applications of results of TMI followup actions Outlines addl short-term actions to be taken.

  VASSALLO, D. B. Division of Project Management. 79/09/27. 41pp.
- 7912110264 Distusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRs & BMRs. Success of program depends on industry response. Supports formation of owners groups to provide necessary info. DENTON, H. R. Dffice of Nuclear Reactor Regulation. 79/10/17. 3pp.
- 7912030028 Summary of 791031 moveting w/util.Qilbert/Commonwealth Associates & BNL at facility re familiarization w/facility & design info for stresses in balance-of-plant piping sys. TIBBETTS.D.L. Light Water Reactors Branch 2, 79/11/15. Spp.
- 7912110136 Forwards proposed Revision 2 to Reg Quide 1.97,
  "Instrumentation for Light Mater Cooled Nuclear Power Plants
  to Assess Plant & Environs Conditions During & Following
  Accident." Requests comment.
  VARGA: S. A. Assistant Director for Light Mater Reactors. 79/11/23.
  3pp.
- 79(2140185 Summary of 791025 meeting w/util,Naval Research Lab. Wastinghouse & Oitbert/Commonwealth to discuss seismic qualification of electrical & mechanical components. TIBBITTS,D.L. Light Water Reactors Branch 2, 79/12/03, 7pp.
- C. Utility Environmental Report (ER), amends & correspondence
- 7912270061 Forwards updated distribution list for environ repts & amends.
  DUNCAN.M. Environmental Projects Branch 2. 79/12/06. Spp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & Ot. review. Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Guide 1.101.
  VASSALLO, D. B. Division of Project Management. 79/11/21. 6pp.

- 7912310286 Summary of 791107 meeting w/util & Gilbert/Commonwealth rediscussion of request for info issued to util resulting from site visit for fire protection review.

  TIBHITTS.D.L. Light Water Reactors Branch 2. 79/12/17. 6pp.
- 7912210166 Forwards Revision 4 to fire protection evaluation of fire hazards analysis rept.
  CREWS,E.H. South Carolina Electric & Gas Co. 79/12/20. 1p.
- --7912210167 Revision 4 to fire protection evaluation of fire hazard analysis rept.
  \* South Carolina Electric & Gas Co. 79/12/20. 4lpp.
- 0. Adjudicatory correspondence
- 7912130ii5 Request for dismissal of intervenor g Bursey & contentions due to failure to provide for discovery & abids by ASLD orders. Certificate of Svc encl.
  CONNER. T.B., RADER.R.M. South Carelina Electric & Gas Co.
  CONNER. T.B. Conner, Hoore & Corber. 79/11/29. 10pp.
- 7912210403 Motion to schedule B00122 hearing on pending issues. Seeks exemption from FEB requirement if ASLB determines that Contention A-9 may not be subj to hearing prior to FES filing. Certificate of Svc ontl. CONNER.T.B. South Carolina Electric & Gas Co. CONNER.T.B. Conner. Moore & Corber. 79/12/17. 7pp.
- 7912260260 Response in opposition to applicant 791129 motion for dismissal of intervenor B Bursey contentions. Urges that alternative relief requiring intervenor to submit summaries of proposed testimony be granted. Certificate of Svc encl. GOLDBERO, S. C. Hearing Branch 2. 79/12/17. 7pp.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 7912030145 Forwards Amend 16 to FSAR.
  CREMS.E.H. South Carolina Electric & Gas Co. 79/11/30. 2pp.
- ---7912030147 Amend 14 to FSAR.

  \* South Carolina Electric & Gas Co. 79/11/30. 120pp.
- 0. Inspection reports, IE Bulletins & correspondence
- 7912070099 Forwards IE Insp Rept 50-395/79-29 on 790925-27.No nancampliance noted. LEMIS,R.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 79/10/22. 2pp.
- --7912070105 IE Insp Rept 50-395/79-29 on 790925-27. No noncompliance noted Hajor areas inspected: preoperational test procedure, preoperational test witnessing & previous insp open items. DONAT. I.J. Region 2, Atlanta, Office of the Director. BURNETT, P.T. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/10/17. 4ap.
- 7912110049 Responds to IE Bulletin 79-14.Revision 1.Suppl 2.re seismic analysis for piping sys.Piping sys design specs & procedures listed.Halkdown insp checklist encl.
  CREWS,E.H. South Carolina Electric & Oas Co. 79/10/30. 5pp.
- 7912060159 Forwards IE Info Notice 79-12A, "Attempted Damage to New Fuel Assemblies." No specific action or response required. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 79/11/09. 2pp.
- 7912280152 Forwards IE Insp Rept 30-395/79-31 on 790915-1012.No noncompliance noted. LEMIS.R.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 79/11/14. 2pp.
- --7912280157 IE Insp Rept 50-395/79-31 on 790915-1012. No noncompliance noted. Hajor areas inspected: preoperational test procedure, inservice insp program, safety relation component receipt insp & followup on open items, KELLOGO.P.J., SKOLDS.J.L., Region 2, Atlanta, Office of the Director. 79/11/13. App.
- 7912100200 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. O'REILLY, J. P. Region 2, Atlanta. Office of the Director. 79/11/16. ip.
- 791211056B Forwards IE Info Notice 79-29, "Loss of Nonsefety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required. O'RETLLY.J.P. Region 2. Atlanta, Office of the Director. 79/11/16. 2pp.

- 7912110570 Forwards IE Info Notice 79-29, "Loss of Nonsefety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/11/16. 2pp.
- 7912310325 Forwards IE Insp Rept 50-395/79-32 on 791030-1102.No noncompliance noted. MURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/11/16. 2pp.
- --7912310331 IE Insp Rept 50-395/79-32 on 791030-1102. No noncompliance noted. Hajor areas inspected: safety-related electrical cable installation & GC records & safety-related instrumentation installation & GC records.

  RUFF.A.B. Region 2, Atlanta, Office of the Director, CONLONIT.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch, 79/11/16. 3pp.
- 7912040419 Forwards IE Circular 79~24, "Proper Installation & Calibr of Care Byray Pipe Break Detection Equipment on BWRs." No response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/24. 10
- 7912110154 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/26. 1p.
- 7912100463 Ack receipt of IE Insp Rept 50-395/79-33 on 791017. Na proprietary info. JOHNSON, M.C. Bouth Carolina Electric & Gas Co. 79/11/28. ip.
- --7912100464 Forwards IE Insp Rept 50-395/79-33 on 791017. No noncompliance noted. SUTHERLAND.J. T. Region 2. Atlanta. Fuel Facility & Materials Bafety Branch. 79/11/06. 2pp.
- --7912100467 IE Insp Rept 50-395/79-33 on 791017. No noncompliance noted. Major areas inspected: mgt meeting discussing IE insp program related to radiation protection & radwaste mgt & brief plant tour.

  JENKINS, O. R., OIBSON, A. F. Region 2, Atlanta, Office of the Director. 79/11/02. 2pp.
- 7912060581 Ack receipt of 791115 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-395/79-30.

  MURPHY, C. E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/11/29. 1p.
- --7712060885 Responds to NRC 791024 ltr re violations noted in IE lnsp Rept 30-395/79-30. Corrective actions: operating procedures being addified per 10CFR21. (4)(3). Completion by 791231. JUHNSON. H. C. Bouth Caroline Electric & Gas Co. 79/11/15. 2pp.
- --7912060587 Forwards IE Insp Rept 50-395/79-30 on 791001-04 & notice of violation. MURPHY.C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/10/24. 2pp.
- --7912060589 Notice of violation from insp on 791001-04.

  \* Region 2. Atlanta, Office of the Director. 79/10/24. lp.
- --7912060890 IE Insp Rept 50-395/79-30 on 791001-04 Nuncompliance note4: appropriate procedures not developed to evaluate deviations. BURDETTE, T. E., BRUMNLEE, V. L., BRYANT, J. C. Region 2, Atlanta, Office of the Director. 79/10/24. App.
- 7912190463 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation," Written response required.

  D'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/30. 10.
- 7912190464 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Written response required. G'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/30. ip.
- 791231030B Forwards IE Info Notice 79-30. "Reporting of Defects & Noncompliances, iOCFR21." No action required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 79/12/06. Spp.
- 7712310310 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 100FR21." No action required.

  O'RETLLY,J.P. Region 2, Atlanta, Office of the Director.

  79/12/06. 5pp.

- 7912200052 Forwards 1E Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. O'REILLY, J. P. Region 2. Atlanta. Office of the Director. 79/12/07. 2pp.
- 7912200055 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps," Action required. O'REILLY.J. P. Region 2, Atlanta, Office of the Director. 79/12/07. ip.
- 7912280421 Forwards IE Info Notice 79-31. "Use of Incorrect Amplified Response Spactra." No written response required.

  O'REILLY, J. P. Hegion 2, Atlanta, Office of the Director.

  79/12/13. 2pp.
- 7712280423 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Bauctra." No written response required. 0'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/12/13. 2pp.
- 79:2280:145 Forwards IE Circular 79-25, "Shock Arrestor Strut Assembly Interference." No written response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/12/20. 4pp.
- 8. Reportable occurrences. LERs & related correspondence
- 7912130433 Interia deficiency rept re welded Hilti bolts on electrical support plates. Reminsp program & engineering evaluation continuing. Final rept will be submitted by Jan 1980. GREMB, E.H. South Carolina Electric & Oss Co. 79/11/01. 1p.
- 7912070026 FNO-11-79-26: on 791107, media mat w/SC lagislature re const practices. Areas of concern included undersize welds on socket welds & use of carbon steel brushes. No decision made by licensee re press release.

  MARSH.R.J., ALDERSON.C. Region 2, Atlanta, Office of the Director. 79/11/07. ip.
- 7912070012 PNO-II-79-29: on 791107. Westinghouse informed NRC of omission in test program re-safety injection circuitry. No Westinghouse test exists for operability of slave relays. Region 4 will follow up in vendor insp
- 7912200462 PNG-II-79-026A: on 791109, util reported that Behedule 160 stainless steel spool pieces mfg by Bouthwest Fabrication & Helding Co do not meet ABME code requirements on socket weld size;
  BURDETTE, T. E., BRYANT, J. C. Region 2, Atlanta, Office of the Director. 79/11/09. ip.
- 791213056B Final deficiency rept re design & procurement of spead & transfer switchgear for component cooling pumps, eve water pumps & charging/sefety injection pumps. Gibbert Associates. Inc revised project mgt manual.

  CREWS.E.H. Bouth Carolina Electric & Gas Co. 79/11/19. 2pp.
- 7912140360 Final deficiency rept: on 791107, undetectable failurs in engineered safety features actuation sys occurred. Analysis revealed sys ability to initiate safety injection could be last under certain conditions. Plant procedures were revised. CREWS, E. H. Bouth Carolina Electric & Das Co. 79/12/03. 2pp.
- 7912140338 Final deficiency rept we design arror in Socicbar pressure resistant & watertight door units frame anchorage. Door frames not yet installed. Design mods will be provided & doors will be installed by 800101.

  CREWS, E. H. South Carolina Electric & Gas Co. 79/12/05. 2pp.
- 7912190563 Deficiency rept re undersize socket welds.Util insp revealed undersized socket welds on both onsite & shop wolds.Caused by inadequate work by welders.ABME inspectors, const co & Bouthwest Fabricating & Welding Co. Corrections underway. .XHNSON.M.C. South Carolina Electric & Oas Co. 79/12/05. App.
- 7912200610 Final deficiency rept re 18 automatic dampers in ventilation sys associated w/12 safety-related fans. Collar holding control arm will be tack welded on to shaft Limit switch sattings will be rechecked during startup.

  CREMS.E.H. Bouth Carolina Electric & Oas Co. 79/12/18. 2pp.
- 7912280532 Interia deficiency rept re rod drop analysis. Westinghouse notified NRC of deficiency on 791115. Heeting held by NRC & Westinghouse. Forwards Westinghouse 791115 It. Final rept will be issued when Westinghouse relays corrective action. CREMB.E.H. South Carolina Electric & Gas Co. 79/12/19. 2pp.

- --7912280540 Confirms Westinghouse 791115 telephone notification re rod drop analysis. SAR analysis may not represent most limiting assumption for credible single failure. Forwards info identifying affected Westinghouse plants. Wo encl. ANDERSON. T. M. Westinghouse Electric Corp. 79/11/15. 2pp.
- DOCKET 50-396 UNIV. OF VIRGINIA CAVALIER REACTOR
- F. Security, medical, exergency & fire protection plans
- 7912120206 Forwards draft Reg Guide S. XX. "Bid Forest & Content for Licensee Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance." W/a encl. REID.R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22.
- DOCKET 50-397 MPPSS NUCLEAR PROJECT. UNIT 2
- A. Application/construction stage documents & correspondence
- 7912110011 Forwards NRC position on status & applicability to pending UL applications of results of TMI followup actions Outlines addl short-term actions to be taken.

  VASSALLO,D.B. Division of Project Management. 79/09/27. 41pp.
- 7912190279 "Results of Hardness Testing & Metallurgical Examination on Feedwater Pipe Welds at Washington Nuclear Project 2." EUE85.M.E. Technimot Corp. NRC-05-77-196. 79/09/28. 35pp.
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRs & BMRs.
  Success of program depends on industry response Supports formation of owners groups to provide necessary info.
  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912130465 Responds to stop work order & deficiency rept re sacrificial shield wall Resumption of work is contingent upon reinspections, quality records reviews & comprehensive action plan.

  ENGELIEN, R. H. Region 5, San Francisco, Office of the Director.
  79/11/21. 1p.
- 7912040246 Requests speting on 791207 re development of safety relief valve load definition.

  RENBERGER, D. L. Hashington Public Power Supply System. 79/11/28.
- 7912040252 Discusses 791003 meeting w/C Anderson re Mark II pool dynamic load tasks. Meeting on 791207 will provide addi info on resolutions for safety relief valve load definitions. Susaary of plant enique areas included.
  REMBERGER. D. L. Washington Public Power Supply System. 79/11/28.
- 7912120322 Notification of 791205 meeting w/util in Bethesda.MD to discuss procedures for review by staff consultants.
  LYNCH,H.D. Light Water Reactors Branch 4. 79/11/30. 3pp.
- 7912120329 Notification of 791207 meeting w/util in Bathesda, HD to discuss plant-unique safety relief valva load definition. LYNCH, H. D. Light Water Reactors Branch 4. 79/11/30. 3pp.
- 7912280566 Forwards XN-NF-103, "Water Content of Solid Matl by Electrolysis," re testing anisture of low-hydrogen electrodos.
  RENBERGER, D. L. Washington Public Power Supply System. 79/12/20.
- --791228GS71 "Water Content of Solid Hatl by Electrolysis." Revision & to Procedure P69281 for testing moisture of low-hydrogen electrodes.

  \* Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). XN-NF-103. 79/01/10. 13pp.
- C. Utility Environmental Report (ER), amonds & correspondence
- 7912270059 Forwards updated distribution list for environ repts & amends.
  DUNCAN.M. Environmental Projects Branch 2. 79/12/06. 4pp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & CL review Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Quide 1.101.
  VASSALLO.D.B. Division of Project Management. 79/11/21. App.

### 9. Adjudicatory correspondence

- 7912040059 Memorandum explaining authority to establish ASLAB. ASLB 791009 notice dismissing proceeding may not be reviewed on ASLAB initiative. Director of Noclear Reactor Regulations is invested w/authority to determine terms of application. BISHOP, C. J. Atomic Safety and Licensing Appeal Panel. 79/11/14. 12na.
- 0. Inspection reports, IE Bulletins & correspondence
- 7912300285 Forwards IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads." No response required. ENGELKEN,R.H. Region 5. San Francisco. Office of the Director. 79/11/16. 1p.
- 7912110522 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/11/16. jp.
- 7912070031 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on GARs." No response required.
  ENGELKEN.R.H. Region 5, San Francisco, Office of the Director.
  79/11/26. 1p.
- 79:2110274 Forwards IE Circular 79-23, "Hotor Starters & Contactors Failed to Operate." No response required. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/11/26. 1p.
- 7912110500 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sent by NRC to licenses.

  ENGELHEN.R.H. Region 5. San Francisco. Office of the Director. 79/11/26. 1p.
- 7712030204 Forwards Amend 1 to preservice insp program plan.consisting of drawing changes which reflect as-built conditions identified during ongoing preservice examinations & program plan text changes.

  RENDERGER, D. L. Washington Public Power Supply System. 79/11/28.
- ---7912030207 Amend 1 to preservice insp program plan, consisting of drawing changes which reflect es-built conditions identified during ongoing preservice examinations & program plan text changes.

  \* Washington Public Power Supply System. 79/09/19. 77pp.
- 791219016) Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." No written response required. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/11/30. lp.
- 7912310279 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances: 100F821," No action required. ENGELHEN.R.H. Region 5, San Francisco, Office of the Director. 79/12/06. 4pg.
- 7912200252 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps," Action required. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director, 70/10/07 in
- 7912280626 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required. ENGELKEN.R.H. Region 5. San Francisco, Office of the Director. 79/12/13. ip.
- S. Reportable occurrences, LERs & related correspondence
- 7912180017 PND-V-79-10: issued two immediate action ltrs to util requesting work stoppage re sacrificial shield wall & certain pips whip restraints due to improper workmanship & possible fradulent records.
  BISHOP.T.W. Region 5, San Francisco, Office of the Diractor.
  79/11/21. 2pp.
- 7912120413 Forwards final deficiency rept re ECGS pump room flooding. RENBERGER, D. L. Washington Public Power Supply System. 79/11/30. ip.

- --7912120418 Fine: deficiency rept re ECCS pump room flooding. Fuel pool cooling sys is not designed to Soismic Category 1 or Class IE stds. Fuel pool cooling sys will be upgraded through re-analysis & redesign to improve reliability.

  \* Washington Public Power Supply System. 79/11/30. 1p.
- 7912280636 Ack receipt of 791130 ltr & final deficiency rept re spent fuel pool cooling sys.
  ENGELKEN R. H. Region 5. San Francisco. Office of the Director.
  79/12/14. ~1p.
- --7912280642 Forwards final deficiency rept re spent fuel pool cooling sys. RENDERGER, D. L. Washington Public Power Supply System. 79/11/30.
- --7912280651 Final deficiency rept re spent fuel pool coeling sys. Spent fuel sys not designed to Seismic Category I stds. Cooling sys will be upgraded. \* Washington Public Power Supply System. 79/11/30. ip.

#### DOCKET 50-379 MENDOCING, UNIT 2

- G. Inspection reports, IE Bulletins & carrespondence
- 79120A0657 IE Insp Rept 50-379/79-41.50-404/79-07 & 50-405/79-07 on 79091B-21. No noncompliance noted Major areas inspected: nonconformance re concrete operations & activities re extended const delay.

  MCFARLAND: C.R. Region 2. Atlanta, Office of the Director.
  79/10/19. 5pp.
- DOCKET 50-400 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1

  A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRs & BMRs.
  Success of program depends on industry response, Supports formation of owners groups to provide necessary info.
  DENTON, H. R. Office of Nuclear Reactor Regulation, 79/10/17. 3pp.
- 7912120392 Forwards facility schedule info, updated to 791130 for PMR const & activities.
  MCDUFFIE, M. A. Carolina Power & Light Co. 79/12/03. 13pp.
- 7912120416 Notifies that util will provide design bases for emergency svc water intake channel in FSAR.
  MCDUFFIE.M.A. Carolina Power & Light Co. 79/12/06, 1p.
- 7912280546 Advises of FSAR submittal by 800601; as reported in encl 781221 ltm. Submittal scheduled to support June 1983 OL issuance for Unit 1. Requests priority for NRC OL review. MCDUFFIG. M.A. Caroline Power & Light Co. 79/12/19. 1p.
- --7912280595 Responds to NRC 7B1107 ltr asking util to identify all applications & requests for review to be submitted to NRC prior to B11231.Will submit OL application in June 1980. including FSAR.

  MCDUFFIE.M. A. Carolina Power & Light Co. 78/12/21. 2gp.
- 7912270342 Forwards info re Harris-Harnett segment of offsite transmission line, identifying major environ features considered in selecting routs for 500 kV line.
  MCDDFFIE.M.A. Carolina Power & Light Co. 79/12/21. 9pp.
- F. Becurity, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & DL review. Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Guide i. 101.

  VASSALLO. D. B. Division of Project Management. 79/11/21. 6pp.
- Q. Adjudicatory correspondence
- 7912110043 Forwards comments on NUREQ-0511 Draft OEIB reflects conscious & deliberate NRC policy to jeopardize public health & safety & thuart objectives of NEPA. KEPFORD, C. Environmental Coalition on Nuclear Power. 79/10/24. 22pp.
- 7912120224 Supports Conservation Council of NC petition to halt facility const.
  EDDLEMAN, W. Kudzu Alliance. 79/11/07. 1p.

- 7912170153 Response in opposition to intervenors 791105 petition requesting reopening of record to consider adequacy of svacuation plans. Intervenors may initiate Commission action if ready to bear burden of proof Centificate of Svc encl. BARTH, C. A. Hearing Branch 3. 79/12/11. 4pp.
- 7912310149 Opposition to intervenor Conservation Council fo NC & Wake Environ. Inc 791105 petition to reppen record. ASLB lacks jurisdiction to grant petition. Certificate of Syc encl. IRDUBERIDGE, G. F. Caroline Power & Light Co. TROUBERIDGE, G. F. Shaw, Pittman, Potts & Troubridge. 79/12/14. App.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912060106 Forwards IE Info Notice 79-12A, "Attempted Damage to New Fuel Assemblies." No specific action or response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 79/11/09. 2pp.
- 7712050633 Atk receipt of IE Insp Repte 50-400/79-20, 50-401/79-20, 30-402/79-19 & 50-403/79-19 on 790924-26. No proprietary info. ZIMMERMAN, S. R. Carolina Power & Light Co. 79/11/15. ip.
- --79]2050636 Forwards IE Insp Repts 50-400/79-20, 50-401/79-20, 50-402/79-19 & 50-403/79-19 on 790924-26. No noncompliance nated.

  HURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch. 79/11/09, 2p.
- --7912050638 IE Insp Repts 50-400/79-20, 50-401/79-20, 50-402/79-19 & 50-403/79-19 on 790924-26. Major areas inspected: steel structures & supports, welding procedure specs & welding matl control.

  ECONOMOS, Region 2, Atlanta, Office of the Director.

  HERDT.A.R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/11/07. 6pp.
- 79:2100:60 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. B'REILLY, J. P. Region 2, Atlanta, Office of the Director, 79/11/16. | 1p.
- 79i2ii0540 Forwards IE Info Notice 79-29: "Loss of Nonsafety-Related Reactor Coalant Bys Instrumentation During Operation." No specific action or response required.

  D'RELLLY.J.P. Region 2: Atlanta, Office of the Director.
  79/11/16. 2pp.
- 7912170142 Supplements response to IE Bulletin 79-15, "Deep Draft Pump Daficiencies," Initial response provided 790910 Insps will be performed at vendor facility prior to shipping. HCDUFFIE.M.A. Carolina Power & Light Co. 79/11/21. ip.
- 7912170161 Supplements response to IE Bulletin 79-23, "Potential Failure of Emergency Diesel Generator Field Exciter Transformer." Confirms that 24-h load test will be performed as part of preoperational testing program.

  HCDUFFIE.M.A. Carolina Power & Light Co. 79/11/21. ip.
- 7912060505 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on DWRs." No response required.

  G'REILLY, J.P. Region 2, Atlanta, Office of the Director.

  79/11/26. ip.
- 7912110123 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operats." No response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/26. 1p.
- 7912110306 Ack receipt of IE Imap Repts 50-400/79-22, 50-401/79-22, 50-402/79-21 & 50-403/79-21 on 791022-25.No proprietary infa.

  HOWE.P.W. Carolina Power & Light Co. 79/11/26. 1p.
- --7912110321 Forwards IE Insp Repts 50-400/79-22, 50-401/79-22, 50-402/79-21 & 50-403/79-21 on 791022-25. No noncompliance noted.

  HURPHY, C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/11/15. 2pp.
- --7912110334 IE Insp Repts 50-400/79-22, 50-401/79-22, 50-402/79-21 & 50-403/79-21 on 791022-23. No noncompliance noted Major areas inspected; lakes, dams & canals, GA/GC controls & work activities & structural concrete quality records. LEMAHANJ.J., Region 2, Atlanta, Diffice of the Director. CONLON.T.E. Region 2, Atlanta, Reactor Construction & Engineering Support Dranch. 79/11/14. 4pp.

- 7912170376 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation "No written response required.

  O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
  79/11/30 10
- 7912310285 Forwards IE Info Notice 79-30. "Reporting of Defects & Noncompliances, 10CFR21." No action required.

  D'REILLY, J. P. Region 2. Atlanta, Office of the Director.
  79/12/06. 5pp.
- 7912200004 Forwards IE Bulletin 79-28. "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. 0'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/12/07. 2pp.
- 7912280370 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required. D'REILLY, J.P. Region 2. Atlanta, Office of the Director. 79/12/13. 2pp.
- 7912280119 Forwards IE Circular 79-25. "Shock Arrestor Strut Assombly Interference." No written response required.

  D'REILLY, J.P. Region 2, Atlanta, Office of the Director.
  79/12/20. 4pp.
- 5. Reportable occurrences, LERs & related correspondence
- 7912210051 PNO-FI-79-013: meeting conducted by 11 electricians w/local TVA station re mgt inability to control tool theft. Locked hoxes broken into at site & tools removed.

  BRADLEY, R. D., MCFARLAND, C.R. Region 2, Atlanta, Office of the Director. 79/10/24. 1p.
- 7912060669 PNO-II-79-19: un 791029, util informed Region 2 that reinforcement steel were amitted during placements of Class I concrete in Unit 1 containment shield wall & Unit 2 reactor auxiliary bldg shear wall. Investigation pending. BRADLEY, R. D., DRYANT, J. C. Region 2. Atlanta, Office of the Director. 79/10/30. 1p.
- 7912130586 Notifies NRC that final rept re deficiencies in procurement, Fabrication & insp of engineered plates for concrete embedment & support of safety-related loads will be completed on 791231. Delays caused by extensive rework. CHIANGI.N.J. Carolina Power & Light Co. 79/11/02. 2pp.
- 7912130448 Interim deficiency rept re omission of rebar in reactor auxiliary bldg. Corrective action will be completed by 800301.
  CHIANGI,N. J. Carolina Power & Light Co. 79/12/05. 2pp.
- --7912130452 Ack receipt of NRC 791030 ltr re placement of concrete omitting rebar. Caused by human error. Repairs on affected walls will commence after NRC approval of corrective action. JONES. J. A. Carolina Power & Light Co. 79/11/01. 6pp.
- --7912130461 Provides supplemental info to 791101 ltr re corrective actions following omission of rebar at two locations.

  Requests authorization to resume placement of concrete & approval of proposed corrective action.

  JONES J. A. Caroline Power & Light Co. 79/11/02. 2pp.
- --7912130472 Notifies that pull test on test bars will be conducted 791217 re engineering avaluation & repairs for reactor auxilliary bldg & containment bldg. Requests approval of proposed repairs. JONES, J. A. Carolina Power & Light Co. 79/11/14. 2pp.
- 7912280529 Interim deficiency rept re defective Beismic Class I hanger welds. Final rept will be forwarded on B00130.
  CHIANGI. N. J. Carolina Power & Light Co. 79/12/19. 2pp.
- DOCKET 50-401 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 2
- A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATWS issue for PWRs & BWRs.
  Success of program depends on industry response. Supports formation of numers groups to provide hecessary info.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.
- 7912120392 Forwards facility schedule info, updated to 791130 for PWR const & activities.

  MCDUFFIE, M. A. Carolina Power & Light Co. 79/12/03. 13pp.

- 7912120416 Notifies that util will provide design bases for emergency svc water intake channol in FSAR. MCDUFFIE.M.A. Carolina Power & Light Co. 79/12/06. 1p.
- 7912280546 Advises of FSAR submittal by 800601, as reported in encl 781221 Itr. Submittal scheduled to support June 1783 OL Issuance for Unit I. Requests priority for NRC OL review. MCDUFFIE. M. A. Carolina Power & Light Co. 79/12/19. 1p.
- --7912280555 Responds to NRC 781107 itr asking util to identify all applications & requests for review to be submitted to NRC prior to 811231. Will submit GL application in June 1980, including FSAR.
  MCDUFFIE.M.A. Carolina Power & Light Co. 78/12/21. 2pp.
- 7912270342 Forwards info re Harris-Harnett segment of offsite transmission line, identifying major environ features considered in selecting route for 500 kV line.

  MCDUFFIE.M.A. Carolina Power & Light Co. 79/12/21. 5pp.
- F. Socurity, medical, emergency & fire protection plans
- 7912040471 Forwards into re upgraded emergency plans to plants under const & OL review. Applicants required to make cortain emergency arrangements w/state & local organizations & submit emergency plans per Reg Quide 1.101.
  VASSALLO.D.B. Division of Project Management. 79/11/21. App.
- G. Adjudicatory correspondence
- 7912110043 Forwards comments on NUREG-0511 Draft GEIS reflects conscious & deliberate NRC policy to jeopardize public health & safety & thwart objectives of NEPA.

  KEPFORD C. Environmental Coalition on Nuclear Power. 79/10/24.
  2205.
- 7912120224 Supports Conservation Council of NC petition to halt facility const. EDDLEMAN, W. Kudru Alliance. 79/11/07. 1p.
- 7912170153 Response in apparition to interveners 791105 petition requesting reopening of record to consider adequacy of evacuation plans. Intervenors may initiate Commission action if ready to bear burden of proof. Certificate of Svc encl. BARTH.C.A. Hearing Branch 3. 79/12/11. 4pp.
- 7912310149 Opposition to intervenor Conservation Council fo NC & Wake Environ. Inc 791105 petition to reopen record. ASLD lacks juriadiction to great petition. Certificate of Svc encl. TROMBRIDGE.O.F. Carolina Power & Light Co. TROMBRIDGE.O.F. Shaw, Pittman. Potts & Trowbridge. 79/12/14. App.
- G. Inspection reports. IE Bulletins & correspondence
- 7912060106 Forwards IE Info Notice 79-12A: "Attempted Domage to New Fuel Assemblies." No specific action or response required. Offectally, J.P. Rogion 2: Atlanta, Office of the Director. 79/11/09. 2pp.
- 79120505433 Ack receipt of IE Insp Repts 50-400/79-20, 50-401/79-20, 50-402/79-19 & 50-403/79-19 on 790924-26. No proprietary info. 21MMERMAN, S. R. Caroline Power & Light Co. 79/11/15. 1p.
- --7912050636 Forwards IE Insp Repts 50-400/79-20, 50-401/79-20, 50-402/79-19 & 50-403/79-19 on 790924-26. No noncompliants noted. HURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/11/09. 2p.
- --791205063B (E Insp Repts 50-400/79-20, 50-401/79-20, 50-402/79-19 & 50-403/79-19 on 790924-26. Major areas inspected: steel structures & supports, welding procedure specs & welding matl control.

  ECONOMOS, N. Region 2, Atlanta, Office of the Director.

  HERDIA, R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/11/07. 6pp.
- 7912100160 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads," No response required.

  O'REILLY,J.P. Region 2, Atlanta, Office of the Director.
  79/11/16. ip.
- 7912110540 Forwards IE Info Notice 79-29, "Loss of Nonsafsty-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. O'RELLLY.J.P. Region 2, Atlanta, Office of the Director. 79/11/16. 2pp.

- 7912170142 Supplements response to IE Bulletin 79-15, "Deep Draft Pusp Deficiencies." Initial response provided 790910 Insps uill be performed at vendor facility prior to shipping. MCDUFFIE.M. A. Carolina Power & Light Co. 79/11/21. 1p.
- 7912170161 Supplements response to IE Bulletin 79-23, "Potential Failure of Emergency Diesel Generator Field Exciter Transformer." Confirms that 24-h load test will be performed as part of preoperational testing program. MCDUFFIE,M.A. Carolina Power & Light Co. 79/11/21. 1p.
- 7912060608 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No response required.

  O'REILLY J. P. Region 2, Atlanta, Office of the Director.
  79/11/26. ip.
- 7912110123 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. O'REILLY J.P. Region 2, Atlanta, Office of the Director. 79/11/26. 1p.
- 7912110306 Ack receipt of IE Insp Rapts 50-400/79-22,50-401/79-22, 50-402/79-21 & 50-403/79-21 on 791022-25. No proprietary info.
  HOWE, P. W. Carolina Power & Light Co. 79/11/26. 1p.
- ~-7912110321 Forwards IE Insp Repts 50-400/79-22, 50-401/79-22, 50-402/79-21 & 50-403/79-21 on 791022-25. No noncompliance noted. HURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Dranch. 79/11/15. 2pp.
- --7912110334 IE Insp Repts 50-400/79-22,50-401/79-22,50-402/79-21 & 50-403/79-21 on 791022-25. No noncompliance noted. Major areas inspected: lakes, dams & canels, GA/GC controls & work activities & structural concrete quality records. LENAHAN, J. J. Region 2, Atlanta, Office of the Director. CONLON, T. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/11/14. App.
- 7912170376 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation."
  No written response required.
  O'REILLY.J.P. Region 2. Atlants, Office of the Director.
  79/11/30. ip.
- 7912310289 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action required. O'REILLY, J. P. Ragion 2, Atlanta, Office of the Director. 79/12/06. 3pp.
- 7912200004 Forwards IE Bulletin 79-28, "Possible Malfunction of Names Model EA180 Limit Switches at Elevated Temps." Action required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director, 79/12/07. 2pp.
- 7912280370 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required. O'RELLVJ.J.P. Region 2, Atlanta, Office of the Director. 79/12/13. 2pp.
- 7912280119 Forwards IE Circular 79-25, "Shock Arrestor Strut Assembly Interference." No written response required. G'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/12/20, 4pp.
- 8. Reportable occurrences, LERs & related correspondence
- 7912210051 PNO-II-79-013: meeting conducted by if electricians w/local TVA station re mpt inability to control tool theft.Locked boxes broken into at site & tools removed. BRADLEY.R.D., MCFARLAND.C.R. Region 2, Atlanta, Office of the Director. 79/10/24. ip.
- 7912060669 PNO-II-79-17: on 791029, util informed Region 2 that reinforcement steel were omitted during placements of Class I contrate in Unit i containment shield wall & Unit 2 reactor auxiliary bldg shear wall. Investigation pending. BRADLEY, R. D., BRYANT, J. C. Region 2, Atlanta, Office of the Director. 79/10/30. ip.
- 7912130584 Notifies NRC that final rept re deficiencies in procurement, fabrication & insp of engineered plates for concrete embedment & support of safety-related loads will be completed on 791251 Delays caused by extensive rework. CHIANGI.N.J. Carolina Power & Light Co. 79/11/02. 2pp.

- 7912130448 Interim deficiency rept re umission of rebar in reactor auxiliary blog. Corrective action will be completed by 800301.
  CHIANOIN.J. Carolina Power & Light Co. 79/12/05. 2pp.
- ---7912130452 Ack receipt of NRC 791030 ltr re placement of concrete omitting reber. Caused by human error. Repairs on affected walls will commence after NRC approval of corrective action. JONES, J. A. Carolina Power & Light Co. 79/11/01. dpp.
- --7912130461 Provides supplemental info to 791101 ltr re corrective actions following omission of rebar at two locations.

  Requests authorization to resume placement of concrete & approval of proposed corrective action.

  JONES, J. A. Carolina Power & Light Co. 79/11/02. 2pp.
- --7912130472 Notifies that pull test on test bars will be conducted 791217 re engineering evaluation & repairs for reactor auxiliary bidg & containment bidg. Requests approval of proposed repairs.

  JONES, J. A. Carolina Power & Light Co. 79/11/14. 2pp.
- 7912280529 Interim deficiency rept re defective Seismic Class I hanger welds. Final rept will be forwarded on 800130. CHIANGI.N. J. Carolina Power & Light Co. 79/12/19. 2pp.
- DOCKET 50-402 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 3 A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to dev verification program to resolve ATHS issue for PHRs & BHRs. Buccess of program depends on industry response. Supports-formation of owners groups to provide necessary info. DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/1 79/10/17. 3pp.
- 7912120392 Forwards facility schedule info.updated to 791130 for PWR const & activities.

  MCDUFFIE.M.A. Carolina Power & Light Co. 79/12/03. 13pp.
- 7912120416 Notifies that util will provide design bases for emergency svc water intake channel in FBAR.

  MCDUFFIE,M.A. Carolina Power & Light Co. 79/12/06, 1p.
- 7912280546 Advises of FBAR submittal by 800601, as reported in encl 781221 itr. Submittal scheduled to support June 1983 OL issuance for Unit 1. Requests priority for NRC OL review. HCDUFFIE, H. A. Carolina Power & Light Co. 79/12/19. ip.
- --7912280555 Responds to NRC 781107 ltr asking util to identify all applications & requests for review to be submitted to NRC prior to 811231. Will submit OL application in June 1980, including FSAR.

  MCDUFFIE, M. A. Carolina Power & Light Co. 78/12/21. 2pp.
- 7912270342 Forwards info re Harris-Harnett segment of offsite transmission line, identifying major environ features considered in selecting route for 500 kV line. MCDUFFIE.H.A. Caroline Power & Light Co. 79/12/21. 9pp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded smergency plans to plants undar const & Ot. review. Applicants required to make certain emergency enrangements w/state & local organizations & subsit emergency plans per Rog Ouide 1.01.
  VASSALLO.D.B. Division of Project Management. 79/11/21. Opp.
- Q. Adjudicatory correspondence
- 7912110043 Forwards comments on NUREO-OB11. Draft GEIB reflects conscious & deliberate NRC policy to Jeopardize public health & safety & thwart objectives of NEPA. KEPFORD.C. Environmental Coalition on Nuclear Power. 79/10/24.
- 7912120224 Supports Conservation Council of NC patition to halt facility const. EDDLEMAN, W. Kudzu Alliance. 79/11/07. 1p.
- 7912170153 Response in opposition to intervenors 791105 petition requesting reopening of record to consider adequacy of evacuation plans. Intervenors may initiate Commission action if ready to bear burden of proof, Centificate of Svc encl. BARTH.C.A. Hearing Branch 3. 79/12/11.4 4pp.

- 7912310149 Opposition to intervenor Conservation Council fo NC & Wake Environ. Inc 791105 petition to reopen record. ASLB lacks jurisdiction to grant petition. Certificate of Svc encl. TROWERIDGE. 0.F. Carolien Power & Light Co. TROWERIDGE. 9.F. Shaw, Pittman. Potts & Trowbridge. 79/12/14. 4pp.
- Q. Inspection reports. IE Bulletins & correspondence
- 7912060106 Forwards IE Info Notice 79-12A, "Attempted Damage to New Fuel Assemblies." No specific action or response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/09. 2pp.
- 7912050633 Ack receipt of IE Insp Repts 50-400/79-20.50-401/79-20.50-402/79-19 & 50-403/79-19 on 790924-26. No proprietary info. ZIMMERMAN, S. R. Caroline Power & Light Co. 79/11/15. ip.
- -7912050636 Forwards IE Insp Repts 50-400/79-20,50-401/79-20, 50-402/79-19 & 50-403/79-19 on 790924-26. No noncompliance noted. MURPHY.C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/11/09. 2p.
- --7912050638 IE Insp Repts 50-400/79-20, 50-401/79-20, 50-402/79-19 & 50-403/79-19 on 790924-26. Major areas inspected: steel structures & supports, welding procedure specs & welding matl control.

  ECONOMOS.N. Region 2. Atlanta, Office of the Director.

  HERDT.A.R. Region 2. Atlanta, Reactor Construction &

  Engineering Support Branch. 79/11/07. App.
- 7912100160 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Bupport Loads," No response required. O'REILLY, J. P. Region 2, Atlanta. Office of the Director. 79/11/16. 1p.
- 7912110940 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/11/16. 2pp.
- 7912170142 Supplements response to IE Bulletin 79-15, "Deep Draft Pump Deficiencies." Initial response provided 790910 Inaps will be performed at vendor facility prior to shipping. MCDUFFIE, M.A. Carolina Power & Light Co. 79/11/21. lp.
- 79:12:70:61 Supplements response to IE Bullstin 79-23. "Potential Failure of Emergency Diesel Generator Field Exciter Transformer." Confirms that 24-h load test will be performed as part of preoperational testing program. MCDUFFIE, M. A. Carolina Power & Light Co. 79/11/21. ip.
- 7912060605 Forwards IE Circular 79-24. "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No response required.
  0/REILLY.J.P. Ragion 2. Atlanta. Office of the Director.
  79/11/26. 1p.
- 7912110123 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/26. 1p.
- 7912110306 Ack receipt of IE Insp Repts 50-400/79-22.50-401/79-22.50-402/79-21 to 50-403/79-21 on 791022-25. No proprietary inro. HOWE.P.W. Carolina Power & Light Co. 79/11/26. 1p.
- --7912110321 Forwards IE Insp Repts 50-400/79-22,50-401/79-22, 50-402/79-21 & 50-403/79-21 on 791022-25.No noncompliance noted. MURPHY, C. E. MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/11/13. 2pp.
- -7912110334 IE Insp Repts 50-400/79-22, 50-401/79-22, 50-402/79-21 & 50-403/79-21 on 791022-25. No noncompliance noted. Major areas inspected: lakes, dams & canals, GA/QC controls & work activities & structural concrete quality records. LENAHAN, J.J. Region 2. Atlanta. Office of the Director, CONLON, T.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/11/14. 4pp.
- 7912190376 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation." No written response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/11/30. 1p. ip.

- 7912310285 Forwards IE Info Notice 79-30. "Reporting of Defects & Noncompliances.10CFR21" No action required.
  0'REILLY, J. P. Region 2. Atlanta, Office of the Director.
  79/12/06. 5pp
- 7912200006 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. 0-REILLY.J.P. Region 2, Atlanta, Diffice of the Director. 79/12/07. 2pp.
- 79122B0370 Forwards IE Info Notice 79-31, "Use of incorrect Amplified Response Spectra." No written response required.
  D'REILLY, J.P. Region 2, Atlanta, Office of the Director.
  79/12/13. 2pp.
- 7912280119 Forwards IE Circular 79-25. "Shock Arrestor Strut Assembly Interference." No written response required. O'RETILLY, J.P. Region 2. Atlanta. Office of the Director. 79/12/20. 4pp.
- S. Reportable occurrences, LERs & related correspondence
- 7912210051 PND-11-79-013: meeting conducted by 11 electricians w/local TVA station re mgt inability to control tool theft. Locked bases broken into at site & tools removed. BRADLEY.R.D. Region 2. Atlanta, Diffice of the Director. 79/10/24.
- 7912060669 PNO-II-79-019: on 791029, util informed Region 2 that reinforcement steel omitted during placements of Class I concrete in Unit 1 containment shield wall & Unit 2 reactor auxiliary bldg shear wall. Investigation pending.

  BRADLEY.R.D. Region 2, Atlanta, Office of the Director. 79/10/30.
- 7912130586 Notifies NRC that final rept re deficiencies in procurement, fabrication & insplof engineered plates for concrete embedment & support of safety-related loads will be completed on 791231. Delays caused by extensive rework. CHIANGLIN. J. Carolina Power & Light Co. 79/11/02. 2pp.
- 77[2130448 Interim deficiency rept re omission of rebar in reactor auxiliary bldg. Corrective action will be completed by B00301. CHIANGI.N. J. Carolina Power & Light Co. 79/12/05. 2pp.
- --7912130452 Ack receipt of NRC 791030 ltr re placement of concrete omitting rebar. Caused by human error. Repairs on affected walls will commence after NRC approval of corrective action. JUNES, J. A. Carolina Power & Light Co. 79/11/01. App.
- --7912130461 Provides supplemental info to 791101 ltr re corrective actions following unission of rebar at two locations. Requests authorization to resume placement of concrete & approval of proposed corrective action. J
- --7912130472 Notifies that pull test on test bars will be conducted 791217 re engineering evaluation & repairs for reactor auxilliary bldg & containment bldg. Requests approval of proposed repairs.

  JUNES, J. A. Carulina Power & Light Co. 79/11/14. 2pp.
- 7912280529 Interim deficiency rept re defective Soismic Class I hanger welds.Final rept will be forwarded on 800130. CHIANGI,N.J. Carolina Power & Light Co. 79/12/19. 2pp.
- DOCKET 50-403 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 4

  A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATWS issue for FWRs & BWRs.
  Success of program depends on industry response Supports formation of owners groups to provide necessary info.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17.
- 7912120392 Forwards facility schedule info.updated to 791130 for PWR const & activities.
  MCDUFFIE.M.A. Carolina Power & Light Co. 79/12/03. 13pp.
- 7912120416 Notifies that util will provide design bases for emergency syr water intake channel in FBAR.

  MCDUFFIE.M.A. Carolina Power & Light Co. 79/12/06. lp.

- 79[2280546 Advises of FSAR submittal by 800601, as reported in encl 78[22] ltr Submittal scheduled to support June 1983 DL issuance for Unit I. Requests priority for NRC DL review. MCDUFFIE, M. A. Caroline Power & Light Co. 79/12/19. lp.
- --7912280555 Responds to NRC 781107 ltr asking util to identify all applications & requests for review to be submitted to NRC prior to 811231. Will submit OL application in June 1980, including FSAR.

  MCDUFFIE,M.A. Carolina Power & Light Co. 78/12/21. 2pp.
- 7912270342 Forwards info re Harris-Harnett segment of offsite transmission line, identifying major environ foatures considered in selecting route for 500 kV line. MCDUFFIE.M.A. Carolina Power & Light Co. 79/12/21. 9pp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review. Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Rog Guide 1.101.
  VASBALLO, D. B. Division of Project Management. 79/11/21. App.
- G. Adjudicatory correspondence
- 7912110043 Forwards comments on NUREG-0511 Draft GEIS reflects conscious & deliberate NRC policy to Jeopardize public health & safety & thwart objectives of NEPA.

  KEPFORD, C. Environmental Coalition on Nuclear Power. 79/10/24.
- 7912120224 Supports Conservation Council of NC petition to halt facility const. EDDLEMAN.W. Kudsu Alliance. 79/11/07. 1p.
- 7912170153 Response in opposition to intervenors 791105 petition requesting reopening of record to consider adequacy of evacuation plans. Intervenors may initiate Commission action if ready to bear burden of proof. Certificate of 8vc encl. BARTH, C.A. Hearing Branch 3. 79/12/11. 4pp.
- 7912310149 Opposition to intervenor Conservation Council fo NC & Wate Environ Enc 791105 petition to reopen record ASLB lacks jurisdiction to grant petition. Certificate of Evc encl. TROMDRIDGE.G.F. Carolina Power & Light Co. 79/12/14. 4pp.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912060106 Forwards IE Info Notice 79-12A, "Attempted Damage to New Fuel Assemblies." No specific action or response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/09. 2pp.
- 7912050633 Ack receipt of IE Insp Repts 50-400/79-20, 50-401/79-20, 50-402/79-19 & 50-403/79-19 on 790924-26. No proprietary info.
  ZIMMERMAN, S. R. Carolina Power & Light Co. 79/11/15. ip.
- --7912050636 Forwards IE Insp Repts 50-400/79-20, 50-401/79-20, 50-402/79-19 & 50-403/79-19 on 790924-26. No noncompliance noted.
  MMRPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/11/09.
- --7912050638 IE Insp Repts 50-400/79-20,50-401/79-20,50-402/79-19 & 50-402/79-19 on 790924-26. Major areas inspected: steel structures & supports, welding procedure specs & welding matl control.

  ECONOMOS, N. Region 2. Atlanta, Office of the Director. 79/11/07. App.
- 7912100160 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/11/16. 1p.
- 7912:10540 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. D'REILLV.J.P. Region 2. Atlanta. Diffice of the Director. 79/11/16. 2pp.
- 7912170142 Supplements response to IE Bulletin 79-15, "Deep Braft Puap Deficiencies." Initial response provided 790910. Insps will be performed at vendor facility prior to shipping. MCDUFFIE.M.A. Carolina Power & Light Co. 79/11/21. Ip.

- 7912170161 Supplements response to IE Bulletin 79-23, "Potential Failure of Emergencyu Diesel Generator Field Exciter Transformer." Confirms that 24-h load test will be performed as part of preoperational testing program.

  MCDUFFIE.M.A. Carolina Power & Light Co. 79/11/21. 1p.
- 7912060605 Forwards IE Circular 79-24, "Proper Installation & Calibr of Cors Spray Pipe Break Detection Equipment on BWRs." No response required.

  0'REILLY.J.P. Region 2, Atlanta, Office of the Director.
  79/11/26. 1p.
- 7912110123 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. D'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/26. 1g.
- 7912110306 Ack receipt of IE Inap Repts 50-400/79-22, 50-401/79-22, 50-402/79-21 & 50-403/79-21 on 791022-25. No proprietary info. HOME, P. H. Carolina Power & Light Co. 79/11/26. ip.
- --7912110321 Forwards IE Insp Repts 50-400/79-22, 50-401/79-22, 50-402/79-21 & 50-403/79-21 on 791022-25. No noncompliance noted.

  HURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/11/15. 2pp.
- 7912190376 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation."
  No written response required.
  0'REILEY,J.P. Region 2, Atlanta, Office of the Director.
  79/11/30. 1p.
- 7912310285 Forwards IE Info Notice 79-30. "Reporting of Defects & Noncompliances.IOCFR21." No action required.

  O'REILLY, J. P. Region 2, Atlanta, Office of the Director.

  79/12/04. 5pp.
- 7912200006 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required.
  O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
  79/12/07, Zeo.
- 7912280370 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required.
  O'REILLLY, J.P. Region 2, Atlanta, Office of the Director.
  79/12/13. 2pp.
- 7712280119 Forwards IE Circular 79-25, "Shock Arrestor Strut Assembly Interference." No written response required. D'REILLLY.P. Region 2, Atlanta, Office of the Director. 79/12/20. 4pp.
- 8. Reportable occurrences, LERs & related correspondence
- 7912210051 PNO-II-79-013: meeting conducted by 11 electricians w/local TVA station rempt inability to control tool theft.Locked topies broken into at site & tools removed.

  BRADLEY.R.D. Region 2. Atlanta, Office of the Director. 79/10/24.

  19.
- 7712060667 PRO-II-79-019: on 791029, util informed Region 2 that reinforcement steel omitted during placements of Class I concrete in Unit 1 containment shield wall & Unit 2 reactor auxiliary bldg shear wall. Investigation pending. BRADLEY.R.D. Region 2. Atlanta, Diffice of the Director. 79/10/30. 1p.
- 7912130586 Notifies NRC that final rept re deficiencies in procurement, fabrication & insp of engineered plates for concrete embedment & support of safety-related loads will be completed on 791231. Delays caused by extensive rework. CHIANGI,N. J. Carolina Power & Light Co. 79/11/02. 2pp.
- 7912130448 Interim deficiency rept re omission of rebar in reactor auxiliary bldg. Corrective action will be completed by 800301. CHIANOI, N. J. Carolina Power & Light Co. 79/12/05. 2pp.

- --7912130452 Ack receipt of NRC 791030 ltr re placement of concrete omitting rebar Caused by human arror. Repairs on affected walls will commence after NRC approval of corrective action. JONES, J. A. Carolina Power & Light Co. 797(1/0). 6pp.
- ~-7912130461 Provides supplemental info to 791101 ltr re corrective actions following omission of rebar at two locations. Requests authorization to resume placement of concrete & approval of proposed corrective action.

  JONES, J. A. Carolina Power & Light Co. 79/11/02. 2pp.
- --7912130472 Notifies that pull test on test bars will be conducted 791217 re engineering evaluation & repairs for reactor auxilliary bldg & containment bldg. Requests approval of proposed repairs.

  JONES, J. A. Carolina Power & Light Co. 79/11/14. 2pp.
- 7912280529 Interim deficiency rept re defective Seismic Class I hanger welds.Final rept will be forwarded on 800130. CHIANGI.N.J. Carolina Power & Light Co. 79/12/19. 2pp.
- DOCKET 50-404 NORTH ANNA POWER STATION, UNIT 3

  A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATWS issue for PWRs & BWRs.
  Success of program depends on industry response. Supports formation of owners groups to provide necessary info.
  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Guide 1.101.
  VASSALLO, D. D. Division of Project Management. 79/11/21. 6pp.
- Q. Inspection reports: IE Bulletins & correspondence
- 7912040651 Forwards IE Insp Repts 50-339/79-41,50-404/79-07 & 50-405/79-07 on 790918-21 No nancompliance noted.
  MURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/10/22. 2pp.
- --7912040457 IE Insp Repts 50-337/79-41.50-404/79-07 & 50-405/79-07 on 790918-21. No noncompliance noted Major areas inspected: nonconformance re concrete operations & activities re extended const delay.

  MCFARLAND, C.R. Region 2, Atlanta, Defice of the Director.

  BRYANT, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/10/19. 5pp.
- 7912100201 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. D'REILLY, J.P. Region 2. Atlanta, Office of the Director. 79/11/16. ip.
- 79:21:10587 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Helated Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/11/16. 2pp.
- 7912070007 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWMs." No response required.

  0'REFLLY.J.P. Region 2. Atlanta, Office of the Director.
  79/11/26. 1p.
- 7912110186 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/26. ip.
- 7912190495 Forwards IE Dulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation."
  No written response required.
  O'REILLY, J.P. Region 2. Atlanta, Office of the Director.
  79/11/30. ip.
- 7912310330 Forwards IE Info Nutice 79-30, "Reporting of Defects & Noncompliances.10CFR21." No action required.
  O'REILLY, J. P. Region 2. Atlanta, Office of the Director.
  79/12/06. 5pp.

- 7912200070 Forwards IE Dulletin 79-20, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required.

  O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
  79/12/07 2nn
- 7912310255 Responds to IE Bulletin 79-02, Revision 2. "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts." No pipe supports for Seissic Category 1 sys attached to concrete block walls w/anchor bolts at facilities. BROWN, S. C. Virginia Electric & Power Co. 79/12/07. 3pp.
- 7912280441 Forwards IE Info Notice 79-31. "Use of Incorrect Amplified Response Spectra." No written response required.

  O'REILLY.J.P. Region 2, Atlanta, Office of the Director.
  79/12/13. 2pp.
- 7912280161 Forwards IE Circular 79-25, "Shock Arrestor Strut Assembly Interference." No written response required. O'REILLY.J.P. Region 2, Ablanta, Office of the Director. 79/12/20. 4pp.
- S. Reportable occurrences, LERs & related correspondence
- 7912200016 PND-II-79-010: on 791015, util announced that study has been commissioned to determine feasibility of converting facilities to coal fired units, due to uncertainty of UB commitment to nuclear power.

  DRYANT.J.C. NURPHY.C.E. Region 2, Atlanta, Office of the Director. 79/10/15. 1p.
- 7912210330 Advises that work on nutstanding items reported under 10CFR50.55(e) & 10CFR21 have been suspended, pending completion of feasibility study resulting from uncertainties re nuclear plants. Lists status of autstanding Items. BROWN, B. C. Virginia Electric & Power Co. 79/10/30. 2pp.
- 7912040349 Supplements 780818 final deficiency rept re pump suction & unstable flow Pump suction mods acceptable.
  BROWN S.C. Virginia Electric & Power Co. 79/11/29. Spp.
- 79122003B7 Suppl to 78081B final deficiency rept re adverse varter action at recirculation spray puap suction & unstable flow into first stage impelier. New flat plate and will be provided on recirculation spray puaps/cans.
  BROWN.B.C. Virginia Electric & Pawer Co. 79/11/29. 2pp.
- 7912280541 Interim deficiency rept concerning significant breakdown in GC program re verification of calibr of Forney compression testing machine. Attempting to calibr forney compression testing machine in range of 0 to 25.000 lbs.

  BROWN.S.C. Virginia Electric & Power Co. 79/12/20. 3pp.
- DUCKET 50-405 NORTH ANNA PORER STATION. UNIT 4
- A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRs & DMRs. Guccess of program depends on industry response Supports formation of owners groups to provide necessary info. DENION, H.R. Office of Nuclear Reactor Regulation. 79/10/17. Opp.
- F. Security, medical, emergency & fire protection plans
- 7910040471 Forwards info no upgraded emergency plans to plants under const & OL review Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Guido L. 101.
  VASSALLO,D.B. Division of Project Hanagement. 79/11/21. App.
- G. Adjudicatory correspondence
- 7911300062 Forwards util 791023 ltr & check re NRC 771001 order imposing civil genelties. W/o encl.
  STELLO,V. Diffice of Inspection & Enforcement, Office of the Director. 79/11/07. lp.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912060451 Forwards IE Insp Repts 50-339/79-41,50-404/79-07 & 30-405/79-07 on 790918-21.No noncompliance noted.
  MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/10/22. 2pp.

- --7912060657 IE Insp Repts 50-339/79-41.50-404/79-07 & 50-405/79-07 on 790918-21. No noncompliance noted, Major areas inspected: nonconformance re concrete operations & activities re extended const delay.

  MCFARLAND.C.R. Region 2. Atlanta, Office of the Director.

  BRYANT.J.C. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/10/19. 5pp.
- 79/2100201 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. O'REILLY, U.F. Region 2, Atlanta, Office of the Director. 79/11/16. 1p.
- 7912110587 Forwards IE Info Notice 79-29, "Loss of Nonsefety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. O'RETLIV.J.P. Region 2, Atlanta, Office of the Director. 79/11/16. 2pp.
- 7911300140 Forwards IE Bulletin 79-26, "Boron Loss From BWR Control Blades." No response required.
  O'REILLY,J.P. Region 2, Atlanta, Office of the Director.
  79/11/20. 2pp.
- 7912070007 Forwards IE Circular 79-24. "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BMRs." No response required. D'REFLLY.J.P. Region 2. Atlanta. Office of the Director. 79/11/26. 1p.
- 7912110186 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/11/26. 1p.
- 7912190495 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." No written response required. O'REILLY, J. P. Region 2. Atlanta. Office of the Director, 79/11/30. 1p.
- 7912310330 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action required.

  O'REILLY,J.P. Region 2, Atlanta, Office of the Director.

  77/12/06. Spp.
- 7912200070 Forwards IE Bulletin 79-28, "Possible Malfunction of Named Model EA180 Limit Switches at Elevated Temps." Action required. 0'RETLLY,J.P. Region 2, Atlanta, Office of the Director. 79/12/07. 2pp.
- 7712310295 Responds to IE Bulletin 79-02.Revision 2, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts."
  No pipe supports for Seismic Category 1 sys attached to concrete block walls w/anchor bolts at facilities.
  BROWN,S.C. Virginia Electric & Power Co. 79/12/07. 3pp.
- 7912280441 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required.
  O'MEILLY.J.P. Region 2, Atlanta, Office of the Director.
  79/12/13. 2pp.
- 7912280161 Forwards IE Circular 79-25, "Shock Arrestor Strut Assembly Interference." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/12/20, 4pp.
- S. Reportable occurrences, LERs & related correspondence
- 7912200016 PNO-II-79-010: on 791015 util announced that study has been commissioned to determine feasibility of converting facilities to coal fired units due to uncertainty of UB commitment to nuclear power.

  BRYANT.J.C. NURPHY.C.E. Region 2, Atlanta, Office of the Director. 79/10/13. 1p.
- 7912210330 Advises that work on outstanding items reported under 10CFR90.59(e) & 10CFR21 have been suspended pending completion of feasibility study resulting from uncertainties re nuclear plants.Lists status of outstanding items. BRO4N.B.C. Virginia Electric & Power Co. 79/10/30. 2pp.
- 7912040347 Supplements 780818 final deficiency rept re pump suction & unstable flow Pump suction mods acceptable.

  BROWN, S. C. Virginia Electric & Power Co. 79/11/29. 25p.

- 7912200387 Suppl to 780818 final deficiency rept re adverse vortex action at recirculation spray pump suction & unstable flow into first stage impeller. New flat plate mod will be provided on recirculation spray pumps/cans. BROWN, S. C. Virginia Electric & Power Co. 79/11/29. 2pp.
- 7912280541 Interim deficiency rept concerning significant breakdown in QC program re-verification of calibr of Forney compression testing machine. Attempting to calibr Forney compression testing machine in range of 0 to 25.000 lbs.
  SRDWN.G.C. Virginia Electric & Power Co. 79/12/20. 3pp.

## DOCKET 50-404 TUSKEGEE INST. RESEARCH REACTOR

# A. Application/construction stage documents & correspondence

- 7912040491 Notifies of typographical error on Page 4 of App A.Tech Specs re safety limits. Should read "reactor power level should not exceed 100 milliwatts. DYBCZAK. Z. M. Tuskagee Inst. 79/11/19. ip.
- F. Becurity, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Quide 5.XX, "Std Format & Content for Licenses Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance." W/o encl. REID.R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22.

## DOCKET 50-407 UNIV. OF UTAH RESEARCH REACTOR

## F. Becurity, madical, emergency & fire protection plans

7912120206 Forwards draft Reg Guids 5.XX, "Std Format & Content for Licensee Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance." W/o encl. REID.R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22.

## DOCKET 50-409 LA CROSSE BOILING WATER REACTOR

- D. MRC Draft/Final Environmental Statements, supple & correspondence
- 7912180278 Forwards add1 questions re-updating of FEB for LACBWR.

  Deadling for comments is 791216. Requests response if unable to comply w/deadline.

  BALLARD,R.L. Environmental Projects Branch 1. 79/11/16. 3pp.
- 7912180865 Provides technical & aditorial comments on FEB (NUREO-0191). STEELE, T. A. Dairyland Power Cooperative. 79/12/14. 19pp.
- 7912180577 Forwards responses to questions contained in NRC 791116 ltr ra LACOHRFEB. BIEELE, T. A. Dairyland Power Cooperative. 79/12/12. 13pp.
- --7912180388 NPDES Permit WI-0003239-2 issued to Dairyland Power Cooperative. MRDEMN.T.A. Environmental Protection Agency. 79/09/28. 15pp.
- --7912180590 "Mussel Burvey of Thief Slough at Mile 678 on MS River Near Gence, MT. 780921-22."

  JOHNSTON. G. L. Dairyland Power Cooperative. 78/09/22. 20pp.
- F. Security, medical, emergency & fire protection plans
- 7912200022 Discusses NRC 791109 meeting re emergency preparedness team review objectives. Provides guidance for improving licensee swargency preparedness & assuring capability of offsite agencies to take appropriate emergency actions.
  ORIMES, B. K. Emergency Preparedness Task Force. 79/11/23. 30pp.
- 7912200037 Notifies that evaluation of fire protection program delayed until util provides required info.NRC is preparing order to thutdown facility until liquefaction issue is resolved. LAINAS.Q. Plant Systems Branch. 79/11/29. 1p.

# Q. Adjudicatory correspondence

7912030113 Findings of fact & conclusions of law on ABLB question re need for glant for next three yes. M/some exceptions & mods, adapts findings on same issue, balanced against EIA. Certificate of Buc encl. MODDHEAD, C. P. Hearing Branch 3. 79/11/05. 10pp.

- 7912110363 Order approving intervenor Coulee Region Energy Coalition Contentions 2A.28.8.9.19 & 22 & rejecting Contention 6.
  Acceptable contentions listed in app.
  BECHHOEFER.C. Atomic Safety and Licensing Board Panel. 79/11/30.
- 7912260028 Interrogatories submitted to intervenor Couler Region Energy Coalition. Includes questions re alleged noncompliance w/App I of Part 50 concerning LACDWR offgas emissions & affected employees. Certificate of Svc psc.
  WOODHEAD.C.P. Hearing Branch 3. 79/12/14. 8pp.

## P. Operating license stage documents & correspondence

- 7912100189 Discusses NRC 791101 meeting w/representatives of NSSS vandors & fuel suppliers re discussion of respective portions of ECGB evaluation models dealing w/fuel cladding swelling & incidence of rupture. Vendor responses encl. EISENHUT, D. O. Division of Operating Reactors. 79/11/09. 65pp.
- --7912100255 Responds to NRC 791101 request re noncompliance of Westinghouse ECCS evaluation model under requirements of 10CFR50 App K. Evaluation of three fuel rod models indicates no safety problems for Westinghouse plants. ANDERSON, T.M. Westinghouse Electric Corp. 79/11/02. 4pp.
- --7912100330 Responds to NRC 791101 request re URNL cladding swelling & rupture data. Review of analytical models & tests indicates compliance w/10CFR50 App K.All GE specs for calculated peak cladding temp remata unchanged.
  BUCHHULZ.R.H. General Electric Ge. 79/12/07. 2pp.
- ---7912100407 Forwards response to NRC 791101 request re rod burst test data. Concludes that data properly represented by fuel models used in vendor evaluation models & that analyses demonstrate all criteria of IOCFR50. 46 satisfied.
  OMSLEY.G.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/11/02. 5pp.
- ---7912100456 Forwards add1 info re ovaluation of impact of NRC proposed rupture/blockage model used in vendor avaluation model. No adverse impact from new rupture burst data or use of NRC rupture/blockage model on licensing calculation results. CMSLEV.G.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/04. 22pp.
- 7912110025 Forwards updated lists of SEP topics not requiring site review due to engoing generic licensing activities outside SEP or because of inapplicability to facility.

  ZIEMANN.D.L. Operating Reactors Branch 2. 79/11/16. Spp.
- 7912130407 Forwards Class III amend fee in response to NRC 791101 ltr re proposed radiological effluent Tech Specs. LINDER, F. Dairyland Power Cooperative. 79/11/21. 1p.
- 7912130419 Forwards Class III amend fee for NRC review & approval of license amend request. LINDER, F. W. Duke Fower Co. 79/11/21 2pp.
- 7912040180 Summary of 791102 mosting w/util re liqusfaction potential at plant (SEP Topic II-4).
  WETMORE, J. S. Operating Reactors Branch 2. 79/11/26. 4pp.
- 7912050493 Advises that licensee conforms w/provisions of 40CFR190 by semiannual calculation Method of calculation outlined in offsite dose calculation manual which was submitted in Aug 1979. Manual uses GASPAR & LADTAP computer codes.

  LINDER, F. Dairyland Power Cooperative. 79/11/29, 1p.
- 7912100318 Forwards Drawings 51-503674 Revision 21,41-503775 Revision 10 & 41-503828 Revision 7. in response to NRC 791009 1tr re SEP Topic III-10.A concerning thermal overload protection. LINDER, F. Dairyland Power Cooperative. 79/11/29. 2pp.
- --7912100321 "Wiring Diagram: Turbine Bldg MCC. 1A." \* Sargent & Lundy. Inc. 77/08/22. 1p.
- --7912100324 "Bchematic Control Diagram: Alternate Core Spray & Misc. " \* Sargent & Lundy, Inc. 78/05/02. ip.
- ---7912100331 "Wiring Diagram: MCA DC Valve & Diesel Pump IA." \* Sargent & Lundy, Inc. 77/08/05. lp.
- 7712110240 forwards draft preliminary rept, "Proposed Measure to Mitigate Potential for Liquefaction at LACEMR Plant Bite Near Genoa, WI," in response to NRC 791102 request. LINDER, F. Dairyland Power Cooperative. 79/11/29. 2pp.

- --7912110246 Draft preliminary rept. "Proposed Measure to Mitigate Fotential for Liquefaction at LACOUR Plant Site Near Geona, WI."
  - \* Dames & Moore. 79/11/29. 11pp.
- 7912100242 Ack receipt of NRC 791002 ltr re certification & training of NRC staff members in radiation safety. Hill accept certification instead of util radiation safety course. LINDER, F. Dairyland Power Cooperative. 79/12/04. ip.
- 7912110230 Provides justification & descriptions of differences from NRC short-term requirements presented in NUREG-0578. LINDER, F. W. Duke Power Co. 79/12/06. Spp.
- 7912180189 Submits descriptions & Justifications for differences from NRC Lessons Learned Task Force short-term requirements presented in NUREG-0578. Discusses performance testing for relief & safety valves & containment isolation.

  LINDER, F. Dairyland Power Cooperative. 79/12/06. 5pp.
- 7912120265 Responds to NRC 791023 ltr re containment purging & venting during normal operation. Manufacturer Allis-Chalmers confirmed that valves would close as designed under pressure differential conditions representative of accident. LINDER, F. Dairyland Power Cooperative. 79/12/07. 2pp.
- 7912200427 Requests Further amend to OL revising schedule for inservice testing of high pressure core spray pumps, alternate core spray pump & high pressure soc water pump. Pumps should be inspected during cold shutdown not during operations.

  LINDER,F. Dairyland Power Cooperative. 79/12/07. 3pp.
- 7912140416 Responds to NRC 791018 Itr re concerns of C Michelson, ACRS consultant. Concerns not applicable to util as reactor is BHR. not PHR. Analyses show HPCS capable of cooling core w/o assistance from LPCS-regardless of reactor water level. LINDER, F. Dairyland Power Cooperative. 79/12/11. 3pp.
- 7912270388 Submits clarification or changes re util responses to short-term recommendations of TMI Lessons Learned Task Force.
  Includes info re transient analysis, inadequate core cooling & valve testing.
  LINDER, F. Dairyland Power Cooperative. 79/12/20. 3pp.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912050220 Forwards IE Insp Ropt 50-409/79-19 on 791001-05.No noncompliance noted HEISHMAN.R.F Region 3. Chicago. Reactor Operations Nuclear Support Branch. 79/10/22. 2pp.
- --7912050231 IE Insp Rept 50-409/74-19 on 791001-05. No noncompliance noted Major areas inspected maint activities, operational activities, followop actions to previous noncompliance, IE bulletins, IE circulars & event repts, RIDGMAY, K. R., BOYD, D. C. Region 3, Chicago, Office of the Director, 79/10/19, 3pp.
- 7912130006 Responds to IE Bulletin 79-02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts." Unscheduled cold shutdown permits insplicitly of pipes support hase plates in restricted areas.

  LINDER:F. Datryland Power Cooperative. 79/10/24. 2pp.
- 7912050123 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required.
  KEPPLER.J.G. Region 3. Chicago. Office of the Director. 79/11/16.
- 79:2100227 Forwards IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads." No response required. KEPPLER.J.O. Region 3. Chicago. Office of the Director. 79/11/16. lp.
- 7912110576 Forwards IE Info Notice 79-29. "Loss of Nonsprety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required.

  KEPPLER.J.G. Region 3: Chicago. Office of the Director. 79/11/16. ip.
- 7912050372 Forwards IE Mulletin 79-26. "Boron Loss From BWR Control Blades." Response required. KEPPLER.J. G. Region 3. Chicago. Office of the Director. 79/11/20.
- 79:12:00429 Forwards IE Circular 79-24. "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No written response required.

  KEPPLER.J.G. Region 3. Chicago, Office of the Director. 79/11/26.

- 7912110255 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/26. 1p.
- 7912110423 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sent by NRC to licensees.

  KEPPLER. J. O. Region 3, Chicago, Office of the Director. 79/11/28.
- 7912190219 Forwards IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation," Written response required.

  KEPPLER.J. G. Region 3. Chicago, Office of the Director. 79/(1/30. lo.
- 7912210174 Responds to IE Bulletin 79-25, "Failure of Westinghouse BFD Relays in Safety-Related Sys." BFD relays not used at facility.

  LINDER,F. Dairyland Power Cooperative. 79/11/30. ip.
- 7912140082 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances,10CFR21." No action or response required. KEPPLER, J. G. Region 3. Chicago, Office of the Director. 79/12/06.
- 7912200112 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/12/10.
- R. Periodic operating reports & related correspondence
- 7912110206 Forwards monthly operating rept for Nov 1979. LINDER.F. Dairyland Power Comperative. 79/12/06. 1p
- --7912110209 Monthly operating rept for Nov 1979. GDDDMAN, L. S. Dairyland Power Cooperative. 79/12/04. 9pp.
- S. Reportable occurrences, LERs & related correspondence
- 791R12006B PNO-III-79-025: on 7910R5, essential sycs mater generator set tripped resulting in tripping of Unit 3 reactor. Caused by slamming of essential sycs electrical panel door. CREED. J. Region 3, Chicago, Office of the Director. 79/10/26. 200.
- 7912040418 Forwards LER 79-017/01T-0. LINDER:F. Dairyland Power Cooperative. 79/11/27. Hpp.
- --7912040423 LER 79-017/01T-0: on 791109, reactor vessel cooled down at rate exceeding Tech Specs during reactor scram. Caused by turbine governor problem resulting in power to flow scram. Turbine governor sys inspected & flushed, GUDDMAN.L.S. Dairyland Power Cooperative. 79/11/27. 1p.
- 7912170287 Forwards Special Rept 79-03 re sampling % analysis resulting from thermal power changes greater than 15%. LINDER,F.W. Duke Power Co. 79/12/07. 2pp.
- ---7912170288 Special Rept 79-03:on 790928 & 1109, reactor thermal power changed by more than 18% of rated thermal power within 1-h during Operational Condition 1 or 2. Caused by scram solenoid burnout. Sampling & analysis data encl.

  8 Duke Power Co. 79/12/07. 6pp
- 7912200568 Forwards Special Rept 79-03 re reactor scrams on 790920 & 1109. LINDER,F. Dairyland Power Cooperative. 79/12/07. 2pp.
- --7912200571 Special Rept 79-03: reactor scram on 790928, due to scram solenoid burn out, caused by failed seal in upper control rod drive mechanism. Scram on 791109, due to restricted freedom of movement of turbine governor initial pressure regulator.
  \* Deiryland Power Cooperative, 79/12/07. 6pp.
- 7912280464 RO 79-18: on 791214, manufacturer notified that containment isolation dampers require repositioning to ensure quick closure at max containment vessel pressure. Dampers repositioned. Containment bldg vented continuously. LINDER: F. Dairyland Power Cooperative. 79/12/18. 2pp.

- 7912270486 Responds to NRC 790925 request for add1 info re loss of offsite power on 710120. Provides datails of seven complete offsite power losses. Facility does not have capability of sustaining power during partial loss of offsite power.

  LINDER, F. W. Dairyland Power Cooperative. 79/12/21. Spp.
- 7912310497 Forwards LER 79-019/01T-0. LINDER, F. Dairyland Fower Cooperative. 79/12/26. 2pp.
- --7912310504 LER 79-019/01T-0: on 791223, periodic leakage rate test for emergency airlock did not meet type B test criteria specified by Tech Specs. Caused by flattened 0 rings & shaft packaging in shaft seal. Beal replaced. 6000MAN.L. S. Dairyland Power Cooperative. 79/12/26. 3pp.
- DOCKET 50-410 NINE MILE POINT NUCLEAR STATION, UNIT 2
- A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early varification program to resolve ATMS issue for PMRs & BHRs. Buccess of program depends on industry response. Bupports formation of owners groups to provide necessary info. DENION, H. R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.
- 7912270324 Advises that FBAR & OL application will be submitted in Jul 1991, based on fuel load date of Mar 1984 & commercial operation date of Oct 1984. RHODE. O. K. Niagara Mohawk Power Corp. 79/12/17. 1p.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review. Applicants required to make certain exergency arrangements w/state & local organizations & submit emergency plans per Reg Ouide 1. 101. VASSALLO.D.B. Division of Project Management. 79/11/21. App.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912140202 Responds to IE Bulletin 79-23, "Potential Failure of Emergency Diesel Generator Field Exciter Transformer." No common connections between control power transformer & generator netural.
  RHODE, G. K. Niagard Mohawk Power Corp. 79/11/01. ip.
- 7912200449 Forwards IE Insp Rept 50-410/79-07 on 791009-12. No noncompliance noted.
  CARLSON.R.T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/11/02. 2pp.
- --7912200457 IE Insp Rept 50-410/79-07 on 791009-12.No noncompliance noted. Major areas inspected: electrical procedures & instructions, downcomer installation & records, audits & CE tafaty relief valve status.

  HCGAUGHY, R. M. Region i, Philadelphia, Reactor Construction & Enginewring Bupport Branch. CERNE, A. C., FINKEL, A. E. Region i, Philadelphia, Office of the Director. 79/11/01. 9pp.
- 7912050044 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required.

  ORIER, B. H. Region I. Philadelphia, Office of the Director.

  79/11/16. ip.
- 7912050271 Forwards IE Info Notice 79-27. "Steam Cenerator Tube Ruptures at Two PWR Plants." No response required. GRIER.B.H. Region 1. Philadelphia, Office of the Director, 79/11/16. 1p.
- 7912100193 Forwards 1E Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director. 79/11/16. 1p.
- 791211044D Forwards IE Info Notice 79-29, "Loss of Nonsefety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required. QRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/11/19. 1p.
- 79:2080261 Forwards IE Bulletin 79-26, "Boron Loss From BWR Control Blades." No response required.
  ORIER, B.H. Region 1, Philadelphia, Office of the Director, 79/11/20. 1p.

- 7912060580 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on DWRs." No response required.
  ORIER.B.H. Region 1. Philadelphia. Office of the Director.
  79/11/26. 1p.
- 7912110064 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operato." No response required.
  ORIER, B.H. Region 1, Philadelphia, Office of the Director.
  79/11/26. 1p.
- 7912190041 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." No written response required. ORIER, B. H. Region 1. Philadelphia. Office of the Director. 79/11/30.
- 7912310232 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action required. ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/12/06. 4pp.
- 7912190756 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Written response required. GRIER B. H. Region 1, Philadelphia, Office of the Director. 79/12/07. 1p.
- 7912280212 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required. CRIER.B.H. Region 1, Philadelphia, Office of the Director. 79/12/13. ip.
- DOCKET 50-412 BEAVER VALLEY POWER STATION, UNIT 2
- A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATWS issue for PWRs & DWRs. Buccess of program depends on industry response. Supports formation of owners groups to provide neressary info.

  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/10/17. Sep.
- 7912280473 Confirms info requested during 791210 telcom.Present schedule for fuel loading is 831231 & FSAR will be submitted by Jul 1981.
  WOOLEVER, E. J. Duquesne Light Co. 79/12/20. 1p.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded omergency plans to plants under const & OL review. Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans por Reg Guide 1.101.
  VASSALLO.D.B. Division of Project Management. 79/11/21. App.
- Q. Inspection reports. IE Bulletins & correspondence
- 7912170182 Updates 790828 response to IE Bulletin 79-17, "Pipe Cracks in Stagmant Borated Water Sys at PWR Plants." Insp of welds will not be completed within required 90-day period due to difficulty in removing concrete slabs.

  WERLING.J.A. Duquesne Light Co. 79/10/29. 2pp.
- 7912050029 Forwards IE Circular 79-22, "Stroke Times for Power Operated Rallef Valves." No response required. GRIER.D.H. Region 1, Philadelphia, Office of the Director. 79/11/16. 1p.
- 7912050241 Forwards IE Info Notice 79-27, "Steam Generator Tube Ruptures at Two PMR Plants." No response required. GRIER.B.H. Region 1, Philadelphio. Office of the Director. 79/11/16. ip.
- 7912100117 Forwards IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads." No response required. GRIER.B.H. Region I, Philadelphia, Office of the Director. 79/11/16. 1p.
- 7912110405 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/11/19. 1p.

- 7912090233 Forwards IE Bulletin 79-26, "Boron Loss From BWR Control Blades," No response required.
  GRIER, B.M. Region 1, Philadelphia, Office of the Director.
  79/11/20. 1p.
- 7912060570 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BHRs." No response required. GRIER.B.H. Region 1. Philadelphia. Office of the Director. 79/11/26. 1p.
- 7912110044 Forwards 1E Circular 79-23. "Motor Starters & Contactors Failed to Operate." No response required. GRIER.B.H. Region 1. Philadelphia. Office of the Director. 79/11/26. 1p.
- 7912190022 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." No written response required. ORIER B.H. Region 1, Philadelphia, Office of the Director. 79/11/30. 1p.
- 7912310211 Forwards IE Info Notice 79-30. "Reporting of Defects & Nancompliances, 10CFR21." No action required. ORIER.B.H. Region 1. Philadelphia. Office of the Director. 79/12/06. 1p.
- 7912190744 Forwards 1E Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Written response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director. 79/12/07. 1p.
- 7912280193 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required.
  ORIER.B.H. Region 1, Philadelphia, Office of the Director.
  79/12/13. 1p.
- 8. Reportable occurrences, LERs & related correspondence
- 7912140092 Ack receipt of 791009 itr forwarding final deficiency rept re safety-releted piping. CARLSON.R.T. Region 1. Philadelphia. Reactor Construction & Engineering Support Branch. 79/10/17. ip.
- 7912310206 Ack receipt of 791019 ltr forwarding Final Significant Deficiency Rept 78-03 re reactor containment liner overlay pad fillet weld crack. CARLSON.R.T. Region 1. Philadelphia. Reactor Construction & Engineering Support Branch. 79/11/15. 1p.
- 7912110340 Forwards Final Deficiency Rept 79-03 re crane wall reinforcing bars omitted from concrete placement. HODLEYER, E. J. Duquesne Light Co. 79/12/05, 3pp.
- --7912110353 Final Deficiency Rept 79-03 re steel reinforcing bars missing from concrete wall. Concrete bars will be removed & rebuilt.Procedures developed & revised to implement insp. \* Duquesne Light Co. 79/12/05. 3pp.
- DOCKET 50-419 CATAWOA NUCLEAR STATION, UNIT 1
- A. Application/construction stage documents & correspondence
- 7912110011 Forwards NRC position on status & applicability to pending OL applications of results of TM1 followup actions Outlines add1 short-term actions to be taken.

  VASSALLO, D. B. Division of Project Management. 79/09/27. 4ipp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgrades emergency plans to plants under const & CL review. Applicants required to make cortain emergency arrangements w/state & local organizations & submit emergency plans per Reg Guide 1.101.

  VASSALLO D. B. Division of Project Management. 79/11/21. 6pp.
- I. Financial information
- 7912270577 Forwards duplicate copies of util 790321 guarantee of retrospective premiums in response to NRC 791210 request. HHITLEY.H.O. Duke Power Co. 79/12/20. ip.
- --7912270585 Requests approved guarantee of payment of deferred premiums for 1979. SALTIMAN J. Antitrust & Indemnity Group. 79/12/10. 1p.

- Q. Inspection reports: IE Bulletins & correspondence
- 7912040130 Responds to IE Bulletins 78-12, 78-12A & 78-12B re weld mail documentation. Info pertinent to Catamba Unit 1 reactor vessel included in RDM rept which was submitted 791029. Hestinghouse transmittal 1tr encl.
  PARXER, H. G. Duke Power Co. 79/11/07. 1p.
- --7912040138 Forwards rept "Weld Matl Documentation of Eleven Reactor Pressure Vessels Fabricated by RDM for Westinghouse," in response to IE Bulletin 78-12. Complete records search made & no atypical weld matl found. ANDERSON.T.M. Westinghouse Electric Corp., PWR Systems Div. 79/10/29. ip.
- 7912060128 Forwards IE Info Notice 79-12A, "Attempted Damage to New Fuel Assemblies." No specific action or response required. D'REILLY, J.P. Region 2. Atlanta, Office of the Director. 79/11/09. 2pp.:
- 7912100169 Forwards IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads." No response required. O'REILLY, J. P. Region 2. Atlanta. Office of the Director. 79/11/16. 1p.
- 7912110545 Forwards IE Info Notice 79-29. "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/16. 2pp.
- 79:2060607 Forwards IE Circular 79-24, "Proper Installation & Calibr of Cure Spray Pipe Break Detection Equipment on BWRs." No response required. 0'REILLY.J.P. Region 2. Atlanta, Office of the Director. 79/11/26. ip.
- 7712110134 Forwards IE Circular 79-12, "Motor Starters & Contactors Failed to Operate." No response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/26, 1p.
- 7912190392 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." No written response required.
  0'REILLY, J. P. Region 2. Atlanta, Office of the Director.
  79/11/30. 1p.
- 7912180161 Ack receipt of IE Insp Repts 50-413/79-19 & 50-414/79-19 on 791009-12 No proprietary info.
  PARKER, N. O. Duke Power Co. 79/12/09, 1p.
- ---7912180166 Forwards IE Insp Repts 50-413/79-19 & 50-414/79-19 on 791009-12 No noncompliancs noted.
  HURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/11/08. 2pp.
- 7912180174 IE Insp rapts 50-413/79-19 & 50-414/79-19 on 791009-12. No noncompliance noted. Major areas inspected: safety-related 4160-voit whitchinger. 600-voit load ctr & 600 mater control ctr installation & quality records.

  WALTERS, D. K. Region 2. Atlanta, Office of the Director, CONLON, T.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/11/08. App.
- 7912310293 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action required.
  O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
  79/12/04. Spp.
- 7912200026 Forwards IE Bulletin 79-28, "Possible Malfunction of Names Model EA180 Limit Switches at Elevated Temps." Action required.
  O'REILLY, J.P. Region 2. Atlanta, Office of the Director, 79/12/07. 2pp.
- 7912280377 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required. O'REILLY, J. P. | Region 2, Atlanta, Office of the Director. 79/12/13. 2pp.
- 7912280129 Forwards IE Circular 79-25, "Shock Arrestor Strut Assembly Interference." No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 79/12/20. 4pp.

- g. Reportable accurrences, LERs & related correspondence
- 79:2180588 Forwards final deficiency rept re deficient weld in steam generator lower lateral support & oversize drawing of reactor bldg. PARKER, M. O. Duke Power Co. 79/12/13. 1p.
- --7912180593 Final deficiency rept re deficient weld in steam generator lower lateral support. In June 1979, pinhole discovered in weld preparation area Reinsp showed three addl rejectable indications. Part returned for repair.

  # Duke Power Co. 79/12/13. 5pp.
- 7912310489 Forwards Significant Deficiency Rept IE-79-05-9DD-413/414 re unqualified main steam power operated relief valves. PARKER, W. O. Dute Power Co. 79/12/26. 1p.
- --7912310493 Significant Deficiency Rept IE-79-05-SDD-413/414. Main steam power operated relief valves not qualified for expected environ resulting from feedwater or steam line break. Valves will be qualified.

  \* Dute Power Co. 79/12/26. 1p.

## DOCKET 50-414 CATAMBA NUCLEAR STATION, UNIT 2

- A. Application/construction stage documents & correspondence
- 7912110011 Forwards NRC position on status & applicability to pending OL applications of results of TMI followup actions. Outlines add1 short-term actions to be taken.
  VASPALLO, D. 8. Division of Froject Management. 79/09/27. 41pp.
- 7912110264 Discusses NRC plans to use generic analyses to develop early varification program to resolve ATWB issue for PMRs & BWRs.
  Buccess of program depends on industry response. Bupports formation of owners groups to provide necessary info.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7911270467 Forwards "Discussions of TMI Lessons Learned Short-Term Requirements" providing addl clarifications of NRC requirements for pending OL applicants. VASEALLO, D. B. Division of Project Management. 79/11/09. 2pp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Quids 1. 101.
  VABBALLO: D.B. Division of Project Management. 79/11/21. 6pp.

# 1. Financial information

- 7912270577 Forwards duplicate copies of util 790321 guarantee of retrospective premiums: in response to NRC 791210 request, MHITLEY, H. D. Duke Power Co. 79/12/20. ip.
- --7912270385 Requests approved guarantee of payment of deferred premiums for 1979. BALTZMAN.J. Antitrust & Indemnity Group. 79/12/10. ip.
- Q. Inspection reports: IE Bulletins & correspondence
- 7912040130 Responds to IE Bulletins 78-12,78-12A & 78-12B re weld math documentation. Info pertinent to Catamba Unit 1 reactor vessel included in RDM rept which was submitted 791029. Hestinghouse transmittel ltr encl. PARKER, W. O. Duke Power Co. 79/11/07. 1p.
- --7912040138 Forwards rept "Weld Matl Documentation of Eleven Reactor Pressure Vessels Fabricated by RDM for Westinghouse." in response to 1E Bulletin 78-12. Complete records search made to a typical weld matl found. ANDERBON.T. M. Westinghouse Electric Corp., PWR Systems Div. 79/10/29. 1p.
- 7912060128 Forwards IE Info Notice 79-12A. "Attempted Damage to New Fuel Assemblies." No specific action or response required. D'REILLY.J.P. Region 2. Atlanta, Office of the Director. 79711/09. 2pp.
- 7912100169 Forwards IE Info Notice 79-28. "Overloading of Structural Elsaents Due to Pipe Support Loads." No response required. D'REILLY, J. P. Region 2. Atlanta, Office of the Director. 79/11/16. ip.

- 7912110545 Forwards IE Info Notice 79-29. "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/16. 2pp
- 7912060607 Forwards 1E Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BURs." No response required.
  O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
  79/11/26. 1p.
- 7912110134 Forwards IE Circular 79-12. "Motor Starters & Contactors Failed to Operate." No response required. D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/26. 1p.
- 7912190392 Forwards IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." No written response required. G'REILLY, J.P. Region 2. Atlanta. Office of the Director. 79/11/30. 1p.
- 7912180161 Ack receipt of IE Insp Repts 50-413/79-19 & 50-414/79-19 on 791009-12 No proprietary info.
  PARKER, H. C. Duke Power Co. 79/12/05. ip.
- --7912180166 Forwards IE Insp Repts 50-413/79-19 & 50-414/79-19 on 791009-12.No noncompliance noted.
  MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/11/08. 2pp.
- 7912180174 IE Insp repts 80-413/79-19 & 50-414/79-19 on 791009-12 No noncompliance noted Major areas inspected: safety-related 4160-volt switchgear 600-volt load ctr & 600 motor control ctr installation & quality records.

  MALTERS, D. K. Region 2, Atlanta, Office of the Director.

  CONLON.T.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch.
- 7912310293 Forwards IE Info Notice 79-30. "Reporting of Defects & Noncompliances: 10CFR21." No action required. O'REILLY, J. P. Region 2: Atlanta, Office of the Director, 79/12/06. Spp.
- 7912200026 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EAISO Limit Switches at Elevated Temps." Action required.

  O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
  79/12/07. 2pp.
- 7912280377 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required.
  O'REILLLY.P. Region 2, Atlanta, Office of the Director.
  79/12/13. 2pp.
- 7912280129 Forwards IE Circular 79-25, "Shock Arrestor Strut Assembly Interference." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/12/20. 4pp.
- 8. Reportable occurrences, LERs & related correspondence
- 791218058B Forwards final deficiency rept re deficient weld in steam generator lower lateral support & oversize drawing of reactor bldg.
  PARKER, M. O. Duke Power Co. 79/12/13. 1p.
- --7912180593 Final deficiency rapt re deficient weld in steam generator lower lateral support in June 1979, pinhole discovered in weld preparation area. Reinsp showed three addl rejectable indications. Part returned for rapair.

  \* Duke Power Co. 79/12/13. 5pp.
- 7912310489 Forwards Significant Deficiency Rest IE-79-05-SDD-413/414 reunqualified main steam power operated relief valves. PARKER, N. O. Duke Power Co. 79/12/26. 1p.
- ---7912310493 Bignificant Deficiency Rept IE-79-05-BDD-413/414. Hain steam pawer operated relief valves not quelified for expectes environ resulting from feedwater or steam line break. Valves will be qualified.

  # Duke Power Co. 79/12/26. 1p.

- DOCKET 50-415 GRAND GULF NUCLEAR STATION, UNIT 1
- A. Application/construction stage documents & correspondence
- 7912110011 Forwards NRC position on status & applicability to pending OL applications of results of TMI followop actions. Outlines addl short-term actions to be taken.

  VASSALLO.D. B. Division of Project Management. 79/09/27. 41pp.
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATM3 issue for PMRs & BMRs. Success of program depends on industry response Supports formation of aumers groups to provide necessary info.

  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.
- 7912110251 Notification of 800103 meeting w/util, ANL, INEL & Savannah River Lab in Port Gibson, MS to familiarize natl lab FSAR reviewers w/facility, HOUGHTON, T. C. Light Water Reactors Branch 2. 79/11/29. 3pp.
- 7912130127 Summary of 791116 meeting w/util & OE in Bethesda, MD re discussion of connector requirements for power generation control complex. HDVQHTQN,T.C. Light Water Reactors Branch 2. 79/11/29. Spp.
- 7912100130 Notification of 791212 meeting & site visit w/Btate of MS representatives to discuss NPDES & glant transmission line impacts on blota.

  COTAP.C. Environmental Projects Branch 1, 79/11/30, 2pp.
- 7912100310 Forwards initial questions re FSAR in response to 791115 discussion. Requests NRC assistance in obtaining answers to all questions.

  TAYLOR.T.M. E. I. du Pont de Nemours & Co., Inc. 79/11/30. 9pp.
- 7912130059 Extends invitation to attend 791013 site visit re environ review of OL application.
  RECAN.H.H. Assistant Director for Environmental Projects.
  79/12/03. 3pp.
- 7912210416 Forwards facility site maps & requests info re endangered plant & animal species in area.
  BALLARD,R.L. Division of Site Safety & Environmental Analysis, 79/12/17. Opp.
- C. Utility Environmental Report (ER), amends & correspondence
- 7912030193 Forwards Amend 2 to environ rept. STAMPLEY.N.L. Mississippi Power & Light Co. 79/11/30. 3pp.
- --7912030194 Amend 2 to environ rept. STAMPLEY,N.L. Mississippi Power & Light Co. 79/11/30. 39pp.
- 7912100339 Forwards affidavit of svc for distribution of Amend 2 to final environ rept in response to 780627 request. DALE, L. F. Mississippi Power & Light Co. 79/12/04. 2pp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review. Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Rog Quide 1. 101. VASSALLO, D.B. Division of Project Management. 79/11/21. 6pp.
- 7912210084 Summary of 791130 meeting w/utils & Bechtel in Bethesda, MD re-current NRC position on fire protection criteria.
  HQUGHTOR, T. C. Light Mater Reactors Branch 2. 79/12/05. 4pp.
- Q. Adjudicatory correspondence
- 7912120361 Requests that DDJ be asked to reconsider recommendations to show cause for compliance w/license conditions in light of new info. Forwards settlement agreement between intervenors & other supporting documentation.

  CONNER.T. B. Conner. Moore & Corber. 79/12/10. 150pp.
- H. General correspondence
- 7912190555 Forwards affidavit of svc for distribution of Amend 34 per NRC 780587 ltr. DALE, L. F. Mississippi Power & Light Co. 79/12/10. 2pp.

- K. Utility Final Bafety Analysis Report (FSAR) & amends
- 7912040497 Forwards Amend 34 to FSAR, submitted as amend to QL application. Also forwards three oversize drawings. Affidavit encl. STAMPLEY, N. L. Mississippi Power & Light Co. 79/11/30. 3pp.
- --7912050500 Amend 34 to FSAR, submitted as amend to OL applications.

  \* Mississippi Power & Light Co. 79/11/30. 500pp.
- 7912310401 Forwards Amend 35 to FSAR, constituting Amend 35 to application for OL.
  STAMPLEY, N. L. Mississippi Power & Light Co. 79/12/28, 3pp.
- --7912310408 Amend 35 to FSAR consisting of responses to second round questions & miscellaneous refinements of design info,

  \* Mississippi Power & Light Co. 79/12/28. AOpp.
- Q. Inspection reports, IE Bullatins & correspondence
- 7912050386 Forwards IE Insp Ropts 50-416/79-24 & 50-417/79-24 on 790926-28. No noncompliance noted. MURPHY.C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/10/23. 2pp.
- --7912050394 IE Insp Repts 50-416/79-24 & 50-417/79-24 on 790926-28 Na noncompliance nuted Major areas inspected: GC program, const progress, IE bulletin followup & licensee followup of licensee identified items.

  BRYANT, U. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. RAUSCH, U. K. Region 2, Atlanta, Office of the Director, 79/10/23, 4pp.
- 7912050562 Forwards IE Insp Repts 50-416/79-22 & 50-417/79-22 on 790725-28. No noncompliance noted.

  MURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/10/24. 2pp.
- --7912050596 IE Insp Repts 50-416/79-22 & 50-417/79-22 on 790925-28.No noncompliance noted. Major areas inspected: instrumentation work work activities & quality records.
  CONLON.T.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. OIBBONS.T.D. Region 2, Atlanta, Office of the Director. 79/10/23, 4pp.
- 7912050616 Forwards IE Insp Repts 50-416/79-23 & 50-417/79-23 on 790925-28. No noncompliance noted. MURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/10/24. 2pp.
- --7912050618 IE Insp Repts 40-416/79-23 & 50-417/79-23 on 790925-28.No noncompliance noted Major areas inspected safety-related pipe welding & insp activities & safety relief valve radiographic film review.

  HERDI.A.R. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. VAN DDORN.P.K. Region 2. Atlants, Office of the Director. 79/10/23. Spp.
- 7912050083 Forwards IE Insp Ropts 50-416/79-25 & 50-417/79-23 on 791003-05. No noncompliance noted. MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 79/10/25. 2pp.
- --7912050089 IE Insp Repts 80-416/79-25 & 50-417/79-25 on 791003-05.No noncompliance noted Major areas inspected: pipe support plate designs using concrete expansion anchor bolts (IE Bulletin 79-02).

  VALLISH E. J. Region 2, Atlanta, Defice of the Director. HERDIA. R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/10/25. 3pp.
- 7912060186 Forwards IE Info Notice 79-12A, "Attempted Damage to New Fuel Assemblies." No specific action or response required. U'REILLY, J. P. Region 2, Atlanta, Office of the Director, 79/11/09. 2pp.
- 79:2100:85 Forwards IE Info Notice 77-28, "Overloading of Btructural Elements Due to Pipe Support Loads." No response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/14. 1p.
- 7912110366 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79711716. 2pp.

- 7912060618 Forwards IE Circular 79-24, "Proper Installation & Calibr of Care Spray Pipe Break Detection Equipment on BWRs." No response required.

  O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
  79/11/26. 1p.
- 79:21:0183 Forwards IE Circular 79-20, "Motor Starters & Contactors Failed to Operate." No response required.
  O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
  79/11/26. 1p.
- 7912060235 Forwards IE Insp Rept 50-416/79-27 on 791003-04.No noncompliance hoted.
  D'REILLY, J.P. Region 2, Atlanta, Office of the Director.
  79/11/28. 2pp.
- --7912060260 IE Insp Rept 50-416/79-27 on 791003-04. No noncompliance noted Major areas inspected: insp program for facility during preoperational & startup testing.

  MAGNER, A.O. Region 2, Atlanta, Office of the Director.

  KELLOGO, P. J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/11/21. 3pp.
- 7912190457 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." Written response required.

  D'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/11/30. 1p.
- 7912310306 Forwards IE Info Notice 79-30, "Reporting of Defects & Montompliances, 10CFR21," No action required.
  D'REILLY, J. P. Region 2. Atlanta, Office of the Director.
  79/12706. Spp.
- 7912200049 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required.

  0'REILLY, J. P. Rugion 2, Atlanta, Office of the Director.
  79/12/07. 2pp.
- 7912280416 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Rasponse Bectra." No written response required.
  O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
  79/12/13. 2pp.
- 7912280144 Forwards IE Circular 79-25, "Shock Arrestor Btrut Assembly Interference." No written response required. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 79/12/20. 4pp.
- S. Reportable occurrences, LERs & related correspondence
- 7912130524 Interim deficiency rept re failure of Type L2 auxiliary switch assembly in 4.16 kV switchgear. Switch assembly returned to equipment supplier, Gould Electric Sys, for analysis. Resolution expected by BO0228.

  DALE, L. F. Mississippi Power & Light Co. 79/11/01. ip.
- 7912130526 Forwards Final Deficiency Rept 79-08.

  DALE, L. F. Mississippi Power & Light Co. 79/11/02. ip.
- --7912130332 Final Deficiency Rept 79-08 re failure of solid-state trip devices in low voltage power circuit breaker Caused by defective assembly of printed circuit boards supplied by Qould-Grown Bover: Suitchgear Div. 

  # Mississippi Power & Light Co. 79/11/02. 2PP.
- 7912180054 Confirms verbal rept re noncompliance to spece for nuclear valves. Caused by error in computer program, developed by subcontractor, All reported frequencies will be re-analyzed. NIEHAUS, P. W. William Powell Co. 79/11/12, 2pp.
- 7952190603 First interim deficiency rept re Rosemount Model 510 master & slave trip units. Results of investigation will be submitted by 800131.

  DALE-L.F. Mississippi Power & Light Co. 78/11/28. 1p.
- 7912190611 Interim deficiency rept re cracked control device assumblies on 4.16 kV switchgear, 6.9 kV switchgear & 480 volt load ctrs. 9autd-ITE conducting life testing of devices. Pinal rept will be submitted by 800125.

  DALE, L. P. Mississippi Power & Light Co. 79/11/30. lp.
- 7512190633 Interim deficiency rept re improper drawings supplied by OE. All termination cabinet panels being reviewed against as-whipped drawings. Findings will be submitted by 800115. DALE, L. F. Mississippi Power & Light Co. 79/11/30. 1p.

- 7912190702 Final deficiency rept re use of inadequately supported long terminal strip in junction boxes on electrical penetration assemblies for containment bldg. "Procedure to Brace CR151-Terminal Blocks for Electrical Penetration." issued.

  DALE, L. F. Mississippi Power & Light Co. 79/12/03. 2pp.
- DOCKET 50-417 GRAND GULF NUCLEAR STATION, UNIT 2
- A. Application/construction stage documents & correspondence
- 7912110011 Forwards NRC position on status & applicability to pending OL applications of results of TMI followup actions. Outlines addl short-term actions to be taken.
  VASBALLO,D.B. Division of Project Management. 79/09/27. 41pp.
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATWS issue for PWRs & DWRs.
  Success of program depends on industry response. Supports formation of numbers groups to provide necessary info.
  DENTON.H. R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.
- 7912110251 Notification of 800103 meeting w/util, ANL, INEL & Savannah River Lab in Port Gibson, MS to familiarize natl lab FBAR reviewers w/facility, HDUOHTON, T. C. Light Water Reactors Branch 2. 79/11/29. 3pp.
- 7912130127 Summary of 791116 meeting w/vtil & GE in Rethesda MD rediscussion of connector requirements for power generation control complex.

  HOUGHTON T. G. Light Water Reactors Branch 2. 79/11/29. Spp.
- 7912100130 Notification of 791212 meeting & site visit w/State of MS representatives to discuss NPDES & plant transmission line impacts on bipta.

  COTALP.C. Environmental Projects Branch 1. 79/11/30. 2pp.
- 7912100310 Forwards initial questions re FSAR in response to 791115 discussion. Requests NRC assistance in obtaining answers to all questions.

  TAYLOR.T.M. E.I.du Pant de Nemours & Co., Inc. 79/11/30. 9pp.
- 7912130099 Extends invitation to attend 791013 site visit re environ review of OL application.
  REGAN, W.H. Assistant Director for Environmental Projects.
  79/12/03. 3pp.
- 7912210416 Forwards facility site maps & requests info me endangered plant & animal species in area.

  BALLARD.R.L. Division of Site Safety & Environmental Analysis.
  79/12/17. Opp.
- C. Utility Environmental Report (ER), amends & correspondence
- 7912030193 Forwards Amend 2 to environ rept. BTAMPLEY,N.L. Mississippi Power & Light Co. 79/11/30. 3pp.
- --7912030194 Amend 2 to environ rept. STAMPLEY,N.L. Mississippi Power & Light Co. 79/11/30. 39pp.
- 7912100339 Forwards affidavit of svr for distribution of Amend 2 to final environ rept in response to 780627 request.

  DALE: L.F. Mississippi Power & Light Co. 79/12/04. 2pp.
- F. Security, medical, emorgency & fire protection plans
- 7912040471 Forwards info re upgraded amergency plans to plants under const & OL review. Applicants required to make certain amergency arrangements w/state & local organizations & submit emergency plans per Reg Guide 1.101.
  VABSALLO, D.B. Division of Project Management. 79/11/21. App.
- 7912210084 Summary of 791130 meeting w/utils & Bechtel in Bethesda,MD re current NRC position on fire protection criteria.

  HDUQHTON,T.C. Light Water Reactors Branch 2. 79/12/05. 4pp.
- O. Adjudicatory correspondence
- 7912120361 Requests that DOJ be asked to reconsider recommendations to show cause for compliance w/license conditions in light of new info. Forwards settlement agreement between intervenors & other supporting documentation.

  CONNER, T. B. Conner, Moore & Corber. 79/12/10. 150gp.

### H. General correspondence

- 7912190555 Forwards affidavit of svc for distribution of Amend 34 per NRC 780627 ltr. / itr. - Mississippi Power & Light Co. - 79/12/10, - 200.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 7912060497 Forwards Amend 34 to FSAR submitted as amend to OL application. Also forwards three oversize drawings.
  Affidavit encl.
  STAMPLEY. N. L. Hississippi Power & Light Co. 79/11/30. 3pp.
- --7912060500 Amend 34 to FSAR, submitted as amend to OL applications. \* Mississippi Power & Light Co. 79/11/30, 500pp.
- 7912310401 Forwards Amend 35 to FSAR, constituting Amend 35 to application for OL. STAMPLEY,N.L. Mississippi Power & Light Co. 79/12/28. 3pp.
- --7912310408 Amend 35 to FSAR consisting of responses to second round questions & miscellaneous refinements of design info.

  \* Mississippi Power & Light Co. 79/12/28. 60pp.
- O. Inspection reports: IE Bulletins & carrespondence
- 7912080384 Forwards IE Insp Repts 50-416/79-24 & 50-417/79-24 on 790926-28. No noncompliance noted. MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 79/10/23. 2pp.
- --7912050394 IE Insp Repts 50-416/79-24 & 50-417/79-24 on 790926-28.No noncompliance noted Major areas inspected: 0C program, const progress, IE bulletin followup & licensee followup of licensee identified items.

  BRYANT, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch, RAUSCH, J. K. Region 2, Atlanta, Office of the Director. 79/10/23, 4pp.
- 7912050562 Forwards IE lnsp Repts 50-416/79-22 & 50-417/79-22 on 790925-28. No noncompliance noted. MURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/10/24. 2pg.
- --7912050896 IE Insp Repts 50-416/79-22 & 50-417/79-22 on 790925-28. No noncompliance noted. Major areas inspected: instrumentation work, work activities & quality records. CONLON.T.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. GIBBONS.T.D. Region 2, Atlanta, Office of the Director. 79/10/23, 4ρp.
- 7912050616 Forwards IE Insp Repts 50-416/79-23 & 50-417/79-23 on 770925-28. No noncompliance noted. MURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/10/24. 2pp.
- --7912050618 IE Insp Repts 40-416/79-23 & 50-417/79-23 on 790925-28.No noncompliance noted. Major areas inspected: safety-related pigs welding & insp activities & safety relief valve radiographic film raview.

  HERDT.A.R. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. VAN DOORN.P.K. Region 2. Atlanta. Diffice of the Director. 79/10/23. 8pp.
- 7912050083 Forwards IE Insp Repts 50-416/79-25 & 50-417/79-25 on 791003-05. No noncompliance noted.
  MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 79/10/25. 2pp.
- ---7912050089 IE Insp Repts 50-416/79-25 & 50-417/79-25 on 791003-05.No noncompliance noted.Major areas inspected:pipe support plate designs using concrete expansion anchor bolts (IE Bulletin 79-02).

  VALLIBH.E.J. Region 2. Atlanta, Office of the Director. HERDIA.R. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/10/25. 3pp.
- 7912060186 Forwards IE Info Notice 79-12A. "Attempted Damage to New Fuel Assemblies." No specific action or response required. O'REILLY.J.P. Region 2. Atlanta. Office of the Director. 79/11/09. 2pp.
- 7912100185 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/16. 1p.

- 7912110566 Forwards IE Info Notice 77-29, "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required.

  0'REILLY, J.P. Region 2. Atlanta, Office of the Director.
  79/11/16. 2pp.
- 7912060618 Forwards IE Circular 79-24. "Proper Installation & Calibr Core Spray Pipe Break Detection Equipment on BMRs." No response required. D'REILLY,J.P. Region 2, Atlanta, Office of the Director. 79/11/26. ip.
- 7912110153 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required, O'REILLY,J.P. Region 2, Atlanta, Office of the Director. 79/11/26. ip.
- 79:2190459 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation," No written response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/11/30. 1p.
- 7912310306 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director, 79/12/06. 5pp.
- 7912200049 Forwards IE Bulletin 79-28, "Possible Malfunction of Manca Model EA180 Limit Switches at Elevated Temps." Action required. O'#HEILLY.J.P. Region 2, Atlanta, Office of the Director. 79/12/07. 2pp.
- 7912280416 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required. O'REILLY,J.P. Region 2. Atlanta. Office of the Director. 79/12/13. 2pp.
- 7912280144 Forwards IE Circuler 79-25, "Shock Arrestor Strut Assembly Interference." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/12/20. 4pp.
- 8. Reportable occurrences: LERs & related correspondence
- 7912130524 Interim deficiency rept re failure of Type L2 auxiliary switch assembly in 4.16 kV switchgear. Switch assembly returned to equipment supplier, Gould Electric Sys, for analysis. Resolution expected by 800228, DALE, L. F. Mississippi Power & Light Co. 79/11/01, 1p.
- 7912130528 Forwards Final Deficiency Rept 79-08, DALE/L.F. Mississippi Power & Light Co. 79/11/02. 1p.
- --7912130832 Final Deficiency Rept 79-08 re failure of molid-state trip devices in low voltage power circuit breaker. Caused by defective assembly of printed circuit boards supplied by Gould-Brown Boveri Suitchgear Div. \* Mississippi Power & Light Co. 79/11/02. 2PP.
- 7912180054 Confirms verbal rept re noncompliance to space for nuclear valves. Caused by error in computer program developed by subcontractor. All reported frequencies will be re-analyzed. NIEHAUG. P. W. William Powell Co. 79/11/12. Rpp.
- 7912190603 First interim deficiency rept re Rosemount Hodel 510 mester & slave trip units. Results of investigation will be submitted by 800131.

  DALE.L.F. Mississippi Power & Light Co. 78/11/28. 1p.
- 7712190611 Interim deficiency rept re cracked control device assembliss on 4.16 kV switchgear, 6.9 kV switchgear & 480 volt load ctrs. Gould-ITE conducting life testing of devices. Final rept will be submitted by BOOIED.

  DALE, L. F. Mississippi Power & Light Co. 79/11/30, ip.
- 7912190633 Interim deficiency rept re improper drawings supplied by 95-All termination cabinet panals being reviewed against as-shipped drawings. Findings will be submitted by 800115, DALE.L.F. Mississippi Power & Light Co. 79/11/30. lp.
- 79:2190702 Final deficienty rept re use of inadequately supported long terminal strip in junction boxes on electrical penetration assemblies for containment bldg. "Procedure to Brace CRIDI-Terminal Blocks for Electrical Penetration: "issued.

  DALE.L.F. Mississippi Power & Light Co. 79/12/03. 2pp.

- DOCKET 50-423 MILLSTONE NUCLEAR POWER STATION, UNIT 3
- A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRs & BMRs.
  Success of program depends on industry response Supports forsestion of owners groups to provide necessary info.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912140227 Responds to IE Bulletin 79-14 re seismic analysis for safety-related piping sys. Requested insp cannot be carried out as piping erection not complete on any safety-related sys. COUNSIL, W. O., FEE, W. F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 79/11/06. 2pp.
- 7912310380 Cites inadequate rate relief & reduced cash requirements as reason for not amending const completion dates from 1984 to 1984. COUNSIL.W.O. Northeast Utilities. 79/12/19. 1p.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & DL review. Applicants required to make certain \*\*emergency arrangements w/state & local organizations & submit emergency plans per Reg Quide 1.
- Q. Inspection reports. IE Bulletins & correspondence
- 7912200521 Forwards IE Insp Rept 50-423/79-08 on 790924-26.No recovered forwards it insp Hept 30-423/79-08 on 790924-26. No moncompliance noted.

  CARLBON.R.T. Region 1. Philadelphia. Reactor Construction & Engineering Support Branch. 79/10/26. 2pp.
- 7912200526 IE Insp Rept 50-423/79-08 on 790924-26.No noncompliance noted Major areas inspected; progress on installation erection & welding on primary containment steel structures, supports & penetrations.

  TRIPP, L. E. Region i, Philadelphia, Reactor Construction & Engineering Support Branch. SANDERS, W.F. Region i, Philadelphia, Office of the Director. 79/10/25. 3pp.
- 7912140237 Responds to IE Bulletin 79-24. "Frozan Lines." Applicant has reviewed freeze protection design criteria & considers them adequats.
  COUNESTL. M. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 79/10/29. 2pp.
- 7912140022 Responds to IE Bulletin 79-23 re potential failure of amergancy dissel generator. Investigation indicates that type of failure described cannot occur at facility. COUNSIL, 41.0. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 79/10/30. ip.
- 7912050039 Forwards IE Circular 79-22, "Stroke Times for Power Operated Ralief Valves." No response required. Office of the Director. 79/11/14. 1p.
- 7912030266 Forwards IE Info Notice 79-27, "Steam Generator Tube Ruptures at Two PMR Plants." No response required. GRIER. B. H. Region 1, Philadelphia, Office of the Director. 79/11/16. 1p.
- 7912100131 Forwards IE Info Notice 77-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. SRIER. B. M. Region 1, Philadelphia, Office of the Director. 79/11/16, 1p.
- 7912110422 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. ORIER, B. H. Region i, Philadelphia, Office of the Director. 79/11/19. 1p.
- 7912030255 Forwards IE Bullstin 79-26, "Boron Loss From BMR Control Blades." No response required.

  ORIER.B. H. Region 1, Philadelphia, Office of the Director.
  79/11/20. 1p.
- 7912060579 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BMRs." No rasponse required.
  ORIER, B. H. Region 1. Philadelphia, Office of the Director.
  79/11/26. 1p.

- 7912110060 Forwards IE Circular 79-29, "Hotor Starters & Contactors Failed to Operata." No response required.
  GRIER, B. H. Region 1, Philadelphia, Office of the Director.
  79/11/26. 1p.
- 7912170039 Forwards IE Bulletin 79~27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation." Written response required.
  GRIER, B. H. Region 1, Philadelphia, Office of the Director.
  79/11/30. lp.
- 7912310226 Forwards IE Info Notice 79-30, "Reporting of Defacts & Noncompliances, 10CFR21." No action required.

  CRIER, B. H. Region 1, Philadelphia, Office of the Director.
  79/12/06. 4pp.
- 7912190754 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Written response required. GRIER.B.H. Region 1, Philadelphia. Office of the Director. 79/12/07. 1p.
- 7912280207 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Epectra." No written response required.

  ORIER, B. H. Region 1, Philadelphia, Office of the Director.
  79/12/13, 1p.
- DOCKET 50-424 ALVIN W. VOOTLE NUCLEAR PLANT, UNIT 1
- A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early varification program to resolve ATMS issue for PMRs & BMRs. Buccess of program depends on industry response. Bupports formation of owners groups to provide necessary info. DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912040445 Informs NRC of two developments which may relate to various requests & communications from Georgians Against Nuclear Energy, Current territorial generation expansion plan for meeting load forecast encl.

  EHRENSPERGER, M. Géorgia Power Co. 79/11/27. 15pp.
- 7912200090 Forwards review of foundation const & water control measures. Addl info necessary for review of foundation safety.
  RUBENSTEIN, L. B. Light Water Reactors Branch 4. 79/12/06. 7pp.
- --7912200096 Forwards trip rept re insp of eroded foundations. Identifies & lists areas affected by erosion. Attendance list & rept on erosion problems encl.
  THOMPSON.O.D. Division of Bite Bafety & Environmental Analysis.
  79/12/06. 9pp.
- 7912140236 Forwards meterological data, including joint frequency tables for intermittent periods between 1972-1979, summary of accident X/O values & two plots of X/O values, EHRENSPERGER. W. Georgia Power Co. 79/12/07. ip.
- ---7912140382 Joint frequency tables of wind speed & direction for temp difference for intermittent periods between 1972-1979, summary of accident X/Q values & two plots of X/Q values. \* Gaorgia Power Co. 79/12/07. IBpp.
- 7912210006 Forwards safety evaluation of erosion problems at facility & request for add1 info.Response requested within seven days.
  RUBENSTEIN.L.S. Light Water Reactors Branch 4. 79/12/10. 2pp.
- -- 7912210009 Bafety evaluation of site erosion problems. Requests addl ro. Office of Nuclear Reactor Regulation. 79/12/10. App.
- 7912280485 Requests NRC approval of use of ABME Section III Code Case N-242. "Matis Certification." List of all sys using matis in code case will be incorporated into FBAR.
  EHRIEMSFERGER.W. Georgia Power Co. 779/12/18. 1p.
- B. Utility Freliminary Safety Analysis Report, amends
- 7912210340 Forwards Suppl 7 to PSAR, submitted as suppl to application for CP & GL. EHRENSPERGER, W. Georgia Power Co. 79/12/10: ip.
- --7912210344 Suppl 7 to PBAR. EHRENSPERGER, W. Georgia Power Co. 79/12/06. 15pp.

## F. Security, medical, emergency & fire protection plans

- 7912040471 Forwards info re upgraded emergency plans to plants under const & DL review. Applicants required to make certain emergency arrangements wistate & local organizations & submit emergency plans per Reg Ouide 1.101.

  VASSALLO.D.B. Division of Project Management. 79/11/21. Opp.
- Q. Adjudicatory correspondence
- 7912270418 Requests apportunity be given to examine & comment on any add1 info re Georgians Against Nuclear Energy petition.
  Inquires whether info in HE Ehresperger 791127 ltr is being considered in relation to docket.
  FLACK. G. Myer. Bauman. Stroup & Flack. 79/12/18. lp.
- G. Inspection reports, IE Bulletins & correspondence
- 7912060148 Forwards IE Info Notice 79-12A. "Attempted Domage to New Fuel Assamblies." No specific action or response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 79/11/09. 2pp.
- 7912100184 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. O'REILLY, J.P. Region 2. Atlanta. Office of the Director. 79/11/14. 1p.
- 7912110562 Forwards IE Info Notice 79-29. "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required. O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 79/11/16. 2pp.
- 7912040617 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipo Break Detection Equipment on BWRs." No response required.

  O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
  79/11/26. lp.
- 7912110149 Forwards IE Circular 79~23, "Motor Starters & Contoctors Failed to Operate." No response required.
  D'REILLY,J.P. Region 2, Atlanta, Office of the Director.
  79/11/26. ip.
- 7912190449 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation."
  No written response required.
  O'REILELY.J.P. Region 2. Atlanta, Office of the Director.
  79/11/30. 12.
- 7912310301 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action required.
  O'REILLY, J. P. Region 2, Atlanta, Office of the Director, 79/12/06. Spp.
- 7912200038 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. 0'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/12/07. 2pp.
- 7912280404 Forwards IE Info Notico 79-31, "Use of Incorrect Amplified Response Spectra," No written response required.
  O'REILLY,J.P. Region 2, Atlanta, Office of the Director.
  79/12/13. 2pp.
- 7912280141 Forwards IE Circular 79-25, "Shock Arrestor Strut Assembly Interference." No written response required. O'REILLY, P. Region 2. Atlanta, Office of the Director. 79/12/20. 4pp.
- 8. Reportable occurrences, LERs & related correspondence
- 7912200471 PND-II-79-032:on 791115.util & inspector at site reported surface run off due to heavy rain-damaged excavation & backfill slopes around power block area.

  HUNT.D. CANTRELL,R.S. Region 2, Atlanta, Office of the Director.
  79/11/15. 1p.
- 7912170301 Interim deficiency rept re dematering & erosion of Backfill.
  Responses to NRC confirmation of action & confirmation of
  concurrence provide current status of evaluation. Followup
  rept will be provided by 800115.
  DUTTON. D. Georgia Power Co. 79/12/10. 2pp.

- DOCKET 50-425 ALVIN W. VOGTLE NUCLEAR PLANT, UNIT 2
- A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRs & BMRs.
  Success of program depends on industry response Supports formation of owners groups to provide necessary info.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912040445 Informs NRC of two developments which may relate to various requests & communications from Georgians Against Nuclear Energy. Current torritorial generation expansion plan for meeting load forecast oncl.

  EHRENSPERGER. W. Georgia Power Co. 79/11/27. 15pp.
- 7912200090 Forwards review of foundation const & water control measures. Addl info necessary for review of foundation safety.
  RUBENSTEIN. L. B. Light Water Reactors Branch 4, 79/12/06. 7pp.
- --7912200096 Forwards trip rept re insp of eroded foundations. Identified & lists areas affected by erosion. Attendance list & rapt on erosion problems enci.
  THOMPSIN, D. C. Division of Site Safety & Environmental Analysis.
  79/12/06. 9pp.
- 7912140236 Forwards meterological dota, including joint frequency tables for intermittent periods between 1972-1979, summary of accident X/O values & two plots of X/O values.

  EHRENSPERGER, W. Georgia Power Co. 79/12/07. 1p.
- --7712140382 Joint frequency tables of wind speed & direction for test difference for intermittent periods between 1972-1979, summary of accident X/Q values & two plots of X/Q values. \* Georgia Power Co. 79/12/07. iBpp.
- 7912210006 Forwards safety evaluation of erosion problems at facility & request for add1 info. Response requested within seven days.
  RUBENBTEIN. L. 8. Light Water Reactors Branch 4. 79/12/10. 2pp.
- --7912210009 Safety evaluation of site erosion problems.Requests adding info.
  # Office of Nuclear Reactor Regulation. 79/12/10. App.
- 7712280485 Requests NRC approval of use of ASME Section III Code Case N-242. "Matis Certification." List of all sys using matls in code case will be incorporated into FSAR. EHRENBFERGER.M. Georgia Fower Co. 77/12/18. ip.
- B. Utility Preliminary Safety Analysis Report, amends
- 7912210340 Forwards Buppl 7 to PSAR, submitted as suppl to application for CP & OL. EHRENBEROGER, Opengia Power Co. 79/12/10, ip.
- --7912210344 Suppl 7 to PSAR. EHRENSPERGER.W. Georgia Power Co. 79/12/06. 15pp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review. Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Quide 1, 101.
  VABSALLO.D.B. Division of Project Management. 79/11/21. 6pp.
- 0. Adjudicatory correspondence
- 7912270418 Requests opportunity be given to examine & comment on any addl info re Georgians Against Nuclear Energy patition.
  Inquires whether info in WE Ehresperger 791127 ltr is being considered in relation to docket.
  FLACK, G. Myer, Bauman, Stroup & Flack, 79/12/18. ip.
- G. Inspection reports, IE Bulletins & correspondence
- 7912060148 Forwards IE Info Notice 79-12A, "Attempted Damage to New Fuel Assemblies." No specific action or response required.
  O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
  79/11/09. 2pp.

- 7912100184 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. O'REILLY, L.P. Region 2, Atlanta, Office of the Director, 79/11/16. ip.
- 7912110862 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No spacific action or response required.

  0'AEELLYJJ.P. Region 2, Atlanta, Office of the Director.
  79/11/16. 2pp.
- 7912050517 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No response required.

  0'REILLY.J.P. Region 2, Atlanta, Office of the Director.
  79/11/26. 1p.
- 77i2110149 Forwards IE Circular 77-23, "Motor Starters & Contactors Failed to Operate." No response required, D'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/26. 1p.
- 7912190449 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." No written response required.
  O'RELLLY, J.P. Rogion 2, Atlanta, Office of the Director.
  79/11/30. 1p.
- 7912310301 Forwards IE Info Notice 79-30, "Reporting of Defects & Nancompliances, 10CFR21," No action required.
  O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
  79/12/06. Spp.
- 7912200038 Forwards IE Bulletin 79-28. "Possible Malfunction of Namco Model EdiBo Limit Switches at Elevated Temps." Action required. O'REELLY.J. P. Region 2. Atlanta, Office of the Director. 79/12/07. 2pp.
- 7712280404 Forwards IE Info Notice 79-31, "use of Incorrect Amplified Response Spectra." No written response required.

  0'REILLY, P. Region 2, Atlants, Office of the Director.

  77/12/13. 2pp.
- 79:2280141 Forwards IE Circular 79-23, "Shock Arrestor Strut Assembly Interferonce." No written response required. D'REILLY,J.P. Region 2, Atlanta, Office of the Director. 79/12/20. 4pp.
- 8. Reportable occurrences, LERs & related correspondence
- 7912200471 PNO-II-79-032: on 791115, util & inspector at site reported surface run off due to heavy rain-damaged excavation & backfill slopes around power block area.
  HUNT, D., CANTRELL, R. S. Region 2, Atlanta, Office of the Director.
  79711/15. 1p.
- 7912170301 Interim deficiency rept re dewatering & erosion of backfill. Responses to NRC confirmation of action & confirmation of concurrence provide current status of evaluation. Followup rept will be provided by 800118.

  BUTTON.D. Georgia Power Co. 79/12/10. 2pp.
- DOCKET 50-426 ALVIN W. VOGTLE NUCLEAR PLANT, UNIT 3

  A. Application/construction stage documents & correspondence
- 7912200090 Forwards review of foundation const & water control massures, Add1 info necessary for review of foundation safety.
  RUBENSTEIN, L. S. Light Water Reactors Branch 4. 79/12/06. 7pp.
- --7912200096 Forwards trip rept re insp of eroded foundations. Identifies & lists areas affected by prosion. Attendance list & rept on erosion problems enci.
  THOMPSON. O. Division of Site Safety & Environmental Analysis.
  79/12/05. 9pp.
- DOCKET 50-427 ALVIN W. VOOTLE NUCLEAR PLANT, UNIT 4

  A. Application/construction stage documents & correspondence
- 7912200090 Forwards review of foundation const & water control measures. Add1 info necessary for review of foundation safety.
  RUBERSTEIN.L.S. Light Water Reactors Branch 4. 79/12/06. 7pp.

- --7912200096 Forwards trip rept ro insp of eroded foundations. Identifies & lists areas affected by erosion. Attendance list & rept on erosion problems encl.
  THOMPSON.O. O. Division of Site Safety & Environmental Analysis.
  79/12/06. 9pp.
- DOCKET 50-433 UC-SANTA BARBARA RESEARCH REACTOR

  F. Security, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Cuide 5.XX, "Std Format & Content for Licensee Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance." W/o encl. REID, R. W. Operating Reactors Branch 4 (Pre 791030), 79/08/22. 20s.

#### DOCKET STN-50-437 FLOATING NUCLEAR PLANT

- A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early vorification program to resolve ATWS issue for PWRs & BWRs. Success of program depends on industry response. Supports formation of owners groups to provide necessary info. DENTON.H.R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912070004 Requests distribution of encl memorandum to board notification syc lists.
  VARGA-5. A. Assistant Director for Light Water Reactors. 79/11/08.
- Inspection reports, IE Bulletins & correspondence
- 7912100188 Forwards IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads." No response required. O'REILLY, J. P. Region 2. Atlanta. Office of the Director. 79/11/16. ip.
- 7912110890 Forwards IE Info Notice 79-29. "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/16. 2pp.
- 7912070013 Forwards IE Circular 79-24. "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No response required. O'REILLYJ.P. Region 2, Atlanta, Office of the Director. 79/11/26. tp.
- 7912110192 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/24. 1p.
- 7912190500 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation."
  No written response required.
  0'REILLY, J.P. Region 2. Atlanta, Office of the Director.
  79/11/30. 1p.
- 7912310352 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances: 100FR21." No action required. O'REILLY, J.P. Region 2. Atlanta, Office of the Director, 79/12/06. 4pp.
- 7912200075 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Nodel EAISO Limit Switches at Elevated Temps." Action required.
  D'REILLY, J.P., Region 2, Atlanta, Diffice of the Director.
  79/12/07. 1g.
- 77:2280450 Forwards IE Info Notice 77-31, "Use of Incorrect Amplified Response Spectra." No written response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/12/13. 2pp.
- 7912280164 Forwards IE Circular 79-25, "Shock Arrestor Strut Assembly Interference." No written response required. O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 79/12/20. 4pp.

#### T. Hearing transcripts on non-antitrust matters

- 7912030031 Transcript of Subcommittee on Floating Nuclear Plant 791117 meeting in Los Angeles.CA.Pp. 1-224. Presentation. "Thermal Evaluation of FNP Core Ladle During Postulated Core Helt." by HT Pratt & RD Gasser encl.

  \* ACRS Advisory Committee on Reactor Safeguards. 79/11/17. 310pp.
- U. Congressional/Executive Correspondence
- 7912210164 Responds to 790906 Itr re B Peters 790806 request for info concerning mfg of floating nuclear plants by DPS NRC has not made final decision re granting of mfg license to DPS. Forwards FES & safety evaluation W/o encl. GOSSICK.L.V. Office of the Executive Director for Operations. 79/10/12. 4pp.
- --7912210178 Forwards 8 Peters ltr re NRC decision to issue license for const of floating nuclear plants. Requests comment. PRYOR.D. Senate. 79/09/06. ip.
- DOCKET 50~438 BELLEFONTE NUCLEAR PLANT, UNIT 1
- A. Application/construction stage documents & correspondence
- 7912110011 Forwards NRC position on status & applicability to pending BL applications of results of TMT followup actions. Dutlines addl short-term actions to be taken.

  VABSALLO, D. B. Division of Project Management. 79/09/27. 41pp.
- 7912110244 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for FMRs & BMRs. Success of program depends on industry response. Bupports formation of owners groups to provide necessary info.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.
- 791213052! Forwards updated proprietary electrical, instrumentation & control drawings. Affidavit encl. Drawings withheld (ref. 10CFR2, 790).
  HILLS.L.H. Tennessee Valley Authority, 79/11/30. 8pp.
- 7912050071 Responds to NRC 791028 ltr re design adaquacy of B&W nuclear steam supply sys utilizing once-through steam generators.
  Based on review of overcooling event consequences concludes continued const justified. CPs should not be changed.
  MILLB.L.M. Tennessee Valley Authority. 79/12/03. 100pp.
- 7912130023 Notification of 800110 meeting w/util to discuss reporting level of util QA & manager & QA review of documents.

  SPRAUL.J.O. Guality Assurance Branch. 79/12/05. ip.
- 7912260309 Requests info re sensitivity-to-feedwater transients be forwarded to TMI-1 Board.
  VULLMER,R.H. Assistant Director for Systematic Evaluation Program (Pre 791030). 79/12/05. 3pp.
- ---7912240315 Responds to request re design adequacy of BLW N88S utilizing once-through-steam generators (Bellefonte Nuclear Plant).

  Response requested by 791203. Necessary sys mode considered as part of post-TMI-2 effort.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/25. 4pp.
- --7912260346 "Primary Sys Perturbations Induced by Once-Through Steam Generators." Feedwater transient summary encl. \* Office of Nuclear Reactor Regulation. 79/10/25. App.
- 7912280495 Proposes change to 761005 fuel surveillance program for Mark C fuel assembly design. One precharacterized fuel assembly will be in Region I, two in Region 2 & three in Region 3.
  MILLS, L. M. Tennessee Valley Authority. 79/12/19. 2pp.
- C. Utility Environmental Report (ER), amends & correspondence
- 7912190773 Forwards updated distribution list for environ rapt suppls & amends for facility.

  BUNCAN.M. Environmental Projects Branch 2. 79/12/06. Spp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & GL review. Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per fleg Guide 1.101.
  VASSALLO, D. B. Division of Project Management. 79/11/21. App.

- G. Inspection reports, IE Bulletins & correspondence
- 7912200617 Forwards IE Insp Repts 50-439/79-24 & 50-439/79-24 on 791010-12. No noncompliance noted. MURPHY.C. E. Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch. 79/11/05. 2pp.
- --7912200821 IE Insp Repts 50-438/79-24 & 50-439/79-24 on 791010-12. No noncompliance noted. Major areas inspected: installation & quality records for safety-related electrical cables & switchgear.
  CONLON, T. E. Region 2, Atlanta, Office of the Director.
  79/10/31. 3pp.
- 7912060163 Forwards IE Info Notice 79-12A, "Attempted Damage to New Fuel Assemblies." No specific action or response required. O'REILLLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/09. 3pp.
- 7912310270 Forwards IE Insp Repts 50-438/79-25 & 50-439/79-25 on 791016-19 & notice of violation.

  MURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/11/13, 2pp.
- --7912310276 Notice of violation from insp on 791016-19.
  \* Region 2, Atlanta, Office of the Director. 79/11/09. ip.
- --7912310287 IE Insp Rapts 50-438/79-25 & 50-439/79-25 on 791016-19.
  Noncompliance noted:failure to follow pipe storage procedure requirements & use of unauthorized tape on gas purge drums.
  ECONOMOB, N. Region 2, Atlanta, Office of the Director.
  HERDT, A. R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/11/09. Spp.
- 7912070499 Forwards IE Info Notice 79-27. "Steam Generator Tube Ruptures at Two PHR Plants." D'REILLY.J.P. Region 2. Atlanta, Office of the Director. 79/11/16. 14pp.
- 7912100192 Forwards IE Info Notice 79-28, "Overloading of Structural Elaments Due to Pipe Support Loads." No response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 79/11/16. ip.
- 7912110575 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required. O'REILLY,U.P. Region 2, Atlanta, Office of the Director. 79/11/16. 2pp.
- 7912060620 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Byray Pipe Break Detection Equipment on BWRs." No response required.

  G'RELLLY,J.P. Region 2, Atlanta, Office of the Director.
  79/11/26. ip.
- 7912110157 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operats." No response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/26. 1p.
- 7912200003 Supplements 790514 initial response to IE Bulletin 79-03 re weld defects in pipe spools, W/o sncl.
  MILLS.L.M. Tennessee Valley Authority. 79/11/29, ip.
- 7712190478 Forwards IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." No written response required. O'REILLY,J.P. Region 2, Atlanta, Office of the Director. 79/11/30. ip.
- 7912310316 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action required, O'REILLY, J.P. Region 2, Atlanta, Office of the Director, 79/12/06. 6pp.
- 7912200050 Forwards IE Builetin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps," Action required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/12/07. 3pp.
- 7912280426 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required. O'AEILLY, J. P. Region 2, Atlanta, Office of the Director. 79/12/13. 3pp.

- 7912280150 Forwards IE Circular 79-25, "Shock Arrestor Strut Assembly Interference." No written response required. O'REILLYJ.P. Region 2, Atlanta, Office of the Director. 79/12/20. App.
- 8. Reportable occurrences. LERs & related correspondence
- 7912030317 Forwards second interim deficiency rept re water found in rock anchor tendon head protective grease cams.
  MILLER, L. N. Tennessee Valley Authority. 79/11/23. ip.
- --7912050522 Forwards second interim deficiency rept re water found in rock anchor tendon head protective grease cans. No erosion of tendon components detected, Second rept should be submitted by 800321.
  HILLB.L.M. Tennessee Valley Authority. 79/11/23. 1p.
- 79:2280557 Fourth interim deficiency rept re tensile anchor capacities identified lower than design allowables. No further progress on nonconformance reported Next written rept will be submitted by 800303.

  HILLS.L.H. Tennessee Valley Authority. 79/12/17. 1p.
- DOCKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2
- A. Application/construction stage documents & correspondence
- 7912110011 Forwards NRC position on status & applicability to pending OL applications of results of TMI followup actions Outlines addl short-term actions to be taken.

  VASBALLO, D. B. Division of Project Management. 79/09/27. 41pp.
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMB issue for PMRs & BMRs.
  Buccess of program depends on industry response Supports formation of owners groups to provide necessary info.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.
- 7912130521 Forwards updated proprietary electrical, instrumentation & control drawings, Affidavit encl. Drawings withheld (ref 10CFR2, 790).
  MILLS, L. M. Tennesse Valley Authority. 79/11/30. 8pp.
- 7912030071 Responds to NRC 791028 ltr re design adequacy of B&W nuclear steam supply sys utilizing once-through steam gonerators.

  Based on review of overcooling event consequences:concludes continued const justified.CPs should not be changed.

  HILLS.L.M. Tennessee Valley Authority. 79/12/03. 100pp.
- 7912130023 Notification of 800110 meeting w/util to discuss reporting level of util GA & manager & GA review of documents.

  BPRAUL.J.G. Quality Assurance Branch. 79/12/05, 1p.
- 7912260309 Requests info re sensitivity-to-feedwater transients be forwarded to IMI-1 Board. VOLLMER.R.H. Assistant Director for Systematic Evaluation Program (Pre 791030). 79/12/05. Spp.
- --79122&0313 Responds to request re design adequacy of B&W NSSS utilizing ence-through-steam generators (Bellsfonts Nuclear Plant).

  Hesponse requested by 791203. Nacessary sys mode considered as part of post-TNI-2 effort.

  DENTON, H. R. Office, of Nuclear Reactor Regulation. 79/10/25. 4pp.
- --7912260346 "Primary Sys Perturbations Induced by Once-Through Steam Generators." Feedwater transient summary encl. • Office of Nuclear Reactor Regulation. 79/10/25, Spp.
- 7912280495 Proposes change to 761005 fuel surveillance program for Mark C fuel assembly design. One precharacterized fuel assembly will be in Region I, two in Region 2 & three in Region 3.
  MSLLS.L.M. Tennessee Valley Authority. 79/12/19. 2pp.
- C. Utility Environmental Report (ER), amends & correspondence
- 7912190773 Forwards updated distribution list for environ rept suppls & amends for facility.

  DUNCAN, M. Environmental Projects Branch 2. 79/12/06. Spp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review. Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Guide 1.101.
  VASSALLO, D. B. Division of Project Management. 79/11/21. 6pp.

- Q. Inspection reports. IE Bulletins & carrespondence
- 7912200617 Forwards IE Insp Repts 50-438/79-24 & 50-439/79-24 on 791010-12. No noncompliance noted. MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 79/11/05. 2pg.
- ---7912200621 IE Insp Repts 50-438/79-24 & 50-439/79-24 on 791010-12. No noncompliance noted Major areas inspected: installation & quality records for safety-related electrical cables & switchgear.
  CONLON. T.E. Region 2, Atlanta, Office of the Director.
  79/10/31. 3pp.
- 7912060163 Forwards IE Info Notice 79-12A, "Attempted Damage to New Fuel Assemblies." No specific action or response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/09. 3pp.
- 7912310270 Forwards IE Insp Repts 50-438/79-25 & 50-439/79-25 on 791016-19 & notice of violation. MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 79/11/13. 2pp.
- --7912310276 Notice of violation from inep on 791016-19.

  \* Region 2, Atlanta, Office of the Director. 79/11/09. 1p.
- --7912310287 IE Insp Repts 50-438/79-25 & 50-439/79-25 on 791016-19.
  Noncompliance noted: failure to follow pipe storage procedure requirements & use of unauthorized tape on gas purge drums.
  ECONOMOS,N. Region 2. Atlanta. Office of the Director.
  HERDI.A.R. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 79/11/09. 8pp.
- 7912070499 Forwards IE Info Notice 79-27, "Steam Generator Tube Ruptures at Two PMR Plants." O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/16. 14pp.
- 7912100192 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. d'REILLY, J. P. Region 2, Atlanta. Office of the Director. 79/11/16. 1p.
- 7912110575 Forwards IE Info Notice 79-29. "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required. O'REILLY.J.P. Region 2. Atlanta. Office of the Director. 79/11/16. 2pp.
- 7912060620 Forwards IE Circular 79-29, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No response required.

  O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
  79/11/26. ip.
- 7912110157 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required.
  O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
  77/11/26. jp.
- 7912200003 Supplements 790514 initial response to IE Bulletin 79-03 rewell defects in pipe spools. W/o encl.
  MILLS.L.M. Tennessee Valley Authority. 79/11/29. ip.
- 7912190478 Forwards IE Bulletin 79-27, "Lose of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." No written response required.
  O'REILLY.J.P. Region 2. Atlanta, Office of the Director.
  79/11/30. 1p.
- 7912310316 Forwards IE Info Notice 79-30. "Reporting of Defects & Noncompliances: 100FR21." No action required. D'REILLY.J.P. Region 2. Atlanta. Office of the Director. 79/12/06. 6pp.
- 7912200060 Forwards IE Bulletin 79-28, "Possible Malfunction of Names Model EA160 Limit Switches at Elevated Temps." Action required. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 79/12/07. 3pp.
- 7912280426 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required. O'REILLY, J. P. Region 2, Atlante, Office of the Director. 79/12/13. Spp.

- 79:2280150 Eqruards IE Circular 79-25, "Shock Arrestor Strut Assembly Interference." No written response required.
  D'REILLY,U.P. Region 2, Atlanta, Office of the Director.
  79/12/20. 4pp.
- S. Reportable occurrences, LERs & related correspondence
- 7912070149 PNG-II-79-021: on 791031, cooling tower crane collapsed. Caused by 60 mph wind. Damage to tower minor & no impact on const schedule.

  HRIGHT.R.H., CANTRELL, F. S. Region 2. Atlanta. Office of the Director. 79/11/01. ip.
- 7912050517 Forwards second interim deficiency rept re water found in rock anchor tendon head protective grease cans.
  MILLS.L.M. Tennessee Valley Authority. 79/11/23. 1p.
- --79:2050522 Forwards second interim deficiency rept re water found in rock anchor tendon head protective grease cans. No erosion of tendon components detected. Second rept should be submitted by 800321. MILLS, L. M. Tennessee Valley Authority. 79/11/23. 1p.
- 7912280557 Fourth interim deficiency rept re tensile anchor capacities identified lower than design allowables. No further progress on nonconformance reported. Next written rept will be submitted by 800303.

  MILLS.L.M. Tennessee Valley Authority. 79/12/17. ip.
- DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1
- A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATWB issue for PWRs & BWRs. Success of program depends on industry response. Supports formation of owners groups to provide necessary info. DENTON.H.R. Office of Nuclear Reactor Regulation. 79/10/17. Opp.
- F. Security, medical, emorgency & fire protection plans
- 7912040471 Forwards info re upgraded energency glams to plants under const & OL review. Applicants required to make certain amergency arrangements w/state & local organizations & submit emergency plans per Reg Guide 1.101.

  VASSALLO.D.B. Division of Project Management. 79/11/21. 6pp.
- M. Antitrust correspondence
- 7912050098 Consolidated answer in opposition to Cleveland Electric Illuminating Co. Toledo Edison & Dhio Edison petitions for ALAB-560 review Petitioners failed to seek Commission review on issue of monopoly existence. Certificate of Svc encl. LESSY.R.P. Antitrust Division. 79/11/21. 32pp.
- 7912180344 Informs of address change as of 791201. HJELHFELT.O.C. Hjelmfelt.D.C. 79/11/26. 3pp.
- 7912110355 Orders extension until 800115 for Commission to review ALAB-540.
  CHILK, S. J. Office of the Secretary of the Commission. 79/12/07. ip.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912050004 Forwards IE Insp Repts 50-440/79-07 & 50-441/79-07 on 790910-12 & notice of violation. FIDRELLIG. Region 3, Chicago. Reactor Construction & Engineering Support Branch. 79/10/04. 2pp.
- --7912050008 Natice of violation from insp on 790910-12.

  \* Region 3. Chicago, Office of the Director. 79/10/02. ip.
- --7912050011 IE Insp Repts 50-440/79-07 & 50-441/79-07 on 790910-12.
  Noncompliance noted: failure to verify hold points during installation of reactor vessel.
  ERB.C.M. Region 3. Chicago, Office of the Director.
  DANIELSON.D.H. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 79/10/02. 5pp.
- 7912050043 Forwards IE Insp Repts 50-440/79-09 & 50-441/79-09 on 791002-05 No noncompliance noted. FIGRELI.6. Region J. Chicago. Reactor Construction & Engineering Support Branch. 79/10/19. 2pp.

- --7912050052 IE Insp Repts 50-440/79-09 & 50-441/79-09 on 791002-05. No noncompliance noted. Major areas inspected: installation & records for Class IE switchgear. HUOHES.J. Region 3. Chicago, Office of the Director. HAYEB.D.W. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 79/10/18. 4pp.
- 7912040223 Forwards response to IE Bulletins 79-14 & 79-14.Revision 1. Suppl 1 & 2 re safety-related piping sys.Licenses has not completed installation of seismic Category 1 piping sys. Analysis of present activities and. DAVIDSON.D.R. Cleveland Electric Illuminating Co. 79/10/26. App.
- 7912180228 Forwards IE Insp Repts 50~440/79-08 & 50~441/79-08 on 790925-26. No noncompliance nated.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/06.
- ---7912180234 IE Insp Repts 50-440/79-08 & 50-441/79-08 on 790925-26. No noncompliance noted Major areas inspected review of anonymous allegation that two US Testing Co technicians performed work for which they were not qualified. PHILLIP.G.A. NORELUSC.E. Region 3, Chicago, Office of the Director. WILLIAMS.C. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/11/03. 23pp.
- 7912050114 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912100221 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads," No response required.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/16.
- 7712110569 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/15.

  10.
- 7912050361 Forwards IE Bullotin 79-26, "Boron Loss From BWR Control Blades." No response required.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/20.

  1p.
- 7912100424 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No written response required.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/25.
- 7912110244 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required.

  KEPPLER, J. 9. Region 3, Chicago, Office of the Director. 79/11/26.
- 7912110397 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sant by NRC to licensees.

  KEPPLER, J. O. Region 3. Chicago, Office of the Director. 79/11/28.
- 7912060073 Ack receipt of 791108 Itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/79-07 & S0-441/79-07. FIGRELI.9. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/11/30. 1p.
- --7912050084 Responds to NRC 791004 ltr re violations noted in IE Insp Repts 50-440/79-07 & 50-441/79-07. Corrective actions: contracts for installation of NMSB equipment withdrawn from Newport News Industrial Corp. DAVIDSON.D.R. Cleveland Electric Illuminating Co. 79/11/08. 2pp.
- 7912190213 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation."
  No written response required.
  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/30.
  1p.
- 7912140074 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action or response required.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/12/06.

  1p.

- 7912200103 Forwards IE Builetin 79-28. "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. KEPPLER. J. O. Region 3. Chicago, Office of the Director. 79/12/10.
- S. Reportable occurrences. LERs & related correspondence
- 7912210055 PND-III-79-13: on 791011, licensee notified NRC that atty provided news media w/negative info re plant regulatory performance. Info obtained from IE inap rept. KONKLIN.J.E., WILLIAMS, C.C., FIORELLI, G. Region 3, Chicago, Office of the Director. 79/10/11. ip.
- 7912200007 PNO-III-79-015:on 791011.const worker died as result of touthing crame in contact w/high voltage overhead line.No Further IE action anticipated.
  KONKLIN.J.E., WILLIAMS, C.C., FIORELLI.G. Region 3, Chicago, Office of the Director. 79/10/12. 1p.
- 7912180027 PNB-III-79-03: on 791115, site security of creceived telephonic bomb threat from unidentified male. Plant svacuated. Search conducted w/negative results. DONAHUE.J.F., KIND.J.A. Region 3, Chicago, Office of the Director. 79/11/16. 1p.
- 7912050519 Interim deficiency rept re cracks & tears in 4.16 kV switchgear panels. Based on satisfactory evaluation of proposals, insp & repair program will be implemented. Final rept will be submitted by 800415.

  DAVIDSON.D.R. Cleveland Electric Illuminating Co. 79/11/23. 2pp.
- 7912140360 Ack receipt of 791031 interim deficiency rept re Roctbestos Co cable. FIGRELLI.O. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 79/11/27. ip.
- 7912210122 Ack receipt of 791109 final rept re eccentric jackets on Class IE small power & control cable. Review will be completed during future insp.
  FIORELLI.O. Region 3. Chicago, Office of the Director. 79/12/06. ip.
- 7912140364 Forwards final deficiency rept re GA program breakdown. DAVIDSON.D.R. Cleveland Electric Illuminating Co. 79/12/07. 1p.
- --7912140371 Final deficiency rept we breakdown of S&M Constructors Inc OA program regarding control over subcontractors. Deficient parts replaced. Periodic audits & surveillance performed during various stages of fabrication.

  \* Cleveland Electric Illuminating Co. 79/12/07. Spp.
- DOCKET 50-441 PERRY NUCLEAR POWER PLANT, UNIT 2
- A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resulve ATMS issue for PMRs & BMRs.
  Success of program depends on industry response. Supports formation of owners groups to provide necessary info.
  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/10/17. App.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & DL review. Applicants required to make certain emergency arrangements w/state & local promizations & submit amorgancy plans per Rog Quide 1.101.
  VASSALLO.D.B. Division of Project Management. 79/11/21. 6pp.
- M. Antitrust correspondence
- 7912050078 Consolidated answer in opposition to Cleveland Electric Illuminating Co. Toledo Edison & Ohio Edison petitions for ALAB-540 review. Petitioners failed to seek Commission review on issue of monopoly existence. Certificate of Svc encl. LESSY, R. P. Antitrust Division, 79/11/21, 32pp.
- 7712180344 Informs of address change as of 791201. HJELMFELT, D. C. Hjelmfalt, D. C. 79/11/26. Spp.
- 7912110356 Orders extension until 800115 for Commission to review ALAS-540.
  CHIER B. J. Diffice of the Secretary of the Commission. 79/12/07.

- Q. Inspection reports, IE Bulletins & correspondence
- 7912050006 Forwards IE Insp Repts 50-440/79-07 & 50-441/79-07 on 790910-12 & notice of violation.' FIDRELLI.G. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 79/10/04. 2pp.
- --791205000B Notice of violation from insp on 790910-12.

  \* Region 3, Chicago, Office of the Director. 79/10/02. 1p.
- --7912050011 IE Insp Repts 50-440/79-07 & 50-441/79-07 on 790910-12.

  Noncompliance noted: failure to verify hold points during installation of reactor vessel.

  ERB.C.M. Region 3. Chicago. Office of the Director.

  DANIELSON.D.H. Region 3. Chicago. Reactor Construction & Engineering Support Branch. 79/10/02. 5pp.
- 7912030043 Forwards IE Insp Repts 50-440/79-09 & 50-441/79-09 on 791002-05. No noncompliance noted. FIORELLIG. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 79/10/19. 2pp.
- --7912050052 IE Insp Repts 50-440/79-09 & 50-441/79-09 on 791002-05. No noncompliance noted Major areas inspected; installation & records for Class IE switchgear. HUGHES. J. Region 3. Chicago, Office of the Director. HAYER.D. H. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 79/10/18. 4pp.
- 7912040223 Forwards response to IE Dulletins 79-14 & 79-14, Revision 1, Suppl 1 & 2 re safety-related piping sys. Licensee has not completed installation of sensmic Cotegory 1 piping sys. Analysis of present activities encl. DAVIDSON, D. R. Cleveland Electric Illuminating Co. 79/10/26. App.
- 791218022D Forwards IE Insp Repts 50-440/79-08 & 50-441/79-08 on 790925-26. No noncompliance noted.

  KEPPLER J. G. Region 3, Chicago, Office of the Director, 79/11/06.

  2pp.
- --7912180234 IE Insp Repts 50-440/79-08 & 50-441/79-08 on 790925-26. No nancompliance noted Major areas inspected review of anonymous allegation that two US Tosting Co technicians performed work for which they were not qualified. PHILLIP-G.A. NORELIUS-C.E. Region 3. Chicago. Defice of the Director. WILLIAMS.C. Region 3. Chicago. Reactor Construction & Engineering Support Branch. 79/11/05. 23pp.
- 7912050114 Forwards IE Circular 79-22, "Stroke Times for Power Operated Reliof Valves." No response required. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/16. 1p.
- 7912100221 Forwards IE Info Notice 79-29, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. KEPPLER, J. G. Region 3, Chicago, Office of the Director, 79/11/16.
- 7912110569 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. KEPPLER.J.G. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912050361 Forwards IE Bulletin 79-26, "Boron Losa From BWR Control Blades." No response required.

  KEPPLER, J. 9. Region 3, Chicago, Office of the Director. 79/11/20, ip.
- 79:2100424 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on DWRs." No written response required.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/26.

  1p.
- 7912110244 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operato," No response required.
  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/26.
  1p.
- 7912110399 Notifies that NRC intends to routinely forward to appropriate state public will regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sont by NRC to licenses.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/28.

  1p.

- 7912060073 Ack receipt of 791108 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/79-07 & 50-441/79-07. FIDRELLI, G. Region G. Chicago, Reactor Construction & Engineering Support Branch. 79/11/30. ip.
- --7912060084 Responds to NRC 791004 itr re violations noted in IE Insp Repts 50-440/79-07 & 50-441/79-07. Corrective actions: contracts for installation of NMSS equipment withdrawn from Newport News Industrial Corp. DAVIDSON,D.R. Cleveland Electric Illuminating Co. 79/11/09. 2pp.
- 7912190213 Forwards IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation." No written response required.

  KEPPLER J. C. Region 3. Chicago, Office of the Director. 79/11/30.
- 7912140074 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances.10CFR21." No action or response required.

  KEPPLER.J. G. Region G. Chicago. Office of the Director. 79/12/06.
- 7912200103 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required.

  KEPPLER. J. G. Region 3, Chicago, Office of the Director. 79/12/10.

### S. Reportable occurrences, LERs & related correspondence

- 7912210055 PNO-III-79-I3:on 791011.licensee notified NRC that atty provided news media w/negative info re plant regulatory performance.lnfo obtained from IE insp rept. MONKLIN.J.E., WILLIAMB.C., FIGRELLI.G. Region 3, Chicago, Office of the Director. 79/10/11. ip.
- 7912200007 PNO-III-79-015; on 791011, const worker died as result of touching trane in contact w/high voltage overhead line. No further IE action anticipated.

  KONKLINJ.E., WILLIAMS.C.C., FIGRELLI.G. Region 3, Chicago, Office of the Director. 79/10/12. 1p.
- 7932180027 PNS-III-79-03:an 793115, site security ofc received telephonic bomb threat from unidentified male. Plant evacuated. Search conducted w/negative results. DENARUE. J. F., MIND. J. A. Region 3, Chicago, Office of the Director. 79/11/16. 1p.
- 7912050519 Interim deficiency rept re cracks & tears in 4.16 kV switchgeer panels. Based on satisfactory evaluation of proposals, insp & repair program will be implemented. Final rept will be submitted by 800415. DAVIDSDN.D.R. Cleveland Electric Illuminating Co. 79/11/23. 2pp.
- 7912140380 Ack receipt of 791031 interim deficiency rept re Rockbestos Co cable. FIGRELLIG. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 79/11/27. 1p.
- 7912210122 Ack receipt of 791109 final rept re eccentric jackets on Class IE small power & control cable. Review will be completed during future insp. FIGRELLI.C. Region 3. Chicago. Dffice of the Director. 79/12/06.
- 7912140364 Forwards final deficiency rept re GA program breakdown. DAVIDSON.D.R. Cleveland Electric Illuminating Co. 79/12/07. 1p.
- --7912140371 Final deficiency rept re breakdown of B&M Constructors Inc GA program regarding control over subcontractors. Deficient parts replaced Periodic audits & surveillance performed during various stages of fabrication. \* Cleveland Electric Illuminating Co. 79/12/07. 5pp.

### DOCKET 50-443 SEABROOK NUCLEAR STATION, UNIT 1

- A. Application/construction stage documents & correspondence
- 7912140231 Responds to IE Bulletin 79-24, "Frozen Lines." Details freeze protection measures.
  DEVINCENTIS, J. Public Service Co. of New Hampshire. 79/10/25, 2pp.
- 7912070004 Requests distribution of encl memorandum to board notification syc lists.

  VAROA.S.A. Assistant Director for Light Water Reactors. 79/11/08.

- 7912280307 Advises of recently amended NRC regulations implementing existing authority to require onsite ofc space & immediate facility access.FR notice dtd 790816 encl.

  STELLOV Office of Inspection & Enforcement, Office of the Director. 79/11/28. 3pp.
- 7912210320 Advises that current schedule calls for June 1980 submittat of FSAR.
  SHEPHERD, A. M. Public Service Co. of New Hampshire. 79/12/13. ip.

## F. Security, medical, emergency & fire protection plans

7912040471 Forwards info re upgraded emergency plans to plants under const & DL review. Applicants required to make certain comergency arrangements w/state & local organizations & submit emergency plans per Reg Quide 1.101.
VASBALLQ.D.B. Division of Project Management. 79/11/21. App.

### Q. Adjudicatory correspondence

- 7912110043 Forwards comments on NUREG-0511. Draft GEIS reflects conscious & deliberate NRC policy to jeopardize public health & safety & thwart objectives of NEPA.

  KEPFORD, C. Environmental Coalition on Nuclear Power. 79/10/24, 22nm
- 7912040481 Memorandum in support of Seacoust Anti-Pollution League 790502 request for order to show cause re suspension or revocation of facility CPs. Certificate of Svc encl. BURT.L. Massachusetts, State of. 79/11/16. 26pp.
- 7912110477 Memorandum in support of Beacomst Anti-Pollution League 790302 request for order to show cause why CP should not be suspended or revoked Concurs w/NH 790502 position remempency planning concerns. Cartificate of Svc encl. BURT, L. Hassachusetts, State of. 79/11/16. 24pp.
- 79:21:10460 Forwards Pages 22 & 23 of State of MA 79:116 memorandum in support of Seacoast Anti-Pollution League 790502 request for order to show cause. BURT.L. Massachusetts, State of. 79/11/27. 3pp.
- 7912260372 Response in opposition to New England Coalition on Nuclear Pollution 790926 supplemental memo seeking Commission review of ALAB-422 re saismic design. Alleged reasons for review raise factual matters conclusively established by ABLBs.
  REIS.E.J., GRAINEY,M.W. Hearing Branch 3. 79/12/11. 10pp.
- --7912260375 Affidavit evaluating June 1979 Seismological Society of America Bulletin 69, NUREO/CR-0563 re seismicity comparison of three regions of Eastern US & seismological investigations of New England reactors. Bibliography encl. MCMULLEN, R. B. , REITER, L. Geosciences Branch. 79/12/05. 17pp.
- 7912260365 Orants extension until 800125 for Commission to decide whather to review ALAB-422 & ALAB-561.
  CHILM.B. J. Office of the Secretary of the Commission. 79/12/19.

# H. General correspondence

- 7912060367 Requests copies of NRC 790323,0717 & 0925 ltrs to FBC of NI & util responses dtd 790427.0622.0806.08,13,15,20,0906.12. 27,1010 & 16. Requested info needed in support of util request for rate relief. CAMFIELD.R.J. New Hampshire, State of. 79/11/27. 1p.
- O. Inspection reports. IE Bulletins & correspondence
- 7912120313 Responds to IE Bulletin 79-23. No connection exists between transformer power windings & generator neutral.

  DEVINCENTIB, J. Public Service Co. of New Hampshire. 79/10/19. lp.
- 7912050062 Ack receipt of 791004 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-443/79-06 & 50-444/79-06. CARLSON,R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/10/22. 1p.
- ---7912050070 Responds to NRC 790828 ltr re violations noted in IE Insp a Repts 50-443/79-06 & 50-444/79-06. Corrective actions:log-in & badge control program begun in warehouses & Insp Procedura X-9 revised. DEVINCENTIS, J. Public Service Co. of New Hampshire. 79/10/04. Spp.

- ---7912050072 Forwards IE Insp Repts 50-443/79-06 & 50-444/79-06 on 790521-25 & notice of violation. CARLEON,R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/08/28. 2pp.
- ---7912050075 Notice of violation from insp on 790521-25.

  \* Region 1, Philadelphia, Office of the Director. 79/08/29.

  Zpp.
- --7912050078 IE Insp Repts 50-443/79-06 & 50-444/79-06 on 790521-25.
  Noncompliance noted: failure to follow welding & document control procedures & to control access to warehouses.
  MATTIA.J., VARELA.A. Region 1, Philadelphia, Office of the Director. McGAUGHY, R. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/08/29. 12pp.
- 7912050058 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required.
  GRIER, B. H. Region i, Philadelphia, Office of the Director.
  79/11/16. 1p.
- 7912050302 Forwards IE Info Notice 79-27, "Bteam Generator Tube Huptures at Two PHR Plants." No response required. CRIER.B.H. Region i, Philadelphia, Office of the Director. 79/11/16. ip.
- 7912100150 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads," No response required. ORIER, B.H. Region i, Philadelphia, Office of the Director, 79/11/16. 1p.
- 7712110470 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required.
  ORIER, B.H, Region 1, Philadelphia, Office of the Director.
  79/11/19, 1p.
- 7912030327 Forwards IE Bulletin 79-24. "Boron Loss From BWR Control Blades." No response required. ORIEA, B. H. Region i, Philadelphia, Office of the Director. 79/11/20. ip.
- 7912060596 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Boray Pipe Break Detection Equipment on BWRs." No response required.

  ORIER.B.H. Region 1. Philadelphia, Office of the Director.

  79/11/26. ip.
- 7912110083 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required.
  ORIER.B.H. Region 1, Philadelphia, Office of the Director.
  79/11/26. Jp.
- 7912190087 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation."
  No written response required.
  ORIER, B. H. Region i, Philadelphia, Office of the Director.
  79/11/30.
- 7912310248 Forwards IE Info Notice 79-30, "Reporting of Defects & Moncompliances: IOCFR21," No action required.

  GRIER.B.H. Region i, Philadelphia, Office of the Director.
  79/12706. 4pp.
- 7912190766 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model E6180 Limit Switches at Elevated Temps," Written response required. GRIER.B.H. Region 1. Philadelphia, Office of the Director, 79/12/07. 1p.
- 7912280242 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required. ORIER. B.H. Region 1, Philadelphia. Office of the Director. 79/12/13. 1p.
- 8. Reportable occurrences, LERs & related correspondence
- 7912120444 Forwards interim deficiency rept re use of invalid seismic applified response spectra. Final rept will be submitted by 800601.
  DEVINCENTIS. J. Public Service Co. of New Hampshire. 79/12/06. ip.
- --7912120466 Interim deficiency mept me use of invalid seismic amplified response spectra in design of safety-related components.

  Contractor is redesigning containment annular steel frame.

  Contractor 791106 It me deficiency encl.

  Public Service Co. of New Hampshire. 79/12/06. 9pp.

- 7912120486 Forwards final deficiency rept on discrepancy in drawings redesign calculation concrete reinforcement requirements for control & dissel generator bldgs.

  DEVINCENTIS, J. Public Service Co. of New Hampshire. 79/12/06. Ip.
- --79121204B7 Final deficiency mept on discrepancy in drawings re design calculation concrete reinforcement requirements for control & diesel generator bldgs. Reinforcement deficiencies in process of being fully corrected to agree w/calculations. \* Public Bervice Co. of New Hampshire. 79/12/05. 25pp.
- 7912140363 Interim deficiency rept re-potential failure in engineered safety features actuation sys. Problem identified by manufacturer. Mestinghouse Info on problem resolution will be provided by 800530.

  DEVINCENTIS.J. Public Service Co. of New Hampshire. 79/12/06. App.

#### DOCKET 50-444 SEABROOK NUCLEAR STATION, UNIT 2

#### A. Application/construction stage documents & correspondence

- 7912110244 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRs & DMRs.

  Buccess of program depends on industry response. Supports formation of owners groups to provide necessary info.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.
- 7912140231 Responds to IE Bulletin 79-24, "Frozen Lines." Details freeze protection measures.

  DEVINCENTIE.J. Public Service Co. of New Hampshire. 79/10/25. 2pp.
- 7912070004 Requests distribution of encl memorandum to board notification syc lists.

  VAROA.B. A. Assistant Director for Light Water Reactors. 79/11/08.
- 7912280307 Advises of recently amended NRC regulations implementing existing authority to require onsite ofc space & immediate facility access.PR notice dtd 790816 encl.

  STELLOV. Office of Inspection & Enforcement, Office of the Director. 79/11/28, Spp.
- 7912210320 Advises that current schedule calls for June 1980 submittal of FBAR.
  SHEPHERD, A.M. Public Service Co. of New Hampshire. 79/12/13. ip.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Guide 1.01.
  VABBALLO, D. B. Division of Project Management. 79/11/21. App.
- Q. Adjudicatory correspondence
- 7912110043 Forwards comments on NUREO-0511 Draft GEIS reflects conscious & deliberate NRC policy to jeopardize public health & safety & thwart objectives of NEPA.
  KEPFORD, C. Environmental Coalition on Nuclear Power. 79/10/24.
  8200.
- 7912040481 Memorandum in support of Seacoast Anti-Pullution League 790302 request for order to show cause re suspension or revocation of facility CPs Certificate of Svc encl. BURT.L. Massachusetts State of 79/11/16. 26pp.
- 7912110477 Memorendum in support of Seacoast Anti-Pollution League 790502 request for order to show cause why CP should not be suspended or revoked Concurs W/NH 790502 position re emergency planning concerns. Certificate of Svc enci. BURT,L. Massachusetts, State of. 79/11/16, 24pp.
- 7912110460 Forwards Pages 22 & 23 of State of MA 791116 memorandum in support of Seaccast Anti-Pollution League 790502 request for order to show cause. BURTLL. Massachusetts, State of. 79/11/27. 3pp.
- 7912260372 Response in apposition to New England Coalition on Nuclear Pollution 790926 supplemental memo seaking Commission review of ALAB-422 re seismic design Alleged reasons for review raise factual matters conclusively established by ASLBs.
  REIS.E.J. GRAINEY.M.W. Hearing Branch 3. 79/12/11. 10pp.

--7912260375 Affidavit evaluating June 1979 Seismological Society of America Bullutin 69. NUREO/CR-0563 re seismicity comparison of three regions of Eastern US & seismological investigations of New England reactors. Bibliography encl. MCMULLEN, R. B. , REITER, L. Ogosciences Branch. 79/12/05. 17pp.

\*

7912260365 Grants extension until B00125 for Commission to decide whether to review ALAD-422 & ALAD-561.
CHILK.S. J. Office of the Secretary of the Commission. 79/12/19.

#### H. General correspondence

- 7912040367 Requests copies of NRC 790523.0717 & 0925 ltrs to PBC of NH & util responses dtd 790427.0622.0806.08.13.15.20.0906.12.27.1010 & 16. Requested info needed in support of util request for rate relief.
  CAMFIELD.R.J. New Hampshire, State of. 79/11/27. 1p.
- O. Inspection reports. IE Bulletins & correspondence
- 7912120513 Responds to 1E Bulletin 79-23. No connection exists between transformer power windings & generator neutral.
  DEVINCENTIS, J. Public Service Co. of New Hampshire. 79/10/19. 1p.
- 7912050062 Ack receipt of 791004 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-443/79-06 & 50-444/79-06. CARLSON.R.T. Region 1. Philadelphia, Reactor Construction & Engineering Support Branch. 79/10/22. 1p.
- --7912050070 Responds to NRC.790828 ltr re violations noted in IE lnap Repts 50-449/79-06 & 50-444/79-06. Corrective actions: log-in & badge control program begun in warehouses & Insp Procedure X-9 revised. DEVINCENTIS.J. Public Service Co. of New Hampshire. 79/10/04. 5pp.
- --7912050072 Forwards 1E Insp Repts 50-443/79-06 & 50-444/79-06 on 790521-25 & matice of violation. CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/08/28. 2pp.
- --7912050075 Notice of violation from imap on 790521-25.

  \* Region i, Philadelphia, Office of the Director. 79/08/29.
  2pp.
- --7912050078 IE Insp Repts S0-443/79-06 & 50-444/79-06 on 790521-25.
  Noncompitance noted: failure to follow welding & document control procedures & to control access to warehouses.
  MATTIA, J. vARELA.A. Region 1, Philadelphia, Dffice of the Director. MCGAUGHY.R. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/08/29. 12pp.
- 7912050058 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required.
  ORIER, D. H. Region 1, Philadelphia, Office of the Director.
  79/11/16. ip.
- 7912050302 Forwards IE Info Notice 79-27, "Bteam Generator Tube Ruptures at Two PUR Plants." No response required. ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/11/16. 1p.
- 7912100150 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Oue to Pipe Support Loads." No response required. ORIER, B. H. Region 1. Philadelphia. Office of the Director. 79/11/16. 1p.
- 7912110470 Forwards IE Info Notice 79-29. "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. GRIER.B.H. Region 1. Philadelphia. Office of the Director, 79/11/19. ip.
- 7912050327 Forwards IE Bulletin 79-26, "Boron Loss From BHR Control Blades." No response required. ORIER,B.H. Region I. Philadelphia, Office of the Director. 79/11/20. 1p.
- 7912060596 Forwards IE Circular 79-24. "Froper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No response required.

  GRIER.B. H. Region 1. Philadelphia. Diffice of the Director.
  79/11/26. 1p.

- 79121100B3 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operato." No response required. GRIER,B.H. Region 1, Philadelphia, Office of the Director. 79/11/26. 1p.
- 7912190087 Forwards IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation." No written response required. GRIER, D. H. Region i, Philadelphia, Office of the Director. 79/11/30.
- 791231024B Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21," No action required, ORIER,D.H. Region 1, Philadelphia, Office of the Director, 79/12/06. 4pp.
- 7912190766 Forwards IE Dulletin 79-28, "Possible Malfunction of Name Model EA180 Limit Switches at Elevated Temps." Written response required. GRIER, D.H. Region 1, Philadelphia, Défice of the Director. 79/12/07. ip.
- 7912280242 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required. ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/12/13. 1p.
- S. Reportable occurrences, LERs & related correspondence
- 7912120464 Forwards interim deficiency rept re use of invalid satisfic amplified response spectra. Final rept will be submitted by 800601.

  DEVINCENTIE, J. Public Service Co. of New Hampshire. 79/12/04. 1p.
- --7912120466 Interim deficiency rept re use of invalid seismic amplified response spectra in design of safety-related components.

  Contractor is redesigning containment annular steel frame.

  Contractor 791106 ltr re deficiency encl.

  \* Public Service Co. of New Hompshire, 79/12/06. 9pp.
- 7912120486 Forwards final deficiency rept on discrepancy in drawings re design calculation concrete reinforcement requirements for control & dissel generator bldgs.
  DEVINCENTIG.J. Public Service Co. of New Hampshire. 79/12/06. 1p.
- --7912120489 Final deficiency rept on discrepancy in Frawings redesign calculation concrete reinforcement requirements for control & discal generator bldgs. Reinforcement deficiencies in process of being fully corrected to agree w/calculations. \* Public Service Co. of New Hampshire. 79/12/05, 25pp.
- 7912140363 Interim deficiency rept re potential failure in angineers safety features actuation sys. Problem identified by manufacturer. Mestinghouse. Info on problem resolution will be provided by BODS30.

  DEVINCENTIS, J. Public Service Co. of New Hampshire. 79/12/06. 4pg.
- DOCKET 50-449 COMANCHE PEAK STEAM ELECTRIC STA., UNIT 1

  A. Application/construction stage documents & correspondence
- 7912040895 Forwards rept "Omission of Bhear Tie Reinforcing Steel, Approx Elevation 993 to 997,Unit 2 - Reactor Containment Bldg." GARY,R.J. Texas Utilities Generating Co. 79/09/17. lp.
- ---7912060602 "Dmission of Shear Tie Reinforcing Steel, Approx Elevation 993 to 997. Unit 2 Reactor Containment Bldg."
  \* Texas Utilities Generating Co. 79/09/17. 28pp.
- 7912110011 Forwards NRC position on status & applicability to profing OL applications of results of TMI followup actions. Outlines addl short-term actions to be taken.
  VABBALLO, D. B. Division of Project Management. 79/09/27. 41sp.
- 79:21:10264 Discusses NRC plans to use generic analyses to develop serig verification program to resolve ATMS issue for PMRs & BMRs. Success of program depends on industry response. Supports formation of owners groups to provide necessary info. DENTON:H.R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912130177 Ack receipt of copy of 781226 application requesting swent to CPPR-126 & CPPR-127 reflecting additional ownership interests in plants. Class I & III fees required.
  DIGGS,R.M. Office of Administration. 79/12/03.

- 7912190429 Forwards payment re NRC 791203 request for add1 fee for amend to CPs.

  OARY, R. J. Texas Utilities Generating Co. 79/12/10. 1p.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review. Applicants required to make certain smargency arrangements w/state & local organizations & submit emergency plans per Reg Quide 1.101.
  VASSALLO.D.B. Division of Project Management. 79/11/21. 6pp.

#### G. Adjudicatory correspondence

- 7912050203 Request to add Contention IX stating that applicants have not determined full effect of radioactive releases on public. Contention based on J Beyea & F Von Hippel rept. Certificate of Bvc encl. FOWELR. L. Citizene for Fair Utility Regulation. 79/10/30. 3pp.
- 7912170088 Response in apposition to Citizens for Fair Util Regulation 791030 addl contention re effect of radioactive releases beyond exclusion boundary. Contention untimely & challenges NRC regulations. H/Certificate of Svc. REYNOLDS, N.S., LIBERMAN, D. Texas Utilities Generating Co. REYNOLDS, N.S., Douglass & Barham. 79/11/15. 7pp.
- 7912130030 Response to intervenor Citizens for Fair Util Regulation 791031 request to add contention, Ruling should be deferred until stipulations on all contentions filed. Certificate of Svc sncl.
  CHANDLER.L.J. Hearing Branch 1. 79/11/20. 3pp.

## H. General correspondence

7912200632 Responds to 791030 request for info. Deneral practice is not to add intervenors to distribution list, but exception made in this case. Insp repts dealing w/intervenor allegations encl. W/o encl.
CHANDLER, L. J. Hearing Branch 1. 79/12/14. 2pp.

## 1. Financial information

- 7912180412 Forwards Annual Financial Repts.1978 for TX Utils Co.TX Electric Bvc Co & TX Power & Light Co.W/accountants' opinion verifying accuracy of TX Utils Generating Co & affiliates' financial statements.

  GARY,R.J. Texas Utilities Generating Co. 79/12/04. 9pp.
- --7912160417 Annual Financial Rept 1978.

  \* Texas Utilities Generating Co. 78/12/31. 30pp.
- --7912180421 Annual Financial Rept 1978.

  \* Texas Electric Service Co. 78/12/31. 30pp.
- --7912880425 Annual Financial Rept 1978.

  \*\* Texas Power & Light Co. 78/12/31. 30pp.
- M. Utility Final Safety Analysis Report (FSAR) & amends
- 7912140264 Forwards Amend 8 of FBAR. GARY, R. J. Texas Utilities Gamerating Co. 79/11/30, 2pp.
- --7912140271 Amend 8 to FSAR for Commanche Peak Steam Electric Station.
  \*\* Terms Utilities Commanting Co. 79/11/30. 600pp.
- 7912190548 Forwards affidavit of svc of FBAR Amend 8. BCHHIDT.H.C. Texas Utilities Generating Co. 79/12/12. 3pp.

### H. Antitrust correspondence

- 7911300021 Identifies documents not produced in Southwastern Electric Power Co document production. Documents necessary for review. Production date will be set at Hartley deposition. Certificate of Styc encl. GREEN.D.Q. Lowerstein.Newman.Reis.Axelrad & Toll. 79/11/01. Spp.
- 7912060247 Discovery rept for Oct 1979. Produced add1 documents to DDJ following RL Hancock, HL Peterson & E Rummel 791009 & 10 depositions. Did not initiate discovery requests. Certificate of Byc entl.

  BALDUOH, R. C. Austin, TX. 79/11/05. 4pp.

 $\lim_{n\to\infty} \frac{1}{n} = \lim_{n\to\infty} \frac{1}{n} = \frac{1}{n} = \frac{1}{n}$ 

- 7912190227 Forwards affidavits of RE Roundtree & LR Gawlik,general manager & associate general manager of Public Utils Board. Brownsville, TX. JABLON,R.A. Spiegel & McDiarmid. 79/11/07. 1p.
- --7912190265 Affidavit by general manager of Public Utils Board of City of Drownsville. Ack that 790502 responses to Houston Lighting & Power first set of interrogatories & 790626 supplemental responses to same discovery have been reviewed.

  ROUNDTREE, R. E. Texas. State of. 79/09/14. 2pp.
- --7912190298 Affidavit by associate general manager of Public Utils Board, Brownsville, TX. Ack that 790502 responses to Houston Lighting & Power first set of interrogatories & 790626 supplemental responses to same discovery have been received. GAHLIK, L. R. Texas, State of. 79/09/14. 2pp.
- --7912190319 Corrected & supplemental answers by Public Utils Board of City of Brownsville.TX in response to Houston Lighting & Power first set of interrogatories & first request for production of documents.Contains info re sale of power. \* Texas, State of. 79/11/07. App.
- 7912190241 Confirms 791106 conversation re intentions not to call J Bmith Cajun Cooperative as witness at hearing. Deposition of J Smith will not be taken Reserves right to depose J Smith at future date.

  BALDWIN J. M. Baker & Botts. 79/11/07. Spp.
- 7911300277 Discovery rept for Sept & Oct 1979. Participated in FS Buchanan, JD Nicholas & G Taylor depositions. Did not initiate discovery requests. Certificate of Svr encl. BURCHETTE, W. H. Texas-Louisiana Electric Cooperative, Inc. 79/11/08.
- 7912140202 Advises that during Oct 1979, South TX Electric Cooperative & Medina Electric Cooperative neither Initiated nor received any discovery requests Certificate of Svc encl.

  JOHN, D.F. Akin, Gump, Hauer & Feld. 79/11/08. 4pp.
- 7912050092 Petition for directed certification & review of ASLB 791005 order denying motions for summary decision. Urgos callateral estoppel of Central & South West Corp re issues previously decided in district court trial. Certificate of Svc encl. BARNETT, E. W., BDUKNIGHT, J. A. Houston Lighting & Power Co. BARNETT, E. W. Baker & Botts. 79/11/09. 22pp.
- 7912030683 Third set of interrogatories & request for production of documents directed to TX Utils Generating Co.et al. Addresses purchase & sale of off-peak interruptible energy & transfer & exchange of electric energy. Certificate of Svc enci. STAHL.D. Central Power & Light Co. STAHL.D. Isham, Lincoln & Beals. 79/11/09. Opp.
- 7912040009 Ack receipt of 791107 ltr advising of Houston Lighting & Power Assertion of work product privilege re Gerber scripts.

  NRC will file motion to compel discovery.

  LEBSY.R.P. Antitrust Division. 79/11/09. lp.
- 7912100300 First set of interrugatories & request for production of documents, directed to City Public Svc Board of San Antonio.
  Addresses coal-fired oconomy energy purchase & sale & electric energy transfer & exchange. W/Certificate of Svc.
  BTAHL.D. Central Power & Light Co. 79/11/09. 7pp.
- 7912100307 Discovery rept for Oct 1979. Took deposition of HL Peterson, EC Rummel, RL Hancock, CT Herring & R Heyler & TL Hatcher & M Tenner in conjunction w/NRC. Participated in Houston Lighting & Power & TX Utils joint depositions. W/Certificate of Svc. CYPHERT, B. B., PARMETER, F. H., DOPSOVIC, D. A. Justice, Dept. of, 79/11/09. 7pp.
- 7912190140 Notifies that J Gambrell of Cajun Electric Power Cooperative has been designated potential witness in DDJ proceedings. Requests notification of Gambrells deposition rescheduling. LUQUE, N. Justice, Dept. of. 79/11/09. ip.
- 7912110270 Advises of postponement of H Woodson deposition until later date, due to Houston Lighting & Power failure to make Woodson working papers available for insp.
  BLUME, M.B. Antitrust Division. 79/11/19. 1p.
- 7912130094 Notice of appearance of AP Hodgdon on behalf of NRC. Certificate of Svc encl. HODGDON, A. P. Antitrust Division. 79/11/20, 4pp.

- 7912130057 Request for expansion of ASLB 790323 protective order to include documents produced by Central & South West Corp & Central & South West Sycs.Inc.to include confidential documents to amend order to bind TX Util companies.

  STAHL.D. Central & Southwest Corp. STAHL.D. Central & Southwest Corp. STAHL.D. 79/11/21. 7pp
- 7912130483 Natifies of AE Autry 791211 deposition in Corpus Christi,TX, MS Borchelt 791112 deposition in Abilene,TX,RH Hardy 791213 deposition in Abilene,TX & 88 Philips 791217 deposition in Dallas,TX,Certificate of Svc encl. MCDIARMID.R.C. Brownsville,TX. MCDIARMID.R.C. Spiegel & McDiarmid, 79/11/26. 7pp.
- 7912130236 Third set of interrogatories & requests for production of documents directed to Houston Lighting & Power & TX Utils Generating Co. Includes questions on power flow between utils. Supporting documentation & Certificate of Suc encl. LESSY, R. P., CHANANIA, F. D., BLUME, M. B. Antitrust Division. 79/11/26. 23pp.
- 7912130328 Notice of appearance of S Welling on behalf of Central & South Mast Corp. Central Power & Light Co. PSC of DK.
  Southwestern Electric Power Co & West TX Utils Co.
  WELLING S. Isham, Lincoln & Beale. 79/11/26. 6pp.
- 7912120043 Third supplemental response to second set of interrogatories & requests for production of documents from applicant.

  Certificate of Syc encl.

  CYPHERT, S. B., PARMENTER, F. H. Justice, Dept. of. 79/11/27. 9pp.
- 7912130337 Notice of TL Austin 791217 deposition in Dollas, TX. CARNEY, J. A. Central & Southwest Corp. CARNEY, J. A. Central Power & Light Co. CARNEY, J. A. Public Service Co. of Oklahoma. 79/11/27. ip.
- --7912130361 Notice of BB Hulsey 791218 deposition in Dallas.TX.

  CARNEY.J.A. Central & Southwest Corp. CARNEY.J.A. Central Power & Light Co. CARNEY.J.A. Public Service Co. of Otlahoma.

  79/11/27. 1p.
- --7912130366 Notice of PG Brittain 791218 deposition in Dallas.TX. CARNEY.J.A. Central & Southwest Corp. CARNEY.J.A. Central Power & Light Co. CARNEY.J.A. Public Service Co. of Oklahoma. 79711/27. 1p.
- ---7912130378 Notice of MD Spence 791219 deposition in Dallas,TX.
  Cantificate of Svc encl.
  CARNEY,J.A. Central & Southwest Corp. CARNEY,J.A. Central Power
  & Light Co. CARNEY,J.A. Public Service Co. of Oklahoma.
  79/11/27. 4pp.
- 7912140184 Notifies that documents discussed in 791107 ltr will be available at law firms for NRC insp.Certificate of Svc encl. FLYNN.P. G. Lowenstein.Neuman,Reis,Azelrad & Toll. 79/11/27. App.
- 791217006B Request for issuance of subpoenas & for mod of ASLB 790724 order. Urder should be modified to relfect outstanding discovery matters & briefing schedule. Certificate of Svc & list of deponents enci.

  CYPHERT, S. B., PARMENTER, F. H. Justice, Dept. of, 79/11/29, 15pp.
- 7912120249 Motion to compel DOJ & NRC responses to Houston Lighting & Power first set of interrogatories & requests for production of documents DOJ 791010 responses & NRC 781201 answers were incomplete. W/Certificate of Svc.
  FLYNN.P. 0. Houston Lighting & Power Co. 79/11/30. 32pp.
- 7912170138 Notifies that DDJ does not intend to call JL Johns as witness. LUQUE.N. Justice.Dept.of. 79/12/03. ip.
- 7912180202 Subpoenas EB Barnes to appear in Houston TX on 800205. MILLER, M. E. Atomic Safety and Licensing Board Panel. 79712/03. ip.
- --7912180209 Subpoenas F Taylor to appear in Houston, TX on 800206. MILLER, M.E. Atomic Safety and Licensing Board Panel. 79/12/03.
- ---7912180231 Subpoonss & Knowles to appear in Houston, TX on B00208. MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
- --7912180240 Subpoenas CH Oprea to appear in Houston.TX on 800130. MILLER.M.E. Atomic Safety and Licensing Board Panel. 79/12/03. 1p.

- ---7912180252 Subpoenas AM Smith to appear in Beaumont, TX on 800122.
  MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
- ---7912180262 Subposenas A Sprawls to appear in Beaumont, TX on 800124.
  MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
- --7912180272 Subpoenas W Atkins to appear in Beaumont, TX on 800122. MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/03. 1p.
- --7912180281 Subpoenas RM McCuistion to appear in Houston TX on 800129. MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/03. lp.
- --7912180289 Subpoenas T Standish to appear in Houston TX on 800117. MILLER M.E. Atomic Safety and Licensing Board Panel. 79/12/03.
- --7912180297 Subpoenas J Organizade to appear in Houston, TX on 800116. HILLER, M. E. Atomic Safety and Licensing Board Panel, 79/12/03.
- --7912180306 Subposens N Les to appear in Deaumont.TX on 800125. MILLER.M.E. Atomic Safety and Licensing Board Panel. 79/12/03. 1p.
- --7912180311 Bubpoenas MW Milberg to appear in Houstom, TX on 800207. MILLER, M. E. Atomic Bafety and Licensing Board Panel. 79/12/03.
- --7912180320 Subposmas TR Locke to appear in Wichita Falls, TX on 800103. MILLER, M. E. Atomic Bafety and Licensing Board Panel. 79/12/03. 1p.
- --7912180329 Subpoenas EA Turner to appear in Houston, TX on 800131.
  MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
- ~~7912180340 Subpoenas RJ Earhart to appear in Houston, TX on 800115.
  MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
- --7912180349 Subpoenas JE Monahan to appear in Haco,TX on 800104. HILLER,M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
- --7912180360 Subpoenas HL Manning to appear in Dallas, TX on 800109, MILLER, M. E. Atomic Sefety and Licensing Board Panel. 79/12/03. ip.
- --7912180372 Subpoons OC De La Gasa to appear in Dallas.TX on 800109. HILLER.M. E. Atomic Safety and Licensing Board Panel. 79/12/03. ip.
- --7912180381 Subposens S Board to appear in Dallas.TX on B00108. MILLER.M.E. Atomic Safety and Licensing Board Panel. 79/12/03. 1p.
- ---7912180375 Subpoenas EL Watson to appear in Dalles.TX on 800110. MILLER.M.E. Atomic Safety and Licensing Board Panel. 79/12/03.
- --7912180404 Subpoenas JE Bondurant to appear in Beaumont, TX on 800123.
  MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
- ---7912180414 Subposes JS Farrington to appear in Dallas,TX on 790111. MILLER,M.E. Atomic Safety and Licensing Board Pans). 79/12/03. ip.
- --7912180423 Subpoenas R Corder to appear in Dellas,TX on B00109. MILLER,M.E. Atomic Safety and Licensing Board Panel. 79/12/03.
- 7912110459 Response by Public Utils Board of City of Brownsvills,TX in support of DOJ motion for mod of ASLB 790724 order requesting addl discovery period. Extension will allow thorough preparation for hearing. Centificate of Svc encl. PDIRIER.M.R. Taxas. State of. 79/12/05. App.
- 7912190110 Requests util provide documents subposmed & produced at AE Naylor 791011 deposition.
  BLUME,M.B. Antitrust Division. 79/12/05. ip.

- 7912190138 Monthly status rept for Nov 1979. Parties arrived at terms of protective order. Four scheduled depositions delayed. Draft of order encl. PMRIER. M.R. Spiegel & McDiarmid. 79/12/05. Spp.
- 7912270084 Status rept for Nov 1979. South TX Electric Cooperative, Inc & Redina Electric Cooperative Inc neither initiated nor received discovery requests.

  JOHN, D. F. South Texas Electric Cooperative, Inc. JOHN, D. F. Matropolitan Edison Co. JOHN, D. F. Akin, Oump, Hauer & Feld. 797/2708. 4pp.
- 7912280539 Discovery rept for Nov 1979. No discovery requests initiated or received. Certificate of Svc enci.
  BALDWH.R.C. Austin, TX. 79/12/06. Spp.
- 7912260297 Response in support of DDJ motion for mod of ASLB 790724 order by extending discovery & hearing schedule. Delay needed to assimilate evidence & to narrow issues. Certificate of Beels. 79/12/07. 10pp.
- 79122&03&O Memorandum in support of DDJ motion requesting mod of ASLB 750724 order. Proposed add1 time for completion of discovery, continuation of depositions & final prehearing conference needed to perform studies. Certificate of Svc encl.
  RITTS.F. H., BURCHETTE. W. H. Texas-Louisiana Electric Cooperative, Inc. RITTS.F. H., Northcutt Ely. 79/12/07. 6pp.
- 7912270123 Discovery rept for Nov 1979. Fifteen depositions taken. Third supplemental response to util second set of interrogatories filed. DOJ filed 791130 request for mod of 790724 ASLB order. CYPHERT, S.B. Justice, Dept. of. 79/12/07. 3pp.
- 7912270104 Discovery status rept for Nov 1979 for Central & Bouthwest Corp. Thirteen depositions taken. CARNEY, J. A. Isham, Lincoln & Beale. 79/12/10. 5pp.
- 7912260357 Response to DOJ 791130 motion for mod of ABLB 790724 order by extending hearing schedule & for ancillary relief. If modified single discovery termination date should be adopted. Cartificate of Svc encl. SLUM.R.L. Houston Lighting & Power Co. BLUM.R.L. Baker & Botts. 79/12/11. 9pp.
- 7912270103 Hod of 790323 protective order expanding categories of documents considered confidential & expanding protected area to include documents produced by Central & South Hest Corp & Central & South Hest Corp & Central & South Hest Bycs, Inc.
  HILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/11.
- 7912280670 Notifies of correct svc list for Central & Bouth West Corp. 8TAHL.D.M. Isham, Lincoln & Beale. 79/12/11. ip.
- 7912280627 Supports util 791005 request for directed certification of ASLB 791005 order re-motions based upon decision of US District Court.Order should be reviewed due to holding that res judicate inapplicable to antitrust proceedings.

  KMOTTS, J. B. Texas Utilities Generating Co. KNOTTS, J. B., AREARN, C. D. Debayoise & Liberman. 79/12/12. 37pp.
- 7912280629 Notice of appearance in proceeding Certificate of 8vc encl.
  AMEARN, C. D. Texas Utilities Generating Co. AMEARN, C. D. Dallas
  Power & Light Co. AMEARN, C. D. Texas Electric Service Co. 79/12/12.
- 7912260081 Brief in opposition to applicant 791109 request that ASLAB certify ASLB 791005 order denying applicant motion for superary disposition. No irreparable harm injury to public interest or unusual delay present to justify certification. CHANANIA.F.D., HODODON,A. Antitrust Division. 79/12/14. Sipp.
- --7912260088 Spacial prehearing conference order directing parties to commence discovery & trial preparation immediately & to complete discovery by 790108. Centificate of Svc encl.
  MILLER.H. E. Atomic Safety and Licensing Board Panel. 78/07/13.
- 7912270137 Order extending time to 800229 for completin of discovery, to 800328 for completion of expert discovery, to 800428 for filing witness lists Schedules prehearing conference for 800305 & evidentiary hearing for 800514, MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/14.

- 7912310137 Motion for extension until 800201 to file supplemental response to Houston Lighting & Power first set of interrogatories. Involvement in depositions requires allocation of add time. W/Certificate of Svc. CVPHERT, S. B. , PARMENTER, F. H. , LUQUE, N. Justice, Dept. of. 79/12. Justice Dent of 79/12/14
- 7912310189 Opposition to util 791109 request for directed certification & review of ASLB order. If certification directed collateral estoppel effect should not be given to fact issues delineated by util in another case.

  POIRIER.M.R. Brownsville, TX. POIRIER, M.R. Spiegel & McDiermid. 79/12/14. 18pp.
- 7912260044 Answer concurring w/DDJ 791130 motion for mod of ASLB 790724 order by extending current hearing & discovery schedule. Facility will be ready for fuel-loading between Aug & Nov 1981. Certificate of Svc encl. LESSY, R. P. , CHANANIA, F. D. Antitrust Division. 79/12/17. 5pp.
- 7912260361 Opposition to util 791130 request to compel further discovery. Util has not requested further discovery from NRC. NRC willing to work w/util to arrive at mutually agreeable discovery schedule.Certificate of Evr encl. LEBSY, R. P. , CHANANIA, F. D. Antitrust Division. 79/12/17. App.
- 7912280649 Forwards documents from files of A Gerber per request.W/o encl.Certificate of Svc encl. FLYNN,P.G. Lowenstein,Newman.Reis.Axelrad & Toll. 79/12/17. 5pp.
- 7912310001 Supplementary response to First set of interrogatories.
  Discusses areas where util & Public Util Board of
  Brownsville, TX compote. Affidavit of JW Hilson, supporting
  documentation & Certificate of Svc encl.
  WILSDN.J.W. Brownsville, TX. 79/12/19. 42pp.
- 7912310161 Opposition to applicant 791218 motion for protective order. Order filed inadvertently & conflicts w/previously agreed to terms. Intervenor willing to consider modifying agreement. POIRTER.M.R. Brownsville.TX. POIRTER.M.R. Spiegel & McDiarmid. 79/12/19. 4pp.
- 0. Inspection reports, IE Bulletins & correspondence
- 7912140240 Responds to IE Bulletin 79-14 re seismic analysis for safety-related piping sys. Requests waiver on 120-day reporting requirements due to ongoing const. OARY.R.J. Texas Utilities Generating Co. 79/10/25. lp.
- 7912100245 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required.
  SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/11/16.
- 7912110537 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. BEYFRIT.K.V. Region 4, Dallas, Office of the Director. 79/11/16.
- 7912110289 Forwards IE Circular 79-23. "Motor Starters & Contactors Failed to Operate." No response required. SEVFRIT.K.V. Region 4, Dallas. Office of the Director. 79/11/26.
- 7912110491 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sent by NRC to licensees.

  BEYFRIT.K.V. Region 4, Dallas, Office of the Director. 79/11/26.
- 7912190056 Forwards IE Circular 79-24. "Proper Installation & Calibr of Core Spray Pipe Break Datection Equipment on DWRs." No written response required.

  SEYFRIT.K.V. Region 4. Dallaw. Office of the Director. 79/11/26.
- 7912190193 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." No written response required.

  SEYFRIT.K.V. Region 4, Dallas, Office of the Director. 79/11/30.
- 7912310267 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, IOCFR21." No action required.

  SEYFRIT, K. V. Region 4. Dallas, Office of the Director. 79/12/06.

- 7912200222 Forwards IE Bulletin 79-20. "Possible Malfunction of Namco Model EAISO Limit Switches at Elevated Temps." Action required.
  SEYFRIY.K.V. Region 4. Dallas. Office of the Director. 79/12/07. ip.
- 7912280592 Forwards 1E Info Notice 79-31, "Use of Incorrect Amplified Response Sportra." No written response required. SEYFRIT.K.V. Region 4, Dallas, Office of the Director. 79/12/13.
- DOCKET 50-446 COMANCHE PEAK STEAM ELECTRIC STA., UNIT 2

  A. Application/construction stage documents & correspondence
- 7912060593 Forwards rept "Caission of Shear Tie Reinforcing Steel. Approx Elevation 993 to 997,Unit 2 - Reactor Containment Bldg." ORRY, R. J. Texas Utilities Generating Co. 79/09/17. 1p.
- ---7912060602 "Omission of Shear Tie Reinforcing Stee), Approx Elevation 993 to 997, Unit 2 Reactor Containment Bldg."

  \* Texas Utilities Generating Co. 79/09/17. 28pp.
- 7912030040 Forwards supplemental rept re inadvertent omission of shoar tie reinforcing steel from 32nd lift of exterior wall of reactor containment bldg.

  GARY, R. J. Texas Utilities Generating Co. 79/09/20. 25pp.
- 79121:100:11 Forwards NRC position on status & applicability to pending OL applications of results of TMI followup actions. Outlines addl short-term actions to be taken.
  VASSALED, D. B. Division of Project Management. 79/09/27. 41pp.
- 7912110244 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATWS issue for PWRs & BWRs.
  Success of program depends on industry response Supports formation of owners groups to provide necessary info.
  DENTON.R.R. Dffice of Nuclear Reactor Regulation. 79/10/17. 3pp.
- 7912130177 Ack receipt of copy of 781226 application requesting amend to CPPR-126 & CPPR-127 reflecting addl ownership interests in plants Class I & III fees required. D1909,R.M. Dffice of Administration. 79/12/03. lp.
- 79(2190429 Forwards payment re NRC 791203 request for add1 fee for amend to CPs.
  GARY, R. J. Texas Utilities Generating Co. 79/12/10. 1p.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review. Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Guide 1.101.
  VASSALLO, D. B. Division of Project Management. 79/11/21. 6pp.

## G. Adjudicatory correspondence

- 7912050203 Request to add Contention IX stating that applicants have not determined full effect of radioactive releases on public.Contention based on J Beyea & F Von Hippel rept. Certificate of Svc encl.
  FOUKE.R.L. Citizens for Fair Utility Regulation. 79/10/30. 3pp.
- 7912170088 Response in opposition to Citizens for Fair Util Regulation 791030 add1 contention re effect of radicactive releases beyond exclusion boundary. Contention untimely & challenges NRC regulations. M/Certificate of Svc.
  REYNOLDS.N.S., LIBERMAN.D. Texas Utilities Generating Co.
  REYNOLDS.N.S. Douglass & Barham. 79/11/15. 7pp.
- 7912130030 Response to intervenor Citizens for Fair Util Regulation 791031 request to add contention. Ruling should be deferred until stigulations on all contentions filed. Certificate of Svc encl.
  CHANDLER, L. J. Hearing Branch 1. 79/11/20. 3pp.

# H. General correspondence

7912200632 Responds to 791030 request for info.General practice is not to add intervenors to distribution list-but exception made in this case. Insp repts dealing w/intervenor allegations encl. W/o encl.

CHANDLER.L.J. Hearing Branch 1. 79/12/14. 2pp.

- I. Financial information
- 7912180412 Forwards Annual Financial Repts.1978 for TX Utils Co.TX Electric Svc Co & TX Power & Light Co.W/accountants' opinion verifying accuracy of TX Utils Generating Co & affiliates' financial statements.

  GARY.R.J. Texas Utilities Generating Co. 79/12/04. 9pp.
- --7912180417 Annual Financial Rept 1978. \* Texas Utilities Generating Co. 78/12/31. 30pp.
- --7912180421 Annual Financial Rept 1978.

  \* Texas Electric Service Co. 78/12/31. 30pp.
- --7912180425 Annual Financial Rept 1978. \* Texas Power & Light Co. 78/12/31. 30pp.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 7912140264 Forwards Amend 8 of FSAR.

  GARY, R. J. Texas Utilities Generating Co. 79/11/30. Ppp.
- ---7912140271 Amend 8 to FSAR for Communities Peak Steam Electric Station.
- 7912190548 Forwards affidavit of svc of FBAR Amend B. SCHMIDT, H. C. Texas Utilities Generating Co. 79/12/12. 3pp.
- M. Antitrust correspondence
- 7912060247 Discovery rept for Oct 1979 Produced add1 documents to RBJ following RL Hancock.HL Peterson & E Rummal 791009 & 10 depositions.Did not initiate discovery requests.Certificate of Svc encl.

  BALDUGH.R.C. Austin. TX. 79/11/05. 4pp.
- 7912190227 Forwards affidavits of RE Roundtree & LR Gawlik, general manager & associate general manager of Public Utils Board, Brownsville, TX.
  JABLON, R. A. Spiegel & McDiarmid. 79/11/07. ip.
- --7912190265 Affidavit by general manager of Public Utils Board of City of Brownsville Ack that 790502 responses to Houston Lighting & Power first set of interrogatories & 790626 supplemental responses to same discovery have been reviewed.

  ROUNDTREE,R. E. Texas, State of, 79/09/14, 2pp.
- --7912190298 Affidavit by associate general manager of Public Utils Board, Brownsville, TX. Ack that 770302 responses to Houston Lighting & Power first set of interrogatories & 790626 supplemental responses to same discovery have been received. GAMLIK, L. R. Texas, State of. 79/09/14. 2pp.
- --7912190319 Corrected & supplemental answers by Public Utils Board of City of Brownsville.TX in response to Houston Lighting & Power first set of interrogatories & first request for production of documents. Contains info
- 7912190241 Confirms 791106 conversation re intentions not to call J Bmith, Cajun Cooperative, as witness at hearing. Deposition of J Smith will not be taken. Reserves right to depose J Smith at future data.

  BALDWIN.J.M. Baker & Botts. 79/11/07. 5pp.
- 7912140202 Advises that during Oct 1979, South TX Electric Cooperative & Medina Electric Cooperative neither initiated nor received any discovery requests. Certificate of Svc encl.

  JOHN, D. F. Akin, Gump, Hauer & Feld. 79/11/08. 4pp.
- 7912050092 Petition for directed certification & review of ASLD 791005 order denying motions for summary decision. Urges collateral estoppel of Central & South West Corp re issues previously decided in district court trial Certificate of Svc encl. BARNETT, E. M., BOURNICHT, J. A. Houston Lighting & Power Co. BARNETT, E. W. Baker & Botts. 79/11/09. 22pp.
- 7912050683 Third set of interrogatories & request for production of documents directed to TX Utils Generating Co.et al. Addresses purchase & sale of off-peak interruptible energy & transfer & exchange of electric energy. Certificate of Svc ent. STAHL.D. Central Power & Light Co. STAHL.D. Isham, Lincoln & Beale. 79/11/09. Spp.

- 79:2060009 Ack receipt of 79:107 ltr advising of Houston Lighting & Pawer assertion of work product privilege re Gerber scripts.
  NRC will file motion to compel discovery.
  LEGSY,R.P. Antitrust Division. 79/11/09. 1p.
- 7912100300 First set of interrogatories & request for production of documents directed to City Public Svc Board of San Antonio. Addresses coal-fired economy energy purchase & sale & siectric spergy transfer & eschange. W/Certificate of Svc. STAHL, D. Central Power & Light Co. 79/11/09. 7pp.
- 7912100307 Discovery rept for Oct 1979. Took deposition of HL Peterson, EC Rummel, RL Hancock, CT Herring & R Heyler & TL Hatcher & M Tanner in conjunction w/NRC. Participated in Houston Lighting & Power & TX Utils joint depositions. W/Certificate of Svc. CYPHERT. B.B., PARAMETER, F. H., DOPSOVIC, D. A. Justice, Dept. of. 79/11/09. 7pp.
- 7912190140 Notifigs that J Gambrell of Cajun Electric Power Cooperative has been designated potential witness in DOJ proceedings. Requests notification of Gambrells deposition rescheduling. LUGUE, N. Justice: Dept. of. 79/11/09. 1p.
- 7912110270 Advises of postponement of H Woodson deposition until later fate, due to Houston Lighting & Power failure to make Woodson working papers available for insp. BLUHE, M. B. Antitrust Division. 79/11/19. 1p.
- 7912130094 Notice of appearance of AP Hodgdon on behalf of NRC. Certificate of Svc encl. HODDON, A. P. Antitrust Division. 79/11/20. 4pp.
- 7912130057 Request for expansion of ASLB 790323 protective order to include documents produced by Central & Bouth West Corp & Central & Bouth West Bycs.inc. to include confidential documents to amend order to bind TX Util companies.

  STAHL.D. Central & Bouthwest Corp. STAHL.D. Central & Southwest Barvices. Inc. STAHL.D. Central Power & Light Co. 79/11/21. 7pp.
- 7912130483 Notifies of AE Autry 791211 deposition in Corpus Christi.TX. MS Borchelt 791112 deposition in Ablene.TX.RW Hardy 791213 deposition in Abilene.TX.RW Hardy 791213 deposition in Balles.TX. Certificate of Svc encl. MCDIARMID.R.C. Brownsville.TX. MCDIARMID.R.C. Spiegel & McDiarmid. 79/11/28. 7pp.
- 7912130236 Third set of interrogatories & requests for production of documents directed to Houston Lighting & Power & TX Utils Ownersting Co. Includes questions on power flow between utils. Supporting documentation & Certificate of Svc encl. LEBBY, R. P., CHANANIA, F. D., BLUME, M. B. Antitrust Division. 79/11/26. 23pp.
- 7912130328 Notice of appearance of 8 Welling on behalf of Central & South West Corp. Central Power & Light Co.PSC of DK. Southwestern Electric Power Co & West TX Utils Co. WELLING. B. Isham, Lincoln & Beale. 79/11/26. 4pp.
- 79(2)20043 Third supplemental response to second set of interrogatories & requests for production of documents from applicant. Certificate of Svc enci. Cyphent, 8, 8, PARMENTER, F. H. Justice, Dept. of. 79/11/27. 9pp.
- 7912180337 Notice of TL Austin 791217 deposition in Dallas.TX.
  CARNEY, J. A. Central & Bouthwest Corp. CARNEY, J. A. Central Power & Light Go. CARNEY, J. A. Public Bervice Co. of Oklahoma. 79/11/27.
  10.
- --7912130361 Notice of BB Hulsey 791218 deposition in Dallas.TX. CARNEY.J.A. Gentral & Southwest Corp. CARNEY.J.A. Central Power & Light Co. CARNEY.J.A. Public Service Co. of Oklahoma. 79/11/27. ip.
- --7912130366 Notice of PO Brittain 791218 deposition in Dallas, TX.
  CARNEY, J. A. Central & Bouthwest Corp. CARNEY, J. A. Central Power & Light Co. CARNEY, J. A. Public Bervice Co. of Oklahoma.
  79/11/27. 19.
- ---7912130378 Notice of MD Spence 791219 deposition in Dallas.TX.
  Centificate of Syc encl.
  CARNEY.J.A. Central & Bouthwest Corp. CARNEY.J.A. Central Power & Light Co. CARNEY.J.A. Public Service Co. of Oklahoma.
  79/11/27.
- 7912140184 Notifies that documents discussed in 791107 ltr will be available at law firms for NRC insp.Certificate of Bvc encl. FLYNN,P. 9. Lowenstein, Newman, Rais, Axelrad & Toll. 79/11/27. 6pp.

- 791217006B Request for issuance of subpoems & for mod of ASLB 790724 order. Order should be modified to relfect outstanding discovery matters & briefing schedule. Certificate of Svc & list of deponents and:

  CYPHERT, S. D.: PARMENTER, F. H. Justice Dept. of. 79/11/29. 15pp.
- 7912120249 Motion to compel DOJ & NRC responses to Houston Lighting & Power First set of interrogatories & requests for production of documents DOJ 791010 responses & NRC 7B1201 answers were incomplete. W/Certificate of Svc.
  FLYNN, P. G. Houston Lighting & Power Co. 79/11/30. 32pp.
- 7912170138 Notifies that DOJ does not intend to call JL Johns as witness. LUQUE N. Justice Dept. of. 79/12/03. 1p.
- 7912180202 Subpoemas EB Barnes to appear in Houston TX on 800205.
  MILLER,M.E. Atomic Safety and Licensing Board Panel. 79/12/03. 1p.
- --7912180209 Bubpoenas F Taylor to appear in Mouston.TX on 800206.
  MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
- ---7912180231 Subpoenas G Knowles to appear in Houston TX on 800208.

  MILLER M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
  10.
- --7912180240 Subpoenas GW Opres to appear in Houston, TX on 800130.

  MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
- --7912180252 Subpoens AM Smith to appear in Beaumont.TX on B00122.
  MILLER.M.E. Atomic Safety and Licensing Board Panel. 79/12/03.
  1p.
- --7912180262 Subposes A Sprawls to appear in Beaumont, TX on 800124.
  MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
- --7912180272 Subpoenas W Atkins to appear in Beaumont, TX on 800122.
  MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
  10.
- --79121802B1 Subpoenas RM McCuistion to appear in Houston.TX on 800129. MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
- --7912180289 Subposes T Standish to appear in Houston, TX on B00117. MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
- --7912180297 Subpoenas J Greenwade to appear in Houston, TX on 800116. MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
- --7912180306 Subposnas N Lee to appear in Beaumont.TX on 800125. MILLER.M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
- --7912180311 Bubpoenas MW Milberg to appear in Houston.TX on 800207. MILLER.M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
- --7912180320 Subposens TR Locks to appear in Nichita Falls, TX on 800103. MILLER, M. E. Atomic Bafety and Licensing Spard Panel. 79/12/03.
- --7912180329 Subposens EA Turner to appear in Houston, TX on 800131.
  MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
- ~-7912180340 Subpoens RJ Earhart to appear in Houston TX on 800115. MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
- --7912180349 Subposens JE Monahan to appear in Maco.TX on 800104. MILLER.M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
- --7912180360 Subpoenas HL Manning to appear in Dallas.TX on 800108.
  MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
- ---7912180372 Subposens DC De La Casa to appear in Dallas,TX on 800109. MILLER,M.E. Atomic Safety and Licensing Board Panel. 79/12/03.

- --7912180381 Subposens S Beard to appear in Dallas, TX on 800108. HILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/03. 1p.
- --7912180395 Subpoenas EL Watson to appear in Dallas,TX on 800110. MILLER,M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
- ---7912180404 Subposens JE Bondurant to appear in Beaumont.TX on 800123. MILLER.M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
- --7912180414 Subpoens JS Farrington to appear in Dallas TX on 790111.
  MILLER.M.E. Atomic Safety and Licensing Board Panel. 79/12/03.
- --7912180423 Subpoenas R Corder to appear in Dailas.TX on 800109. MILLER.M.E. Atomic Safety and Licensing Board Panel. 79/12/03.
- 7912110459 Response by Public Utils Board of City of Brownsville, TX in support of DDJ motion for mod of ASLB 790724 order requesting addi discovery period. Extension will allow thorough preparation for hearing. Certificate of Svc encl. PDIRIER, M. R. Texos, State of. 79/12/05. App.
- 7912190110 Requests util provide documents subposnaed & produced at AE Naylor 791011 deposition BLUME,M.B. Antitrust Division. 79/12/05. 1p.
- 791219013B Monthly status rept for Nov 1979. Parties arrived at terms of protective order. Four scheduled depositions delayed. Draft of order encl.
  PDIRIER, M. R. Spiegel & McDiarmid. 79/12/05. Bpp.
- 7912270084 Status rept for Nov 1979. South TX Electric Cooperative. Inc & Medina Electric Cooperative. Inc neither initiated nor received discovery requests.
  JOHN. D.F. South Texas Electric Cooperative. Inc. JDHN. D.F. Hetropolitan Edison Co. JDHN. D.F. Akin. Gump. Hauer & Feld. 79/12/05. 4pp.
- 7912280639 Discovery rept for Nov 1979. No discovery requests initiated or received. Certificate of Svc encl.
  BALGUGH, R. C. Austin, TX. 79/12/06. Spp.
- 7912260297 Response in support of DOJ motion for mod of ASLB 790724 order by extending discovery & hearing schedule. Delay needed to assimilate evidence & to narrow issues. Cortificate of Svc encl.

  WELLING. B. Central & Southwest Corp. HELLING. S. Isham. Lincoln & Beale. 79/12/07. 10pp.
- 7912260360 Memorandum in support of DDJ motion requesting mod of ABLD 790724 order.Proposed addl time for completion of discovery, continuation of depositions & final prehearing conference needed to perform studies. Centificate of Byc encl.
  RITTB.F.H., BURCHETTE, W.H. Fexas-Louisiana Electric Cooperative, Inc. RITTB.F.H. Northcutt Ely, 79/12/07. 6pp.
- 7912270123 Discovery rept for Nov 1979. Fifteen depositions taken. Third supplemental response to util second set of interrogetories filed DDJ filed 79130 request for mod of 790724 ASLB order. CYPHERT. S. B. Justice. Dept. of. 79/12/07. Jpp.
- 7912270104 Discovery status rept for Nov 1979 for Central & Southwest Corp. Thirteen depositions taken.
  CARNEY, J. A. Isham, Lincoln & Beale. 79/12/10. 5pp.
- 7912240357 Response to DOJ 791130 motion for mod of ASLB 790724 order by extending hearing schedule to for ancillary relief. If modified, single discovery termination date should be adopted. Certificate of Svc enci.
  BLUM.R. L. Houston Lighting & Power Co. BLUM.R. L. Baker & Butts. 79/12/11, 9pp.
- 7912270103 Mod of 790323 protective order expanding categories of documents considered confidential & expanding protected area to include documents produced by Central & South West Corp & Central & South West Sycs. Inc.

  MILLER. M. E. Atomic Safety and Licensing Board Panel. 79/12/11.
  2pp.
- 7912280670 Notifies of correct svc list for Central & South West Corp. STAHL, D. M. Isham, Lincoln & Reale. 79/12/11. ip.

- 7912280627 Supports util 791005 request for directed certification of ASLB 791005 order re-motions based upon decision of US District Court Order should be reviewed due to holding that res judicate inapplicable to antitrust proceedings.

  KNOTTS.J.B. Texas Utilities Generating Co. KNOTTS, J.B., AMEARN, C.B. Debevoise & Liberman. 79/12/12. 37pp.
- .7912280629 Notice of appearance in proceeding. Certificate of Svc encl. AHEARN, C. D. Texas Utilities Generating Co. AHEARN, C. D. Dallas Power & Light Co. AHEARN, C. D. Texas Electric Service Co. 79/12/12. App.
- 7912260081 Brief in opposition to applicant 791109 request that ASLAB certify ASLB 791005 order denying applicant motion for summary disposition. No irreparable harm injury to public interest or unusual delay present to justify certification. CHANANIA.F.D., HODODON, A. Antitrust Division. 79/12/14. 31pp.
- 7912270137 Order extending time to 800229 for completin of discovery, to 800328 for completion of expert discovery, to 800428 for filing witness lists. Schedules prehearing conference for 800305 & evidentiary hearing for 800514.
  MILLERM.E. Atomic Safety and Licensing Board Panel. 79/12/14.
  App.
- 7912310137 Motion for extension until 800201 to file supplemental response to Houston Lighting & Power first set of interregatories. Involvement in depositions requires allocation of additime. W/Certificate of Svc. CYPHERT, S. B., PARMENTER, F. H., LUGUE, N. Justice, Dept. of. 79/12/14. Bpp.
- 7712310187 Opposition to util 771109 request for directed certification & review of ASLR order. If certification directed, collateral estoppel effect should not be given to fact issues delineated by util in another case.

  POIRTER.M.R. Brownsville, TX. POIRTER, M.R. Spiegel & McDiarmid, 79/12/14. 18pp.
- 7912260044 Answer concurring w/DOJ 791130 motion for mod of ASLB 790724 order by extending current hearing & discovery schedule. Facility will be ready for fuel-loading between Aug & Nov 1981. Certificate of Svc encl. LESSY,R.P., CHANANIA.F.D. Antitrust Division. 79/12/17. 5pp.
- 7912260361 Opposition to util 791130 request to compel further discovery. Util has not requested further discovery from NRC. NRC willing to work w/util to arrive at mutually agreeable discovery schedule. Cortificate of Svc encl. LESSY,R.P., CHANANIA,F.D. Antitrust Division. 79/12/17. App.
- 7912280649 Forwards documents from files of A Gerber per request. W/o encl. Certificate of Svc encl. FLYNN, P. G. Lowenstein, Newman, Reis, Axelrad & Toll. 79/12/17. Spp.
- 7912310001 Supplementary response to first set of interrogatories.
  Discusses areas where util & Public Util Board of
  Brownsville.TX compete.Affidavit of JW Wilson, supporting
  documentation & Cortificate of 8 byc encl.
  WILSON,J.W. Brownsville.TX. 79/12/19. 62pp.
- 7912310161 Opposition to applicant 791218 motion for protective order. Order filed inadvertently & conflicts w/previously agreed to terms. Intervenor willing to consider modifying agreement. PDIRIER.M.R. Brownsville.TX. POIRIER.M.R. Spiegel & McDiarmid. 79/12/19. 4pp.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912140240 Responds to IE Bulletin 79-14 re seismic analysis for safety-related piping sys. Requests waiver on 120-day reporting requirements due to ongoing const. GARY.R.J. Texas Utilities Generating Co. 79/10/25. 1p.
- 7912100265 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/11/16. 1p.
- 7912110537 Forwards IE Info Notice 79-29, "Loss of Noneafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required.

  BEYFRIT.K.V. Region 4, Dallas, Office of the Director. 79/11/16.
  1p.
- 7912110285 Forwards IE Circular 79-23; "Motor Starters & Contactors Failed to Operate." No response required.
  8EYFRIT.K. V. Region 4, Dallas, Office of the Director. 79/11/26.

- 79:21:049: Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty gameral ofes copies of escalated enforcement correspondence sent by NRC to licensees.

  SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/11/26.
- 79:2190056 Forwards IE Circular 79-24. "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BHRs." No written response required. EEYFRIT.K.V. Region 4. Dallas. Office of the Director. 79/11/26.
- 7912190193 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation."
  No written response required.
  BEYFRIT.M.V. Region 4, Dallas, Office of the Director. 79/11/30.
- 7912310267 Forwards IE Info Notice 79-30, "Reporting of Defects & Moncompliances, 10CFR21." No action required.
  BEYFRIT, M. V. Region 4, Dallas, Office of the Director. 79/12/06.
- 7912200222 Forwards IE Bulletin 79-28, "Possible Maifunction of Namco Model EA180 Limit Switches at Elevated Temps," Action required.
  BEYFRIT,K.V. Region 4. Dallas, Office of the Director. 79/12/07.
- 7912280592 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required.
  BEYFRIT.K.V. Region 4, Dallas, Office of the Director. 79/12/13.
  1p.

### DOCKET 8TN-50-447 GEBBAR-238

- A. Application/construction stage documents & correspondence
- 7912130493 Forwards Revision 3 pages to QE rapt 22A4365, "Interim Containment Loads Rept - Mark III Containment." Proprietary version withheld (ref IOCFR2.790). BHERHOOD, G. G. General Electric Co. 79/11/30. 2pp.
- --7912130500 Revision 3 pages to 22A4365, "Interim Containment Loads Rept - Mork III Containment," nonproprietary version. REUTER,F., 9TANCAVAGE,P.P., IANNI.P.W. General Electric Co. 22A4365, 79/11/21, 175pp.

### DOCKET 50-448 DOUGLAS POINT NUCLEAR STATION, UNIT 1

- A. Application/construction stage documents & correspondence
- 7912180650 Forwards detailed comments by CW Billups on aquatic sections of draft ORNL testimony re alternative site analysis. Aquatic savessment fails to support conclusion that no alternative sites are better than Douglas dite.

  LEAR, Q. Environmental Specialists Branch. 79/12/05. 7pp.

### M. Antitrust correspondence

- 7912270103 Mod of 790323 protective order, expanding categories of documents considered confidential & expanding protected area to include documents produced by Central & South West Corp & Central & South West Svcs. Inc.
  MILLER, M.E. Atomic Safety and Licensing Board Panel. 79/12/11.
- DOCKET 50-449 DOUGLAG POINT NUCLEAR STATION, UNIT 2
- A. Application/construction stage documents & correspondence
- 7912180650 Forwards detailed comments by CW Billups on aquatic sections of draft ORNL testimony re alternative site analysis. Aquatic assessment fails to support conclusion that no alternative sites are better than Douglas site.

  LEAR. O. Environmental Specialists Brench. 79/12/05. 7pp.
- . Antitrust correspondence
- 79:1300021 Identifies documents not produced in Southwestern Electric Flower Co document production, Documents necessary for review. Production data will be set at Hartley deposition. Cartificate of Svc sucl. GREEN.D. G. Lowenstein, Newman, Reis, Axelrad & Toll. 79/11/01. Spp.

- DOCKET 50-452 GREENWOOD ENERGY CENTER. UNIT 2
- A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early vertification program to resolve ATHS issue for PHRs & BHRs. Success of program depends on industry response Supports formation of numers groups to provide necessary info. DENTON.H.R. Office of Nuclear Reactor Regulation. 79/10/17. Opp.
- C. Utility Environmental Report (ER), amends & correspondence
- 7912180269 Notifies that review of Suppl 5 to environ rept is suspended due to licensee indication that licensing effort has ceased.

  BALLARD.R.L. Environmental Projects Branch 1. 79/11/16. ip.
- S. Reportable occurrences, LERs & related correspondence
- 7912280058 Ack receipt of 791120 interim rept re raceway hanger support limitations. Final rapt will be reviewed upon receipt. FIORELLI,G. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 79/12/12. ip.

#### DOCKET 50-453 GREENWOOD ENERGY CENTER, UNIT 3

- A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRs & BMRs.
  Buccess of program depends on industry response. Supports formation of cumers groups to provide necessary info.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.
- C. Utility Environmental Report (ER), amends & correspondence
- 7912180269 Notifies that review of Suppl 5 to environ rept is suspended, due to licensee indication that licensing effort has ceased.

  BALLARD.R.L. Environmental Projects Branch 1, 79/11/16. ip.
- S. Reportable occurrences, LERs & related correspondence
- 7912280058 Ack receipt of 791120 interim rept re receway hanger support limitations. Final rept will be reviewed upon receipt. FIORELLI.G. Region 3. Chicago. Reactor Construction & Engineering Support Branch. 79/12/12. 1p.

### DOCKET 50-454 BYRON STATION, UNIT 1

- A. Application/construction stage documents & correspondence
- 7912110011 Forwards NRC position on status & applicability to pending Oi, applications of results of TMI followup actions. Outlines addl short-term actions to be taken.
  VASBALLO, D. B. Division of Project Management. 79/09/27. 41pp.
- 7912110254 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRs & BMRs. Success of program depends on industry response. Supports formation of owners groups to provide necessary info. DENTON, M. R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 79:2110435 Notification of 79:218 meeting w/util, INEL & Bargent & Lundy in Byron Béation, IL re orientation of NRC personnel & INEL raview personnel relative to facility structure.

  MOGN, C. W. Light Water Reactors Branch 4. 79/12/04. 2pp.
- --7912110447 Notification of 791219 meeting w/util.INEL & Sargent & Lundy in Chicago.IL re selection of structural drawings for NRC audits & independent analyses. MODN.C.W. Light Water Reactors Branch 4. 79/12/04. ip.
- --7912110463 Notification of 791217 meeting w/util, INEL & Bargent & Lundy in Braidwood Station, IL re orientation of NRC personnel & INEL review personnel relative to facility structures. MODN.C. W. Light Water Reactors Branch 4. 79/12/04. ip.
- --7912110475 Notification of 791220 meating w/util.ANL.Hestinghouse & Sargent & Lundy in Argonne.IL re identification for util of gameral info omission in Chapter 7 of FSAR.concerning instrumentation & control.

  MODN.C.W. Light Water Reactors Branch 4. 79/12/04. 2pp.

- 7912310348 Forwards revised pages to CE-1-A. "Comm Ed GA Program for Nuclear Generating Stations:" Revision 11.

  JANECEK.R.F. Commonwealth Edison Co. 79/12/20. 1p.
- --7912310359 Revised pages to CE-1-A. "Comm Ed QA Program for Nuclear Generating Stations." Revision II. & Commonwealth Edison Co. CE-1-A. 79/11/21. 16pp.

## F. Security, medical, emergency & fire protection plans

- 7912040471 Forwards info re upgraded emergency plans to plants under const & DL review Applicants required to make certain emergency arrangements w/state & lucal organizations & submit emergency plans par Reg Guide 1.101.

  VASSALLO,D.B. Division of Project Management. 79/11/21. App.
- 7912040285 Forwards Revision 1 to physical security plans. Revision withheld (ref 10CFR2.790).
  PEOPLES, D. L. Commonwealth Edison Co. 79/11/26. 1p.

### Adjudicatory correspondence

- 7912060545 Submits updated info as followup to 791111 progress rept on continuing negotiations between applicant, intervenors & NRC Statements on position furnished to interfenors. NRC & applicant responses to contentions will be filed by 800209. KARMAN, M. Hearing Branch 2. 79/11/27. 2pp.
- 7912260363 Statement of contentions. Applicant should re-evaluate dose impacts of projected routine releases of radioactive matls to determine cumulative affects. Applicant incapable of operating within NRC regulations. Certificate of Svc encl. MAHLER. J. DeKalb Area Alliance for Responsible Energy. MAHLER. J. Sinnissippi Alliance for the Environment (SAFE). 79/12/10. 15pp.

#### H. General correspondence

7912280605 Discusses 791204 title change of manager of nuclear operations to vice president Organization structure not altered. No revision will be made to QA program topical rept CE-1-A until organization structure is delineated.

JANECEK, R. F. Commonwealth Edison Co. 79/12/19. 1p.

## 0. Inspection reports, IE Bulletins & correspondence

- 7912050538 Forwards IE Insp Repts 50-454/79-14 & 50-455/79-14 on 790911-28 & notice of violation.
  FIDRELLIA. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/10/25. 2pp.
- --7912050542 Notice of violation from insp on 790911-28.

  \* Region 3, Chicago. Office of the Director. 79/10/23. 2pp.
- --7912050554 IE Insp Repts 50-454/79-14 & 90-455/79-14 on 790911-28.
  Noncompliance noted: inadequate procedures & failure to
  follow procedures re qualification of personnel & inadequate
  document control.
  WILLIAMS.C., BUERMANN.J.F., MAXWELL.G.F Region 3, Chicago,
  Office of the Director. 79/10/23, 23pp.
- 7912200577 Forwards IE Insp Repts 50-454/79-14 & 50-455/79-14 on 791023-25 & notice of violation. FIGRELLI.G. Region GJ. Chicago, Reactor Construction & Engineering Support Branch. 79/11/07. 2pp.
- --7912200582 Notice of violation from insp on 791023-25.

  \* Region 3. Chicago. Office of the Director. 79/11/06. 1p.
- ---7912200589 IE Insp Repts 50-454/79-16 & 50-455/79-16 on 791023-25.
  Noncompliance noted inadequate procedure re observation of welding activities in Unit 1.
  LEE,E.W., DANIELSON, D.H. Region 3, Chicago, Office of the Director. 79/11/06. 6pp.
- 7712050106 Forwards IE Circular 77-22, "Stroke Times for Power Operated Relief Valves." No response required.

  KEPPLER, J. G. Region 3: Chicago, Office of the Director. 79/11/16.
- 7912100213 Forwards IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads." No response required. KEPPLER, J. 9. Region 3. Chicago, Office of the Director. 79/11/16.

- 7712110557 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required.
  KEPPLER. J. G. Region 3. Chicago. Office of the Director. 79/11/16.
  10.
- 7912050344 Forwards 1E Bulletin 79-26, "Boron Loss From BWR Control Blades," No response required.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/20.
- 7912100417 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No written response required.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/28.
- 7912140187 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operats." No written response required.
  KEPPLER, J. G. 'Region 3, Chicago, Office of the Director. 79/11/26.
- 7912110375 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofce copies of escalated enforcement correspondence sent by NRC to licensees.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/28.

  ip.
- 79:2190207 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation."
  No written response required.
  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/30.
  ip.
- 7912140056 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances: 10CFR21." No action or response required. KEPPLER. J. 9. Region 3. Chicago, Office of the Director. 79/12/08.
- 7712200086 Forwards IE Bulletin 79-28, "Possible Malfunction of Nasco-Model EAIBO Limit Buitches at Elevated Temps," Action required. KEPPLER, J. G. Region 3, Chicago, Office of the Director, 79/12/10.

## DOCKET 50-455 BYRON STATION, UNIT 2

- A. Application/construction stage documents & correspondence
- 7912110011 Forwards NRC position on status & applicability to panding OL applications of results of TMI followup actions. Outlines addl short-term actions to be taken.
  VASSALLO.D.B. Division of Project Hanagement. 79/09/27, 41pp.
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRs & BMRs. Success of program depends on industry response. Supports formation of owners groups to provide necessary info. DENTON.H.R. Office of Nuclear Reactor Regulation. 79/10/17. Upp.
- 7912110435 Notification of 791218 meeting w/util, INEL & Sargent & Lundy in Syron Station, IL re crientation of NRC personnel & INEL review personnel relative to facility structure.
  MODN.C.W. Light Water Reactors Branch 4. 79/12/04. 2pp.
- --7912110447 Notification of 791219 meeting w/util, INEL & Bargent & Lundy in Chicago, IL re selection of structural drawings for NRC audits & independent analyses. MODN.C.W. Light Water Reactors Branch 4. 79/12/04. ip.
- ---7912110475 Notification of 791220 meeting w/util, ANL, Westinghouse & Sargent & Lundy in Argonne, IL re identification for util of general info omission in Chapter 7 of FBAR, concerning instrumentation & control.

  MOON, C. W. Light Water Reactors Branch 4. 79/12/04. 2pp.
- 791231034B Forwards revised pages to CE-1-A, "Comm Ed GA Program for Nuclear Generating Stations," Revision 11, JANECEK, R. F. Commonwealth Edison Co. 79/12/20, 1p.
- ---7912310359 Revised pages to CE-1-A, "Comm Ed GA Program for Nuclear Generating Stations," Revision 11. \*\* Commonwealth Edison Co. CE-1-A, 79/11/21, 14pp.

# F. Security, medical, emergency & fire protection plans

- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review. Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Quide 1.101.
  VASSALLO, D. B. Division of Project Management. 79/11/21. App.
- 7912040205 Forwards Revision 1 to physical security plans.Revision withheld (ref 10CFR2.790). PEOPLES.D.L. Commonwealth Edison Co. 79/11/26. 1p.

## 9. Adjudicatory correspondence

- 7712050B49 Bubmits updated info as followup to 791111 progress rept on continuing negotiations between applicant intervenors & NRC. Statements on position furnished to interfenors. NRC & applicant responses to contentions will be filed by 800209. KARHAN, M. Hearing Branch 2. 79/11/27. 2pp.
- 7712240363 Statement of contentions Applicant should re-evaluate dose impacts of projected routine releases of radioactive mat1s to determine cumulative effects Applicant incapable of operating within NRC regulations. Certificate of Svc encl. MAHLER, J. Dekalb Area Alliance for Responsible Energy. MAHLER, J. Sinnissippi Alliance for the Environment (SAFE). 79/12/10. 15pp.

## H. General correspondence

- 7912280605 Discusses 791204 title change of manager of nuclear operations to vice president. Organization structure not altered. No revision will be made to GA program topical rept CE-1-A until organization structure is delineated. JANECEK.R.F. Commonwealth Edison Co. 79/12/19. 1p.
- 8. Inspection reports, IE Bulletins & correspondence
- 791205053B Forwards IE Insp Repts 50-454/79-14 & 50-455/79-14 on 790911-28 & notice of violation.
  FIORELLI.O. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/10/25. 2pp.
- --7912050542 Notice of violation from insp on 790911-28. # Region 3, Chicago, Office of the Director. 79/10/23. 2pp.
- --7912050534 IE Insp Repts 50-434/79-14 & 50-455/79-14 on 790911-28. Noncompliance noted inadequate procedures & failure to follow procedures re qualification of personnel & inadequate document control. WILLIAMS.C.C., SUERMANN, J.F., MAXWELL, Q.F. Region 3, Chicago, Office of the Director. 79/10/23. 23pp.
- 7912200577 Forwards IE Insp Repts 50-464/79-16 & 50-455/79-16 on 791023-25 & notice of violation.
  FIDRELLI.O. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/11/07. 2pp.
- --7912200582 Notice of violation from insp on 791029-25. • Region 3, Chicago, Dffice of the Director. 79/11/06. 1p.
- --7912200589 IE Insp Repts 50-454/79-16 & 50-455/79-16 on 791023-25.
  Noncompliance noted: inadequate procedure re observation of welding activities in Unit 1.
  LEF.E. H., DANIELSON, D. H. Region G. Chicago, Office of the Director. 79/11/06. 6pp.
- 7912030106 Forwards IE Circular 79-22, "Btroke Times for Power Operated Relief Valves." No response required.
  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912100213 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/16, ip.
- 7912110557 Forwards IE Info Notice 79-29, "Lpss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required.

  KEPPLER. J. G. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912050344 Forwards IE Bulletin 79-26, "Boron Loss From BHR Control Blades." No response required.

  KEPPLER, J. C. Region G. Chicago, Office of the Director. 79/11/20.

- 7912100417 Forwards IE Circular 79-24. "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No written response required.

  KEPPLER, J. G. Region 3. Chicago Office of the Director. 79/11/26.
- 7912140187 Forwards IE Circular 79-23. "Motor Starters & Contactors Failed to Operate." No written response required. KEPPLER.J. Q. Region 3. Chicago. Office of the Director. 79/11/26.
- 7912110398 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state attugeneral ofcs copies of escalated enforcement correspondence sent by NRC to licensees.

  KEPPLER, J. G. Region 3. Chicago, Office of the Director. 79/11/28.
- 7912190207 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation."
  No written response required.
  KEPPLER.J. G. Region 3. Chicago, Office of the Director. 79/11/30.
- 7912140056 Forwards IE Info Notice 79-30. "Reporting of Defects & Noncompliances, 10CFR21." No action or response required.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/12/06.
- 7912200086 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. KEPPLER, J. 9. Region 3, Chicago, Office of the Director. 79/12/10.

## DOCKET 50-456 BRAIDWOOD STATION, UNIT 1

- A. Application/construction stage documents & correspondence
- 7912110011 Forwards NRC position on status & applicability to pending DL applications of results of TMI followup actions Outlines add1 short-term actions to be taken.
  VASSALLO.D.B.. Division of Project Management. 79/09/27. 41pp.
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRs & BMRs.
  Buccess of program depends on industry response Supports formation of numbers groups to provide necessary info.
  DENTON.H.R. Office of Nuclear Reactor Regulation, 79/10/17. Opp.
- 7912110435 Notification of 791218 meeting w/util, INEL & Sargent & Lundy in Byron Station, IL re orientation of NRC personnel & INEL review personnel relative to facility structure, MOON, C. W. Light Water Reactors Branch 4, 79/12/04, 2pp.
- --7912110447 Notification of 791219 meeting w/util, INEL & Bargent & Lundy in Chicago, IL re selection of structural drawings for NRC audits & independent analyses. MODN.C.W. Light Water Reactors Branch 4. 79/12/04. 1p.
- ---7912110463 Notification of 791219 meeting w/util, INEL & Bargent & Lundy in Braidwood Station, IL re orientation of NRC personnel & INEL review personnel relative to facility structures, MBON, C. W. Light Water Reactors Branch 4. 79/12/04. 1p.
- ---7912110479 Notification of 791220 meeting w/util, ANL, Westinghouse & Bargent & Lundy in Argonne, IL re identification for util of general info omission in Chapter 7 of FBAR, concerning instrumentation & control.

  MODN, C. W. Light Water Reactors Branch 4. 79/12/04. 2pp.
- 7912310348 Forwards revised pages to CE-1-A. "Comm Ed GA Program for Nuclear Generating Stations." Revision 11.
  JANECEK.R.F. Commonwealth Edison Cg. 79/12/20. 1p.
- --7912310359 Revised pages to CE-i-A, "Comm Ed QA Program for Nuclear Generating Stations," Revision 11. \* Commonwealth Edison Co. CE-i-A, 79/11/21, 14pp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review. Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Ouide 1.10i.
  VASSALLO.D.B. Division of Project Management. 79/11/21. 6pp.

- 7912040285 Forwards Revision I to physical security plans. Revision withheld (ref 10CFR2, 790).
  PEOPLES, D. L. Communwealth Edison Co. 79/11/26. 1p.
- G. Adjudicatory correspondence
- 7912030537 Advises of 790912 const suspension following issuance of IL Commerce Commission 790912 rate order affirmed on 791012.

  Date of resumption of const still undetermined ASLB will be informed of future changes.

  HURPHY.P.M. Isham, Lincoln & Beale, 79/10/24. 3pp.
- H. General correspondence
- 7912280605 Discusses 791204 title change of manager of nuclear operations to vice president Drganization structure not altered. No revision will be made to GA program topical rept CE-1-A until organization structure is delineated.

  JANECEK, R. F. Commonwealth Edison Co. 79/12/19. jp.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912040043 Forwards IE Insp Repts 50-456/79-12 & 50-457/79-12 on 790925-28 & notice of violation.
  FIORELLI.O. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 79/10/24. 2pp.
- --7912060048 Notice of violation from insp on 790925-28.
  Region 3. Chicago, Office of the Director. 79/10/23. ip.
- --7912060063 IE Insp Repts 50-456/79-12 & 50-457/79-12 on 790925-28. Noncompliance noted: failure to have procedures for control of safety-related activities during extended shutdown. SCHMEIBINZ.E.R., JONES.C.E., WILLIAMS.C.C. Region 3, Chicago, Office of the Director. 79/10/23, 7gp.
- 7912050106 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912100213 Forwards IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads." No response required.

  KEPPLER.J. C. Region 3: Chicago. Office of the Director. 79/11/16.
- 7912110557 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912050344 Forwards IE Bulletin 79-26, "Boron Loss From BHR Control Blades," No response required. MEPPLER, J. G. Region 3. Chicago, Office of the Director. 79/11/20.
- 7912100417 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." Now written response required.

  KEPPLER, J. O. Region 3. Chicago, Office of the Director. 79/11/26.

  1p.
- 7912140187 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No written response required.
  KEPPLER.J. G. Region 3. Chicago. Office of the Director. 79/11/26.
- 7912110395 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ufcs copies of escalated enforcement correspondence sent by NRC to licensees.

  KEPPLER, J. 9. Region 3, Chicago, Office of the Director. 79/11/28.
- 7912190207 Forwards IE Dulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." No written response required. KEPPLER.J.O. Region 3. Chicago, Office of the Director. 79/11/30.
- 7912140056 Forwards IE Info Notice 79-30. "Reporting of Defects & Moncompliances, iOCFR21." No action or response required.
  KEPPLER.J.O. Region 3, Chicago, Office of the Director. 79/12/06.

- 79:2200086 Forwards IE Bulletin 79-28, "Possible Malfunction of Masco Model EALBO Limit Switches at Elevated Temps." Action required. KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/12/10.
- U. Congressional/Executive Correspondence
- 7712270043 Responds to 770827 itr re Q Topolsti 770825 concern about const of nuclear plant over shaft mines & underground water. Deep mine shafts have been sealed & siurry trench designed to prevent water seepage out of cooling lake. ODSSICK.L.V. Diffice of the Executive Director for Operations, 79/10/17. 2pp.
- DOCKET 50-457 BRAIDWOOD STATION, UNIT 2
- A. Application/construction stage documents & correspondence
- 7912110011 Forwards NRC position on status & applicability to pending OL applications of results of TMI followup actions. Outlines addl short-term actions to be taken.
  VASSALLO, D. B. Division of Project Management. 79/09/27. 41pp.
- 7912110264 Discusses NRC plans to use generic analyses to develop early varification program to resolve ATWB issue for PMRs & BWRs. Success of program depends on industry response. Supports formation of owners groups to provide necessary info. DENTON. M.R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912110447 Notification of 791219 meeting w/util INEL & Bargent & Lundg in Chicago. IL re selection of structural drawings for NRC audits & independent analyses. MDDN.C.M. Light Water Reactors Branch 4. 79/12/04. 1p.
- --7912110463 Notification of 791219 meeting w/util, INEL & Bargent & Lundq in Braidwood Btation, IL re orientation of NRC personnel & INEL review personnel relative to facility structures. MODN, C. W. Light Water Reactors Branch 4. 79/12/04. ip.
- --7912110475 Notification of 791220 meeting w/util, ANL, Westinghouse & Bargent & Lundy in Argonne, IL re identification for util of general info omission in Chapter 7 of FBAR, concerning instrumentation & control.

  MOGN, C. H. Light Water Reactors Branch 4. 79/12/04. 2pp.
- 7912310348 Forwards revised pages to CE-1-A, "Comm Ed QA Program for Nuclear Generating Stations," Revision 11.

  JANECEK,R.F. Commonwealth Edison Co. 79/12/20. ip.
- --7912310359 Revised pages to CE-1-A, "Comm Ed GA Program for Nuclear Generating Stations," Revision 11. \* Commonwealth Edison Co. GE-1-A. 79/11/21. 16pp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards into re upgraded emergency plans to plants under const & OL review. Applicants required to make certain emergency arrangements w/state & local organizations & submit amorgancy plans per Reg Guide 1.101.
  VASSALLO.D.B. Division of Project Management. 79/11/21. Opp.
- 7712040285 Forwards Revision 1 to physical security plans.Revision withheld (ref 10CFR2,790).
  PEOPLES.D.L. Commonwealth Edison Co. 79/11/26. 1p.
- G. Adjudicatory correspondence
- 7912050539 Advises of 790912 const suspension following issuance of EL Commerce Commission 790912 rate order affirmed on 791012. Date of resumption of const still undetermined ASLB will be informed of future changes. MURPHY.P.M. Isham, Lincoln & Beale. 79/10/24. 3pp.
- H. General correspondence
- 7912280605 Discusses 791204 title change of manager of nuclear operations to vice president Organization structure not altered. No revision will be made to GA program topical rept CE-1-A until organization structure is delineated, JANECEK.R.F. Commonwealth Edison Co. 79/12/19. 1p.

### Q. Inspection reports, IE Bulletins & correspondence

- 7912060043 Forwards IE Insp Repts 50-456/79-12 & 50-457/79-12 on 790925-28 & notice of violation. FIGRELLI.0. Region 3. Chicago. Reactor Construction & Engineering Support Branch. 79/10/24. 2pp.
- --79120A004B Notice of violation from insp on 790925-28.
  \*\* Region 3, Chicago, Office of the Director. 79/10/23. 1p.
- --7912060063 IE Insp Repts 50-456/79-12 & 50-457/79-12 on 790925-28. Nancompliance noted: failure to have procedures for control of safety-related activities during extended shutdown. BCHMEJBINZ, E. R. JONES, C. E., WILLIAMS, C. C. Region G, Chicage, Office of the Director. 79/10/23. 7pp.
- 7912050106 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912100213 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Fipe Support Loads." No response required.

  KEPPLER, J. Q. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912110557 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required.

  REPPLER, J. 9. Region 3, Chicago, Office of the Director. 79/(1/16.
- 7912050344 Forwards IE Bulletin 79-26, "Boron Loss From BUR Control Blades," No response required.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/20.
  ip.
- 7912100417 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BMRs." No written response required.

  KEPPLER. J. Q. Region 3, Chicago, Office of the Director. 79/11/26.
- 7912140187 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No written response required.

  KEPPLER. J. 9. Region 3. Chicago. Office of the Director. 79/11/26.
- 7712110395 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofce copies of escalated enforcement correspondence sent by MRC to licensees.

  KEPPLER, J. G. Region 3, Chicago, Office of the Birector. 79/11/28.
- 7912190207 Forwards IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation." No written response required.

  KEPPLER, J. Q. Region G. Chicago, Office of the Director. 79/11/30.
- 7912140036 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action or response required.

  KEPPLER, J. Q. Region 3, Chicago, Office of the Director. 79/12/06.
  ip.
- 7912200086 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Madel EALBO Limit Switches at Elevated Temps." Action required.

  KEPPLER, J. Q. Region 3, Chicago, Office of the Director. 79/12/10.

  1p.

## U. Congressional/Executive Correspondence

7912270043 Hesponds to 790829 ltr re G Topolski 790825 concern about const of nuclear plant over shaft mines & underground water. Deep mine shafts have been sealed & slurry trench designed to prevent water seepage out of cooling lake. OBSEICK.L.V. Office of the Executive Director for Operations. 79/10/17. 2pp.

- DOCKET 50-458 RIVER BEND STATION, UNIT 1
- A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRs & BMRs. Success of program depends on industry response. Supports formation of numers groups to provide necessary info. DENTON.H.R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912050363 Forwards "Alternatives Studied to Minimize Impact on Port Hudson Battlefield Natl Historic Landmark." Two oversize aerial photomocaics & two mylar overlays of battlefield encl & available in Central Files only. WEIGAND.J. G. Gulf States Utilities Co. 79/11/30. 2pp.
- ---7912050368 "Alturnatives Studied to Minimize Impact on Port Hudson Battlefield Historic Natl Landmark." One oversize map encl & available in Central Files only. \* Gulf States Utilities Co. 79/11/30. 31pp.
- 7912210335 Advises of plans to submit DL applications for docteting on B01201, in response to NRC request. WEIGAND, J. G. Oulf States Utilities Co. 79/12/12. ip.
- F. Security, modical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Quide 1. 101. VASBALLO, D. B. Division of Project Management. 79/11/21. App.
- G. Inspection reports, IE Bulletins & correspondence
- 7912070137 Forwards suppl updating 790911 response to IE Bulletin 79-15 "Deep Draft Pump Deficiencies." Response to Inquiries 4-6 not applicable.
  MEIGAND, J. G. Quif States Utilities Co. 79/10/22. 2pp.
- 7912060551 Responds to IE Bulletin 79-23. Emergency diesel generators are designed & supplied for operation w/flooding primary neutral. Testing program will be outlined in FSAR. WEIGAND. J. G. Gulf States Utilities Co. 79/10/26. 2pp.
- 7912100257 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. SEYFRIT.K.V. Region 4, Dallas. Office of the Director. 79/11/16. 1p.
- 7912110526 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required.

  SEYFRIT.K.V. Region 4, Dallas, Office of the Director. 79/11/16.
- 7912110278 Forwards 1E Circular 79-23, "Motor Starters & Contactors Failed to Operato," No response required. SEYFRIT. K. V. Region 4, Dallas, Office of the Director. 79/11/26.
- 7912110472 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofts copies of escalated enforcement correspondence sent by NRC to licensees.

  BEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/11/26.
  18.
- 7912190040 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Byray Pipe Break Detection Equipment on BWRs." No written response required. SEYFRIT.K.V. Region 4, Dallos, Office of the Director. 79/11/26. ip.
- 7912190174 Forwards IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." No written response required.

  SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/11/30.
- 7912310260 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances: 10CFR21." No action required.

  BEYFRIT. K. V. Region 4, Dallas, Diffice of the Director. 79/12/06.

  4pp.

- 7912200210 Forwards 1E Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. SEYFRIT.K.V. Region 4, Dallas, Office of the Director. 79/12/07
- 7912280582 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required. SEYFRIT.K.V. Region 4, Dallas, Office of the Director. 79/12/13.
- S. Reportable occurrences, LERs & related correspondence
- 7912060598 PND-IV-79-012: on 791005. StW identified irregularities in concrete matl tests conducted by Southwestern Labs. Safety-related concrete placement halted until Pittsburgh Testing Labs completes sample testing.

  DBERO, C.R. CROSSMAN.W. Region 4. Dalkas, Office of the Director. 79/11/06. 2pp.

## DOCKET 50-459 RIVER BEND STATION, UNIT 2

- A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRs & BMRs. Success of program depends on industry response. Supports formation of owners groups to provide necessary info. DENTON. H. R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.
- 7912050353 Forwards "Alternatives Studied to Minimize Impact on Port Hudson Battlefield Natl Historic Landmart." Two oversize aerial photomosaics & two mylar overlays of battlefield encl & available in Central Files only. WEIGAND, J. G. Gulf States Utilities Co. 79/11/30. 2pp.
- --7912050368 "Alternatives Studied to Minimize Impact on Port Hudson Battlefield Historic Natl Landmark." One oversize map encl & available in Central Files only. # Guif States Utilities Co. 79/11/30. 31pp.
- 7912210336 Advices of plans to submit OL applications for docketing on 801201, in response to NRC request.
  WEIGAND, J. G. Gulf States Utilities Co. 79/12/12. lp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review. Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Guide 1.101.
  VASSALLO, D. B. Division of Project Management, 79/11/21. App.
- Inspection reports, IE Bulletins & correspondence
- 7912070137 Forwards suppl updating 790911 response to IE Bulletin 79-15 "Deep Braft Pump Deficiencies." Response to Inquiries 4-6 not applicable.
  WEIGAND.J. G. Gulf States Utilities Co. 79/10/22, 2pp.
- 7912060551 Responds to IE Bulletin 79-23 Emergency diesel generators are designed & supplied for operation w/flooding primary neutral Testing program will be outlined in FSAR.
  HEIGAND. J. G. Gulf States Utilities Co. 79/10/25. 2pp.
- 79:12:00257 Forwards IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads." No response required. SEYFRIT.K.V. Region 4. Dallas, Office of the Director. 79/11/16. lp.
- 7912110526 Forwards IE Info Notice 79-29. "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required.

  SEYFRIT.K.V. Region 4. Dallas, Office of the Director. 79/11/16.
- 7912110278 Forwards IE Circular 79-23. "Motor Starters & Contactors Failed to Operate." No response required.

  SEYPRIT, K. V. Region 4. Dallas. Office of the Director. 79/11/26.
- 7912110472 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sent by NRC to licensees.

  SEYFRIT.K.V. Region 4, Dalias, Office of the Director. 79/11/26.

- 7912190040 Forwards IE Circular 79-24, "Proper Installation & Catibr of Core Spray Pipe Break Detection Equipment on BWRs." No written response required.

  SEYFRIT.K.V. Region 4, Dallas, Office of the Director. 79/11/26.
- 7912190174 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." No written response required. SEYFRIT,K.V. Region 4, Dallas, Office of the Director. 79/11/30.
- 7912310260 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action required.
  SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/12/06.
- 7912200210 Forwards IE Bulletin 79-28, "Possible Malfunction of Nacco Model EA180 Limit Switches at Elevated Temps." Action required. SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/12/02.
- 7912280382 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra," No written response required. SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/12/13.
- 8. Reportable occurrences. LERs & related correspondence
- 79:2060898 PND-IV-79-012: on 79:1005.8&W identified irregularities in concrete mat1 tests conducted by Southwestern Labs. Bafety-related concrete placement halted until Pittsburgh Testing Labs completes sample testing.

  CBERG, C. R., CRUSSMAN, W. Region 4, Dallas, Office of the Director. 79/11/06. 2pp.

### DOCKET 50-440 WPPSS NUCLEAR PROJECT, UNIT 1

- A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop sarig verification program to resolve ATWS issue for PWRs & BWRs. Success of program depends on industry response. Supports formation of numers groups to provide necessary info. DENTON.H.R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.
- 7912060476 Forwards responses to NRC 791025 ltr requesting info resensitivity of primary coelant may behavior to fmedwater transients & status of various sys. Includes recommendations for plant changes.

  RENBERGER, D. L. Washington Public Power Supply System. 79/12/03.2000:
- 7912180626 Notifies of plans to submit WNP-1/4 FSAR for acceptance review by 800530 & WNP-3/5 FSAR by 810630.

  RENBERGER, D. L. Washington Public Power Supply System. 79/12/12.

  10.
- 7912280546 Forwards XN-NF-103. "Water Content of Solid Matl by Electrolysis." re testing moisture of low-hydrogen electrodes.
  RENBERGER.D. L. Washington Public Fower Supply System. 79/12/20.
  2pp.
- ---79\$2280571 "Water Content of Solid Matl by Electrolysis," Revision 6 to Procedure P69281 for testing moisture of low-hydrogen electrodes,
  \* Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). XN-NF-100.
  79/01/10. 13pp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded amergency plans to plants under const & OL review. Applicants required to make certain amergency arrangements w/state & local organizations & submit emergency plans per Reg Guide 1.101.
  VASSALLG.D.B. Division of Project Management. 79/11/21. App.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912100285 Forwards IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads." No response required. ENGELKEN.R.H. Region 5. Ben Francisco. Office of the Director. 79/11/16. ip.

- 7912110522 Forwards IE Info Notice 79-29. "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. ENGLKEN.R.H. Region 5. San Francisco. Office of the Director. 79/11/16. 1p.
- 79;2070031 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BHRs." No response required ENGELKEN, R. M. Region 5, San Francisco, Office of the Director. 79/11/26. ip.
- 7912110274 Forwards IE Circular 79-23, "Motor Btarters & Contactors Failed to Operate." No response required. ENDELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/11/26. 1p.
- 79:21:10500 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sent by NRC to licensees.
  ENGELKEN.R.H. Region 5. Ban Francisco, Office of the Director. 79/11/26. 1p.
- 79:2190161 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." No written response required. ENDELKEN,R.H. Region 5, San Francisco, Office of the Director. 79/11/30. 1p.
- 7912310279 Forwards IE Info Notice 79-30, "Reporting of Defects & Moncompliances,10CfR21." No action required. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/12/06. 4pp.
- 7912200252 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EAIBO Limit Switches at Elevated Temps." Action required. EMBELKEN.R.H. Region 5, San Francisco. Office of the Director. 79/12/07. 1p.
- 79122B0626 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No writton response required. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/12/13: 1p.
- S. Reportable occurrences, LERs & related correspondence
- 7912190745 PNO-V-79-4: on 790606.NRC received eight allegations refaulty const of util sacrificial shield wall. Three were substantiated by NRC: concrete voids in wall & visually rejectable & improperly located welds in atructure. BISHOP.T.W., DODDS.R.T. Region 5. San Francisco, Office of the Director. 79/10/12. 2pp.

## DOCKET 50-461 CLINTON POWER STATION, UNIT 1

- A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRs & BMRs.
  Buccess of program depends on industry response. Supports formation of owners groups to provide necessary info.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912060652 Notification of 791204-05 meeting w/util in Clinton, IL to assess const status.

  BUCKLEY, B. C. Light Water Reactors Branch 1. 79/11/26. 4pp.
- 7912070266 Supplements response to FOIA request for documents re facilities & Reed Rept Forwards documents listed in App A. CARR.J.C. Division of Rules and Records. 79/11/26. 3pp.
- 7912050483 Requests approval for use of ABME Code Case N-240 to exempt certain piping from hydrostatic tasting.

  HULLER, C. E. Illinois Power Co. 79/11/30. 2pp:
- F. Security, medical, emergency & fire protection plans

1

- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL raview, Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Quide 1.101.
  VABSALLO.D.B. Division of Project Management. 79/11/21. App.
- 791204027B Forwards physical security plans & safeguards contingency plan. Plans withheld (ref iOCFR2, 790).
  KUCK,L.J. Illinois Power Co. 79/12/01, ip.

- G. Inspection reports, IE Bulletins & correspondence
- 7912260087 Forwards IE Insp Rept 50-461/79-09 on 790924-28 & 1004-06.
  No noncompliance noted.
  FIGRELLI.G. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 79/11/09. 2pp.
- --7912260091 IE Insp Rept 50-461/79-09 on 790924-28 & 1004-06.No noncompliance noted: Major areas inspected: followup on items of noncompliance, review of ASME certification & reactor vessel lift installation implementing procedures. KNDP, R. C., WESCOTT, M. M., VANDEL, T. E. Region 3, Chicago, Office of the Director. 79/11/08. 7pp.
- 7912050128 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves," No response required.
  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/16.
- 79:2100233 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required.
  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912110581 Forwards IE Info Notice 79-27, "Loss of Nonsafety-Related Reactor Coolant 8ys Instrumentation During Operation." No specific action or response required. KEFPLER.J.G. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912050384 Forwards IE Dulletin 79-26. "Boron Loss From BWR Control Blades." No response required. KEPPLER.J.G. Region 3. Chicago. Office of the Director. 79/11/20.
- 7912100435 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No written response required.
  KEPPLER.J. G. Region 3, Chicago, Office of the Director. 79/11/26.
- 7912110262 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required.
  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/26.
- 7912110430 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sent by NRC to licensees.

  KEPPLER, J. G. Region 3. Chicago, Office of the Director. 79/11/28.
- 7912190224 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation."
  No written response required.
  KEPPLER. J. G. Region 3. Chicago, Office of the Director. 79/11/30.
  ip.
- 79:2:140087 Forwards IE Info Notice 79-30. "Reporting of Defects & Moncompliances. IOCFR21." No action or response required.

  KEPPLER, J. G. Region 3, Chicago. Defice of the Director. 79/12/06.
- 7912200123 Forwards IE Bulletin 79-28, "Possible Malfunction of Nameo Model EA180 Limit Switches at Elevated Temps." Action required. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/12/10.
- 8. Reportable occurrences. LERs & related correspondence
- 7912030105 PNB-III-79-001: on 791103, telephone bomb threat received. First shift evacuated & search conducted No device found & second shift commenced work. DDNAHUE, J. F. Office of Inspection & Enforcement, Office of the Director. HIND, J. A. Region 9, Chicago, Safeguards Branch. 79/11/06. 19.
- DOCKET 50-462 CLINTON POWER STATION, UNIT 2
- A. Application/construction stage documents & correspondence
- 7908070310 Forwards NUREO/CR-0660. "Enhancement of Onsite Emergency Diesel Generator Reliability." Requests comments. M/o encl. VABSALLO.D. 3. Assistant Director for Light Water Reactors. 79/04/18. 3pp.

- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATHS issue for FMRs & BMRs.
  Success of program depends on industry response. Supports formation of owners groups to provide necessary info.
  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.
- 7912070266 Supplements response to FOIA request for documents refacilities & Reed Rept. Forwards documents listed in App A. CARR, J. C. Division of Rules and Records. 79/11/26. 3pp.
- 7912050483 Requests approval for use of ASME Code Case N-240 to exempt certain piping from hydrostatic testing.
  WULLER, G. E. Illinois Power Co. 79/11/30. 2pp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review. Applicants required to make certain emergency arrangements wistate & local organizations & submit emergency plans per Reg Guide 1.101.

  VASSALLO, D. B. Division of Project Management. 79/11/21. App.
- 791204027B Forwards physical security plans & safeguards contingency plan. Plans withheld (ref 10CFR2.790).

  KOCK.L.J. Illinois Power Co. 79/12/01. 1p.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912050128 Forwards IE Circular 79-22, "Strole Times for Power Deerated Relief Valves." No response required.

  KEPPLER, J. G. Region 3, Chicago. Office of the Director. 79/11/16.
- 7912100233 Forwards IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads." No response required. KEPPLER, J. G. Region 3. Chicago, Office of the Director. 79/11/16.
- 7912110581 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/16.
- 79120903B4 Forwards IE Bulletin 79-26, "Boron Loss From BWR Control Blades." No response required. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/20.
- 7912100435 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No written response required.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/26, 10.
- 7912110262 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/26.
- 7912110430 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general office of escalated enforcement correspondence sent by NRC to licensees.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/28.
- 7912190224 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." No written response required. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/30.
- 7912140087 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action or response required.

  KEPPLER, J. G. Region 3. Chicago, Office of the Director. 79/12/06.
- 7912200123 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/12/10.

- DOCKET 50-463 FULTON GENERATING STATION, UNIT 1
- A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATWS issue for PMRs & BWRs.
  Success of program depends on industry response. Supports formation of owners groups to provide necessary info.
  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- DOCKET 50-466 ALLENS CREEK NUCLEAR STATION, UNIT 1
- A. Application/construction stage documents & correspondence
- 7911280163 Discusses mode to NRC position re status & applicability of TMI-2 accident review & NUREG-0578 to facilities under const. Forwards addi info to be considered in development of final plant design & procedures.

  VASSALLO, D. B. Division of Project Management. 79/10/10. 4pp.
- 7912110244 Discusses NRC plans to use generic analyses to davelop early verification program to resolve ATMS issue for PWRs & BWRs.
  Buccess of program depends on industry response. Supports formation of owners groups to provide necessary info.
  DENTON.H.R. Office of Nuclear Roacter Regulation. 79/10/17. 3pp.
- 7912120179 Notification of 791129 site insp of proposed barge landing in Braidria County, TX. FROELICH, R. W. Environmental Projects Branch 1. 79/11/06. App.
- 7912210188 Forwards "Containment Structures Design Rept.Revision 2" incorporating GE load definition info & documenting design change to containment dome.

  TURNER.E.A. Houston Lighting & Power Co. 79/12/20. ip.
- --7912210194 "Containment Structures Design Rept.Revision 2."

  \* Ebasco Services, Inc. (subs. of Enserch Corp.). 79/12/31.
- B. Utility Preliminary Safety Analysis Report, amends
- 7912210209 Forwards Amend 54 to PSAR. TURNER, E. A. Houston Lighting & Power Co. 79/12/20. ip.
- --7912210211 Amend 54 to PSAR.
  TURNER, E. A. Houston Lighting & Power Co. 79/12/11. 200pp.
- F. Security, medical, emergency & fire protection plans
- 7912070469 Notification of 791204 meeting w/utils in Bethesda.MD re NRC info requirements for emergency preparedness.Room change indicated.

  MOON.C.W. Light Water Reactors Branch 4. 79/11/16. 11pp.
- G. Adjudicatory correspondence
- 7912040002 Forwards intervenor TX PIRG fifth set of interrogatories. SCOTT, J. Texas Public Interest Research Group. 79/11/02. 10pp.
- 791214021B Discusses NRC ltr re possible Jan 1979 discussion W/representatives from Lowenstein Newman Rois. Axelrad & Toll. Confirms that discussion could have taken place during Feb 1979 rate procusading.

  SCOTT, J. Texas Public Interest Research Group. 79/11/06. 2pp.
- 79:2100338 Response to TX PIRO third set of interrogatories. TX Dept of Highways & Public Transportation hazardous matls regulations limited to certain ferries & to Baytown & La Porte tunnel. Certificate of Syc encl.
  LOWERRE.R. W. Texas. State of 79/11/07. App.
- 7912140168 Request for dismissal of intervenor TX PIRO due to repeated noncompliance re discovery requests. Intervenor did not resubmit answers to applicant first & second set of interrogatories. Certificate of Svc encl. CDPELAND, J. Q. Houston Lighting & Power Co. COPELAND, J. Q. Baker & Botts. 79/11/09. 19pp.
- --791214018B Response to third set of interrogatories. Submits info resale of conservation retrofits, sale of eletricity by applicant, passive solar technique & cost of passive retrofit. Certificate of Svc encl.

  JOHNSON, C. Texas Public Interest Research Group. 79/09/07. App.

- 7912140525 Motion to dismiss intervenors BA McCorkle & C Hinderstein from proceeding. Intervenors failed to comply w/ABLB 790827 & 1005 orders requesting complete answers to applicant interrogatories. Cartificate of Svc encl. COPELAND.J.O., NEWHAN.J.R. Howston Lighting & Power Co. COPELAND.J. G. Baker & Botts. 79/11/09. 11p.
- 7912120006 Answers to util third set of interrogatories re Contentions 9,10,14 & 17. Certificate of Svc encl. MCCORKLE, B. A. Affiliation Unknown. 79/11/13. App.
- 7912170246 Response to JF Doherty sixth set of interrogatories. Includes info on inboard sys leakage. closure of isolation valves in containment purge sys & PBAR Drawing 1.2-B. Affidavit & Certificate of Bvc encl. COPELAND, J. C., NEMMAN J. R. Houston Lighting & Power Co. COPELAND, J. O. Baker & Botts. 79/11/13. 7pp.
- 7912100471 Response in opposition to R Alexander 791018 petition to intervene. Petition untimaly w/o good cause astablished. Petitioner failed to establish intervest & to submit litigable contentions. Certificate of Svc ancl. NEHMAN, J. R., COPELAND, J. O. Houston Lighting & Power Co. NEHMAN, J. R. Lowenstein, Newman, Reis, Axelrad & Toll. 79/11/14. 9pp.
- 7912120478 Seeks denial of util 791109 request for dismissal of intervenor TX FIRO.No violations of rules or orders identified Speculation re motives cannot be basis for denial of due process rights. Certificate of Svc encl.

  8COTT, J. Texas Public Interest Research Group. 79/11/14. 16pp.
- 7912140193 Clarifies Jan & Feb 1979 telcons w/RM Lazo of ABLB re delay in issuance of ABLB order reflecting results of Nov 1978 prehearing conference.

  NEWHAN J. R. Lowenstein, Newman, Reis, Axelrad & Toll, 79/11/14. 2pp.
- 7912190104 Clarifies exchange of correspondence among Scott, ASLB & law firm from Jan 1979 through present. Two telcons w/RM Laib in Jan & Feb 1979 did not deal w/substance of matter currently before ASLB & are not within NRC ex parts ruls.

  NEHMAN, J. R. Lowenstein, Newman, Reis, Axelrad & Toll. 79/11/14. 2pp.
- 7912060078 Order granting parties 45 days from 791022 to complete discovery re previously admitted contentions. Orants 120 days from same date re stipulated contentions. M Warner & Individuals permitted to make Ilmited appearance may appeal. HDLFE.S.J. Atomic Bafety and Licensing Board Fenel. 79/11/19.
- 7912060212 Order notifying JH Kamras of ABLB 790824 order denying 790620 petition to intervene. Order in question not served on petitioner. May be appealed within 10 days of present avc. WOLFE.S. J. Atomic Bafety and Licensing Board Panel. 79/11/19. 1p.
- --7912060220 Order denying JH Kamras 790824 petition to intervene. Petition untimely. Contention speculative. Certificate of Svc encl.

  MOLFE. S. J. Atomic Safety and Licensing Board Panel. 79/06/20.
- 77:2:190:192 Forwards all documents requested in 79:0:30 ltr except list of research info ltrs. Requests that documents relevant to proceeding issues be identified. W/o encl. SOHINKI.S.M. Hearing Branch 3. 79/11/19. 1p.
- 7712050223 Order denying R Alexander 791018 petition to intervane. Limited appearance may be made Order may be appealed to ABLAB within 10 days from svc. MOLFE, S. J. Atomic Safety and Licensing Appeal Panel. 79/11/20. 2pp.
- 7912050198 Requests new updated copies of environ rept & PBAR. HOLFE.B. J. Atomic Bafety and Licensing Board Panel. 79/11/21. 1p.
- 7912120056 Requests to reply to intervenor TX PIRO 791114 response to applicant 791107 motion to dismiss intervenor from proceeding. Seeks opportunity to address new contradictory factual assertions.

  COPELAND, J. O. Houston Lighting & Power Co. COPELAND, J. G. Baker & Botts. 79/11/21. 2pp.
- ---7912120067 Reply to intervenor TX PIRG 791114 brief re applicant 791109 motion to dismiss intervenor Intervenor disregarded NRC 790712 order re identification of witness to enswer interrogatories, Certificate of Byc encl. COPELAND, J. 9. Houston Lighting & Power Co. COPELAND, J. 0. Baker & Botts. 79/11/21. 3pp.
- 7912140032 Forwards corrected Page 2 of applicant 791121 reply to TX PIRO brief in response to licensee motion to dismiss. COPELAND, J. O. Houston Lighting & Power Co. 79/11/26. 2pp.

- 7912170035 Response in opposition to Houston Lighting & Power 791121 mation & answer to TX PIRG reply remation for intervenor dismissal. Clarifies position on Doherty responses to util interrogatories. Except of TX PIRG answers encl. SCOTT. J. Texas Public Interest Research Group. 79/11/26. Bpp.
- 7912170046 Response to fifth set of interrogatories Answers Interrogatories 1-31 Certificate of Svc encl. COPELAND, J. G. Houston Lighting & Power Co. COPELAND, J. O. Baker & Botts. 79/11/26. 20pp.
- 7912050132 Discusses request from PA Polasek-Rhodes to intervene. Since no requirements fulfilled to intervene, ltr being treated as request to make limited appearance statement. NRC has no objection to making of such statement.

  SOHINKI, S. M. Hearing Branch 3. 79/11/27. 2pp.
- 7912190072 Notifies that applicant believes ASLB should treat undated ltr from PA Polasek-Rhodes as request to make limited appearance statement. Document is untimely for petition to intervene, gives no contentions & fails interest requirement. NEWHAN, J. R. Lowenstein, Newman, Reis, Azelrad & Toll. 79/11/28. Spp.
- 7912100479 Response in opposition to applicant 791109 motion to dismiss BA McCorkle & C Hinderstein as parties for failure to respond to interrogatories. Untimeliness of McCorkle filling has not prejudiced applicant. Supports Hinderstein dismissal. SOHINKI.S. M. Hearing Branch 3. 79/11/29. 1p.
- --79121004B2 Response in opposition to applicant 791109 motion requesting dismissal of TX PIRO Although atty-client privilege wrongly invoked. TX PIRO should be given opportunity to provide basis for contention re experts. W/Certificate of Svc. BOHINKI, S. M. Hearing Branch 3. 79/11/29. Opp.
- 7912180227 Notice of appeal of SJ Wolfe 791119 order denying full party status in plan CP proceedings.Requests extention to file detailed brief. MUELLER,E.F. Affiliation Unknown. 79/11/29. 2pp.
- 7912100357 Requests clarification of ASLB 791119 order re stipulated & withdrawn contentions by JF Dohorty. Differences between order & transcript refs re number of withdrawn contentions should be defined.

  MOODHEAD, C. F. Hearing Branch 3. 79/11/30. 2pp.
- 7912140005 Response to intervenor JF Doherty seventh request for documents. Bubmits list of available & unavailable documents. Certificate of Svc ancl. COPELAND, J. G. Houston Lighting & Power Co. COPELAND, J. G. Baker & Batts. 79/11/30. 5pp.
- 7912130054 Requests order to comps! NRC to answer 790525,0606.0717 & 0731 interrugatories.
  DHERTY, J. F. Affiliation Unknown. 79/12/03. lp.
- 7912140055 Order granting extension until 791213 for EE Miller to file supplemental brief re ASLB 791119 order treating Miller 790710 petition as request to make limited appearance statement, rather than as petition to intervene.

  BISHOP, C. J. Atomic Safety and Licensing Appeal Panel. 79/12/03.
- 7912170001 Requests extension until 800127 for discovery re Contentions 3 & 5-9.NRC has not responded to intervenor interrogatories. Extension would cause no delay in licensing process due to licensing moratorium. Certificate of 8vc encl. DDHERTY, J. F. Affiliation Unknown. 79/12/03. 2pp.
- 7912170002 Contention 45 re need for add1 lateral support in reactor core. Contention untimely due to delayed availability of NUREO/CR-1018. Cortificate of Svc encl. DDHERTY, J. F. Affiliation Unknown. 79/12/03. 2pp.
- 7912310195 Response to applicant motion to dismiss. Intervenor has responded to all interrogatories. Cartificate of Svc encl. MCCORKLE, B. A. Affiliation Unknown. 79/12/03. 2pp.
- 7912120381 Order granting 30 add1 days for applicant to complete discovery on TX PIRO contentions. Applicant & TX PIRO shall confer informelly to communicate problems. WOLFE.B. J. Atomic Safety and Licensing Board Panel. 79/12/04. Spp.
- 7912120385 Order deferring ruling on applicant 791109 motion to discuss intervenors BA McCorkle & C Hinderstein Directs intervenors to answer certain questions by 791217. ASLB will rule upon applicant motion after 791217.

  WOLFE B. J. Atomic Safety and Licensing Board Panel. 79/12/04. Spp.

- 7912140008 Response to intervenor JF Doherty seventh set of interrogatories. Answers Interrogatories 7-1 through 7-9. Certificate of Svc encl. CCPELAND. J. G. Houston Lighting & Power Co. CCPELAND. J. G. Baker & Botts. 79712/04. 10pp.
- 7912280631 Notice of appeal of ASLB 791119 order denying 8A Doggett 790717 petition to intervene Alleges defects in FR 790612 supplemental notice of intervention procedures. DBGGETT.S. A. Affiliation Unknown. DGGGETT.S. A. Doggett, S. A. 79/12/04. 2pp.
- 7912310168 Requests extension for filing notices of appeals & supporting briefs for DD Weaver,PL Streilen & K Otto.
  Certificate of Svc encl.
  DDGETT,S.A. Affiliation Unknown. DGGETT,S.A. Doggett, S.A.
  79/12/04. 4pp.
- --7912310170 Notice of appeal of PL Streilen ASLB 791119 order ruling that PL Streilen 790617 ltr be treated as request to make limited appearance statement rather than as request to intervene Alleges denial of due process & fair notice. DEGETT.S.A. Affiliation Unknown. DEGETT.S.A. Doggett. S.A. 79/12/04. 1p.
- --7912310178 Notice of appeal of K Dtto to ASLB 791119 order ruling that K Otto 790718 & 0913 ltrs be treated as requests to make limited appearance statement rather than as request to intervene. Asserts denial of due process & notice. DUGGETT.S.A. Affiliation Unknown. DUGGETT.S.A. Doggett. S.A. 79/12/04. 1p.
- --7912310183 Notice of appeal fo DD Weaver, based on denial of due process & fair notice of ASLS 791119 order roling DD Weaver 790717
  Ith be treated as request to make limited appearance statement rather than as request to intervens.

  DEGETT, S. A. Affiliation Unknown. DEGETT, S. A. Doggett, S. A. 79/12/04. 2pp.
- 79:2140091 Sixth set of interrogatories Requests info re power plant const to determine how much power conservation will obviate facility.

  JOHNSON, C. Texas Public Interest Research Group. 79/12/05. 2pp.
- 7912140179 Ack receipt of NRC 791120 response to applicant request for dismissal of intervenor TX PIRO. No objection to granting extension to TX PIRO. Intervenor McCorkle should be dismissed due to failure to answer interrogatories.

  NEWMAN. J. R. Lowenstein. Newman. Reis. Axelred & Toll. 79/12/05. 3pp.
- 7912180170 Requests that util be compelled to respond to Interrogatory 10 of intervenor fifth set of interrogatories. Answer needed to determine correct position re Contention 7. Certificate of Syc encl.

  SCOTT, J. M., JOHNSON, C. Texas Public Interest Research Group.
  79/12/05. 6pp.
- 7912170207 Response to first set of interrogatories, Submits info re ATMB, recirculation pump, role of costs in safety div & evaluation of SWRs. Prof qualifications fo CW Moon, ML Brooks & AC Thadani encl.

  SDHINKI, S. M. Hearing Branch 3. 79/12/06. 24pp.
- --7912170208 Response to second set of interrogatories Bubmits info re combustible gas control systradiolytic generation of hydrogen & breaks in ECCS.Prof qualifications of JA Kudrick NB Fields encl. SOHINKI.S.M. Hearing Branch 3. 79/12/06, 9pp.
- --79:2170212 Response to 790717 set of interrogatories. Submits info ro publication of insp results void collapse during overpressure transient rod control & info sys & location of drywell containment breakers. SOHINKI S. M. Hearing Branch 3. 79/12/06. 6pp.
- ~-7912170215 Response to fifth set of interrogatories. Submits info recost/benefit of const crossing at Allens Creek & use of high flux signal rather than high pressure signal for initiating reactor screen.
  SOHINKI.S.M. Hearing Branch 3, 79/12/06. 3pp.
- --7912170221 Response to sixth set of interrogatories. Submits info re witness for effect of pool swell on safety features, safety design of suppression pool & computer codes for predicting containment pressure. SORINKI.S.M. Hearing Branch 3, 79/12/06, 7pp.
- --7912170225 Response to seventh set of interrogatories. Answers: Interrogatories 1-3 & 5.8W Proplich & CW Wood affidavite & . Certificate of Svc oncl. SOHINKI.S.M. Hearing Branch 3. 79/12/06. Bpp.

- 7912140081 Errata to response to NRC second set of interrogatories.
  Page 1/Request 1/Line 13 should road "five 1b" rather than
  "five tons."
  JCHNEON.C. Texas Public Interest Research Group. 79/12/07. ip.
- 7912270053 Notifies that environ rept & PSAR have been forwarded under separate cover in response to 791121 request.
  BIDDLE.C.T. Baker & Botts. 79/12/07. ip.
- 7912170165 Opposes intervenor JF Deherty 791203 request that ASLB compel additesponses by NRC to intervener discovery requests. NRC responded to all outstanding interrogatories on 791206. Certificate of Svc encl.
  SOMINKI
- 7712170173 Discusses reaction to intervenor 771203 motion to compel discovery.NRC has responded beyond legal obligation. Motion violates understanding between parties. Requests listing of nexus between eighth set of interrogatories & contentions. BGHINKI.B.M. Hearing Granch 3. 77/12/10. 2pp.
- 7912260286 Response in opposition to intervenor JF Doherty 791203 motion requesting extension of discovery period until 800127. Intervenor failed to demonstrate good cause. Certificate of 8vc encl. NEWAN, J. R., COPELAND, J. G. Houston Lighting & Power Co. NEWAN, J. R. Lowenstein, Newman, Reis, Axelrad & Toll. 79/12/11. 6pp.
- 7912190502 Ack receipt of ninth set of interrogatories. Addendum identifying relation to contentions requested. Time will be computed from date of receipt.
  SOHINKI, S. H. Hearing Branch 3. 79/12/14. lp.
- 7912190523 Ack receipt of intervenor sixth, seventh & eighth requests for production of documents. Will be available for insp & copying in NRC PDR. Dethesda.Md. oxcept for Reed rept. SOHINAI.S. M. Hearing Branch 3. 79/12/14. 2pp.
- 7912260266 Responce in opposition to JF Doherty 791203 motion requesting extension of discovery until 800127. Intervenor alleged justifications re need for followup interrogatories unavailing & w/o merit W/Certificate of Svc. SOHINKI.S.M. Hearing Branch 3. 79/12/17. Spp.
- 7912280655 Order denying PA Polasek-Rhodes 791114 untimely patition to intervene. Request may be treated as petition to make limited appearance statement. PA Polasek-Rhodes may appeal within 10 days.

  WOLFE, S. J. Atomic Safety and Licensing Board Panel. 79/12/19. 2pp.
- 7912280662 Orders extension until R00127 for J Doherty to serve interrogatories on NRC. Interrogatories must be generated from NRC 791206 responses to four sets of interrogatories re Doherty Contentions 3 & 5-9.

  WOLFE, B. J. Atomic Safety and Licensing Board Panel. 79/12/19. 3pp.
- 7912280668 Order granting extension until 800104 for R Alexander to file supplemental brief in support of appeal.
  BISHOP.C.J. Atomic Safety and Licensing Appeal Panel. 79/12/18. 2pp.
- 7912310135 Response in apposition to UF Doharty Contention 45 re nawd for add1 lateral support in reactor core. Intervenor misread NUREG/CR-1018 by relying on analysis & recommendations relating solely to PMRs. Certificate of Svc enci. SDHINKI.S.M. Hearing Branch 3. 79/12/20, 4pp.
- BOCKET 50-467 ALLENS CREEK NUCLEAR STATION, UNIT 2 G. Adjudicatory correspondence
- 7912190104 Clarifies exchange of correspondence among Scott, ABLB & law firm from Jan 1979 through present. Two telcons w/RM Lazo in Jan & Feb 1979 did not deal w/substance of matter currently before ASLB & are not within NRC ex parte rule.

  NESMAN, J. R. Lowenstein, Newman, Reis, Axelrad & Toll. 79/11/14. 2pp.
- DDCKET 50-471 PILORIM NUCLEAR POWER STATION, UNIT 2

  A. Application/construction stage documents & correspondence
- 7911280153 Discusses mods to NRC position re status & applicability of TMI-2 accident review & NUREQ-C878 to facilities under const Forwards addl info to be considered in development of final plant design & procedures, VASSALLO, D.B. Division of Project Management. 79/10/10. 4pp.

- 7912110264 Discusses NRC plans to use generic analyses to devolop early verification program to resulve ATMS issue for PMRs & BMRs. Success of program depends on industry response. Supports formation of numers groups to provide necessary info.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912070004 Requests distribution of entl memorandum to board notification lists.
  VAROA.S.A. Assistant Director for Light Water Reactors. 79/11/08.
- 7912200156 Forwards info needed to complete review of breakwater, including design basis for changing configuration.

  BIVINS, H. S. Hydrology Meteorology Branch. 79/12/04. 3pp.
- 7912270144 Forwards util response, w/o attachments, to 791026 notice of violation & of proposed imposition of civil penalties, in response to State of MA 791126 request. Attachments withheld (ref 10CFR2, 790), H/o encl.

  STELLOV. Office of Inspection & Enforcement, Office of the Director. 79/12/07. ip.
- F. Security, medical, emergency & fire protection plans
- 7912070469 Notification of 791204 meeting w/utils in Dethesda.MD re NRC info requirements for emergency preparedness. Room change indicated. MDDN-C.W. Light Water Reactors Branch 4. 79/11/16. 11pp.
- O. Adjudicatory correspondence
- 7912070142 Forwards proposed findings of fact & conclusions of law in form of partial initial decision. BURT.L. Massachusetts, State of. 79/11/05. Ip.
- --7912070146 Forwards proposed findings of fact & conclusions of law in form of partial initial decision Certificate of Svc encl. BURT.L. Massachusetts, State of. 79/11/05. 3pp.
- --7912070152 Proposed findings of fact & conclusions of law in form of partial initial decision. Applicants Pinancially unqualified & technically incommpetent Environ review inadequate. Site suitability will be decided after hearings.

  DURT, L., WRIGHT, F. S., MEYER, M. Massachusetts, Btate of. 79/11/05. 136pp.
- --7912070186 Proposed findings of fact & conclusions of law corresponding to applicants' request for LWA Need for facility not established under principles of substitution theory.

  8 Massachusetts, Blate of. 79/11/05. 22pp.
- 7912110276 Discusses applicant 791101 transmittal of four documents on revolving credit agreement. If introduced as evidence. State of MA reserves right to crose-examine rebuttal testimony.
  BURT, L. Massachusetts, State of. 79/11/08. 1p.
- 7912180459 Informs of minor change in schedule for requests for findings of fact & conclusions of law. Possibility exists of stipulation between NRC intervenor MA Wildlife Federation & applicant.
  HERRMANN, H. Herrmann, H. 79/11/12. 2pp.
- 7712110124 Proposed findings of fact & conclusions of law in form of partial initial decision. Adopts applicants' Finding 685 subj to further findings on theft & sabotage. Concurs w/ applicant's proposed order. Certificate of Svc encl. BMITH. B. H. Hearing Branch 2. 79/11/20. 144pp.
- 7912190154 Notifies that 791119 meeting w/MA Wildlife Federation & NRC will be reschaduled either 791123 or filing date for MA Wildlife Federation pleadings moved to 791130. STOUDLEY.D.O. Buston Edison Co. 79/11720. ip.
- 7912100337 Notice of withdrawal from proceeding effective 791130.8H Lewis should be added to svc lists.Certificate of Svc encl. BMITH.B.H. Hearing Branch 2. 79/11/29. 3pp.
- 7912120358 Objects to ASL8 780714 order in lieu of requests for findings of fact & conclusions of law Application of App 1 to proceeding violates procedural & substantive rights. Centificate of Svc enci.
  HERRMANN.H. Massachusetts Wildlife Federation. 79/11/30. Spp.
- 7912210100 Reply in opposition to intervenor State of MA 791105 proposed findings of fact & conclusions of law Number of conceptual legal & factual errors prevade certain findings on applicant financial qualifications & other issues. LEWALD, O. H., STOODLEY, D. G. Boston Edison Co. LEWALD, O. H. Ropes & Gray. 79/12/05. 93pp.

- G. Inspection reports. IE Bulletins & correspondence
- 7912260045 Responds to 790913 request for addl info needed to complete review of util response to IE Bulletin 70-10 re Bergen-Patterson hydraulic shack suppressor accumulator spring coils. Safety-related hydraulic snubbers inspected in 1979. ANDDONINI.G. C. Boston Edison Co. 79/10/29. 2pp.

## DOCKET STN-50-477 ATLANTIC GENERATING STATION, UNIT 1

- A. Application/construction stage documents & correspondence
- 7912100022 Discusses issuance of Amend 17 to License DPR-64, which authorized operation at 100% power. Max allowable fee already paid by util. No addi fee required. MILLER, M. D. License Fee Management Branch. 79/11/13. lp.
- --7912100043 Forwards assessment of review costs for CP & OL actions, to aid in fee determination. W/o encl. BERKOW, H. N. Office of Nuclear Reactor Regulation. 79/10/30. 1p.
- DOCKET STN-50-478 ATLANTIC GENERATING STATION, UNIT 2

  A. Application/construction stage documents & correspondence
- 7912100032 Discusses issuance of Amend 17 to License DPR-64, which authorized operation at 100% power. Max allowable fee already paid by util No addl fee required.
  MILLER, W. O. License Fee Management Branch. 79/11/13. 1p.
- --7912100043 Forwards assessment of review costs for CP & OL actions, to aid in fee determination. W/o encl.
  BERKOW, H. N. Office of Nuclear Reactor Regulation. 79/10/30. 1p.
- DUCKET STN-50-482 WOLF CREEK GENERATING STATION
- A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATWB issue for PWRs & BWRs.
  Buccess of program depends on industry response. Supports formation of ouners groups to provide necessary infe.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.
- 7912270280 Advises that application for DL will be tendered on 790131, per 791211 telcon. KOESTER, G.L. Kansas Gos & Electric Co. 79/12/11. 1p.
- 7912280429 Forwards updated "QA Programs for Design & Cunst." PETRICK.N.A. Standardized Nuclear Unit Power Plant System. 79/12/20. 2pp.
- --7912280436 Updated "GA Programs for Design & Const." \* Standardized Nuclear Unit Power Plant System. 79/12/20. 225pp.
- F. Security, medical, emergency & fire protection plans
- 7912060562 Discusses investigation of use of ALBI duraspray fireproofing mati. No damage caused by duraspray mati. Tests & analyses of duraspray & potential alternate mati will continue.

  KOESTER.O.L. Kansas Gas & Electric Co. 79/09/11. 2pp.
- 7912040471 Forwards info re upgraded emergency plans to plants under const & DL review. Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Quide 1, 101.
  VASSALLO, D. D. Division of Project Management. 79/11/21. 4pp.
- 7912280449 Responds to NRC 771018 request for add1 info re SNUPPS fire protection sys. Detailed responses to requests will be included in FSAR revision. Clarification of sys description will show design in compliance w/NRC requirements. PETRICK N. A. Standardized Nuclear Unit Power Plant System. 79/12/20. ip.
- G. Adjudicatory correspondence
- 7912110393 Petition to intervene by Public Svc Commission of MD.
  Proposed amend adding KS Electric Power Cooperative as coumper of 17% interest will create conflict of purisdiction
  on rate base. Affidavit & Certificate of Svc encl.
  PHILLIPS,P.W., HEARNE,T.J. Missouri, State of. 79/10/23. Opp.

- 7912110043 Forwards comments on NUREG-0511. Draft GEIS reflects conscious & deliberate NRC policy to jeopardize public health & safety & thwart objectives of NEPA. KEPFORD.C. Environmental Coalition on Nuclear Power. 79/10/24. 22pp.
- 7912050321 Response to PSC of MO 791023 request to intervene as representative of state. Since no request for hearing filed no hearing appropriate. Certificate of Svc encl. SILBERG, J.E. Kansas Gas & Electric Co. SILBERG, J.E. Shaw, Pittman, Potts & Trowbridge. 79/11/07. Spp.
- 7912100475 Answer to MO Public Svc Commission 791023 petition for intervention. Ambiquity of petition re whether filed per "interested states" regulation or "intervenor" status should be clarified. Certificate of Svc encl. LENIG. S. H. Hearing Dranch 2. 79/11/13. 3pp.
- 7912050692 Order establishing ASLB to preside in proceeding ref Commission order published on 790924 in FR re proposed amend to CP. Appoints H Grossman as chairman.RF Cole & GD Bright as members. LAZO.R. M. Atomic Safety and Licensing Board Panel. 79/11/14. 2pp.
- 7912100355 Order directing petitioner MD Public Svc. Commission to file statement of agreement re cessation of proceedings to amend petition to intervene or submit memorandum in support of current petition.
  GNOSSMAN.H. Atomic Safety and Licensing Board Panel. 79/11/21.
- 7912270071 Responds to 790811 ltr requesting revocation of CP.Request denied. Suppl to be issued by 800131. List of other petitioners encl.
  STELLO.V. Office of Inspection & Enforcement, Office of the Director. 79/11/27. 3pp.
- 7912100336 Order granting add1 time for Commission to determine whether to review Director of JE 790712 decision denying petitions to suspend or revoke CP. Time extended until 20 days after issuance of director's supplemental decision.
  CHILK.S. J. Office of the Secretary of the Commission. 79/11/28. ip.
- 7912170083 Request by PSC of MO for extension until 791221 to respond to ASLB 791123 order to CP amend Order was received on 791203. Notice of appearance of TJ Hearne on behalf of PSC of MO, affidavit of TJ Hearne & Certificate of Svc encl. PHILLIPS.P.W., HEARNE,T.J. Missouri, State of. 79/12/03. Spp.
- O. Inspection reports, IE Bulletins & correspondence
- 7912190197 Responds to IE Bulletin 79-03 followup rept.Data developed on generic basis & considered applicable to all SNUPPS units.Fabrication & installation of Youngstown pipe spools will proceed w/all matl analyzed prior to use.
  PETRICK.N.A. Standardized Nuclear Unit Power Plant System.
  79/10/05. 3pp.
- ---7912190210 "Rept on Investigation of Weld Imperfections in ABME SA-312 Double Welded Austenitic Stainless Steel Pipe for Compliance WARC IE Bulletin 79-03."

  CANN.A.L., STANLEY,C., KDEPKE,W. Dechtel Corp. 79/08/09. 115pp.
- 7912060556 Responds to IE Bulletin 79-23 re potential failure of emergency diesel generator field exciter transformer.Problem not applicable to SNUPPS diesel generators. PETRICK.N.A. Standardized Nuclear Unit Power Plant System. 79/10/26. ip.
- 7912050463 Forwards IE Insp Rept 50-482/79-17 on 790917-20 & notice of violation.
  SEIDLE, W.C. Region 4, Dalles, Reactor Construction & Engineering Support Branch. 79/10/29. 2pp.
- ---7912050468 Notice of violation from insp on 790917-20.

  Region 4, Dallas, Office of the Director. 79/10/24. 1p.
- ---7912050473 IE Insp Rept 50-482/79-17 on 790917-20. Noncompliance noted: failure to follow procedures re reviewing qualifications of blasting specialist prior to commencement of blasting for UHS discharge structure foundation. CROSSHAN.M.A., OBERO.C.R. Region 4, Dallas, Office of the Director. 79/10/24. Spp.
- 7912180175 Submits generic response to IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Seismic analysis input info conforms to actual as-built configuration of safety-related sys. PETRICK.N.A. Standardized Nuclear Unit Power Plant System. 79/11/01. 71pp.

- 7912100261 Forwards 16 Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. SEYFRIT.K.V. Region 4. Dallas, Office of the Director. 79/11/16. ip.
- 7912110533 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required.
  SEYFRIT.K.V. Region 4. Dallas, Office of the Director. 79/11/16.
- 7912110281 Forwards IE Circular 79-23. "Motor Starters & Contactors Failed to Operate." No response required. SEYPRIT.K.V. Region 4. Dallas, Office of the Director. 79/11/26.
- 7912110480 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sent by NRC to licensees.

  SEYFRIT, K. V. Region 4. Dallas, Office of the Director. 79/11/26.
- 7912190050 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BMRs." No written response required.

  SEYFRIT.K. V. Region 4, Dallas. Office of the Director. 79/11/26.

  1p.
- 7912190180 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation."
  No written response required.
  SEYFRIT.K.V. Region 4, Dallas, Office of the Director. 79/11/30.
  ip.
- 7912310264 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21," No action required, SEYRIT, M. V. Region 4, Dellas, Office of the Director. 79/12/06.
- 7912200215 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. SEYFRIT.K.V. Region 4, Dallas, Office of the Director. 79/12/07.
- 7712280586 Forwards IE Info Notice 77-31, "Use of Incorrect Amplified Response Spectra." No written response required.
  SEYFRIT.K.V. Region 4. Dallas. Office of the Director. 79/12/13.
- S. Reportable occurrences, LERs & related correspondence
- 7912070140 Confirms 790824 notification to include Class II & III assemblies in investigation of potential deficiencies in piping assemblies furnished by Gulf & Western Energy Products Group.

  KDESTER.G.L. Kansas Gas & Electric Co. 79/09/11. 1p.
- 7912070174 Forwards final deficiency rept re concrete void in reactor bldg. KDEBTER, O. L. Kansas Gas & Electric Co. 79/09/25. ip.
- ---7912070175 Final deficiency rapt to 781213 concrets void beneath aquipment batch reactor bldg. Void repaired on 790709 by placing grant between new concrete & liner. \* Kansas Oas & Electric Co. 79/09/25. 4pp.
- 7912200429 PNS-IV-79-004: on 791008, Daniel Intl Corp switchboard operator received bomb threat call that Bomb was in main bldg. Bldg search conducted & no bomb found. Call traced to pay phone in LeRoy. KS. 08ERO, C., SEIDLE, M. Region 4, Dallas, Office of the Director. 79/10/09. 2pp.
- 7912200448 PNS-IV-79-005: on 791011, Daniel Intl Corp switchboard operator received bomb threat call re bomb in turbine bldg.
  Search revealed no bomb.
  OBERO.C. CROSSMAN.W. Region 4, Dallas, Office of the Director.
  79/10/11
- 7912120142 Ack receipt of 790928 ltr forwarding interim deficiency rept re qualification of control sys. CARLSON,R.T. Region 1. Philadelphia. Reactor Construction & Engineering Support Branch. 79/10/15. ip.
- ---7912120146 Forwards interim deficiency rept re qualification of controx sys. Supplemental rept in approx three months. PETRICK.N.A. Standardized Nuclear Unit Power Plant System. 79/10/15. 1p.

- 7912200454 PNS-IV-79-006: on 791016, Daniel Intl Corp switchboard operator received bomb threat call re bomb in control bldg.
  Evacuation & search of bldg conducted. No bomb found.
  DBEGG.C. CROSSMAN. H. Region 4. Dallas, Office of the Director.
  79/10/16. 1p.
- 7912200080 PNS-IV-79-007: on 791019, bomb threat received by Daniel Intl Corp from onsite extension 140. No bomb found in search of auxiliary bidg.
  TAPIA.J.I. CROSSHAN, W. Region 4, Dallas, Office of the Director. 79/10/19. 2pp.
- 7912200091 PNS-IV-79-008: on 791023. Daniel Intl Corp personnel trailer received bomb threat. Search conducted & no bomb found.

  STEMART.R., CROSSMAN.M. Region 4. Dallas, Office of the Director. 79/10/23. 1p.
- 7912200085 PNS-IV-79-009: on 791025, Daniel Intl Corp telephone switchboard operator received bomb threat Bearch conducted & no bomb found.

  OBERG.C., CROSSMAN.W. Region 4, Dailas, Office of the Director.
  79/10/25. 2pp.
- 7912210037 PNS-IV-79-011:on 791025, third book threat via telcon was received at 1:50 PM on 791025. Pipe fabrication shop received call from onsite extension. Shop evacuated. Search completed. No book found.

  OBERG.C., CROSSMAN.W. Region 4, Dallas, Office of the Director. 79/10/25. 1p.
- 7912260000 PNS-IV-79-010: on 791025, Daniel Intl Corp operator received second boab threat, Call came from extension within bidg.
  Search conducted w/negative results. Facility under const.
  OBERG.C.. CROSSMAN. M. Region 4. Dallas, Office of the Director.
  79/10/25. 2pp.
- 7912200560 PNS-IV-79-013:on 791114, Daniel Intl Corp switchboard operator received bomb threat call from site extension.
  Control bldg evacuated & search conducted, No bomb found,
  DBERG, C., CROSSMAN, M. Region 4, Dallas, Office of the Director.
  79/11/14. ip.
- 7912180119 PND-IV-79-15: on 791117. Daniel Intl GC lab technician accidentally hit by concrete truck during concrete placement. Technician taken to hosp & returned to site only to suffer from internal bleading. Readmitted to hosp.

  OBERG, C.R., CROBSHAN. M.A. Region 4, Dallas, Office of the Director. 79/11/19, 1p.
- 7912120395 Notifies of corrective action for potential deficiency re engineered sefety features actuation sys. Test sequence to detect failure will be incorporated into appropriate procedures. PETRICK, N. A. Standardized Nuclear Unit Power Plant System. 79/12/06. 1e.
- 7912280593 Discusses potential deficiency, per 791116 telcon to NRC.
  Westinghouse review reveals that dropped rod safety analysis
  deficiency may affect four addi loop plants. Further info
  will be provided by FBAR revision.
  PETRICK, N.A. Standardized Nuclear Unit Power Plant System.
  79/12/14. 2pp.

### DOCKET STN-50-483 CALLONAY PLANT, UNIT 1

- A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early varification program to resolve ATMS issue for PMRs & BMRs. Buccess of program depends on industry response. Supports formation of owners groups to provide necessary info. DENTON, M. R. Office of Nuclear Reactor Regulation, 79/10/17. Spp.
- 7912280429 Forwards updated "GA Programs for Design & Const." PETRICK.N.A. Btandardized Nuclear Unit Power Plant System. 79/12/20. 2pp.
- ---7912280436 Updated "QA Programs for Design & Const."

  \* Standardized Nuclear Unit Power Plant System. 79/12/20. 225pp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Res Sudde i 101, VABSALLO, D. B. Division of Project Management. 79/11/21, App.

3 - 360

- 7912280469 Responds to NRC 791018 request for add1 info re SMUPPS fire protection sys. Detailed responses to requests will be included in FSAR revision. Clarification of sys description will show design in compliance w/NRC requirements. PETRICK.N.A. Etandardized Nuclear Unit Power Plant System. 79/12/20. 1p.
- Adjudicatory correspondence
- 7912180206 Responds to 791128 inquiry re two kinds of licensing proceedings described in Atomic Energy Act Clarifies difference between Dt. & CP proceedings. WOODHEAD, C.P. Hearing Branch 3. 79/12/05. 1p.
- H. Ceneral correspondence
- 7912180535 Notifies of appointment of JF McLaughlin to position of Assistant to Vice President Nuclear. BRYAN, J. K. Union Electric Co. 79/12/11. 1p.
- Q. Inspection reports. IE Bulletins & correspondence
- 7912190197 Responds to IE Bulletin 79-03 followup rept. Data developed on generic basis & considered applicable to all SMMPPS units. Fabrication & installation of Youngstown pipe spools will proceed w/all math analyzed prior to use. PETRICK.N.A. Standardized Nuclear Unit Power Plant System. 79/10/05. 3pp.
- ---7912190210 "Rept on Investigation of Weld Imperfections in ABME 9A-312 Double Melded Austenitic Stainless Steel Pipe for Compliance W/NRC IE-Bulletin 79-03."

  CANN.A.L., STANLEY, C., KOEPKE, M. Bechtel Corp. 79/08/09. 115pp.
- 7912060556 Responds to IE Bulletin 79-23 re potential failure of emergency diesel generator field exciter transformer. Problem not applicable to SNUPPS diesel generators. PETRICK.N.A. Btandardized Nuclear Unit Power Plant System. 79/10/26. 1p.
- 7912180175 Submits generic response to IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Seismic analysis input info conforms to actual as-built configuration of safety-related sys. PETRICK.N.A. Standardized Nuclear Unit Power Plant System. 79/11/01. 7ipp.
- 7912210028 Forwards IE Insp Rept 50-483/79-11 on 791016-18.No noncompliance noted. FIGNELLI,O. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/11/09. 2pp.
- ---7912210033 IE Insp Rept 50-483/79-11 on 791016-10. No noncompliance noted Major areas inspected: activities re concrete placement & site.

  HANSEN, H.A., KNOP, R.C. Region 3, Chicago, Office of the Director. 79/11/07. Spp.
- 7912050184 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required.
  KEPPLER, J. O. Region 3. Chicago, Office of the Director. 79/11/16.
- 79/12/10/024B Forwards IE Info Notice 79-2B, "Overloading of Structural Elements Due to Pipe Bupport Loads." No response required.

  KEPPLER, J. 0. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912110592 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/16.
  ip.
- 7912050413 Forwards IE Bulletin 79-26, "Boron Loss From BWR Control Blades." No response required.

  MEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/20.
  1p.
- 7912100446 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BMRs." No written response required.

  KEPPLER, J. O. Region 3. Chicago. Office of the Director. 79/11/26.
- 7912140242 Forwards IE Circular 79-23. "Motor Starters & Contactors Failed to Operate." No written response required.
  KEPPLER, J. 9. Region 3, Chicago, Office of the Director. 79/11/26.

- 7912110444 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sent by NRC to licensees.

  KEPPLER, J. G. Region 3, Chicago, Diffice of the Director. 79/11/28.
- 7912190246 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." No written response required. KEPPLER.J.G. Region 3. Chicago, Office of the Director. 79/11/30.
- 79:2140104 Forwards 1E Info Notice 79-30. "Reporting of Defects & Noncompliances, iOCFR21." No action or response required.
  KEPPLER, J. O. Region 3. Chicago. Office of the Director. 79/12/06.
- 7912200148 Forwards IE Builetin 79-28, "Possible Malfunction of Namco Model EALBO Limit Switches at Elevated Temps." Action required. KEPPLER.J. G. Region 3. Chicago. Office of the Director. 79/12/10 Region 3. Chicago, Office of the Director. 79/12/10.
- S. Reportable occurrences, LERs & related correspondence
- 7912120142 Ack receipt of 790928 ltr forwarding interim deficiency rept re qualification of control sys. CARLSON.R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/10/15. 1p.
- --7912120146 Forwards interim deficiency rept re qualification of control sys. Supplemental rept in approx three months.

  PETRICK, N. A. Standardized Nuclear Unit Power Plant System.

  79/10/15. 1p.
- 791218037B PND-III-79-016: un 791012, Bechtol Pawer Corp received inquiry from ABC Television re embeds used in const of facility. Prevous investigation of stude to concrete weld problems concluded embed are sound & meet design & load requirements. HANSEN, W. A., KNOP, R. C., FIORELLI, C. Region 3, Chicago, Office of the Director. 79/10/15. ip.
- 7912070033 PNO-III-79-33: on 791101, employment discrimination claimed by W Smart because of allegations made re quality of const on previous job.Referred to Dept of Labor.
  KNOP.R.C., FIGRELLIO. Region 3, Chicago. Office of the Director.
  79/11/02. 1p.
- 7912180331 PNS-III-79-002: on 791115, telephonic bomb threat received by operator of Daniel Const Co. Call was traced to pay phone. Licensee conducting search of facility & surrounding area. CREED, J. R. Region 3, Chicago, Office of the Director. 79/11/15.
- 7912120395 Notifies of corrective action for potential deficiency re engineered safety features actuation sys. Yest sequence to detect failure will be incorporated into appropriate procedures. PETRICK.N.A. Standardized Nuclear Unit Power Plant System. 79/12/06. ip.
- 7912280593 Discusses potential deficiency, per 791116 telcon to NRC. Westinghouse review reveals that dropped rod safety analysis deficiency may affect four addl loop plants. Further info will be provided by FSAR revision.
  PETRICKY.N.A. Standardized Nuclear Unit Power Plant System.
  79/12/14. 2pp.

## DOCKET STN-50-484 TYRONE ENERGY PARK, UNIT 1

- G. Adjudicatory correspondence
- 7912110043 Forwards comments on NUREG-0511 Draft GEIG reflects conscious & deliberate NRC policy to jeopardize public health & safety & thwart objectives of NEPA.

  XEPFORD. C. Environmental Coalition on Nuclear Power. 79/10/24.

  22pp.
- DOCKET STN-50-485 STERLING POWER PROJECT NUCLEAR, UNIT 1
- A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATWB issue for PWRs & BWRs.
  Buccess of program depends on industry response. Supports formation of owners groups to provide necessary info.
  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.

- 7912280429 Forwards updated "GA Programs for Design & Const." PETRICK.N.A. Standardized Nuclear Unit Power Plant System. PETRICK, N. A. 5 79/12/20. 2pp.
- --7912280436 Updated "GA Programs for Design & Const." \* Standardized Nuclear Unit Power Plant System. 79/12/20. 225pp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review. Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Guide 1.101.

  VASSALLO, D. B. Division of Project Management. 79/11/21. Opp.
- 7912280469 Responds to NRC 791018 request for add1 info re SNUPPS first protection sys. Detailed responses to requests will be included in FBAR revision. Clarification of sys description will show design in compliance w/NRC requirements. PETRICK-N.A. Standardized Nuclear Unit Power Plant System. will show design FETRICK, N. A. 5 79/12/20. 1p.
- Adjudicatory correspondence
- 7912110043 Forwards comments on NUREG-0511 Draft GEIS reflects conscious & deliberate NRC policy to Jeopardize public health & safety & thwart objectives of NEPA.

  KEPFORD, C. Environmental Coalition on Nuclear Power. 79/10/24.
- Inspection reports, IE Bulletins & correspondence
- 7912190197 Responds to 1E Bulletin 79-03 followup rept.Data developed on generic basis & considered applicable to all SNUPPS units.Fabrication & installation of Youngstown pipe spools will proceed w/all matl analyzed prior to use. PETRICK,N.A. Standardized Nuclear Unit Power Plant System. 79/10/05. 3pp.
- --7912190210 "Rept on Investigation of Weld Imperfections in ASME 8A-312 Double Welded Austenitic Stainless Steel Pipe for Compliance W/NRC IE Bulletin 79-03." CAHN.A.L., STANLEY.C., KOEPKE,W. Bechtel Corp. 79/08/09. 115pp.
- 7912060556 Responds to IE Bulletin 79-23 re potential failure of emergency diesel generator field exciter transformer Problem not applicable to SNUPP5 diesel generators. PETRICK.N.A. Standardized Nuclear Unit Power Plant System. 79/10/26. 1p.
- 7912180175 Submits generic response to IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Seismic analysis input info conforms to actual as-built configuration of safety-related sys. PETRICK.N.A. Standardized Nuclear Unit Power Plant System. 79/11/01. 71pp.
- 7912050064 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required.
  ORIER, B.H. Rogion 1, Philadelphia, Office of the Director.
  79/11/16. ip.
- 7912050306 Forwards IE Info Notice 79-27, "Steam Generator Tube Ruptures at Two PWR Plants." No response required. GRIGR.B.H. Region 1, Philadelphia, Office of the Director, 79/11/16. ip.
- 7912100152 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads," No response required. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/11/16, 1p.
- 7912110478 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required. ORIER, B. H. Region 1. Philadelphia, Office of the Director.
- 7912050332 Forwards IE Bulletin 79-26, "Boron Loss From BWR Control Blades." No response required.
  ORIER, B. H. Region i. Philadelphia. Office of the Director.
  79/11/20, ip.
- 7912060597 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Broak Detection Equipment on BWRs." No response required.
  ORIER.B.H. Region 1, Philadelphia, Office of the Director.
  79/11/26. 1p.

- 7912110087 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. GRIER.B.H. Region i, Philadolphia, Office of the Director. 79/11/26. 1p.
- 7912190089 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Dus During Operation."
  No written response required.
  ORIER, B. H. Region i, Philadelphia, Office of the Director.
  79/11/30:
- 7912310252 Forwards IE Info Notice 79-30. "Reporting of Defects & Noncompliances, 10CFR21." No action required. ORIER.D.H. Region i. Philadelphia. Office of the Director. 79/12/06. 4pp.
- 7912190767 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EAi80 Limit Switches at Elevated Temps." Written response required. GRIER.B.H. Region 1, Philadelphia. Office of the Director. 79/12/07. 1p.
- 7912280246 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required. ORIER.B.H. Region 1, Philadelphia, Office of the Director. 79/12/13. 1p.
- 8. Reportable occurrences. LERs & related correspondence
- 7912120142 Ack receipt of 790928 ltr forwarding interim deficiency rept re qualification of control sys. GARLSON:R.T. Region i, Philadelphia, Reactor Construction & Engineering Support Branch. 79/10/15. 1p.
- ---7912120146 Forwards interim deficiency rept re qualification of control sys. Supplemental rept in approx three months.
  PETRICK N.A. Standardized Nuclear Unit Power Plant System.
  79/10/15. ip.
- 7912120395 Notifies of corrective action for potential deficiency re engineered safety features actuation sys. Test sequence to detect failure will be incorporated into appropriate procedures.
  PETRICK, N. A. Standardized Nuclear Unit Power Plant System.
  79/12/06. 1p.
- 7912280593 Discusses potential deficiency, per 791116 telcon to NRC. Westinghouse review reveals that dropped rod safety analysis deficiency may affect four addl loop plants. Further info will be provided by FBAR revision. PETRICK, N.A. Standardized Nucleor Unit Power Plant Bystem. 79/12/14. 2pp.

## DOCKET BTN-50-486 CALLOWAY PLANT, UNIT 2

- A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early varification program to resolve ATWB insue for PWRs & EWRs.
  Buccess of program depends on industry response. Bupports formation of owners groups to provide necessary info.
  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912280429 Forwards updated "GA Programs for Design & Const." PETRICK.N.A. Standardized Nuclear Unit Power Plant System. 79/12/20. 2pp.
- --79122B0436 Updated "QA Programs for Design & Const."
  \* Standardized Nuclear Unit Power Plant System. 79/12/20. 225pp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review Applicants required to make certain emergency arrangements w/state & local organizations & subsit emergency plans per Reg Ouide 1.101.
  VASSALLO,D.B. Division of Project Management. 79/11/21. 6pp.
- 79:2280469 Responds to NRC 79:018 request for addl info re SNUPPS fire protection sys. Detailed responses to requests will be included in FSAR revision. Clarification of sys description will show design in compliance w/NRC requirements. PETRICK: N. A. Standardized Nuclear Unit Power Plant System. 79/12/20. ip.

## G. Adjudicatory correspondence

- 7912180206 Responds to 79112B inquiry re two kinds of licensing praceedings described in Atomic Energy Act Clarifies difference between DL & CP proceedings. WODDHEAD, C.P. Hearing Branch 3. 79/12/05. 19.
- H. General correspondence
- 7912180535 Notifies of appointment of JF McLaughlin to position of Assistant to Vice President Nuclear.
  BRYAN, J. K. Union Electric Co. 79/12/11. 1p.
- Q. Inspection reports: IE Bulletins & correspondence
- 7912190197 Responds to IE Builetin 79-03, followup ropt. Data developed on generic basis & considered applicable to all SNUPPS units. Fabrication & installation of Youngstown pipe spools will proceed w/all matl analyzed prior to use. PETRICK, N. A. Standardized Nuclear Unit Power Plant System. 79/10/05. 3pp.
- --7912190210 "Rept on Investigation of Weld Imperfections in ASME BA-312 Double Welded Austenitic Stainless Steel Pipe for Compliance w/NRC IE Bulletin 79-03." CAHN.A.L. Bechtel Corp. 79/09/09. 115pp.
- 7912060556 Responds to IE Bulletin 79-23 re potential failure of emergency diesel generator field exciter transformer. Problem not applicable to SNUPPS diesel generators. PETRICK.N.A. Standardized Nuclear Unit Power Plant System. 79/10/26. ip.
- 7912180175 Submits generic response to IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Plping Sys." Seismic analysis input info conforms to actual as-built configuration of safety-related sys.
  PETRICK, N.A. Bkandardized Nuclear Unit Power Plant System.
  79/11/01. 7ipp.
- 7912050154 Forwards. IE Circular 79-22. "Stroke Times for Power Operated Relief Valves." No response required. KEPPLER, J. C. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912100248 Forwards IE Info Natice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. KEPPLER, J. Q. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912110592 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required.
  KEPPLER; J. O. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912050413 Forwards IE Bulletin 79-26. "Boron Loss From BWR Control Blades." No response required. KEPPLER, J. G. Region 3, Chicago. Office of the Director. 79/11/20.
- 7912100446 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No written response required.

  KEPPLER, J. Q. Region 3, Chicago, Office of the Director. 79/11/26.
- 7912140242 Forwards IE Circular 79-23, "Mutor Starters & Contactors Failed to Operate." No written response required.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/26.
- 7912110444 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sent by NRC to licensees.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/28.
- 7912190246 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation."
  No written response required.
  KEPPLER, J. 9. Region 3, Chicago, Diffice of the Director. 79/11/30.
- 7912140104 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 100FR21." No action or response required.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/12/04, in.

- 791220014B Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/12/10.
- 6. Reportable occurrences, LERs & related correspondence
- 7912120142 Act receipt of 790928 ltr forwarding interim deficiency rept re qualification of control sys. CARLSON.R.T. Region 1. Philadelphia, Reactor Construction & Engineering Support Branch. 79/10/15. lp.
- --7912120146 Forwards interim deficiency rept re qualification of control sys. Supplemental rept in approx three months. PETRICK.N.A. Standardized Nuclear Unit Power Plant System. 79/10/15. 1p.
- 7912180331 PNS-III-79-002; on 791115, telephonic bomb threat received by operator of Daniel Const Co. Call was traced to pay phone. Licensee conducting search of facility & surrounding area. CREED, J. R. Region 3, Chicago
- 7912120395 Notifies of corrective action for potential deficiency re engineered safety features actuation sys. Test sequence to detect failure will be incorporated into appropriate procedures. PETRICK, N. A. Standardized Nuclear Unit Power Plant Bystem. 79/12/06. 1p.
- 7912280993 Discusses potential deficiency, per 791116 telcon to NRC. Hestinghouse review reveals that dropped rod safety analysis deficiency may affect four addl loop plants. Further info will be provided by FBAR revision. PETRICK.N.A. Standardized Nuclear Unit Power Plant System. 79/12/14. 2pp.

## DOCKET STN-50-49B PERKINS NUCLEAR STATION: UNIT 1

- A. Application/construction stage documents & correspondence
- 7911280153 Discusses ands to NRC position restatus & applicability of TMI-2 accident review & NUREO-0578 to facilities under const. Forwards addl info to be considered in development of final plant design & procedures.

  VASSALLO, D. B. Division of Project Management. 79/10/10. 4pp.
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRs & BMRs. Buccess of program depends on industry responses Bupparts formation of owners groups to provide necessary info. DENTON.H.R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912070004 Requests distribution of encl memorandum to board notification lists.
  VAROA.S.A. Assistant Director for Light Water Reactors. 79/11/08.
- 7912270494 Estimates submittal date for FSAR for Cherotee 1 as Jan 1984. DAIL, L. C. Duke Power Co. 79/12/20. 1p.
- F. Security, medical, emergency & fire protection plans
- 7912070469 Notification of 791204 meeting w/utils in Bethesda, MD re NRC info requirements for emergency preparadness. Room change indicated. MDON, C.W. Light Water Reactors Branch 4. 79/11/16. 11pp.
- Q. Adjudicatory correspondence
- 7912180211 Forwards NRC Dept of Natural Resources & Community Development 791128 ltr clarifying ltr referenced in NRC alternative site testimony re condenser cooling. REIS, E. J. Hearing Branch 3. 79/12/05. ip.
- —7912180217 Clarifies 791019 ltr stating views on condenser cooling types. Can establish official position only in context of permit application & review process. State employee advice as no legal status under NC law. GRIGG, N. B. North Carolina, State of, 79/11/28. ip.

## I. Financial information

- 7912270377 Forwards duplicate copies of util 790321 guarantee of retrospective premiums, in response to NRC 791210 request. WHITLEY, H. D. Duke Power Cd. 79/12/20. ip.
- --7912270585 Requests approved guarantee of payment of deferred premiums for 1979.
  SALTIMAN.J. Antitrust & Indemnity Group. 79/12/10. 1p.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912060119 Forwards IE Info Notice 79-12A, "Attempted Damage to New Fuel Assemblies." No specific action or response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/11/09. 2pp.
- 7912100166 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. D'REILLY.J.P. Region 2. Atlanta, Office of the Director. 79/11/16. 1p.
- 7912110351 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/16. 2pp.
- 7912060607 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on SWRs." No response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/11/26. ip.
- 7912110140 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. O'RELLLYJ.P. Region 2, Atlanta, Office of the Director. 79/11/26. 1p.
- 7912190397 Forwards IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 79/11/30. ip.
- 7912310290 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action required. D'REILLY, J. P. Ragion 2, Atlanta, Office of the Director. 79/12/06. Spp.
- 7912200010 Forwards IE Bulletin 79-28, "Possible Maifunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. 0'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/12/07. 2pp.
- 7912280391 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required. O'RELLY,J.P. Region 2. Atlanta. Office of the Director. 79/12/13. 2pp.
- 7912280124 Forwards IE Circular 79-25, "Shock Arrestor Strut Assembly Interference." No written response required. O'REILLY,U.P. Region 2, Atlanta, Office of the Director. 79/12/20. 4pp.
- DOCKET STN-50-489 PERKINS NUCLEAR STATION, UNIT 2
- A. Application/construction stage documents & correspondence
- 7911280183 Discusses mods to NRC position re status & applicability of TMI-2 accident review & NUREO-0878 to facilities under const. Forwards add1 info to be considered in development of final plant design & procedures.

  VASSALLD.D.B. Division of Project Management. 79/10/10. App.
- 7712110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATWS issue for PMRs & BMRs. Success of program depends on industry response. Supports formation of owners groups to provide necessary info. DENIGN.H.R. Office of Nuclear Reactor Regulation. 79/10/17. Opp.
- 7912270496 Estimates submittal date for FSAR for Charokes 1 as Jan 1984. DAIL, L. C. Duke Power Co. 79/12/20. 1p.

## F. Security, medical, emergency & fire protection plans

7912070469 Notification of 791204 meeting w/utils in Bathesda, MD re NRG info requirements for amergency preparedness. Room change indicated. MCCN, C. W. Light Water Reactors Branch 4. 79/11/16. 11pp.

#### Q. Adjudicatory correspondence

- 7912180211 Forwards NRC Dept of Natural Resources & Community Development 791288 ltr clarifying ltr referenced in NRC alternative site testimony re condenser cooling. REIG.E.J. Hearing Branch 3. 79/12/05. lp.
- --7912180217 Clarifies 791019 ltr stating views on condenser cooling types. Can establish official position only in context of permit application & review process. State employee advice as no legal status under NC law.

  GRIGO, N. S. North Caroline, State of. 79/11/28, ip.

#### I. Financial information

- 7912270577 Forwards duplicate copies of util 790321 guarantee of retrospective premiums in response to NRC 791210 request. WHITLEY, H. D. Duke Power Co. 79/12/20. 1p.
- --7912270585 Requests approved guarantee of payment of deferred premiums for 1979.
  SALTZHAN, J. Antitrust & Indemnity Group, 79/12/10. ip.
- G. Inspection reports, IE Bulletins & correspondence
- 7912060119 Forwards IE Info Notice 79-12A, "Attempted Damage to New Fuel Assemblies." No specific action or response required.
  O'REILLY.J.P. Region 2. Atlanta, Office of the Director.
  79/11/09. 2pp.
- 7912100166 Forwards IE Info Notice 77-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/16. 1p.
- 7912110551 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/16. 2pp.
- 7912060607 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BHRs." No response required.
  0'REILLY, J. P. Region 2, Atlanta, Office of the Director.
  79/11/26. ip.
- 7912110140 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required.
  D'REILLY, J. P. Region 2, Atlanta, Office of the Director.
  79711/26, 1p.
- 7912190397 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation," No written response required. D'ARELLY,J.P. Region 2, Atlanta, Office of the Director. 79/11/30. ip.
- 7912310290 Forwards IE Info Notice 79-30, "Reporting of Defects to Noncompliances, 100FR21." No action required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 79/12/04. Spp.
- 7912200010 Forwards IE Bulletin 79-28, "Possible Halfunction of Namco-Model EA180 Limit Bwitches at Elevated Temps." Action required, O'REILLY,J.P. Region 2, Atlanta, Office of the Director. 79/12/07. 2pp.
- 7912280391 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Basctra." No written response required. D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/12/13, 2pp.
- 7912280124 Forwards IE Circular 79-25, "Shock Arrestor Strut Assembly Interference," No written response required. Office of the Director. 79/12/20. 4pp.

- DOCKET STN-50-490 PERKINS NUCLEAR STATION, UNIT 3
- A. Application/construction stage documents & correspondence
- 7911280153 Discusses mods to NRC position me status & applicability of TMI-2 accident review & NUREO-0378 to facilities under const. Forwards addl info to be considered in development of final plant design & procedures. VASSALLO, D. B. Division of Project Management. 79/10/10. 4pp.
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PHRs & BMRs.
  Success of program depends on industry response. Supports formation of owners groups to provide necessary info.
  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.
- 7912070004 Requests distribution of encl memorandum to board notification lists.
  VARQA-8. A. Assistant Director for Light Water Reactors. 79/11/08.
- 7912270496 Estimates submittal date for FBAR for Cherokee 1 as Jan 1984. DALL-L. C. Duks Power Co. 79/12/20. 1p.
- F. Security, medical, emergency & fire protection plans
- 7912070469 Notification of 791204 meeting w/utils in Bathesda, HD re NRC info requirements for emergency preparedness. Room change indicated. HDON.C.W. Light Water Reactors Branch 4. 79/11/16. 11oo.
- Q. Adjudicatory correspondence
- 7912180211 Forwards NRC Dept of Natural Resources & Community Development 791128 ltr clarifying itr referenced in NRC alternative site testimony recondenser cooling. REIN-E.J. Hearing Branch J. 79/12/05. ip.
- ---7912180217 Clarifies 791019 ltr stating views on condenser cooling types. Can establish official position only in context of permit application & review process. State employes advice as no legal status under NC 1aw.

  ORIOG.N. 8. North Carolina, State of. 79/11/28. 1p.
- I, Financial information
- 7912270577 Forwards duplicate copies of util 790321 guarantee of ratrospective premiums, in response to NRC 791210 request. WHITLEY, H. D. Duke Power Co. 79/12/20. ip.
- --7912270585 Requests approved guarantee of payment of deferred premiums for 1979.
  BALTZMAN, J. Antitrust & Indomnity Group. 79/12/10. 1p.
- G. Inspection reports. IE Bulletins & correspondence
- 7912060119 Forwards IE Info Notice 79-12A. "Attempted Damage to New Fuel Assemblies." No specific action or response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 79/11/09. 2pp.
- 7912100166 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. O'REILLY,J.P. Region 2, Atlanta, Office of the Director. 79/11/16. ip.
- 7912110551 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required.
  O'REILLLyJ.P. Region 2. Atlanta, Office of the Director.
  79/11/16. 2pp.
- 7912060607 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Datection Equipment on EMRs." No response required. O'REILLY.J. P. Region 2, Atlanta, Office of the Director. 79/11/26. 1p.
- 7912110140 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/26. 1p.

- 7912190397 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." No written response required. D'ARILLYJ.P. Region 2. Atlanta, Office of the Director. 79/11/30. 1p.
- 7912310270 Forwards IE Info Natice 79-30, "Reporting of Defects & Nuncompliances, 10CFR21." No action required. G'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/12/06. 5pp.
- 7912200010 Forwards IE Bulletin 79-28, "Passible Malfunction of Namco Nodel EA180 Limit Switches at Elevated Temps." Action required. 0'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/12/07. 2pp.
- 7912280391 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/12/13. 2pp.
- 7912280124 Forwards IE Circular 79-29, "Shock Arrestor Strut Assembly Interference." No written response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/12/20. 49p.
- DOCKET STN-50-491 CHEROKEE NUCLEAR STATION. UNIT 1
- A. Application/construction stage documents & correspondence
- 79:2110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATHS issue for PHRs & BHRs. Success of program depends on industry response. Supports foreaction of owners groups to pravide necessary info. DENTON.H.R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912270496 Estimates submittal date for FSAR for Cherokee i es Jan 1984. DAIL.L.C. Duke Power Co. 79/12/20. ip.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & DL review. Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Guide 1.101.
  VASSALLD, D. B. Division of Project Management. 79/11/21. App.
- G. Adjudicatory correspondence
- 7912110043 Forwards comments on NUREG-0511 Draft GEIS reflects conscious & deliberate NRC policy to Jeopardize public health & tafety & thwart objectives of NEPA.

  KEPFORD, C. Environmental Coalition on Nuclear Power. 79/10/24.
  2209.
- 7912060045 Requests correction of record to substitute RP Hilson, Assistant Atty General, SC Dept of Health & Environ Control, for Roberson.
  MILEON, R.P. South Carolina, State of. 79/11/16. lp.
- 1. Financial information
- 7912270577 Forwards duplicate copies of util 790321 guarantee of retrospective premiums.in response to NRC 791210 request. HHITLEY.H.D. Duke Power Co. 79/12/20. ip.
- --7912270585 Requests approved guarantee of payment of deferred premiums for 1979. SALTZMAN, J. Antitrust & Indemnity Group. 79/12/10. ip.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912060119 Forwards IE Info Notice 79-12A, "Attempted Damage to New Fuel Assumblies." No specific action or response required. O'RETLLY, J. P. Region 2. Atlanta, Diffice of the Director. 79/11/09. 2pp.
- 7912100166 Forwards IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads." No response required. O'RELLYJ.P. Region 2, Atlanta, Office of the Director. 79/11/16. lp.

- 7912110551 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/16. 2pp.
- 7912060607 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No response required.

  O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
  79/11/26. 1p.
- 7912110140 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/26. 1p.
- 7912130088 Ack receipt of IE Insp Repts 50-491/79-19,50-492/79-19 & 50-493/79-19 on 791023-26. No proprietary info.
  DAILLL.C. Duke Power Co. 79/11/29. ip.
- ---7912130093 Forwards IE Insp Repts 50-491/79-19,50-492/79-19 & 50-493/79-19 on 791023-26. No noncompliance noted. MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/11/19. 2pp.
- --7912130100 IE Insp Repts 50-491/79-19.50-492/79-19 & 50-493/79-19 on 791023-26. No noncompliance noted Major areas inspected: GA program implementation & rebar & containment plate placement.
  BRYANT, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. RAUSCH, J. K. Region 2, Atlanta, Office of the Director. 79/11/16. 4pp.
- 7912190397 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation."
  No written response required.
  O'REILLY, J. P. Region 2, Atlanta, Office of the Director,
  79/11/30. ip.
- 7912210135 Ack receipt of 791114 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-491/79-18, 50-492/79-18 & 50-493/79-18.

  HURPHY,C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/12/06. ip.
- --7912210145 Responds to NRC 791031 ltr re violations noted in IE Insa Repts 50-491/79-18.50-492/79-18 & 50-493/79-18. Corrective actions: const procedure CKP-8 revised re electrode stubs. Personnel involved have been instructed. DAIL-L. C. Duke Power Co. 79/11/16. ip.
- ---7912210152 Forwards IE Insp Repts 50-491/79-19.50-492/79-19 & 50-493/79-18 on 791009-12 & notice of violation.

  MURPHY. C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/10/31. 2pp.
- --7912210161 Notice of violation from insp on 791009-12.
  \* Region 3. Chicago. Office of the Director. 79/10/31. 1p.
- --7912210172 IE Insp Regts 50-471/79-18.50-492/79-18 & 50-493/79-18 on 791009-12. Noncompliance noted: failure to document welding surveillance & welding electrode stubs found in unmarked trash can. VAN DUDRN.P.K. Region 2. Atlanta. Office of the Director. HERDT.A.R. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 79/10/31. 4pp.
- 7912310290 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21," No action required. Of REILLY, J. P. Region 2. Atlanta, Office of the Director, 79/12/06, 5pp.
- 7912200010 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EAIBO Limit Buitches at Elevated Temps," Action required.

  D'REILLY, J.P. Region 2, Atlanta, Office of the Director.
  79/12/07. 2pp.
- 791228039: Forwards IE Info Notice 79-3:, "Use of Incorrect Amplified Response Spectra." No written response required.

  0/REILLY, U.P. Region 2, Atlanta, Office of the Director.

  79/12/13. 2pp.
- 7912280124 Forwards IE Circular 79-25: "Shock Arrestor Strut Assembly Interforence." No written response required.

  O'REILLY, J. P. Region 2. Atlants, Office of the Director.

  79/12/20. 4pp.

- DOCKET SYN-50-492 CHEROKEE NUCLEAR STATION, UNIT 2
- A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRs & BMRs.
  Success of program depends on industry response Supports formation of ouners groups to provide necessary info.
  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912270496 Estimates submittel data for FBAR for Charokee 1 as Jan 1784. DAIL-L.C. Duke Power Co. 79/12/20. 1p.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & DL review. Applicants required to make certain amergency arrengements w/state & local organizations & submit emergency plans per Reg Quide 1.101.

  VABBALLO, D. B. Division of Project Management. 79/11/21. 6pp.
- Q. Adjudicatory correspondence
- 7912110043 Forwards comments on NUREG-0311 Draft GEIS reflects conscious & deliberate NRC policy to jeopardize public health & safety & thwart objectives of NEPA. KEPFORD. C. Environmental Coalition on Nuclear Power. 79/10/24. 22pp.
- 7912060045 Requests correction of record to substitute RP Wilson, Assistant Atty General, SC Dept of Health & Environ Control, for Roberson.
  WILBON, R. P. Bouth Carolina, State of. 79/11/16. ip.
- I. Financial information
- 7912270577 Forwards duplicate copies of util 790321 guarantee of retrospective premiums in response to NRC 791210 request. WHITLEY, H. D. Duke Power Co. 79/12/20. ip.
- --7912270385 Requests approved guarantee of payment of deferred premiums for 1979. SALTZHAN.J. Antitrust & Indemnity Group. 79/12/10. 1p.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912060119 Forwards IE Info Notice 79-12A. "Attempted Damage to New Fuel Assemblies." No specific action or response required. O'REILLY, J. P. Region 2. Atlanta. Office of the Director. 79/11/09. 2pp.
- 7912100166 Forwards IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads." No response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 79/11/16. ip.
- 7912110551 Forwards IE Info Notice 79-29. "Loss of Nonsefety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required. O'RELLLY, J.P. Region 2. Atlanta, Office of the Director. 79/11/16. Epp.
- 7912060607 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on SWRs." No response required.

  0'REILLY, J. P. Region 2, Atlanta, Office of the Director.
  79/11/26, 1p.
- 7912110140 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Decrate." No response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/26, ip.
- 7912130088 Ack receipt of IE Insp Repts 50-491/79-19,50-492/79-19 & 50-493/79-19 on 791023-26. No proprietary info, DAIL, L. C. Duke Power Co. 79/11/29, 1p.
- --7912130093 Forwards IE Insp Repts 50-491/79-19,50-492/79-19 & 50-493/79-19 on 791023-26. No noncompliance noted. MURPHY.G.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/11/19. 2pp.

- --7912130100 IE Insp Repts 50-491/79-19,50-492/79-19 & 50-493/79-19 on 791023-26. No noncompliance noted, Major areas inspected: QA program implementation & rebar & containment plate placement.

  BRYANT, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. RAUSCH, J. K. Region 2, Atlanta, Office of the Director. 79/11/16. 4pp.
- 7912190397 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." No written response required. O'REILLY,J.P. Region 2, Atlanta, Office of the Director. 79/11/30. 1p.
- 7912210135 Ack receipt of 791116 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-491/79-18, 50-492/79-18 & 50-493/79-18. MURPHY.C.E. Region 2, Atlanta. Reactor Construction & Engineering Support Granch. 79/12/06. 1p.
- --7912210145 Responds to NRC 791031 ltr re violations noted in IE Insp Repts 50-491/79-18,50-492/79-18 & 50-493/79-18. Corrective actions: const procedure CRP-8 revised re electrode stubs. Personnel involved have been instructed. DAIL.L.C. Duke Power Co. 79/11/16. ip.
- --7712210152 Forwards IE Insp Repts 50-491/79-18, 50-492/79-18 & 50-493/79-18 on 791009-12 & notice of violation. MURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/10/31. 2pp.
- --7712210161 Notice of violation from insp on 791009-12.

  \* Region 3, Chicago, Office of the Director. 79/10/31. 1p.
- --7912210172 IE Insp Repts 50-491/79-18,50-492/79-18 & 50-493/79-19 on 791009-12. Noncompliance noted: failure to document welding surveillance & welding electrode stubs found in unmarked trash can.
  VAN DORN,P.K. Region 2, Atlanta, Office of the Director. HERDT,A.R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/10/31. 4pp.
- 7912310290 Forwards IE Info Notice 79-30, "Regorting of Defects & Noncompliances, 10CFR21." No action required.
  O'REILLY,J.P. Region 2, Atlanta, Office of the Director.
  79/12/06. 5pp.
- 7912200010 Forwards IE Bulletin 79-29, "Possible Malfunction of Namco Model Edi80 Limit Switches at Elevated Temps." Action required. 0'REILLY.J.P. Region 2. Atlanta. Office of the Director. 79/12/07. 2pp.
- 7912280391 Forwards IE Info Notice 79-31. "Use of Incorrect Amplified Response Spactra." No written response required. O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 79/12/13. 2pp.
- 7912280124 Forwards IE Circular 79-25, "Shock Arrestor Strut Assembly Interference." No written response required. O'REILLY.J.F. Region 2, Atlanta, Office of the Director. 79/12/20. 4pp.
- DOCKET STN-50-493 CHEROKEE NUCLEAR STATION, UNIT 3
- A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PNRs & BURS. Buccess of program depends on industry response. Bupports formation of owners groups to provide necessary info. DENTON:H.R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912270496 Estimates submittal date for FSAR for Cherokes 1 as Jan 1784. DAIL L. C. Duke Power Co. 79/12/20. 1p.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review. Applicants required to make certain emergency errangements wistate & local organizations & submit emergency plans per Reg Guide 1.101.

  VASBALLO, D. B. Division of Project Management. 79/11/21, App.

## Adjudicatory correspondence

12110043 Forwards comments on NUREO-0511. Draft QEIS reflects conscious & deliberate MRC policy to peopardize public health & safety & thwart objectives of NEPA. KEFFORD.C. Environmental Coalition on Nuclear Power. 79/10/24. 22pp.

12050045 Requests correction of record to substitute RP Hilson, Assistant Atty General,SC Dept of Health & Environ Control, for Roberson. WILSON.R.P. South Carolina, State of. 79/11/14. 1p.

#### Financial information

12270577 Forwards duplicate copies of util 790321 guarantee of retrospective premiums, in response to NRC 791210 request. HHITLEY, H. D. Dute Power Co. 79/12/20. 1p.

7912270585 Requests approved quarantee of baument of deferred premiums for 1979. BALTZMAN J. Antitrust & Indemnity Group, 79/12/10, 15.

Inspection reports, IE Bulletins & correspondence

1204D119 Forwards IE Info Notice 79-12A. "Attempted Damage to New Fuel Assemblies." No specific action or response required. O'REILLY.J.P. Region 2. Atlanta. Office of the Director. 79/11/09. 2pp.

t2100166 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/16. , 1p.

12110551 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required. Office of the Director. 078ELLYJ.P. Region 2. Atlanta. Office of the Director. 79/11/16. 2pp.

12060607 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BMRs." No response required. 0/REILLYJ.P. Region 2, Atlanta, Office of the Director. 79/11/26. 1p.

12110140 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/11/26. 1p.

12130088 Ack receipt of IE Insp Repts 50-491/79-19,50-492/79-19 & 50-493/79-19 on 791023-26.Ng proprietary info. DAIL.L.C. Duke Power Co. 79/11/29, ip.

7912130093 Forwards IE Insp Repts 50-491/79-19.50-492/79-19 & 50-493/79-19 on 791023-26.No noncompliance noted. HURRHY.C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/11/19. 2pp.

7912130100 IE Insp Repts 50-491/79-19, 50-492/79-19 & 50-492/79-19 on 791023-26. No noncompliance noted Major areas inspected: QA program implementation & rebar & containment plate placement.
BRYANT.J.C. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. RAUSCH.J.K. Region 2. Atlanta, Office of the Director. 79/11/16. 4pp.

12190397 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." No written response required. OFREILLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/30. 1p.

791116 ltr informing NRC of steps taken to f in IE Insp Repts 50-491/79-18.

tm. Reactor Construction & Engineering

tr re violations noted in IE Insp 50-493/79-18. Corrective ised re electrode stubs, ructed, 16. 1p.

- --7912210132 Forwards IE Insp Repts 30-491/79-18,50-492/79-18 & 30-493/79-18 on 791009-12 & notice of violation.
  MRPHY.C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/10/31. 2pp.
- --7912210161 Natice of violation from insp on 791009-12.

  Region 3, Chicago, Office of the Director. 79/10/31. ip.
- ---7912210172 IE Insp Repts 50-491/79-18,50-492/79-18 & 50-493/79-18 on 791009-12. Noncompliance noted: failure to ducument wolding surveillance & welding electrode stubs found in unmarked trash can.
  VAN DOORN.P.K. Region 2, Atlanta, Office of the Director.
  HERDT.A.R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/10/31. 4pp.
- 7912310290 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances,10CFR21." No action required.
  D'REILLY.J.P. Region 2. Atlanta, Office of the Director.
  77/12/06. 5pp.
- 7912200010 Forwards IE Bulletin 79-28. "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Teaps." Action required.
  O'REILLY, J. P. Region 2. Atlanta, Office of the Director, 79/12/07. 2pp.
- 7912280391 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required.

  O'REILLY.U.P. Region 2, Atlanta. Office of the Director.

  79/12/13. 2pp.
- 7912280124 Forwards IE Circular 79-25, "Bhock Arrestor Strut Assembly Interference." No written response required. D'REILLY, J.P. Region 2. Atlanta, Office of the Director. 79/12/20. 4pp.

## DOCKET 50-496 MONTAQUE NUCLEAR POWER STATION, UNIT 1

A. Application/construction stage documents & correspondence

7911280153 Discusses mode to NRC position re status & applicability of TMI-2 accident review & NUREO-0578 to facilities under const. Forwards addl info to be considered in development of final plant design & procedures. VASSALLO.D.B. Division of Project Management. 79/10/10. 4pp.

7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRs & BMRs. Success of program depends on industry response. Supports formation of owners groups to provide necessary info. DENYON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. Sep.

### DOCKET 50-497 MONTAGUE NUCLEAR POWER STATION, UNIT 2

A. Application/construction stage documents & correspondence

7911280153 Discusses mods to NRC position re-status & applicability of TMI-2 accident review & NUREQ-0578 to facilities under const. Forwards addl info to be considered in development of final plant design & procedures.

VASSALLO.D.B. Division of Project Management. 79/10/10. 4pp.

7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRs & BMRs. Success of program depends on industry response Supports forsation of owners groups to provide necessary info. DENTON, H.R. Office of Nuclear Reactor Regulation. 79/10/17. Sep.

DOCKET STN-50-498 BOUTH TEXAS PROJECT, UNIT 1

- A. Application/construction.stage documents & correspondence
- 7912060560 Confirms 790831 telcon re 790628 ltr concerning 790622 stop work order on placement of safety-related concrete. Util will resume placement of concrete in reactor containment bidg exterior shell walls.

  TURNER, E. A. Houston Lighting & Power Co. 79/08/31. 3pp...
- 7912110011 Forwards NRC position on status & applicability to pending OL applications of results of TMI followup actions Dutlines addl short-ture actions to be taken. VASSALLO.D.B. Division of Project Management. 79/09/27. 41pp.

- 7912110264 Discusses NRC plans to use generic analyses to develop early varification program to resolve ATMS issue for PMRs & BMRs.
  Buccess of program depends on industry response Supports formation of owners groups to provide necessary info.
  DENTON M.R. Office of Nuclear Reactor Regulation. 79/10/17. Gpp.
- 7912070361 Forwards Amend 6 to application for OL.
  TURNER, E. A. Houston Lighting & Fower Co. 79/12/05. 3pp.
- --7912070370 Amend 6 to application for OL, describing business & organization of applicants. BEC Forms 8-16 & 10-K. financial info & Annual Financial Rept 1978 encl.

  TURNER, E. A. Houston Lighting & Power Co. 79/12/05. 275pp.
- ---7912070375 Annual Financial Rept 1978.

   Houston Industries Inc. 78/12/31. 39pp.
- 7912180463 Forwards request for add1 info re initial testing to complete review of FBAR.
  PARR.O.D. Light Water Reactors Branch 3. 79/12/07. 17pp.
- 7912270369 Informs TX Historical Commission that naither historical nor prehistorical remains were found at proposed barge off-loading facility sits in Brazaria County.TX. Results of archaeological survey performed by Dames & Moore.

  MCGUIRE, M. F. Houston Lighting & Power Co. 79/12/17. 3pp.
- F. Bacurity, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & DL review Applicants required to make certain exergency arrangement. exists & local organizations & submit emergency p' or Reg Quide 1. [0].
  VABSALLO, D. B. D' of Project Hanagement. 79/11/21. App.
- 7912310089 Natification s. ime change for B00109 meeting w/util in Bethasda, MD to discuss review of security plan.
  LIGITRA, E. A. Light Water Reactors Branch 3. 79/12/10. 3pp.
- 9. Adjudicatory correspondence
- 7912050442 First set of interrogatories & requests for production of documents directed to intervenor Citizens for Equitable Utils. Requests identification of documents & info supporting alleged "field const error." Certificate of Svc encl. SCHMARZ, M. D., NEWMAN, J. R. Houston Lighting & Power Co. SCHMARZ, M. D., Baker & Botts. 79/11/05. 30pp.
- 7912030611 Interrogatories & requests for production of documents directed to Citizens for Equitable Utils Questions re alledged falsification of const records by util employees. Certificate of Svc encl. MCGURREN.H.J. Hearing Branch 1. 79/11/05. 14sp.
- --7912050615 Interrogatories & requests for production of documents directed to Citizens Concerned About Nuclear Power Includes questions re alleged falsification of const records by util suployees.

  MCOURREN.H.J. Hearing Branch 1. 79/11/05. 10pp.
- 7912130447 First set of interrogatories & request for insp & production of documents. Requests into re basis for Section 2.6 of FSAR, pook wind guests used for design & concrete bonding requirements. Certificate of Bvc encl.
  BUCHORN, P. Citizens for Equitable Utilities. BUCHORN, P. Citizens Concerned About Nuclear Power, Inc. 79/11/05, 10pp.
- 791R170384 Forwards add1 request for production of documents re Ban Antonio Express News 791111 article reporting that results of FBI inquiry were turned over to NRC. SINKIN.L.A. Citixens Concerned About Nuclear Power, Inc. 79/11/12.
- 7912190061 Forwards util 791120 ltr to NRC & encl. SCHMARZ.M.D. Baker & Botts. 79/11/28. 3pp.
- 7912180087 Requests capy of documents transmitted to Citizens Concerned About Nuclear Pawer per L Sinkin 791112 FOIA Request 79-493, re FBI investigation.
  MCOURREN.H.J. Hearing Branch 1. 79/12/11, ip.

- 7912280664 Responds to FOIA request for documents generated as result of investigation of South TX project by FBI Request forwarded to FBI for response.

  CARR. J. C. Bivision of Rules and Records. 79/12/17. 1p.
- M. Antitrust correspondence
- 7912060088 Discovery rept for Oct 1979. Corrected & signed City Public Svc Board depositions taken by DDJ & NRC. Produced add1 documents requested by DDJ during JB Poston deposition. Certificate of Svc encl.
  WILSON, N. R. Matthews, Nowlin, Macfarlane & Barrett. 79/11/05. App.
- 7912060247 Discovery rept for Oct 1979. Produced add1 documents to DOJ following RL Hancock, HL Peterson & E Rumael 791009 & 10 dapositions. Did not initiate discovery requests. Certificate of Svc enci.

  BALOUGH, R. C. Austin, TX. 79/11/05. 4pp.
- 7912190227 Forwards affidavits of RE Roundtree & LR Gawlik,general manager & associate general manager of Public Utils Board, Brownsvills, TX,
  JABLON, R. A. Spiegel & McDiarmid, 79/11/07, ip.
- ---7912190265 Affidavit by general manager of Public Utils Board of City of Brownsville. Ack that 790502 responses to Houston Lighting & Power first set of interrogatories & 790626 supplemental responses to same discovery have been reviewed. ROUNDTREE. R. E. Texas, State of. 79/09/14. 2pp.
- --7912190298 Affidavit by associate general manager of Public Utils Board, Brownsville, TX. Ack that 790302 responses to Houston Lighting & Power first est of interrogatories & 790826 supplemental responses to same discovery have been received. GAMLIK, L.R. Taxas, State of. 79/09/14. 2pp.
- ~~79:12:1903:9 Corrected & supplemental answers by Public Utile Board of City of Brownsville, TX in response to Houston Lighting & Power first set of interrogatories & first request for production of documents. Contains info re sale of power.

  \* Texas, State of, 79/11/07. App.
- 7912190241 Confirms 791106 conversation re intentions not to call J Smith, Cajun Cooperative, as witness at hearing. Deposition of J Smith will not be taken. Reserves right to depose J Smith at future date.

  BALDWIN, J. M. Baker & Botts. 79/11/07. 5pp.
- 7912140202 Advises that during Oct 1979, Bouth TX Electric Cooperative & Medina Electric Cooperative neither initiated nor received any discovery requests. Certificate of Syc ancl. JOHN, D. F. Akin, Gump, Hauer & Feld. 79/11/08. App.
- 7912050092 Petition for directed certification & review of ASLB 791005 order denying motions for summary decision. Urges collateral estoppel of Central & Bouth West Corp re issues previously decided in district court trial. Cartificate of Hvc encl. BARNETT, E. W. , BOUKNIGHT, J. A. Houston Lighting & Power Co. BARNETT, E. W. Baker & Botts, 79/11/09, 22pp.
- 7912050683 Third set of interrogatories & request for production of documents directed to TX Utils Generating Co.et al. Addresses purchase & sale of off-peak interruptible energy & transfer & exchange of electric energy Certificate of Syc encl. STAHL.D. Central Power & Light Co. STAHL.D. Isham, Lincoln & Beale. 79/11/09. Bpp.
- 7912060009 Ack receipt of 791107 Itr advising of Houston Lighting & Power assertion of work product privilege re Gerber scripts. MRC will file anotion to compel discovery.
  LEBBY, R. P. Antitrust Division. 79/11/09. ip.
- 7912100300 First set of interrogatories & request for production of documents, directed to City Public Svc Board of San Antonio. Addresses coal-fired economy energy purchase & sale & electric energy transfer & exchange. W/Certificate of Svc. STAML.D. Central Power & Light Co. 79/11/09. 7pp.
- 7912100307 Discovery rept for Oct 1979. Took deposition of HL Peterson. EC Rummel.RL Hancock.CT Herring & R Houler & TL Hatcher & H Tanner in conjunction w/NRC. Participated in Houston Lighting & Power & TX Utils joint depositions, W/Certificate of Svc. CYPHERT. B. B., PARAMETER.F. H., DOPSOVIG.D. A. Justice, Dept. of. 79/11/09, 7pp.
- 7912190140 Notifies that J Cambroll of Cajun Electric Power Coopenative has been designated potential witness in DOJ proceedings. Requests notification of Cambrells deposition rescheduling. LUGUE.N. Justice, Dept. of. 79/11/09. ip.

- 79:2100332 Notice of appearance in proceeding Certificate of Syc encl. LUGUE, N. Justice, Dept. of. 79/11/13. 4pp.
- 7912110270 Advises of postponement of H Hoodson deposition until later date, due to Houston Lighting & Power failure to make Hoodson working papers available for insp.
  BLUHE, M.B. Antitrust Division. 79/11/19. 1p.
- 7912130094 Notice of appearance of AP Hodgdon on behalf of NRC. Cortificate of Svc encl. HODGDAN.A.P. Antitrust Division. 79/11/20. 4pp.
- 7912060040 Application for subposense for deposition of J Qambrell & keeper of records of Cajun Electric Power Cooperative.
  Testimony will include transmission planning & fuel supply.
  Drafts of subposense & Certificate of Svc encl.
  FRANKLIN.M.J. Houston Lighting & Power Co. FRANKLIN.M.J. Baker & 79/11/21
- 7912130097 Request for espansion of ASLB 790323 protective order to include documents produced by Central & South West Corp & Central & South West Socs. Inc. to include confidential documents to amend order to bind TX Util companies.

  STAHL.D. Central & Southwest Corp. STAHL.D. Central & Southwest Services, Inc. STAHL.D. Central Power & Light Co. 79/11/21. 7p
- 7912130483 Notifies of AE Autry 791211 deposition in Corpus Christi.TX, MS Borchelt 791112 deposition in Abilene.TX.RW Hardy 791213 deposition in Abilene.TX & SB Philips 791217 deposition in Dallas.TX. Certificate of Svc encl. MCDIARMID.R.C. Brownsville.TX. MCDIARMID.R.C. Spiegel & McDiarmid. 79/11/26. 7pp.
- 7912130236 Third set of interrogatories & requests for production of documents directed to Houston Lighting & Power & TX Utils Generating Co. Includes questions on power flow between utils. Supporting documentation & Centificate of Svc encl. LESSY, R. P., CHANANIA, F. D., BLUME, M. B. Antitrust Division, 79/11/26.
- 7912130328 Notice of appearance of S Welling on behalf of Central & South West Corp.Central Power & Light Co.PSC of QK, Southwestern Electric Power Co & West TX Utils Co. WELLING.S. Isham, Lincoln & Beele. 79/11/26. 6pp.
- 7912120043 Third supplemental response to second set of interragatories & requests for production of documents from applicant.
  Certificate of Svc encl.
  CYPHERT.S.B., PARMENTER.F.B. Justice.Dept.of. 79/11/27. 9pp.
- 7912130337 Notice of Ti. Austin 791217 deposition in Dallas, TX.
  CARNEY, J. A. Central & Southwest Corp. CARNEY, J. A. Central Power &
  Light Co. CARNEY, J. A. Public Service Co. of Oklahoma. 79/11/27.
- ~~7912130361 Notice of BB Hulsey 791218 deposition in Dallas.TX. CARNEY, J.A. Central & Southwest Corp. CARNEY, J.A. Central Power & Light Co. CARNEY, J.A. Public Service Co. of Oklahoma. 79/11/27. ip.
- ---7912130366 Notice of PO Brittain 791218 deposition in Dallas.TX. CARNEY.J.A. Central & Southwest Corp. CARNEY.J.A. Central Power & Light Co. CARNEY.J.A. Public Service Co. of Oklahoms. 79/11/27. 1p.
- --7912130378 Notice of MD Spence 791219 deposition in Dallas.TX.
  Certificate of Svc encl.
  CARNEY.J.A. Central & Southwest Corp. CARNEY.J.A. Contral
  & Light Co. CARNEY.J.A. Public Service Co. of Oklahema.
  79/11/27. 4pp. Contral Power
- 79121401B4 Notifies that documents discussed in 791107 ltr will be available at law firms for NRC insp. Cortificate of Svc encl. FLYNN.P.G. Lowenstein,Nowman,Reis,Arelrad & Toll. 79/11/27. App.
- 7912170048 Request for issuance of subpanes & for mod of ASLB 790724 order. Order should be modified to relfect outstanding discovery matters & briefing schedule. Certificate of Svc & list of degenents encl.

  CYPHERT, S. 9., PARMENTER, F. H. Justice, Dept. of. 79/11/29. 15pp.
- 7912270048 Forwards City of San Antonio.TX responses to Central Power & Light Interregatories & request for production of documents. WILSON, M.R. , Watthews, Moulin, Macforlans & Barrett. 79/11/27, 1p.

- 79:12270032 Response to Central Power & Light first set of interrogatories & request for production of documents. Includes data sheets re coal-fired economy energy sale. Certificate of Svc encl. POSTON.J. II. Ban Antonio
- 7912120249 Motion to compel DOJ & NRC responses to Houston Lighting & Power first set of interrogetories & requests for production of documents DOJ 791010 responses & NRC 781201 answers were incomplete W/Certificate of Svc.
  FLYNN, P. 9. Houston Lighting & Power Co. 79/11/30, 32pp.
- 7912170138 Notifies that DOJ does not intend to call JL Johns as witness, LUQUE.N. Justice.Dept.of. 79/12/03. ip.
- 7912180202 Subpoenas EB Barnes to appear in Houston, TX on 800208.
  MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/03. ip.
- -7912180209 Subpoenas F Taylor to appear in Houston,TX on 800206. MILLER,M.E. Atomic Safety and Licensing Board Panel. 79/12/03.
- --7912180231 Bubpoonas G Knowles to appear in Houston TX on 800208. MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/03. 1p.
- --79121B0240 Bubpoenas GW Opres to appear in Houston,TX on 800130. HILLER.M.E. Atomic Safety and Licensing Board Panel. 79/12/03.
- --7912180252 Subpoenas AM Smith to appear in Beaumont.TX on 800122. HILLER.M.E. Atomic Safety and Licensing Board Panel. 79/12/03. ip.
- --7912180262 Bubpoons A Sprawls to appear in Beaumont.TX on 800124, MILLER.M.E. Atomic Safety and Licensing Board Panel. 79/12/03.
- --7912180272 Subpoenas W Atkins to appear in Beaumont, TX on 800122.
  MILLER.M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
- ---7912180281 Subposense RM McCuistion to appear in Houston, TX on 800129. MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/03. 1p.
- --79(2180289 Subpoenas T Standish to appear in Houston.TX on 800117. HILLER.M.E. Atomic Safety and Licensing Board Panel. 79/12/03.
- --7912180297 Subposens J Greenwade to appear in Houston, TX on 800116. MILLER, M. E. Atomic Safoty and Licensing Board Panel. 79/12/03.
- --7912180306 Subposens N Lee to appear in Beaument.TX on 800125 MILLER.M.E. Atomic Safety and Licensing Board Panel. 79/1
- ---7912180311 Subposes MM Milberg to appear in Houston TX on 800207. MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
- --7912190320 Subpoenss TR Locks to appear in Wichita Falls, TX on 800103. MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
- --7912180329 Subpoenas EA Turner to appear in Houston, TX on 800131. MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
- --7912180340 Subpoonss RJ Earhart to appear in Houston TX on 800118. MILLER M. E. Atomic Eafety and Licensing Board Panel. 79/12/03.
- -7912180349 Subpoenas JE Monahan to appear in Haco,TX on 800104. MILLER,M.E. Atomic Safety and Licensing Board Panel. 79/12/03.
- --7912180360 Subpoenas HL Manning to appear in Dallas.TX on 800108. MILLER.M.E. Atomic Safety and Licensing Board Panel. 79/12/03. 1p.
- --7912180372 Subposens OC Da La Gasa to appear in Dellas.TX on 800109.
  MILLER,M.E. Atomic Safety and Licensing Board Panel. 79/12/03.

- --79121803B1 Subpoenss S Beard to appear in Dailas, TX on 800108.
  MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
  ip.
- --7912180395 Subpoemas EL Watson to appear in Dallas.TX on 800110. MILLER.M.E. Atomic Safety and Licensing Board Panel. 79/12/03.
- ~-7912180404 Bubpoons JE Bondurant to appear in Beaumont, TX on 800123.
  MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
  10.
- --7912180414 Subposens JS Ferrington to appear in Dallas.TX on 790111. HILLER.M.E. Atomic Safety and Licensing Soard Panel. 79/12/03. ip.
- --7912180423 Subposens R Corder to appear in Dallas,TX on 800109. MILLER,M.E. Atomic Safety and Licensing Board Panel. 79/12/03. 1p.
- 7912280118 Discovery rept by City Public Svc Board of San Antonio, TX for Nov 1979. Received & responded to Central Power & Light first set of interrogatories & request for production of documents. Certificate of Svc encl.

  MILSON, W. R. Texas, State of. WILSON, W. R. Matthews, Nowlin, Macfarlens & Barrett, 79/12/03. App.
- 7912130313 Application for issuance of subposmas to Bardell, Bravenec & recordkesper, College Station, TX. Will testify on bulk elsectric power supply, transmission planning & other related issues. Drafts of subpoemas & Certificate of Svc encl. FRANKLIN. W. J. Baker & Botts. \* Lowenstein, Newman, Reis, Axelrad & Toll. 79/12/04. 27pp.
- 7912110439 Response by Public Utils Board of City of Brownsville, TX in support of DOJ motion for mod of ASLB 790724 order requesting add1 discovery period. Extension will allow thorough preparation for hearing. Certificate of Svc encl. POIRIER, M. R. Texas, State of. 79/12/05. 6pp.
- 79:2190:10 Requests util provide documents subpossed & produced at AE Newlor 79:01: deposition, BLUME, M.B. Antitrust Division, 79/12/05, 1p.
- 7912190138 Monthly status rept for Nov 1979. Parties arrived at terms of protective order. Four scheduled depositions delayed, Draft of order encl.
  POIRIER.M.R. Spiegel & McDiarmid. 79/12/05. Spp.
- 7912270084 Status rept for Nov 1977. South TX Electric Cooperative, Inc & Hedina Electric Cooperative, Inc neither initiated nor received discovery requests.

  JOHN, D. F. Bouth Taxas Electric Cooperative, Inc. JOHN, D. F. Matropolitan Edison Co. JOHN, D. F. Akin, Qump, Hauer & Feld, 79/12/05. 4pp.
- 7912280639 Discovery rept for Nov 1979. No discovery requests initiated or received. Certificate of Svc encl. BALGUQH, R. G. Austin, TX. 79/12/06. Spp.
- 7912260297 Response in support of DOJ motion for mod of A818 790724 order by extending discovery & hearing schedule. Delay needed to assimilate evidence & to narrow issues. Certificate of SVc encl.

  MELLING, S. Central & Southwest Corp. MELLING, S. Isham, Lincoln & Beale. 79/12/07. 10pp.
- 7912260360 Memorandum in support of DOJ motion requesting mod of ABLB 790724 order. Proposed addl time for completion of discovery, continuation of depositions & final prehearing conference needed to perform studies. Cortificate of Evc encl. RITTS, F. H., BURCHETTE, W. H. Texas-Louisiana Electric Cooperative, Inc. RITTS, F. H. Northcutt Elg. 79/12/07. 6pp.
- 7912270101 Notifies of postponement of JT Wenders deposition. STAHL, D. M. Isham, Lincoln & Beale. 79/12/07. ip.
- 7912270123 Discovery rept for Nov 1979 Fifteen depositions taken. Third supplemental response to util second set of interrogatories filed DOJ filed 791130 request for mod af 790724 ABLE order. CYPHERT, B. B. Justice, Dept. of. 79/12/07. 3pp.
- 7912270104 Discovery status rept for Nov 1979 for Central & Southwest Corp. Thirteen depositions taken. CARNEY. J. A. Isham, Lincoln & Beale. 79/12/10. 5pp.

- 7912260357 Response to DOJ 791130 motion for mod of ASLB 790724 order by oxtending hearing schedule & for ancillary relief. If modified, single discovery termination date should be adopted. Certificate of Svc encl.
  BLUM.R.L. Houston Lighting & Power Co: BLUM, R.L. Baker & Botts. 79/12/11. 9pp.
- 7912280670 Notifies of correct svc list for Central & Bauth West Corp. STAHL, D. M. — Isham, Lincoln & Beale. 79/12/11. | 1p.
- 7912310514 Advises that applicant possesses addl documents responsive to 790709 subpoena addressed to A Gerber Documents will be ready for DOJ insp at mutually convenient time.
  FLYNN.P.O. Lowenstein.Newman.Reis.Axelrad & Tall. 79/12/11. 1p.
- --7912310519 Advises that applicant possesses addl documents responsive to 790709 subpoena addressed to A Gerbor. Documents will be ready for NRC insp at mutually convenient time. Certificate of Syc encl.

  FLYNN, P. G. Lowenstein, Newman, Reis, Azelrad & Toli. 79/12/11. 5pp.
- 7912280627 Supports util 791005 request for directed certification of ABLB 791005 order re motions based upon decision of US District Court. Order should be reviewed due to holding that res judicata inapplicable to antitrust proceedings.

  KNDTTS. J. B. Texas Utilities Generating Co. KNDTTS, J. B., AHEARN, C. D. Debevoise & Liberman. 79/12/12. 37pp.
- 77122B0629 Notice of appearance in proceeding Certificate of Svc encl. AHEARN.C.D. Texas Utilities Generating Co. AHEARN,C.D. Dallas Power & Light Co. AHEARN.C.D. Texas Electric Service Co. 79/12/12.4pp.
- 7912260001 Brief in opposition to applicant 791109 request that ASLAB cortify ASLB 791005 order denying applicant motion for summary disposition. No irreperable harm.injury to public interest or Unusual delay present to justify certification. CHANANIA.F.D., HODODON.A. Antitrust Division. 79/12/14. 31pp.
- --7912260088 Special prehearing conference order directing parties to commence discovery & trial preparation immediately & to complete discovery by 790108, Certificate of Svc encl. MILLER, H. E. Atomic Safety and Licensing Board Panel, 78/07/13.
- 7912270137 Order extending time to B00227 for completin of discovery, to B00328 for completion of expert discovery, to B00428 for filing witness lists. Schedules prehearing conference for B00505 & evidentiary bearing for B00505 Marketiary hearing for B00510.

  MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/14.
- 7912280630 Application for issuance of subpoens calling for deposition of JR Milford. 8 Phelps. P Meyers. HJ Marsh. RA Yarbrough. GR Harrison. R Segrest. D Wright. FJ Meyer. A Higginbotham & JM Ammons. M/twelve drafts of subpoens & Certificate of Svc. FRANKLIN. W. Baker & FRANKLIN. Houston Lighting & Power Co. FRANKLIN. W. Baker & Botts. \* Lowenstein. Newman. Reis. Axelrad & Toll. 79/12/14. 90pp.
- 7912310137 Motion for extension until 800201 to file supplemental response to Houston Lighting & Power first set of interrogatories. Involvement in depositions requires allocation of add1 time. W/Certificate of Svc. CYPHERT, S.B. PARMENTER, F. H., LUQUE, N. Justice, Dept. of. 79/12/14. Bns.
- 7912310189 Opposition to util 791109 request for directed certification & review of ABLB order. If certification directed collaberal estoppel effect should not be given to fact issues delineated by util in another case.
  PDIRIER.H.R. Brownsville.TX. POIRIER.H.R. Spiegel & McDiarmid. 7971274. 18pp.
- 7912260044 Answer concurring w/DOJ 791130 motion for mod of ASLB 790724 order by extending current hearing & discovery schedule. Factility will be ready for fuel-loading between Aug & Nov 1981. Centificate of Svc encl. LESSY,R.P., CHANANIA.F.D. Antitrust Division. 79/12/17. Spp.
- 7912R60361 Dpposition to util 791130 request to compel further discovery Util has not requested further discovery from NRC. NRC willing to work w/util to arrive at mutually agreeable discovery schedule. Certificate of Svc encl.

  LESSY.R. P. GHANANIA, F. D. Antitrust Division. 79/12/17. dap.
- 7912280649 Forwards documents from files of A Gerber per request H/o encl. Certificate of Evc encl.
  FLYNN, P. O. Lowenstein, Newman, Reis, Axelrad & Toll. 79/12/17. 5pp.

- 7912310001 Supplementary response to first set of interrogatories.
  Discusses areas where util & Public Util Board of
  Brownsville.TX compete.Affidavit of JW Wilson supporting
  documentation & Centificate of Svc encl.
  WILSON.J.W. Brownsville.TX. 79/12/19. 62pp.
- 7912310161 Opposition to applicant 791218 motion for protective order. Order filed inadvertently & conflicts w/previously agreed to terms. Intervenor willing to consider modifying agreement. PDIRIER,M.R. Brownsville,TX. POIRIER,M.R. Spiegel & McDiarmid. 79/12/19. 4pp.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912060555 Responds to IE Bulletin 79-23.Emergency diesel generators differ from type liable to reported failure. OPREA.O.W. Houston Lighting & Power Co. 79/10/22. ip.
- 7912280022 Forwards IE Insp Regts 50-498/79-17 & 50-499/79-17 on 791024-26. No noncompliance noted. SEIDLE, W. C. Region 4, Dailas, Reactor Construction & Engineering Support Branch. 79/11/14. 2pp.
- --7912280329 IE Insp Repts 50-498/79-17 t 50-499/79-17 on 791024-26. No noncompliance noted Major areas inspected: licensee responses to praviously identified insp findings & review of reported 100FRSO. 55(e) items.
  HUBACKE, M. O., PHILLIPS, H. B., CROSSMAN, W. A. Region 4, Dallas, Office of the Director. 79/11/13. 4pp.
- 7912100258 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Bupport Loads." No response required.
  SEYPRIT, K. V. Region 4, Dallas. Dffice of the Director. 79/11/16.
- 7912110530 Forwards IE Info Notice 79-29, "Loss of Noneafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required.

  SEYPRIT, K. V. Region 4, Dallas, Diffice of the Director. 79/11/16.
- 7912110279 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required.
  SEYPRIT, K. V. Region 4, Dailas, Office of the Director. 79/11/26.
- 7912110476 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sent by NRC to licensees.

  SEYPRIT.X.V. Region 4. Dallas, Office of the Director. 79/11/26.
- 7912190043 Forwards IE Circular 79-24. "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BHRs." No written response required.
  SEYFRIT, K. V. Region 4. Dallas, Office of the Director. 79/11/26.
- 7912190177 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation."
  No written response required.
  SEYFRIT.K.V. Region 4, Dallas, Office of the Director. 79/11/30.
- 7912310261 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action required.
  SEYPRIT.K.V. Region 4, Dallas, Office of the Director, 79/12/06.
- 7912200212 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. SEYFRIT.K.V. Region 4, Dallas, Office of the Director. 79/12/07. 1p.
  - f Incorrect Amplified d. | Director. 79/12/13.

parted

- U. Congressional/Executive Correspondence
- 7912120053 Responds to 790924 1tr re L Sinkin request for establishment of local PDR in San Antonio TX. Arrangements made to forward copies of NRC insp repts to San Antonio Public Library. ODSSICK.L.V. Office of the Executive Director for Operations. 79/10/15. ip.
- --7912120066 Forwards LA Binkin 790801 request that NRC establish PDR in San Antonio, TX. Requests comments.
  GDNZALEZ, H. B. House of Rep. 79/09/24. 1p.
- --7912120071 Requests establishment of PDR in Ban Antonio.TX. BINKIN.L.A. Citizens Concerned About Nuclear Power, Inc. 79/08/01. 1p.
- DOCKET STN-50-499 SOUTH TEXAS PROJECT, UNIT 2
- A. Application/construction stage documents & correspondence
- 7712060560 Confirms 790831 telcon re 790628 ltr concerning 790622 stop work order on placement of safety-related concrete. Util will resume placement of concrete in reactor containment bidg exterior shell walls.
  TURNER.E.A. Houston Lighting & Power Co. 79/08/31. 3pp.
- 7912110011 Forwards NRC position on status & applicability to pending OL applications of results of TMT followup actions. Outlines add short-term actions to be taken.
  VASSALLO, D. B. Division of Project Management. 79/09/27. 41pp.
- 7912110244 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATWB issue for PWRs & BWRs.
  Success of program depends on industry response. Supports formation of owners groups to provide necessary info.
  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912070361 Forwards Amend 6 to application for OL. YURNER, E. A. Houston Lighting & Power Co. 79/12/05. 3pp.
- --7912070370 Amend & to application for OL, describing business & organization of applicants. GEC Forms 8-16 & 10-K, financial info & Annual Financial Rept 1978 and.
  TURNER, E. A. Houston Lighting & Power Co. 79/12/05. 275pp.
- --7912070375 Annual Financial Rept 1978. \* Houston Industries.Inc. 78/12/31. 39pp.
- 7712180465 Forwards request for add1 info re initial testing to complete review of FBAR.
  PARR.O.D. Light Water Reactors Branch 3. 79/12/07. 17pp.
- 7912270369 Informs TX Historical Commission that neither historical nor prehistorical remains were found at proposed barge off-leading facility site in Brauria County.TX. Results of archaeological survey performed by Dames & Moore.

  MCGUIRE,W.F. Houston Lighting & Power Co. 79/12/17. 3pp.
- F. Security, medical, emergency & fire protection plans
- 79:2040471 Forwards info re upgraded emergency plans to plants under const & OL review. Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Guide 1.101.
  VABSALLO, D. B. Division of Project Hanagement. 79/11/21. App.
- 7912310089 Notification of time change for 800109 meeting w/util in Bethesda, MD to discuss review of security plan.
  LICITRA.E.A. Light Hater Reactors Branch 3, 79/12/10, 3pp.
- Q. Adjudicatory correspondence
- 7912050442 First set of interrogatories & requests for production of documents directed to intervenor Citizens for Equitable Utils. Requests identification of documents & info supporting alleged "field const error." Certificate of Buc encl. SCHMARZ, M. D., NEWHAN, J. R. Houston Lighting & Power Co. BCHMARZ, M. D., Bater & Butts. 79/11/05. 30pp.
- 7912050611 Interrogatories & requests for production of documents directed to Citizens for Equitable Utils, Questions realledged falsification of const records by util employees, Certificate of Svc encl.

  MCGURREN.H. J. Hearing Branch 1. 79/11/05, 14pp.

- --- 7912050515 Interrogatories & requests for production of documents directed to Citizens Concerned About Nuclear Power. Includes questions re alleged falsification of const records by util eaployees.

  MCGURREN.H.J. Hearing Branch 1. 79/11/05. 10pp.
- 7912130467 First set of interrogatories & request for inse & production of documents. Requests info re basis for Section 2.6 of FBAR. peak wind gusts used for design & concrete bonding requirements. Certificate of Svc encl.
  BUCHORN.P. Citizens for Equitable Utilities. BUCHORN.P. Citizens Concerned About Nuclear Power, Inc. 79/11/05. 10pp.
- 7912050092 Petition for directed certification & review of ASLE 791005 order denying motions for summary decision. Urges collateral estopped of Central & South West Corp re issues previously decided in district court trial. Certificate of Svc encl. BARNETT. E. W. Houston Lighting & Power Co. BOUNNICHT, J. A. Lowenstein, Newman, Reis, Azelrad & Toll. 79/11/09. 22pp.
- 7712170384 Forwards addl request for production of documents re San Antenio Express News 791111 article reporting that results of FBI inquiry were turned over to MRC.

  BINKIN.L.A. Citizens Concerned About Nuclear Power, Inc. 79/11/12.
  ip.
- ---7912170395 Request for production of documents, Demands all FBI documents re investigation of facility, Cartificate of Bvc ancl.

  BINKIN.L.A. Citizens Concerned About Nuclear Power, Inc.
  79/11/12. 2pp.
- 7912190061 Forwards util 791120 ltr to NRC & encl. SCHMARZ.M.D. Bater & Botts. 79/11/28. 3pp.
- 7912180087 Requests copy of documents transmitted to Citizens Concerned About Nuclear Power per L Binkin 791112 FOIA Request 79-493, re FBI investigation. MCGURREN.H.J. Hearing Branch 1. 79/12/11. 1p.
- 7912280664 Responds to FOIA request for documents generated as result of investigation of Bouth TX project by FBI.Request formerded to FBI for response.

  CARR.J.C. Division of Rules and Records, 79/12/17. 1p.

### M. Antitrust correspondence

- 7912060088 Discovery rept for Oct 1979. Corrected & signed City Public Svc Board depositions taken by DOJ & MRC. Produced addl documents requested by DOJ during JB Poston deposition. Certificate of Svc encl. MILSON, M. R. Matthews, Nowlin, Macfarlane & Barrett. 79/11/05. 4pp.
- 7912060247 Discovery rept for Oct 1979. Produced add1 documents to DOJ following RL Hancock.HL Peterson & E Rummel 791009 & 10 depositions. Did not initiate discovery requests. Certificate of Svc encl.
  BALOUDH.R. C. Austin, TX. 79/11/03. 4pp.
- 791R190227 Forwards affidavits of RE Roundtree & LR Qawlik,general amager & associate general amager of Public Utils Board, Brownsville, TK.

  JABLON, R. A. Bplegel & HcDiarmid. 79/11/07. ip.
- ---7912190265 Affidavit by ganarel manager of Public Utils Board of City of Brownsvills. Ack that 790502 responses to Houston Lighting & Power first set of interrogatories & 790626 supplemental responses to same discovery have been revisued, ROWADTREE, R.E. Texas, State of. 79/09/14. 2pp.
- --7912190298 Affidavit by associate general manager of Public Utils Seard. Brownsville, TX. Ack that 790502 responses to Houston Lighting & Power first set of interregatories & 790626 supplemental responses to same discovery have been received. GME.IK.L.R. Texas, State of. 79/09/14. 2pp.
- --- 79:2190319 Corrected & supplemental answers by Public Utils Board of City of Brownsville.TX in response to Houston Lighting & Power first set of interrogatories & first request for production of documents. Contains info re sale of power.

   Texas, State of. 79:11/07. App.
- 7712190241 Confirms 771106 conversation re intentions not to cell J Baith. Cajun Cooperative. as witness at hearing, Deposition of J Baith will not he taken. Reserves right to depose J Baith at future date.

  BALDWIN. J. M. Baker & Botts. 79/11/07. 5pp.

- 7911300277 Discovery rept for Sept & Oct 1979. Participated in FS
  Buchanan, JD Nicholas & O Taylor depositions, Did not initiate
  discovery requests, Certificate of Svc encl.
  BURCHETTE, N. H. Texas-Louisiana Electric Cooperative, Inc. 79/11/08.
- 7912140202 Advises that during Oct 1979, South TX Electric Cooperative & Medina Electric Cooperative neither initiated nor received any discovery requests. Certificate of Svc encl. JOHN.D.F. Akin. Ousp. Hauer & Feld. 79/11/08. 4pp.
- 7912050683 Third set of interrogatories & request for production of documents directed to TX Utils Generating Co. et al. Addresses purchase & sale of off-peak interruptible energy & transfer & exchange of electric energy. Certificate of Bvc ancl. STAHL.D. Central Power & Light Co. 79/11/09. 8pp.
- 7912060009 Ack receipt of 791107 ltr advising of Houston Lighting & Power assertion of work product privilege re Gerber scripts. NRC will file motion to compel discovery. LEBSY.R.P. Antitrust Division. 79/11/09. jp.
- 7912100300 First set of interrogatories & request for production of documents, directed to City Public Byc Board of San Antonio. Addresses coal-fired economy energy purchase & sale & electric energy transfer & exchange. W/Certificate of Syc. STANL.D. Cantral Power & Light Co. 79/11/09. 7pp.
- 7912100307 Discovery rept for Oct 1979. Took depositions of HL Peterson, EC Rumael, RL Hencock, CT Herring & R Heyler, & TL Hatcher & M Tanner in conjunction w/NRC. Participated in Houston Lighting & Power & TX Utils joint depositions W/Certificate of Syc. CYPHERT, S. B. Justice, Dept. of. 79/11/09. 7pp.
- 7912190140 Notifies that J Cambrell of Cajun Electric Power Cooperative has been designated potential witness in DQJ proceedings. Requests notification of Cambrells deposition rescheduling. LUGUE, N. Justice, Dept. of. 79/11/09. 1p.
- 7912100332 Notice of appearance in proceeding Certificate of Evc encl. LURUE.N. Justice Dept. of. 79/11/13. 4pp.
- 7912110270 Advises of postponement of H Woodson deposition until later date, due to Houston Lighting & Power failure to make Hoodson working papers available for insp. BLUME: M. B. Antitrust Division. 79/11/19. 1p.
- 7912130094 Notice of appearance of AP Hodgdon on behalf of NRC. Cartificate of Svc encl. HOSGDON.A.P. Antitrust Division. 79/11/20, App.
- 7912060040 Application for subpoense for deposition of J Gambrell & leaper of records of Cajun Electric Power Cooperative.
  Testimony will include transmission planning & fuel supply.
  Drafts of subpoense & Certificate of Svc encl.
  FRANKLIN.W.J. Houston Lighting & Power Co. FRANKLIN.W.J. Baker & Botts. 79/11/21, 20pp.
- 7912130057 Request for expansion of ASLB 790323 protective order to include documents produced by Central & South Mest Corp & Central & South Hest Svcs. Inc. to include confidential documents to amend order to bind TX Util companies.

  STAHL, D. Central & Southwest Corp. STAHL, D. Heat Texas Utilities Co. STAHL, D. Isham. Lincoln & Beale. 79/11/21. 7pp.
- 79121304B3 Notifies of AE Autry 791211 deposition in Corpus Christi.TX. MB Borchelt 791112 deposition in Abilene.TX.RW Hardy 791213 deposition in Abilene.TX & SB Philips 791217 deposition in Ballas.TX.Certificate of Byc encl.

  MCDIARMID.R.C. Brownsville.TX. 79/11/26. 7pp.
- 7912130236 Third set of interrogatories & requests for production of documents directed to Houston Lighting & Power & TX Utils Generating Co. Includes questions on power flow between utils. Supporting documentation & Certificate of Syc encl. LEBSY, R. P. Antitrust Division. HOUGDON. A. P. Commission. 79/11/26. 23pp.
- 7912130328 Notice of appearance of 8 Welling on hehalf of Central & Bouth West Corp. Central Power & Light Co. PSC of OK. Southwestern Electric Power Co & West TX Utils Co. MELLING. S. Isham, Lincoln & Beale. 79/11/26. 6pp.
- 7912120043 Third supplemental response to second set of interrogatories & requests for production of documents from applicant Cortificate of Bvc ancl.

  CYPHERT, B. R. Justice/Dept. of. 79/11/27. 7pp.

- 7912130337 Notice of TL Austin 791217 deposition in Dallas.TX.
  CARNEY, J. A. Central & Southwest Carp. CARNEY, J. A. West Texas
  Utilities Co. CARNEY, J. A. Isham, Lincoln & Beale. 79/11/27, Ip.
- --7912130361 Notice of BB Hulsey 791218 deposition in Dallas, TX.
  CARNEY, J. A. Central & Southwest Corp. CARNEY, J. A. West Texas
  Utilities Co. CARNEY, J. A. Isham, Lincoln & Beale. 79/11/27. 1p.
- --7912130366 Notice of PG Brittain 791218 deposition in Dallas.TX. CARNEY.J.A. Central & Southwest Corp. CARNEY.J.A. West Texas Utilities Cg. CARNEY.J.A. Isham, Lincoln & Beale. 79/11/27. 1p
- --7912130378 Notice of MD Spence 791219 deposition in Dallas.TX. Certificate of Svc encl. CARNEY.J.A. Central & Southwest Corp. CARNEY.J.A. West Texas Utilities Co. CARNEY.J.A. Isham, Lincoln & Beele. 79/11/27.
- 7912140184 Notifies that documents discussed in 791107 ltr will be available at law firms for NRC insp.Certificate of Svc encl. FLYNN.P.G. Lowenstein, Newman, Reis, Axelrad & Toll. 79/11/27. 6pp.
- 7912170048 Request for issuance of subpoenas & for mod of ABLB 790724 order.Order should be modified to reflect outstanding discovery matters & briefing schedule.Certificate of Svc & list of deponents encl.

  CYPHERT.S.B. Justice.Dept. of. 79/11/29. 15pp.
- 7912270048 Forwards City of San Antonio.TX responses to Central Power & Light interrogatories & request for production of documents. WILEON.W.R., WILEON.W.R. Matthews, Nowlin. Macferlane & Darrett. 79/11/29, ip.
- 7912270052 Response to Central Power & Light first set of interrogatories & request for production of documents. Includes data sheets re coal-fired economy energy sale. Certificate of Svc enci.
  PDSTON, J. B. San Antonio
- 79:2120249 Motion to compel DOJ & NRC responses to Houston Lighting & Power first set of interrogatories & requests for production of documents. DOJ 78:010 responses & NRC 78:201 answers were incomplete. H/Certificate of Svc. FLYNN.P.G. Houston Lighting & Power Co. 79/11/30. 32pp.
- 7912170138 Notifies that DOJ does not intend to call JL Johns as witness. LUQUE.N. Justice.Dept.of. 79/12/03. 1p.
- 7912180202 Subposmas EB Barnes to appear in Houston, TX on 600205.
  MELLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/03. ip.
- ---7912180209 Subposens F Taylor to appear in Houston,TX on 800204. MILLER.M. E. Atomic Safety and Licensing Board Panel. 79/12/03. ip.
- ---7912180231 Subpoenas & Knowles to appear in Houston, TX on 800208.
  MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
  10.
- ~~7912180240 Subposens GW Opres to appear in Houston TX on 800130. MILLER,M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
- --7912180252 Subpoenas AM Smith to appear in Deaumont, TX on 800122. MILLER, M. E. Atomic Safety and Licensing Board Panel, 79/12/03. 1p.
- --7912180262 Subposens A Sprawls to appear in Beaumont, TX on 800124. MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
- --7912180272 Subposens W Atkins to appear in Beaumont, TX on 800122, MILLER, M. E. Atomic Safety and Licensing Board Panol. 79/12/03.
- --7912180281 Subpoens RM McCuistion to appear in Houston,TX on 800129. MILLER,M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
- --7912180289 Subpoenas T Standish to appear in Houston, TX on 800117. MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/03. 1b.
  - Subpoenss J Greenwade to appear in Houston.TX on 800116. E. Atomic Safety and Licensing Board Panel. 79/12/03.

- --7912180306 Subposens N Les to appear in Beaumont, TX on 800125. MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
- --7912180311 Subpossas MW Milberg to appear in Houston.TX on 800207. MILLER.M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
- --7912180020 Subpoenas YR Locke to appear in Wichita Falls.TX on 800103. MILLER.M. E. Atomic Safety and Licensing Board Panel. 79/12/03. in.
- --7912180329 Subpoenas EA Turner to appear in Houston, TX on 800131. MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/03. 1p.
- --7912180340 Subposens RJ Earhart to appear in Houston, TX on 800115. MILLER, M. E. Atomic Safety and Licensing Soard Panel. 79/12/03.
- --7912180349 Subposens JE Monahan to appear in Waco,TX on 800104. MILLER,M. E. Atomic Safety and Licensing Board Panel. 79/12/03. 1p.
- --7912180360 Subpoenas HL Manning to appear in Dallas, TX on 800108. MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
- --7912180372 Subposnas OC De La Gasa to appear in Dallas, TX on 800109. MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
- --79121803B1 Subpoenas S Beard to appear in Dallas.TX on 800108.
  MILLER.M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
- --7912180395 Subpoenas EL Watson to appear in Dallas.TX on 800110. MILLER.M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
- --7912180404 Subposens JE Bondurant to appear in Beaumont.TX on 800123. MILLER.M. E. Atomic Safety and Licensing Board Panel. 79/12/03. ip.
- --7912180414 Subpoenas JS Farrington to appear in Dallas.TX on 790111. HILLER.M. E. Atomic Safety and Licensing Board Panel. 79/12/03. 1p.
- ---7912180423 Bubposnas R Corder to appear in Dallas,TX on 800109.
  MILLER.M. E. Atomic Safety and Licensing Board Panel. 79/12/03.
  1p.
- 7912280118 Discovery rept by City Public Svc Board of San Antonio.TX for Nov 1979.Received & responded to Central Power & Light first set of interrogatories & request for production of documents.Certificate of Svc encl.

  WILSON, W.R. Texas, State of. WILSON, W.R. Matthews, Nowlin, Macfarlane & Barrett. 79/12/03. 4pp.
- 7912130313 Application for issuance of subposmas to Bardell, Bravenec & recordkeeper, College Station, TX. Will testify on bulk electric power supply, transmission planning & other related issues. Drafts of subposmas & Certificate of Svc encl. FRANKLIN, W. J. Houston Lighting & Power Co. FRANKLIN, W. J. Baker & Botts. # Lowenstein, Newman, Reis, Axelrad & Toll. 79/12/04. 27pp.
- 7912110459 Response by Public Utils Board of City Brownsvills.TX in support of DOJ motion for mod of ASLB 790724 order requesting addl discovery period Extension will allow thorough preparation for hearing Certificate of Svc encl. POIRIER.M.R. Taxas, State of. 79/12/05. App.
- 7912190110 Requests util provide documents subposmeed & produced of AE Naylor 791011 deposition.
  BLUME.M.B. Antitrust Division. 79/12/05. ip.
- 7912190138 Monthly status rept for Nov 1979. Parties arrived at terms of protective order. Four scheduled depositions delayed. Draft of order encl. POIRIER. M. R. Spiegel & McDiarmid. 79/12/05. Spp.
- 7912270084 Status rept for Nov 1979. South TX Electric Cooperative, Inc. & Medina Electric Cooperative, Inc neither initiated nor received discovery requests.

  JOHN.D.F. South Texas Electric Cooperative, Inc. 79/12/05. 4pp.

- 7912280639 Discovery rept for Nov 1979. No discovery requests initiated or received. Certificate of Svc encl. BALDUOH, R. C. Austin, TX. 79/12/06, 5pp.
- 7912260297 Response in support of BOJ motion for mod of ASLB 790724 order by extending discovery & hearing achedule. Delay needed to assimilate evidence & to narrow issues. Certificate of Svc encl.

  WELLING.B. Central & Southwest Corp. 79/12/07. 10pp.
- 7912260360 Hemorandum in support of DOJ motion requesting mod of ASLB 790724 order. Proposed add1 time for completion of discovery, continuation of depositions & final prehearing conference needed to perform studies, Certificate of Svc encl.
  RITTS,F.H. Texas-Louisians Electric Cooperative, Inc. BURCHETTE, H.H. Northcutt Ely. 79/12/07. App.
- 7912270101 Notifies of postponement of JT Henders deposition. 8TAHL, D. M. Isham, Lincoln & Beele. 79/12/07. 1p.
- 7912270123 Discovery rept for Nov 1979. Fifteen depositions taken. Third supplemental response to util second set of interrogatories filed. DDJ filed 791130 request for mod of 790724 ABLB order. GYPHERT, B. B. Justice, Dept. of. 79/12/07. 3pp.
- 7912270104 Discovery status rept for Nov 1979 for Central & Bouthwest Corp. Thirteen depositions taken. CARNEY.J.A. 1sham, Lincoln & Beals. 79/12/10. 5pp.
- 7912260357 Response to DOJ 791130 motion for mod of ASLB 790724 order by extending hearing schedule & for ancillary relief. If modified single discovery termination date should be adopted. Certificate of Bvc encl.

  BLUM.R. L. Houston Lighting & Power Co. 79/12/11. 9pp.
- 7912270103 Hod of 790323 protective order, expanding categories of documents considered confidential & expanding protected area to include documents produced by Central & Bouth West Corp & Central & Bouth West Corp & Central & Bouth West Stycs, Inc.
  MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/12/11.
- 7912280670 Notifies of correct svc list for Central & South West Corp. STAHL, D. M. Isham, Lincoln & Beele. 79/12/11. ip.
- 7912310514 Advises that applicant possesses addl documents responsive to 790709 subposna addressed to A Gerber. Documents will be ready for DOJ insp at motually convenient time.

  FLYNN, P. Q. Lowenstein, Newman, Reis, Axeirad & Toll. 79/12/11. ip.
- --7912310519 Advises that applicant possesses addl documents responsive to 790709 subposes addressed to A Garber Documents will be ready for NRC insp at mutually convenient time. Certificate of Byc enci.
  FLYNN, P. Q. Lowenstein, Newman, Reis, Axelrad & Toll. 79/12/11. Bpp.
- 7912280627 Supports util 79100 Request for directed certification of ABLB 791005 order re motions based upon decision of US District Court Order should be reviewed due to result that res judicate inapplicable to antitrust proceedings.

  KNOTTS, J. B. Texas Utilities Generating Co. 79/12/12. 37pp.
- 7912280627 Notice of Appearance in proceeding Certificate of Svc encl.
  AHEARN, C. D. Texas Utilities Generating Co. AHEARN, C. D. Yexas Power & Light Co. AHEARN, C.D. Debevoise & Liberman. 79/12/12, 4pp.
- 79122600B1 Brisf in opposition to applicant 791109 request that ASLAB certify ASLB 791005 order denying applicant motion for summary disposition. No irreparable harm injury to public interest or unusual dalay present to justify certification. CHANANIA, F.D. Antitrust Division. 79/12/14. 31pp.
- --7912260088 Special prehearing conference order directing parties to commence discovery & trial preparation immediately & to complete discovery by 790108. Certificate of Svc encl. MILLER, M. E. Atomic Safety and Licensing Board Panel. 78/07/13. iipp.
- 7912280630 Application for issuance of subposess calling for deposition of JR Milford S Phelps, P Meyers, HJ Marsh RA Yarbrough, OR Harrison, R Begrest, D Wright, FJ Meyer, A Higginbotham & JM Ammons. M/twelve darfts of subposess & Certificate of Svc. FRANKLIN, M. Baker & Botts. \* Lowenstein, Newman, Reis, Axelrad & Toil. 79/12/14. 90pp.
- 7912310137 Motion for extension until 800201 to file supplemental response to Houston Lighting & Power first set of interrogatories. Involvement in depositions requires allocation of addl time. W/Certificate of Evc. CYPHERT: 8. B. Justice, Dept. of. 79/12/14. Spp.

- 79123101B9 Opposition to util 791109 request for directed certification & review of ASLB order. If certification directed.collateral estoppel effect should not be given to fact issues delineated by util in another case.

  POIRIER.M.R. Brownsville.TX. 79/12/14. 18pp.
- 7912260044 Answer concurring w/DOJ 791130 motion for mod of ASLB 790724 order by extending current hearing & discovery schedule. Facility will be ready for fuel-loading between Aug & Nov 1981. Certificate of Svc encl. LEBSY,R.P. Antitrust Division. 79/12/17. 5pp.
- 7912260361 Opposition to util 791130 request to compel further discovery. Util has not requested further discovery from NRC. NRC willing to work w/util to arrive at mutually agreeable discovery schedule. Certificate of Svc encl. LEBGY, R. P. Antitrust Division. 79/12/17. 6pp.
- 7912280649 Forwards documents from files of A Gerber per request. H/o encl. Cartificate of Svc encl. FLYNN, P. G. Lowenstein, Newman, Reis, Axelrad & Toll. 79/12/17, 5pp.
- 7912270137 Order extending time to 800227 for completion of discovery, to 800328 for completion of expert discovery, to 800428 for filing witness lists. Schedules prehearing conference for 800505 & evidentiary hearing for 800514.

  MILLER M.E. Atomic Safety and Licensing Board Panel. 79/12/14.

  6pp.
- 7912310001 Bupplementary response to first set of interrogatories.
  Discusses areas where util & Public Util Board of
  Brownsville, TX compete. Affidavit of JW Wilson, supporting
  documentation & Certificate of 8 vc encl.
  WILSON, J. W. Brownsville, TX. 79/12/19. 62pp,
- 7912310161 Opposition to applicant 79121B motion for protective order. Order filed inadvertently & conflicts u/previously agreed to terms. Intervenor willing to consider modifying agreement. POIRIER.M.R. Brownsville.TX. 79/12/19. 4pp.
- G. Inspection reports: IE Bulletins & correspondence
- 7712060535 Responds to IE Bulletin 79-23.Emergency diesel generators differ from type liable to reported failure.
  OPREA, G. W. Houston Lighting & Power Co. 79/10/22. ip.
- 7912280322 Forwards IE Insp Repts 50-498/79-17 & 50-499/79-17 on 791024-26. No noncompliance noted.
  BEIDLE-W.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/11/14. 2pp.
- --7912280929 IE Insp Repts 50-498/79-17 & 50-499/79-17 on 791024-26. No noncompliance noted Major areas inspected: licensee responses to proviously identified insp findings & review of reported 10CFR50. 59(e) items.
  HUBACEK, M. O. PHILLIPS H. S. , CROSSMAN, M. A. Region 4, Dallas, Office of the Director. 79/11/13. 4pp.
- 79:2100258 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. SEYFRIT.K.V. Region 4, Dalias, Office of the Director. 79/11/16.
- 7912110530 Forwards IE Info Notice 79-29. "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required.

  SEYPRIT.K.V. Region 4. Dallas. Office of the Director. 79/11/16.
- 7912110279 Forwards IE Gircular 79-23, "Motor Starters & Contactors Failed to Operate." No response required.

  SEYPRIT.K.V. Region 4. Dallas, Office of the Director. 79/11/26.
- 7912110476 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general efcs copies of escalated enforcement correspondence sent by NRC to licensees.

  SEYFRIT.K.V. Region 4: Dallas, Office of the Director. 79/11/26.

  1p.
- 7912190043 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BMRs." No written response required.

  SEYFRIT.K.V. Region 4, Dallas, Office of the Director. 79/11/26.

- 7912190177 Forwards IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation."
  No written response required.
  SEYFRIT.K.V. Region 4. Dallas. Office of the Director. 79/11/30.
- 7912310261 Forwards IE Info Notice 79-30. "Reporting of Defects & Noncompliances, 10CFR21." No action required. SEYFRIT.K.V. Region 4. Dallas. Office of the Director. 79/12/06.
- 7912200212 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. SEYFRIT, K. V. Region 4. Dallas. Office of the Director. 79/12/07.
- 7912280585 Forwards IE Info Notice 79-31. "Use of Incorrect Amplified Response Spectra." No written response required. SEYFRIT.K.V. Region 4, Dallas, Office of the Director. 79/12/13.
- 5. Reportable occurrences, LERs & related correspondence
- 7912060670 PNO-IV-79-013:on 791102. Brown & Root GC inspectors reported intimidation by const workers at South TX project. Region 4 will investigate.
  HUBACEK, M. G., CROSSHAN, W. A. Region 4, Dallas, Office of the Director. 79/11/06. 1p.
- U. Congressional/Executive Correspondence
- 7912120053 Responds to 790924 ltr re L Binkin request for establishment of local PDR in Ban Antonio.TX. Arrangements made to forward copies of NRC insp repts to San Antonio Public Library. GOSBICK.L.V. Office of the Executive Director for Operations. 79/10/15. 1p.
- --7912120066 Forwards LA Sinkin 790801 request that NRC establish PDR in San Antonio.TX. Requests comments. GONZALEZ, H. B. House of Rep. 79/09/24. ip.
- --7912120071 Requests establishment of PDR in San Antonio.TX. SINKIN.L.A. Citizens Concerned About Nuclear Power, Inc. 79/08/01. ip.
- DOCKET 50-500 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 2
- A. Application/construction stage documents & correspondence
- 7911280153 Discusses mods to NRC position re status & applicability of TMI-2 accident review & NUREG-0578 to facilities under const. Forwards addl info to be considered in development of final plant design & procedures.

  VASSALLO.D.B. Division of Project Management. 79/10/10. App.
- 7912110264 Discusses NRC plans to use generic analyses to develop early varification program to resolve ATWB issue for PWRs & BMRs. Success of program depends on industry response. Supports formation of owners groups to provide necessary info.

  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/10/17. Opp.
- G. Adjudicatory correspondence
- 7912110043 Forwards comments on NURES-0511. Draft OEIS reflects conscious & deliberate NRC policy to jeopardize public health & safety & thwart objectives of NEPA. KEPFORD, C. Environmental Coalition on Nuclear Power. 79/10/24. 22pp.
- M. Antitrust correspondence
- 7912050078 Consolidated answer in opposition to Cleveland Electric Illuminating Co. Toledo Edison & Ohio Edison petitions for ALAB-560 review. Petitioners failed to seek Commission review on issue of monopoly existence Certificate of Svc encl. LEGBY, R. P. Antitrust Division. 79/11/21. SEpp.
- 7912180344 Informs of address change as of 791201. HUELMFELT, D. C. Hjelmfelt, D. C. 79/11/26. Spp.
- 7912110355 Orders extension until BOD115 for Commission to review ALAB-560. CHILKS B.J. Office of the Secretary of the Commission. 79/12/07. ip.

- DOCKET 50-501 DAVIS-SESSE NUCLEAR POWER STATION, UNIT 3
- A. Application/construction stage documents & correspondence
- 7911280153 Discusses mods to NRC position re status & applicability of TMI-2 accident review & NUREO-0578 to facilities under const. Forwards addi info to be considered in development of final plant design & procedures.

  VASSALLO, D. B. Division of Project Management. 79/10/10. 4pp.
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRs & BWRs.
  Buccess of program depends on industry response. Supports formation of owners groups to provide necessary info.
  DENTON, M. R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.
- Q. Adjudicatory correspondence
- 7912110043 Forwards comments on NUREQ-0511. Draft QEIB reflects conscious & deliberate NRC policy to jeopardize public health & safety & thwart objectives of NEPA.

  KEPFORD, C. Environmental Coalition on Nuclear Power. 79/10/24.
- M. Antitrust correspondence
- 7912050098 Consolidated answer in opposition to Cleveland Electric Illuminating Co. Toledo Edison & Dhio Edison petitions for ALAB-540 review. Petitioners failed to seek Commission review on issue of monpoly existence. Certificate of Svc encl. LESSY, R. P. Antitrust Division. 79/11/21. 32pp.
- 7712180344 Informs of address change as of 771201. HJELMFELT, D. C. Hjelmfelt, D. C. 79/11/26. Spp.
- 7912110356 Orders extension until 800115 for Commission to review ALAB-560.
  CHILK, S. J. Office of the Secretary of the Commission. 79/12/07.
- DOCKET STN-SO-SOR HAVEN NUCLEAR PLANT, UNIT 1
- A. Application/construction stage documents & correspondence
- 7911280153 Discusses mods to NRC position re status & applicability of TMI-2 accident review & NUREO-0578 to facilities under const. Forwards addl info to be considered in development of final plant design & procedures. VASGALLO.D.B. Division of Project Management. 79/10/10. App.
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRs & BHRs.
  Success of program depends on industry response. Supports formation of owners groups to provide necessary info.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- I. Financial information
- 7912040419 Forwards monthly rept of expanditures & commitments in connection w/proposed facility.
  BURSTEIN.B. Wisconsin Electric Power Co. 79/11/29. Spp.
- DOCKET STN-50-503 HAVEN NUCLEAR PLANT, UNIT 2
- I. Financial information
- 7912040419 Forwards monthly rept of expenditures & commitments in connection w/proposed facility.
  BURSTEIN.S. Wisconsin Electric Power Co. 79/11/29. 5pp.
- DOCKET STN-50-504 KOSHKONONG NUCLEAR PLANT, UNIT 1
- I. Financial information
- 7912040419 Forwards monthly rept of expenditures & commitments in connection u/proposed facility.
  BURBTEIN B. Wisconsin Electric Power Co. 79/11/29. Spp.

DOCKET STN-50-505 KOSHKONONO NUCLEAR PLANT, UNIT 2

I. Financial information

 $\mathcal{H}$ 

7912040419 Forwards monthly rept of expenditures & commitments in connection w/proposed facility.
BURSTEIN.B. Wisconsin Electric Power Co. 79/11/29, 5pp.

DOCKET STN-50-506 KOSHKONONO NUCLEAR PLANT, UNIT 3

I. Financial information

7912040419 Forwards monthly rept of expenditures & commitments in connection w/proposed facility.
BURSTEIN S. Hisconsin Electric Power Co. 79/11/29. Spp.

DOCKET BTN-50-507 KOSHKONONO NUCLEAR PLANT, UNIT 4

I. Financial information

7912040419 Forwards monthly rept of expenditures & commitments in connection w/proposed facility.
BURSTEIN, 8. Wisconsin Electric Power Co. 79/11/29. Spp.

DOCKET STN-50-508 WPPSS NUCLEAR PROJECT, UNIT 3

- A. Application/construction stage documents & correspondence
- 791R110264 Discusses NRC plans to use generic analyses to develop early varification program to resolve ATMS issue for PMRs & DMRs. Buccess of program depends on industry response. Supports formation of owners groups to provide necessary info. DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912100022 Discusses issuance of Amend 17 to License DPR-64, which authorized operation at 100% power. Max allowable fee already paid by util No addl fee required.

  MILLER, W. C. License Fee Management Branch. 79/11/13. ip.
- --7912100066 Provides ACRS prof manpower expenditure estimates for CP & OL raviews. FRALEY.R.F. ACRS - Advisory Committee on Reactor Safeguards. 78/11/01. ip.
- --7912100079 Requests info re ACRB prof men-hrs expended on review of each reactor. Data for safety, anyiron & antitrust hearing concerns should be included. Associated travel should not be shown.

  MILLER, W. O. License Fee Management Branch. 78/10/02. 1p.
- 7912180626 Notifies of plans to submit WNP-1/4 FBAR for acceptance review by 800530 & WNP-3/5 FBAR by 810630. RENBERGER.D.L. Washington Public Power Supply System. 79/12/12. ip.
- 7912280566 Forwards XN-NF-103, "Water Content of Bolid Matl by Electrolysis," re testing moisture of low-hydrogen electrodes.
  RENBERGER, D. L. Washington Public Power Supply System. 79/12/20.
- --7912280571 "Water Content of Solid Matl by Electrolysis," Revision & to Procedure P49281 for testing mpisture of low-hydragen electrodes.

  \* Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). XN-NF-103, 79/01/10. 13pp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Quide 1. 101. VASSALLO, D. B. Division of Project Henagement, 79/11/21. App.
- G. Inspection reports, IE Bulletins & correspondence
- 7912120802 Forwards IE Insp Rept S0-508/79-09 on 791003-11.No noncompliance noted Statement by SD Bos encl. ENGLKEN, R. H. Region 5. Ban Francisco, Office of the Director. 79/10/23. 4pp.

- ---7912120505 IE Insp Rept 50-508/79-07 on 791003-ii.No noncompliance noted, Major areas inspected: allegation that radiograph, purported to be of repaired weld, was taken of different weld than original.

  MIRBCH.D.F., SHACKLETON.D.C. Region 5, San Francisco, Office of the Director. DODDS.R.T. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/10/22. 6pp.
- 7912100285 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. ENGELKEN,R.H. Region 3, San Francisco, Office of the Director. 79/11/16. | 1p.
- 7912110522 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required. EMGELKEN,R.M. Region 5, San Francisco, Office of the Director. 79/11/16. 1p.
- 7912070031 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No response required.
  ENGELKEN,R.H. Region 5, San Francisco, Office of the Director.
  79/11/26. 10.
- 7912110274 Forwards IE Circular 79-12, "Motor Starters & Contractors Failed to Operate." No response required. ENGELKEN.R.H. Region 5, San Francisco. Office of the Director. 79/11/26, 1p.
- 7912110500 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs capies of ascalated enforcement correspondence sent by NRC to licensees.

  EMOBLKEN.R.H. Region 5, San Francisco, Office of the Director. 79/11/26. ip.
- 7912110462 Ack receipt of 791031 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-508/79-06 & 30-509/79-06.
  SPENCER, G. B. Region 5. San Francisco, Reactor Construction & Engineering Support Branch. 79/11/29. ip.
- --7912110471 Responds to NRC 790828 itr re violations noted in IE Insp. Repts 50-308/79-07 & 50-509/79-06. Corrective actions: preheat sys modified to prevent gas pressure decreases & preheat being chacked by welders to assure compliance w/Tech Specs. RENBERGER, D. L. Washington Public Power Supply System. 79/10/31.
- --79121104Bi Forwards IE Insp Repts 50-508/79-07 & 509/79-06 on 790827-30 & notice of violation.

  SPENCER.9.8. Region 5. San Francisco, Reactor Construction & Engineering Bupport Branch. 79/08/28. 2pp.
- ---7912110488 Notice of violation from insp on 790827-30.

  \* Ragion 5. Ban Francisco, Office of the Director. 79/09/26.
  2pp.
- --7912110493 IE Insp Repts 80-508/79-07 & 50-509/79-06 on 790827-30.

  Noncompliance noted: failure to maintain specified preheat
  on joint being welded & Failure to identify reinforcing
  steel as required by procedures.

  KIRBCH.D.F., HAIST.D.P. Region 5, San Francisco. Office of the
  Director. DDDB.R.T. Region 5, San Francisco, Reactor
  Construction & Engineering Support Branch. 79/09/26. 10pp.
- 7912190161 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation." No written response required. EMGELKEN.R.H. Region B, San Francisco. Office of the Director. 79/11/30. 1p.
- 7912310279 Forwards IE Info Notice 79-30. "Reporting of Defects & Noncompliances: 10CFR21." No action required.
  ENGELKEN.R.H. Region J. San Francisco. Office of the Director.
  79/12/04. 4pp.
- 7912200252 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required.
  ENGELERI, R. H. Region 5, San Francisco, Office of the Director. 79/12/07. ip.
- 7912280626 Forwards IE Info Notice 79-31. "Use of Incorrect Amplified Rasponse Spectre." No written response required. ENGELKEN.R.H. Region 5. San Francisco, Office of the Director. 79/12/13. 1p.

- S. Reportable occurrences. LERs & related correspondence
- B001110502 PNO-V-003: on 791005, licensee informed NRC that inspectors signature had been forged on welding record of nonsafety-related pipe. Contractor examined all records in field to determine if other falsifications occurred.

  KIRSCH.D.F. Region 5, San Francisco. Office of the Director. 79/10/05. 19.
- 7912120470 Forwards deficiency rept re omission of vertical reinforcing steel in fuel handling bldg wall.
  STRAND.N.O. Hashington Public Power Supply System. 79/12/03. 1p.
- ~-7912120473 Deficiency rept re ommission of vertical reinforcing steel in fuel handling bidg wall Caused by contractor oversight. All omitted dowels shall be installed in drilled holes & grouted in place using approved nonshrink grout. \* Washington Public Power Supply System. 79/12/03. 2pp.
- 7912280511 Ack receipt of 791203 interim deficiency rept re omission of vertical reinforcing steel in walls. Advises resumption of work in accordance w/NRC 791107 Immediate Action Ltr. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/12/14. 19.

# DOCKET STN-50-909 WPPSS NUCLEAR PROJECT, UNIT 5

- A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRs & BMRs.
  Success of program depends on industry response Supports formation of owners groups to provide necessary info.
  DENTON, H. R. Office of Nuclear Reactor Regulation, 79/10/17, 3pp.
- 7912100022 Discusses issuance of Amend i7 to License DPR-64, which authorized operation at 100% power. Max allowable fee already paid by util No addl fee required.
  MILLER.W.D. License Fee Management Branch. 79/11/13, 1p.
- --7912100066 Provides ACRS prof manpower expenditure estimates for CP & OL reviews.
  FRALEY.R.F. ACRS Advisory Committee on Reactor Bafeguards.
  78/11/01. ip.
- --7912100079 Requests info re ACRB prof man-hrs expended on review of each reactor. Data for safety, environ & antitrust hearing concerns should be included. Associated travel should not be shown.
  MILLER.W.D. License Fee Management Branch. 78/10/02. 1p.
- 7912180626 Notifies of plans to submit WNP-1/4 FSAR for acceptance review by 800530 & WNP-3/5 FSAR by 810630. RENBERGER, D. L. Washington Public Power Supply 8ystem. 79/12/12. ip.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Guide 1.101.

  VASSALLO,D.B. Division of Project Management. 79/11/21. 6pp.
- Q. Inspection reports, 1E Bulletins & correspondence
- 7912100285 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required.
  ENGELKEN R.H. Region 5, San Francisco, Office of the Director, 79/11/16, ip.
- 7912110522 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Cocient Sys Instrumentation During Operation." No specific action or response required. EMPELKEN,R.H. Region 5, San Francisco, Office of the Director. 79/11/16. 1p.
  - (s IE Circular 79-24, "Proper Installation & Calibr of Break Detection Equipment on BWRs." No
    - harion 5, San Francisco, Office of the Director.
      - ular 79-12, "Motor Starters & Contractors sponse required.
        San Francisco, Office of the Director.

- 7912110300 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general offs copies of escalated enforcement correspondence sent by NRC to licensees.
  ENGELKEN.R.H. Region 5. San Francisco. Office of the Director. 79/11/26. 1p.
- 7912110462 Ack receipt of 791031 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-508/79-07 & 50-509/79-06.

  SPENCER, G. S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/11/29. 1p.
- --7912110471 Responds to NRC 790828 ltr re violations noted in IE Insp Repts 50-508/79-07 & 50-509/79-06. Corrective actions: preheat sys modified to prevent gas pressure decreases & preheat being checked by welders to assure compliance w/Tech Specs. REMBERGER, D. L. Washington Public Power Supply System. 79/10/31. Spo.
- --7912110481 Forwards IE Insp Repts 50-508/79-07 & 509/79-06 on 790827-30 & notice of violation.

  BPENGER, G. S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/08/28. 2pp.
- --79121104BB Notice of violation from insp on 790827-30.

  \*\* Region 5. Ban Francisco, Office of the Director. 79/09/26.

  \*\* 20p.
- --7912110493 IE Insp Repts 50-508/79-07 & 50-509/79-06 on 790827-30.

  Noncompliance noted: failure to maintain specified preheat
  on joint being welded & failure to identify reinforcing
  steel as required by procedures.

  KIRBCH, D. F., HAIBT, D. P. Region 5. San Francisco, Office of the
  Director. DODDS.R.T. Region 5. Ban Francisco, Reactor
  Construction & Engineering Support Branch. 79/09/24, 10pp.
- 7912190161 Forwards IE Bullstin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation," No written response required.
  ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/11/30. 1p.
- 7912310279 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21," No action required.
  ENGELKEN.R.H. Region 3, Ban Francisco, Office of the Director.
  79/12/06. 4pp.
- 7912200252 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/12/07. 1p.
- 7912280626 Forwards IE Info Notice 79-31. "Use of Incorrect Amplified Response Spectra." No written response required. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/12/13. 1p.
- 8. Reportable occurrences, LERs & related correspondence
- G001110502 PNO-V-003: on 791005, licensee informed NRC that inspectors eignsture had been forged on welding record of nonsafety-related pipe. Contractor examined all records in field to determine if other falsifications occurred. KIRGCH.D.F. Region B. San Francisco, Office of the Director. 79/10/05. 1p.
- DOCKET 50-513 WPP88 NUCLEAR PROJECT, UNIT 4
- A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PHRs & BURS.
  Success of program depends on industry response. Bupports formation of owners groups to provide necessary info.
  DENTON: H. R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912060476 Forwards responses to NRC 791028 ltr requesting info resentitivity of primary coolant sys behavior to feedwater transients & status of various sys. Includes recommendations for plant changes.
  RENBERGER, D. L. Washington Public Power Supply System. 79/12/03. 200pp.

### F. Security, medical, emergency & fire protection plans

7912040471 Forwards info re upgraded emergency plans to plants under const & OL review. Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Guide 1. 101.
VASSALLO.D.B. Division of Project Management. 79/11/21. Opp.

## Adjudicatory correspondence

- 7912110043 Forwards comments on NUREQ-0511. Draft GEIB reflects conscious & deliberate NRC policy to jeopardize public health & safety & thwart objectives of NEPA.

  KEPFORD, C. Environmental Coalition on Nuclear Power. 79/10/24.
- 0. Inspection reports, IE Bulletins & correspondence
- 7912100285 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Bupport Loads." No response required. ENGELKEN,R.H. Region 5, San Francisco, Office of the Director. 79/11/16. 1p.
- 7912110522 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required.
  ENOELKEN.R.H. Region 5, Ban Francisco, Office of the Director. 79/11/16. 1p.
- 79:2070031 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Datection Equipment on BMRs." No response required.
  ENGELKEN, R. H. Region 5, San Francisco, Office of the Director.
- 7912110274 Forwards IE Circular 79-23, "Motor Starters & Contactors Falled to Operate." No response required. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/11/26, ip.
- 7912110500 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sent by NRC to licensess.

  ENGELHEN.R.H. Region 5, Ban Francisco, Office of the Director. 79/11/26. ip.
- 7912190161 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation," No written response required. EMPELKEN,R.H. Region 5, San Francisco, Office of the Director, 79/11/30
- 77:23:0277 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, IOCFR21." No action required. ENGELKEN, R. H. Region 5. Ban Francisco, Office of the Director, 79/12/06. 4pp.
- 7912200252 Forwards IE Bulletin 79-28, "Possible Helfunction of Namco Model EA180 Limit Buitches at Elevated Temps." Action required. ENGELKEN,R.H. Region 5, San Francisco, Office of the Director. 79/12/07. ip.
- 7912280626 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required. ENGELKEN,R.H. Region 5, San Francisco, Office of the Director. 79/12/13. 1p.

## DOCKET 50-514 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 1

- A. Application/construction stage documents & correspondence
- 7911280153 Discusses mods to NRC position re status & applicability of TMI-2 accident review & NUREG-0578 to facilities under const. Forwards addl. Info to be considered in development of final plant design & procedures.

  VASBALLO.D. B. Division of Project Management, 79/10/10. App.
- 7912110264 Discusses NRC plans to use generic analyses to develop early varification program to resolve ATMS issue for PMRs & BURS.
  Success of program depends on industry response. Supports formation of owners groups to provide nacessary info.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.

- 7912070004 Requests distribution of encl memorandum to board notification svc lists.

  VARGA-5.A. Assistant Director for Light Water Reactors. 79/11/08.
- D. NRC Draft/Final Environmental Statements, suppls & correspondence
- 7912060968 Forwards NUREG-75/025, draft Suppl 1 to FES re re-evaluation of alternative const sites. Notice of issuance & availability also enti.
  BALLARD.R.L. Environmental Projects Branch 1. 79/11/21. 2pp.
- --7912060575 Notice of issuance & availability of draft Suppl 1 to FES BALLARD, R. L. Environmental Projects Branch 1, 79/11/21, 2pp.
- 7912170056 Forwards DES & FR notice of availability of FES.W/o statement. BALLARD.R.L. Environmental Projects Branch 1, 79/11/21 Ann
- 7912050464 Offers no comments on draft EIS. COTNER.M. L. Agriculture.Dept. of. 79/11/30. 1p.
- 7912120328 Ack receipt of draft Suppl 1 to final EIS.Regrets that review & comments on EIS cannot be made in timely manner pursuant to Natl Environ Policy Act of 1969.
  WALL L.S. Advisory Council on Historic Preservation. 79/12/06.
- 7912270554 Submits no comments following review of draft suppl to FES. NUTT. G. N. Agriculture, Dept. of. 79/12/21. 1p.
- F. Becurity, medical, emergency & fire protection plans
- 7912070469 Notification of 791204 meeting w/utils in Bethesda.MD re NRC info requirements for emergency preparedness.Room change indicated. MODN.C.W. Light Water Reactors Branch 4. 79/11/16. 11pp.
- 9. Adjudicatory correspondence
- 7912060130 Memorandum & order scheduling 791219 conference at Portland. OR. Schedules, State of OR proceeding status & open item status re alternative sites & generic issues will be discussed. No limited appearances will be permitted. BOWERS, E. S. Atomic Safety and Licensing Board Panel. 79/11/16.
- DOCKET 50-515 PEDBLE SPRINGS NUCLEAR PLANT, UNIT 2
- A. Application/construction stage documents & correspondence
- 7911280133 Discusses mods to NRC position re status & applicability of THI-2 accident review & NUREO-0578 to facilities under const. Forwards addl info to be considered in development of final plant design & procedures.

  VASSALLO,D.B. Division of Project Management. 79/10/10. 4pp.
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATWS issue for PMRs & BWRs. Success of program depends on industry response. Supports formation of buners groups to provide necessary info.

  DENTON: H. R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912070004 Requests distribution of encl memorandum to board notification svc lists.

  VAROA: S.A. Assistant Director for Light Hater Reactors. 79/11/08.
- D. NRC Draft/Final Environmental Statements, suppls & correspondence
- 791206086B Forwards NUREG-75/025, draft Suppl 1 to FEB re re-evaluation of alternative const sites. Notice of issuance & availability also encl.

  BALLARD, R. L. Environmental Projects Branch 1, 79/11/21, 2pp.
- --7912060975 Notice of issuance & availability of draft Buppl 1 to FES.
  BALLARD, R. L. Environmental Projects Branch 1, 79/11/21, 2pp.
- 7912170056 Forwards DES & FR notice of availability of FES.W/s statement.
  BALLARD.R.L. Environmental Projects Branch 1. 79/11/21. 4pp.
- 7912050464 Offers no comments on draft EIB. COTNER.M.L. Agriculture.Dept. of. 79/11/30. ip.

- 7912120328 Act receipt of draft Suppl 1 to final EIS.Regrets that review & comments on EIS cannot be made in timely manner pursuant to Natl Environ Policy Act of 1969.
  WALL.L.S. Advisory Council on Historic Preservation. 79/12/06.
- 7912270354 Submits no comments following review of draft suppl to FEU. NUTT, Q. W. Agriculture, Dept. of. 79/12/21. 1p.
- F. Security, medical, emergency & fire protection plans
- 7912070469 Rotification of 791204 meeting w/utils in Bethesda. HD re NRC info requirements for emergency preparadness. Room change indicated. HDONN.C.W. Light Water Reactors Branch 4. 79/11/16. 11pp.
- G. Adjudicatory correspondence
- 7912060130 Hezorandum & order scheduling 791219 confurence at Portland. OR. Schedules, State of OR proceeding status & open item status re alternative sites & generic issues will be discussed. No limited appearances will be parmitted. BORERS.E.S. Atomic Safety and Licensing Board Panel. 79/11/16. 2pp.

## DOCKET STN-50-516 JAMESPORT NUCLEAR STATION, UNIT 1

- A. Application/construction stage documents & correspondence
- 7908070310 Forwards NUREO/CR-0560, "Enhancement of Onsite Emergency Diesel Generator Reliability." Requests comments. W/o encl. VASSALLD, D. B. Assistant Director for Light Hater Reactors. 79/04/18. 3pp.
- 7912110264 Discusses MRG plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRs & BMRs. Success of program depends on industry response. Busports formation of owners groups to provide necessary info. DENTON, M.R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912070004 Requests distribution of encl memorandum to Board notification syc lists.
  VARGA.B.A. Assistant Director for Light Water Reactors. 79/11/08.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review. Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Guide 1.101.

  VASSALID. D. B. Division of Project Management. 79/11/21. 6pp.
- G. Adjudicatory correspondence
- 7912100344 Fifth status rept.per ASLAB 790607 Indefinite extension for NRC to respond to Suffolk County antion to file supplemental brief. Exploring possibility of stipulation re Suffolk County pending action. Certificate of Svc encl.
  BORDENICK, S. M. Hearing Branch 4. 79/11/09. 4pp.
- --7912100348 \*Rules of Practice for Domestic Licensing Proceedings -- Modifies Adjudicatory Procedures, \* 100FR2, effective 791109. Suspends 100FR2, 764 until further notice. Supplementary info encl. CMILK, S. J. Office of the Secretary of the Commission. 79/11/05.
- 7912170227 Notice by NY State Board on Electric Generation Siting & Environ. Replies to utils' application for reheaving of ASLB order dismissing application for certificate of environ compatibility will be accepted if filed by 791203.

  MADISON-S.R. New York. State of. 79/11/20. ip.
- 7912120431 Birth status rept.per ASLAB 790607 grant for indefinite extension to respond to Suffolk County action to file supplemental brief. Kemeny Commission recommendations being revisued a svaluated. Certificate of Bvc encl.
  BORDENICK.B.M. Hearing Branch 4. 79/12/10. 4pp.

- ---7912120455 Proposed rule changes for "Emergency Planning," 100FR30 & App E.Provides interim upgrade of NRC regulations, requiring applicant emergency plans to be approved by NRC Supporting documentation encl.

  2 Commission. 79/12/10. 35pp.
- G. Inspection reports, IE Bulletins & correspondence
- 7912030036 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valvus." No response required.

  CRIEF, S. H. Region 1, Philadelphia, Office of the Director.
  79/11/16. 1p.
- 7912080256 Forwards IE Info Notice 79-27, "Steam Concrator Tube Ruptures at Two PWR Plants." No response required. GRIER, B. H. Region 1, Philadelphia. Office of the Director. 79/11/16. 1p.
- 7912100124 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. GRIER.B.H. Region 1. Philadelphia. Office of the Director. 79/11/16. 1p.
- 7912110413 Forwards IE Info Notice 79-29, "Lose of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. ORIER, B.H. Region 1, Philadelphia, Office of the Director. 79/11/19. 1p.
- 7912050243 Forwards IE Bulletin 79-26, "Boron Loss From HAR Control Blades." No response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director. 79/11/20. ip.
- 7912060574 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BMRs." No response required.

  GRIER.B.H. Region i. Philadelphia. Office of the Director.

  79/11/26. 1p.
- 7912110051 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operats." No response required. ORIER. B. H. Region i. Philadolphia. Office of the Director. 79/11/26. 1p.
- 7912190031 Forwards IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." No written response required. ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/11/30.
- 7712310220 Forwards IE Info Notice 79-30. "Reporting of Defects & Moncompliances. 10CFR21." No action required. GRIER.B.H. Region 1. Philadelphia, Office of the Director. 77712706. 4pp.
- 7912190750 Forwards IE Bulletin 79-28, "Possible Halfunction of Name: Model EA180 Limit Buitches at Elevated Temps." Written response required.
  ORIER, B. H. Region 1. Philadelphia. Office of the Director.
  79/12/07. 19.
- 7912280200 Forwards IE Info Natice 79-31. "Use of Incorrect Amplified Response Spactra." No written response required. GRIER. B. H. Region 1. Philadelphia, Office of the Director. 79/12/13. 1p.
- DOCKET STN-50-517 JAMESPORT NUCLEAR STATION, UNIT 2
- A. Application/construction stage documents & correspondence
- 790B070310 Forwards MUREO/CR-0860, "Enhancement of Onsite Emergency Diesel Generator Reliability," Requests comments W/o encl. VABSALLO.D.B. Assistant Director for Light Water Reactors. 79/De/18 | Jan.
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRs & BMRs. Buccess of program depends on industry response. Supports formation of center groups to provide necessary info.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. Days.
- 7912070004 Requests distribution of encl memorandum to board notification svc lists. VARGA.S.A. Assistant Director for Light Water Reactors. 79/11/09. Opp.

### F. Becurity, medical, emergency & fire protection plans

7912040471 Forwards info re upgraded emergency plans to plants under const & CL review. Applicants required to aske certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Quide 1.101.

VASSALLO, D. B. Division of Project Management. 79/11/21. 6pp.

#### Q. Adjudicatory correspondence

- 7912100344 Fifth status rept.per ASLAB 790607 indefinite extension for NRC to respond to Suffolk County action to file supplemental brief. Exploring possibility of stipulation re Suffolk County pending action. Cartificate of Svc encl.
  BORDENICK, B. M. Hearing Branch 4. 79/11/09. 4pp.
- 7912170227 Notice by NY State Board on Electric Generation Siting & Environ Replies to utils' application for rehearing of ABLB order disalasing application for certificate of environ coapatibility will be accepted if filed by 791203.

  HADISON, B. R. New York, State of, 79/11/20. ip.
- 7912120431 Sixth status rept.per ASLAB 790607 grant for indefinite extension to respond to Suffoli County motion to file supplemental brief. Remeny Commission recommendations being reviewed & evaluated. Certificate of Svc anci.
  BORDENICK.B.M. Hearing Stanch 4. 79/12/10. 4pp.

#### Q. Inspection reports, IE Bulletins & correspondence

- 7912050036 Forwards IE Gircular 79-22, "Stroke Times for Power Operated Relief Valves." No response required. ORIER.B.H. Region 1. Philadelphia. Office of the Director. 79/11/16. 1p.
- 7912050236 Forwards IE Info Notice 79-27, "Steam Cenerator Tube Ruptures at Two PHR Plants." No response required. CRIER.3.H. Region i. Philadelphia, Office of the Director. 79/11/16. 1p.
- 7912100124 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/11/16. 1p.
- 7912110413 Ferwards JE Info Notice 79-29. "Loss of Nonsefety-Related Reactor Goolant Bys Instrumentation During Operation." No specific action or response required. ORIER, B. H. Region 1. Philadelphia. Office of the Director. 79/11/19. 1p.
- 7912050243 Forwards IE Bulletin 79-26, "Boron Loss From BUR Control Blades." No response required. GRIER, B.H. Region i, Philadelphia, Office of the Director. 79/11/20. Ip.
- 7912060574 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pips Break Detection Equipment on BMRs." No response required.

  GRICE, B. H. Region 1, Philadelphia, Office of the Director.

  79/11/26, ip.
- 7912110051 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director. 79/11/26. 1p.
- 79/2190031 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation." No written response required. ORIEN.E.H. Region 1, Philadelphia, Office of the Director. 79/11/30. 1
- 79:2310220 Forwards IE Info Notice 79-30, "Reporting of Defects & Honcompliances, iOCFR21." No action required, ORIER, B.H. Region i, Philadelphia, Office of the Director, 79/12/06.
- 7912190730 Forwards IE Bulletin 79-28. "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Written response required. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/12/07. 1p.
- 7912280200 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required. GRIER, B. H. Region 1. Philadelphia. Office of the Director. 79/12/13. 1p.

- DOCKET STN-50-518 HARTSVILLE NUCLEAR PLANT, UNIT 1
- A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early varification program to resolve ATWS issue for PMRs & BWRs. Success of program depends on industry response. Supports formation of owners groups to provide necessary info. DENTON. H. R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.
- 7911140152 Amend 3 to CPPR-150, CPPR-151, CPPR-152 & CPPR-153 deleting requirements for add1 studies to estimate & evaluate drift deposition impact associated w/cooling tower operation.
  VABSALLO, D. B. Division of Project Management. 79/10/23. 4pp.
- 7912140232 Forwards topographic maps, clearing & seeding spacs & findings & attigative actions re transalssion line const.
  Drawlings available in Central Files only.
  MILLS, L. M. Tennessee Valley Authority. 79/11/30. 21pp.
- 7912130023 Notification of 800110 meeting w/util to discuss reporting level of util GA & manager & GA review of documents.

  SPRAUL, J. Q. Guality Assurance Branch, 79/12/05. 1p.
- 7912280607 Forwards "Const Effects Honitoring Program." EL-ASHRY, M. T. Tennessee Valley Authority. 79/12/19. 1p.
- ---7912280613 "Const Effects Monitoring Program."
  \* Tennessee Valley Authority, 79/12/19. 2pp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review. Applicants required to make certain emergency arrangements w/state & local organizations & submit seargency plans per Reg Quide 1.101. VASBALLO.D.B. Division of Project Management. 79/11/21. App.
- O. Adjudicatory correspondence
- 7912110043 Forwards comments on NUREQ-0511 Draft QEIS reflects conscious & deliberate NRC policy to jeopardize public health & safety & thwart objectives of NEPA.

  KEPFORD, C. Environmental Coalition on Nuclear Power. 79/10/24.
- Q. Inspaction reports. IE Bulletins & correspondence
- 7912030323 Forwards IE Insp Repts 50-518/79-23,50-519/79-23, 50-520/79-23 & 50-521/79-23 on 790925-28. No noncoepliance noted. MRRPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/10/25. 2pp.
- 7912060163 Forwards IE Info Notice 79-12A. "Attempted Damage to New Fuel Assemblies." No specific action or response required. O'RETLLYJ.P. Region 2. Atlanta. Office of the Director. 79/11/09. 3pp.
- 7912070479 Forwards IE Info Notice 79-27, "Steam Concrator Tube Ruptures at Two PLR Plants." O'REILLYJ.P. Region 2. Atlanta. Office of the Director. 79/11/16. 14pp.
- 7912100192 Forwards 1E Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads." No response required. O'AEILLY, J.P. Region 2. Atlanta, Office of the Director. 79/11/16. 1p.
- 7912110575 Forwards IE Info Notice 79-29, "Loss of Nonsafaty-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. O'REILLY.U.P. Region 2, Atlanta, Office of the Director. 79/11/16. 29p.

- 79120A0520 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No rasponse required.
  O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
  79/11/25. 1p.
- 7912110157 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/11/26. 1p.
- 7912190478 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." No written response required. O'RELLY'J.P. Region 2, Atlanta, Office of the Director. 79/11/30. ip.
- 7912310316 Forwards IE Info Notice 79-30. "Reporting of Defects & Noncompliances: IOCFR21." No action required. G'REILLY.J.P. Region 2. Atlanta, Office of the Director. 79/12/06. 6pp.
- 7912200060 Forwards IE Bulletin 79-28, "Possible Halfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. O'REILLY J.P. Region 2. Atlanta, Office of the Director. 79/12/07. 3pp.
- 7912280426 Forwards IE Info Notice 79-31. "Use of Incorrect Amplified Response Spectra." No written response required. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 79/12/13. 3pp.
- 7912280150 Forwards IE Circular 79-25, "Shock Arrestor Strut Assembly Interference." No written response required, O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/12/20. 4pp.
- S. Reportable occurrences. LERs & related correspondence
- 7912210039 PNO-II-79-014: on 791025, immediate action ltr issued to TVA confirming that actions assuring design of reactor vessel pedestals not compromised during extensive weld repairs will be completed prior to placing concrete around structure. CANITELL.F.S., HERDI.A.R. Region 2, Atlanta, Office of the Director. 79/10/25. ip.
- 7912130581 Forwards final deficiency rept re design deficiency of T-head section of Anchor/Darling gate valves.
  MILLS,L.M. Tennessee Valley Authority. 79/11/15. 1p.
- --7912130601 Final deficiency rept re design deficiency of T-head section of Anchor/Darling gate valves. Company has implemented results of evaluation of T-head section for svc condition, into internal design std.

  \* Tennessee Valley Authority. 79/11/15. 2pp.

## DOCKET STN-50-519 HARTSVILLE NUCLEAR PLANT, UNIT 2

- A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRs & BHRs.
  Success of program depends on industry response. Supports formation of owners groups to provide necessary info.
  DENTIN.H.R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912140232 Forwards topographic maps, clearing & seeding specs & findings & mitigative actions re transmission line const. Brawings available in Central Files only.
  MILLE.L.M. Tennessee Valley Authority. 79/11/30. 21pp.
- 7912130023 Notification of 800110 meeting w/util to discuss reporting level of util GA & manager & GA review of documents.

  SPRAUL, J. G. Quality Assurance Branch. 79/12/05, 1p.
- 7912280607 Forwards "Const Effects Monitoring Program." EL-ASHRY.M.T. Tennessee Valley Authority. 79/12/19. 1p.
- --7912280613 "Const Effects Monitoring Program."
  \* Tennessee Valley Authority. 79/12/19. 2pp.

- F. Security, modical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & CL review. Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Guide 1.101.
  VASSALLO, D. B. Division of Project Management. 79/11/21. 6pp.
- G. Adjudicatory correspondence
- 7912110043 Forwards comments on NUREO-0511. Draft GEIB reflects conscious & deliberate NRC policy to jeopardize public health & safety & thwart objectives of NEPA.

  KEPFORD, C. Environmental Coalition on Nuclear Power. 79/10/24.
- G. Inspection reports. IE Bulletins & correspondence
- 7912050323 Forwards IE Insp Repts 50-518/79-23, 50-519/79-23, 50-520/79-23 & 50-521/79-23 on 790925-28. No nancompliance noted. HURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/10/25. 2pp.
- ---7912050338 IE Insp Repts 50-518/79-23, 30-519/79-23, 50-520/79-23 & 50-521/79-23 on 790925-28. No noncompliance noted Major areas inspected: steel structures & supports & welding matl control.

  BLAKE.J.J. Region 2, Atlanta, Office of the Director, HERDT.A.R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/10/24. App.
- 79:2050:63 Forwards IE Info Notice 79-12A. "Attempted Damage to New Fuel Assemblies." No spacific action or response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/11/09. 3pp.
- 7912070499 Forwards IE Info Notice 79-27, "Steam Generator Tube Ruptures at Two PWR Plants." D'REILLY,J.P. Region 2, Atlanta, Office of the Director. 79/11/16. 14pp.
- 7912100192 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads," No response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/16. 1p.
- 7912110575 Forwards IE Info Notice 79-29, "Loss of Nonsefety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required.

  O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
  79/11/16. 2pp.
- 7912060620 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/26. 1p.
- 7912110157 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required.
  O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
  79/11/26. ip.
- 7912190478 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation." No written response required. ("REILLY,J.P. Region 2, Atlanta, Office of the Director. 79/11/30. ip.
- 7912310316 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, iOCFR21." No action required.
  O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
  79/12/06. 6pp.
- 7912200060 Forwards IE Bulletin 79-28. "Possible Maifunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/12/07. 3pp.
- 7912280426 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra," No written response required.
  O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
  79/12/13. 3pp.

- 7912280150 Forwards IE Circular 79-25, "Shock Arrestor Strut Assembly Interference." No written response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director, 79/12/20. 4pp.
- S. Reportable occurrences. LERs & related correspondence
- 7912130581 Forwards final deficiency rept re design deficiency of Thead section of Anchor/Darling gate valves. MILLS.L.M. Tennessee Vallay Authority. 79/11/15. ip.
- --7912130601 Final deficiency rept re design deficiency of T-head section of Anchor/Darling gate valves. Company has implemented results of evaluation of T-head section for syc condition, into internal design std.

  \* Tennesses Valley Authority. 79/11/15. 2pp.
- DOCKET STN-50-520 HARTSVILLE NUCLEAR PLANT, UNIT 3
- A. Application/construction stage documents & correspondence
- 79:21:10:264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATHS issue for PHRs & DHRs. Buccess of program depends on industry response. Supports formation of owners groups to provide necessary info. DENTON, H. R. Dffice of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912140232 Forwards topographic maps, clearing & seeding specs & findings & mitigative actions re transmission line const. Drawings available in Central Files only, MILLS.L.M. Tannesses Valley Authority. 79/11/30. 21pp.
- 7912130023 Notification of 800110 masting w/util to discuss reporting level of util GA & manager & GA review of documents, SPRAUL.J.Q. Quality Assurance Branch. 79/12/05. 1p.
- 7912280607 Forwards "Const Effects Monitoring Program." EL-ASHRY.M.T. Tennessee Valley Authority. 79/12/19. 1p.
- --7919280613 "Const Effects Monitoring Program," \* Tennesses Valley Authority. 79/12/19. 2pp.
- F. Becurity, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review. Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Rag Guide 1, 101.
  VABSALLO, D. B. Division of Froject Management. 79/11/21. 6pp.
- 9. Adjudicatory correspondence
- 7912110043 Forwards comments on NUREG-0511. Draft GEIS reflects conscious & deliberate NRC policy to jeopardize public health & safety & thwart objectives of NEPA.
  KEPFORD. C. Environmental Coelition on Nuclear Power. 79/10/24.
- G. Inspection reports, IE Bulletins & correspondence
- 7912050323 Forwards IE Insp Repts 50-519/79-23,50-519/79-23, 50-520/79-23 & 50-521/79-23 on 790925-28, No noncompliance noted. MURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch, 79/10/25, 2pp.
- --7912050338 IE Insp Repts 50-518/79-23,50-519/79-23,50-520/79-23 & 50-521/79-23 on 790925-28. No noncompliance noted Major areas inspected: steel structures & supports & walding metl control.

  BLAKE, J. J. Region 2, Atlanta, Office of the Director.
  HEADTIA, R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/10/24. App.
- 7912060163 Forwards IE Info Notice 79-12A, "Attempted Damage to New Fuel Assemblies," No specific action or response required. D'RELLLY, J. P., Region 2, Atlanta, Office of the Director. 79/11/09. 3pp.
- 7912070499 Forwards IE info Notice 79-27, "Steam Generator Tube Ruptures at Two PHR Plants." O'REILLY.U.F. Region 2, Atlanta, Office of the Director. 79/11/16. 14pp.

- 7912100192 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. O'REILLY,J.P. Region 2, Atlanta, Office of the Director. 79/11/16. 1p.
- 79:21:0375 Forwards IE Info Notice 79-27. "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required. D'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/16. 2pp.
- 7912060620 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Byray Pipe Break Detection Equipment on IWRs." No response required.

  O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
  79/11/24, 1a
- 7912110197 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required.

  O'REILLY, J. P. Region 2, Atlanta, Office of the Director.

  79/11/26. ip.
- 7912190478 Forwards IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 79/11/30. 1p.
- 7912310316 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 100FR21," No action required, O'REILLY, J.P. Region 2, Atlanta, Office of the Director, 79/12/06. 6pp.
- 7912200060 Forwards IE Bulletin 79-28. "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Tamps." Action required. O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 79/12/07. 3pp.
- 7912280426 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Beetra." No written response required.
  O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
  79/12/13. 3pp.
- 79:2280:50 Forwards IE Circular 79-25, "Shock Arrestor Strut Assembly Interference," No written response required.
  0'ABILLY.J.P. Region 2, Atlanta, Office of the Director.
  79/12/20. 4pp.
- S. Reportable occurrences, LERs & related correspondence
- 7912210039 PNO-II-79-014: on 791025, immediate action ltr issued to TVA confirming that actions assuring design of reactor vessel pedestals not compromised during extensive weld repairs will be completed prior to placing concrete around structure. CANTRELL.F.S., HERDT.A.R. Region 2, Atlanta, Office of the Director. 79/10/25, ig.
- 7912130581 Forwards final deficiency rept re design deficiency of T-head section of Anchor/Darling gate valves.
  MILLS,L.M. Tennessee Valley Authority. 79/11/15. ip.
- --7912130401 Final deficiency rept re design deficiency of T-head section of Anchor/Derling gate valves. Company has implemented results of evaluation of T-head section for svc condition, into internal design std.

  \* Tannessee Valley Authority. 79/11/15. 2pp.
- DOCKET STN-50-521 HARTSVILLE NUCLEAR PLANT, UNIT 4
- A. Application/construction stage documents & correspondence
- 7712110264 Discusses NRC plans to use generic analyses to develop early varification program to resolve ATMS issue for PMRs & BMRs. Success of program depends on industry response, Eupports formation of owners groups to provide necessary info. DENTON. H. R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912140232 Forwards topographic maps, clearing & seeding spacs & findings & mitigative actions re transmission line const, Drawings available in Central Files only, MILLS, L.M. Tennessee Valley Authority, 79/11/30. 21pp.
- 791R1300R3 Notification of 800110 meeting w/util to discuss reporting level of util GA & manager & GA review of documents.

  SPRAUL, J. Q. Quality Assurance Branch. 79/12/05. 1p.

- 7912280807 Forwards "Const Effects Monitoring Program." EL-ASHRY.M.F. Tennessee Valley Authority. 79/12/19. 1p.
- F. Security, sedical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & GL review. Applicants required to make certain emergency arrangements w/state & local organizations & submit swergency plans per Reg Guide 1.101.
  VASSALLO, D. B. Division of Project Management. 79/11/21. App.
- O. Adjudicatory correspondence
- 79:21:10043 Forwards comments on NUREG-OS:1. Draft GEIS reflects constitute & deliberate NRC policy to jeopardize public health & safety & thwart objectives of NEPA.
  MEPFORD, C. Environmental Coalition on Nuclear Power. 79/10/24.
- G. Inspection reports, IE Bulletins & correspondence
- 7912050323 Forwards 1E Insp Repts 50-518/79-23, 50-519/79-23, 50-520/79-23 & 30-521/79-23 on 790925-28. No noncompliance nated. MRPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/10/25. 2pp.
- 7912060163 Forwards IE Info Notice 79-12A, "Attempted Damage to New Fuel Assemblies." No specific action or response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/11/09. 3pp.
- 7912070499 Forwards IE Info Notice 79-27. "Steam Cenerator Tube Ruptures at Two PUR Plants." O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 79/11/16. 14pp.
- 7912100192 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. D'AEILLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/16. 1p.
- 7912110575 Forwards IE Info Notice 79-29, "Loss of Nonsefety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/11/16. 2pp.
- 7912060620 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No response required. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 79/11/26. 1p.
- 7912110157 Forwards IE Circular 79-23, "Notor Starters & Contactors Failed to Operate." No response required.
  O'REILLY. J.P. Region 2. Atlanta. Office of the Director.
  79/11/26. 1p.
- 7912190478 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation." No written response required.

  O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 79/11/30. is.

N=mco

٠ &

\*\*\*\*\*\*\*\*\*\* Jpp.

7912280426 Forwards IE Info Notice 77-31. "Use of Incorrect Amplified Response Spectra." No written response required. D'RELLLY, J.P. Region 2. Atlanta, Office of the Director. 79/12/13. 3pp.

- 7912280150 Forwards IE Circular 79-25, "Shock Arrestor Strut Assacbly Interference." No written response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/12/20. 4pp.
- 8. Reportable occurrences, LERs & related correspondence
- 79:2(3058) Forwards final deficiency rept re design deficiency of Thead section of Anchor/Darling gate valves. MILLS.L.M. Tennesses Valley Authority. 79/11/15. ip.
- --7912130501 Final deficiency rept re design deficiency of T-head section of Anchor/Darling gate valves. Company has implemented results of evaluation of T-head section for svc condition, into internal design std.

  \*\*Tennessee Valley Authority. 79/11/15. 2pp.
- DOCKET BIN-50-522 SKAGIT NUCLEAR POWER PROJECT, UNIT 1

  A. Application/construction stage documents & correspondence
- 7911280153 Discusses mods to NRC position re status & applicability of TMI-2 accident review & NUREG-0578 to facilities under const. Forwards addl info to be considered in development of final plant design & procedures.

  VASBALLO, D. D. Division of Project Hanagement. 79/10/10. 4pp.
- 7912110264 Discusses NRC plans to use generic analyses to develop early varification program to resolve ATH9 issue for PMRs & BHRs.
  Success of program depends on industry response. Supports formation of owners groups to provide nacessary info.
  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.
- 7912310080 Summary of 791026 meeting w/Bechtel. USOS & util in Sethesda.

  MD re new USOS data which could revise evaluation of geology
  & seismology re high angle faults not previously considered
  for potential high energy generators.

  PELTIER, I. A. Light Water Reactors Branch 1. 79/12/05, 4pp.
- 7912270215 Forwards Mobil Cil Corp shot point map for Whidbey Island vicinity. Map available in Central Files only.
  MECCA: J. E. Puget Bound Power & Light Co. 79/12/19. 2pp.
- C. Utility Environmental Report (ER), amends & correspondence
- 791220009B Forwards updated distribution list for environ rept suppls & amends for facility.

  DUNCAN, M. Environmental Projects Branch 2. 79/12/07. Spp.
- D. NRC Draft/Final Environmental Statements, suppls & correspondence
- 7912310113 Advises of error in EIB re impact on demography, agriculture & industry from increase in moisture. Dumping 24 million gallons of water per day will bring cloudiness & hours or days of heavy drizzle.

  BRADY, E. Affiliation Unknown. 79/11/13. ip.
- F. Security, medical, emergency & fire protection plans
- 7912070469 Notification of 791204 meeting w/utils in Bethesda, HD re NRC info requirements for emergency preparedness. Room change indicated. HOON.C.W. Light Water Reactors Branch 4. 79/11/16. 11pp.
- 9. Adjudicatory correspondence
- 7912030007 Answers in opposition to intervenor Skagitonians Concerned About Nuclear Power 791017 motion for implementation of Executive Order 12114. FEB & final suppl to FEB addressed environ issues. Certificate of Svc ancl THOMBEN.F.T. LITTLE.D.S., BAUBER.M.A. Puget Sound Power & Light Co., 79/11/01. Spp.
- 7912060101 Request to postpone geologic & seismic evidentiary hearings until after applicant responds to USOS outstanding concerns. RE Jackson affidavit & Certificate of Svc encl. BLACK, R. L. Hearing Branch 1. 79/11/02. App.
- 7912050115 Requests extension until 791109 for intevenor Bkegitonians Concerned About Nuclear Power to file proposed findings reapplicant financial qualifications.

  OENDLER, M. W. Leed, Robert M. 79/11/05. ip.

- --7912040125 Applies for subposes to take deposition of Hestern Geophysical re geology & seismology of Hestern HA & Puget Bound region. Proposed deposes is in possession of important data. Certificate of Svc encl. GENDLER, M. W. Lead, Robert M. 79/11/05. 3pp.
- 7912200102 "Rules of Practice for Domestic Licensing Proceedings," 10CFR2 effective rule Suspends rule of practice on issuance of licenses after adjudicatory proceedings. Forwarding ltr & Certificate of Euc encl.
  CHILK.S. J. Office of the Secretary of the Commission. 79/11/05. 109p.
- 7912070355 Response in opposition to Skagitonions Concerned About Nuclear Power 791114 motion to direct certification, stay proceedings & review ASLB actions. Detriment to public interpset as basis for interlocutory review not established. THOMSEN.F.T. LITTLE.D.B. Puget Sound Power & Light Co. THOMSEN.F.T. Perkins, Coie, Stone, Olsen & Williams. 79/11/08. 1506.
- --7912070472 Presents applicants' position re util evidence on geology & seismology scheduled per Black/Leed & Thomsen agreement on order of presentation for 790717 session. Applicants' presentation must be postponed. Cartificate of Byc encl. THOMBEN, F. T. Perkins, Coie, Stone, Olsen & Williams, 79/06/29.
- 7912110267 Ack receipt of 791018 ltr. Subpoens forms completed & returned for signature. Skagitonians Concerned About Nuclear Power 791025 ltr demonstrated relevance of testimony sought from three experts on geology & seismology.

  LEED, R. M. Leed, Robert M. 79/11/08. ip.
- 7912100344 Fifth status rept.per ABLAB 790607 indefinite extension for NRC to respond to Buffolk County motion to file supplemental brief. Exploring possibility of stipulation re Suffolk County pending motion. Certificate of Svc encl. BORDENICK, B. M. Hearing Branch 4, 79/11/09. 4pp.
- --7912100348 "Rules of Practice for Domestic Licensing Proceedings -- Modifies Adjudicatory Procedures." 10CFR2, effective 791109, Suspends 10CFR2, 764 until further notice, Supplementary info encl.

  CHILM, 8, J. Office of the Secretary of the Commission. 79/11/05, 10pp.
- 7912140025 Pleading re applicants' financial qualifications. Total cost of project exceeds applicants' figures. Certificate of Svc encl.

  LEED, R. M. Leed, Robert M. 79/11/09. 12pp.
- 7912170152 Response in opposition to Skegitonians Concerned About Nuclear Power 791017 & 24 motions to direct certification & stay proceeding Edds not met ASLAB discretionary involvement not warranted Certificate of Syc encl.

  BLACK.R.i. Hearing Branch 1. 79/11/13. 18pp.
- 7912170216 Response to CA Energy Commission 791024 motion for reconsideration of ASLB 791005 order ruling on scope of contentions, Urges inclusion of emergency planning issues & exclusion of offsite matters.

  LEWIG. 8. H. Hearing Branch 2. 79/11/13. 7pp.
- --7912170236 "Modified Adjudicatory Procedures," 10CFR2.764 suspension & statement of policy on conduct of adjudicatory proceedings. Constitutes final action on petitions received in proceedings. SJ Chilk 791105 suppl & Certificate of Svc encl. \* Office of the Secratary of the Commission. 79/11/09. 12pp.
- 7912050148 Order extanding to 791121 time to respond to Intervenor Tribes supplemental petition for revisu. CHILK.S.J. Office of the Secretary of the Commission. 79/11/20. ip.
- 7912060072 Memorandum & order ALAB-B72 denying Skagitonians Concerned About Nuclear Power motion requesting interlocutory review by directed certification Intervenor complaints re exclusion of redon issue & seismology set do not warrant intercession. BISHOP, C. J. Atomic Bafety and Licensing Appeal Panel. 79/11/20, 7pp.
- 7912050130 Order denying Greenpeace Foundation of Vancouver, British Columbia, 790913 petition to intervens. No good cause shown. Contention of improving record speculative, Proper interest not established. Petitioner documentation encl.

  DEALE, V. B. Atomic Gafaty and Licensing Board Panel. 79/11/20.

  Zipp.

- 7912100473 Response in opposition to Indian Tribes 791105 supplemental patition for ALAB-552 & ALAB-559 review. Patitioner failed to raise good cause re alleged ASLB misapplication of late intervention factor. Certificate of Svc encl. LITTLE, D. B. Puget Bound Power & Light Co. LITTLE, D. B. Perkins, Coie. Stone, Olsen & Williams. 79/11/20. 12pp.
- 7912080376 Response in apposition to Indian Tribes 780613 petition to intervene. Stds for Commission review re procedural, policy & factual issues not met. Certificate of Svc encl. BLACK,R.L. Hearing Branch i. 79/11/21. 14pp.
- 7912030059 Order granting extension until 791217 for Commission to determine whether to review ALAB-559.
  CHILK-S. J. Diffice of the Secretary of the Commission. 79/11/26.
- 7912060004 Bubmits typographical correction to NRC 791121 response in apposition to Indian Tribes supplemental patition for review. Corrected page re last paragraph. Line 3 encl. BLACK.R.L. Hearing Branch 1. 79/11/26. 2pp.
- 7912050421 Request for extension to 791221 to file proposed findings of fact & conclusions of law Opposing attys have no objection.
  BLACK.R.L. Hearing Branch 1. 79/11/28. Spp.
- 7912100132 Advises that Coalition for Safe Power petition to review ASLB decision is deemed denied due to Commission negative exercise of discretion to take review. States Commissioners Glinsky & Bradford dissenting views.

  CHILK.S. J. Office of the Secretary of the Commission. 79/11/29.
- 7912110407 Order denying intervenor Skagitomians Against Nuclear Power 790927 request for ASLB reconsideration of 790913 orders.

  D Btensby 790913 affidavit insufficient re concentration of cycles issue.

  DEALE, V.B. Atomic Bafety and Licensing Board Panel 79/11/30. 9pp.
- 79:2170020 Raply in opposition to intervenor Forelaws on Board/Citizens for Safe Power findings of fact re alternative sites & postulated accidents. Certificate of Svc encl.
  THOMBEN.F.T., LITTLE.D.B. Puget Sound Power & Light Co.
  THOMBEN.F.T. Perkins. Coie, Stone, Olsen & Williams. 79/11/30.
  RDs.
- ---7912170041 Reply to NRC 791005 proposed findings of fact Urges Board to reject Recommendation 3 contained in Finding 44, Pages 27-28. Condition re environ evaluation prior to commencement of const activities is not authorized by NEPA & NRC rules. THOMSEN, F. T., LITTLE, D. S. Puget Sound Power & Light Co. THOMSEN, F. T. Perkins, Coie, Stone, Disen & Williams, 79/11/30.
- ---7912170048 Reply to Stagitonians Concerned About Nuclear Power 791112 proposed findings of fact.FEB & FES final suppl addressed environ impacts & whole population issues indiscriminately Certificate of Svc encl.

  THOMSEN.F.T., LITTLE.D.S. Puget Sound Power & Light Co.
  THOMSEN.F.T. Perkins, Cole, Stone, Olsen & Williams, 79/11/30, 1000p.
- 7912260039 Reply to Skagitonians Concerned About Nuclear Power 791109 proposed findings on financial qualifications. Intervenor adopted short-term view rather than long-term considerations re inflation rates & market ratios, Certificate of Bvc encl. THOMBEN.F.T. Puget Bound Power & Light Co. THOMSEN.F.T. Parkins, Coie, Btone, Olson & Williams. 79/12/05. 4pp.
- 7912310494 Forwards draft subposna for Hestern Geophysical Codeposition.per 791109 ltr. Bignature requested. OENDLER,M. H. Leed. Robert M. 79/12/05. 2pp.
- 7912140117 Responds to 791203 request for extension until 791203 for filing certain replies & request for extension until 791207 time to reply to intervenor Blagitonians Against Nuclear Power findings re finencial qualifications.

  DEALE.V.B. Atomic Safety and Licensing Board Panel. 79/12/06. 1p.
- 79:12310503 Advises that TF Carr has been replaced by KM Ryan as counsel in proceeding. Title & address remain unchanged. RYAN, K. M. Washington, State of. 79/12/06. ip.
- 7912270090 Forwards NRC subposes form addressed to officers of Western Geophysical Co.in response to 791205 request.
  DEALE, V. B. Atomic Safety and Licensing Board Panel. 79/12/10. 2pp.

- 7912270106 Denies intervenor Skagitonians Concerned About Nuclear Power 791017 request that ASLB implement Executive Order 12114. NRC is independent agency not within Executive Dept. Intervenor has no standing under order. DEALE, V.B. Atomic Safety and Licensing Board Panel. 79/12/10. 3pp.
- 7912270054 Forwards AO Hotulsky rept. "Possible Impact of Planned Nuclear Power Plant on Skagtt Indian Population." in response to intervention attempt by Indian Tribes. BLACK.R.L. Hearing Branch 1. 79/12/14. 1p.
- --7912270055 Forwards "Possible Impact of Planned Nuclear Power Plant on Skagit Indian Population." MOTULSKY.A.O. Hashington, Univ. of. 79/10/30. 1p.
- --7912270059 "Possible Inpact of Planned Nuclear Power Plant on Skagit Indian Population." MOTULSKY.A.Q. Washington, Univ. of. 79/10/30. 5pp.
- 7912240369 Order granting extension until 800118 for Commission to elect whether to review ALAB-559.
  CHILK.S. J. Diffice of the Secretary of the Commission. 79/12/17.
- 7912310207 Act receipt of 791207 ltr requesting permission to appeal ASLB 791120 decision. DEALE.V.B. Atomic Safety and Licensing Board Panel. 79/12/17. 1p.

#### H. General correspondence

- 7912170358 Forwards NUREQ-0555, NUREG-0625, NUREG-0578, SECY-79-300 & SECY-79-36, in response to 791114 & 20 requests for documents. Explains NRC policy re distribution of documents. Expective Order 11988 may be requested under FOIA. BLACK, R. L. Hearing Branch 1. 79/12/10. 2pp.
- 7912270512 Notifies of personnel change for manager of nuclear licensing & safety. H Stimar replaced by JE Mecca. MECCA.J.E. Puget Sound Power & Light Co. 79/12/20. 1p.
- DOCKET 9TN-50-523 SKAGIT NUCLEAR POWER PROJECT. UNIT 2

  A. Application/construction stage documents & correspondence
- 7911280153 Discusses mods to NRC position re status & applicability of TMI-2 accident review & NUREO-0578 to facilities under const Forwards addl info to be considered in development of final plant design & procedures.

  VASSALLO.D.8. Division of Project Management. 79/10/10. 4pp.
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATHS issue for FMRs & BHRs. Success of program depends on industry response. Bupports formation of owners groups to provide necessary info.

  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912310080 Summary of 791026 meeting w/Bechtel, USSS & util in Bethesda, MD re new USSS data which could revise evaluation of geology & seismology re high angle faults not previously considered for potential high energy generators.
  PELTIER, I. A. Light Water Reactors Branch 1. 79/12/05. 4pp.
- 7912270215 Forwards Mobil Gil Corp shot point map for Whidbey Island vicinity. Map available in Central Files only.
  MECCA.J.E. Puget Sound Power & Light Co. 79/12/19. 2pp.
- C. Utility Environmental Report (ER), amends & correspondence
- 7912200098 Forwards updated distribution list for environ rept suppls & amends for facility.

upple & correspondence

praphy, agriculture lion urs or

- G. Adjudicatory correspondence
- 7912030007 Answers in opposition to intervenor Skagitonians Concerned About Nuclear Power 791017 motion for implementation of Executive Order 12114.FES & final suppl to FES addressed environ issues. Certificate of Svc anci. THOMSEN.F.T., LITTLE, D. S., BAUSER, M. A. Puget Sound Power & Light Co. 79/11/01. Spp.
- 7912060101 Request to postpone geologic & seismic evidentiary hearings until after applicant responds to USQS outstanding concerns. RE Jackson affidavit & Certificate of Svc encl. BLACK.R.L. Hearing Branch 1. 79/11/02. 6pp.
- 7912060115 Requests extension until 791109 for intevenor Bkagitonians Concerned About Nuclear Power to file proposed findings re applicant financial qualifications. GENDLER.M. W. Leed, Robert M. 79/11/05, 1p.
- --79120A0125 Applies for subpoena to take deposition of Western Geophysical re geology & seismology of Western WA & Puget Sound region.Proposed deposes is in possession of important data.Centificate of Svc secl. GENDLER,M.W. Leed, Robert M. 79/11/05. 3pp.
- 7912200102 "Rules of Practice for Domestic Licensing Proceedings," 10GFR2 effective rule. Suspends rule of practice on issuance of licenses after adjudicatory proceedings. Forwarding ltr & Certificate of Svc encl. CHILK.S.J. Office of the Secretary of the Commission. 79/11/05.10no.
- 7912070395 Response in opposition to Skagitonions Concerned About Nuclear Power 791116 motion to direct certification stay graceedings & review ASLB actions. Detriment to public interest as basis for interlocutory review not established. THOMSEN.F.T., LITTLE,D.S., Puget Sound Power & Light Co. THOMSEN.F.T., Perkins, Coie, Stone, Olsen & Williams. 79/11/08. 15pp.
- --7912070472 Prosents applicants' position ra util evidence on geology & saismology scheduled per Black.Leed & Thomsen agreement on order of presentation for 790717 session, Applicants' presentation must be postponed Certificate of 9vc encl. THOMBEN, F. T. Perkins, Coie, Stone, Olsen & Williams. 79/06/29.
- 791R110267 Ack receipt of 791018 ltr. Subpoens forms completed & returned for signature. Skagitonians Concerned About Nuclear Power 791028 ltr demonstrated relevance of testimony sought from three experts on geology & se
- 7912100344 Fifth status rept.per ASLAB 790607 indefinite extension for NRC to respond to Suffolk County motion to file supplemental brise. Exploring possibility of stipulation re Suffolk County pending motion. Certificate of Svc encl. BORDENICK, B. M. Hearing Branch 4. 79/11/09. 4pp.
- --7912100348 "Rules of Practice for Domestic Licensing Proceedings -- Modifies Adjudicatory Proceedures," 10CFR2, effective 791109.
  Suspends 10CFR2. 764 until further notice. Supplementary infoent.
  CMILK, S. J. Office of the Secretary of the Commission. 79/11/05. 10pp.
- 7912140025 Pleading re applicants' financial qualifications. Total cost of project exceeds applicants' figures. Certificate of Svc encl.
  LEED.R.M. Leed. Robert M. 79/11/09. 12pp.
- 7912170152 Response in opposition to Skapitonians Concerned About Nuclear Power 791017 & 24 motions to direct certification & stay proceeding Stds not met ASLAB discretionary involvement not warranted. Certificate of Svc encl.

  BLACK, R. L. Hearing Branch 1. 79/11/13. 18pp.
- 7912170216 Response to CA Energy Commission 791024 motion for reconsideration of ABLB 791005 order ruling on scope of contentions. Urges inclusion of emergency planning issues & exclusion of offsite matters.

  LEWIG.S.H. Hearing Branch 2. 79/11/13: 7pp.
- --7912170236 "Modified Adjudicatory Procedures," 10CFR2.764 suspension & statement of policy on conduct of adjudicatory proceedings. Constitutes final action on petitions received in proceedings. By Chilk 799105 suppl & Certificate of Svc encl. \* Office of the Secretary of the Commission. 79/11/07. 12pp.

- 7912030168 Order extending to 791121 time to respond to Intervenor Tribes supplemental patition for review.

  CHILK.S. J. Office of the Secretary of the Commission. 79/11/20.

  1p.
- 7912060072 Memorandum & order ALAB-572 denying Skagitonians Concerned About Nuclear Power motion requesting interlocutory review by directed certification. Intervenor complaints re exclusion of radon issue & seismology std do not warrant intercession. BISHOP, C. J. Atomic Safety and Licensing Appeal Panel. 79/11/20. 760.
- 7912060150 Order denying Oreenpeace Foundation of Vancouver, British Columbia, 790913 petition to intervene. No good cause shown. Contention of improving record spaculative, Proper interest not established Petitioner documentation encl.
  DEALE.V.B. Atomic Safety and Licensing Board Panel. 79/11/20.
  21ac.
- 7912100473 Response in apposition to Indian Tribes 791105 supplemental petition for ALAB-552 & ALAB-559 review.Petitioner failed to raise good cause re alleged ASCB misapplication of late intervention factor.Certificate of Bvc encl.
  LITTLE, D. B. Puget Bound Power & Light Co. LITTLE, D. B. Perkins, Coie, Stone, Olsen & Williams. 79/11/20. 12pp.
- 7912050376 Response in opposition to Indian Tribes 780613 petition to intervens.8tds for Commission review re procedural, policy & factual issues not met. Certificate of Svc encl.
  BLACK.R.L. Hearing Branch 1. 79/11/21. 14pp.
- 7912080059 Order granting extension until 791217 for Commission to determine whether to review ALAR-559, CHILK:S.J. Office of the Secretary of the Commission. 79/11/26, ip.
- 7912060004 Submits typographical correction to NRC 791121 response in opposition to Indian Tribes supplemental patition for raview. Corrected page re last paragraph.Line 3 encl. BLACK.R.L. Hearing Branch 1. 79/11/26. 2pp.
- 7912050421 Request for extension to 791221 to file proposed findings of fact & conclusions of law. Opposing attys have no objection.
  BLACK,R.L. Hearing Branch 1. 79/11/28. 3pp.
- 7912100132 Advises that Coalition for Bafe Power petition to review ASLB decision is deemed denied due to Commission negative exercise of discretion to take review. States Commissionera Oilinsky & Bradford dissenting views.

  CHILK.B. J. Office of the Secretary of the Commission. 79/11/29.
- 7912110407 Order denying intervenor Skagitonians Against Nuclear Power 790927 request for ABLB reconsideration of 790913 orders.

  B Stansby 790913 affidavit insufficient re concentration of cycles issue.

  DEALE, V. B. Atomic Safety and Licensing Board Panel. 79/11/30. 9pp.
- 7912170020 Reply in opposition to intervenor Forelaws on Board/Citizens for Safe Power findings of fact re alternative sites & postulated accidents. Certificate of Svc encl.
  THOMESN.F.T., LITTLE.D. S. Puget Bound Power & Light Co.
  THOMSEN.F.T. Parkins, Coie, Stone, Olsen & Williams. 79/11/30.
  2pg.
- --7912170041 Reply to NRC 791005 proposed findings of fact, Urges Board to reject Recommendation 3 contained in Finding 44, Pages 27-28. Condition re snviron evaluation prior to commencement of const activities is not authorized by NEPA & NRC rules. THOMBEN, F. T., LITTLE, D. S. Puget Sound Power & Light Co. THOMBEN, F. T. Perkins, Cois, Stone, Clien & Hilliams. 79/11/30, 22p.
- ---791217004B Reply to Skagitonians Concerned About Nuclear Power 791112 proposed findings of Fact.FEB & FEB final suppl addressed environ inpacts & whole population issues indiscriminately Gertificate of Svc encl.
  THOMBEN.F.T., LITTLE.D.S., Puget Bound Power & Light Co. THOMBEN.F.T. Porkins, Coie, Stone, Olsen & Hilliams. 79/11/30. 100pp.
- 7912R60039 Reply to Skagitonians Concerned About Nuclear Power 791109 proposed findings on financial qualifications. Intervenor adopted short-term view rather than long-term considerations to inflation rates & market ratios. Certificate of Svc encl. THOMSEN.F.T. Puget Sound Power & Light Co. THOMSEN.F.T. Perkins, Coie, Stone, Olsen & Hilliams. 79/12/05. 4pp.
- 7912310494 Forwards draft subposes for Hestern Geophysical Codeposition, per 791109 ltr. Signature requested. OENDLER, M. W. Laed, Robert M. 79/12/05. 2pp.

- 79:2:40:117 Responds to 79:203 request for extension until 79:1203 for filling cortain replies & request for extension until 79:1207 time to reply to intervenor Skagitonians Against Nuclear Power findings re Financial qualifications.

  DEALE, V. B. Atomic Safety and Licensing Board Panel. 79/12/06.
- 7912310503 Advises that TF Carr has been replaced by KM Ryan as count in proceeding. Title & address remain unchanged.
  RYAN, K. M. Washington, State of. 79/12/06. 1p.
- 7912270090 Forwards NRC subpoens form addressed to officers of Wester Gaophysical Co. in response to 791205 request.
  DEALE, V. B. Atomic Safety and Licensing Board Panel. 79/12/10. 2p
- 7912270106 Denies intervenor Skagitonians Concerned About Nuclear Pow 791017 request that ASLB implement Executive Order 12114. NRC is independent agency not within Executive Dept. Intervenor has no standing under order. DEALE, V. B. Atomic Bafety and Licensing Board Panel. 79/12/10. Sp
- 7912270054 Forwards AO Motulsky rept. \*Possible Impact of Planned Nuclear Power Plant on Skagit Indian Population. \*In response to intervention attempt by Indian Tribes.
  BLACK.R.L. Hearing Branch 1. 79712/14. ip.
- --7912270056 Forwards "Possible Impact of Plannod Nuclear Power Plant Skagit Indian Population." MOTULSKY,A.C. Washington, Univ. of. 79/10/30. ip.
- --7912270059 "Possible Impact of Planned Nuclear Power Plant on Skapi Indian Population." MOTULSKY.A.G. Washington, Univ. of. 79/10/30. Spp.
- 7912240349 Order granting extension until 800118 for Commission to elect whether to review ALAB-559.
  CHILK.S.J. Office of the Secretary of the Commission. 79/12/17.
- 7912310207 Ack receipt of 791207 ltr requesting permission to appeal ABLE 791120 decision.
  DEALE, V. B. Atomic Bafety and Licensing Board Panel. 79/12/17. 1p.
- H. Cameral correspondence
- 7912170358 Forwards NUREO-0555, NUREO-0628, NUREO-0578, SECY-79-300 & SECY-79-362, in response to 791114 & 20 requests for documents. Explains NRC policy re distribution of documents. Executive Order 11988 may be requested under FOIA. BLACK, R. L. Hearing Branch 1. 79/12/10. 2pp.
- 7912270512 Notifies of personnel change for manager of nuclear licensing & safety. M Stimac replaced by JE Mecca. MECCA, J. E. Puget Bound Power & Light Co. 79/12/20. 1p.
- DOCKET 50-525 BARTON, UNIT 2
- A. Application/construction stage documents & correspondence
- 791R110244 Discusses NRC plans to use generic analyses to develop early serification program to resolve ATMS issue for PMRs & BMRs. Buccess of program depends on industry response. Supports formation of owners groups to provide necessary info. DENTON: H. R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.
- DOCKET BIN-50-528 PALO VERDE NUCLEAR STATION, UNIT &
- A. Application/construction stage documents & correspondence
- 791217003B Forwards WA Baldwin of Friends of the Earth 791024 request for preparation of addl environ statements to Class 9 accidents at facilities, Potition being handled as request for action under 100FR2 206.
  DENTON H.R. Office of Nuclear Reactor Regulation. 79/11/27. 200.
- 7912170064 Forwards HA Baldwin of Friends of the Earth 791024 request for preparation of addl environ statements re Class 9 accidents at facilities. Petition being handled as request for action under 10CFR2 206.

  DENYON, H. R. Office of Nuclear Reactor Regulation. 79/11/27. 2pp.
- 7912130048 Responds to 790411 ltr re concerns w/emergency situations a disposal of waste math Bummarizes requirements & procedures affecting design & operational aspects of nuclear power glants. VAROA, 8. A. Assistant Director for Light Water Reactors. 79/11/28

- 7912130132 Responds to 790405 ltr re concerns w/const of plant.
  Summarizes requirements, & procedures affecting design & operational aspects of nuclear power plants.
  VAROA.S.A. Assistant Director for Light Water Reactors. 79/11/28.
- 7912130135 Responds to 790329 ltr re concerns w/nuclear power.
  Summarizes requirements & procedures affecting design & operational aspects of nuclear power plants.
  VAROA.S.A. Assistant Director for Light Water Reactors. 79/11/28.
- 7912190165 Forwards Amend 2 to CPPR-141.CPPR-142 & CPPR-143 & notice of issuance & availability.
  SELLS,D.E. Environmental Projects Branch 2. 79/11/29. 2pp.
- ---7912190173 Amend 2 to CPPR-141.CPPR-142 & CPPR-143.reflecting waiver to licensee commitment made during environ review & providing for weed control along pipeline route.
  VASSALLO.D.B. Division of Project Management. 79/11/30. 3pp.
- --7912190186 Notice of issuance & availability of Amend 2.to CPPR-141. CPPR-142 & CPPR-143. SELLS.D.E. Environmental Projects Branch 2, 79/11/30. 2pp.
- D. NRC Draft/Final Environmental Statements, suppls & correspondence
- 7912130561 Discusses rejection of preferred right-of-way for alignment of transmission line from plant site to Kyrene.AZ, & provides alternative routing through Rainbow Valley.One oversize drawing.available in Central Files only.

  VAN BRUNT, E. E. Arizona Public Service Co. 79/12/03. 3pp.
- F. Security, medical, emergency & fire protection plans
- 79:2040471 Forwards info re upgraded emergency plans to plants under const & DL review. Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Quide 1. 101. VABSALLO. D. B. Division of Project Management. 79/11/21. 6pp.
- 9. Adjudicatory correspondence
- 7912130058 Forwards petition by WA Baldwin requesting that NRC prepare supplemental environ statements re Class 7 accidents at facilities. Appropriate action will be taken.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/27. Spp.
- ---7912130070 Request for action under 10CFR2.206.for preparation of supplemental EIB concerning impact of Class 9 accidents at facilities.

  MULER.D.R. Division of Site Safety & Environmental Analysis.
  79/11/23. in.
- 7912200158 Ack receipt of 791024 petition & forwards FR notice for request for action per 10CFR2.206.

  BENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/27. 3pp.
- --7912200168 Notice of issuance & availability of Friends of the Earth 791024 petition requesting that NRC prepare supplemental EIS re impact of class 9 accident at facilities. MULTER.D.R. Division of Bite Safety & Environmental Analysis. 79/11/23. 1p.
- 7912280508 Requests substantive response to 791024 request for NRC to supplement EIS to consider consequences of Class 9 nuclear accidents. Failure to respond by 800104 will indicate NRC does not plan to require suppl.

  BALDHIN.H.A. Friends of the Earth. 79/12/21. 1p.
- I. Financial information
- 7912190627 Notifies of completion of review of util registration statement per SEC request. No inaccuracies or omissions found.

  LICITRA E. A. Light Water Reactors Branch 3. 79/12/03. ip.
- Q. Inspection reports, 1E Bulletins & correspondence
- 7912060035 Forwards 1E Insp Repts 50-529/79-06 & 50-529/79-06 on 790917-21. No noncompliance noted.
  SPENCER 0. B. Region 5. San Francisco. Reactor Construction & Engineering Support Branch. 79/11/02 2sp.

- --7912060047 IE Insp Repts 50-528/79-06 & 50-529/79-06 on 790917-21.No noncompliance noted Major areas inspected: ABME certified—const activities, safety-related piping installation & welding & containment steel structures & supports.

  DODDS, R.T. Region 5. San Francisco, Reactor Construction & Engineering Bupport Branch. ECKHARDI, J. H., HUTSON, T. M. Region 5, San Francisco, Office of the Director. 79/11/01. Bpp.
- 7912100271 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads," No response required. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/11/16. 1p.
- 791211050B Forwards IE Info Notice 79-29. "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required. ENGELKEN.R.H. Region S. Ban Francisco, Office of the Director. 79/11/16. 1p.
- 7912070016 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BHRs." No response required.
  EMPELKEN.R. H. Region 5, Ban Francisco, Office of the Director.
  79/11/26. 1p.
- 7912110266 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/11/26. 1p.
- 7912110492 Notifias that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sent by NRC to licensees.

  ENGELEBIR.H. Region S. San Francisco, Office of the Director. 79/11/26. ip.
- 79:21901:B Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation."
  No written response required.
  EMMELKEN.R.H. Region 9, San Francisco, Office of the Director.
  79/11/30. 1p.
- 7912310268 Forwards IE Info Notice 79-30. "Reporting of Defects & Noncospliances, iOCFR21." No action required. ENGELKEN, R. H. Region 5. San Francisco. Office of the Director. 79/12/06. 4pp.
- 7912180439 Forwards reply to IE Bulletin 79-23, "Packaging Failure of Emergency Diesel Generator Field Exciter Transformer." BPENCER. 0. S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 77/12/07. ip.
- --7912180445 Responds to 1E Bulletin 79-23, "Potential Failure of Emergency Diesel Generator Field Exciter Transformer." Btartup schedule includes 24-h full load test for Unit 1 prior to fuel load.

  VAN BRUNT, E. E. Arizona Public Service Co. 79/10/05. 1p.
- 7912200229 Forwards IE Bulletin 79-29, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/12/07. 10.
- 7912280595 Forwards IE Info Notice 79-31. "Use of Incorrect Amplified Response Spectra." No written response required. ENSELKEN, R.H. Region 5. Ban Francisco. Office of the Director. 79/12/13. ip.

## DOCKET STN-50-529 PALO VERDE NUCLEAR STATION, UNIT 2

- A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early varification program to resolve ATMS issum for PMRs & BMRs.
  Success of program depends on industry response. Bupports formation of owners groups to provide necessary info.
  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.
- 791217003B Forwards HA Baldwin of Friends of the Earth 791024 request for preparation of addl environ statements re Class 9 accidents at facilities. Patition being handled as request for action under 10CFR2.206.

  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/11/27. 2pp.

- 7912170064 Forwards WA Baldwin of Friends of the Earth 791024 request for preparation of addl environ statements re Class 9 accidents at facilities. Petition being handled as request for action under 100FR2.206.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/27. 2pp.
- 79:2130048 Responds to 790411 itr re concerns w/emergency situations & disposal of waste mati. Summarizes requirements & procedures affecting design & operational aspects of nuclear power plants.

  VARQA, 8. A. Assistant Director for Light Water Reactors. 79/11/28.
- 7912130132 Responds to 790405 ltr re concerns w/const of plant.

  Bummarizes requirements: & procedures effecting design & operational aspacts of nuclear power plants.

  VAROA: B. A. Assistant Director for Light Water Reactors. 79/11/28.
- 7-912130138 Responds to 7-90329 ltr re concerns w/nuclear power.

  Bummarizes requirements & procedures affecting design & operational aspects of nuclear power plants.

  VAROA: S. A. Assistant Director for Light Hater Reactors. 79/11/28.
  20n.
- 7912190165 Forwards Amend 2 to CPPR-141.CPPR-142 & CPPR-143 & notice of issuance & availability.

  9ELLB.D.E. Environmental Projects Branch 2. 79/11/29. 2pp.
- ---7912190173 Amend 2 to CPPR-141, CPPR-142 & CPPR-143, reflecting waiver to licenses commitment made during environ review & providing for weed control along pipeline route. VABBALLO, D. B. Division of Project Management. 79/11/30. 3pp.
- --7912190186 Notice of issuance & availability of Amend 2, to CPPR-141, CPPR-142 & CPPR-143.

  SELLB. D. E. Environmental Projects Branch 2. 79/11/30. 2pp.
- D. NRC Draft/Final Environmental Statements, supple & correspondence
- 7912130561 Discusses rejection of preferred right-of-way for alignment of transmission line from plant site to Kyrene, AZ, & provides alternative routing through Rainbow Valley. One oversize drawing, available in Central Files only.

  VAN BRUNT. E. E. Arizona Public Service Co. 79/12/03. 3pp.
- F. Security, medical, emergency & fire protection plans
- 79:2040471 Forwards info re upgraded emergency plans to plants under const & OL review. Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Quide 1.00.
  VASSALLO, D. B. Division of Project Management. 79/11/21. 6pp.

### Q. Adjudicatory correspondence

- 7912130058 Forwards potition by WA Baldwin requesting that NRC prepare supplemental environ statements re Class 9 accidents at facilities Appropriate action will be taken.
  DENTON M. R. Office of Nuclear Reactor Regulation. 79/11/27. Spp.
- ---7912130070 Request for action under 10CFR2.206.for preparation of supplemental EIB concerning impact of Class 9 accidents at facilities.
  MULLER.D.R. Division of Site Safety & Environmental Analysis.
  79/11/23. ip.
- 7912200158 Ack receipt of 791024 patition & forwards FR notice for request for action per 100FRR. 206.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/27. 3pp.
- --7912200168 Notice of issuance & availability of Friends of the Earth 791024 patition requesting that NRC prepare supplemental EIS re impact of Class 9 accident at facilities. MULER.D.R. Division of Site Bafety & Environmental Analysis. 79/11/23. ip.
- 7912280508 Requests substantive response to 791024 request for NRC to supplement EIS to consider consequences of Class 9 nuclear accidents. Failure to respond by 800104 will indicate NRC does not plan to require suppl.

  BALDWIN, W. A. Friends of the Earth. 79/12/21. ip.

## I. Financial information

- 7912190627 Notifies of completion of review of util registration statement per SEC request. No inaccuracies or omissions found.
  LICITRALE. A. Light Water Reactors Branch 3. 79/12/03. ip.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912060035 Ferwards IE Insp Repts 50-528/79-06 & 50-529/79-06 on 790917-21. No noncompliance noted. SPENCER, G.S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/11/02. 2pp.
- --7912060047 IE Insp Repts 50-528/79-06 & 50-529/79-06 on 790917-21.No noncompliance noted Major areas inspected: ASME certified—const activities: safety-related piping installation & welding & containment steel structures & supports.

  DODDE: R.T. Region 5. San Francisco. Reactor Construction & Engineering Support Branch. ECKHARDT.J.H., PUSCON.T.W. Region 5. Sen Francisco. Uffice of the Director. 79/11/01. Bpp.
- 7912100271 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. ENDELKEN, R. H. Region 5, San Francisco. Office of the Director. 79/11/16. ip.
- 7912110508 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/11/16. 10.
- 7912070016 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No response required.
  ENDELERIN.R.H. Region.S. San Francisco. Office of the Director.
  79/11/26. 1p.
- 7912110266 Forwards IE Circular 79-23. "Motor Starters & Contactors Failed to Operats." No response required. ENGELKEN, R. H. Region 5. Ban Francisco, Office of the Director. 79/11/26. 1p.
- 7912110492 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sent by NRC to licensees. ENGELKEN.R.H. Region 5. San Francisco, Office of the Director. 79/11/26. 1p.
- 7912190118 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation." No written response required. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/11/30. 1p.
- 7912310268 Forwards IE Info Notice 79-30. "Reporting of Defects & Noncompliances, IOCFR21." No action required. ENGELKEN. R.H. Region 5. San Francisco, Office of the Director. 79/12/06. 4pp.
- 7912180437 Forwards reply to IE Bulletin 79-23, "Packaging Failure of Emergency Diesel Generator Field Exciter Transformer."

  SPENCER, O. S. Règion 5. Ban Francisco, Reactor Construction & Engineering Support Branch. 79/12/07. 1p.
- --7912180445 Responds to IE Bulletin 79-23, "Potantial Failure of Emergency Dissel Generator Field Exciter Transformer."

  Btartup schedule includes 24-h full load test for Unit i prior to fuel load.

  VAN BRUNT.E.E. Arizona Public Service Co. 79/10/05. 1p.
- 7912200229 Forwards IE Bulletin 79-28, "Possible Halfunction of Namco-Model EAIBO Limit Switches at Elevated Temps." Action required. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director-79/12/07. 10.
- 7912280575 Forwards IE Info Notice 77-31, "Use of Incorrect Amplified Response Bectra." No written response required. ENGELKEN,R.H. Region 5, San Francisco. Office of the Director. 79/12/13. ip.

### **DOCKETED ITEMS**

- DOCKET STN-50-530 PALD VERDE NUCLEAR STATION, UNIT 3
- A Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plane to use generic analyses to develop early verification program to resolve ATMB issue for PWRs & DWRs. Success of program depends on industry response Supports formation of owners groups to provide necessary info.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.
- 791217003B Forwards HA Baldwin of Friends of the Earth 791024 request for preparation of addl environ statements re Class 9 accidents at facilities. Petition being handled as request for action under ECCFR. 206.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/27. 2pp.
- 7912170064 Forwards WA Baldwin of Friends of the Earth 791024 request for preparation of addl environ statements re Class 9 accidents at facilities. Petition being handled as request for action under 10CFR2.206.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/27. 2pp.
- 7912130048 Responds to 790411 ltr re concerns w/emergancy situations & disposal of waste matl. Summarizes requirements & procedures affecting design & operational aspects of nuclear power plants.

  VAROA.S.A. Assistant Director for Light Water Reactors. 79/11/28.
- 7912130132 Responds to 790405 ltr re concerns w/const of plant.
  Summarizes requirements, & procedures affecting design & operational aspects of nuclear power plants.
  VARGA.S.A. Assistant Director for Light Water Reactors.
- 7912130135 Responds to 790329 ltr re concerns w/nuclear power.
  Summarizes requirements & procedures affecting design & operational aspects of nuclear power plants.
  VARGA.S.A. Assistant Director for Light Water Reactors 79/11/28.
- 7912190165 Forwards Amend 2 to CPPR-141.CPPR-142 & CPPR-143 & notice of issuance b availability.
  SELLS.D.E. Environmental Projects Branch 2. 79/11/29. 2pp.
- --7912190173 Amend 2 to CPPR-141. CPPR-142 & CPPR-143. reflecting waiver to licensee commitment made during environ review & providing for weed control along pipeline route.

  VASSALLO, D. B. Division of Project Management. 79/11/30. 3pp.
- --7912190186 Notice of issuance & availability of Amend 2.to CPPR-141, GPPR-142 & CPPR-143. SELLS, O. E. Environmental Projects Branch 2, 79/11/30, 2pp.
- D. NRC Draft/Final Environmental Statements, supple & correspondence
- 7912130561 Discusses rejection of preferred right-of-way for alignment of transmission line from plant site to Kyrene, AL. & provides alternative routing through Rainbow Valley. One oversite drawing, available in Central Files only.

  VAN BRUNT, E.E. Arizona Public Service Co. 79/12/03. 3pp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards into to upgraded emergency plans to plants under const & DL review. Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Guide 1.101. VASSALLO, D. B. Division of Project Management. 79/11/21. App.
- G. Adjudicatory correspondence
- 7912130098 Forwards petition by UA Baldwin requesting that NRC prepare supplemental environ statements re Class 9 accidents at facilities. Appropriate action will be taken.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/27. 3pp.
- --7912130070 Request for action under 100FR2 206 for preparation of supplemental EIS concerning impact of Class 9 accidents at facilities.

  MULLER D. R. Division of Site Eafety & Environmental Analysis.
  79/11/23. 1p.
- 7912200158 Ack receipt of 791024 petition & forwards FR notice for request for action per 10CFR2 205.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/27. 3pp.

- --7912200168 Notice of issuance & availability of Friends of the Earth 791024 petition requesting that NRC prepare supplemental EIS re impact of Class 9 accident at facilities. MULLER.D.R. Division of Site Safety & Environmental Analysis. 79/11/23. ip.
- 7912280508 Requests substantive response to 791024 request for NRC to supplement EIS to consider consequences of Class 9 nuclear accidents. Failure to respond by 800104 will indicate NRC does not plan to require suppl.

  BALDWIN.W.A. Friends of the Earth. 79/12/21. 1p.
- 1. Financial information
- 7912190627 Notifies of completion of review of util registration statement per SEC request. No inaccuracies or omissions found.
  LICITRA, E. A. Light Water Reactors Branch 3. 79/12/03. ip.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912100271 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/11/16. 1p.
- 7912110508 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required.
  ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/11/14. ip.
- 7912070016 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No response required. ENGELKEN.R.H. Region 5. San Francisco, Office of the Director. 79/11/26. ip.
- 7912110266 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. ENGELKEN,R.H. Region 5, San Francisco, Office of the Director. 79/11/26. ip.
- 7912110492 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sent by NRC to licensees.
  ENGELKEN,R. H. Region 5, San Francisco, Office of the Director. 79/11/26. 10.
- 7912190118 Forwards IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation."
  No written response required.
  ENGELKEN.R. M. Region 5. San Francisco, Office of the Director.
  79/11/30. 1p.
- 7912310268 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 100FR21." No action required. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/12/06. 4pp.
- 7912180439 Forwards reply to JE Bulletin 79-23, "Packaging Failure of Emergency Diesel Generator Field Exciter Transformer." SPENCER, G. S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/12/07. 1p.
- --7912180445 Responds to IE Bulletin 79-23, "Potential Failure of Emergency Diesel Generator Field Exciter Transformer." Startup schedule includes 24-h full load test for Unit 1 prior to fuel load.

  VAN BRUNT,E.E. Arizona Public Service Co. 79/10/05. 1p.
- 7912200229 Forwards IE Bulletin 79-28, "Possible Malfunction of Nameo Model EA180 Limit Switches at Elevated Temps." Action required.
  ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/12/07. ip.
- 7912280595 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. 79/12/13. 1p.

- DOCKET 50-537 CLINCH RIVER BREEDER REACTOR
- A. Application/construction stage documents & correspondence
- 7911280193 Discusses mods to NRC position re status & applicability of TMI-2 accident review & NUREO-0578 to facilities under const. Forwards addl info to be considered in development of final plant design & procedures.

  VASBALLO, D. B. Division of Project Management. 79/10/10. 4pp.
- 7912110264 Discusses NRC plans to use generic analyses to develop early varification program to resolve ATWS issue for PWRs & BWRs. Success of program depends on industry response Supports formation of owners groups to provide necessary info.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.
- 7912200578 Forwards WARD-D-0050, Revision 3, "Facility Core Assembly Hot Channel Factors Preliminary Analysis." COPELAND.R.L. Energy, Dept. of, Clinch River Breeder Reactor Plant. 79/12/14. ip.
- --7912200584 "Facility Core Assembly Hot Channel Factors Preliminary Analysis," Revision 3. FRIEDLAND, A. J. MARKLEY, R. A. Westinghouse Electric Corp. WARD-D-0050 R3. 79/12/14. 162pp.

#### DOCKET 50-539 MEMPHIB STATE UNIV. RESEARCH REACTOR

- F. Security, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Quide 5.XX, "Std Format & Content for Licensee Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance." W/O encl. REID:R.W. Operating Reactors Branch 4 (Pre 791030). 79/08/22.20.
- J. Insurance & indemnity information
- 7912210297 Forwards executed Amend 3 to Indemnity Agreement E-59 defining "in course of transportation."

  JONES, D. W. Memphis State Univ. 79/12/14. 2pp.
- 9. Reportable occurrences, LERs & related correspondence
- 7912130415 Forwards followup rept to RD-79-3.
  JONES, D. W. Memphis State Univ. 79/11/26, 1p.
- --7912130628 Followup rept to RO-79-3: on 791116, during prestartup, shield water level float switch assembly failed to initiate protective trip signal. Caused by gradual buildup of corrosion products in internal mechanism of microswitch.

  \* Memphis Btate Univ. 79/11/26. App.

#### DOCKET 9TN-50-545 RESAR-39

- A. Application/construction stage documents & correspondence
- 7912280047 Discusses extension review matters for preliminary dusign approvals in response to 781215 ltr submitting Amend 14 to REBAR-38.
  VASSALLO, D. B. Division of Project Management. 79/12/13. 5pp.
- B. Utility Preliminary Safety Analysis Report, amends
- 7912200396 Forwards Amend 15 to REBAR-38 in response to NRC 791213 request for add1 info.
  ANDERSON.T.M. Westinghouse Electric Corp. 79/12/18. 2pp.
- --7912200400 Amend 15 to REBAR-39, \* Wastinghouse Electric Corp. 79/12/31. 23pp.
- DOCKET 8TN-50-546 MARBLE HILL NUCLEAR BTATION, UNIT 1
- A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop earl verification program to resolve ATWB issue for PWRs & BWRs.

  Buccess of program depends on industry response Eupports formation of numers groups to provide necessary info.

  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/10/17. Gpp.

- 7912100022 Discusses issuance of Amend 17 to License DPR-64, which authorized operation at 100% power Max allowable foe already paid by util No addl fee required. MILLER, W. O. License Fee Management Branch. 79/11/13. 1p.
- --7912100066 Provides ACRS prof manpower expenditure estimates for CP & DL reviews. FRALEY.R.F. ACRS - Advisory Committee on Reactor Safeguards. 78/11/01. 1p.
- --7912100079 Requests info re ACRS prof man-hrs expended on review of each reactor. Data for safety, environ & antitrust hearing concerns should be included. Associated travel should not be shown.

  MILLER, M. O. License Fee Management Branch. 78/10/02. 1p.
- 7912170021 Informs of denial of 790629 & 0727 requests for suspension or revocation of CPs.
  CASE.E.G. Office of Nuclear Reactor Regulation. 79/11/27. 4pp.
- --7912170024 Denies 790629 & 0727 requests for suspension or revocation of CPs due to absence of special circumstances. Items raised were considered in OL review.

  CASE, E. Q. Office of Nuclear Reactor Regulation. 79/11/27. 14pp.
- --7912170031 Bubmits add1 itams to be considered in review of 790429 request for suspension or revocation of CPs. Requests hearing. EYED. J. A. Sassafras Audubon Society. 79/09/04. 3pp.
- 7912120398 Forwards proposed pre-operational radiological environ monitoring program Requests concurrence.

  SHIELDS, S. W. Public Service Co. of Indiana, Inc. 79/11/30. App.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review. Applicants required to make cortain amergency arrangements w/state & local organizations & submit emergency plans per Reg Guide 1.101.

  VASSALLO, D. B. Division of Project Hanagement. 79/11/21. 6pg.
- G. Adjudicatory correspondence
- 7912110043 Forwards comments on NUREG-0511. Draft GEIS reflects conscious & deliberate NRC policy to jeopardize public health & safety & thwart objectives of NEPA.

  KEPFORD, C. Environmental Coalition on Nuclear Power. 79/10/24.

  R20p.
- 7912210360 Forwards appeal re NRC review of Director's decision under IOCFR2.206. EYED, J. A. Sassafras Audubon Society. 79/12/14. 1p.
- --7912210364 Appeals for review of Director's decision under 10CFR2.206.
  Director abused discretionary power in denying requests to roopen safety hearings at meaningful point in licensing process.
  EYED.J.A. Sassafras Audubon Society. 79/12/10. 12pp.
- 7912200517 Orders extension until 800104 for NRC to review 791127 director's decision denying Sassafras Audubon Society request for action under 100FR2.206 CHILK, S. J. Office of the Secretary of the Commission. 79/12/17. 1p.
- Q. Inspection reports: IE Bulletins & correspondence
- 7912130131 Forwards IE Insp Repts 50-546/79-19 & 50-547/79-19 on 790925-28 & 1009-12.No noncompliance nated. FIORELLI,0. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 79/10/23. 2pp.
- --7912130136 IE Insp Repts 50-546/79-19 & 50-547/79-19 on 790925-28 & 1009-12.No noncompliance noted Major areas inspected: review of quality records, maint for installed Category I math & work re off-loading reactor pressure vessel.

  HAYES, D. W. Region 3: Chicago, Reactor Construction & Engineering Support Branch. HAMKINSF.C. WILLIAMS.C.C. Region 3: Chicago, Office of the Director. 79/10/18. 5pp.
- 7912110261 Forwards IE Insp Repts 50-546/79-19 & 50-547/79-19 on 790925-28 & 1009-12.No noncompliance noted. FIORELLI.G. Region J. Chicago, Reactor Construction & Engineering Support Branch. 79/10/25. 2pp.

- --7912110286 IE Insp Repts 50-546/79-19 & 30-547/79-19 on 790925-28 & 1009-12. No noncompliance noted Major areas inspected: observation of concrete coring work & maint for installed Category 1 matl & review of quality records. HAWKINS.F.C., HARRISON.J.J. Region 3. Chicago. Defice of the Director. HAYES.D.W. Region 3. Chicago. Reactor Construction & Engineering Support Branch. 79/10/18. 5pp.
- 7912040057 Responds to NRC 791002 ltr re violations noted in IE Insp Repts 50-546/79-18 & 50-547/79-18 Corrective actions: instructed personnel to verify rate of load twice faily for min of 10 intervals. SHIELDS.8.W. Public Service Co. of Indiana, Inc. 79/11/01. 5pp.
- 7912090148 forwards IE Circular 79-22. "Btroke Times for Power Operated Reliof Valves." No response required.

  KEPPLER.J. 9. Region 3. Chicago, Office of the Director. 79/11/16.

  1p.
- 7912100243 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/14.
- 7912110588 Forwards IE Info Notice 79-29. "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. XEPPLER.J.O. Region 3. Chicago, Office of the Director. 79/11/16.
- 7912260148 Forwards IE Insp Repts 50-546/79-21 & 50-547/79-21 on 791022-23. No noncompliance noted. FIGRELLI.G. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 79/11/16. 2pp.
- --7912260153 IE Insp Repts 50-546/79-21 & 50-547/79-21 on 791023-26. No noncompliance noted Major areas inspected: surveillance of auxiliary bidg. containments, storage areas & various locations to verify compliance w/790807 stop work order. JONES.C.E., WILLIAMS.C.C. Region 3. Chicago, Office of the Director. 79/11/14. 3pp.
- 7912050407 Forwards IE Bulletin 79-26, "Boron Loss From BWR Control Blades." No response required.

  KEPPLER.J.O. Region 3: Chicago, Office of the Director. 79/11/20.
- 7912050418 Ack receipt of 791102 ltr informing NRC of steps taten to correct violations noted in IE Insp Repts 50-546/79-09 & 50-547/79-09.
  FIORELI-G. Region 3. Chicago. Reactor Construction & Engineering Support Branch. 79/11/20. 1p.
- --7912050424 Responds to NRC 791002 ltr re violations noted in IE Insp. Repts 50-546/79-09 & 50-547/79-09. Corrective actions: all nuclear safety-related const stopped, Organization & procedures being re-evaluated.

  SHIELDS, B. H. Public Service Co. of Indiana, Inc. 79/11/02. 2pp.
- 7912100442 Forwards IE Circular 79-24. "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No written response required.

  KEPPLER.J. G. Region 3. Chicago, Office of the Director. 79/11/26.
- 7912140228 Forwards IE Circular 79-23. "Motor Starters & Contactors Failed to Operate." No written response required.

  KEPPLER.J. G. Region 3. Chicago. Office of the Director. 79/11/26.
- 7912050290 Ack receipt of 791101 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-546/79-11 & 50-547/79-11. FigReLI.9. Region 3. Chicago, Reactor Construction & Engineering Eupport Branch. 79/11/27. ip.
- --7912050301 Responds to NRC ltr re violations noted in IE Insp Rept 50-546/79-11 & 50-547/79-11. Corrective actions: independent mpt evaluation of PSI Nuclear Project. Stringer bead technique under re-evaluation. SHIELDS
- 7912070402 Ack receipt of 791101 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-546/79-07 & 50-547/79-07. FIDRELLI-G. Region G. Chicago, Reactor Construction & Engineering Support Branch. 79/11/27. ip.

- --7912070411 Responds to NRC 791002 ltr re violations noted in IE Insp Repts 50-546/79-07 & 50-547/79-07. Corrective actions: personnel instructed to acquire records & retest areas tested before records were on site & accepted. GHIELDS.S.W. Public Service Co. of Indiana, Inc. 79/11/01, 2pp.
- 7912110440 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sent by NRC to licensees.

  KEPPLER, J. O. Region 3, Chicago: Office of the Director. 79/11/28.
- 7912190244 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation."
  No written response required.
  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/30.
- 7912140098 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action or response required.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/12/06.

  1p.
- 7912200141 Forwards IE Bulletin 79-28, "Possible MalPunction of Nagro Model EA180 Limit Switches at Elevated Temps." Action required.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/12/10.
- B. Reportable occurrences, LERs & related correspondence
- 79122:0047 PNO-III-79-12: on 791010.NRC will hold press conference to summarize activities re-project.
  KEPPLER, J. O., FIGRELLI, O. Region 3, Chicago, Office of the Birsctor. 79/10/10. ip.
- 7912200442 PND-III-79-047: on 791127, regional direction & selected members of Const Branch requested by Chairman of Bubcommittee on Environ Energy & Natural Resources to testify & respond to questions on facilities. FIORRLLI, G., KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/26. 1p.
- T. Hearing transcripts on non-antitrust matters
- 79/12/100362 Statement of CC Williams before House Committee on Govt Operations, Subcommittee on Energy & Natural Resources requality of const at site.
  WILLIAMS, G. C. Region 3. Chicago, Office of the Director.
  79/12/06.
- U. Congressional/Executive Correspondence
- 7912130171 Comments on House testimony re difficulty in evacuation of large population ctrs in event of nuclear accident, Facility should be considered for shutdown due to proximity to Louisville, KY.
  FORD W. H. Senate. 79/11/06. ip.
- DOCKET STN-50-547 MARBLE HILL NUCLEAR STATION, UNIT 2
- A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATWS issue for PWRs & BWRs. Success of program depends on industry response. Supports formation of numera groups to provide necessary info. DENTON, H. R. Office of Nuclear Reactor Regulation, 79/10/17. 3pp.
- 7912100022 Discusses issuance of Amend 17 to License DPR-64, which authorized operation at 100% power. Max allowable fee already paid by util. No addl fee required.

  MILLER, M. G. License Fee Management Branch. 79/11/13. 1p.
- --7912100066 Provides ACRB prof manpower expenditure estimates for CF & OL reviews. FRALEY.R.F. ACRB - Advisory Committee on Reactor Bafeguards, 78/11/01. 1p.
- --7912100079 Requests info re ACRB prof man-hrs expended on review of each reactor. Data for safety, environ & antitrust hearing concerns should be included. Associated travel should not be shown.

  MILLER, W. O. License Fee Management Branch. 78/10/02. ip.

- 7912170021 Informs of denial of 790629 & 0727 requests for suspension or revocation of CPs.
  CASE, E. Q. Office of Nuclear Reactor Regulation. 79/11/27. 4pp.
- --7912170026 Denies 790629 & 0727 requests for suspension or revocation of CPs due to absence of special circumstances. Items raised were considered in OL review.

  GABE, E. G. Office of Nuclear Reactor Regulation. 79/11/27. 14pp.
- --7912170031 Submits add1 items to be considered in review of 790629 request for suspension or revocation of CPs.Requests hearing. EYED.J.A. Bassafras Audubon Society. 79/09/04. 3pp.
- 791212039B Forwards proposed pre-operational radiological environ munitoring program Requests concurrence. BHIELDS, B.W. Public Bervice Co. of Indiana, Inc. 79/11/30. App.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & DL review Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Quide 1.101. VASSALLO.D.B. Division of Project Management. 79/11/21. 6pp.
- Q. Adjudicatory correspondence
- 7912110043 Forwards comments on NUREO-0511 Draft QEIS reflects conscious & deliberate NRC policy to Jeopardize public health & safety & thwart objectives of NEPA.

  KEPFORD, C. Environmental Coalition on Nuclear Power. 79/10/24.
  220s.
- 7912210360 Forwards appeal re NRC review of Director's decision under 10CFR2.206, EYED, J.A. Bassafras Audubon Bociety, 79/12/14, 1p.
- ---7912210364 Appeals for review of Director's decision under 10CFR2.206.

  Director abused discretionary power in denying requests to reopen safety hearings at meaningful point in licensing process.

  EYED, J. A. Sassafras Audubon Society. 79/12/10. 12pp.
- 7912200517 Orders extension until 800104 for NRC to review 791127 director's decision danying Bassafras Audubon Society raquest for action under 10CFR2 206.
  CHILK.S.J. Office of the Secretary of the Commission. 79/12/17.
- G. Inspection reports, IE Bulletins & correspondence
- 7912130131 Forwards IE Insp Repts 50-546/79-19 & 50-547/79-19 on 790925-28 & 1009-12. No noncompliance noted. FIORELLI, 0. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/10/23, 2pp.
- ---7912130134 IE Insp Repts 50-544/79-19 & 50-547/79-19 on 790925-28 & 1009-12. No noncompliance noted, Major areas inspected: review of quality records: maint for installed Category 1 matl & work re off-loading reactor pressure vessel.

  HAYEB, D. H. Region 3; Chicago, Reactor Construction & Engineering Support Stranch. HAWKINB, F. C., WILLIAMS, C. C. Region 3; Chicago, Office of the Director. 79/10/18. Spp.
- 7912110261 Forwards IE Insp Repts 50-546/79-19 & 50-547/79-19 on 790925-28 & 1009-12 No noncompliance noted. FIORELLIO. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/10/25. 2pp.
- ---7912110286 IE Insp Repts 50-546/79-19 k 50-547/79-19 on 790925-28 k 1009-12. No noncompliance noted. Hajor areas inspected: observation of concrete coring work & maint for installed Category I matl & review of quality records. HAWKINS,F.C. HARRISON, J. J. Region 3. Chicago. Office of the Director, HAYESD. W. Region 3. Chicago. Reactor Construction & Engineering Support Branch. 79/10/18. Spp.
- 7912060037 Responds to NRC 791002 Itr re-violations noted in IE Insp Repts 50-346/79-18 & 50-347/79-18 Corrective actions: instructed personnel to verify rate of load twice daily for ain of 10 intervals, BMIELDS, S. M. Public Bervice Co. of Indiana, Inc. 79/11/01. Spp.
- 7912030148 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves," No response required, REPPLER, J. Q. Region 3, Chicago, Office of the Director. 79/11/16,

- 79:2100243 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required.
  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/16.
  1p.
- 7912110588 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912260148 Forwards IE Insp Regts 50-546/79-21 & 50-547/79-21 on 791022-23. No noncompliance noted. FIORELLI, G. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 79/ii/16. 2pp.
- --7912260153 IE Insp Repts 50-546/79-21 & 50-547/79-21 on 791023-26. No noncompliance noted. Major areas inspected: surveillance of auxiliary bldg.containments, storage areas & various locations to verify compliance w/790807 stop work order. JONES C.E., WILLIAMS, C.C. Region 3, Chicago, Office of the Director, 79/11/14, 3pp.
- 7912050407 Forwards IE Bulletin 79-24, "Boron Loss From BWR Control Blades." No response required.
  KEPPLER, J. 9. Region 3, Chicago, Office of the Director. 79/11/20.
- 7912050418 Ack receipt of 791102 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-546/79-09 & 50-547/79-09.
  FIORELLIA. Region 3. Chicago, Reactor Construction & Engineering Bupport Branch. 79/11/20. 1p.
- --79,12050424 Responds to NRC 791002 ltr re violations noted in IE Insp. Repts 50-546/79-09 & 50-547/79-09. Corrective actions: all nuclear safety-related const stopped. Organization & procedures being re-evaluated. SHIELDS.S.H. Public Service Co. of Indiana, Inc. 79/11/02. 2pp.
- 7912100442 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pips Break Detection Equipment on BHRs." No written response required. KEPPLER, J. 9. Region 3, Chicago, Office of the Director. 79/11/26.
- 7912140228 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No written response required.
  KEPPLER.J. 9. Region 3, Chicago, Office of the Director. 79/11/26.
  ip.
- 7912050270 Ack receipt of 791101 ltr informing NRC of steps taken to correct violations noted in IE Imap Repts 50-546/79-11 & 50-547/79-11. FIORELLI, 6. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/11/27. ip.
  - Support Branch. 79/11/27. ip.
- --7912050301 Responds to NRC ltr re violations noted in IE Insp Rept 50-546/79-11 & 50-547/79-11 Corrective actions: independent mpt evaluation of PSI Nuclear Project Stringer bead technique under re-evaluation. BHIELDS
- 7912070402 Ack receipt of 791101 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-546/79-07 & 50-547/79-07.
  FIDRELLIO. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/11/27. ip.
- --7912070411 Responds to NRC 791002 ltr re violations noted in IE Insp Repts 50-546/79-07 & 50-547/79-07. Corrective actions: personnel instructed to acquire records & retest areas tested before records ware on site & accepted. GHIELDS, S.W. Public Bervice Co. of Indiana, Inc. 79/11/01. 2pp.
- 77:21:0440 Notifies that NRC intends to routinaly forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sent by NRC to licensees.

  KEPPLER, J. 9. Region 3. Chicago, Office of the Director. 79/11/28.

  19.
- 7912190244 Forwards IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation."
  No written response required.
  KEPPLER. J. G. Region 3. Chicago. Office of the Director. 79/11/30.
  19.

- 7912140078 Forwards IE Info Notice 79-30. "Reporting of Defects & Noncompliances: 10CFR21." No action or response required.

  KEPPLER. J. G. Region 3. Chicago, Office of the Birector. 79/12/06.

  1p.
- 7912200141 Forwards IE Bulletin 79-28. "Passible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. KEPPLER.J. G. Region S. Chicago. Office of the Director. 79/12/10
- S. Reportable occurrences, LERs & related correspondence
- 7912210047 PND-TII-79-12:on 791010,NRC will hold press conference to summarize activities re project.

  KEPPLER.J.O., FIORELLI.O. Region 3, Chicago, Office of the Director. 79/10/10. 1p.
- 7912200442 PNO-III-79-047: on 791127, regional direction & selected members of Const Branch requested by Chairman of Subcommittee on Environ Energy & Natural Resources to testify & respond to questions on facilities.
  FIORELLIG., KEPPLERJ.C. Region 3. Chicago, Office of the Director. 79/11/26. 1p.
- T. Hearing transcripts on non-antitrust matters
- 7912100362 Statement of CC Williams before House Committee on Govt Operations, Subcommittee on Energy & Natural Resources re quality of const at site. HILLIAMS.C.C. Region 3, Chicago, Office of the Director. 79/12/06. 12pp.
- U. Congressional/Executive Correspondence
- 7912130171 Comments on House testimony re difficulty in evacuation of large population ctrs in event of nuclear accident Facility should be considered for shutdown due to proximity to Louisville, KY.
  FDRD: H. H. Senate. 79/11/06. 1p.
- DOCKET 50-549 GREENE COUNTY NUCLEAR POWER PLANT
- A. Application/construction stage documents & correspondence
- 7911280153 Discusses mods to NRC position re status & applicability of TMI-2 accident review & NUREG-0578 to facilities under const. Forwards addl info to be considered in development of final plant design & procedures.

  VASSALLO.D.B. Division of Project Management. 79/10/10. 4pp.
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRs & BMRs. Success of program depends on industry response. Supports formation of owners groups to provide necessary info.

  DENION.H.R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.
- 7912070004 Requests distribution of encl memorandum to board notification lists VARGA S.A. Assistant Director for Light Water Reactors. 79/11/08. 3pp.
- 7912070291 Submits partial response to FOIA request for documents re Nuclear Development Association. United Nuclear Corp. Gulf United Nuclear Corp & ATCOR. Inc. concerning facility site. Forwards requested info. Provides addl info re site. CARR. J. C. Division of Rules and Records. 79/11/18. 3pp.
- G. Adjudicatory correspondence
- 7912050447 Forwards response of Greene County et/al to util 791016 rept re status of application.
  BUTZEL.A.K. Berle,Butzel,Kass & Case. 79/10/24. lp.
- --7912050451 Response to util 791016 rept ro status of application.Util application must be dismissed per ASLB 791016 order. BUTZEL,A.K. Oreene County, NY. BUTZEL,A.K. Daker & Botts. 79/10/24. 4pp.
- J. Insurance & indemnity information
- 7912270605 Confirms that PASNY has loan commitment for \$10 million from Manufacturers Hanover Trust for retrospective insurance payment. If necessary, in event of nuclear disaster. Commitment expires 800630.

  MCCARTHY, R.H. Affiliation Unknown. 79/12/18. Ip.

- P. Operating licenso stage documents & correspondence
- 7912070263 Partially responds to FOIA request for document re Pawling, NY site. Forwards requested info. Submits addl info: sodium dauterium reactor never built at site. no matl ever used at site & no radioactive matl disposed of in lake. CARN. J. C. Division of Rules and Records. 79/11/16. 3pp.
- DOCKET STN-50-553 PHIPPS BEND NUCLEAR PLANT, UNIT 1
- A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRe & BWRs. Success of program depends on industry response Supports formation of cumers groups to provide necessary info.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.
- 79121300R3 Notification of 800110 meeting w/util to discuss reporting level of util QA & manager & QA review of documents. SPRAUL, J. G. Quality Assurance Branch. 79/12/05. 1p.
- 79:2270424 Forwards US Fish & Wildlife Svc 791101 ltr stating that no federally listed proposed endangered or threatened species are known to inhabit area to be impacted by const of transmission line connectors.

  MILLS.L.M. Tennesses Valley Authority. 79/12/17. 2pp.
- f. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review. Applicants required to make cartain emergency arrangements w/state & local organizations & subnit emergency plans per Reg Guide 1.101.
  VASSALLO, D. B. Division of Project Management. 79/11/21. App.
- O. Adjudicatory correspondence
- 7912110043 Forwards comments on NUREO-0511. Draft GEIS reflects conscious & deliberate NRC policy to jeopardize public health & safety & thwart objectives of NEPA.

  KEPFORD, C. Environmental Coalition on Nuclear Power. 79/10/24.
- Q. Inspection reports, IE Bulletins & correspondence
- 7912060392 Forwards IE Insp Repts 50-553/79-15 & 50-554/79-14 on 791009-12. No noncompliance noted. MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 79/10/31. 2pp.
- --7912060594 IE Insp Repts 50-553/79-15 & 50-554/79-14 on 791007-12 No noncompliance noted Major areas inspected action on previous insp findings, general insp of const status, review of GA manual & licensee identified items.
  WRIGHT.R.W. Region 2. Atlanta, Office of the Director.
  CANTERLL.F. S. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/10/31. Spp.
- 7912060163 Forwards IE Info Notice 79-12A, "Attempted Damage to New Fuel Assemblies." No specific action or response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 79/11/09. 3pp.
- 7912070499 Forwards IE Info Notice 79-27. "Steam Generator Tube Ruptures at Two PWR Plants." D'MRILLY.J.P. Region 2. Atlanta, Office of the Director. 79/11/16. 14pp.
- 7912100192 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. O'REILLY, J. P. Region 2, Atlanta, Dffice of the Director. 79/11/16. 1p.
- 7912110575 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. O'RELLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/16. 2pp.
- 7912040620 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No response required. O'REILLY.J.P. Region 2, Atlanta. Office of the Director. 79/11/26. 1p.

- 7912110157 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/26. 1p.
- 7912190478 forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation."
  No written response required.
  D'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/30. 10.
- 7912310316 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action required.
  O'REILLY,J.P. Region 2. Atlanta, Office of the Director.
  79/12/06. 6pp.
- 7912200060 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Bultches at Elevated Temps." Action required. 0'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/12/07. 3pp.
- 7912280426 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra," No written response required. O'REILLY, J.P. Region 2. Atlanta, Office of the Director, 79/12/13. 3pp.
- 7912280150 Forwards IE Circular 79-25, "Shock Arrestor Strut Assembly Interference." No written response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/12/20. 4pp.
- 8. Reportable occurrences. LERs & related correspondence
- 7912130427 Forwards interim deficiency rept re brittle rebar, produced by FL Stool Corp.
  MILLS,L.M. Tennessee Valley Authority, 79/11/15, ip.
- --7912130431 Interim deficiency rept re discovery of extremely brittle rebar produced by FL Steel Corp. Caused by high mangonese content. Defective rebar heats will be returned by 791116. Other heats found acceptable.

  \* Tennessee Valley Authority. 79/11/18. 2pp.
- 7912130581 Forwards final deficiency rept re design deficiency of Thead section of Anchor/Darling gata valvos. MILLS.L.M. Tennessee Valley Authority. 79/11/15. 1p.
- ~~7912130401 Final deficiency rept re design deficiency of T-head section of Anchor/Darling gate valves. Company has implemented results of evaluation of T-head section for svc condition, into internal design std.

  \* Tennessee Valley Authority. 79/11/15. 2pp.
- DOCKET STN-50-554 PHIPPS BEND NUCLEAR PLANT, UNIT 2
  A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRs & DMRs. Success of program depends on industry response Supports formation of owners groups to provide necessary info.

  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.
- 7912130023 Notification of 800110 meeting w/util to discuss reporting level of util GA & manager & GA review of documents.

  BPRAUL, J. G. Guality Assurance Branch, 79/12/05, ip.
- 7912270424 Forwards US Fish & Wildlife Svc 791101 ltr stating that no federally listed proposed endangered or throatened species are known to inhabit area to be impacted by const of transmission line connectors.

  MILLS.L.M. Tannessee Vallay Authority. 79/12/17. 2pp.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review, Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Quide 1, 101.
  VABBALLO, D. B. Division of Project Management. 79/11/21. 6pp.

- Q. Adjudicatory correspondence
- 7912110043 Forwards comments on NUREG-0511 Draft GEIS reflects conscious & deliberate NRC policy to jeopardize public health & safety & thwart objectives of NEPA.

  KEPFORD, C. Environmental Coalition on Nuclear Power. 79/10/24.

  22pp.
- O. Inspection reports. IE Bulletins & correspondence
- 7912040592 Forwards IE Insp Repts 50-953/79-15 & 50-554/79-14 on 791009-12. No noncompliance noted.
  MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 79/10/31. 2pp
- ---7912060594 IE Insp Repts 50-553/79-15 & 50-554/79-14 on 791009-12.No noncompliance noted. Major areas inspected action on previous insp findings, general insp of const status, review of GA manual & licensee identified items.

  WRIGHT, R.W. Region 2, Atlanta, Office of the Director.
  CANTRELL, F.S. Region 2, Atlanta, Factor Construction & Engineering Support Dranch. 79/10/31. Spp.
- 7712060163 Forwards IE Info Notice 77-12A, "Attempted Damage to New Fuel Assemblies." No specific action or response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/09. 3pp.
- 7912070499 Forwards IE Info Notice 79-27, "Steam Queerator Tube Ruptures at Two PMR Plants." O'REILLY,J.P. Region 2. Atlanta. Office of the Director. 79/11/16. 1490
- 7912100192 Forwards IE 1mfo Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 79/11/16. 1p.
- 7912110875 Forwards IE Info Notice 79-29, "Loss of Ronsafety-Related Reactor Coulant Sys Instrumentation During Operation." No specific action or response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/16. 29p.
- 7912060620 Forwards IE Circular 79-24. "Proper Installation & Calibr of Goro Spray Pipo Break Detection Equipment on BMRs." No response required.

  O'RETLLY, J. P. Region 2. Atlanta, Office of the Director.
  79/11/26. 1p.
- 7912190478 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." No written response required. O'RETLLY,J.P. Region 2. Atlanta, Office of the Director. 79/11/30. 1p.
- 7912310316 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 100FR21." No action required.
  O'REILLY, J. P. Region 2. Atlanta, Office of the Director, 79/12/06. Opp.
- 7912200060 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EAIBO Limit Switches at Elevated Tomps." Action required. D'REILLY, J. P. Region 2. Atlanta, Office of the Director.
- 79:12280426 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required.
  0'REILLY, J. P. Region 2. Atlanta, Office of the Director.
  79/12/13. 3pp.
- 7912280100 Forwards IE Circular 79-25, "Shock Arrestor Strut Assembly Interference." No written response required. O'REILLY, J. P. Region 2: Ablanta, Office of the Director. 79/12/20. 4pp.
- S. Reportable occurrences, LERs & related correspondence
- 7912130429 Forwards interim deficiency rept re brittle rebar, produced by FL Steel Corp.
  MILLS,L.M. Tennessee Valley Authority. 79/11/15. 1p.
- ---7912130431 Interim deficiency rept re discovery of extremely brittle rebar produced by FL Steel Corp. Caused by high manganese content. Defective rebar heats will be returned by 791116. Other heats found acceptable.

  \* Tennessee Valley Authority. 79/11/15. 2pp.

- 7912130501 Forwards final deficiency rept re design deficiency of Thead section of Anchor/Darling gate valves. MILLS.L.M. Tennessee Valley Authority. 79/11/15. 1p.
- ~-7912130601 Final deficiency rept to design deficiency of T-head section of Anchor/Darling gate valves. Company has implemented results of evaluation of T-head section for svc condition, into internal design std.
  # Tennessee Valley Authority. 79/11/15. 2pp.

### DOCKET STN-50-556 BLACK FOX STATION, UNIT 1

### A. Application/construction stage documents & correspondence

- 7911280153 Discusses mods to NRC position re status & applicability of TMI-2 accident review & NUREG-0578 to facilities under const. Forwards addition to be considered in development of final plant design & procedures.

  VASSALLO, D. B. Division of Project Management. 79/10/10. 4pp.
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRs & BMRs. Success of program depends on industry response. Supports formation of owners groups to provide necessary info. DENTON: H.R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912180959 Forwards analyses re excavation seal. Analyses involve assessment of strength of mass fill of lean concrete ve natural rock structure & effect on dynamic response of safety-related structures.

  EWING.T.N. Public Service Co. of Oklahoma. 79/12/12. Opp.
- --7912180567 Informs NRC of delay in preparation of analyses re excavation seal Excavation authorized under Amend 3 of LMA. To bring entire structure up to design base elevation, mass fill of lean concrete will be required. EWING, T. N. Public Service Co. of Oklahoma, 79/10/19. Spp.

#### F. Security, medical, emergency & fire protection plans

7912070469 Notification of 791204 meeting w/utils in Bethesda.MD re NRC info requirements for emergency preparedness. Room change indicated. MOON.C.M. Light Water Reactors Branch 4. 79/11/16. 1100.

#### moditio. W. Light water Reactors Branch 4, 77711910.

#### Q. Adjudicatory correspondence

- 7912200102 "Rules of Practice for Domestic Licensing Proceedings," 10CFR2 effective rule. Suspends rule of practice on issuance of licenses after adjudicatory proceedings. Forwarding 1tr & Certificate of Svc enci.
  CHILK.B. J. Office of the Secretary of the Commission. 79/11/05, 10pp.
- 7912100344 Fifth status rapt, per ASLAB 790607 indefinite extension for NRC to respond to Suffolk County motion to file supplemental brise, Exploring possibility of stipulation re Suffolk County pending motion, Certificate of Svc encl.
  BORDENICK, B. M. Hearing Branch 4. 79/11/09, App.
- --7912100348 "Rules of Practice for Domestic Licensing Proceedings --Modifies Adjudicatory Procedures," 10CFR2.effective 791109. Suspends 10CFR2.764 until further notice. Supplementary info encl. CHILK.S.J. Office of the Secretary of the Commission. 79/11/05. 10pp.
- 7712170216 Response to CA Energy Commission 791024 motion for reconsideration of ASLB 791005 order ruling on scope of contentions. Urges inclusion of emergency planning issues & exclusion of offsite matters. LEWIS, S. H. Hearing Branch 2. 79/11/13. 7pp.
- --7912170236 "Modified Adjudicatory Procedures," 10CFR2.764 suspension & statement of policy on conduct of adjudicatory proceedings. Constitutes final action on petitions received in proceedings. SJ Catik 791105 suppl & Certificate of Byc encl.
  \* Office of the Secretary of the Commission. 79/11/09. 12pp.
- 7912030004 Notion for clarification of Commission 791105 final statement modifying adjudicatory procedures Questions whether final statement superseds or supplements Commission 791005 Interior statement Certificate of Svc encl. OALLO, J., 01888, M.E. Public Service Co. of Oklahoma, QALLO, J. Isham, Lincoln & Beale. 79/11/16. 9pp.
- 7912180069 Requests that CP not be granted & limited work order be canteled.
  BUERCKLIN.J.E. Affiliation Unknown. 79/11/20. 1p.

- 7912170101 Requests revocation of CPs due to inherent lack of safety & soaring const costs. Recommends other power sources be used.
  PIERCE.J. Affiliation Unknown. 79/11/25. 2pp.
- 7912140006 Beeks denial of applicant 791116 request for order clarifying NRC 79110B statement re modified adjudicatory procedures. No valid basis for motion. NRC statement sufficiently clear. Certificate of Byc encl.
  DAVIS,L.D. Hearing Branch 4. 79/12/04. 6pp.
- 7912180032 Decision ALAB-573 affirming ASLB determination re power from proposed facility Decision was supported by weight of evidence & ruling that App I pracludes litigation of health effects of radioactive emissions.

  SALZMAN.R.S., JOHNSON, H.R. Atomic Bafety and Licensing Board Panel, 79/12/07. 74pp.

### G. Inspection reports. IE Bulletine & correspondence

- 7912030011 Ark receipt of 791101 Itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-554/79-04 & 30-557/79-04.
  SEIDLE,N.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch.
- --7912030015 Responds to NRC 791016 ltr re violations noted in IE Insp Repts:50-556/79-04 & 50-557/79-04. Corrective actions: preventative maint record forms revised & approved 791030. PEREZ. J. B. Public Service Co. of Oklahoma. 79/11/01. 1p.
- --7912030020 Notice of deviation from insp on 791002-05. \* Region 4. Dallas, Reactor Construction & Engineering Support Branch. 79/10/15. ip.

#### DOCKET STN-50-557 BLACK FOX STATION, UNIT 2

### A. Application/construction stage documents & correspondence

- 7911280153 Discusses mode to NRC position re status & applicability of TMI-2 accident review & NUREQ-0578 to facilities under const. Forwards addl info to be considered in development of final plant design & procedures.

  VASSALLO.D.B. Division of Project Management. 79/10/10. 4pp.
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMB issue for PMRs & BMRs. Success of program depends on industry response. Supports formation of owners groups to provide necessary info. DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912180559 Forwards analyses re excavation seal. Analyses involve assessment of strength of mass fill of lean concrete vs natural rock structure & affect on dynamic response of safety-replated structures.

  EMING.T.N. Public Service Co. of Oklahoma. 79/12/12. 3pp.
- ---7912180567 Informs NRC of delay in preparation of analyses re ercavation seal. Excavation authorized under Amend 3 of LWA. To bring entire structure up to design base elevation, mass fill of lean concrete will be required. EMINO.T.N. Public Service Co. of Oklahoma. 79/10/19. Bpp.

### F. Becurity, medical, emergency & fire protection plans

7912070469 Notification of 791204 meeting w/utils in Bethesda, MD re NRG info requirements for emergency preparedness. Room change indicated. MDDN.C.M. Light Water Reactors Branch 4. 79/11/16. 11pp.

### Q. Adjudicatory correspondence

- 7912200102 "Rules of Practice for Domestic Licensing Proceedings;"
  10CFR2 effective rule. Suspends rule of practice on issuance
  of licenses after adjudicatory proceedings. Forwarding ltr &
  Certificate of Svc encl.
  CHILK, S. J. Diffice of the Secretary of the Commission, 79/11/05.
  100s.
- 7912100344 Fifth status rept.per ASLAB 790407 indefinite extension for NRC to respond to Suffolk County motion to file supplemental brise. Exploring possibility of stipulation re Suffolk County pending motion. Certificate of Svc encl.
  BORDENICK.B.M. Hearing Branch 4. 79/11/09. 4pp.

- ---791210034B "Rules of Practice for Domestic Licensing Proceedings --Modifies Adjudicatory Procedures," 10CFR2, effective 791109, Suspends 10CFR2, 764 until further notice. Supplementary info ent. CHILK.B.J. Office of the Secretary of the Commission. 79/11/05, 10an
- 7912170216 Response to CA Energy Commission 791024 motion for reconsideration of ASLB 791005 order ruling on scope of contentions. Urgas inclusion of emergency planning issues & exclusion of offsite matters.

  LENIB, S. H. Hearing Branch 2. 79/11/13. 7pp.
- --7912170236 "Modified Adjudicatory Procedures," 10CFR2,764 suspension & statement of policy on conduct of adjudicatory proceedings. Constitutes final action on petitions received in proceedings. BJ Chilk 791103 suppl & Certificate of Svc encl. # Office of the Secretary of the Commission, 79/11/09, 12pp.
- 7912030004 Metion for clarification of Commission 791105 final statement modifying adjudicatory procedures. Questions whether final statement supersedes or supplements Commission 791005 interim statement. Certificate of Byc encl. QALLO, J., QIBBS, M.E. Public Service Co. of Oklahoma. QALLO, J. Isham, Lincoln & Beale. 79/11/16. 9pp.
- 7912180069 Requests that CP not be granted & limited work order be canceled.

  BUERCKLIN.J.E. Affiliation Unknown. 79/11/20. 1p.
- 7912170101 Requests revocation of CPs due to inherent lack of safety & sourcing const costs. Recommends other power sources be used. PIERCE, J. Affiliation Unknown. 79/11/25. 2pp.
- 7912140006 Beeks denial of applicant 791116 request for order clarifying NRC 791105 statement re modified adjudicatory procedures. No valid basis for motion, NRC statement sufficiently claim Certificate of Sive encl. DAVIB.L.D. Hearing Branch 4. 79/12/04. 6pp.
- 7912180032 Decision ALAB-573 affirming ASLB determination re power from proposed facility. Decision was supported by weight of evidence & ruling that App I precludes litigation of health affects of radioactive emissions.

  SALTMAN R. 9., JOHNBON, W. R. Atomic Safety and Licensing Board Panel, 79/12/07. 94pp.
- G. Inspection reports, IE Bulletins & correspondence
- 7912030011 Ack receipt of 791101 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-356/79-04 & 30-557/79-04.

  SEIDLE, H. C. Region 4, Dellas, Reactor Construction & Engineering Support Branch. 79/11/14, ip.
- --7912030015 Responds to NRC 791016 ltr re violations noted in IE Insp. Repts 50-556/79-04 & 50-557/79-04. Corrective actions: preventative maint record forms revised & approved 791030. PEREZ.J.B. Public Bervice Co. of Uklahoma. 79/11/01. ip.
- --7912030020 Notice of deviation from insp on 791002-05.

  # Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/10/15, ip.
- DOCKET STN-50-566 YELLOW CREEK NUCLEAR PLANT, UNIT 1

  A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PWRs & BMRs. Success of program depends on industry response. Supports formation of owners groups to provide necessary info. DENTON, H.R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912130023 Natification of 800110 meeting w/util to discuss reporting level of util GA & manager & GA review of documents.

  BPRAUL, J. G. Quelity Assurance Branch. 79/12/05. 1p.
- F. Becurity, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & DL review. Applicants required to make cartain emergency arrangements wistate & local organizations & submit emergency plans par Reg Quide 1.01.
  VABSALLO, D. B. Division of Project Management. 79/11/21. Opp.

- G. Inspection reports, IE Bulletins & correspondence
- 7912030657 Forwards IE Insp Repts 50-566/79-15 & 50-567/79-15 on 790926-28. No noncompliance noted. SUTHERLAND.J.T. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 79/10/24. 2pp.
- --7912050666 IE Insp Repts 50-566/79-15 & 50-567/79-15 on 790926-28.No noncompliance noted. Major areas inspected: administrative procedures, plant site insp & review of meteorological measurements program.

  CUNNINGHAM.A.L. Region 2. Atlanta. Office of the Director. HUFHAM.J.H. Region 2. Atlanta, Fuel Facility & Materials Bafety Branch. 79/10/23. 3pp.
- 7912060077 Forwards IE Insp Repts 50-566/79-16 & 50-567/79-16 on 791016-18. No noncompliance moted.

  MURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/10/31, 2pp.
- --7912060089 IE Insp Repts 50-566/79-16 & 50-567/79-16 on 791016-18.No noncompliance noted. Major areas inspected concrete placement (Unit 1).GA audits, work packages & IE circulars.

  CANRTELL.F. 9. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. GOUGE.M.J. Region 2. Atlanta, Office of the Director. 79/10/29. Spp.
- 79:2060163 Forwards IE Info Notice 79-12A, "Attempted Damage to New Fuel Assemblies." No specific action or response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/09. 3pp.
- 7912070479 Forwards IE Info Notice 77-27, "Steam Generator Tube Ruptures at Two PMR Plants." O'REILLYJ.P. Region 2, Atlanta, Office of the Director. 79/11/16. 14pp.
- 7912100192 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pips Support Loads." No response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/11/16. ip.
- 7912110575 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Bys Instrumentation During Operation." No specific action or response required.

  O'REILLY.J.P. Region 2, Atlanta, Office of the Director.

  79/11/14. 2pp.
- 7912060620 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No response requires.

  0'RELLLY.J.P. Region 2, Atlanta, Office of the Director.
  79/11/26. ip.
- 7912110187 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 79/11/26. 1p.
- 7912190478 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus Buring Operation." No written response required.

  D'REILLY, J.P. Region 2, Atlenta, Office of the Director, 79/11/30. 10.
- 7912310316 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, 100FR21," No action required.

  D'RELLLY,J.P. Region 2. Atlanta. Office of the Director, 79/12/06. 6pp.
- 7912200060 Forwards IE Bulletin 79-28, "Possible Malfunction of Nameo Model EA180 Limit Switches at Elevated Temps." Action required. O'REILLY,J.P. Region 2, Atlanta, Office of the Director. 79/12/07. 3pp.
- 7912280426 Forwards IE Info Notice 79-31, "Uss of Incorrect Amplified Response Spectra." No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director, 79/12/13, 3pp.
- 7912280150 Forwards IE Circular 79-25, "Shock Arrestor Btrut Assembly Interference." No written response required. 0'AELLY.J.P. Region 2. Atlanta. Office of the Director. 79/12/20. 4pp.

- S. Reportable occurrences, LERs & related correspondence
- 7912050541 Second interim deficiency rept re crack in partially embedded rebar. Const procedures at sites revised Plans to submit next rept by 800208.
  MILLS,L.M. Tennessee Valley Authority. 79/11/23. 2pp.
- 7912190578 Forwards second interim deficiency rept re rebar bending not in accordance w/specs.
  MILLS.L.M. Tennessee Valley Authority. 79/11/23. 1p.
- --7912190610 Second interim deficiency rept re rebar bending not in accordance w/specs. Div of Const procedures for bending partially embedded rebar did not implement Const Spec G-2 requirements. Const Spacedures revised.

  \* Tennessee Valley Authority. 79/11/23. ip.
- 7912030199 First interim deficiency rept re nonconformance in metal conduits. Damaged threads, burrs & flaked galvanized coating detected. Defective parts will be returned to Triangle PWC & all conduits inspected.

  MILLS, L. M. Tennessee Valley Authority. 79/11/26. 2pp.
- 7912190692 Forwards first interim deficiency rept re defective electrical conduit.
  NILLS, L. M. Tannessee Valley Authority. 79/11/26. ip.
- --791217069B First interim deficiency rept re defective electrical conduit. Defects identified as damaged threads, burrs, out of round & flaking of galvanized coating. All conduits being inspected & defective conduit returned to Triangle PMC.
  \* Tennessee Valley Authority. 79/11/26. 1p.
- DOCKET STN-50-567 YELLOW CREEK NUCLEAR PLANT, UNIT 2

  A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATW3 issue for PWRs & DWRs.
  Success of program depends on industry responde. Supports formation of ouners groups to provide necessary info.
  DENTON, H. R. Office of Nucloar Reactor Regulation. 79/10/17. 3pp.
- 7912130023 Notification of 800110 meeting w/util to discuss reporting tovel of util GA & manager & OA review of documents.

  SPRAUL, J. G. Quality Assurance Branch. 79/12/05. 1p.
- F. Security, medical, emergency & fire protection plans
- 7912040471 Forwards info re upgraded emergency plans to plants under const & OL review Applicants required to make certain emergency arrangements w/state & local organizations & submit emergency plans per Reg Guide 1.101.
  VASSALLO.D.B Division of Project Management. 79/11/21. 6pp.
- G. Inspection reports: IE Bulletins & correspondence
- 7912050657 Forwards IE Insp Repts 50-564/79-15 & 50-567/79-15 on 790926-28. No noncompilance noted.
  SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/10/24. 2pp.
- --7912050466 IE Insp Repts 50-566/79-15 & 50-567/79-15 on 790926-28. No noncompliance noted Major areas inspected: administrative procedures, plant site insp & review of meteorological measurements program.
  CUNNINGHAH.A.L. Region 2, Atlanta, Office of the Director.
  HUFHAM.J.W. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/10/23. 3pp.
- 7912040D77 Forwards IE Insp Regts. 50-566/79-16 & 50-567/79-16 on 791016-18. No noncompliance noted. MURPHY.C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 79/10/31. 2pp.
- --7912060087 IE Insp Repts S0-566/79-16 & 50-367/79-16 on 791016-18. No noncompliance noted Major areas inspected concrete placement (Unit 1). 0A audits work packages & IE circulars.

  CANRTELL.F. B. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. GDUGE, M. J. Region 2. Atlanta, Office of the Director. 79/10/29. 5pp.
- 7912060163 Forwards IE Info Notice 79-12A, "Attempted Damage to New Fuel Assemblies." No specific action or response required. O'REILLY, P. Region 2, Atlanta, Office of the Director. 79/11/09. 3pp.

- 7912070499 Forwards IE Info Notice 79-27, "Steam Generator Tube Ruptures at Two PWR Plants." O'REILLY,J.P. Region 2, Atlanta, Dffice of the Director. 79/11/16. 14pp.
- 7912100192 Forwards IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads." No response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/16. 1p.
- 7912110575 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required.

  D'REILLY,J.P. Region 2, Atlanta, Office of the Director.
  79/11/16. 2pp.
- 7912060620 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." No response required.

  D'REILLY, J. P. Region 2, Atlanta, Office of the Director.
  79/11/26. 1p.
- 7912110157 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 79/11/26. 19.
- 7912190428 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation."
  No written response required.
  O'REILLY,J.P. Region 2, Atlanta, Office of the Director.
  79/11/30. 1p.
- 7912310316 Forwards IE Info Natice 79-30, "Reporting of Defects & Noncompliances, 10CFR21." No action required.
  O'REILLY.J.P. Region 2, Atlanta, Office of the Director.
  79/12/06. 6pp.
- 79:2200060 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required. D'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/12/07. 3pp.
- 7912280426 Forwards IE Info Notice 79-31, "Use of Incorrect Amplified Response Spectra." No written response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/12/13. 3pp.
- 7912280130 Forwards IE Circular 79-28, "Shock Arrestor Strut Assembly Interference." No written response required.
  O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
  79/12/20. 4pp.
- S. Reportable occurrences, LERs & related correspondence
- 7712030541 Second interim deficiency rept re crack in partially embedded rebar. Const procedures at situs revised. Plans to submit next rept by 800208.

  MILLS,L.M. Tennessee Valley Authority. 79/11/23. 2pp.
- 791219057B Forwards second interim deficiency rept re rebar bending not in accordance w/specs. MILLS.L.M. Tennossee Valley Authority. 79/11/23. ip.
- --7912190610 Second interim deficiency rept re rebar bending not in accordance w/specs. Div of Const pracedures for bending partially embedded rebar did not implement Const Spec G-2 requirements. Canst procedures revised.

  \* Tennessee Valley Authority. 79/11/23. ip.
- 7912030197 First interim deficiency rept re nonconformance in metal. conduits, Damaged threads, burrs & flaked galvanized coating detected. Defective parts will be returned to Triangle PMC & all conduits inepected. MILLS,L.M. Tennessee Valley Authority. 79/11/26. 2pp.
- 7912190692 Forwards first interim deficiency rept re defective electrical conduit.
  MILLS,L.M. Tennessee Valley Authority. 79/11/26. 1p.
- --7912190698 First interim deficiency rept re defective electrical conduit. Defects identified as damaged threads burrs out of round & flaking of galvanized coating. All conduits being inspected & defective conduit returned to Triangle PMC. \* Tennessee Valley Authority: 79/11/26. ip.

DOCKET STN-50-568 NEP NUCLEAR, UNIT 1

### A. Application/construction stage documents & correspondence

- 791128D153 Discusses made to NRC position me status & applicability of TMI-2 accident review & NUREO-0578 to facilities under const.Forwards addl info to be considered in development of final plant design & procedures.

  VASBALLO, D. B. Division of Project Management. 79/10/10. 4pp.
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMB issue for PWRs & BWRs. Guccess of program depends on industry response. Supports formation of owners groups to provide necessary info. DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. App.

#### H. Gemeral correspondence

- 7912200603 Responds to encl request for data on positive points on nuclear energy Forwards excerpts of DES (NUREO-0527).
  Probable lifetime generating costs & health effects favored nuclear plant over coal.
  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/12/03. ip.
- --7912200605 Requests data on positive points of nuclear energy, for use in class debate.
  PEEBLES, Y. S. Affiliation Unknown. 79/12/03. ip.
- 7912190019 Responds to 791101 ltr requesting nuclear energy info.
  Forwards DES re facility const.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/12/04. ip.

DOCKET STN-50-549 NEP NUCLEAR, UNIT 2

### A. Application/construction stage documents & correspondence

- 7911280133 Discusses mods to NRC position re etatus & applicability of TMI-2 accident review & NUREQ-0578 to facilities under const.Forwards addl info to be considered in development of final plant design & procedures.

  VASSALLO,D:B. Division of Project Management, 79/10/10. App.
- 7912110204 Discusses NRC plans to use generic analyses to develop early varification program to resolve ATMO issue for PMRs & BMRs.
  Success of program depends on industry response Supports formation of owners groups to provide necessary info.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. 3pp.

#### H. Gemeral correspondence

- 7912200603 Responds to encl request for data on positive points on nuclear energy. Forwards excepts of DES (NUREO-0329). Probable lifetime generating costs & health effects favored nuclear plant over coal.

  DENTON, H. R. Office of Nuclear Reactor Regulation, 79/12/03, 1p.
- --7912200605 Requests data on positive points of nuclear energy, for use in class debate.
  PEEBLE6, Y. S. Affiliation Unknown. 79/12/03. 1p.
- 7912190019 Responds to 791101 ltr requesting nuclear energy info. Forwards DEG re facility const. DENTON.H.R. Office of Nuclear Reactor Regulation. 79/12/04. lp.

DOCKET STN-50-574 BAGNAC NUCLEAR POWER PROJECT

### A. Application/construction stage documents & correspondence

- 7912030071 Forwards comments re procedural & jurisdictional issues raised by Westinghouse application. Health & safety impact of exported nuclear matts in foreign nations outside NRC jurisdiction.

  DANKMEYER, T. R. General Electric Co. 79/11/13, 14pp.
- 7912030075 Submits comments on procedural & jurisdictional issues involved in Westinghouse application. NRC has no estratoritorial jurisdiction. Health, safety & soviron aspects are responsibility of recipient country.

  DEPDIX.V.P. Atomic Industrial Forum. 79/11/16. Spp.
- 7912030066 Comments on safety & environ factors re proposed Hestinghouse application Opposes loan to Filipino govt to finance nuclear plant NRC obliged to study safety health & environ impacts of facility.

  COLLENS, B. H. Affiliation Unknown, 79/11/19. 6pp.

- 7912050219 Forwards notes & errata sheet to views on procedural & jurisdictional issues re Westinghouse application to export nuclear reactor to Philippines.

  PERLAS, J. N. Affiliation Unknown. 79/11/21. Bpp.
- 7912210141 Forwards IAEA safety expert repts & cover ltr. HAUBER,R.D. Office of International Programs. 79/12/05. 2pp.
- --7912210160 "Technical Assistance In GA & NonDestructive Testing," Field Rept 1,790710-0810. AUBERT, M. Q. International Atomic Energy Agency (Austria). 79/08/31. Bpp.
- --7912210173 "Technical Assistance In GA & MonDestructive Testing." Field Ropt 2,790810-1110. ALBERT,W. G. International Atomic Energy Agency (Austria). 79/11/30. 30pp.

#### G. Adjudicatory correspondence

- 7912080392 Forwards, on behalf of Embassy of Philippines, Natl Power Gurp views re export as interested state agency of Govt of Philippines. ROMUALDEZ, E. Z. Philippines. 79/11/15. lp.
- ---7912050396 Statement of views by Natl Power Corp. agency of Govt of Philippines, in response to Commission 791019 order. Atomic Energy & Nuclear Monproliferation Acts were not promulgated to dictate policies on foreign nations.

  \* Philippines. 79/11/15. Hpp.
- 7912030023 Response to Commission 791019 order requesting views on muclear reactor export to Philippines. Requests hearing on issues presented in 790419 patition to intervene. Supporting documentation encl.

  ASHER. T. R. Center for Development Policy. BO9IN. T. R. Bogin. M. B. 79/11/19. 67pp.
- 7912050097 Comments in response to Commission 791019 order requesting views on Commission jurisdiction to consider nuclear reactor effects in foreign country. Proceeding affects foreign policy which NRC cannot formulate.

  SCAROLA, J. A. Ebasco Gervices, Inc. (subs. of Enserch Corp.).
  79/11/19. 17pp.
- 7912050328 Affidavit of C Planas on 791119 re Westinghouse application to export nuclear reactor to Philippines. Application should be denied due to health & safety risks & high cost of maint. PLANAS.C. Affiliation Unknown. 79/11/19. 4pp.
- 7912050326 Forwards petition stating views of 16 individuals & 14 public interest groups re Westinghouse application to export nuclear reactor to Philippines in response to NRC 791019 request for comments.

  ASHER, T. R. Asher, T. R., PC. 79/11/19. 1p.
- --7912050343 Urges NRC to undertake examination of health, safety & environ impacts of proposed Philippines reactor. MATTISON, L. Center for Development Policy. 79/11/13. 2pp.
- 7912110375 Forwards Concerned Citizens Reactor Export Review Board responses to NRC hearing on nuclear reactor export to Philippines.
  HAYES,P.J. California, Univ. of, Berkeley. 79/11/19. lp.
- --7912110383 Brief in lieu of pleading, re nuclear reactor export to Philippines, Questions ability of less developed nations to deal w/nuclear technology issues. Supporting documentation encl. ZARSKY, L. Concerned Citizens Reactor Export Review Board. 79/11/19. 132pp.
- 7912030206 Forwards revised request for hearing on seven issues outlined in 790419 request to intervene.
  ASHER.T.R. Asher.T.R., PC. 79/11/21. 1p.
- --7912050211 Response to NRC 791019 request for views on Philippine export proceedings. Hearing on seven items outlined in 790419 petition to intervene requested.
  ASHER.T.R. Center for Development Policy. 79/11/21. 69pp.
- 7912050077 Response in opposition to Ctr for Development Policy, Philippine Movement for Environ Protection et al 791117 request that Commission waive rules on export proceedings. Kelloher rept available to public. Certificate of Svc encl. BECKER, J. M. Office of the Executive Legal Director. 79/11/29. Spp.

- 79:2100474 Response in opposition to Ctr for Davelopment Policy. Philippine Mavement for Environ Protection, Movement for Free Philippines & NJ Periss 79:119 pleading, Walver of seport rules will create uncertainty among importing countries. BETTAUER.R.J. State, Dept. of. 79/11/29. 4pp.
- 79:2110349 Forwards Friends of the Flipino People 79:114 ltr transmitting 1.900 signatures requesting denial of nuclear reactor export license to Philippines. Entire document available in PDR in Washingon. DC. e Docketing & Services Branch. 79/12/05. ip.
- --7912110330 Forwards petitions containing 1.900 signatures requesting denial of nuclear reactor export license to Philippines, Public hearing orged. SCHIRMER.D.S. Friends of the Filipino People, 79/11/14. Spp.

#### DOCKET STN-50-580 ERIE NUCLEAR PLANT, UNIT 1

- A. Application/construction stage documents & correspondence
- 7911280153 Discusses mods to NRC position re status & applicability of TMI-2 accident review & NUREO-0578 to facilities under const. Forwards additinfo to be considered in development of final plant design & procedures.

  VASBALLO, D. B. Division of Project Management. 79/10/10. 4pp.
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATMS issue for PMRs & BMRs.
  Success of program depends on industry response Supports formation of owners groups to provide necessary info.
  DENTON, H.R. Diffice of Nuclear Reactor Regulation. 79/10/17. Spp.
- 7912070004 Requests distribution of encl memorandum to board notification syc lists.
  VAROA.S.A. Assistant Director for Light Water Reactors. 79/11/08.
- C. Utility Environmental Report (ER), amends & correspondence
- 7912270081 Forwards updated distribution list for environ rapts & amends.
  DUNCAN.M. Environmental Projects Branch 2. 79/12/06. 4pp.
- P. Operating license stage documents & correspondence
- 7912120340 Forwards 10-yr forecast rept to be used in updating plants Final Environ Statement. W/o encl. MILLER, B. M. Ohio Edison Co. 79/12/05. ip.
- Q. Inspection reports, IE Bullatins & correspondence
- 7912050147 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No response required.
  KEPPLER, J. G. Region 3. Chicago. Office of the Director. 79/11/16.
- 7912100241 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads." No response required.

  KEPPLER, J. C. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912110586 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required. KEPPLER.J.O. Region 3. Chicago, Office of the Director. 79/11/16.
- 7912050405 Forwards IE Bulletin 79-26. "Boron Loss From BWR Control Blades." No response required.

  KEPPLER, J. C. Region 3. Chicago. Office of the Director. 79/11/20.
- 7912100441 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Sprey Pipe Break Detection Equipment on BWRs." No written response required.
  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/26.
- 7912140223 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No written response required.
  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/26.

- 7912110437 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sent by NRC to licensees.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/28.
- 7912190240 Forwards IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation."
  No written response required.
  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/11/30.
- 77:2140095 Forwards IE Info Notice 79-30. "Reporting of Defects & Noncompliances: 10CFR21." No action or response required.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/12/06.
- 7912200136 Forwards IE Bulletin 79-28. "Possible Malfunction of Nanco Model EA180 Limit Switches at Elevated Temps." Action required. KEPPLER.J. G. Region 3. Chicago. Diffice of the Director. 79/12/10.

### DUCKET STN-50-501 ERIE NUCLEAR PLANT, UNIT 2

- A. Application/construction stage decuments & correspondence
- 7911280133 Discusses mods to NRC position re status & applicability of TMI-2 accident review & NUREG-0578 to facilities under const. Forwards addl info to be considered in development of final plant design & procedures.

  VASSALLD, D. B. Division of Project Management. 79/10/10. App.
- 7912110264 Discusses NRC plans to use generic analyses to develop sarly verification program to resolve ATMS issue for PMRs & BMRs.
  Success of program depends on industry response. Supports formation of owners groups to provide necessary info.
  DENION, M. R. Office of Nuclear Reactor Regulation, 79/10/17. 3pp.
- 7912070004 Requests distribution of encl memorandum to board notification svc lists.
  VARQA.S.A. Assistant Director for Light Water Reactors. 79/11/08.
- C. Utility Environmental Report (ER), amends & correspondence
- 7912270081 Forwards updated distribution list for environ repts & amends.
  DUNCAN.M. Environmental Projects Branch 2. 79/12/06. 4pp.
- P. Operating license stage documents & correspondence
- 7912120340 Forwards 10-yr forecast rept to be used in updating plants Final Environ Statement W/o encl. MILLER, B. M. Ohio Edison Co. 79/12/05. 1p.
- Q. Inspection reports. IE Bulletins & correspondence
- 7912050147 Porwards IE Circular 79-22, "Btroke Times for Power Operated Rollef Valves." No response required. KEPPLER, J. O. Region 3. Chicago, Office of the Director. 79/11/16. ip.
- 79:2100241 Forwards IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads," No response required. KEPPLER, J. 0. Region 3, Chicago, Office of the Director. 79/11/16.
- 79:2:110586 Forwards IE Info Notice 79-29, "Loss of Nonsafety-Related Reactor Coolant Sys Instrumentation During Operation." No specific action or response required.

  KEPPLER. J. O. Region 3, Chicago, Office of the Director. 79/11/16.
- 7912050405 Forwards IE Bullatin 79-26, "Boron Loss From BUR Control Blades." No response required.
  KEPPLER, J. G. Region 3. Chicago, Office of the Director. 79/11/20.
- 7912100441 Forwards IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs." Now written response required.

  KEPPLER.J. G. Region 3, Chicago, Office of the Director. 79/11/26.

- 7912140223 Forwards IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." No written response required.
  KEPPLER, J. 9. Region 3, Chicago, Office of the Director. 79/11/26.
- 7912110437 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs copies of escalated enforcement correspondence sent by NRC to licensees.

  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/11/28.
- 7912190240 Forwards IR Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation." No written response required.

  KEPPLER, J. 9. Region 3, Chicago, Office of the Director. 79/11/30.
- 79:2140095 Forwards IE Info Notice 79-30, "Reporting of Defects & Noncompliances, IOCFR21." No action or response required. KEPPLER, J. 9. Region S. Chicago, Office of the Director. 79/12/06.
- 7912200136 Forwards IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps." Action required.

  KEPPLER, J. C. Region 3, Chicago, Office of the Director. 79/12/10.

### DOCKET BIN-50-584 GIBBBAR, GIBBB & HILL

- A. Application/construction stage documents & correspondence
- 7912120474 Forwards verification documents for in-house computer programs SCDNV. SPECTRA, QUAKE & TIME, in support of response to NRC Guestion 131, 43, PRIETO, R. Qibbs & Hill, Inc. (subs. of Dravo Corp.). 79/11/30. 53pp.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 7912120315 Forwards Amend 15 to OIBBSAR. PRIETO, R. Oibbs & Hill. Inc. (subs. of Dravo Corp.). 79/11/30. 2pp.
- --7912120318 Amend 15 to 01888AR, revising pages in Vols 1,2,3,5 & 6. Three oversize drawings and.

  \* Oibhs & Hill, Inc. (subs. of Dravo Corp.). 79/11/30. 200pp.

## DOCKET STN-50-592 PALO VERDE NUCLEAR STATION, UNIT 4

- O. Adjudicatory correspondence
- 7912280508 Requests substantive response to 791024 request for NRC to supplement EI8 to consider consequences of Class 9 nuclear accidents. Failure to respond by 800104 will indicate NRC does not plan to require suppl.

  BALDWIN.W.A. Friends of the Earth. 79/12/21. 1p.

# DOCKET BIN-50-593 FALO VERDE NUCLEAR STATION, UNIT 5

7912280308 Requests substantive response to 791024 request for NRC to supplement EI8 to consider consequences of Class 9 nuclear accidents. Failure to respond by 800104 will indicate NRC does not plan to require suppl.

BALDHIN.W.A. Friends of the Earth, 79/12/21, 1p.

### DOCKET STN-50-596 NEW HAVEN, UNIT 1

- A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early varification program to resolve ATMS issue for PMRs & BMRs. Buccess of program depends on industry response Supports formation of owners groups to provide necessary info. DENTON, H. R. Office of Nuclear Reactor Regulation, 79/10/17. Spp.
- C. Utility Environmental Report (ER), amends & correspondence
- 7712200556 Forwards updated distribution list for environ rept supple & amends.
  DUNGAN.M. Environmental Projects Branch 2. 79/12/07. 5pp.

#### G. Adjudicatory correspondence

- 7912120040 Requests for reversal of NY State Board on Electric Generation Siting & Environ 791012 dismissal of application or if reversal denied, for rehearing Ownership of proposed station did not constitute sufficient grounds for dismissal. SCHUTT.R. New York State Electric & Gas Corp. SCHUTT,R. Huber, Magill, Lawrence & Farreli. FUTTER, J.L. Long Island Lighting Co. 79/11/12. 34pp.
- 7912170149 Supports util 791029 request for indefinite delay due to NY State Siting Board 791012 dismissal of Case GOOOB. Recommends waiting for outcome of util motion due to joint federal & state proceedings. Certificate of Svc encl. LEWIB, S. H. Hearing Branch 2. 79/11/19. 6pp.
- 7912170227 Notice by NY State Board on Electric Generation Siting & Environ. Replies to utils' application for rehearing of ASLB order dismissing application for certificate of environ compactibility will be accepted if filed by 791203.

  MADISON, S. R. New York, State of. 79/11/20. 19.
- 791214001B Statement in opposition to applicants 791112 motion for rehearing re ASLB order dismissing application. Applicants failed to establish present intention to build plant. Certificate of 8vc ancl.
  ABRAMS,R., BIALIK,E.I. New York, State of. 79/11/21. 12pp.
- 7912260282 Reply in opposition to applicants 791112 mution for rehearing re NY State Siting Board dismissal of proceeding. Applicants failed to state new arguments. No beneficial purpose will be served by rehearing Certificate of Svc encl. INDYKE, C. M., FLYNN, M. New York, State of, 79/12/03. 21pp.

#### DOCKET STN-50-597 NEW HAVEN, UNIT 2

- A. Application/construction stage documents & correspondence
- 7912110264 Discusses NRC plans to use generic analyses to develop early verification program to resolve ATHB issue for PMRs & BMRs.
  Buccess of program depends on industry response. Supports formation of owners groups to provide necessary info.
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/17. Spp.
- C. Utility Environmental Report (ER), amends & correspondence
- 7912200656 Forwards updated distribution list for environ rept suppls & amends.
  DUNGAN,M. Environmental Projects Branch 2. 79/12/07. 5pp.
- Q. Adjudicatory correspondence
- 7912170149 Supports util 791029 request for indefinite delay due to NY State Siting Board 791012 dismissal of Case 80008. Recommends waiting for outcome of util motion due to joint federal & state proceedings. Certificate of Svc encl. LEWIB, S. H. Hearing Branch 2. 79/11/19. 6pp.
- 7912170227 Notice by NY State Board on Electric Generation Siting & Environ Replies to utils' application for rehearing of ASLB order dismissing application for certificate of environ compatibility will be accepted if filed by 791203.

  MADIBON, S. R. New York, State of, 79/11/20, ip.
- 7912140018 Statement in opposition to applicants 791112 motion for rehearing re ASLB order dismissing application Applicants failed to establish present intention to build plant. Certificate of 8vc ancl.
  ABRAMS.R.: BIALIK.E.I. New York: State of, 79/11/21. 12pp.
- 7912260282 Reply in opposition to applicants 791112 motion for rehearing re NY State Siting Board dismissal of proceeding. Applicants failed to state new arguments No beneficial purpose will be served by rehearing. Certificate of Byc encl. INDYKE. C. M., FLYNN, M., New York, State of. 79/12/03. 21pp.

### DOCKET 50-0598 NORTHWESTERN UNIV.

- F. Security, medical, emergency & fire protection plans
- 7912120206 Forwards draft Reg Guide S.XX, "8td Format & Content for Licensee Physical Becurity Plan for Protection of SNM of Moderate or Low Strategic Significance." W/o encl. REID, R. M. Derating Reactors Branch 4 (Pre 791030), 79/08/22... 2pp.

DOCKET 50-599 CARROLL FACILITY I

- G. Adjudicatory correspondence
- 7912130098 Supplementary brief for Contention 9 re solar energy. Details geographical & meteorological basis to establish credibility & gain admissibility for early site review. Certificate of Svc encl.
  SCHWAB. J. C. I owa Public Interest Research Group. 79/11/14. 3pp.
- 7912140034 Supplementary brief in lieu of pleading re Contention 9.
  Submits detailed geographical & meteorological basis for
  contention re feasibility studies of solar energy.
  Certificate of Svc encl.
  SCHWAB.J.C. lowa Public Interest Research Group. 79/11/14. 3pp.
- 7912130049 Deposition to admission of intervenor Citizens Against Nuclear Power Contention 15, intervenor IA Socialist Party Contentions 14(ii), 1b.ic & Id(i), intervenor State of IL Contentions 8,9 & 15b & intervenor IA PIRO Contention IIIa. GODDARD, R. J., COLDBERG, S. C. Hearing Branch 2, 79/11/21, 13pp.
- 7912130294 Notice of 791123 filing of motion to file second amended petition.memorandum in support of second amended petition filing, second agended petition.brief in support of E Gogol standing & petition for reconsideration of motion to defer.

  KODNER.J.L. Citizens Against Nuclear Power. 79/11/23. 2pp.
- 7912140192 Response to ASLB 791010 memorandum & order re special prehearing conference. Requests dismissal or mod of some of intervenors' contentions due to noncompliance w/regulations. Certificate of Svc encl. \* Commonwealth Edison Co. \* Isham, Lincoln & Beals. 79/11/23.
- 7912120557 Request for reconsideration of ASLB 791010 order for enlargement of hearing scope & for acceptance of previously filed contentions. ASLB should consider modified adjudicatory procedures & facts in case. SEKULER, S. N. Illinois, State of. 79/11/26. 16pp.
- 7912130117 Motion to file second amended petition to intervene. KODNER, J. L. Citizens Against Nuclear Power. KODNER, J. L. Kodner, J. L. 79/11/26. lp.
- --7912130120 Memorandum in support of motion to file second amended petition to intervene.Petitioner standing was confirmed by ASLB following 790919 prehearing conference. KODER, J. L. Citizens Against Nuclear Power. KODER, J. L. Kodner, J. L. 79/11/26. 5pp.
- --7912130121 Second amended petition to intervene Applicants failed to establish that Plum River fault & proximity to Stansky Airport & Savanna Army Depot will not affect site geologic & safety suitability.

  KODNER, J. L. Citirens Against Nuclear Power. 79/11/26. 1p.
- 7912140295 Petition for reconsideration of intervenors 791107 oral motion to defer further consideration of applicants' request re early site review until President's Commission results are known. Radiation-related issues should be insured. KODNER. J.L. Citizens Against Nuclear Power. KODNER. J.L. Kodner, J.L. 79/11/26. 2pp.
- 7912310340 Forwards Certificate of Svc for State of IL 791121 motion for reconsideration SEKULERS. N. 1111mgis. State of. 79/11/26. 3pp.
- 7912130066 Requests for reconsideration of ASLB 791010 order revests acceptance of Contentions I
  ), IV (6), V (a) (1) & (2). Submits
  (J) & VI

nomittee on Nuclear Energy

pport of E Gogol standing & of rejected
EPA requirements.
wer. KODNER, J. L. Kodner.

7912270049 Notifies that "Site Suitability - Site Safety Rept" & "Site Suitability - Environ Rept" will be updated & forwarded to ASLB in response to 791204 telcon.
BIELAHSKI.A.P. Isham. Lincoln & Beale. 79/12/05. 1p.

- 7912280226 Opposes Citizens Against Nuclear Power, Inc 791123 request to file second amended petition to intervene. Inexperience is no cause for filing late contentions nor is withdrawal of two proposed findings.

  BIELAMSKI.A.P. Consolidated Edison Co. of New York. BIELAMSKI.A.P. Isham, Lincoln & Beale. 79/12/10. 7pp.
- --7912280257 Opposes intervenor Jo Daviess County request to reconsider rejected contentions. Contentions 1b. III & V(a)(1)(2) & amended Contention [II(g)] re fuel & radwaste onsite storage should be dismissed. Certificate of Svc encl.
  BIELAMSKI.A.P. Consolidated Edison Co. of New York.
  BIELAWSKI.A.P. Isham. Lincoln & Beale. 79/12/10. Epp.
- 7912210406 Opposes Cititens Against Nuclear Power, Inc. J Runyon & E Gogol 791123 request for reconsideration of ABLD 791107 denial of request to defer further consideration of early site review. Certificate of Svc encl. GODDARD, R. J. Hearing Branch 2. 79/12/12. 4pp.
- 7912260110 Seeks denial of Citizens Against Nuclear Power, J Runyon & E Gogol 791123 request to file second amended petition to intervene. New contentions do not expand issues before ASLS. Cortificate of Svc encl.

  GDDDARD, R. J. Hearing Branch 2. 79/12/12. 11pp.
- 7912210093 Response to intervenor Jo Daviess County Ad Hoc Committee on Nuclear Energy Info 791123 motion to reconsider contentions rejected on ASLB 791010 order Opposes Contention IV & supports Contention III(g) deferrals.W/Certificate of Svc. GDDDARD,R. J. Hearing Branch 2. 79/12/13. App.
- H. Cemeral correspondence
- 7712310537 Certificate of Bvc for NRC statement of position on contentions & motion to consolidate.

  GDDDARD, R. J. Hearing Branch 2. 79/11/21. 2pp.

DOCKET 50-600 CARROLL FACILITY 11

- Q. Adjudicatory correspondence
- 791213009B Supplementary brief for Contention 9 re solar energy Datails geographical & meteorological basis to establish credibility & gain admissibility for early site review Certificate of Svc encl. SCHMAD.J.C. Iowa Public Interest Research Group. 79/11/14. 3pp.
- 77:2140034 Supplementary brief in lieu of pleading re Contention 9. Submits detailed geographical & meteorological basis for contention re feasibility studies of solar energy. Certificate of Svc entl. SCHWAD.J.C. Iowa Public Interest Research Group. 79/ii/i4. 3pp.
- 7912130049 Opposition to admission of intervenor Citizens Against Nuclear Power Contention 15 intervenor IA Socialist Party Contentions 1a(1), 1b, 1c & 1d(1), intervenor State of IL Contentions 8.9 & 15b & intervenor IA PIRO Contention IIIa. GODDARD.R.J. GOLDBERG.S.C. Hearing Branch 2. 79/11/21. 13pp.
- 7912130294 Notice of 791123 filing of motion to file second amended petition, memorandum in support of second amended petition filing, second amended petition, brief in support of E Gopol standing & petition for reconsideration of motion to defer. KUDNER, J. L. Citizens Against Nuclear Power. 79/11/23. 2pp.
- 7912140192 Response to ASLB 791010 memorandum & order re special prehearing conference. Requests dismissal or mod of some of intervenors' contentions due to noncompliance w/regulations. Certificate of Svc encl.

  \*\*Commonwealth Edison Co. \*\* Isham, Lincoln & Beals. 79/11/23.
- 7912120557 Request for reconsideration of ASLB 791010 order for enlargement of hearing scope & for acceptance of previously filed contentions, ASLB should consider modified adjudicatory procedures & facts in case.

  SEKULER, B. N. Illinois, State of, 79/11/26, 14pp.
- 7912130117 Motion to file second amended petition to intervens. KODNER, J. L. Citizens Against Nuclear Power. KODNER, J. L. Kodner, J. L. 79/11/26. 1p.
- ---7912130120 Memorandum in support of motion to file second amanded patition to intervene Petitioner standing was confirmed by ASLE following 790919 prehearing conference. KODNER, J. L. Citizens Against Nuclear Power. KODNER, J. L. Kodner, J. L. 79/11/26. Spp.

- ---7912130121 Second amended petition to intervene. Applicants failed to establish that Plum River fault & proximity to Stansky Airport & Savanna Army Depot will not affect site geologic & safety suitability.

  KODNER, J. L. Citizens Against Nuclear Power. 79/11/26. 1p.
- 7912140295 Petition for reconsideration of intervenors 791107 oral motion to defer further consideration of applicants' request re early site review until President's Commission results are known. Radiation-related issues should be insured.

  KODNER. J. L. Citizens Against Nuclear Power. KODNER. J. L. Kodner, J. L. 79/11/26. 2pp.
- 7912310340 Forwards Certificate of Svc for State of IL 791121 motion for reconsideration.
  SEKULER, S. N. Illinois, State of. 79/11/26, 3pp.
- 7912130066 Requests for reconsideration of ASLB 791010 order replected contentions. Requests acceptance of Contentions I (b), III (2), III (c) & (g), IV (6), V (a) (1) & (2), Submits amended Contentions III (j) & VI.
  CDX.J.N. Jo Daviess County Ad Hoc Committee on Nuclear Energy Information. 79/11/28. Spp.
- 7912130128 Brief in lieu of pleading in support of E Gogol standing & rejected contentions. Urges reinstatement of rejected Contentions 1, 2, 4, 5, 7, B, 10, 11 & 13 per NEPA requirements. KODNER, J. L. Citizens Against Nuclear Power. KODNER, J. L. Kodner, J. L. 79/11/26. 6pp.
- 7912270049 Notifies that "Bite Buitability Site Safety Rept" & "Bite Buitability Environ Rept" will be updated & forwarded to ASLB in response to 791204 telcon.
  BIELAWSKI,A.P. Isham, Lincoln & Beale. 79/12/05. 1p.
- 7912280226 Opposes Citizens Against Nuclear Power, Inc 791123 request to file second amended petition to intervene, Inexperience is no cause for filing late contentions nor is withdrawal of two proposed findings.

  BIELAMSKI.A.P. Consolidated Edison Co. of New York. BIELAWSKI.A.P. Isham, Lincoln & Beale. 79/12/10. 7pp.
- --7912280287 Opposes intervenor Jo Daviess County request to reconsider rejected contentions. Contentions ib. III & V(a)(1)(2) & amended Contention III(g) re fuel & radwaste onsite storage should be dismissed. Centificate of Svc encl.
  BIELAMSKI.A.P. Consolidated Edison Co. of New York.
  BIELAMSKI.A.P. Isham. Lincoln & Beale. 79/12/10. Spp.
- 7912210406 Opposes Citizens Against Nuclear Power, Inc. J Runyon & E Oogol 791123 request for reconsideration of ASLB 791107 denial of request to defer further consideration of early site review. Certificate of Svc encl. GODDARD.R. J. Hearing Branch 2. 79/12/12, 4pp.
- 791224011Q Beeks denial of Citizens Against Nuclear Power, J Runyon & E Gogol 791123 request to file second amended petition to intervene. New contentions do not expand issues before ASLB. Cartificate of Swc encl.
  ODDDARD, R. J. Hearing Branch 2. 79/12/12. lipp.
- 7912210093 Response to intervenor Jo Daviess County Ad Hoc Committee on Nuclear Energy Info 791123 motion to reconsider contentions rejected on ASLB 791010 order Opposes Contention IV & supports Contention III(g) deferrals.W/Certificate of Svc. CDDDARD, R. J. Hearing Branch 2. 79/12/13. 4pp.
- H. General correspondence
- 7912310539 Certificate of Svc for NRC statement of position on contentions & motion to consolidate. GDDDARD,R.J. Hearing Branch 2. 79/11/21. Rpp.

### DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

## DOCKET 70-000B BATTELLE COLUMBUS LABORATORIES

- 7912130172 Denies 790808 request for approval of tri-state primary & alternate routes. Approves 790830 request for tri-state/ alternate route. Proposal & initial arrangements w/local law enforcement agencies withheld (ref 10CFR2, 790).

  MCCORKLE, G. H. Physical Security Licensing Branch. 79/10/23, 2pp.
- 7912120038 Refunds portion of fee for License SNM-7 re Amend MPP-1, incorporating safeguards contingency plan.
  MILLER, H. D. License Fee Management Branch. 79/11/01. ip.

- 7912120052 Refunds portion of fee for License SNN-7 re Amand MPP-1, incorporating site security personnel training plan.
  MILLER.W. O. License Fee Management Branch. 79/11/02. 1p.
- DOCKET 70-0025 ROCKWELL INTERNATIONAL CORP.
- 7912260352 Requests exemption from licensing fees. Amends will be issued to licencees to incorporate decommissioning & emergency plans as conditions of licenses.
  ROUGE, L. C. Probabilistic Analysis Branch (Pre 791030). 78/07/13.
  5pp.
- 7912100433 Ack receipt of 791107 ltr informing NRC of steps taken to correct violations noted in 791026 notice of violation.
  Corrective action ltr withheld (ref 10CFR2.790).
  NGRDERHAUG.L. R. Ragion 5, Ban Francisco, Bafeguards Branch.
  79/11/19. 1p.

### DOCKET 70-0027 BARCOCK & WILCOX CO.

- 7912050093 Discusses IE insp of facility to review adequacy of operations, licenses & amend application to modify emergency evacuation procedures.

  KETZLACH, N. Uranium Fuel Licensing Branch. 79/10/31. 4pp.
- 7912170043 Discusses insp of B&H Naval Nuclear Fuel Div Facility, Commercial Nuclear Fuel Plant & Lynchburg Research Ctr. Implementation of packaging, transport & burial of low level radwaste per IE Bulletin 77-17 was adequate. KETZLACH, N. Uranium Fuel Licensing Branch. 79/10/31. 4pp.
- 7912280594 Discusses site visit of facilities for routine insp & review actions taken in response to IE Bulletin 79~19, "Packaging of Low Level Waste for Transport & Burial." KETZLACH.N. Uranium Fuel Licensing Branch. 79/10/31. 4pp.
- 7912110536 Forwards IE Insp Rept 70-0027/79-12 un 791016-19.No noncompliance noted. KENNA, M. B. Region 2, Atlanta, Safeguards Branch. 79/11/01. 2pp.
- --7912110544 IE Insp Rept 70-0027/79-12 on 791016-19. No noncompliance noted Major areas inspected organization, facility change & mod, internal review, operations procedure control & activities re packaging & shipment of low level waste. CORYELL, O.P. Region 2. Atlanta, Office of the Director. KETZLACH, N. Division of Fuel Cycle & Material Safety. GILLESPIE, F. P. Region 2. Atlanta, Safeguards Branch, 79/10/31.
- 7912110288 Refunds portion of fee for Amend MPP-1 to License SNM-42 incorporating safeguards contingency plan.
  MILLER, W. O. License Fee Management Branch. 79/11/02. 1p.
- 7912120252 Refunds portion of fee for License SNM-42 re Amend MPP-1, incorporating guard qualification & training plan.
  MILLER, W. U. License Fee Management Branch. 79/11/02. 1p.
- 791220060B Forwards IE Insp Rept 70-0027/79-14 on 791001-05. No noncompliance noted. SUTHERLAND.J.T. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 79/11/06. 1p.
- --7912200612 IE Insp Rept 70-0027/79-14 on 791001-05. No noncompliance noted. Major areas inspected external & Internal exposure, respiratory protection, internal audits, shipping containers independent surveys & procedures.

  GIBSON: A.F. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. MILLSAP, W. J. Region 2. Atlanta, Office of the Director. 79/11/06. Spp.
- 7912170052 Responds to 790209 request for exemption to License Condition 3.1 re measuring retainer samples. No exemption or license revision required if outlined procedure followed. Ltr of 790209 deemed proprietary (ref 10CFR2.790). PARTLOW, J. G. Material Control Licensing Branch. 79/11/19. 1p.
- 7912170061 Responds to 791002 submittal of revised pages to fundamental nuclear metl control plan. Safeguards Amend MPP-1 to License SNM-42 revised by adding Contention 5.5 re physical inventories. Info in 791002 itr proprietary (ref. 10CFR2. 790). PARTLOW, J. O. Material Control Licensing Branch. 79/11/19. 1p.
- 7912270015 Responds to 791115 ltr requesting time extension to complete requirements of lOCFR70, 51(e)(4)(i) for Sept-Oct mat1 balance period Safeguards Amend MPP-I revised to grant request.

  PARTLOW, J. G. Material Control Licensing Branch. 79/12/05, ip.

### DOCKET 70-0033 TEXAS INSTRUMENTS, INC.

- 7912200294 Forwards IE Insp Rept 70-0033/79-11 on 790911-13.No noncompliance noted. rteo. Region 1. Philadelphia, Safeguards Branch. 79/10/26.
- ~~7912200308 IE Insp Rept 70-0033/79-11 on 790911-13. No noncompliance noted Major areas inspected measurement & statistical controls & ID & associated LEID. Details withheld (ref 100cf82.790).

  JDYNER, J. H. Region 1. Philadelphia. Bafeguards Branch.
  HOLODY, O. J. Region 1. Philadelphia. Office of the Director.
  79/10/25. 1p.
- 7912040093 Requests registration as user of Model GRNL-BNL-NBS UN Fuel Container. SHERMAN,F.L. Texas Instruments, Inc. 79/11/15, ip.
- 7912130197 Confirms 791114 approval to use statistical procedure described in Section 3.3.8 of JL Jaech "Statistical Methods in Nuclear Matl Control." in waste drum measurement sys. PARTLOW.J. 9. Material Control Licensing Branch. 79/11/20. ip.

### DOCKET 70-0036 COMBUSTION ENGINEERING, INC.

- 7912130445 Amend 4 to License SNH-33 authorizing incinerator operation & semiannual insp by Radiation Specialist-Windsor.Forwards updated Page 1. CROM-N.T. Uranium Fuel Licensing Branch. 79/10/26. 29p.
- 7912170118 Discusses environ & safety reviews of license amend application & suppl. Incinerator for combustible scrap is acceptable.
  STEVENBON.R.L. Uranium Recovery Licensing Branch. 79/10/26.
- 7912110222 Forwards IE Insp Rept 70-0036/79-08 on 791023-26. No noncompliance noted Details withheld (ref 10CFR2.790), HIND, J. A. Region 3, Chicago, Safeguards Branch. 79/11/21. 3pp.
- -7912110275 IE Insp Rept 70-0036/79-08 on 791023-26. No noncompliance noted Major areas inspected measurement control program.

  Details withheld (ref 10CFR2. 790).
  PATTERSON.J. P., HOLDBY, D. J. Region 3, Chicago, Office of the Director. HIND, J. A. Region 3, Chicago, Safeguards Branch.
  79/11/20. 1p.

#### DOCKET 70-0135 BABCOCK & WILCOX CO.

- 7912050120 Ack receipt of 790912 ltr informing NRC of steps taken to currect violations noted in IE Imap Rept 70-0133/79-08 & 79-0364/79-12 Dotails withheld (ref 10CFR2.790).
  MARTIN. H. O. Region i, Philadelphia, Bafeguards Branch. 79/10/11.
- --7912050127 Forwards IE Insp Rept 70-0135/79-08 & 70-0364/79-12 on 790416-20 & notice of violation Notice of violation withheld (ref 10CFR2.790). HARTIN.M.O. Region I. Philadelphia, Bafeguards Branch. MARTIN. W. G. Region 1. Philadelphia, Bafeguards Branch. 79/08/20. 2pp.
- --7912050141 IE Insp Rept 70-0135/79-08 & 70-0364/79-12 on 790416-20.
  Noncompliance noted:failure to properly search vehicle
  entering protected area Details withheld (ref 10CFR2.790).
  SMITH.G.C., DUMER.J.H. Region 1, Philadelphia, Bafeguards
  Branch. 79/08/08. 4pp.
- 7912200092 Ack receipt of 791012 ltr informing NHC of steps taken to correct violations noted in IE Insp Repts 70-0135/79-06 k 70-0364/79-09. Region i, Philadelphia, Safeguards Branch. 79/11/19.
- --7912200D95 Forwards IE Insp Repts 70-0135/79-06 & 70-0364/79-09 on 790305-0427 & notice of violation. Notice of violation withheld (ref 10CFR2, 790).

  HARTIN, H. C. Region 1, Philadelphia, Eafaguards Branch. 79/10/01.
- --7912200100 IE Insp Repts 70-0135/79-06 & 70-0364/79-09 on 790305-0427.
  Noncompliance noted: failure to maintain required number of arned guards at Apollo facility. Portions withheld (ref 10CFR2, 790). of 10CFR2.7903. YNER.J.H. Region 2. Atlanta, Bafaguards Branch. KUSHNER.W.L. Region 1. Philadelphia, Office of the Director. 79/09/24. 7pp.

- 7912200426 Ack receipt of 790906 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-0135/79-04 & 70-0364/79-04.

  MARTIN, W. G. Region i, Philadelphia, Bafeguards Brench. 79/11/19.
- --7912200433 Forwards IE Insp Repts 70-0135/79-04 & 70-0364/79-04 on 790205-0302 & notice of violation. Encls withheld (ref 10CFR2.90.)
  MARTIN, M. O. Region 1, Philadelphia, Safeguards Branch, 79/08/08. 2pp.
- 7912310351 RO: on 791116, technician exposed to airborne insoluble Pu. Caused by leak in flanged connection on glovebox 175 due to failures of gasket surface & room temp vulcanized caulking compound. Gloveboxes inspected & air monitors used. AUSTIN.M. A. Babcock & Wilcox Co. 79/12/14. 2pp.

### DOCKET 70-0143 NUCLEAR FUEL SERVICES, INC.

- 7912200477 PNS-II-79-102J: on 791010, mobile lab analyzed metal sigg turned in to Johnson City Press Chronicle reporter. Matl found to be depleted U measuring one by two inches. No radiological hazard.
  OILLESPIE.F.P. Region 2. Atlanta. Office of the Director. 79/10/10.
- 7912170044 Confirms clarifications re 791108 ltr on measurement requirement for inventory samples, Condition 2.14 of Amend MPP-1 to License SMM-124 revised. Info in licensee ltr proprietary (ref 10CFR2.790).
  PARTLOW, J. O. Material Control Licensing Branch. 79/11/20. 2pp.
- 7912200305 Requests fee for 791107 application for amend of License SNM-124 for exemption from annual evacuation drill requirements for each shift.
  WEISS.J.D. License Fee Management Branch. 79/11/23. 1p.
- 7912260171 Ack receipt of 791126 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0143/79-39.
  KENNA, W. B. Region 2, Atlanta, Bafeguards Branch. 79/12/11. lp.
- --7912260175 Responds to NRC 791102 ltr re violations noted in IE Insp. Rept 70-0143/79-09. Corrective actions withheld (ref. 10CFR2. 790).
  MANBER. W. C. Nuclear Fuel Services, Inc. (subs. of Oatty Dil Co.). 79/11/26. |p.
- --7912260178 Forwards IE Insp Rept 70-0143/79-39 on 790910-14 & notice of violation. Notice of violation withheld (ref 10CFR2.790).
  KENNA, H. B. Region 2, Atlanta, Bafeguards Branch. 79/11/02.
- --7912260181 IE Insp Rept 70-0143/79-39 on 790910-14. Noncompliance nates: failure to report stack, laundry & sanitary sewer losses for May, June & Jul 1979. Details withheld (ref 10CFR2.790). BATES J.W. Region 2. Atlanta, Dffice of the Director. OILLESPIE.F.P. Region 2. Atlanta, Bafeguards Branch. 79/10/31.

#### DOCKET 70-0250 THE BOEING CO.

- 7912200685 IE Insp Findings & Licensee Ack dtd 791023 of License ENM-255. Insp findings: no items of noncompliance or unsafe conditions found. \* Region 5. Ban Francisco, Office of the Director. 79/10/23. 1p.
- DOCKET 70-0364 PARKS TOWNSHIP SITE, BASCOCK & WILCOX CO.
- 7912050120 Ack receipt of 790912 ltr informing NRC of steps taken to correct violations noted in IE Imap Rept 70-0135/79-08 & 79-0364/79-12 Details withheld (ref 100FR2, 790).
  MARTIN, W. Q. Region 1, Philadelphia, Safeguards Branch. 79/10/11.
- --7912050127 Forwards IE Insp Rept 70-0135/79-08 & 70-0364/79-12 on 790416-20 & notice of violation Notice of violation withheld (ref 100FRZ 790).

  MARTIN H. O. Region i, Philadelphia, Safeguards Branch.
  79/08/20. 2pp.
- -7912050141 IE Insp Rept 70-0135/79-08 & 70-0364/79-12 on 790416-20. Noncompliance noted: failurs to properly search vehicle entering protected area Details withheld (ref 100FR2.790), SMITH, G.C., JOYNER, J.H. Region 1, Philadelphia, Safeguards Branch. 79/08/08. 4pp.

- 7912200510 Forwards IE Insp Rept 70-0364/79-23 on 790910-14, No noncompliance noted
  MARTIN. N. C. Reg Region 1, Philadolphia, Bafeguards Branch. 79/11/02.
- --7912200516 IE Insp Rept 70- 0364/79-23 on 790910-14 No noncompliance noted Major areas inspected: measurement control program inventory reconciliation & records & repts. Details withheld (ref 10CFR2.790.) (ref 10CFR2.790.) JOYNER, J. H., RATTA, A. D., ZIBULSKY, H. Bafeguards Branch. 79/10/23. 1p. Region 1, Philadelphia,
- 7912120101 Ack receipt of 791009 ltr informing NRC of stepts taken to correct violations noted in IE Insp Rept 70-0364/79-22.
  QRIER,B.H. Region 1, Philadelphia, Office of the Director.
  79/11/09. ip.
- --7912120106 Responds to NRC 790918 ltr re violations noted in IE Insp Rept 70-0364/79-22. Corrective actions:neutron maters calibr in accordance w/Procedure GC-CD-80-019. AUSTIN.M.A. Babcock & Wilcox Co., Nuclear Material Div. 79/10/09.
- --7912120110 Forwards IE Insp Rept 70-0364/79-22 on 790821-23 & notice of violation.

  Region 1, Philadelphia, Fuel Facility & Materials
  Bafety Branch. 79/09/18. 2pp.
- --7912120115 Notice of violation from insp on 790821-23.
  \* Region i. Philadelphia. Office of the Director. 79/09/17. 200.
- 7912200092 Ack receipt of 791012 1tr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-0135/79-06 & 70-0364/79-09.

  MARTIN, H. G. Region 1, Philadelphia, Safeguards Branch. 79/11/19.
- --7912200100 IE Insp Repts 70-0135/79-06 & 70-0364/79-09 on 790308-0427.
  Noncompliance noted:failure to maintain required number of armed guards at Apollo facility.Portions withheld (ref 10CFR2.790).
  JUYNER.J.H. Region 2. Atlanta. Bafeguards Branch. KUSHNER.W.L. Region 1. Philadelphia. Office of the Director. 79/09/24. 7pp.
- 7912200426 Ack receipt of 790906 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-013B/79-04 & 70-0364/79-04.

  MARTIN.W. G. Region 1, Philadelphia, Safeguards Branch. 79/11/19.
- --7912200433 Forwards IE Insp Repts 70-0135/79-04 & 70-0364/79-04 on 790205-0302 & notice of violation. Encls withheld (ref 10CFR2. 90.)
  MARTIN. N. G. Region i, Philadelphia, Safaguards Branch. 79/08/08. 2pp.

### DOCKET 70-0371 UNITED NUCLEAR CORP.

- 7912070269 Forwards IE Insp Rept 70-0371/79-14 on 790813-17. No noncompliance noted.

  MARTIN. M. O. Region 1. Philadelphia. Safeguards Branch. 79/09/26.
- --7912070273 IE Insp Rept 70-0371/79-14 on 790813-17. No noncompliance noted. Major areas inspected: physical inventory reconciliation & records & repts.
  COHEN, I. Region 1, Philadelphia, Office of the Director.
  WOLTNER, E., JOYNER, J. H. Region 1, Philadelphia, Bafeguards Branch. 79/09/20. ip.
- 7912200317 Forwards IE Insp Rept 70-0371/79-17 on 790910-14. No nuncompliance noted.
  MARTIN.W. Q. Region 1. Philadelphia, Safeguards Branch. 79/10/29.
- -7912200333 IE Insp Rept ,70-0371/79-17 on 790910-14. No noncompliance moted. Major areas inspected: facility organization, facility operation & storage & internal control. Details withheld (ref 10CFR2, 790).

  UCYNER, J. H., MDLTNER, E., SMITH, Q. Region 1, Philadelphia, Bafaguards Branch. 79/10/23. 1p.
- 7912120032 Notifies of completion of review of 790307 revised emergency plan. Forwards request for addl info.
  ROW.W.T. Uranium Fuel Licensing Branch. 79/10/30. 4pp.

- 7912260043 Forwards IE Insp Rept 70-0371/79-18 on 791001-04.No noncompliance noted.

  MARTIN.W. G. Region 1, Philadelphia, Bafeguards Branch. 79/11/07.
- --7912260046 IE Insp Rept 70-0371/79-18 on 791001-14. No noncompliance noted Major areas inspected:mgt of matis control sys & licensee action on previous insp findings.
  WOLTNER.E. Region 1. Philadelphia. Office of the Director.
  JOYNER.J. M. Region 1. Philadelphia. Safeguards Branch.
  79/11/05. 1p.
- 7912200076 Ack receipt of 791008 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0371/79-09.
  Details withheld (ref 10CFR2.790).
  MARTIN.W.O. Region 1. Philadelphia, Bafeguards Branch. 79/11/19.
- --7912200081 Forwards IE Insp Rept 79-0371/79-09 on 790517-24 & notice of violation Notice of violation withheld (ref 100FR2 790). MARTIN N. O. Region 1, Philadelphia, Safeguards Branch. 79/09/13. 2pp.
- --7912200088 IE Insp Rept 70-0371/79-09 on 790517-24. Noncompliance noted: unsecured boxes did not include verification of serial numbers, 9% of items in scrap storage area have errors in stated U inventory values. Details withheld (ref 10CFR2,790). JUVNER, J. H. Region 1, Philadelphia, Safeguards Branch. COHEN, I. Region 1, Philadelphia, Office of the Director. 79/09/01. 1p.

#### DOCKET 70-0687 UNION CARBIDE CORP.

- 7912070077 Ack receipt of 790706 ltr informing NRC of steps taken to corract violations noted in IE Insp Rept 70-0687/79-02. SMITH.O.H. Region 1. Philadelphia, Fuel Facility & Materials Safety Branch. 79/10/15. 1p.
- -7912070086 Responds to NRC 790808 ltr re violations noted in IE Insp. Rept 70-0687/79-02 Corrective actions: radiation personnel monitors conveniently placed & warning sign posted on GC lab MCGOVERN, J. J. Union Carbide Corp. 79/09/06. 4pp.
- --7912070088 Forwards 790907 memo instructing personnel to use monitoring equipment. MCGOVERN.J.J. Union Carbide Corp. 79/09/13. 2pp.
- --7912070095 Forwards IE linsp Rept 70-0687/79-02 on 790514-16 & notice of wiolation.

  SMITH.G.H. Region 1, Philadolphia, Fuel Facility & Materials
  Bafety Branch. 79/08/08. 2pp.
- --7912070098 Natice of violation from insp on 790514-14.

  \* Region 1: Philadelphia. Office of the Director. 79/08/06. 2рр.
- --7912070113 IE Insp Rept 70-0687/79-02 on 790514-16. Noncompliance noted: failure to maintain drum array in storage hot cells, to survey for alpha contamination & to maintain running inventory log of U-23.

  ROTH.J., CROCKER, H. H. Region 1, Philadelphia, Fuel Facility & inventory log of U-235. ROTH.J., CROCKER.H.H. Region 1. Philadelphia, Fuel Facility & Materials Safety Branch. 79/08/06. 11pp.
- 7912090642 Ack receipt of 790924 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 79-0687/79-03. SHITH, O. H. Region 1. Philadelphia, Fuel Facility & Materials Bafety Branch. 79/10/24. 2pp.
- ---7912050648 Responds to NRC 790830 ltr re violations noted in IE Insp. Rept 70-0687/79-03. Corrective actions: reviewed & updated personnel exposure history forms & urinalyses performed on hot lab personnel.

  KCGOVERN, J. J. Union Carbide Corp. 79/09/24. 3pp.
- --7912050655 Forwards IE Insp Rept 70-0687/79-03 on 790711-13 & notice of violation. SMITH, G. H. viciation. BMITH.O.H. Region 1. Philadelphia. Fuel Facility & Materials Safety Branch. 79/08/30. 2pp.
- --7912050658 Notice of violation from insp on 790711-13.

  \* Region i. Philadelphia. Office of the Director. 79/08/27.
  3pp.

- --7912050662 IE Insp Rept 70-04B7/79-03 on 790711-13. Noncompliance noted: failure to post criticality sign.complete Form 4, provide alpha monitor & perform bioassay.
  STOHR.J.P. Region 1. Philadelphia. Fuel Facility & Materials Safety Branch. CLEMONS.P.E. Region 1. Philadelphia, Office of the Director 79/08/27 9pp.
- 7912360054 Ack receipt of 791025 ltm informing NRC of steps taken to currect violations noted in IE Insp Repts 50-054/79-03 & 70-0687/79-01.
  MRTIN.W. G. Region 1, Philadelphia, Safeguards Branch. 79/11/19.
  19.
- --7912260061 Responds to NRC 790919 ltr re violations noted in IE lnsp Repts 50-054779-00 & 70-0607/79-01. Corrective actions: increasing mgt control of training program & schedule of audits promulgated. MCGOVERN, J. J. Union Carbide Corp. 79/10/25. lp.
- --791226006B Forwards IE Insp Repts 50-054/79-03 & 70-06B7/79-01 on 790424-27 & notice of violation withheld (ref 10CFR2.790).
  MARTN. H. G. Region 1, Philadelphia, Safeguards Branch. 79/09/19. 2pp.
- --7912260074 IE Insp Repts 50-054/79-03 & 70-0687/79-01 on 790424-27.

  Noncompliance noted:fasture to perform required training of personnel Details of insp withheld traf LOCER2. 790).

  HOLDDY,D.J., ZIBULSKY,H. Region 1, Philadelphia, Office of the Director. JUYNER.J.H. Region 1, Philadelphia, Safeguards Branch. 79/08/20. ip.

#### DUCKET 70-0493 NUCLEAR RESEARCH CORP.

7912110182 Discusses IE (hsp Repts 30-04048/79-01.30-08867/79-01.40-8621/79-01 & 70-0693/79-01 on 791003 No noncompliance noted Major areas inspected: radiation safety & compliance w/NRC regulations.
MCCLINTOCK, R. O. Region 1. Philadelphia, Office of the Director. 79/10/18. 2pp

### DOCKET 70-0734 GENERAL ATOMIC CO.

- 7912120050 Refunds portion of fee for License SNM-696 re Amend MPP-1, incorporating security guard training & qualification plan.
  MILLER, M. O. License Fee Management Branch. 79/11/01. 1p.
- 7912120045 Refunds portion of fee for License BNM-696 re Amend MPP-1, incorporating contingency plan.
  MILLER, W. O. License Fee Management Branch. 79/11/02. 1p.
- 7912180244 Forwards IE Insp Rept 70-0734/79-10 on 791015-19. No noncompliance nobod Major areas inspected procedures & records re program for controlling & accounting for SNM. Insp rept withheld (ref 10CFR2. 790).
  NGROERHAUG, L. R. Region 5, San Francisco, Bafeguards Branch. 79/11/08. 2pp.
- 7912260029 Forwards IE Insp Rept 70-0734/79-12 on 791113-15. No noncompliance noted Major areas inspected activities rephysical protection against industrial sabotage & theft of nuclear matl. Rept withheld (ref 10CFR2, 790).
  NORDERHAUS. L. R. Region 5. San Francisco, Safeguards Branch, 79/12/11. 2pp.

### DOCKET 70-0754 VALLECITOS NUCLEAR CENTER, GENERAL ELECTRIC CO.

- 7912070256 Request for interlocutory appeal from ASLO 791010 memorandum & order re demial of RV Dellums request to participate in proceedings & to be represented by staff members not admitted to practice before federal or state bars.

  DELLUMS.R.V. House of Rep. 79/10/26. 3ρρ.
- 7912100350 Refunds portion of fee for Amend MPP-2 to License SNN-940, incorporating security guard training & qualification plan.
  MILLER.W.D. License Fee Management Branch. 79/11/02. lp.
- 7912180086 Forwards IE Insp Rept 70-0754/79-09 on 790918-21.Nu noncompliance noted. BOOK.H.E. Region 5. San Francisco, Fuel Facility & Materials Safety Branch. 79/11/13. 2pp.
- --7912180092 IE Insp Rept 70-0754/79-09 on 790918-21. No noncompliance noted Major areas inspected prantization facility changes & mods, safety committee activities & operations review. COUCEV.W.J. Region 3, Chicago, Fuel Facility & Materials Safety Branch. BOOK.H.E. NRC Regional Offices. 79/11/09. 5pp.

- 7912310166 Responds to 790815 request for approval of spent fuel shipment routes. Primary routing disapproved. Alternate routing approved w/mod recommended by CA Highway Patrol. MCCORKLE, G. W. Physical Security Licensing Branch. 79/11/21. 200.
- 7912190113 Forwards analyses of postulated accident scenarios at facility to support Chapter 7 of GE BER, for which LASL was responsible.
  ROSE, D. Q. Los Alamos Scientific Laboratory. 79/12/13. 78pp.

### DOCKET 70-0820 UNITED NUCLEAR CORP.

- 7912120531 Ack receipt of 790710 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0820/79-08.
  MARTIN, H. G. Region i, Philadelphia, Safeguards Branch. 79/10/11.
- --7912120540 Responds to NRC 790622 ltr re violations noted in IE Insp Rept 70-0820/79-08. Corrective actions withheld (ref 10CFR2, 790). BUMERB,C.E. United Nuclear Corp., UNC Recovery Systems Div. 79/07/10. 1p.
- --7912120549 Forwards IE Insp Rept 70-0820/79-0B & notice of violation. Notice of violation withheld (ref 10CFR2.790). MARTIN.W.O. Region 1. Philadelphia. Safeguards Branch. 79/06/22. 2pp.
- --7912120560 IE Insp Rept 70-0820/79-08 on 790313-16. Noncompliance nated: failure to adjust control & subsidiary accounts to results of two physical inventories within 30 calendar days after start of each inventory. Details withheld (ref 10CFR2, 790). ODDY, A., HOLODY, D.J. Region i, Philadelphia, Dffice of the Director. JOYNER, J. H. Region i, Philadelphia, Safeguards Branch. 79/06/20. ip.
- 7912100049 Forwards IE Insp Rept 70-0820/79-14 on 790710-13.No noncompliance noted.

  MARTIN, W. G. Region I, Philadelphia, Safeguards Branch. 79/10/23.
- --7912100057 IE Insp Rept 70-0820/79-14 on 790710-13. No noncompliance noted Major areas inspected security plan, security organization physical barriers, access controls, detection aids & response controls. Details withheld (ref 10CFR2. 790). LADUN, R., ROSAND, R. Region i, Philadelphia, Dffice of the Director. DEVLIN, J. W. Region 1, Philadelphia, Bafeguards Branch. 79/10/18. 1p.
- 7912260059 Forwards IE Insp Rept 70-0820/79-19 on 790910-14. No noncompliance noted.
  MARTIN. N. G. Region 1. Philadelphia, Bafeguards Branch. 79/11/06.
- --7912260063 IE insp Rept 70-0820/79-19 on 790910-14. No noncompliance noted Major areas inspected: facility organization & operation. Dotails withheld (ref IOCFR2.790).

  COHEN, I., GODY, A. Region 1, Philadelphia, Office of the Director. JOYNER, J.H. Region 1, Philadelphia, Bafeguards Branch. 79/10/25. 1p.
- 7912060085 Ack receipt of 791003 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0820/79-18.
  EMITH.C.H. Region 1. Philadelphia, Fuel Facility & Materials Bafety Branch. 79/11/09. 1p.
- --7912060091 Responds to NRC 790924 ltr re violations noted in IE Insp. Rept 70-0820/79-18. Advises ref sign not required for Co-60 room. Twice-weekly surveys of beta-gamma radiation conducted. BOHERB. C.E. United Nuclear Corp., UNC Recovery Systems Div. 79/10/03. App.
- --7912060096 Forwards IE Insp Rept 70-0820/79-18 on 790905-07 & notice of violation. SMITH.O.H. Region i. Philadelphia, Fuel Facility & Materials Safety Branch. 79/09/24. 2pp.
- ---7912060105 Notice of violation from insp on 790905-07.

  \* Region 1. Philadelphia, Office of the Director. 79/09/21.
  io.
- --7912060110 IE Insp Rept 70-0820/79-18 on 790905-07. Noncompliance notes:
  failure to post room & failure to perform survey at stated
  fraquency,
  CLEMONS, P. E. Region i, Philadelphia, Offics of the Director.
  BTOHR, J. P. Region i, Philadelphia, Fuel Facility & Materials
  Safety Branch. 79/09/21. 6pp.

- 7912170067 Responds to 790420 submittal of revised pages to fundamental nuclear math control plan. Requests review of encl comments & forwarding of revisions within 30 days. Info in 790420 ltr proprietary (ref 10CFR2. 790).
  PARTLOW, J. G. Material Control Licensing Branch. 79/11/16. 2pp.,
- 7912310291 Ack receipt of 791024 1tr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0820/79-16.

  EMITH.G.H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 79/11/30. 2pp.
- --7912310299 Responds to NRC 791009 ltr re violations noted in IE Insp Rept 70-0820/79-16. Corrective actions: future shipments of BNM in containers w/inner container will have required records. BDMERG. C.E. United Nuclear Corp., UNC Recovery Systems Div. 79/10/24, 4pp.
- --7912310304 Forwards IE Insp Rept 70-0820/79-16 on 790827-31 & notice of violation.
  BMITH.G.H. Region i. Philadelphia, Fuel Facility & Materials Safety Branch. 79/10/09. 2pp.
- --7912310311 Notice of violation from insp on 790827-31.

  \* Region I. Philadelphia, Office of the Director. 79/10/04.
  2pp.
- --7912310320 IE Insp Rept 70-0820/79-16 on 790827-31. Noncompliance noted: failure to have procedures which specifically address proper closure of shipping containers, especially inner container. KINNEY.H.H. Region 1, Philadelphia, Office of the Director, CROCKER,H.H. Region 1, Philadelphia, Fuel Facility & Materials Bafety Branch. 79/10/04. 13pp.

#### DOCKET 70-0824 BABCOCK & WILCOX CO.

- 7912260352 Requests exemption from licensing fees. Amends will be issued to licences to incorporate decommissioning & emergency plans as conditions of licenses. ROUSE, L. C. Probabilistic Analysis Branch (Pre 791030). 78/07/13. 3pp.
- 7912050093 Discusses IE insp of facility to review adequacy of operations. Licenses & amend application to modify emergency evacuation procedures.

  KETZLACH.N. Uranium Fuel Licensing Branch. 79/10/3i. 4pp.
- 7912170043 Discusses insp of 8&H Naval Nuclear Fuel Div Facility.
  Commercial Nuclear Fuel Plant & Lynchburg Research Ctr.
  Implementation of packaging transport & burial of low level
  radwaste per IE Bulletin 79-19 was adequate.
  KETZLACH.N. Uranium Fuel Licensing Branch. 79/10/31. 4pp.
- 7912280594 Discusses site visit of facilities for routine insp & review actions taken in response to IE Bulletin 79-19.
  "Packaging of Low Level Haste far Transport & Burtal."
  KETZLACH.N. Uranium Fuel Licensing Branch. 79/10/31. 4pp.
- 7912100046 Ack receipt of 791112 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0824/79-06.

  SUTHERLAND.J. T. Region 2. Atlanta. Fuel Facility & Materials Safety Branch. 79/11/19. 1p.
- --7912100052 Responds to NRC 791019 ltr re violation noted in IE Insp. Rept 70-0824/79-04. Corrective actions: powered air respirators used in hot cell entries & supplied air sysbeing installed.

  ENGELDER, T. C. Babcock & Wilcox Co. 79/11/12. lp.
- --7912100056 Forwards IE Insp Rept 70-0824/79-06 on 790910-14 & notice of violation.

  SUTHERLAND.J.T. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 79/10/19. 2pp.
- ---7912100060 Notice of violation from insp on 790910-14.

  \* Region 2, Atlanta, Office of the Director. 79/10/18. ip.
- --7912100070 IE Insp Rept 70-0824/79-06 on 790910-14 Noncompliance noted:improper control of issuance & return of respiratirs. MILLSAP, U.J. Region 2, Atlanta, Office of the Director. OIBSDN.A.F. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/10/18. 7pp.

### BOCKET 70-0903 GULF UNITED NUCLEAR FUELS CORP.

- 7912070263 Partially responds to FOIA request for document re Pawling, NY site. Forwards requested info. Submits addl info: sodium deuterium reactor never built at site, no matl ever used at site & no radioactive matl disposed of in lake.

  CARR.J. C. Division of Rules and Records. 79/11/16. 3pp.
- ---7912070274 Discusses GA Co 740311 application to delete Pawling, NY as authorized place of use for License SNM-071. Site represents insignificant risk to public. Recommends that license be terminated.

  CROW, W. T. Division of Fuel Cycle & Material Safety. 75/07/14.
- --7912070289 Forwards ltrs sent to NY transmitting analytical results of 780408 soil sampling at Gulf United Nuclear in Pawling, NY. Submits tabulation of Pu-238 & Pu-239 results. No objection to termination of Gulf United Nuclear license. W/o encl. DAVIE. J. G. Office of Inspection & Enforcement, Office of the Director. 75/07/07. 2pp.
- --7912070299 Discusses 740603 notification by Region 1 re suspicion of Pu contamination in concrete Region 1 will investigate.

  Region 1 has requested that Pawling, NY site not be deleted from License SMM-871.

  CROW, W. T. Division of Fuel Cycle & Material Safety. 74/06/05.
  1p.
- --7912070305 Discusses review of data on Pu concentrations in soil samples taken at Pawling.NY site. Concentrations do not represent radiation exposure hazard.
  MAGNO, P. J. Commission. 75/06/25. 1p.
- --7912070335 Forwards results of analyses performed by IE Health Svcs Lab on soil samples taken at Gulf United Nuclear, Pawling, NY site, NY Health Dept 750308 ltr & EPA 750108 ltrs encl. NELSON, P. R. Region 1, Philadelphia, Office of the Director. 75/05/06. 4pp.
- ---7912070368 Forwards Insp Rept 70-0903/74-17 on 740905. No noncompliance noted. Major areas inspected: followup on decontamination of facility.

  NELEGN.P.R. Region 1: Philadelphia: Office of the Director. 74/09/26. 9pp.
- --7912070376 Bummary of 740729 meeting in Washington.DC re Pu concentrations in soil, in connection b/decommissioning NRC recommended that ALAP approach be used & each site be treated on case-by-case basis. W/decommissioning description. HAMADA.G. Atomic Energy Commission. 74/08/22. App.
- 79.12070291 Submits partial response to FOIA request for documents re Nuclear Development Association,United Nuclear Corp.Gulf United Nuclear Corp & ATCOR.Inc.concerning facility sits. Forwards requested info. Provides add! info re site. CARR.J.C. Division of Rules and Records. 79/11/16. 3pp.
- --7912070300 Requests deletion of Pawling & Eastview, NY as authorized places of use & that all records re locations be destroyed.

  Also requests that License SNM-871 not be terminated, LOYSEN,P. Gulf Oil Corp. 74/03/11. Jpp.
- --7912070303 "Results of Radiological Survey." # ATCOR. 74/03/11. 67pp.
- --7912070316 Forwards addl results of analyses performed by ID Health Svcs Lab on soil samples taken at site. NELBON.P.R. Region 1. Philadelphia. Office of the Director. 75/06/09. 2pp.
- --7912070317 Forwards supporting documentation for conclusion that 2.0 disintegrations/minute of Pu/g of soil is appropriate criteria for use in determining acceptable Pu concentration. BYRNISA.F.V. New York, State of. 75/06/20. 13pp.
- --7912070347 Requests guidance re levels of Pu acceptable to AEC for unrestricted areas. Forwards results of licensee subcontractor & AEC analyses of four soil samples. BTOHR, J. P. Atomic Energy Commission. 74/07/10. 7pp.
- ---7912070360 Discusses 74080B site visit by QA Co & United Nuclear Corp to examine Site, review results of analyses of radioactive math in soil & to determine course of action for termination of license portion concerning Pawling, NY. LOYSEN, P. General Atomic Co. (subs. of Quif Gil Co.). 74/08/15.

## DOCKET 70-0925 CIMMARON FACILITY, KERR-MCGEE CORP.

- 7912040013 Forwards IE Insp Repts 70-0925/79-04 & 70-1193/79-04 on 790827-29 & 0926-27 & notice of violation. DAVIS.A.B. Region 3. Chicago: Fuel Facility & Materials Safety Branch. 79/10/30. 2pp.
- --7912040015 Notice of violation from insp on 790827-29 & 0926-27.

  Region 3, Chicago, Office of the Director. 79/10/30. ip
- ---7912040016 IE 1nsp Repts 70-0925/79-04 & 70-1193/79-04 on 790827-29 & 0926-27. Noncompliance noted failure to submit employee termination repts to NRC.
  OREGER.L.R. Region 3. Chicago, Fuel Facility & Materials Safety Branch. DUBRY, N.E. Region 3. Chicago, Office of the Director. 79/10/30. 10pp.

### DOCKET 70-1100 COMBUSTION ENGINEERING, INC.

- 7912190768 Ack receipt of 791010 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 70-1100/79-06.
  MARTIN.W.O. Region 1, Philadelphia, Safeguards Branch. 79/11/19.
- --7912190775 Forwards IE Insp Rept 70-1100/79-06 on 790724-26 & notice of violation Notice of violation withheld (ref 10CFR2.790).
  MARTIN.H. 0. Region 1, Philadelphia, Safeguards Branch.
  79/09/25, 2pp.
- --7912190781 IE Insp Rept 70-1100/79-06 on 790724-26. Noncompliance noted:
  limit of error calculations for receipts of U dioxide powder
  & shipments of finished fuel failed to include proper error
  rate. Details withheld (ref 10CFR2. 790).
  JOYNER.J.H. Region 1, Philadelphia, Bafeguards Branch.
  HDLODY,D.J. Region 1, Philadelphia, Office of the Director.
  79/09/13. ip.
- 7912260256 Notifies of partial refund of review fee for Amend 22 to License SMM-1067. MILLER, W. D. License Fee Management Branch. 79/12/06. 1p.

### DOCKET 70-1113 GENERAL ELECTRIC CO.

- 7912190320 Discusses review of GE transfer of liquid hydrogen fluoride containing 2.600 uCi V enriched to 4% Matl will be used by Brush Weilman Co for beryllium pebble production. Environ contamination not expected.

  SHUM, E. Y. Uranium Recovery Licensing Branch. 79/10/25. 2pp.
- 7912180025 U Process Licensing Section input to safety evaluation reamend deleting requirement for separate training program for each worker category.

  STEVENSON, R. L. Office of Nuclear Reactor Regulation. 79/11/06.
  2pp.
- 7912180239 Amends License SNM-t097 to delete requirement for separate radiation safety training program for each working position in fuel mfg operation. Corrects date error in Amend B. CROM, M. T. Uranium Fuel Licensing Branch. 79/11/06. ip.

### DOCKET 70-1143 WESTINGHOUSE ELECTRIC CORP.

- 7912090080 Ack receipt of 790928 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1143/79-0.

  BMITH, O. H. Region 1. Philadelphia: Fuel Facility & Materials Safety Branch. 79/10/15. 1p.
- --7912050085 Responds to NRC 790706 ltr re violation noted in IE Insp Rept 70-1143/79-05. Corrective actions: until renewed license is issued, storage & Gatling gun arrangement will be limited to 3.8 kg Pu. MORE, J. 9. Westinghouse Electric Corp., Nuclear Energy Systems, 79/09/28. tp.
- --7912050095 Responds to 790712 ltr re violation noted in IE Insp Rept 70-1143/79-05. May permissible value in storage rack & horizontal square area for fissile matl overlapped completely. Requests info re corrective actions. GMITH, G. H. Region i. Philadelphia, Fuel Facility & Materials Safety Branch. 79/09/06. 2pp.

- --7912050099 Responds to NRC 770621 ltr re violations noted in IE 140 Rept 70-143/79-05. Disagrees w/NRC & requests item of noncompliance be dropped. Figures re improperly centered subcriticals & overlapping areas encl.
  MODRE, J. S. Westinghouse Electric Corp., Nuclear Energy Bystess, 79/07/12. Spp.
- --7912050102 Forwards IE Insp Rept 70-1143/79-03 on 790327-30 & notion of violation.
  SMITH, O.H. Region 1, Philadelphia, Fuel Facility & Haterielt Bafety Branch. 79/06/21. 2pp.
- --7912050104 Notice of violation from insp on 790327-20.

  Region 1. Philadelphia: Office of the Director. 79/08/20.
- --791208010B IE insp Rept 70-1143/779-05 on 790327-30. Noncompliance p failure to maintain fissile unit spacing. KINNEY,M.W. Region 1. Philadelphia. Office of the Director. CROCKER,H.W. Ragion 1. Philadelphia. Fuel Facility & Materia Safety Branch. 79/06/20. 15pp.
- 7912050374 Forwards IE Insp Rept 70-1143/79-14 on 790829-31. No noncompliance noted.
  MARTIN.W.O. Region 1, Philadelphia, Safeguards Branch. 79/16/
- --7912050383 IE Insp Rept 70-1143/77-14 on 790829-31. No noncompliant nated. Major areas inspected; envicined U & Pu physical inventories. Details withhold (ref 100FR2.790). SHITH, O. C., SUMMERS, R., JOYNER, J. H. Region 1, Philadelphia, Safeguards Branch. 79/10/10. ip.
- 771212034B Forwards IE Insp Rept 70-1143/77-15 on 770917-21, No noncompliance noted. SMITH.0.H. Region 1, Philadelphia, Office of the Director, 79/10/24. 2pp.
- --7912120353 IE Insp Rept 70-1143/79-15 on 790917-21. No nuncompliand noted Major arms inspected; packaging of radioactive math for transport operations, nuclear criticality safety & 100FR21 compliance.
  CROCKER, H. M. Region 1, Philadelphia, Fuel Facility & Materil Bafety Branch. KINNEY, W. Region 1, Philadelphia, Office & the Director. 79/10/23. 14pp.
- 7912060674 PND-I-79-014: on 791025, welded inner vessel of one of four FL-10-1 shipping containers received by Bayannah River from Hestinghouse was slightly pressurized resulting in airborned contamination. Caused by ruptured can of Pu oxide. KINNEY, M.H., CHUCKER, H.H., DHITH, O.H. Region I, Philadelphis, Office of the Director, 79/10/29. 2pp.
- 7912200023 Requests registration as user of Hodel HU-7 chipping container. DIPIAZAR, P. Hestinghouse Electric Corp. 79/11/02. is.
- 7912250066 Forwards IE insp Rept 70-1143/79-15 on 790918-20. No nancampliance noted. MARTIN.W.O. Region 1, Philadelphia, Bafeguards Branck. 79/18
- --7912260071 1E Insp Rept 70-1143/79-16 on 790918-20. No noncemptian noted, Hajor areas inspected: security plan, central alarm & communication sys, testing & maint. Details withheld (ref 10CFR2. 790).

  JONESS.E. H. MADDEN.H. Region 1, Philadelphia, Dffice of the Director. DEVLIN.J. H. Region 1, Philadelphia, Dafequards Branch. 79/10/29, 1p.
- 7912270173 Forwards IE Insp Rept 70-1143/79-17 on 790924-28 No noncompliance noted. MARTIN.W.O. Region i. Philadelphia, Safaguards Branch. 79/11
- --7912270180 IE Insp Rept 70-1143/79-17 on 791029 No noncomplients Major arass inspected:physical inventory escondilistion. RATTA:A.D., JUNHER:J.H. Region 1. Philadalphia. Office of th Director, 79/10/29. Spp.

#### DOCKET 70-1191 WESTINGHOUSE ELECTRIC CORP.

7912260392 Requests exemption from licensing fees. Amonds will be to licensees to incorporate decommissioning & emergency plans as conditions of licenses.
ROUSELL.C. Probabilistic Analysis Branch (Pre 791030). 78/07/5pp.

- 7912130484 Amend 3 to License SNM-1107 authorizing const & use of waste storage bldg, by revising Condition 10.
  CROW, W. T. Uranium Fuel Licensing Branch. 79/10/23. 1p.
- --7912130527 Bafety evaluation supporting 790903 amend application to ilcense BNM-1107 re const & use of wasts storage bldg. BTEVENSON.R.L., CROW.W.T. Uranium Fuel Licensing Branch. 79/10/23. 2pp.
- 7912210224 Forwards IE Insp Rept 70-1151/79-15 on 790911-14.No noncompliance noted. Details withheld (ref 10CFR2. 790), KENNA, W. B. Region 2, Atlanta, Bafeguards Branch. 79/11/29. 2pp.
- --79:22:0235 IE Insp Rept 70-1:51/79-15 on 7909:1:-14.No noncompliance noted. Major areas inspected: inventory difference & limit of errors, shipping & receiving records & repts & followy on items of noncompliance. Details withheld (ref 10CFR2.790).

  GILLESPIE. F. P. Region 2. Atlanta: Safeguards Branch.
  TODD.O. A. JONES, D. W. Region 2. Atlanta, Office of the Director. 79/11/29. 1p.

#### DOCKET 70-1193 CIMARRON FACILITY, KERR-MCGEE CORP.

- 7912040013 Forwards IE Insp Repts 70-0925/79-04 & 70-1193/79-04 on 790827-29 & 0926-27 & notice of violation. DAVIS,A.B. Region 3, Chicago, Fuel Facility & Materials Safety Branch. 79/10/30. 2pp.
- ---7912040015 Notice of violation from insp on 790827-29 & 0926-27.
  \* Region 3, Chicago, Office of the Director. 79/10/30, ip.
- --7912040016 IE Insp Repts 70-0925/79-04 & 70-1193/79-04 on 790827-29 & 0926-27. Noncompliance noted: failure to submit employee termination repts to NRC.
  ORECER, L. R. Region 3. Chicago, Fuel Facility & Haterials Bafety Branch, DUBRY, N.E. Region 3. Chicago, Office of the Director. 79/10/30. 10pp.

#### DOCKET 70-1201 UF & CONVERSION FACILITY, BABCOCK & WILCOX CO.

- 7912050093 Discusses IE insp of facility to review adequacy of operations. Licenses & amend application to modify emergency evacuation procedures.

  KETZLACH.N. Uraniua Fuel Licensing Branch. 79/10/31. 4pp.
- 7912170043 Discusses insp of B&W Navel Nuclear Fuel Div facility, Commercial Nuclear Fuel Plant & Lynchburg Research Ctr. Implementation of packaging transport & burial of low level radwasta per IE Bulletin 79-19 was adequate. KETZLAGH, N. Uranium Fuel Licensing Branch. 79/10/31. 4pp.
- 7912280594 Discusses site visit of facilities for routine insp & review actions taken in response to IE Bulletin 79-19.
  "Packaging of Low Level Haste for Transport & Burial."
  KETZLAGH.N. Uranium Fuel Licensing Branch. 79/10/31. 4pp.
- 7912280001 Advises that complete revision of procedure addressing shipment & receipt of radioactive maths por IE Bulletin 79-19 will be completed by 800201 instead of 791231.as indicated. ZEFF.D.W. Babcock & Milcox Co. 79/12/12. ip.
- DOCKET 70-1287 MIXED GXIDE FABRICATION PLANT, EXXON NUCLEAR CO., INC.
- 7912100353 Refunds portion of fee for Amend MPP-2 to License BNM-960, incorporating security guard training & qualification plan. MILLER, W. C. License Fee Management Branch. 79/11/02. 1p.
- 7912180029 U Process Licensing Section input to safety evaluation reproposed laundry sys for U-contaminated cluthing.

  STEVENBON, R. L. Office of Nuclear Reactor Regulation. 79/11/06.

  2pp.
- 7412200225 Notifies of Americ 20 to License SNM-1227, authorizing installation to use of laundry for U-contaminated protective clothing.

  CRDW.W.T. Uranium Fuel Licensing Branch. 79/11/06. 1p.
- 7912170073 Responds to 791005 submittal of revised pages to fundamental nuclear matl control plan. Revision 2.1 of Amend MPP-2 approved. Info in 791005 ltr proprietary (ref 10CFR2, 790). PARTLON. J. Q. Material Control Licensing Branch. 79/11/15. lp.

- 7912170121 Notifies of partial refund of amount paid for review of Amend 20 to License SNM-1227.

  MILLER, W. D. Uranium Recovery Licensing Pranch. 79/11/15. 1p.
- 7912200437 PNS-V-79-002: on 791128, licensee reported questioning by FBI Portland.OR ofc as to whether Pu was SNM. Agency investigating offers to sell Pu nitrate. NGROERHAUG.L.R. Region 5. San Francisco. Office of the Director. 79/11/28. 1p.
- 7912190543 Requests payment of Category 1C fee re 791114 amend request for physical protection plan to process mixed oxide finished fuel rods.
  WEISS.J.D. License Fee Management Branch. 79/12/03. 1p.
- DOCKET 70-1308 MORRIS OPERATIONS, GENERAL ELECTRIC CO.
- 7912110416 Summary of 791004 meeting w/OE in Silver Spring, HD repossible add1 work at Morris operation.
  EMPSON, F. M. Advanced Fuel & Spent Fuel Licensing Branch. 79/10/17.
- 7912120068 PNO-III-79-025.on 791025.essential svcs motor generator set tripped.resulting in tripping of Unit 3 reactor. Caused by slamming of essential svcs electrical panel door. CREED. J. Region 3. Chicago. Office of the Director. 79/10/26.
- 7912310082 Responds to vendor 790815 & 1001 ltrs re revised security personnel training & qualification plan & to 791002 ltr re revised safeguards contingency plan. Both revised plans acceptable.

  MCCORKLE.G.W. Physical Security Licensing Branch. 77/11/06.
- 7912060032 Requests to be notified of all hearings & actions re GE nuclear waste facility at Morris, IL.
  CREEK, L. Affiliation Unknown. 79/11/19. ip.
- 7912110142 Statement of position objecting to State of IL 790501 contentions. Failed to satisfy specificity & basis requirements. Petition may be amended w/o prior approval within time limit specified in rules.
  ROTHSCHILD.M.U. Hearing Branch 1. 79/11/20. 23pp.
- --7912110176 Statement of position objecting to B Roremet al 790523 contentions. Adheres to NRC 790614 response noting deficiencies in potition. Failed to satisfy specificity & basis requirements. Certificate of Svc oncl. ROTHSCHILD, M. U. Hearing Branch i. 79/11/20. [7pp.
- 7912120048 Objection to intervenor State of IL 790521 contentions. All contentions should be stricken for failure to meet code requirements & for lack of specificity. Certificate of Svc encl.
  - enci. SZWAJKOHSKI.R. U. RODNEY.M.A. General Electric Co. SZWAJKOHSKI.R.W Magar, Brown & Platt. 79/11/20, 12pp.
- 7912130154 Objection to intervenors BL & R Rorem 790525 contentions.
  Contentions 3.4.6.7 & 9 irrelevant Contentions 2.5 & 8
  attack validity of existing regulation All contentions
  should be stricken. Certificate of Bvc encl.
  SZWAJKOWSKI.R. W. RDDREY.M.A. Ogneral Electric Co. BZWAJKOWSKI.R.W
  Mayer. Brown & Platt. 79/11/20. 7pp.
- DOCKET 70-1362 HAHNEMANN MEDICAL COLLEGE & HOSP. PHILADELPHIA PA
- 7912040248 Ack receipt of 791015 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 30-02959/79-01 & 70-1362/79-01. Region 1. Philadelphia. Office of the Director. 79/11/01. 1p.
- --7912060259 Responds to NRC 791001 ltr re violations noted in IE Insp. Repts 30-02959/79-01 & 70-1362/79-01 Corrective actions new equipment ordered to chock indination & safety procedures initiated re radioactive package disposal & lab.

  LIMOFF.W. Hahnemann Medical College & Hosp. of Philadelphia, PH. Pennsylvania. 79/10/15. 2pp.
- --7912060269 Forwards IE Insp Repts 30-02959/79-01 & 70-1362/79-01 on 790920-21 & notice of violation. MCCLINTOCK.R.D. Region 1, Philadelphia, Office of the Director. 79/01/01. 2pp.

--7912060279 Notice of violation from insp on 790920 & 21. Noncompliance noted: Failure to make adequate surveys of iodination in labs & unrestricted areas & failure to initiate safety procedures re radioactive package disposal.

\* Region 1, Philadelphia, Office of the Director. 79/10/01.

## DOCKET 70-1729 FUEL REC. & STOR. STA., ALLIED GENERAL NUCLEAR SERVICES

7912040041 Requests correction of record to substitute RP Wilson, Assistant Atty General, SC Dept of Health & Environ Control, for Roberson.
WILSON, R. P. South Carolina, State of. 79/11/16. ip.

7912060036 Forwards notice of TS Moore withdrawal from proceedings. Certificate of Svc encl BOSKEY.B. Volpe. Boskey & Lyons. 79/11/28. 3pp.

### DOCKET 70-2205 ST. LUKE'S HOSP. MILWAUKEE-WI

7912050471 Responds to FGIA request for documents re NRC insps of St Luke's & St Mary's Hosps in Milwaukee.WI since Jan 1979. Forwards insp repts of 791102 for each facility. CARR.J.C. Division of Rules and Records. 79/11/19. lp.

--7912050402 Forwards IE Inso Rept on 790824 & 27. DAVIS.A.B. Region 3. Chicago, Fuel Facility & Materials Safety Branch. 79/09/12. ip.

--7912050485 IE insp Rept on 790824 & 27 Noncompliance not stated. TONGUE, T.M. Region 3, Chicago, Uffice of the Director. 79/09/11. 19pp.

## DOCKET 70-2623 MCGUIRE SPENT FUEL POOL, DUKE POWER CO.

7912050318 Notice of transmittal of proposed interfacility transportation route description maps & route summary in response to NRC 791102 order. W/o encl. Certificate of Svc encl.

MDEFLING, R.K. Hearing Branch 4. 79/11/07. Spp.

7912060092 Memorandum explaining why no full opinion to NRC 790906 order will be issued.
BISHOP, C. J. Atomic Safety and Licensing Board Panul. 79/11/08.
4pp.

7912100135 Forwards description of proposed transportation routes from Oconee to McGuire maps of routes & route summary.per affidavits of nondisclosure MDEFLING.R.X. Hearing Branch 4 79/11/16. ip.

7912080034 Act receipt of Carolina Environ Study Group State of SC & licensee executed affidavits re-protected matls per Commission 791102 order NRDC will not execute affidavit. Protected info should be sent to persons listed in encl. BICKMIT.L. Office of the General Counsel. 79/11/27. 28p.

7912060608 Response to Commission 791102 order inviting execution of nondisclosure affidavits re-routing of info for spent nuclear fuel trans shipment Urges denial of NRC petition for review Certificate of Svc encl.
FLEISCHAKER, D. Natural Resources Defense Council. FLEISCHAKER, D. Fleischaker, D. S. 79/11/30. 7pp.

7912110432 Response in opposition to Commission 791102 order inviting execution of affidavits of mondisclosure re spent nuclear fuel transchipment routing info. Declines invitation. Urges denial of NRC request for review. Certificate of Svc encl. FLEISCHAMER, D. Natural Resources Defense Council. FLEISCHAMER, D. Fleischaker, D. S. 79/11/30. 7pp.

7912190084 Requests confirmation of availability of C Marotta to assist in Ocones/McQuire hearings w/completion date of 791214. ROUSE, L. C. Advanced Fuel & Spent Fuel Licensing Branch. 79/12/03. 1p.

7912140108 Order correcting transcript of W Bateman 790913 testimony.
Orants KS McGovern request that 791116 ltr & attachment be
associated w/transcript of W Bateman testimony.
MILLERI,M.E. Atomic Safety and Licensing Board Panel. 79/12/06. 1p.

---7912140112 Forwards corrections to transcript of W Dateman 790913 testimong. MCGOVERN.K.S. Energy, Dept. of. 79/11/14. 2pp. 7912260371 Response to interveners Carolina Environ Study Group NROC & State of SC apposition to NRC 790907 request for protective order re spent fuel transport route info. Certificate of Svc encl.

KETCHEN, E. O. Hearing Branch 4. 79/12/10. 7pp.

#### DOCKET 70-2756 TRANSNUCLEAR, INC.

79120700B5 Forwards IE Insp Repts 70~2756/79~01,79~2761/79~01 & 70~2776/79~01 on 790925. No noncompliance noted.

MARTIN, H. O. Region i, Philadelphia, Safeguards Branch. 79/10/17.

--7912070091 IE Insp Repts 70-2756/79-01, 70-2761/79-01 & 70-2776/79-01 on 790925. No noncompliance noted. Major areas inspected: security measures re export shipment of SNM. Details withheld (ref 10CFR2 790).

SMITH.R. ROGERS.M.E. Region 1, Philadelphia, Office of the Director. DEVLIN.J. Region 1, Philadelphia, Bafeguards Branch. 79/10/16. lp.

#### DOCKET 70-2741 TRANSNUCLEAR, INC.

7912070085 Forwards IE Insp Repts 70-2756/79-01,79-2761/79-01 & 70-2776/79-01 on 790925 No noncompliance noted. MARTIN,N, G. Region 1. Philadelphia, Safeguards Branch. 79/10/17. 200.

--7912070091 IE Insp Repts 70-2756/79-01.70-2761/79-01 & 70-2776/79-01 on 790925. No noncompliance noted Major areas inspected: security measures re export shipment of BNM. Details withheld (ref loCFR2.790).

BMITH: R. H. , ROGERB. M. E. Region 1, Philadelphia, Office of the Director. DEVLIN. J. Region 1, Philadelphia, Bafeguards Branch. 79/10/16. 1p.

#### DOCKET 70-2774 TRANSNUCLEAR, INC.

7912070085 Forwards IE Insp Repts 70-2756/79-01.79-2761/79-01 & 70-2776/79-01 on 790925.No noncompliance noted. MARTIN, N. G. Region 1, Philadelphia, Bafeguards Branch. 79/10/17.

--7912070091 IE Insp Repts 70-2756/79-01,70-2761/79-01 to 70-2776/79-01 on 790925. No noncompliance noted Major areas inspected: security measures re export shipment of SNM. Details withheld (ref 10CR2.790).
SMITH. R. H. , ROGERS, M. E. Region 1, Philadelphia, Office of the Director. DEVLIN. J. Region 1, Philadelphia, Safeguards Branch. 79/10/16. 1p.

### PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

### DOCKET 71-0003 EXXON NUCLEAR CO. , INC.

7912270124 Forwards chart of Exxon Nuclear current corporate organization. Supplies addresses for correspondence re fuel facility licensing & transportation licensing.

NILSON.R. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/20.

2pp.

### DOCKET 71-0004 UNITED NUCLEAR CORP.

7912040020 Forwards GA program approval for radioactive mat1 package. MACDONALD.C. E. Transportation Branch. 79/11/20. 1p.

--7912040023 GA program approval for radioactive matl package: 0006 Revision O. HACDDNALD; C. E. Transportation Branch. 79/10/17. 1p.

7912060140 Forwards GA program approval for radioactive mat1 package. MACDDNALD.C.E. Transportation Branch. 79/11/26. ip.

--7912060147 GA program approval for radioactive matl package: 000&. Revision O. MACDONALD.C.E. Transportation Branch. 79/11/26. ip.

7912270050 Disavous 791126 GA program approval for radioactive matl packages 0006, Revision O. as previous 791120 approval remains in effect. MACDONALD, C. E. Transportation Branch. 79/12/10. ip.

### DOCKET 71-0024 HITTMAN NUCLEAR & DEVELOPMENT CORP.

- 7912260052 Forwards GA program approval for radioactive matl package. MACDONALD.C.E. Transportation Branch. 79/12/06. ip.
- ---7912260055 Ga program approval for radioactive matl package:0024, Revision O. MACDONALD.C.E. Transportation Branch. 79/12/06. ip.

#### DOCKET 71-0026 EASTERN TESTING & INSPECTION

- 7912120525 Forwards GA program approval for radioactive matl package. MACDONALD, C. E. Transportation Branch. 79/12/04. ip.
- --7912120527 QA program approval for radioactive mat1 package: 0026, Revision O. MACDONALD. C.E. Transportation Branch. 79/12/04, 1p.

### BOCKET 71-0027 BABCOCK & WILCOX CO.

- 7912170155 Forwards revised QA requirements & measures for transportation packaging as applied to industrial radiography. VAUOHN, H. Babcock & Wilcox Co. 79/12/12. ip.
- --7912170162 Revised GA requirements & measures for transportation packaging as applied to industrial radiography.

  \* Babcock & Wilcox Co. 79/12/12. 3pp.

### DOCKET 71-0040 MORRISON-KNUDSEN CO. , INC.

- 7912260036 Forwards QA program reflecting addl info requested in 791029 ltr. PETERSQN.B.H. Morrison Knudsen Co., Inc. 79/12/04, ip.
- --7912260038 QA program reflecting addl info requested in 791029 ltr. \* Morrison Knudsen Co., Inc. 79/12/04. 3pp.

#### DOCKET 71-0079 MORRISON-KNUDSEN CD., INC.

- 7912260036 Forwards QA program reflecting add1 info requested in 791029 ltr. PETERBON-B.H. Marrison Knudsen Co., Inc. 79/12/04. ip.
- --791224003B GA program reflecting addl info requested in 791029 ltr. \* Morrison Knudsen Co., Inc. 79/12/04. 3pp.

### DOCKET 71-0079 BABCOCK & WILCOX CO.

- 7912060151 Forwards GA program approval for radioactive matl package. MACDQNALD, C. E. Transportation Branch. 79/11/26. 1p.
- --7912060160 QA program approval for radioactive matl package:0079, Havision 0. MACDQNALD.C.E. Transportation Branch. 79/11/26. 1p.

### DOCKET 71-0088 BABCOCK & WILCOX CO.

- 7912200030 Forwards QA program for shipping containers. Revision 2. CORDANI.R.A. Babcock & Wilcox Co. 79/11/12. 1p.
- ---7912200035 GA program for shipping containers, Revision 2. \* Babcock & Wilcox Co. 79/11/12, 35pp.
- 7912190469 Forwards QA program approval for radioactive matl package. MACDONALD, C. E. Transportation Branch. 79/12/10, ip.
- --7912190474 GA program approval for radioactive matl package:0088. Revision O. MAGDONALD.C.E. Transportation Branch. 79/12/10. ip.

### DOCKET 71-0096 PAN AMERICAN WORLD AIRWAYS

- 7912200116 Requests extension until 791231 to file revised QA program. BUNN, N. M. Pan American World Airways, Inc. 79/11/08. 2pp.
- 7912210149 Approves of request for extension until 791231 to file GA program for radioactive shipping packages.
  MAGDONALD.C.E. Transportation Branch. 79/12/04. ip.

### DOCKET 71-0114 COLBY-THIELMEIER TESTING CO.

- 7912210185 Forwards GA program for industrial radiography.
  THIELMETER, L. F. Colby-Thislmior Testing Co., Inc. 79711/29. ip.
- --7912210189 9A program for industrial radiography. \* Colby-Thielmior Testing Co., Inc. 79/11/23. 3pp.

#### DOCKET 71-0121 NEUTRON PRODUCTS: INC.

7912040209 Submits request for add1 info to complete review of Revision 1 to 9A program.

MACDDNALD.C.E. Transportation Branch. 79/11/26. 1p.

#### DUCKET 71-0159 LUCKHEED MISSILES & SPACE

7912140541 Submits add1 info necessary for approval of QA program.
Organizational chart enci.
ORR.N.D. Lockheed Missiles & Space Co. (subs. Lockheed Aircraft
Corp.). 79/11/02. 2pp.

#### DOCKET 71-0160 QMAHA TESTING LABS., INC.

7912140143 Requests copy of NRC 791002 ltr requesting addl info re GA program for receipt handling & shipment of radioactive matl. MERTZ.1.R. Dmaha Nondestructive & Hetallurgical Testing, Inc. 79/11/23. 1p.

### DOCKET 71-0193 NAVY, DEPT. OF

- 7912040071 Forwards GA program approval for radioactive matl package. MACDONALD.C.E. Transportation Branch. 79/11/20. 1p.
- --7912040072 0A program approval for radioactive matl package: 0193, Revision O. MACDONALD, C.E. Transportation Branch. 79/11/02. 1p.

### DOCKET 71-0199 NAVY, DEPT. DE

- 7912200146 Forwards GA program for industrial radiography, in response to NRC 780501 ltr.
  SPENCER, H. A. Navy, Dept. of. 79/11/08. ip.
- --7912200154 OA program for industrial radiography. BPENGER, H. A. Navy, Dept. of. 79/11/09. 3pp.
- 7912120910 Forwards GA program approval for radioactive matl package. MACDONALD.C.E. Transportation Branch. 79/12/04. 1p.
- --7912120512 GA program approval for radioactive matl package:0199, Revision O. MACDONALD.C.E. Transportation Branch, 79/12/04. lp.

### BOCKET 71-0206 PRYOR FOUNDRY, INC.

- 7912180059 Submits GA program in response to NRC 790803 request. FULLER.E. JI Case Co. 79/11/21. ip.
- --7912180068 Ack receipt of 781130 application for approval of GA program. Program does not meet requirements. Requests revised application & forwards sample GA program. MAGDUNALD.C. E. Transportation Branch. 79/08/03. 4pp.

### DOCKET 71-0225 NAVY DEPT. OF

- 7912130016 Forwards GA program approval for radioactive mat1 package.
  MACDONALD, C. E. Transportation Branch. 79/12/04. 1p.
- ---7912130019 GA program approval for radioactive matl package:0225, Revision 1. MACDONALD, C.E. Transportation Branch. 79/12/04. 1p.

#### DOCKET 71-0239 NAVY, DEPT. OF

- 7912180153 Forwards QA program approval for radioactive math package. MACDONALD.C.E. Transportation Branch. 79/12/04. ip.
- ---7912180159 GA program approval for radioactive mat1 package:0239, Revision O. MACDONALD,C.E. Transportation Branch. 79/12/04. 1p.

#### DOCKET 71-0248 MONSANTO RESEARCH CORP.

- 7912060211 Forwards GA program approval for radioactive matl package. MACDONALD.C.E. Transportation Branch, 79/11/26. 1p.
- ---7912060217 GA gragram approval for radioactive matl package: 0248, Revision 1. MACDONALD, C.E. Transportation Brench. 79/11/26. 1p.

#### DOCKET 71-0250 TRANSNUCLEAR, INC.

- 7912270027 Forwards Revision 1 to GA program for designimfg.testiuse. maint & repair of packagings in transport of radioactive matls. ODLDMANN.K. Transpuclear, Inc. 79/12/07. 1p.
- --7912270027 Revision 1 to 0A program for design,mfg.test.use.maint & repair of packagings in transport of radioactive matls.

  # Transpurlear. Inc. 79/12/07. 41pp.

## DOCKET 71-0258 NUCLEAR ENGINEERING CO., INC.

- 7912040018 Forwards request for add1 info to complete review of GA program.

  MACBONALD, C. E. Transportation Branch, 79/11/20. 2pp.
- 7912310064 PND-III-79-046: on 791127. State of NV Dept of Public Health is holding public hearing in Carson City to determine whether facility license should be suspended, revoked or modified.

  JURGENBEN. B. L. Office of Inspection & Enforcement, Office of the Director. DOVD.D.C. Region 3. Chicago, Office of the Director. 79/11/26. 1p.

### DOCKET 71-0345 CARDLINA POWER & LIGHT GO.

- 7912120529 Forwards GA program approval for radioactive matl package. MACBONALD, C. E. Transportation Branch. 79/12/04. 1p.
- --7912120503 GA program approval for radioactive mat1 package: 0345; Revision 1. MACDONALD.C.E. Transportation Brench. 79/12/04. 1p.

### DOCKET 71-0347 STONE & MEDSTER ENGINEERING CORP.

- 7912200117 Forwards revised corporate radioactive matls GA program in response to NRC 791009 request. W/o encl. QIESON. J. D. Stone & Webster Engineering Corp. 79/11/09. ip.
- 7912120516 Forwards GA program approval for radioactive mat1 package. MACDONALD.C.E. Transportation Branch. 79/12/04. ip.
- ---7912120517 GA program approval for radioactive matl package: 0347, Revision O. HACDONALD, C. E. Transportation Bronch, 79/12/04, ip.

### DOCKET 71-0349 CATERPILLAR TRACTOR CO.

- 7912200124 Forwards corrected GA program for industrial radiography. VGGEL, R. J. Caterpillar Tractor Co. 79/11/05. 1p.
- ~~7912200132 Denies 790926 request for approval of GA program.
  Organization chart & text are not consistant.
  MACDONALD.C. E. Transportation Branch. 79/11/05. 1p.
- --7912200140 GA program for industrial radiography. VGGEL:R. J. Caterpiliar Tractor Co. 79/11/05. 4pp.
- 7912120519 Forwards QA program approval for radioactive matl package. MACDDNALD.C.E. Transportation Branch. 79/12/Q4. ip.
- --7912120321 GA program approval for radioactive mat1 package: 0349, Revision O. MACDONALD, C.E. Transportation Branch. 79/12/04. ip.

#### DOCKET 71-0352 NILES STEEL TANK CO.

- 7912180654 Forwards GA program. WOOD, J.C. Niles Steel Tank. 79/11/20. ip.
- --7912180657 Revised GA manual for handling, storage & shipping of radinactive mat1 shipping packages. WOOD, J. C. Niles Bteel Tank. 79/11/20. 10pp.

### DOCKET 71-0355 JERSEY CENTRAL POWER & LIGHT CO.

- 7912040032 Forwards GA program approval for radioactive matl package. MACDDNALD, C. E. Transportation Branch. 79/11/20. ip.
- --7912040035 GA program for radioactive mat1 package: 0395, Revision 0. MACDQNALD, C. E. Transportation Branch. 79/10/23. ip.

### DOCKET 71-0356 NAVY, DEPT. OF, USS PIEDMONT

- 7912180164 Forwards GA program approval for radioactive matl package.
  MACDONALD, C. E. Transportation Branch. 79/12/04. 1p.
- --7912180169 GA program approval for radioactive matl package: 0356. Revision O. HACDDNALD, C.E. Transportation Branch. 79/12/04. 1p.

### DUCKET 71-0357 NAVY, DEPT. OF, USS VULCAN

- 7912190251 Forwards QA program for industrial radiography in response to NRC 780501 ltr.

  BPENCER, H. A. Navy, Dept. of. 79/11/08. ip.
- --7912190254 GA program for industrial radiography. SPENCER.H. A. Navy.Dept. of. 79/11/09. 3pp.
- 7912180144 Forwards request for add1 info to complete review of GA program.
  MACDONALD, C. E. Transportation Branch. 79/12/04. 2pp.

### DOCKET 71-0958 NAVY, DEPT. OF, USS SIERRA

- 7912190473 Forwards GA program for industrial radiography. BRYANT, F. B. Navy, Dept. of. 79/11/14. ip.
- ---7912190479 QA program for industrial radiography. KINQSLEY, S. B. Navy, Dept. of. 79/11/14. Spp.
- 7912180180 Forwards updated GA program for industrial radiography. BRYANT, F. S. Navy, Dept. of, Forces Afloat. 79/11/21. 1p.
- --7912180187 Updated GA program for industrial radiography. KINGSLEY, S. S. Navy, Dept. of. 79/11/14. 3pp.
- 7912270248 Forwards GA program approval for radioactive matl package.
  MACDONALD, C. E. Tronsportation Branch. 79/12/10. 1p.

--7912270235 QA program approval for radioactive matl package:0358, Revision O. MACDONALD, C.E. Transportation Branch. 79/12/10. ip.

#### DOCKET 71-0359 PICK INSTRUMENT PRODUCTS CO., INC.

- 7912180339 Forwards QA program for mfg radioactive matl transport equipment. MACDONALD.C.E. Pick Instrument Products Co., Inc. 79/11/27, 1p.
- --7912180359 GA program for mfg radioactive mat1 transport equipment. PICKENS.F.W. Pick Instrument Products Co., Inc. 79/11/30, 19pp.

#### DOCKET 71-0360 NAVY, DEPT. OF, UBS YOSEMITE

- 7912180137 Forwards GA program for industrial radiography. GARDNER, D. C. Navy, Dept. of, Forces Afloat, 79/11/16, 1p.
- --7912180140 QA program for industrial radiography.
  VELAZQUEZBUAREZ Navy, Dapt. of, Naval Investigativa Service.
  79/11/16. 3pp.

#### DOCKET 71-0362 WISCONBIN PUBLIC SERVICE CORP.

- 7912210439 Notifies that radioactive matl shipping activities to be performed per util GA program, 780120 Revision 2, approved 790723.
  RICHMOND, J., LUOMA, C.R. Wisconsin Public Service Corp. 79/11/27. io.
- DOCKET 71-0363 BRIGGS ENGINEERING & TESTING CO. . INC.
- 7912210433 Forwards GA program for industrial radiography. 8KOROHAD, P. M. Briggs Engineering & Testing. 79/11/21. 4pp.
- --7912210437 GA program for industrial radiography.
  \* Briggs Engineering & Testing. 79/11/21. 3pp.

#### DOCKET 71-0364 NAVAL NUCLEAR POWER UNIT PORT HUENEME, CA

- 7912210419 Forwards endorsed QA program.
  VOQT, J. F. Navy, Dept. of, Naval Nuclear Power Unit. 79/11/27. 2pp.
- --7912210429 Endorsed GA Program for radioactive mat1 shipping program. OREEN, O. E. Navy, Dept. of. 79/11/20. Spp.
- DOCKET 71-4949 MODEL: UNC-1484, COMBUSTION ENGINEERING CO., INC.
- 7912180035 Forwards revised Page 1 of application for renswal. Gertificate of Compliance 4949. L\*HEREUN.J. United Nuclear Corp., UNC Recovery Bystems Div. 79/11/14. 2pp.

### DOCKET 71-5026 HODEL: 80-48-220, ATCOR, INC.

- 7912100084 Requests registration as user of Madels Vandenburgh, 6144, 6244, PB-1, LL-50-100, 9E-1400, CNS1-14-195-H, CNS1-21-300, CNS-1600, Radwasts Carrier I, CNS-80A, 7-100, BC-48-220, LL-28-4 t AL-33-90. CLAYTON, F. L. Alabama Power Co. 79/11/06, 2pp.
- 7912100399 Notification of registration as user of Models LL-28-4,N-55, PB-1,6244,AL-33-90,CN6-BOA.Radwaste Carrier 1,7-100, LL-50-100,BC-48-220 & CN8I-14-195-H in response to itr. MACDONALD,C.E. Transportation Branch. 79/11/20. lp.

### DOCKET 71-5059 MODEL: URANY NIT-THE, NUCLEAR FUEL SERVICES, INC.

- 7912140210 Forwards Revision 6 to Certificate of Compliance 5059 for Model NFB Uranyl Nitrate Tank Trailer. HACDONALD, C. E. Transportation Branch. 79/12/04. 2pp.
- --7912140215 Certificate of Compliance 5059, Ravision 6, for Model NFS Uranil Nitrate Tank Trailer. MACDUNALD, C. E. Transportation Branch. 79/12/04. 3pp.

- DOCKET 71-5086 MODEL: UNC-2600, GENERAL ATOMIC CO.
- 7912210341 Forwards Revision 1 to Certificate of Compliance 5086 for Model UNC-2600.
  MACDDNALD,C.E. Transportation Branch. 79/12/10. 2pp.
- --7912210246 Certificate of Compliance 5086, Revision 1 for Model UNC-2500. MACDUNALD, C.E. Transportation Branch. 79/12/10. 2pp.
- DOCKET 71-9395 MDDEL: CC. WESTINGHOUSE ELECTRIC CORP.
- 7912180304 Requests renewal of Certificate of Compliance 5395 Package info referenced by current NRC certification consolidated into single application. Package description fee. & drawings encl. Eleven oversize drawings wailable Central Files only. DIPIAZZA,R.P. Westinghouse Electric Carp. 79/10/17. 37pp.
- 7912050219 Forwards Revision 4 to Certificate of Compliance 5395 for Model GC shipping container.
  MACDONALD.C.E. Transportation Branch. 79/11/26. 1p.
- --7912060222 Certificate of Compliance 5395, Revision 4, for Model CC shipping container.
  MACDUNALD, C. E., Transportation Branch. 79/11/26. 4gg.
- DOCKET 71-5450 MODEL: RCC-1,-2,-3, WESTINOHOUSE ELECTRIC CORP.
- .7912060642 Notification of registration as user of Models RCC.RCC-1. RCC-2 t RCC-3 in response to request. MACDONALD.C.E. Transportation Branch. 79/11/20. ip.
- DOCKET 71-5467 MODELS: MARK VR, VE & MARK 15, ENERGY, DEPT. OF
- 7912050458 Forwards updated Attachment D to Certificate of Compliance 5467. Revision 4 re packaging & shipping limits for Mark VR. VE & 15 cores & slugs.
  RDSB,D,M. Energy, Dept. of. 79/10/30. 2pp.
- 7912210419 Forwards Revision 4 to Certificate of Compliance 5467 for boxes w/lids & pallets w/covers & w/o covers Supporting technical info encl.
  RDSB.D.M. Energy, Dept. of. 79/12/03. ip.
- --7912210425 Certificate of Compliance 5467.Revision 4.for boxes w/lids, pallets w/covers & pallets w/o covers.Interdepartmental correspondence encl.

  \* Energy, Dept. of. 79/08/13. 13pp.
- --7912210434 Buppl to "BAR for Packaging Steal-Banded Hooden Shipping Containers for Slightly Enriched U Metal (NLCD-1107)." HONKONEN.D.L. E.I.du Pont de Nemours & Co., Inc. DPSPU 79-124-2. 79/06/30. 13pp.

### DOCKET 71-8441 MDDEL: UNC-2500

- 7912210299 Notifies of expiration of Certificats of Compliance S441 for Model UNC-2500. To continue using package, should submit consolidated application & drawings for renewal. MACDOMALD.C. E. Transportetion Firanch. 79/12/07. 1p.
- DOCKET 71-5768 MODEL: 88-250-2, COMBUSTION ENGINEERING CO., INC.
- 7712100463 Forwards Revision 2 to Cartificate of Compliance 5768 for Model BB-250-2.
  MACDONALD.C.E. Transportation Branch. 79/11/30. 2pp.
- --7912100465 Certificate of Compliance 5768.Revision 2.for Model BB-250-2. MACDONALD.C. E. Transportation Branch. 79/11/30. Spp.
- DOCKET 71-5796 MODEL: 181361. PICKER CORPORATION
- 79120600B1 Requests registration as user of Models 181375, 181361 & E-MEH-00-00004. KELBLEY, N. D. Advanced Medical Systems, Inc. 79/11/02. 1p.

- 7912070509 Requests registration as user of Models 191375 & 191361 & E-MEH-00-00004.
  - e-nen-ud-outles. KELBLEY, N.D. Advanced Medical Systems. Inc. 79/11/02. 1p.
- 7912070010 Notification of registration as user of Models 181375 & 181361 & E-MEH-00-00004 in response to request.

  MACDUNALD, C. E. Transportation Branch. 79/11/30. 1p.
- 7912280241 Forwards request for add1 info re proposed Cs-137 source capsule for review of 791002 amend request for Model 181361 packaging. MACDONALD.C.E. Transportation Branch. 79/12/03. 2pp.
- DOCKET 71-5805 HUDEL: ATCOR VNOB CASK, ATCOR, INC.
- 7912100084 Requests registration as user of Models Vandenburgh, 6144, 6244, PB-1, LL-50-100, GE-1600, CNS1-14-195-H. CNS1-21-300, CNS-1600, Radwaste Carrier I, CNS-80A, 7-100, BC-49-220, LL-20-4 AL-33-90, CLAYTON, F.L. Alabama Power Co. 79/11/06, 2pp.
- 7912060144 Notification of registration as user of Hodela CN81-1600, 0E-1600, Vandenburgh & PB-1. MACDONALD, C. E. Transportation Branch. 79/11/20. ip.
- DOCKET 71-5939 HODEL: GE-1500, GENERAL ELECTRIC CO.
- 7912060118 Notification of registration as user of Model 9E-1500. MACDONALD.C.E. Transportation Branch. 79/11/16. 1p.
- 7912060216 Notification of registration as user of Model GE-1500. MAGDONALD.C.E. Transportation Branch. 79/11/16. lp.
- 7912280622 Notifies that failure to file QA program by 790101 resulted in elimination of registered user status. Model QA program & code acceptance criteria encl.

  MACDONALD.C.E. Transportation Branch. 79/12/03. 14pp.
- 7912270116 Forwards GA program for shipping radioactive sources. Requests program review GE Model 1500 shipping cask used. CUTHBERTSON.R. Army Dept. of. 79/12/04. 5pp.
- DOCKET 71-5957 MODEL: BMI-1, ENERGY, DEPT. OF
- 7912200170 Requests registration as user of Model BMI-1. HART.H.C. Union Carbide Corp. 79/12/04. lp.
- DUCKET 71-5980 MODEL: GE-600, GENERAL ELECTRIC CO.
- 7912200105 Certificate of Compliance 5980, Revision 3, for Model GE-600, IAEA Certificate of Competent Authority encl.
  MACDONALD, C. E. Transportation Branch. 79/10/31. 5pp.
- DOCKET 71-6058 HODEL: 83-1, NUCLEAR ENGINEERING CO.
- 7912030082 Requests amend of Certificate of Compliance 6058 for Hodel B3-1 to allow monsafety-related variances from licensed drawing Table outlining proposed changes encl. VDTH.H.H. Union Carbide Corp. 79/11/03. 3pp.
- 7912310379 Requests renewal of Certificate of Compliance 8058 for Model B3-1.
  BAER.T.S. Nuclear Engineering Co., Inc., (subs. of Teledyne, Inc.),
  79/11/27. 1p.
- DOCKET 71-6078 MODEL: 927 A1 & C1, COMBUSTION ENGINEERING, INC.
- 7912180007 Requests 90-day extension of Certificate of Compliance 6078 for Models 92761 & 92701. Company is preparing consolidated renewal application.
  BAKEVICH.C.J. C-E Power Systems. 79/10/16. 1p.
- 7912240040 Forwards Revision 5 to Certificate of Compliance 4078 for Models 92741 t 2701.

  MACDONALD.C.E. Transportation Branch. 79/12/10. ip.
- ---7912260041 Certificate of Compliance 6078 Revision 5 for Kodels 927A1 & 927C1. MACDONALD.C.E. Transportation Branch. 79/12/10. Spp.

- DECKET 71-6144 MEDEL: 6144, NUCLEAR ENGINEERING CO.
- 7912100084 Requests registration as user of Models Vandenburgh, 6144, 6244, PB-1, LL-50-100, GE-1600, CNSI-14-195-H, CNSI-21-300, CNS-1600, Radwaste Carrier 1, CNS-80A, 7-160, BC-48-220, LL-28-4 & AL-33-90. CLAYION F.L. Alabama Power Co. 79/11/06. 2pp.
- 7912060801 Notification of registration as user of Models Super Tiger & 6144 in response to request.

  MACDENALD.C.E. Transportation Branch. 79/11/20. 1p.
- 7912070512 Notifies that approved GA program is required prior to registration as package user or delivery of licensed matl to carrier re 790823 request.

  MACDDNALD.C.E. Transportation Brench. 79/11/20. 1p.
- 7912130045 Requests renewal of Certification of Compliance 6144.
  BAER.T.S. Nuclear Engineering Co., Inc. (subs. of Teledyne, Inc.).
  79/11/27. 1p.
- 7912110057 Notification of registration as user of Models 6144 k MACRONAL D. C. E. Transportation Branch. 79/11/30. 1p.
- 7912200619 Requests registration as user of Model 6144. MUNRO.J. J. Tech/Ops (Technical Operations, Inc.). 79/12/03. ip.
- DOCKET 71-6206 MODEL: B. BABCOCK & WILCOX CO.
- 7912270051 Forwards application for reissuance of Certificate of Compliance 6206 for Model B fresh fuel shipping container. Certificate dtd 700116 & supplemented 700303 & 790321. ZEFF.D.W. Babtock & Wilcox Co. 79/11/20. 11pp.
- --7912270055 Responds to 791121 ltr requesting renewal of Certificate of Compliance 6206. Requests submittal of \$150 renewal fee.
  WEISS.D. License Fee Management Branch. 79/11/28. ip.
- --7912270058 Responds to NRC 791128 ltr requesting submittal of fee for renewal of Certificate of Compliance 6206. Forwards check for \$150. ZEFF.D.W. Babcock & Wilcox Co. 79/12/04. 1p.
- 7912310061 Notifies of expiration of Cortificate of Compliance 6206 for Model B.To continue using package should submit consolidated application for renewal & fee.

  MACDDNALD.C.E. Transportation Branch, 79/12/07, 1p.
- DOCKET 71-6244 MODEL: 6244. CHEM-NUCLEAR BYSTEMS, INC.
- 7912100084 Requests registration as user of Models Vandemburgh, 6144, 6244, PB-1, LL-50-100, GE-1600, CNS1-14-195-H, CNS1-21-300, CNS-1600, Radwasts Carrier I, CNS-80A, 7-100, BC-48-220, LL-28-4 & AL-33-90. CLAYTON:F.L. Alabama Power Co. 79/11/04. 2pp.
- 7912100399 Notification of registration as user of Models LL-28-4,N-55, PB-1,6244,AL-33-90,CN6-80A,Radwaste Carrier I,7-100, LL-50-100,BC-48-220 & CN6I-14-195-H in response to ltr. MACDDNALD,C. E. Transportation Branch. 79/11/20. 1p.
- DOCKET 71-6275 MODEL: LL-28-4, CHEM-NUCLEAR SYSTEMS, INC.
- 7912180095 Application for renewal of Certificate of Compliance 6275 for CNS O-4 (LL-28-4) cask.
  CORBETT. J. B. Chem-Nuclear Systems, Inc. 79/10/31. 85pp.
- 7912100084 Requests registration as user of Models Vandenburgh, 6144, 6244, PB-1, LL-50-100, GE-1600, CNS1-14-195-H, CNS1-21-300, CNS-1600, Radwaste Carrier I, CNS-80A, 7-100, 80-48-220, LL-28-4 & AL-33-90.

  \*\*CLAYTON, F. L. Alabama Power Co. 79/11/06. 2pp.
- 7912100399 Notification of registration as user of Models LL-28-4,N-55, PB-1,6244,AL-33-90,CN6-804,Radwaste Carrier I,7-100, LL-50-100,BC-48-220 & CNSI-14-195-H in response to ltr. MACDONALD,C.E. Transportation Branch. 79/11/20. 1p.

#### DOCKET 71-6280 MODEL: A-0109

- 7912110059 Forwards Revision 2 to Certificate of Compliance 6280 for Model A-0109. MACDONALD, C. E. Transportation Branch. 79/11/30. 20p.
- --7912110062 Certificate of Compliance 6280 Revision 2. For Model A-0109. MACDONALD.C.E. Transportation Branch. 79/11/30. 2pp.

DOCKET 71~6300 MODEL: UNC-1352, COMBUSTION ENGINEERING, INC.

\_\_\_\_\_\_

- 7912070226 Plans no renewal of Certificate of Compliance 5455.
  MDMRV.W.R. Oeneral Atomic Co. (subs. of Gulf Oil Co.). 79/10/29.
- DOCKET 71-6945 MODEL: ANL-402-SPM, -403-SPM, E. I. DU PONT DE NEMOURS &
- 7912140116 Requests registration as user of Model ANL-402-SPM-403-SPM. FITZSIMMONS.T.R Energy, Dept. of. 79/10/04. 1p.
- 7912100142 Discusses 791004 request re registration as user of depleted U shielded cask. Approved certificate of compliance for cask not issued. Application currently under review. MACDONALD. C. E. Transportation Branch. 79/11/20. ip.
- DOCKET 71-4357 MODEL: NNFD-10, BABCOCK & WILCOX
- 7912060124 Notification of registration as user of Model NNFD-10. MACDONALD.C.E. Transportation Branch. 79/11/16. 1p.
- DOCKET 71-6375 MODEL: PB-1. CHEM-NUCLEAR SYSTEMS, INC.
- 7912100084 Requests registration as user of Models Vandenburgh, 6144, 6244, PB-1, LL-50-100, GE-1600, CNS1-14-195-H, CNS1-21-300, CNS-1600, Radwaste Carrier I, CNS-80A, 7-100, BC-48-220, LL-28-4 t.AL-33-90.

  CLAYTON, F. L. Alabama Power Co. 79/11/06. 2pp.
- 7912060144 Notification of registration as user of Models CNSI-1600, QE-1600, Vandenburgh & PB-1.
  MACDONALD, C. E. Transportation Branch. 79/11/20. 1p.
- 7912100399 Notification of registration as user of Models LL-28-4,N-55, PB-1,6244,AL-33-90,CNS-BOA,Radwaste Carrier I,7-100, LL-50-100,BC-4B-220 & CNSI-14-195-H in response to 1tr. HACDONALD,C.E. Transportation Branch. 79/11/20. 1p.
- DOCKET 71-6386 MODEL: 235ROO1, ENERGY, DEPT. OF
- 7912120568 Forwards Revision 5 to Certificate of Compliance 4836 for Model 235R001.
  MACDONALD.C.E. Transportation Branch. 79/12/03. 1p.
- --7912120571 Certificate of Compliance 6386.Revision 5.for Model 235R001. MACDONALD.C.E. Transportation Branch. 79/12/03. 3pp.
- DOCKET 71-6400 MODEL: SUPER TIGER, WESTINGHOUSE ELECTRIC CORP.
- 7712060196 Notification of registration as user of Model Super Tiger. MACDONALD.C.E. Transportation Branch. 79/11/16. 1p.
- 7912070117 Notification of registration as user of Model Buper Tiger in response to request.

  MACDONALD, C. E. Transportation Branch. 79/11/16. ip.
- 7912060501 Notification of registration as user of Models Super Tiger & 6144 in response to request.

  MACDONALD, C. E. Transportation Branch. 79/11/20. 1p.
- 7912140036 Notification of registration as user of Model Super Tiger in response to request. MACDONALD, C. E. Transportation Branch. 79/11/20, ip.
- 7912200662 Requests registration as user of Model Buper Tiger. KREY8A,F.J. Neutron Products, Inc. 79/12/04. 1p.

### DOCKET 71-6569 MODEL: LL-60-150, TVA

- 7912040207 Notification of registration as user of Model 11-40-150. MACDONALD.C.E. Transportation Branch. 79/11/16. 19.
- 7912060638 Notification of registration as user of Model LL-60-150 in response to request.

  MACDUNALD, C. E. Transportation Branch. 79/11/16. ip.
- DOCKET 71-6581 MODEL: 51032-1 & 1A: EXXON NUCLEAR CO.: INC.
- 7912200110 Informs that add1 info & changes to consolidated license renewal application, XN-52. Revision 1 will be completed & forwarded for review by 79130.
  NILSON,R. Exzon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/08.
- 79122B0003 Forwards chart of internal structure reorganization, showing revised position titles & responsibility lines. Fuel facility licensing communications should be addressed to HP Estey. Transportation matters should be directed to LE Hansen. NILBON, R. Exxon Nuclear Co. / Inc. (subs. of Exxon Corp.). 79/11/20. ip.
- --7712280006 Corporate organization chart depicting licensing to compliance line of responsibility.
  NILSON-R. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/11/20. 1p.
- 7912200008 Forwards revised pages of "Consolidated License Application for Exxon Nuclear Model 51032-1 & la Shipping Containers." HANSEN, L. E. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/11/30. 7pp.
- --7912200011 "Consolidated License Application for Exxon Nuclear Co.Inc Model 51032-1 & la Shipping Containers," Revision 1. HANSEN, L.E.: EHLERG, R. J., SOFER, Q. A. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). XN-52. 79/11/30. 90pp.
- --7912200015 "Critical Paramoters of Pu Sys.Part 1: Analysis of Experiments," HANGEN.L.E., CLAYTON,E.D., LLOYD,R.C. Battelle Memorial Institute, Pacific Northwest Laboratory. 68/12/20. 10pp.
- --7912200020 "Thermal Reactors: Calculations of Power Distributions & Reactivities."

  VOTINEN, V. O., HELHAUS, O. L., JENGUIN, J. P. Battelle Hemorial Institute, Pacific Northwest Laboratory. NMWL-1381-2. 79/11/30. 7pp.
- --7912200029 "Criticality Safety Benchmark Calculations for Low Enriched U Metal & U Oxide Rod-Water Lattices." BROWN,C.O., HANSEN,L.E., ECHODOM,H.S. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). XN-FN-499. 79/04/30. 36pp.
- DOCKET 71-6401 MODEL: LL-50-100, CHEM-NUCLEAR SYSTEMS, INC.
- 7912100084 Requests registration as user of Models Vandenburgh, 6144, 6244, PB-1, LL-50-100, GE-1600, CNS1-14-199-H, CNS1-21-300, CNS-1600, Radwaste Carrier I, CNS-80A, 7-100, BC-4B-220, LL-2B-4 & AL-33-90. CLAYTON, F. L. Alabama Power Co. 79/11/06. 2pp.
- 7912100399 Notification of registration as user of Models LL-28-4,N-55, PB-1,6244,AL-33-90,CN6-80A.Radwaste Carrier I.7-100, LL-50-100,BC-48-220 & CN81-14-195-H in response to ltr. MACDONALD,C.E. Transportation Branch. 79/11/20, 1g.
- DOCKET 71-6478 MODEL: LP-50, ENERGY, DEPT. OF
- 7912050461 Certificate of Compliance 6678 Revision O for Model LP-50. DDT 791106 IAEA Certificate of Competent Authority encl. MACDDNALD.C.E. Transportation Branch. 77/09/29, 4pp.
- DOCKET 71-6698 MODEL: NFS-4, NUCLEAR FUEL SERVICES, INC.
- 7912310488 Responds to 791017 ltr suggesting numberstructive examination or engineering analysis be performed on C-2 weld on NAC-1C cask. Ultrasonic examination on 791105 verified integrity of weld.

  BONNELL, J. R. Nuclear Assurance Corp. 79/11/09. 2pp.

- 7912280033 Forwards 791212 order amending Certificate of Compliance 6598 & lifting suspension of license to use Casks NAC-1B. NAC-1B. NAC-1B. BIRKS.H.J. Office of Nuclear Material Safety & Safeguards. 79/12/12. 2pp.
- --7912280037 Order amending Certificate of Compliance 6678 & partially terminating 790406 order to show cause by lifting suspension of license to use Casks NAC-18, NAC-10 & NAC-1E. Requests for bearing shall not stay affectiveness of order. MACDUNALD.C.F. Transportation Branch. 79/12/12. App.
- --7912280038 Certificate of Compliance 6698 Revision 9, for radioactive matt shipping package Model NFS-4.
  HACDONALD.C.E. Transportation Branch. 79/12/12. 6pp.

### DOCKET 71-6717 MODEL: 6717 B

- 7912070503 Requests registration as user of Model 6716 B shipping container.
  KWIRANT.E.H. Argonne National Laboratory. 79/11/01. 1p.
- 7912100378 Notification of registration as user of Model 6717-B in response to request.

  MACDONALD, C. E. Transportation Branch. 79/11/30. ip.

## DOCKET 71-7001 MODEL: IF-300, GENERAL ELECTRIC CO.

- 7912260045 Forwards Revision 9 to Cartificate of Compliance 9001 for Model IF-300 shipping container. MACDUNALD, C. E. Transportation Branch. 79/12/10. 2pp.
- --7912260049 Certificate of Compliance 9001, Revision 9, for Model IF-300 shipping container. MACDONALD, C. E. Transportation Branch. 79/12/10. 6pp.

## DUCKET 71-9006 MODEL: 500 SU, ARGUNNE NATIONAL LABORATORY

- 7912260042 Requests renewal of Certificates of Compliance 9006 & 9007. EANTORD M.P. Automation Industries, Inc. 79/11/15. 1p.
- --7912260047 Requests payment of fees for renewal of Gertificates of Compliance 9006 & 9007. WEI86.J.D. License Fee Management Branch. 79/11/26. 1p.

## DOCKET 71-9007 MODEL: 520, ARGUNNE NATIONAL LABORATORY

- 7912260042 Requests renewal of Certificates of Compliance 9006 & 9007. SANTORO.M.P. Automation Industries, Inc. 79/11/15. 1p.
- --7912260047 Requests payment of fews for renewal of Certificates of Compliance 9006 & 9007. WEISS.J.B. License Fee Management Branch. 79/11/26. ip.

## DOCKET 71-9009 MODEL: FL 10-1, GENERAL ELECTRIC CO.

- 7912170136 Requests that phenolic foam be approved for Hodel FL-10-1 packages. Foam uses starting matls outlined in rept. "Evaluation of Matls Used in Fire-Resistant Phenolic Foam." TRAVIS. W.H. Energy, Dept. of. 79/11/19. Epp.
- ---7912170144 "Evaluation of Matla Usad in Fire Resistant Phenolic Foam." DAUGHERTY, C. E., HARRIS, G. E., WRIGHT, R.R. Union Carbide Corp. 78/03/01. 15pp.

## DOCKET 71-9010 MODEL: NLI-1/2, NL INDUSTRIES, INC.

- 7912040080 Notification of registration as user of Model NLI-1/2. MACDONALD, C.E. Transportation Branch. 79/11/16. 1p.
- 791204017B Notification of registration as user of Model NLT-1/2 in response to request.

  MAGDONALD.C.E. Transportation Branch. 79/11/16. 1p.
- 7712040089 Notification of registration as user of Model NLI-1/2. MACDONALD, C. E. Transportation Branch. 79/11/20. ip.

- 7912270002 Withdraws 791018 request for temporary administrative change in packaging operation.
  WILLIAMS.C.E. NL Industries, NL Nuclear Div. 79/12/05. 1p.
- DOCKET 71-9011 MODEL: E-MEH-00-00004, TRANSPORTATION, DEPT. OF
- 79120600B1 Requests registration as user of Models 181375, 181361 & E-MEH-00-00004. KELBLEY, N. D. Advanced Medical Systems, Inc. 79/11/02. 1p.
- 7912070509 Requests registration as user of Models 191375 & 181361 & E-MEH-00-00004. KELBLEY, N. D. Advanced Medical Systems: Inc. 79/11/02. 1p.
- 7912070010 Notification of registration as user of Models 181375 & 181361 & E-MEH-00-00004 in response to request.

  MACDUNALD, C. E. Transportation Branch. 79/11/30. ip.
- DOCKET 71-9019 MODEL: BU-7, GENERAL ELECTRIC CO.
- 7912200023 Requests registration as user of Model BU-7 shipping container. DIFIAZZA.R.P. Westinghouse Electric Corp. 79/11/02. ip.
- 7912070107 Notification of registration as user of Model BU-7. MACDONALD.C.E. Transportation Branch. 79/11/16. ip.
- 7712310079 Notification of registration as user of Model BU-7 in response to vendor request.

  MACDONALD, C. E. Transportation Branch. 79/12/10, 1p.

# DOCKET 71-9027 MODEL: 741; TECHNICAL OPERATIONS, INC.

- 7912200461 Requests renewal of Certificate of Compliance 9027 for Models 741 & 741E Type B packages. Consolidated application encl. MUNRO, J. J. Tech/Dps (Technical Operations, Inc.). 79/11/E9. 70ap.
- DOCKET 71-9028 MODEL: 684, TECHNICAL OPERATIONS, INC.
- 7912180293 Forwards revised drawings of Models 684 & 6846 Type 8 packaging re NRC 791107 request. MUNRO, J. J. Tech/Ops (Technical Operations, Inc.). 79/11/09. 8pp.
- 791204015B Notification of registration as user of Models 660,660E,650,684E,680,680E,715 & 771.
  MACDONALD, C. E. Transportation Branch. 79/11/20. 1p.

## DOCKET 71-9032 MODEL: 650. TECHNICAL OPERATIONS, INC.

- 7912060138 Notification of registration as user of Models 660,660E,630,684,684E,680,680E,713 % 771.

  MACDONALD,C.E. Transportation Branch. 79/11/20. ip.
- DUCKET 71-9033 MODEL: 660 & 660E, TECHNICAL OPERATIONS, INC.
- 791206015B Nutification of registration as user of Hodels 660,660E,650,684E,680,680E,715 & 771.

  MACDONALD,C.E. Transportation Branch. 79/11/20. 1p.
- 7912140075 Requests continuation as user of Models 660 & 660£. ROGERS.H.W. H. R. Inspection Service. 79/11/21. 1p.
- DOCKET 71-9035 MODEL: 680, TECHNICAL OPERATIONS, INC.
- 7912060333 Requests registration as user of Model 680. KOMALSKI, J. G. ITT Grinnell. 79/11/09. ip.
- 791206019B Notification of registration as user of Models 660,660E,650. 684,684E,680,680E,715 & 771. MACDONALD.C.E. Transportation Branch. 79/11/20. 1p.
- 7712200555 Notification of registration as user of Models 600 % 680% in response to request. MACDQNALD.C.E. Transportation Branch. 79/12/10. 1p.

DOCKET 71-9039 MODEL: 715, TECHNICAL OPERATIONS, INC.

7912060138 Notification of registration as user of Models 660,660E,650,664,684E,680,680E,715 % 771.

MACDONALD,C.E. Transportation Branch. 79/11/20, 1p.

DOCKET 71-9044 MODEL: 0E-1600, GENERAL ELECTRIC CO.

7712100084 Requests registration as user of Models Vandenburgh, 6144, 6244, P8-1, LL-50-100, GE-1600, CNB1-14-195-H. CNB1-21-300, CNB-1600, Radwaste Carrier I, CNB-80A, 7-100, BC-48-220, LL-28-4 & AL-33-90.

CLAYTON, F. L. Alabama Power Co. 79/11/06. 2pp.

7912060144 Natification of registration as user of Models CNBI-1600, OE-1600, Vandenburgh & PB-1.
MACDONALD, G. E. Transportation Branch. 79/11/20. 1p.

DOCKET 71-9070 MODEL: N-55, ENERGY, DEPT. OF

7912040069 Requests registration as user of Model CNSI 1-8. BTRACCIA, F. P. Unior Carbida Corp., Chem. & Plantics Div. 79/11/12. 1p.

7912040064 Requests registration as user of Model CNSI 1-8.
LUCAB, B.V. Unior Carbida Corp. .. Chem. & Plastics Div. 77/11/13.
ip.

7912170125 Requests registration as user of Model CNBI 1-8. Notifies of proposed shipment of Type B quantity of radioactive mat! for disposal.

BTRACCIA, F. P. Unior Carbide Corp., Chem. & Plastics Div. 79/11/19.

7912100399 Notification of registration as user of Models LL-28-4,N-55, PB-1,6244,AL-33-90,CN6-80A,Radwaste Carrier I,7-100, LL-50-100,BC-48-220 & CNBI-14-195-H in response to itr. MACDEMALD,C.E. Transportation Branch. 79/11/20. lp.

7952110050 Notification of registration as user of Model N-55 in response to 791119 request.
MACDONALD,C.E. Transportation Branch. 79/11/28. 1p.

DOCKET 71-9079 MODEL: HN-100 BERIEB 2. HITTMAN NUCLEAR & DEVELOPMENT

7912070506 Requests registration as user of Models Hittman HN-100 Series 2 & CNSI 21-300.

CALHOUN J.R. Tennesse Valley Authority. 79/11/07. ip.

7912110553 Notification of registration as user of Model HN-100 Beries 2 in response to request.

HACDONALD.C.E. Transportation Branch. 79/11/20. 1p.

7912070017 Notification of registration as user of Models RN-100 Series 2 & CNSI-21-300 in response to request.

MACDONALD, C. E. Trensportation Branch. 79/11/30, 1p.

DOCKET 71-9081 MODEL: CN81-1600, CHEM-NUCLEAR SYSTEMS, INC.

7912070494 Requests registration as user of Model CNS-1-13C. ANDOGNINI, Q. C. Boston Edison Co. 79/10/26. 1p.

7912100084 Requests registration as user of Models Vandenburgh, 6144, 6244, FB-1, LL-50-100, GE-1600, CNB1-14-195-H, CNB1-21-300, CNB-1600, Radwaste Carrier I, CNB-80A, 7-100, BC-48-220, LL-28-4 & AL-33-90, CLAYTON, F. L. Alabama Power Co. 79/11/06. 2pp.

7912040188 Notification of registration as user of Model CNS-1400 in response to request.

MACDONALD,C.E. Transportation Branch. 79/11/14. ip.

7912060144 Notification of registration as user of Models CNSI-1600, OE-1600, Vandenburgh & PB-1.
MACDONALD, C. E. Transportation Branch. 79/11/20. ip.

7912110057 Notification of registration as user of Models 6144 & CNB-1600.
MACDONALD, C. E. Transportation Branch. 79/11/30. 1p.

DOCKET 71-9085 MODEL: SENTINEL 85

7912050455 Certificate of Compliance 9085, Revision 1 for Model Sentinel 85.
MACDONALD, C. E. Transportation Branch. 78/04/07. 49p.

DOCKET 71-9086 MODEL: HN-100 SERIES 1. HITTMAN NUCLEAR & DEVELOPMENT

791206019B Notification of registration as user of Model HN-100 Series
1.
MACDONALD, C. E. Transportation Branch. 79/11/16. 1s.

DOCKET 71-9089 MODEL: NH-100 8. HITTMAN NUCLEAR & DEVELOPMENT CORP.

7912040076 Notification of registration as user of Model HN-1009. MACDONALD.C.E. Transportation Branch. 79/11/16. ip.

DOCKET 71-9094 MODEL: CNSI-14-195-H, CHEM-NUCLEAR SYSTEMS, INC.

7912100084 Requests registration as user of Models Vandenburgh,6144,6244.P8-1,LL-50-100,GE-1600,CNS1-14-195-H,CNS1-21-300,CNS-1600,Radwaste Carrier I,CNS-80A,7-100,BC-48-220,LL-28-4&AL-33-90.CLAYTON.F.L. Alabama Power Co. 79/11/06. 2pp.

7912100396 Notification of registration as user of Models 7-100, CNSI-14-195-H & CNSI-21-300.
MACDONALD, C. E. Transportation Branch. 79/11/20, ip.

7912100399 Natification of registration as user of Models LL-28-4,N-55, FB-1,6244,AL-33-90,CN6-80A,Radwasta Carrier 1,7-100,LL-50-100,BC-48-220 & CNB1-14-195-H in response to 1tr. MACDONALD.C.E. Transportation Branch. 79/11/20. 1g.

791211000B Notification of registration as user of Models 7-100. CMSI-14-195-H & CMSI-21-300. HACDONALD, C. E. Transportation Branch. 79/11/20. ip.

DOCKET 71-9094 MODEL: CNSI-21-300, CHEM-NUCLEAR SYSTEMS, INC.

7912100084 Requests registration as user of Models Vandenburgh, 6144, 6244, PB-1, LL-50-100, QE-1600, CNS1-14-195-H. CNS1-21-300, CNS1-1600, Radwaste Carrier I, CNS-BOA, 7-100, BC-4B-220, LL-28-4 & AL-33-90.

CLAYTON, F. L. Alabama Power Co. 79/11/06. 2pp.

7912070506 Requests registration as user of Hodels Hittman HN-100 Berles 2 & CNSI 21-300. CALHOUN, J. R. Tennessee Valley Authority. 79/11/07. 1p.

7912040183 Notification of registration as user of Model CNSI-21-300 in response to request.

MACDONALD.C.E. Transportation Branch. 79/11/16. ip.

7912060202 Notification of registration as user of Model CNSI-21-300. MACDONALD.C.E. Transportation Branch. 79/11/16. 1g.

7912100396 Notification of registration as user of Models 7-100. CN91-14-195-H & CN91-21-300. MACDONALD, C. E. Transportation Branch. 79/11/20. ip.

7912110008 Notification of registration as user of Models 7-100, CNSI-14-195-H & CNSI-21-300, MACDONALD,C.E. Transportation Branch. 79/11/20, 19.

7912070017 Notification of registration as user of Models HN-100 Beries 2 & CNST-21-300 in response to request.

MACDONALD.C.E. Transportation Branch. 79/11/30. ip.

DUCKET 71-9105 MODEL: RAD-WASTE CR. I. CHEM-NUCLEAR SYSTEMS, INC.

7912100084 Requests registration as user of Models Vandenburgh, 6144, 6244, PB-1, LL-50-100, GE-1600, CNS1-14-195-H, CNS1-21-300, CNS-1600, Radwaste Carrier I, CNS-80A, 7-100, BC-48-220, LL-28-4 & AL-33-90.

CLAYTON, F. L. Alabama Power Co. 79/11/06. 2pp.

## **DOCKETED ITEMS**

7912100399 Notification of registration as user of Models LL-28-4.N-55, PB-1.6244,AL-33-90,CN6-806.Radwaste Carrier 1.7-100, LL-50-100,BC-48-220 & CN81-14-195-H in response to 1tr. MACDONALD.C. E. Transportation Branch. 79/11/20. 1p.

### DOCKET 71-9107 MODEL: 771, TECHNICAL OPERATIONS, INC.

791206015B Notification of registration as user of Models 660,660E,650,684E,680,680E,715 & 771.

MACDONALD, C. E. Transportation Branch, 79/11/20, 1p.

### DOCKET 71-9108 MODEL: AL-33-90, ATCOR, INC.

7912060647 Notification of registration as user of Model AL-33-90 in response to request.
MACDDNALD.C.E. Transportation Branch. 79/11/20. 1p.

7912100399 Notification of registration as user of Models LL-28-4,N-55, PB-1,6244,AL-33-90,CN6-80A,Radwaste Carrien I,7-100, LL-50-100,BC-48-220 & CN8I-14-195-H in response to ltr. MACDONALD,C.E. Transportation Branch. 79/11/20. 1p.

## DOCKET 71-9111 MODEL: CN6-80A, CHEM-NUCLEAR, INC.

7912100084 Requests registration as user of Models Vandenburgh, 6144, 6244, PB-1, LL-50-100, GE-1600, CNS1-14-195-H. CNS1-21-300, CNB-1600, Radwaste Carrier I, CNS-80A, 7-100, BC-48-220, LL-28-4 & AL-33-90.
CLAYTON, E. L. Alabama Power Co. 79/11/06. 2pp.

7912060648 Notification of registration as user of Model CN6-80A in response to request.

MACDQNALD, C. E. Transportation Branch. 79/11/20. ip.

7912100399 Notification of registration as user of Models LL-28-4,N-55, PB-1,6244,AL-33-90,CN6-80A,Radwaste Carrier I,7-100, LL-50-100,BC-48-220 & CN81-14-195-H in response to ltr. HACDDNALD,C.E. Transportation Branch. 79/11/20. 1p.

7912100460 Forwards Revision 2 to Certificate of Compliance 9111 for Model CN6-80A.
MACBONALD, C. E. Transportation Branch. 79/11/30. 2pp.

--791210D462 Certificate of Compliance 9111.Revision 2,for Model CN6-80A. MACODNALD.C.E. Transportation Branch. 79/11/30. 3pp.

## DOCKET 71-9113 MODEL:7-100, CHEM-NUCLEAR BYSTEMS, INC.

7912100084 Requests registration as user of Models Vandenburgh, 6144, 6244, PB-1, LL-50-100, GE-1600, CNB1-14-195-H, CNB1-21-300, CNB-1600, Radwaste Carrier I, CNB-80A, 7-100, BC-48-220, LL-28-4 & AL-33-90. CLAYTON, F. L. Alabama Power Co. 79/11/06. 2pp.

7912100396 Notificaton of registration as user of Nodels 7-100, CNSI-14-195-H & CNSI-21-300.

MACDDNALD.C. E. Transportation Branch. 79/11/20. ip.

7912100399 Notification of registration as user of Hodels LL-28-4,N-85, PB-1,6244,AL-33-90,CN6-80A. Radwaste Carrier 1,7-100, LL-50-100,BC-48-220 & CNSI-14-195-H in response to ltr. HACDONALB.C.E. Transportation Branch. 79/11/20. ip.

7912110008 Notification of registration as user of Models 7-100.

79/11/20. 1p.

:e of Compliance 9113 for 79/11/28. Spp.

evision 2. for Model 7-100. 79/11/28. Spp. DECKET 71-9119 MODEL: BAPL 5910 BRDC9, ENERGY, DEPT. OF

7912100371 Forwards Revision 2 to Certificate of Compliance 9119 for Model BAPL 5910.
MACDONALD, C. E. Transportation Branch. 79/11/30. 2pp.

--7912100373 Certificate of Compliance 9119, Revision 2 for Model DAPL 5910. MACDDNALD, C. E. Transportation Branch. 79/11/30. 3pp.

DOCKET 71-9132 MDDEL: T-3, NUCLEAR PACKAGING, INC.

7712270057 Forwards request for addl info re approval to deliver Model T-3 packaging to carrier for transport. MACDONALD.C.E. Transportation Branch. 79/12/06. 3pp.

DOCKET 71-9137 MODEL: 820

7912210287 Requests certificate of compliance for Model 820 Type B. Package description & fee encl. MUNRO, J. J. Tech/Ops (Technical Operations, Inc.). 79/11/09. 60pp.

DOCKET 71-9851 MODEL: LITHIUM HYDROXIDE FIRE/IMPACT SHIELD,

7712100149 Forwards request for add1 info for review of model lithium hydroxide fire & impact shield shipping package, MACDONALD, C. E. Transportation Branch. 79/11/20. 2pp.

DOCKET 71-9853 MODEL: ORNL - BNL - NBS UN FUEL CONTAINER, ENERGY,

7912040093 Requests registration as user of Model ORNL-BNL-NBS UN Fuel Container. SHERMAN,F.L. Texas Instruments, Inc. 79/11/15. 1p.

7912040027 Forwards Revision 0 to Certificate of Compliance 9853 for Models DRNL-BNL-NBS unirradiated fuel shipping container. MACDONALD, C. E. Transportation Branch. 79/11/20, ip.

--7912040030 Certificate of Compliance 9853, Revision O, for Models QRNL-GNL-NBS.
MACDENALD, C. E. Transportation Branch. 79/11/20. 3pp.

7912140135 Requests registration as user of Model ORNL-BNL-NBS.
CARTER.R.S. Commerce Dept. of, National Bureau of Standards.
79/11/20, ip.

7912140096 Requests registration as user of Model ORNL-BNL-NBS UN fuel container. PENNEY, J. A. Brookhaven National Laboratory. 79/11/26, 1p.

7912190130 Requests that Union Carbide Corp. Nuclear Div be registered as authorized user of Model ORNL-BNL-NDS on Fuel Container Energy.
BLALOCK, L. Energy, Dept. of. 79/11/30. ip.

DOCKET 71-9932 MODEL: UC-609, ENERGY, DEPT. OF

7912210293 Forwards Revision O to Certificate of Compliance 9932 for Madel UC-409.
MACDONALD, C. E. Transportation Branch. 79/09/18. 1p.

--7912210296 Certificate of Compliance 9932, Revision O. for Model UC-609. MACDONALD, C. E. Transportation Branch. 79/09/18. 6pp.

### NONDOCKETED ITEMS

#### 10CFR COMMISSION MEETING RECORDS

- 7912030005 Transcript of Subcommittee on GE Test Reactor 791114 meeting in Burlingame.CA.Pp 1-331.Presentation by Earth Sciences Associates encl. #\_ACRS Advisory Committee on Reactor Safeguards. 79/11/14.
- 7912030036 Transcript of Subcommittee on Extreme External Phenomena 791115 meeting in Los Angeles CA Pp. 1-280 Presentation "Seismic Safety Mergine Research Program" by JE Richardson ACRS - Advisory Committee on Reactor Safeguards. 79/11/15.
- 7912030039 Transcript of Subcommittee on Extreme External Phenomena 79116 meeting in Los Angeles.CA. Pp. 281-533. Presentation "Project 6: Component & Structural Fragilities" by RO Dong encl. ACRS - Advisory Committee on Reactor Bafeguards. 79/11/16. 449pp.
- 7912030213 Transcript of 791119 public meeting in Washington.DC re SECY-79-580, "Disposal of High Level Radwastes in Geologic Repositories: Procedural Aspects." Pp 1-64. SECY-79-580 encl. \* Commission. 79/11/19. 73pp.
- 7912050160 Transcript of 791114 meeting in Washington, DC. Pp 1-7. \* Commission. 79/11/14. 7pp.
- 7912050288 Transcript of 791114 meeting in Washington, DC. Pp 1~83. \* Commission. 79/11/14, 84pp.
- 7912060387 Transcript of Commission 791121 briefing in Washington.DC retechnical assistance projects in waste mgt.Pp 1-32.

  \* Commission. 79/11/21. 34pp.
- 7912060398 Transcript of Affirmation Session 79-38 on 791121 re SECY-79-609, program impact statement for TNI-2, in Hashington, DC. Pp. 1-3. \* Commission. \* Docketing & Services Branch. 79/11/21. Spp.
- 7912170054 Transcript of 791203 discussion in Washington,DC on SECY-79-591, "Plans for Coping w/Emargencies at Production & Utilization Facilities." Pp 1-51, Summary encl. BRDWN.C.H. Office of the Secretary of the Commission. 79/12/03.
- 7912180249 Unofficial transcript of 791205 public meeting in Washington, DC to discuss & vote on SECY-79-591A, BECY-79-591B & BECY-79-591C, Pp 1-12, Draft FR notice re proposed rule on emergency planning encl. \* Commission. 79/12/05. Sipp.
- 7912190198 Transcript of 791212 public meeting in Washington, DC. Pp 1-6. ★ Cammission, 79/12/12. 7pp.
- 7912190272 Transcript of 791212 public meeting in Washington DC. Pp 1-63 Forwards visual aids & discussions re Lessons Learned Task Force short-term requirements implementation. 8 Commission. 79/12/12. 168pp.
- 7912200223 Transcript of 791206 public briefing an policy, planning & program guidance in Washington, DC. Pp 1-67.

  # Commission. 79/12/06. 68pp.
- 7912200227 Transcript of 791206 public meeting in Washington. DC. Pp 1-73. \* Commission, 79/12/04. 74pp.

- 7912280620 Transcript of 791212 public meeting in Washington DC reaction plan. Pp 1-62, W/draft action plans for implementing recommendations of President's Commission & other studies of TMI accident accident (NUREO-0660).

  \* Commission. DENTON, H. R. Office of Nuclear Reactor Regulation. MATTSON, R. J. Division of Systems Safety. 79/12/12. 70pp.
- 7912310296 Transcript of 791212 public meeting in Washington,DC re I&E briefing on TMI lessons learned.Pp 1-47. Std Review Group findings & draft NOREO-0616. "Rept to Director,Ofc of IE on Lessons Learned From TMI" encl.

  \* Commission. 79/12/12. 58pp.

#### ADVISORY COMMITTEE ON REACTOR SAFEGUARDS ACRE

- 7912050216 Transcript of 791116 ACRS Bubcommittee on Fluid Dynamics meeting in San Francisco (CA.Pp 1-229.

  \* ACRB Advisory Committee on Reactor Safeguards. 79/11/16.
- 7912070281 Summary of ACRS Subcommittee on LERs 790628-27 meeting w/Duke Power & EPRI in Washington.DC re review of LERs & preparation of draft rept for consideration of Full ACRS.

  ACRS Advisory Committee on Reactor Safeguards. 79/10/01. 79/10/01. 1600.
- 7912070287 Summary of ACRS Subcommittee on Evaluation of LERs 790322-24 meeting w/Univ of CA.Union Carbide & IEAL in Washington, DC re NRC procedures, methods & criteria re LERs.

  w ACRS Advisory Committee on Reactor Safeguards. 79/06/14. 12pp.
- 7912070276 Summary of ACRB Subcommittee on Reactor Operations 790613 meeting w/C-E.Northeast Utils.FL Power & Light & Exxon Nuclear Co in Washington.DC re Milletone 2 power level increase & safety research program on operational safety.

  \* ACRS Advisory Committee on Reactor Safeguards. 79708/07. Bipp.
- 7912070302 Summary of ACRS ECCS Subcommittee 790319-20 meeting w/Exxon Nuclear Co.8&M, Bechtel & Westinghouse in Los Angeles, CA rereview of status of NRC research programs on analytical work related to LOCA/ECCS & ECCS-related experiments.

  \* ACRS Advisory Committee on Reactor Safeguards. 79/06/14. 75pp.
- 7912070312 Summary of ACRS Subcommittee on Reactor Safety Research 790710 meeting w/EPRI in Washington.DC re gathering info for & preparing draft rept on Ofc of Nuclear Regulatory Research FYSO budget suppl & 1981 budget. \* ACRS Advisory Committee on Reactor Safeguards. 79/08/11. App.
- 7912070315 Summary of ACRS Extreme External Phenomena Subcommittee 790711 open meeting in Washington.DC re matters concerning NRC-sponsored research. \* ACRS Advisory Committee on Reactor Safeguards. 79/10/11. 15pp.
- 7912070382 Summary of ACRS LER Subcommittee 790426-27 meeting w/IA State Univ in Washington,DC re continued review of LERs. \* ACRS Advisory Committee on Seactor Safeguards. 79/06/14. 15pp.
- 7912070482 Summary of ACRS Subcommittee on LERs 790718-19 meeting w/DDE & EPRI in Washington. DC re continuing review of LERs & preparing of draft rept for consideration by full ACRS.

  \* ACRS Advisory Committee on Reactor Safeguards. 79/09/20. Spp.
- 7912070490 Summary of ACRS Subcommittee on Advanced Reactors 790807 open meeting in Washington. DC re continuing subcommittee review of matters related to NRC-sponsored research on safety of advanced reactors.

  \*\*ACRS Advisory Committee on Reactor Safeguards. 79/09/08. 15pp.
- Pi2070510 Summary of ACRS Waste Mgt Bubcommittee 790418-19 moeting w/DDE,Bechtel,Rockwell & BNML in Richland.WA re recent developments in vitrification & solidification of high level wastes. \* ACRS — Advisory Committee on Reactor Safeguards. 79/08/10. 93pp.

- 7912100029 Transcript of ACRB 791129 subcommittee meeting in Albuquerque, NM. Pp 1-317. KERR W., CARBON, M., MARK, C. ACRB Advisory Committee on Reactor Bafeguards. 79/11/29. 318pp.
- 7912100034 Transcript of ACRS 791130 subcommittee meeting in Albuquerque, NM. Pp. 318-675.
  KERR, W., CARBON, M., MARK, C. ACRS Advisory Committee on Reactor Safeguards. 79/11/30. 358pp.
- 7912100195 Summary of ACRS Subcommittee on Regulatory Activities 790809 meeting w/EPRI & Sachtel in Washington.DC re review of proposed res guides & stds & revisions to existing guides & stds.
- ACRB Advisory Committee on Reactor Safeguards. 79/09/18. 11pp.
- 7912100204 Summary of ACRS Subcommittee on Advanced Reactors 790711 meeting in Hashington DC re matters related to ACRS review of NRC sponsored research on advanced reactors.

  \* ACRS Advisory Committee on Reactor Safeguards. 79/10/17. 1ipp.
- 7912110085 Summery of ACRS Subcommittee on Fort St Vrain Generating Station 790315 meeting w/GA Co in Longmont CO re review of operations to date & discussion of refueling operations
  - in progress. ACRS Advisory Committee on Reactor Bafeguards, 79/07/06. 29pp.
- --7912110070 Notifies of ACRS Submoommittee on Fort St Vrain 790315 meeting in Longmont.CO to review operations to date & witness portions of refueling operations.

  MCKINLEY.J.C. ACRS Advisory Committee on Reactor Safeguards.
  79/03/07. 3pp.
- 7912110097 Summary of ACRS Subcommittee on Regulatory Activities meeting w/EPRI.OR. IEEE & Yonkee Atomic Electric Co in Washington.DC re review of proposed reg guides & revisions to existing reg guides & stds.

  # ACRS Advisory Committee on Reactor Safeguards. 79/07/13. 18pp.
- .--7912110104 Forwards comments on Reg Quide 1.9, "Relection.Design & Qualification of Dissel Generator Units Used as Onsite Electric Power Sys at Nuclear Power Plants." \* Tennessee Valley Authority. 79/04/05. 2pp.
- 7912110105 Summary of ACRS Subcommittee on Improved Safety Sys 790626 meeting w/B&H:Sandia:ERRI & Westinghouse in Washington.DC re discussion of NRC & DDE plans for research to improve reactor safety sys.

  \* ACRS Advisory Committee on Reactor Safeguards. 79/08/09. 67pp.
- --791211010B Notifies of budget allowances & significant policy determinations applicable to agency. Budget authority approved by President for 1979-1980. MCINTYRE. J. Office of Management & Budget. 79/01/31. 3pp.
- 791212005B Summary of 790709 open meeting of ACRB Subcommittee on TMI-2 Accident Bulletin & Orders, in Hashington, DC re vendor & util response to IE bulletins & NRC orders, ACRB Advisory Committee on Reactor Safeguards, 79/08/11, 47pp.
- 7912140208 Transcript of ACRS 791205 subcommittee moeting in Hashington DC on fire protection Pp 1-50. ETHERINGTON H., BENDER, M., EBERGOLE, J. C. ACRS Advisory Committee on Reactor Safeguards. 79/12/05. 51ep.
- 79:21402:1 Transcript of ACRS 79:205 subcommittee meeting in Mashington, DC on reliability & probabilistic assessment. Pp 1-276. OKRENT, D., ETHERINOTON, H., MARK, J. C., ACRS Advisory Committee on Reactor Bafeguards. 79/12/05. 279pp.
- 79:2:140544 Informs that public safety will not be jeopardized by extending implementation schedule of short-term recommendations of Lessons Lawrned Task Force.

  on Reactor Bafeguards.

incurred in regulatory in agreed Safeguards.

-evaluation of SEP Reactor Safequards.

- 7912170097 Responds to 790912 ltr re emission of xenon from TMI-2. Rept will be completed within three months. CARBON.M.M. AGRB Advisory Committee on Reactor Safeguards. 79/10/09. 2pp.
- 7912170107 Notifies of completion of ACRS review of NUREQ-0600. Rept found to be less than satisfactory & to have misleading title. Recommends preparation & issuance of supplemental rept. CARBON.M.H. ACRS - Advisory Committee on Reactor Safeguards. 79/11/14. 2pp.
- 7912180258 Comments on ACRS Waste Mgt Bubcommittee meeting Research program left no gaps in coverage & no glaring need for curtailment. Explanation is needed on use of voting form. GRENDOM.A. Affiliation Unknown. 79/09/24. 2pp.
- 7912180267 Discusses concerns re nuclear regulation & disposal of nuclear wasts. CREMER.B. Affiliation Unknown. 79/09/25, 2pp.
- 7912180276 Summarizes impressions & recommendations arising from recent-review of NRC wasts mgt research program Dutlines priority procedures. STEINDLER, M. J. Argonne National Laboratory. 79/09/27. 2pp.
- 7912180284 Discusses validity of 88E of 0, 12 gravity for Wolf Greek project & deterioration of concrete in base mat of reactor containment bldg. 88E should be redatermined. No bases for further comment re concrete.

  HAYWELL,J.C. Affiliation Unknown, 79/10/01, 2pp.
- 7912180290 Discusses concerns re ACRS Weste Mgt Subcommittee 790918-19 meeting. Not enough info was presented on research programs. Documentation for EIS on milling should have been sent to members prior to meeting. PARKER, F. L. Vanderbilt Univ. 79/10/03. 2pp.
- 7912180294 Summary of ACRS ECCS Subcommittee 790827-28 meeting in Idaho Falls: ID.
  CATION I. ACRB - Advisory Committee on Reactor Bafeguards.
  79/10/09. 3pp.
- 7912180457 Summary of 790510-12 open meeting in Mashington, DC recurrent status of TMI-2, Sequoyah Power Plants Units i & 2 & Dyster Creek transient resulting in low core water level. \* ACRS Advisory Committee on Reactor Safeguards. 79/05/12. 352pp.
- --7912180461 Forwards draft rept. "Interegency Task Force on Ionizing Rediation on Institutional Arrangements."
  TAYLOR.L.S. National Council on Radiation Protection & Heasurement. 79/04/30. 70pp.
- --7912180462 Discusses fuel element cladding. OILINSKY, V. Commission. 79/05/08. ip.
- --7912180522 Ack receipt of Interagency Task Force Rept.Committee will discuss rept at June 1979 meeting.
  CARBON.M.W. ACRB Advisory Committee on Reactor Bafeguards.
  1638. 79/05/15. ip.
- 7912170274 Summary of 790614-16 open meeting in Washington DC restatus of TMI-2 & implications on future power plant design. Sume encl memos ref Deletion 1.

  \* ACR8 Advisory Committee on Reactor Safeguards. 79/06/16.
- --7912190278 Discusses schedule of ACRS subcommittee meetings & tours. LIBARKIN.M.W. ACRS Advisory Committee on Reactor Bafaguards. 79/06/16. 2pp.
- --7912190282 Discusses erroneous statements provided by applicant at Zimmer ACRS subcommittee meeting.

  KEPPLER, J. Q. Region 3. Chicago, Office of the Director. AITS F30488H6. 79/04/10. Spp.
- ---7912190297 Discusses apparent false statements by applicant at Zimmer ACRB subcommittee meeting.
  THOMPSON, D. Office of Inspection & Enforcement, Office of the Director. AITB F30488H6. 79/05/02. 2pp.
- --7912190304 Discusses TMI-2 implications. CATTON.I. ACRB Advisory Committee on Reactor Safeguards. 79/06/14. 4pp.

- --7912190311 Discusses project status re Millstone Unit 2 power level increaso.

  \*\* ACRS Advisory Committee on Reactor Safeguards. 79/06/08.

  \*\*4pp.
- --7912190315 Lists plants w/pending applications for power lavel increase. w ACRB - Advisory Committee on Reactor Bafeguards. 79/06/21. 18pp.
- --7912190321 Discusses status of Millstone Nuclear Power Station Unit ? CP application. HENDRIE.J.M. ACRS - Advisory Committee on Reactor Safeguards. 70/05/19. 3pp.
- --7912190325 Discusses status of Millstone Nuclear Power Station Unit 2 OL application. STRATION, N. R. ACRS - Advisory Committee on Reactor Safeguards. 74/06/11. 4pp.
- --7912190330 Discusses status of Zion Station Units 1 & 2 re operating power limits.

  MANGELBOORF.H. ACRS Advisory Committee on Reactor Safeguards.
  73/05/17. 2pp.
- --7912190336 Discusses status of Zion Station Units i & 2 re proposal to increase power level. STRATTON, W.R. ACRS - Advisory Committee on Reactor Safeguards. 74/12/09. 3pp.
- --7912190341 Discusses status of Zion Station Units 1 & 2 re request to increase max reactor power.

  MOELLER.D. W. ACRS Advisory Committee on Reactor Safeguards. 76/06/09. 3pp.
- --7912190346 Discisses status of operations review for Zion Station Units 1 & 2. BENDER, M. ACRB - Advisory Committee on Reactor Safeguards. 77/06/17. 4pp.
- --7912190352 Discusses review status of Maine Yankee Atomic Power Station proposed increased power levels. LANRORNIB. ACRS - Advisory Committee on Reactor Safeguards. 78/06/07. 2pp.
- --7912190336 Discusses status of Indian Point Nuclear Generating Unit 3 proposed increased power levels.

  LANKORKI,S. AGRS Advisory Committee on Reactor Sefaguards.
  78707/13. 3pp.
- --7912190362 Discusses requests, agreements & commitments during 230th ACRB meeting on 790614-16. FRALEV.R.F. ACRB - Advisory Committee on Reactor Safeguards, 79706/19. 2pp.
- --7912190375 Ack receipt of 790605 ltr re generic safety implications of control sys & discusses post-TMI NRC actions. CARBON.H.W. ACRB - Advisory Committee on Reactor Bafeguards. 79/06/18. 3pp.
- 7712190651 Bummary of Ad Hoc Subcommittee on THI-2 Accident Implications 790711 meeting w/B&W.NUB Corp. B&&E. Bachtel & Tokyo Electric Power Co in Washington, DC re long-term TMI-2 implications.

  # ACRB Advisory Committee on Reactor Safeguards. 79/07/11. 45pp.
- 7912210049 Responds to questions raised re development of hybrid power reactor design, incorporating plant features that maximize safety. Not value of proposed design approach cannot be adequately measured.

  CARBONIM.W. ACRS Advisory Committee on Reactor Safeguards.
  79/10/10. 5pp.
- 7912210351 Transcript of ACRB subcommittee on power & electrical sys 791213 meeting. Pp 1-258.
  KERR. W., MARK. J. C., EBERSOLE. J. ACRB Advisory Committee on Reactor Bafeguards. 79/12/13. 259pp.
- 7912260288 Transcript of 791207 ACR8 meeting in Washington, DC. Pp 210-373. Implications of lessons learned at TMI-2 & recommendations of President's Commission on Accident at TMI-2 discussed.

  A ACR8 Advisory Committee on Reactor Safeguards. 79/12/07. L65pp.

- 7912260341 Transcript of 791206 ACRS general meeting in Washington DC. Pp 1-209 Implications of lessons learned at IM1-2 & recommendations of President's Commission on Accident at IM1-2 discussed.

   ACRS Advisory Committee on Reactor Safeguards. 79/12/06 210pp.
- 7912310214 Summary of Special ACRS 790416-17 meeting w/BBW & numerous public attendees in Washington DC re accident at TMI.

   ACRS Advisory Committee on Reactor Safeguards 79/08/23 34pp.
- --7912310227 Transcript of 790416 statement on behalf of BbW MACMILLAN, J. H. Babcock & Wilcor Co. 79/04/16. 27pp.
- ~~7912310239 "Decay Heat Removal During Very Small Break LOCA for BAH 205 Fuel Assembly PWR." MICHELSON.C. Babcock & Milcox Co. 78/01/31. 36pp.

### COMMISSION NRC COMMISSIONERS

- 7912040215 Weekly info rept for week ending 791123. REHM.T.A. Office of the Executive Director for Operations. 79/11/27. 26pp.
- 7912170051 Weekly info rept for week ending 791116. REHM-T.A. Office of the Executive Director for Operations. 79/11/23. 35pp.
- 7912180148 Weekly info rept for week ending 791130. REHM.T.A. Office of the Executive Director for Operations. 79/12/06. 25pp.
- 7912200034 Comments on Commissions rale in emergency response Emergency situations cannot be anticipated in sufficient detail to relieve necessity of on-the-spot judgements Util has major responsibility for emergency planning.

  HENDRIE, J. M. Commission. 79/11/26, 4pp.
- 7912270062 Responds to 790614 questions re status & future of nuclear power in Mf. NRC has summarized historical & economic data requested. Forwards NUREG-0510 Cover sheet only encl HENDRIE, J. M. Commission 79/10/12. 7pp
- ---7912270077 "NRC SEP." speech for presentation at Oct 1978 meeting of ENS/ANS in Brussels, Belgium.
  EISENHUT, D. G. Division of Operating Reactors 78/10/31. 30pp.
- 7912270000 Notifies that NRC approved proposed agreement w/State of HI whereby RI will assume some regulatory authority over byproduct source & SNM.
  HENDRIE J. M. Commission. 79/12/04. ip.
- 7912270083 Ack receipt of comments to President on TMT. Comments will be circulated among commissioners.
  HENDRIE, J. M. Commission. 79/12/03 2pp.
- --7912270085 "Axelrod Recommendations on Nuclear Power Plant Safety."
  AXELROD, D. M. Axelrod, D. M. 79/11/30. 33op
- 7912270097 Informs of no objection to DDS proposed rept on S.1119 & H.R. 5244 re-procedures for transport & storage of spent fuel in US trust territories HENDRIE J.M. Commission 79/12/07 tp.
- --7912270097 Requests comment on DOS proposed rept on 9 1119 & H.R. 5244 re nuclear spent fuel & trust territories by 791212.
  PETERSON,R K. Office of Management & Budget. 79/11/23. 6pp.
- 7912270102 Notifies of completion of NRC form for training course on C-E simulator Payment forthcoming
  HENDRIE: J. M. Commission. 79/12/04. 1p.
- 7912270107 Responds to 790731 Itr re evacuation distances around TMI-2. Forwards table developed on 790401 giving recommended actions for various contingencies & draft of long-term contingencies. Ten-mile evacuation sufficient. HENDRIE J. M. Commission 79/12/09. 48pp.
- 7912270110 Requests opinion re M Rogovin 791115 suggestion that NRC develop program to alleviate mental stress among residents in TMI area HENDRIE.J.M. Commission. 79/11/30. ip.
- --7912270114 Recommends implementation of program in TMI area to alleviate severe mental stress caused by accident.
  ROGOVIN;M NRC Three Mile Island Task Force. 79/(1/15, 2pp.

- ---7912270117 Ack receipt of 791130 memo re program to alleviate mental stress in TMI area Memo forwarded to Governor of State of PA w/request for comments. HENDRIE.J.M. Commission. 79/11/30. ip.
- 79:2270:22 Notifies of appointment to Screening Committee for Lawyer Vacancies on ASLB for 4-ur term to begin 800:01. HENDRIE.J.M. Commission. 79/11/28. ip.
- --7912270125 Notifies of appointment to Screening Committee for Lawyer Vacancies on ASLB for 4-yr term to begin B00101. HENDRIE.J. M. Commission. 79/11/2B. ip.
- --7912270131 Notifies of appointment to Screening Committee for Lawyer Vacancies on ASLB for 4-yr term to begin 800101. HENDRIE, J. M. Commission. 79/11/28. 1p.
- --7912270135 Notifies of appointment to Screening Committee for Lawyer Vacancies on ASLB for 4-yr term to begin 800101. HENDRIE, J. M. Commission. 79/11/28. 1p.
- --7912270149 Notifies of appointment to Screening Committee for Lawyer Vacancies on ASLB for 4-yr term to begin BOD101. HENDRIE, J. M. Commission. 79/11/28. tp.
- --7912270154 Natifies of appointment to Screening Committee for Lawyer Vacancies on ASLB for 4-yr term to begin 800101. HENDRIE, J. M. Commission. 79/11/28. 1p.
- --7912270158 Notifies of appointment to Screening Committee for Lawyer Vacancies on ASLB for 4-yr term to begin 800101. HENDRIE.J.M. Commission. 79/11/28. 1p.
- --7912270160 Notifies of appointment to Screening Committee for Lawyer Vacancies on ASLO for 4-yr term to begin 800101. HENDRIE, J. M. Commission. 79/11/28. 1p.
- 7912270163 Notifies of completion of paperwork to increase NRC funding for radioactive maths transportation surveillance contract w/Btate of HA.
  HENDRIE, J. M. Commission. 79/11/28. 1p.
- 7912270192 Responds to 790417 ltr re future operation of TMI-2.Unit 2 may be restarted in mid-1983 at earliest.DL for Unit 2 suspended pending amend.
  HENDRIE, J. M. Commission. 79/11/28, 3pp.
- 7912310126 Requests acceleration of Bureau of Drugs policy re administration of thuroid blocking agents to public. NRC is developing recommendations re stockpiling of blocking agents around nuclear power plants. HENDRIE, J. M. Commission. 79/11/21. 1g.

## CONTRACT NRC CONTRACTS AND MODIFICATIONS

- 7912060167 Notification of contract execution. Mod 1 to "Engineering Evaluation & Establishment of Critoria Basis for Regulation of Low Level Waste Burial Sites." Contractor: Univ of AZ. JACOBS.A. Research Contracts Branch. FIN 9-6669. NRC-04-78-270. 79/11/05. ip.
- ---7912060176 Mod 1. extending period of performance to 791031. to
  "Engineering Evaluation & Establishment of Criteria Basis
  for Regulation of Low Level Waste Burial Sites."
  MORTON.K.V. Research Contracts Branch. CARR.S.E. Arizona.
  Univ. of. FIN B-6668. NRC-04-78-270. 79/11/05. 2pp.
- 7912070164 Notification of contract execution, Mod 1 to "Courses in C-E Facility Design & Operation." Contractor: C-E Pauer sys.
  BAISDEN.L. Research Contracts Branch. NRC-05-79-251. 79/11/23.
  1p.
- --7912070169 Mod 1.exercising option & providing funding for second course, to "Courses in C-E Facility Design & Operation." MORTON, K. V. Division of Contracts. NRC-03-79-251. 79/11/23. ip.
- 7912070173 Notification of contract execution. Mod 1 to "Reliability & Probabilistic Assessment Analysis." Contractor: Brookings Inst. 1840ESER, C. M. Purchasing Saction. FIN B-1557. NRC-11-80-401, 79/11/20. 1p.

- --7912070258 Mod i, incorporating contractor travel regulations in lieu of federal regulations to "Reliability & Probablistic Assessment Analysis."
  PERLMAN.J. Division of Contracts. FIN B-1557. NRC-11-80-401. 79/11/20. 2pp.
- 7912070489 Notification of contract execution.Mod 2 to "Radioactive Matl Transportation." Contractor:Univ of Denver. FLYNM. Administrative Contracts Branch. NRC-06-78-361. 79/10/02. 1p.
- --7912070492 Mod 2. extending period of performance at no add1 cost & increasing overhead rate, to "Radipactive Mat1 Transportation."

  MATTIA.M.J. Administrative Contracts Branch. DAVIS, P. L. Denver, Univ. of. NRC-06-78-361. 79/10/02. 1p.
- 7912100087 Notification of contract execution, Mod 2-1 to "Cental VA Regional Spismic Network." Contractor: VA Tech. HAGEYH. Research Contracts Branch. FIN 8-6249. NRC-04-77-134. 79/10/03. 1p.
- --7912100091 Mod 2-1, replacing Mods 1 & 2, to "Central VA Regional Seiseld Network." MORTON, K. V. Research Contracts Branch. KREBS, A. H. Virginia Tech. FIN 8-6249. NRC-04-77-134. 79/10/03. 4pp.
- 7912100097 Notification of contract execution: "Technical Assistance to Support NRC IE Technical Personnel in Investigations & Evaluation of Incidents, Allegations & Reported Discrepancies," awarded to Parameter, Inc. BAISDEN,L. Research Contracts Branch. FIN A-4015. NRC-05-77-184. 79/11/14. ip.
- --7912100105 Contract: "Technical Assistance to Support NRC IE Technical Personnel in Investigations & Evaluation of Incidents. Allegations & Reported Discrepancies." awarded to Parameter, Inc. MORTON. M. V. Research Contracts Branch. LOFY, R. A. Parameter. Inc. FIN A-4015. NRC-05-77-186. 79/11/14. 4pp.
- 7912100116 Notification of contract execution Mod 7 to "Technical Assistance to Support NRC IE Technical Personnel in Investigations & Evaluation of Incidents Allegations & Reported Discregamies." Contractor:Parameter. Inc. BAISDEN.L. Research Contracts Branch. FIN A-4015. NRC-05-77-186. 79/11/02. 1p.
- --7912100125 Mod 7. providing addl funding, to "Technical Assistance to Support NRC IE Technical Personnel in Investigations & Evaluatorion of Incidents, Allagations & Reported Discrepancies."

  MORTON, K. V. Research Contracts Branch. FIN A-4015.
  79/11/02. ip.
- 7912100270 Notification of contract execution: "Reliability & Probablistic Assessment Analysis," awarded to Brookings Inst.
  TRACEBER, C. M. Purchasing Section, FIN B-1557, NRC-11-80-401, 79/11/20, ip.
- --7912100276 Contract: "Reliability & Probablistic Assessment Analysis," awarded to Brookings Inst. PERLMAN.J. Division of Contracts. MITCHELL.C.D. Brookings Institute. FIN B-1597. NRC-11-80-401. 79/11/20. 4pp.
- 79121003B0 Notification of contract execution Mod 2 to "Perform Ad Hoc Special Analyses of Operating Experience Data." Contractor: Bouthwest Research Inst.
  PERLMAN.J. Purchasing Section. FIN 8-1437. NRC-07-78-347.
  79/08/24. ip.
- --7912100383 Mod 2, deobligating balance of funds not used, to "Perform Af Hoc Special Analyses of Operating Experience Data." HAROETTI D. Administrative Contracts Branch. FIN B-1637. NRC-07-78-367. 79/08/24. 1p.
- 7912100GBS Notification of contract execution.Mod 5 to "Environ Surveillance for Measuring Concentrations of Radioactivity & Radiation Lavels in Environ of Commission-Licensed Activities..." Contractror:State of ME. BAISDENL. Research Contracts Branch. FIN 8-5119, NRC-05-76-382, 79/11/30. ip.
- --7912100386 Mod 5, extending performance period & providing add1 funds, to "Environ Surveillance for Measuring Concentrations of Redioactivity & Rediation Levels in Environ of Commission-Licensed Activities Located Within State of ME..."

  HORTON, M. V. Research Contracts Branch. HINCKLEY, W. W. Mains, State of. FIN 8-5113. NRC-05-74-382. 79/11/30. ip.

- 7912100390 Notification of contract execution, Mod 2 to "Memphis Area Regional Beismic Naturk," Contractor: Memphis State Univ. HAGEV.H. Research Contracts Branch. FIN 8-6276. NRC-04-78-200 79/11/30. 1p.
- --7912100374 Mod 2, extending performance period & adding funds, to
  "Memphis Area Regional Beismic Network."
  HORTON, K.V. Research Contracts Branch, JONES, B. H. Memphis
  State Univ. FIN B-6276. NRC-04-78-200. 79/11/30. 4pp.
- 7912100449 Notification of contract execution: "Keystone Peer Review, Morkshop on Waste Mgt Technical Rule," awarded to Keystone Ctr for Continuing Education.
  MCNULTY, A. Purchasing Section. FIN B-6936-O. NRC-02-80-04B, 79710725. ip.
- --7912100452 Contract: "Keystone Peer Review.Workshop on Waste Mgt Technical Rule," awarded to Keystone Ctr for Continuing Education. PERLMAN.J. Division of Contracts. CRAIG.R.W. Keystone Center for Continuing Education. FIN 8-6936-0. NRC-02-80-048. 79/10/25. Jpp.
- 7912:10001 Notification of contract execution. Mod 4 to "Environ Surveillance for Measuring Concentrations of Radioactivity & Radiation Levels in Environ of Commission Licensed Activities..." Contractor: State of SC. BAISDENIL. Research Contracts Branch. 8-5112. NRC-09-77-106. 79/11/30. 1p.
- --7912110002 Mod 4, extending period of performance & providing addl funding, to "Environ Surveillance for Measuring Concentrations of Radioactivity & Radiation Levels in Environ of Commission Licensed Activities..." MORTON.K.V. Division of Contracts. ShiTH.J.W. South Carolina, State of. FIN B-512. NRC-05-77-106. 79/11/30. ip.
- 7912110003 Notification of contract execution, Mod B to "Performance Testing for Personnel Dosimetry," Contractor: Univ of MI. QUSTAVE, R. P. Research Contracts Branch. FIN B-10499. NRC-01-77-180. 79/11/29. 1p.
- --7912110004 Mod 8, extending contract at no cost, to "Performance Testing for Personnel Dosimetry."
  MORTON, K. V. Division of Contracts. STENPLE, P. J. Hichigan, Univ. of. FIN 8-10499. NRC-01-77-180. 79/11/29. 2p.
- 7912110006 Notification of contract execution. Mod 4 to "Environ Burveillance for Measuring Concentrations of Radioactivity & Radiation Levels in Environ of Commission Licensed Activities..." Contractor: State of TN. BAISDEN, L. Research Contracts Branch. FIN B-5208. NRC-05-77-385. 79/11/30, ip.
- --7912110009 Mod 5, extending period of performance & providing addlending, to "Environ Surveillance for Measuring Concentrations of Radioactivity & Radioation Levels in Environ of Commission Licensed Activities..."

  MORTON, K. V. Division of Contracts. FONTINKLE, E. W. Tennessee, State of. FIN 8-5208. NRC-05-77-385. 79/11/30. 1p.
- 7912110013 Notification of contract execution. Mod 5 to "Environ Surveillance for Measuring Concentrations of Radioactivity & Radiation Levels in Environ of Commission Licensed Activities..." Contractor: State of AR. BAISDEN.L. Research Contracts Branch. FIN B-5207. NRC-05-74-379. 79/11/30. ip.
- --7912110019 Mod 5, extending pariod of performance & providing additional funding, to "Environ Surveillance for Measuring Concentrations of Radioactivity & Radiation Levels in Environ of Commission Licensed Activities..."

  HORTON, K. V. Division of Contracts. MENT, O.D. Arkansas, Bists of, FINB-5207. NRC-05-76-379. 79/11/30. ip.
- 7912110028 Notification of contract execution, Mod 4 to "Testing of Reinforced Concrete Containments Under Combined Membrane Tension & Tangential Shear." Contractor: Portland Cement Association.

  HOLLETT. 8. Research Contracts Branch. FIN B-6203.

  NRC-04-77-118. 79/11/28. ip.
- --7912110036 Mod 4, extending period of performance for two months at no cost, to "Testing of Reinforced Concrete Containments Under Combined Membrane Tension & Tangential Shear."
  HORTON, K. V. Division of Contracts. KUNIE.N.E. Portland Cement Association. FIN B-6203. NRC-04-77-118, 79/11/28, 1p.

- 7912110040 Notification of contract execution: "Revise Detailed Definition of Requirements Document Which Was Previously Prepared By Booing Computer Svcs Under NRC-04-77-065..." awarded to Boeing Computer Svcs Co.
  MCNULTY.A. Purchasing Section. NRC-10-80-664. 79/i1/28. ip.
- --7912110048 Contract: "Revise Detailed Definition of Requirements
  Document Which Was Previously Prepared By Boeing Computer
  Svcs Co Under NRC-04-77-065 to Reflect Reduction of
  Modules..." awarded to Boeing Computer Svcs Co.
  PERLMAN.J. Division of Contracts. HOPKINS.H.R. Doeing Computer
  Services, Inc. (subs. of Boeing Co.). NRC-10-80-664. 79/11/28.
  7pp.
- 7912110179 Notification of contract execution.Mod 4 to "Electrostatic Copying Svcs." Contractor:Potomac Research.Inc. HIGGINS.E. Administrative Contracts Branch. NRC-17-77-152. 79/11/29. 1p.
- --7912110185 Mod 4:ravising Article I re svcs & prices:to "Electrostatic Copying Svcs." MATTIA.H.J. Division of Contracts. MDDRE,R.E. Potomac Research. Inc. NRC-17-77-152. 79/11/29. 1p.
- 7912110239 Forwards outlines of tentative work assignments for containment purge control of heavy loads & performance monitor.
  ZECH.0. Division of Operating Reactors. NRC-03-79-118. 79/11/19.
- 7912110529 Notification of contract execution. Mod 2 to "Personnel Neutron Dosimetry for Nuclear Power Plants." Contractor: Rensselaer Polytechnic Inst.
  JACOBS.A. Research Contracts Branch. FIN 8-6651. NRC-04-78-263.
  79/11/16. ip.
- --7912110541 Mod 2.extending period of performance from 790930 to 800229, to "Personnel Neutron Dosimetry for Nuclear Power Plants." MORTON,K.Y. Research Contracts Branch. LODIUDICE.J.M. Rensselaer Polytechnic Inst. FIN 8-6651. NRC-04-78-263. 79/10/24. 2pp.
- 7912120065 Notification of contract execution, Mod 2 to "Environ Surveillance for Measuring Concentrations of Radioactivity & Radioation Levels in Environ of Commission Licensed Activities..." Contractor: State of OR. BAISDEN.L. Research Contracts Branch. FIN B-5200. NRC-05-78-313. 79/11/30. lp.
- --7912120073 Mod 2.extending period of performance to 791231 & changing govt support ceiling, to "Burveillance for Measuring Concentrations of Radioactivity & Radiation Levels in Environ of Commission Licensed Activities..."

  HORTON, K. V. Research Contracts Branch. GEBBIE, K. M. Oregon, State of. FIN B-5200. NRC-08-78-313. 79/10/01. 1p.
- 7912120078 Notification of contract execution.Mod 2 to "Kinetics of Nuclear Waste/Repository Interface Reactions," Contractor: San Jose State Univ Foundation.

  HAGEY.H. Research Contracts Branch. FIN 8-6625. NRC-04-78-258.
  79/11/28. io.
- --7912120086 Mod 2.extending period of performance to 791130 to "Kinetics of Nuclear Waste/Repository Interface Reactions." HORTON, K.V. Research Contracts Branch. Bilt. R.C. San Jose State Univ. FIN B-6428. NRC-04-78-258. 79/10/29. 2pp.
- 7912120261 Notification of contract execution.Mod 7 to "Improved Ultrasonic Nondestructive Testing of Pressure Vessels." Contractor:Univ of MI. JACOBS.A. Research Contracts Branch. FIN A-4047. NRC-04-75-182. 79/11/19. ip.
- --7912120266 Mod 9,deleting J Frederick & inserting Ganapthy,to "Improved Ultrasonic Mondestructive Testing of Pressure Vessels."
  MORTON,K.V. Research Contracts Branch. MATTHEWS,C.W.:
  Michigan, Univ. of. FIN A-4047. NRC-04-75-182. 79/10/27. 2pp.
- 7912120308 Notification of contract execution Mod 5 to "Studies in Two Phases Flow Gas Liquid Interaction in Upflow Sys."
  Contractor:Univ of Houston,
  HAGEY,H. Research Contracts Branch, FIN B-5684, NRC-04-75-194,
  79/11/30, ip.
- --7912120310 Mod S.extending period of performance from 790930 to 791215, to "Studies in Two Phase Flow Gas Liquid Interaction Upflow Sys."

  HORTON, K. V. Research Contracts Branch NORRIS, J. T. Houston, Univ. of FIN 8-5684, NRC-04-75-182, 79/10/01, 2pp.

- 7912140288 Notification of contract execution, Mod I to "DocuMate II Basic Sys." Contractor:Terminal Data Corp. MEDROW.L.A.W. Administrative Contracts Branch. NRC-10-77-176. 79/12/06. 1p
- --7912140294 Mod 1.decreasing obligation & closing contract to "DocuMate #1 Basic Sys."

  MATTIA.M.J Division of Contracts. DEAN.D.P. Terminal Data Corp. NRC-10-77-176. 79/12/06. Ip.
- 7912140297 Notification of contract execution, Mod 3 to "Grievance Review Examiner." Contractor: AH Maller MEDROW, L. A.K. Administrative Contracts Branch. NRC-10-78-585. 79/12/06. 1p
- ~-79[2]40303 Mod 3.decreasing obligation & closing contract, to "Grievance Review Examiner." MATTIA.H.J. Division of Contracts, MALLER.A.H. Affiliation Unknown, NRC-10-78-585, 79/12/06. lp.
- 7912170401 Notification of contract execution.Mod 5 to "Document Distribution." Contractor:Computer Control Corp. MEDROW.L.A.K. Administrative Contracts Branch. NRC-10-77-121. 79/11/30. ip.
- --7712170408 Mod 5.decreasing total amount & completing close-out action for contract to "Document Distribution."

  MATTIA, M.J. Administrative Contracts Branch. PROCTOR, W. G. Affiliation Unknown. NRC-10-77-121. 79/11/20. ip.
- 7912170414 Notification of contract execution Mod 2 to "Determination of Occupational Man-Rem Exposures." Contractor Science Applications, Inc.
  MENCZER.W.R. Technical Assistance Contracts Branch.
  NRC-03-78-161. 79/11/29. ip.
- --7912170420 Mod 2.extending period of performance from 780925 to 800115, to "Determination of Occupational Man-Rem Exposures."

  DUGHERTY, D. J. Technical Assistance Contracts Branch.

  NRC-03-78-161. 79/11/29. 1p.
- 7912180006 Notification of contract execution, Mod & to "Develop Certification Criteria for Industrial Radiographers."
  Contractor Univ of Lowell.
  GUSTAVE.R.P. Research Contracts Branch. FIN B-10276.
  NRC-01-76-337. 79/11/30. jp.
- --7912180011 Mod 6,correcting error in Mod 5.to "Develop Certification Criteria for Industrial Radiographers." MORTON,K.V. Research Contracts Branch. MILLER,E.F. Lowell, Univ. of. FIN 8-10276 NRC-01-76-337. 79/11/30. 2pp.
- 7912180014 Natification of contract execution. Mod 19 to "Downcomer Effects Experimental Program." Contractor: CREARE. Inc. MOLLETT. 6. Research Contracts Branch. FIN A-4070. NRC-04-75-162. 79/11/26 1p
- --7912180019 Mod 19.providing incremental funding for FY80 & specified funds due in FY81.to "Downcomer Effects Experimental Program." ΜΩΕΤΟΝ,Κ. V Research Contracts Branch. HICKIN,R.A. Create, inc. FIN A-4070 NRC-04-75-142. 79/11/28. 3pp.
- 7912180023 Notification of contract execution, Mod 3 to "Specially Designed File Folders " Contractor: Ames Color File. HIGGINS.E Administrative Contracts Branch. NRC-10-79-374. 79/12/07. 1p
- ---7912180026 Mod 3 changing delivery schedule, to "Specially Designed File Folders." MATTIA.H.J. Administrative Contracts Branch. NRC-01-79-374. 7912/07. ip.
- 7912180031 Notification of contract execution.Mod 2 to "Technical Assistance Program for State-of-the-Art Study Concerning Near-Field Earthquake Motion " Contractor: Sys. Science & Software.

  MOLLETTIS. Research Contracts Branch FIN 8-6491.

  NRC-03-78-155. 79/11/01. 1p.
- --7912180037 Mod 2.providing incremental funding to "Technical Assistance Program for State-of-the-Art Study Concerning Near-Field Earthquake Ground Motion." HORTON.K.V. Research Contracts Branch. BLACKMAN.V.H. Bystems, Sciences & Software. FIN 8-6491. NRC-03-78-155. 79/11/01. 1p.
- 7912200031 Notification of contract execution, Mod 1 to "Mobile Lab." Contractor: Mobile Bys. Wilgolbs E. Administrative Contracts Branch. NRC-05-79-257. 79/11/16. 1p.

- --7912200037 Mod legercising option for two addl vehicles,to "Mobile Lab." MATTIA.M.J. Division of Contracts. NRC-05-79-297. 79/11/16. 1p.
- 7912200149 Notification of contract execution, Mod 4 to "Design of IFMIS." Contractors: Small Business Administration & Technassociates, Inc.
  HAGAN, T.F. Administrative Contracts Branch. FIN B-5131.
  79/11/23. 1p.
- --7912200175 Mod 4.changing contract number to FYBO NRC-09-80-395, to "Design of IFHIB."

  MATTIA.M.J. Administrative Contracts Branch. ZENTNER, M. A. Technassociates, Inc. CHISHOLM.J.R. Small Business Administration. FIN D-5131. NRC-09-80-395. 79/11/23. 3pp.
- 7912200177 Notification of contract execution Mod 3 to "Design of IFMIS" Contractor: US Small Business Administration.
  Subcontractor: Technassociates: Inc.
  HAGAN.T.F. Administrative Contracts Branch. FIN 8-5131.
  NRG-09-79-349. 79/11/06. ip.
- ---7912200182 Mod 3.revising period of performance re Article II,to
  "Design of IFM18."
  MATTIA:M.J. Division of Contracts. YTHIER.P. Technassociates.
  Inc. BECHET.L.J. Small Business Administration. FIN 8-5131.
  NRC-09-79-349. 79/11/06. 2pp.
- 7912200179 Notification of contract execution.Mod 5 to "Design of IFMIS." Contractors: Small Business Administration & Technassociates, Inc.
  HAGAN.T.F. Administrative Contracts Branch. FIN B-5131.
  NRC-09-80-395. 79/12/03. ip.
- --7912200183 Mod 5,changing effective date of contract, to "Design of IFMIS." MATTIA,M.J. Administrative Contracts Brench. FIN B-5131. NRC-09-80-395. 79/12/03. ip.
- 791220019D Notification of contract execution: "Publication Distribution Sycs." Contractor:Computer Data Sys. Inc. HAGAN.T.F. Administrative Contracts Branch. NRC-10-80-262. 79/11/27. ip.
- --7912200198 Contract: "Publication Distribution Bycs," awarded to Computer Data Sys. Inc. MATTIA.M. J. Division of Contracts. COMBB.C. Computer Data Gystems, Inc. NRC-10-80-362. 79/11/27. 109pp.
- 7912210382 Notification of contract execution. Mod 1 to "Nuclear Reactor Crisis Mgt Alternatives for Govt Action." Contractor: Nat1 Academy of Public Administration Foundation.
  HAGANIT.F. Administrative Contracts Branch. FIN 8-6792.
  NRC-04-79-210. 79/11/06. 1p.
- --7912210383 Mod I, changing scope of work & extending period of performance to 791231, to "Nuclear Reactor Crisis Mgt Alternatives for Govt Action."

  MATTIA, M. J. Administrative Contracts Branch. WOOD, W. L. National Academy of Public Administration Foundation. FIN 8-4792. NRC-04-79-210. 79/11/06. 2pp.
- 7912210385 Notification of contract execution, Mod 7 to "Keypunch Sycs." Contractor:Federal Prison Industries. HAGAN, T. F. Administrative Contracts Branch. NRC-10-76-334. 79711/06. 1p.
- --7912210387 Mod 7.increasing total estimated cost to "Keypunch Svcs." MATTIA.M.J. Administrative Contracts Branch. \* Federal Prisons Industries. NRC-10-76-334. 79/11/06. 2pp.
- FOIA FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES
- 7902260150 Responds to 790116 FOIA request for nine categories of documents re fire protection at six nuclear plants. Documents forwarded except for one not found & one other already located in PDR.

  FELTON. J. M. Division of Rules and Records. 79/02/09. Ip.
- 7912050466 FOIA request for documents re NRC insps of St Luke's & St Mary's Hosps in Milwaukes WI since Jan 1979.
  VAKERIGS.T.V. O'Connor & Hannan. 79/10/05. 2pp.
- 7712050471 Responds to FOIA request for documents re NRC inses of St Luke's & 8t Mary's Hosps in Milwaukee HI since Jan 1979. Forwards inse repts of 791102 for each facility. CARR.J.C. Division of Rules and Records. 79/11/19. ip.

- --7912050476 IE Insp Rept on 790827~28. No noncompliance noted Major areas inspected organization, training & instructions to employees, radiation protection procedures & leak tests of sources.
  TENCUE, T. M. Region 3, Chicago, Office of the Director.
  79/09/11. 14pp.
- --7912050479 IE Insp Rept on 790827-28. Noncompliance noted: no surveys conducted of incoming byproduct matl since 790618 & no records of transfer maintained for returned byproduct matl. TONGUE, T.M. Region 3, Chicago, Office of the Director. 79/09/11. 32pp.
- 7912050630 FOIA request for UCLA Nuclear Energy Lab Facility License R-71.BAR & application for license Amend 10.
  VOELZKE,D. Committee to Bridge the Gap. 79/10/30. ip.
- 7912050558 Supplements response to FDIA request for documents re radwaste disposal. Forwards two addl documents subject to request: deposition of NRC by JM Hendrie & notice of proposed rulemaking. CARR, J. C. Division of Rules and Records. 79/11/15. ip.
- --7912060559 Deposition by JM Hendris on 790911 in Washington, DC. Pp 1-19. Notice of proposed rulemaking re storage & disposal on nuclear waste encl. HENDRIE. J. M. Commission. 79/09/11. 23pp.
- 79120A0571 Bupplements response to FOIA request for documents re plants operating & under const & libility insurance. Forwards addl documents subject to request: JM Hendrie testimony & notice of proposed rulemaking.

  CARR.J.C. Division of Rules and Records. 79/11/15. 1p.
- 7912070161 Supplements response to FOIA request for correspondence prepared by JH Conran from 1960 to present Portions of "threat list" in PDR. Info partially withheld (ref FOIA Exemption 1).
  FELTON, J. M. Division of Rules and Records. 79/11/16. Ip.
- 7712070165 FOIA request for correspondence prepared by JH Conran from 1960 to present.
  MCCAIN.R. Community Supported Television LA, California. 77/07/26.
- 7912070172 FOIA request for documents re determination of route for shipment of spent nuclear fuel from foreign sources to DDE Savannah River plant Info re legal proceedings of intervention by Portsmouth citizens not sought.

  REYNOLDS.W. American Friends Service Committee. 79/10/20. 1p.
- 7712070181 Submits partial response to FOIA request for documents re shipment of spent nuclear fuel from foreign sources to Savannah River plant Forwards documents listed in app. CARR. J. C. Division of Rules and Records. 79/11/23. 2pp.
- --7912070186 Discusses regulatory afforts to protect spent fuel during transport. Currently examining public comments on regulation & guidance, Also discusses study of potential ports of entry. Forwards 10CFR73 re fuel in transit.

  DIRCKG.W.J. Office of Nuclear Material Bafety & Safeguards.
  79/09/12. 4pp.
- --7912070199 Responds to 790723 ltr re import shipments of spent fuel from foreign research reactors. Has not approved any plan to import spent fuel from research reactors through Savanneh, OA. Owners of, foreign research reactors pay cost. BUANETT.R.F. Commission. 79/08/28. Spp.
- --7912070203 Forwards ltr excerpt re spent fuel shipments & new physical protection rule, w/related guidance document in response to 790823 telcon. Also forwards 10CFR73 re fuel in transit. HCCORMICK, R. G. Division of Bafeguards. 79/08/23. Spp.
- --7912070206 Responds to 790713 ltr requesting that NRC approve no domestic shipping routes for imported spent fuel until local hearings are held Local hearings not appropriate at present. DIRCKG.H.J. Office of Nuclear Material Safety & Safeguards. 79/08/08. 2pp.
- --7912070211 Discusses request for approval of route for imports of irradiated MTR fuel, Approves proposed route on interim basis. Requests analysis of alternatives be submitted to NRC by 790831. Proposed subj. to 100FR2. 790.

  MCCORKLE, O. W. Commission. 79/07/23. 2pp.
- --7912070214 Forwards informal notes describing 790612 meeting in Norfolk, VA re security for spent fuel shipments.
  ERICKSON, R. A. Commission. 79/06/14. 1p.

- --7912070218 Summary of 790612 meeting w/VA Port Authority, Atlantic Container Lines, Portsmouth Terminal. Inc & Transmuclear, Inc in Norfolk, VA re security for spent fuel shipments. ERICKSON.R.A. Commission 79/06/13. Spp.
- 7912070192 Responds to 790716 ltr re imports of spent fuel from foreign reactors. New regulations require that shipment of spent fuel must be routed to avoid keavily populated areas. List of foreign research reactors encl.

  BURNETT.R.F. Division of Safeguards. 79/08/28. 6pp.
- 7912070224 Supplements response to FOIA request for info re Nuclear Matls & Equipment Corp & NRC investigation into previously withheld Executive Director for Oper tions remarks. Info partially withheld (ref FOIA Exemption 1).

  CARR.J. C. Division of Rules and Records. 79/11/16. 1p.
- 7912070229 Responds to FOIA requests for regulations issued pursuant to or implementing FOIA. Confirms 791119 agreement to limit request to 10CFR9. Forwards 10CFR9. W/o encl.

  CARR. J. C. Division of Rules and Records. 79/11/20. 1p.
- 7912070231 FOIA request for regulations issued pursuant to or implementing FOIA.

  8EIVER, J. D. Cole, Raywid & Braverman. 79/11/16. ip.
- 7912070246 FDIA request for five categories of info re NRC organization & records concerning TMI. #IENCUS.L. Affiliation Unknown. 79/11/07. ip.
- 7912070250 Responds to FDIA request for five categories of info re NRC organization & records concerning TMI. Response to first four categories submitted in NRC 791106 ltr. Forwards "Title List of Publicly Available Documents." W/O encl. CARR. J. C. Division of Rules and Records. 79/11/21. 1p.
- 7912070255 FQIA request for info re United Nuclear Corp activities in Pauling, NY.
  DAVIB, C. Affiliation Unknown. 79/10/02. ip.
- 7912070263 Partially responds to FOIA request for document re Pawling, NY site Forwards requested info. Submits addl info: sodium deuterium reactor never built at site, no matl ever used at site & no radioactive matl disposed of in lake.

  CARR, J. C. Division of Rules and Records. 79/11/16. Opp.
- --7912070276 Discusses QA Co 740311 application to delete Pawling, NY as authorized place of use for License SNN-871. Site represents insignificant risk to public, Recummends that license be terminated.

  CROW, W. T. Division of Fuel Cycle & Material Safety. 75/07/14. 686.
- --7912070289 Forwards Itrs sent to NY transmitting analytical results of 780408 soil sampling at Oulf United Nuclear in Pauling,NY.
  Submits tabulation of Pu-238 & Pu-239 results. No objection to termination of Gulf United Nuclear license. H/o sncl.
  DAVIS.J. Q. Office of Inspection & Enforcement, Office of the Director. 75/07/07. 2pp.
- --7912070299 Discusses 740603 notification by Region 1 re suspicion of Pu contamination in concrete Region 1 will investigate.

  Region 1 has requested that Pawling NY site not be deleted from License SNM-871.

  CROM, H. T. Division of Fuel Cycle & Material Safety. 74/06/05.
- --7912070305 Discusses review of data on Pu concentrations in soil samples taken at Pawling.NY site Concentrations do not represent radiation exposure hazard.

  MAGNO.P.J. Commission. 75/06/25. ip.
- --7912070335 Forwards results of analyses performed by IE Health Svcs Lab on soil samples taken at Gulf United Nuclear Pauling, NY site. NY Health Dept 750308 ltr & EPA 750108 ltrs encl. NELBON P. R. Region 1, Philadelphia, Office of the Director. 75/05/06. App.
- ---7912070368 Forwards Insp Rept 70-0903/74-17 on 740905 No nencompliance noted. Hajor areas inspected: following on decontamination of facility.

  NELSON, P. R. Region 1, Philadelphia, Diffice of the Director.

  74/09/26, 9pp.
- --7912070376 Summary of 740729 meeting in Washington.DC re Pu concentrations in soil, in connection w/decommissioning. NRC recommended that ALAP approach be used & each site be treated on case-by-case basis. W/decommissioning description. HAMADA.O. Atomic Energy Commission. 74/08/22. 6pp.

- 7912070280 FOIA request for documents re ATCOR. Inc. Nuclear Development Association. United Nuclear Corp & Gulf United Nuclear Corp. GUTMAN. J. S. Levu, Gutman, Goldberg & Kaplan. 79/09/17. 2pp.
- 7912070284 FDIA request for documents re Nuclear Development Association,United Nuclear Corp &/or Gulf United Nuclear Corp. GUTHAN, J. S. Levy, Gutman, Goldberg & Kaplan. 79/08/30. 1p.
- 7912070291 Submits partial response to FOIA request for documents re Nuclear Development Association, United Nuclear Corp. Gulf United Nuclear Corp & ATCOR. Inc. concerning facility sits. Forwards requested info. Provides addl info re site. CARR. J. C. Division of Rules and Records. 79/11/16. 3pp.
- ---7912070300 Requests deletion of Pawling & Eastview, NY as authorized places of use & that all records re locations be destroyed.

  Also requests that License SNM-871 not be terminated.

  LOYSEN, P. Quif Oil Corp. MRA-74-37. 74/03/11. 3pp.
- --7912070303 "Results of Radiological Burvey." \* ATCOR. 74/03/11. 67pp.
- --7912070316 Forwards add1 results of analyses performed by ID Health Byrs Lab on soil samples taken at site. NELSON.P.R. Region i. Philadelphia. Office of the Director. 75/06/09. 2pp.
- --7912070319 Forwards supporting documentation for conclusion that 2.0 disintegrations/minute of Pu/g of soil is appropriate criteria for use in determining acceptable Pu concentration. STRNISA.F.V. New York, State of, 75/06/20. 13pp.
- --7912070321 Responds to W Kerr 741031 memo listing alternative actions leading to development of Pu soil contamination limits.
  Favors establishment of task force within Natl Conference of Radiation Control Program Directors.
  MATTSON.R. J. Atomic Energy Commission. 74/11/18. 1p.
- --7912070342 Forwards NRC memo requesting guidance re levels of Pu acceptable to AEC for unrestricted areas. Specifically requests determination whether Pu soil levels are low enough & guidance on recommended levels. KUHLMAN.C.W. Atomic Energy Commission. 74/07/17. ip.
- --7912070347 Requests guidance re levels of Pu acceptable to AEG for unrestricted areas.Forwards results of licensee subcontractor & AEC analyses of four soil samples. STOHR, J. P. Atomic Energy Commission. 74/07/10. 7pp.
- --7912070360 Discusses 740808 site visit by GA Co & United Nuclear Corp to examine site, review results of analyses of radioactive matl in soil & to determine course of action for termination of license portion conterning Pawling. MY.
  LUYSEN.P. General Atomic Co. (subs. of Gulf Dil Co.). MRA-74-141.
  74/08/19. 2pp.
- 79121004B0 Supplements response to FDIA request on behalf of CH Dfc of Consumers Counsel for documents re-postponement & delay of inservice date for WH Zimmer Unit i.No add1 documents located subj to request.

  CARR, J. C. Division of Rules and Records. 79/11/21. 1p.
- 7912110086 Supplements response to FOIA request for Task Force of Safeguards Policy documents & recommendations. Forwards requested info. Info partially withheld: statements reupgrading program & internal threat (ref. FOIA exemption 1). CARR.J. C. Division of Rules and Records. NRDC/TBC/79-25. 79/11/28. ip.
- --7912110089 Forwards S Chilk 761223 memo re Commission action on NRC recommendations to upgrade safeguards at existing SSNM fuel cycle facilities. Requests classification of memo as confidential.

  COMBS.T.R. Diffice of Administration. 79/01/14. 2pp.
- --7912110099 Submits decision re Commission action on NRC recommendations to upgrade safeguards at existing SSNM nuclear fuel cycle facilities. Portions of document re upgrading program & internal threat withheld (ref FOIA Exemption 1). CHILM.S. J. Office of the Sucretary of the Commission. 76/12/23.
- 7912120156 FOIA request for NRC records re CL Stone. STONE, C.L. Affiliation Unknown. 79/11/16. ip.

- 7912120160 Responds to FOIA request for all NRC records re CL Stone. No info subj to request in personnel, security or radiation exposure records. Forwards notice listing NRC sys of records. W/o encl. CARR.J.C. Division of Rules and Records. 79/12/04. ip.
- 7912120163 FOIA request for winning technical proposal submitted in response to RFP NMS-79-024, "Vol Reduction Techniques in Low Level Radwaste Mgt." FINDLEY, D. E. Science Applications, Inc. 79/10/03. 1p.
- 7912120166 Responds to FOIA request for winning technical proposal submitted by Teknekron Research. Inc in response to RFP NMB-79-024. Forwards nonproprietary version of requested info.

  CARR. J. C. Division of Rules and Records. 79/11/29. 1p.
- --7912120170 Response to RFP RB-NMB-79-024, "Vol Reduction Techniques in Low Level Radwaste Mgt." Includes technical & business proposal personnel qualification & experience, COHEN, B. Teknekron, Inc. RB-NMB-79-024, 78/11/15, 24pp.
- 791212024B Responds to 790829 ltr re B Romic FOIA request for info about US nuclear power plant accidents from 1949-1979.NRC has responded to B Romic request per FOIA. Forwards NRC responses. ODSSICK.L.V. Office of the Executive Director for Operations. 79/10/02. 1p.
- --7912120279 Forwards B Romic 790822 ltr re FOIA request for info about US nuclear power plant accidents from 1949-1979. Requests comment. CULVER.J.C. Senate. 79/08/29. 2pp.
- 7912120482 FOIA request for License 37-00245-06MD w/amends. REDMORE, G. Pharmaco Nuclear, Inc. 79/11/09. 1p.
- 7912120485 Responds to FDIA request for License 37-00245-06MD w/amends. Forwards requested info. CARR.J.C. Division of Rules and Records. 79/12/03. ip.
- 7912120478 Appeals initial FOIA response re deletions in documents concerning proposed routes for transport of irrediated reactor fuel, NY Dept of Transportation & Nine Mile Point atty 1trs enci.

  AUDIN.L. Affiliation Unknown. 79/10/22. 5pp.
- 7912120501 Responds to appeal of initial FDIA response re deletions in documents concerning routing of spent fuel shipments. Denies appeal. Info withheld (ref FDIA Exemption 4).
  GGSSICK.L.V. Office of the Executive Director for Operations. 79/12/04. 200.
- 7912120538 Responds to FOIA request for IE bulletins & circulars for 1975 & IE info notices for 1975-79. Forwards documents listed in App A. IE circulars not issued in 1975 & IE info notices not issued prior to 1979.

  CARR. J. C. Division of Rules and Records. 79/11/27. 3pp.
- --7912120543 IE Bulletin 75-02, "Defective Radionics Radiographic Exposure Devices & Sources Changers," # Office of Inspection & Enforcement, Office of the Director, 75/02/14. 5pp.
- --7912120544 IE Hulletin 75-07 re emission of corrosive gases into ventilation sys filtered by HEPA filters.
  \* Office of Inspection & Enforcement, Office of the Director, 75/11/26. 2pp.
- ---7912120548 IE Info Notice 79-04, "Degradation of Engineered Safety Fratures."

  # Office of Inspection & Enforcement, Office of the Director. 79/02/16. 6p.
- 7912120958 FOIA request for IE bulletins & circulars for 1975 & info notices for 1975-79. CARFAGNO.B.P. Franklin Institute/Franklin Research Center. 79/10/29. ip.
- 7912130141 FOIA request for technical proposal submitted by Essex Corp for Contract NRC-04-79-209, "Human Factors Evaluation." FINDLEY, D. E. Science Applications, Inc. 79/10/17. ip.
- --7912130146 Responds to FOIA request for winning technical proposal submitted by EGBEX Corp for Contract NRC-04-79-209, "Human Factors Eyalustion," Forwards monproprietary version of requested info W/o encl.

  CARR, J. C. Division of Rules and Records, 79/12/03, ip.

- 7912130301 FDIA request for winning proposal submitted by Teknekron Research. Inc. in response to RFP R8-NRR-80-105, "Util Mgt t Tachnical Resources."

  8ALUJA, J. Viking Energy Corp. 79/10/30. 1p.
- 7912130310 Responds to FOIA request for winning proposal submitted by Teknekron Research, Inc. in response to RFP RS-NRR-80-105. Forwards nonproprietary version of requested info. CARR.J.C. Division of Rules and Records. 79711/30. 1p.
- ---7912130315 Response to RFP RS-NRR-80-105, "Util Mgt & Technical Responses." Submits technical & cost proposal. POWER8.J.A. Teknekron, Inc. RB-NRR-80-105. 79/10/04. 91pp.
- 7912140164 FDIA request for all NRC prepared case histories of all SNM licenses that have or have had strategic quantities of SNM. ROISMAN, A. Z. Natural Resources Defense Council. 77/07/18. 2pp.
- 7912140171 Discussed delay in repsonse to FOIA 79-452 request.
  Dissemination of requested info will be through Nucleonics
  Wh & other McOraw Hill Publications. Lists ways in which
  public health would be enhanced by release of info.
  MARTIN.D.L. McOraw-Hill Publications Co. 79/11/12, 1p.
- 7912140174 Responds to FOIA request for info re closed meetings concerning Ofc of Executive Director for Operations. Tapes will be audited & releasable portions forwarded SECY 79-82 in PDR.NRC authority review withheld (ref FOIA Exemption 5). GARR, J. C. Division of Rules and Records. 79/11/28. 2pp.
- 79:2140181 Supplements response to FOIA request for case histories prepared by NRC for all SNM licensees. Requested info in Hashington: DC PDR. Info partially withheld: safeguards procedures & security measures (ref FOIA Exemption 4). CARR. J. C. Division of Rules and Records. 79/11/28. 3pp.
- 7912140302 Forwards FOIA 79-488 request by FJ Boncher. KEPPLER, J.O. Region 3, Chicago, Diffice of the Director. 79/11/02.
- --7912140307 FOIA request for records re Zion 1 & 2.Cook 1 & 2.Brunswick 1 & 2 & Union Carbide nuclear facility in Yabucoa, Puerto Rico.
  BUNCHER, F. J. Schenk & Buncher. 79/10/29. 2pp.
- 7912140312 Responds to FOIA request for records re Zion 1 & 2.Cook 1 & 2.Brunswick 1 & 2 & Union Carbide nuclear facility in PR. Forwards documents listed in App A.No records exist for Yabucoa.PR facility.DOE rept encl.
  CARR.J.C. Division of Rules and Records. 79/11/30. 9pp.
- --7912140317 "Efficent Waste Disposal & Potential Doses Semiannual Rept. Jan-June 1976." \*\* Carolina Power & Light Co. 9298. 76/08/12. 16pp.
- ---7912140319 "Effluent Waste Disposal & Potential Doses Semiannual Rept, Jul-Dec 1976."

  \* Carolina Power & Light Co. 76/02/08. 17pp.
- --7912140322 "Semiannual Environ & Effluent Release Rept for Jan-June 1977." \* Carolina Power & Light Co. 77/08/31. 20pp.
- --7912140329 "Environ Rept. Jul-Dec 1977."
  \* Carolina Power & Light Co. 78/02/07 19pp.
- --7912140332 "Environ Rept Jan-June 1978." \* Carolina Power & Light Co. 78/08/08. 20pp.
- --7912140337 "Semiannual Environ Rept. Jul-Dec 1978."
  \* Carolina Power & Light Co. 78/12/31. 20pp.
- --7912140346 "Bemiannual Environ Rept, Jan-June 1979."

  \* Carolina Power & Light Co. 79/06/30. 17pp.
- ---7912140349 "Radioactive Effluent Release Rept. Jan-June 1977." \* Indiana & Michigan Power Co. 77/06/30. 17pp.
- --7912140350 "Radioactive Effluent Release Rept.Jul-Dec 1977."

   Indiana & Michigan Power Co. 77/12/31. 16pp.
- ---7912140354 "Radioactive Effluent Release Rapt, Jan-June 1978." \* Indiana & Michigan Power Co. 78/06/30. 14pp.

- --7912140366 "Solid Radwaste Rept, Aug+Oct £976." \* Commonwealth Edison Co. 76/11/30. 3pp.
- --7912140372 "Rept of Radioactive Effluents, 1976."
  \* Commonwealth Edison Co. 76/12/31. 4pp.
- ---7912140376 Forwards "Solid Radwaste Rept, Jan-June 1977," "Rept of Radipactive Effluents, 1977," "Liquid Radwaste Rept Jan-June 1977," "Liquid Effluent Rept. 1977," "Liquid Radwaste Rept, 1977," & "Rept of Radioactive Effluents, 1976." BITEL, J. S. Commonwealth Edison Co. 77/08/24. 1p.
- --7912140379 "Bolid Radwaste Rept, Jan-June 1977." \* Commonwealth Edison Co. 77/08/24. 6pp.
- --79121403B9 "Rept of Radioactive Effluents, 1977."

  \* Commonwealth Edison Co. 77/08/24. App.
- --7912140400 "Liquid Radwaste Rept, Jan-June 1977."

  \* Commonwealth Edison Co. 77/06/30. 9pg.
- --7912140402 "Liquid Effluent Rept.1977."

  \* Commonwealth Edison Co. 77/12/31. 3pp.
- --7912140408 "Liquid Radwaste Rept, Jan-June 1977." \* Commonwealth Edison Co. 77/06/30. App.
- --7912140426 "Rept of Radioactive Effluents, 1976." \* Commonwealth Edison Co. 76/12/31. 1p.
- --7912140431 Forwards "Rept of Radioactive Effluents,1977," "Solid Radwaste Rept.Jul-Dec 1977" & "1977 Rept of Occupational Personnel Radiation Doses." WANDKE.N.E. Commonwealth Edison Co. 78/02/15. 2pp.
- ---7912140435 "Rept of Radicactive Effluents, 1977."
  \* Commonwealth Edison Co. 78/02/15. 9pp.
- --7912140439 "Bolid Radwaste Rept.Jul-Dec 1977." \* Commonwealth Edison Co. 78/02/15. 6pp.
- --7912140446 "1977 Rept of Occupational Personnel Radiation Doses." \* Commonwealth Edison Co. 77/12/31. 1p.
- --79121A0452 Forwards "Rept of Radioactive Effluents 1978," "Liquid Radwaste Rept.Jan-June 1978," "Bolid Radwaste Rept.Jan-June 1978," "Liquid Radwaste Rept.Jan-June, 1978" & "Rept of Radioactive Effluents, 1978." WANDKE, N.E. Commonwealth Edison Co. 78/08/09. 4pp.
- --7912140456 "Rept of Radioactive Effluents,1978." \* Commonwealth Edison Co. 78/08/09. 9pp.
- --7912140460 "Liquid Radwaste Rept, Jan-June 1978." \* Commonwealth Edison Co. 78/08/09. ip.
- ---7912140465 "Solid Radwaste Rept.Jan-June 1978." \* Commonwealth Edison Co. 78/08/09. 8pp.
- --7912140472 "Liquid Radwaste Rept, Jan-June 1978." \* Commonwealth Edison Co. 78/06/30. 12pp.
- --7912140478 "Rept of Radioactive Effluents, 1978." \* Communuealth Edison Co. 78/12/31. App.
- --7912140481 "Liquid Radwaste Rept, Jul-Dec 1978." \* Commonwealth Edison Co. 79/06/30. 9pp.
- ---7912140485 "Rept of Radioactive Effluents, 1978."

  \* Commonwealth Edison Co. 79/06/30. 3pp.
- ---7912140490 "Liquid Radwaste Rept, Sept-Dec 1978." \* Commonwealth Edison Co. 79/06/30. 7pp.
- --7912140494 "Bolid Radwaste Rept.Jul-Dec 1978," \* Commonwealth Edison Co. 79/06/30. Spp.
- --7912140498 "Rept of Radioactive Effluents, 1978." \* Commonwealth Edison Co. 78/12/31. 3pp.

- --7912140500 "Rept of Occupational Personnel Radiation Doses,1970," w Commonwealth Edison Co. 78/42/31. 1p.
- --7912140504 "LER Output on Events Involving Releases From 1969-Present." • Commonwealth Edison Co. 4 Indiana & Michigan Electric Co. e Carolina Power & Light Co. 79/11/20 11pp.
- --7912140508 Forwards "Environ Dose Pathway Study Spring 1977-Fall 1978." GILLION J. R. Commonwealth Edison Co. 78/12/27. ip.
- --7912140513 "Environ Dose Pathway Study-Spring 1977-Fall 1978." \* Commonwealth Edison Co. 78/12/31. 23pp.
- 7912170160 FGIA request for comprehensive evaluation rept of United Nuclear Corp plant in Wood River Junction, RI & of three addl facilities evaluated during \$977 & reported in 771223 weekly info rept.

  COCHRAN, T. B. Natural Resources Defense Council. 78/02/21. 1p.
- 7912170175 Responds to FOIA request for comprehensive evaluation repts of four facilities evaluated during 1977. Rept for Wood River Junction.RI plant in PDR Info partially withheld: safeguard & security procedures (ref FOIA Exemptions 1, 3 & 4).

  CARR.J.C. Division of Rules and Records. 79/11/19. 2pp.
- 791217017B Responds to FDIA request for insp repts of radiologic sites at Univ of Gouthern CA from last two yrs. Has no documents subj to request.

  CARR, J. C. Division of Rules and Hecords. 79/12/06. 1p.
- 7912170181 Responds to FOIA request for records re Tarapur, India, Atomic Power Station & use of atomic energy by India, Document w/ requested info in Washington. DC PDR, Info partially withheld (ref FOIA Exemption 1).

  CARR, J. C. Division of Rules and Records. 79/11/26. 1p.
- 7912170183 FOIA request for insp repts of radiologic sites at Univ of Southern CA from last two yrs. GOLDHAGEN, D. I. Affiliation Unknown. 79/11/15. 1p.
- 7912170187 FOIA request for various info re NRC activities & nuclear power plants, including NRC personnel responsibilities, radiation doses regulatory stds for public protection from radiation & opposition to unsafe nuclear energy.

  GANNIS S. Affiliation Unknown 79/11/18. 1p.
- 7912170191 Responds to FOIA request for various info re NRC activities & nuclear power plants.Forwards documents listed in App A. Remainder of request not stated in FOIA terms.

  CARR.J.C. Division of Rules and Records. 79/12/05. 2pp.
- 7912170197 FOLA request for winning proposal submitted by Personnol Decisions.inc in response to NRC & RFP RS-USD-79-003.
  "Behavioral Observation Program to Assure Continued Reliability of Employees."
  RUTHERFORD.J.F. BDM Corp. BDM/H-JFR-B343- 79/10/26. lp.
- 7912170200 Responds to FOIA request for winning groposal submitted in response to NRC RFP R8-DSD-79-003, "Behavioral Observation Program to Assure Continued Reliability of Employees." Forwards requested info. W/o encl CARR.J. C. Division of Rules and Records. 79/11/21. 1p.
- 7912180336 "Guidelines for Decontamination of Facilities & Equipment Prior to Release for Unrestricted Use or Termination of Licenses for Byproduct, Source or SNM."

  Division of Fuel Cycle & Material Safety. 77/09/15. 6pp.
- 7912170377 FGIA request for info re winning proposal submitted in response to NRC RFP RS-GSD-79-002. "Stds for Psychological Assessment of Security Personnel."
  FLYRN.E. National Evaluation Systems Inc. 79/10/24. 1p.
- 7912170380 Responds to FDIA request for info re winning proposal submitted in response to NRC RFP RS-DSD-79-002. Forwards nonproprietary version of proposal. W/o encl. Also forwards addl info requested.

  CARR. J. C. Division of Rules and Records. 79/11/27. 2pp.
- 7912170386 FOIA reugest for documents containing analysis of proposed siting criteria application to existing sites.
  WEISS.E.R. Sheldon, Harmon & Weiss. 79/11/05. 1p.
- 7912170394 Responds to FDIA request for documents containing analysis of proposed siting criteria application to existing sites. Forwards NRC 790926 memo re NUREO-0625 Recommendation 2, w/ list of plants meeting criteria ACRS transcript in PPR. CARR, J. C. Division of Rules and Records. 79/11/30, ip.

- --7912170379 Lists factors to be considered for interpreting three distance criteria in surveillance of OL & CP sites re hazardous facilities, airports & pipolines. Depending upon interpretation, 10-20% of existing sites would fail criteria. HOUSTON, R. W. Division of Site Safety & Environmental Analysis. 79/09/26. Spp
- 7912170403 FOIA request for six listed reg guides & for placement on NRC distribution list for future reg guides.
  PTAK. J. Iowa Public Interest Research Group. 79/11/19. 1p.
- 7912170409 Responds to FOIA request for six listed reg guides & for placement on NRC distribution list for future reg guides.
  Forwards 790830 reg guide distribution list Name placed on distribution list for future draft reg guides.
  CARR, J. C. Division of Rules and Records. 79/11/30. 1p.
- 7912170412 Bupplements response to FOIA request for correspondence prepared by JH Conram. JH Conram "threat list" in PDR. Info partially withheld (ref FOIA Exemption 1). FELTON.J.M. Division of Rules and Records. 79/11/16. lp.
- 7912180109 FOIA request for records not released to press & Congress re Commission inquiry into Ofc of Inspector & Auditory Ofc of General Counsel rept on Apollo testimony of executive Director for Operations. KRANISH.A. Trends Publishing.Inc. 78/03/02. Ip.
- 7912180116 Supplements response to FOIA request for info re Oft of Inspector & Auditor/Oft of General Counsel rept on Apollo testimony. Forwards documents listed in App A. Portions of documents in App B withheld (ref FOIA Exemptions 1.3.6 & 7). CARR. J. C. Division of Rules and Records. 79/12/10. App.
- 7912180123 FOIA request for drafts of NUREO/CR-0570.NUREO/CR-0672. NUREO/CR-0130.NUREO-0584 & NUREO-0584.w/respective additions & comments. PTAK.J. Iowa Public Interest Research Group. 79/11/16. 1p.
- 7912180131 Responds to FOIA request for five NUREG repts w/additions & comments. Forwards NUREG-0584 & comments. NUREG/CR-0130 addendum available at NTIB & NRC. NUREG/CR-0570, NUREG CR-0672 & NUREG-0586 not yet published. W/o encl. CARR. J. C. Division of Rulas and Records. 79/12/06. 1c.
- 7912180147 FOIA request for info re higher fuel burnups in commercial LWRs (particularly Zion & Quad Cities) from 1975 to present. QUIGG.C. Pollution Environmental Problems. 79/11/28. 1p.
- --7912180156 NEDO-21660
  "Experience W/BMR Fuel Through Dec 1976."
  ELKINS.R.B., DAVIES.J.H., HOLTZCLAW.K.H. General Electric Co. 77NED120. 77/07/31. 10pp.
- 7912180151 Responds to FOIA request for info re higher fuel burnups in commercial LWRs. Forwards documents listed in App A. Addl info can be found in proceedings of 790427 & 0503 ANS topical meeting in Portland. OR published by ANS.

  CARR. J. C. Division of Rules and Records. 79/12/06. 2pp.
- 7912180255 FDIA request for index of Civil Svc employees in federal agencies. Public Law 93-579 encl.
  CAVAZDS.E.C. Lincoln National Life Insurance Co. 79/11/07. 2pp.
- 7912180263 Responds to FOIA request for index of NRC employees. Forwarded organizational computer listing of positions as of 790831.W/o encl. CARR.J.C. Division of Rules and Records. 79/11/26. 1p.
- 7912180265 Appeals response to FOIA request for Ofc of Inspector & Auditor rept on Apollo testimony.
  COCHRAN.T.B. Natural Resources Defense Council. 78/02/28. 1p.
- 7912180277 Responds to appeal of initial FOIA decision re request for info concerning Ofc of Inspector & Auditor on Apollo testimony. Forwards documents listed in App A. Info partially withheld (ref FOIA Exemptions 1,3.6 & 7).

  CARR. J. C. Division of Rules and Records. 79/12/10. 4pp.
- 7912180282 Responds to FOIA request for info re winning proposal submitted by Franklin Research Inst.in response to RFP RB-NRR-79-118. Forwards requested info. Info partially withheld: NRC advice opinions & recommendations(ref FOIA Exemption 5). CARR, J. C. Division of Rules and Records. 79/11/28. 2pp.
- 7912180288 FOIA request for info re winning proposal submitted by Franklin Research Inst.in response to RFP RS-NRR-79-118, "Review & Evaluation of Approximately 500 Pending Operator Reactor Licensing Actions."

  MONROE. Q. E. PRC Energy Analysis Co. 79/09/26. 1p.

- 7912180302 Responds to FOIA request for SNM license issued to Atumics Intl for Canoga Park.CA & Santa Susana.CA facilities. Forwards request info. CARR.J.C. Division of Rules and Records. 79/12/10. lp.
- --7912180325 License SNM-21 for Atomics Intl.authorizing use of U enriched in U-235.U-233 & Pu.for use per 750627 application & 770201,0413,0616 & OB12 application supple.Forwards Licensing Management Branch, 77/09/15, 15pp.
- 7912180369 Supplements response to AZ Roisman FOIA request for documents re NUREO-0459 & preparation of upgraded physical protection regulations in 10CFR73. Forwards list of NRC documents & govt repts. Remaining list classified. CARR<sub>t</sub>J. C. Division of Rules and Records. 79/12/11. 17pp.
- 79:2:80374 Appeals initial decision re FOIA request for documents concerning route determination of spent nuclear fuel from foreign sources to DOE Savannah River plant.

  BOUGHERTY, J. B. Dougherty, J. B. 79/11/15. p.
- --7912180382 Responds to appeal of initial decision re FOIA request for documents concerning route determination of spent nuclear fuel from foreign sources to DDE Bavannah River plant. Documents provided 791123. No further action required. CARR. J. C. Division of Rules and Records. 79/11/28, ip.
- 7912180380 Supplements response to AZ Reisman FOIA request for decuments & communications re TMI-2.Lists documents subj to request. Decuments withheld (ref FOIA Exemption 4). Will consider direct request for purchase of documents. CARR.J.C. Division of Rules and Records. 79/12/11. 2pp.
- 7912180393 FOIA request for correspondence between NRC & Appalachian Power Co or American Electric Power Co re possible nuclear facilities in VA & WV in next 15 yrs.

  MCMAHAN. J. Affiliation Uninown. 79/11/20. ip.
- 7912180409 Responds to FOIA request for correspondence between NRC & Appalachian Power Co or American Electric Power Co repossible nuclear facilities in VA & WV in next 15 yrs. Previous FOIA 77-271 response forwarded requested info. CARR.J.C. Division of Rules and Records. 79/12/13. 1p.
- 7912180646 FOIA request for changes made to NRC IE Manual from Change Notice 78-35 to present. JOHNSON, J. M. Carolina Power & Light Co. 00A-79-223. 79/10/17. 1p.
- 791218064B Responds to FOIA request for changes made to IE Manual, from Change Notice 78-35 to present.Forwards releasable portions of requested info.

  CARR, J. C. Division of Rules and Records. 79/12/04. 1g.
- --7912180649 IE Change Notice 78-33 re insp procedures. \* Office of Inspection & Enforcement, Office of the Director. 78/16/04. 17pp.
- ---7912180651 IE Change Notice 78-36 implementing Temporary Instruction 2915/16. "IE Fire Protection Reviews Program Plan." \*\* Office of Inspection & Enforcement, Office of the Director. 78/10/12. 29pp.
- --7912180453 IE Change Notice 78-37 implementing Temporary Instruction 2315/15, "Bpent Fuel Racks Insp Requirements," # Defice of Inspection & Enforcement, Office of the Director. 78/10/24. 9pp.
- --7912180A55 IE Change Notice 78-38, revising instructions re-manpawar sus. \* Office of Inspection & Enforcement, Office of the Director. 78/10/27. 48pp.
- --7912180A58 IE Change Notice 78-39, including instructions w/guidance on 10GFR20. Also includes procedure re independent measurements of teletherapy unit radiation output.

  \* Office of Inspection & Enforcement, Office of the Director. 787208. 78/11/01. 17pp.
- --7912180659 IE Change Notice 78-40, re IE positions & personnel. \* Office of Inspection & Enforcement, Office of the Director. 78/11/15. 11pp.
- --7912180663 IE Change Notice 78-41, implementing Temporary Instruction 2800/1. "Survey-Questionnaire Program for Priority 6 & 7 Licensees."

  \* Office of Inspection & Enforcement, Office of the Director, 78/11/24. 9pp.

- --7912180664 IE Change Notice 78-42.re distribution of IE repts, annual operating plan & temporary reduction in operations inspection.

  \* Office of Inspection & Enforcement. Office of the Director. 78/11/27. 18pp.
- --7912180666 IE Change Notice 79-08, implementing Temporary Instruction 2595/02. "Insp Requirements to Review B&W Licensee Actions Taken in Response to 1E Bulletin 79-05 & 79-05A." \* Office of Inspection & Enforcement. Office of the Director. 79/04/09. 10pp.
- --7912180667 IE Change Notice 78-43, including Temporary Instruction 2015/18. "Insp Programs During Periods of Long-Term Shutdown," which provides modified requirements for insp of operating reactors.

  \* Office of Inspection & Enforcement. Office of the Director. 78/12/28. 9pp.
- --7912180669 IE Change Notice 79-09, including revision of Chapter 0525, "Action Item Tracking Sys." # Office of Inspection & Enforcement, Office of the Director. 79/06/04. 20pp.
- --7912180671 IE Change Notice 79-10, implementing Chapter 1006, "Safeguards Insp Repts." \* Office of Inspection & Enforcement, Office of the Director. 79/06/11, 20pp.
- --7912180672 IE Change Notice 78-44,re use of medical consultants.

  \* Office of Inspection & Enforcement, Office of the Director.
  78/12/29. 19pp.
- --79121B0674 IE Change Notice 79-11, re verification of licensee actions required by IE Bulletin 79-0B.

  \* Office of Inspection & Enforcement, Office of the Director. IEB-79-0B. 79/06/25. 50sp.
- --7912180676 IE Change Notice 79-12, testing & operations phase of insp program for LURS.

  \* Office of Inspection & Enforcement, Office of the Director, 79/07/01, EOpp.
- --7912180677 IE Change Notice 78-45, modifying frequencies of insp in 814XX series. \* Office of Inspection & Enforcement, Office of the Director. 814208. 78/12/29. 14pp.
- --7912180678 IE Change Notice 79-13, re establishment of new general inspares 6400, "Fire Protection/Prevention," & issuance of Procedure 640538.

  \* Office of Inspection & Enforcement, Office of the Director. 79/07/01. Sopp.
- --7912180579 IE Change Notice 78-45, re fuel facility resident inspector program.

  \* Office of Inspection & Enforcement, Office of the Director.
  85204C. 78/12/29. 100pp.
- -7912180681 IE Change Notice 79-14, implementing Procedure 757208 for inspecting field site radiography & including revisions to Procedures 838908 which clarify requirements for submission of final insprepts. Diffice of Inspection & Enforcement, Office of the Director. 79/07/01. 40pp.
- --7912180682 IE Change Notice 78-47, re operations phase of fuel facility insp program. \* Office of Inspection & Enforcement, Office of the Director. 78/12/27. Sopp.
- --79121806B3 1E Change Notice 79-15, adding Chapters 1220, 1230, 1240 & 1450 re agreement states.

  \* Office of Inspection & Enforcement, Office of the Director. 79/07/01. 20pp.
- --7912180684 IE Change Notice 79-16, re IE investigation program.

  \* Office of Inspection & Enforcement, Office of the Director.
  79/07/01. 20pp.
- --7912180685 IE Change Notice 78-48, re various insp program procedures in Chapters 2513,2515 & 2525. \* Office of Inspection & Enforcement, Office of the Director. 78/12/29. 300pp.
- --79121806B7 IE Change Notice 78-49 re insp of welding at power reactors values to change notice 78-44, re insp of welding at power res under const. \* Office of Inspection & Enforcement, Office of the Director. 78/12/29, 50pp.

- --7912180688 IE Change Notice 79-17, re matl centrol & accounting, insps of SNN in transit & import-export licenses & fuel cycle facilty safeguards insps.

   Diffice of Inspection & Enforcement, Diffice of the Director, 79/09/13. 30pp.
- --7912180689 IE Change Notice 79-02, re physical security at power & research reactors.

  \* Office of Inspection & Enforcement, Office of the Director.
  79/02/01. 50pp.
- --7912180690 IE Change Notice 79-21, re safeguards program. \* Office of Inspection & Enforcement, Office of the Director. 79/11/01. 20pp.
- --7912180691 IE Manual Change Notice 78-50, re operating phase of resident insp program for power reactors.

  \* Office of Inspection & Enforcement, Office of the Director. 78/12/29. App.
- --7912180693 IE Change Notice 79-03, revising table of contents which list currently effective instructions, as of 790101.

   Office of Inspection & Enforcement, Office of the Director, 79/03/01. 40pp.
- --7912180694 IE Change Notice 79-18 re insp requirements for licenses followups to IE Bulletins.

  \* Office of Inspection & Enforcement, Office of the Director.
  79/09/14. 20pp.
- --7912180495 IE Change Notice 79-22,re preoperational test & operating phase for power reactors.

  \* Office of Inspection & Enforcement, Office of the Director.
  79/11/01. 20pp.
- ---7912180696 IE Change Notice 79-04, re insp of welding & nondestructive examination of welds during const phase.
  \* Office of Inspection & Enforcement, Office of the Director.
  79/04/02. 40pp.
- ~~7912180697 IE Change Notice 79-01.re preservice & inservice insps.

  \* Dffice of Inspection & Enforcement, Office of the Director.
  79/02/01. 24pp.
- --7912180498 IE Change Notice 79-23, re periodic status repts.

  \* Office of Inspection & Enforcement, Office of the Director.
  79/11/15. 20pp.
- --79121B0699 IE Change Notice 79-05, revising operation phase of insp program for LWRs. \* Office of Inspection & Enforcement, Office of the Director. 79/04/02. 100pp.
- --7912180701 IE Change Notice 79-19, implementing Temporary Instruction 1016/1, "Gafequards Analysis of Noncompliance," # Office of Inspection & Enforcement, Office of the Director, 79/11/01. 20pp.
- --7912180702 IE Change Notice 79-20, re IE investigation program & IE review of responses to IE Bulletin 79-19.

  \* Office of Inspection & Enforcement, Office of the Director. IEB-79-19. 79/11/01. 30pp.
- --7912180703 IE Change Notice 79-06, deleting Procedures 907108 & 908268 & retaining Procedures 927008 & 907128 to fuel cycle & matls programs & revising Procedure 847108 re solid waste processing & disposal.

  \* Diffice of Inspection & Enforcement, Office of the Director. 79/04/02. 40pp.
- --7912180704 IE Change Notice Notice 79-07. Implementing Temporary Instruction 2575/01. "Insp Requirements to Review B&W Licenses Actions Taken in Response to IE Bulletin 79-05." \* Office of Inspection & Enforcement, Office of the Director. IEB-79-05. 79/04/02. 1p.
- 79121900B1 FOIA request for three categories of documents re Quad-Cities Units 1 & 2. RDMIC.B. Affiliation Unknown. 79/11/04. 2pp.
- 79:2190096 Responds to FOIA request for documents re Quad-Cities Units 1 & 2. Forwards documents listed in App A. Bomm records not located. Remaining documents in FDR & LFDR. No documents subj to second part of request.

  CARR. J. C. Division of Rules and Records. 79/12/05. 4pp.
- --7912190106 Excerpts of "Bemiannual Rept. Jul-Dec 1971, Section II: Radwaste & Environ Monitoring." \* Commonwealth Edison Co. 71/12/31. 11pp.

- ---7912190112 Excerpts of "Radwaste & Environ Monitoring Bemiannual Rept. Jan-June 1972." \* Industrial Bio-Test Laboratories.Inc. W1607. 72/06/30. 14pp.
- --7912170115 Excerpts of "Radwasts & Environ Monitoring, Jan-June 1973." \* Commonwealth Edison Co. 73/06/30. 11pp.
- --7912190117 Excerpts of "Radwaste & Environ Monitoring, Jul-Dec 1973." \* Commonwealth Edison Co. 74/02/28. 10pp.
- --7912190122 Excerpts from "Radwaste & Environ Monitoring, Jan-June 1974." \* Commonwealth Edison Co. 74/08/31. Bpp.
- --7912190126 Excerpts from "Radwaste Environ Monitoring & Occupational Personnel Radiation Exposure Jul-Dec 1974." \* Commonwealth Edison Co. 75/02/28. 8pp.
- --7912190128 Excerpts from "Radweste,Environ Monitoring & Occupational Personnel Radiation Exposure, Jan-June 1975." • Commonwealth Edison Co. 75/06/30. 11pp.
- --7912190135 Excerpts from "Radwaste, Environ Monitoring & Occupational Personnel Radiation Exposure, Jul-Dac 1975." \* Commonwealth Edison Co. 76/02/29. 2ipp.
- --7912170139 Excerpts from "Radwaste, Environ Monitoring & Occupational Personnel Radiation Exposure, Jan-June 1976."
  « Commonwealth Edison Co. 76/06/30. 16pp.
- ---7912190145 Excerpts from "Radwaste Environ Monitoring & Occupational Personnel Radiation Exposure Jul-Dec 1976."

  \* Commonwealth Edison Co. 77/02/28. 19pp.
- --7912190152 Excerpts from "Radwaste Environ Monitoring & Occupational Personnel Radiation Exposure Jan-June 1977." \* Commonwealth Edison Co. 77/06/30. 15pp.
- --7912190159 Excerpts from "Radwasts & Environ Monitoring 1977 Annual Rept."

  \* Commonwealth Edison Co. 77/12/31. 24pp.
- --7912190166 Excerpts from "Annual Rept 1976." \* Commission. 76/12/31. 3pp.
- --7912190171 Forwards notice of violation & 75082B notice of proposed imposition of civil penalties, resulting from 750522-23 & 0721-23 insps.
  KNUTH, D. F. Region 3, Chicago, Office of the Director. 75/08/28.
  3pp.
- --7912190179 Notice of violation from insp on 750522-23. Noncompliance noted: linear heat generation rate exceeded max allowable on 750521 & 22, procedures not prepared for all normal startup activities & instructions not recorded. KNUTH.D.F. Region 3, Chicago, Office of the Director. 75/08/23.
- --7912190183 Notice of proposed imposition of civil penalties from insp on 750822-23. KNUTH.D.F. Office of Inspection & Enforcement, Office of the Director. 75/08/28. 3pp.
- --7912190190 Forwards responses to NRC 750828 ltr requesting info re mgt steps to improve compliance in two major areas of violation. Program initiated to improve analysis of equipment failures. Reply to App A withheld (ref 100FR2, 790). LEE,B. Commonwealth Edison Co. 75/10/06. App.
- --7912190194 Forwards fee in payment of civil penalty issued in NRC 750828 itr. ABRELL, G. A. Commonwealth Edison Co. 75/10/08. 1p.
- --7912190201 Ack receipt of 751008 ltr & fee for full payment of civil penalties issued in NRC 750828 ltr.
  KNUTH D.F. Office of Inspection & Enforcement, Office of the Director. 75/11/07. 2pp.
- 7912190175 FDIA request for repts of radiation exposure to personnel filed by Con Ed of NY & Power Authority of NY under 10CFR20. 405 &/or as required elsewhere.

  JAFFE.S. Village Voice. 79/11/13. 1p.
- 7912190187 Responds to FOIA request for rapts of radiation exposure to personnel filed by Con ED of NY & Power Authority of NY under 10CFR20. 405 &/or as required slaswhere. Forwards documents listed in App A. CARR. J. C. Division of Rules and Records. 79/12/07. 3pp.

### NONDOCKETED ITEMS

- --7912190196 Discusses investigations of recorded exposure discrepancies, conducted by util & NRC on 780413 at Indian Point 2.Film badges found anomalous. Film badge readings for individuals involved will be recorded representing exposures received. ZARAKAB.P. Consolidated Edison Go. of New York. 78/08/08. lp.
- --7912170204 Bubmits addl info re discrepancy between exposure recorded on film badge & that of self-reading pocket dosimeter at Indian Point 2. Whole body exposure of individuals most accurately reflected by self-reading pocket dosimeters.

  CAHILL. W. J. Consolidated Edison Co. of New York. 78/05/12. 4pp.
- --7912190214 IE Insp Repts 50-003/78-09 & 50-247/78-25 on 780711-14. Nancompliance noted:failure to adhere to limits specified in certificate of compliance to ship radioactive matls consistent w/10GFR71.3.
  WHITE:J.R., YUHAS.O.P. Region 1, Philadelphia, Office of the Director. 50-247/78-25. 78/08/07. 15pp.
- --7912190222 Ack receipt of 760429 ltr w/encl.reporting exposure of individual to radiation at Indian Point Unit 2. Findings of insp conducted 760406-09 will be discussed in separate correspondence.
  THOMPSON D. Office of Inspection & Enforcement, Office of the Director. 76/05/25, ip.
- --7912190226 Bubmits rept describing exceeded whole body exposure limits. Corrective actions: access hatch locked warning sign posted at entrance, thimbies partially reinserted & design re-evaluated.

  CAMILL. M. J. Consolidated Edison Co. of New York. 76/04/29. App.
- --79;2190236 Notifies of personnel radiation exposure of 10 rem on 760405. Access entrances to reactor pit area secured & will require watch foreman permission & direct health physics survey before entering.

  CANILL, H. J. Consolidated Edison Co. of New York. 76/04/06. 1p.
- ---7912190242 Bubmits rept describing unexplainable film badge reading.
  Exposed individual & supervisor interviewed. Resurveys of work areas performed. Dosimeter readings determined representative of exposure.

  GAHILL, H. J. Consolidated Edison Co. of New York. 75/11/14. 4pp.
- --7912170247 WASH-1350 R6
  "Sixth Annual Rept of Operation of US AEC Centralized Ionizing Radiation Exposure Records & Repts Sys."

  4 Atomic Energy Commission. 74/09/30. 23pp.
- ---7912190249 "Bemiannual Operating Rept for Indian Point Units 1 & 2, Jul-Dec 1974."

  \* Consolidated Edison Co. of New York. 74/12/31. 12pp.
- --7912190253 Forwards supplemental radiation exposure info for Indian Point Units 1 & 2 for CY73, in response to NRC 740220 ltr which includes tabulation of man-rem exposure vs duty function.

  CANSUL, N. J. Consolidated Edison Co. of New York. 74/04/15. App.
- ---7912190257 Ack receipt of 740214 ltr w/encls, reporting exposure of individual to radiation at Indian Point Unit 1 during fourth quarter, 1978, Forwards 1tr.
  DAVIB.J.O. Atomic Energy Commission. 74/03/08. ip.
- --79121902B4 Submits rept describing incident at Indian Point Unit 1 in which whole body exposure limits were exceeded.

  Administrative controls will be changed to restrict entry into high radiation areas of all personnel.

  CAMILL, M. J. Consolidated Edison Co. of New York. 74/02/14. 3pp.
- ---7912190289 Ack receipt of 731213 & 18 ltrs reporting exposure of personnel to radiation at Indian Point Unit 1. Ltr dtd 731218 not encl. Forwards ltr. DAVIG.J. 0. Atomic Energy Commission. 74/01/22. ip.
- ---7912190295 Submits rept describing instance in which whole body exposure limits were exceeded at Indian Point Unit 1. Desimeter & film badge indicated reading discrepancy Cause Unknown, Whole body exposure readings table encl. CAHILL, W. J. Consolidated Edison Co. of New York, 73/12/13. 3pp.
- --7912190301 Ack receipt of 731123 ltr w/encl.reporting high file badge reading for individual during third quarter, 1973 at Indian Point Unit 1. Forwards ltr. DAVIS, J. Q. Atomic Energy Commission, 73/12/05. 1p.
- -- 79:2:90308 Submits rept describing instance in which limit for whole body exposure was exceeded at Indian Point Unit 1. Dosimeter & film badge indicated reading discrepancies. Forwards table listing whole body gamma exposure.

  NEWMAN.C.L. Consolidated Edison Co. of New York, 73/11/23, 2pp.

- --7912190313 Ack receipt of 730914 ltr.reporting exposure of two individuals to radiation at Indian Point Unit 1. Forwards 1tr. DAVIS, J. O. Atomic Energy Commission. 73/09/24. Ip.
- --7912190318 Submits rept describing instances in which whole body expasure was exceeded at Indian Point Unit 1. Efforts being reinforced re observing personnel in abnormally high radiation areas. Forwards table indicating readings.
  ZARAKAS.P. Consolidated Edison Co. of New York. 73/09/14. 4pp.
- --7912190323 Ack receipt of 730618 ltr u/encls, reporting exposure of individual to radioactive matl at Indian Point Unit 1. Forwards ltr. DAVIS.J.O. Atomic Energy Commission. 73/07/30. lp.
- --7912190332 Eubmits rept re individual exposure indicated by film badge processor for Apr 1973 at Indian Point Unit 1. Total film exposure not indicative of individual actual exposure. Individual received exposure indicated by dosimeter. ZARAKAB, P. Consolidated Edison Co. of New York. 73/06/18. 4pp.
- --7912190338 Ack receipt of 730517 ltr w/encl, reporting exposure of individual to radioactive mati during first quarter 1973 at Indian Point Unit 1. Forwards 1tr. KNUTH.D.F. Atomic Energy Commission. 73/06/08. lp.
- --7912190347 Bubmits rept describing incident involving nonconformance re limits of individual whole body exposure at Indian Point Unit 1. Bosimeter readings inadvertently not transcribed to tally book Methods of transposition revised. CALDMELL: M. E. Consolidated Edison Co. of New York. 73/05/17.
- --7912190351 Act receipt of 730416 ltr reporting individual high film badge reading at Indian Point Unit 1.Forwards ltr. KNUTH.D.F. Atomic Energy Commission. 73/05/09, 1p.
- ~-7912190357 Submits rept re individual exposure at Indian Point Unit 1 during first quarter 1973. Discrepancy indicated between film badge & dosimeter readings. Another individual inadvertently wore badge of exposed individual.

  ZARAKAB,P. Consolidated Edison Co. of New York, 73/04/16. 3pp.
- --7912190360 Act receipt of 721122 ltr reporting exposure of individual to radiation at Indian Point Unit 1. Forwards ltr.
  KRUEBI.F.E. Atomic Energy Commission. 72/12/04. 1p.
- --7912190367 Submits rept indicating radiation exposure exceeding whole body exposure limits Individual age not specifically identified & precautions not taken accordingly Program of exposure systuation reinforced.

  CALDHELL, N. E. Consolidated Edison Co. of New York. 72/12/22.
- --7912190373 Act receipt of 6604i9 ltr reporting exposure of three individuals to eirborne concentrations of radioactive matl at Indian Point Unit 1. PRICE, E. N. Atomic Energy Commission. 66/03/04. 1p.
- --7912190382 Submits rept re 660125 incident at Indian Point Unit 1 concerning overexposure of three individuals. Air sampling 6ata indicated body burdens were higher than predicted measured dust concentration. MCCORMACK, J. E. Consolidated Edison Co. of New York. 66/04/19. Bao.
- 7912190406 FOIA request for info re rules, regulations & stds, in effect 1987-77, governing safety of underground U miners & info concerning exposure of Navajo U miners to radon daughters in Kern-Hügee mining operations in Cove. AZ from 1987-65.
  WEZELMAN.J.A. Miller, Pitt & Feldman, P.C. 79/11/28. ip.
- 7912190410 Responds to FOIA request for info re 1957-77 regulations & stds governing safety of underground U miners & info concerning exposure of Navajo miners to radon daughters in Cove. AZ. 1997-65. No documents subj to request. CARR, J. C. Division of Rules and Records. 79/12/11. 1p.
- 7912190415 FDIA request for proposal & request for proposal for Contract NRC-07-79-312. "Statistical Review & Methodology Development Automated Sciences Oroup." HERRILLI. M. Kinetic Research, Inc. NRC-07-79-312. 79/10/18.
- 7912190422 Resents to FOIA request for winning technical proposal & request for proposal for Contract NRC-07-79-312 Forwards nonpropristary version of proposal & add1 requested info. CARR.J.C. Division of Rules and Records. NRC-07-79-312. 79/11/30. 1p.

- --7912190428 Concurs w/790919 discussed changes to RFP RS-MPA-79-312 & proposal contract will be time & matl type rather than straight labor hour & matl & travel for base yr estimated at \$1,000 & \$100.respectively

  DENGIT.H Automated Sciences Group. Inc. 79/09/24. 2pp.
- -7912190436 "Technical Proposal to Provide Statistical Review & Methodology Development Svcs," in response to RFP RS-MPA-79-312.
  - Automated Sciences Group, Inc. ASG TP 79-21. 79/09/19. 17pp.
- --7912190448 "Business Proposal to Provide Statistical Review & Hethodology Development Svcs," in response to RFP RB-MPA-79-312 Discusses negotiated rates, travel policy & mgt/staffing aspects.

  \* Automated Sciences Group, Inc. ASG BP 79-21, 79/09/19, 18pp.
- --7912190453 Solicitation RS-MPA-79-312 for statistical review & methodology development sycs. GTLDENHORN.A.J. Division of Contracts, 79/09/11. 88pp.
- 7912190458 FOIA request for documents re export of sensitive technology that could be used to develop nuclear weapons. Fee waiver request encl.

  MEYER,R. Nation Institute. 79/10/25. 5pp.
- 7912190467 Responds to FOIA request for documents we export of sensitive technology that could be used to develop nuclear weapons. Request is too broad. Does not meet requirements of SUSC 552(a)(3). Also suggests contacting DOE. CARR. J. C. Division of Rules and Records. 79/12/13. 2pp.
- 7912210394 Responds to FOIA request for nonexempt portion of NRC Investigation Rept 078-154-A, Part 2. Forwards requested document. Division of Rules and Records. 79/12/19. Ip.
- --7908010163 IE Investigation 078-154-A Part 2 on 781114 & 790401. Major areas inspected: source of U matl found in Norton MA landfill based on J Sullivan allegations that TX Instruments had discarded radioactive matl in private landfill in Norton. MARTIN, W. G. Region 1. Philadelphia. Safeguards Branch. ALLAN, J. M. Region 1. Philadelphia. Office of the Director. 79/10/07 2900. ALLAN, J. M. R 79/06/07. 29pp
- 7912210394 FOIA request for nonexempt portion of NRC Investigation Rept 078-154-A.Part 2. SULLIVAN.J.W. Affiliation Unknown. 79/11/14. 2pp.
- 7912210399 FDIA request for citations for violations of law or regulation governing activities of Union Carbide Corp & TVA under specific source matl licenses possessed for mining or milling. REID.A.B. Affiliation Unknown. 79/11/28. Sp.
- 7912210402 Responds to FOIA request re citations for violations of law or regulation governing activities of Union Carbide Corp & TVA under specific source matl licenses possessed for mining or milling forwards documents listed in App A. GARR.J.C. Division of Rules and Records. 79/12/13. 2pp.
- --7912210405 Forwards notice of violation re insp conducted 750219 BROWN,O.D. Region 4: Dallas, Office of the Director. 75/02
- --7912210407 Notice of violation from insp on 750219. \* Region 4, Dallas, Office of the Director. 75/02/28. 1p.
- -7912210409 IE Insp Findings & Licensee Ack dtd 791030 of License SUA-648 Insp findings no items of noncompliance notes BANGART,R.L. Atomic Energy Commission. 75/10/30. 1p.
- --7912210411 IE Insp Findings & Licensee Ack dtd 691202 of License 8UA-648 Insp findings:no item of noncompliance noted. \* Atomic Energy Commission. 69/12/02. 1p.
- --7912210424 Discusses noncompliance noted in recent insp. May submit written position relitem of noncompliance & corrective actions taken or needed to be taken. Requests reply within 20 days of itr receipt. Forwards Form AEC-592.

  HALKER.D. I. Atomic Energy Commission. 68/09/03. 2pp.
- -7912210426 IE Insp Findings & Licensee Ack dtd 791129 & 30 of License BUA-448. Insp findings: no item of noncompliance noted. SANDELL.P.S. Atomic Energy Commission. 65/11/30. 1p.

- ~~7912210428 Discusses item of nancompliance noted in recent insp.May submit written position re item of nancompliance & corrective actions taken or needed to be taken. Response requested within 20 days Forwards Form AEC-592.

  MALKER,D. I. Atomic Energy Commission. 64/06/19. 2pp.
- --7912210430 Notifies of consideration being given to Union Carbide Corpapplication re continuation of discharging mill effluents to unrestricted areas. CUNNINGHAM.R.E. Atomic Energy Commission. 62/03/13. ip.
- -7912210432 Forwards Compliance Insp Rept of Globe Mining Co. DUBINSKI.L. Atomic Energy Commission. 41/11/28. 1p.
- --7912210435 Compliance Insp Rept of Olobe Mining Co on 610830-31.
  Noncompliance noted: licenses received, used & transferred source matl w/o valid license.
  \* Atomic Energy Commission. 61/08/31. App.
- 7912270028 Responds to FOIA request for info re explosion of nuclear device in southern hemisphere, including respective analysis weapons fallout data. BOS 791214 telegram undergoing disclosure determination in response to request. CARR, J. C. Division of Rules and Records. 79/12/18. 1p.
- 7912270031 FOIA request for info re explosion of nuclear device in southern hemisphere, including respective analysis weapons fallout data.

  CDCHRAN, T. B. Natural Resources Defense Council. 79/11/26. 1p.
- 7912270032 Responds to FOIA request for info re 8 Laudig FOIA request for documents concerning Marbie Hill nuclear power station. Forwards 8 Laudig 790622 ltr & NRC 790709 & 1105 ltrs.W/o encl. CARR, J. C. Division of Rules and Records. 79/12/20. 1p.
- 7912270034 FOIA request for info re 8 Laudig FOIA request for documents concerning Marble Hill nuclear power station.
  VDIOT,H.H. LeBoeuf, Lamb, Leiby & MacRae. 79/12/10. ip.
- 791227003B Responds to FOIA request for testimony of Director of Ofc of State Programs to President's Commission on Accident at TMI. Forwards requested info. W/o encl. CARR.J. C. Division of Rules and Records. 79/12/20. ip.
- 7912270040 FOIA request for testimony of Director of Ofc of Btate Programs to President's Commission on Accident at THI. HEISS,E.R. Sheldon, Harmon & Weiss. 79/12/12. ip.
- 7912270044 Responds to FOIA request for info re activities of nuclear power plants. Not proper request made per FOIA. Forwards 10CFRP, specifying charges for searching & reproducing records. W/o encl. CARR. J. C. Division of Rules and Records. 79/12/24. 1p.
- 7912270045 FOIA request for info re activities of NRC & nuclear power plants. GANNIS, S. Affiliation Unknown. 79/12/11. 1p.
- 7912280660 FOIA request for access to info re nuclear facilities in RI. KOHN.B. New Paper Providence.RI. 79/11/23. ip.
- 7912280649 FOIA request for documents generated as result of investigation of South TX project by FBI.

  SINKIN.L.A. Citizens Concerned About Nuclear Power, Inc. 79/11/12.
- 7912280675 Responds to FOIA request for documents concerning #11 aspects of stationary low power reactor incident at INEL. Requested info in Washington, DC FDR. Recommends that DDE be contacted for add1 info.

  CARR, J. C. Division of Rules and Records. 79/12/20. ip.
- 7912280679 FDIA request for documents concerning all aspects of stationary low power reactor incident at INEL. DRYER,R.L. Parsons, Behle & Latimer. 79/11/27. 3pp.
- 7912280682 FOIA request for Bargent & Lundy 1969 rept, "Economic Evaluation of Alternatives," w/transmittal ltr & summary WOLIVER, J. Legal Aid Society of Clermont County, OH, 79/11/05. ip.

#### GEN TEC 18 GENERIC TECHNICAL ISSUES

- 7912050559 Requests final NRC position ro acceptance criteria for Mark I containment long-borm program Plant unique analysis will be submitted upon receipt of final resolution of NRC acceptance criteria.
  BDBQN.L.J. General Electric Co., Nuclear Energy Products Div. MFN-289-79. 79/11/30. 4pp.
- 7912040401 Value/impact assessment of proposed Revision 2 to Reg Guide 1.97, "Instrumentation in Light Water Cooled Nuclear Power Plants to Assess Plant & Environs Conditions During & Following Accident." Revision should be issued.

  B Office of Standards Development. 79/10/15. Spp.
- 7912110196 Notification of cancelled 791205 meeting w/B&W & B&W numers to provide summary of submittal of B&W ATMB rept.
  THADANI.A. Reactor Systems Branch. 79/11/27. 2pp.
- 7912110555 INL-NUREG-26789
  "Condensation Induced Water Hammer in Steam Generators," prepared for presentation at Joint UB-Japan Info Exchanges on Two Flow Dynamics, Dsaka Univ. Osaka, Japan, 790801-03.
  JONES, C. C., SAHA, P., WU, B. J. C. Brookhaven National Laboratory, INL-NUREG-26787. 79/06/30. 19pp.
- 7912310323 Notification of 791212 meeting w/Bandia Lab in Bethesda.MD to review procedures for evaluating fault trees using set equation transformation sys.

  ANGELO.J. Light Water Reactors Branch 1. 79/12/05. 2pp.
- 7912310545 Comments on draft integrated reliability evalution program in relation to Mark I containment long-term program:program results could be useful in implementation of long-term program.

  GRIMES, C. I. Plant Systems Branch. 79/11/27. ip.

# 1&E INSPECTION AND ENFORCEMENT

- 7910280485 IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads."

  © Office of Inspection & Enforcement, Office of the Director.
  79/11/09. 0.
- 7910280492 IE Circular 79-24, "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BURS.". a Office of Inspection & Enforcement, Office of the Director. 79/11/26. 4pp.
- 7910250496 IE Circular 79-23, "Motor Starters & Contactors Failed to Operate." # Office of Inspection & Enforcement, Office of the Director. 79/11/26. 3pp.
- 7910230499 IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation."

  \* Office of Inspection & Enforcement, Office of the Director.
  79/11/30. 3pp.
- 7910250502 IE Info Notice 79-30, "Reporting of Defects & Noncompliance, 100FR21."

  # Office of Inspection & Enforcement, Office of the Director, 79/12/06. 2pp.
- 7910280805 IE Bulletin 79-28, "Possible Maifunction of NAMCO Model EA180 Limit Suitches at Elevated Temps," \* Office of Inspection & Enforcement, Office of the Director, 79/12/07. 3pp.
- 7910230507 IE Info Notice 79-31. "Use of Incorrect Amplified Response Spectra (ARS)."

   Office of Inspection & Enforcement, Office of the Director, 79/12/13. ipp.
- 7912030100 PNB-II-79-005: on 791029, telephone bomb threat received.

  Search conducted w/negative results.

  MODRE D. E. Region 2. Atlanta, Defice of the Director. 79/10/30.

  1p.
- 7952120838 Responds to FOIA request for IE bulletins & circulars for 1975 & IE info notices for 1975-79. Forwards documents listed in App A. IE circulars not issued in 1975 & IE info notices not issued prior to 1979.

  CARR.J.C. Division of Rules and Records. 79/11/27. 3pp.

- --7912120943 IE Bulletin 75-02, "Defective Radionics Radiographic Exposure Devices & Sources Changers " \*\* Office of Inspection & Enforcement, Office of the Director. 75/02/14. 5pp
- --7912120544 IE Bullotin 75+07 re emission of corrusive gases into ventilation sys filtered by HEPA filters. \* Office of Inspection & Enforcement, Office of the Director 75/11/26. 2pp
- --7912120549 IE Info Notice 79-04, "Degradation of Engineered Safety Features." \* Office of Inspection & Enforcement, Office of the Director. 79/02/16. 6pp.
- 7912180103 PNO-III-79-44: on 791111; seven partially decayed Mo-99/Tc-99m generators removed from hosp storage room possibly by carrier delivering new generators. Region 3 investigating inclident.
  PAPERIELLO.C.J., DAVIS.A.B. Region 3. Chicago, Office of the Director. 79/11/21. 1p.
- 7912180111 PNO-IV-79-16: on recent aerial survey of old vitro site, radiation levels detacted at higher levels due to contaminated equipment at Minerals Equipment Co.Salt Lake City, UT. Equipment originally From Yuba City U mill, AZ. EVERETT, R. J. Region 4, Dallas, Office of the Director. 79/11/21. in.
- 7912180318 PND-III-79-044A: on 791111, seven partially decayed Squibb generators removed from storage area. Caused by accidental removal by driver of Casperson Courier Svc. Generators to be returned & disposed of.
  NICHOLSON, N. A., PAGLIARO, J. A. Region 3, Chicago, Office of the Director. 79/11/23. 1p.
- 7912200298 EN-79-011: on 791015 notice of violation & notice of proposed imposition of civil geneities will be issued for Licenses 29-13985-01 & 29-13985-04MD. Action based on alleged noncompliances re pharmaceutical operations.

  RRDCKETT, J., OCHER, O.C. Diffice of Inspection & Enforcement, Office of the Director. 79/10/10. ip.
- 7912200473 PND III-79-037: on 791109 & 10 during open house at nuclear engineering facility.0. 7 uCi Cs-137 std plastic sealed source was stolen.
  PAUL.R.A. DAVIS.A.B. Region 3. Chicago. Office of the Director. 79/11/13.
- 7912200663 PNO-111-79-22: on 791025, wehicle carrying 300 mCi of Tc-99m & small quantity of I-123 sideswiped Packages of byproduct matl remained intactino cantamination found. PAPERIELLO.C. DAVIS.A.B. Region 3. Chicago, Office of the Director. 79/10/25. Bp.
- 7912310051 PNO-I-79-005: on 791008.licensee emplayee picked up 7.5 mCi Cs-137 source which separated from retraction rod of moisture density gauge. Emplayee carried source in pocket for 30 minutes: receiving 10-15 rems to whole body. GLENN. J. JERMAN.P. Region I. Philadelphia, Office of the Director. 79/10/09. 1p.
- 7912310059 PNO-IV-79-007: on 791015, one individual performing well logging received high YLD reading of 64 rem. Other workers performing similar duties received typical readings. No unusual events or activities indicated.

  EVERETT, R. J. Region 4, Dallas, Office of the Director. 79/10/17.
- 7712310077 PND-77-008:on 771015, two carpenters received whole body doses of 30 millinem.after gaining access to roof area of radioactive cell. Licensee initiating corrective action to prevent access to area.

  EVERETT.R.J. Region 4, Dalias, Office of the Director. 79/10/17.
  1p.
- 7912310121 PND-1-79-003: on 791015, wristfilm badges for two individuals indicated beta doses of 150 rem & 70 rem. No measurable exposure for whole body badges. Individuals used Army AM/UDM-2 radiac calibrator containing 100 mCi Sr-90. CDSTELLO,F., MCCLINTOCKUR. O. Office of Inspection & Enforcement, Office of the Director. 79/10/15. 12.
- 791231029B PNG-IV-79-017: on 791204, State of NE will conduct emergency response exercise based on incident at Gooper nuclear power station involving simulated offsite releases.

  BATRD, J.B., HARRISDN.H. Region 4. Dallas, Office of the Director. 79/11/24. 1p.

- 7912310315 PND-II-79-008:on 791010.annual exercise will be conducted at facility to test State of SC emergency plan. CORVELL. Q., HUFHAM. J. H. Region 2. Atlanta, Office of the Director. 79/10/09. lp.
- 7912310021 PND-I-79-006: on 79100B.possible overexposure occurred to radiographer & assistant on tank trailer outside facility during radiography test using 56 Ci Ir-192 source not fully retracted into device.Estimates 7-14 rems exposure. DAVIS.J.B., JERNAN.P.C. Office of Inspection & Enforcement, Office of the Director. 79/10/10. 1p.
- 7912310329 PND-I-79-019:on 791114.employes film badge read 21.5 rem for Oct 1979, resulting from low energy x-rays. Employee had not worked w/licensed matl during period, but performed radiography one day w/200 KVP x-ray machine.
  COSTELLO.F., MCCLINTOCK.R.O., SMITH.G.M. Office of Inspection & Enforcement, Office of the Director. 79/11/14. 1p.
- 7910250514 IE Circular 79-25, "Shock Arrestor Strut Assembly Interference." \* Office of Inspection & Enforcement, Office of the Director, 79/12/20, 1pp.

#### PDR MISC

- 7908140497 Responds to 790706 memo for comments re draft IE bulletin "Audibility Problems Encountered on Evacuation of Personnel From High Noise Areas." No comments.

  6AMHILLUP. Assistant Director for Operating Reactor Projects (Pre 791030). 79/07/26. 1p.
- --7908140509 Forwards draft IE Bulletin. "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas," for review & comment. JURDAN.E.L. Division of Reactor Operations Inspections. 79/07/06. 4pp.
- 7908290525 Responds to 790823 teleon re issuance of facility form policies for 158 risks in 1969. Gives amounts of premiums returned.
  JONES, R. D. American Nuclear Insurers. 79/08/23. 1p.
- 7912050100 Discusses 790820 memo re toss of offsite power survey.

  Requests that survey include all plants. Info has high
  priority for Task Action Plan A-44, station blackout.

  EISENHUT, D. G. Division of Operating Reactors. 79/11/16. 4pp.
- 7912050284 Forwards IE Circular 79-24. "Proper Installation & Calibr of Core Spray Pipe Break Detection Equipment on BWRs."
  Draft transmittal encl.
  MOSELEY, N. C. Division of Reactor Operations Inspections. 79/11/24.
  7pp.
- 7912050007 Notification of 791205 meeting w/IE & Dfc of Btds Pevelopment to discuss documentation of interdisciplinary approval of design documents. LIEDERBACH.F.J Guality Assurance Branch. 79/11/27. 1p.
- 7912120024 Responds to DDE 790611 ltr re U mining in Las Padres Natl Forest Neither DDE nor NRC has authority over U mining. Submits name & address of appropriate authority to contact. GOSSICKL.V. Office of the Executive Director for Operations. 79/10/10. ip.
- 7912120035 Responds to MC Jay 790418 itr re method developed to prevent cracks in piping of BWRs. Neither NRC nor GE can evaluate efficacy of ideas due to lack of technical details reproposed methods.

  GGSBICKL.V. Office of the Executive Director for Operations.
  79/10/22. lp.
- --7912120044 Recommends that MC Jay contact QE to provide technical info re proposed method to prevent pipe cracks in BWRs. NHC does not fabricate or repair piping sys. BIRCKG.W.J. Office of the Executive Director for Operations. 77/05/23. 2pp.
- ---7912120049 Forwards MC Jay 790418 ltr re prevention of pipe lead occurrence in EWRs.Requests comment. CRANSTON.A. Senata. 79/08/22. Spp.
- 79:2120097 Discusses licensing actions awaiting review by bulletins & orders group & possibility of increased workload on operating reactors group.

  EISENHUT, D. 0. Division of Operating Reactors. 79/11/05. 2pp.

- 7712120221 Informs Subcommittee on Energy & Environ of notice of effective rulemaking to amend iOCFR50 re fracture toughness & reactor vessel surveillance.FR notice encl. W/o encl. MINIOUE.R. B. Office of Standards Development. 79/09/18. 3pp.
- 7912120296 Notifies NRC of State historic preservation officer name & address change. CARRIER.E.B. Louisiana, State of. 79/12/05. ip.
- 7912120541 Responds to DC Prince 790919 request for info re procedures for adoption of FL plan for const nuclear plants. State of FL responsible for assuring adequate supplies of energy. Forwards pamphlet re nuclear reactor licensing. GCBSICN.L.V. Office of the Executive Director for Operations. 79/10/31. ip.
- --7912120544 Forwards DC Prince 790919 ltr re procedures for adoption of plan for const of nuclear plants in FL.Requests comments. IRELAND, A. House of Rep. 79/09/25. 3pp.
- 7912130214 Forwards outline of basis for proposed fee schedule for tailings kicense reviews. MILLER, H. J. Uranium Recovery Licensing Branch. 79/11/02. ip.
- --7912130226 Justifies calculation of proposed fees for licensing action used in SECY 79-413 & licensing requirements for U mills.
  HDLLOHAY, C. J. License Fee Management Branch. 79/08/31. 429.
- 7912130234 Responds to 791030 draft rept re three add1 sites for designation under Public Law 95-604. Concurs w/designation of sites. Areas are remote from population & contain relatively small quantities of tailings.

  SCARAND.R.A. Uranium Recovery Licensing Branch. 79/11/06. 2pp.
- 7912180020 Summarizes updated activities for U Mill Tailings Radiation Control Act of 1978 re DDE 791030 request NRC has concurred w/DDE designation of site boundaries for 22 processing sites.

  SCARAND.R.A. Uranium Recovery Licensing Branch. 79/11/09. 2pp.
- 7010100118 Commands evaluation as affects of fire on associated
- 7912180115 Forwards evaluation re effects of fire on associated nonsafety circuits & oil collection sys for reactor coolant pumps. FEROUSON, R. Plant Bystems Branch. 79/11/09. App.
- 7912180250 Responds to 791102 memo urging NRC to expedite issuance of final regulations to implement Section 504 of Rehabilitation Act. Anticipates final regulations will be forwarded to NRC for approval by Dec 1979. GDS8ICK, L. V. Office of the Executive Director for Operations. 79/11/30. 1p.
- --7912180253 Asks NRC to finalize regulations to implement Section 504 of Rehabilitation Act of 1973.
  EISENSTAT.S.E. President of US & Executive Offices. 79/11/02.
  ip.
- 7912180308 Forwards NRC 791015 Imperial Valley earthquake reconnaissance repts.
  KNIGHT, J. P. Assistant Director for Engineering. 79/11/27. 1p.
- --7912180307 Forwards 791015 Imperial Valley earthquake reconnaissance rapts.
  LEVIN.H.A., MARTORE, J.A. Division of Operating Reactors. JENO, D. Division of Systems Safety. 79/11/02. 2pp.
- --7912180312 "Reconnaissance Rept Imperial Valley Earthquate 791015." Catalog of photographs & observations by L. Reiter and L. LEVIN.H. A., MARTDRE, J. A. Division of Operating Reactors. 79711702. 35pp.
- --7912180316 "Observed Effects of 791015 El Centro Earthquake,"
  HELLER, L. W. Division of Systems Safety. 79/11/02. 5pp.
- --7912180321 "Earthquake Damage Observation Rept."
  JENG, D. C. Division of Systems Bafety. 79/11/02. 9pp.
- 7912190004 Discusses training program & curriculum for planning course & operations course (RERO). Forwards various documents. W/a encl. CDLLINS.H.E. Office of State Programs. 79/11/21, 2pp.
- 7912190132 Responds to 791101 request for info on nuclear energy. Annual rapt for 1978 encl. Suggests other sources for more specific info. DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/30. 2pp.

- 7912190142 Forwards comments on NRC sponsored radiological emergency response operations training program w/o encl. RYAN, R. O. Office of State Programs. 79/11/27. 1p.
- 79:12190292 NUREG-0632
  Discusses draft rept "Siting Nuclear Power Plants."
  Disagrees that risk assessment methodology should not be based on arithmetic formula. Forwards comments.
  MULLER.D.R. Division of Site Safety & Environmental Analysis.
  79/12/04. 16pp.
- --7912190302 "Methodological Concepts & Issues Involving Psychic Costs & Benefits, Risk Perception & Risk Aversion in Use Mgt of Alternative Energy Sources."
  SPANGLER.M.B. Division of Site Safety & Environmental Analysis.
  79/10/26. 10pp.
- 7912190482 Responds to 791022 Itr re distribution of environ impact statements & related info. Requests environ statements for plants located in region.
  REGAN.H. Assistant Director for Environmental Technology.
  79/11/07.
- 7912190527 Forwards latest annual rept in response to 791119 request for info re nuclear power. Request is being forwarded to Div. of Technical Info & Document Control.

  KOPECK.J. Office of Public Affairs. 79/11/30. 1p.
- --7912190531 Requests info re nuclear energy & catalogue of info available for purchase. DELECUM.W.L. Affiliation Unknown. 79/11/19. 1p.
- 7912190536 Responds to 791106 ltr requesting NRC opinion re future of specific power plants & util dividends No opinion can be issued. Several months required to develop & implement improved safety objectives. Unnecessary delay will be avoided DENTON. H. R. Office of Nuclear Reactor Regulation. 79/12/03. 1p.
- 7912190538 Responds to 791102 request for info re need for nuclear power in US. Excerpt from President Carter 790507 Second Natl Energy Plan encl. H/d encl.

  DENTON H.R. Office of Nuclear Reactor Regulation. 79/12/03. ip.
- ---7912190541 Requests info re need for nuclear energy in US. NICHOLS.L. A. Affiliation Unknown. 79/11/02. 1p.
- 7912190340 Responds to 791113 ltr re need for nuclear power. Use of coal & nuclear power must expand. NRC is making every effort to ensure public health & safety for all nuclear power plants so that existing plants can continue to operate.

  DENTON, H. R. Office of Nuclear Reactor Regulation, 79/12/03. ig.
- 7912190634 Forwards corrected Page 7 to 791113 memo re guidelines for avaluating qualification of Class IE electrical equipment in apperating reactors.

  BUTCHER.E. Plant Bystems Branch. 79/11/28. 2pp.
- 7912190733 Forwards guidelines for evaluating qualification of Class IE electrical equipment in operating reactors for use in reviews of licenses responses to IE Bulletin 79-01. Repts from other NRC consultants will supplement App C. DENTON.H.R. Office of Nuclear Reactor Regulation, IEB-79-01. 79/11/13. 35pp.
- 7912200042 Grants exemption from code requirements & approves of participation in matters before NRC affecting GE. As former amployee of GE. interest in company is not likely to affect integrity of svcs to NRC.

  LEVINE.S. Office of Nuclear Regulatory Research. 79/12/17. ip.
- 7912200069 Responds to 791119 request for info on research related to health effects of ionizing radiation. Lists projects stimulated by Ofc of Nuclear Reactor Regulation, primarily in category of human exposure pathways.

  MULLER, D. R. Division of Site Safety & Environmental Analysis.

  79/11/30. 2pp.
- --7912200078 Requests add1 info about long-range program goals re health effects from low level radiation, Seeks info re epidemiology. comparative biology, basic biology & human exposure pathways. Info needed for 791207 briefing.
  PARBONTIM. A. Radiological Health Standards Branch. 79/11/19. 2pp.
- --79122000B4 Discusses replacement of performance appraisal rept by decision unit tracking sys. New sys will emphasize program areas rather than ofc performance.

  GOSSIGKL.V. Office of the Executive Director for Operations.
  79/10/15. Spp.

- 7912210067 Revised notification of 791211 meeting w/IE & Btds Development to discuss NRC criteria for records storage facilities. Meeting date changed from 791210 to 791211. SPRAUL.J.G. Quality Assurance Branch. 79/12/07. ip.
- 7912210087 Notification of 791210 meeting w/IE & Stds Development to discuss NRC criteria for records storage facilities. SPRAUL.J.O. Quality Assurance Branch. 79/12/07. Ip.
- 7912210184 Discusses NRC outline for environ statements prepared in support of applications for CPs & GLs. Requests that NRC outline include conservation as alternative to licensing proposal.

  SHEA D.F. Council on Environmental Quality. 79/12/12. ip.
- 7912260124 Responds to CF Miller 790817 request for info re use of U-235 in power plants. Power plants use from 2.5-4% of U-238, Approx 70% U-235 burned up during feel cycle. Spent fuel is not reprocessed & no unburned U-235 recovered. ODS91CK.t. V. Office of the Executive Director for Operations. 79/10/22. 3pp.
- 7912260235 Discusses response by licensees to IE Bulletin 79-10. "Environ Qualification of Class IE Equipment." Farwards listing by plant of equipment for operation in accident conditions & evaluation guidelines. EISENHUT.D.Q. Division of Operating Reactors. IEB-79-01. 79/12/05. 49pp.
- 7912270001 Responds to 790830 ltr re NL Gelbman suggestion re const of nuclear power plants underground. Several studies have been performed. Benefits would not justify costs & problems. GCRSIGK.L.V. Office of the Executive Director for Operations. 79/10/09. 2pp.
- --7912270005 Forwards NL Gelbman 790722 ltr re const of nuclear power plants underground. Requests comment. STONE.R. Senate. 79/08/30. 2pp.
- 7912270033 Responds to 790911 ltr re T Schlegelmilch concern about licensing of nuclear plants built from same design as TMI plant. Forwards list of plants w/designs which include B&W NSSS.
  OSSICK.L.V. Office of the Executive Director for Operations. 79/10/31. 3pp.
- --7912270037 Request, submitted on behalf of T Schlegelmilch, for status rept on licensing of nuclear plants built from same design as TMI plant. LUEFFLER.T. House of Rep. 79/09/11. 1p.
- 791227014B Forwards notice of violation for performance of radiographic insps w/licensed radioactive matl from Jan-Oct 1979 on board US Navy vessels. Response required within 20 days. BOOK.H.E. Region 5. San Francisco, Fuel Facility & Materials Safety Branch. 79/12/07. 2pp.
- --7912270152 Notice of violation from Jan-Oct 1979 performance of radiographic insps on board US Navy vessels. \* Region 5. San Francisco. Office of the Director. 79/12/07. 1p.
- 7912310013 Responds to 790925 request to stds review of ANS 59.2.
  "Heating. Ventilation & Air Conditioning Sys. Important to
  Bafety, Located Outside Primary Containment." Draft std
  should be modified.
  ORIMES, B. K. Assistant Director for Engineering. 79/11/27. 2pp.
- 7912310221 Notification of 800107 meeting w/Fluid Components Corp in Bethesda.HD. to discuss & view demonstrations of flow & lavel measure sys produced by company.
  8ATTERFIELD,R. Electric. Instrumentation & Control Systems
  Branch. 79/12/18. 2pp.
- 7912310222 Responds to 791120 ltr re moratorium on licensing of nuclear facilities. Continuing effort to ensure public health & safety so that existing plants can continue to be operated & new plants licensed.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/12/03. 1p.
- 7912310227 Comments on draft circular re States Co sliding link electrical terminal block penultimate paragraph should be changed Problem should be Followed up by inspectors to ensure licenses compliance.

  QAMMILL.W.P. Assistant Director for Systems & Projects. 79/12/11.
  200.

7912310263 Notification of 791217 meeting w/Japan Atomic Power Co.
Hitsubishi Heavy Industries D Obaqashi Const Co to discuss
low-temp fracture toughness of prestressed concrete
containment components
HERRING, K.S. Engineering Branch, 79/12/12. 2pp.

# NUREO NUREO REPORTS AND RELATED CORRESPONDENCE

7902260150 Responds to 790116 F01A request for mine categories of documents re-fire protection at six nuclear plants. Documents forwarded except for one not found & one other already located in PDR. FELTON, J.M. Division of Rules and Records. 79/02/09. 1p.

7912040520 NUREG/CR-I102 V3
"Systematic Assessment of Safeguards Regulations.Apps."
FRALEY.D.M. Battelle Memorial Institute. Pacific Northwest
Laboratory. FIN B-21427. PNL-2804. 79/11/30. 160pp. Available at
NTIS.

7912050002 NUREG/CR-1076
"Development of High-Sensitivity Ultrasonic Techniques for Inservice Insp of Nuclear Reactors." annual rept.Oct 1977 - Sept 1978
LINZER.M., PARKS.S. I., DIETZ,D.R. Commerce,Dept.of, National Bureau of Standards. FIN 9-5680. 79/11/30. 55pp.

7912050005 NUREG/CR-0662
"Computational Tools for Matl Control Assessment & Design
of Processing Monitors:Overview."
DUNN, D. R., CANDY, J. V., RUEGEL, J. O. Lawrence Livermore Laboratory.
FIN A-0115. UCRL-52702. 79/02/28. 30pp. Available at NT19.

7912050009 NUREG/CR-1040
"LWR Safety Research Program: Quarterly Programs Rept,"
Jan-Mar 1977.
PEMITT.E.G., KYGER, J.A. Argonne National Laboratory, FIN A-2014.
ANL-79-43. 79/08/31. 48pp. Available at NTIS.

7912050012 NUREC-0090 V2
"Rept to Congress on Abnormal Occurrences, Apr-June 1979,"
Vol 2, Number 2.
• Office of Management and Program Analysis. 79/11/30. 42pp.
Available at NTIS.

7912060307 NUREG/CR-0955

"Regional Tectonics & Seismicity of Southwestern IA," annual rept.FY79.
VAN ECK.O.J., ANDERSON.R.R., BLACK.R.A. Idwa, State of. NRC-04-787-228 79/07/31. 31pp. Available at NTIS.

7912070491 Notification of 791120 meeting w/Eberline Instrument Corp in Dethesda.MD to discuss high range effluent munitors & improved inplant iodine instrumentation in response to requirements resulting from TMI Lessons Learned Task Force. BARRETT.L. Environmental Evaluation Granch. 79/11/20. 2pp.

7912110224 Comments on draft NUREG-0610 proposes establishment of hetter public info sys in emergency situations. Exact knowledge of malfunction imappropriate. Expected frequency item discouraging CLEARY, P. Citizens for a Better Environment. 79/10/18. ip.

7912110227 Comments on draft NUREG-0610 notification of NRC should be itsted as licensee action for all four classes. Suggests amends & deletions. GARRETTIE G. Affiliation Unknown. 79/10/31. Ip.

7912110442 NUREG/CR-0190 V2
"Estimates of Internal Dose Equivalent to 22 Target Organs for Radionociides occuring in Routine Releases from Nuclear Fuel Cycle Facilities." Vol 2
DUNNING.D E. BERNARD.S R., WALSH.P. J. Oak Ridge National Laboratory. FIN 8-0188. ORNE/NUREG/TM-1. 79/10/31. 509pp

7912110521 NUREO-0568
"Title List Publicly Available Documents.TMI-2." Revision 1.
Suppl 1.Jul-Oct 1979.
• Office of Administration. 79/10/31. 109pp.

7912120033 NUREG/CR-0717
"Dynamic Model of Global Iodina Cycle for Estimation of Dose to World Papulation from Releases of I-129 to Environ."
KOCHER, D C Dak Ridge National Laboratory. FIN B-0188.
ORNL/NUREG-39 79/11/30 112pp. Available at NTIS.

7912120036 NUREO-0632
"NRC Views & Analysis of Recommendations of President's Commission on Accident at TML."
\* Office of Nuclear Reactor Regulation. 79/11/30. 20pp.

7912120096 Forwards DB Waters ltr re implementation of mods to nuclear plant equipment & administration, per new NRC regulations. Requests NRC position re extension of deadline for compliance w/lessons learned recommendations. MCRGAN.R. Senate. 79/12/07. 3pp.

7912120099 NUREG-0380 V3 NL1
"Program Bummary Rept." Vol 3.Number 11.
\* Office of Management and Program Analysis. 79/11/16. 60pp.
Available at NTIS.

7912120126 Forwards comments on NUREG-0511 re U mill tailings wites, on behalf of Americans for Rational Energy Alternatives, Inc. General philosophy toward radiation protection & risk mittgation is too extreme.
WILLIAMS, D. C. Affiliation Unknown. 14546. 79/10/24. 5pp.

79:2120:30 Comments on NUREG-05:1; "Draft Generic Impact Statement on U Milling" fails to mention U mining industry in eastern US. BARLEY, S. R. Affiliation Unknown. 14552. 79/10/23. 3pp.

7912120132 NUREG/CR-1156
"Environ Assessment of Ionization Chamber Smoke Detectors
Containing Am-241."
BELANGER R. , BUCKLEY, D. W. Science Applications, Inc. NRC-02-78-045.
BAI 01379-729LJ. 79/11/30. 110pp.

7912120139 NUREO/CR-0963
"DYMESTI: Revised Dunamic Estimator Calculation Program."
FREEMAN, D. W., CANDY, J. V. Lawrence Livermore Laboratory, FIN A-0115.
UCRL-92721. 79711/30. 50pp.

7912120157 NUREO/CR-0628
"Prediction of Net Radon Emission from Model Open Pit U
Mine."
NIELSON.K.K., PERKINS,R.W., SCHWENDIMAN.L.C Battella Memorial
Institute, Pacific Northwest Laboratory. FIN 8-2279. PNL-2889.
79/09/30. 30pp.

7912120168 Comments on NUREG-0511: activity consistent w/social, economic & physical goals & policies of GA Dfc of Planning & Budget. BADGER.C.H. Georgia: State of. 79/10/29. lp.

7912120190 NUREG/CR-1022
"U & Sodium Dride Aerosol Experiments: Nuclear Bafety Pilot
Plant Tests 201-203 & Tests 301-302, Data Record Rept."
ADAHS, R. E., HAN. J. T., KRESS, T. S. Qak Ridge National Laboratory. FIN
B-0121. ORNL/NUREG/TM 3. 79/11/30. 90pp. Available at NTIS.

7912120442 NUREO/CR-0998
"Technical Manual Operation & Equipment Instructions for In
Situ Impulse Test."
Bhannon & Wilson Inc. FIN B-3015. 79/11/30. 75pp.

7912120520 Responds to 790B10 ltr rs public availability of NRG NUREQ/CF-01B1. "Barrier Penstration Database." FOIA requires that NRC make all non-exempt documents available to public NUREG/CR-01B1 is not exempt. Amend sought to Atomic Energy Act. QOSSICK.L.V. Defice of the Executive Diractor for Operations. 79/10/12. 1p.

--7912120526 Forwards Q Hiller 790726 ltr re public availability of NUREO/CR-0181, "Barrier Penetration Database." Requests comment. ORISHAM. W. House of Rep. 79/08/10. 2pp.

7912120641 NUREG/CR-0990
"Use of Reconnaissance Level Info for Environ Assessment."
FOSTER:R.F., RICKARD, W.H., STRAND, J.A. Battelle Memorial Institute,
Pacific Northwest Laboratory. FIN B-2156-8. PNL-3080. 79/11/30.
47pp. Available at NTIS.

7912120645 NUREG/CR-0982
"Evaluating Strength & Ductility of Irradiated Zircaloy:
Task 5." quarterly progress rept for Jan-Mar 1979.
LOMRY,L.M. PERRIN,J. S., MARKWORTH,A.J. Battelis Memorial Institute.
Columbus Laboratories. FIN A-4069. BMI-2034. 79/11/30. 45pp.
Available at NTIG.

7912130041 Comments on NUREG 0410; expresses concern that licensee action to promptly inform state & local authorities of unusual conditions will have adverse effect on public safety & welfare.

MILLIAMSON.T.G., SHRIVER, B.L. Virginia, Univ. of. 79/10/15. 2pp.

7912130072 NUREO-0330 V3 N5
Buff Book 2: "Status Summary Rept. Advanced Reactor Safsty
Research." Vol 3. Number 5. data as of 790930.

+ Office of Nuclear Regulatory Research. 79/10/24. 82pp.
Available at NTIS.

7912130075 NUREO-0525
"Safeguards Summary Event List," pre-NRC through 790630.
DAVIDSON, J. J. Office of Nuclear Material Safety & Safeguards.
79/11/30. 139pp.

79121300B9 NUREG/CR-0794
"Oeneral Investigation of Radionuclide Retention in
Higration Pathways at West Valley,NY Low Level Burial Site,"
annual rept Sept 1977-Sept 1978.
DANA,R.H., HOLELLO,S.A., FICKIES,R.H. New York, State of. FIN
B-6008. NYSOS/79-2403. 79/11/30. 108pp.

7912130332 Comments on proposed rulemaking 50~22: since decommissioning of nuclear power facilities is inevitable, cost estimates of financial mechanisms to meet plannned & premature decommissioning should be incerparated into code. POLLACK, R. P. Critical Mass Energy Project. GARLOW, C. Public Interest Research Group. GABCIATO, P. A. Affiliation Unknown. 79/11/21. 11pp.

7912130403 Comments on draft GEIS on U milling:supports comments of American Mining Congress. DRYLOFF.G.D. Exxon Minerals Co., USA. 14549. 79/10/24. ip.

7912130406 Comments, on behalf of Black Hills Energy Coalition, on NUREO-0511:re U mill tailings sites:does not produce worst-case estimates. Validity is limited.

BANDERFORD. J. Affiliation Unknown. 14542. 79/11/05. 1p.

7912130489 Forwards assessment of NUREO-0511, draft GEIS re U milling: NEPA does not permit justification of doses by comparison to background. LOCHSTET, H. A. Pennsylvania State Univ. 79/10/24. 12pp.

7912140125 NUREO/CR-1155
"Interactions of Radioactive Wastes w/Soils - Review," Oct
1976 - May 1979.
FOHLER, E. E. ESBINGTON, E. H. POLZER, H. L. Los Alamos Scientific
Laboratory, FIN A-7040-9. LA-UR-79-2910. 79/12/31. 48pp.
Available at NTIS.

7712140165 NUREO/CR-0987
"SANDIA-ORIGEN User's Manual."
EENNET.D.E. Sandia Laboratories. FIN A-1060. SAND79-0299,
79/10/31. 112pp. Available at NTIS.

7912140186 NUREG/CR-1101 V7
"Repts Distributed Under NRC Reactor Safety Research Foreign Technical Exchange Program." Vol VII. Jan-June 1979.
GUEENER D. S. Oak Ridge National Laboratory. FIN B-0126.
ORNL/NUREG/NBIC. 79/11/30. 84pp. Available at NTIB.

7912140206 NUREO/CR-0967
"Multiple Property Variations in Coaxial Cylindrical
Conductors Determined w/Multiple-Frequency Eddy Currents."
DEEDS.W.E., DODD.C.V. Oak Ridge National Laboratory. FIN 8-0417.
DRNL/NUREO/TM-3. 79/10/31. 63pp. Available at NTIS.

7912140339 NUREO/CR-0944

"Hydrodynamics & Heat Transfer Characteristics of Liquid Pools w/Bubble Agitation."
BLOTTNER,F. Q. Sandia Laboratories. FIN A-1019. BAND79-1132.
79/11/30. 73pp. Available at NTIS.

7912140474 RIL-026
Research Info Ltr 26: transmits results of completed research
on impact of offshore nuclear generation stations on
recreational behavior at adjacent coastal sites
(NNREO-0394).
LEVING.B. Office of Nuclear Regulatory Research, 78/04/27, 2pp.

--7912140483 NUREG-0394
"Impact of Offshore Nuclear Opporating Stations on Recreational Behavior at Adjacent Coastal Sites."
BAKER.E.J., MOSS,D.J., WEST.B.9. Florida State Univ. AT(49-24-0320. 77/12/31. 147pp. Available at NTIS.

912140522 RIL-033
Research Info Ltr 03: transmits documented results from research program to design, dovelop & test PAT-1 Pu package per criteria in NUREO-0360. Forwards SAND78-0724, "Pu Accident Resistant Container Project" & NUREO/CR-0030.
LEVINE.S. Office of Standards Development. 78/08/03, Epp.

--7912140524 NUREQ/CR-0030

"PARC (Pu Accident Resistant Container) Program Research,
Dasign & Development."

ANDERSEN. J. A, , DUFFEY. T. A. , DUPREE, S. A. Sandia Laboratories,
SAND74-587. 78/07/31. 397pp. Available at NTIS.

7912140544 Informs that public safety will not be jeopardised by extending implementation schedule of short-term recommendations of Lessons Learned Task Force CARBON, W. ACRS - Advisory Committee on Reactor Safequards 79

7912170003 NUREG-0135 V3 N4
Buff Book 1: "Status Summary Rept.Hater Reactor Safety
Research," data as of 790831
\* Office of Nuclear Regulatory Research 79/08/31 i1Opp.
Available at NTIS.

7912170011 NUREC-0650 "Technical Writing Style Guide" SAVOLAINEN.A., FELDMAN,R.H., DLIU,W.E. Office of Nuclear Reactor Regulation, 79/11/30, 92pp. Available at NTIS.

7912170024 "Fractographic & Microstructural Analysis of Fatigue Specimens of A302 Grade B Steel Tested in Air at Room Temp." OADETTA.G., PROVENZANO.V. Navy.Dapt.of, Naval Research Laboratory. FIN D-552B. NRL 4062, 79/09/28, 22pp. Available at NTIS

7912170034 Requests review of NUREG-0635 re excess cancer in Mesa County, CO. to determine impact on NRC analysis of health effects of U mill tailings industry, MILLER, H. J. Uranium Recovery Licensing Branch. 79/09/27. lp.

7912170089 Forwards rept re emergency preparedness, to be published in IEEE 791017-19 symposium proceedings & NUREG-0553 W/a encl. COLLINS, H. E. Office of State Programs. 79/11/23. jp.

7912170102 Responds to 791105 ltr re issuance of OLs Forwards NUREG-0094 & license examination grade data from various utils. W/o encl. COLLINGIP.F. Operator Licensing Branch. 79/11/10. 200.

7912170394 Responds to FDIA request for documents containing analysis of proposed siting criteria application to existing sites. Forwards NRC 790926 memo re NUREG-0625 Recommendation 2.w/ list of plants meeting criteria AGRS transcript in PDR. CARR.J. C. Division of Rules and Records. 79/11/30. 1p.

--7912170399 Lists factors to be considered for interpreting three distance criteria in surveillance of QL & CP sites re hazardous facilities, airports & pipelines. Depending upon interpretation: 10-20% of existing sites would fail criteria. HOUSTON.R.W. Division of Site Safety & Environmental Analysis. 79/09/26. Bpp.

7912180123 FOIA request for drafts of NUREG/CR-0570, NUREG/CR-0672, NUREG/CR-0130, NUREC-0584 & NUREG-0586, w/respective additions & comments.

PTAK, J. Iowa Public Interest Research Group. 79/11/16. 1p

7912180131 Responds to FOIA request for five NUREO repts w/additions & comments. Forwards NUREO-0584 & comments. NUREO/CR-0130 addendum available at NTIS & NRC. NUREO/CR-0570. NUREO CR-0672 & NUREO-0586 not yet published My o enc1 CARR. J. C. Division of Rules and Records. 79/12/06. 1p.

7912180207 NUREG-0596
"Nonradialogical Consequences to Aquatic Biota & Fisheries
of Busquehanna River from 1979 Accident at TMI Nuclear
Station."
HICKEY, C. R., SAMMORTH, R. B. Division of Site Safety & Environmental
Analysis. 79/11/30. 100pp.

7912180223 NUREG/CR-1068
"Transient Reponse of Beams to Correlated Random Excitation
Applied at Boundaries."
ARYAFARA. A MASRIS.F. UDMADIA.F.E. Southern California, Univ. of
FIN 8-5976. 79/12/31. 16Opp.

7912180226 NUREO-0616
"Rept of Special Revision Group IE on Lessons Learned from TMI."
\* Region 3, Chicago, Office of the Director. 79/12/31. 200pp.

7912180497 Summary of 790510-12 open meeting in Washington, DC recurrent status of TMI-2, Sequovah Power Plants Units 1 & 2 & Byster Creek transient resulting in low core water level.

\* ACRS - Advisory Committee on Reactor Safeguards. 79/05/12.

7912190068 Discusses options for financial assistance to state & local governments for emergency preparedness programs in addition to federally administored fund suggested in NUREG 0553.

RYAN, R. O. Office of Nuclear Reactor Regulation. 79/11/21. Spp.

- 7912190133 Forwards draft memo & ltr requesting implementation of NUREO/CR-0660 recommendations Manpower requirements encl. GRIMES.B.K. Assistant Director for Site & Safeguards (Pre 791030), 79711/19. Epp.
- 7912190172 Comments on draft NUREC-0610. "Draft Emergency Action Level Quidelines for Nuclear Power Plants." VETTER.W.E. Region 4, Dallas, Office of the Director. 79/11/27.
- 7912190461 Comments on NUREO-0610 re emergency actions pertaining to nuclear power facilities. Population should be given advanced warning & info on radioactivity.
  SIMMONS.J.W. Affiliation Unknown. 79/10/15. 2pp.
- 7912190504 Forwards comments on NUREO-0595. Agrees generally w/thesis that operational safety factors require proportionally greater attention.

  LEE-B. Atomic Industrial Forum. 79/12/13. 33pp.
- 7912190526 Responds to 791110 ltr re implementation of Kemeny Commission recommendations. All recommendations, except reorganization of NRC deemed necessary & feasible. DENTON, H. R. Office of Nuclear Reactor Regulation. 79/12/03. lp.
- ~~7911190354 Discusses need to take action to assure implementation of recommendations of TMI Lessons Learned Task Force.
  Utilization of sound technology & public attitudes will meet Future energy needs. DUFFY, J. P. Affiliation Unknown. 79/11/10. 3pp.
- 7912190558 Responds to NRC 791108 ltr re NUREG-0630. "Cladding Swelling & Rupture Models for LOCA Analysis." Rept appears to be thorough compilation of recent experimental data on cladding deformation. deformation. SCHERER.A.E. C-E Power Systems. LD-79-070. 79/12/11. 10pp.
- 7912190573 Responds to NRC 791108 ltr re NUREO-0630, "Cladding Swelling & Rupture Models for LGCA Analysis." Vendor recommends evaluation of all cladding data accumulated since issuance of 10CFR50. 46, App K. Industry committee is proper forum. TAYLOR, J. H. Babcock & Wilcox Cu. 79/12/10. 3pp.
- 7912190599 Forwards response to NRC 791108 ltr re NUREG-0630, "Cladding, Swelling & Rupture Models for LGCA Analysis." Comments on model representation, location of curves, industry std. ECC5 model, sensitivity studies & future programs. BUCHHOLZ, R. H. General Electric Co. MFN-294-79. 79/12/07. 79/12/07. 18pp.
- 7912190639 Forwards responses to NRC 791108 ltr re NUREG-0630, "Cladding Swelling & Rupture Hodels for LOCA Analysis," Concludes that rupture blockage data supports conservatism of current vendor rupture blockage model.

  OMSLEY, 6, F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/12/10. 7pp.
- 7912190651 Summary of Ad Hoc Subcommittee on THI-2 Accident
  Implications 790711 meeting w/B&H.NUS Corp.BQ&E.Bechtel &
  Takyo Electric Power Co in Washington.BC re long-term THI-2
  implications.
  # ACRS Advisory Committee on Reactor Safeguards. 79/07/11. 45pp.
- 7912200755 NUREG-0002

  Errata for final GEIS re use of recycled Pu in mixed oxide fuel in LWR. el in Lwn. Commission. 76/11/26. 41pp. Available at NTIS.
- 7912200766 NURE0-0316 "Alternative Electrical Transmission Sys & Environ Impact."
  SCHIEFELBEIN.G. Battelle Hemorial Institute, Pacific Northwest
  Laboratory. EY-76-C-04-1830. BNWL-1774. 77/08/31. 70pp.
  Available at NTIS.
- 7912200B50 NUREO-0306
  "Nurlean Power Plant Operating Experience 1976."

  \* Office of Hanagement and Program Analysis. 77/12/31. 260pp.
  Available at NTIS.
- 7912210023 "Gas Scintillation Proportional Counter for Measuring Plutonium in Humans & Environ." final rept for 760701-790920. 770930. PALMER.H.E. Battelle Memorial Institute, Pacific Northwest Leboratory. FIN 8-2091. PNL-3151. 79/11/30. 27pp.
- 7912210053 Comments on NUREO-0610:action level criteria should not be incorporated in any indivival emergency plan w/o plant-specific mods. Notification of unusual event & alert levels tog severe. KNUTH, D.F. KMC, Inc. 79/11/26, 35pp.

- 7912210059 Comments on NUREO-0610: sequence of licensee actions inappropriate for max protection of public health & safety, since "assess & respond" listed as Item 3, not Item 1.
  UTLEY.E.E. Carolina Power & Light Co. 79/11/29. 3pp.
- 791221006B Comments on NUREO-0610: new classification scheme unacceptable. Class 9 accident could occur w/o declaration of general emergency.
  SHOLLY.S. Affiliation Unknown, 79/11/26. 2pp.
- 7912210073 Comments on NUREO-0610: recommends notification of unusual event class be omitted first level of emergency action should be in-plant occurrence.
  WARD, J. E. Atomic Industrial Forum. 79/11/28. 14pp.
- 7912210079 "DECOST-Computer Routine for Decommissioning Cost & Funding elysis." Office of Nuclear Material Bafety & Safeguards. 79/12/31. 86pp.
- 7912210337 "Confirmation of Conversion Factors Relating Exposura & Dose-Equivalent Index Presented in ANSI N19.11."
  YODER, R.C., BARTLETT, H.T., COURTNEY, J. H. Battelle Memorial Institute. Pacific Northwest Laboratory. PNL-3219. 79/11/30. 77pp.
- 7912240002 NUREG/CR-1144
  "Nemaha Uplift Seismotectonic Study:Regional Tectonics & Seismicity of Eastern KS."
  WILSON.F. M. Kansas, State of. FIN 8-6172, 79/11/30. 25pp.
- 7912240184 Ack receipt of PA Emergency Mgt Agency 791113 ltr re NUREG-0553. "Beyond Defense-in-Depth." Recommendations will be submitted to Commission after public comments are reviewed. reviewed. RYAN.R.G. Office of State Programs, 79/12/04. ip.
- 7912270026 Notice of issuance & availability of proceedings of radiological emergency preparedness trained conference on 790724-25 in KG City, MO. RYAN, R. O. Office of State Programs, 79/11/27, 7pp.
- 7912270200 Forwards rept, "Westinghouse Prediction for LOFT Nuclear Experiment 13-1."

  REED.C. Commonwealth Edison Co. 09-26. 79/12/15. 1p.
- ---7912270207 "Westinghouse Prediction for LOFT Nuclear Experiment LG-1."

  \* Westinghouse Electric Corp. 79/12/15. 84pp.
- 7912270601 Responds to NRC 790902,13 % 1030 ltrs re completion data for analyses of transients & accidents. Hestinghouse owners group will submit analysis by BOO331,per NUREG-0578.
  REED,C. Westinghouse Operating Plants Dwners Group, 79/12/20. lp.
- 7912280121 Comments on NUREG-0610: consideration of emergency classification sys should be subj to negotiation & agreement between licensee & local/state authorities based upon site & plant specific characteristics.

  JOHNSON.W.P. Yankee Atomic Electric Co. WYC-79-31. 79/11/28. 2pp.
- 7912280126 Responds to 791112 ltr expressing concern re health effects of radioactivity from nuclear reactors. Forwards excerpts from NRC 1978 Annual Rept & cover page of NUREQ-0558, DENTON. H. R. Office of Nuclear Reactor Regulation. 79/12/05. 11pp.
- --7912280132 Expresses concern re health effects of radioactivity from nuclear reactors.

  CARTER, R. A. Affiliation Unknown. 79/11/12. 3pp.
- 7912280409 Comments on NUREG-0610: improvement in emergency preparedness by switch to four emergency classifications does not support change.
  RENBERGER, D. L. Washington Public Power Supply System. 79/11/27.
- 79:12280419 Commants on NUREQ-06:0: extensive communication between plant & state & local agencies is overkill & overreaction & not in interest of public safety.

  OLBON, R. C. Baltimore Gas & Electric Co. 79/12/05. 2pp.
- 79:12280425 Comments on NUREQ-06:10: time in which emergency repts must be made is unduly restrictive. Licensee should not be required to promptly notify state & local offsite agencies for many unusual events.

  FERRY.J.L. Affiliation Unknown. 79/11/12. 2pp.
- 7912280815 Comments on NUREO-0313 Revision 1: classification of piping should be by safety class Guestions exclusions of Cast 304 & 316 matl from list of conforming matl. Recommends 1-up interval for nonconforming svc sensitive line insp. HOFFMAN, J. R. Yankse Atomic Electric Co. MEO 533/79. 79/12/19, 1p.

- 7912280647 Discusses availability of funds for radiological emergency response plans & preparedness in response to 791105 comments on rept: "Beyond Dafense-In-Dapth."
  RYAN.R.O. Office of Blate Programs. 79/12/07. 2pp.
- 7912280681 Forwards NRC/EPA task force rept on emergancy planning, NUREO-0396/EPA 3201-78-016.W/o ancl. COLLINS,H.E. Assistant Director for Emergancy Preparadness, 79/11/30. ip.
- 7912310085 Comments on NUREO-0610: state & lucal offsite authority actions checklist is especially valuable in common emergency for inculing what each state should be doing at each level. EARLY.M.P. Wisconsin, State of. 79/11/28, 3pp.
- 79123:0144 Forwards draft proposed text for response to UCS petition. Lessons Learned & Bulletins & Orders Task Forces should concur before response issuance. LAINAS. Plant Systems Branch. 79/12/13. 6pp.
- 7912310153 NUREO/CR-0970
  "Qualification Testing Evaluation Program, LWR Safety
  Research, Quarterly Rept, Jan-Mar 1979."
  BDNION.L.L., CLOUGH.R.L., SALAZAR.E.A. Sandia Laboratories. FIN
  A-1051-9. BAND79-1314. 79/11/30. 49pp. Available at NTIS.
- 7912310202 NUREO/CR-1075
  "Rafill Effects Program," quarterly progress rapt, Apr-June
  1979,
  CRDMLEY, C. J., CARY, C. N., ROTHE, P. H. Crears, Inc. FIN A-4070.
  CREARE TN-304, 79/12/01, 26pp.
- 791231020B NUREO/CR-1175
  "Statistical Analysis of Earthquake Oround Motion
  Parameters."
  \* Shannon & Wilson, Inc. FIN B-3015, NRC-04-76-200, 79/12/31, 201pp.
- 7912310363 NUREO-0503

  Orsen book: "FYBO Bupplemental Budget Request."

  \* Division of Budget. 79/12/10. 24pp. Available at NTIB.
- 7912310529 NUREO/CR-0947
  "Steam Explosion Efficiency Studies."
  BURTON,L.D., BENEDICK,W.B. Sandia Laboratories. FIN A-1030.
  SAND79-1399. 79/11/30. 62pp. Available at NTIS.
- ORG CORRESPONDENCE WITH OTHER ORGANIZATIONS
- 7912040023 Responds to 790921 ltr forwarding Aug progress rept.Requests clarifying info re cost figures for June & Jul. SCARANG.R.A. Uranium Recovery Licensing Branch. FIN A-2010. 79/10/15. ip.
- 7712050606 Urges prompt response to UCS patition for emergency & remedial action filed 2 yrs previous UCS 770307 motion for expedited decisionmaking & accompanying 1tr are still unanswered.

  WEISS.E.R. Sheldon, Harmon & Heiss. 79/11/05. 1p.
- 7912060184 Notifies that IE Info Notice 79-12A, "Attempted Damage to New Fuel Assemblies," was sent to Encl list of licensees in State of IL.
  PAPPAS.H. Region 3, Chicago, Office of the Director. 79/11/15.
- 7912120004 Forwards util distribution list & IE Info Notice 79-29.
  "Loss of Nonsafety-Related Reactor Coolant Sys
  Instrumentation During Operation."
  PAPPAS.H. Region 3, Chicago, Office of the Director. 79/11/26, 280.
- 7912120345 Forwards IE Bulletin 79-26, "Boron Loss From BHR Control Blades."

  PAPPAS.H. Region 3, Chicago, Office of the Director. 79/11/26, lp.
- 79:12:170:193 Forwards "Critical Reviews.Core Motion Monitoring" by ANS. Requests info re distribution of ANB critical reviews. BENNETT.Q.L. Research Support Branch. 79/11/27, ip.
- ~~7912170199 "Critical Reviews, Core Motion Monitoring," THIS: J. A. American Nuclear Society. 79/08/15. 45pp.
- 7912180219 Forwards std order for DOE.work, "Electrical, Instrumentation & Control Bys Bupport," issued to LLL.
  EISEMHUT.D. 9. Division of Operating Reactors. 79/11/20. ip.

- --7912180222 Std drder for DOE work: "Electrical Instrumentation & Control Sys Support:" issued to LLL.
  TRIPLETT, M.P. Office of Nuclear Reactor Regulation. FIN A-0231.
  20-80-38, 79/10/10. 13pp.
- 7912180700 Forwards results of tritium target container leak test. No detectable loss of pressure evident. HAFF, K. W. Dak Ridge National Laboratory. 14664. 79/11/09. 4pp.
- 7912190025 Forwards IE Circular 79-22, "Stroke Times for Power Operated Relief Valves." No written response required. PAPPAS.H. Region 3, Chicago. Office of the Director. 79/11/19. 2pp.
- 7912190051 Forwards Std Order for DOE work, "Electrical Instrumentation & Control Sys Support." EISENHUT.D. 0. Office of Nuclear Reactor Regulation. 79/11/12. 1p.
- --7912190064 Btd order for DDE work: "Electrical Instrumentation & Control Sys Support:" issued to EC&O.
  TRIPLETT.H.P. Office of Nuclear Reactor Regulation. FIN A-6256.
  20-80-39. 79/11/13. 11pp.
- 7912190503 Advises that IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation," was sent to listed utils on 791130 for action & info. CARRDLL.D.E. Region 3, Chicago, Office of the Director. 79/12/05.
- 7912190504 Forwards comments on NUREG-0505. Agrees generally w/thesis that operational safety factors require proportionally greater attention.

  LEE, G. Atomic Industrial Forum. 79/12/13. 33pp.
- 7912200204 Describes info needed for license application review scheduling & resource planning through FY82 Requests response by 791201.

  DENTON.H.R. Office of Nuclear Reactor Regulation. 79/11/29. lp.
- 7912200666 Requests comment on pilot installation of atmoshpere modeling computer codes. NRC reviewing codes as means of assessing need for protective actions offsite during nuclear emergencies.

  GDSBICK. L. V. Office of the Executive Director for Operations.
  79/12/07. 2pp.
- 7912280403 Forwards summary of 791107 meeting w/DDE re draft regulation on radwaste disposal. MARTIN, J. B. Division of Waste Management. 79/12/03. 7pp.
- 7912310144 Forwards draft proposed text for response to UCS petition. Lessons Learned & Dulletins & Orders Task Forces should concur before response issuance. LAINAS.O. Plant Systems Branch. 79/12/13. App.
- 7912310195 Requests identification of all anticipated agency requests for NRC safety reviews through FYBO.

  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/11/29. 1p.
- 7912310218 Forwards two std orders for DDE work re-fire protection re-evaluation. Requests DDE acceptance.
  EISENHUT, D. G. Diffice of Nuclear Reactor Regulation. FIN A-3107-0.
  FIN A-3339. 79/12/11. 1p.
- --7912310225 Std order for DOE work: "Fire Protection Re-evaluation," issued to BNL.
  TRIPLETT.M. P. Office of Nuclear Reactor Regulation. FIN A-3107-0.
  20-80-52. 79/12/05. ip.
- --7912310233 Std order for DDE work: "Fire Protection Re-evaluation," issued to INL..
  TRIPLETT.H.P. Office of Nuclear Reactor Regulation. FIN A-3335-0, 20-80-53. 79/12/05. 9pp.

# PR PROPOSED RULE

7912030103 Comments in opposition to proposed revisions to 10CFR30.40.
70.150 & 170 governing mot of U mill tailings & const of major milling plants. Rules not based on final EIS & are therefore premature.

8TEVENS.B. Kerr-McGme Corp. 79/10/23. 14pp.

- 7912040033 Forwards proposed rule changes to 10CFR30, 40, 70, 150 & 170 which were issued on 790824 Regulations amended to include recommendations in draft OEIS on U milling, W/o enci.
  MILLER.N J. Urantum Recovery Licensing Branch. 79/11/01. 1p.
- 77(2040)52 Comments on proposed rule 10CFR30:points out gotential conflict in Criterion 4. Suggests that thinner clay cover may meet requirements. "Major site const" should be defined. Surety review processes have no regulatory provisions. MILLS, L.M. Tennessee Valley Authority. 79/11/08. 2pp.
- 4.79\204045] Comments on proposed rules 10CFR30,40.70.150 & 170:agrees ω/ alternative methods of establishing financial responsibility & formally records previous oral comments. PROVGST.L. Affiliation Unknown. 79/09/19. lp.
- 7912040525 Comments on proposed rules 10CFR30,40 & 150: license requirements covering use of U for research appear to be counterproductive.

  VAN MICHAELIS.H Affiliation Untrown. 79/10/30. 1p.
- 7912050617 Comments on proposed rules 10CFR30,40,70,150 & 170: Environmental Policy Inst maintains that NRC has not considered erosive nature of mill tailings deposits. BERICK,D. Environmental Policy Institute. 79/10/24.
- 7912060023 Comments on proposed rule 100FR30: Dept of Health suggests appropriate adjustments be made re health effects & restoration of tailings sites. Long-term monitoring should be asjusted according to mill site.
  ANDERSON, L. F. Utah, State of. 79/10/25. 2pp.
- 7912050030 Comments on proposed rule 10CFR30: Dept of Health suggests further evaluation needed of environ & occupational hazards caused by U mills & mines.

  HAZLE: A. J. Colorado, State of. 79/10/18. 2pp.
- 7912060039 Comments on progosed rule iQCFR30: GEIS reflects NRC policy to jeopardize public health & safety. NRC continues to thwart NEPA objectives. Radon issue first raised by citizen intervenors.

  KEPFORD, C. Environmental Coalition on Nuclear Power. 79/10/24.
- 7912060052 Comments on proposed rule 10CFR30:NRC should have jurisdiction over disposal sites. Proposes that lotal vote redisposal sites be accepted. Uninhabited areas do not remain uninhabited forever.
  EIKUM.R L. Affiliation Unknown. 79/10/20. lp.
- 79120a0062 Comments on proposed rules 10CFR30.40.70,150 & 170:health & safety of future generations should considered prior to present day economic considerations re U mill tailings requirements.

  BATES.A. Affiliation Unknown. 79/09/13. 2pp.
- 7912060075 Comments on proposed rule 10CFR30 authority to license U mills on Indian lands should remain w/NRC Charges levied on activities on Indian lands should be paid to US in trust for Indian tribes.

  GABRIELIE. Council of Energy Resource Tribes. 79/10/23. 14pp.
- 7912060002 Comments on proposed rule 10CFR30: NRC should have licensing authority over BOE-owned U mill tailings. Erosion must be considered Suggests that annual imap results be made public. LOCHSTET.W.A. Environmental Coalition on Nuclear Power. 79/10/23.
- 7912060204 Comments on proposed rule 10CFR30.facilities for downgradient monitoring of groundwater should be included in design of disposal facility for U mill tallings & wastes. MEIEROTTD.4.E. Energy, Dept. of. ER-79/882
- 7912060603 Comments on proposed rule 10°CFR30: siting should be primary concern in tailings mot Suggests more discussion on implementation of tailings control in agreement states.

  DANIELSON.L.J. National Wildlife Federation. 79/10/24. 23pp.

CFR30: on behalf of Spokane responsibility & in state. Federal govt adequate monitoring. 10/30. 4up.

30: private property rights in tives to prevent ivities. ion. 79/10/25. 3pp.

- 7912070277 Comments on proposed rule iOCFR30:concurs w/NRC position that control measures be based on site-specific evaluations. Proposes that public health be made primary consideration in mgt objectives.
  RITCHIE.M. I. Pathfinder Mines Corp. 79/10/23. 31pp.
- 7912070487 Comments on proposed rule 10CFR61: regulations do not cover all radioactive matl & clarification needed for role of independent waste processor. SCHNEIDER: K. N. Office of State Programs. 79/11/02. 1p.
- 7912110170 Comments on proposed rule 10CFR&1: regulations concerning radwaste packaging by licensees should be placed in 10CFR20, 40,50.% 70. Waste generators should be required to solidfy liquid waste w/o leaving free standing liquid. VADEN, J. Novada, State of. 79/11/19. 2pp.
- 7912110108 Comments on proposed rule 10CFR30; supports comments by American Mining Congress. Suitable discussion of environ aspects of mining is omitted. DDE comments on proposed EPA radwaste criteria encl. SCHENDEL, N. R. Westinghouse Electric Corp., Wyoming Mineral Corp. GEA-79-933. 79/10/24. 38pp.
- 79:21:10:175 Comments on proposed rule 10CFR71: recommends alternate means of compliance to conditions specifying radioactive mat1 packaging Clearer indication should be made of subparagraph conditions.
  BURSTEIN: 8. Wisconsin Electric Power Co. 79/10/31. ip.
- 7912110198 Comments on proposed rule 10CFR70: authorization of routine use of Pu powered pacemakers not advantageous due to relative life span & cost. DELAND,F. H. Vet. Admin. Hosp. Lexington.KY. 79/10/31. lp.
- 79:2120012 Comments on proposed rule iOCFR71: objects to segregation of radioactive matis regulation due to implication that radioactive matis present special hazards. MOURY.W.R. General Atomic Co. (subs. of Oulf Cil Co.). OEN-1119, 79/10/29. Gpp.
- 7912120039 Comments on proposed rule 10CFR30: clarity needed in Criterion 3 re-prime option for tailings disposal & in conflicting definitions of byproduct mat1.

   Rocky Mountain Energy Co. 79/10/24, 69pp.
- 7912120042 Comments on proposed rule 10CFR30; should not allow U industry to continue hapharand disposal of U mill tailings. Regulation definitions need clarity. WEISD.R.W. Affiliation Unknown. 79/10/21. 2pp.
- 7912120046 Comments on proposed rule 10CFR30: supports comments of American Mining Congress re U milling. CANFIELD.K.S. Homestake Mining Co. 79/10/24. lp.
- 7912120051 Comments on proposed rule 10CFR30: fails to emphasize contamination prevention & outline stringent criteria for containment siting areas. PERRYL Black Hills Alliance. 79/11/08. 2pp.
- 7912120055 Comments on proposed rule iOCFR30: NEPA & health & safety provisions play no part in agency consideration of radom problem. Certificate of Svc re NRC answers on GEIS encl. XEPFORD: C. Environmental Coalition on Nuclear Power. 79/10/24. 49pp.
- 7912120063 Comments on proposed rule 10CFR30: fails to comply w/NEPA due to lack of assessment of total Rn-222 CI released over full period of toxicity of U mill tailings piles.

  JOHNSRUD, J. H. Environmental Coalition on Nuclear Power. 79/10/23.
- 7912120238 Comments on proposed rules 10CFR30, 40, 70, 150 & 170: licensing stds for U mill tailings are too loose. Criterion 6 is dangerous & counterproductive.
  LEWIS, M. L. Affiliation Unknown. 79/09/22, 1p.
- 7912120240 Forwards comments on proposed rules 10CFR30.40.70.150 & 170 & draft OEIS: draft OEIS fails to achieve stated purpose. Should be revised & reissued Three vols of comments encl. GVERION, J. A. American Mining Congress. 79/10/24. 300pp.
- 7912120247 Comments on proposed rules 10CFR30,40,70,150 & 170; proposes amend to account for differences in mining procedures. Encourages redefinition of const Disposal & surveillance of waste impractical & costly.

  MARSHALL,W.K. Mobil Dil Corp. (subs. Mobil Corp.), 79/10/23, 10pp.

- --79(2)20294 Comments on proposed rules 10CFR40 & 150:efficacy of requirement for specific NRC license during renewal period of Agreement state license is highly questionable.

  MAREHALL, W. H. Mobil Oil Corp. (subs. Mobil Corp.). 79/10/23.
- 7912120253 Comments on proposed rule 10CFR30; overestimated risks, understated costs & inadequate support for proposed rules. SCOTT.C.B. Union Oil Co. of California. CBS 79-311. 79/10/23. 2pp.
- --7912120260 Comments on proposed rule 10CFR30: objects to adoption of rules based on draft EIA.NRC should re-evaluate draft OEIS & repropose rules as justified. BCOTT.C.B. Union Oil Co. of California. CBS 79-312. 79/10/23.
- 7912120363 Comments on proposed rule 10CFR30: omits discussion of environ impacts of U mill mining operation.
  SCHENDEL,K.R. Wyoming Mineral Corp. 0EA-79-933. 79/10/24. 31pp.
- 7912120364 Comments on proposed rule 10CFR30: fails to set min containment requirement for mill tailings & clarify how new stds apply to old tailings sites.

  EAST.D. Wycming Outdoor Council. 79/10/23, 1p.
- 7912130025 Notifies Bubcommittee on Nuclear Regulation of 791015 notice of final rulemaking re-antitrust review procedures.FR notice encl.
  DENTON, M. R. Office of Nuclear Reactor Regulation. 79/10/15. 2pp.
- --7912130028 Notice of final rulemaking re antitrust review procedures. CHILK. B. J. Office of the Secretary of the Commission. 79/10/15. 9pp.
- 7912130031 Comments on proposed rule 10CFR30: endorses comments & testimony of American Mining Congress re OEIS on U milling. CANFIELD, K.S. Affiliation Unknown. 79/10/24. ip.
- 7912130036 Notifies Bubcommittee on Environ Energy & Natural Resources of 791015 notice re antitrust review procedures.

  DENTON. H. R. Office of Nuclear Reactor Regulation, 79/10/15. 2pp.
- 7912130045 Notifies Subcommittee on Energy & Power of 791015 notice of final rulemaking re-antitrust review procedures. FR notice encl. DENTON, H. R. Office of Nuclear Reactor Regulation. 79/10/15. 2pp.
- 7912130077 Natifies Bubcommittee on Energy & Environ of 791015 notice of final rulemaking re-antitrust review pracedures. FR notice encl. .
  DENTON. M.R. Office of Nuclear Reactor Regulation. 79/10/15. 2pp.
- 79(2)30255 Natice of intent to participate in proposed rulemaking restorage & disposal of nuclear wastes. Position on issues: reasonable assurance for safe unsite storage exists.
  CRAMER.E.N. Naighburs for the Environment. 79/11/18. 1p.
- 7912130261 Notice of intent to participate in proposed rulemaking restorage & disposal of nuclear wastes.
  ANDALMAN.E. Mississippians Against Disposal. ANDALMAN.E. Andalman.
  Adalman & Steiner.P.A. 79/11/20. ip.
- 7912130267 Notice of intent to participate in proposed rulemaking restorage & disposal of nuclear wastes.

  MCORANERY, J.P. Scientists & Engineers for Secure Energy.

  MCORANERY, J.P. LeBosuf, Lamb. Luiby & MacRas. 79/11/26.
- 7912130274 Notice of intent to participate in proposed rulemaking restorage & disposal of nuclear wastes.
  RICHARDB, J.R. Beientists & Engineers for Becure Energy.
  RICHARDB, J.R. Capital Legal Foundation. 79/11/26. 2pp.
- 791213027B Notice of intent to participate in proposed rulemaking restorage & disposal of nuclear wastes. Position on issues: adequate assurance that radwaste can be safely stored & disposed of exists.

  GALLO, J. Consumers Power Co. GALLO, J. Isham, Lincoln & Beals. 79/11/24. 2pp.
- 7912130287 Notice of intent to participate in proposed rulemaking restorage & disposal of nuclear wastes. Position on issues: unclear whether storage will be available in future. Onsite storage will be proven unsafe.

  LOCKBTET.W.A. Affiliation Unknown. 79/11/20. 2pp.

- 7912130289 Notice of intent to participate in proposed rulemaking restorage % disposal of nuclear wastes. Position on issues:
  NRC lacks authority to promulgate rule resonsite storage after licence approaching DARBY.C. Hanford Conversion Project. 79/11/21. [p.
- 7912130292 Notice of intent to participate in proposed rulemaking restorage & disposal of nuclear wastes. Position on issues:

  NRC has not adequately addressed time frame for U tailings isolation.

  GERICK-D. Environmental Policy Institute. 79/11/23. ip.
- 7912130296 Notice of intent to participate in proposed rulemaking restorage & disposal of nuclear wastes. Position on issues: spent fuel can be stored onsite safely. Expansion of capacity presents no safety hazards \* Public Service Electric & Gas Co. of New Jersey 79/12/12. 2pp.
- 7912130299 Notice of intent to participate in proposed rulemaking re storage & disposal of nuclear wastes. Position on issues: engineered barrier concept inadequate to overcome potential problems. HLUCHAN, R. M. New Jersey, State of 79/11/28. 3pp.
- 7912130307 Notice of intent to participate in proposed rulemaking restorage & disposal of nuclear wastes. Position on issues: recommends investigation into conditions of spent fuel storage to document problems.

  SCHAEFER.W.W. Bafe Haven.Ltd. 79/11/12. 2pp.
- 7912130309 Notice of intent to participate in proposed rulemaking re storage & disposal of nuclear wastes. Position on issues: util must undertake responsibility of providing safe offsite disposal. Certificate of Svc encl. VALDRE, C. H. W. Drean County, NJ. 79/11/23. 10pp.
- 7912130311 Notice of intent to participate in proposed rulemaking re storage & disposal of nuclear wastes. Due to uncertainty of availability of future raduaste disposal sites, onsite storage impact must be included in environ evaluation. MUCHNIGKI, E. D. Ohio, State of. 79/12/12. 2pp.
- 7912130316 Notice of intent to participate in proposed rulemaking re storage & disposal of nuclear wastes. Identity, qualifications & positions set forth in 791123 petition to intervene incorporated by ref. MILLER, D. S. Sensible Maine Power. 79/11/26. lp.
- 7912130317 Notice of intent to participate in proposed rulemaking restorage & disposal of nuclear wastes. Position on issues: reasonable assurance of safe radwaste disposal exists. IRNIN.D.P. Uranium Fuel Cycle Group. IRWIN.D.P. Hunton & Williams. 79/11/24. App.
- 7912130319 Forwards petition for intervention.
  WILSON, R. P. South Carolina, State of, 79/11/20, ip.
- ---7912130320 Requests to intervene RP Wilson will be atty of record. WILSON R. P. South Carolina, State of. 79/11/20. 1p.
- 7912130324 Forwards "High Level Radwaste Mgt Revisited," presented at American Chemical Society 790911 meeting in Washington. DC. HILL.O.F. Affiliation Unknown. 79/11/21. 1p.
- --7912130326 "High Level Radwaste Mgt Revisited." HILL,O.F., NIGHTINGALE.R.E. Battelle Memorial Institute, Pacific Northwest Laboratory. PNL-SA-7951. 79/09/30. 27pp.
- 7912130333 Dept of Conservation, Div of Mines & Geology notice of intent to participate in proposed rulemaking re storage & disposal of nuclear wastes.

  OREW.P. C. California, State of. 79/11/27. lp.
- 7912130336 Notice of intent to participate in proposed rulemaking restorage & disposal of nuclear wastes.
  RAUDENBUSH.M.H. B. M. Stoller Corp. (subs. of Arthur D. Little, Inc.).
  79/11/12. ip.
- 7912130342 Forwards notice & petition to participate in rulemaking renuclear waste disposal. LOMERRE, R. M. Texas, State of. 79/11/20. 1p.
- --7912130344 Notice of intent to participate in proposed rulemaking re storage & disposal of nuclear was res. LOMERRE, R. W. Texas, State of. 79/11/20, 3pp.

- 7912130348 Forwards nutice of intent to participate in rulemaking renuclear waste disposal.
  BIALIK.E.I. New York, State of, 79/11/21, 1p.
- --7912130352 Notice of intent to participate in proposed rulemaking restorage & disposal of nuclear wastes. Position on issues: NRC should impose moratorium on licensing new facilities during proceeding. BIALIK, E. I. New York, State of. 79/11/21. App.
- 7912130396 Seeks denial of intervenor Christa-Maria request for reconsideration of NRC 791025 notice of proposed rulemaking. Notice of appearance of MI MILIER, J Gallo & P Thornton on behalf of util & Certificate of Svc encl. GALLOJ. Consumers Fower Co. GALLOJ. Isham, Lincoln & Heake. 79/12/08. 17pp.
- 7912130398 Supplemental filing to notice of intent to participate in proposed rulemaking re storage & disposal of nuclear wastes. Position on issues:testimony of experts from educational & technical institutions should be solicited. HILSON,R.J. Natural Resources Defense Council. 79/12/07. 9pp.
- 7912130450 Notice of intent to participate in proposed rulemaking restorage & disposal of nuclear wastes. Position on issues: safe storage & disposal reasonably assured. Formal discovery on issue unnecessary.

  DISTEFANG. J., BROWN, O. F., MCGOVERN, K. S. Energy, Dept. of. 79/11/23.
- 7912130453 Notice of intent to participate in proposed rulemaking restorage & disposal of nuclear wastes. Position on issues: not advocated Objects to elimination of discovery. SALZMAN.L. Friends of the Earth. 79/11/26. 1p.
- 7912130458 Notice of intent to participate in proposed rulemaking restorage & disposel of nuclear wastes. Position on issues: low level radwaste can be safely stored until viable option for disposal is found.

  SNAGER.H.S. Tennessee Valley Authority. 79/11/26. 3pp.
- 7912130460 Notice of intent to participate in proposed rulemaking restorage & disposal of nuclear wastes. Position on issues: safe disposal scientifically & technically proven. Encourages full participation re discovery.

  VOIOT, H. H. Niagara Mohawk Power Corp. VOIOT, H. H. Omaha Public Power District. VOIOT, H. H. Power Authority of the State of New York. 79/11/26. 3pp.
- 7912130463 Notice of intent to participate in proposed rulemaking re storage & disposal of nuclear wastes. Position on issues: citizen rights re environ matters will be adversely affected by rule.

  MACARTOR, J. D. Delaware, State of. 79/11/26, 29p.
- 7912130469 Notice of intent to participate in proposed rulemaking restorage & disposal of nuclear wastes. Position on issues: safe disposal & storage not reasonably assured. Notice of appearance encl.
  SHELDON, K. P. New England Coalition on Nuclear Pollution.
  SHELDON, K. P. Sheldon, Harmon & Weiss. 79/11/26. 5pp.
- 7912130475 Notice of intent to participate in proposed rulemaking restorage & disposal of nuclear wastes. Position on issues: will assist in establishing basis for possibility of safe atorage & disposal. Detailed discovery unnocessary. ROBINGONIR. K. Exxon Nuclear Co. . Inc. (subs. of Exxon Corp.). 79/11/26. 29p.
- 7712130481 Notice of intent to participate in proposed rulemaking re storage & disposal of nuclear wastes. Position on issues: safe storage & disposal assured. Dbjects to addl procedures for interparticipant discovery. Certificate of Svc encl. AXELRAD, M. Edison Electric Institute. AXELRAD, M. Lowenstein, Newman, Reis, Axelrad & Toll. 79/11/26. 20sp.
- 7712130485 Notice of intent to participate in proposed rulemaking restorage & disposal of nuclear wastes. Position on issues: safe disposal & storage not reasonably assured Notice of appearance encl. GHELDEN, K. P. Christa-Maria. SHELDEN, K. P. Sheldon, Harmon & Weiss. 77/11/16. Spp.
- 7912130490 Notice of intent of Div of State Energy to participate in proposed rulemaking re storage & disposal of muclear wastes. Position on issues not advocated. MUNNERY. H. J. Wisconsin, State of, 79/11/23, 1p.

- 7912130496 Notice of intent to participate in proposed rulemaking re storage & disposal of nuclear wastes. Position on issues: safe storage & disposal may be achieved by implementing available technology. MUNNERY, W. J. General Electric Co. 79/11/23. 1p.
- 7912130499 Notice of intent to participate in proposed rulemaking re storage & disposal of nuclear wastes. Position on issues: safe storage & disposal reasonably assured. Formal discovery unnaccessary. Statement on nuclear waste disposal ancl. HALBKE.C. Atomic Industrial Forum. 79/11/21. 4pp.
- 7912130502 Notice of intent to participate in proposed rulemaking re storage & disposal of nuclear wastes. Position on issues not advocated. LEWIS, M. I. Affiliation Unknown. 79/10/24. 1p.
- 7912130510 Notice of intent to participate in proposed rulemaking re storage & disposal of nuclear wastes. Position on issues not advocated. Greater participation should be encouraged. WILSON, R. J. Natural Resources Defense Council. 79/11/26. App.
- 7912130518 Notice of intent of Lone Star Chapt to participate in proposed rulemaking re-storage & disposal of nuclear wastes. Position on issues not advocated.

  KRAMER, K. Sierra Club. 79/11/21, 2pp.
- 7912130523 Notice of intent by OR DDJ to participate in proposed rulemaking re storage & disposal of nuclear wastes. Position on issues not advocated. House Bill 2570 re nuclear-fueled thermal plants encl.
  BANDUK, R. M. Oregon, State of. 79/11/13. Spp.
- 7912130525 Notice of intent by Mockingbird Alliance to participate in proposed rulemaking re storage & disposal of nuclear wastes. Position on issues: clarification of risks should take precedence over methods. Comments on draft EIS encl. BAKER, B. E. Affiliation Unknown. 79/11/25. Opp.
- 79121310529 Notice of intent by American Inst of Chemical Engineers to participate in proposed rulemaking re storage & disposal of nuclear wastes. Position on issues, stated in bulletin, "Radioactive Mastes."
  WEST.A.S. Affiliation Unknown. 79/11/20. App.
- 7912130530 Notice of intent by CA Dept of Conservation to participate in proposed rulemaking re storage & disposal of nuclear wastes. Position on issues will be coordinated w/CA Energy Commission.

  OREW.P.C. California, State of. 79/11/27. ip.
- 7912130933 Notice of intent by ANS to participate in proposed rulemaking re storage & disposal of nuclear wastes. Position on issues: safe disposal in mined geologic repository is acceptable approach. Opposes in-depth discovery. Policy encl. MOWBOISSE, R. M. Pacific Legal Foundation. 79/11/26. 7pp.
- 7912130545 Motion for reconsideration of proposed rulemaking re storage & disposed of nuclear wastes. Conequences of proposed action should be subj of adjudicatory decision, Urgea completion of generic review before issuance of proposed rule.
  SHELDON, K. P. Christa-Maria, SHELDON, K. P. Sheldon, Harmon & Weiss. 79/11/07. 7pp.
- 7912130549 Forwards CA Energy Commission notice of intent to participate in proposed rulemaking re storage & disposal of nuclear wastes.
  ELLIBON.C. California: State of. 79/11/26. lp.
- ---79121309B2 Notice of intent by CA Energy Commission to participate in proposed rulemaking re storage & disposal of nuclear wastes. Position on issues: safe storage & disposal surrounded by significant technical & economical uncertainties. ELLISDN.C. California, State of. 79/11/26. Spp.
- 7912130559 Forwards notice of intent to participate in proposed rulemaking re storage & disposal of nuclear wastes. JOHNSRUD.J. Environmental Coalition on Nuclear Power. 79/11/26.
- --7912130562 Notice of intent to participate in proposed rulemaking restorage & disposal of nuclear wastes. Position on issues; cessation of radioactive waste generation should be addressed. Objects to limited discovery. W/Catificate of Bvc. JOHNSRUD. J. Environmental Coalition on Nuclear Power. 79/11/25.
- 7912130964 Forwards NJ Dept of Public Advocate notice of intent to participate in proposed rulemaking proceding.

  DNBDDRFF.K.A. New Jarsey, State of. 79/11/07. ip.

- ---7912130567 Notice of intent by NJ Dept of Public Advocate to participate in proposed rulemaking re storage & disposal of nuclear wastes. Position on issues: environ impacts substantially uncertain.
  ONSDORFF.K.A. New Jersey, State of. 79/11/07. 5pp.
- 7912130570 Forwards notice of intent to participate in proposed rulewaking re storage & disposal of radioactive wastes.

  KINDER, E. T. New Hampshire, State of. 79/11/21. 1p.
- ---7912130378 Notice of intent to participate in proposed rulemaking rostorage & disposal of nuclear wastes. Position on issues: safe storage & disposal surrounded by technological uncertainties. Encourages discovery procedures.

  KINDER. E. T. , RATH. T. D. New Hampshire, State of. 79/11/21. 3pp.
- 79121305B2 Forwards MN Pollution Control Agency notice of intent to participate in proposed rulemaking re storage & disposal of radicactive wastes.

  SEMECHALIM.E. Minnesota. State of. 79/11/21. ip.
- ~-7912130590 Notice of intent by MN Pollution Control Agency to participate in proposed rulemaking re storage & disposal of nuclear wastes. Position on issues: safe storage & disposal is uncertain. OLBON. J. F., BENECHAL, M. E., BPANNAUB, W. Minnesota, State of, 79/11/21, App.
- 7912:30596 Forwards notice of intent to participate in proposed rulemaking re storage & disposal of nuclear wastes.

  DALTON, J. N. Virginia, State of. 79/11/26. ip.
- --7912130603 Notice of intent to participate in proposed rulemaking re storage & disposal of nuclear waste. Unable to state position on issues, Encourages full discovery, subj to mechanism of protective orders, DALTON, J., KENLEY, J. B. Virginia, State of, 79/11/26, 2pp.
- 7912130611 Forwards notice of intent to participate in proposed rulemaking re storage & disposal of nuclear wastes. ORIFFINM. Vermont. State of. 79/11/26. 1p.
- --7912130619 Notice of intent to participate in proposed rulemaking re storage & disposal of nuclear wastes. Position on issues: availability of safe storage & disposal should be demonstrated. Encourages full discovery. GRIFFIN.W. Vermont, State of. 79/11/26. 2pp.
- 7912140137 Comments on proposed rule 10CFR140: radiation measurements taken during accident are inaccurate due to antiquated & inaccurate instruments. TMI meets extraordinary nuclear accurrence criteria.

  BRDUDY, P. Affiliation Unknown. 79/11/14. 2pp.
- --7912140144 Comments on proposed rule 10CFR140:NRC decision is foregone conclusion. Public comment simply allows individuals hurt by TMI incident to blow off steam, CRUMLEY, J.A. Affiliation Unknown. 79/11/14. Spp.
- 7912140147 Comments on proposed rule 10CFR140: Het Ed & NRC are derelict in role of protecting public health & safety.
  CRUMLEY, J. A. Affiliation Unknown. 79/11/30. Rpp.
- 79:2:40:52 Comments on proposed rules iOCFR50 & 70:FBAR emergency plan should be emended by referencing details in original plan. Proposed rule is redundent & should be withdrawn. JOHNSON.W.P. Yankee Atomic Electric Co. 797:11/23. 1p.
- 7912140161 Comments on proposed rule 10CFR70:positive benefits of Pupacemaker over risk constitute satisfactory ratio.Pupawared pacemaker should remain available.
  COLLINGS.V.P. Collins.V.P. MD. 79/11/17. 1p.
- 7912170360 Comments on proposed rule 10CFR30: regulations deficient in treatment of siting criteria, below-grade disposal, financial surety provisions, agreement state regulatory progress & in situ U processing.

  LEWIS.B.E. Affiliation Unknown. 79/11/09. 16pp.
- 7912170378 Comments on proposed rules 10CFR50 & 70: implementing procedures should be subj to review during licensing process. App E inadequate due to scant requirements for seargency planning in PSAR.

  MELLB, K. Affiliation Unknown. 79/11/15. 4pp.
- 7912170383 Comments on proposed rule iOCFR30:in order to assure public health & safety,NRC licensing of U mill tailings should centinue along w/state licensing,
  MEISS, J. L. Affiliation Unknown. 79/10/22. Bpp.

- 7912170385 Comments on proposed rule iCCFR30: requiations fail to address enforcement & integrity of operators applying for licenses & to make siting primary consideration over control technology.

  KNAPP, D. Affiliation Unknown. 79/10/29. 2pp.
- 7912180009 Informs of principal area of commentary for Dept of Conservation geologists at rulemaking proceeding on radwaste disposal. List of dept qualifications to participate included.

  OREW.P.C. California, State of. 79/11/30. 2pp.
- --7912180015 Notice by Dept of Conservation of intent to participate in proposed rulemaking re storage & disposel of nuclear wastes. CA Heath 791108 ltr to DDE & JF Davis of State of CA Div of Mines & Ocology commentary on draft EIS encl. OREW.F.C. California, State of. 79/11/27. 15pp.
- 7912180097 Requests placement of OF Brown & R Stein of DOE & MA Glora of Ofc of Nuclear Waste Isolation, Columbus, OH, on svc list. BROWN, O. F. Energy, Dept. of. 79/12/05. ip.
- 7912200077 Patition to intervene in generic rulemaking hearing on storage & disposal of nuclear waste. Potitioner resides within 50 mile radius of Big Rock Point reactor. Dutcome of rulemaking hearing will impact facility.

  O'NEILL.J. Affiliation Unknown. 79/11/29. 4pp.
- 7912200585 Fallowup to 791126 natice of intent to participate in proposed rulemaking re storage & disposal of nuclear wastes. Pasition on issues: will be stated after prehearing conference.per 791129 telecon w/88 Ostrach. VANCE.R.L. Virginia, State of. 79/11/29. 2pp.
- 7912210097 Bubmits names of NRC personnel for addition to distribution list in waste confidence rulemaking.

  CVR.K. Rulemaking & Enforcement Division. 79/11/21. ip.
- 7912210243 Notification of 791128 meeting w/AIF Decommissioning Subcommittee in Bethesda. MD to discuss technical & financial aspects of decommissioning.
  HDWARD, E.D. Atomic Industrial Forum. 79/11/21. 1p.
- 7912280114 Comments on proposed rule 10CFR30: cannot make detailed comparison of regulations until final judgment reached on existing proposals.

  HAWKINS, D. O. Environmental Protection Agency. 79/11/19. 2pp.
- 7912280203 Comments on NUREO-0511: several areas w/incomplete coverage due to lack of info.
  HEDEMAN, W. N. Environmental Protection Agency. 79/11/29. 24pp.
- 7912280218 Comments on proposed rule 10CFR41: releases of nonradicactive liquid or gas effluents should meet federal & state air & water quality stat.

  OVEN, M. B. Florida, State of. 79/11/28. ip.
- 7912280233 Comments on proposed rule 10CFR61: definition of "low-activity bulk solid wastes" needs clarification. Requirement for period of post-closure observation & maint is excellent way to assure adequate decommissioning actions. DERTEL, Q. K. Energy, Dept. of, 79/11/29, 7pp.
- 7912280614 Notifies that Environ Chalition on Nuclear Power intends to participate in rulemaking proceeding. Requests FR notice of proposed rulemaking.

  JOHNGRUD, J. Environmental Coalition on Nuclear Power. 79/10/25.
- 7912310116 Comments on proposed rules 10CFR70 & 73:Category I spec should be increased to higher values such as 10 kg for irradiated fuel. ROTH, J. M. Westinghouse Electric Corp. 79/11/19. 5pp.
- 7912310187 Comments on proposed rules 10CFR30, 40, 70, 150 & 170; application expresses concern that developing regulatory scheme does not adequately take into account unique processes used in fsolation extraction of U. MARSHALL, W. H. Mobil Oil Corp. (qubs. Mobil Corp.), 79/10/23, 10pp.

### PRH PETITION FOR RULEMAKING

7911050268 Notice of issuance & availability of PRH 71-7,
"Nondestructive Testing Mgt Association Denial of Petition
for Rulemaking."
ODBSIGK-L.V. Office of the Executive Director for Operations.
79/10/02. 10pp.

- 7912060610 Notice of intent to fully participate in proposed rulemaking re-storage t disposal of nuclear waste Scupe of rulemaking fails to indale socioeconomic factors Procedures may prevent meaningful participation.

  LAFOLLETIE.B C WALSH.P Wisconsin, State of. 79/11/27. 7pp.
- 7912040411 Notice of intent to fully participate in proposed rulemaking re storage & disposal of nuclear waste. States interests.

  Supports limited participation re aspects of discovery.

  CAHILL, N. J. Consolidated Edison Co. of New York. 797/11/26. App.
- 7912120009 Comments on petition for rulemaking 2-9: favors proposed limits on examination to contentions admitted by NASLP. Regulatory process should move from politics & back to public health & safety.
  PARKYN.J.D. Affiliation Unknown. 79/10/10. lp.
- 7912120022 Denies 771209 request for amend of regulation re agreement state licenses.Limit of 180 days to conduct business in nonagreement states.contained in IQCFR150.20.cannot be changed.

  90581CK.L.V. Office of the Executive Director for Operations.
  79/11/20 4nn
- --7912120028 Notice of denial of petition for rulemaking to Chem Nuclear Sys. Inc 771209 request for amend of 10CFR150, 20 re agreement state licenses. GOSSICH.L.V. Diffice of the Executive Director for Operations. 79/11/20. opp.
- 7912120162 Notifies Subcommittee on Energy & Power of 791002 FR notice of denial of petition for rulemaking PRM-71-7 requiring licensees to have effective GA programs for packaging & transportation to improve safety FR notice encl.

  MINDGUE R. B. Office of Standards Development. 79/10/22. 3pp.
- 7912130332 Comments on proposed rulemaking 50-22 since decommissioning of nuclear power facilities is inevitable, cost estimates of financial mechanisms to meet plannaed & premature decommissioning should be incorporated into code.
  POLLACK.R.P. Critical Mass Enorgy Project. GARLOW, C. Public Interest Research Group. CASCIATO, P. A. Affiliation Unknown.
  79/11/21. 11pp.
- 7912170368 Comments on getition for rulemaking 20-12; radiation warning posting should begin at transition point where permissible unrestricted area exposure levels are exceeded. URC1UOLG.L.R. Pennsylvania State of 79/11/20. 3pp.
- 7912180134 Forwards quarterly rept on petitions for rulemaking as of 790930 Requests placement in PDR.
  FELTON, J. M. Division of Rules and Records. 79/10/18. 20pp.
- 7912310029 Denies 79101B request for reconsideration of NRC 791002 denial of 780510 request for revocation of App E to 10CFR71. Requests comment on use of graded approach where situation—specific OA procedures used. GDSDICK.L.V. Office of the Executive Director for Degrations. 79/12/17. 2pp.
- --7912310032 Requests reconsideration of NRC 791002 denial of 780510 request to revoke App E to 10CFR71 Majority of comments received favored revocation. Requirements impose unnecessary hardships on nuclear industry.

  PEEPLES, W. P. Gulf Nuclear. Inc. 79/10/18. 3pp.

### PROJ PROJECTS - PREDOCKET LICENSING

- 7912030042 Motion by Northern CA Power Agency for reconsideration or mod of ASLB 791101 order for PO&E insp of agency files.
  "Green datting" process should not be imposed Supporting documents & Certificate of Svc encl.
  HCDIARMID.R.C. TRAUGER, T.C.: ADRAGNA, J. M. California, State of. 79/11/09. 31pp.
- 7912030103 Comments in opposition to proposed revisions to iOCFR30:40. 70:150 & 170 governing mgt of U mill tailings & const of major milling plants Rules not based on final EIS & are therefore premature.

  STEVENS.B. Kerr-McGee Corp 79/10/23. 16pp.
- 7912030118 Response in opposition to Northern CA Power Agency motion for protective order re POME fifth set of interregatories. Efforts to eliminate depositions by propounding detailed questions should be considered. Certificate of Svc encl. LENIS.R.A., DOYLE.M.M. Pacific Gas & Electric Co. LENIS.R.A. McCutchen, Doyle, Brown & Emerson 79/10/30, 12pp.

- 7912040453 Comments on proposed rules 10CFR30,40,70,150 & 170:Agrees &/
  alternative methods of establishing financial responsibility
  & formally records previous oral comments.
  PROVDST.L. Affiliation Unknown. 79/09/19. 1p.
- 7912040525 Comments on proposed rules 10CFR30,40 & 150:license requirements covering use of U for research appear to be counterproductive.

  VAN MICHAELIS: H. Affiliation Unknown. 79/10/30. 1p.
- 7912050607 Forwards corrections to intervenors Cities of Anaheim & Riverside 791019 responses to PQ&E fourth set of interrogatories.

  MATT, P. K. Spiegel & McDiarmid. 79/10/29. 2pp.
- --7912050612 Errata for intervenor City of Anaheim 791019 responses to util fourth set of interrogatories.

  \* Anaheim. CA. 79/10/29. App.
- --7912050414 Errata for intervenor City of Riverside 791019 response to util fourth set interrogatories. \* Riverside, CA. 79710/29. Ip.
- 7912050617 Comments on proposed rules 10CFR30, 40, 70, 150 & 170: Environmental Policy Inst maintains that NRC has not considered erosive nature of mill tailings deposits. BERICK.D. Environmental Policy Institute. 79/10/24, Spp.
- 7912090672 Submits comments on Southern CA Edison Co (Edison) & CA Dept of Water Resources joint statement re subpoena duces tecum directed to Edison. Production of documents by Edison in lieu of subpoena duces tecum is unsatisfactory.

  COLDBERG, J. R. Hearing Branch 2. 79/11/14, 2pp.
- 7912060016 Response to POLE motion to compel answers to Cities of Anaheim & Riverside.CA fourth set of interrogatories.Shall comply w/ASLB 791109 order.Certificate of Svc encl. MATT, P. K. Anaheim, CA. MATT, P. K. Spiegel & McDiarmid. 79/11/20.4pp.
- 7912050023 Comments on proposed rule 10CFR30: Dept of Health suggests appropriate adjustments be made re health effects & restoration of tailings sites. Long-term monitoring should be as justed according to mill size.

  ANDERSON, L. F. Utah, State of, 79/10/25, 2pp.
- 7912060030 Comments on proposed rule iOCFR30; Dept of Health suggests further evaluation needed of environ & occupational hazards caused by U mills & mines.

  HAZLE, A. J. Colorado, Btate of. 79/10/18. 2pp.
- 7912040037 Comments on proposed rule 10CFR30: GEIS reflects NRC policy to jeopardize public health & safety, NRC continues to thwart NEPA objectives. Radon issue first raised by citizen intervenors. REPFORD, C. Environmental Coalition on Nuclear Power. 79/10/24, 22pp.
- 79120A0052 Comments on proposed rule 10CFR30: NRC should have jurisdiction over disposel sites. Proposes that local vote redisposel sites he accepted. Uninhabited areas do not remain uninhabited forever.

  EIKUM: R. L. Affiliation Unknown. 79/10/20. 1p.
- 7912060062 Comments on proposed rules 10CFR30, 40, 70, 150 & 170: health & safety of future generations should be considered prior to present day economic considerations re U mill tailings requirements.

  BATES, A. Affiliation Unknown. 79/09/13, 2pp,
- 7912060075 Comments on proposed rule 10CFR30: authority to license U mills on Indian lands should remain w/NRC. Charges levied on activities on Indian lands should be paid to US in trust for Indian tribes.

  GABRIEL, E. Council of Energy Resource Tribes. 79/10/23. 14pp.
- 7912060082 Comments on proposed rule iOCFR30:NRC should have licensing authority over DDE-owned U mill tailings. Erosion must be considered. Buggests that annual inspresults be made public. LOCHBYET.W.A. Environmental Coalition on Nuclear Power. 79/10/23.
- 79120600B7 Advises of NRC refusal to consent to PG&E intention not to produce documents in FERC proceedings. Documents in question subj to insp per ASLAB 78011B order. GOLDBERG, J. R. Antitrust Division. 79/11/14. ip.

- 7952050103 Requests plans re production of documents identified in NRC objections to joint statement of Southern CA Edison Co & State of CA Dept of Water Resources. Reasonable means of minimizing burden are open to discussion.

  GDLDEERG, J. R. Antitrust Division. 79/11/14. 1p.
- 7912050166 Reply of CA Dept of Water Resources to POSE 791024 motion to compel further answers to POSE 790719 fifth set of interrogatories. Objects to all questions. Certificate of Svc encl.

  BIRUMHABEER.M., DEUKMEJIAN.G., CONNETT.R.H. California, State of, 79711708. 11pp.
- 7912080204 Comments on proposed rule 10CFR30; facilities for downgradient monitoring of groundwater should be included in design of disposal facility for U mill tailings & wastes MEIERDTTO,1.E. Energy, Dept. of. ER-79/882.
- 7912060603 Comments on proposed rule iOCFR30; siting should be primary concern in tailings mgt. Suggests more discussion on implementation of tailings control in agreement states. DANIELSON.L. J. National Wildlife Federation. 79/10/24. 23pp.
- 7912050505 Comments on proposed rule 10CFR30: on behalf of Spokane Indian Tribe of WA, objects to placing responsibility & jurisdiction of tallings reclamation on state. Federal govt should carry responsibility to ensure adequate monitoring. DELLWO,R.D. Affiliation Unknown. 79/10/30. 4pp.
- 7712060675 Comments on proposed rule 10CFR30: private property rights in water must be protected. Dutlines alternatives to prevent groundwater contamination from U mill activities.

  DANIELSON,L.J. National Wildlife Federation. 77/10/25. 3pp.
- 7912070129 Notification of 791114 meeting re response to comments on fraft mill GEIS & proposed rules on tailing mgt. MILLER, H. J. Uranium Recovery Licensing Branch. 79/12/06. 19.
- 7912070277 Comments on proposed rule 10CFR30: concurs w/NRC position that control measures be based on site-specific evaluations. Proposes that public health be made primary consideration in most objectives.

  RITCHIE, M. I. Pathfinder Mines Corp. 79/10/R3. 3ipp.
- 7912100469 Response in opposition to Cities of Anaheim & Riverside mation for protective order re PO&E fourth set of interrogatories. Info re best estimate may be provided by any municipal finance officer. Certificate of Bvc encl. ARMSTRONO, M. H. DVLE. M. M. Pacific Oas & Electric Co. ARKSTRONO, N. H. McCutchen, Doyle, Brown & Emerson. 79/11/05. App.
- 7912100477 Motion to compel Cities of Anaheim & Riverside to answer certain of PQ&E 790719 fourth set of interrogatories. In Fo provided in 791019 responses inadequate & incomplete. Certificate of Boc enci. ARMBTRONG.W.H., DDYLE.M.M. Pacific Gas & Electric Co. ARMBTRONG.W.H. McCutchen, Doyle, Brown & Emerson. 79/11/05, 18pp.
- 79121i0188 Comments on proposed rule 10CFR30: supports comments by American Hining Congress Suitable discussion of environ aspects of mining is omitted DOE comments on proposed EPA radueste criteria encl.

  8CHENDEL. W. R. Westinghouse Electric Corp. Wyoming Mineral Corp. 9EA-79-933. 79/10/24. 38pp.
- 7912120039 Comments on proposed rule 10CFR30: clarity needed in Criterion 3 re prime option for tailings disposal & in conflicting definitions of byproduct matl.

   Racky Mountain Energy Co. 79/10/24. 69pp.
- 7912120042 Comments on proposed rule 10CFR30: should not allow U industry to continue haphazard disposal of U mill tailings. Regulation definitions need clarity.
  WEISH.R. H. Affiliation Unknown. 79/10/21. 2pp.
- 7912120046 Comments on proposed rule 10CFR30; supports comments of American Mining Congress re U milling.
  CANFIELD, K. S. Homestake Mining Co. 79/10/24. lp.
- 7912120051 Comments on proposed rule 10CFR30: fails to emphasize contamination prevention & outline stringent criteria for containment siting areas.
  PERRY, L. Black Hills Alliance. 79/11/05. 2pp.
- 7912120055 Comments on proposed rule 10CFR30: NEPA & health & safety provisions play no part in agency consideration of radon problem. Certificate of Svc re NRC answers on CEIS encl. KEPFORD, C. Environmental Coalition on Nuclear Power. 79/10/24, 490s.

- 79121200AO Comments on proposed rule 10CFR30: fails to complu w/NEPA due to lack of assessment of total An-222 Ci released over full period of toxicity of U mill tailings piles.

  JOHNSRUD, J. H. Environmental Coalition on Nuclear Power 79/10/23.

  Jpp.
- 7912120120 Forwards locations of 791015-16 water soil & vegetation samples. Analysis should be completed by B00130 DREESEN, D. R. Los Alamos Scientific Laboratory LS6-79-51. 79710719. 4pp.
- 7912120124 Forwards comments on NUREO-0511 re U mill tailings sites, on behalf of Americans for Rational Energy Alternatives, Inc.
  General philosophy toward radiation protection & risk mitigation is too extreme.
  WILLIAMS, D. C. Affiliation Unknown. 14544. 79/10/24. 5pp.
- 7912120130 Comments on NUREG-0511. "Draft Generic Impact Statement on U Milling" fails to mention U mining industry in eastern US. BARLEY, S. R. Affiliation Unknown. 14552. 79/10/23. 3pp.
- 7912120168 Comments on NUREG-0511: activity consistent w/social, economic & physical goals & polities of GA Oft of Planning & Budget. BADGER, C. H. Georgia, State of. 79/10/29. 1p.
- 7912120238 Comments on proposed rules 10CFR30,40,70,150 & 170:licensing stds for U mill tailings are too losse.Criterion 6 is dangerous & counterproductive.

  LEWIS.M.L. Affiliation Unknown. 79/09/22. 1p.
- 7912120240 Forwards comments on proposed rules 10CFRGO,40,70,150 & 170 & draft GEIS:draft GEIS Fails to actieve stated purpose. Should be revised & reissued Three vols of comments encl. OVERTON.J. A. American Mining Congress. 79710724. 300pp.
- 7912120247 Comments on proposed rules 10CFR30,40,70,150 & 170:proposes amend to account for differences in mining procedures.
  Encourages redefinition of const.D(sposal & surveillance of waste impractical & costig.
  MARSHALL,W.H. Mobil Oil Corp. (subs. Mobil Corp.). 79/10/23. 10pp.
- 7912120253 Comments on proposed rule 10CFR30: overestimated risks, understated costs & inadequate support for proposed rules. SCOTT.C.B. Union Oil Co. of California. CBS 79-311. 79/10/23. 2no.
- --7912120260 Comments on proposed rule 10CFR36: objects to adoption of rules based on draft EIA. NRC should re-evaluate draft GEIS & repropose rules as justified.

  SCOTT. C. B. Union Oii Co. of California. CBS 79-312. 79/10/23. 3pp.
- 7912120363 Comments on proposed rule 10CFR30: units discussion of environ impacts of U mill mining operation.
  BCHENDEL. N. R. Wyoming Mineral Corp. GEA-79-933. 79/10/24. 31pp.
- 7912120366 Comments on proposed rule 10CFR30: fails to set min containment requirement for mill tailings & clarify how new stds apply to old tailings sites.
  EABT.D. Wyoming Outdoor Council. 79/10/23. lp.
- 7912120446 Response by Northorn CA Power Agency in opposition to motion to compel answers to certain of PO&E 791030 fifth set of interrogatories. Urges ABLB to deny motion except for interrogatories for which add1 answers will be provided. MCDLARMID.R.C. California, State of, TRAUGER T.C. North Carolina, State of, MCDLARMID.R.C. Bpiegel & McDlarmid. 79711/14. 22pp.
- --7912120453 Response by Northern CA Power Agency (NCPA) to PO&E fifth set of interrogatories directed to NCPA & Dept of Water Resources, Includes asswers to fourth set of interrogatories to Cities of Anaheim & Riverside, W/Certificate of Svc. \* California, State of. 79/10/15. 71pp.
- 7912130031 Comments on proposed rule 10CFR30: endorses comments & testimony of American Mining Congress re 0EIS on U milling. CANFIELD, K. S. Affiliation Unknown. 79/10/24, 1p.
- 7912130149 Summary of 791106-07 meeting w/Bechtel Corp.Union Carbide & DOE at ORNL re Hot Experimental Facility project process, equipment designs, schedules & NRC involvment. CLARK, A. T. Advanced Fuel & Spent Fuel Licensing Branch. 79/12/04. 3pp.
- --7912130154 Requests meeting w/NRC relactions required to achieve NRC review of Hot Experimental Facility.
  FERGUSON, R. L. Energy, Dept. of. 79/05/15. 2pp.

- 7912130376 Comments on draft CEIB re U Hill tailing sites:stds for reclaimed tailings covered are not based on scientific evidence. DEIB should be revised. BOODEN.O. Western Nuclear.Inc. 14955. 79/10/23. 2pp.
- 7912130403 Comments on draft GEIS on U milling: supports comments of American Hining Congress. QRTLOFF.Q.D. Exxon Minerals Co., USA. 14549. 79/10/24. 1p.
- 7912130404 Comments on behalf of Black Hills Energy Coalition on NUREG-0511 be U mill tailings sites does not produce worst-case estimates. Validity is limited.

  BANDERFORD J. Affiliation Unknown. 14342. 79/11/05. 1p.
- 7912130489 Forwards assessment of NUREG-0511, draft GEIS re U milling: NEPA does not permit justification of doses by comparison to background. LOCHSTET, W. A. Pennsylvania State Univ. 79/10/24. 12pp.
- 7912140007 Answer in apposition to Northern CA Pawer Agency motion for reconsideration or mod of ASLB 791101 order. Motion raises no substantial new arguments. Requests permission to file apposition to motion for reason of late eve on PO&E, ARMSTRONG. W. H. DOYLE, M. M. Pacific Oas & Electric Co. ARMSTRONG. W. H. McCutchen, Doyle, Brown & Emerson. 79/12/05. 2pp.
- --7912140020 Application to file apposition to Northern CA Power Agency (NCPA) motion for reconsideration or mod of ASLB 791101 order.NCPA request contrary to stipulation & to ASLB 780415 order. Supporting documentation encl.

  ARMSTRONG.W.H., DDYLE.H.M. Pacific Gas & Electric Co.

  ARMSTRONG.W.H. McCutchen, Doyle, Brown & Emerson. 79/12/05.
- 7912140226 Responds to 791108 Itr re application for reconsideration concerning green dotting of files already searched. Filing indices of Northern CA Power Agency members are open for insp.

  MCDIARMID.R.C. Spiegel & McDiarmid. 79/11/14. 1p.
- 7912170034 Requests review of NUREQ-0635, re excess cancer in Mesa County, CO. to determine impact on NRC analysis of health effects of U mill tailings industry, MILLER, H. J. Uranium Recovery Licensing Branch. 79709/27. 1p.
- 7912170251 Supplemental response to CA Dept of Water Resources fourth set of interrogatories. Submits info re Interrogatories 403, 404 & 415. Verification by MH Furbush, supporting documentation & Certificate of Svc encl.

  MEISB, R. L. Pacific Gas & Electric Co. MEISB, R. L. McCutchen, Doyle, Brown & Emerson. 79/11/15. 18pp.
- 7912170360 Comments on proposed rule 10CFR30: regulations deficient in treatment of siting criteria.below-grade disposal. financial surety provisions.agreement state regulatory programs & in sit U processing.

  LEWIS.B. E. Affiliation Unknown. 79/11/09. 16pp.
- 7912170383 Comments on proposed rule iQCFR30: in order to assure public health & safety,NRC licensing of U mill tailings should continue along w/state licensing.
  WEISS,J.L. Affiliation Unknown. 79/10/22. 8pp.
- 7912170385 Comments on proposed rule 10CFR30: regulations fail to address enforcement & integrity of operators applying for licenses & to make siting primary consideration over control technology.

  KNAPP, D. Affiliation Unknown. 79/10/29. 2pp.
- 7912170413 Comments on amended regulations re U mill tailings licensing EIS.Clarification needed for several words used in regulation.

  MADDEN, J. L. Aleska, State of. 14764. 79/11/08. 2pp.
- 7912170417 Supports American Mining Congress comments re draft GEIE on U mining. GRTLOFF, Q. D. Exxon Minerals Co., USA. 14520, 79/10/24. 1p.
- 7912200596 Comments on draft GEIS on U milling, NUREG-0511. Evaluation of environ impact & costs of disposal alternatives inadequate. Rept does not fully consider time scale of radiotoxicity of mill tailings.
  POHL,R.O. Cornell Univ. 14767, 79/10/31. 2pp.
- 7912260339 Response by Northern CA Power Agency (NCPA) to POME 791205 application requesting to file opposition to NCPA motion & for reconsideration or mod of ABLB order. Does not oppose application. Certificate of Svc encl.
  TRAUGER, T. C. California, State of TRAUGER, T. C. Spiegel & McDiarmid, 79/12/13, 5pp.

- 7912280203 Comments on NUREG-0511: several areas w/incomplete coverage due to lack of info. HEDEHAN.H.N. Environmental Protection Agency. 79/11/27. 24pp.
- 7712310187 Comments on proposed rules 10CFR30, 40, 70, 150 & 170: application expresses concern that developing regulatory scheme does not adequately take into account unique processes used in isolation extraction of U. MARSHALL, W. H. Mobil Dil Corp. (subs. Mobil Corp.). 79/10/23. ICpp.
- 7912310294 Discusses Northern CA Power Agency commitment to maintain privileged status of current negotiations. Viability of privilege jeopardized by CA Dept of Water Resources objection to procedure. W/supporting documentation.

  ADRAGNA...I M. Springel & McDiarmid 79/12/06 7cm

#### PT21 NONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE

- 7912180049 Discusses undetectable failure in engineered safety features actuation sys. Sys ability to automatically initiate protective function could be lost under certain conditions. Recommends various corrective actions.
  ANDERSON.T.M. Westinghouse Electric Corp. N8-TMA-2150. 79/11/07. 1300.
- 7912180075 Informs of 791106 source exposure mechanism malfunction during clinical use of AECL-CP beam teletherapy unit. Caused by intermittent failure of electrical relay. Manufacturer will correct defect.
  RIDECUTIE. F. Atomic Energy of Canada, Ltd. GA79-11-334, 79/11/14. 6pp.

#### GAPPP GUALITY ASSURANCE INSPECTIONS

- 7912080537 Forwards GA Program Insp Rept 99900239/79-01 on 790806-10. No noncompilence noted. POTAPUS.U. Region 4. Dallas, Vendor Inspection Branch. 79/09/12. 2pp.
- ---7912050544 GA Program Insp Rept 99900239/79-01 on 790806-10.No noncompliance noted. Major areas inspected: implementation of 10CFR80. App B & applicable codes & stds including action on previous insp findings & calibr.

  BUTTON, J. W. KELLEY, W. D. , WHITEBELL, D. E. Region 4, Dallas, Vandor Inspection Branch. 79/09/10. 9pp.
- 7912100404 Forwards GA Program Insp Rept 99900522/79-04 on 790910-ii. No noncompliance noted. POTAPDUS.U. Region 4. Dallas, Vendor Inspection Branch. 79/09/26. 2pp.
- --7912100409 GA Program Insp Rept 99900522/79-04 on 790910-11.No noncompliance noted Major areas inspected: implementation of 100FR90.App B.re IE Dulletin 79-14.

  HALE.C.J., BRICKLEY, R.H. Region 4. Dallas, Vendor Inspection Branch. MDDENDS.L. Region 4. Dallas, Office of the Director. 79/09/26. 10pp.
- 7912100412 Forwards GA Program Insp Rept 99900385/79-01 on 790817. No noncompliance noted. POTAPOVS.U. Region 4, Dallas, Vendor Inspection Branch, 79/10/22. 2pp.
- --7912100415 GA Program Insp Rept 99900385/79-01 on 790817. No noncompliance noted. Major areas inspected: data re failed suing check valve previously reported. HUNNICUTT.D. M., ELLERSHAW, L. E., Region 4, Dallas, Vendor Inspection Branch. 79/10/17. 3pp.
- 7912110016 Ack receipt of 790725 & 1026 ltrs informing NRC of steps taken to correct deviations noted in GA Program Insp Rept 99900521/79-02.
  POTAPOUS.U. Region 4. Dallas. Vandor Inspection Branch. 79/11/16. ip.
- --7912110024 Responds to NRC 791016 ltr re deviations noted in QA Program Insp Rept 99700521/79-02. Corrective actions: eliminated ambiguity in Section 17 Eq-TQP-1. CARACO.I.R. Bachtel Power Corp. (subs. of Bechtel Corp.). 79/10/26. 1p.
- ~-7912110034 Ack receipt of 790725 ltr informing NRC of steps taken to correct deviations noted in QA Program Insp Rept 99900521/79-02. Requests add1 info.
  POTAPOVB.U. Region 4, Dallas, Vendor Inspection Branch, 79/10/16.

- ---7912110041 Responds to NRC 790628 ltr re deviations noted in GA Program Insp Rept 79700521/79-02. Corrective actions: audit schedule requirements revised to reflect current audit up & will be updated during first month of each new yr. CARCOLIR. Bechtel Power Corp. (subs. of Bechtel Corp.). 79/07/25. 7pp.
- ---7912110042 Forwards GA Program Insp Rept 99900521/79-02 on 790604-07 & notice of deviation.
  POTAPOVB.U. Region 4. Dallas, Vendor Inspection Branch.
  79/06/28. 2pp.
- --7912110046 Notice of deviation from insp on 790604-07.

  Region 4, Dallas, Office of the Director. 79/06/27. 3pp.
- --7912110032 GA Program Insp Rept 99900521/79-02 on 790604-07.
  Noncompliance noted: failure to follow audit procedures &
  failure to follow GA records procedures.
  BRICKLEYR, H., JOHNBOIN, J. M. HALE, C. J. Region 4, Dallas, Vendor
  Inspection Branch. 79/06/27. 10pp.
- 7912110058 Forwards GA Program Insp Rept 99900601/79-01 on 790829. No noncompliance noted. PDTAPGVB.U. Region 4. Dallas, Vendor Inspection Branch. 79/09/21. 2pp.
- --7912110061 0A Program Insp Rept 99900601/79-01 on 790829. No noncompliance noted. Major areas inspected:organization qualification of authorized inspected: argency & inspectors & parformance of authorized agency duties.

  ANDERBON, D. O. , HALE, C. J. , FOTRAPQUS, U. Region 4, Dallas, Vendor Inspection Branch. 79/09/19. App.
- 7912110065 Forwards GA Program Insp Rept 99900029/79-02 on 790918-21.
  No noncompliance noted.
  POYAPOVB.U. Region 4. Dallas, Vendor Inspection Branch.
  79/10/31. 2pp.
- ---7912110071 GA Program Insp Rept 99900029/79-02 on 790918-21. No noncompliance noted Major areas inspected:action on previous insp findings, review of vendor activities, mati identification & control & radiographic examination.

  DLERR.E. HUNNICUTT.D.M. Region 4. Dallas, Vendor Inspection Branch. 79/10/29. 11pp.
- 7912110076 Forwards GA Program Insp Rept 99900528/79-02 on 790912.Nu noncompliants noted. PDTAPDVS.U. Region 4. Dallas, Vendor Inspection Branch. 79/10/02. 2pp.
- --77121100Bi 0A Program Insp Rept 99900528/79-02 on 790912.No noncompliance noted.Major areas inspected:seismic analysis for as-built safety-related piping systems.

  HALE:C. J. Region 4, Dallas, Vendor Inspection Branch.

  HODENOB, L. Region 3: Chicago: Office of the Director.

  LAGRANGE, R. O. Division of Operating Reactors. 79/10/02. App.
- 7912110082 Forwards GA Program Insp Rept 99900080/79-02 on 790917-18. No noncompliance noted. PDTAPUS.U. Region 4. Dallas, Vendor Inspection Branch. 79/10/23. 2pp.
- --7912110088 OA Program Insp Rept 99900080/79-02 on 790917-18.No noncompliance noted. Major areas inspected: cause: corrective action & generic considerations re deficiency found in pressurizer power operated relief valves.

  OLLERR.E., HUNNICUTT.D.M. Region 4, Dallas, Vendor Inspection Branch, 79/10/18, 8pp.
- 7912110101 Ack receipt of 791011 & 1108 ltrs informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 999030279-03.
  POTAPOVS, U. Region 4: Dallas: Vendor Inspection Branch.
  79/11/19. ip.
- --7912110110 Responds to NRC 791026 request for addl info re QA Insp Program Rept 99700502/79-03. Bys design documentation method re advising editors of deviation & need to prevent recurrance was both verbal & by memb. PIEPER, N. B. Brown & Root Corp. (subs. of Halliburton Corp.). 79/11/08. 2pp.
- --7912110114 Ack receipt of 791011 1tr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 9990802779-03, Requests add1 info. POTAPOVS.U. Region 4, Dallas, Vendor Inspection Branch. 79/10/26.

- --7912110118 Responds to NRC 790914 ltr re deviation noted in QA Program Imap Rept 9990302/79-03. Corrective actions: all sys design descriptions reviewed for deviation & corrected according to completion schedule.
  PIEPER.M.B. Brown & Root Corp. (subs. of Halliburton Corp.).
  79/10/11. 3pp.
- --7912110122 Forwards QA Program Insp Rept 99900502/79-03 on 790827-31 & notice of deviation. POTAPOVS,U. Region 4, Dallas, Vendor Inspection Branch. 79/09/14. 2pp.
- --7912110127 Notice of deviation from insp on 790827-31.

  Region 4. Dallas. Office of the Director. 79709/12. ip.
- --7912110133 QA Program Insp Rept 99900502/79-03 on 790827-31.
  Noncompliance noted:design input wef for design input
  parameters not identified in sys design description w/
  superscript numeral indicating footnote.
  HALE.C.J., ANDERBON, D. C., BROWN, R. L. Region 4, Dallas, Vendor
  Inspection Branch. 79/09/12. 12pp.
- 7912110107 Ack receipt of 791109 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99700109179-01.
  PGTAPOVS.U. Region 4. Dallas, Vendor Inspection Branch. 79/11/23. 1p.
- --7912110111 Responds to NRC 791025 ltr re deviation noted in GA Program Insp Rept 99900105/79-01. Corrective actions: valve meat ring rehardfaced at proper temp. Welders instructed that specified preheat temp must be maintained.
  EBTILL.D.D. Fischer Controls Co., Inc. (subs. of Monsanto Co.).
  79/11/09. 1p.
- --7912110117 Forwards GA Program Insp Rept 99900105/79-01 on 790924-28 & notice of deviation.
  POTAPDVB.U. Region 4, Dallas, Vendor Inspection Branch.
  79/10/22, 2pp.
- --7912110120 Notice of deviation from insp on 790924-28.

  \* Region 4, Dallas, Office of the Director. 79/10/19. ip.
- --7912110128 GA Program Insp Rept 99700105/77-01 on 790924-28.

  Noncompliance noted: hardfacing preheat temp not maintained during welding.

  SUTTON.J. W. HHITESELL.D. E. Region 4, Dallas, Vendor Inspection Branch. 79/10/19. Bpp.
- 7912110501 Forwards GA Program Insp Rept 99700091/79-01 on 791001-05. No noncompliance noted. PDTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 79/10/30. 2pp.
- --7912110506 CA Program Insp Rept 99900091/79-01 on 791001-05.No nuncompliance noted Major areas inspected special insp of spent fuel shipping cask performed in response to request from Transportation Branch.

  MCNEILL, M. M., WHITEBELL, D. E. Region 4, Dallas, Vendor Inspection Branch, 79/10/29, 4pp.
- 7912110511 Forwards GA Program Insp Rept 99900505/79-04 on 791029-1102. No noncompliance noted. PUTAPUS.V. Region 4, Dallas, Vendor Inspection Branch. 79/11/26. Rpp.
- --7912110516 GA Program Insp Rept 99900505/79-04 on 791029-1102. No noncompliance noted Major areas inspected implementation of ETR-1001 in areas of IE Bulletin 79-14 regional request for insp & followup on previous insp findings.

  CDSTELLD.J. R., ANDERGON, D. G., HALE, C. J. Region 4, Dallas, Vendor Inspection Branch. 79/11/26, 13pp.
- 7912120077 Ack receipt of 791010 & 1115 ltrs informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 9990026079-02.
  POTAPUS, U. Region 4, Dallas, Vendor Inspection Branch. 79/11/23. 1p.
- ---7912120083 Responds to NRC 791024 ltr re deviation noted in OA Program Insp Rept 79900268/79-02 Corrective actions: revised GA manual abbreviations & definitions to include welding angineer & welding supervisor.

  MOON.R.E. ARMCO International, Inc. 79/11/15, 1p.
- ---7912120089 Ack receipt of 791010 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900268/79-02 Requests add1 info. PDTAFOUS.U. Region 4. Dallas, Vendor Inspection Branch. 79/10/24.

- --791212009B Responds to NRC 790904 ltr re deviation noted in GA Program Insp Rept 99900268/79-02 Corrective actions: Matl Review Board meeting held to review proper procedures for handling nonconforming repts.

  MOON, R. E. ARMCO International, Inc. 79/10/10. 3pp.
- ~~7912120104 Forwards GA Program Insp Rept 99900268/79-02 on 790723~27 & notice of deviation. POTAPOVS,U. Region 4. Dalias, Vendor Inspection Branch. 79/09/04. 2pp.
- --7912120109 Notice of deviation from insp on 790723-27. \* Region 4. Dallas. Vendor Inspection Branch. 79/08/24. 2pp.
- --7912120118 GA Program Insp Rept 99900268/79-02 on 790723-27.

  Noncompliance noted:welding procedure Specs 10 & 11 revised by unauthorized personnel & training programs not arranged on monthly basis.

  HUNNICUTT.D.N., OLLER,R.E. Region 4, Dallas, Vendor Inspection Branch. 79/08/24, 13pp.
- 7912120272 Ack receipt of 791112 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900279/79-01. PDTAPDVS.U. Region 4. Dallas, Vendor Inspection Branth.
- --7912120278 Responds to NRC 791031 ltr re deviation noted in QA Program Insp Rept 99900279/79-01. Corrective actions: 00358 cards corrected for specific instructions, calibr records indicating deviations will be filed.

  WATHEN, R. P. Oould, Inc. 79/11/12. 3pp.
- --7912120281 Forwards QA Program Insp Rept 99900279/79-01 on 790904-07 & notice of deviation.
  POTAPOVS.U. Region 4. Dallas. Vendor Inspection Branch.
  79/10/31. 2pp.
- --7912120287 Notice of deviation from insp on 770904-07.

  \* Region 4, Dallas, Vendor Inspection Branch. 79/10/30. ip.
- --7912120293 GA Program Insp Rept 99900279/79-01 on 790904-07.
  Noncompliance noted: failure to record calibr & measurements & nonconforming components discarded as trash.
  AGEL J.R. HUNNICUTT. D.M. Region 4, Dallas, Vendor Inspection Branch. 79/10/30. Bpp.
- 7912130374 Ack receipt of 791114 ltr informing NRC of steps taken to correct deviation noted in OA Program Insp Rept 99900301779-01. POTAPOUS, U. Region 4: Dallas, Vandor Inspection Branch. 79/11/27. ip.
- --7912130381 Responds to NRC 791012 ltr re deviation noted in GA Program Insp Rept 99900301/79-01. Corrective actions: revised visual insp procedure & implemented temporary attachments use, removal procedures & instrument serial number recording. DELORENZO,F. Atlas Industrial Manufacturing Co. 79/11/14. 2pp.
- --7912130423 Forwards GA Program Insp Rept 99900301/79-01 on 790910-14 & notice of deviation. POTAPDVS.U. Region 4, Dallas, Vendor Inspection Branch. 79/10/12. 2pp.
- --7912130427 Notice of deviation from insp on 790910-14.

  \* Region 4. Dallas. Office of the Director. 79/10/11. ip.
- ---791213042B QA Program Insp Rept 99700301/79-01 on 790910-14.

  Noncompliance noted: no ref made by Visual Insp Procedure 140 of acceptance criteria of tolerance for vessel shells.max offset of aligned sections & reinforcement of welds.

  WHITESELL.D.E., SUTTON.J.W. MCNETLL.W.M. Region 4. Dallas. Vendor Inspection Branch. 79/10/11. 13pp.
- 7912140543 Forwards GA Program Insp Rept 99900523/79-01 on 790926-28. No noncompliance noted. POTAPOVS.U. Region 4, Dallas. Vendur Inspection Branch. 79/10/22. 2pp.
- --7912140545 0A Program Insp Rept 99900523/79-01 on 790926-28.No noncompliance noted Major areas inspected: seismic analysis input. HALE.C.J. Region 4. Dallas, Vendor Inspection Branch. YIN. I.T. Region 3. Chicago, Office of the Director. BRICKLEY.R.H. Region 4. Dallas, Office of the Director. 79/10/19. 7sp.

- 7912170382 Ack receipt of 791102 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 9900510/79-03.
  POTAPUS.U. Region 4, Dallas, Vendor Inspection Branch.
  79/11/23. ip.
- --79121703B7 Responds to NRC 791003 ltr re deviation noted in GA Program Insp Rept 79900510/79-03. Corrective actions: spec approval Form for Revision 2 of Spec 113 on file.
  CURNAMER.R.A. United Engineers & Constructors, Inc. (subs. of Raytheon Co.). 79/11/02. 3pp.
- --7912170391 Forwards GA Program Insp Rept 99900510/79-03 on 790910-14 & notice of deviation.
  POTAPOVS.U. Region 4. Dallas, Vendor Inspection Branch.
  79/11/03. 2pp.
- --7912170393 Nutice of deviation from insp on 790910-14,
  \* Region 4. Dallas, Vendor Inspection Branch. 79/10/02. 1p.
- --7912170398 GA Program Insp Rept 99900510/79-03 on 790910-14.
  Noncompliance noted:failure to file copy of spec approval
  form & retain vendor nonconformance repts for Seabrook.
  HALE, C. J., JOHNSON, J. M., COSTELLÜ, J. R. Region 4, Dallas, Vendor
  Inspection Branch. 79/10/02. 12pp.
- 7912180112 Ack receipt of 791126 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900630/79-01.
  PDTAPOVS.U. Region 4, Dallas, Vendor Inspection Branch. 79/12/04. 1p.
- --7912180124 Responds to NRC 791107 ltr re deviation noted in GA Program Insp Rept 99900650/79-01. Corrective actions: completed written procedures describing method of controlling topical rept copies & GA records.
  PESPIEK, G. American Institute of Steel Construction, Inc. 79/11/26. 2pp.
- --7912180132 Forwards GA Program Insp Rept 99900650/79-01 on 791015-17 & notice of deviation.
  POTAPOVB.U. Region 4: Dallas: Vendor Inspection Branch.
  79/11/07. 2pp.
- --791218013B Notice of deviation from insp on 791015-17.

  \* Region 4, Dailas, Office of the Director. 79/11/05. 1p.
- --7912180142 GA Program Insp Rept 99900650/79-01 on 791015-17.
  Noncompliance noted:failure to establish procedures for topical rept control & failure to sign & date topical rept.
  HALE.C.J., BROWN.R.L., ANDERSON,D. G. Region 4, Dallas, Vendor Inspection Branch. 79/11/05. 10pp.
- 7912180177 Ack receipt of 791031 itr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900217/79-01. POTAPOUS, U. Region 4, Dallas, Vendor Inspection Branch, 79/11/26. 1p.
- --79121B01B5 Responds to NRC 790914 ltr re deviation noted in GA Program Insp rept 99900217/79-01. Corrective actions: revised organizational chart to include angineering. mfg & purchasing depts.

  HGLCOMB.D.D. Westinghouse Electric Corp. 79/10/31. App.
- --791218D18B Forwards GA Program Insp Rept 99900217/79-01 on 790723-26 & notice of deviation. POTAPOVS.U. Region 4, Dallas, Vendor Inspection Branch. 79/09/14. 2pp.
- --79121B0190 Notice of deviation from insp on 790723-26.
  \* Region 4. Dallas, Vendor Inspection Branch. 79/09/07. ip.
- --7912180196 GA Program Insp Rept 99900217/79-01 on 790723-26.

  Noncompliance noted: failure to include responsibilities of engineering, mfg & purchasing dept in product assurance manual organization chart.

  HUNNICUTT.D.M., ABEE, J.R. Region 4, Dallas, Vendor Inspection Branch. 79/09707. 6pp.
- 7912180247 Ack receipt of 791121 itr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 9990314/79-02. POTAPDUS U. Region 4. Dallas, Vendor Inspection Branch. 79/12/04. ip.

- --7912180256 Responds to NRC 791017 ltr re deviation noted in OA Program Insp Rapt 99900314/79-02 Corrective actions:personnel reinstructed that bundle tickets must accompany pipe bundles & single lengths of pipe.

  HEHRLE, J. L. Colt Industries, Inc. 79/11/21, 2pp.
- --7912180261 Forwards GA Program Insp Rept 99900314/79-02 on 790827-31 & notice of deviation. POTAPOVS.U. Region 4. Dallas, Vendor Inspection Branch. 79/10/17. 2pp.
- --7912180248 Notice of deviation from insp on 790827-31.

   Region 4, Dallas, Office of the Director. 79/10/15. 2pg.
- --7912180273 GA Program Insp Rept 99900314/79-02 on 790827-31.
  Noncompliance noted:failure to maintain rejection tags
  w/four nonconforming stainless steel pipes.
  OLLER.R.E., HUNNICUTT.D.M. Region 4, Dallas, Vendor Inspection
  Branch. 79/10/15. 10pp.
- 7912180464 Forwards GA Program Insp Rept 99900005/79-11 on 790314-0996.No noncompliance noted.
  BOOK, H. E. Region 5. San Francisco, Fuel Facility & Materials Safety Branch. 79/11/13. 2pp.
- --7912180467 OA Program Insp Rept 99900005/79-i1 on 790314-0906. No noncompliances noted. Major areas inspected: cause of leakage of Xe-133 from primary container & actions to preclude addl leaking shipments.

  CODLEY.W. J., BODK.H.E. Region 5. Ban Francisco, Fuel Facility & Materials Bafety Branch. 79/11/09. 15pp.
- 7912200187 Forwards GA Program Insp Rept 99900389/79-01 on 791001-02. No noncompliance noted. PDTAPQV8.U. Region 4, Dallas, Vendor Inspection Branch. 79711/06. Upp.
- --7912200176 GA Program Insp Ropt 99900389/79-01 on 791001-02. No noncompliance noted Major areas inspected initial mgt meeting & implementation of 100FR50. App D including design control re field reported deficiencies in air locks.

  BROWN, R.L., WHITESELL, D.E. Region 4, Dallas, Vendor Inspection Branch. 79/11/05. Spp.
- 7912200491 Forwards QA Program Insp Rept 99900390/79-01 on 791004-05.No noncompliance moted. PDTAPOVS.U. Region 4: Dallas, Vendor Inspection Branch. 79/11/06. 2pp.
- --7912200499 QA Program Insp Rept 99900390/79-01 on 791004-05. No noncompliance noted Major areas Inspected: initial mgt meeting & implementation of IOCFR90B including mfg process & weld controls re reported airlock deficiencies.
  HHITEGELL, D. E., BROWN, R. L. Region 4, Dallas, Vendor Inspection Branch. 79/11/05. Bpp.
- 7912210001 Ack receipt 791106 & 0808 ltrs informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 97900036/79-02.
  20TAPOVS.V. Region 4. Dallas, Vendor Inspection Branch.
- --7912210012 Responds to NRC 791029 ltr re deviation noted in GA Program Insp Rept 99700036/79-02. Corrective actions: documented detail rept of insp findings forwarded to CNU managers & supervisors requesting written corrective action responses. STONE. W. A. Combustion Engineering, Inc. 79/11/06. 1p.
- --7912210017 Ack receipt of 791008 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 9990036/79-02. Requests addl info re documentation of instructions, re-instructions & personnel discussions. POTAPDVS.V Region 4, Dallas, Vendor Inspection Branch. 79/10/29. 1p.
- --7912210020 Responds to NRC 790906 ltr re deviation noted in QA Program Insp Rept 99900036/79-02. Corrective actions: tie straps re-welded per welding procedures & unidentified alignment to tie strap material, welded to vessel assemblies, removed. SATEB, B. J., MILLER, L. C., STONE, W. A. Combustion Engineering, Inc. 79/10/08. 6pp.
- --7912210029 Forwards QA Program Insp Rept 99900036/79-02 on 790813-17 & actice of deviation.
  POTAPQVS.V. Region A. Dallas, Vendor Inspection Branch.
  79/09/06. 2pp.
- --7912210032 Notice of deviation from insp on 790813-17.
  Region 4: Dallas: Office of the Director. 79/09/05. 3pp.

- ---7912210036 QA Program Insp Rept 99900036/79-02 on 790813-17.
  Noncompliance noted: welding being performed contrary to procedures & unidentified alignment & tie strap material found welded to vessel assemblies BARNES. I. ROBERDS. H. W. HUNNICUTT. D. M. Region 4. Dallass Vendor Inspection Branch. 79/09/05 12pp
- 7912210196 Forwards QA Program Insp Rept 99900346/79-02 on 791016-18. No noncompliance noted. POTAPEVS,U. Region 4. Dallas, Vendor Inspection Branch. 79/11/06 2pp.
- --7912210199 QA Program Insp Rept 99900346/79-02 on 791016-18.Nu noncompliance noted Major areas inspected implementation of 10CFR50 & applicable codes & stds.
  WHITESELLE, D. E., KELLEY, D. Region 4, Dallas, Vendor Inspection Branch. 79/11/05. 10pp.
- 7912210198 Ack receipt of 791112 & 19 ltrs informing NRC of steps taken to correct deviations noted in QA Program Insp Rept 99700355/79-02.
  POTAFOUS.U. Region 4. Dallas, Vendor Inspection Branch.
  79/11/29. 1p.
- --7912210201 Corrects clerical errors appearing in 791112 itr to NRC responding to deviations noted in GA Program Insp Rept 99900355/79-02.
  MIRATALY. Hirata Valve Industry Co., Ltd., Kawaski Div. 79/11/19.
- --7912210210 Responds to NRC 791002 ltr re deviations noted in GA Program Insp Rept 99900355/79-02. Corrective actions: vendor statement correcting HPB number on weld repair record attached to repair record welding specs revised.

  HIRATA: Y. Hirata Valve Industry Co., Ltd., Kawaski Biv. 79/11/12.
- --7912210219 Forwards GA Program Insp Rept 99900335/79-02 on 790827-0903 & notice of deviation. SEYFRIT.K.V. Region 4. Dallas, Office of the Director 79/10/02. 3pp.
- --7912210222 Notice of deviation from imap on 790827-0903.

  \* Region 4 Dallas, Office of the Director. 79/09/27. 3pp.
- ---7912210233 QA Program Insp Rept 99900355/79-02 on 790827-0903.

  Noncompliance noted: vendor statement correcting MPS number on weld repair record not attached to repair record & hardsurfacing travel speeds in excess of permitted values.

  BARNES.I., HUNNIEUTT.D.M. Region 4. Dallas, Vendor Inspection Branch. 79/09/27. 14pp.
- 7912260074 Ack receipt of 790713.0913 & 1114 ltrs informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 97900017/79-01. PDTAPDVS.U. Region 4. Dallas, Vendor Inspection Branch 79/11/29. ip.
- --7912260104 Responds to NRC 791017 ltr re deviation noted in GA Program Insp Rept 79900019/79-01 Corrective actions: original test temp unnecessarily low & raised for piping sys by design engineers Retests performed w/satisfactory results.

  JOHNSON, E. ITT Grinnell Industrial Piping, Inc. (subs. of ITT Grinnell) 79/11/16. ip
- ---7912260111 Ack receipt of 790913 ltr re QA Program Insp Rept 99900019779-01. Requests info re date by which determination & submittal of Item D corrective actions will be completed. POTAPOVS.U. Region 4. Dellas, Vendor Inspection Branch. 79/10/17. ip.
- ---7912280125 Responds to NRC 790816 ltr re deviation noted in GA Program Insp Rept 99900019/79-01. Corrective actions: procedure being implemented to resolve design spec conflicts using sequentially numbered form to document questions & answers. JUHNBON.E. JTT Grinnell Industrial Piping, Inc. (subs. of ITT Grinnell). 79/09/19. 6pp.
- --7912260130 Ack receipt of 790713 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 9990019779-01 Requests completion date for determination & submittal of proposed corrective actions.

  SEYFRIT, K. V. Region 4. Dallas. Diffice of the Director. 79708/16. 2pp.
- --791226013B Responds to NRC 790402 ltr re deviation noted in OA Program Insp Rept 99900019/79-01 Corrective actions: spec revised to include requirement for stainless steel piping subj to hot bending to receive solution anneal & rapid quench.

  JOHNSON E ITT Granell Industrial Piping, Inc. (subs. of ITT Orinnell). 79/07/13. 12pp.

- --7912260141 Requests extension for response to deviation noted in QA Program Insp Rept 99900019/79-01. JOHNSON.E. ITT Grinnell Industrial Piping, Inc. (subs. of ITT Grinnell). 79/05/24. 1p.
- ---7912260146 Forwards QA Program Insp Rept 59900019/79-01 on 750226-0301 & notice of deviation.

  SEYFRIT.K. V. Region 4, Dallas, Office of the Director.

  79/04/02. 2pp.
- --7912260150 Notice of deviation from insp on 790226-0301. \* Region 4, Dallas, Office of the Director. 79/03/28. 2pp.
- --7912260155 0A Program Insp Rept 99900019/79-01 on 790224-0301.

  Noncompliance noted: failure to provide criteria assuring compliance of austenitic stainless steel hot bends w/requirements of Reg Quide 1.44.

  BARNES I. Region 4, Dallas, Vendor Inspection Branch.
  79/03/28. 10pp.
- 7912260152 Ack receipt of 791119 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 9990378/79-01. Pagion 4, Dallas, Vendor Inspection Branch. 79/12/10. 1p.
- --7912260154 Responds to NRC 791102 ltr re deviation noted in QA Program Insp Rept 999003/8/79-01. Corrective actions: purchase orders now specify certificates of compliance when appropriate & insp equipment being calibr.

  SWANBON, N. E. Acme-Cleveland Co., Namco Controls Div. 79/11/19. 200.
- --7912260156 Forwards QA Program Insp Rept 99900378/79-01 on 790808-09 & notice of deviation. POTAPDVB.U. Region 4, Dallas, Vendor Inspection Branch. 79/11/02. 2pp.
- --7912260157 Notice of deviation from insp on 790808-09.
   Region 4. Dallas. Office of the Director. 79/10/30. Ip.
- --7912260159 GA Program Insp Rept 99900378/79-01 on 790808-09.
  Noncompliance noted:purchase orders to vendors failed to require certificates of conformance & instruments not calibr although used in insp & testing.
  AGEE.J.R., KUNNICUTI.D.M. Region 4, Dallas, Vendor Inspection Branch. 79/10/30. App.
- 7912260185 Ack receipt of 791030 & 0920 ltrs informing NRC of steps taken to correct deviations noted in GA Program Insp Rept 99900526/79-02. POTAPOVS,U. Region 4, Dallas, Vendor Inspection Branch. 79/12/12. 1p.
- --7912260193 Responds to NRC 791016 ltr re deviations noted in GA Program
  Insp Rept 99900526/79-02. Corrective actions:content of
  current issue of project design manual to be reviewed &
  listing of effective content of manual to be prepared.
  ADAM.P.J. Black & Veatch. 79/10/30. 2pp.
- --7912260198 Ack receipt of 770920 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 97900526/79-02 Requests add1 info re specific corrective actions & preventive measures for deviations & B. PDTAPDV8:U. Region 4. Dallas, Vendor Inspection Branch. 79/10/16. 1p.
- ~-7912260202 Responds to NRC 790822 ltr re deviations noted in QA Program Insp Rept 99900526/79-02. Corrective actions: requirements for retention of design interface review records to be modified & project design manual now properly identified. ADAM, P. J. Black & Veatch. 79/09/20. 3pp.
- --7712260203 Forwards QA Program Insp-Rept 99900526/79-02 on 790806-10 & notice of deviation.
  POTAPOVS,U. Region 4. Dallas. Vendor Inspection Branch.
  79/08/22. 2pp.
- --7912260204 Notice of deviation from insp on 790806-10. \* Region 4, Dallas, Office of the Director. 79/08/22. 2ps.
- ---7912260206 GA Program Insp Rept 99900526/79-02 on 790806-10.
  Noncompliance noted:failure to have adequate procedural requirements for retention of design interface review records & failure to identify project design manual.
  BRICKLEY, R. H., FOX. D. F., HALE, C. J. Region 4, Dallas, Vendor Inspection Branch. 79708/22. 7pp.

REGOD REGULATORY GUIDES

- 7912050034 "Personal Dosimetry Performance Testing Pilot Study."
  results of Test 1.in support of Reg Guide B.XXX.
  \* Michigan, Univ. of. 79/12/04. 2400pp.
- 7712050056 "Personal Dosimetry Performance Testing: Pilot Study," results of Test 2. in support of Reg Quide 8. XXX. \* Michigan, Univ. of. 79/12/04. 2400pp.
- 7912040601 Value/impact assessment of proposed Revision 2 to Reg Guide 1.97. "Instrumentation in Light Water Cooled Nuclear Power Plants to Assess Plant & Environs Conditions During & Following Accident." Revision should be issued.

  # Office of Standards Development. 79/10/15. Spp.
- 7912110097 Summary of ACRS Subcommittee on Regulatory Activities meeting w/EPR1.06. IEEE & Vanker Atomic Electric Co in Hashington, DC or review of proposed reg guides & revisions to existing reg guides & stds.

  \* ACRS Advisory Committee on Reactor Bafeguards. 79/07/13. iBpp.
- --7912110104 Forwards comments on Reg Guide 1.9, "Belection, Design & Gualification of Diesel Generator Units Used as Onsite Electric Power Sys at Nuclear Power Plants."

  \* Tennessee Valley Authority. 79/04/05. 2pp.
- 79:2110235 Comments on proposed reg guide & value/impact statement, "Applications on Bioassay for Fission & Activation Products," Recommends that guide not be implemented in present form. Guide should not endorse ANSI N343 Std. BKRADLE,K.W. Lowell, Univ. of. 79/10/25. 152pp.
- 7912110549 Comments on proposed Reg Quide 1.131: "Radiation Protection Training for Light Water Cooled Nuclear Power Plant Personnel." Training may discourage mutually beneficial short visits. Numerical test grade should be delated. BAXTER, R.C. Allied Qeneral Nuclear Services. 79/10/24. ip.
- 7912110554 Comments on proposed Reg Guide 1.131, "Radiation Protection Training for Light Mater Couled Nuclear Power Plant Personnel." Subj of contamination control should be more unified & presented whore prominence.

  COPELAND.R.L. Energy, Dept. of, Clinch River Breeder Reactor Plant. 79/10/22. 2pp.
- 7912110559 Comments on proposed Reg Guide 1.131, "Radiation Protection Training for Light Hater Cooled Nuclear Power Plant Personnel." Guide is reasonable & adequata. Subjs covered in Table 1 can be covered in less than one week. LUNDVALL.A.E. Baltimore Gas & Electric Co. 79/10/R3. 1p.
- 7912110565 Comments on proposed Reg Quide 1.131, "Radiation Protection Training for Light Water Cooled Nuclear Power Plant Personnel." Individualized training would be impossible to efficiently & effectively achieve.
  PARKER.W.O. Duke Power Co. 79/10/24. 4pp.
- 79:2110572 Comments on draft reg guide, "Qualification Test for Cable Penetration Fire Stops for Use in Nuclear Power Plants."

  Design verification of fire stops does not fall within jurisdiction of 10CFR50.

  D'DONNELL,E.P. Ebasco Services, Inc. (subs. of Enserch Corp.).
  79/10/11. 2pp.
- 7912110580 Comments on draft reg guide, "Lightning Protection for Nuclear Power Plants." Authors confuse usage of terms lightning strake & lightning surge, CAHN, A.L. Bechtel Power Corp. (subs. of Bechtel Corp.). 79/10/19.
- 7912110584 Comments on draft reg guide, "Lightning Protection for Nuclear Power Plants." Guide should be rewritten to address pertinent interface criteria.

  DATE, L. C. Duke Power Co. 79/10/24. 4pp.
- 79:212:00:3 Comments on proposed reg guide. "Audible Alarm Dosimeters," State-of-the-art renders such instruments unacceptable. DERMYER, H. D. Affiliation Unknown. 79/10/23, 2p.
- 7712120016 Comments on proposed reg guide: "Safety-Related Permanent Dewatering Bys for Nuclear Power Plants." Items C. 4a.C. 4b & C. 4c are too Vaguely worded for application by designers. BARNES.P.L. Commonwealth Edison Co. 79/10/23. ip.
- 7912120019 Comments on proposed reg guide: "Applications of Bidassay for Fission & Activitation Products." Limits established under licensee methodology should be sole criteria. CURTIE: N. W. Pennsylvania Power & Light Co. 79/10/23. ip.

- 7912120023 Comments on proposed Reg Quide 1.131.: "Radiation Protection Training for Light Water Cooled Nuclear Plant Personnel." Length of training excessive. Six to sixteen hours of training have produced excellent results.

  JENTZ. T. L. NUB Corp. HP8-79-224. 79/10/23. 1p.
- 7912120027 Comments on proposed Reg Guide 1.136, Revision 2: testing of concrete containment should not include insp of embedments. Concrete embedments do not affect structural capacity of concrete. COUNSIL, M. G. Northeast Utilities. 79/10/16. 200.
- 7912130079 Draft Reg Guide 8.22, "Personal Dosimstry Performance Testing:Pilot Study." • Michigan, Univ. of. 79/12/11. 43pp.
- 7912130359 Forwards Reg Ouide 4.14. "Branch Position For Presperational Radiological Environ Monitoring Program for U Mills" & "Proposed Branch Position for Operational Radiological Environ Monitoring Programs," W/o encl. SCARANO, R.A. Uranium Recovery Licensing Branch. 79/11/19. ip.
- 7912130542 Forwards notice of intention to change App D of QA Program Topical Rapt NU QA-1.Revision 3A.Change updates commitment from ANSI N45.2.12 to Reg Guide 1.144.
  COUNSIL.W. Q. Northeast Utilities, QA-3561, 79/12/06. 2pp.
- 7912180662 Concurs w/issuance of Reg Guide 1.9.Revision 2, "Section, Design & Qualification of Diesel Generator Units Used as Standby (Onsite) Electric Power Sys at Nuclear Power Plants."

  EISENHUT, D. 0. Division of Operating Reactors. 79/12/03. ip.
- 7912200268 Forwards comments on draft reg guide "Lightning Protection for Nuclear Power Plants." Alternative regulatory position in App A to value/impact statement preferred to position offered in guide.

  MILLB.L.M. Tennessee Valley Authority. 79/11/19. 2pp.
- 7912200274 Comments on proposed Reg Quide 1, 137; use of design base rather than performance requirements limits flexibility & control in enforcement. Prescribing actual cleaning matls limits flexibility of enforcement & improvements in sys. SCHOCK, H. Affiliation Unknown. 79/10/29, 1p.
- 7912200289 Forwards comments on proposed Reg Guide 1.131:
  "Qualification Tests of Electric Cables & Field Splices Por
  Light-Water Cooled Nuclear Power Plants." Synergistic
  Effects should not be discussed on individual basis.
  HILLS,L.M. Tennessee Valley Authority. 79/11/19. 2pp.
- 7912200304 Comments on proposed Reg Guide 1.131, "Radiation Protection Training for Light-Water Cooled Nuclear Power Plant Paraonnel." Praises NRC for efforts made to establish position re acceptable training programs.

  PETCOVIC.W.L. Nuclear Support Svcs Inc. 79/11/05, 2pp.
- 7912200419 Comments on proposed reg guide. "Reporting of Safeguard Events." Unitsions made in reg guide.Part 21 fines & prealties not addressed. LEMIB.M.I. Affiliation Unknown. 79/11/15. ip.
- 7912210055 Comments on proposed reg guide: "Reporting of Bafaguards Events." Same objective could be accomplished by integrating particular requirement for reporting into present LER requirements.

  DERMYER. W. D. Affiliation Unknown. 79/11/14. 1p.
- 7912260318 Comments on proposed Reg Guide 1.145: suggests NRC consider supplying add1 info re wet deposition affects for sites adjacent to large water bodies & alternative topographic athease for sites in complex terrain. FEDEYKO. J. K. Oilbert/Commonwealth Cos. 79/10/18. ip.
- 7912280027 Comments on proposed reg guide. "Lightning Protection for Nuclear Power Plants." Alternative regulatory position presented as App A to value/impact statement preferred to that offered in draft reg guide.

  MELLB.L.M. Tennessee Valley Authority. 79/11/19. 2pp.
- 7912280143 Comments on proposed reg guide. "Quidance on Applications for Amends to OL & on Refueling & Startup Tests." Quide should be revised to reflect agreements between NRC & BHR commers on startup physics testing.

  SHERWOOD, G. G. General Electric Co. MFN-271-79, 79/11/13. App.
- 7912280151 Comments on proposed reg guide, "Lighting Protection for Nuclear Power Plants," Surge protection requirement is severe & unwarranted.

  LDOMIG.J. S. Bargent & Lundy, Inc. 79/11/06. 4pp.

- 7912280155 Comments on proposed reg guide, "Qualification Test for Cable Penetration Fire Stops." Paragraph C2(b) state-of-the-art does not provide data on calculating actual pressure differential created by fire in given fire area.

  JACOBS, S. B. Stone & Webster Engineering Corp. 79/11/14. 1p.
- 7912280173 Comments on proposed Reg Quide 01.033: Page 14.App A.Section 9. a list of routine maint activities that may not require step by step written procedures should be clarified as to when step by step instructions are unnecessary.

  MILLS.L.M. Tennessee Valley Authority. 79/11/19. 2pp.
- 7912280185 Comments on proposed reg guide, "Lightning Protection for Nuclear Power Plants." Subsection 2 wording should be changed to insure that lightning discharge transient voltage withstand levels.

  JOCOBS.S.B. Stone & Webster Engineering Corp. 79/10/30. 1p.
- 79122805B7 Comments on proposed reg guide. "Gualification Test for Cable Penetration Fire Stops for Use in Nuclear Power Plants." No technical reason for requiring mockup of cable terminations within two ft of barrier.

  KILLS.L.M. Tennessee Valley Authority. 79/11/19. 2pp.
- 7912280648 Comments on proposed Reg Guide 8.JB; key to effective training in ALARA is training of supervisors in mgt of work in these areas.
  ANDREMS.J.P. Catalytic. Inc. (subs. of Air Products & Chemicals, Inc.). 79/11/30. 2pg.
- 7912280654 Comments on proposed Reg Ouide Oi. 131. Revision 1: addressing margin in qualification testing should be approached as described in IEEE 8td 627.
  OARSHICK.A. Power Engineering Society. 79/11/15. 13pp.
- 7712280661 Comments on proposed Reg Guides 1.120 Revision 1.1.132 Revision 1.1.70 Revision 3 & 3.44. Conditions under which an absorber fire is postulated should be clarified. MILLEL.H. Tennesses Valley Authority. 79/11/09. Opp.
- 7912310012 Comments on proposed reg guide. "Audible Alarm Dosimeters." Suggests mandatory use of dosimeters by industrial radiographers as secondary instrumentation to back up primary survey meters.

  CLARKE.E.T. Technical Operatums. Inc. 79/10/30. 3pp.
- 7912310020 Comments on proposed Reg Guides 1, 120, 1, 132, 1, 70 & 3, 44: clarification should be made of conditions under which adsorber fire should be postulated. Suggests various editoral changes.

  MILLS, L. M. Tennessee Valley Authority. 79/11/16. Sap.
- 7912310026 Comments on proposed reg guide, "Audible Alarm Dosimeters." High noise environ should be defined by db level. WHITAMERIM.B. South Carolina Electric & Gas Co. 79/11/05. lp.
- 7912310031 Comments on proposed Reg Guide 1.131.Revision 1:revision streeds process of regulatory review & embarks upon design & standardization elements not within purview of NRC. BURSTEIN.N.M. Institute of Electrical & Electronic Engineers. 79/10/31. 7pp.
- 7912310036 Comments on proposed Reg Quide i.131: Position C.5 does not explain criteria to be used to determine if accelerated aging techniques are or are not causing cable to respond in representative manner. SALDARINI.J.C. Ebasco Services, Inc. (subs. of Enserch Corp.). 79/11/06. 2pp.
- 7912310110 Comments on proposed Reg Quide 8. UB, "Radiation Protection Training for Light Water Cooled Nuclear Power Plant Personnel." Reg guide strongly endorsed Training program content refs in Paragraph 9.1 considered relevant. CROSS, L.A. American Nuclear Insurers. 79/10/28. 1p.
- 7912310130 Comments on proposed reg guide. "LWR Core Reloads: Ouidance on Applications for Amends to Ois on Refueling & Startup Tests." Initial gas fill pressure is considered vendor proprietary info.
  UHRIQ:R.E. Florida Power & Light Co. 79/11/20. 3pp.
- 7912310136 Comments on proposed reg guide, "Lightning Protection for Nuclear Power Plants." Approach in Attachment A is more logical than in reg guide.
  GETTLER.F.W. Gibbs & Hill, Inc. (subs. of Dravo Corp.). 79/10/30.

- 7918310177 Comments on proposed reg guide. "Lightning Protection for Nuclear Power Plants" Goide does not establish NRC basis for 200,000 ampere lightning surges or state required actions should surge arrestor fail required test. COPELAND.R.L. Energy, Dept. of. Clinch River Breeder Reactor Plant 79/11/07 3pp.
- 7912310182 Comments on proposed reg guide, "Ultrasonic Testing of Reactor Vessel Helds During Inservice Examination."
  Discussion should state that reg guide is intended to supplement ASME Section XI
  BUCHHOLZ,R.H. General Electric Co. 79/11/26. 2pp.
- 79:2310184 Comments on proposed Reg Guide 8. JB. "Radiation Protection Training for Light Water Cooled Nuclear Power Plant Personne)." Suggests changes to various paragraphs of guide. Changes include man-rem needs & training procedures. JENCKES.T.A. Pacific Gas & Electric Co. 79/11/07. 2pg.
- 7912310194 Comments on proposed reg guide, "Lightning Protection for Power Plants" Braft suffers in technical content due to insufficient IEEE input & should not be issued as presently written.

  ALEXANDERGON.E. Detroit Edison Co. 79/11/21. ip.
- 7912310198 Comments on proposed reg guide. "Lightning Protection for Nuclear Power Plants." Possibility of eliminating problems such as instrument failure or fuse blowing by pre-design is small. Once problem occure, solutions can be found.

  BDYER.V.S. Philadelphia Electric Co. 79/11/19. 4pp.
- 7912310360 Comments on proposed Reg Quide 8. XX:all decisionmaking supervisors & temporary & permanent parties should receive radiation prection training.
  HICKS, M.M., DESTHOFF, R.E. Utility Workers Union of America.
  79/11/28. 3pp.
- 7912310387 Reg Guide 1.97.Revision 2. "Instrumentation for Light Water Cooled Nuclear Power Plants to Assess Plant Environs Conditions During & Following Accident "

   Office of Standards Development. 79/12/31. 32pp.
- 791231049) Comments on proposed reg guide, "LWR Core Reloads: Guidance on Applications for Amends to OLs & Refueling & Startup Tests" Quantification of impact not addressed in value/impact assessment.
  HDFFMAN.D.P. Consumers Power Co. 79/11/28. 2pp.

## RES RESEARCH AND TECHNICAL ASSISTANCE REPORTS

- 7912040103 "HTGR Safety Program," For Aug 1979. SCHWEITZER,D G. Brockhaven National Laboratory. FIN A-3016. 79708/31. 49p.
- 7912040112 "Advanced Reactor Safety Analysis Technical Assistance, Reactor Projects," monthly highlights for Sept 1979. BARI.R.A. Brookhaven National Laboratory, FIN A-3000. 79709730.
- 7912040119 "SSC Code Development & Validation," monthly highlights for Sept 1979 AGRAMAL,A K., GUPPY,J.G. Brookhaven National Laboratory, FIN A-3015-8, 79/09/30, 4pp
- 7912040125 "LWR Thermal Hydraulic Development Program." monthly progress rept for Sept 1979
  JUNES.O C. Brookhaven National Laboratory. FIN A-3045. 79/09/30.
- 7912040133 "Thermal Hydraulic LMFOR Safety Experiments," monthly highlights for Sept 1979.
  JBNES, D.C. Broothaven National Laboratory. FIN A-3024. 79/09/30.
- 7912100001 "Recommendation to NRC for SER of TMI-1: Inservice Insp & Testing Program." Revision 1.
  CDPPOLA.A. RESTIVO.I. LEITIERI.V. Brookhaven National Laboratory.
  FIN A-3117. BNL-NUREC-26827. 79/09/31. 48pp.
- 7912100005 "Recommendations to NRC for SER of Cooper Nuclear Station: Inservice Insp & Testing Program," Revision 2. MALL,R.E. DEBORNE,W.C. Brookhaven National Laboratory, FIN A-3117, BNL-NUREG 26687, 79/07/31, 40pp
- 7912100011 "Review of Critical Experiments Performed for Fuel Cycle Safety Guidance," quarterly progress rept for Jul-Sept 1979. WHITEBIDES, G.E., WESTFALL, R.M. Union Carbide Corp. FIN B-0409. 79/10/24. 17pp.

- 7912110465 "Assessment of Radiation Doses Resulting From Releases of Re-222 & Re-226 from U Mining & Milling Activities," monthly progress rept for Sept 1979 TRAVIS.C.C. MCDOWELL-BOYER, WATSON, A. P. Oak Ridge National Laboratory. FIN 8-0281, 79/10/30. 3pp.
- 7912110509 "Environ Statements Project," monthly progress rept for Sept 1979. ZITTEL,H.E. Dak Ridge National Laboratory. FIN B-001. DRNL/ED/EIS-107. 79/09/30. 7pp.
- 7912140040 "Program for Standardized Analysis of Fuel Shipping Containers," quarterly summary for Jul-Bept 1979. MHITESIDES.G.E., WESTFALL.R.M. Union Carbide Corp. FIN B-0172. DRNL/CSD/INF-79. 79/10/25. 6pp.
- 7912140296 "Evaluation of Two Ultrasonic Procedures for Detection of Intergranular Stress Corrosion Cracking in Stainless Steel Piping, Code Assessment & Applications Program," evaluation rapt. REINHARDT. W. W. EG & G. Inc. FIN A-6162. EGG-FM-5035, 79/10/31.
- 7912140300 "Water Reactor Research Directorate Monthly Rept for Oct 1979."
  YBARRONDD, L. J. EG & G. Inc. YBR-199-79, 79/11/30, 100pp.
- 7912140309 "Evaluation & Recommendations for Ultrasonic Examinations of ASME Nuclear Class 1 & 2 Piping Welds.Code Assessment & Applications Program," evaluation rept. BAKER, B.L. EQ & G. Inc. COOK.J.F., WILKIN,H.A. Energy.Dept.of, Idaho Operations Office, FIN A-6162. EQO-FM-5034. 79/10/31. 55pp.
- 7912140314 "Nondestructive Examination Methods for Detection of Intergranular Stress Corresion Cracking in Stainless Steel Piping, Code Assessment & Applications Program, " evaluation rept.
  REINMARDT, W. W. EG & G, Inc. FIN A-6162. EGG-FM-5036. 79/10/31.
- 7912140368 "Decontamination as Precursor to Decommissioning," informal monthly progress rept for Oct-Nov 1979. PERRIOD.L.D. Battalle Memorial Institute, Pacific Northwest Laboratory. FIN 8-2303. 79/12/05. 25p.
- 7712140391 "Impact of Decontamination on LWR Radwaste Treatment Sys," informal monthly progress rept for Nov 1979, PERRIGO.L.D. Dattelle Memorial Institute, Pacific Northwest Laboratory. FIN B-2281, 79/12/04. 2pp.
- 7912140418 RIL-001
  Research Info Ltr 01:provides experimental evidence that safe failure mode (leak-before-break) may exist for reactor pressure vessels Forwards ORML test result of V-5 intermediate vessel Further study under way. W/o encl. KOUTS. H. J. C. Atomic Energy Commission. 74/03/19. 1p.
- 7912140420 RIL-002
  Research Info Ltr 02: transmits draft "Seismotectonic Map of Eastern United States" & accompanying text, prepared by USGS & NOAA.
  KOUTS, H J. C. Atomic Energy Commission. 74/05/20. 2pp.
- --7912140423 "Beismotectonic Map of Eastern United States." 3 sheets of oversize map encl. HADLEY.J.B., DEVINE, J.F. Interior, Dept. of, U.S. Geological Survey. 74/05/20. 8pp.
- 79121404R4 RIL-003
  Research Info Ltr 03: transmits ORNL 740724 ltr w/preliminary
  test results for heavy section steel technology
  intermediate test vessel V-7.
  KDUTS, H. J. C. Atomic Energy Commission. 74/08/07. Ip.
- --7912140427 Provides preliminary test results for heavy section steel technology intermediate test vessel V-7. Large flaws that extend nearly through reactor pressure vessel wall do not result in failure at design pressure level.

  TRAUGER. D. B. Oak Ridge National Laboratory: 74/07/24. 4pg.
- 7912140433 RIL-004
  Research Info Ltr 04: transmits USGS Miscellaneous File
  Studies Map MF-589 to provide updated info on faulting in
  coastal Southern CA.W.o encl.
  KOUTS.H.J.C. Atomic Energy Commission. 74/09/10. 2pp.

7912140440 RIL-005
Research Info Ltr 05: submits results of ORNL test ITV-7A completed 750618 flawed, 6-inch thick intermediate test vassel under sustained pneumatic load. Vessel behavior can be predicted accurately.

KNUTH, D. F. Division of Reactor Safety Research. 76/06/28. 2pp.

7912140447 RiL-005
Research Info Ltr 06: forwards Bandia Lab rept "Critique of Board-Hall Model for Detonating Thermal Explosions as Applied to U Dioxide - Sodium Sys." Board-Hall models Envalid for LMFBR accident conditions.

LEVING. B. Office of Nuclear Regulatory Research. 76/10/12. 2pp.

---7912140453 "Critique of Board-Hall Nodel for Detonating Thermal Esplosions as Applied to U Dioxide - Sodium Sys." Draft rept. WILLIAMS,D. Bandia Laboratories. AT(49-24)-018. 76/08/19. 9pp.

7912140484 RIL-025 .
Research Info Ltr 25:transmits FRAP-53 code description & verification documentation. Forwards ID Natl Engineering Lab Repts TFEP-TR-164 Revision 2 & TEBP-TR-28, LEVINE,S. Office of Nuclear Regulatory Research. 78/03/24. 17pp.

--7912140461 TFBP-TR-164 V1
"FRAP-53 Analytical Models & Input Manual:FRAP-53.Computer
Code for Steady-State Analysis of Oxide Fuel Rods: " Vol 1.
SOHN.M.P., DEARIEN.J.A., CROCKER.J.G. Idaho National Engineering
Laboratory. EY-76-C-07-1570. 78/03/31. 178pp.

--7912140468 TFBP-TR-228 V2
-FRAP 53:Computer Code for Steady-State Analysis of Oxide
Fuel Rode: Vol 2 - Model Verification Rept."
DEATEN, J. A., CROCKER, J. G. Idaho National Engineering Laboratory,
EY-76-C-07-1570. 77/08/31, 157pp.

7912140458 RIL-007
Research Info Ltr 07: submits info re SIMMER-T computer code developed at Los Alamos Lab to follow motion & neutronics of LMFBR cores during hypothetical core disruptive accidents.

LEVINE: 8. Office of Nuclear Regulatory Research. 76/08/25. 4pp.

7912140464 RIL-008 Suppl to Research Info Ltr 8: transmits draft ORNL/NUREO-14, "Decay Heat Applicable to LOCA Evaluation." M/o encl. LEVINE,S. Office of Nuclear Regulatory Research. 77/05/18, 1p.

7912140467 "Review of Critical Experiments Performed for Fuel Cycle Safety Guidance: " informal quarterly progress rept. HHITEGLOEG, O. E. HERIFALL, R. M. Oak Ridge National Laboratory. FIN 8-0409, DRNL/CSD/INF-79, 79/10/24, 18pp.

7912140471 RIL-009
Research Info Ltr 09: transmits results of completed
research on high temp oxidation of Zircaloy fuel cladding
in stame.
LEVING.B. Office of Nuclear Regulatory Research. 77/03/14. 17pp.

7912140474 RIL-026
Rassarch Info Ltr 26: transmits results of completed research on impact of offenore nuclear generation stations on recreational behavior at adjacent coastal sites (MREO-0374).
LEVING. 8. Office of Nuclear Regulatory Research. 78/04/27. 2pp.

--79121404B3 NUREC-0394
"Impact of Offshore Nuclear Generating Stations on
Secreational Behavior at Adjacent Coastal Sites."
SMER: E. J., MOSB, D. J., MEST, S. O. Florida State Univ.
AT449-24-0320. 77/12/31. 147pp. Available at NTIS.

7982140475 RIL-010
Research Info Ltr 10:transmits results of completed
research on evaluation of probability of pressure vessel
failure from pressure transients that can occur during PNR
operation.
LEVINE.S. Office of Nuclear Regulatory Research. 77/02/25. 4pp.

7712140460 RIL-011
Research Info Ltr 11: transmits results of completed research on dayalogent of failure rate data manual applicable in risk & replainity analysis of reactor sys. H/o encl. 1EVINE.S. Office of Nuclear Regulatory Research. 77/09/15. 2pp.

7912140486 "Shipping Cask Sabotage Source Term Investigation," informal annihity progress rept for Nov 1979. SCHHIDT,E.W. Battelle Memorial Institute, Columbus Laboratories, FIN 8-6012. 79/12/06. Spp.

7912140487 RIL-027
Research Info Ltr 27: transmits BEACON/MOD 2 code manual & description. Code intended for evaluation of short-term thermodyldraulic conditions within full pressure multicompartment containments or within containment drywell. LEVINE.S. Office of Nuclear Regulatory Research. 78/06/02. 23pp.

7912140488 RIL-012
Research Info Ltr 12: transmits results of mods to OCTAVIA computer code for pressure vessel failure probability prediction. Wo encl.
LEVINE, S. Office of Nuclear Regulatory Research. 77/06/16. 2pp.

7912140493 RIL--013
Research Info Ltr 13: transmits verified model for predicting residual stresses resulting from girth-butt welding of pipes & strimation of residual stresses resulting from weld repairs of vessels.

LEVINE, B. Office of Nuclear Regulatory Research. 77/ii/ii. 3pp.

--7912140503 "Evaluation of Mathod for Predicting Residual Stresses in Girth-Butt Welds." a Dattelle Mamorial Institute, Columbus Laboratories. 77/11/11. 34pp.

7912140495 RIL-028
Research Info Ltr 28: describes INTER-1 code for calculating effects of interaction between molten matls & concrete.
Forwards Sandi Lab Rept SAND77-2042, "Exploratory Study of Holten Core Matl/Concrete Interactions, Jul 1975-Har 1977."
LEVINE, B. Office of Nuclear Regulatory Research. 78/05/09. Spp.

--7912140499 SAND77-2042
"Exploratory Study of Molten Core Matl/Concrete
Interactions Jul 1973-Mar 1977."
POMERS D. A. PANLOREN, D. A. MUIR, J. F. Sandia Laboratories,
AT(29-1)-789, 78/02/28, 180pp. Available at NTIS.

7912140502 RIL-029
Research Info Ltr 29: transmits results of completed research to prepare & test FRAP-T3 feel rod analysis computer code.
Forwards ID Natl Lab Rept TFEP-TR-194. "FRAP-T3 - Computer Code for Transient Analysis of Oxide Fuel Rods."
LEVINE.S. Office of Nuclear Regulatory Research. 78/06/07. 16pp.

--7912140505 TEBP-TR-194
"FRAP-T3 - Computer Code for Transiant Analysis of Dride
Fuel Rads."
DEARIEM J. A., CROCKER, J. G.
EY-76-C-07-1570, 77/08/31, 356pp.

79:2:140506 RIL-014
Research Info Ltr 14: transmits results of completed portion of NRC fire protection research program re adequacy of cable tray separation to prevent spread of electrically initiated & dyposure fires. W/o encl.
LEVINE. 8. Office of Nuclear Regulatory Research. 77/11/09. 7pp.

7912140507 RIL-030
Research Info Ltr 30: discusses Phase I final rapt. "Barrier Penetration Data Base." of study "Assistance - Physical Protection Assessments."
LEVING.S. Office of Nuclear Regulatory Research. FIN A-3210. 78/06/29. 2pp.

7912140509 RIL-015
Research Info Ltr 15: transmits current info on fracture
machenics characterization of nozzle corner cracks in BWR
feedwater nozzles. W/o sncl.
LEVINE.S. Office of Nuclear Regulatory Research. 77/12/01. 4pp.

7912140510 "Program for Standardized Analysis of Fuel Shipping Containers," informal quarterly progress rept. WHITESIDES, C.E., WESTFALLR.M. Oak Ridge National Laboratory. FIN B-0172. DRNL/CSD/INF-79. 79/10/25. Spp.

7912140511 RIL-016
Research Info Ltr 16: transmits verified experimental data on warm prestressing for use in licensing evaluation of nuclear power plants.
LEVING.B. Office of Nuclear Regulatory Research. 77/12/01. App.

7912140512 RTL-008
Research Info Ltr 8:transmits results of completed research re-decay heat data applicable to LOCA evaluation for LWRs.
H/o encl.
LEVINE.8. Office of Nuclear Regulatory Research. 77/01/31. App.

- 7912140514 RIL-017
  Research Info Ltr 17 transmits "Response of Unirradiated & Irradiated PWR Fuel Rods lested Under Power-Cooling-Mismatch Conditions" prepared by ID Natl Engineering Lab.
  LEVINE.S. Office of Nuclear Regulatory Research. 78/05/05. 18pp.
- 7912140515 RIL-021
  Research Info Ltr 21 transmits results of completed
  research entitled "Critical Review of Sodium Hydroxide
  Aerosol Toxicity," designated HSPH/EHS (NUREG)-880.
  LEVINE.S. Office of Nuclear Regulatory Research. 78/03/24. 3pp.
- --7912140517 HSPH/EHS(NUREO)-880
  "Critical Review of Sodium Hydroxide Aerosol Toxicity."
  COOPER,D.W., UNDERHILL,D.W., ELLENDECKER,M. Harvard Univ.
  AT(49-24)-0300. 77/12/31. 64pp.
- 7912140518 RIL-018
  Research Info Ltr 18:transmits results of completed research on development of FRANTIC computer code to calculate sys unavailabilities. Forwards user's manual (NUREG-0193) & descriptive rept. M/o encl.
  LEVINE, S. Office of Nuclear Regulatory Research. 77/11/09, 2pp.
- 7912140519 RIL-023 Research Info Ltr 23 transmits results of completed research on devolopment of graphics display version of EASI estimate of adversary sequence interruption model.Forwards SAND70-0112, SAND76-0500, SAND76-0597 & SAND77-0082, W/o encl. LEVINE, S. Office of Nuclear Regulatory Research. 78/04/10. 3pp
- 7912140520 RIL-019
  Research Info Ltr 19 transmits research results on assessment of GD methodology for performing reliability evaluations of sys & subsys W/o encl.
  LEVINE,S. Office of Nuclear Regulatory Research. 78/01/31. 2pp.
- 7912140521 RIL-024 Research Info Ltr 24:transmits results of completed research by Sandia Lab on FESEM forcible entry effectiveness model. LEVINE.S. Office of Nuclear Regulatory Research. 78/04/10. Spp.
- 7912140522 RIL-033
  Research Info Ltr 33 transmits documented results from research propriem to design develop & test PAT-1 Pu package per criteria in NUREG-0360. Forwards SAND78-0724: "Pu Accident Resistant Container Project" & NUREG/CR-0030. LEVINE, S Office of Standards Development. 79/08/03. 8pp
- --7912140524 SAND78-0724
  "Pu Accident Resistant Container Project."
  ANDERSEN, J. A. Sandia Laboratories. 78/05/31. 28pp. Available at NYIS
- --7912140526 NUREG/CR-0030

  "PARC (Pu Accident Resistant Container) Program Research,
  Dasign & Development."
  ANDERSEN, J. A., BUFFEY, T. A., BUPREE, G. A., Sandia Laboratories,
  SAND76-587 78/07/31, 397pp. Available at NTIS.
- 7912140523 RIL-020
  Research Info Ltr 20:transmits results of completed research into physical protection equipment Study is Phase I of continuous research effort re insp methods for physical protection.
  LEVINE, S. Office of Nuclear Regulatory Research. 78/01/24. 2pp.
- 7912140540 "Code Assussment & Applications Program Addl Audit Calculations for Westinghouse PWR Small Breaks." preliminary assussment rept for Nov 1979.
  FLETCHER, C. D. EG & G. Inc. FIN A-6047. EGG-CAPP-5052. 79/11/30.
- 7912170167 "Div of Reactor Safety Research ORNL Programs," monthly highlights for Oct 1979.

  HYNATT,F.R. Dak Ridge National Laboratory. FIN 0-0413.

  ORNL-41-89-55-1. 79/11/13 30pp.
- 7912170174 "Safeguards Analysis for Byproduct Hatls & Small Quantities of SNN," monthly progress rept for Oct 1979.
  CHEBTER, R. D., KANAK, K. K., RANDOLPH, H. L. Oak Ridge National Laboratory. FIN B-6108. QRNL/HASRD-57. 79/11/13. 6pp.
- 7912170194 "Semiscale Program." summary rept for Oct 1979. CDZZUDL.J.M., ROGERS.Q.M. EQ & O. Inc. FIN A-6038. E00-BEMI-5018. 79/10/31. 72pp.
- 7912170320 "Integration of NDE (Nondestructive Examination) Reliability & Fracture Mechanics," monthly progress rept for Nov 1979.
  BECKER, F. L. Battelle Memorial Institute, Pacific Northwest
  Laboratory, flN 8-2289, 79/12/10, 4pp.

- 7912170337 "Sandia Core Melt & Separate Effects Program," monthly ltr for Oct 1979. DERMAN.M. Sandia Laboratories. 79/11/30. 8pp.
- 7912170359 "Neutron Dosimitry at Commercial Nuclear Sites," preliminary rept at Sites E.F & Q. ENDRES, G.W. R., ALDRICH, J. M., GRIFFITH, R.V. Battelle Memorial Institute, Pacific Northwest Laboratory. FIN B-2282. 79/12/17.
- 7912170422 "Environ Assessments of Fuel Cycle Facilities," monthly progress rept for Oct 1979.
  ZITTEL.H.E. Dak Ridge National Laboratory, FIN B-0279.
  GRNL/ED/EIS-108. 79/10/31. 4pp.
- 7912180143 "LWR Pressure Vessel Irradiation Program," foreign trip rept. STALLMANN,F.H. Qak Ridge National Laboratory. FIN B-0415. QRNL\_FTR-751. 79711/06. 10pp.
- 7912180146 "LWR Source Torm Measurements Program," informal monthly progress rept for Nov 1979. MANDLER, J. W. EG & G. Inc. FIN A-6075. 79/11/20. 4pp.
- 7912180152 "Radiation Streaming Study," informal monthly progress rept for Oct 1979. COHEN.M. O. Mathematical Applications, Inc. FIN 8-6206. 79/11/20.
- 7912180158 "Experimental Criticality Data for Code Validation," progress rept for Nov 1979.
  BIERMAN, S.R. Battelle Memorial Institute, Pacific Northwest Laboratory. FIN 11-2094. TDO-777. 79/12/03. 2pp.
- 7912180165 "Investigation of Post-Critical Heat Flux Heat Transfer for Mater Cooled Reactor Application & Development of Two-Phase Flow Instrumentation." monthly progress rept for Nov 1979. CHEN.J.C., SUNDARAM.R.K., NIJHAWAN,S. Lehigh Univ. FIR A-4055. 79/12/06. 5pp.
- 7912190544 "Chemical Effluents in Surface Waters from Nuclear Power Plants," quarterly progress rept for Apr-June 1979. HARRIBON.F. L. Laurence Livermore Laboratory. FIN A-0119. 79/08/13. 15pc.
- 7712190846 "Threadfin Shad Impingement:Population Response," quarterly progress rept for Apr-June 1979.
  VAN WINKLE, W., MCLEAN.R.V. Oak Ridge National Laboratory. FIN B-0406. 79706/30. Spp.
- 7912190547 "Bediment & Radionuclide Transport in Rivers Field Sampling Program Cattaraugus & Duttermilk Creeks,NY," quarterly progress rept for Apr-June 1979.

  \* Dattelle Memorial Institute, Pacific Northwest Laboratory. FIN B-2275. 79/06/30. 18pp.
- 7712190552 "Kinetics of Chlorine-Ammonia Reactions in Sea Water," quarterly progress rept for Apr-June 1979.
  JOHNBON, J. D., INMAN, G. W. North Carolina, Univ. of. FIN B-6248.
  NRC-04-77-119. 79/06/30. 9pp.
- 7912190557 "Mathematical Simulation of Sediment & Contaminant Transport in Surface Waters," quarterly rept for Apr-June 1979.

   Battelle Memorial Institute, Pacific Northwest Laboratory. FIN 8-2271 79/06/30, 16pp.
- 7912190561 "Threadfin Shad Impingement:Causes & Ecological Implications in Southeastern Reservior." HCLEAN.R.B., ORIFFITH.J.S., MCOEE.M.V. Dak Ridge National Laboratory. FIN B-0406. 79706/30. 34pp.
- 7912190367 "LOFT Experimental Program Division," pretest prediction rept. GRUSH, W. H., SHINKO, M. S. EG & G, Inc. FIN A-6048. DE-ACC7~761D019. 79/11/30. 77pp.
- 7912190570 "Gode Assessment & Applications Program," preliminary assessment rept for Nov 1979.
  DAVIS,C.B., FLETCHER,C.D. EG & G. Inc. FIN A-6047.
  DE-ACO7-7610015, 79/11/30. 43pp.
- 7912200279 "Fission Product Transport Analysis," monthly 1tr for Oct 1979.
  0IESEKE, J. A. Battelle Homorial Institute, Columbus Laboratories.
  NRC-04-76-293-02. 79/11/27. 3pp.

- 7912310035 "Biocide Byproducts in Aquatic Environs," quarterly progress rept for Apr-June 1979.
  ANDERSON.D.R., BEAN.R., GIBSON.C. Battelle Memorial Institute,
  Pacific Northwest Laboratory. FIN 8-2098-9. PNL-3084. 79/07/31.
  7pp.
- REVIEW ORP NRC RESEARCH REVIEW GROUPS
- 7912140253 Summary of 791101 meeting w/vendors.utils & licensees re cladding rupture temp, cladding strain & assembly flow blockage. DENISE, P. Assistant Director for Reactor Safety. 79/11/20. 6498.
- 7912190000 Notifies of fuel code program review meeting to be held B00108 in Silver Spring, MD. Discussions will be held restates of FRAP-T & FRAPCON fuel codes & severe fuel damage modeling requirements.

  MARIND, G. P. Fuel Behavior Branch. 79/12/03. 3pp.
- 7912190273 Notifies of informal meeting w/Natl Weather Svc to discuss use of NDAA weather radio for early warning & notification criteria.

  AXELSON, H. L. Emergency Preparadness Task Force. 79/11/19. 1p.
- 7912190276 Summary of 791105-08 review of facility emergency plan & AR radiological emergency plans.
  AXELSCN: W. L. Emergency Preparedness Task Force. 79/11/15. Spp.
- 7712190281 Buggests agency contact Federal Emergency Mgt Agency natl ofs & request adequate radiological instrumentation for US Casst Guard emergency teams. AXELBON.W.L. Emergency Proparedness Task Force. 79/11/19. 1p.
- BECY POSITION PAPERS DEFORE THE COMMISSION
- 7912170054 Transcript of 791203 discussion in Washington.DC on SECY-79-591. "Plans for Coping w/Emergencies at Production & Utilization Facilities." Pp 1-51. Summary encl. BRDHN:C.H. Office of the Secretary of the Commission. 79/12/03. 53pp.
- 7912200087 Discusses delegation of authority to director of NMS9 to approve actions under Public Law 95-204 (BECY-79-484).
  Actions re concurrence same as performed in licensing activo mills. Concurrence actions & Title 1 activities lists encl.
  DIRCMS.M.J. Office of Nuclear Material Bafety & Bafeguards.
  SECY-79-484. 79/12/07. 7pp.
- STATE PROG STATE PROGRAMS
- 7912030239 Comments on emergency preparedness section of TMI Lessons learned rept in response to 791017 meno. RYAN.R.O. Office of State Programs. 79/11/06. 1p.
- 7912040012 Comments on draft rept on lessons learned from TMI. Suggests Ofc of Stds take lead in coordinating changes in emergency preparedness plans.

  RYAN.R.G. Office of State Programs, 79/11/06. 2pp.
- 7912040055 Notification of housing arrangements for 791203-07 Federal Interagency course in Wildwood,FL for radiological amergency response coordinators. COLLINS.H.E. Office of State Programs. 79/11/16. ip.
- 7712040068 Forwards draft copy of SANDI SAI contract statement of work & stercise scenario. Funds not available for continued support of technical assistance for state programs.

  COLLINS: H. E. Diffice of State Programs. 77/11/07. ip.
- 7912040146 Forwards special insp repts to WA Dept of Social & Health Svcs. In Aug 1979, NRC conducted special insps of Nuclear Enginessing Co burbal sites in WA & NV to observe arrivals of radwaste shipments from TMI-2. W/o encl. MERR. O. M. Assistant Director for State Agreements Programs. SA/JOL. 79/11/08. ip.
- 7912040171 Advises Dept of Public Health that CO Springs Memorial Hosp.

  Danver Mini-Dose Labs & CO Springs Penrose Hosp received

  Xe-133 from nonapproved supplier (ORNL) in FY7B Requests

  review of license condition wording.

  KERR, O. M. Assistant Director for State Agreements Programs.

  BA/ECA. 79/11/15. 2pp.

- 7912040175 Advises Dept of Conservation that St Patrick Hosp & Telatope Pharmacy received Xe-133 shipments from nonapproved supplier (ORNL) in FY78 Review of license condition wording requested.

  KERR, G. M. Assistant Director for State Agreements Programs.

  79/11/15. 2pp.
- 7912040185 Advises Dept of Health that Methodist Hosp & Texatope Pharmacy received Xe-133 shipments from monapproved supplier (DRNL) in FY7B. Review of license condition wording requested.

  KERR.G. M. Assistant Director for State Agreements Programs.

  79/11/15. 2pp.
- 7912040192 Advises Dept of Health & Social Svcs that Holy Family Hosp & Univ of WA received Xe-133 shipments from nonapproved supplier (CRNL) in FV78. Review of license condition wording requested. KERR. G. U. Assistant Director for State Agreements Programs. 79/11/15. 2pp.
- 7912040199 Advises NY State Energy Ofc that Sloan-Kettering Inst received Xe-133 shipments from nonapproved supplier (ORNL) in FY7B. Review of wording in license condition requested. KERR. G. W. Assistant Director for State Agreements Programs. 79/11/15. 1p.
- 7912040205 Advises Div of Facility Svc that Dute Univ received Xe-133 shipments from nonapproved supplier (ORNL) in FY78 Review of wording in license condition requested.

  KERR. G.W. Assistant Director for State Agreements Programs, 79/11/15. 1p.
- 7912050565 Notifies that on 790911. Chairmanship of Federal Interagency Central Coordinating Committee passed to Federal Emergency Mgt Agency. RYAN. R. 6. Federal Interagency Central Coordinating Committee. 79/11/19. ip.
- --7912050571 Notifies that on 790911 Chairmanship of Federal Interagency Central Goordinating Committee passed to Federal Emergency Hgt Agency. HENDRIE.J.M. Commission. MACY.J.W. Federal Emergency Hanagement Agency. 79/10/31. ip:
- --7912050573 Notifies that on 790911 Chairmanship of Edderal Interagency Central Coordinating Committee passed to Federal Emergency Mgt Agency. HENDRIE, J. M. Commission. MACY, J. W. Federal Emergency Management Agency. 79/10/31. 1p.
- --7912050578 Notifies that on 790911 Chairmanship of Federal Interagency Central Coordinating Committee passed to Federal Emergency Mgt Agency. HENDRIE.J.M. Commission. MACY.J.W. Federal Emergency Management Agency. 79/10/31. tp.
- --79120505B1 Notifies that on 790911 Chairmanship of Federal Interagency Central Coordinating Committee passed to Federal Emergency Mgt Agency. HENDRIG.J.M. Commission. MACY.J.W. Federal Emergency Management Agency. 79/10/31. (p.
- 7912030595 Requests that comments on NUREO-0625 be sent to HR Denton & RO Ryan by 791122.

  RYAN,R.O. Federal Interagency Central Coordinating Committee.
  79/11/06. 1p.
- 7912060298 Discusses Western Interstate Energy Board decision to join Task Force on Emergency Planning for Transportation Accidents, RYAN.R.G. Office of State Programs. 79/11/09. 1p.
- 7912100379 Forwards NRC & EPA emergency planning guidance publications & regulations. M/o encl.
  COLLING.H.E. Assistant Director for Emergency Preparedness.
  79/11/28, ip.
- 7912100381 Notifies of forthcoming draft of example plan for response to radiological accident by fictitious town of Brownvillo. Requests evaluation using NUREG-75/111 criteria. CDLLING.H.E. Assistant Director for Emergency Preparedness. 79/11/28. 1p.
- 7912100382 Requests add1 PA Emergency Mgt Agency brochures. "What You Should Know About Nuclear Radiation Incidents." COLLINS.H.E. Assistant Director for Emergency Preparadness. 79/11/28. ip.

- 7912110039 Forwards rupy of catalog portions pertaining to agreement natl licences & amends to LOCFR71.Wo encls.
  ASHLEY, E. C. Office of State Programs. 79/11/23. 1p.
- 7912110053 Notifies of 791210-14 review of TN radiation control program, including field evaluations by state inspections. Suggests summarization of results on 791214.

  KERR, O. W. Office of State Programs. SA/KNS. 79/11/23. 1p.
- 7912110063 Discusses 791210 telcon re review of HA radiation control program. Suggests summarization of results on 791224.

  KERR. O. W. Office of State Programs. SA/JOL. 79/11/23. 1p.
- 7912110242 Forwards draft catalog of training programs on radiological emergency response planning & preparedness re 790817 request. Wo encl. COLLING. H.E. Assistant Director for Emergency Preparedness. 79/11/28. 1p.
- 7912120091 Responds to 790814 1tr & forwards info re measurements made to determine time radwaste matl may be disposed of an regular trash.

  KERR, G. M. Office of State Programs. 79/11/05. 1p.
- 7912120183 Forwards discrepancy rept re radwaste shipment from FL shipper to Barnwell site. W/o encl. KERR. C. W. Office of State Programs. 79/11/05. 1p.
- 7912120371 Fowards comments on 790907 draft of \*NV Regulations for Control of Radiation. \* Strongly urges some additions & corrections M/o encl.

  KERR, C. M. Assistant Director for State Agreements Programs.

  79/11/23. 1p.
- 7912170103 Forwards list of approved state govt attendees for 791128-1207 radiological energency response operations course for security requirements & recordkeeping. COLLING.H.E. Office of State Programs. 79/11/21. 1p.
- 7912170392 Expresses appreciation for NRC 791025 ltr.describing visit & investigation of radiation control program. Concurs w/findings & suggestions.

  TRAYLOR,F. Colorado, State of. 79/11/09. 1p.
- 7912180101 Expresses appraciation for arranging for TERA Corp to microfiche radiological emergency response plans. CAUT.H. Office of State Programs. 79/11/23. 1p.
- 7912180104 Details progress made on providing potassium Iodide for large scale radiological accident at nuclear power plant. GREEN.K. Office of State Programs. 79/11/09. 2pp.
- 7912180300 Responds to 791106 1tr re research programs in emergency planning & preparedness Suggestions on needed research encl.

  DIRCKS, W. J. Office of Nuclear Material Bafety & Bafeguards.

  79/12/03. 2pp.
- 7912190037 Discusses potential for conflict of interest in util emergency planning for state & local jurisdictions. Opinion requested.
  RYAN.R.O. Office of State Programs. 79/11/28. 2pp.
- 791219006B Discusses uptions for financial assistance to state & local governments for emergency preparedness programs, in addition to federally administered fund suggested in NUREO 0553.

  RYAN.R.G. Office of Nuclear Reactor Regulation, 79/11/21. 2pp.
- 7912:90101 Responds to request for review of LABL "Statement of Work for Technical Assistance in Implementing Emergency Preparedness Requirements." Document does not everlap w/ Standard Order for DOE work (INEL), COLLING.H.E. Assistant Director for State Agreements Programs, 79/11/27, 1p.
- 7912190111 Forwards maths requested by OK State Civil Defense re thyroid blocking & NRC training program. M/o encl. COLLINS. H.E. Assistant Director for State Agreements Programs. 79/11/20. ip.
- 7912210015 Discusses membership k history of Interorganizational Advisory Committee on Radiological Emergency Response Planning & Preparedness. Act AV Godwin participation. RYAN.R.O. Office of State Programs. 79/12/07.

- 7912210056 Natifies there are no instances where emergency plan concurrance expected to pose difficulty provided current std far concurrence (NUREO-75) used Addl requirements may raise problems.

  COLLINS, H. E. Assistant Director for Emergency Preparadness. 79/11/29. 1p.
- 7912260023 Forwards comments on draft City of Brownsville, TX mxample of radiological emergency response plan for nuclear facility accident. Plan not consistent w/NUREO-75/11.
  RYAN.R.O. Office of State Programs. 79/12/04. 7pp.
- 7912260123 Designates ME Sanders as Acting Assistant Director 791215-1222. COLLINS, H. E. Assistant Director for Emergency Preparedness. 79/12/14. ip.
- 7912260263 Forwards comments on French emergency planning documents requested by French Civil Defense Director Documents fail to give clear guidance for emergency planning procedures. CDLLINS.H.E. Defice of State Programs. 79/11/27. 7pp.
- 7912270037 Dutlines history of Interorganizational Advisory Committee on Radiological Emergency Response Planning & Preparedness. Ack participation of LJ Daly.
  RYAN.R.O. Office of State Programs. 79/12/07. 1p.
- 7912270042 Dutlines history of Interorgenizational Advisory Committee on Radiological Emergency Response Planning & Preparedness. Ack participation of WM Bjørenson. RYAN.R.G. Office of State Programs. 79/12/07. 1p.
- 79:2270046 Dutlines history of Interorganizational Advisory Committee on Radiological Emergency Response Planning & Preparedness. Ack participation of TA Mack. RYAN.R. @. Office of State Programs. 79/12/07. ip.
- 7912270074 Outlines history of Interorganizational Advisory Committee on Radiological Emergency Response Planning & Preparedness.
  Ack participation of JL Montgomery.
  RYAN-P. O. Office of State Programs. 79/12/07. 1p.
- 7912270076 Outlines history of Interorganizational Advisory Committee on Radiological Emergency Response Planning & Preparedness.
  Ack participation of GM Brower.
  RYANS. O. Office of State Programs. 79/12/07. ip.
- 7912270079 Outlines history of Interorganizational Advisory Committee on Radiological Emergency Response Planning & Preparedness. Ack participation of JJ Kearns. RYAN.R.Q. Office of State Programs. 79/12/07. 1p.
- 7912270086 Outlines history of Interorganizational Advisory Committee on Radiological Emergency Response Planning & Preparedness. Ack participation of 8 Davies. RYAN-R.O. Office of State Programs. 79/12/07. 1p.
- 7912270074 Outlines history of Interorganizational Advisory Committee on Radiological Emergency Response Planning & Preparedness. Ack participation of EE Jones. RYAN.R.O. Office of State Programs. 79/12/07. 1p.
- 7912270108 Outlines history of Interorganizational Advisory Committee on Radiological Emergency Response Planning & Preparadness. Ack participation of BJ McClelland. RYAN.R.9. Office of State Programs. 79/12/07. 1p.
- 7712270112 Outlines history of Interorganizational Advisory Committee on Radiological Emergency Response Planning & Preparadness. Act participation of F Mancuso. RYAN.R.O. Office of State Programs. 79/12/07. 1p.
- 7912270129 Forwards AR Emergency Operations Plan Annex G-Radiological Incident Response, w/790827 transmittal ltr. W/o encl. CLEVELAND, R. Assistant Director for Emergency Preparedness, 79/12/06. 1p.
- 7912270157 Outlines history of Interorganizational Advisory Committee on Radiological Emergency Response Planning & Preparedness, Ack participation of JH Proctor.
  RYAN.R.O. Office of State Programs. 79/12/07. ip.
- 7912280615 Forwards TMI task action plan resource requirements in response to 791214 request. W/o encl.
  RYAN.R.O. Office of State Programs. 79/12/20. 1p.

- 7912280624 Forwards list of NRC approved state govt attendees (students) for 80009-18 radiological emergency response aparations course.
   CQLLINS.H.E. Assistant Director for Emergency Preparadness.
   79/12/20. 1p.
- 7912310185 Confirms discussions following review of State of TX radiation control program. NRC program for regulation of agreement astl is adequate to protect public health & safety. Improvement possible in budgeting.
  RYAN.R. 0. Office of State Programs. SA/LAB. 79/12/13. Ppp.
- 7912310327 Forwards CO Dept of Health 790525 ltr requesting that Federal Emergency Mgt Agency inventory & redistribute Model CDV 7DO survey meters & CDV 138 dosimaters. Seeks views re usefulness & feasibility of request. RYAN.R. G. Office of State Programs. 79/12/11. 1p.
- 7912310334 Requests printed descriptional matter mini terminal data satellite.
  COLLING. H. E. Office of State Programs. 79/12/06. ip.
- 7912310484 Forwards proposed additions to ection plan items, including facusents covering radioiodine easing collection devices.

  W/o ancl.

  COLLINS.H.E. Assistant Director for Emergency Preparadness.
  79/12/05. 1p.

## TOPREP VENDOR REPORTS AND RELATED CORRESPONDENCE

- 7907260948 Discusses investigation of possible overexposures of four suplayers to radioactive matls. Cites evidence indicating siposure values reported by Helgeson Nuclear Bycs are in effor.

  REYNOLDS.L.E. Chem-Nuclear Systems, Inc. 79/06/14. ip.
- 7912030074 Bushary of 791025 meeting w/OE & OE owners group in Sathesda. MD re development of emergency procedures for imal! break LOCAs & outstanding request for add1 info. THOMAS. C. O. TMI-2 Bulletins & Orders. 79/11/16, 12pp.
- 7912030303 Forwards proprietary & nonproprietary versions of CENPD-263, "ATM8 Early Verification," in response to NRC 790215 ltr re C-E MESS. Proprietary version withheld (ref 10CFR2. 790). Affidavit and.
  POINDEXTER, C. H. C-E Operating Plants Owners Oroup. 79/11/30. 5pp.
- ---7912030203 CENPD-263-NP
  Nonproprietary version of "ATMS Early Verification," in
  response to NRC 790215 1tr re C-E NSSS.
  6 C-E Power Systems. 79/11/30. 147pp.
- 7912040213 Forwards Revision 1 to "Nuclear Energy Business Group EWR GA Program Description."
  DREED, A. General Electric Co. 79/11/29, 2pp.
- --- 7912040235 NEDO-11209-04A
  "Nuclear Energy Business Group BWR QA Progrem Description,"
  Revision 1.

   General Electric Co., Nuclear Energy Products Div. 79/11/29.
- 7912040300 "Review of LLL Draft Beissic Hazard Analysis." # 1837/John A. Blues & Assoc. Engineers (subs. of URS). 79/10/31.
- 7912040336 Bubmits results of avaluation of fuel rad heatup rats prior to burst. No safety problem for Westinghouse plants identified & all plants are in conformance w/NRC regulations.

  ANDERSON, T. M. Westinghouse Electric Corp. N8-THA-2163. 79/11/16. 55s.
- --7912040357 Confirms 791102 telcon re nonconservative feature in Nestinghouse large break ECCS evaluation models. Overall evaluation planned.

  AMDERSON, T. M. Westinghouse Electric Corp. NS-TMA-2158. 79/11/16.
- 7f12040383 Submits evaluation of NUTECH 791003 rept.88P-01-001, "Smoke Simulation Prototype Test Conducted at Yankes Rowe Nuclear Plant." Tracer gas technique feasible for study of smoke mevament.

  300010.J. Brookhaven National Leboratory. 79/11/30. 15pp.

- 7912050509 Submits results of evaluation of all operating plants licensed w/Mestinghouse ECCS evaluation model re use of heatup rate dependent burst model in small break evaluation model. No safety problems identified.

  ANDERSON.T.M. Westinghouse Electric Corp. NS-TMA-2163. 79/11/16. Opp.
- 7912050548 Discusses abnormal event evaluation repts on nuclear steam supply sys designed by Hestinghouse Requests feedback on format & content of repts & recommendations or distribution of repts.

  ANDERSON.T.M. Hestinghouse Electric Corp., PHR Systems Div. 79/11/13. 39pp.
- 7912050559 Requests finel NRC position re acceptance criteria for Mark I containment long-term program. Plant unique analysis will be submitted upon receipt of final resolution of NRC acceptance criteria.

  5080N.L.J. General Electric Co., Nuclear Energy Products Div. MFN-289-79, 79/11/30. 4pp.
- 7912060521 Discusses method used to calculate cladding hoop stresses at perforation. Forwards Suppl A re CHASTE 05 swelling & rupture model.

  BUCHHOLZ, R. H. General Electric Co. MFN-278-79, 79/11/16, 13pp.
- 7912070391 Forwards Mark 1 contamination program strata to NEDE-24539-P, "Full Scale Test Program Final Rept." Froprietary info withheld (ref 10CFR 2.790). SDEON, L. J. General Electric Co. MFN-283-79, 79/11/27, 2pp.
- 7912070477 Notification of 791206 meeting w/9844 to discuss technical support ctr design, including data transmission. TELFORD, J. T. MI-2 Lessons Learned Task Force. 79/11/29. 2pp.
- 7912110332 Forwards std order for DDE work. EISENMUT.D.O. Division of Operating Reactors. FIN A-6265. 79/11/12. ip.
- --7912110357 Btd order for DDE work: "Electrical Instrumentation & Control Bys Support," issued to EQ & Q.Inc.
  TRIPLETT.M.P. Office of Nuclear Reactor Regulation. FIN A-6256.
  20-80-39. 79/10/11. 11pp.
- 7912110595 BNL-NUREO-26789
  "Condensation Induced Water Hammer in Steam Generators," grepared for presentation at Joint US-Japan Info Exchanges on Two Flow Dynamics Osaka Univ. Osaka, Japan, 790801-03, JONES, G. C., BAHA, P., WU, B. J. C. Brookhaven National Laboratory, BNL-NUREO-26789, 79/06/30. 19pp.
- 791212010B BNL-NUREO-26422
  "LMFBR Thermal Hydraulic Analysis:Impact of Fleat Transport
  Bys."
  MADMI, I.K., AQRAMAL, A.K. Brunkhaven National Laboratory, 79/12/11,
  43pp.
- 7912120112 Bummary of 791113 meeting w/Westinghouse rs LOCA cladding models. DEN186.R.P. Assistant Director for Reactor Safety. 79/11/16. 2pp.
- 7912120121 BNL-NWRE0-26464

  "Inception & Davelopment of Voids in Flashing Liquids."
  prepared for presentation at Joint US Japan Info Exchange
  on Two Phase Flow Dynamics, Osaka Unity, Dsaka, Japan, 790801-03.
  JONES, C. C. Broothavan National Laboratory. 79/06/30. 35pp.
- 7912120129 BNL-NUREO-26572
  "Feedback Control Sys for Nonlinear Simulation of
  Operational Transients in LHCBRs."
  KHATIB-RAHBARH, AGRAWAL,A.K., SPINIVABAN,E.S. Brookhaven National
  Laboratory, 79/12/11. 42pp.
- 7912130003 Forwards BAH-10122A, "Normal Operating Controls." TAYLOR, J. H. Babcock & Wilcox Co. 79/11/30. 2pp.
- ---7912130009 BAN-10122A "Normal Operating Controls." HANSON.G.E. Babcock & Hilcox Co. 79/11/30. 78pp.

- 791213014B Forwards "Analysis to Demonstrate Adequate Core Cooling." More detailed description of analyses will be provided by 79122B. BUCHHDLZ,R.H. General Electric Operating Plant Owners Group. MFN-290-79. 79/11/30. Ip.
- --7912130152 "Analysis to Demonstrate Adequate Core Cooling."

   General Electric Operating Plant Owners Group. 79/11/30.
  400pp.
- 7912130244 Notifies of programmatic changes to topical rept, before implementation of change Forwards revised Pages 19 & 21 of "0A Program for American Inst of Steel Const Nuclear Guality Certification Program."

  PESHEK
- 79121310447 Submits C-E pro-test analysis of Semiscale Test 8-07-108 performed using best-estimate approach w/modified version of small break evaluation model. Analysis data withheld tref 10CFR2. 79().

  LIEBLER, O. C-E Operating Plants Owners Group. 79/12/03. 2pp.
- 791213053B Informs of delay in responding to 790B15 ltr re dc power source failure for BHR/3 & 4. due to increasing amount of high priority THI work. Response to Items 1. 1. 1. 2. 1. 4 & 2. 1 will be submitted by 791221 & to remaining Items by 800221. ENGEL, R. €. General Electric Co. MFN-281-79. 79711/26. 1p.
- 7912130342 Forwards notice of intention to change App D of GA Program Topical Rept NU GA-1.Revision 3A. Change updates commitment from ANSI N45.2.12 to Reg Guide 1.144. COUNSIL.W.G. Northeast Utilities. GA-3561. 79/12/06. 2pp.
- 7912130563 Notifies that NRC 790815 request for add1 info re CENPS-178, "Structural Analysis of Fuel Assomblies for Combined Seismic & LOCA Loading" is under review. Due to extent of request no schedule possible until Feb 1980.

  ECHERER: A. E. C-E Power Systems. LD-79-069. 79/12/04. 2pp.
- 7912130566 Informs of availability of NEDE-25162. "Lab Examination of Garigliano Secondary Steam Generatur B Core Samples." Rept contains progriptory info Affidavit for withholding (ref 10CFR2.790).
  WATANABE, H. T. General Electric Co. MFN-292-79. 79/12/06. App.
- 7912140251 Forwards proprietary rept NEDE-24196, "Basis for BWR/6 8±8 Fuel Thermal Analysis Application." Affidavit re withholding proprietary info encl. Document withhold (ref 105FR2.790). BVCHHOLZ.R.H. General Electric Co. RHB-065-79. 79/12/10. App.
- 7912140258 Notifies of organizational change for GA dept & Site Const manager re 790702 approval of topical GA rept. UHRIG.R.E. Florida Power & Light Co. L-79-337. 79/12/07. 1p.
- 7912170023 Discusses 791120 meeting in Lynchburg, VA w/D&V to discuss pre-test calculation for LOFT LG-1 experiment. Meeting minutes attached.
  NORIAN, P.E. TMI-2 Bulletins & Orders. 79/11/21. 1p.
- ---7912170027 Summary of 791120 meeting w/B&W in Lynchburg.VA re pre-test calculation for LOFT LS-1 experiment.Meeting minutes attached. NORIAN-F.E. TMI-2 Bulletins & Orders. 79/11/20. 2pp.
- --7912170030 "Preliminary Craft2 Model of LOFT L3-1 Experiment -Presented to P Nortan & J Guttman." SAVANI.N.K. Babcock & Wilcox Co. 79/11/20. 2ipp.
- 7912170128 Requests evaluation of NUTECH test method be prepared by J Boccio, I Aspr.J Klevan & T Pinkel & submitted by 791203. Evaluation should state whether prototype satisfies in situ testing criteria PEROUSON, R. L. Plant Systems Branch. 79/11/07. 2pp.
- 7912180022 Responds to 791116 ltr re evaluation of mods of small break LOCA guidelines contained in Revision i.NEDO-24708.Mods acceptable. ROSS.D.F. THI-2 Builetins & Orders. 79/11/28. 24pp.
- 7912180024 Approves of 791031 changes to BMR-002A Revision 3 "QA Program for Nuclear Power Plants." HAA9S.W.P. Quality Assurance Branch. 79/11/21. ip.
- 7912180156 NEDO-21660
  "Experience W/BUR Fuel Through Dec 1976."
  ELKING,R.B., DAVIES,J.H., HOLTZCLAW,K.W. General Electric Co.
  77NED120. 77/07/31. 10pp.

- 7912180151 Responds to FDIA request for info re higher fuel burnups in commercial LWRs. Forwards documents listed in App A. Addl info can be found in proceedings of 790429 & 0503 ANB topical meeting in Portland.OR published by ANS.

  CARR, J. C. Division of Rules and Records. 79/12/06. 2pp.
- 7912180523 Responds to NRC 791017 telcon re small break accident guidelines in NEDO-24708. Guidelines structured so that misdiagnosis will not lead to inappropriate action for actual break location. Discusses symptom differences. STARK, S. J. General Electric Co. MC 682. 79/12/13. 3pp.
- 7912180534 Forwards ETR-1001, "Nuclear QA Program Manual," Revision B. TENZER, B.E. Ebasco Services, Inc. (subs. of Enserch Corp.), 79/12/14. 2pp.
- --7912180541 "Nuclear QA Program Hanual, "Revision 8. \* Ebasco Services, Inc. (subs. of Enserch Corp.), 79/12/14. 42pp.
- 7912180574 Forwards documentation to support 791116 meeting on power generation control complex cable connector requirements & proposal for supplementing NEOD-10466A. "Power Generation Control Complex Criteria & Safety Evaluation."

  STROUPE, E. P. General Electric Co. MFN 300-79, 79/12/13. 1p.
- 7912180587 Submits info re flow path between control vol representing core/upper plenum & control vol representing upper head in response to NRC 791120 request for addl info. REED.C. Westinghouse Operating Plants Owners Group. 79/12/10. lp.
- 7912190077 Requests add1 info re geometry of uppor head region of reactor vessel to complete evaluation of Westinghouse small break LOCA analyses presented in WCAP-9600.
  ROSS, D. F. THI-2 Bulletins & Orders. 79/11/20. 4pp.
- 7912190209 Ack receipt of 790720 request for withholding info re mobile radwaste solidification sys topical rept from public disclosure. Request granted (ref 10CFR2.790).

  BAER.R. L. Light Water Reactors Branch 2. 79/12/05. 2pp.
- 7912190414 Forwards HCAP-7800.Revision 5A. "Nuclear Fuel Div GA Program Flan." nonproprietary version.
  ANDERSON.T. N. Westinghouse Electric Corp. NS-TMA-2176. 79/12/12.
- ---7912190424 HCAP-7500 R5A
  "Nuclear Fuel Div GA Program Plan," Revision 5A,
  nonproprietary version.
  HODRE, J. S. Westinghouse Electric Corp. 79/11/20. 79pp.
- 7912190509 Forwards discussion of criteria for use in local power range monitors in average power range monitor sys of operating IMRs, per 791106 commitment. IRRUGOE, R. O. General Electric Co. MFN 304-79. 79/12/14. 9pp.
- 7912190558 Responds to NRC 791108 ltr re NUREG-0430, "Cladding Swelling & Rupture Models for LOCA Analysis." Rept appears to be thorough compilation of recent experimental data on cladding deformation.

  SCHERER, A. E. C-E Power Bystems. LD-79-070. 79/12/11. 10pp.
- 7912190568 Responds to NRC 790215 request for summary of reasons for concluding that containment NSSS & balance-of-plant equipment can accompdate effects of ATMS requiring boron injection for mitigation Specific answers encl.

  BUCHMDLZ.R.H. General Electric Co. MFN-303-79, 79/12/14, 19pp.
- 7912190573 Responds to NRC 791108 ltr re NUREQ-0630, "Cladding, Swelling & Rupture Models for LOGA Analysis." Vendor recommends evaluation of all cladding data accumulated since issuance of 10CFR0. 46. App & Industry committee is proper forum. TAYLOR, J. H. Babcock & Hilcox Co. 79/12/10. 3pp.
- 7912190597 Forwards HCAP-9639, "Rept on Small Break Accidents for Westinghouse NSBS w/Upper Head Injection," nonproprietary version.
  ANDERSON, T. H. Westinghouse Electric Corp. N8-TMA-2177, 79/12/13.
- ---7912190601 WCAP-9639

  "Rept on Small Dreak Accidents for Westinghouse NSSB w/Upper Head Injection," menproprietary version.
  DDHERTY.P. J., OREGHAM, J., ANDERSON, T. M. Westinghouse Electric Corp. 79/12/31. 63pp.

- 7912190599 Forwards response to NRC 79110B itr re NUREG-0640, "Cladding Swelling & Rupture Models for LCCA Analysis."
  Comments on model representation location of curves industry std. ECCS model, sensitivity stddies & Future programs.
  BUCHHOLZ.R.H. General Electric Co. MFN-294-79. 79/12/07. Bpp.
- 7912190839 Forwards responses to NRC 791108 ltm re NUREO-0630, "Cladding, Ewelling & Rupture Models for LOCA Analysis." Concludes that rupture blockage data supports conservatism of current vendor rupture blockage model.

  OMSLEY.O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  79/12/10. 7pp.
- 7912200338 Forwards summary of Westinghouse investigation re cracking in north region of French fabricated reactor vessels observed by French licenses.
  ANDERSON, T. M. Westinghouse Electric Corp. NS-TMA-2178, 79/12/13, 568.
- 7912200331 Responds to NRC 791030 itr re request for additinfo on NEDO-23652 concerning analysis of BWR-6 and plant mainsteam head fitting analysis documentation.
  DEB, B. J. SSSMEIN O. A. Owners! Electric Co. 79/12/12. 3pp.
- 7912200519 "B&W LOFT L3-1 Production Dec 1979."
  TAYLOR.J. H. Babcock & Wilcox Co. 79/12/31. 218pp.
- 7912200631 Affirms acceptance of 791105 revised pages re guidelines for emergency operating procedures for nominal 1400 ps; range safety injection pump plants. Copy of approved guidelines encl. W/o encl.
  ROSS.D.F. TMI-2 Bulletins & Orders. 79/12/06. 4pp.
- 7912200615 Identifies lead plants & dates for audit of implementation of guidelines for emergency operational procedures ro small break LOCAs. Auditors will represent operator licensing, reactor sys. IE & project ogt disciplines.

  ROSS.D.F. TMI-2 Bulletins & Orders. 79/12/05. 5pp.
- 7912200638 Confirms plans to audit certain GE GWR licensee emergency procedures & apprator rotraining re small break LOCAs. Identifies plants & dates for audit.

  NDS9.D.F. THI-2 Bulletins & Orders. 79/12/04. Opp.
- 7912200697 Forwards proposed 1E builtein re 0E cable separation violation.
  EISENHUT, D. G. Division of Operating Reactors. 79/11/23. 3pp.
- 7912210119 Forwards completed LLL/ARAC questionaire in response to 791128 request Recommends questionaire be sent to Federal Emergency Mgt Agency, W/o encl. CDLLING. H. E. Assistant Director for Emergency Preparedness. 79912707. 1p.
- 7912210347 Forwards EG-TOP-1, Revision 3, "QA Program for Nuclear Power Plants."
  DAVIS.4. K. Bechtel Power Corp. (subs. of Bechtel Corp.). 79/12/13. ip.
- --7912210353 DG-TOP-1
  "GA Program for Nuclear Power Plants," Revision 3.
  \* Bechtel Power Corp. (subs. of Dechtel Corp.). 79/10/31. 104pp.
- 7912260012 Forwards minutes of 791119 meeting in Mindsor, CT re status of C-E LDFT L3-1 pretest calculation.
  MORIAN.P. E. TMI-2 Bulletins & Orders. 79/11/21. ip.
- --79:2260017 Summary of 79:119 meeting w/C-E & C-E owners group in Windsor.CT re status of LOFT L3-1 pretest calculation.
  NURIAN.P.E. TMI-2 Bulletins & Orders. LONGO.J. Combustion Engineering. Inc. QASPER.J. C-E Operating Plants Owners Group.
  79/11/19. 3pp.
- 7912260020 Discusses Recommendation 2.1.7a of Denton 791030 ltr to all licensess re automatic initiation of auxiliary feedwater flow Licensess' responses revealed generic issue involving unreviewed safety question Meeting will be held.
  ROSS, D.F. TMI-2 Bulletins & Orders. 79/11/28. 2pp.
- 7912240124 Discusses 791109 meeting w/C-E & C-E owners group re draft of proposed rept on ATWS in C-E plants. Agenda encl. PARCZEWSKI.K.I. Reactor Safety Branch. 79/12/07. Sipp.
- 7912260291 Forwards "Mode to Westinghouse ECCS Evaluation Model for Two Loop Upper Plenum Injection Plants " Document withheld (raf 100FR2.790). ANDERSON, T. M. Westinghouse Electric Corp. NB-TMA-2172. 79/12/06. 363.

- 7912270109 Forwards results of bail-off rate analyses, control rod drive pump makeup capability use for plants not previously addressed & draft procedure for optimizing control rod drive pump flow to reactor.

  SHERWOOD, G. G. General Electric Co. MFN-285-79. 79/(1/27. 7pp.
- 7912270162 Forwards topical repts re radwaste solidification systim response to 791101 request.W/o enct.

  BAER.R.L. Light Water Reactors Dranch 2. 79/12/11. 2pp.
- 7912270200 Forwards rept. "Hestinghouse Prediction for LOFT Nuclear Experiment 13-1." REED.C. Commonwealth Edison Co. QR-24. 79/12/15. 1p.
- --7912270207 "Westinghouse Prediction for LOFT Nuclear Experiment L3-1." \* Westinghouse Electric Corp. 79/12/15. 94pp.
- 7912270292 Forwards protest predictions for two small break tests to be performed in two-loop test apparatus. Provides basis to be used to evaluate validity of assumptions applied in preparing operator guidelines for small break accidents. BUCHHOLZ, R. H. General Electric Co. RHB-071-79. 79/12/18. 15pp.
- 7912270546 Discusses fuel pellet/clad interaction analyses, in response to NRC request for topical rept. Conclusions of previous 761210 study remain valid, obviating new affort at present time.

  ANDERSON, T. N. Westinghouse Electric Corp. NS-TMA-2171. 79/12/04.
- 7912270601 Responds to NRC 790902.13 & 1030 ltrs re completion date for analyses of transients & accidents Westinghouse owners group will submit analysis by 800331, per NUREG-0578.

  REED.C. Hestinghouse Operating Plants Owners Group. 79/12/20. ip.
- 7912280063 Transmits memo forwarding DNL repts on iodine monitors & Sandia Labs rept on accident descriptions. W/o encl. COLLINS. H. E. Assistant Director for Emergency Preparedness. 79/12/04. 1p.
- 7912280517 Forwards QAL-TR-106. "QA Program for Nuclear Power Plants." Revision 2. Revisions reflect organizational changes Additional changes for clarification & update are marked in margins. BARKER. N. R. Gilbert/Commenwealth Cos. 79/12/19. ip.
- --7912280528 GAI-TR-106 "GA Frogram for Nuclear Power Plants," Revision 2. BARKER, N. R. Gilbert/Commonwealth Cos. 77/11/30. 115pp.
- 7912280547 Forwards proprietary errata & addends to App D of NEDE-24011-P-A. "Generic Reload Fuel Application." Occument withheld (ref 10CFR2.790)
  ENOEL,R.E. General Electric Co., Nuclear Energy Products Div MC-682, 79/12/14, 2pp.
- 7912280569 Forwards proprietary updates to notes on 791630 presentation to electric util executives.LP disc insp rept & discussion of method for softing priorities of units in response to 791217 requests info withheld (r
- 7912310014 Notifies of completion of review of BAN-1555, "Evaluation of Atypical Weldment." Requests re-issuance of rept according to provisions of NRC topical rept program RUBENSTEIN.L.B. Light Water Reactors Branch 4. 79/12/12. 3pp.
- ---7912310024 Topical rept evaluation of GAW-1556, "Evaluation of Atypical Weldment." Rept acceptable.

  # Engineering Branch. 79/12/12. 5pp.
- 7912310119 Forwards evaluation re areas of disagreement in WCAP-V157. Includes method of calculating qualified life of resistance temp detectors & qualification of remote ballows sensing pressure transmitters. Encl withheld (ref 100FR2.790). BTOLZ, J. F. Light Water Reactors Branch 1. 79/11/16 1p.
- 7912310108 Initiates new generic task to develop NRC position establishing water shields that protect sensitive electrical equipment from water damage. Forwards NRC draft position on water shields & portion of Denton memo to Bradford, FERGUSON, R. L. Plant Systems Branch. 79/12/12. 6pp.

- 7912310323 Notification of 791212 meeting w/Sandia Lab in Bethesda,MD to review procedures for evaluating fault trees using set equation transformation sys.

  ANGELO, J. Light Hater Reactors Branch 1. 79/12/05. 2pp.
- 7912310389 BVTR-1-0
  Revised pages for "QA Program Description."
  # Black & Veatch. 79/12/04. 150pp.

#### MASTE MOT NUCLEAR HASTE MANAGEMENT

- 7912030026 Forwards water quality analytical data collected from Jul-Oct 1979. MAIXNER,R.D. Cotter Corp. 14538. 79/10/04. 11pp.
- 7912050574 Notifies that Civil Sys.Inc 790910 drawing. "Bokum Resources Corp. Marquez U Mill Tailings Disposal Area ~ Conceptual Design Solid & Liquid Waste Disposal." has been forwarded in response to NRC 790911 request. TDPP.A.A. New Mexico. State of. 79/10/11. Ip.
- --7912030580 Forwards requisite number of documents re Bokum Resources Corp application. TOPP.A.A. New Mexico, State of, 79/10/12. 1p.
- --7912050585 Forwards "Designers Memorandum 8, Design Concepts for Solid Maste Disposal Trench 1 for Bokum Resources Corp. Bante Fe. NM. " RL Volpe 790926 ltr to Bokum Resources Corp encl. W/o TOPP.A.A. New Mexico, State of, 79/10/12, 1s.
- --7912050989 "Designers Memorandum 4. General Design Concepts for Solid Waste Disposal," prepared for Bokum Resources Corp. Banta Fe. NM. \* Civil Systems: Inc. 14600. 79/09/24. 12pp.
- --7912050601 "Designers Memorandum 5.Revegetation Program: Morque: Mill," prepared for Bokum Resources Corp. Sante Fe. NM. \* Science Applications. Inc. 14600. 79/09/24, 14pp.
- --7912050604 "Designers Memorandum 6.Geomorphology Considerations: Marquez Mill: "prepared for Bokum Resources Corp. Sante Fe. NM. \* Science Applications, Inc. 14600. 79/09/24. Spp.
- --7912050607 "Designers Memorandum 7.Analysis of Capillary Rise Above Buried Tailings: Marques Mill," prepared for Bokum Resources Corp. Santa Fe. NM. Beience Applications. Inc. 14600. 79/09/24. 10pp.
- ---7912050610 "Designers Hemorandum B.Design Concepts for Bolid Waste Disposal Trench i." prepared for Bolum Resources Corp. Santa Fe.NM. Civil Systems. Inc. 79/10/10. 21pp.
- --7912050613 "Designers Memorandum 9.Design Concepts for Completion of Stage I Dam." prepared for Bokum Resources Corp. Santa Fe. NM. Civil Systems, Inc. 14600. 79/10/12. 9pp.
- 7912060368 Submits outline for soil sampling program review. EADIE.0.0. Uranium Recovery Licensing Branch. 79/10/25. 2pp.
- 7912120873 Notification of 791211 meeting w/AZ Atomic Energy Commission, NM Environ Improvement Div.EPA Regions 6.8 & 9 & Navago Nation in Albuguerque.NM to discuss ed programs for public re U development on Navago land.

  BCARANO.R.A. Uranium Recovery Licensing Branch. 79/12/03. 1p.
- 7912140102 Forwards "Radiological Duse Assessment of Church Rock U Hill Tailings Dam Failure," EADIE.0. Uranium Recovery Licensing Branch. 79/11/26. 2pp.
- -7912140121 "Radiological Dose Assessment of Church Rock U Mill Tailings Dam Failure."
  GNUGNOLI, G. N., EADIE, G. G., MILLER, H. J.
  Licensing Branch. 79/10/31. 28pp. Uranium Recovery
- 7912140536 "Oround Water Discharge Plan Using Below Grade Tailings Disposal:Marquez Hill, NM." Applications. Inc. 79/10/22, pp.
  - avan mili tailings status due reement states, d be verified, ng Branch. 79/11/16. Spp.

- 7912170047 Responds to Technical Assistance Request 5331 re Union Carbide U tailings retention at Uravan project. Insp has revealed alarming signs of retention dam instability. Unscheduled safety review not possible. KERR, G. W. Assistant Director for Engineering. 79/11/21. 2pp.
- 7912170100 Responds to 791025 request for draft EIB re proposed Mount Taylor project U mill tailings impoundment. No EIB will be prepared since NRC does not have direct licensing authority over U mill tailings. over U mill tailings. TRAGER, S. A. Uranium Recovery Licensing Branch. 79/11/21. 1p.
- 7912170109 Notifies that request for hansen project environ rept should have been directed to Cyprus Mines Corp. NRC will forward request.

  \*\*\*HILLER: H. J.\*\*\* Uranium Recovery Licensing Branch. 79/11/23. ip.
- 791217018B Forwards request for addl info to perform radiological assessments of ore-upgrading operations & tailings disposal.
  MILLER.H.J. Uranium Recovery Licensing Branch. 79/10/16. 7pp.
- 7912170280 Expresses appreciation for participation on Hansen project tour. Forwards aerial photograph of mill & tailings area & app to Wahler rept on Hansen project tailings impoundment & raffinate pond. W/o encl.

  THOMPSON.M.A. Cyprus Mines Corp. 14802. 79/11/09. 1p.
- 7912180050 Forwards background info for use in preparing for 790403 meeting re technical assistance to State of KB re Lyons KB salt mine waste facility.

  KERR, 9. Assistant Director for State Agreements Programs, 79/03/23. 2pp.
- 7912180053 Forwards most recent info re state of KB request for assistance for Rickano Corp application for low level waste facility at Lyon KB.
  KERR, O. W. Assistant Director for State Agreements Programs, 79/10/11. 1p.
- ---7912180060 Forwards State of KS Bureau of Radiation Control 790905 ltr to Rickeno Corp raquesting addl info re proposal to operate low level waste facility at Lyons, KS Requests comment. BDCHERT, H. R. Kansas, State of
- --7912180067 Statement of cooperation between State of KB. Agresment State, Mine Bafety & Health Administration & NRC. ALLEN.G. W., GRAY.M.K., STOLTENBERG.G. Kansas, State of. 79/09/25.
- 7912180072 Forwards info re proposed salt mine storage application in Lyons.KB in view of announced closing of nuclear waste burial sites in Beatty.NV & Hanford.WA. Forwards Rickeno Corp. 791113 response to State of KB 790905 questions. BEIERLE.F. P. Rickano Corp., 79/10/27. 240pp.
- 7912190038 Advises that request for denial of byproduct matl license for Hansen project has been forwarded to state of CO wasts control offices.

  8CARAND.R.A. Uranium Recovery Licensing Branch. 79/11/23. 2pp.
- 7912190070 Forwards response to request for info re licensing authority & requirements for proposed Hansen project.Parmits applicable to Cyprus Mines Corp encl. SCARANG.R.A. Uranium Recovery Licensing Branch. 79/11/23. 2pp.
- 7912190184 Bubmits dose estimates from ingestion of Church Rock livestock. EADIE, Q. Uranium Recovery Licensing Branch. 79/12/02. 3pp.
- --7912190225 Submits preliminary radionuclide results re tissus samples from Church Rock livestock. DOUGLAS.R.L. Environmental Protection Agency. 79/10/12. 10pp.
- 7912190259 Forwards comments re "Draft EIS for Mgt of Commercially Generated Radwastes, Apr 1979." MARTIN.J.B. Division of Waste Management. DDE/EIS-0046-D. 79/10/25. App.
- ---7912190266 "Comments on Draft EIS for Mgt of Commercially Generated Radwastes. Apr 1979."

  \* Commission. DOE/EIS-0046-D. 79/10/01. 93pp.
- 7912190285 "Designer Memo 12: General Dasign of Evaporation Ponds for Liquid Waste Disposal," prepared for Bokum Resources Corp. \* Civil Bystems, Inc. 79/10/19. 250pp.

- 7912190288 Summary of 791026 discussion w/Homestake re proposed assessment studies for delineating geologic & hydrologic conditions at Site B of below grade disposal area. ROBINETIE.M.S. Williams-Robinetta & Associates, Inc. 14803. 79/11/02. 4pp.
- 79:2:90350 Forwards revised radioactive license application re Designer Memo 12 & Boium Resources Corp "Ground Water Discharge Plan Using Below Grade Tailings Disposal-Marquer, 184. " W/o encl. TOPP, A. A. New Mexico, State of. 14366. 79/10/23. ip.
- 7912190355 Summary of NRC 790911 site visit re proposed U mill tailings disposed scheme, as alternative to original design.

  KRUG, M. E. Uranium Recovery Licensing Branch. 79/10/16. 3pp.
- ---79(2)70359 "Conceptual Design Rept.Below Orace Tailings Disposal at Marquex U Hill Bits." Oversize drawing encl. s Civil Bystems, Inc. 79/10/16. 7pp.
- P912190785 Discusses NRC 791120 telcon w/Botum Resources Corp re radiological questions on revised "Groundwater Discharge Plan Using Below-Grade Tailings Disposal" for Botum Narquez Hill. Semmary of questions & answers and. KRUG.M.E. Uranium Recovery Licensing Branch, 79/12/04. Spp.
- 7912200446 Forwards William Matotan & Associates, Inc drawing, "Mill Maul Road & Tailings Area: Exclusion Area from Juan, Tafoya. Orant, McKinley, Sandoval & Valencia Counties," re Bokum Resources Corp application.
  TOPP, A. A. New Mexico, State of. 14882. 79/11/28. 1p.
- 7912200580 Confirms 791026 telcon re NRC & state agency 791105 tour of Hansen Project site. THOMPSON.M.A. Cyprus Mines Corp. 14801. 79/10/29. 2pp.
- 7918200610 Forwards 791106 FR notice of withdrawal of NRC intent to prepare draft EIS draft low & high level waste mgt programs, draft OEIS re U milling & Interagency Review Group rept to President re nuclear waste mgt in response to 791030 ltr. ECARANG.R.A. Uranium Recovery Licensing Branch. 79/11/21. 2pp.
- 7912210091 Request by State of CO Dept of Health for Acres American rept to Union Carbide including criteria, engineering design spaces, stabilization work & criteria & design estimates for Phase II stabilization work.

  HAKLE.A.J. Colorado, State of. 79/11/28. 2pp.
- 7912270126 Forwards list of outstanding geotechnical engineering safety issues re revised design of Church Rock tailings dam which failed in Jul 1979.

  JACKSON.R.E. Division of Sits Safety & Environmental Analysis.
  79712710. 680.
- 7912860100 Forwards mill water belence calculations, Nati Wildlife Federation Appeal & Forest Byc responsive statement re approval of Homestake operating plan. FES is still inadequate & approval of operating plan is not within law. BINCHUM. 8. Homestake Mining. Co. 14776. 79/10/19. 40pp.
- 7912280133 Forwards compilation of documents re facility U mill tailings dem failure. EADIE. 9.8. Uranium Recovery Licensing Branch. 79/12/07, 2pp.
- -- 791R2G0139 Summarizes facility environ impact assessment efforts. EADIE.G.Q. Uranium Recovery Licensing Branch. 79/12/07. 5pp.
- -- 7912280148 Advises of results of review efforts to date re facility tailings impoundment failure.

  90881CK, L. V. Office of the Executive Director for Operations.
  79/08/23. 9pp.
- ---7912280168 Forwards procedures for sampling Rio Puerco stream bed. Sampling to be completed 791004. MCEFF.T.A. New Mexico, State of. 79/09/24. Spp.
- 7912280167 Submits outline providing general guidance re facility suil assoling program review.
  EADIE.6.9. Uranium Recovery Licensing Branch. 79/12/05. 2pp.

- --7912280171 Recommends sempling locations for monitoring program re effects on drinking water of facility spill & Rio Puerco discharges. STUMPH, T.L. Environmental Protection Agency. 79/08/15. 10pp.
- --7912280177 Forwards list of constituents possibly present at facility tailings spill, for use in monitoring program.

  BTUMPH, T. L. Environmental Protection Agency. 79/10/18. 3pp.
- --7912280182 Discusses testing of livestock specimens in area of facility First results espected early in Oct 1979.
  HOFFMAN.R. New Mexico. Bhate of. 79/09/13. 1p.
- --7912280192 Submits estimates of livestock radiation dose ingestion.
  Recommends refraining from eating possibly contaminated
  animals.
  EADIE, G. Uranium Recovery Licensing Branch. 79/12/02. 3pp.
- --7912280202 Forwards printout showing preliminary radionuclide results obtained to date on tissue samples collected by Indian Health Byo from livestock associated w/facility tailings dan release. Addl results pending.

  DOUGLAS.R.L. Environmental Protection Agency. 79/10/12. 1ipp.
- --7912280210 "Radiological Dose Assessment of Facility V Mill Tailings Dam Failure." QNUCNOC.I.O.N., EADIE.O.O., MILLER.H.J. Uranium Recovery Licensing Branch. 79/10/31. 28pp.
- 7912280684 Forwards "Preoperational Environ Data Collection Program: Aurora Joint Venture Project," Jul 1979. DOE comments encl. HCGRATH, E. J. McGrath, E. J. 14361. 79/09/25. 4pp.
- --7912280687 "Preoperational Environ Data Collection Programs: Aurora Joint Venture Project." \* Placer Amex, Inc. 79/07/31, 42pp.
- 7912310509 Bummary of 791016 meeting w/Util Waste Mgt Group in Bilver Bpring.MD re comments on draft of NRC high-level waste mgt regulations. MULERO, J.C. High Level Waste Licensing Management Branch. 79/11/09. Spp.

## XPORTLIC EXPORT AND IMPORT LICENSES

- 7912030023 Response to Commission 791019 order requesting views on nuclear reactor export to Philippines Requests hearing on issues presented in 790419 petition to intervene Supporting documentation encl.

  ABHER, T.R. Center for Development Policy. BDGIN, M.B. Hovement For a Free Philippines. ASHER, T.R. Asher, T.R., PC. 79/11/19. 67pp.
- 7912030041 Application by Spex Industries, Inc for license to export 2.96 g U-235, contained in 50 g U oxide, to Japan. End use statement encl.
  COYNE, M. J. SPEX Industries, Inc. 01004, 79/10/01. 3pp.
- 7912030046 Amend 4 to Transnuclear Inc license, increasing quantity of matl authorized for import to 6.742.6 kg U.enriched to 1.01% U-235.
  MOORE R. N. Assistant Director for Export/Import & International Baseguards. 79/11/16. ipp.
- 7912030049 Application by Sigma Chemical Co for license to export 5 kg of deuterium oxide liquid.

  BTERN.W.C. Sigma Chemical Co. (subs. of Sigma Aldrich Corp.). B-29.
  79/11/08. ipp.
- 7912030066 Comments on safety & environ factors re proposed Westinghouse application. Opposes loan to Filipino govt to finance nuclear plant NRC obliged to study safety health & environ impacts of facility.
  COLLINGS.H., CONAP.C., JEFFERSON,K. Affiliation Unknown. 79/11/19.6pp.
- 7912030075 Submits comments on procedural & surisdictional issued involved in Hestinghouse application, NRC has no extraterritorial jurisdiction. Health safety & environ aspects are responsibility of recipient country.

  DEPOIX, V. P. Atomic Industrial Forum. 79/11/16. 5pp.

- 7912030897 Executive Branch position re Westinghouse application for license to export 1/130 micrograms of CF-252 to Spain. License should be granted. NDSENZD.L.V. State.Dept of. Bureau of Oceans & Internat1. Environ. & Scipntific Affairs. 79/11/13. 2pp
- 791203010B License for Monsanto Research Corp to export 8.500 g Pu-238 to Australia Austria Belgium Canada Denmark Finland France, West Germany Ireland Italy Japan Luxembourg Norway. The Netherlands Sweden Switzerland & United Kingdom. MOORE, R.N. Assistant Director for Export/Import & International Safeguards. 79/11/13. 2pp.
- 7912030110 Submits application for amend to Westinghouse license, to include export of two addl moveable incore detectors to Belgium. KEENAN.R.P. Westinghouse Electric Corp., Nuclear Energy Systems. ICS-9374. 79/10/26. 1p.
- 7912030214 Executive Branch position re Edlow Intl Co application for license to export 6.5 Cf-252 as cermet wire to United Kingdom. License should be granted.
  NOSENZO, L. V. State, Dept. of. 79/11/19. 2pp.
- 7912030215 Application by GE for license to export 12,306 kg U dioxide powder to Japan. WILSON.B.D. General Electric Co. ODW 79232. 79/11/01. 1p.
- 7712030216 Requests Executive Branch position re Edlow Intl Co application for license amend increasing amount for export to Japan to 60,000 Ci of tritium gas. PETERSUM.M.R. Assistant Director for Export/Import & International Safeguards. 79/11/23. 1p.
- --791203021B Requests amend to License X8-1005 increasing amount for export to Japan to 60,000 Ci tritium gas.
  HARMON, D.W. Edlow International Co. 79/11/13. 2pp.
- 7912030243 Forwards application by DDE for literage to export 5 kg U metal.enriched to 45% U-235, & 20 kg U metal.enriched to 19.75% U-235, to The Netherlands.
  MCDDNOUGH.H.D. Energy, Dept. of. 79/11/02. ip.
- ---7712030244 Application by DDE for license to export 5 kg V metal, enriched to 45% U-235, & 20 kg V metal, enriched to 19.75% U-235, to The Netherlands.

  \* Energy Dept. of. 79711/06. 2pp.
- 7912030261 License for Mitsui & Co.Inc to export 73.000 lb of Zircaloy-2 tube shells to Japan. SHEALJ.R Assistant Director for Export/Import & International Safeguards. 79/11/23. 1p.
- 7912040003 Application by Teledyne Wah Chang Albany for license to export Zircalog-2 tube shells to West Germany.
  WATTENBARGER.S. Teledyne Wah Chang Albany. C 1382. 79/11/14. 1p.
- 7912040037 Requests amend to export licenso naming Bristol Agrospace as intermediate consignee.
  ENYDER, B. KB1 Tobe Div. 79/11/05. 1g.
- 7912040040 License for Hestinghouse to export 1130 micrograms Cf-252, contained in two primary sources, to Spain.
  PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. MNC-NRC-36, 79/11/23. 2pp.
- 7912040041 Amend 1 to Westinghouse license extending expiration date to B01201.
  PETERSON, M. R. Assistant Director for Export/Import & International Bafeguards. ARN-ZE-10149. 79/11/23. Jp.
- 7912040042 Amend 2 to M. Industries, Inc license, increasing export of U metal by 18,144 kg & extending expiration date to 800101. PETERSON, M. R. Assistant Director for Export/Import & International Safeguards. 79/11/23. 1p.
- 79:2040047 License for Signa Chemical Co to export 5 kg deuterium oxide.contained in compounds.to India PETERSON.M.R. Assistant Director for Export/Import & International Safeguards. 0-25. 79/11/23. 2pp.
- 7912040055 License for Ediow Inti Co. as agent for Radiochomical Centre Limited, to export 6.5 mg Cf-282 to United Kingdom. PETERSON.M.R. Assistant Director for Export/Import & International Safaguards, RCC-CA. 79/11/23. 2pp.

- 7912040061 License for Isotec Inc to export 1 kg deuterium.containsd in 5 kg deuterium oxide. & 1.8 kg deuterium as gas to Austria. Australia. Belgium. Canada. Denmark. Finland. Franco. Italy. Japan. Wost Germany. Notherlands. Spain. Sweden & United Kingdom. PETERSON.M.R. Assistant Director for Export/Import & International Safeguards. 79/11/23. 2pp.
- 7912050077 Response in opposition to Ctr for Development Policy.
  Philippine Movement for Environ Protection et al 791119
  request that Commission waive rules on export proceedings.
  Relieher rept available to public.Cortificate of Svc oncl.
  BECKER, J. M. Office of the Executive Legal Director. 79/11/29. Spp.
- 7912050097 Comments in response to Commission 791019 order requesting views on Commission jurisdiction to consider nuclear reactor effects in foreign country. Proceeding affects foreign policy which NRC connot formulate.

  SCAROLA: J. A. Ebasco Services, Inc. (subs. of Enserch Corp. ).
  79/11/19. 170s.
- 7912050206 Forwards revised request for hearing on seven issues outlined in 790419 request to intervene.
  ASHER, T. R. Asher, T. R., PC. 79/11/21. ip.
- --7912050211 Response to NRC 791019 request for views on Philippine export proceedings. Hearing an seven items outlined in 790419 petition to intervene requested.
  ABHER.T.R. Contor for Development Policy. ABHER.T.R. Asher.T.R., PC. 79/11/21. 69pp.
- 7912090219 Forwards notes & errata sheet to views on procedural & jurisdictional issues re Westinghouse application to export nuclear reactor to Philippines.
  PERLAS, J. N. Affiliation Unknown. 79/11/21. 8pp.
- 7912050328 Affidavit of C Planas on 791119 re Westinghouse application to export nuclear reactor to Philippines Application should be denied due to health & safety risks & high cost of maint. PLANAS, C. Affiliation Unknown. 79/11/19. 4pp.
- 7912050336 Forwards petition stating views of 16 individuals & 14 public interest groups re Westinghouse application to export nuclear reactor to Philippines in response to NRC 791019 request for comments.

  ABHER, T. R. Asher, T. R., PC. 79/11/19. 1p.
- --7912050343 Urgas NRC to undertake examination of health, safety & environ impacts of proposed Philippines reactor. MATTISON.L. Center for Development Policy. POLLACK.R. Critical Mass Energy Project. ALVAREZ.R. Environmental Policy Center. 79/11/13. 2pp.
- 7912050396 Statement of views by Natl Power Corp agency of Govt of Philippines, in response to Commission 791019 order, Atomic Energy & Nuclear Nonproliferation Acts were not promulgated to dictate policies on foreign nations.

  # Philippines. 79/11/15. Bpp.
- 7712030546 Application by NGRCA Machinery Co for license to export 2 shear valves to India. STERN.R.N. NORGA Machinery Co. 79/11/06. 1p.
- 7912060174 License for GE to export miscellaneous components, except assembled pressure vessols, primary coolant pumps, Puel charging & discharging machines & control rods, to Italy, PETERSON, N.R. Assistant Director for Export/Import & International Safeguards. BDW-7923B. 79/11/20. 1p.
- 791206017B Submits application to amend license, adding addl 10.000 Ci tritium for export to Japan. HARMON, D. W. Edlow International Co. 79/11/13. 2pp.
- 7912060183 Application by Pathfinder Mines Corp for license to export 65,000 kg of yellowcake to Mexico.

  \* Pathfinder Mines Corp. 79/11/14. 1p.
- 7912060187 License for Sigma Chamical Co to export 5 kg deuterium axide.contained in compounds.to New Zealand. PETERSON.H.R. Assistant Director for Export/Import & International Safaguards. D-26. 79/11/20. 2pp.

- 7912060193 License for Paul-Munroe Hydraulics, Inc to export 12 hydraulic snubbers to France. PETERSON, M. R. Assistant Director for Export/Import & International Safeguards. 79/11/20. 1p.
- 79120&0199 Licanse for Paul-Munroe Hydraulics, Inc to export 12 hydraulic anubbers to France.
  PETERSON.H.R. Assistant Director for Export/Emport & International Bafeguards. 79/11/20. 1p.
- 7912050205 License for Sigma Chemical Co to export 5 kg deuterium office contained in compounds, to Canada.
  PETERSON.H.R. Assistant Director for Export/Import & International Bafeguards. D-27. 79/11/20. 2pp.
- --7912050327 Application by Paul-Munroe Hydraulics, Inc for license to export 20 hydraulic steel supports to West Geroang.
  81EGFRIED, J. R. Paul Munroe Hydraulics, Inc. 87608N, 79/11/12.
- 7912070181 Submits partial response to FOIA request for documents re shipment of spent nuclear fuel from foreign sources to Savannah River plant.Forwards documents listed in app. CARR.J.C. Division of Rules and Records. 79/11/23. 2pp.
- --79120702i1 Discusses request for approval of route for imports of irradiated MTR fuel Approves proposed route on interim basis Requests analysis of alternatives be submitted to NRC by 790891. Proposal subj to 10CFR2. 790.

  HCCDRRLE.G.H. Commission. 79/07/23. 2pp.
- 7912070235 License for GA Co to export 390 g U-235, contained in 1,970 g U & 5,1 g U-235, contained in 5.7 g U to United Kingdom.
  PETERSNI, H. R. Assistant Director for Export/Import & International Bafeguards. TFI-1081. 79/11/20. 2pp.
- 7912100216 Application by Edlow Intl Co for license to export 86 g U as natural U powder & slugs to United Kingdom.

  HARMON.D.W. Edlow International Co. BN NAT U. 79/11/16. ip.
- 7912100474 Response in opposition to Ctr for Development Policy, Philippine Movement for Environ Protection Movement for Free Philippines & NJ Perlas 791119 pleading Waiver of export rules will create uncertainty among importing countries, BETTAUER, R. J. State, Dept. of. 79/11/29. 4pp.
- 7912|10|56 License for Sigma Chemical Co to export 5 kg deutorium oxide contained in compounds to Canada.
  PETERSON.M.R. Assistant Director for Export/Import & International Bafaguards. 79/i1/30. 2pp.
- 7912110160 License for Sigma Chemical Co to export 5 kg deuterium outse contained in compounds to Brazil. PETERSON.H.R. Assistant Director for Export/Import & International Safeguards. 79/11/30. 2pp.
- 7912110163 License for Mitsui & Co. Inc to export 250 1b of Zircaloy-2 tube shells co-extruded w/zirconium sponge liner to Bweden. PETEREUN-H.R. Assistant Director for Export/Import & International Bafeguards. 79/11/30. ip.
- 7912110166 Application by Bigma Chemical Co for license to export compounds containing 8 kg deutorium to Norway.

  BTERN.H.C. Sigma Chemical Co. (subs. of Sigma Aldrich Corp.). D-30. 79/11/20. ip.
- 7912110173 License for Thiotol Corp to export 250 g douterium oxide as liquid to India. PETERSON.H.R. Assistant Director for Export/Import & International Bafeguards. 79/11/23. 2pp.
- 7912110280 Forwards application by DOE for license to export 5 kg U metal.enriched to 45% U-235. & 20 kg U metal.enriched to 19.73% U-235. to The Netherlands.
  MCDONOUGH.H.D. Energy.Dept.of. 79/10/31. lp.
- --7912110284 Application by DDE for license to export 5 kg U metal enriched to 45% U-235, & 20 kg U metal, enriched to 19.75% U-235, to The Netherlands.

   Emergy, Dept. of. 79/10/31, 2pp.

- 7912110295 Forwards application by Mitsubishi Intl Corp for license to export 310 kg U-235 contained in 9.824 kg U.tu Japan.
  MATANABE.N. Mitsubishi International Corp. (subs. of Mitsubishi Corp.). HSA-5480-01. 79/10/29. 3pp.
- -7912110297 Application by Mitsubishi Intl Corp for license to export 310 kg U-235, contained in 9.824 kg U.to Japan. End use statement encl. FUKAZAKA, Y. Mitsubishi International Corp. (subs. of Mitsubishi Corp.). HSA-5480-01. 79/10/29. 2pp.
- 7912110383 Brief in lieu of pleading re nuclear reactor export to Philippines. Questions ability of less developed nations to deal w/nuclear technology issues. Supporting documentation encl.

  ZARSKY, L. Affiliation Unknown. 79/11/19. 132pp.
- 7912110455 forwards application for export license for minor nuclear export. Ltr of assurance required.
  PETERBON.M.R. Assistant Director for Export/Import & International Safeguards. 79/12/04. 1p.
- 7912110523 Forwards application for export license for minor nuclear export.Ltr of assurance required.
  PETERSON.M.R. Assistant Director for Export/Import & International Safeguards. 79/12/04. 1p.
- 7912110528 Forwards application for export license for minor nuclear export.Ltr of assurance required.
  PETERSON.M.R. Assistant Director for Export/Import & International Safeguards. 79/12/04. ip.
- 7912110547 License for Exxon Nuclear Co. Inc to export Zircolog tubing & end caps. Income! plenum springs, alumina insulator discs, tie plates & skeleton sets to West Germany.
  #EIERSON.M.R. Assistant Director for Export/Import & International Safeguards. 79/11/27. | p.
- 7712120143 Amend 1 to GE export license extending expiration date to 821201 & removing Condition 1.
  PETERSON.H.R. Assistant Director for Export/Import & International Safeguards. 79/12/03. 1p.
- 7912120145 Amend 1 to Hoke, Inc export license, increasing value of equipment to \$205,601.25.
  PETERSON, M. R. Assistant Director for Export/Import & International Safeguards. 79/12/03. 1p.
- 7912120203 Requests Executive Branch position re Paul-Munroe Hydraulics, Inc. application for license to export 6 snubbers to Republic of South Africa. MODRE, R. R. Assistant Director for Export/Import & International Safeguards. 79/11/13. 1p.
- ---7912120205 Forwards application by Paul-Munroe Hydraulics, Inc for license to export & snubbers to Republic of South Africa. SIEGFRIED.J. Paul Munroe Hydraulics, Inc. 79/10/30. 1p.
- 79:2120407 Amend 1 to GE export license extending expiration date to 810201.
  PETERSON H. R. Assistant Director for Export/Import & International Safeguards. 79/12/03. 1p.
- 7912120456 Requests Executive Branch position re Norca Machinery Co application for license to export two pieces of shear valve to India. MOCRE.B.N. Assistant Director for Export/Emport & International Safeguards. SC-8252. 79/11/19. 1p.
- --7712120462 Application by Norra Hachinery Co for license to export two shear valves to India.
  STERN.R.N. WORCA Machinery Co. SC-8252. 79/11/06. 1p.
- 7912120460 Requests Executive Branch position re GE application for license to export 12,304 kg U,enriched to 3.1% U-238, to Japan.

  MODRE,R.N. Office of International Programs. 79/11/13. ip.
- --7912120476 Application by GE for license to export 12,306 kg U. enriched to 3 1% U-235, to Japan.

  \* General Electric Co. BBH-79232. 79/11/01. 1p.
- 7912120537 License for Westinghouse to import 1305 kg U.enriched to max 2% U-235, from Sweden. PETERSON.H.R. Assistant Director for Export/Import & International Bafeguards. 79/12/05. 2pp.

- 7912120539 License for Westinghouse to export four compensated innization chambres to France. PETERBON.M.R. Assistant Director for Export/Import & International Safeguards. 79/12/05. ip.
- 79:2120542 License for Paul-Monroe Hydraulics, Inc to export 20 hydraulic snubbers for steam generator & primary pump seismic & accident restraint to West Germany. PETERSON.H.R. Assistant Director for Export/Import & International Bafeguards. 79/12/05. ip.
- 7912120547 License for Teledyne Wah Chang Albany to export 51,000 ib irrealoy, contained in two tube shells, to West Germany. PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 79/12/05. ip.
- 7912120551 Submits application to assend license to extend expiration date to 830101.
  WILEBUR B.D. General Electric Co., Nuclear Energy Products Div.
  BDW-79243. 79/11/16. 19.
- 7912120569 Amend 1 to Edlow Intl Co export license, authorizing re-export of matl to Japan. PETERBUN.M.R. Assistant Director for Export/Import & International Safeguards. 79/12/03. 1p.
- 7912120572 Forwards application by Marubent America Corp for license to export 20 g Pu & 6 g Pu sulfate tetrahydrate to Japan. OKUDA:H. Harubent America Corp. (subs. of Marubent Corp.). HA1-HO-5976. 79/11/01. 1p.
- --7912120576 Application by Harubeni America Corp for license to export 20 g Fu & 6 g Pu sulfate tetrahydrate to Japan. MANIYA.S. Marubani America Corp. (subs. of Marubani Corp.). ZH-0119. 79/11/06. 2pp.
- 7912130040 Application by Kawecki Berylco Industries. Inc for license to export io4 ft of Zircaloy II seamless tubing to West Germany.
  BNYDER, B. KEI Tube Div. 79375. 79/11/21. 2pp.
- 7912130087 Forwards application for license amend for minor nuclear export. Ltr of assurance required.

  MOORE,R.N. Office of International Programs. 79/11/13. ip.
- --7912130102 Requests license amend to include two addl moveable incore detectors for export to Belgium. KEENAN,R.P. Westinghouse Electric Corp. 79/10/24. 1p.
- 7912130109 Application by Dresser Industries, Inc. for license to export 2 Ci Cs-137.0,0002 mCi radium, 18 Ci Am-241-Be & 375 mCi Am-241-Be to Bovist Union.
  HILSON, D. J. Dresser Industries, Inc. 8-154/1-007, 79/11/16, 1p.
- 7912130123 Requests Executive Branch position of Manubeni America Corpapplication for license to export NBS stds containing 22 g Pu to Japan.

  NDMRR, R.N. Assistant Director for Export/Import & International Bafeguards. 79/11/13. ip.
- --7912130129 Application by Marubeni America Corp for license to export NBB stds containing 22 g to Japan. MAHIYA,B. Marubeni America Corp. (subs. of Marubeni Corp.). ZH-0119, 79/11/04. 3pp.
- 7912130124 License for Tube Div of Kawacki Berylco Industries, Inc to export 164 ft Zircaloy II seamless tubing to West Germany. PETERBON.M.R. Assistant Director for Export/Import & International Safeguards. 79/11/27. 1p.
- 7912130139 Application by Sigma Chemical Co for license to export 5 kg deuterium oride liquid to Australia.
  STERN.M.C. Sigma Chemical Co. (subs. of Sigma Aldrich Corp.). D-31.
  79/11/20. 1p.
- 7912140004 Submits application for amend to export license, increasing value.
  BRUSH, P. N. Hoke, Inc. 79/11/19. ip.
- 79:2140010 Requests Executive Branch position re Westinghouse application for license to export proportional counter to Philippines.
  PETERSON.M.R. Assistant Director for Export/Import & International Safeguards. 79/12/03. ip.

- 7912140013 Requests Executive Branch position re Edlow Intl Co application for license to export hexafluoride to United Kingdom. PETERSON M.R. Assistant Director for Export/Import & International Bafoguards. 79/12/03. ip.
- 7912140017 Requests Executive Branch position re Boeing Co application for Amend 5 to export license, adding airlines in Thailand. Philippines & Indonesia, to list of ultimate consignees to receive seergency aircraft counterweights. PETERBORN M. Assistant Director for Export/Import & International Bafeguards. 79/12/03. 1p.
- 7912140061 Requests Executive Branch position re DRO Intl.Inc application for license to export SRM to Boviet Union. PETERSON.M.R. Assistant Director for Export/Import & International Bafeguards. 79/12/04. 1p.
- 7912140111 Executive Branch position re Westinghouse application for license to export 2,874 kg U-235, contained in 82,826 kg U. to Yugoslavia, Ltr of assurance encl. License should be granted.
  NOSENZO, L. V. Stote, Dept. of, Bureau of Oceans & Internati. Environ. & Scientific Affairs. 79/11/30. 3pp.
- 7912140115 Amend 1 to export license for Paul-Munroe Hydraulics. Inc. adding intermediate consignee.
  PETERBON, M.R. Assistant Director for Export/Import & International Safeguards. 79/11/27. 1p.
- 7912140118 Submits request to amend export license, adding intermediate consignee.
  BIEOFRIED, J. R. Paul Munroe Hydraulics, Inc. 79/11/27. 1p.
- 7912140122 Bubmits application to amend license, increasing amount exported to 10.5 kg U, containing 0.073 kg U-235.
  HARMON,D. Edlow International Co. 79/11/26. ip.
- 7912140139 Forwards application for export license for minor nuclear export. Ltr of assurance required.
  PETERSON, M.R. Assistant Director for Export/Import & International Bafaguards. 79/11/30. ip.
- 7912140141 Executive Branch position re B&W application for license to export 60 kg U-235.contained in 1.500 kg U, to United Kingdom. Bince application has been withdrawn, no action will be taken.
  NOBENZO.L.V. State, Dept. of, Bureau of Oceans & Internatl. Environ. & Bcientific Affairs. 79/11/21. ip.
- 7912140146 Submits application for amend to export license, extending expiration data to 810201.
  WILSON, B. D. General Electric Co., Nuclear Energy Products Div. BDN-79245. 79/11/26. ip.
- 7912140149 Executive Branch position re Eddow Intl application for license to export 68,500 kg U to Switzerland via France.Ltrs of assurance encl.License should be granted.
  NOSENZO.L.V. State, Dept. of, Bureau of Oceans & Internati. Environ. & Scientific Affairs. 79/11/27. 23pp.
- 7912140153 Forwards application for export license for minor nuclear export.Ltr of assurance required. PETERSON.H.R. Assistant Director for Export/Import & International Bafeguards. 79/12/03. 1p.
- 7912140176 Requests Executive Branch position re Matl Bellows Corp application for license to export nuclear reactor components to Spain. PETERBON.M.R. Assistant Director for Export/Import & International Bafeguards. 79/12/03. 1p.
- 7912170338 Forwards application by Transnuclear, Inc for license to export 3.008 kg U, enriched to 93.30% U-235, to The Natherlands.
  MATSON, V. Transnuclear, Inc. 79/11/16. ip.
- --7912170343 Application by Transnuclear, Inc. for license to export 3.008 kg U.enriched to 73.30X U-235, to The Netherlands. End use statement encl. \* Transnuclear, Inc. NUK 307,79-315. 79/11/16. 3pp.
- 7912170348 Forwards application by Bosing Co for license to export depleted U exempt counterweights to China. MDRGAN.W.E. Bosing Co. 79/11/21. 1p.
- --7912170353 Application by Boeing Co for license to export depleted U exempt counterweights to China.
  MDROAN. H. E. Boeing Co. DOC# 40-7783. 79/11/21, 2pp.

- P912170356 Forwards application by Transnuclear, Inc for license to apport 34,901 kg U hexafluoride, enriched to 3,35% U-235, to West Osmany.
  MATSON.V. Transnuclear, Inc. 79/11/07. 1p.
- T912170364 Forwards application by Transnuclear, Inc for license to export 17,400 kg U.anriched to 3.35% U-235, to West Garmany.
  MATSON, V. Transnuclear, Inc. 79/11/07. 1p.
- ---7912170366 Application by Transnuclear, Inc for license to export 17,400 kg U.enriched to 3.35% U-235, to Nest Germany, End use statement encl.

  Transnuclear, Inc. RBU 306 79-308. 79/11/08. 3pp.
- 7932170389 Application by Edlow Intl Co for license to export 13,000 kg tails depleted U hexafluoride to United Kingdom. HARMON, D. W. Edlow International Co. 79/11/21. 1p.
- 7912170371 Application by Reuter-Stokes Inc for license to export U-235 deposited as U distide on internal surface of model RB-CA-0201-231 radiation detector to France End use statement encl.

  SKARUPA. J. D. Reuter-Stokes, Inc. V-8374. 79/11/07. 4pp.
- 7912170374 Application by Hewlett Packard Co for license to export HP Model 5736A gas chromatograph equipped w/electron capture detector 18713A, 15 aci Ni-63 plated part to China.

  KAMANKRA.D. Hawlett Packard Co. 1820-01623. 79/10/14. 1p.
- 7912170376 Application by Westinghouse for license to export one compensated ionization chamber NLB105 to West Germany.
  POCHAL-N.F. Westinghouse Electric Corp. ZE-10269. 79/11/26. 1p.
- 7952180002 Application by Matheson Cas Products for license to export 3.000 liters deuterium to Taiwan. WOOD.L.D. Matheson Gas Products. 79/12/04. 2pp.
- 7912180003 Application by Isotope Products Labs for license to export 3 mCi Cu-244 to The Netherlands.
  PELM.K. Isotope Products Laboratories. 79/12/04. 1p.
- T912180039 Application by Westinghouse for license to export two uncompensated ionization chambers to Belgium.
  POCHAL.H.F. Westinghouse Electric Corp. 79/12/05. 1p.
- 7912180046 License for Ediow Intl Co to export 0.6 micrograms Pu-242 to Finland. PETERSON M.R. Assistant Director for Export/Import & International Bafeguards. 79/12/10. 2pp.
- 79121B0061 Amend 3 to license for QE, extending expiration date from 800101 to 830101 & removing Conditions 1 & 5. PETERSON.M.R. Assistant Director for Export/Import & International Safeguards. 79/12/10. 1p.
- 7912180079 Application by Bandia Labs for license to export approx 4.41g Batch 1 U.enriched 30% to U-235, to West Germany. MALKER, J. V. Bandia Laboratories. 79/11/13, 1p.
- 7912180076 Requests termination of License XBNM-1384 due to cancellation of commercial contract Returns License ISNM-790916 Notification is presented on behalf of B&M. MARNON.D.W. Edlow International Co. 79/11/13. 1p.
- P9:2180106 Returns License IBNM-79016 & requests withdrawal of License XBNM-1384 due to concellation of commercial contract. Metification is presented on behalf of BEW, MARMON, D. W. Ediow International Co. 79/11/13, ip.
- 7912170155 Forwards statements presented to Philippine Commission on nuclear reactor plants. LAFLERR.J.D. Office of International Programs. 79/11/15. 1p.
- 791219041R Bubmits application to smend export license extending supfration date to 821201. WILBOWNS. D. General Electric Co., Nuclear Energy Products Div. 504-79242. 79/11/16. ip.
- 7912190789 Forwards application by Appleton Papers, Inc for license to appert electron capture detector unit containing Ni-63 source to Soviet Union. CRAINICH.V.A. Appleton Papers, Inc. 79/11/21. 1p.

- --7912190794 Application by Appleton Papers, Inc for license to export one electron capture detector unit containing Ni-63 source to Soviet Union. CRAINIGH, V. A. Appleton Papers, Inc. 73/77420-4, 3, 19. 79/11/20. lp.
- 7912200044 Hithdraws application for export License XCOM-0312. GRAY. J. Q. ITT Grinnell. 79/12/06. ip.
- 7912200093 Notifies of waiver of 15-day vaiting period for issuance of license due to organt requirement re export of Zircaloy-II seamless tubing to West Oermany. PETERBON.H.R. Assistant Director for Export/Import & International Safeguards. 79/11/27. 1p.
- 7912200283 Application by Mitsui & Co. Inc. for license to export 8,500 lb Zircalay-2 tube shells to Japan.
  MCNOEN.T. Mitsui & Co., Ltd. 136123. 79/12/04. lp.
- 7912200286 Forwards revised and use statements & research training test reactor directories to be included in export license applications. Amends quantity of U-235 on License XBNM-1545 from 24, 258 kg to 24, 260 kg.
  MATBON, V. Transnuclear, Inc. 79/11/28, 18pp.
- 7712200310 Bubmits application to amend license adding IAEA.Vienna. Austria as intermediate consignee in foreign country. TAYLOR.R.R. Monsanto Co. 79/11/27. 1p.
- 7912200321 Amend 1 to Monsanto Research Corp license, adding IAEA as intermediate consignee.
  PETERBOM M. R. Assistant Director for Export/Import & International Safeguards. 79/12/07. 1p.
- 7912200329 Application by GE for license to export 115,000 kg U dioxide BWR fuel bundles to Spain. WILSON.B. Ceneral Electric Co. 79/11/30. 1p.
- 7912200397 Bubmits application to amend license changing licensee name & address, ultimate & intermediate consignees in foreign country & description of matls exported.
  WILEON.B.D. General Electric Co. 79/11/29. 2pp.
- 7912200402 Responds to 791025 ltr confirming authorization of Korea Electric Co to receive & possess ten pieces of An-core detector.

  PARK.S. Korea. Republic of (South Korea). 79/11/15. 1p.
- 7912200407 Bubmits application to amend license. Radex SA of Madrid. Spain. importing two detectors for transshipment to Union Electrica but will not take possession of matl. GERAGHTY.C. Reuter-Stokes, Inc. 79/11/29. ip.
- 7912200412 Requests Executive Branch position re Spex Disc, Inc application for license to export SNM to Japan. PETERBON.M.R. Assistant Director for Export/Import & International Bafeguards. 79/12/06. 1p.
- 7912200497 License for Transnuclear, Inc to export 3, 17 g U-235 contained in 8 g U as NBB stds U-005, U-005, U-100, U-500 & U-930 & 4, 25 g Pu as NBB stds 8RM946, 947, 948, 949d, to France. PETERSON, M. R. Assistant Director for Export/Import & International Safeguards. 79/12/10. 2pp.
- 7912200501 License for Westinghouse to export 0.0410 g U-235, contained in .0440 g U.to South Korea. PETERSON.M.R. Assistant Director for Export/Import & International Safeguards. 79/12/10. 2pp.
- 7912200392 Requests Executive Branch position re Transnuclear, Inc application for license to export SNM to Brazil. QG891CK,L.V. Office of the Executive Director for Operations. 79/12/10. 1p.
- 7912200594 Requests Executive Branch position re GE application for license to export SNM to Spain.

  90881CK.L.V. Office of the Executive Director for Operations.
  79/12/10. 1p.
- 7912200598 Requests Executive Branch position of Transnuclear, Inc application for license to export SNM to Canada. 60881CK.L.V. Office of the Executive Director for Operations. 79/12/10. ip.

- 791221001B Requests Executive Branch position re Transnuclear, Inc application for license to export SNM to The Netherlands. COSSICK.L.V. Office of the Executive Director for Operations. 79/12/06. 1p.
- 7912210027 Submits application to amend license, setting max isotope weight at 3 micrograms.
  JOHNSON.N. Exertine Instrument Corp. 79/11/28. 1p.
- 7912210044 Notifies of cancellation of 781002 application due to error in spec & end user statement. Seisòin Trading Co. Ltd submitted corrected application on 790605 COYNE.M.J. SPEX Industries, Inc. 79/11/16. Spp.
- 7912210070 Advises that 791002 export license application has been cancelled.
  PETERSON,M.R. Assistant Director for Export/Emport & International Safeguards. 79/12/10. 1p.
- 7912210077 Requests Executive Branch position re Boeing Co application for license to export depleted U contained in counterweights to China. PETERSON.H.R. Assistant Director for Export/Import & International Safeguards. 79/12/10. 1p.
- 7912210082 Advises of withdrawal of export license application by Edlow International Co 791113 ltr.
  PETERSON.M.R. Assistant Director for Export/Import & International Safeguards. 79/12/10 ip.
- 7912210086 Forwards 791119 ltr from Reuter-Stokes, Inc. withdrawing export license applications XCOM-0206 & XCOM-0213 for export of components to Patistan. W/o encl.
  PETERSON.M.R. Assistant Director for Export/Import & International Safeguards. 79/12/10. 1p.
- 7912210092 Advises of applicant end use of NBS Stds for NBS SRM 946-949 under export license application XSNM-1617.
  PETERSON.M.R. Assistant Director for Export/Import & International Safguards. 79/12/11. 1p.
- 7912210099 Requests amend of export license application XSNM-1593 revising quantity of exported matl.
  HERSCH.M.M. Westinghouse Electric Corp. ICB-9479. 79/11/26. 1p.
- 7912210104 Corrects physical form of SNM & requested delivery date in 791126 export license application XSNM-1355.
  MATSON.V. Transnuclear, Inc. 79/12/04. 1p.
- 7912210128 Ltr of assurance in support of Transnuclear Inc 790927 application to export 19 N9S stds w/total of 3.078430 g U-235 & 4.25 g Pu to France.

  CDPPEL.M. European Communities, Commission of, 79/11/20. 1p.
- 7912210138 Forwards ltr from Edlow Intl Co requesting amend to export license application increasing quantity of depleted U to 10.5 kg.
  PETERSON.H.R. Office of International Programs. 79/12/14. lp.
- 7912210139 Requests withdrawal of 790308 & 28 applications to export U to Pakistam.

  QERACHTY.C. Reuter-Stokes, Inc. 79/11/15. 1p.
- 7912210141 Forwards IAEA safety expert repts & cover 1tr. HAUBER.R.D. Office of International Programs. 79/12/05. 2pp.
- ---7912210160 "Technical Assistance In QA & NonDestructive Testing," Field Rept 1.790710-0810. ALBERT.W.G. International Atomic Energy Agency (Austria). PHI/9F/06-B. 79/08/31. Bpp.
- --7912210160 "Technical Assistance In QA & NonDestructive Testing," Field Rept 1,790710-0810. ALBERT.M. Q. International Atomic Energy Agency (Austria). PHI/9F/06-B. 79708/31. Bpp.
- --7912210160 "Technical Assistance In GA & NonDestructive Testing," Field Rept 1,790710-0810. ALBERTH G. International Atomic Energy Agency (Austria). PHI/9F/04-B. 79/08/31. 8pp.
- --7912210173 "Technical Assistance In QA & NonDestructive Testing," Field Rept 2,790910-1110. ALBERT,H. Q. International Atomic Energy Agency (Austria). PHI/9F/06-B. 79/11/30. 30pp.

- --7912210173 "Technical Assistance In QA & NonDestructive Testing." Field Rept 2.790810-1110. ALBERT.M.G. International Atomic Energy Agency (Austria). PHI/9F/06-B. 79/11/30. 30pp.
- ---7912210173 "Technical Assistance In QA & NonDestructive Testing," Field Rept 2,790810-1110. ALBERT.N.G. International Atomic Energy Agency (Austria). PHI/9F/06-8. 79/11/30. 30pp.
- 7912210157 Forwards 1tr from ITT Grinnell Valve Co. Inc. withdrawing licence request for valve export to Spain. W/o encl. PETERSON, N. R. Office of International Programs. 79/12/14. 1p.
- 7912240011 Advises of waiver of 15-day waiting period before issuance of export license to Bio-Rad Labs.
  PETERISDN,H.R. Assistant Director for Export/Import & International Safeguards. 79/12/03. ip.
- ---7912260014 License for Bio-Rad Labs to export 1 kg deutorium oxide, contained in compounds.to The Netherlands. PETERSON, M. R. Assistant Director for Export/Import & International Safeguards. 79/12/03. lp.
- 7912260060 Forwards application for export license for minor nuclear matl.Ltr of assurance required.
  PETERSON.H.R. Assistant Director for Export/Import & International Bafeguards. 79/12/06. ip.
- 7912260067 Forwards application for export license for minor nuclear mat1.Ltr of assurance required.
  PETERSON, H.R. Assistant Director for Export/Import & International Safeguards. 79/12/10. ip.
- 7912260073 Forwards application for export license for minor nuclear natl.Ltr of assurance required.
  PETERSON,M.R. Assistant Director for Export/Import & International Safeguards. 79/12/10. ip.
- 7912260161 Forwards end use statement for U hexafluoride stds being purchased by Power Reactor & Nuclear Fuel Dovelopment Corp. MCALDUFF.H.J. Energy, Dept. of. 79/11/29. Spp.
- --7912260165 Advises that total max element weight for 791101 license application is 1,410 g. OKUDA-H. Marubeni America Corp. (subs. of Marubeni Corp.). Mai-5989, 79/11/15, lp.
- --7912260168 Forwards application by Harubeni America.Corp for license to export 1.049.011 g U hexafluoride to Japan.

  DHUDA.H. Marubeni America Corp. (subs. of Marubeni Corp.).

  HAI-HO-5977. 79/11/01. 2pp.
- --7912260174 Application by Marubeni America Corp for license to export 1.049.011 g U hexafluoride to Japan. OKUDA.H. Marubeni America Corp. (subs. of Marubeni Corp.). 7911/01. 2pp.
- 7912260189 Forwards application by Transnuclear Inc for license to export 16,242 kg U in form of U hexaluoride enriched to max 3.35% U-235 to Brazil.

  MATSON, V. Transnuclear Inc. 79-320/01. 79/11/29. ip.
- --7912260196 Application by Transnuclear, Inc. for license to export
  16.242 kg U in form of U hexafluoride, enriched to max 3.35%
  U-235, to Brazil. End use statement encl.
  MATBON.V. Transnuclear, Inc. 79/11/30. 2pp.
- 7912260205 Advises that physical form of matl listed on 791126 license application should be corrected to total of 191 kg U as U setal. AECL requested delivery of matl in early Nov 1980.

  MATSON.V. Transnuclear. Inc. 79-231/01. 79/12/04. ip.
- --791226020B Forwards application by Transnuclear,Inc for license to export 191 kg U in form of U metal,enriched to max 93.3% U-235.to Canada. HATSON,V. Transnuclear, Inc. 79-231/5/01. 79/11/26. 1p.
- --7912260212 Application by Transnuclear Inc for license to export 191 kg U in form of U metal enriched to max 93.3% U-235 to Canada. MATSON, V. Transnuclear Inc. 79/11/26. 2pp.
- 7912260232 Amend 1 to License XBNM-1502 to increase amount of U-235 in 0.0132 g U.enriched to 94% w/o max.Commission of European Communities 791207 ltr to DDE requesting increase in amount of U encl.
  PETERSON.M.R. Office of International Programs. 79/12/11. 2pp.

- 7912280050 Forwards Transnuclear, Inc 1tr transmitting add1 info re export license XSNM-1543, to be considered w/790727 application.
  GOSSICK.L.V. Office of the Executive Director for Operations, 79/12/14. 1p.
- 7912280067 Discusses Westinghouse 791026 application to import 1.305 kg U.enriched to 2% U-235.from Sweden.License should be issued. MOORE.R.N. Office of International Programs. 79/12/05. 1p.
- 7912280116 Forwards end use statement by Ministry of Trade & Industry of Finland re export license application for transfer of Pu-242 to be used as calibr std.
  MAKIPENTILI. Finland. 79/11/29. 3pp.
- 7912280193 Forwards license for Westinghouse to export two uncompensated ionization chambers to Belgium. PETERSON.M.R. Assistant Director for Export/Import & International Safeguards. 79/12/11. 1p.
- --7712280156 License for Westinghouse to export two uncompensated ionization chambers to Bolgium.
  PETERSON.M.R. Assistant Director for Export/Import & International Bafeguards. 79/12/11. 1p.
- 7912280602 Application by Westinghouse for license to export one plece proportional counter WL22793 to Philippines. POCKAL.W.F. Westinghouse Electric Corp. ZE-60160. 79/11/26. 1p.
- 7912280456 Forwards application by TX Nuclear Division for license to export 9 g of Fu-23888e, contained in sealed source, to Brazil.

  HENDRICK, M. G. Texas Nuclear Div. (subs. of Ramsay Eng. Co.).
  T-9509. 79/11/04. 1p.

- --7912280663 Application by TX Nuclear Division for license to export U g of Pu-23888e.contained in sealed source, to Brazil, End use statement encl.

  HENDRICK.W.O. Texas Nuclear Div. (subs. of Ramsay Eng. Co.).
  T-9509. 79/11/06. 2pp
- 7912280577 Application by Spex Bisc. Inc. for license to export 0.036 y U-235.contained in 12 g of U oxide to Japan. End use statement encl.
  COYNE, M. J. Spex Bisc. Inc. (01. 79/09/26. 3pp.
- 7912310117 Forwards Transnuclear, Inc. 791128 ltr re. add1 info on license application & requests increase in quantity of U-235 to be exported. Requests consideration of ltr in conjunction w/application forwarded on 790727 W/o encl. ODSSICK.L.V. Office of the Executive Director for Operations. 79/12/10. 1p.
- 7912310122 Forwards request to amend application for export license for minor nuclear export/decreasing quantity of mat1 exported. Requests Japanese embassy advised. FETERSON.H.R. Assistant Director for Export/Import & International Safeguards. 79/12/50. ip.
- 7912310176 Forwards application for Amend 5 to export license, extending license period for two yrs & adding three ultimate consignees.

  MORGAN.M.E. Boeing Co. 4-1635-79R-0317. 79/11/20. ip.
- ~-7912310180 Application by Boeing Co for Amend 5 to export license, extending license period for two yrs & adding three ultimate consignees.

  MORGAN.W.E. Boeing Co. DOC 40-7783. 79/11/20. 2pp.
- 7912310547 Application by Nitsui & Co for license to export fireonium 2.5 niobium pressure tube samples to Japan. MONDEN,T. Mitsui & Co. . Ltd. 79/12/10. lp.



The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index titled "Cross Reference of Enclosures to Principal Documents."

AUTHOR	ACCESSION	SUBJECT		ACCESSION	SUBJECT			ACCESSION	6UBJECT .
AUTHUR	NUMBER	CATEGORY	ROHTUA	NAME R	CATEOOR	Υ	AUTHOR	NUHUI ER	CATEOGRY
AAHODT, H. H.	7912310142	50-289 0	ALLEN, H. L.	7912190452	50-272	p	AGUILA, N. H.	7912280393+	50-320 H
ABERCROMBIE, H. L.	7912130438	50-259 B	ALLEN, P. B.	7912310432	50-366	R	ARCHITZEL, R.	7912070139*	50-293 G
ABERCROMBIE: H.	7912190554	50-296 8	ALLEN, P. B.	7912310433*	50-366	R	ARENAL, A.	7912130704+	50-361 G
ABERCROMBIE.H.	7912140384	50-259 R	ALTON, C. Q.	7912070462	50-312	J	ARENALI A.	7912180324	50-361 8
abrans, R.	7912060644	50-3 <del>0</del>	ALTON, C. Q.	7912180580	50-244	J	ARENAL, A.	7912190602	50-361 B
ABRAYS, R.	7912140018	50-594 0	ALVAREZ, R.	7912050343*	XPDRTL.IC		ARENAL, A.	7912200541	50-361 B
ABRELL, C. A.	7912190194*	FOIA	ANDALHAN, E.	7912130261	PR		ARMSTRONO, W. H.	7912100469	PROJ
ACOSTA, A. P.	7912170283	40-8584	ANDALMAN, E.	7912130261	PA		ARMSTRONG, W. H.	7912100477	PROJ
ADAH, P. J.	7912260202*	GA777	ANDERBON, D.	7712130224*	50-329	В	ARMSTRONG, W. H.	7912140009	PROJ
ADAM P. J.	7912260193*	0A999	ANDERBON, T. H.	7912100255*	50-3	P	ARMSTRONG, W. H.	7912140020*	PROJ
ADAMS, N. E.	7912130293	50-255 R	ANDERBON: T. M.	7712180049	PT21		ARMSTRONG, W. H.	7912100469	PROJ
ADAMS, R. E.	7912120190 7912170070*	NUREO	ANDERBON, T. H.	7912280540*	50-375	B	ARHSTRONG, W. H.	7912100477	PROJ
ADLER, T. A. ADLER, T. A.	7912170070#	50-289 0 50-289 0	ANDERBON, T. H.	7912040356	TOPREP		ARMSTRONO, IJ. H.	7912140009	PROJ
ADLER, T. A.	7712270087	50-287 0	ANDERSON, T. M. ANDERSON, T. M.	7912040357* 7912050509	TOPREP		ARMSTRONG, W. H.	7912140020#	PROJ
		JU-207 U	ARDEMOUNT I. N.	7412090904	TOPREP		ARNOLD, R. C.	7912100341	50-297 H
ADLER, T. A.	7912270111	50-289 0	ANDERSON, T. M.	7912270546	TOPREP		ARNOLD, R. C.	7912120401	50-299 P
ADLER, T. A.	7912170066	50-289 0	ANDERSON, T. H.	7912260291	TOPREP		ARNOLD, R. C.	7912180521	50~297 H
ADLER, T. A. ADLER, T. A.	7912170070* 7912140151	50-287 0 50-287 0	ANDERSON, T. H.	7912130684#	50-247	P	ARNOLD, R. C.	7912130435	50-320 P
ADLER, T. A.	7912270087	50-289 G 50-289 G	ANDERSON, T. H. ANDERSON, T. H.	7912190416 7912190597	TOPREP TOPREP		ARNOLD, R. C.	7912130441*	50-320 P
POPLETT 1. M.		30-207 V	ANDERSON, F. N.	1415140241	IUPREP		ARYAFAR, A.	7912180223	MUREO
ADLER, T. A.	7912270111	50-289 0	ANDERSON, T. M.	7912200338	TOPREP		ASH, R. F.	7912060358	50-317 0
ADRACNA, J. H.	7912030042	PROJ	ANDERSON, T. M.	7912200396	50-545	B	ASHENDEN, M. C.	7912110514 <del>#</del>	50-261 G
ADRAGNA: J. H.	7912310294	PRDJ	ANDERSON, T. H.	7912280569	50-282	8	ASHER, T. R.	7912030023	XPDRTLIC
ADRACNA, J. M. AEBIE: K.	7912030042 7912170297*	PROJ 50~346 8	ANDERSON, V. S.	7912280569	TOPREP		ASHER, T. R.	7912050211#	XPORTLIC
NCBIELO.	/7121/027/*	30,440 8	ANDERSON, T. M.	7912190601*	TOPREP		ASHER, T. R.	7712030023	XPORTLIC
ACEE, J. R.	7912180196*	0A799	ANDERSON, T. H.	7912040014×	50-369	Q	ASHER, T. R.	7912050336	XPORTL.IC
ACEE, J. R.	7912120293*	QA799	ANDERSON, T. H.	7912040138*	50-413	G	ASHER, T. R.	7912050206	XPORTLIC
ACEE, J. R.	7912260159*	QA999	ANDERSON, T. M.	7912050548	TOPREP		ABHER, T. R.	7912050211*	XPORTLIC
AGRAHAL, A. K. AGRAHAL, A. K.	7912040119 7912120108	RES TOPREP	ANDERSON, R. R.	7912060307	NUREC		ASHLEY, E. C. ASHELL, D. L.	7912110039 7912070150	State Prog 50-362 S
			ANDERBON, L. F.	7912060023	PROJ			/7120/0130	30-30K A
ADRAHAL, A. K.	7912120129	TOPREP	ANDERSON, D. R.	7912310035	RES		ASHELL, D. L.	7912060561	50-302 0
AHEARN, C. D.	7912280627	50-445 H	ANDERBEN, J. A.	7912140524*	RE8		ABHELL, D. L.	7912170362	50-382 G
AHEARN, C. D.	7712280629	50-449 M	ANDERBEN: J. A.	7912140526*	REB		ASHELL, D. L.	7912070145	50-382 9
AHEARN, C. D. AHEARN, C. D.	7912280429 7912280429	50-445 M 50-445 H	ANDERBON, D. O.	7912110133+	GA999		ASHELL, D. L. ASHELL, D. L.	7912170357	50-382 0
PERCENTING, D.	/TIRROUGE/	DU-445 H	ANDERSON, D. G.	7912110061*	0A979		ASMCLL; D. C.	7912070392	50-382 8
AHEARN, C. D.	7912280629	50-445 H	ANDERSON, D. Q.	7912180142#	0A999		ASHELL, D, L.	7912070455	50-382 9
AHEARN, C. D. ALBERT, N. O.	7912280629 7912210160*	50-445 M XPORTLIC	ANDERSON, D. O.	7912110516*	0A999		ASHELL, D. L. AUDIN, L.	79122702 <b>74</b> 7912120498	50-382 A FDIA
ALBERT, W. O.	7912210170*	XPORTLIC	ANDGONINI.O.C. ANDGONINI.O.C.	7912070126# 7912140286	50~293 50–293	Q Q	AUSTIN, H. A.	7912310351	70-135
ALBOSTA, D.	7912120574*	50-155 U	ANDUGNINI, O. C.	7912070494	71-9081	u	AUSTIN, H. A.	7712120106*	70-364
			**						
ALDEN, N. H.	7912140359#	50-277 R	ANDGGHINI, Q. C.	7712260045	50-293	Q.	AUTIO, H. A.	7912070437	50-29 9
ALDERSON, C. ALDERSON, C. E.	7912190751 7912200423	50-336 B 50-260 B	ANDOGNINI, 9, C.	7712190485	50-293	Q	AUTIO, H. A. AUTIO, H. A.	7912100292 7912110287	50-29 S
ALDERSON, C.	7912070026	50-260 S 50-395 S	ANDGONINI, Q. C.	7912040259	50-293	P P	AUTIO, H. A.	7912110207	ສບ~ຂາ ສ 50~29 B
ALDRICH, J. M.	7912170359	RES	andcionini, O. C. Andcionini, O. C.	7912120419 7912120440	50-293 50-293	F	AXELROD, D. M.	79122700050	CONNIESTON
						* *			
ALEXAKOERSON, E.	7912310194	REGOD	ANDOONINI, O. C.	7912120333	50-273	P	AXELRAD. H.	7912130481	PR
ALLAN, J. ALLAN, J.	7912200575 7912200567	50-247 8	ANDOGNINI, O. C.	7912270321	50-293	0	AXELRAD, M. AXELRAD, M.	7912130257	50-344 O
ALEAN, J.	7912200567 7912200493	50-334 B 50-272 S	ANDOONINI, O. C.	7912270419	50-293	P	AXELRAD, H.	7912180113 7912270091	50-344 0 : 50-344 0
ALLAN, J.	7912200493	50-272 S 50-247 S	ANDOONINI, G. C. ANDRAS, R. F.	7912310312 7912270365	50-293 50-244	F H	AXELRAD, H.	7912270091 7912130481	20-344 W
						D			
ALLAN, J.	7912200444	50-247 B	ANDREUS, J. P.	7912280648	RECOD		AXELRAD, H.	7912130257	50-344 O
ALLAN, J. M.	7909010163*	FOIA	ANDREHS, D. L.	7912180364*	50-335	ā	AXELSON, W. L.	7912190276	REVIEW ORP
ALLAN, J. ALLEN, J.	7912030114 7912190088*	50-266 B 50-260 9	ANO. W. P.	7912310300	50-348	a	AXELSON, W. L. AXELSON, W. L.	7912190273 7912190281	REVIEW ORP
ALLEN, O. M.	7912190067±	NABYE MOT	ANGELO, J. ANTONOPOULOS, P.	7912310323 7912120337*	TOPREP 50-293	P	BABBITT, B.	7912070006	REVIEW ORP
	( . : F : OAAO \ =	101E 1191	MILITARIO CALGRIP.	/T161KU33/#	#U"#73	F	w.w	4.1785/0000	JV-JEU F

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	ROHIUA	ACCESSION NAMBER	SUBJECT CATEGORY	ROLITUA	ACCESSION NUMBER	SUBJECT CATEGORY
BACON, J. L.	7912120397	50-329 A	BATES, A. BATES, B. J. BATES, R. U. BATES, R. U. BATES, R. U.	7912060062	PROJ	BIALIK, E. I.	7912060644	50-3 0
BADGER, C. H.	7912120168	PROJ		7912210020*	GA779	BIALIK, E. I.	7912130348	PR
BADRAM, S.	7912140491*	50-237 S		7912040426*	50-236 S	BIALIK, E. I.	7912130352*	PR
BAER, T. S.	7912130045	71-6144		7912040401*	50-336 S	BIALIK, E. I.	7912140018	50-596 0
BAER, T. S.	7912180444	27-39		7912130468*	50-336 S	BICKWIT, L.	7912060034	70-2623
BAER, T. S. BAER, R. L. BAER, R. L. BAER, R. L. BAER, R. L.	7912310379 7912200574 7912190209 7912190215 7912270162	71-5058 50-367 P TOPREP 50-361 A TOPREP	Bates, R. W. Bates, J. W. Bauer, E. R. Baumann, C. Bauser, M. A.	7912040413* 7912260181* 7912130543* 7912280458* 7912280407	50-336	BICKHIT, L. BIDDLE, C. T. BIDEN, J. R. BIELAWSKI, A. P. BIELAWSKI, A. P.	7912100217* 7912270053 7912280287* 7912270049 791228022&	50-266 T 50-466 9 50-320 U 50-599 9 50~599 9
BAILEY, K. BAILEY, R. J. BAILEY, R. J. BAILEY, R. J. BAIRD, J. B.	7912280565* 7912040129* 7912200478* 7912260119* 7912310298	50-329	BAUSER, H. A. BAUSER, H. A. BAXLEY, S. X. BAXTER, R. C. BAXTER, T. A.	7912140177 7912030607 7912270489* 7912110549 7912030627	50-387 0 50-522 0 50-321 S REGOD 50-312 0	BIELAWSKI, A. P. BIELAWSKI, A. P. BIELAWSKI, A. P. BIER, J. DIERMAN, C.	7912280257* 7912280226 7912280257* 7912210443* 7912100459	50~599 0 50~599 0 50~599 0 50~155 0 50~289 0
Baird, J. B.	7912050355#	50-142 G	BAXTER, T. A.	7912030034=	50-312 0	Dierman, S. R.	7912180158	RES
Baird, J. B.	7912260139#	50-228 G		7912270093	50-312 6	Biley, B. W.	79120601524	50-325 Q
Baisden, L.	7912100116	CONTRACT		7912270347	50-312 6	Birchan, J.	7912140528	50-3 U
Baisden, L.	7912100097	CONTRACT		7912280456	50-320 0	Birkel, R.	7809290053	50-269 F
Baisden, L.	7912070164	CONTRACT		7912030027	50-312 6	Bischeff, C. A.	7912110371	50-275 H
Batsden, L. Batsden, L. Batsden, L. Batsden, L. Batsden, L.	7912100385 7912110001 7912110004 7912110013 7912120065	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	Baxter, T. A. Baymard, P. Y. Baynard, P. Y. Baynard, P. Y. Bayner, J. P.	7912030034* 7912190795 7912130201 7912180271 7912170176	50-312 0 50-302 0 50-302 F 50-302 P 50-296 0	BISHOP, C. J. BISHOP, C. J. BISHOP, C. J. BISHOP, C. J.	7912050481 7912060059 7912060239 7912060072 7912140062	50-338 0 50-397 0 50-338 0 50-522 0 50-389 0
BAKER, B. L.	7912130525	PR	BAYNE, J. P.	7912140293	50-284 0	BISHOP, C. J.	7912140055	50-466 0
BAKER, B. L.	7912140309	RES	BAYNE, J. P.	7912310367	50-284 6	BISHOP, C. J.	7912190120	50-389 0
BAKER, E. J.	7912140483*	RES	BAYNE, J. P.	7912040319	50-284 5	BISHOP, C. J.	7912140002	50-338 0
BAKER, C. E.	7912190010	40-8581	BAYNE, J. P.	7912040367	50-284 5	BISHOP, C. J.	7912280668	50-466 0
BAKER, D. P.	7912130133*	40-8721	BAYNE, J. P.	7912040388	50-284 5	BISHOP, C. J.	7912060092	70-2623
Baker: K. R.	7912070079#	50-346 0	BAYPE, J. P.	7912040482	50-286 S	BISHOP, C.J.	7912060541	50-275 0
Bakevich G. J.	7912180007	71-6078	BAYPE, J. P.	7912310328	50-286 S	BISHOP, T.W.	7912190745	50-460 9
Baldhin: V. A.	7912170007#	50-70 6	BAYPE, J. P.	7912110332	50-286 S	BISHOP, T.W.	7912180017	50-397 6
Baldhin: V. A.	7912140425	50-224 6	BAYPE, J. P.	7912180569	50-286 S	BISSETT, P.M.	7912260095=	50-333 9
Baldhin: V. A.	7912280508	50-275 6	BAYPE, J. P.	7912200342	50-286 R	BITEL, J.S.	7912140376+	FOIA
Baldwin, W. A.	7912130276	50-275 0	BAYNE, J. P.	7912270553	50-286 S	BIVINS, W. S.	7912180005	50-397 A
Baldwin, J. H.	7912190241	50-445 H	BEAD, J. O.	7912190006*	50-133 Q	BIVINS, W. B.	7912200154	50-471 A
Baldwin, W. A.	7912130176	50-312 P	BEAN, D. P.	7912140294*	CONTRACT	BLACKMAN, V. H.	7912180037#	CONTRACT
Baldwin, W. A.	7912130276	50-275 0	BEAN, R.	7912310035	RES	BLACKSHAW, O. L.	7912040449	50-129 P
Ballard, R. L.	7912210416	50-416 A	BEATON, R. H.	7912170017#	50-70 G	BLACK, H. A.	7912060307	NUREO
BALLARD, R. L.	7912180247	50-452 C	BECHET, L. J.	7912200182* 7912110353 7912170262 7912170320 7912050077	CONTRACT	BLACK, R. L.	7912060101	50-522 0
BALLARD, R. L.	7912180278	50-409 D	BECHBOEFER, C.		50-409 C	BLACK, R. L.	7912170152	50-522 0
BALLARD, R. L.	7912060568	50-514 D	BECHBOEFER, C.		50-387 G	BLACK, R. L.	7912050376	50-522 0
BALLARD, R. L.	7912060575*	50-514 D	BECKER, F. L.		RES	BLACK, R. L.	7912060004	50-522 0
BALLARD, R. L.	7912170056	50-514 D	BECKER, J. M.		50-574 C	BLACK, R. L.	7912050421	50-522 0
Ballinger, P. L.	7912140399* 7912060247 7912280639 7912210409* 7912070160*	50-298 R	BECKHAN, D. A.	7912160253=	50-334 Q	BLACK, R. L.	791217035B	50-522 H
Baldugh, R. C.		50-445 M	BECKNER, D. A.	7912190716=	50-313 P	BLACK, R. L.	7912270054	50-522 C
Baldugh, R. C.		50-445 M	BECKNER, D. A.	7912190721=	50-313 P	BLAIR, Q. Q.	7912140367+	50-344 R
Bangart, R. L.		FOIA	BECKNER, D. A.	7912040412=	50-312 P	BLAKE, J. J.	7912050336+	50-510 Q
Banks, H. R.		50-324 Q	BEDONT, N. E.	7912310372	40-8721	BLAKE, J. J.	7912160145+	50-261 Q
Banks H. R.	7912030225*	50-324 & 50-324 & 50-329 T 50-363 H RES	BEELER, T. P.	7912170303#	50-346 9	DLALOCK, L.	7912190130	71-9853
Banks H. R.	7912050629*		BEIERLE, F. P.	7912180072	HASTE HOT	BLOTTNER, F, G.	7912140339	NUREO
Barandusky P. M.	7912210324*		BEIRLACOUE, A. H.	7912280337*	50-320 H	BLUM, R. L.	7912260357	50-445 H
Bardur O. H.	7912190109*		BELANGER, R.	7912120132	NUREO	BLUM, R. L.	7912260357	50-445 M
Bari R. A.	7912040112		BELANGER, J.	7912170166	50-10 9	BLUME, M. B.	7912110270	50-445 M
BARKER, M. R.	7912280528#	TOPREP	HELISLE, G. A.	7912060573*	50-302 Q	BLUME, M. B.	7912130236	50-445 M
BARKER, M. R.	7912280517	TOPREP	BELISLE, G. A.	7912310310*	50-390 Q	BLUME, M. B.	7912190110	50-445 M
BARKER, J. L.	7912050037#	50-10 &	BELL, N.	7912170272	50-344 Q	BOCCIGI J.	7912040383	TOPREP
BARKER, J. L.	7912070143	50-249 S	BENDER, H.	7912170346*	ACRS	BOCKERT, H. R.	7912180060=	HASTE HOT
BARKER, J. L.	7912030088	50-10 S	BENDER, N.	7912140208	ACRS	BOOTKE, P. J.	7912130297+	50-255 R
Barmer, J. Barley, B. R. Barnest, E. W. Barnes, P. L. Barnest, E. W.	7912200546 7912120130 7912050092 7912120016 7912050092	50-237 8 PROJ 50-445 H REGOD 50-445 M	BENEDICK, M. B. BENEDICT, R. A. BENEET, D. E. BENEET, Q. L.	7912310529 7912210107 7912200492# 7912140165 7912170193	MUREG 50-382 A 50-367 U MUREG ORG	BOEPE. D. J. BOODEN, G. BOODEN, G. BOODN, M. B. BOODN, T. R.	7912270439 7912130376 7912030032 7912030023 7912030023	50-344 S PROJ 40-1163 XPORTLIC 50-574 Q
Barney, I. Barney, I. Barney, I. Barrett, P. A. Barrett, L.	7912240155* 7912210034* 7912210233* 7912070162* 7912070491	0A999 0A999 0A999 50-373 0 NUREO	BENDLY, N. BERTCK, D. BERTCK, D. BERTCK, D. BERKOW, H. N.	7912190420= 7912050617 7912050617 7912130292 7912100043=	FOIA PRDJ PRDJ PR 50~286 P	BOHN, R. J. BOHN, R. J. BOHN, R. J. BOHN, R. J.	7912030184 7912030184 7912110364 7912110254 7912140234	50-367 R 50-367 R 50-367 R 50-367 R 50-367 R
EARTH, C. A. BARTH, C. A. BARTLETT, J. BARTLETT, J. BARTLETT, J.	7912050426 7912170153 7912100208* 7912210179 7912270259	50-358 9 50-400 6 50-220 9 50-220 F 50-220 S	BERMAN, H. BERNARD, S. R. BERNARD, E. R. BERNARDTER, D. L. BERNARDTER, D. L. BERRYHILL, F.	7912170337 7912110442 7912210343* 7912210332 7912040004	REG MUREG 50-204 P 50-206 P 90-209 Q	DOWN, R. J. BOWN, M. P. BOLSER, C. M. BOLTE, B. BONCHER, F. J.	7912310466 7912140461* 7912310200 7912280348* 7912140307*	50-367 R RE9 40-8721 50-320 H FDIA
Bartlett, J.	7912270507	50-220 P	DERRYHILL, F. DERRY, O. T. BERTRAM, K. D. BESECKER, K. BESTHOFF, R. E.	7912040008#	50-269 C	BOND, R. T.	7912130556	50-287 S
Bartlett, W. T.	7912210337	NUREO		7912040500	50-333 P	BONZON, L., L.	7912310153	NUREQ
Baskin, K. P.	7912140484#	50-361 G		7912050583	50-182 J	BOOK, H. E.	7912180092=	70-754
Baskin, K. P.	7912100306	50-206 P		7912200480	50-390 S	BOOK, H. E.	7912190125=	50-142 O
Baskin, K. P.	7912180315	50-206 P		7912310360	RECOD	BOOK, H. E.	7912280653=	27-10
Bask in, K. P. Bask in, K. P. Bask in, K. P. Bask in, K. P. Bask in, K. P.	7912180972 7912210369 7912270584 7912270390 7912280502	90-204 F 50-204 P 50-204 P 50-361 A	BETTAUER, R. J. DETTENHAUSEN, L. BETTENHAUSEN, L. BETTENHAUSEN, L. BEYER, J. K.	7912100474 7912260122# 7912050395# 7912200332# 7912140534	50-574 C 50-213 G 50-309 G 50-220 G 50-320 H	BOOK, H. E. BOOK, H. E. BOOK, H. E. BOOK, H. E.	7912050691 7912050693# 7912060031# 7912060021 7912050355#	50-94 0 50-94 0 50-147 0 50-147 0 50-142 0

379

AUTHOR	ACCEBGION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY
B DOK	7912050346 7912180467* 7912180086 7912180464 7912260135*	50-142 G GA999 70-754 GA999 50-228 G	BROEHL, D. J. BROEHL, D. J. BROOKS, E. H. BROUDY, P. BROWN, P. D. G.	7912270183 7912270181 7912310353* 7912140137 7912200276*	50-344 P 50-344 P 50-281 G PR 50-3 G	BRUNNER, E. J. DRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J.	7912260301 7912310041 7912310054 7912130056 7912200303	50-29 Q 50-318 Q 50-322 Q 50-309 Q 50-220 Q
BOOK, H. E. BOOK, H. E. BOOK, H. E. BORDENICK, D. H. BORDENICK, D. H.	7912260139* 7912270148 7912260132 7912100344 7912120431	50-228	Brown, P. D. O. Brown, H. H. Brown, L. J. Brown, C. O. Brown, H. H.	7912200270 7912170012 7912260097 7912200029# 7912030107	50-3 G 50-275 G 50-133 G 71-4581 50-312 G	BRUNNER; E. J. BRUNNER; E. J. BRUSH; P. N. BRYAN; R. H. BRYANT; F. S.	7912210096 7912260113 7912140004 7912280645* 7912190473	50-284 Q 50-213 Q XPORTLIC 27-10 71-358
EGRES, R. J. BORES, R. J. BORES, R. J. BORGMANN. E. A. BORGMANN. E. A.	7912170421 7912260013 7912260339* 7912110439 7912110376	50-272 8 50-272 8 50-387 9 50-358 9 50-358 9	BROWN, H. H. BROWN, H. H. BROWN, H. H. BROWN, H. H. BROWN, O. F.	7912030112* 7912030117* 7912070171 7912170012 7912130450	50-312 0 50-312 0 50-275 0 50-275 0 PR	BRYANT, F. S. BRYANT, J. K. BRYANT, J. C. BRYANT, J. C. URYANT, J. C.	7912180180 7912180535 7912200014 7912040590* 7912040549	71-358 50-483 H 50-404 B 50-375 G 50-400 S
BORGHANN, E. A. BORGMANN, E. A. BOSKEY, B. BOSS, W. BOUKNIGHT, J. A.	7912050391 7912200438 7912060036 7912120508 7912050092	50-358 F 50-358 F 70-1729 50-272 F 50-445 M	DROWN, O. F. Brown, M. S. Brown, D. H. Drown, S. C. Brown, S. C.	7912180097 7912130380* 7912270599* 7912210330 7912040377	PR 50-315 8 50-346 9 50-404 5 50-338 9	BRYANT, J. C.	7912200462 7912060657* 7912050394* 7912310288* 7912170016*	50-395 S 50-339 Q 50-416 Q 50-389 Q 50-364 Q
BOUKNIGHT, J. A. BOUKNIGHT, J. A. BOUKNIGHT, J. A. BOUKNIA, A. BOWERG, C. E.	7912110438 7912110438 7912050092 7912310498 7912120540*	50-250 M 50-250 M 50-445 M 50-373 A 70-820	BROWN, S. C. BROWN, S. C. BROWN, S. C. BROWN, S. C. BROWN, S. C.	7912130434 7912040349 7912200387 7912040487 7912070398	50-339 8 50-404 8 50-404 8 50-339 8 50-339 8	BRYANT, J. C. BUCHHOLZ, R. H. BUCHHOLZ, R. H. BUCHHOLZ, R. H. BUCHHOLZ, R. H.	7912130100* 7912040521 7912310182 7912100330* 7912190599	50-491 G TOPHEP REGOD 50-3 P NUREO
BONERS, C. E. BONERS, C. E. BONERS, E. S. BONERS, E. S. BONERS, E. S.	7912060091* 7912310299* 7912060203 7912060050 7912060130	70-820 70-820 50-250	BROWN, G. C. BROWN, G. C. BROWN, B. C. BROWN, B. C. BROWN, G. C.	7912170443 7912070395 7912310255 7912180538 7912180540	50-339 8 50-339 8 50-339 0 50-339 8 50-339 8	BUCHHOLZ, R. H.	7912140251 7912190548 7912270292 7912130148 7912130467	TOPREP TOPREP TOPREP TOPREP 50-498 0
Cohers, E. S. Bohers, E. S. Bohers, E. S. Bohers, E. S. Bohers, E. S.	7912060139 7912190191* 7912140068 7912310278 7912270143	50-275 0 50-322 0 50-312 0 50-312 0 50-312 0	OROWN, B. C. BROWN, B. C. BROWN, B. C. BROWN, S. C. BROWN, S. C.	7912200391 7912260216 7912260259 7912280541 7912270348	50-339 S 50-338 P 50-339 A 50-339 S 50-338 P	BUCHORN, P. BUCKLEY, B. G. BUCKLEY, B. C. BUCKLEY, B. C. BUCKLEY, B. C.	7912130467 7912120132 7912060652 7912310172 7912180069	50-49B 0 NURE0 50-461 A 50-275 A 50-586 G
BOYD, D. C. BOYD, D. C. BOYD, D. C. BOYD, D. C. BOYD, D. C.	7912210041 7912180373 7912050231* 7912110271* 7912120061	50-255 S 50-275 S 50-407 G 50-315 G 50-315 S	BROWN, B. C. DROWNLEE, V. L. BROWNLEE, V. L. DROWN, R. A. BROWN, R. A.	7912270366 7912110514* 7912060590* 7912200395* 7912260145*	50-939 A 50-261 Q 50-395 Q 27-47 27-47	BUI, J. BURCHETTE, W. H. BURCHETTE, W. H. BURCHETTE, H. H. BURCHETTE, T. E.	7912170418* 7912240340 7911300277 7912240360 7912310288*	50-195 0 50-445 M 50-445 M 50-445 M 50-389 @
BDYD, D, C. BDYD, D, C. BDYD, D, C. BDYD, D, C. BDYD, D, C.	7912070070 7912260144* 7912180084 7912190090 7912310064	50-155 8 50-155 9 50-254 8 50-275 8 71-258	Brown, R. A. Brown, G. D. Brown, G. D. Brown, G. D. Brown, R. L.	7912310238* 7912210405* 7912280360* 7912030231* 7912110133*	27-47 FOIA 40-2259 40-3453 GA999	BUADETTE, T. E. BUADETTE, T. E. BURGER, A. BURGER, A. BURKE, D. J.	7912040590* 7912200462 7912040175 7912190783 7912050467*	50-395 Q 50-395 S 50-29 P 50-29 P 50-280 Q
BOYER: V. S. BOYER: V. S. BOYER: V. S. BOYLIN: V. T. BOYLE: M. L.	7912120511 7912070151* 7912310198 7912200376* 7912310377*	50-352	BROWN, R. L. BROWN, R. L. BROWN, R. L. BROWN, C. H. BRUGGER, R. M.	79121801424 7912200196* 7912200499* 7912170054 7912030220*	GA999 GA999 GA999 IOCFR 50-1GA G	BURKE, D. J. BURNETT, P. T. BURNETT, P. T. BURNETT, P. T. BURNETT, P. T.	7912050624* 7912030065* 7912070105* 7912040215* 7912040235*	50~280 Q 50~327 Q 50~395 Q 50~369 Q 50~280 Q
BOYTER, T. A. BRADFORD, B. BRADFORD, W. H. BRADFORD, W. H. BRADFORD, W. H.	7912280454 7912180286 7912070097* 7912070020 7912070050	50-320 0 50-348 5 50-348 9 50-348 5 50-348 5	BRUGGE, R. D. BRUNNER, E. J.	7912190509 7912260010 7912200456 7912070200 7912200542	TOPREP 50-272 6 50-317 8 50-322 6 50-309 8	BURNETT, P. T. BURNETT, P. T. BURNETT, P. T. BURNETT, R. F. BURNETT, R. F.	7912180121* 7912210049* 7912210353* 7912070192* 7912070199*	50-302
BRADFORD, W. H. BRADFORD, P. A. BRADLEY, R. D. BRADLEY, R. D. BRADBHAN, J. L.	7912070063 7912280406# 7912210051 7912060669 7912130410	50-348 5 50-320 P 50-400 S 50-400 B 50-337 H	BRUNNER, E. J.	7912060662 7912030114 7912030104 7912180309 7912050331	50-27 6 50-286 8 50-245 9 50-245 8 50-387 0	BURBTEIN, N. M. BURBTEIN, S. BURBTEIN, B. BURBTEIN, B. BURBTEIN, B.	7912310031 7912110195 7912030172 7912040419 7912040486	REGOD PR 50-266 P 50-502 I 50-266 P
BRADSHAN, J. L. BRADY, E. BRAMLETT, L. S. BRAMLETT, L. S. BRANAGAN, D. R.	7912200370* 7912310113 7912170335* 7912260274* 7912130353*	50-337 A 50-522 D 50-313 R 50-313 B 50-320 U	BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J.	7912050088* 7912030241* 7912070132* 7912060214* 7912100197*	50-333 Q 50-272 Q 50-273 Q 50-334 Q 50-213 Q	BURSTEIN.S. BURSTEIN.S. BURSTEIN.S. BURSTEIN.S. BURSTEIN.S.	7912040247 7912180449* 7912120230 7912140422 7912180446	50-266 P 50-266 R 50-266 F 50-266 P 50-266 R
BRANAGAN, E. F. BRANDS, F. W. BRAUL, H. J. BREED, A. BRICHLEY, R. H.	7912130363* 7912100267 7912310513* 7912040213 7912140545*	50-320 U 50-27 F 50-255 P TOPREP GA999	BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J.	7912240118* 7912050179* 7912030059 7912040003 7912040048	50-213 G 50-247 G 50-272 G 50-307 G 50-272 G	BURSTEIN, 8. BURSTEIN, 8. BURSTEIN, 8. BURSTEIN, 8. BURSTEIN, 8.	7912260554 7912270206 7912280501 7912270492 7912280506	50-246 P 50-266 P 50-266 P 50-266 P 50-266 P
BRICKLEY, R. H. BRICKLEY, R. H. BRICKLEY, R. H. BRICGS, L. BRICGS, L.	7912110052* 7912260206* 7912100409* 7912030256* 7912200213*	GA779 GA779 GA779 50-219 G 50-219 G	BRUNNER; E. J. BRUNNER; E. J. BRUNNER; E. J. BRUNNER; E. J. BRUNNER; E. J.	7912210103* 7912200318* 7912050390 7912060191 7912100193	50-286 Q 50-220 Q 50-309 Q 50-334 Q 50-213 Q	DURT, L. BURT, L. BURT, L. BURT, L. BURT, L.	7912070142 7912070145* 7912070152* 7912110276 7912040481	50-471 Q 50-471 Q 50-471 Q 50-471 Q 50-471 Q
BATCHT, R. M. BATCHT, R. M. BROCKETT, J. BROCKETT, T. W. BROCBERY, N.	7912040441 7912040499 7912200298 7912200476 7912310078	50-302 P 50-302 P 1&E 50-273 9 90-9 0	BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J.	7912070123 7912030245 7912190787 7912200054 7912180270	50-293 Q 50-219 Q 50-213 Q 50-247 Q 50-271 Q	BURT, L. BURT, L. BURTON, L. D. BUSSELHAN, G. J.	7912110477 7912110460 7912310529 7912280461* 7912280240*	50-443 0 50-443 0 NUREO 50-320 H 50-244 P
SRODHAN, R. BROERL, D. J. BROERL, D. J. BROERL, D. J. BROERL, D. J.	7912280316# 7912120321# 7912180618 7912180127# 7912190379	90-320 H 50-344 9 50-344 9 50-344 9 50-344 P	BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J.	7912200206 7912200043 7912210357 7912310125 7912050164	50-217 G 50-272 G 50-244 G 50-284 G 50-284 G	DUTCHER, E. BUTZEL, A. K. BUTZEL, A. K. BUTZEL, A. K. BYRON, B. B.	7912190634 7912030451* 7912030447 7912030451* 7912120535*	PDR M18C 50-549 0 50-549 0 50-549 0 50-320 U

AUTHOR	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR	ACCESSION NUMBER	CATEGO!	₹Y	AUTHOR	ACCESSION NUMBER	BUBUECT' CATEGORY
CABA, E. CAHILL, W. J. CAHILL, W. J. CAHILL, W. J. CAHILL, W. J.	7912130375± 7912130215 7912190295± 7912190286± 7912190253±	50-346 90-3 FOIA FOIA FOIA	R G	CARBON, M. W. CARBON, M. CARBON, M. CARFACNO, S. P. CARLSON, R. T.	7912170107 7912100029 7912100034 7912120558 7912050072*	ACRB ACRB ACRB FOIA 50-443	a	CARR, J. C. CARR, J. C. CARR, J. C. CARR, J. C. CARR, J. C.	7912130310 7912140312 7912170394 7912170409 7912190422	FOIA FOIA FOIA FOIA FOIA
CAHILLAW.J. CAHILLAW.J. CAHILLAW.J. CAHILLAW.J. CAHILLAW.J.	7912190242* 7912190236* 7912190226* 7912190204* 7912050172*	FOIA FOIA FOIA FOIA 50-247	a	CARLEON, R. T. CARLEON, R. T. CARLEON, R. T. CARLEON, R. T. CARLEON, R. T.	7912060664* 7912060656= 7912060022 7912030045 7912030054	50-289 50-289 50-317 50-333 50-336	G G G G	CARR, J. C. CARR, J. C. CARR, J. C. CARR, J. C. CARR, J. C.	7912120485 7912130146* 7912120140 7912180648 7912170191	FOIA FOIA FOIA FOIA FOIA
CAHILL, W. J. CAHILL, W. J. CAHILL, W. J. CAHILL, W. J. CAHILL, W. J.	7912170186 7912060611 7912040465 7912040470 7912040466	50-3 PRM 50-247 50-247 50-247	G B P	CARLSON, R. T. CARLSON, R. T. CARLSON, R. T. CARLSON, R. T. CARLSON, R. T.	7912280286 7912260194 7912280330 7912050001 7912120142	50-287 50-397 50-320 50-296 50-482	8 9 9 9	CARR, J. C. CARR, J. C. CARR, J. C. CARR, J. C. CARR, J. C.	7912190096 7912170178 7912180131 7912180131 7912180131	FOIA FOIA FOIA FOIA
CAHILL, W. J. CAHILL, W. J. CAHILL, W. J. CAHILL, W. J. CAHILL, W. J.	7912130284 7912130291* 7912120465 7912130667 7912140410	50-3 50-3 50-247 50-247 50-247	P P S P S	CARLEON, R. T. CARLEON, R. T. CARLEON, R. T. CARLEON, R. T. CARLEON, R. T.	7912120175 7912140128 7912140533 7912050007 7912130454	50-311 50-311 50-311 50-333 50-354	5 5 6 9	CARR, J. C. CARR, J. C. CARR, J. C. CARR, J. C. CARR, J. C.	7912180116 7912180277 7912180302 7912180369 7912180380	FOIA FOIA FOIA FOIA
CAMILL, W. J. CAMILL, W. J. CAMILL, W. J. CAMILL, W. J. CAMILL, W. J.	7912180561 7912170245 7912170302 7912270232 7912270339	50-3 50-247 50-3 50-247 50-3	Р Я Р	CARLBON, R. T.	7912140042 7912280379 7912050062 7912130335 7912200521	50-412 50-320 50-443 50-387 50-423	8 Q S G	CARR, J. C. CARR, J. C. CARR, J. C. CARR, J. C. CARR, J. C.	7912190410 7912180409 7912190467 7912210394 7912210402	FOIA FOIA FOIA FOIA
CAHILL, M. J. CAHILL, M. J. CAHILL, M. J. GAHILL, M. J. CAHN, A. L.	7912270188 7912310303 7912310181 7912310403 7912170210*	50-247 50-247 50-3 50-247 50-482	ዋ ዋ ይ <b>3</b>	CARLEON, R. T.	7912200159 7912200466 7912210319 7912200449 7912260296	50-247 50-286 50-318 50-410 50-352	0 0 0 0 0	CARR, J. C. CARR, J. C. CARR, J. C. CARR, J. C. CARR, J. C.	7912280664 7912270028 7912280657 7912270032 7912270038	50-498 <b>0</b> Foia 50-193 r Foia Foia
Cain, a. l. Cain, c. l. Cain, c. l. Calcagno, l. Caldwell, w. e.	7712110580 7712280360* 7712316449* 7712280279* 7712170367*	REGOD 40-2259 40-4492 50-320 FOIA	н	CARLBON, R. T. CARLBON, R. T. CARLBON, R. T. CARLBON, R. T. CARLBON, R. T.	7912260051 7912060643 7912070144 7912310206 7912210019+	50-287 50-287 50-352 50-412 50-387	0 0 0 8 0	CARR, J. C. CARR, J. C. CARR, J. C. CARRIER, E. B. CARROLL, D. E.	7912280679 7912280685 7912270044 7912120276 7912190503	FOIA 50-358 <b>0</b> FOIA PDR MISC ORQ
CALDHELL, H. E. CALDWELL, R. A. CALHOUN, J. R. CALHOUN, J. R. CALHOUN, J. R.	7912190347* 7912050680* 7912070506 7912040301 7912040477	FOIA 50-128 71-9079 50-259 50-260	g S S	CARLEON, J. D. CARNEY, J. A. CARNEY, J. A. CARNEY, J. A. CARNEY, J. A.	7712050316# 7712130337 7712130361# 7712130366# 7712130378#	50~187 50~445 50~445 50~445 50~445	G Н Н Н	CARTER, R. A. CARTER, P. D. CARTER, D. CARTER, R. S. CARTER, R. S.	7912280192* 7912180544 7912050443 7912140135 7912100262	NUREO 50-208 J 40-8725 71-9853 50-184 F
CALHOUN, J. R. CALHOUN, J. R. CALHOUN, J. R. CALHOUN, J. R. CALHOUN, J. R.	7912180615 7912180623 7912870475 7912270564 7912270299	50-257 50-257 50-276 50-276 50-260	8 6 8	CARNEY, J. A. CARNEY, J. A. CARNEY, J. A. CARNEY, J. A. CARNEY, J. A.	7912270104 7912130337 7912130361* 7912130366* 7912130378*	50-445 50-445 50-445 50-445 50-445	м н н н	CARTER, H. L. CARTURIOHT, W. R. CARTURIOHT, W. R. CARTURIOHT, W. R. CARTURIOHT, W. R.	7912050280# 7912040316# 7912070386# 7912070388# 7912070409#	50-312 q 50-338 8 50-338 9 50-338 9 50-338 9
CALHOUN, J. R. CALHOUN, J. R. CALVARUBO, G. CAMFIELD, R. J. CAMPBELL, P.	7912280503 7912280509 7912280373= 7912060367 7912280470=	50-274 50-257 50-320 50-443 50-320	S S H H	CARNEY, J. A.	7912130337 7912130361* 7912130366* 7912130378* 7912130337	50-445 50-445 50-445 50-445 50-445	м м м м	CARTWRIGHT, W. R. CARTWRIGHT, W. R. CARY, C. N. CASCIATO, P. A. CASE, E. O.	7912120311* 7912180570* 7912310202 7912130332 7912170021	50~338 8 50~338 8 NUREO PRM 50~546 A
CAMPBELL, S. E. CAMDY, J. V. CAMDY, J. V. CAMFIELD, K. S. CAMFIELD, K. S.	7912260353* 7912050005 7912120137 7912130031 7912120046	50-373 NUREG NUREG PROJ PROJ	e e	CARNEY, J. A.	7912130361* 7912130366* 7912130337 7912130337 7912130361*	50-445 50-445 50-445 50-445 50-445	н н м н	CASE, E. O. CASE, E. O. CASE, E. O. CASE, E. O. CASE, E. O.	7912170026* 7912200068 7912200072* 7912200074* 7912200079*	50-546 A 50-266 0 50-266 0 50-266 0
CANNADY, F. X. CANNADY, F. X. CANRTELL, F. S. CANTRELL, F. S. CANTRELL, F. S.	7912120153* 7912120137* 79120400B9* 79122004B8 7912210039	40-8443 40-8443 50-544 50-390 50-516	Q S S	CARNEY, J. A. CARNEY, J. A. CARNLEY, J. B. CARR, H. CARR, B. E.	7912130366* 7912130378* 7912130553 7912190045* 7912060176*	50-445 50-445 50-271 50-275 CONTRACT	м м Р	CASE, E. Q. CASE, E. Q. CASE, E. Q. CASE, E. Q. CATCHPOLE, Q. J.	7912200642 7912200645* 7912270004 7912270008* 7912210186	50-329 0 50-329 0 50-329 0 50-329 0 40-8745
CANTRELL, F, 8. CANTRELL, F, 8. CANTRELL, F, 8. CANTRELL, F, 9. CANTRELL, F, 8.	7912070149 7912200471 7912040299+ 7912070067+ 7912030489*	50-439 50-424 50-390 50-390 50-327	5 9 9 9	CARR, J. C. CARR, J. C. CARR, J. C. CARR, J. C. CARR, J. C.	7912060558 7912060571 7912050635 7912070224 7912070263	FOIA FOIA 50-142 FOIA FOIA	Р	CATCHPOLE, Q. J. CATCHPOLE, G. J. CATTON, I. CATTON, I. CAVANAUGH, W.	7912130402 7912200616 7912190304* 7912180294 7912040187	40-8745 40-8745 ACRS ACRS 50-368 P
CANTRELL, F. S. CANTRELL, F. S. CAPHTON, D. L. CAPHTON, D. L. CAPHTON, D. L.	7912040594 + 7912240304 + 7912050395 + 7912050341 + 7912240122 >	50-553 50-327 50-309 50-387 50-213	a a a a	CARR, J. C. CARR, J. C. CARR, J. C. CARR, J. C. CARR, J. C.	7912070291 7912050471 7912170175 7912070229 7912070250	FOIA 70-2205 FOIA FOIA FOIA		CAVANAUGH, W. CAVANAUGH, W. CAVANAUGH, W. CAVANAUGH, W. CAVAZOB, E. C.	7912070424 7912130249 7912140327 7912210342 7912180255	50-368 P 50-313 P 50-313 P 50-313 P FOIA
CAPHTON, D. L.	7912050192* 7912070202* 7912060017* 7912200332* 7912310047*	50-247 50-322 50-307 50-220 50-318	0 0 0 0	CARR: J. C. CARR: J. C. CARR: J. C. CARR: J. C. CARR: J. C.	7912100480 7912170200 7912070181 7912100484 7912070266	FOIA FOIA FOIA 50-275 50-461	A A	CERNE, A. C. CHADWELL, H. M. CHADWELL, H. M. CHADWELL, H. M. CHALK, W. 8,	7912200457# 7912040430* 7912070356* 7912070377* 7912280608	50-410 9 50-316 9 50-316 9 50-315 9 50-137 8
CAPHTON, D. L. CARAGO, I. R. CARACO, I. R. CARBON, H. W. CARBON, M. W.	7912310058* 7912110041* 7912110024* 7912180522* 7912190375*	50-322 0A999 0A999 ACRS ACRS	a	CARR, J. C. CARR, J. C. CARR, J. C. CARR, J. C. CARR, J. C.	7912170181 7912180263 7912120538 7912170380 7912110086	FOIA FOIA FOIA FOIA		CHANANIA, F. D. CHANANIA, F. D. CHANANIA, F. D. CHANANIA, F. D. CHANANIA, F. D.	7912130236 7912110345 7912260081 7912260044 7912260361	50-445 H 50-230 H 50-445 H 50-445 H 50-445 H
CARBON, H. W. CARBON, H. W. CARBON, H. W. CARBON, H. W. CARBON, H. W.	7912170097 7912210049 7912170094 7912140544 7912170080	ACRS ACRS ACRS ACRS ACRS		CARR. J. C. CARR. J. C. CARR. J. C. CARR. J. C. CARR. J. C.	7912140174 7912140181 7912180282 7912180382* 7912120166	FOIA FOIA FOIA FOIA		CHANDLER, L. J. CHANDLER, L. J. CHANDLER, L. J. GHANDLER, L. J. CHANDLER, L. J.	7912280463 7912130030 7912070170 7912280319 7912280456	50-320 0 50-445 0 50-320 0 50-320 T 50-320 0

AUTHOR	NOW DEU VCC EASION	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CHANDLER, L. J. CHARNOFF, 9. CHARNOFF, 9. CHANDFF, 9. CHAUDHARY, 8. K.	7912200632 7912280459* 7912280459* 7912050087 7912280301*	50-445 H 50-320 0 50-320 0 50-266 0 50-320 0	CLEMONS, P. E. CLEMONS, P. E. CLEMONS, P. E. CLEVELAND, R. CLOUGH, R. L.	7912050662* 7912060240* 7912060110* 7912270129 7912310153	70-687 50-201 G 70-820 State Preg NUREG	COLLING, J. T. COLLING, J. T. COLOMBO, R. H. COLOMBO, R. H. COLOMBO, R. H.	7912280444 7912170381 7912070430* 7912110327* 7912180641*	50-320 P 27-47 50-312 S 50-312 S 50-312 S
CHECK, P. S. CHEN, J. C. CHESTER, R. O. CHIANGI, N. J. CHIANGI, N. J.	7912190060 7912180165 7912170174 7912130586 7912130448	50-193 P RES RES 50-241 S 50-400 S	CLOUTIER, R. COBB, J. M. COBB, L. I. COCHRAN, T. B. COCHRAN, T. B.	7912120325 7912310513* 7912100062* 7912170160 7912180265	50-277 P 50-255 P 50-286 P FOIA FOIA	COLOMBO, R. W. COLOMBO, R. W. COLOMBO, R. W. COLOMBO, R. W. COLOMBO, R. W.	7912170278* 7912140457* 7912180555* 7912260229* 7912260217*	50-312 R 50-312 8 50-312 8 50-312 8
CHIANGI, R. J. CHILDB, W. V. CHILDB, W. V. CHILDB, W. V. CHILDB, W. V.	7912280529 7912130454* 7912040313* 7912110282* 7912110329*	50-261 8 50-333 8 50-333 8 50-333 8 50-333 8	Cochran, T. B. Cochran, B. J. Coen, K. B. Coggin, C. L. Coggin, C. L.	7912270031 7912040299# 7912190245# 7912110323# 7912110372#	FOIA 50-390	COLOMBO, R. W. COLOMBO, R. W. COMBS, C. COMBS, T. R. COMPTON, R. M.	7912240283* 7912240277* 7912200198* 7912110089* 7912070112*	50-312 8 50-312 5 CONTRACT FOIA 50-280 G
CHILDS, M. V. CHILDS, M. V. CHILDS, M. V. CHILDS, M. V.	7912110347* 7912110359* 7912140449* 7912180599* 7912210322*	50-933 8 50-333 8 50-333 8 50-333 8 50-333 8	CD90IN, C. L. CD90IN, C. L. CD90IN, C. L. CDHEN, H. O, CDHEN, S.	7912130436* 7912270477* 7912310430* 7912180152 7912120170*	50-321 8 50-321 8 50-321 8 RES FOIA	COMPTON, R. M. CONGEL, F. J. CONGEL, F. J. CONLON, T. E. CONLON, T. E.	7912050622* 7912130353* 7912130363* 7912110247* 7912200621*	50-280 Q 50-320 U 50-320 U 50-370 Q 50-438 Q
CHILK, 8, J. CHILK, 8, J. CHILK, 8, J.	7912210336* 7912170395 7912060229 7912110099* 7912190012*	50-333 S 50-250 U 50-275 O FDIA 50-275 H	COHEN, H. W. COHEN, H. W. COHEN, H. W. COHEN, I. COHEN, I.	7912050232 7912180162 7912180193 7912200088 7912070273*	50-289 0 50-289 0 50-289 0 70-371 70-371	CONLON, T. E. CONLON, T. E. CONLON, T. E. CONLON, T. E. CONLON, T. E.	7912050596# 7912160367# 7912160174# 7912110334# 7912310331#	50-416 Q 50-387 Q 50-413 Q 50-400 Q 50-395 Q
CHILK, B. J. CHILK, B. J. CHILK, B. J. CHILK, B. J. CHILK, B. J.	7912130028* 7912100348* 7912200102 7912170019* 7912050168	PR 50-516 Q 50-522 Q 50-287 Q 50-522 Q	COHEN, I. COHN, N. D. COLE, R. F. COLEHAN, M. COLL, N. A.	7912240063* 7911190530* 7912310278 7912200322* 7912130050	70-820 50-322 0 50-312 0 50-339 A 50-250 0	CONLON, T. E. CONLON, T. E. CONNER, T. B. CONNER, T. B. CONNER, T. B.	7912310333* 7912210021* 7912130115 7912120361 7912260290	50-327 Q 50-348 Q 50-375 Q 50-416 Q 27-39
CHILK, B. J. CHILK, B. J. CHILK, B. J. CHILK, B. J. CHILK, B. J.	7912050439 7912040083 7912050059 7912050069 7912100336	50~275 9 50~320 P 50~522 0 50~280 0 50~402 0	COLL, N. A. COLL, N. A. COLLINS, B. H. COLLINS, V. P.	7912140014 7912130050 7912140014 7912030066 7912140161	50-250 0 50-250 0 50-250 0 XPORTLIC PR	CONNER, T. B. CONNETT, R. H. CONNELL, C. CONNELL, C.	7912210403 7912240290 7912240290 7912200349# 7912130115	50-375 0 27-37 PROJ 50-286 R 50-375 0
CHICM: 8. J. CHICM: 8. J. CHICM: 8. J. CHICM: 8. J. CHICM: 8. J.	7912100132 7912110356 7912190239 7912200517 7912260369	90-922	COLLINS; H. E. COLLINS; H. E. COLLINS; H. E. COLLINS; H. E. COLLINS; H. E.	7912040049 7912040065 7912170103 7912170004 7912170089	State Prog State Prog State Prog PDR MISC NUREQ	CONNER, T. B. CONSTABLE, I. CONSTABLE, Q. L. CONTE, R. J. CONWAY, W. F.	7712210403 7912200019 7912120204* 7912040082 7912110379	50-375 0 50-278 8 50-382 0 50-320 8 50-271 8
Chilk, B. J. Chilk, B. J. Chisholm, J. R. Chon, W. Y. Choules, N. C.	7912260365 7912260367 7912200175* 7912120144* 7912260105*	50-443 0 50-260 0 CONTRACT 50-57 Q 50-282 Q	COLLING, H. E. COLLING, H. E. COLLING, H. E. COLLING, H. E. COLLING, H. E.	7912170094 7912260263 7912310334 7912100379 7912100381	50-320 H State Prog State Prog State Prog State Prog	CONHAY, H. F. CONHAY, H. F. CONHAY, H. F. CONHAY, W. F. CONHAY, H. F.	7912110402* 7912110382 7912110385* 7912130379 7912130385*	50-271 8 50-271 8 50-271 8 50-271 8 50-271 8
CHON, E. T. CHRISTNAN, J. N. CHRISTNAN, J. N. CHRISTNAN, J. N. CHRISTNAN, J. N.	7912050036* 7912140148 7912140172 7912310343 7912120169	50-305	COLLING, H. E. COLLING, H. E. COLLING, H. E. COLLING, H. E. COLLING, H. E.	7912100382 7912110242 7912210056 7912280681 791228063	State Prog State Prog State Prog NUREO TOPREF	CONHAY, H. F. CONHAY, H. F. CONHAY, H. F. CONHAY, H. F. CONHAY, H. F.	7912180486 7912180489* 7912170326 7912170329* 7912270332	50-271 S 50-271 S 50-271 S 50-271 S 50-271 S
CHRISSOTINGS, N. CIANE, F. CIESZKIENICZ, S, CLARKE, E. T. CLARK, L.	7912180084 7912030120 7912180386* 7912310012 7912060146#	50-254 8 40-8677 50-10 R REGOD 50-20 Q	COLLING. H. E. COLLING. H. E. COLLING. H. E. COLLING. H. E. COLLING. H. E.	7912310484 7912200415 7912210119 7912240123 7912260624	State Prog 50-3 P TOPREP State Prog State Prog	CONMAY, M. F. COOK, J. F. COOKEY, H. J. COOKEY, H. J. COOKEY, W. J.	7912270336* 7912140309 7912110223* 7912190799* 7912180092*	50-271 B REB 50-295 R 50-255 G 70-754
CLARME, N. L. CLARM, N. H. CLARM, A. T. CLARM, R. CLAYTON, F. L.	7912110532* 7912270262* 7912130149 7912140162 7912170006	50-295 0 50-259 P PRGJ 50-277 P 50-364 0	COLLING H. E. COLLING H. E. COLLING J. T. COLLING J. T. COLLING P. F.	7912170111 7912190101 7912040082 7912180051 7912120532#	8tate Prog 8tate Prog 50-320 8 50-320 8 50-320 U	COOLEY, M. J. COONEY, M. J. COONEY, M. J. COONEY, M. J.	7912180467# 7912040295 7912040405 7912070349 7912120343	0A999 50-278
CLAYTON F. E. CLAYTON F. L. CLAYTON F. L. CLAYTON F. L. CLAYTON F. L.	7912100084 7912030183 7912140473 7912140531 7912040369	71-5026 50-340 8 50-348 0 50-349 0 50-340 8	COLLING. P. F. COLLING. P. F. COLLING. P. F. COLLING. P. F. COLLING. H.	7911020180 7912170102 7912240188 7912270017 7912200022	50-275 V NUREO 50-83 P 50-73 P 50-3 F	COONEY, M. J. COONEY, M. J. COONEY, M. J. COONEY, M. J. COONEY, M. J.	7912120347* 7912120429 7912120435* 7912140455 7912140463*	50-277 S 50-277 S 50-277 S 50-277 S 50-277 S
CLAYTON F. L. CLAYTON F. L. CLAYTON F. L. CLAYTON F. L. CLAYTON F. L.	7912110335 7912310025 7912120426 7912180397 7912210170	50-346 8 50-348 0 50-348 8 50-348 P 50-348 0	COLLING, J. T. COLLING, J. T. COLLING, J. T. COLLING, J. T. COLLING, J. T.	7912040084 7912040095 7912280466 7912040060 7912040077	50-320 P 50-320 P 50-320 H 50-320 H 50-320 P	COONEY, M. J. COONEY, M. J. COONEY, M. J.	7912180586 7912180591* 7912140344 7912180644 7912180647*	50-278 8 50-278 8 50-277 R 50-277 8 50-277 8
CLAYTON F. L. CLAYTON F. L. CLAYTON F. L. CLAYTON F. L. CLAYTON F. L.	7912310274 7912180405 7912210010 7912180342 7912190350	50-348 9 50-348 P 50-348 9 50-348 P 50-348 F	COLLINS, J. T.	7912040101 7912040116 7912040063 7912040070 7912040056	50-320 H 50-320 P 50-320 H 50-320 P	COONEY, M. J. COONEY, M. J. COONEY, M. J. COOPER, P. COOPER, J. H.	7912180558 7912270497 7912270510* 7912180480* 7912050157*	50-278 8 50-278 8 50-278 8 50-275 U
CLAYTON F. L. CLAYTON F. L. CLAYTON F. L. CLAYTON F. L. CLAYTON F. L.	7912310015 7912190856 7912270386 7912310424 7912270212	50-344	COLLINS, J. T.	7912040067 7912040090 7912280351 7912280362 7912310554	50-320 P 50-320 R 50-320 P 50-320 P 50-320 H	COOPER.D.W. COOPER.J. COOPERSTEIN.R. COOPERSTEIN.R. COOPERSTEIN.R.	7912140517* 7912100275* 7912170113 7912120093 7912180100	REB 50-302 9 40-8436 40-8304 40-8304
CLAYTON, F. L. CLAYTON, E. D. CLEARY, P. CLEMENT, C. H. CLEMENBON, F.	7912310448 7912200015* 7912110224 7912070385* 7912170237*	50-349 8 71-4581 NUREO 50-334 8 50-344 0	COLLINS, J. T. COLLINS, J. T. COLLINS, J. T. COLLINS, J. T. COLLINS, J. T.	7912310555 7912280369 7912280453 7912280418 7912280430	50-320 H 50-320 P 50-320 P 50-320 F 50-320 P	COPELAND, J. O. COPELAND, J. O. COPELAND, J. O. COPELAND, J. O. COPELAND, J. O.	7912140168 7912140525 7912170246 7912170471 7912120056	50-466 0 50-466 0 50-466 0 50-466 0

AUTHOR	ACCESSION NUMBER	SUBJEC CATEGO		AUTHER	ACCESSION NUMBER	SUBJE CATEG		AUTHOR	ACCESSION NUMBER	9UDJE CATEG	
COPELAND, J. G. COPELAND, J. G. COPELAND, J. G. COPELAND, J. G. COPELAND, J. G.	7912120067* 7912170046 7912140005 7912140008 7912260286	50-466 50-466 50-466 50-466 50-466	G G G	COYNE, M. J. COYNE, M. J. COYNE, M. J. COZZUGL, J. M. CRAIG, R. W.	7912280677 7912030041 7912210064 7912170194 7912100452*	XPORTL XPORTL XPORTL RES CONTRA	IC C	CROUSE, R. P. CROW, W. T. CROW, W. T. GROW, W. T. CROW, W. T.	7912310480 7912070299* 7912070276* 7912130484 7912130527*	50-346 FOIA FOIA 70-115 70-115	ı
COPELAND, R. L. COPELAND, R. L. COPELAND, R. L. COPELAND, J. 9. COPELAND, J. 9.	7912110554 7912310177 7912200578 7912140168 7912140525	REGGD REGGD 50-537 50-466 50-466	A G G	CRAINICH, V. A. CRAINICH, V. A. CRAMER, E. N. GRANE, P. A. CRANE, P. A.	7912190794* 7912190789 7912130255 7912050360* 7912050364*	XPORTL XPORTL PR 50-133 50-133		CROW, W. T. CROW, W. T. CROW, W. T. CROW, W. T. CROW, W. T.	7912130445 7912180239 7912200225 7912260103 7912260106#	70-34 70-1110 70-1257 40-2061 40-2061	7
COPELAND, J. O. COPELAND, J. O. COPELAND, J. O. COPELAND, J. O. COPELAND, J. O.	7912170246 7912100471 7912120056 7912120067* 7912140032	50-466 50-466 50-466 50-466 50-466	6 6 6	CRANE, P. A.	7912050349* 7912140497* 7912270070* 7912190002* 7912030038	50-133 50-275 50-275 50-133 50-275	G G G G	CROWLEY, C. J. CROWLEY, B. R. CROWLEY, B. R. CROWLEY, B. R. CROWLEY, J. A.	7912310202 7912060486* 7912050532* 7912260151* 7912140144*	NUREQ 50-327 50-349 50-327 PR	0 0 9
COPELAND, J. G. COPELAND, J. G. COPELAND, J. G. COPELAND, J. G. COPPOLA, A.	7912170046 7912140005 7912140008 7912260286 7912100001	50-466 50-466 50-466 50-466 RES	6 6 6 6	CRANE, P. A. CRANE, P. A. CRANE, P. A. CRANE, P. A. CRANE, P. A.	7912040498 7912110322 7912120317 7912130271 7912190614	50-275 50-275 50-275 50-275 50-275	A A A Q	GRUMLEY, J. A. CBALA, Q. P. CULVER, J. C. CULVER, M. W. CUMMINOB, B. C.	7912140147 7912180056 7912120279* 7912180398* 7912180484*	PR 50-387 F01A 50-302 50-275	Q R U
CORBETT, J. S. CORDANI, R. A. CORYELL, Q. CORYELL, Q. P. COSTELLO, D. J.	7912180095 7912200030 7912310315 7912110544* 7912140338*	71-6275 71-88 1&E 70-27 50-280	R	CRANE, P. A. CRANSTON, A. CRANSTON, A. CREED, J. R. CREED, J.	7912050356* 7912120049* 7912210133* 7912180045 7912120068	50-133 PDR MIS 50-275 50-358 50-10	6 GC U S S	CUNNINGHAM, J. D. CUNNINGHAM, J. D. CUNNINGHAM, J. D. CUNNINGHAM, Q. E. CUNNINGHAM, A. L.	7912050180 7912180246 7912180246 7912140243 7912050666#	50-269 50-289 50-289 50-70 50-566	0 0 P 0
COSTELLO, F. COSTELLO, F. COSTELLO, J. R. COSTELLO, J. R. COTA, P. C.	7912310121 7912310329 7912170398* 7912110516* 7912120072	1&E 1&E 0A999 0A999 50-382	A	CREED, J. R. CREED, J. R. CREEK, L. CREMER, S. CREWS, E. H.	7912180331 7912120065* 7912060032 7912160267 7912110049	50~483 50-305 70-1308 ACR8 50~375	g G G	CUNNINGHAM, A. L. CUNNINGHAM, A. L. CUNNINGHAM, R. E. CUNNINGHAM, R. E. CUNNINGHAM, R. E.	7912210088# 7912310086# 7912170075 7912170078* 7912210430#	50-269 50-389 40-6940 40-6940 FOIA	
COTA, P. C. COTNER, M. L. COTTLE, W. T. COTTLE, W. T. COUNSIL, W. G.	7912100130 7912050464 7912050628* 7912180130* 7912100196*	50-416 50-514 50-327 50-327 50-213	A D Q Q	CREWS, E. H. CREWS, E. H. CREWS, E. H. CREWS, E. H. CREWS, E. H.	7912130433 7912130568 7912030145 7912140360 7912140358	50-395 50-395 50-395 50-395 50-395	9 % 8 8	CURNANE; R. A. CURRAN, J. M. CURRAN, J. M. CURRAN, J. M. CURRAN, J. M.	7912170387* 7912040473* 7912030176 7912040408* 7912180532*	6A999 50-204 50-206 50-206 50-206	8 6 8
COUNSIL, W. G. COUNSIL, W. G. COUNSIL, W. G. COUNSIL, W. G.	7912260116# 7912140285 7912210109 7912170244 7912030173	50-213 50-213 50-213 50-213 50-213	0 0 0 P	CREMB, E. H. GREWS, E. H. CREWS, E. H. CREWS, J. L. GREWS, J. L.	7912280610 7912280532 7912210166 7912310104 7912310132	50-395 50-395 50-395 50-344 50-206	5 F 9 9	CURRAN, J. M. CURRAN, J. M. CURRAN, J. M. CURRAN, J. M. CURRY, J. J.	7912110212 7912170293* 7912170314* 7912180617* 7912180525	50-206 50-206 50-206 50-206 50-272	R 8 8
COUNSIL, W. O. COUNSIL, W. G. COUNSIL, W. G. COUNSIL, W. G. COUNSIL, W. G.	7912040306 7912070400 7912180248 7912180478 7912170294	50-213 50-213 50-213 50-213 50-213	P P P P	CREWB, J. L. CREWS, J. L. CREWS, J. L. CREWS, J. L. CREWS, J. L.	7912050272 7912040112 7912040090 7912070179 7912050094	50-312 50-344 50-275 50-89 50-206	0 0 0 0 0	CURTIS, A. E. CURTIS, N. W.	7912190521* 7912130347# 7912120019 7912140275 7912260333*	50-244 50-387 REGOD 50-387	6 9 9
COUNSIL, W. G. COUNSIL, W. G. COUNSIL, W. G. COUNSIL, W. G. COUNSIL, W. G.	7912180476 7912210288 7912270403 7912270589 7912140257	50-213 50-213	P P P Q	CREWS, J. L. CREWS, J. L. CREWS, J. L. CREWS, J. L. CREWS, J. L.	7912050312 7912180479 7912190001 7912190042 7912280671	50-197 50-206 50-133 50-312 50-344	0 0 0 0 0	CURTIS, N. W.	7912040351 7912040507 7912050506 7912140265 7912120384	00-387 50-387 50-387 50-387 50-387	8 9 9 K
COUNSIL. H. G. COUNSIL. H. G. COUNSIL. H. G. COUNSIL. H. G.	7912140022 7912140287 7912140227 7912120027 7912170228	50-336 50-423 REGOD	Q Q A Q	CROCKER, J. G. CROCKER, J. G. CROCKER, J. G. CROCKER, H. H. CROCKER, H. W.	7912140468* 7912140805* 7912140461* 7912040179* 7912060674	RES RES RES 50-320 70-1143	a	CURTIS, N. W. CURTIS, N. W. CURTIS, A. E. CURTIS, J. R. CURTIS, J. R.	7912270245 7912270298 7912270442* 7912050693* 7912060031*	50-397 50-397 50-244 50-94 50-147	A B C C
COUNSIL, H. G. COUNSIL, H. G. COUNSIL, H. G. COUNSIL, H. G.	7912130113 7912130383 7912180487 7912080504 7912030206	50-245 50-336 50-245	0 0 0 P P	CROCKER, H. W. CROCKER, H. W. CROCKER, H. W. CROCKER, H. W. CROKE, D.	7912050108* 7912070113* 7912310320* 7912120353* 7912280304*	70-1143 70-697 70-820 70-1143 50-320	н	CUTCHIN, J. M. CUTCHIN, J. M. CUTHBERTBON, R. CYPHERT, B. B. CYPHERT, S. B.	7912190129 7912210014 7912270116 7912100307 7912120043	50-387 50-387 71-5939 50-445 50-445	0 0 H
COUNSIL, W. C.	7912040225 7912050502 7912040505 7912190261 7912110305	50-336 50-213 50-213	P <del>P</del> P P F	CROSS, L. A, CROSS, J. L, CROSSMAN, H, CROSSMAN, H, CROSSMAN, H,	7912310110 7912140273 7912200448 7912200454 7912200080	REGOD 50-259 50-482 50-482 50-482	ድ 8 8	CYPHERT, B. B. CYPHERT, B. B. CYPHERT, S. B. CYR, K. DAHLOREN, D. A.	7912170068 7912270123 7912310137 7912210097 7912140499#	50-445 50-445 50-445 PR RES	H H
COUNSIL, H. O.	7912100284 7912120390 7912130542 7912130321 7912130455	50-213 TOPREP 50-213 50-213	P P F	CROSSMAN, W. A. CROSSMAN, W. A. CROSSMAN, W. A. CROSSMAN, W. CROSSMAN, W.	7912200091 7912050473* 7912050531* 7912200085 7912210037	50-482 50-482 50-382 50-482 50-482	8 0 8 8	DAHLMAN, L. DAIL: L. C.	7912070440* 7912110584 7912210145* 7912130088 7912270496	50-282 REQQD 50-491 50-491 50-480	a a a A
COUNSIL, W. O. COUNSIL, W. O. COUNSIL, W. O. COUNSIL, W. G.	7912190409 7912180279 7912210148 7912210187 7912210282	50-334   50-334   50-334	P P F P	CROSSMAN, W. CROSSMAN, W. CROSSMAN, W. A. CROSSMAN, W. A. CROSSMAN, W.	7912240090 7912060598 7912060470 7912280329* 7912200560	50-492 50~438 50-498 50-498 50-482	8 8 9 9	DALE, L. F. DALE, L. F. DALE, L. F. DALE, L. F. DALE, L. F.	7912190603 7912130524 7912130528 7912190611 7912190633	50-416 50-416 50-416 50-416 50-416	5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5
COUNSIL, H. G. CDUNSIL, H. G. CDUNSIL, H. G. CDUNSIL, H. G. CDUNSIL, H. G.	7912260276 7912270293 7912280004 7912270318 7912310376	50-245   50-334   50-213   50-245	P P P	CROSSMAN, W. A. CROUSE, R. P. CROUSE, R. P. CROUSE, R. P. CROUSE, R. P.	7912180119 7912130210 7912210147# 7912190127 7912190402	50-482 50-346 50-346 50-346 50-346	8 0 0 0 P	DALE, L. F. DALE, L. F. DALE, L. F. DALTON, J. N. DALTON, J.	7912190702 7912100939 7912190555 7912190596 7912130603*	50-414 50-414 50-416 PR PR	B C H
COUNSIL, H. G. COUNSIL, H. G. COURTNEY, J. H. COHAP, C. COX, J. N.	7912310380 7912310543 7912210337 791221030066 7912130066		3	CROUSE, R. P.	7912180584 7912280643 7912190433 7912180505 7912310443	50-346 50-346 50-346 50-346 50-346	P G P P	DALTROFF, 8. L.	7912060044* 7912050105* 7912170240 7912280031 7912180606	50-277 50-277 50-277 50-277 50-277	0 0 0 P

AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION MANUER	SUBJECT CATEGORY
DAL TROFF, S. L. BANG, R. H. BANGE, R. G. BANGE, R. G. BANGE, R. G.	7912280561 7912130089 7912180299 7912210060 7912260019	50-277 P NUREC 50-294 S 50-325 S 50-325 S	DELONG, S. D.  BELDRENZD, F.  DENISE, R. P.  DENISE, R. P.  DENISE, R. P.  DENISH, H. R.	7912170257* 7912130381* 7912120112 7912140253 7912130020*	S0-315 S GA999 TOPREP REVIEW GRP 50-302 U	DENTON, H. R. DENTON, H. R. DENTON, H. R. DENTON, H. R. DEPOLY, V. P.	7912310002 7912310004* 7912310240 7912280634 7912030075	50-204 ¢ 50-204 ¢ 50-320 H 50-317 P XPORTILIC
DANCE, H. C. DANCE, H. C. DANCE, H. C. DANCE, H. C. DANCE, H. C.	7912050620= 7912060673* 7912050631= 7912050379* 7912160130=	50-327 0 50-302 G 50-327 0 50-259 0 50-327 0	DENTON, H. R.	7912040086+ 7909180006 7912130025 7912130036 7912130065	50-320 P 50-320 H PR PR PR PR	DERMYER, W. D. DERMYER, W. D. DEUKKEJIAN, G. DEVINE, J. F. DEVINE, J. F.	7912120013 7912210065 7912060166 7912190791 7912140423*	REGGD REGGD PROJ 50-206 P RES
Dance, H. C. Danielson, L. J. Danielson, L. J. Daniel, K. H. Daniel, U. C.	7912310318= 7912060603 7912060675 7912200351= 7912200328=	50-390 Q PROJ PROJ 50-339 A 50-339 A	DENTON, H. R.	7912130077 7912110264 7912040148* 7912130371* 7912210013*	PR 50-275 A 50-320 P 50-320 U 50-262 P	DEVINE, J. C. DEVINCENTIS, J. DEVINCENTIS, J. DEVINCENTIS, J. DEVINCENTIS, J.	7912040104 7912050070* 7912120513 7912140231 7912120464	50-320 P 50-443 Q 50-443 G 50-443 A 50-443 S
DAN I ELBON, D. H. DAN I ELBON, D. H. DAN I ELBON, D. H. DAN I ELBON, D. H. DAN I ELBON, D. H.	7912310115# 7912130087# 7912200174# 7912200589# 7912180346	50-281 9 50-331 0 50-263 0 50-454 0 50-295 8	DENTOR, H. R. DENTON, H. R.	7912260315* 7911190148 7912200411 7912190733 7912170009	50-289 P 50-3 P 50-220 P PDR NISC 50-289 G	DEVINCENTIS, J. DEVINCENTIS, J. BEVLIN, J. H. DEVLIN, J. H. DEVLIN, J. H.	7912120486 7912140363 7912200552 7912200575 7912200567	50-443 5 50-443 5 50-334 5 50-247 8 50-334 5
Dan I Elson, D. H. Dan I Elson, D. H. Dan I Elson, D. H. Dankheyer, T. R. Darby, C.	7912050011= 7912030257* 7912050022= 7912030071 7912130289	50-440 Q 50-329 Q 50-341 Q 50-574 A PR	DENTON, H. R.	7912160419 7912116038 7912130058 7912176038 7912176034	50-336 H 50-3 Q 50-275 Q 50-275 A 50-275 A	DEVLIN, J. W. DEVLIN, J. W. DEVLIN, J. H. DEVLIN, J. DEVLIN, J. H.	7912200490 7912200494 7912200073 7912180041 7912040129*	50-247 S 50-247 S 50-247 S 50-213 S 50-334 0
DARMITIEL, R. M. DAUGHERTY, C. E. DAVIDSON, D. R. DAVIDSON, D. R. DAVIDSON, D. R.	7912140365# 7912170144# 7912040223 7912060084# 7912050519	50-70 P 719007 50-440 G 50-440 G 50-440 S	DENTON, H. R. DENTON, H. R. DENTON, H. R. DENTON, H. R. DENTON, H. R.	7912200159 7912180660 7912190102 7912190082 7912200204	50-275	DEVLIN, J. N. DEVLIN, J. N. DEVLIN, J. N. DEVLIN, J. N.	7912100215* 7912060664* 7912200478* 7912260119* 7912050262*	50-220 0 50-289 6 50-29 0 50-277 0 50-273 0
DAVIDBON.D.R. DAVIDBON.J.J. DAVIES.J.H. DAVIB.C. DAVIB.W.K.	7912140364 7912130075 7912180156* 7912070255 7912210347	50-440 S NUREO FDIA FDIA TOPREP	DENTONS H. R.	7912310195 7912190132 7912190391 7912280264 7912280274	ORC FDR MISC 50-289 H 50-320 H 50-320 H	DEVLIN. J. W. DEVLIN. J. DEVLIN. J. W. DEVEY, L. S.	7912050086* 7912070091* 7912100057* 7912260071* 7912110345	50-184 @ 70-2756 70-820 70-1143 50-250 H
DAVIS.C.S. DAVIS.P.L. DAVIS.J.P. DAVIS.J.P. DAVIS.L.D.	7912190570 7912070492= 7912140127 7912140158 7912060109	RES CONTRACT 50-284 H 50-3 H 50-275 Q	DENTON, H. R.	7912280288 7912280298 7912280309 7912280320 791228032 <i>b</i>	50-320 H 50-320 H 50-320 H 50-320 H 50-320 H	DEMITTAR. B. DIAZAR. J. DICAAF. DICKERSON M. N. DIDESCH. T. E.	7912060535* 7912210058* 7912280293* 7912120223* 7912310501*	50-255
DAVIS, L. D. DAVIS, L. D. DAVIS, L. D. DAVIS, J. O. DAVIS, J. O.	7912050161 7912050025 7912140006 7912070289* 7912280658#	50-275	DENTON: H. R.	7912280332 7912280340 7912280353 7912280367 7912280378	50-320 H 50-320 H 50-320 H 50-320 H 50-320 H	DIECKAMP, H. DIETZ, D. R. DIGGS, R. M. DIGGS, R. M. DIGGS, R. M.	7912260477 7912050002 7912130177 7912190510 7912190164	50-209 T NUREG 50-445 A 50-266 P 50-321 P
DAV18, J. G. DAV18, J. B. DAV18, A. B. DAV18, A. B. DAV18, A. B.	7912120554* 7912310321 7912200663 7912190799* 7912200473	50-313 0 1&E 1&E 50-255 0 1&E	DENTON, H. R. DENTON, H. R. DENTON, H. R. DENTON, H. R. DENTON, H. R.	7912280388 7912280399 7912280415 7912280433 7912280445	50-320 H 50-320 H 50-320 H 50-320 H 50-320 H	Diggs, R. M. Diggs, R. M. Diggs, R. M. Diggs, R. M. Dignan, T. G.	7912200618 7912200630 7912200094 7912200672 7912170053	50-250 F 50-261 P 50-302 F 50-254 F 50-307 0
DAVIS.A.B. DAVIS.A.B. DAVIS.A.B. DAVIS.A.B. DAVIS.A.B.	7912180103 7912050482± 7912050073 7912070264 7912040013	18E 70-2205 50-264 0 50-10 0 70-925	DENTON: H. R.	7912280452 7912280457 7912280460 7912280462 7912280468	50-320 H 50-320 H 50-320 H 50-320 H 50-320 H	DIGNAN, T. O. DIGNAN, T. C. DIGNAN, T. C. DINEGLIO, A. F. DINEGLIO, A. F.	7912180028 7912170053 7912180028 7912130522 7912130531	50-309 6 50-309 6 50-309 0 50-193 8 50-193 8
DAVIS.A.B. DAVIS.A.B. DAVIS.A.B. DAVIS.J.O. DAVIS.J.O.	7912030219 7912240074 7912130344 7912190323* 7912190313*	50-186 G 50-266 G 50-264 G FOIA FOIA	DENTON, H. R.	7912280472 7912280478 7912280481 7912280484 7912280510	50-320 H 50-320 H 50-320 H 50-320 H 50-320 H	DIMEGLIO, A. F. DIPIAZZA, R. P. DIPIAZZA, R. P. DIRCKS, N. J. BIRCKS, W. J.	7912190590 7912180304 7912206023 7912120044* 7912070206*	50-193 S 71-5395 70-1143 PDR HISC FOIA
DAV 18, J. O. DAV 18, J. O. DAV 18, J. O. DAY, B. D. DEALE, V. B.	7912190301* 7912190289* 7912190257* 7912270580* 7912060150	FDIA FDIA FDIA 50-263 8 50-522 0	DENTON, H. R.	7912280516 7912280534 7912280543 7912280553 7912190526	50-320 H 50-320 H 50-320 H 50-320 H NUREO	DIRCKS, M. J. DIRCKS, M. J. DIRCKS, M. J. DIRCKS, M. J. DISE, D. P.	7912070186* 7912180300 7912200087 7912280033 7912040462	FOIA State Prog SECY 71-6698 50-220 P
DEALE, V. B. DEALE, V. B. DEALE, V. B. DEALE, V. B. DEALE, V. B.	7912110407 7912140117 7912270090 7912270106 7912310207	50-522 0 50-522 0 50-522 0 50-522 0 50-522 0	DENTON, H. R. DENTON, H. R. DENTON, H. R. DENTON, H. R. DENTON, H. R.	7912190530 7912190536 7912190538 7912190540 7912200603	50-311	DISE, D. P. DISE, D. P. DISE, D. P. DISE, D. P. DISE, D. P.	7912040277 7912040469 7912050492 7912040315 7912040346	50-220 Q 50-220 P 50-220 P 50-220 P 50-220 P
DEARTEN, J. A. DEARTEN, J. A. DEB, B. DEEDS, W. E.	7912140468* 7912140505* 7912140461* 7912200381 7912140206	RES RES RES TOPREP MIREQ	DENTON, H. R. DENTON, H. R. DENTON, H. R. DENTON, H. R. DENTON, H. R.	7912310222 7912190919 7912210438 7912210441# 7912260347	PDR H15C 50-568 H 50-155 C 50-155 C 50-373 C	DISE, D. P. DISE, D. P. DISE, D. P. DISE, D. P. DISTEFANG, J.	7912180547 7912180539 7912210377 7912270379 7912130450	50-220 P 50-220 F 50-220 P 50-220 P PR
DELAND, F. H. DELEEUN, M. L. DELGEORGE, L. O. DELGEORGE, L. O. DELLUNG, R. V.	7912110198 7912190531# 7912050501 7912100313 7912070256	PR PBR MISC 50-373 B 50-373 A 50-70 0	DENTON: H. R. DENTON: H. R. DENTON: H. R. DENTON: H. R. DENTON: H. R.	7912250350* 7912250351* 7912200634 7912290125 7912270012		DOAN, P. F. BOAN, P. F. DODD, C. V. DODDS, R. T. DODDS, R. T.	7912310450* 7912310444* 7912140206 7912190745 7912110493*	50-278 S 50-278 S NAREC 50-460 S 50-508 Q
DELLINO, R. D. DELCINO, S. D. DELCINO, S. D. DELCINO, S. D. DELCINO, S. D.	7912060606 7912040390+ 7912040370+ 7912130372+ 7912170252+	PROJ 50-315 S 50-316 S 50-315 S 50-315 S	DENTON, H. R.	7912270068 7912280600 7912200061 7912280620 7912310171	50-244 H 50-275 H 50-320 H 100FR 50-266 P	DODDS, R. T. DODDS, R. T. DODDS, R. T. DODDS, R. T. DODDS, R. T.	7912130723* 7912120505* 7912060025* 7912060047* 7912060065*	50-361 0 50-508 0 50-361 0 50-528 0 50-275 0

AUTHOR	ACCESSION MANUER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
DOGETT, S. A. DOGETT, S. A. DOGGETT, S. A. DOGGETT, S. A. DOGGETT, S. A. DOGGETT, S. A.	7912310168 7912310168 7912280631 7912310170* 7912310178*		DUFF, J. B. DUFFEY, T. A. BUFFY, J. P. DUBLETON, D. DUNBAR, J.	7912180579 7912140526 7911190354 7912280385 7912270265	≠ NURE¢ * 50-320 H	ECHODOM, M. 8. ECKHARDT, J. H. ECONOHOS, N. ECONOHOS, N. ECONOHOS, N.	7912200029* 7912060047* 7912110214* 7912050438* 7912310287*	71-6581 50-528 g 50-387 g 50-400 g 50-438 g
DOGGETT, S. A.	7912310183+ 7912280631 7912310170+ 7912310183+ 7912310183+	50-466 0 50-466 0 50-466 0 50-466 0 50-466 0	DUNCAN, M. DUNCAN, M. DUNCAN, M. DUNCAN, M. DUNCAN, M.	7912190773 7912190777 7912200109 7912270061 7912270065	50-438 C 50-387 C 50-361 C 50-395 C 50-397 C	EDDLEMAN, W. EDMARDS, D. R. EDMARDS, D. R. EDWARDS, D. R. EDWARDS, D. W.	7912120224 7912040267 7912200364 7912200452 7912180470	50-400 0 50-123 P 50-123 F 50-123 P 50-309 P
DOVERTY, J. F. DOVERTY, J. F. DOVERTY, J. F. DOVERTY, P. J. DOLAN, J. E.	7912130054 7912170001 7912170002 7912190601* 7912170018	50-466 Q 50-466 Q 50-466 Q TOPREP 50-315 P	DUNCAN, M. DUNCAN, M. DUNCAN, M. DUNCAN, M. DUNN, N. M.	7912270081 7912200098 7912200104 7912200656 7912200116	50-580 C 50-522 C 50-322 C 50-594 C 71-96	eherto, R. F. Ehlerg, R. J. Ehrensperoer, W. Ehrensperoer, W. Ehrensperoer, W.	7912180469# 7912200011# 7912100139 7912040448 7912210344#	50-317 B 71-4581 50-321 H 50-424 A 50-424 B
DOLAN; J. E. EOLAN; J. E. DOLAN; J. E. DOLAN; J. E. DOLAN; J. E.	7912040254 7912040404 7912200036 7912110308 7912110312	50-316 P 50-316 P 50-315 Q 50-315 P 50-315 P	DURNI, C. N.	7912040105: 7912060205: 7912170164 7912100224: 7912040269	50-334 0 50-334 0	EHRENBPEROER, W. EHRENSPEROER, W. EHRENSPEROER, W. EIDEM, M. E. EIKUM, R. L.	7912140236 7912210340 7912280485 7912110366* 7912060032	50-424 A 50-424 B 50-424 A 50-285 B PROJ
DOLAN, J. E. DOLAN, J. E. DOLAN, J. E. BOLAN, J. E. DOLAN, J. E.	7712120404 7912180390 7912180436 7912190560 7912270431	50-315 P 50-315 P 50-316 P 50-315 P 50-315 P	DUNN, C. N. DUNN, C. N. DUNN, C. N. DUNN, C. N. DURN, C. N. BUNN, C. N.	7912040379 7912050465 7912100305 7912120312 7912280002	50-334 P 50-334 P 50-334 P 50-334 Q 50-334 Q	EILPERIN, B. F. EISENHAUER, C. EISENHAUT, D. Q. EISENHAUT, D. Q. EISENHAUT, D. Q.	7912280459# 7912040109 7912180253# 7912130017# 7912190051	50-320 g 50-320 p PDR HISC 50-302 U DRO
DOLAN, J. E. DOLAN, J. E. DOLAN, J. E. DOLAN, J. E. DOLAN, J. E.	7912200509 7912270258 7912070109 7912200687 7912040489	50-314 P 50-315 P 50-315 Q 50-315 Q 50-315 P	DURN, C. N. DURN, C. N. DURN, C. N. DURN, C. N. DURN, D. R.	7912180362 7912270354 7912270456 7912270370 7912050005	50-334 R 50-334 P 50-334 P 50-334 P NUREO	EIGENAUT, D. Q. EISENAUT, D. Q. EISENAUT, D. Q. EIGENAUT, D. Q. EISENAUT, D. Q.	7912100171 7912310218 7912370077# 7911090248# 7912070038#	50-200 P ORG CDHNISSION 50-3 P 50-275 A
DOLAN; J. E. DOLAN; J. E. DONAHUE; J. F. DONAHUE; J. F. DONAHUE; J. F.	7912040257 7912270604 7912030105 7912180045 7912120068	50-315 P 50-315 1 50-461 B 50-358 8 50-10 8	DURNING, D. E. DURRE, B. A. DURR, J. P. DUTTON, D. DYBCZAK, Z. N.	7912110442 7912140326* 7912060026* 7912170301 7912040491	NUREO REG 50-317 0 50-424 8 50-404 A	Eibenhut, D. G. Eibenhut, D. G. Eibenhut, D. G. Eibenhut, D. G. Eibenhut, D. G.	7912100051* 7912120097 7912170384* 7912100169 7912110352	50-286 P POR MIBC 27-47 50-3 P TOPREP
DONAHUE, J. F. DONALDSON, D. DONAT, T. J. DONAT, T. J.	7912170166 7912180027 7912120158# 7912039065# 7912070105#	50-10 B 50-440 B 50-57 Q 50-327 G 50-395 G	DYER, J. A. DYER, J. A. DYER, J. A. DYER, J. A. DYER, J. A.	7912180326 7912180291 7912060553 7912070103 7912070020	50-250 8 50-335 8 50-270 8 50-287 8 50-346 8	EISENHUT, D. Q. EISENHUT, D. Q. EISENHUT, D. Q. EISENHUT, D. Q. EISENHUT, D. Q.	7912200065 7912050100 7912160219 7912170261 7912200697	50-206 P PDR HIBC CRG 50-247 F TOPREP
DEMAT, T. J. DOMAT, T. J. DOMAT, T. J. DOMNELL, J. R. DOPSOVIC, D. A.	7912180154# 7912310318# 7912280174# 7912310488 7912100307	50-327 G 50-390 G 50-369 G 71-6698 50-445 M	DYER, J. A. DYER, J. A. DYER, J. A. EADIE, Q. Q. EADIE, Q. Q.	7912050069+ 7912180154+ 7912280174+ 7912060368 7912140121+	50-302 G 50-327 G 50-349 G MASTE MOT MASTE MOT	EIGENRUT, D. Q. EISENRUT, D. Q. EISENRUT, D. Q. EIBENRUT, D. Q. EIBENRUT, D. Q.	7912180126 7912190784 7912200122 7912210115 7912180662	50-235 Q 50-287 8 50-3 F 50-286 P REGOD
DORMAN, R. M. DORMAN, R. M. DOUGHERTY, J. B. DOUGHERTY, J. B. DOUGHERTY, J. B.	7912270156* 7912270161* 7912120197* 7912120174* 7912120178*	50-313 P 50-313 P 50-338 G 50-338 G 50-338 G	EADIE, G. Q. EADIE, G. EADIE, G. EADIE, G. EADIE, G. G.	7912280210* 7912140102 7912190184 7912280192* 7912280169*	HASTE MOT HASTE MOT HASTE MOT HASTE MOT HASTE MOT	EIBENAUT, D. Q. EIBENAUT, D. Q. EIBENAUT, D. Q. EIBENAUT, D. Q. EIBENAUT, D. Q.	7912260235 7912190264 7912190776 7912170084	PDR MISC 50-312 P 50-269 P 50-29 P
DOUGHERTY, J. B. DOUGHERTY, J. B. DOUGHERTY, J. B. DOUGHERTY, D. J. DOUGHERTY, D. J. DOUGLAS, R. L.	7912120184* 7912120189* 7912180374 7912170420* 7912190225*	50-938 0 50-938 0 FOIA CONTRACT WASTE HOT	EADIE, O. G. EADIE, O. Q. EARLY, M. P. EARLY, P. J. EARLY, P. J.	7912280133 7912280139* 7912210085 7912030168 7912030181	WARTE HOT WARTE HOT NUREG 50-333 P 50-286 F	EL-ABIRY, M. T. ELIABON, L. R. ELKINS, R. B. ELLENBECKER, M. ELLERBHAM, L. E.	7912280607 7912270444 7912180156# 7912140517#	50-516 A 50-263 B FOIA REG
DOUGLAS, R. L. DOUGLAS, R. P. DOYLE, H. H. DOYLE, H. H. DOYLE, H. H.	7912280202* 7912190092* 7912030118 7912100477 7912140009	WASTE MOT 50-272 Q PROJ PROJ PROJ	EARLY, P. J. EARLY, P. J. EARLY, P. J. EARLY, P. J. EARLY, A. E.	7912040200 7912060528* 7912060526 7912100316 7912130291*	50-286 P 50-286 P 50-286 P 50-333 Q 50-3 P	ELLISON, C. ELLISON, C. ELLISON, C. ELLISON, C. ELLISON, C. ELLISON, C.	7912030107 7912030112# 7912030117# 7912140054	9A999 50-312 0 50-312 0 50-312 0 50-312 0
DOYLE, M. M. DOYLE, M. M. DOYLE, M. M. BOYLE, M. M. BOYLE, M. K.	7912140020* 7912030118 7912100469 7912100477 7912140009	PROJ PROJ PROJ PROJ PROJ	EARLY, P. J. EARLY, P. J. EARLY, P. J. EARLY, P. J. EARLY, P. J.	7912070397 7912120421 7912120457 7912130545 7912130547*	50-286 P 50-333 P 50-333 P 50-333 P	ELLIBON, C. ELLIBON, C. ELROD, B. A. ENPSON, F. M. ENDRES, Q. M. R.	7912130549 7912130552# 7912210045 7912116416	PR PR 50-280 8 70-1308
DOYLE, M. H. DRAGONETTE, K. S. DRAGONETTE, K. S. DRAGONETTE, K. S. DRAGONETTE, K. S.	7912140020* 7912140119* 7912140114 7912310259* 7912310249	PRGJ 27-47 27-47 27-48 27-48	EARLY, P. J. EARLY, P. J. EARLY, P. J. EARLY, P. J. EARLY, P. J.	7912170296 7912180543 7912180571 7912190513 7912190513	50-286 P 50-286 P 50-286 P 50-286 H 50-296 H	ENGELDER, T. C. ENGEL, R. E. ENGEL, R. E. ENGELKEN, R. H. ENGELHARDT, T. F.	7912100052* 7912130538 7912280547 7912270581	RE6 70-824 TOPREP TOPREP 50-206 8
DRAGONETTE, K. S. BRAKE, J. H. DREESEN, D. R. BROMERICK, A. M. DROMERICK, A. M.	7912210136*	27-48 50-204 G PROJ 50-339 A 50-339 A	EARLY, P. J. EARLY, P. J. EARLY, P. J. EARLY, P. J. EARLY, P. J.	7912190572 7912280504 7912270305 7912270315 7912270335	50-286 P 50-286 H 50-286 P 50-286 P 50-286 P	ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H.	7912280567# (7912120502 ) 7912100271 (7912100273 )	50-275 H 27-10 50-508 G 50-528 G 50-133 G
DROMERICK, A. W. DROMERICK, A. W. DROMERICK, A. W. DROMERICK, A. W. DROMERICK, A. W. DROMERICK, A. W.	7912180071 7912140046 7912270007 7912280328*	50-339 A 50-311 A 50-339 A 50-339 A 50-320 H	EARLY, P. J. EARLY, P. J. EARLY, P. J. EAST, D. EATON, R. Q.	7912270447# 7912270353 7912280612 7912120366 7912190671#	30-264 P 50-264 P 50-286 P PROJ 50-217 P	ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H.	7912100280 5 7912100283 5 7912100285 5 7912110508 5	80-344 0 80-204 0 80-312 0 80-397 0 80-528 0
ORYER, R. L. DUBINSKI, L. DUBRY, N. E. DUCKGORTH, J. P. DUERR, R. F.	7912210432* 7912040016* 7912060213*	FOIA FOIA 70-925 50-201 Q 50-294 P	EBERBOLE, J. C. EDERBOLE, J. EDNETER, S. D. EBNETER, S. D. EBNETER, S. D.	7912140208 7912210351 7912040664* 7912280301* 7912050004*	ACR8 ACR8 5C-207 Q 5C-320 Q 5C-286 Q	ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H.	7912110517 5 7912110519 5 7912110522 5 7912130465 5	60-20A 0 60-312 0 60-377 0 60-397 0 60-397 A

AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	6UBJECT CATEOORY
ENGELLEN, R. H.	7912070018	50-344 G	FAIRTILE, H. B.	7809190350	50-269 J	FIORELLI, Q. FIORELLI, Q. FIORELLI, Q. FIORELLI, Q. FIORELLI, Q.	7912180364	50-275 S
ENGELKEN, R. H.	7912070022	50-133 G	FALK, K. H.	7912050091	50-266 G		7912210122	50-440 S
ENGELKEN, R. H.	7912070023	50-206 G	FALK, K. H.	7912100470	50-266 C		7912050006	50-440 G
ENGELKEN, R. H.	7912070028	90-312 G	FALK, K. H.	7912100472*	50-266 O		7912030260	50-327 G
ENGELKEN, R. H.	7912070031	50-397 Q	FALK, K. H.	7912190234	50-266 O		7912030249	50-327 G
ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H.	7912110266 7912110269 7912110269 7912110272 7912110273	50-528	FARON, R. 8. FARRAR, M. FARRAR, M. FARRAR, H. FARRAR, H.	7912140167 7912200601 7912200613 7912200625 7912200587	50-244 H 50-387 T 50-387 T 50-387 T 50-387 T	FIGRELLI.O. FIGRELLI.O. FIGRELLI.O. FIGRELLI.O. FIGRELLI.O.	7912050016 7912050043 7912130131 7912060043 7912050538	50-341 Q 50-440 Q 50-546 Q 50-456 Q 50-459 Q
ENGELMEN, R. H.	7912110274	50-397 G	FAULKENBERRY, B.	7912040504	50-206 B	FIORELLI, O.	7912110261	50-546 0
ENGELMEN, R. H.	7912110492	50-528 G	FAULKENBERRY, B.	7912050280*	50-312 0	FIORELLI, O.	7912070155	50-373 0
ENGELMEN, R. H.	7912110494	50-133 G	FAULKENBERRY, B.	7912070198*	50-89 Q	FIORELLI, O.	7912260129	50-329 0
ENGELMEN, R. H.	7912110495	50-344 G	FAULKENBERRY, D.	7912050094*	50-206 Q	FIORELLI, O.	7912130064	50-331 0
ENGELMEN, R. H.	7912110496	50-206 G	FAV. C. H.	7912310139	50-266 Q	FIORELLI, O.	7912180333	50-373 0
ENGELMEN, R. H.	7912110499	50-312	FAY, C. H.	7912050474	50-266 P	FIDRELLI.C.	7912180224	50-275 G
ENGELMEN, R. H.	7912110590		FAY, C. H.	7912030171	50-266 P	FIDRELLI.C.	7912200189	50-263 G
ENGELMEN, R. H.	7912190118		FAY, C. H.	7912070412	50-266 B	FIDRELLI.C.	7912200577	50-454 G
ENGELMEN, R. H.	7912190121		FAY, C. H.	7912070416=	50-266 B	FIDRELLI.C.	7912210028	50-483 G
ENGELMEN, R. H.	7912190143		FAY, C. H.	7912070427	50-266 B	FIDRELLI.C.	7912240087	50-461 G
ENGELKEN, R. H.	7912190147	50-344 @	FAY, C. W.	7912070433*	50-266 8	FIORELLI.O. FIORELLI.O. FIORELLI.O. FIORELLI.O. FIORELLI.O.	7912130418	50-327 8
ENGELKEN, R. H.	7912190151	50-312 @	FAY, C. W.	7912200027	50-266 9		7912170105	50-329 8
ENGELKEN, R. H.	7912190153	50-206 @	FAY, C. H.	7912130296	50-266 F		7912260167	50-367 0
ENGELKEN, R. H.	7912190156	50-361 @	FAY, C. H.	7912140369	50-266 P		7912260148	50-546 0
ENGELKEN, R. H.	7912190161	50-377 @	FAY, C. H.	7912180578	50-266 P		7912050418	50-546 0
ENGELREN, R. H.	7912200129	50-312	FAY, C. W.	7912280650	50-266 0	FIORELLI, O.	7912050290	50-546 0
ENGELREN, R. H.	7912310269		FAY, C. H.	7912190562	50-266 P	FIORELLI, O.	7912070402	50-546 0
ENGELREN, R. H.	7912310269		FAY, C. H.	7912210143	50-266 P	FIORELLI, O.	7912140380	50-440 8
ENGELREN, R. H.	7912310272		FAY, C. H.	7912270300	50-266 P	FIORELLI, O.	7912140385	50-367 8
ENGELREN, R. H.	7912310273		FAY, C. H.	7912270209	50-266 P	FIORELLI, O.	7912040012	50-327 0
ENGELKEN, R. H.	7912310277	50-312 G	FAY, C. H.	7912270430	50-266 P	FIORELLI, O. FIORELLI, O. FIORELLI, O. FIORELLI, O. FIORELLI, O.	7912060073	50-440 Q
ENGELKEN, R. H.	7912310279	50-397 G	FAY, C. H.	7912270495	50-266 F		7912120556	50-341 Q
ENGELKEN, R. H.	7912200229	50-528 G	FAY, C. H.	7912280550	50-266 P		7912260075	50-374 S
ENGELKEN, N. H.	7912200236	50-133 G	FAY, C. H.	7912270191	50-266 F		7912260079	50-373 S
ENGELKEN, R. H.	7912200237	50-275 G	FEDEYKO, J. K.	7912260318	REPOD		7912170062	50-329 S
ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H.	7912200240 7912200244 7912200247 7912200248 7912200252	50-344 G 50-206 G 50-361 G 50-312 G 50-397 G	FEE, W. F. FFE, W. F. FEE, W. F. FEE, W. F. FEE, W. F.	7912170244 7912180248 7912170294 7912170294 7912180476 7912140227	50-213 Q 50-213 P 50-213 P 50-213 P 50-423 A	Fiorelli, O. Firch, R. H. Fish, H. Fish, H. Fish, R.	7912280058 7912200424* 7912190107 7912190114* 7912060645	50-341 S 50-337 A 50-3 G 50-3 G 50-344 B
ENGELNEN, R. H.	7912280595	50-528	FEIERABEND.C.D.	7912050406*	90-282 0	Fibher, W. L.	7912210081	50-344 B
ENGELKEN, R. H.	7912280519		FEIERABEND.C.D.	7912210074*	50-282 0	Fibher, W. L.	7912070270*	50-10 Q
ENGELKEN, R. H.	7912280523		FEIL.R.	7912050010*	50-333 0	Fibher, W. L.	7912190799*	50-255 Q
ENGELKEN, R. H.	7912280525		FEIL.R.	7912260167*	50-247 0	Fibher, W. L.	7912050315*	50-264 Q
ENGELKEN, R. H.	7912280525		FELDHAN, J. H.	7912120002	50-358 0	Fithian, F. J.	7912200692*	50-367 U
ENGELKEN, R. H.	7912260511	50-508 S	FELDHAN, J. H.	7912130033	50-35H 0	Fitzbihmons, K.	7912280454*	50-320 H
ENGELKEN, R. H.	7912280636	50-397 S	FELDHAN, R. H.	7912170011	NUME9	Fitzbihmons, T. R	7912140116	71-6345
ENGLE, L.	7912140134	50-338 P	FELT, R.	7912240355=	50-37G 9	Flack, Q.	7912270418	60-424 0
ENGLE, L.	7912206047	50-339 P	FELTON, J. H.	7902240180	FOIA	Flannigan, R. D.	7912310467*	50-298 8
ENGLISCIA, R. B.	7912270156#	50-313 P	FELTON, J. H.	7912180134	PRM	Fleibchaker, D. B	7912136160	50-275 0
enz irna. R. S.	7912270161*	70-313 P	FELTON, J. M.	7912070161	FDIA	FLEIBCHAKER, D. 8	7912130169	50~275 0
Ers. C. H.	7912310115*	50-281 0	FELTON, J. M.	7912170412	FOIA	FLEIBCHAKER, D.	7912060608	70~2623
Ers. C. M.	7912050011*	50-440 0	FENNER, E. H.	7912170303	50-59 J	FLEIBCHAKER, D.	7912110432	70~2623
Ers. C. M.	7912050022*	50-341 0	FERQUBON, R. L.	7912130154#	PRDJ	FLEIBCHAKER, D.	7912100483	50~275 A
Ericneon, P. S.	7912120090	50-285 P	FERQUBON, R. L.	7912170298	50-261 F	FLEIBCHAKER, D. 8	7912130160	50~275 Q
ERICKBON, P. B.	7912040360	50-285 P	FERQUEON, R. L.	7912170128	TOPREP	fleischaker, D.	7912050046	50-275 0
ERICKBON, R. A.	7912070218*	FOIA	FERQUEON, R.	7912160115	POR MISC	Fleischaker, D.	7912050117	50-275 0
ERICKBON, R. A.	7912070214*	FOIA	FERGUEON, R. L.	7912310188	TOPREP	Fleischaker, D. S	7912130168	50-275 0
ERNET, T.	7912180473*	50-275 U	FERRY, J. L.	7912280425	MUSEO	Fleischaker, D.	7912140011	80-275 0
ESPOSITO, B.	7912310508*	50-255 P	FICKIEB, R. H.	7912130089	MUSEO	Fleischaker, D.	7912060608	70-2623
ESBIO, T. H. ESBIO, T. H. ESBINGTON, E. H. ESBAEIN, O. A. EBTEROWITZ, R.	7912070135	50-282 8	FIELDS, H.	7912120432	50-155 6	Fleibchaker, D.	7912110432	70-2423
	7912260098*	50-266 9	FIELDS, H.	7912310483	50-155 8	Fleibchaker, D. B	7912310457	50-275 Q
	7912140125	NUREQ	FINDLEY, D. E.	7912120163	FOIA	Fleibchaker, D. B	7912270064	50-275 Q
	7912200381	TOPREP	FINDLEY, D. E.	7912130141	FOIA	Fleicher, C. D.	7912140540	RES
	7912310078	50-3 9	FINFROCK, I. R.	7912180401	50-369 0	Fleicher, C. D.	7912140570	RES
EBTER, J.	7912130478	50-266 H	FINFROCK, I.R.	7911200385	30-217 P	Flowers, M. R.	7912200393#	50-337 A
* EBTER, J.	7912140535	50-266 . 0	FINFROCK, I.R.	7912040504	50-217 P	Flynn, E.	7912170377	FOIA
EBT ILL, D. D.	7912110111#	0A797	FINFROCK, I.R.	7912070327	50-217 P	Flynn, P. Q.	7912140184	50-445 M
ETHER INSTON, H.	7912140208	ACRE	FINFROCK, I.R.	7912110260	50-217 P	Flynn, P. Q.	7912310514	50-498 M
ETHER INSTON, H.	7912140211	ACRE	FINFROCK, I.R.	7912140209	50-217 P	Flynn, P. Q.	7912310519#	50-498 M
EVERETT, R. J.	7912310059	1845	FINFROCK, I.R.	7912190631	50-217 P	FLYIEN, P. Q. FLYNN, M. FLYNN, J. D. FLYNN, J. D. FLYNN, J. D. FLYNN, P. Q.	7912280649	50-445 M
EVERETT, R. J.	7912310077	1845	FINFROCK, I.R.	7912140417	50-219 P		7912260282	50-596 Q
EVERETT, R. J.	7912180111	1845	FINFROCK, I.R.	7912140419*	50-219 P		7912170308	50-358 A
EVERETT, R. J.	7912030228#	50-3842 G	FINFROCK, I.R.	7912190564	50-217 P		7912270336	50-358 A
EVERETT, R. J.	7912030229	40-3453	FINFROCK, I.R.	7912270384	50-219 P		7912120249	50-445 M
EVERETT, R. J.	7912280285	40-2259	FINKEL, A.	7912040221#	50-334 Q	FLYNN.M.	7912070489	CONTRACT
EMALD: B. C.	7912210191*	50-32 G	FINKEL, A. E.	7912200457#	50-410 Q	FOBES.R.L.	7912310425=	30-255 S
EMINOR: J.	7912210035	50-320 H	FIORELLI, Q.	7912170089	50-327 B	FOBES.R.L.	7912310441=	50-255 S
EMINO: T. N.	7912180567*	50-556 A	FIORELLI, Q.	7912210047	50-546 B	FOBES.R.L.	7912180512=	50-255 S
EMINO: T. N.	7912180559	50-556 A	FIORELLI, Q.	7912210095	50-440 B	FOBES.R.L.	7912180514=	50-255 S
EYED, J. A. EYED, J. A. EYED, J. A. FAIRNER, H. J. FAIRNER, H. J.	7912170031* 7912210364* 7912210360 7912120382 7912120437	50-546 A 50-046 Q 50-346 Q 50-341 B 50-341 B	FIGRELLI.C. FIGRELLI.C. FIGRELLI.O. FIGRELLI.C.	7912200007 7912180376 7912070033 7912200442 7912170416	50-440 8 50-483 8 50-483 8 90-344 8 50-329 8	FOBER, R. L. FOGO, M. O. FOLEY, T. FOLEY, T.	7912180517# 7912040519 7912070125 7912040171# 7912050192#	50-255 8 50-255 % 50-155 P 50-20 0 50-247 0

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER			ACCESSION	l Dibbert
FOLEY, T. FORD, W.	79122001674		GALLO, J.	7912030004	CATEGORY	AUTHOR	MUMBER	SUBJECT CATEGORY
FORD, W. H.	7912200014 7912130011	40-8502 40-8502	GALLO, J. GALLO, J.	7912130278	50-556 g Pr	GLASSPIEGEL, H. GLASSPIEGEL, H.	7912170209	Water 18
FORD, W. H. FORT, C. W.	791213017 <b>1</b> 7912280676*	50-546 U	GALLE, J.	7912170179 7912170008	50-155 G 50-155 G	GLASSPIEGEL, H.	7912170217 7912100326	50-392 e 50-392 e
FOSTER. R. M.			GALLD, J.	7912170058	50-155 g	Glasspiegel, H. Glasspiegel, H.	7912170209 7912170217	50-382 p
FOSTER, R. F.	7912180332 7912120641	50-330 H NUREG	GALLO, J. GALLO, J.	7912130396	PR	GLENN, J.	-	50-382 ¢
FOUCHARD, J. J. FOUKE, R. L.	7912120552 7912050203	50-344 U	DALLO, J.	7912070344± 7912130278	9 50-155 Q PR	ENUSNOLI, C. N.	7912310051 7912140121	IGE MASTE HOT
FOUNTAIN, L. H.	7912200388#	50-445 g 50-337 a	GALLO, J. GALLO, J.	7912170179	50-155 ¢	CNUGNOLI, G. N. CODDARD, R. J.	79122802104	HASTE HOT
FONTNKLE, E. N.	7912110009#			7912170008	50-155 g	GODDARD, R. J.	7912130049 7912310539	50-599 p 50-599 h
FONLER, E. B. FONLER, B. Q.	7912140125	NUREG	GALLO, J. Gallo, J.	7912170058 7912130396	50-155 g	GODDARD, R. J.	7912100476	
FOX. C. N.	7912200512* 791213060B	50-316 P 50-266 P	GALLO, J. GALLO, R. M.	7912030004	PR 50-554 g	GODDARD, R. J. GODDARD, R. J.	7912180178	50-295 g
FOX. D. F.	7912260204*	QA999	GALLO, R. H.	7912060200± 7912210024*	50-387 g 50-387 g	GODDARD, R. J.	7912210406 7912210420	50-599 g 50-295 g
FRALEY, D. W. FRALEY, R. F.	7912040520	NUREO	CAMMILL, N. P.	7912310512*		GODDARD, R. J.	7912260110	50-599 g
FRALEY, R. F.	7912100066# 7912190362#	90-286 P 8078	CAMMILL, H. P. CAMMILL, H. P.	7912310229	50-133 <b>o</b> PDR HISC	GODDARD, R. J. GODY, A.	7912210093	50-597 0
FRANKLIN, W. J. FRANKLIN, W. J.	7912060040 7912130313	50-498 M 50-498 M	GAMMILL.U.P	7908140497 7912200655	PDR HISC 50-309 H	GODY, A.	7912120560± 7912260063±	70-820 70-820
FRANKLIN, N.		·	CAPHILL, N. P.	7912270119	50-348 P	GOLDIERO, J. R.	7912260355 <b>+</b> 7912050672	50-373 e PROJ
FRANK, L.	7912280630 7912050525	50~498 M 50~344 P	Cander, 5. Cannis, 8.	7912280558#	50-320 H	COLDBERG, S. C.		
Franklin, W. J. Franklin, H. J.	7912060040 7912130313	50~498 M	Camis, S.	7912170187 7912270045	FDIA FDIA	GOLDBERG, B. C.	7912170347 7912130049	50-367 A 50-599 0
Franklin, H.	7912280630	50-498 H 50-498 H	CANNON, J. CARDNER, D. C.	79122804824 7912180137	50−320 H	COLDBERG, S. C. GOLDBERG, S. C.	7912070168 7912180168	50-250 p
FRANK, L.	7912110341	50-344 8	GARLOW, C.		71-340	COLDBERO, B. C.	7912200636	50-338 g 50-338 g
FREEMAN, D. W. FREITAG, J. D.	7912120139 7912170629	MUREO 50-302 J	CARRETT.E.O.	7912130332 7912110227	PRH NUREO	COLDBERG, S. C.	7912260260	50-375 g
FRENCH, L. D. FRENCH, L. D.	7912070444+	50-29 S	GARSHICK.A. GARY.R.J.	7912280654	REGOD	GOLDBERG, S. C. GOLDBERG, J. R.	7912310510 7912060087	50-133 Q PROJ
	7912110290±	50-29 s	GARY, R. J.	7912060595 7912030040	50-445 A 50-446 A	COLDBERG, J. R. COLDBERG, S. C.	E010402197	PROJ
FRIEDLAND, A. J. FRIZZLE, C. D.	7912200584# 7912040328#	50-537 A 50-309 B	CARY, R. J.	7912140240			7912100322	50-155 g
FRIZZLE, C. D. FRIZZLE, C. D.	7912140501#	50-309 8	GARY, R. J. GARY, R. J.	7912140264	50-445 K	Goldhagen, B. I. Goldhann, K.	7912170183 7912270027	FOIA 71-250
FRIZZLE, C. D.	7912180557± 7912040398#	50-309 S 50-309 S	GARY, R. J. GASPER, J.	7912180412 7912190429	50-445 I 50-445 A	GONZALEZ, H. B. GOODHOPE, A. C.	7912120066#	50-498 U
FROELICH, R. H.	7912120179			7912260017*	TOPREP	GOODHAN, L. S.	7912130290 7912040423*	27-39 50-409 8
FROST, S. R. FROST, S. R.	791⊋110303	50-255 P	GAUT, H. GAHLIK, L. R.	7912180101 7912190298•	State Prog	COODHAN, L. S.	7912110209+	50-409 R
FROST, S. R.	7912280499 7912310296	50-255 G 50-255 Q	GAZDAQ, L. Gebbie, K. M.	7912280480±	50-445 H 50-320 H	Coodhin, C.	7912310504*	50-409 B
FROST, S. R.	7912310344	50-255 P	GEHR, A. C.	7912120073* 7912030030	CONTRACT 50-275 C	GOODHIN, C.	7912210162+ 7912280678+	50~206 8 50~344 0
FROST, S. R. FROST, S. R.	7912310373 7912310417	50-255 P	GEHR, A. C.	7912030039		GOODHIN. C.	7912190003#	50~133 û
FROST, S. R. FUKAZAWA, Y.	7912310436	50-255 g 50-255 g	GENDLER, M. W. GENDLER, M. W.	7912060115	50-275 e 50-522 e	GOODHIN, C.	7912040360	50-344 P
FULLER, E.	7912110297 <b>+</b> 7912180059	XPORTLIC 71-204	CENDLER, H. U.	7912060125± 7912310494	50-522 g 50-522 g	GOODWIN, C.	7912060496 7912070452	50-344 F 50-344 P
FULLER, J. K.	7912210098		GEORGE, J.	7912180612	50-224 g	COODHIN, C.	7912120319 7912140353	50-344 P 50-344 P
FULLER, J. K. FULLER, J. K.	7912040216	50-267 Q 50-267 P	GERAGHTY, C. GERAGHTY, C.	7912210139	XPORTLIC	GOODHIN, C.		
FURBUSH, H. H.	7912180266 7912030038	50-267 Q 50-275 G	GERGLD, C.	7912200407 7912280410#	XPORTLIC 50-320 H	CODMIN. C.	7912190548 7912180 <u>622</u>	50-344 P 50-344 P
FURR, B. J.	7912110497#	50-261 Q	GETTLER, F. H. GETTY, B. C.	7912310136 7912120350#	REGOD	GOODHIN.C.	7912210366 7912270269	50-344 P 50-344 F
FURR, B. J. FURR, B. J.	7912040270	50-324 P	CHINGER. J.		50-133 R	Coodwin, C.	7912290491	50-344 P
FURR, B. J.	7912040505 7912310053	50-324 P 50-261 G	CIBBENS, T. D.	7912310109 7912110247*	50-3 φ 50-370 q	Goodwin, C. Goodwin, C.	7912280518	50-344 P
FURR, O. J. FURR, B. J.	7912310500	50-324 Q	CIBBONS, T. D. CIBEONS, T. D.	7912050594+ 7912310333#	50-416 Q	GOODNIN, C.	7912280525 <b>&gt;</b> 7912310516	50-344 P 50-344 P
FURR, B. J.	****	_	GIBBONS, T. D.		50-327 g 50-348 g	GOODWIN, C. GOPPEL, H.	7912070405 7912210128	50-344 F
FURR. B. J.	7912310266	50-261 g. 50-324 g	01885, M. E. 01885, M. E.	7912030004	50-556 g	COSSICK, L. V.		XPORTLIC
FURR, B. J. FURR, B. J.		50-324 R 50-261 Q	© 1860N, J. D.		50-556 0 71-347	60881CK' F' A'	791228014 <del>0*</del> 7911050248*	Waste Not Prn
FURR. D. J.		50-324 G	Oleson, C. Oleson, A. F.	7912310035	RES	COSSICK, L. V.	7912120268 7912040107	FOIA 50-320 U
FUTTER, J. L.	7712120040	50-59A g	GIBSON, A. F.		50-348 g	COSSICK, L. V.	7912120243	50-287 U
GABETTA, O. Gabriel, E.		NUREO PROJ	GIBSON A.F.		50-395 q 50-261 g	COSSICK, L. V.	7912120250	50-209 H
GAD.R.K. GAD.R.K.	7912170053	50-309 g	01850N, A. F. G1850N, A. F.	7912100070*	70-824	Gossick, L. V. Gossick, L. V.	7912130014 7912270001	50-302 U PDR MIBC
GAD, R. K		50-309 g	GIBSON, A. F.		50-327 g 50-62 g	COSSICK, L. V.	7912120024	PDR MISC
GAD, R. K.	7912170202 :	50-309 ¢ 50-309 ¢	OIBSON, A. F.	7912200612= 7	7027		7912120224	50-209 U
GAFFNEY, C. M. GAHM, J. M.	7912200375*	50-293 R	GIESEKE, J. A. GILDENHORN, A. J.	7912200279	EB	COSSICK. L. V.		MUREQ 50-153 U
GAHM, J. H.		50-247 R 50-247 B	GILFOY, R. GILINSKY, V.	7912310508*	OIA 50–255 p	60881CK, L. V.	7912210095	50-352 U
GAHH, J. H.	7912040298* 5	50-267 s			CRS	GOSSICK, L. V.		50-437 U 50-352 U
CAIRI, J. W.	7912040335# 5	i0-267 g	gilinsky, v. Gilinsky, v.	7912280397* 5 7912180098 5	Ю-320 Р Ю-277 Н	00881CK, L. V.	7912120053	50~498 U
GAHM, J. H. GAHM, J. N.	7912040363+ 5	i0-267 8 i0-267 8	GILL, H. H. GILLETT, H. T.	7912130350+ 5	0-264 Q	60881CK, L. V.	79122000B4+	POR HISC
		i0~267 g	GILLELAND, J. E.		0-315 R 0-327 A	GOESICK, L. V.	7912120035	50-456 V PDR H16C
9A <del>12</del> 1, J. W. 9AHH, J. W.		0-267 S	PILLESPIE, F. P.		0-143	GOSSICK, L. V.	7912260124	PDR MISC
CAHH, J. W. CAHH, J. H.	7912140335# 5	0-267 B	GILLESPIE, F. P. GILLESPIE, F. P.	7912180213 5	0-259 s	GOSSICK, L. V.		50-219 U
GAHN, J. W.		0-267 R 0-267 S	OILLESPIE.F.P. GILLESPIE.F.P.	7912240181* 7	0~27 0~143	00881CK, L. V.	7912210237	50-219 U 50-219 U
CAHM, J. W.		. I.		7912210235# 7	0-1151	GOESICK, F. A.		50-347 U 50-347 U
CARM, J. III.	7912180610* 50	0-267 S	GILLEN, D. M. GILLEN, D. M.		<del>-4492</del>	GOSSICK, L. V.		
CALLACHER, J. H.	7912170171 50	0-247 S 0-277 Q	CLLIDH, J. R. CLASSERO, V. M.	7912140508* F	)~2259 }[A	COSSICK, L. V.	7912210216	50-275 U
GALLACHER, E. J.		0-237 a	GLASSPIECEL, H.	7912200410+ 50	)-339 A )-382 G	COSSICK, L. V.	7912120529 5 7912120541 F	50-320 U DR H190
				<b></b>	<b>U</b>	COSSICK, L. V.		50-35B U
, i								

POHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY
edssick, L. V.	7912210124	50-275 U	ORIER, B. H.	7912050030	50-363 Q	GRIER, B. H.	7912110449	50-220 G
edssick, L. V.	7912270033	PDR MISC	GRIER, D. H.	7912050032	50-219 Q	GRIER, B. H.	7912110452	50-333 G
edssick, L. V.	7912280253	50-320 U	GRIER, B. H.	7912050036	50-322 Q	GRIER, B. H.	7912110453	50-286 G
edssick, L. V.	7912280259	50-320 U	GRIER, D. H.	7912050038	50-309 Q	GRIER, B. H.	7912110456	50-352 G
edssick, L. V.	7912120022	PRM	GRIER, B. H.	7912050039	50-245 Q	GRIER, B. H.	7912110458	50-277 G
00891CK, L. V. 60891CK, L. V. 60891CK, L. V. 90891CK, L. V. 60891CK, L. V.	7912120028* 7912280411 7912280471 7912180250 7912120501	PRM 50-320 U 50-289 U PDR MIBC FOIA	ORIER, B. H.	7912050040 7912050044 7912050045 7912050047 7912050049	50-220 G 50-410 G 50-333 G 50-284 G 50-277 G	GRIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, B. H.	7912110461 7912110466 7912110468 7912110470 7912110473	50-387
odseick, L. V.	7912210018	XPORTLIC	ORIER, B. H. ORIER, B. H. ORIER, B. H. GRIER, B. H. ORIER, B. H. ORIER, B. H.	7912050051	50~387 Q	GRIER, B. H.	7912110478	50-485 G
odseick, L. V.	7912200666	ORG		7912050055	50~272 Q	GRIER, B. H.	7912110487	50-271 G
odseick, L. V.	7912200592	XPORTLIC		7912050057	50~311 Q	GRIER, B. H.	7912110490	50-27 G
odseick, L. V.	7912200594	XPORTLIC		7912050058	50~443 Q	GRIER, B. H.	7912110073	50-309 G
odseick, L. V.	7912200598	XPORTLIC		7912050061	50~244 Q	ORIER, G. H.	7912050213	50-293 G
90881CK, L. V.	7912310117	XPORTLIC	ORIER. D. H.	7912050064	50~495 Q	GRIER, B. H.	7912050217	50-317
90881CK, L. V.	7912280050	XPORTLIC	GRIER. B. H.	7912050065	50~271 Q	GRIER, B. H.	7912050221	
90881CK, L. V.	7912310029	PRM	GRIER. B. H.	7912050067	50~27 Q	GRIER, B. H.	7912050224	
9009E, H. J.	7912050489*	50-327 Q	GRIER. B. H.	7912050225	50~293 Q	GRIER, B. H.	7912050228	
9009E, H. J.	7912060089*	50-966 Q	GRIER. B. H.	7912050230	50~317 Q	GRIER, B. H.	7912050223	
ODUSE, N. J. COMER, O. C. OOMER, O. C. OOMER, O. C. ORACE, R. H.	7912240306* 7912200298 7912200476 7912280440 7912140252	50-327	GRIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, D. H.	7912050234 7912050239 7912050241 7912050245 7912050250	50-3	GRIER.B.H. GRIER.B.H. GRIER.B.H. GRIER.B.H. GRIER.B.H.	7912050235 7912050237 7912050243 7912050248 7912050251	50-363
ORAHAM.E.T.	7912270204#	50-293 8	GRIER, B. H.	7912050253	50-217 G	GRIER, B. H.	7912050255	50-336 0
ORAHAM.E.T.	7912280475	50-293 8	GRIER, B. H.	7912050256	50-322 G	GRIER, B. H.	7912050258	50-245 0
ORAHAM.J.	7912280479	50-289 T	GRIER, B. H.	7912050260	50-287 G	GRIER, B. H.	7912050261	50-410 0
ORAHAM.P.D.	7912260122#	50-213 0	GRIER, B. H.	7912050264	50-309 G	GRIER, B. H.	7912050263	50-220 0
ORAHAM.P.D.	7912200332#	90-220 0	GRIER, B. H.	7912050266	50-245 G	GRIER, B. H.	7912050267	50-286 0
ORAINEY, M. W.	7912240372	50-443 0	CRIER, B. H.	7912050271	50-410 Q	GRIER, B. H.	7912050269	50-333
ORANT, W. B.	7912170185*	40-2061	GRIER, B. H.	7912050274	50-220 Q	GRIER, B. H.	7912050273	
ORANT, P.	7912050322	50-10 P	GRIER, D. H.	7912050278	50-333 Q	GRIER, B. H.	7912050277	
ORAVES, R. H.	7912040501	50-213 8	GRIER, B. H.	7912050281	50-296 Q	GRIER, B. H.	7912050282	
ORAVES, R. H.	7912180437	50-213 R	GRIER, B. H.	7912050286	50-277 Q	GRIER, B. H.	7912050287	
ORAVES, R. H.	7912260262	50-213 6	GRIER, B. H.	79120502B9	50-352 Q	GRIER, B. H.	7912050291	50-272 0
ORAY, J. G.	7912200044	XPORTLIC	GRIER, B. H.	7912030295	50-387 Q	GRIER, B. H.	7912080327	50-443 0
ORAY, H. K.	7912180067*	WASTE MOT	GRIER, B. H.	7912030297	50-272 Q	GRIER, B. H.	7912050330	50-244 0
GRAY, J. R.	7912060094	50-344 0	GRIER, B. H.	7912050298	50-311 Q	GRIER, B. H.	7912050332	50-485 0
ORAY, J. R.	7912130074	50-265 0	GRIER, B. H.	7912050302	50-443 Q	GRIER, B. H.	7912050335	50-271 G
GRAY, J. R.	7912130081	50-285	GRIER, B. H.	7912050304	50-244 0	GRIER.B.H.	7912050337	50-29 0
GRAY, J. R.	7912190168		GRIER, B. H.	7912050306	50-485 0	GRIER.B.H.	7912260332	50-387 0
GRAY, J. R.	7912050142		GRIER, B. H.	7912050309	50-271 0	GRIER.B.H.	7912060564	50-293 0
GRAY, J. R.	7912100126		GRIER, B. H.	7912050311	50-27 0	GRIER.B.H.	7912060565	50-317 0
GRAY, J. R.	7912120302		GRIER, B. H.	7912100107	50-273 0	GRIER.B.H.	7912060566	50-3 0
GRAY, J. R. GRAY, J. R. GRAY, J. R. GRAY, J. R. GREEN, W. W.	7912140942 7912170218 7912190488 7912280130 7912310901*	50-344	ORIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, B. H.	7912100109 7912100113 7912100115 7912100117 7912100118	50-317 0 50-3 0 50-213 0 50-412 0 50-334 0	GRIER.D.M. GRIER.D.H. GRIER.B.H. GRIER.D.H. GRIER.D.H.	7912060567 7912060570 7912060573 7912060574 7912060576	50-213
GREEN, H. H.	7912310473*	50~155 P	ORIER, B. H.	7912100120	50-21.9	ORIER.B.H.	7912040577	50-309 0
GREEN, D. Q.	7911300021	50~445 M	ORIER, B. H.	7912100122		ORIER.B.H.	7912040579	50-245 0
GREEN, O. E.	7912210429*	71-364	ORIER, D. H.	7912100124		ORIER.B.H.	7912040580	50-220 0
GREEN, D.	7912140393*	50~257 R	ORIER, B. H.	7912100127		GRIER.D.H.	7912040582	50-333 0
GREEN, K.	7912180104	State Prog	ORIER, B. H.	7912100129		ORIER.B.H.	7912040583	50-286 0
OREGER, L. R.	7912210091	50-346 B	GRIER, B. H.	7912100131	50-245	GRIER, D. H.	7912040584	50-277 0
GREGER, L. R.	7912040016*	70-725	GRIER, B. H.	7912100133		GRIER, B. H.	7912040584	50-387 0
GRENDON, A.	7912180259	ACRS	GRIER, D. H.	7912100134		GRIER, B. H.	7912040588	50-272 0
GRESHAN, J.	7912190601*	TOPREP	GRIER, B. H.	7912100134		GRIER, B. H.	7912040594	50-443 0
GREW, P. C.	7912130333	FR	GRIER, D. H.	7912100138		GRIER, B. H.	7912040597	50-244 0
OREM, P. C. OREM, P. C. OREM, P. C. ORIBBON, D. M. ORIBBON, D. M.	7912130530 7912180015* 7912180009 7912110438 7912110438	PR PR PR 50-250 M 50-250 M	GRIER, B. H.	7912100140 7912100144 7912100145 7912100146 7912100148	50-352	ORIER.B.M. ORIER.B.H. ORIER.B.H. ORIER.B.H. ORIER.B.H.	7912060599 7912060600 7912110022 7912110027 7912110031	50-271 0 50-29 0 50-293 0 50-317 0 50-3 0
ORIDER, H. O.	7912140381	50-274 J	GRIER, B. H.	7912100150	50-443 G	GRIER, B. M.	7912110035	50-213 G
ORIER, B. H.	7912030251 *	50-219 G	GRIER, B. H.	7912100152	50-485 G	GRIER, B. H.	7912110037	50-334 G
ORIER, B. H.	7912210011	50-279 G	GRIER, B. H.	7912100155	50-244 G	GRIER, B. H.	7912110044	50-412 G
ORIER, B. H.	7912040049*	50-277 G	ORIER, B. H.	7912100156	50-271 G	GRIER, B. H.	7912110047	50-363 G
ORIER, B. H.	7912040153*	50-20 G	GRIER, B. H.	7912100157	50-29 G	GRIER, B. H.	7912110048	50-217 G
CRIER, B. H. CRIER, B. H. CRIER, B. H. CRIER, B. H. CRIER, B. H.	7912040166 7912100236* 7912030236 7912030074 7912060033	50-320	GRIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, B. H.	7912100405 7912280266 7912110389 7912110394 7912110396	50-352 G 50-269 G 50-293 G 50-317 G 50-3 G	GRIER, B. H.	7912110051 7912110054 7912110054 7912110060 7912110064	50-322 0 50-209 0 50-309 0 50-245 0 50-245 0
ORTER, B. H. ORTER, B. H. ORTER, B. H. ORTER, B. H. ORTER, B. H.	7912060191 7912100219 7912100402 7912120101 7912050017	50-20	GRIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, B. H.	7912110400 7912110404 7912110405 7912110409 7912110411	50-213	GRIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, B. H.	7912110066 7912110067 7912110069 7912110073 7912110075	50-220 0 50-286 0 50-333 0 50-277 0 50-352 0
ORIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H.	7912050021 7912050023 7912050024 7912050026 7912050029	50-317 Q 50-3 Q 50-213 Q 50-334 Q 50-412 Q	GRIER, B. H. GRIER, B. H. GRIER, D. H. GRIER, D. H. GRIER, B. H.	7912110413 7912110415 7912110419 7912110422 7912110445	50-322 Q 50-287 Q 50-307 Q 50-345 Q 50-410 Q	GRIER, B. H. ORIER, B. H.	7912110077 7912110079 7912110080 7912110083 7912110087	50-387 @ 50-272 @ 50-311 @ 50-443 @ 50-495 @

AUTHOR	ACCEBBION NUMBER	SUB VECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	·· AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY
GRIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, B. H.	7912110091 7912110094 7912110094 7912210005 7912310007	50-244 q 50-271 q 50-29 q 50-277 q 50-272 q	GRIER, B. H. Grier, B. H. Grier, B. H. Grier, B. H. Grier, B. H.	7912280188 7912280190 7912280193 7912280194 7912280194	50-3 Q 50-213 Q 50-412 Q 50-334 Q 50-363 Q	HAGAN, T. F. HAGEY, H. HAGEY, H. HAGEY, H. HAGEY, H.	7912200179 7912100087 7912120078 7912100390 7912120308	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
ORIER.B.H. ORIER.B.H. ORIER.B.H. ORIER.B.H. ORIER.B.H. ORIER.B.H.	7912210022 7912190011 7912190017 7912190018 7912190020	50-29 Q 50-293 Q 50-317 Q 50-3 Q 50-213 Q	GRIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, B. H.	7912280199 7912280200 7912280204 7912280205 7912280207	50-219 0 50-322 0 50-289 0 50-309 0 50-245 0	HAGOERTY, P. E. HAIG, D. A. HAIRSTON, W. G. HAIRSTON, W. G. HAIRSTON, W. G.	7912070004 7909180007* 7912130422 7912130421 7912030187*	50-320 P 50-320 M 50-348 8 50-348 8 50-348 8
ORIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H.	7912190021 7912190022 7912190027 7912190031 7912190034	50-334 Q 50-412 Q 50-217 Q 50-322 Q 50-287 Q	ORIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H. GRIER, B. H.	7912280212 7912280219 7912280217 7912280220 7912280224	50-410 G 50-220 G 50-286 G 50-333 G 50-352 G	Hairston, W. G. Hairston, W. G. Hairston, W. G. Hairston, W. G. Hairston, W. G.	7912040381* 7912270389* 7912310426* 7912110336* 7912110337*	50-348 g 50-348 g 50-348 g 50-348 g 50-348 g
ORIER, B. H.	7912190036 7912190039 7912190041 7912190044 7912190049	50-307 0 50-245 0 50-410 0 50-220 0 50-286 0	ORIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H.	7912280227 7912280230 7912280234 7912280234 7912280234	50-277 G 50-387 G 50-272 G 50-311 G 50-443 G	Hairston, W. O. Hairston, M. O. Hairston, M. G. Hairston, W. O. Hairston, W. G.	7912110338+ 7912110339+ 7912120433+ 7912120459+ 7912270228+	50-348 8 50-348 8 50-348 8 50-348 8
CRIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, B. H.	7912190055 7912190059 7912190063 7912190065 7912190071	50-333	GRIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, D. H. GRIFFIN, W.	7912280244 7912280246 7912280248 7912280252 7912130611	50-244 0 50-485 0 50-271 9 50-29 0 PR	HAIRSTON, W. G. HAIRSTON, W. G. HAIST, D. P. HALE, C. J. HALE, C. J.	7912270238# 7912310451# 7912110493# 7912110052# 7912260204#	50-348 B 50-348 B 50-508 B GA779 GA779
ORIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H.	7912170075 7912170078 7912190087 7912190089 7912190094	50-354 Q 50-272 Q 50-443 Q 50-485 Q 50-244 Q	GRIFFIN.H. GRIFFITHS.R. GRIFFITH.R.V. GRIFFITH.J.S. GRIGO.N.S.	7912130619* 7912040374 7912170359 7912170561 7912180217*	PR 50-272 J RES RES 50-466 Q	HALE, C. J. HALE, C. J. HALE, C. J. HALE, C. J. HALE, C. J.	7912110133* 7912110061* 7912100409* 7912110081* 7912170398*	GA799 GA799 GA799 GA799 GA799
ORIER.B.H. ORIER.B.H. ORIER.B.H. ORIER.B.H. ORIER.B.H.	7912190095 7912190099 7912310204 7912310205 7912310209	50-271	orimes, c. I. Orimes, b. K. Orimes, b. K. Orimes, b. K. Orisham, d.	7912310545 7912190133 7912310013 7912200022 7912120526*	GEN TEC 18 NUREQ POR MISC 90-3 F NUREO	HALE, C, J, HALE, C, J, HALE, C, J, HALL, R, E, HALL, R, E,	7912140545# 7912180142# 7912110516# 7912100005 7912050531#	GA999 GA999 GA999 RE8 50-382 <b>G</b>
GRIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, B. H. ORIER, B. H.	7912310210 7912310211 7912310213 7912310216 7912310219	50-213 G 50-412 G 50-334 G 50-219 G 50-343 G	Groce, R. H. Groce, R. H. Groce, R. H. Groce, R. H. Groce, R. H.	7912120536 7912040057 7912040019 7912130086 7912310472	50-309 @ 50-309 @ 50-309 @ 50-309 @ 50-309 @	HALLIOAN, T. J. HALLMAN, D. HAMADA, Q. HARMOND, E. L. HAMMOND, E. L.	7912050207 7912040412* 7912070376* 7912050505 7912110340	50-367 9 50-312 P FDIA 50-331 8 50-331 8
GRIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, B. H.	7912310220 7912310224 7912310226 7912310228 7912310232	50-322	GROCE, R. H. GROCE, R. H. OROCE, R. H. GROCE, R. H. GROCE, R. H.	7912120218 7912140370 7912130096 7912030175 7912040208	50-29 g 50-29 p 50-29 g 50-29 p 50-29 p	HAMMOND, E. L. HAN, J. T. HANGOCK, J. A. HANGOCK, J. A. HANGOCK, J. A.	7912180614 7912120190 7912060666* 7912100207 7912030154	50-331 9 NUREO 50-302 0 50-302 0 50-302 8
ORIER, B. H. ORIER, G. H. ORIER, B. H. ORIER, B. H. ORIER, B. H.	7912310234 7912310235 7912310237 7912310241 7912310242	50-284 q 50-333 q 50-277 q 50-352 q 50-387 q	QROBSMAN, H. QROBSMAN, H. QROBSMAN, H. QROBSMAN, H. QROTEMHUIB, M.	7912060120 7912100355 7912100319 7912190344 7912120070	50-321 0 50-402 0 50-155 0 50-155 T 50-250 P	HANGOCK, J. A. HANGOCK, J. A. HANGOCK, J. A. HANGOCK, J. A. HANGOCK, J. A.	7912070460 7912100269 7912110410 7912110330 7912140222	50-302 P 50-302 B 50-302 P 50-302 B 50-302 P
ORIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H.	7912310244 7912310246 7912310248 7912310250 7912310252	50-311 G 50-272 Q 50-443 Q 50-244 Q 50-485 Q	GROTENHUIS, M. GROTENHUIS, M. GRUSH, M. H. GUHBLE, F. H. GUMBLE, F. W.	7912120103 7912210008 7912190567 7912040321* 7912040369*	50-282 P 50-282 P RES 50-284 B 50-286 B	HANCOCK, J. A. HANCOCK, J. A. HANCOCK, J. A. HANCOCK, J. A. HANCOCK, J. A.	7912140239 7912310018 7912310016 7912180371 7912260245	50-302 F 50-302 Q 50-302 Q 50-302 R 50-302 F
ORIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H.	7912310253 7912310284 7912190833 7912190731 7912190734	50~271	Gumble, F. N. Gumble, F. W. Gumble, F. W. Guppy, J. Q. Gubtave, R. P.	7912110333* 7912180582* 7912270862* 7912040119 7912110003	50-286 8 50-286 8 50-286 8 RES CONTRACT	HANGOCK, J. A. HANGOCK, J. A. HANKEY, D. HANNON, J. N. HANNON, J. N.	7912260239 7912270575 7912280492* 7912110428 7912260077	50-302 g 50-302 p 50-269 U 50-293 F 50-293 p
CRIER, B. H. ORIER, B. H. GRIER, B. H. ORIER, B. H. GRIER, B. H.	7912190736 7912190739 7912190744 7912190747 7912190748	50-213 0 50-334 0 50-412 0 50-363 0 50-217 0	Gustave, R. P. Guthan, J. B. Guthan, J. S. Haasb, W. P. Haasb, W. P.	7912180006 7912070284 7912070280 7912180024 7912120334	CONTRACT FOIA FOIA TOPREP 50-313 P	HANBEN, L. E. HANBEN, L. E. HANBEN, L. E. HANBELL, D. HANBELL, D,	7912200029* 7912200008 7912200011* 7912170180* 7912030024	71-6581 71-6581 71-6581 40-2061 40-2061
GRIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, B. H.	7912190750 7912190752 7912190753 7912190754 7912190756	50-322 0 50-289 0 50-309 0 50-245 0 50-410 0	наава, и. р. Наава, и. р. Наава, и. р. Наава, и. р. Наава, и. р.	7912310236 7912310243* 7912310251* 7912310257* 7912310258*	50-320 H 50-320 H 50-320 H 50-320 H 50-320 H	HANBELL, D. HANBEN, D. B. HANBEN, L. E. HANBEN, H. A. HANBEN, H. A.	7912190217 7912070440* 7912200015* 7912180378 7913210033*	40-2061 50-292 4 71-6591 50-463 8 50-483 9
ORIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, B. H. ORIER, B. H.	7912190757 7912190758 7912190760 7912190761 7912190762	50-220 Q 50-284 Q 50-333 Q 50-277 Q 50-352 Q	HACKNEY, R. HADLEY, J. B. HAEUSSNER, T. E. HAEUSSNER, T. E. HAFER, F. D.	7912040221* 7912140423* 7912190664* 7912190659* 7912040345	50~267 P RES 50~219 P 50~219 P 50~289 I	HANBON, Q. E. HARDIN, A. K. HARDIN, A. X. HARDIN, A. K. HAROSIT, D.	7912130009# 7912180324 7912180291 7912070097# 7912100363*	TOPREP 50-250 8 50-335 8 50-348 0 CONTRACT
GRIER.B.H. GRIER.S.H. GRIER.B.H. GRIER.B.H. GRIER.B.H.	7912190763 7912190764 7912190765 7912190766 7912190767	50-387 g 50-272 g 50-3(1 g 50-443 g 60-485 g	HAFER: F. D. HAFER: F. D. HAFER: F. D. HAFER: F. D. MAFF: K. W.	7912040087 7912050511 7912130243 7912260219 7912180700	50-289 I 50-269 I 50-289 G 50-289 I ORG	HARMON, D. W. HARMON, D. W. HARMON, D. W. HARMON, D. W. HARMON, D. W.	7912030218* 7912060178 7912180096 7912180106	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
ORIER, B. H. CRIER, B. H. ORIER, B. H. ORIER, B. H. GRIER, B. H.	7912190769 7912190770 7912190772 7912280181 7912280183	50-244 Q 50-271 Q 50-27 Q 50-293 Q 50-317 Q	HAGAN, T. F.	7912200177 7912210382 7912210385 7912200149 7912200190	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	Harmon, D. W. Harmon, D. Harmis, G. E. Harris, J. B. Harris, J. B.	7912170369 7912140122 7912170144# 7912180601#	XPORTLIC XPORTLIC 71-9009 50-335 8 50-335 8

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBSION NUMBER	SUBJECT CATEGORY	AUTHDR	ACCESSION NUMBER	SUBJECT CATEGORY
HARRIBON, F. L.	7912170544	REB	HENDRIE, J. M.	7912170013	50-70 0	HERSLOFT, L. W. HESTERMAN, I. F. HEWARD, R. W. HEWARD, R. W. HIATT, J. W.	7912270252	40-8452
HARRIBON, J. J.	7912110286*	50-546 G	HENDRIE, J. M.	7912060859*	FOIA		7912200019	50-298 8
HARRIBON, H. C.	7912280360*	40-2259	HENDRIE, J. M.	7912270062	COMMISSION		7912280437*	50-320 P
HARRIBON, H.	7912310298	I&E	HENDRIE, J. M.	7912050871*	State Prog		7912130441*	50-320 P
HARRIBON, G. A.	7912310298	50-322 G	HENDRIE, J. M.	7912050573*	State Prog		7912050315*	50-264 0
HART, H. C. HARTON, J. J. HARHOOD, T. P. HARWOOD, T. P. HAWEER, R. D.	7912200170 7912070387 7912130410 7912200370* 7912210141	71-5957 50-313 J 50-339 H 50-339 A XPORTLIC	HENDRIE, J. M. HENDRIE, J. M. HENDRIE, J. M. HENDRIE, J. M. HENDRIE, J. M.	7912050578* 7912050581* 7912130241 7912130314* 7912310126	State Prop State Prop 50-320 U 50-320 U COMMISSION	Hiatt, J. H. Hickey, C. R. Hickin, R. A. Hickle, B. J. Hicke, H. M.	7912070270* 7912180207 7912180019* 7912140352* 7912310360	90-10 G NUREO CONTRACT 50-289 R REGOD
HANKING D. C. HANKING D. C. HANKING F. C. HANKING F. C. HAYES P. J.	7912040179* 7912200114 7912110286* 7912130136* 7912110375	50-320 G PR 50-546 G 50-546 G 50-574 G	HENDRIE: J. M.	7912200034 7912270122 7912270125* 7912270131* 7912270135*	COMMISSION COMMISSION COMMISSION COMMISSION	HIGOINS, J. C. HILL, C. F. HILL, C. F. HINCKLEY, W. W. HIND, J. A.	7912070202* 7912130324 7912130326* 7912100386* 7912120068	50-322 0 FR FR CONTRACT 50-10 S
HAYES, J. K. HAYES, D. H. HAYES, D. H. HAYES, D. H. HAYES, D. H.	7912140229 7912030263* 7912110286* 7912130136* 7912180236*	50-250 B 50-329 Q 50-546 Q 50-546 Q 50-295 Q	HENDRIE; J. M. HENDRIE; J. M. HENDRIE; J. M. HENDRIE; J. M. HENDRIE; J. M.	7912270149* 7912270154* 7912270158* 7912270160* 7912270163	COMPISSION COMPISSION COMPISSION COMPISSION	HIND: J. A. HIND: J. A. HIND: J. A. HIND: J. A. HIND: J. A.	7912170186 7912180027 7912030105 7912130679 7912110275*	50-10 5 50-440 8 50-461 8 50-10 9 70-36
Hayes, D. W.	7912210031*	50-237 G	HENDRIE: J. M.	7912270192	COMMISSION	HIND, J. A.	7912120085*	50-305 G
Hayes, D. W.	7912050052*	50-440 G	HENDRIE: J. M.	7912270110	COMMISSION	HIND, J. A.	7912110222	70-34
Haynes, J. C.	7912120443	50-206 F	HENDRIE: J. M.	7912270117*	COMMISSION	HIND, J. A.	7912120079	50-305 G
Haynes, J. C.	7912140340	50-206 P	HENDRIE: J. H.	7912200334*	50-339 A	HINES, E.	7912120562*	50-341 G
Hayles, A. J.	7912040030	PROJ	HENDRIE: J. M.	7912200345*	50-339 A	HIRATA, Y.	7912210210*	QA999
HAZLE, A. J. HEAD, J. T. HEAD, J. T. HEAD, J. T. HEAD, J. T.	7912210091 7912210142 7912040468 7912040397 7912180528	Wabte Mgt 50-204	HENDRIE, J. H. HENDRIE, J. M. HENDRIE, J. M. HENDRIE, J. M. HENDRIE, J. M.	7912270083 7912270080 7912270102 7912270107 7912270069	COMMISSION COMMISSION COMMISSION SO-330 P	HIRATA, Y. HIRBOU, D. O. HJELMFELT, D. C. HJELMFELT, D. C. HLOWATY. R.	7912210201* 7912190105* 7912190232 7912180344 7912280465*	GA999 50-142 G 50-348 H 50-346 H 50-320 H
HEAD, J. T.	7912170292	50-206 S	HENDRIE, J. H.	7912270092	50-338 P	HLUCHAN; R. M.	7912130299	PR
HEAD, J. T.	7912170311	50-206 B	HENDRIE, J. M.	7912270097	COMMISSION	HOBBON; J. W.	7912050661*	50-142 P
HEAD, J. T.	7912180609	50-206 B	HENRIKGON, P. H.	7912040249*	50-263 P	HODDER; M. H.	7912270147	50-387 O
HEARNE, T. J.	7912110393	50-482 Q	HERBERT, B.	7912030194*	50-237 B	HODDER; M. H.	7912270150*	50-387 G
HEARNE, T. J.	7912170083	50-482 Q	HERBEIN, J. O.	7912040453*	50-289 Q	HODDON; A. P.	7912130094	50-445 M
igedeman, H, N.	7912260203	PROJ	Herbe in. J. O.	7912170220	50-287 0	HODODON: A. HODODON: A. P. HOEFLING: R. K. HOEFLING: R. K. HOEFLING: R. K.	7912260081	50-445 H
Heibel, R. P.	7912060454*	50-317 8	Herbe in. J. O.	7912180494	50-287 0		7912130236	50-445 H
Heibel, R. P.	7912060485*	50-317 8	Herbe in. J. G.	7912130367	50-287 S		7912060079*	50-322 O
Heibel, R. P.	7912060499*	50-317 8	Herbe in. J. O.	7912030170	50-320 F		7912050318	70-2623
Heibel, R. P.	7912130543*	50-317 8	Herbe in. J. O.	7912070136	50-320 F		7912100137	50-312 G
HEIDEL, C.M.	7912270448	50-341 A	HERBEIN, J. O.	7912050320	50-287 P	HOEFLING, R. K.	7912100143#	50-312
HEISHMAN, R.F.	7912200435	50-346 B	HERBEIN, J. O.	7912060340	50-287 P	HOEFLING, R. K.	7912100147#	
HEISHMAN, R.F.	7912260364	50-331 B	HERBEIN, J. O.	7912060346	50-287 P	HOEFLING, R. K.	7912100153#	
HEISHMAN, R.F.	7912310088	50-346 B	HERBEIN, J. O.	7912100328	50-287 P	HOEFLING, R. K.	7912100158#	
HEISHMAN, R.F.	7912160373	50-295 B	HERBEIN, J. G.	7912120335	50-287 B	HOEFLING, R. K.	7912100161#	
HE ISHMAN, R. F.	7912200564	50-346 8	HERBE IN. J. Q.	7912120414	50-289 P	Hoefiling, R. K.	79121700B2	50-312 0
SHE ISHMAN, R. F.	7912310045	50-295 8		7912270323	50-289 8	Hoefiling, R. K.	7912100135	70-2623
HE ISHMAN, R. F.	7912310095	50-295 8		7912200513	50-289 P	Hoefiling, R. K.	7912130038	50-322 0
HE ISHMAN, R. F.	7912070066	50-346 0		7912180254	50-287 P	Hoefiling, R. K.	7912190178	50-322 0
HE ISHMAN, R. F.	7912070143	50-247 6		7912200365	50-289 R	Hoefiling, R. K.	7912170158	50-312 0
HE LEHMAN R. F.	7912120061	80-318 B	HERBE IN, J. O.	7912270523	50-289 P	HOEFLING, R. K.	7912170266	50-312 0
HE ISHMAN R. F.	7912030088	50-10 B	HERBE IN, J. G.	7912310378	50-289 P	HOEFLING, R. K.	7912180048	50-312 0
HE ISHMAN R. F.	7912060654	50-295 B	HERBE IN, J. G.	7912310382	50-289 F	HOEFLING, R. K.	7912240327	50-312 0
HE ISHMAN R. F.	7912060630	50-304 B	HERDT, A. R.	7912210039	50-516 B	HOEFLING, R. K.	7912240329*	50-312 0
HE ISHMAN R. F.	7912170390	80-10 S	HERDT, A. R.	7912310300#	50-348 Q	HOEFLING, R. K.	7912260344*	50-312 0
HE ISHMAN, R. F.	7912170423	50-282 8	HERDT, A. R.	7912070112#	50-280 0	HOEFLING, R. K.	7912260345*	50-312 G
HE ISHMAN, R. F.	7912050050	50-275 G	HERDT, A. R.	7912110214#	50-389 0	HOFFMAN, H.	7912280512	50-275 Q
HE ISHMAN, R. F.	7912050013	50-10 G	HERDT, A. R.	7912060495#	50-280 0	HOFFMAN, G. L.	7912170143	40-2259
HE ISHMAN, R. F.	7912050028	50-305 G	HERDT, A. R.	7912060486#	50-327 9	HOFFMAN, R.	7912280182*	WASTE HOT
HE ISHMAN, R. F.	7912050220	50-409 G	HERDT, A. R.	7912050395#	50-327 0	HOFFMAN, D. P.	7912060210	50-255 G
HEIBHMAN R. F.	7912110257	50-315 Q	HERDT, A. R.	7912050618*	50-416 0	HOFFMAN, D. P.	7912200678	50-255 0
HEIBHMAN R. F.	7912050400	50-305 Q	HERDT, A. R.	7912050338*	50-518 0	HOFFMAN, D. P.	7912040219	50-255 0
HEIBHMAN R. F.	7912070079#	50-346 Q	HERDT, A. R.	7912050555*	50-281 0	HOFFMAN, D. P.	7912310491	REGOD
HEIBHMAN R. F.	7912050401	50-282 Q	HERDT, A. R.	7912050622*	50-280 0	HOFFMAN, D. P.	7912050497	50-155 P
HEIBHMAN R. F.	7912050348	50-346 Q	HERDT, A. R.	7912050089*	50-416 0	HOFFMAN, D. P.	7912060446	50-155 B
HE ISHMAN, R. F.	7912260102	90-282 0	HERDT, A. R.	7912210172*	50~471	HOFFMAN, D. P.	7912060621	50-155 P
HE ISHMAN, R. F.	7912210150	50-373 G	HERDT, A. R.	7912050532*		HOFFMAN, D. P.	7912100374	50-155 P
HE ISHMAN, R. F.	7912200242	50-344 O	HERDT, A. R.	7912180145*		HOFFMAN, D. P.	7912170235	50-155 P
HE ISHMAN, R. F.	7912210066	50-282 G	HERDT, A. R.	7912050438*		HOFFMAN, D. P.	7912180604	50-155 F
HE ISHMAN, R. F.	7912260140	50-153 G	HERDT, A. R.	7912210218*		HOFFMAN, D. P.	7912180508	50-255 8
HEISHMAN, R. F.	7912040009	50-10 9	HERDT, A. R.	7912310115*	50-291	HOFFMAN, D. P.	7912190466	50-255 P
HEISHMAN, R. F.	7912050667	50-282 G	HERDT, A. R.	7912310100*		HOFFMAN, D. P.	7912310458	50-155 P
HEISHMAN, R. F.	7912210140	50-346 G	HERDT, A. R.	7912310287*		HOFFMAN, D. P.	7912310476	50-255 P
HEIGEBON, Q. L.	7912170285*	40-2259	HERDT, A. R.	7912240151*		HOFFMAN, D. P.	7912310355	50-155 P
HEIGHAUS, Q. L.	7912200020*	71-6581	HERRELL, D. C.	7912110324*		HOFFMAN, D. P.	7912310364	50-255 S
HELLER, L. W.	7912190205	00-367 A PDR MIGC XPDRTLIC 50-337 A 50-255 P	Herring, K. B.	7908030578	50-244 P	HOFFMAN, J. R.	7912040348	50-29 P
PELLER, L. W.	7912180316*		Herring, K. B.	7912170223*	50-344 Q	HOFFMAN, J. R.	7912280518	NUREG
PELM, K.	7912180003		Herring, K. B.	7912170229*	50-344 Q	HOFMAYER, C. H.	7912130008	50-219 P
PELMS, J.	7912200388*		Herring, K. B.	7912170248*	50-344 Q	HOLCOMB, D. D.	7912180185#	GA799
PENDERBON, S. A.	7912310495*		Herring, K. B.	7912310263	FDR MISC	HOLLAND, P.	7912030166#	50-249 E
HENDRICK, N. G. HENDRICK, N. G. HENDRICKS, D. H. HENDRIE, J. M. HENDRIE, J. M.	7912280656 7912280653* 7912280676* 7912190321* 7912170004	XPORTLIC XPORTLIC 27-10 ACRE 50-70 9	HERRINO, K. S. HERRMANN, H. HERRMANN, H. HERSCH, M. M. HERSCHLER, E.	7912280137* 7912120358 7912180455 7912210099 7912310212	50-344 0 50-471 0 50-471 0 XPORTLIC 40-8745	HOLLAND, P. HOLLINGBHAW, H. HOLLOWAY, C. J. HOLLOWAY, C. J. HOLLOWAY, D. J.	7912140404* 7912040353* 7912130226* 7912100039* 7912120560*	50-286 P

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY
HOLODY, D. J.	7912260074* 7912190781* 7912200308* 7912110275* 7912190393	50-54 G 70-1100 70-33 70-36 50-320 G	HUNSTAD, A. A. HUNT, J. S. HUNT, M. D. HUNT, D. HUNTER, R. S.	7912310478* 7912200362* 7912170016* 7912200471 7912270284	50-282 B 50-337 A 50-364 Q 50-364 B 50-316 P	Jenkins, G. R. Jenkins, G. R. Jens, W. H. Jens, W. H. Jens, W. H.	7912100467* 7912310086* 7912200020* 7912040508 7912140428	50-375 Q 50-387 Q 71-658( 50-341 A 50-341 A
HOLTZCLAW, K. W. HONKONEN, D. L. HOUD, D. HOUD, D. HOUD, D. S.	7912180196* 7912210434* 7912050305* 7912140175 7912070511	F01A 71-5467 50-929 A 50-929 A 50-929 A	HUSEBY, D. E. HUSEBY, D. E. HUSEBY, D. E. HUSEBY, D. E. HUSTON, R. W.	7912310357* 7912060454* 7912180602* 7912180619* 7912140407	50-317 S 50-317 S 50-317 B 50-317 B 50-155 S	JENB, W. H. JENB, W. H. JENTZ, T. L. JERMAN, P. C. JERMAN, P.	7912270555 7912270569* 7912120023 7912310321 7912310051	50-341 A 50-341 A Recor 1&E 1&E
HDDD: D. S. HDDD: D. HDDK: J. O. HDPKINS: H. R. HDRN: A. J.	7912110406 7912120297 7912280565* 7912110045* 7912060104*	50-329 A 50-329 A 50-329 S CGNTRACT 50-275 Q	HUSTON, R. W. HUSTON, R. W. HUSTON, R. W. HUSTON, R. W. HUTSON, T. W.	7912140412 7912140415 7912210146 7912210162 7912060047*	50-185 B 50-255 P 50-185 P 50-155 P 50-528 G	JERNIGAN, E. P. JERNIGAN, E. P. JDCDB8, B. B. JDHN, D. F. JDHN, D. F.	7912280392* 7912260056* 7912280185 7912140202 7912270084	50-320 Q 50-289 Q REGOD 50-445 H 50-443 H
HORN, A. HORNE, C. O. HOSEY, C. M. HOSFORD, S. B. HOSFORD, S. B.	7912050096* 7912200316* 7912200012 7912200098 7912120092	50-206 Q 50-339 A 50-287 8 50-29 P 50-269 P	HUTSON, T. W. IANNI, P. W. INDYKE, C. M. INMAN, O. W. IPPOLITO, T. A.	7912060065* 7912130500* 7912260282 7912190552 7912050279	50-275 Q 50-447 A 50-596 Q RES 50-271 P	JOHN, D, F. JOHN, D. F. JOHN, W. N. JOHNS, S. J. JOHNSRUD, J. H.	7912270084 7912270084 7912210283* 7912210443* 7912120063	50-445 M 50-445 M 50-269 Q 50-155 Q PROJ
HOSFORD, S. B. HOUGHTON, T. C. HOUGHTON, T. C. HOUGHTON, T. C. HOUGHTON, R. W.	7912120262 7912110251 7912130127 7912210084 7912170399*	50-255 P 50-416 A 50-416 A 50-414 F FO1A	IPPOLITO, T. A.	7912050272* 7912050307* 7912170039 7912030233 7912030235*	90-271 P 50-271 P 50-285 P 50-331 P 50-331 P	JOHNBRUD, J. JOHNBRUD, J. JOHNBRUD, J. JOHNBON, C. JOHNBON, C.	7912280614 7912130562* 7912130569 7912140188* 7912140091	PR PR PR 50~455 0 50~466 0
HOWARD, T. R. HOWARD, E. D. HOWARD, J. E. HOWARD, J. E. HOWE, P. W.	7912280638 7912210243 7912260242 7912270320 7912110306	40-3453 PR 50-293 P 50-293 P 50-400 Q	IPPOLITO, T. A.	7912030240* 7912070476 7912070493* 7912070485* 7912070497	50-331 P 50-273 P 50-273 P 50-273 P 50-344 P	JOHNSON, C. JOHNSON, C. JOHNSON, J. D. JOHNSON, N. JOHNSON, B. L.	7912180170 7912140081 7912190552 7912210027 7912280240*	50-464 0 50-466 0 RES XPORTLIC 50-244 P
HOWELL, S. H. HOWELL, S. H. HOWELL, S. H. HOWELL, B. H. HOWELL, S. H.	7912060015* 7912040110 7912120180* 7912030155 7912030188	50-329 G 50-329 R 50-329 G 50-329 C 50-329 C	IPPOLITO, T. A.	7912070501* 7912070508* 7912260018 7912180064 7912190343	50~366 P 50~364 P 50~259 P 50~331 P 50~366 P	JOHNBON, E. JOHNBON, E. JOHNBON, E. JOHNBON, E. JOHNBON, E. JOHNBON, P. O.	7912240141* 7912240138* 7912240125* 7912260104* 7912280344	GA999 GA999 GA999 GA999 BO-320 H
HOWELL, S. H. HOWELL, S. H. HOWELL, S. H. HOWELL, S. H. HOWELL, S. H.	7912040286 7912070451 7912110358 7912130219 7912180176	50-329 A 50-329 A 50-329 S 50-329 S 50-329 S	TPPOLITO, T. A. IPPOLITO, T. A.	7912280178 7912280189 7912140007 7912140250 7912130439	50~293 P 50~293 P 50~293 F 50~293 P 50~296 P	JOHNBON, J. M. JOHNBTON, G. L. JOHNBON, G. L. JOHNBON, G. L. JOHNBON, G. L.	7912180646 7912180590* 7912310434* 7912180434* 7912180443*	FOIA 50-409 B 50-366 R 50-321 R 50-366 R
HOWELL, S. H. HOWELL, S. H. HOWELL, S. H. HOWELL, S. H. HOWELL, S. H.	7912180526 7912110365 7912130544 7912270193 7912270197*	50-329 8 50-329 8 50-329 8 50-329 A 50-329 A	IPPOLITO, T. A. IRELAND, A.	7912130706# 7912130726# 7912270063 7912170106 7912120546#	50-294 P 50-294 P 50-10 F 50-293 P PDR MIBC	JOHNSON, M. C. JOHNSON, M. C. JOHNSON, W. A. JOHNSON, W. P.	7912060585* 7912100463 7912190563 7912190334 7912140152	50-395 9 50-395 9 50-395 8 50-346 K
HOWELL, S. H. HOWELL, S. H. HOWELL, J. C. HOWELL, J. C.	7912280483 7912280522 7912280560 7912210283* 7912030074*	50-329 8 50-329 R 50-329 8 50-249 Q 50-338 Q	IRELAND, J. H. IRVING, B. M. IRVING, S. M. IRVING, S. M. IRVING, S. M.	7912040447 7912200025 7912260210 7912260213* 7912200025	50-155 J 50-382 G 50-382 G 50-382 G 50-382 G	JOHNSON, W. P. JOHNSON, W. R. JOHNSON, D. JOHNSON, D. JOHNSON, R.	7912280121 7912180032 7912200456 7912200542 7912200067*	NUREO 50-556 0 50-317 8 50-309 B 50-247 0
HOMLETT, E. NOHLETT, G. H. INBACEK, W. G. HUBACEK, W. G. HUBACEK, W. G. HUDDLESTON, W. D.	7912170143 7912180403* 7912060670 7912280329* 7912210089*	402259 50-334 R 50499 S 50-498 Q 50-358 U	IRWIN; D. P. IRWIN; D. P. JABLON; R. A. JABLON; R. A. JABLON; R. A.	7912130317 7912130317 7912130327 7912200287 79122060020	PR PR 50-445 M 50-387 M 50-250 M	JOHNBON, J. JOHNBON, J. JOHNBON, A. H, JOHNBON, A. H. JOHNBON, N. D.	7712310131* 7712040058* 7712040215* 7712180121* 7912050342*	50-284 9 50-277 0 50-369 0 50-302 0 50-313 0
HUEBEL, J. O. HUFHAM, J. W. HUFHAM, J. W. HUFHAM, J. H. HUFHAM, J. H.	7912050005 7712310315 7912180364* 7912100461* 7912100274*	NUREG 1&E 50-335 Q 50-335 Q	JAILEN, R. A. JABLONSKI, F. J. JACKSON, O. M. JACKSON, G. JACKSON, T. J.	7912200287 7912260169* 7912180475* 7912280102* 7912050116*	50-387 M 50-367 G 50-275 U 40-8674 50-277 G	JDHNSON, J. M. JOHNSON, J. M. JOHNSON, P. JOHNSON, A. D. JOHNSON, R.	7912110052* 7912170398* 7912050260* 7912070198* 7912200401	GA999 GA999 50-312 G 50-89 G 50-389 T
HUFHAM, J. W. HUFHAM, J. W. HUFHAM, J. W. HUFHAM, J. W. HUGHES, W. G.	7912050666* 7912060134* 7912120255* 7912210088* 7912270361	50-566 Q 50-261 Q 50-327 Q 50-269 Q 50-206 I	JACKSON, L. L. JACKSON, R. E. JACOBS, B. B. JACOBS, A. JACOBS, A.	7912040467* 7912270126 7912280155 7912060167 7912110529	50-327 G WASTE MOT REGOD CONTRACT CONTRACT	JOHNSON, R. JOHNBON, R. JONES, L. L. JONES, L. L. JONES, L. L.	7912200413 7912200425 7912200587 7912120345 7912120352*	50-389 T 50-389 T 50-389 T 50-382 0 50-382 0
HUCHES, J. HULHAN, L. G. HULHAN, L. G. HULHAN, L. G. HUNNI CUTT, D. N.	7912050052* 7809270104* 7809270093 7912200083 7912120118*	50-440 Q 50-269 P 50-269 P 50-262 P GA799	JACOBS, A, JADMIN, D, JAFFE, S, JANEGEK, R. F. JANEGEK, R. F.	7912120261 7912070470 7912190175 7912120323 7912070417	CONTRACT 50-155 Q FOIA 50-10 P 50-10 P	JONES, Y. I. JONES, D. H. JONES, B. M. JONES, D. H. JONES, R. D.	7912130615 7912100394* 7912210297	50-275 G 50-538 8 CONTRACT 50-538 J PDR HISC
HUNNICUTT, D. M.	7912210034* 7912180194* 7912210233* 7912180273* 7912100415*	QA779 QA799 QA799 QA799 QA799	JANECEK, R. F. JANECEK, R. F. JANECEK, R. F. JANECEK, R. F. JANECEK, R. F.	7912310361 7912140266 7912190542 7912310370 7912270345	50-10 P 50-10 P 50-237 P 50-237 P 50-10 S	JDNES, L. L. JONES, L. L. JONES, J. A. JONES, J. A. JONES, J. A.	7912120352* 7912130452* 7912130461*	50-382 0 50-382 0 50-400 8 30-400 8
HUNNICUTT, D. M. HUNSTAD, A. A.	7912110088* 7912110071* 7912120293* 7912240159* 7912030202*	QA797 QA799 QA799 QA797 50-304 8	JANECEK, R. F. JANECEK, R. F. JANECEK, R. F. JANECEK, R. F. JEFFERSON, K.	7912280605 7912270394 7912270459 7912310348 7912330066	50-10 H 50-204 S 50-297 P 50-10 F XPORTLIC	JONES, W. C. JONES, W. C. JONES, W. C. JONES, W. C. JONES, W. C.	7912210105 7912170195 7912030212	50-285 @ 50-285 @ 50-285 @ 50-285 P 50-285 P
HUNGTAD, A. A. HUNGTAD, A. A. HUNGTAD, A. A. HUNGTAD, A. A. HUNGTAD, A. A.	7912180628* 7912180634* 7912180636* 7912180640* 7912270498*	50-282 R 50-282 R 50-282 R 50-282 R 50-282 S	JENCKER, T. A. JENG, D. C. JENKINS, C. R. JENKINS, G. R.	7912310184 7912180307* 7912180321* 7912030083* 7912120005	REGOD PDR MISC PDR MISC 50-241 Q 50-327 S	JONES: W. C. JONES: W. C. JONES: W. C. JONES: W. C. JONES: W. C.	7912070463 7912140347 7912140397	50-285 P 50-285 P 50-285 A 50-285 P 50-285 F

AUTHOR		BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION HUMBER	SUBJECT CATEGORY
JONES, N. C. JONES, N. C. JONES, N. C. JONES, N. C. JONES, D. C.	7912190965 5 7912270270 5 7912270376	60-205 H 60-205 P 60-285 P 60-285 P FORREP	KEENAN, R. P. KEENAN, R. P. KEENAN, T. D. KEIHIG, R. R. KEIHIG, R.	7912130102* 7912030110 7912310521 7912260010 7912200456	XPORTLIC XPORTLIC 50-271 P 50-272 S 50-317 S	KEPPLER, J. Q. KEPPLER, J. Q. KEPPLER, J. Q. KEPPLER, J. Q. KEPPLER, J. Q.	7912050124 7912050126 7912050128 7912050130 7912050140	50-34: 0 50-33: 0 50-46: 9 90-315 0 50-367 0
JONES, D. C. JONES, D. C. JONES, L. M. JONES, L. M. JONES, L. M.	7912040123 7912040123 7912200493	roprer Res Res 50–272 S 50–286 S	Keihio, R. R. Keihio, R. Keihio, R. Keihio, R. R. Keihio, R. R.	7912100253* 7912200542 7912030104 7912180309 7912060221*	50-334 0 50-309 S 50-245 S 50-245 S 50-334 0	KEPPLER, J. Q. KEPPLER, J. Q. KEPPLER, J. Q. KEPPLER, J. Q. KEPPLER, J. Q.	7912050144 7912050147 7912050149 7912050162 7912050154	50-283 0 50-580 0 50-545 0 50-346 0 50-483 0
JONES, D. U. JONES, D. U. JONES, D. U.	7912050262* 7912260071# 7912180213	50-29 Q 50-293 Q 70-1143 50-259 S 70-1151	KEIHIO, R. R. KEIHIG, R. R. KEIHIG, R. R. KEIHIO, R. R. KEIHIO, R. R.	7912100199* 791203004* 7912050076* 7912210363* 7912190797*	50-213 Q 50-272 Q 50-272 Q 50-244 Q 50-213 Q	KEPPLER, J. Q. KEPPLER, J. Q. KEPPLER, J. Q. KEPPLER, J. Q. KEPPLER, J. Q.	7912050156 7912050158 7912108209 7912100213 7912100218	50-285 G 50-365 G 50-315 G 50-10 G 50-358 G
JONES I C. E. JONES I C. E. JORDANI II. S. JORDANI II. S. JORDANI II. S.	7912260153* 7912060238 7912060242*	50-456 G 50-546 G 50-289 O 50-289 O 50-289 O	KEIMIO, R. R. KEIMIO, R. R. KEIMIO, R. KEIMIO, R. R. KELBLEY, N. D.	7912200067* 7912200046* 7912210131* 7912260302* 7912060081	50-247 0 50-272 0 50-286 0 50-29 9 71-5796	KEPPLER, J. C. KEPPLER, J. C. KEPPLER, J. C. KEPPLER, J. C. KEPPLER, J. C.	7912100221 7912100223 7912100226 7 <del>9</del> 12160227 7912100230	50-440
JORDANI W. S. JORDANI W. S. JORDANI W. S. JORDANI W. S. JORDANI W. S.	7912050230 7912050242* 7912130026	50-287 0 50-287 0 50-287 0 50-287 0 50-289 0	KELBLEY, N. D. KELLEY, D. L. KELLEY, H. D. KELLEY, H. D. KELLOGO, P. J.	7912070509 7912130359= 7912050544* 7912210199= 7912190751	71~5796 50~131	KEPPLER, J. Q. KEPPLER, J. Q. KEPPLER, J. Q. KEPPLER, J. Q. KEPPLER, J. Q.	7912100232 7912100233 7912100235 7912100239 7912100241	50-331 0 50-461 0 50-367 0 50-263 0 50-560 0
JOREDAN, N. G. JOREDAN, E. L. JOREDAN, E. L. JOREDAN, E. L. JOREDAN, E. L.	7912270011 7908140309* 7912050027 7912040135 7912130150	50-289 0 PDR HISC 50-255 0 50-346 0 50-255 0	KELLOGO, P. J. KELLOGO, P. J. KELLOGO, P. J. KELLOGO, P. J. KELLOGO, P. J.	7912200423 7912210060 7912260019 7912210045 7912070046	50-280 S 50-325 S 50-325 S 50-280 S 50-338 S	KEPPLER, J. G. KEPPLER, J. G. KEPPLER, J. G. KEPPLER, J. G. KEPPLER, J. G.	7912100243 7912100244 7912100248 7912100249 7912100252	50-545 0 50-345 0 50-483 0 50-266 0 50-305 0
JORDAN, E. L. JORDENSEN, B. L. JOYNER, J. H. JOYNER, J. H. JOYNER, J. H.	7912200443 7912310064 7912270180# 7912120560# 7912030141#	50-10 0 71-250 70-1143 70-820 70-135	KELLOGO, P. J. KELLOGO, P. J. KELLOGO, P. J. KELLOGO, P. J.	7912040444 7912200447 7912280157* 7912170407 7912040152*	50-336 S 50-325 S 50-395 Q 50-336 S 50-325 Q	KEPPLER: J. G. KEPPLER: J. G. KEPPLER: J. G. KEPPLER: J. G. KEPPLER: J. G.	7512110357 7912110367 7912110369 7912110571 7912110574	50-10 G 50-358 G 50-440 G 50-155 G 56-329 G
JOYNER, J. H. JOYNER, J. H. JOYNER, J. H. JOYNER, J. H. JOYNER, J. H.	7912260074# 791220088# 7912190781# 7912070273# 7912050303#	50-54 Q 70-371 70-1100 70-371 70-1143	KELL000, P. J. KELL000, P. J. KELL000, P. J. KELL000, P. J. KELL000, P. J.	7912070167* 7912050641* 7912050467* 7912050119* 7912050624*	50-324	KEPPLER, J. 9. KEPPLER, J. 9. KEPPLER, J. 9. KEPPLER, J. 9. KEPPLER, J. 9.	7912110574 7912110578 7912110579 7912110581 7912110582	50-407 Q 50-341 Q 50-331 Q 50-441 Q 50-315 Q
JOYNER, J. H. JOYNER, J. H. JOYNER, J. H. JOYNER, J. H.	7912200333* 7912260516* 791226095* 7912260331* 7912200308*	70-971 70-364 50-333 0 50-134 0 70-33	KELLDGO, P. J. KELLDGO, P. J. KELLDGO, P. J. KELLDGO, P. J. KELLDGO, P. J.	7912060114# 7912120275# 7912180343# 7912310346# 7912060260#	50~338	KEPPLER, J. G. KEPPLER, J. G. KEPPLER, J. G. KEPPLER, J. G. KEPPLER, J. G.	7912110583 7912110585 7912110586 7912110588 7912110589	50-367 G 50-263 G 50-590 G 50-346 G 50-346 G
JOYNER, J. H. JOYNER, J. H. JOYNER, J. H. JOYNER, J. H. JOYNER, J. H.	7912200534* 7912260643* 791226046* 7912200100* 7912210069*	50-334 0 70-620 70-371 70-135 50-83 0	MELLY, R. J. MELLY, R. J. MELLY, R. J. MELLY, R. J. MELLY, R. J.	7912280559 7912050150 7912050533 7912140321 7912270519	50-321 F 50-321 P 50-321 P 50-321 F 50-321 P	KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. G. KEPPLER, J. G. KEPPLER, J. O.	7912110572 7912110573 7912120001 7912210025 7912050340	50-483
JULIAN C. KAIBI J. D. KALIVIANAKIS N. KALIVIANAKIS N.	7912050254* 7912280222* 7912120088 7912070443	50-335 0 50-244 P 50-254 P 50-254 B 50-254 B	KENENY, J. 9. KENFORD, C. KENLEY, J. B. KENNARD, N. J. KENNARD, N. J.	7912070004 7912210423 7912130603* 7912180162 7912180193	50-320 P 50-289 0 PR 50-289 0 50-289 0	KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. G. KEPPLER, J. G. KEPPLER, J. G.	7912050344 7912050350 7912050358 7912059361 7912059363	50-293 0 50-10 0 50-358 0 50-440 0 50-135 0
Kaliyanakibin. Kaliyaniq. Kaliyereric. Kaniyereric. Kaniyanil.	7912310047# 7912310047# 7912280489# 7912280493# 7912310078	50-318 0 50-287 U 50-320 U 50-3 0 50-3 0	KENNA, H. B. KENNA, H. B. KENNA, H. B. KENNA, H. B. KENNA, H. B.	79122102634 7912110536 79122601784 7912030050 7912030070	70-27 50-143 50-335 Q	KEPPLER, J. 0. KEPPLER, J. 9. KEPPLER, J. 6. KEPPLER, J. 6. KEPPLER, J. 6.	7912050367 7912050370 7912050372 7912050375 7912050377	50-329 0 50-409 G 50-341 9 50-331 0
KAMEAN I KANAK K. K. KANEI H. F. KANNAZZIOTI N. KANPLEI A. N.	7912310109 7912170174 7912260112 7912280268# 7912030195#	RES 50-312 II 50-320 H 50-272 S	MENRIA, II. B. MERNIA, II. B. MERNIA, II. B. MERNIA, II. B. MENTI, O. D.	7912210224 7912210202 7912210227 7912260171 7912110019	50-249 G 70-143	KEPPLER, J. G. KEPPLER, J. G. KEPPLER, J. G. KEPPLER, J. G. KEPPLER, J. G.	7912050384 7912050388 7912050399 7912050404 7912050405	50-367 G 50-263 G 50-262 G 50-560 G
KAPPLE: A. H. KAPPLE: A. H. KAPPLE: A. H. KAPPLE: A. H.	7912040317* 7912040343* 7912040360* 7912040395* 7912040409*	50-272 8 50-272 8 50-272 8 50-272 8	Kepford, C. Kepford, C. Kepford, C. Kepford, C.	7912040039 7912110043 7912120055 7912170095 7912200403	50-277 9 PRDJ 50-387 0	KEPPLER, J. G. KEPPLER, J. G. KEPPLER, J. G. KEPPLER, J. G. KEPPLER, J. G.	7912050407 7912050410 7912050410 7912050414 7912050414	50-346 0 50-483 0 90-266 0 50-305 0
KAPPLE: A. H. KAPPLE: A. H. KAPPLE: A. H. KAPPLE: A. H.	7912040416* 7912050429* 7912110290* 7912270290* 7912270591*	50-272 8 50-272 8 50-272 9 50-272 8 50-272 8	KEPPLER, J. O. KEPPLER, J. G. KEPPLER, J. G. KEPPLER, J. O.	7912190282 7912210047 7912050014 7912076049 7912140302	50-346 G 50-341 G	KEPPLER, J. Q. KEPPLER, J. Q. KEPPLER, J. Q. KEPPLER, J. Q. KEPPLER, J. Q.	791213040 791228563 791210041 791210042 791210042	50~315 P 50~10 9 50~358 9 50~440 9
KAPPLE: A. U. KAPPLE: A. U. KARHAN: H. KASTENSERO: U. E. KAUL: E. O.	7912270600# 7912060545 7912050660# 7912130590#	50-272 S 50-454 G 50-142 P PR 50-312 F	Keppler, J. 9. Keppler, J. 9. Keppler, J. 6. Keppler, J. 9.	7912180226 7912190786 7912200121 791205010 791205010	50-440 0 5 50-255 0 9 50-329 0 3 50-315 0	Keppler, J. O. Keppler, J. O. Keppler, J. O. Keppler, J. O. Keppler, J. O.	791210042 791210042 791210042 791210043 791210043	50-155 0 50-409 0 50-341 0 4 50-331 0
KAMRANK B. A. KAMRAN D. KAMRA L. KAY. J. A. KAY. J. A. KAY. J. A. KAY. J. A.	7912040412* 7912170374 7912170297* 7912180150 7912180155 7912270454 7912270203	50-247 F 50-29 F 50-29 F 50-29 F 50-29 F 50-29 F	MEPPLER, J. O.	791205011 791205011 791205011 791205012 791205012	3 50-358 0 4 50-440 0 8 50-155 9 2 50-329 0	KEPPLER, J. G. KEPPLER, J. G. KEPPLER, J. G. KEPPLER, J. G. KEPPLER, J. G.	791210043 791210043 791210042 791210044 791210044	4 50-315 0 8 50-367 9 0 50-263 0

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY
KEPPLER, J. Q.	7912100442	50-546 0	KEPPLER, J. O.	7912140109	50-305 Q	KNOTTS, J. B. KNOTTS, J. B. KNOPP, R. L. KNOTH, D. F. KNOTH, D. F.	7912280627	50-445 M
KEPPLER, J. Q.	7912100444	50-346 0	KEPPLER, J. O.	7912200086	50-10 Q		7912280627	50-445 M
KEPPLER, J. Q.	7912100446	50-483 0	KEPPLER, J. O.	7912200099	50-358 Q		791206066	50-289 0
KEPPLER, J. Q.	7912100447	50-266 0	KEPPLER, J. O.	7912200103	50-440 Q		7912210053	NUREO
KEPPLER, J. Q.	7912100448	50-305 0	KEPPLER, J. O.	7912200106	50-155 Q		7912190183	FOIA
KEPPLER, J. O.	7912110244	50-440 0	KEPPLER, J. Q.	7912200108	50-329 G	KNUTH, D. F.	7912190201* 7912190171* 7912190179* 7912140440 7912190351*	FDIA
KEPPLER, J. O.	7912110249	50-329 0	KEPPLER, J. Q.	7912200112	50-409 G	KNUTH, D. F.		FOIA
KEPPLER, J. O.	7912110252	50-155 0	KEPPLER, J. Q.	7912200115	50-341 G	KNUTH, D. F.		FOIA
KEPPLER, J. O.	7912110255	50-409 0	KEPPLER, J. Q.	7912200117	50-331 G	KNUTH, D. F.		RES
KEPPLER, J. O.	7912110258	50-341 0	KEPPLER, J. Q.	7912200123	50-461 G	KNUTH, D. F.		FOIA
KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O.	7912110259 7912110265 7912110265 7912120172 7912140187	50-331 Q 50-441 Q 50-347 Q 50-329 Q 50-10 Q	KEPPLER, J. G. KEPPLER, J. G. KEPPLER, J. G. KEPPLER, J. G. KEPPLER, J. G.	7912200127 7912200130 7912200134 7912200136 7912200141	50-315 G 50-367 G 50-263 G 50-580 G 50-546 G	KNUTH, D, F. KOCH, N. KOCHER, D. C. KOCK, L. J. KODNER, J. L.	7912190338* 7912200064* 7912120033 7912040278 7912260354*	FOIA 50-320 H NUREQ 50-461 F 50-373 Q
KEPPLER, J. Q.	7912140203	50-358	KEPPLER, J. O.	7912200144	50-346 G	KODNER, J. L.	7912130294	50-599 0
KEPPLER, J. Q.	7912140213		KEPPLER, J. O.	7912200148	50-483 G	KODNER, J. L.	7912130117	50-599 0
KEPPLER, J. Q.	7912140216		KEPPLER, J. O.	7912200153	50-266 G	KODNER, J. L.	7912130120*	50-599 0
KEPPLER, J. Q.	7912140223		KEPPLER, J. O.	7912200155	50-305 G	KODNER, J. L.	7912130121*	50-599 0
KEPPLER, J. Q.	7912140228		KERR, H.	7912100029	ACRS	KODNER, J. L.	7912130128	50-599 0
KEPPLER, J. G. KEPPLER, J. G. KEPPLER, J. G. KEPPLER, J. G. KEPPLER, J. G.	7912140237 7912140242 7912140245 7912140249 7912200442	50-346 Q 50-483 Q 50-266 Q 50-305 Q 50-346 S	KERR, H. KERR, O. H. KERR, O. H. KERR, O. H. HERR, O. H.	7912100034 7912210351 7912120091 7912120183 7912110053	ACRS ACRS State Prog State Prog State Prog	KODNER, J. L.	7912140295 7912130117 7912130120+ 7912130128 7912140295	50-599
KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O.	7912110392 7912110395 7912110397 7912110399 7912110403	50-315 Q 50-10 Q 50-358 Q 50-440 Q 50-155 Q	KERR, G. W. KERR, G. W. KERR, G. W. KERR, G. W.	7912110063 7912180050 7912180053 7912040131 7912040140	State Prog WASTE MGT WASTE MGT 50-320 G 50-320 G	KOEPKE, W. KOESTER, O. L. KOESTER, G. L. KOESTER, O. L. KDESTER, O. L.	7912190210* 7912040542 7912070140 7912070174 7912270280	50-482 q 50-482 F 50-482 S 50-482 S
KEPPLER, J. G.	7912110420	50-329 Q	NERR, G. H.	7912040146	State Prog	KOHLER, J. E.	7912050066*	50-295 q
KEPPLER, J. G.	7912110423	50-409 Q	KERR, G. H.	7912040171	State Prog	KOHLER, J. E.	7912060654	50-295 g
KEPPLER, J. G.	7912110426	50-341 Q	KERR, G. H.	7912040175	State Prog	KOHLER, J. L.	7912060650	50-304 g
KEPPLER, J. G.	7912110427	50-331 Q	KERR, G. H.	7912040185	State Prog	KOHLER, J. E.	7912180090	50-295 g
KEPPLER, J. G.	7912110430	50-461 Q	KERR, G. H.	7912040192	State Prog	KOHN, B.	7912280660	F01A
KEPPLER, J. O.	7912110431	50-347 0	KEAR, G. H.	7912040199	State Prog	KOLTAY, P.	7912280301*	50-320 q
KEPPLER, J. O.	7912110433	50-263 0	KEAR, G. H.	7912040205	State Prog	KOLTAY, P. S.	7912250004*	50-284 q
KEPPLER, J. O.	7912110437	50-580 0	KEAR, G. H.	7912120371	State Prog	KONKLIN, J. E.	7912210055	50-440 s
KEPPLER, J. O.	7912110440	50-546 0	KEAR, G. H.	7912170047	WASTE MGT	KONKLIN, J. E.	7912200007	50-440 s
KEPPLER, J. O.	7912110443	50-346 0	KETCHEN, E. G.	7912260371	70-2623	KOPECK, J.	7912190327	FDR MISC
KEPPLER, J. O.	7712110444	50-493 Q	KETZLACH, N. KETZLACH, N. KETZLACH, N. KETZLACH, N. KETZLACH, N. KHATIB-RAHBAR, M	7912110944#	70-27	KORCHYNSKY, M.	7912140469*	50-237 8
KEPPLER, J. O.	7912110448	50-266 Q		7912050093	70-27	KORCHYNSKY, M.	7912180399*	50-249 9
KEPPLER, J. O.	7912110450	50-305 Q		7912170043	70-27	KOTSCH, J. L.	7912120575	40-229
KEPPLER, J. G.	7912140375	50-346 Q		7912280594	70-27	KOUTS, H. J. C.	7912140418	REG
KEPPLER, J. G.	7912190199	50-10 Q		7912120129	TOPREP	KOUTS, H. J. C.	7912140420	RES
KEPPLER, J. G.	7912190207	50-373 Q	Kidd, M. 8	7912040114#	50-338 Q	KOUTS, H, J, C,	7912140424	RE9
KEPPLER, J. G.	7912190211	50-350 Q	Kinder, E. T.	7912130570	PR	KOUTS, H, J, C,	7912140433	RE5
KEPPLER, J. G.	7912190213	50-440 Q	Kinder, E. T.	7912130578#	PR	KOWALSKI, J, 9,	7912040333	71-9035
KEPPLER, J. G.	7912190214	50-155 Q	Kingsley, S. S.	7912180187#	71-358	KRAMER, K,	7912130518	PR
KEPPLER, J. G.	7912190218	50-329 Q	Kingsley, S. S.	7912190479#	71-358	KRANISH, A,	7912180109	FOIA
KEPPLER, J. G. KEPPLER, J. G. KEPPLER, J. G. KEPPLER, J. G. KEPPLER, J. G.	7912190219 7912190221 7912190223 7912190224 791219022B	50-409	KINNEY, H. H. KINNEY, H. H. KINNEY, H. H. KINNEY, H. H. KINTNER, L. L.	7912050108* 7912310320* 7912120353* 7912060674 7912270176*	70-1143 70-820 70-1143 70-1143 50-364 A	KREBB, A. H. KRESS, T. S. KREYSA, F. J. KROEHN, T. A. KRUESI, F. E.	7912100091* 7912120170 7912200662 7912180585* 7912190360*	CONTRACT NUREQ 71-6400 50-409 D FOIA
MEPPLER, J. G.	7912190229	50-367 Q	KINTNER, L. L.	7912270035	50-341 A	KRUO, M. E.	7912190355	WASTE MOT
MEPPLER, J. G.	7912190231	50-263 Q	KIRKPATRICK, D.	7912190237*	50-275 Q	KRUO, M. E.	7912190785	WASTE MOT
MEPPLER, J. G.	7912190233	50-346 Q	KIRSCH D. F.	7912110493*	50-50B Q	KUHLMAN, C. H.	7912070342*	FOLA
MEPPLER, J. G.	7912190235	50-266 Q	KIRSCH D. F.	8001110502	50-50B S	KUMP, R.	7912280321*	50-320 H
MEPPLER, J. G.	7912190238	50-305 Q	KIRSCH, D. F.	7912120505*	50-50B G	KUNZE, N. E.	7912110036*	CONTRACT
KEPPLER, J. O.	7912190240	50-580 Q	Kirbhen, A. H.	7912050599	50-285 0	KUSEK, L. T.	7912110366*	50-285 9
KEPPLER, J. O.	7912190244	50-546 Q	Kirbhen, A. H.	7912060612	50-285 0	KUSHNER, W. L.	7912200100*	70-135
KEPPLER, J. O.	7912190246	50-483 Q	Kirshen, A. H.	7912050599	50-285 0	KUTRANT, E. M.	7912070503	71-6717
KEPPLER, J. O.	7912310092	50-155 F	Kirshen, A. H.	7912060612	50-285 0	KYGER, J. A.	7912050009	NURE0
KEPPLER, J. O.	7912310098	50-263 F	Kirshen, G. J.	7912170036*	50-289 0	L'HEUREUX, J.	7912180035	71-4949
KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O.	7912310103 7912210127 7912210129 7912210144 7912140056	50-346 F 50-295 F 50-305 F 90-266 Q 50-10 Q	Kister, H. B. Kister, H. B. Kister, H. B. Kleinsorge, W. P. Kleinsorge, W. P.	7912050131* 7912060058* 7912180274* 7912050555* 7912280537*	50-333	LADUN, R. LADUN, R. H. LADUN, R. LAFLEUR, J. D. LAFOLLETTE, B. C.	7912260119* 7912050086* 7912100057* 7912190155 7912040610	50-277 0 50-104 0 70-820 XPORTLIC PRH
KEPPLER, J. Q.	7912140069	50-358 Q	KLINE, J.A.	7912070171	50-275 0	LAGIENSKI, J. B.		50-317 8
KEPPLER, J. Q.	7912140074	50-440 Q	KLINE, J.A.	7912170012	50-275 0	LAGIENSKI, J. S.		50-317 8
KEPPLER, J. Q.	7912140077	50-329 Q	KNAPP, D.	7912170395	PRDJ	LAGIENSKI, J. S.		50-317 8
KEPPLER, J. Q.	7912140079	50-155 Q	KNIGHT, G.F.	7912200071#	50-289 0	LAGOMARSINO, R.		50-320 U
KEPPLER, J. Q.	7912140082	50-409 Q	KNIGHT, J.E.	7912170242#	50-344 0	LAGOMARSINO, R.		50-275 U
KEPPLER, J. Q. KEPPLER, J. Q. KEPPLER, J. Q.	7912140086 7912140087 7912140089 7912140090 7912140093	50-341 Q 50-461 Q 50-315 Q 50-367 Q 90-263 Q	KNICHT, J. P. KNICHT, J. P. KNOLL, H. KNOP, R. C. KNOP, R. C.	7912070030* 7912180305 7912280551* 7912180378 7912260137*	50-275 A PDR MISC 50-320 H 50-483 S 50-329 Q	LAGDMARBIND, R. J LAGDMARBIND, R. J LAGDMARBIND, R. J LAGRANGE, R. Q. LAINAS, Q.	7912130206 7912180468 7912110081*	50-275 U 50-275 U 50-275 U 0A999 50-348 P
	7912140095 7912140098 7912140099 7912140104 7912140106	50-580 Q 50-546 Q 50-346 Q 50-483 Q 50-266 Q	KNOP. R. C. KNOP. R. C. KNOP. R. C. KNOP. R. C. KNOP. R. C.	7912070033 7912210033* 7912260169* 7912260091* 7912170416	50~4B3 5 50~4B3 0 50~367 0 50~461 0 50~329 B	Lainas, g. Lainas, g. Lainas, g. Lainas, g. Lainas, g.	7912260082 7912180057 7912180117	50-321 P 50-346 0 50-317 P 50-333 P 50-269 P

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT Category	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
LAINAS, 0.	7912050146	50-263 P	LEONARD, J. D.	7912120128	50-333 S	LEWIS, S. H.	7912170149	50-594 0
LAINAS, 0.	7912180319	50-324 P	LEONARD, J. D.	7912140278	50-333 Q	LEWIS, S. H.	7912060024	50-312 0
LAINAS, 0.	7912190123	50-271 P	LEONARD, J. D.	7912170214	50-333 Q	LEWIS, S. H.	7912170266	50-312 0
LAINAS, 0.	7912180259	50-219 F	LEONARD, J. D.	7912260053	50-333 Q	LEWIS, S. H.	7912180048	50-312 0
LAINAS, 0.	7912180395	50-155 F	LEONARD, J. D.	7912260057	50-333 Q	LEWIS, S. H.	7912210431	50-312 0
LAINAS, O.	7912180198	50-349 P	LEONARD, J. D.	7912130449	50-339 8	LEWIS, R. C.	7912070103	50-287 8
Lainas, O.	7912180200	50-313 P	LEONARD, J. D.	7912040308	50-339 8	LEWIS, R. C.	7912060254*	50-335 0
Lainas, O.	7912190046	50-272 P	LEONARD, J. D.	7912110277	50-339 8	LEWIS, R. C.	7912070163*	50-324 0
Lainas, O.	7912190163	50-334 P	LEONARD, J. D.	7912110328	50-339 9	LEWIS, R. C.	7912050632*	50-324 0
Lainas, O.	7912260227	50-243 P	LEONARD, J. D.	7912110343	50-339 8	LEWIS, R. C.	7912050456*	50-280 0
Lainas, O.	7912200114	50-305 F	LEONARD, J. D.	7912110355	90-333 8	LEWIS.R.C.	7912110502* 7912050405* 7912050111 7912030041 7912040192*	50-241 Q
Lainas, O.	7912200125	50-155 F	LEONARD, J. D.	7912110250	50-333 R	LEWIS.R.C.		50-327 Q
Lainas, O.	7912200139	50-287 P	LEONARD, J. D.	7912140438	50-333 8	LEWIS.R.C.		50-241 Q
Lainas, O.	7912260131	50-321 P	LEONARD, J. D.	7912180573	50-333 P	LEWIS.R.C.		50-327 Q
Lainas, O.	7912200057	50-409 F	LEONARD, J. D.	7912180594	50-333 S	LEWIS.R.C.		50-369 Q
Lainas, O.	7912200062	50-317 F	LEONARD, J. D.	7912210316	50-333 8	LEWIS, R. C.	7912060668* 7912070089 7912070099 7912050060 7912050627	50-302 9
Lainas, O.	7912190057	50-244 P	LEONARD, J. D.	7912210327	50-333 8	LEWIS, R. C.		50-348 9
Lainas, O.	7912190069	50-285 P	LESSOR, L. C.	7912130387	50-298 8	LEWIS, R. C.		50-395 9
Lainas, O.	7912310470	50-317 P	LESSOR, L. C.	7912130391	50-298 8	LEWIS, R. C.		50-302 9
Lainas, O.	7912310148	50-335 P	LESSOR, L. C.	7912310435	50-298 8	LEWIS, R. C.		50-327 9
Lainab, O.	7912310144	ORO	LESSOR, L. C.	7912310447	50~298 8	LEWIS.R.C.	7912040228	50-250 G
Lainab, O.	7912310217	50-264 F	LESSOR, L. C.	7912140395	50-298 R	LEWIS.R.C.	7912090366	50-259 G
Lainab, O.	7912310392	50-245 F	LESSOR, L. C.	7912310459	50-298 8	LEWIS.R.C.	7912090423	50-250 G
Lainab, O.	7908010339	50-29 P	LESSOR, L. C.	7912310442	50-298 8	LEWIS.R.C.	7912040100	50-338 G
Lancabter, J. L.	7912170254	50-261 J	LESSOR, L. C.	7912310438	50-298 8	LEWIS.R.C.	7912040249	50-335 G
LANCASTER, K. F. LANCASTER, K. F. LANCASTER, K. F. LANCASTER, R. R. LANCASTON, N.	7912030157#	50-302 8	LESSY, R. P.	7912060009	50-445 M	LEWIG.R.C.	7912120264	90-338 Q
	7912110331#	50-302 8	LESSY, R. P.	7912050098	50-346 M	LEWIG.R.C.	7912180149	50-327 Q
	7912260243#	50-302 8	LESSY, R. P.	7912130236	50-445 M	LEWIG.R.C.	7912180337	90-324 Q
	7912130350#	50-264 9	LESSY, R. P.	7912260044	50-445 M	LEWIG.R.C.	7912180114	50-302 Q
	7912030469	50-313 I	LESSY, R. P.	7912260361	50-445 M	LEWIG.R.C.	7912180125	50-327 Q
LAMPHER, L. C. LAMPHER, L. C. LAMSON, L. K. LAMSON, L. K. LAMSON, L. K.	7912140054 7912170005 7912030027 7912030034# 7912140015	50-312 0 50-312 0 50-312 0 50-312 0	LETARTE, H. LETTIERI, V. LEVIN, C. LEVIN, H. A. LEVIN, H. A.	7912040135 7912100001 7912140530 7912180307* 7912180312*	50-155 G RES 50-155 U PDR MISC PDR MISC	LEWIS, R. C. LEWIS, R. C. LEWIS, R. C. LEWIS, R. C. LEWIS, R. C.	7912280152 7912310349 7912100154 7912310307 7912310336	50-395 Q 50-281 Q 50-269 Q 50-390 Q 50-302 Q
CARBON, L. K. LARBON, L. K. LARBON, L. K. LARBON, L. K. LARBON, L. K.	7912140023# 7912140033 7912140041# 7912140124 7912140159#	50-312 0 50-312 0 50-312 0 50-312 0 50-312 0	LEVIN, H. A. LEVIN, H. A. LEVINE, B. LEVINE, B.	7912110412 7912170411 7912110398 7912140522 7912140458	50-206 P 50-29 P 50-10 P RES RES	LEWIS.R.C. LEWIS.R.C. LEWIS.R.C. LEWIS.R.C. LEWIS.R.C.	7912050597 7912050626 7912060661 7912070158 7912210061*	50-327
LARBON, H. C.	7912190212	40-8745	LEVINE, 8.	7912140447	res	LEWIS.R.C.	7912050446	50-260
LARBON, L. K.	7912030027	50-312 0	LEVINE, 8.	7912140512	res	LEWIS.R.C.	7912280163*	
LARBON, L. K.	7912030034*	50-312 0	LEVINE, 8.	7912140475	res	LEWIS.R.C.	7912060182	
LARBON, L. K.	7912140015	50-312 0	LEVINE, 8.	7912140471	res	LEWIS.R.C.	7912110486	
LARBON, L. K.	7912140023*	50-312 0	LEVINE, 8.	7912140464	res	LEWIS.R.C.	7912210052	
LARBON, L. K. LARBON, L. K. LARBON, L. K. LARBON, L. K. LAURN, V. W.	7912140033 7912140041* 7912140124 7912140159* 7912190230	50-312 0 50-312 0 50-312 0 50-312 0 50-275 0	LEVINE, 8. LEVINE, 8. LEVINE, 8. LEVINE, 8.	7912140488 7912140480 7912140506 7912140518 7912140493	RES RES RES RES RES	LEXA, A.F. LIBARKIN, M.W. LIBERMAN, D. LIDERMAN, D. LIBRIZZI, F.P.	7912310513* 7912190278* 7912170088 7912170088 7912030190	50-255 P ACRS 50-445 G 50-445 G 50-272 S
LAWRENCE, L. I.	7912130393*	50-298	LEVINE, 8.	7912140509	REB	LIBRIZZI, F. P.	7912040311	50-272 S
LAWROSKI, S.	7912190352*		LEVINE, 8.	7912140511	REB	LIBRIZZI, F. P.	7912040338	50-272 S
LAWROSKI, S.	7912190356*		LEVINE, 8.	7912140523	REB	LIBRIZZI, F. P.	7912040359	50-272 S
LAWSON, M.	7912180616*		LEVINE, 8.	7912140520	REB	LIBRIZZI, F. P.	7912040386	50-272 S
LAYARUS, W.	7912100199*		LEVINE, 8.	7912140454	REB	LIBRIZZI, F. P.	7912040402	50-272 S
LAZARUS, W. LAZARUS, W. LAZARUS, W. J. LAZO, R. H. LAZO, R. H.	7912190797* 7912060662 7912260302* 7912110367 7912030692	50-213	LEVINE, 8. LEVINE, 8. LEVINE, 8. LEVINE, 8. LEVINE, 8.	7912140515 7912140519 7912140521 7912140474 7912140514	res res res res	LIORIZZI, F. P. LIORIZZI, F. P. LIORIZZI, F. P. LIORIZZI, F. P. LIORIZZI, F. P.	7912040414 7912050487 7912040410 7912040318 7912040504	50-272 S 50-272 F 50-272 P 50-272 P 50-272 P
LAZO, R. H.	7912050433	50-312	LEVINE, 8.	7912140495	RES	LIBRIZZI, F. P.	7912050422	50-272 8
LAZO, R. H.	7912130277		LEVINE, 8.	7912140487	RES	LIBRIZZI, F. P.	7912110294	50-272 8
LEACH, C. E.	7912280222*		LEVINE, 8.	7912140502	RES	LIBRIZZI, F. P.	7912140304	50-272 P
LEAR, Q.	7912180650		LEVINE, 8.	7912140507	RES	LIBRIZZI, F. P.	7912140369	50-272 H
LEAR, Q.	7912050637*		LEVINE, 8.	7912200042	PDR MISC	LIBRIZZI, F. R.	7912190577	50-272 P
LEAR, O.	7912080640*	50-142 P	LEVY, A.	7912280479	50-287 T	LIBRIZZI, F. P.	7912200527	50-272 P
LEASE, R. S.	7912170271*	50-316 B	LEWALD, Q. H.	7912210100	50-471 G	LIBRIZZI, F. P.	7912280538	50-272 P
LEE, B.	7912190504	ORG	LEWALD, G. H.	7912210100	50-471 O	LIBRIZZI, F. P.	7912270286	50-272 S
LEE, B.	7912190190*	FOIA	LEWIS, M. I.	7912040092*	50-320 H	LIBRIZZI, F. P.	7912270584	50-272 S
LEE, D. R.	7912180062	50-267 B	LEWIS, M. L.	7912120238	PROJ	LIBRIZZI, F. P.	7912270595	50-272 S
Lee, E. W. K.	7912180342*	50-373	Lewis, M. I.	7912130502	PR	LICITRA, E. A.	7912190627	50-528 1
Lee, E. W.	7912200589*		Lewis, B. E.	7912170360	PROJ	LICITRA, E. A.	7912310089	50-498 F
Lee, J. T.	7912280336		Lewis, M. I.	7912200419	REGOD	LIEBLER, G.	7912130447	TOPREP
Lee, W. F.	7912180478		Lewis, M. I.	7912270095	50-289 0	LIEBLER, G. E.	7912180550	50-307 P
Leechi K.	7912180370*		Lewis, M. J.	7912280486	90-352 H	LIEDERBACH, F. J.	7912060007	PDR MISC
LEED, R. M.	7912110267	50-522 G	Lewis, R. A.	7912030118	PROJ	LIKE, I.	7912040079*	50-322 G
LEED, R. M.	7912140025	50-522 G	Lewis, B. R.	7912070442*	50-287 B	LIKOFF, W.	7912040259*	70-1362
LEFEVRE, H.	7912170226	27-47	Lewis, B. R.	7912110388*	50-287 S	LINDER, F.	7912130006	50-409 G
LEMAHAN, J. J.	7912180367*	50-389 G	Lewis, B. R.	7912270509*	50-270 S	LINDER, F.	7912130407	50-409 P
LENAHAN, J. J.	7912110334*	50-400 G	Lewis, R. A.	7912030118	PROJ	LINDER, F.	7912040418	50-409 B
LENTSCH. J. H.	7912050478	50-344 P	Lenis, B. H.	7912050242	50-312 0	LINDER, F.	7912050493	50-409 P
LEONARD, J. D.	7912050084*	50-333 Q	Lenis, B. H.	7912100475	50-462 0	LINDER, F.	7912100318	50-409 P
LEONARD, J. D.	7912120003	50-333 Q	Lenis, B. H.	7912170072	50-312 0	LINDER, F.	7912110240	50-409 P
LEONARD, J. D.	7912130200	50-333 Q	Lenis, B. H.	7912170082	50-312 0	LINDER, F.	7912210174	50-409 Q
LEONARD, J. D.	7912130504	50-333 Q	Lenis, B. H.	7912170216	50-312 0	LINDER, F.	7912100242	50-409 P

AUTHOR	ACCESSION NUMBER	SUB JECT CATEGOS		AUTHOR	ACCEBSION NUMBER	SUBJECT CATEGORY	AUTHÖR	ACCEBSION NUMBER	SUBJECT CATEGORY
LINDER, F. LINDER, F. LINDER, F. LINDER, F.	7912110206 7912180189 7912120245 7912200427 7912200568	50-409 50-409 50-409 50-409 50-409	ր P P	MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E.	7912200105 7912040072* 7912200132* 7912040076 7912040080	71-5980 71-193	MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E.	7912180169* 7912210149 7912260052 7912260055* 7912270057	71-356 71~96 71-24 71-24 71-9132
LINDER, F. LINDER, F. LINDER, F. LINDER, F. H. LINDER, F.	7912140416 7912280464 7912270388 7912270486 7912310497	50-409 50-409 50-409 50-409 50-409	8 8 8	MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E.	7912040178 7912040183 7912040188 7912040118 7912060124	71-9010 71-9094 71-9081 71-5939 71-6357	MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E.	7912210299 7912310061 7912190469 7912190474* 7912200555	71-5441 71-6204 71-68 71-68 71-9035
LINDER, F. W. LINDER, F. W. LINDER, F. H. LINEHAN, J. J. LINEHAN, J. J.	7912130419 7912110230 7912170287 7912170099 7912170114	50-409 50-409 50-409 40-7869 40-4492	P P S	MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E.	7912040194 7912040198 7912040202 7912040207 7912040216	71-6400 71-7086 71-7096 71-6568 71-5939	MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E.	7912210341 7912210346* 7912260040 7912260041* 7912260045	71-5084 71-5084 71-4078 71-4070 71-9001
LINEHAN, J. J. LINZER, M. LIOTTA: R. LIPPOLD: W. J. LITTLE: D. S.	7912310445 7912050002 7912280487* 7912260064* 7912070355	40-4492 NUREQ 50-320 50-317 50-522	H 8 0	MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E.	7912060638 7912070107 7912070117 7912040018 7912040020	71-6568 71-9019 71-6400 71-258 71-6	MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E.	7912240049* 7912270050 7912270248 7912270255* 7912210099	71-9001 71-4 71-358 71-358 71-9019
LITTLE, D. S. LITTLE, D. S. LITTLE, D. S. LITTLE, D. S. LITTLE, D. S.	7912100473 7912170020 7912170041* 7912170048* 7912030007	50-522 50-522 50-522 50-522 50-522	0 0 0 0	MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E.	7912040027 7912040030# 7912040032 7912040071 7912040089	71-9853 71-9853 71-355 71-193 71-9010	MACDONALD, C. F. MACDONALD, C. E. MACMILLAN, J. H. MACY, J. W. MACY, J. W.	7912280037* 7912280038* 7912310227* 7912050571* 7912050573*	71-6698 71-6698 ACRS State Prog State Prog
LITTLE, D. S.	7912070355 7912100473 7912170020 7912170041* 7912170048*	50-522 50-522 50-522 50-522 50-522	6 0 0 6	MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E.	7912060144 7912060158 7912060501 7912060642 7912060647	71-5805 71-9028 71-6400 71-5450 71-9108	MACY, J. W. MACY, J. W. MADDEN, J. L. MADDEN, W. MADDEN, W.	7912050578* 7912050581* 7912170413 7912260071* 7912180041	State Prog State Prog PROJ 70~1143 50~213 \$
LITTLE, L. W. LLOYD, R. C. LO, R. LOCHSTET, W. A. LOCHSTET, W. A.	7912270011 7912200015* 7912050322 7912130287 7912060082	50-289 71-6581 50-10 PR PROJ	Q: P	MACDONALD, C.E. MACDONALD, C.E. MACDONALD, C.E. MACDONALD, C.E. MACDONALD, C.E.	7912040448 7912070512 7912100142 7912100149 7912100396	71-9111 71-6144 71-6345 71-7851 71-9094	MADISON, S.R. MADISON, W.R. MADNI, I.K. MADSEN, G.L. MADSEN, Q.L.	7912170227 7912140390* 7912120108 7912310055 7912310069	50-322 0 50-338 R TOPREP 50-267 9 50-313 8
LOCHSTET, W. A. LOCKE, R. F. LOCKE, R. F. LOCKE, R. F. LOEFFLER, T.	7912130489 7912050347 7912050351* 7912060251 7912270039*		G G	MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. HACDONALD, C. E. MACDONALD, C. E.	7912100399 7912110008 7912110553 7912140036 7912060140	71-5026 71-9094 71-9079 71-6400 71-6	MADSEN, G. L.	7912310073 7912310084 7912050326 7912120196 7912130359*	50-313 8 50-368 8 50-313 0 50-382 0 50-131 0
LOFY, R. A. LOGIUDICE, J. M. LONG, C. LONGHIRE, J. E. LONGO, J.	7912160105* 7912110541* 7912110158 7912310145 7912260017*		P A	MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E.	7912060147# 7912060151 7912060160# 7912060209 7912060211	71-6 71~79 71-79 71-721 71-248	MADSEN, G. L.	7912130356 7912120223* 7912120212 7912120239* 7912120229	50-131 Q 50-267 Q 50-267 Q 50-148 Q 50-148 Q
LODMIS, J. S. LODMIS, P. A. LOUDERNELAGER, T. LOWERRE, R. W. LOWERRE, R. W.	7912280151 7912280479 7912060508 7912100338 7912130342	50-155	T H Q	MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E.	7912060217* 7912060219 7912060222* 7912110050 7912110301	71-248 71-5395 71-5395 71-9070 71-9113	MADSEN, G. L. MADBEN, G. L. MADBEN, G. L. MAGNO, F. J. MAGROW, R.	7912050680* 7912050675 7912050684 7912070305* 7912140430*	50-128 G 50-128 G 50-313 G FOIA 50-249 S
LOHERRE, R. W. LOHRY, L. M. LOYSEN, P. LOYSEN, P. LUCAS, S. V.	7912130344* 7912120645 7912070360* 7912070300* 7912040064	PR NUREG FOIA FOIA 71-9070		MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E.	7912110531* 7912070010 7912070017 7912100371 7912100373*	71-9113 71-5796 71-9079 71-9119 71-9119	MAHLER, J. MAHLER, J. MAIXNER, R. D. MAKEPEAGE, J. M. MAKEPEAGE, J. M.	7912260363 7912260363 7912030026 7912120469* 7912140411*	50-454 0 50-454 0 WASTE HOT 50-247 9 50-247 9
LUKENS, T. H. LUNDVALL, A. E. LUNDVALL, A. E. LUNDVALL, A. E. LUNDVALL, A. E.	791211051B* 7912110559 7912040463 7912120274 7912120269	RECCD 50-317 50-317 50-317	G F P	MACDONALD, C. E. MACDONALD, C. E. MACDONALD, G. E. MACDONALD, C. E. MACDONALD, C. E.	7912100378 7912100460 7912100462* 7912100465 7912100466*	71-6717 71-9111 71-9111 71-9768 71-5768	MAKEPEAGE, J. M. MAKEPEACE, J. M. MAKIPENTTI, I. MALLER, A. H. MALMROS, M. H.	7912310406* 7912310410* 7912280116 7912140303* 7912040123#	50-247 S 50-247 S XPORTLIC CONTRACT 50-344 Q
LUNDVALL, A. E. LUNDVALL, A. E. LUNDVALL, A. E. LUNDVALL, A. E. LUNDVALL, A. E.	7912260010 7912190364 7912190403 7912190497 7912190571	50-317 50-317 50-317 50-317	9 P P 3	MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E.	7912110057 7912110059 7912110062* 7912120548 7912120571*	71-6144 71-6280 71-6280 71-6280 71-6386	MALDNEY, G. P. MAMIYA, G. MAMIYA, S. MANDLER, J. W. MANGELBOORF, H.	7912140043 7912120574* 7912130129* 7912130146 7912190330*	50-315 Q XPORTLIC XPORTLIC RES ACRS
LUNDVALL, A. E. LUNDVALL, A. E. LUNDVALL, A. E. LUNDVALL, A. E. LUOMA, C. R.	7912270404 7912270416 7912260220 7912310388 7912210439	50-317 1 50-317 1 50-317 1 50-317 1 50-305 1	? = <del>-</del>	MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E.	7912280241 7912280A22 7912120510 7912120512* 7912120514	71-5796 71-5939 71-199 71-199 71-347	MANRY, M. MANRY, M. MANRY, M. MANRY, M. MANRY, M.	7912130426 7912050450 7912110320 7912050440 7912070445	50-321 8 50-321 9 50-321 5 50-366 8 50-366 8
LUQUE, N. LUQUE, N. LUQUE, N. LYNCH, M. D.	7912190140 7912100332 7912170138 7912310137 7912120322	50-445   50-498   50-445   50-445   50-397	1 1 1	MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E.	7912120517* 7912120521* 7912120525 7912120527*	71-347 71-349 71-349 71-26 71-26	MANRY, M. MANRY, M. MANRY, M. MANRY, M. MANRY, M.	7912110368 7912130424 7912130384 7912130394 7912130404	50~345 8 50~321 8 50~346 8 50~346 8 50~346 8
LYNCH, M. D. MACAR TOR, J. D. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E.	7912120329 7912130463 7912180338 7912050461 7912050455	50-397 / PR 71-359 71-6678 71-9085		MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E.	7912120529 7912120533* 7912130016 7912130019* 7912140210	71-345 71-345 71-225 71-225 71-5059	MANRY, M. MANRY, M. MANRY, M. MANRY, M. MANRY, W.	7912130412 7912140429 7912140441 7912180430 7912180438	50-366 8 50-321 8 50-366 8 50-321 R 50-366 R
MACDONALD, C. E. HACDDNALD, C. E. HACDDNALD, C. E. MACDUNALD, C. E. HACDUNALD, C. E.	7912180068* 7912210293 7912210296* 7912040023* 7912040035*	71-204 71-9932 71-9932 71-6 71-355		MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E.	7912140215* 7912180144 7912180153 7912180159* 7912180164	71-3059 71-357 71-237 71-239 71-354	MANRY, M. MANRY, M. MANRY, M. MANRY, M. MANRY, M.	7912170304 7912170319 7912180435 7912240221 7912240247	50-321 8 50-321 8 50-346 8 50-346 8 50-321 8

AUTOHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION MARGER	SUBJECT CATEGORY	AUTHER	ACCESSION MANDER	SUBJECT CATEGORY
Marry, H.	7912260265	50-366 S	MARTIN, R.	7912170402	50-297 S	HATTSON, R. J. MAUPIN, N. U. MAURA, F. A. MAXWELL, J. C. MAXWELL, Q. F.	7912040122	50-320 P
Harry, H.	7912270472	50-321 S	MARTIN, R. D.	7912070097*	50-348 Q		7912120169	50-338 G
Harry, H.	7912270482	50-321 S	MARTIN, J. B.	7912190259	NASTE MOT		7912210154=	50-373 Q
Harry, H.	7912310429	50-321 S	MARTIN, J. B.	7912260603	ORG		7912180284	ACRS
Harry, H.	7912310462	50-321 S	MARTIN, J. B.	7912260672	27-49		7912050554=	50-454 Q
MANRY, H.	7912310415	50-321 S	HARTORE, J. A.	7912180307*	PDR MISC	MAY, E. L.	7912100296* 7912110293* 7912040201 7912030197 7912040242	50-29 S
MANSER, H. C.	7912240175*	70-143	HARTORE, J. A.	7912180312*	PDR MISC	MAY, E. L.		50-29 S
MANZER, R.	7912180507*	50-275 U	HASRI, S. F.	7912180223	MAREC	MAYER, L. O.		50-282 P
MARCHELLO, J. M.	7912070459	50-123 P	HASSE, R. E.	7912110271*	50-315 Q	MAYER, L. G.		50-304 S
MARCHELLO, J. M.	7912200458*	50-123 P	HATERS, B. R.	7912180520	50-341 H	MAYER, L. O.		50-283 P
MARDONSKI, F. J.	7912280222+	50-244 P	MATHENS, E. R.	7912140357	50-305 R	MAYER, L. D.	7912070431	50-263 F
MARINO, O. P.	7912190090	REVIEW GRP	MATHENS, E. R.	7912040211	50-305 Q	MAYER, L. D.	7912100369	50-263 F
MARK, C.	7912100029	ACRS	MATHENS, E. R.	7912170210	50-305 Q	MAYER, L. D.	7912120244	50-282 F
MARK, C.	7912100034	ACRS	MATHENS, E. R.	7912200089	50-305 Q	MAYER, L. D.	7912070434	50-282 6
MARK, J. C.	7912140211	ACRS	MATHENS, E. R.	7912120362	50-305 P	MAYER, L. D.	7912110307	50-282 P
Mark. J. C.	7912210351	ACRS	MATHENS, E. R.	7912180481	50-305 P	MAYER, L. O.	7912110310	50-263 P
Markley. R. A.	7912200584*	50-537 A	MATHENS, E. R.	7912180501	50-305 P	MAYER, L. O.	7912120364	50-263 P
Markonski. R.	7912070139*	50-293 G	MATHENS, E. R.	7912180621	50-305 P	MAYER, L. O.	7912140259	50-263 P
Markonski. R. S.	7912210363*	50-244 G	MATHENS, E. R.	7912190420	50-305 P	MAYER, L. O.	7912140367	50-263 R
Markonski. R.	7912060058*	50-277 G	MATHENS, E. R.	7912210325	50-305 P	MAYER, L. O.	7912200414	50-263 P
HARKE, M. L.	7912120233*	50-289 U	HATHIB; C. J.	7912070393+	50-293 S	MAYER, L. O.	7912180620	50-282 R
MARKHORTH, A. J.	7912120645	NUREO		7912260281+	50-293 S	MAYER, L. O.	7912190167	50-263 F
MARRANE, J.	7908290534	50-320 J		7912270316	50-293 S	MAYER, L. O.	7912170304	50-263 F
MARSHALL, H. H.	7912120247	PROJ		7912280577	50-293 S	MAYER, L. O.	7912170354	50-263 F
MARSHALL, N. H.	7912120254*	PR		7912310454+	50-293 S	MAYER, L. O.	7912200432	50-282 P
Marshall, W. H.	7912310187	PROJ	HATOTAN, H. I.	7912200453*	HASTE MOT	MAYER, L. D.	7912200369	50-263 P
Marsh, R. J.	7912070026	50-395 S	MATEON, V.	7912170356	XPORTLIC	MAYER, L. D.	7912200365	50-282 P
Martino, I.	7912140425	50-224 G	HATSON, V.	7912170364	XPORTLIC	MAYER, L. D.	7912270568	50-263 S
Martin, D. L.	7912140171	FOTA	MATSON, V.	7912170338	XPORTLIC	MAYER, L. D.	7912270333	50-263 S
Martin, T. J.	7912130464*	50-354 S	MATEON, V.	7912260208*	XPORTLIC	MAYER, L. D.	7912270491	50-282 S
.t., T., Nitram	7912140537*	50-311 S	MATSON, V.	7912260212*	XPORTLIC	MAYER, L. O.	7912270540	50-263 F
J., T., Nitram	7912140267	50-354 Q	MATSON, V.	7912260298	XPORTLIC	MAYER, L. O.	7912310475	50-282 S
J., T., Nitram	7912170234	50-354 Q	MATSON, V.	7912260189	XPORTLIC	MAYER, L. O.	7912310365	50-263 F
J., T., Nitram	7912140289	50-354 Q	MATSON, V.	7912260196*	XPORTLIC	MAYER, L. O.	7912310422	50-263 S
J., T., Nitram	7912180435	50-311 Q	MATSON, V.	7912210104	XPORTLIC	MCALDUFF, H. J.	7912260161	XPORTLIC
Martin, H. O. Martin, H. O. Martin, H. O. Martin, H. O. Martin, H. O.	7912200552 7912200575 7912200493 7912200490 7912200444	50-334 S 50-247 S 50-272 S 50-247 S 50-247 S	HATSON, V. HATT, P. K. HATT, P. K. HATT, P. K. NATTHENS, C. M.	7912260205 7912050609 7912060016 7912060016 7912120266+	XPORTLIC PROJ PROJ CONTRACT	MCDREARTY, R. A. MCDREARTY, R. A. MCCABE, E. C. MCCABE, E. C. MCCABE, E. C.	7912030048± 7912200472± 7912070139± 7912060171± 7912200213±	50-333 Q 50-284 Q 50-293 Q 50-20 Q 50-219 Q
MARTIN, H. O. MARTIN, T. T. MARTIN, H. O. MARTIN, H. O. MARTIN, H. O.	7912200073 7912060662 7912180041 7908010163* 7912120549*	50-247 S 50-29 S 50-213 S FOIA 70-820	HATTISON, L. HATTISON, L. HATTIHOE, J. J. HATTIHOE, J. J. HATTIHOE, J. J.	7912050343+ 7912050343+ 7912210155+ 7912040392 7912040478	XPORTLIC 50-574	HCCAIN.R. HCCARTHY.R.H. HCCAUGHY.R.U. MCCLAREN.S.A. HCCLAIN.C.H.	7912070165 7912270605 7912040082 7912130175 7912210310=	FOIA 50-286 J 50-320 S 50-289 C 50-219 R
Martin, H. O. Martin, H. G. Martin, H. O. Martin, H. O. Martin, H. O.	7912200433* 7912050127* 7912040121* 7912100211* 7912200081*	70~135 70~135 50~334	MATTIMOE, J. J. MATTIMOE, J. J. MATTIMOE, J. J. MATTIMOE, J. J. MATTIMOE, J. J.	7912050500 7912070426 7912110325 7912180638 7912110319	50-312 J 50-312 S 50-312 S 50-312 S 50-312 P	HCCLINTOCK, R. O. HCCLINTOCK, R. O. HCCLINTOCK, R. O. HCCLINTOCK, R. O. HCCLINTOCK, R. O.	7912310121 7912310329 7912060269* 7912030224* 7912040038*	1&E 1&E 70-1362 40-1386 40-341
MARTIN, H. O.	7912260115* 7912260068* 7912200475* 7912190775* 7912070269	50-277 Q	MATTIMOE, J. J.	7912140450	50-312 S	HECLINTDEK, R. O.	7912110182	40-8631
MARTIN, H. G.		50-54 Q	MATTIMOE, J. J.	7912270462	50-312 P	HECLINTOCK, R. O.	7912110175#	40-7344
MARTIN, H. G.		50-29 Q	MATTIMOE, J. J.	7912180551	50-312 S	HECLINTDEK, R. O.	7912040031	40-341
MARTIN, H. O.		70-1100	MATTIMOE, J. J.	7912180607	50-312 P	HECLINTOCK, R. O.	7912030221	40-1386
MARTIN, H. G.		70-371	MATTIMOE, J. J.	7912280575	50-312 P	HECLINTDEK, R. O.	7912060248	70-1362
MARTIN, H. O.	7912200095#	70-135	MATTIMOE, J. J.	7912270246	50-312	HCCLINTOCK, R. O.	7912110159	40-7344
MARTIN, H. G.	7912050252	50-293 Q	MATTIMOE, J. J.	7912260215		HCCORKLE, B. A.	7912120004	50-466 0
MARTIN, H. O.	7912050079	50-184 Q	MATTIMOE, J. J.	7912260279		HCCORKLE, B. A.	7912310155	50-466 G
MARTIN, H. O.	7912050120	70-135	MATTIMOE, J. J.	7912270329		HCCORHACK, J. E.	7912190362*	FOIA
MARTIN, H. O.	7912120531	70-820	MATTIMOE, J. J.	7912310358		HCCORHACK, R. O.	7912070203*	FOIA
MARTIN, N. O. MARTIN, H. O. MARTIN, H. O. MARTIN, H. O. MARTIN, H. O.	7912040097 7912050374 7912070085 7912100049 7912100205	50~334	MATTIMOE, J. J. MATTIMOE, J. J. MATTIMOE, J. J. MATTIMOE, J. J. MATTIMOE, J. J.	7912240273 7912240230 7912240255 7912240224 7912280467	50-312 S 50-312 F 50-312 P 50-312 P	HCCORKLE, O. M. HCCORKLE, O. M. HCCORKLE, O. M. HCCORKLE, O. M. HCCORKLE, O. M.	7912270003 7912130172 7912310082 7912310166 7912070211*	50-267 F 70-8 70-1308 70-754 FDIA
MARTIN, H. G. MARTIN, H. G. MARTIN, H. G. MARTIN, H. G. MARTIN, H. G.	7912200296 7912260092 7912200317 7912200530 7912200510	70-33 50-333 <b>Q</b> 70-371 50-334 <b>Q</b> 70-364	HATTIMOE, J. J. HATTIMOE, J. J. HATTIA, H. J. HATTIA, H. J. HATTIA, H. J.	7912280496 7912310452 7912200182* 7912200037* 7912200198*	50-312 P 50-312 G CONTRACT CONTRACT CONTRACT	McDiarnid, R. C McDiarnid, R. C. McDiarnid, R. C. McDiarnid, R. C. McDiarnid, R. C.	7912030042 7912120446 7912140226 7912130483 7912130483	PROJ PROJ PROJ 50-445 M
MARTIN, N. O. MARTIN, N. O. MARTIN, N. O. MARTIN, N. O. MARTIN, N. O.	7912260050 7912260330 7912260059 7912260066 7912270173	50-220 Q 50-134 Q 70-820 70-1143 70-1143	HATTIA, H. J. HATTIA, H. J. HATTIA, H. J. HATTIA, H. J. HATTIA, H. J.	7912110185* 7912140294* 7912140303* 7912070492* 7912210383*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	MCDIARNID, R. C MCDIARNID, R. C. MCDIRGUGH, M. D. MCDIRGUGH, M. D. MCDIRGUGH, M. D. MCDIRGUGH, M. D.	7912030042 7912120446 7912110280 7912030243 7912110465	PROJ PROJ XPORTLIC XPORTLIC RES
MARTIN, U, O,	7912260043	70-371	MATTIA, M. J.	7912210387*	CONTRACT	HCDUFFIE, M. A.	7912280555=	50-400 A
MARTIN, U, O,	7912200474	50-29 0	MATTIA, M. J.	7912200175*	CONTRACT	HCDUFFIE, M. A.	7912176142	50-400 0
MARTIN, U, O,	7912190768	70-1100	MATTIA, M. J.	7912170408*	CONTRACT	HCDUFFIE, M. A.	7912170161	50-400 Q
MARTIN, U, O,	7912200076	70-371	MATTIA, M. J.	7912200183*	CONTRACT	HCDUFFIE, M. A.	7912120392	50-400 A
MARTIN, U, O,	7912200092	70-135	MATTIA, M. J.	7912180026*	CONTRACT	HCDUFFIE, M. A.	7912120416	50-400 A
MARTIN, U. G.	7912200426	70-135	HATTIA: J.	7912050078+	50-443 6	MCDUFFIE; M. A.	7912290546	50-400 A
MARTIN, U. G.	7912260054	50-54 0	HATTIA: J.	7912260298+	50-352 6	MCDUFFIE; M. A.	7912270342	50-400 A
MARTIN, M. G.	7912260109	50-277 0	HATTSON: R. J.	7912280620	10CFR	MCFADDEN, J. R.	7912110167=	40-7344
MARTIN, R. D.	7912070050	50-348 \$	HATTSON: R. J.	7912070321+	FOIA	MCFARLAND, C. R.	7912060657=	50-339 Q
MARTIN, R. D.	7912070063	50-348 \$	HATTSON: R. J.	7912070102+	50-155 6	MCFARLAND, C. R.	7912060657=	50-399 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	AGCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUB-JECT CATEGORY
MCFARLAND, C. R. MCGAUGHY, R. MCGAUGHY, R. W. MCGAUGHY, R. H. MCGAUGHY, R. W.	7912210051 7912050078* 7912060200* 7912200457* 7912260298*	50-400 B 50-443 Q 50-387 Q 50-410 G 50-352 G	MILLER, H. I. HILLER, H. I. MILLER, M. I. MILLER, L. C. MILLER, M. I.	7912190162 7912170058 7912310339 7912210020* 7912170179	50-329 0 50-155 0 50-329 0 GA999 50-155 0	MILLB, L. M. MILLB, L. M. MILLB, L. M. MILLB, L. M. MILLB, L. M.	7912140255 7910310325 7912040448 7912030602* 7912040152	50-327 8 50-327 0 50-327 0
MCGAUGHY, R. W.	7912210024*	50-387 G	MILLER, M. I.	7912170058	50-155 Q	MILLS, L. M.	7912110202	50-327
MCGEE, M. V.	7912190561	RES	MILLER, B. M.	7912120340	50-580 P	MILLS, L. M.	7912280461	
MCGDVERN, J. J.	7912070086*	70-687	MILLER, C. K.	7912170201	50-247 Q	MILLS, L. M.	7912130429	
MCGDVERN, J. J.	7912070088*	70-687	MILLER, L. K.	7912180383*	50-272 R	MILLS, L. M.	7912130581	
MCGOVERN, J. J.	7912050648*	70-687	MILLER, M. E.	7912260088*	50-445 M	MILLS, L. M.	7912310020	
MCGOVERN, J. J.	7912260061*	50-54 Q	MILLER, M. E.	7912040075	50-320 G	MILLS, L. M.	7912130520	50-327 B
MCGOVERN, K. S.	7912140112*	70-2423	MILLER, M. E.	7912040079	50-320 G	MILLS, L. M.	7912200269	REGOD
MCGOVERN, K. S.	7912130450	PR	MILLER, M. E.	7912280310	50-320 G	MILLS, L. M.	7912200289	REGOD
MCGRANERY, J. P.	7912130267	PR	MILLER, M. E.	7912120030	50-344 G	MILLS, L. M.	7912260027	REGOD
MCGRANERY, J. P.	7912130267	PR	MILLER, M. E.	7912180202	50-445 M	MILLS, L. M.	7912280173	REGOD
MCGRATH, E. J.	7912280684	WASTE MOT	MILLER, M. E.	7912180209*	50-445 M	MILLS, L. M.	7912280587	REGGD
MCGREGOR, L. G.	7912050412+	50-305 G	MILLER, M. E.	7912180231*	50-445 M	MILLS, L. M.	7912050507	50-327 G
HCGUIRE, P. J.	7912040259	50-293 P	MILLER, M. E.	7912180240*	50-445 M	MILLS, L. M.	7912050513	50-370 S
MCGUIRE, P. J.	79120403B7	50-293 8	MILLER, M. E.	7912180252*	50-445 M	MILLS, L. M.	7912050517	50-438 S
HCGUIRE, P. J.	7912050448	50-293 R	MILLER, M. E.	7912180262*	50-445 M	MILLS, L. M.	7912050522*	50-438 S
MCGUIRE, P. J. MCGUIRE, P. J. MCGUIRE, P. J. MCGUIRE, P. J. MCGUIRE, P. J.	7912070390 7912200372 7912110311 7912110370 7912180630	50-293 S 50-293 R 50-293 S 50-293 S 50-293 S	MILLER, M. E. MILLER, M. E. MILLER, M. E. MILLER, M. E. MILLER, N. E.	7912180272* 7912180281* 7912180289* 7912180297* 7912180306*	50~445 M 50~445 M 50~445 M 50~445 M 50~445 M	MILLE, L. M. MILLE, L. M. MILLE, L. M. MILLE, L. M. MILLE, L. M.	7912050524 7912050541 7912190578 7912030199 7912190692	50-327 9 50~564 9 50~566 6 50~566 8
MCGUIRE, P. J.	7912200353	50-273 S	MILLER, M. E.	7912180311* 7912180320* 7912180329* 7912180340* 7912180349*	50-445 M	MILLS, L. M.	7912050477	50-370 S
MCGUIRE, P. J.	7912270182	50-273 S	MILLER, M. E.		50-445 M	MILLS, L. M.	7912040435	50-259 P
MCGUIRE, P. J.	7912260278	50-293 S	MILLER, M. E.		50-445 M	MILLS, L. M.	7912050484	50-390 S
MCGUIRE, P. J.	7912310413	50-273 R	MILLER, M. E.		50-445 M	MILLS, L. M.	7912050508	50-259 P
MCGUIRE, P. J.	7912310453	50-273 S	MILLER, M. E.		50-445 M	MILLS, L. M.	7912200003	50-390 G
MCGUTRE: W, F,	7912270369	50-478 A	NILLER, M. E.	7912180360*	50-445 M	MILLS, L. M,	7912130521	50-438 A
MCGURREN: H, J,	7912050611	50-478 Q	HILLER, M. E.	7912180372*	50-445 M	MILLS, L. M,	7912140232	50-518 A
MCGURREN: H, J,	7912050615*	50-478 Q	HILLER, M. E.	7912180361*	50-445 M	MILLS, L. M,	7912190620	50-390 S
MCGURREN: M, J,	7912070243	50-382 Q	HILLER, M. E.	7912180395*	50-449 M	MILLS, L. M,	7912050071	50-438 A
MCGURREN: H, J,	7912070248*	50-382 Q	HILLER, M. E.	7912180404*	50-445 M	MILLS, L. M,	7912060525	50-327 A
HCOURREN, H. J.	7912180087	50-498	MILLER, M. E.	7912180414*	50-445 M	MILLE, L. M.	7912040522	50-327 A
HCOURREN, H. J.	7912260006		MILLER, M. E.	7912180423*	50-445 M	MILLE, L. M.	7912110369	50-327 A
HCOURREN, H. J.	7912260292		MILLER, M. E.	7912140108	70-2623	MILLE, L. M.	7912120422	50-327 S
HCHENRY, T. J.	7912050119#		MILLER, M. E.	7912270103	50-445 M	MILLE, L. M.	7912120477	50-327 S
HCHENRY, T. J.	7912310346*		MILLER, M. E.	7912270137	50-445 M	MILLE, L. M.	7912130258	50-390 R
HGINTYRE, J. HCKEOWN, L. M. HCKEOWN, L. M. HCKINLEY, J. C. MCLEAN, R. V.	7912110108# 7912040129# 7912050086# 7912110090# 79121190546	ACR9 50-334 Q 50-184 Q ACR6 RE9	MILLER, W. O.	7912100079* 7912120038 7912120050 7912100350 7912100353	50-286 P 70-8 70-734 70-754 70-1257	MILLE, L. M. MILLE, L. M. MILLE, L. M. MILLE, L. M. MILLE, L. M.	7912130482 7912100359 7912100361* 7912170313 7912170317	50-257 P 50-327 K 50-327 K 50-320 S 50-370 S
MCLEAN, R. B.	7912190561	RES	MILLER, W. O.	7912110115	40-1162	MILLS, L. M.	7912170323*	50-390 8
MCMAHAN, J.	7912180393	FOIA	MILLER, W. O.	7912110288	70-27	MILLS, L. M.	7912170324	50-390 8
MCMULLEN, R. B.	7912260375*	50-443 G	MILLER, W. O.	7912120045	70-734	MILLS, L. M.	7912310008	50-327 0
MCNAMARA, A. E.	7912180351*	50-244 R	MILLER, W. O.	7912120052	70-8	MILLS, L. M.	7912190574	50-327 8
MCNATT, T.	7912060221*	50-334 G	MILLER, W. O.	7912120252	70-27	MILLS, L. M.	7912210348	50-327 A
MCNEILL, H. M.	7912130428* 7912110506* 7912200586 7912100449 7912110040	GA999	MILLER, W. O.	7912040022	50-201 F	MILLB.L.M.	7912270289	50-327 K
MCNEILL, M.		GA999	MILLER, W. O.	7912100022	50-286 P	MILLB.L.M.	7912200503	50-327 A
MCNIEL, M.		50-339 H	MILLER, W. O.	7912180283	50-346 P	MILLB.L.M.	7912280544	50-327 6
MCNULTY, A.		CONTRACT	MILLER, W. O.	7912170132	50-280 P	MILLB.L.M.	7912270251	50-327 F
MCNULTY, A.		CONTRACT	MILLER, W. O.	7912170324	50-293 F	MILLB.L.M.	7912270424	50-553 A
MECCA, J. E. MECCA, J. E. MEDLOCK, R. L. MEDROW, L. A. K. MEDROW, L. A. K.	7912270215 7912270512 7912200604 7912170401 7912140288	50-522 A 50-522 H 40-8452 CONTRACT CONTRACT	MILLER, W. O. MILLER, W. O. MILLER, W. O. MILLER, W. O. MILLER, W. O.	7912170042 7912170071 7912170123 7912190156 7912190327	50-195 P 50-318 P 50-344 P 50-285 P 50-284 P	MILLS, L. M. MILLS, L. M. MILLS, L. M. MILLS, L. M. MILLS, L. M.	7712280557 7712280581 7912270473 7912270480 7912270356	50-438 S 50-327 S 50-327 S 50-390 S
MEDROW, L. A. K.	7912140297	CONTRACT	MILLER, W. O.	7912190337	50-288 P	MILLB, L. M.	7912270527	50~259 P
MEIEROTTO, L. E.	7912060204	PRDJ	MILLER, W. O.	7912190617	50-289 P	MILLB, L. M.	7912270533	50~327 K
MEISS, R. L.	7912170251	PRDJ	MILLER, W. O.	7912200674	50-368 P	MILLB, L. M.	7912280495	50~438 A
MEISS, R. L.	7912170251	PROJ	MILLER, W. O.	7912260256	70-1100	MILLB, L. M.	7912270363	50~327 A
MENARO, H. W.	7912310315	40-8745	MILLER, W. O.	7912270088	50-10 F	MILLB, L. M.	7912310382	50~327 A
MENCZER, W, N. MERRILL, J. MERROW, R. J. HERSON, B. D. MERSON, B. D.	7912170414	CONTRACT	MILLER, W. O.	7912210131	50-310 P	MILLBAP, W. J.	7912100070*	70-824
	7912190415	FOIA	HILLER, H. O.	7912280040	50-247 P	MILLBAP, W. J.	7912200612*	70-27
	7912030222*	40-1386	MILLER, W. O.	7912280064	50-293 P	MILLTER, D. B.	7912110408	50-309 0
	7912310416	50-317 R	MILLER, W. O.	7912280147	50-244 P	MILNB, M. C.	7908080606*	50-311 0
	7912310418*	50-317 R	MILLER, L. F.	7912280096*	50-206 Q	MINEGK, D. L.	7912140470	50-931 8
MERSON, S. D.	7912280523	50-318 R	MILLER, H. J.	7912040029	40-8102	MINECK, D. L.	7912140479	50-331 8
MERSON, S. D.	7912280527*	50-318 R	MILLER, H. J.	7912170034	PROJ	MINECK, D. L.	7912170213	50-331 8
MERTZ, L. R.	7912140143	71-160	MILLER, H. J.	7912170188	WASTE MOT	MINECK, D. L.	7912170224	50-331 8
METZENBAUM, H. M.	7912120563*	50-344 U	MILLER, H. J.	7912180394	40-8728	MINECK, D. L.	7912180518	50-331 9
MEYER, R.	7912190458	F01A	MILLER, H. J.	7912140121*	WASTE MOT	MINECK, D. L.	7912190398	50-331 R
MEYER, M. MICHELBON, C. MIDURA, H. J. MIDURA, H. J. MIDURA, H. J.	7912070152*	50-471 G	MILLER, H. J.	7912280210*	WASTE MOT	Minoque, R. B.	7910010550	50-257 P
	7912310239*	ACRB	MILLER, H. J.	7912040033	PR	Minoque, R. B.	7912120221	PDR MISC
	7912040511	50-272 R	MILLER, H. J.	7912130214	PDR MISC	Minoque, R. B.	7912120162	PRM
	7912040521	50-272 R	MILLER, H. J.	7912170129	40-8745	Minoque, R. B.	7912280474	50-320 T
	7912040493	50-272 R	MILLER, H. J.	7912200293	40-8728	Mitchell, R.	7912180058*	50-387 0
MIDURA: H. J. MILLER: D. S. MILLER: D. S. MILLER: D. S. MILLER: D. S. MILLER: E. F.	7912110418# 7912110425#	50-272 R PR 50-309 G 50-309 G CONTRACT	MILLER, W. O. MILLER, H. J. MILLER, H. J. MILLER, H. J. MILLER, J. R.	7912170121 7912170109 7912270067 7912070129 7912120448*	70-1257 WASTE MOT 40-8745 PRDJ 50-516 G	MITCHELL, C, D. MITCHELL, D, G. MITCHELL, D, G. MITCHELL, D, G. MITTL, R, L. MITTL, R, L.	7912100276* 7912130479* 7912270328* 7912180530 7912270567	CONTRACT 50-289 8 50-289 8 50-311 A 50-354 A

	ACCESSION	BUBJECT	ROHTUA	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
.AUTHOR HIGDENOS, L. HIGDENOS, L. HIGDENOS, L. HODENOS, L.	NUMBER 7912050385* 7912050622* 7912110081* 7912100409*	CATEGORY 50-327 G 50-280 G GA799 GA799 ACRS	MORTON, K. V.	7912110004* 7912110002* 7912110007* 7912110017* 7912110017* 7912120073*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	MURPHY. C. E. MURPHY. C. E. MURPHY. C. E.	7912310326 7912130093* 7912110220 7912110193	50-395
MOLELLO, S. A. MOLELLO, S. A. MONDEN, T. MONDEN, T. MONDEN, T.	7912190341* 7912130089 7912030058 7912200283 7912310549 7912180288	NUREG XPORTLIC XPORTLIC XPORTLIC FOIA	MORTON, K. V. MORTON, K. V. MORTON, K. V. MORTON, K. V. MORTON, K. V.	7912120310* 7912100091* 7912110541* 7912120086* 7912120266*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	HURPHY, C. E. Murphy, C. E. Murphy, C. E. Kurphy, C. E. Murphy, C. E.	7912060266 7912060981 7912210016* 7912180347 7912210135	50-390 G 50-393 G 50-348 G 50-389 G 50-471 G
HONTION A. HOODY, R. HOODY, D. E. HOODY, D. E.	7912180233 7912180510* 7912180016 7912260222 7912180387	50-3 R 50-275 U 50-309 G 50-309 P 50-309 R	MORTON, K. V. MORTON, K. V. MORTON, K. V. MORTON, K. V. MORTON, K. V.	7912180037* 7912100125* 7912060176* 7912100105* 7912180019*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	MURRAY, T. D. HURRAY, J. O. MURRAY, T. D. MURRAY, T. D. MURRAY, T. D.	7912130277 7912130377 7912130373 7912170295 7912170300	50-346 S 50-346 R 50-346 S 50-346 S 50-346 S
MOODY, D. E. MOODY, D. E. MOODY, D. E. MOODY, D. E. MOODY, D. E.	7912030086* 7912170365 7912140260 7912130018 7912180433	50-271	MORTON, K. V. MORTON, K. V. MORTON, R. V. MOSELEY, N. C. MOSS, D. J.	7912100386* 7912100394* 7912180011* 7912050284 7912140483*	CONTRACT CONTRACT CONTRACT POR MISC RES	MURRAY, T. B. MURRAY, T. D. MURRAY, T. D. MURRAY, T. D. MURRAY, T. D.	7912260234 7912260253 7912270594 7912270395 7912270402	50-344 S 50-344 S 50-346 S 50-346 S
HOODY, D. E. HOODY, D. E. HOODY, D. E. HOODY, D. E.	7912180238 7912180402 7912310341 7912040185* 7912110314	50-271 P 50-271 R 50-271 P 50-27 Q 50-29 P	HOTT, J. E. MOTULSKY, A. G. HOTULSKY, A. G. HOWBOTSSE, R. M. MOWRY, M. R.	7912110326* 7912270056* 7912270059* 7912130933 7912120012	50-335 P 50-522 G 50-522 G PR PR	MURRAY, T. D. MURRAY, T. D. MYNATT, F. R. MYRADO, A. L. NACHTER, L. J.	7912270413 7912170167 7912140374* 7912270545*	50-346 8 RES 50-263 R 50-263 P
HOGDY, D. E. HOGDY, D. E. HOGDY, D. E. HOGDY, D. E. HOGDY, D. E.	7912120299 7912130230 7912180611 7912180341 7912270532	50-29 P 50-29 P 50-29 P 50-29 R 50-29 P	MOWRY, W. R. MUCHNICKI, E. D. MUELLER, E. F. MUIR, J. F. MULERD, J. G.	7912070226 7912130311 7912180227 7912140499= 7912310509	71-6300 PR 50-486 9 RES WASTE MOT	NAGAI, Y. NAGAI, Y. NAGAI, Y. NAIDU, K. R. NAIDU, K. R.	7912040327 7912270544 7912230263* 7912260137* 7912180236*	50-219 P 50-219 P 50-329 Q 50-329 Q
MOODY, D. E. HOODY, D. E. HOON, R. E. MOON, R. E. MOON, B. T.	7912310554 7912120098* 7912120083* 7912280174*	50-27 P GA979 GA979 50-349 G 50-466 F	MULKEY, M. E. MULKEY, M. E. MULKEY, M. E. MULKEY, M. E. MULKIN, R.	7912190606 7912130130 7912310120 7912310138 7912190113	50-287 0 50-287 0 50-287 0 50-287 0 70-754	NATOU, K. R. NAUGHTON H. F. NAUMAN. G. NAVARRO, J. P. NAYLOR, R. M.	7912210349 7912260355* 7912270517 7912100288*	50-10 P 50-373 0 50-322 0 50-346 S
HOOR, C. H. HOOR, C. H. HOOR, C. H. HOOR, C. H. HOOR, C. H.	7912070469 7912110435 7912110447* 7912110463* 7912110475*	50-454 A 50-454 A 50-454 A 50-454 A	MULLER, D. R. MULLER, D. R. MULLER, D. R. MULLER, D. R. MULLER, D. R.	7912110126* 7912130070* 7912200168* 7912200069 7912190292	50-3 0 50-275 0 50-275 0 POR MISC PDR MISC	NAYLOR, R. W. NAYLOR, R. W. NEEL, J. N. NEELY, D. R. NEELY, D. R.	7912130486* 7912170309* 7912280674* 7912030256* 7912040179*	50-346 8 27-48 50-219 0 50-320 0
HOORE, R. E.  - HOORE, J. S. HOORE, J. S. HOORE, J. S. HOORE, J. S.	7912110185* 7912170424* 7912050095* 7912040439	TOPREP 70-1143 70-1143 50-334 R	MUNNERY, H. J. MUNNERY, M. J. MUNRO, J. J. MUNRO, J. J. MUNRO, J. J.	7912130494 7912130490 7912180293 7912210289 7912200461	PR PR 71-9028 71-9137 71-9027	NEELY, D. R. NEIGHBORB, D. NEIGLER, J. H. NEIGLER, J. H. NELGON, J. D.	7912310045* 7912190200 7912070162* 7912180342* 7912310169	50-280 P 50-373 G 50-373 G 40-8481
MOORE, 9, 0, MOORE, 9, 0, MOORE, 9, 0, MOORE, 9, 0, MOORE, 9, 0,	7912040443* 7912100114 7912110351 7912120288 7912310010	50-302 Q 50-302 P 50-302 P 50-302 G 50-302 F	MUNRO, J. J. HURPHY, P. M. HURPHY, C. E. HURPHY, C. E. MURPHY, C. E.	7912200619 7912050539 7912200016 7912110233* 7912060287*		NELSON: B. M. NELBON: P. R. NELSON: P. R. NELBON: P. R. NEUMANN: M. R.	7912280645* 7912070368* 7912070335* 7912070316* 7912170267	FOIA FOIA FOIA 40-8721
MODRE, J. E. MODRE, J. E. MODRE, R. N. MODRE, R. N. MODRE, R. N.	7912310533 7912030211 7912120468 7912130087 7912280069	50-250 S XPORTLIC XPORTLIC XPORTLIC XPORTLIC	MURPHY, C. E. MURPHY, C. E. MURPHY, C. E. MURPHY, C. E. MURPHY, C. E.	7912110203 7912040681 7912070056 7912050386 7912060479	50-387 0 50-339 0 50-390 0 50-416 0 50-327 0	NEUMANN, M. R. NEVINSKI, D. E. NEUACHECK, R. L. NEUMAN, P. NEUMAN, P.	7912160088 7912310428 7912260134 7912130360 7912260108	* 50-263 S * 50-228 G 40-7869 * 40-8674
MOCRETR. N. MOCRETR. N. MOCRETR. N. MOCRETR. N. MOCRETR. N.	7912030108 7912120203 7912130123 7912030046 7912120456	XPORTLIC XPORTLIC XPORTLIC XPORTLIC	MURPHY, C. E. MURPHY, C. E. MURPHY, C. E. MURPHY, C. E. MURPHY, C. E.	7912060490 7912050380 7912050562 7912050616 7912060587	50-327 G 50-416 G 50-416 G	NEMMAN, J. R. NEMMAN, J. R. NEMMAN, J. R. NEMMAN, J. R. NEMMAN, J. R.	7912140525 7912170246 7912100471 7912140193 7912190104	50-466 0 50-466 0 50-466 0 50-466 0
HOORE, J. E. HOORE, J. E. HOORE, J. E. HOORE, J. E.	7912130104 7912070344 7912040078 7912070074 7912190204	# 50-155 Q 50-3 Q 50-155 Q 50-155 Q	MURPHY, C. E. MURPHY, C. E. HURPHY, C. E. MURPHY, C. E. MURPHY, C. E.	7912070108 7912050083 7912050323 7912050486 7912050550	50-416 Q 50-518 Q 50-327 Q	NEWMAN, J. R. NEWMAN, J. R. NEWMAN, J. R. NEWMAN, G. L. NEWMAN, J. R.	7912190072 7912140174 7912260286 7912190301 791209044	7 50-466 0 5 50-466 0 8* FUIA 2 50-478 0
MOORE, J. E. MOORE, J. E. MOORE, J. E. MOORE, D. E.	7912190310 7912260366 7912310132 7912070006 7912210283	50-3 0 2 50-272 0 3 50-159 0 3 50-269 0	MURPHY, C. E. HURPHY, C. E. MURPHY, C. E. MURPHY, C. E. HURPHY, C. E.	7912050621 7912060077 7912060597 7912210157 7912030521	50-546 0 50-553 0 2* 50-491 0	NEWMAN, J. R. NEWMAN, J. R. NEWMAN, J. R. NEWMAN, J. R. NICHOLB, L. A.	771214052 791217024 791210047 791224028 791219054	6 50-466 0 1 50-466 0 6 50-466 0 1* PDR MISC
MOORE, D. E. HORRAN, R. G. MORGAN, D. W. MORGAN, U. E.	7912030100 791203005 791211021 791231022 791231017	3* 50-335 Q 5* 50-206 R 3 50-297 Q 6 XPORTLIC	MURPHY, C. E. HURPHY, C. E. HURPHY, C. E. HURPHY, C. E. HURPHY, C. E.	791218035 791220061 791218014 791218016 791231009	7 50-438 G 1 50-261 G 6* 50-413 G	NICHOLAB, H. H. NICHOLAB, H. H. NICHOLAB, H. H. NICHOLBON, N. A. NICHAUS, P. H.	791207020 791205034 791231005 791218035 791218005	11+ 50-387 0 39+ 50-322 0 1B 1&E 54 50-416 \$
HORGAN, H. E. HORGAN, H. E. HORGAN, R. HORGAN, R.	791231018 791217034 791217035 791220038 791220031	0* XPORTLIC 8 XPORTLIC 3* XPORTLIC 8* 50-339 A 2 50-339 A	HURPHY, C. E. MURPHY, C. E. MURPHY, G. E. MURPHY, C. E.	791231010 791203043 791221020 791231026 791231027	7 50-281 G 6* 50-400 G 3 50-257 G 1 50-387 G	NIGHTINGALE, R. I NIJHAWAN, B.	79121901 79121201 79121303 79121801 79122001	57 NUREG 26* PR 65 RES 10 71-6581
HORGAN, R. HORGAN, R. HORRILL, P. J. HORRILL, P. J. HORRILL, P. J. HORTON, K. V. HORTON, K. V.	791212009 791204010 791207019 791209031 791207018 79121100	04* 50-275 Q 04* 50-275 Q 06* 50-87 Q 06* 50-187 Q	MURPHY, C. E.	79121103 79121700 79123102 79122601 79122603	11* 50-400 G 0* 50-364 G 22 50-348 G 17 50-327 G	NILSON, R. NILSON, R. NIX, R. T.	79122701 79122800 79122800 79120804 79120704	03 71-6561 06* 71-6561 45* 50-366

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	АИТНОЯ	ACCEBSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
NIX.R. T. NIX.R. T. NIX.R. T. NIX.R. T. NIX.R. T.	79121303924 79121304004 79121304004 79121304214 79121404364	50-356 S 50-366 S 50-366 S 50-321 S	O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P.	7912110538 7912110540 7912110545 7912110551 7912110558	50-348 0 50-261 0 50-269 0 50-488 0 50-302 0	O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P.	7912200075 7912280345 7912280370 7912280377 7912280391	50-437 Q 50-348 Q 50-261 A
MIX.R. T. MIX.R. T. MIX.R. T. MIX.R. T. MIX.R. T.	7912170316* 7912170321* 7912260224* 7912260249*	50-321 S 50-321 S 50-356 S 50-321 S	G'REILLY, J.P. G'REILLY, J.P. G'REILLY, J.P. G'REILLY, J.P. G'REILLY, J.P.	7912110561 7912110562 7912110566 7912110568 7912110570	50-250 0 50-321 0 50-416 0 50-395 0 50-395 0	O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P.	7912280398 7912280402 7912280404 7912280416 7912280421	
NIX.R. T. NIX.R. T. NIXON. M. A. NIXON. M. A. NIXON. M. A.	7912310468* 7912310420* 7912050019 7912170177	50-386 S 50-386 S 50-321 S 40-2061 40-2061	O'REILLY, J.P. O'REILLY, J.P. O'REILLY, J.P. O'REILLY, J.P. O'REILLY, J.P.	7912110575 7912110587 7912110590 7911300140 7912040404	50-259 0 50-280 0 50-437 0 50-280 0 50-348 0	O'REILLY, J. P. D'REILLY, J. P.	7912280423 7912280426 7912280441 7912280450 7912280115	50-395 0 50-259 0 50-260 9 50-437 0 50-348 0
NORDERHAUG, L. R. NORDERHAUG, L. R. NORDERHAUG, L. R. NORDERHAUG, L. R.	7912050041 7912030101 7912200437 7912180244 7912110095	40-2061 50-344 S 70-1257 70-734 50-27 Q	O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P.	7912060605 7912060607 7912060614 7912060616 7912060617	50-261 0 50-269 0 50-302 0 50-320 0 50-321 0	O'REILLY, J. P.	7912280119 7912280124 7912280129 7912280134 7912280136	50-261 q 50-469 q 50-269 q 50-302 q 50-250 q
NORDERHAUG, L. R. NORDERHAUG, L. R. NORDERHAUG, L. R. NORDERHAUG, L. R. NORDERHAUG, L. R.	7912110100 7912110200 7912100433 7912130150 7912260162	50-243 Q 50-268 Q 70-25 50-344 Q 50-204 Q	O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P.	7912040418 7912040419 7912040420 7912070007 7912070013	50-416 Q 50-395 Q 50-259 Q 50-280 Q 50-437 Q	O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P.	7912280141 7912280144 7912280146 7912280150 7912280161	50-321 0 50-416 0 50-395 0 50-259 0 50-250 0
MORDERHAUG, L. R. NORDERHAUG, L. R. MOREL LUS, C. E. MOREL LUS, C. E. MORIAN, P. E.	7912260029 7912260375 7912070062* 7912160234* 7912260017*	70-734 50-70 () 50-341 () 50-440 () TOPREP	O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P.	7912110113 7912110123 7912110134 7912110140 7912110143	50-348	O'REILLY, J. P. OBERG, C. OBERG, C. OBERG, C. OBERG, C. R.	7912280164 7912200429 7912200448 7912200454 79122050473*	50-437 0 50-482 5 50-482 5 50-482 5
NORIAN, P. E. NORIAN, P. E. NORIAN, P. E. NORRHOLM, L. J. NORRHOLM, L. J.	7912170027* 7912176023 7912260012 7912030064* 7912060076*	TOPREP TOPREP TOPREP 50-272 Q 50-272 Q	G'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P.	7912110147 7912110149 7912110153 7912110154 7912110157	50~250 0 50~321 0 50~416 0 50~395 0 50~259 0	OBERG. C. OBERG. C. OBERG. C. OBERG. C. R. OBERG. C.	7912200085 7912210037 7912250090 7912050598 7912200560	50-482 S 50-482 S 50-482 S 50-458 S 50-458 S
MORRISA J. T. MOSENZO, L. V. MOSENZO, L. V. MOSENZO, L. V.	7912200046+ 7912120310+ 7912030214 7912036097 7912140141	50-272 G CENTRACT XPORTLIC XPORTLIC XFORTLIC	O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. F.	7912110186 7912110192 7912060142 7912060255 7912190371	50-280 0 50-437 0 50-325 0 50-416 0 50-364 0	OBERG, C. R. OERTEL, G. K. DESTHANN, H. J. OESTHANN, H. J. OESTHANN, H. J.	7912180119 7912280233 7912070135 7912060593 7912260105*	50-482 S PR 50-282 S 50-282 S 50-282 G
NOSENZO, L. V. NOSENZO L. V. NOVAK, T. M. NOVARRO, J. P. NOVARRO, J. P.	7912140149 7912140111 7908226421 7912120181 7912136451	XPORTLIC XPORTLIC 50-320 P 50-322 Q 50-322 Q	O'REILLY, J. P.	7912190374 7912190376 7912190383 7912190386 7912190392	50~34B Q 50~400 Q 50~261 Q 50~269 Q 50~370 Q	OESTMARN, M. J. OESTMARN, M. J. OKREIJT, D. OKUDA: H. OKUDA: H.	7912240098* 7912210031* 7912140211 7912120572 7912260148*	50-266 Q 50-237 Q ACRS XPORTLIC XPORTLIC
NOVARRO, J. P. MOHICKT, S. J. MUSENT, E. L. NUSENT, E. L. MUSENT, E. L.	7912130015 7912060132 7912280331* 7912280311* 7912280295*	50-322 0 50-219 8 40-2259 40-2259 40-2259	O'RETLLY, J. P. O'RETLLY, J. P. O'RETLLY, J. P. O'RETLLY, J. P. O'RETLLY, J. P.	7912190397 7912190439 7912190442 7912190447 7912190449	50~488	ORUDA, H. ORUDA, H. OLIU, W. E. OLLER, R. E. OLLER, R. E.	7912260174* 7912260165* 7912170011 7912120118* 7912180273*	XPORTLIC XPORTLIC NUMEO GA799 GA799
NUGENT, E. L. NUGENT, E. L. NUTT, C. W. O'CONNOR, P. M. O'DONNELL, E. P.	7912170282 7912170284 7912270554 7912070475 7912110572	40-2259 40-2257 50-514 D 50-10 P REGGD	O'REILLY, J, P. O'REILLY, J, P. O'REILLY, J, P. O'REILLY, J, P.	7912190454 7912190457 7912190459 7912190463 7912190464	50-321 q 50-414 Q 50-417 q 50-395 q 50-395 q	OLLER, R. E. OLLER, R. E. OLMSTEAD, W. J. OLMSTEAD, W. J. OLSEN, A. F.	7912110088* 7912110071* 7912210314 7912140100 7912070456	0A999 0A999 50-389 T 50-329 O
O'NEILL, J. P. O'NEILL, J. O'NEILL, J. H. O'REILLY, J. P.	7912110374 7912200077 7912260258+ 7912280154 7912030227+	50-155 0 FR 50-346 S 50-266 0 50-324 0	O.REITTA'T 6 O.REITTA'T 6 O.REITTA'T 6 O.REITTA'T 6 O.REITTA'A' 6	7912190472 7912190478 7912190492 7912190495 7912190500	50-259 Q 50-328 Q 50-3280 Q 50-404 Q 50-437 Q	DLSHAN, L. N. OLSHAN, L. N. OLSHAN, L. N. OLSHAN, L. N. OLSHAN, L. N.	7912060126 7912040102 7912060029 7912060070 7912120064	50-247 P 50-305 P 50-305 P 50-284 P
O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P.	7912030076* 7912040097 7912040106 7912040119 7912040128	50-261 0 50-348 0 50-261 0 50-468 0 50-269 0	O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P.	7912310284 7712310285 7912310290 7912310293 7912310297	50-348	OLSHAN, L. N. DLSON, D. L. OLSON, J. F. OLSON, R. C. OLSON, R. C.	7912240003 7912030220* 7912130590* 7912280419 7912240300	50-286 P 50-3 F 50-186 Q PR NUREQ 50-318 Q
O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P.	7912060136 7912060143 7912060148 7912060156 7912060159	50-302 q 50-250 g 50-321 0 50-416 8 50-395 q	O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P.	7912310301 7912310306 7912310308 7912310310 7912310313	50-321 a 50-416 a 50-395 a 50-395 a 50-392 a	ONSDORFF, K. A. ONSDORFF, K. A. ONSDORFF, K. A. OPEKA, J. F. OPEKA, J. F.	7912050177 7912130564 7912130567* 7912040421 7912040396	50-272 0 PR PR 50-336 9 50-336 8
D'REILLY, J. P.	7912050163 7912030223 7912070499 7912100159 7912100160	50-259 0 50-324 0 50-259 0 50-348 0 50-261 0	O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P.	7912310316 7912310330 7912310552 7912200005 7912200006	50-259 Q 50-280 Q 50-437 Q 50-348 Q 50-261 Q	OPEKA, J. F. OPEKA, J. F. OPEKA, J. F. OPEKA, J. F. OPEKA, J. F.	7912130459 7912040407 7912070381 7912070343 7912100299	50-336 S 50-336 S 50-336 S 50-245 S 50-245 S
D. WEITTA' 'Y 'B'  O. WEITTA' 'Y 'B'  O. WEITTA' 'Y 'B'  O. WEITTA' 'Y 'B'  O. WEITTA' 'Y 'B'	7912100166 7912100169 7912100176 7912100181 7912100184	50-488 Q 50-259 Q 50-302 Q 50-250 Q 50-321 Q	O. GEITTA' Y' b' O. BEITTA' Y' b' O. BEITTA' Y' b' O. BEITTA' Y' b'	7912200010 7912200026 7912200032 7912200033 7912200038	50-488 Q 50-269 Q 50-302 Q 50-250 Q 50-321 Q	OPEKA, J. F. DPEKA, J. F. OPEKA, J. F. OPEKA, J. F. OPEKA, J. F.	7912180363 7912180589 7912180392 7912180579 7912270515	50-245 R 50-336 S 50-336 R 50-336 G 50-245 S
D. WEITTA' 7' 6' D. WEITTA' 7' 6' D. WEITTA' 7' 6'	7912100188 7912100192 7912100200	50-416 Q 50-437 Q 50-259 Q 50-395 Q 50-260 Q	O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P.	7912200049 7912200052 7912200055 7912200040 7912200070	50-414 Q 50-375 Q 50-375 Q 50-257 Q 50-280 Q	OPREA, 6, W. ORR, W. D. ORTLOFF, 6, D. ORTLOFF, 6, D. ORTLOFF, 6, D.	7912060555 7912140541 7912130403 7912170417 7912310190	50-498 Q 71-159 PROJ PROJ 40-8102

					ACCESSION	SUBJECT		ANTHOD	ACCESSION NUMBER	SUBJECT CATEGORY
AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR	NUMBER	CATEGORY	- p	AUTHOR ETERSON. M. R.	7912070235	KPORTLIC KPORTLIC
ORTLOFF, C. D. DSSORNE, W. C. OUTTS, J. E.	7912190780 7912100005 7912050641* 7912180343*	40-8102 RES 50-324 50-324	1	PARR, O. D. PARR, O. D. PARR, O. D. PARR, O. D.	7912140057 7912180465 7912270060 7912280597 7912280602	50-387 P 50-498 A 50-373 F 50-387 A 50-311 A	<u>የ</u> የ	EYERSON, M. R. ETERSON, M. R. ETERSON, M. R. ETERSON, M. R.	7912040040	XPORTLIC XPORTLIC XPORTLIC
OVEN, H. S.  CYENTON, J. A.  OHSUEY, G. F.	7912280218 7912120240 7912100407* 7912100456*	PR PROJ 50-3 50-3	P P	PARR. D. D.  PARSONT, H. A.  PARTLOW, J. G.  PARTLOW, J. G.	7912200078* 7912170073 7912170067 7912170052	POR MISC 70-1257 70-620 70-27	F F	ETERSON: M. R. ETERSON: M. R. ETERSON: M. R. ETERSON: M. R. ETERSON: M. R.	7912040047 7912040055 7912040061 7912110173 7912110547	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
OMSLEY, G. F. OMSLEY, G. F. OMSLEY, G. F.	7912120305 7912190639 7912180318	NUREO I&E	P	PARTLOW, J. C. PARTLOW, J. C. PARTLOW, J. C. PARTLOW, J. G.	7912170061 7912130197 7912170044	70-27 70-33 70-143		PETERSON, M. R. PETERSON, M. R. PETERSON, M. R.	7912130124 7912140115 7912200093	XPORTLIC XPORTLIC XPORTLIC XPORTLIC
FAGL TARO, J. A. FALMER, H. E. PAPER TELLO, C. PAPER TELLO, C. J. PAPER TELLO, C. J.	7912210023 7912200663 7912180103 7912200450	NUREG 1&E 1&E 40~2061		PARTLON, J. C. PASCIAK, M. PASCIAK, M.	7912270015 7912130353* 7912130363*	70-27 50-320 U 50-320 U 50-341 Q		PETERSON, M. R. PETERSON, M. R. PETERSON, M. R.	7912110156 7912110160 7912110163 7912140139	XPORTLIC XPORTLIC XPORTLIC
Pappas.H. Pappas.H. Pappas.H. Pappas.H.	7912060184 7912190013 7912190025 7912120004	ORG 50-10 ORG ORG ORG	G	PATE, R. J. PATE, R. J. PATERSON, J. M. PATERSON, J. M. R. PATON, W. D.	7912130723* 7912060025* 7912190005 7912190009* 7912130169	50-361 0 50-307 0 50-309 0 50-289 0		PETERSON, M. R. PETERSON, M. R. PETERSON, M. R. PETERSON, M. R	7912120143 7912120145 7912120145 7912120407	XPORTLIC XPORTLIC XPORTLIC
PAPPAS.H.  PARAMETER.F.H.  PARIS.O.H.  PARK.S.	7912120545 7912100307 7912260126 7912190344 7912200402	50-445 TOPREP 50-155 XPORTLIC	<b>н</b> т	PATTERSON, J. P. PAULICKI, B. S. PEARSON, C. F. PEEBLES, Y. S.	7912110275* 7912200473 7912310366 7912270098 7912200605*	70-36 116 90-338		PETERBON, M. R. PETERSON, M. R. PETERBON, M. R. PETERBON, M. R. PETERBON, M. R. PETERBON, M. R.	7912140010 7912140013 7912140017 7912140153	XPORTLIC XPORTLIC XPORTLIC XPORTLIC
PARKER, F. L.  PARKER, W. D.  PARKER, W. O.  PARKER, W. D.	7912180290 7912040476* 7912110229* 7912110565	ACRS 50-269 50-370 REGGD	9 0	PEEPLES, W.P. PEERY, W.W. PELYIER, I.A. PELYIER, 1.A.	7912310032* 7912100274* 7912310080 7912210007 7912170279*	FRM 50-335 G 50-522 A 50-358 A 50-368 S		PETERSON, M. R. PETERSON, M. R. PETERSON, M. R. PETERSON, M. R. PETERSON, M. R.	7912140176 7912260011 7912260014* 7912110455 7912110523	XPORTLIC XPORTLIC XPORTLIC XPORTLIC
PASKER: W. O. PASKER: W. O. PASKER: W. O. PASKER: W. O.	7912170211 7912040010 7912040130 7911160464 7912100165*	50-269 50-369 50-413 50-369 50-269	0 0 8	PENDERGRAFT, R. PENDERGRAFT, R. PENDERGRAFT, R. PENDERGRAFT, R.	79121702032 79122702822 79122104042 7912140096	50-368 R 50-368 R 50-368 S 71-9853		PETERSON, M. R. PETERSON, M. R. PETERSON, M. R. PETERSON, M. R. PETERSON, M. R.	7912110528 7912140041 7912120537 7912120539 7912120542	XPORTLIC XPORTLIC XPORTLIC XPORTLIC
PARKER, W. O. PARKER, W. O. PARKER, W. O. PARKER, W. O.	7912040188* 7912040549 7912210248* 7912170127	50-369 50-269 50-269 50-269	G G G	PEOPLES, D. L. PEOPLES, D. L. PEOPLES, D. L.	7912040011* 7912060190 7912200404 7912040261	50-265 G 50-265 G 50-10 P	i )	PETERSON, M. A. PETERSON, M. H. PETERSON, M. R. PETERSON, M. R.	7912120547 7912200412 7912260060 7912200321	XPORTLIC XPORTLIC XPORTLIC XPORTLIC
PARKER, W. O. PARKER, W. O. PARKER, W. O. PARKER, W. O.	7912050518 7912130430 7912040355	50-349 50-287 50-249	9 9 P	PEOPLES, D. L. PEOPLES, D. L. PEOPLES, D. L. PEOPLES, D. L.	7912180012 7912040285 7912040485	50-237 6 50-454 F 50-10 F 50-10 F	<del>-</del>	PETERSON, M. R. PETERSON, M. R. PETERSON, M. R.	7912180046 7912180041 7912200497 7912200501	XPORTLIC XPORTLIC XPORTLIC XPORTLIC
PARKER, W. O. PARKER, W. O. PARKER, W. O. PARKER, N. O.	7912040293 7912040415 7912040434 7912040514 7912190790	50-269 50-269 50-269 50-269 50-269	P Q P G	PEOPLES, D. L. PEOPLES, D. L. PEOPLES, D. L. PEOPLES, D. L.	7912120425 7912110309 7912110318 7912110380	50-275 F 50-275 F 50-237 F	P P P	PETERSON, M. R. PETERSON, M. R. PETERSON, M. R. PETERSON, M. R.	7912210070 7912210077 7912210062	XPORTLIC XPORTLIC XPORTLIC XFORTLIC
PARKER, M. O.	7912050592 7912050503 7912070439 7912190710	50-349 90-34 <del>7</del> 50-287 50-369	9 9 9	PEOPLES, D. L.	7912210169 7912190622 7912180531 7912270469 7912270470	50-247 50-237 50-10	0 Р Р Р	PETERSON, M. R. PETERSON, M. R. PETERSON, M. R. PETERSON, M. R.	7912210086 7912260067 7912260073 7912310122 7912210092	XPORTLIC XPORTLIC XPORTLIC
PARKER, W. O.  PARKER, W. O.  PARKER, W. O.  PARKER, W. O.	7912210236 7912060502 7912120434 7912040474	50-269 50-269 50-269	G P P S	PEOPLES, D. L. PEOPLES, D. L. PEOPLES, D. L. PEOPLES, D. L.	7912270597 7912270464 7912280533 7912270267	50-295 50-237 50-3	P P P Q	PETERSON, M. R. PETERSON, M. R. PETERSON, M. R. PETRICK, N. A. PETRICK, N. A.	7912260153 7912280154 7912190197 7912120144	* XPORTLIC * XPORTLIC 50-482 0
PARKER, M. O. PARKER, H. O. PARKER, H. O.	7912120294 7912180161 7912140348 7912280017	50-269 50-413 50-269 50-269	<u>a</u>	PEREZ, J. B. PERKINS, T. J. PERKINS, R. W.	7912030016 7912260346 791212015 791205021	9* 50-220 7 NUREG 9 XPORTLIC	R	PETRICK, N. A.	7912060996 791216017 791212039 791228059	5 50-482 5 5 50-482 5 3 50-482 5
PARKER, H. O. PARKER, H. O. PARKER, H. O. PARKER, H. O.	7912110362 7912310009 7912310022	50-287 50-269 50-269	S G G	PERLASIJ. N. PERLMANIJ. PERLMANIJ.	791210045 791207025 791210027	E CONTRACT  6 CONTRACT		PETRICK, N. A. PETRICK, N. A. PEWITT, E. G.	791228042 791228046 791205000	9 50-482 F 9 NUREO
PARKER, U. D. PARKER, U. O. PARKER, U. C. PARKER, U. O.	7912130411 7912210075 7912180140 7912180581	50-249 50-270 50-413	9 G 9 P 9 S	PERLMAN, J. PERLMAN, J. PERRIN, J. 8. PERRIOG, L. D.	791211004 791210038 791212064 791214039	O CONTRACT S NUREG		PHILLIPS J. R. PHILLIPS J. R. PHILLIPS, J. R.	791205004 791205011 791214001 791211039	7 50-275 0 1 50-275 0 13 50-482 9
PARKER, W. O. PARKER, W. O. PARKER, W. O. PARKER, W. O.	791228015° 791218037' 791221015 791221017 791227026	5 50-26° 1 50-36° 1 50-36°	7 R 7 A 9 F	PERRIOD, L. D. PERROTTI. D. J. PERROTTI. D. J. PERRY. L.	791214036 791210046 791206013 791212003 791204063	14 50-230 14 50-261 31 PROJ	a a	PHILLIPS, P. W. PHILLIPS, P. W. PHILLIPS, D. L. PHILLIPS, D. L. PHILLIP, Q. A.	791217008 791213036 79123104 79120700	13 50-492 6 39* 50-298 5 10* 50-298 6 52* 50-341 0
FARKER, N. O.  PARKER, N. O.  PARKER, N. O.  PARKER, N. O.  PARKER, N. O.	791227035 791227032 791227050 791228049	50-36 7 50-36 3 50-27 7 50-27	9 A 9 A 0 S 0 G	PERRYMAN, G. 1. PERRYMAN, G. 1. PESHEK, C. PESHEK, C. PETCOVIC, H. L.	79122800( 79121801) 79121302 79122003	07 40-341 24* 9A999 44 TOPREP 04 REGGD		PHILLIP, G.A. PHILLIPS, H.S. PHILLIPS, H.S. PHILLIP, G.A. PICKENS, F.W.	79121802 79122601 79122803 79122806 79121803	69* 50-367 G 29* 50-498 G 53* 27-10
PARKER, W. O. PARKER, W. O. PARKS, B. I. PARKYN, J. D.	791231046 791231046 791205000 791212000	0 50-36 19 50-41 02 NUREO 09 PRM	3 8	PETERSON, B. H. PETERSON, R. K. PETERS, R. J. PETERSON, H. R.	79122600 79122700 79120404 79122602 79122101	99* COMMISS 52 50-275 32 XPORTLI 38 XPORTLI	A IC IC	PIEPER.W.B. PIEPER.W.B. PIERCE, J. PIGOTT, D. R.	79121101 79121101 79121701 79121001 7912130	10* GA779 01 50-554 9 352 50-341 9
PARMENTER, F. H. PARMENTER, F. H. PARMENTER, F. H.	791212004 791217000 79123101 79121904	8 50-44 37 50-44	15 M 15 M 79 A	PETERSON, M. R. PETERSON, M. R. PETERSON, M. R. PETERSON, M. R.	79122101 79120601 79120601	74 XPORTLI R7 XPORTLI	1C 1C	PIGOTT, D. R. PIGOTT, D. R. PIGOTT, D. R. PIGOTT, D. R.	7912140 7912100 7912130	142 50-361 0 352 50-361 0 061 50-361 0
PARR, D. D. PARR, D. D. PARR, D. D. PARR, O. D. PARR, O. D.	79121701 79123101 79123101 79123101 79121801	20 50-36 08 50-3 14 50-3	97 A 11 B	PETERBUNG IT. R. PETERBONG IT. R. PETERBONG IT. R. PETERBONG IT. R.	7912060 7912060 7912060	198 XPORTLI	1C	PIGOTT, D. R. PIGOTT, D. R.	7912140 7912140	142 00 000

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSIC NUMBER	IN SUSJECT CATEGORY		ACCESSIO	4 SUBJECT	
PILANT, J; M; PILANT, J, M; PILANT, J, M; PILANT, J, M;	7712140248 7712140233 7712170150* 7712040251		PRICE, D. S. PRICE, D. S. PRICE, E. N.	791218029 791208037 791209037 791219037	9 50-296 S 9* 50-259 G	AUTHOR REID, R. W. REID, R. W.	NUMBER	CATEGORY > 50-346	Y  P
PILANT, J. M. PILANT, J. M. PILANT, J. M.	7912070329 7912120259	50~278 P 50~278 P	PRIETO, R. PRIETO, R. PROCTOR, W. Q.	791212031 791212047 791217040	5 50-584 K 4 50-584 A	REID, R. W. REID, R. W. REID, R. W.	7912280605 7912280641 7912120206	* 50-313 * 50-317	PPF
PILANT, J. M. PLANAS, G. PLUMLEE, K. PLUMLEE, K.	7912190549 7912280542 7912050328 7912260008	50-298 P 50-298 P XPORTLIC 50-144 S	PROFFITT, W. L. PROVENZANO, V. PROVOST, L. PRYOR, D.	791220051 791217002 791204045 791221017	9 50-280 p 4 NURE9 3 PROJ	REID,R.W. REINHARDT,H.W. REINHARDT,H.W. REIS,E.J. REIS,E.J.	7912120301 7912140296 7912140314 7912140539	RES RES 50-387 (	
POCHAL, M. F. POCHAL, M. F. POCHAL, W. F. POCHAL, W. F. POHL, R. D. PDINDEXTER, C. H.	7912060201* 7912170376 7912280652 7912180039 7912200596	50-29 G XPORTLIC XPORTLIC XPORTLIC PROJ	PRYOR, D. PTAK, J. PTAK, J. PULASKI, L. J. PUTNEY, L. W.	791228026 791218012: 791217040: 791206047: 791218032:	9 FOIA 9 FOIA 9 50-387 n	REIS, E. J. REIS, E. J. REIS, E. J. REITER, L. REKEMEYER, P. C.	7912180173 7912180201 7912180211 7912260372 7912260375	- 17th B	G G
POIRIER, M. R.	7912030203 791219013B 7912310189 7912310161 7912310189	TOPREP 50-445 M 50-445 M 50-445 M 50-445 M	GUEENER, D. S. GUICK, D. R. GUICK, D. R. GUIGG, C. RADER, R. M.	7912140188 7912050068 7912170402 7912180147 7912130115	* 50-302 G 50-287 B FOIA	REKITO, W. A. RENBERGER, D. L. RENBERGER, D. L. RENBERGER, D. L. RENBERGER, D. L.	7912170284 7912060017* 7912110471* 7912280409 7912030204	50-508 0 NUREO 50-397 Q	1
POIRIERIM, R. POLAND, C. P. POLLACKIR, POLLACKIR,	7912310161 7912110459 7912200413* 7912050343* 7912130332	50-445 M 50-445 M 50-339 A XPDRTLIC PRM	RADER, R. M. RAGONE, 8. RANDOL, A. G. RANDOLPH, M. L. RASH, J. L.	7912130115 7912200362 7912200399 7912170174 7912240246	* 50-339 A * 50-339 A RES	RENBERGER, D. L.	7912040244 7912040252 7912120413 7912280642* 7912060476	50-397 A 50-397 A 50-397 B 50-397 S 50-460 A	1
POLLARD, R. D. POLZER, W. L. POSTON, J. B. POTAPOVS, U. POTAPOVS, U. POTAPOVS, U.	7912050003 7912140125 7912270052* 7912110042* 7912240203*	50-266 G NUREG 50-498 M GA999 GA999	RATH, T. D. RATTA, A. D. RATTA, A. D. RAUDENBUSH, M. H. RAUSCHENBACH, P.	7912130378 7912270180 7912200516 7912130336 7912280514	* 70-1143 * 70-364 PR	RENBERGER, D. L. RENBELS, A. E. RESTIVO, T. REUTER, F. REVELY, W. T.	7912180626 7912280966 7912030008 7912100001 7912130500#	50-460 A 50-397 A 40-2061 RES 50-447 A	
POTAPOVS, V. POTAPOVS, V. POTAPOVS, V. POTAPOVS, V. POTAPOVS, U. POTAPOVS, U.	7912120104* 7912210029* 7912050537 7912110122* 7912180188*	<u>ወ</u> ልዋዋዋ <u>ወ</u> ልዋዋዋ <u>ወ</u> ልዋዋዋ <u>ወ</u> ልዋዋዋ <u>ወ</u> ልዋዋዋ	RAUSCH, J. K. RAUSCH, J. K. RAWA, E. REAVIS, J. A. REBELDWSKI, T.	7912050394; 7912130100; 7912280474; 7912180364; 7912200067;	50-491 Q 50-320 H 50-249 B	REVELY, W. T. REYES, L. A. REYES, L. A. REYES, L. A. REYES, L. A.	7912040074 7912040079* 7912200435 7912050018* 7912200544	50-322 g 50-322 0 50-346 9 50-346 0 50-346 8	
POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. POTAPOVS, U.	7912110058 7912100404 7912110076 7912130423* 7912110034*	0A999 GA999 GA999 GA999 GA999	REBELOWSKI, T. REDMORE, G. REED, C. REED, C. REED, C.	7912310131* 7912120482 7912040297 7912120411 7912270200	50-286 Q FOIA 50-10 P 50-10 P NUREO	REYES, L. A. REYNOLDS, W.	7912200250* 7912200250* 7912180094 7912180221 7912200028	50-346 Q 50-346 B 50-346 S 50-346 S	
POTAPOVS.U. POTAPOVS.U. POTAPOVS.U. POTAPOVS.U. POTAPOVS.U.	7912260198* 7912180261* 7912260111* 7912100412 7912110117*	QA999 QA999 QA999 QA999 QA999	REED, C. REED, C. REEVES, E. A. REEVES, E. A. REGAN, M. H.	7912180587 7912270601 7912040141 7912040218 7912050646*	TOPREP TOPREP 50-348 P 50-348 P 50-142 P	REYNOLDS, N. S. REYNOLDS, W. B. REYNOLDS, W. B. REYNOLDS, L. E.	7912070172 7912170088 7912060061 7912190029 7907260948	FOIA 50-445 G 50-329 G 50-329 G TOPREP	
POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. POTAPOVS, U.	7912140543 7912110082 7912120089* 7912110114* 7912210017*	GA797 GA799 GA779 GA77 <del>9</del> GA797	REGAN, W. H. REGAN, W. H. REGAN, W. H. REGAN, W. H. REGAN, W. H.	7912130063 7912130059 7912190079 7912310215 7912190482	50-275 D 50-416 A 50-382 A 50-313 H PDR MISC	REYNOLDS, N. S.  RHODE, G. K. RHODE, G. K. RHODE, G. K. RICHARDS, J. R.	7912170088 7912140282 7912270324 7912270330 7912130274	50-445 G 50-410 G 50-410 A 50-220 P PR	
POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. POTAPOVS, U.	7912110065 7912120281* 7912260156*	GAŸ79 GA?79 GAŸ79 GAŸ79 GAŸ79	REGAN, W. H. REHM, T. A. REHM, T. A. REHM, T. A. REID, A. B.	7912310037 7912170051 7912040215 7912180148 7912210399	50-275 A COMMISSION COMMISSION COMMISSION FOIA	RICHARDS, J. R. RICHARD, A. W. RICHMOND, J. RICKARD, W. H. RIDEGUT, E. F.	7912130274 7912070410* 7912210439 7912120641 7912180075	PR 50-285 8 50-305 P NUREG PT21	
POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. POTAPOVS, U.	7912200491 7912210194 7912180132*	GA999 GA999 GA999 GA999 GA999	REID, R. W. REID, R. W. REID, R. W. REID, R. W. REID, R. W.	7912310231 7912310070 7912100422 7912100478 7912050081	50-313 F 50-269 P 50-318 P 50-269 P	RIDGWAY,K.R. RIDGWAY,K.R. RIDGWAY,K.R. RILEY,C.I. RILEY,B.W.	7912050231* 7912070070 7912260144*	50-409 @ 50-155 8 50-155 @ 50-320 H	
POTAPOVB, U. POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. POTAPOVS, U.	7912110107 ( 7912120077 ( 7912170382 (	0A999 0A999 1A999 1A999	REID, R. W. REID, R. W. REID, R. W. REID, R. W. REID, R. W.	7912060591 7912100222 7912100229 7912100237 7912100416	50-312 P 50-302 P 50-313 P 50-314 P 50-249 P	RISCHLING, J. L. RISCHLING, J. L. RITCHIE, M. I. RITTS, F. H. RITTS, F. H.	7912270598* 7912270602* 7912070277 7912260360	50-325 B 50-314 S 50-314 S FROJ 50-445 M 50-445 M	
POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. POTAPOVS, V. POTAPOVS, U.	7912120272 G 7912130374 G 7912210001 G	) A779 } A777 A779 A797 A799	REID, R. W. REID, R. W. REID, R. W. REID, R. W. REID, R. W.	7912180287 7912210072 7912050042 7912050048* 7912050053*	50-312 Q 50-312 Q 50-302 P 50-302 P 50-302 P	ROBB, C. S. ROBERDS, H. W. ROBINETTE, M. S. ROBINSON, R. K. ROBINSON, J. C.	7912200357# 7912210036# 791219028B 7912130475 7912110326#	50-339 A 0A999 WASTE MGT PR 50-335 P	
POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. POTAPOVS, U. POTAPOVS, U.	7912180112 Q 7912180247 Q 7912240182 Q	A999 A999 A999 A999 A999	REID, R. W. REID, R. W. REID, R. W. REID, W. R. REID, R. W.	7912110131 7912130005 7912170045 7912180118 7912140012	50-269 P 50-336 P 50-309 P 50-346 P	RODRIQUEZ, R. J. RODRIQUEZ, R. J. RODRIQUEZ, R. J. ROGERB, O. M. ROGERB, H. W.	7912190052* 5 7912170277 5 7912190437 5 7912170194 8	50-312 g 30-312 R 50-312 P 1E8 1-7033	
POTRAPOVB, U. POTTER, J. P. POTTER, J. P. POTTER, J. P. POTTER, J. P.	7912260085* 2: 7912200395* 2: 7912260145* 2: 7912200002* 2:	A779 7-47 7-47 7-47 7-47	REID, R. W. REID, R. W. REID, R. W. REID, R. W. REID, R. W.	7912180233 7912240025 7912240207 7912240328 7912280437	50-307 P 50-302 P 50-285 P 50-335 P	ROGERB, C. L. ROGERB, W. H. ROGERB, M. H. ROGERB, M. E. ROGOVIN, M.	7912070422* 5 7912050457* 5 7912180642* 5 7912070091* 7	0-295 8 0-321 8 0-366 8 0-2756 0MM15810N	
POWERS, J. A. POWERS, D. A.	7912040043 50 7912130315# FC 7912140499# RE	7-47 0-289 8 DIA 18 1-320 H	REID, R. W. REID, R. W. REID, R. W. REID, R. W. REID, R. W.	7912200150 7912270070 7912260083 7912280275 7912280281*	50-302 P 50-309 P 50-313 F 50-346 P 50-346 P 50-346 P	ROCOW, B. S. ROCOW, B. B. ROCOW, B. B. ROCOW, B. B. ROHRER, E. ROISMAN, A. Z.	7912120015 5 7912120125 5 7912120018 5 7912120125 5 7912270407* 5	0-250 H 0-250 G 0-250 H 0-250 G 0-346 S	

AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	CATEOD!
ROMIC; B. ROMUALDEZ; E. Z. ROCNEY; M. A. ROCNEY; M. A. ROCNEY; M. A.	7912170081 7912050392 7912120048 7912130154 7912120048	FOIA 50-574 G 70-1308 70-1308 70-1308	RUSSELL, L. B. RUSSELL, L. B. RUSSELL, L. B. RUSSELL, L. B. RUSSELL, L. B.	7912060494 7912130541 7912180456 7912180597 7912180608	50-317 8 50-317 8 50-317 8 50-317 8 50-317 8	SCARAND, R. A.	7912170022 7912130369 7912170069 7912200615 7912190058	WASTE MOREGOD 40-1941 WASTE MO WASTE MO
ROONEY, M. A. ROONEY, M. ROONEY, V. L. ROONEY, V. L. ROOT, L. D.	7912130156	70-1308	RUSSELL, L. B.	7912310354	50-317 S	SCARAND, R. A.	7912190070	HABTE H
	7912180504	50-270 S	RUTHERFORD, J. F.	7912170197	FOIA	SCARANO, R. A.	7912120573	HABTE H
	7912070087	50-271 P	RYAN, R. Q.	7912050595	State Prog	SCARDLA, J. A.	7912050097	50-574
	7912200439	50-133 P	RYAN, R. Q.	7912050545	State Prog	SCHAEFER, K.	7912280530*	50-320
	7912060364	50-331 G	RYAN, X. M.	7912310503	50-522 G	SCHAEFER, H. H	7912130307	PR
ROOT, L. D.	7912200683	50-331 Q	RYAN, R. Q.	7912030259	State Prog	SCHENDEL, K. R.	7912310193	40-8502
ROOT, L. D.	7912130229	50-331 Q	RYAN, R. G.	7912040012	State Prog	SCHENDEL, K. R.	7912310197	40-8502
ROOT, L. D.	7912050472	50-331 P	RYAN, R. G.	7912040278	State Prog	SCHENDEL, K. R.	7912110188	PROJ
ROOT, L. D.	7912040350	50-331 F	RYAN, R. G.	7912190738	50-312 F	SCHENDEL, K. R.	7912120363	PROJ
ROOT, L. D.	7912070141	50-331 P	RYAN, R. G.	7912190142	PDR HISC	SCHENDEL, K. R.	7912170170	40-8502
ROOT, L. D.	7912280611	50-331 G	RYAN, R. G.	7912270026	NUREO	SCHENDEL.K.R.	7912190768	40-8304
ROOT, L. D.	7912310369	50-331 P	RYAN, R. G.	7912190037	State Prog	SCHENDEL.K.R.	7912210042	40-8502
ROBEN, B.	7912260355*	50-373 G	RYAN, R. G.	7912260023	State Prog	SCHENDEL.K.R.	7912270047	40-8502
ROSAND, R.	7912100057*	70-820	RYAN, R. G.	7912260184	NUREO	SCHERER.A.E.	7912130563	TOPREP
ROSE, D. G.	7912190113	70-754	RYAN, R. G.	7912200406	50-320 H	SCHERER.A.E.	7912190558	NUREQ
ROSENBAUM, W. E.	7912200522	50-244 G	RYAN, R. G.	7912210015	State Prog	SCHIEFELBEIN, C.	7912200766	NUREG
ROSOLIE, E.	7912170272	50-344 G	RYAN, R. G.	7912270037	State Prog	SCHIRMER, D. B.	7912110350*	50~574
ROSS, W. W.	7912180212	50-327 M	RYAN, R. G.	7912270042	State Prog	SCHMIDT, A. D.	7912040438	80-335
ROSS, D. M.	7912050458	71-5467	RYAN, R. G.	7912270044	State Prog	SCHMIDT, A. D.	7912040422	50-335
ROSS, D. M.	7912210419	71-5467	RYAN, R. G.	7912270074	State Prog	SCHMIDT, A. D.	7912130440	50-335
ROSS, W. W.	7912070120	50-329 H	RYAN, R. G.	7912270076	State Prog	SCHMIDT, A. D.	7912030146	50-251
ROSS, W. W.	7912180212	50-329 H	RYAN, R. G.	7912270079	State Prog	SCHMIDT, A. D.	7912030152	50-250
ROSS, D. A.	7912030248*	50-219 G	RYAN, R. G.	7912270086	State Prog	SCHMIDT, A. D.	7912130639	50-250
ROSS, D. A.	7912070323	50-219 S	RYAN, R. G.	7912270094	State Prog	SCHMIDT, A. D.	7912130653	50-250
ROSS, D. A.	7912070328*	50-219 S	RYAN, R. G.	7912270108	State Prog	SCHMIDT, A. D.	7912130632	50-250
RDSS; D. A.	7912070334	50-217 \$ 50-217 \$ 50-217 \$ 50-217 \$ 50-217 \$	RYAN, R. O.	7912270112	State Prog	SCHMIDT, A. D.	7712130534	50-250
RDSS; D. A.	7912070340*		RYAN, R. G.	7912270157	State Prog	ECHMIDT, A. D.	7712170520	50-250
RDSS; D. A.	7912070359		RYAN, R. Q.	7912280647	NUREG	SCHMIEDER, J. R.	7712280005	30-286
RDSS; D. A.	7912070353		RYAN, R. G.	7912310327	State Prog	SCHMIDT, H. C.	7712170548	50-445
RDSS; D. A.	7912070333		RYAN, R. G.	7912310185	State Prog	ECHMIDT, E. W.	7712140486	RES
ROSS, D. A. ROSS, D. A. ROSS, D. A. ROSS, D. A. ROSS, D. A.	7912070345* 7912070350 7912070364* 7912110315 7912110317*	50-219 8 50-219 8 50-219 8 50-219 8 50-219 8	RYAN, R. G. RYAN, R. G. SAHA, P. SALAZAR, E. A. SALDARINI, J. C.	7912280615 7912190068 7912110555 7912310153 7912310036	State Prog NUREO TOPREP NUREG REGOD	SCHNEIDER, R. R. GCHNEIDER, R. R. SCHNEIDER, R. R. SCHNEIDER, R. R. SCHNEIDER, R. R.	7912170168 7912200313* 7912310427 7912140157 7912280019	50-220 50-220 50-220 50-220
ROSS, D. A.	7912280015	50-219 0	SALMONSON: E. J.	7912200169	40-8102	SCHNEIDER, R. R.	7912260267	50-220
ROSS, D. A.	7912210306	50-219 R	SALTZMAN: J.	7912280474	50-320 T	SCHNEIDER, J. R.	7912130515	50-284
ROSS, D. A.	7912210338	50-219 S	SALTZMAN: J.	7912180579	50-223 J	SCHNEIDER, F. H.	7912030239*	50-272
ROSS, W. J.	7912060013	50-272 P	SALTZMAN: J.	7912270585	50-269 I	SCHNEIDER, F. H.	7912180472	50-272
ROSS, D. F.	7912190097	TOPREP	SALTZMAN: J.	7912180544	50-208 J	SCHNEIDER, F. H.	7912170190	50-272
ROSS, D. F.	7912180022	TOPREP	Saluja, j.	7912130301	FD1A	SCHNE I DER, F. W.	7912260032	50-272
ROSS, D. F.	7912260020	TOPREP	Salzman, e.	7912130453	PR	SCHNE I DER, F. W.	7912040495*	50-272
ROSS, D. F.	7912300638	TOPREP	Salzman, R. S.	7912180032	30-554 G	SCHNE I DER, F. W.	7912060329*	50-272
ROSS, D. F.	7912200631	TOPREP	Salzman, R.	7912200601	50-389 T	SCHNE I DER, F. W.	7912070423	50-272
ROSS, D. F.	7912200635	TOPREP	Balzman, R.	7912200613	80-389 T	SCHNE I DER, K. N.	7912070487	PR
ROTH, J. L.	7912040081	50-320 U	Salzman, R.	7912200625	50-399 T	SCHOCK, H.	7912200274	REGOD
ROTH, J. M.	7912070341	50-87 P	Salzman, R.	7912200587	50-389 T	SCHOLL, R.	7912280633	50-344
ROTH, J. M.	7912310116	PR	Sashorth, R. B.	7912180207	NUREO	SCHOPPMAN, M. A.	7912040444*	50-335
ROTH, U.	7912120155	50-320 U	Sandas, S. M.	7912280492*	50-287 U	SCHOPPMAN, M. A.	7912040425*	50-335
ROTH, J.	7912070113*	70-487	Sanderford, J.	7912130406	PROJ	SCHOPPMAN, M. A.	7912130457*	50-335
ROTHE, P. H.	7912310202	NUREO	SANDERS, W. F.	7912030056*	50-336 0	БСНОРРНАМ, И. А.	7912030149*	50-251
ROTHFLEISCH, J. E	7912130091*	40-8721	SANDERS, W. F.	7912200526*	50-423 0	БСНОРРНАМ, М. А.	7912030160*	50-250
ROTHFLEISCH, J. E	7912130702	40-8721	SANDELL, P. S.	7912210426*	FOIA	БСНОРРНАМ, И. А.	7912130647*	50-235
ROTHFLEISCH, J. E	7912130084	40-8721	SANDVIK, R. M.	7912130523	PR	БСНОРРНАМ, И. А.	7912130658*	50-250
ROTHFLEISCH, J. E	7912260250	40-8721	SANTORO, M. P.	7912260042	71-9006	БСНОРРНАМ, И. А.	7912130641*	50-250
ROTHFLEISCH, J. E	7912190638	40-8692	SATTERFIELD, D. E	7912200328* 7912310221 7912170030* 7912170011 7912130432	50-339 A	SCHOPPMAN, M. A.	7912130536*	50-250
ROTHFLEISCH, J. E	7912170172	40-8380	SATTERFIELD, R.		PDR MISC	SCHOPPMAN, M. A.	7912190522*	50-250
ROTHSCHILD, M. U.	7912110142	70-1308	SAVANI, N. K.		TOPREP	SCHUERMAN, L. E.	7912040364	50-341
ROTHSCHILD, M. U.	7912110176*	70-1308	SAVOLAINEN, A.		NUREQ	SCHULTE, F. L.	7912190484	40-8721
ROUNDTREE, R. E.	7912190265*	50-445 M	SAXE, R. F.		50-111 P	SCHULTT, R.	7912120040	50-596
RDUSE, L. C.	7912190084	70-2623	SCARAND, R. A.	7912190086	40-1341	SCHUTT, R.	7912120040	50-596
RDUSE, L. C.	7912180325*	F01A		7912180264*	40-8475	SCHWAB, J. C.	7912130098	50-599
RDUSE, L. C.	7912260352	70-25		7912130192	40-8698	SCHWAB, J. C.	7912140034	50-599
ROW, W. T.	7912120032	70-371		7912180260	40-8675	SCHWARTZ, M. H.	7912280232*	50-244
ROY, Q.	7912200450	40-2061		7912210312*	40-8745	SCHWARZ, M. D.	7912050442	50-498
ROYTEK, C. RUBENSTE IN, L. S. RUBENSTE IN, L. S. RUBENSTE IN, L. S. RUBENSTE IN, L. S.	7912260098* 7912130159 7912130163* 7912100272 7912130001	50-266 Q 50-367 Q 50-367 Q 50-329 A 50-327 A	SCARANO, R. A.	7912270069* 7912110072 7912120011 7912040025 7912130318	40-8745 40-1162 40-8681 CRO 40-8748	Schhart, M. D. Schhart, M. D. Schhan, C. A. Schheiker, R. S. Schhendiman, L. C	7912190061 7912050442 7912120085* 7912210266* 7912120157	50-498 50-498 50-305 50-352 NURES
RUBENSTE IN, L. S.	7912180074	50-327 A	SCARANO, R. A.	7912130002	40-9694	SCHWEITZER, D. G.	7712040103	RES
RUBENSTE IN, L. S.	7912200090	50-424 A	SCARANO, R. A.	7912130167	40-9691	SCHWEIBINZ, E. R.	7712060063#	50-454
RUBENSTE IN, L. S.	7912210006	50-424 A	SCARANO, R. A.	7912210295*	40-9748	BCHWENCER, A.	7712100413	50-271
RUBENSTE IN, L. S.	7912310014	TOPREP	SCARANO, R. A.	7912110292	40-9748	BCHWENCER, A.	7712040164	50-262
RUCKER, M. J.	7912120239*	50-148 G	SCARANO, R. A.	7912110092	40-8304	BCHWENCER, A.	7712050157	50-348
RUFF, A. B. RUPPE, L. RUSSELL, L. B. RUSSEL, L. B. RUSSELL, L. B.	7912310331* 7912280439* 7912260062 7912060453 7912060469	50-375 Q 50-320 H 50-317 B 50-317 B 50-317 B	SCARAND, R. A.	7912200137 7912130234 7912180020 7912180073 7912190400	40-3453 PDR MISC PDR MISC 40-1162 40-2259	SCHWENCER, A. SCHWENCER, A. SCHWENCER, A. SCHWENCER, A. SCHWENCER, A.	7912050162 7912050163 7912050165 7912050167 7912050170	50-295 50-3 50-261 50-213 50-334

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	GOOGE C F		ACCESSION SUBJECT
Schwencer, A. Schwencer, A. Schwencer, A. Schwencer, A. Schwencer, A.	7912050174 7912050175 7912050176 7912050178 7912050181	50-250 P 50-315 P 50-282 P 50-244 P 50-286 P	SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V.	7912120541 7912120544 7912120545 7912120546 7912120546	50~298 G 50~285 A	AUTHOR  SHALLER, D. V. SHAMEL, W. H. SHANBAKY, M. SHANBAKY, M. M.	NUMBER CATEGORY  7912310345 50-316 S 7912310349# 50-255 P 7912260013 50-272 8 7912260337# 50-382 0
SCHMENCER, A. SCHWENCER, A. SCHWENCER, A. SCHWENCER, A. SCHWENCER, A. SCHWENCER, A.	7912050183 7912050184 7912050187 7912050193 7912050194	50-344 P 50-272 P 50-206 P 50-266 P 50-305 P	SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V.	7912100258 7912100261 7912100264 7912100265 7912110526	50-498 Q 50-482 Q 50-382 Q 50-445 Q 50-458 Q	SHANNON, P. C. SHANNON, P. C. SHANNON, R. SHAPAR, H. K. SHAPAR, H. SHAUB, E. T.	7912130410 50-339 R 7912200370* 50-339 A 7912110525* 50-295 9 7912280486* 50-289 U 7912280474 50-320 T
SCHWENGER, A. SCHWENGER, A. SCHWENGER, A. SCHWENGER, A. SCHWENGER, A.	7912050199 7912100408 7912170029 7912100410 7912100411 7912100163	50-280 P 50-334 P 50-280 P 50-272 P 50-338 P	SEYFRIT, K, V, SEYFRIT, K, V, SEYFRIT, K, V, SEYFRIT, K, V, SEYFRIT, K, V,	7912110530 7912110533 7912110535 7912110537 7912190026	50-498 Q 50-482 Q 50-382 Q 50-445 Q 50-298 Q	SHAW, H. E. SHEA, D. F. SHEA, J. R. SHEA, J. J. SHEA, J. J.	7912260095# 50-333 q 7912190220 50-275 H 7912210184 PDR HISC 7912040144 F0-244 P
Schwencer, A. Schwencer, A. BCHWENCER, A. SCHWENCER, A. SCHWENCER, A.	7912100178 7912100178 7912100180 7912100246 7912130415	50-344 P 50-272 P 50-272 Q 50-250 P 50-305 F	SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V.	7912190028 7912190030 7912190033 7912120550 7912120553	50-285 G 50-267 G 50-313 G 50-313 G 50-298 G	SHEA, J. J. SHELDON, K. P. SHELDON, K. P. SHELDON, K. P. SHELDON, K. P.	7912040170 50-206 P 7912040117 50-244 P 7912130546 FR 7912130485 PR 7912040640 50-155 0
Schwencer, A. Schwencer, A. Schwencer, A. Schwencer, A. Schwencer, A.	7912100266 7912100266 7912100266 7912130068 7912130071*	50-250 P 50-348 P 50-348 P 50-261 P 50-251 P	SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V.	7912120555 7912120559 7912110278 7912110279 7912110281	50-285 q 50-267 q 50-458 q 50-458 q 50-462 q	SHELDON, K. P. SHELDON, K. P. SHELDON, K. P. SHELDON, K. P. SHELDON, K. P.	7912070344* 50-155 0 7912130469 PR 7912060238 50-289 0 7912130026 50-289 0 7912130026 50-289 0
Schwenger, A. Schwenger, A. Schwenger, A. Schwenger, A. Schwenger, A.	7912100180* 7912100174 7912040108 7912040124* 7912040137* 7912180346	50-261 P 50-250 P 50-272 P 50-272 P 50-272 P	SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V.	7912110283 7912110285 7912110467 7912110472 7912110474	50~382 · 0 50~445 · 0 50~313 · 0 50~458 · 0 50~498 · 0	SHELDON, K, P.	7912040238 50~289 0 7912040242* 50~289 9 7912130544 PR 7912130585 PR 7912040540 50~155 0
SCHWENCER, A. SCHWENCER, A. SCHWENCER, A. BCHWENCER, A. SCHWENCER, A.	7912210134 7912210134 7912310505 7912200609 7912210121	50-251 P 50-334 P 50-315 P 50-348 P 50-272 P	SEYFRIT, K. V.	7512110480 7912110483 7912110484 7912110485 7912110489	50-482	SHELLEY, W. J. SHELLEY, W. J. SHEPHERD, A. M. SHEPHERD, R. E. SHEPHERD, R. E.	7912130469 PR 7912030017 40-8027 79121901301 40-8727 7912210320 50-443 A 7912200073 50-247 \$
SCHWENCER, A. SCHWENCER, A. SCHWENCER, A. SCHWENCER, A.	7912310199 7912310159 7912270018 7912270021*	50-305 P 50-338 P 50-338 P 50-315 P 50-315 P	SEYFRIT, K. V. BRYFRIT, G. V. SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V.	7912110491 7912180055 7912190040 7912190043 7912190050	50-445	SHERLOCK, P. SHERMAN, F. L. SHERWOOD, G. G. SHERWOOD, G. G. SHERWOOD, G. G.	7912100215* 50-220 Q  7912190678* 50-219 P  7912040093 70-33  7912280143 REGGD  7912270109 IDPREP
SCHWENCER, A. SCIRTING, A. SCOTT, J. SCOTT, J. SCOTT, J.	7912270024# 7912200041 7912280449# 7912060002 7912140218	50-315 P 50-295 P 50-320 H 50-446 G 50-466 G	SEYFRIT, K. V.	7912190056 7912190141 7912190169 7912190174 7912190177	50-445 Q 50-298 Q 50-313 Q 50-458 Q 50-498 Q	SHIELDS, 6. W. SHIELDS, 8. W. SHIELDB, S. W. SHIELDB, S. W.	7912130493 50-447 A  7912050301* 50-545 0  7912060057 50-546 0  7912070411* 50-546 0  7912050424* 50-546 0
SCOTT, J. SCOTT, J. M. SCOTT, C. B. SCOTT, C. B. SCOTT, C. B.	7912180170 7912120253 7912120260>	50~466 0 50~466 G 50~466 G PROJ PROJ	SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V.	7912190180 7912190181 7912190185 7912190188 7912190189	50-482 G 50-382 G 50-278 G 50-285 G 50-267 G	SHINKO, M. S. SHIVELY, C. M. SHIVELY, C. N. SHIVELY, C. N.	7912120398 50-546 A  7912190567 REB 7912170264* 50-313 8 7912170289* 50-368 8
SEIDLE, W. SEIDLE, W. C. SEIDLE, W. C. SEIDLE, W. C. SEIDLE, W. C.	7912200429 7912030226 7912050526 7912050463	50-367	SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V.	7912190193 7912310260 7912310261 7912310264 7912310265	50-445 0 50-458 0 50-478 0 50-482 0 50-382 0	SHIVELY, C. N. SHIVELY, C. N. SHIVELY, C. N. SHIVELY, C. N. SHIVELY, T.	7912310384* 50-348 8 7912310393* 50-348 9 7912310397* 50-348 9 7912310409* 50-348 9 79123030104 50-245 8
SEIDLE, W. C. SEILLA, A. SEIVER, J. D. SEKULER, S. N. SEKULER, S. N.	7912280322 5 7912280361* 5 7912070231 F 7912120557 5	50-556 G 50-498 G 60-320 H FOIA 60-599 G	SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V.	7912200210 7912200212 7912200215	50-445 G 50-458 G 50-498 G 50-482 G 50-382 G	SHOLLY, S. SHON, F. J. SHON, F. J. SHORT, R. H.	7912210068 NUREG  7912210422 50-289 G 7912190344 50-155 T 7912310278 50-312 0 7912180120* 50-344 G
SELKONITZ, L. B. SELKONITZ, L. B. SELKONITZ, L. B. SELLS, D. E.	7912280456 5 7912140151 5 7912140151 5 7912280456 5	0-079	SEYFRIT, K. V.	7912200222 7912280582 7912280585 7912280586	50-445 Q 50-458 Q 50-498 Q 50-492 Q	SHRIVER, B. L. SHRIVER, B. N. SHULTZ, G. R. SHUM, E. Y. SHUSTER, B.	7912130041 NUREQ 7912210038* 50-42 0 7912110161 50-387 0 7912190320 70-1113 7912120250* 50-289 U
SELLS, D. E. SELLS, D. E. SENECHAL, M. E. SENECHAL, M. E. SERABIAN, J. A.	7912190186* 56 7912200649 56 7912130582 PF 7912130590* PF		SEYFRIT, K. V. SHACKLEFORD, B. W. SHACKLETON, D. C. SHALLER, D. V. SHALLER, D. V.	7912280592 7912260280 7912120505* 7912280524*	30-443 Q 50-275 K 50-275 Q 50-315 R	SIEGFRIED, J. SIEGFRIED, J. R. SIEGFRIED, J. R. SIEGFRIED, J. R. SILBERG, J. E.	7912120205# XPORTLIC  7912040327# XPORTLIC  7912040320 XPORTLIC  7912140118 XPORTLIC  7912050321 50-402 q
SEVELL, R. B. SEHELL, R. B. SEXTON, R. SEYFRIT, K. V. SEYFRIT, K. V.	7912280082 40 7912280089* 40 7912180301 50 7912260146* GA	0-277 0 -8674 -8674 -339 H 999	SMALLER, D. V. SMALLER, D. V. SMALLER, D. V. SMALLER, D. V. SMALLER, D. V.	7912040365 5 7912040375 5 7912040424 5 7912070351 5	0-315 8 0-316 8 0-316 8 0-316 8	SILBERG, J. E. SILBERG, J. E. SILBERG, J. E. SILVER, R. D. SILVER, H.	7912270096 50-387 Q 7912050321 50-482 0 7912130246 50-387 0 7912190782 50-213 P 7912050033 50-289 P
SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V.	7912260130# QA 7712280325# 40 7912280303# 40 7912210219# QA	2259 979 2259 2259 979	SHALLER, D. V. SHALLER, D. V. SHALLER, D. V. SHALLER, D. V. SHALLER, D. V.	7912070378 5 7912100277 5 7912130312 5 7912130330 5	0-316	SIMCHUK, O. SIMMONS, J. W. SINGER, L. N. SINKIN, L. A. SINKIN, L. A.	7912280100 WASTE MOT  7912190441 NUREG 7912120522 50-289 G 7912120071* 50-498 U 7912170334 80-499 G
SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V. BEYFRIT, K. V.	7912140094 50- 7912140103 50- 7912140133 50-	-285 G -267 G -313 G -298 G -267 G	SHALLER, D. V. SHALLER, D. V. SHALLER, D. V. SHALLER, D. V. SHALLER, D. V.	7912170260 50 7912170270 50 7912270590 50 7912270337 50	0-316	SINKIN, L. A. SISESTA, J. SJOGREN, R. M. SJOGREN, R. M.	7912170355* 50-498 g 7912280669 F0IA 7912040353* 50-387 8 7912180407* 50-309 8 7912180407* 50-271 8
						Samutation () (1)	7912180348+ 50-29 R
Tuest Tuest							

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTH <b>O</b> R	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SKARITKA, J. D. SKARUPA, J. D. SKOLDS, J. L. SKOLDS, J. L. SKOROHAD, P. M.	7912280213* 7912170371 7912070167* 7912280157* 7912210433	50-244 P XPORTLIC 50-324 Q 50-395 Q 71-363	Schinki, B. M. Schinki, B. M. Schinki, B. M. Schinki, S. M. Scherville, K. C.	7912190502 7912190523 7912260266 7912310135 7912190275	50-466 0 50-466 0 50-466 0 50-466 0 40-9200	STALLINGS, C. M. STALLINGS, C. M. STALLINGS, C. M. STALLINGS, C. M. STALLINGS, C. M.	7912070325 7912100364 7912110387 7912120306 7912120438	50-338 P 50-338 P 50-280 9 50-336 S 50-336 Q
SKOVHOLT, D. J. SMRABLE, K. U. SLAP, A. SLAP, A. SMITH, J. L.	7912050665# 7912110235 7912280459# 7912280459# 7912310006#	50-142 P REGGD 50-320 0 50-320 0 50-204 9	SOUDER, J. L. SOUDER, J. L. SPACKNAN, T. SPALLONE, K. SPANGLER, R. G.	7912200233 7912200243 7912180107+ 7912180214 7912120239+	50-287 P 50-312 P 50-277 H 50-387 9 50-148 Q	STALLINGS, C. M. STALLINGS, C. M. STALLINGS, C. H. STALLINGS, C. M. STALLINGS, C. M.	7912130327 7912140432 7912140464 7912140324 7912140377	50-338 F 50-260 3 50-260 5 50-260 R 50-338 R
SMITH, J. H. SMITH, R. L. SMITH, I. W. SMITH, I. W. SMITH, I. W.	7912110002* 7912170310 7912050698 7912100314 7912180082	CONTRACT 50-271 P 50-289 0 50-361 9 50-289 0	SPANGLER, M. B. BRANNAUS, M. SPENCER, M. A. SPENCER, M. A. SPENCER, M. A.	7912190302* 7912130590* 7912190251 7912200146 7912190254*	PDR H15C PR 71-357 71-199 71-357	STALLINGS, C. M. BTALLINGS, C. M. STALLINGS, C. H. STALLINGS, C. H. STALLINGS, C. N.	7912140386 7912180364 7912180182 7912200378 7912200362	50-280 B 50-338 B 50-280 P 50-281 0 50-338 P
SHITH I.W. SHITH B.H. SHITH B.H. SHITH I.H SHITH B.H.	7912270011 7912070093* 7912040118* 7912130106 7912110124	50-289 0 50-272 0 50-320 U 50-272 0 30-471 0	SPENCER, H. A. SPENCER, M. C. SPENCER, H. C. SPENCER, H. C. SPENCER, O. S.	7912200154* 7912310280 7912180536 7912310370 7912110481*	71-199 50-280	STALLINGS. C. M. STALLINGS. C. M. STALLINGS. C. M. STALLINGS. C. M. STALLINGS. C. M.	7912270107 7912260209 7912260211 7912260231 7912260234	50-238 P 50-238 P 50-238 P 50-280 G 50-280 G
SHITH, B. H. SMITH, B. H. SHITH, B. H. SHITH, O. SMITH, G. H.	7912040074 7912100329 7912100337 7912260013 7912260008	50-3	SPENCER, G. S. SPENCER, G. S. SPENCER, G. S. SPENCER, G. S. SPENCER, G. S.	7912130797* 7912050018 7912050055 7912050035 7912110462	50-261 0 50-361 0 50-275 0 50-529 0 50-500 0	STALL INCS, C. M. STALL INCS, C. M. STALL INCS, C. M. STALL INCS, C. M. STALL INCS, C. M.	7912240251 7912270460 7912270307 7912270421 7912270441	50-280 @ 50-280 S 50-280 S 50-280 G
SHITH, C. H. SMITH, T. H. SMITH, R. H. SMITH, O. H. SMITH, O.	7912310329 7912040017* 7912070091* 7912120348 7912200534*	1&E 50-307	SPENCER, G. S. SPENCER, G. S. SPENCER, G. S. SPENCER, G. S. SPENCER, G. S.	7912130700 7912140474 7912140492 7912180439 7912270072	50-341 0 50-341 0 50-275 0 50-528 0 50-275 0	Stallings, C. M. Stallings, C. M. Stallings, C. M. Stallings, C. M. Stallings, C. M.	7912270494 7912270547 7912270582 7912270582 7912280490	50-338 P 50-280 S 50-338 S 50-281 0 50-280 G
.H. 0. H. 16 .H. 8. H. 16 .S. 17 H. 16 .S. 17 H. 18 .S. 17 H. 18 .S. 17 H. 18	7912060674 7912210024# 7912120147# 7912050102# 7912070095#	70-1143 50-387 6 50-57 9 70-1143 70-687	SPESSARD, R. L. SPESSARD, R. L. SPESSARD, R. L. SPESSARD, R. L. SPESSARD, R. L.	7912260364 79120500378 7912050066* 7912310045 7912070143	50-331 S 50-10 0 50-275 0 50-275 S 50-247 S	STALLINGS, C. M. STALLINGS, C. M. STALLINGS, C. M. STALLINGS, C. M. STAMPLEY, N. L.	7912310948 7912310499 7912310371 7912100143 7912030193	50-33B G 50-250 P 50-33B P RES 50-416 C
Shith, O. H Shith, O. H Shith, O. H. Shith, O. H. Ehith, O. H.	7912050655* 7912050075* 7912030089* 7912060233* 7912120110*	70-487 70-1143 50-271	Spessard, R. Spessard, R. L. Spessard, R. L. Spessard, R. Spessard, R.	7912030698 7912060454 7912060450 7912200546 7912170390	50-10 9 50-295 9 50-304 9 50-237 9 50-10 8	STAMPLEY, N. L., STAMPLEY, N. L., STAMPLEY, N. L., STAMCAVAGE, P. P., STAMLEY, C.	7912030194* 7912040497 7912310401 7912130500> 7912190210*	50-416 C 50-416 X 50-416 X 50-467 A 50-482 Q
SHITH C.H. SHITH C.H. SHITH C.H. SHITH C.H. SHITH C.H.	7912060189* 7912050107* 7912060096* 7912310304* 7912260335*	50~29 0 50-277 0 70-920 70-820 50-387 0	SPESSARD, R. L. SPINELLI, D. J. SPINIVASAN, E. S. SPISAK, J. F. SPISAK, J. F.	7912170910 7912310517# 7912120129 7912310375 7912030012	50-254 S 50-255 P TOPREP 40-4492 40-4492	STARK, S. J. STARKEY, R. B. STARKEY, R. B. STARKEY, R. B. STARKEY, R. S.	7912180523 7912030073* 7912050549* 7912040428 7912040432*	TOPREP 50-261 0 50-261 8 50-261 9 50-261 9
Smith. C. H Smith. C. H. Smith. C. H. Smith. C. H. Smith. C. H.	7912050080 7912070077 7912120141 7912030080 7912050642	70-1143 70-687 50-57 G 50-271 G 70-697	SPITZNOGLE.A. SPITZBERÐ.D.B. SPRAUL.J.G. SPRAUL.J.G. SPRAUL.J.G.	7912180368* 7912030228* 7912130023 7912210067 7912210087	50-334 R 50-382 0 50-259 P PDR MISC PDR MISC	STARMEY, R. B. SYARMEY, R. B. STARMEY, R. B. STARMEY, R. B. STEED, L. S.	7912050534 7912130285 7912140445 7912140451* 7912040443>	50-261 8 50-261 R 50-261 3 50-261 9 90-334 R
SMITH, O. H. SMITH, G. H. SMITH, G. H. SMITH, G. H. SMITH, G. H.	7912050101 7912040177 7912040209 7912310040 7912040085	50-277 G 50-29 G 50-201 G 50-219 G 70-820	STAEHLE, R. STAHL, D. STAHL, D. STAHL, D. H. STAHL, D. H.	7912110542+ 7912050683 7912130057 7912270101 7912280670	50-295 0 50-445 M 50-445 M 50-498 H 50-449 M	STEELE, T. A. STEELE, T. A. STEINDLER, M. J. STELLO, V. STELLO, V.	7912180577 7912180565 7912180276 7911300662 7912130176	50-409 D 50-409 D ACRS 50-280 U 50-312 P
SMITH, O. H. SMITH, O. H. SMITH, O. C. SMITH, O. C. SMITH, O.	7912310291 7912310011 7912050141* 7912050383* 7912200333*	70-1143	STARL, D. STARL, D. STARL, D. STARL, D. STARL, D.	7912050689 7912100300 7912130057 7912130057 7912130057	50-445 M 50-445 M 50-445 M 50-445 M 50-445 M	STELLO, V. STELLO, V. STELLO, V. STELLO, V.	7912130181 7912130184 7912130187 7912130190 7912270071	50-302 P 50-320 P 50-346 P 50-269 P 50-482 9
EMITHIR.D. EMITHIR.D. ENAGERIII.S. SNIEZEKIJ. ENDALB.A.	7912210110# 7912210108 7912130458 7912206022 7912130526	27-48 27-48 PR 50-3 F 50-244 S	STARL, D. STARLE, C. B. STAIR, J. R. STAILINGS, C. M. STAILINGS, C. M.	7912130057 7912210003 7912200369* 7912120449 7912050452*	50-445 H 50-327 A 50-289 R 50-338 P 50-280 Q	STELLO, V. STELLO, V. STELLO, V. STELLO, V.	7912280307 7912280312 7912310245 7912197091 7912190098*	50~443 A 50~352 A 50~354 H 50~142 G 50~142 G
SNOW, B. A. SNOW, B. A. SNYDER, D. SNYDER, D. SOBON, L. J.	7912180348 7912270603 7912040037 7912130040 7912070391	50-244 R 50-244 S XPDRTLIC XPDRTLIC TOPREP	STALLINGS, C. M. STALLINGS, C. M. STALLINGS, C. M. STALLINGS, C. M. STALLINGS, C. M.	7912120059 7912040399 7912140538 7912040496 7912190668	50-338	STELLO, V. STELLO, V. STELLO, V. STELLO, V.	7912200452 7912200657 7912200637 7912200642 7912200645	50-334 9 50-334 0 50-213 0 50-329 0 50-329 0
Bobon, L. J. Sofer, G. A. Bohtnki, S. H. Bohinki, S. H.	7912050359 7912200011* 7912280240* 7912190192 7912050132		STALLINGS, C. M. STALLINGS, C. M. STALLINGS, C. M. STALLINGS, C. M. STALLINGS, C. M.	7912030201 7912030209 7912040312 7912040376 7912050570	50-260 P 30-338 P 50-338 8 50-338 F 50-338 F	STELLO, V. STELLO, V. STELLO, V. STELLO, V.	7912270004 7912270008 7912270144 7912280083 7912280086	50-327 0 50-329 0 50-273 P 50-327 0 50-327 0
Schinki S. M. Schinki S. M. Schinki S. M. Schinki S. M. Schinki S. M.	7912100479 7912100482* 7912170207 7912170208* 7912170212*	50-466 G 50-466 G	STALL INGS, C. M. STALL INGS, C. M. STALL INGS, C. M. STALL INGS, C. M. STALL INGS, C. M.	7912050576 7912200097 7912200107 7912030189 7912070131	50-280 F 50-280 Q 50-338 Q 50-280 F 50-338 F	STELLO, V. STEMPLE, P. J. STEPHENSON, B. B. STEPHENSON, B. B. STEPHENSON, B. B.	7912280318 7912110004# 7912030192 7912030192 7912140442	50-249 S 50-237 S 50-237 S
Schinki, B. M. Schinki, B. M. Schinki, B. M. Schinki, B. M. Schinki, B. H.	7912170215# 7912170221# 7912170225# 7912170165 7912170173	50~466 D	Stallings, C. H. Stallings, C. H. Stallings, C. H. Stallings, C. H. Stallings, C. H.	7912070380 7912070407 7912100250 7912100302 7912070338	50-338 S 50-336 S 50-280 F 50-280 P 50-339 A	STEPHENSON, B. B. STEPHENSON, B. B. STEPHENSON, B. B. STEPHENSON, B. B. STEPHENSON, B. B.	7912140398 7912140421 7912140459 7912180419 7912180377	50-237 S 50-249 S 50-207 S 50-249 S 50-10 R

				•						
AUTHOR STEPHENSON, B. B	ACCESSION NUMBER	CATEGORY	AUTHOR	ACCEGSION NUMBER	N SUBJEC CATEGO		AUTHOR	ACCESSIO	CODO	
STEPHENSON, B. B STEPTOE, P. STEPTOE, P. STEPTOE, P. STEPTOE, P. P.	79122702: 791211050 791219001 791217017	54 50-237 8 03 50-295 0 15 50-295 0 79 50-155 0	SUNDARAM, R. K. SUTHERLAND, J. T SUTHERLAND, J. T SUTHERLAND, J. T SUTHERLAND, J. T SUTHERLAND, J. T	7912100455	5 50-335 5 50-335 5 70-824	a a	THOMSEN, F. T. THOMSEN, F. T. THOMSEN, F. T. THOMSEN, F. T.	791207047. 791203000 791203035 7912170026	7 50-522 5 50-522	5 6
STEPTOE, P. STEPTOE, P. STERN, R. N. STERN, R. N.	791218023 791217017 791217805 791205054 791212046	9 50-155 0 8 50-155 0 4 XEDRTOIC	SUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T.	7912040458 7912050457 7912210043 7912240078	50-327 50-566 * 50-62 * 27-47	Q Q Q	THOMSEN, F. T.	791217004: 7912170046 7912240039 7912030007	1* 50-522 8* 50-522 9 50-522 7 30-522	
STERN, H. C. STERN, H. C. STERN, W. C. STERNBERG, D. STERNBERG, D. M.	791203004 791211016 791213013 791231010 791206012	5 XPORTLIC 7 XPORTLIC 4 50-344 P	SUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T.	7912050121 7912120248 7912100464 7912200608 7912200001	50-261 50-327 50-395 70-27 27-47	0 0 0	THOMSEN, F. T.  THOMSEN, F. T.  THOMSEN, F. T.  THOMSEN, F. T.	7912070355 7912170020 7912170041 7912170048 7912260039	5 50~522 50~522 \$ 50~522 \$ 50~522	0
STERNBERG, D. M. STERNBERG, D. M. STETKA, T. F. STEVENSON, A. C. STEVENS, B.	7912060104 791205031 <i>£</i> 7912060171 7912040354 7912030103	50-275 q 58-50-187 q 50-187 q 50-320 q	SUTHERLAND, J. T.	7912260344 7912260072 7912260142 7912210080# 791203006#	27-47 27-47 27-47 50-269	a	THONUS, L. H. THORNBERRY, R. THORNBURG, H. P. THORTON, L. THRASH, H. O.	7912030096 7912200515 7910040479 7912030189	* 50-271 * 50-316 50-324 50-361	9 9
STEVENS, S. C. STEVENS, S. C. STEVENSON, R. L. STEVENSON, R. L. STEVENSON, R. L.	7912070406 7912110360 7912130527 7912170118	50-285 8 50-285 8 70-1151 70-36	SUTHERLAND, J. T.	7912100046 7912310230 7912310076* 7912100451	70-824 27-47 50-389	Q Q	THULLEN, P. TIBDETTS, D. L. TIBBITTS, D. L. TIBBITTS, D. L. TIBBITTS, D. L.	7912280401 79121907038 7912030028 7912140185 7912190779	50-348 50-219 50-395 50-395 50-352	H A A
STEVENSON, R. L. STEWART, W. P. STEWART, W. J. STEWART, W. J. STEWART, W. L.	7912180025 7912180029 7912190268 79121103901 79121404421	50-260 B	SUTHERLAND, J, T. SUTTON, J, W. SUTTON, J. W. SUTTON, J. W.	7912310067 7912210034 7912030544# 7912130428# 7912110128#		Q Q	TILLMAN.A. TILLMAN.A. TOALBTON.A. TOBIN.W.T.	7912310286 7912030074* 7912210212* 7912060406 7912030100	50-395 50-338 50-259 50-341	F Q H
STEWART, R. STEWART, R. C. STILL: R. C. STILL: R. C.	7912140477* 7912200091 7912120204* 7912310165 7912120086*	50-482 8 50-482 9 50-382 0 40-8745	SHANBY, O. T.	7912030230# 7912170241 7912030035 7912200162 7912310162	40-3453 40-3453 40-3453 40-3453		TOBIN, W. J. TOBIN, W. J. TOBIN, W. J. TODD, O. A. TOKARZ, F. J.	7912030074# 7912030053# 7912210212# 7912210235#	50-335 50-259 70-1151	0 0 0
STOHR, J. P. STOHR, J. P. STOHR, J. P. STOHR, J. P. STOHR, J. P.	7912170421 7912120158* 7912050114* 7912050662*	50-272 g 50-277 q 50-277 q 70-687	SWANSON, N. E. SWANSON, D. T. SWANSON, D. T. SWART, F. E.	7912240154# 7912130103 7912050015 7912170204	40-3453 GA979 50-70 G 50-289 G 50-247 G	)	TOLF, M. L. TOLLIBON, A. C. TOLLIBON, A. C. TOLLIBON, A. C.	7912210332 7912310508* 7912030177 7912130539 7912050432	50-255 50-325	P 9 8
STOHR, J. P. STOHR, J. P. STOHR, J. P. STOHR, J. P.	7912030096* 7912040240* 7912040201* 7912040110* 7912310045*	50-271	SWART, F. E. SWART, F. E. SWART, F. E. SWART, F. E. SWITZER, D. C.	7912190580 7912180595 7912270233 7912310175	50-267 P 50-267 P 50-267 P		TOLLISON, A. C.	7912050438* 7912050462 7912050470* 7912050475	50-325 50-325 50-325	8 8 8
STOHR, J. P. STOICK, A. F. STOICK, A. F. STOICK, A. F. STOLTENBERG, G.	7912070347# 7912120150# 7912120135 7912210112	50~217	SZHAJKOHSKI,R.W SZHAJKOHSKI,R.W H.R.YINGHONCAHSE SZHAJKOHSKI,R.W	7912310543 7912120048 7912120156 7912120048 7912130156	50-334 P 70-1308 70-1308 70-1308		TOLLIBON, A. C. TOLLIBON, A. C. TOLLIBON, A. C. TOLLIBON, A. C.	7912050480* 7912310507 7912110381* 7912180477 7912180482*		9
STOLZ, J. F. STOLZ, J. F. STOLZ, J. F. STOLZ, J. F.	7912180067* 7912100418 7912310119 7912130078 7912190534	WASTE MOT 50-358 A TOPREP 50-341 A	TARDADA, A. TAGGART, B. TAMBLING, T. N. TAMBLING, T. N. TAMBLING, T. N.	7912180186* 7912030158* 7912310088 7912050018*	50-295 Q 50-327 C 50-346 S 50-346 Q		TOLLISON, A. C.	7912180533 7912180537* 7912180603 7912180613* 7912270279	50-324 8 50-324 8 50-325 8 50-325 8 50-324 8	3 3
STOLZ, J. F. STONE, C. L. STONE, W. A. BTONE, W. A. STONE, R.	7912310262 7912120136 7912210020* 7912210012*	50-358 A 50-358 A FOIA GA999	Tambling, T. N. Tapia, J. I. Tapia, J. I. Taub, B. H.	7912180094 7912200028 7912200080 7912050531* 7912180085	50-346 B 50-346 B 50-482 S 50-382 Q 40-1341		TOLLIBON, A. C.	7912270301* 7912120298 7912120303* 7912180549 7912180552*	50-324 s 50-324 s 50-324 s 50-325 s 50-325 s	
STONE, R. STOODLEY, D. G. STOODLEY, D. G. STOUT, J. W.	7912130022* 7912270005* 7912190154 7912210100 7912210276	50-302 U PDR MISC 50-471 G 50-471 0	TAYLOR, L, S, TAYLOR, D, R. TAYLOR, J, H. TAYLOR, J, W. TAYLOR, J, H.	7912130003 7912190573	ACRS 50-339 A TOPREP NUREG TOPREP		TOLLISON, A. C.	7912180494 7912180498* 7912180540 7912180545*	50-324 8 50-324 8 50-325 8 50-325 8	
STONE, R. L. STRACCIA, F. P. STRACCIA, F. P. STRAND, N. O. STRAND, J. A.	7912190390* 7912040069 7912170125 7912120470	50-317 B 50-344 P 71-9070 71-9070 50-508 B	TAYLOR, T. M. TAYLOR, R. R. TAYLOR, P. A. TAYLOR, P. A. TAYLOR, P. A. TELFORD, J. T.	7912200310 7912180364# 7912060134#	50-416 A XPORTLIC 50-335 Q 50-261 Q TOPREP		TOLLISON, A. C. TOLLISON, A. C. TOLLISON, A. C. TOLLISON, A. C.	7912270536# 5 7912270549 7912270561# 5	50-324 s 50-324 s 50-324 s 50-324 s 50-325 s	
STRATTON, W. R. STRATTON, W. R. STREETER, J. P. STREETER, J. F.		NUREQ ACR8 ACR8 50-295 S 50-346 Q	TENZER, B. E. TERC, N. M. TETER: H. M. THADANI, A. THIE, J. A.	7912180534 7912260339* 7912180488* 7912110196	TOPREP 50-387 Q 50-275 U DEN TEC IS		TOLLISON, A. C.	7912270317* 5 7912270406 5 7912270414* 5 7912270322 5	50-325 s 50-324 s 50-324 s 50-325 s	
STREETER, J. F. STREETER, J. F. STREETER, J. E. STRINGER, B. M. STRNISA, F. V.	7912050035* 7912050412* 7912040158*	50-373	Thielmeier, L. F. Thiesing, J. W. Thies, A. C. Thies, A. C. Thies, A. C.	7912210185 7 7912280477 5 7912040512 5 7912270399 5	71-114 71-114 70-287 T 70-367 A 70-267 P	•	TOLLISON, A. C.	7912270535* 5 7912270541* 56 7912270563 56 7912270487 56	60-325 8 60-325 8 60-325 8 60-325 9 60-325 8	
TUMPH, T. L.	7912060164 7912280171#   7912280177#	TOPREP PROJ WASTE HOT WASTE MOT 70-454 g	THOM, W. T. THOMAS, C. D. THOMAS, E. B. THOMAS, H.	7912040470 5 7912040094 5 7912030198 5 7912040298# ##	0-269 р 0-387 о 0-320 н 0-341 к 0-390 q		TOLLISON, A. C.	7912270518 50 7912270528* 50 7912270537 50 7912270551* 50	0-325 & 0-325 & 0-325 & 0-325 & 0-325 &	
AMERS, R. T. HWERS, R.	7912210396 F 7912260331* 5 7912200534* 5	00-397 A 001A 00-134 Q 10-334 Q	THOMPSON, M. A. THOMPSON, M. A. THOMPSON, D. THOMPSON, D.	7912200580 W 7912170280 W 7912170280 W	DEREP ABTE MOT ABTE MOT		TOLLIBON, A. C. TOLLIBON, A. C. TOLLIBON, A. C.	7912270556 50 7912270559 50 7912270570# 50 7912270572 50	)-325 8 )-324 8 )-324 8  -325 8	
	. — —	C_1143	THOMSOME		RB 2-424 A				-325 8 -324 8 -324 8	

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION	SUBJECT CATEGORY	ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	
TONGUE, T. M. TONGUE, T. M. TONGUE, T. M. TOPP, A. A. TOPP, A. A.	7912050476* 7912050479* 7912050485* 7912050574 7912050580*	FOIA FOIA 70-2205 WASTE MOT WASTE MOT	TROUP, O. TROWBRIDGE, O. F. TROWBRIDGE, O. F. TROWBRIDGE, O. F. TROWBRIDGE, O. F. TROWBRIDGE, G. F.	7912200012 7912170209 7912170217 7912060095 7912130085	50-287 S 50-382 0 50-382 0 50-289 0 50-289 6	UTLEY, E. E.	7912130548 7912190559 7912270358 7912270380 7912270380 7912270325	50-261 P 50-261 P 50-261 P 50-324 P 50-324 S	
TOPP, A. A. TOPP, A. A. TOPP, A. A. TOYNE, Q. H. TRAGEBER, C. M.	7912050585* 7912190350 7912200446 7912190507 7912070173	WASTE HOT HASTE MOT HASTE MOT SO-331 J CONTRACT	TROWDRIDGE, G.F. TROWDRIDGE, G.F. TROWDRIDGE, G.F. TROWDRIDGE, G.F. TROWDRIDGE, G.F. TROWDRIDGE, G.F.	7912130308 7912280105 7912130034 7912130042 7912130110	50-289 6 50-289 6 50-382 6 50-289 6	UTLEY, E. E. UTLEY, E. E. VADEN, J. VAHRENWALD, J. VAKERICH, T. V.	79122703B3 7912270534 7912110170 7912070450* 7912050466	50-261 P 50-261 P PR 50-254 S FDIA	
TRACEBER; C. M. TRACER; E. A. TRACER; E. A. TRACER; E. A. TRACER; E. A. TRACER; IND. T. N.	7912100270 7912190642 7912190725 7912170100 7912160221	CONTRACT 40-8725 40-1341 WASTE MOT 50-346 S	TROWDRIDGE, G. F.	7912280140 7912270082 7912310176 7912260100 7912260293	50-392 0 50-287 0 50-287 0 50-287 0 50-287 0	VALENTINE, P. C. VALENTINE, P. C. VALENTINE, P. C. VALLISH, E. J. VALLISH, E. J.	7912130276 7912130176 7912130276 7912030495* 7912050089*	50-275 G 50-312 P 50-275 G 50-280 G 50-416 O	
TRAMM, T. R. TRAMMELL, C. M. TRAMMELL, C. M. TRAMMELL, C. M. THAMMELL, C. M.	7912110513* 7912170233* 7912170248* 7912040167 7912070096	90-295 0 90-344 0 50-344 0 90-266 P 90-344 P	TROWBRIDGE, G. F.	7912310149 7912130042 7912310149 7912170209 7912170217	50-400 0 50-382 0 50-400 0 50-382 0 50-382 0	VALLISH, E. J. VALORE, C. W. H. VAN BRUNT, E. E. VAN BRUNT, E. E. VAN DOORN, P. K.	7912310100* 7912130309 7912180445* 7912130961 7912050618*	50-390 G PR 50-528 G 50-528 D 50-416 G	
TRAMMELL, C. M. TRAMMELL, C. M. TRAMMELL, C. M. TRAMMELL, C. M. TRAUGER, T. C. TRAUGER, T. C.	7912120095 7912130012 7912280137* 7912120446 7912260359	50-344 8 50-266 P 50-344 0 PROJ PROJ	TROWBRIDGE, G. F.	7912280140 7712130085 7912110384 7912130308 7912130034	50-392 0 50-289 0 50-289 0 50-289 0 50-289 0	VAN DODRN, P. K. VAN DODRN, P. K. VAN ECK. O. J. VAN MICHAELIS, H VAN NESS, S. C.	7912210172* 7912210218* 7912040307 7912040525 7912050177	50-491 0 50-259 0 NUREO PROJ 50-272 G	
TRAUGER, T. C. TRAUGER, T. C. TRAUGER, T. C. TRAUGER, D. B. TRAUTHAN, D.	7912030042 7912260359 7912120446 7912140427* 7912260237*	PROJ PROJ PROJ REB 50-346 B	TROMBRIDGE, Q. F.	7912130110 7912270082 7912310196 7912260100 7912260293	50-287 0 50-287 0 50-287 0 50-287 0 50-287 0	VAN BICKEL, J. VAN WINKLE, H. VANCE, R. L. VANDENBURGH, D. VANDEL, T. E.	7912190405* 7912190546 7912200585 7912200551 7912260137*	50-331 R RES PR 50-29 F 50-327 G	
Travis, W. H. Travis, C. C. Traylor, F. Trible, P. S. Trimble, D. C.	7912170136 7912110465 7912170372 7912200320* 7912170134	71-9009 RES State Prog 50-339 A 50-313 G	TRZYNA, O. TUPPER, S. R. TURI, O. P. TURNER, J. A. TURNER, E. A.	7912070457* 7912110408 7912170230* 7912040099 7912060560	50-275 8 50-307 9 27-47 50-320 H 50-47B A	VANDEL, T. E. VARELA, A. VARGA, S. A. VARGA, S. A. VARGA, S. A.	7912260091+ 7912050078+ 7912070212 7912050294 7912070004	50-461 G 50-443 G 50-373 A 50-329 A 50-275 A	
TRIMBLE, D. C.	7912140236 7912050687* 7912040181 7912040305 7912040459	50-348	TURNER, E. A.	7912070361 7912070370* 79122102:1* 791221018B 7912210209	50-498 A 50-498 A 50-466 B 50-466 A 50-466 B	VARGA, S. A. VARGA, S. A. VARGA, S. A. VARGA, S. A. VARGA, B. A.	7912060563 7912060609 7912110005 7912110007 7912110010	50-387 A 50-311 A 50-390 A 50-369 A 50-339 A	
TRIMBLE, D. C.	7912040191 7912040197# 7912070446 7912120356 7912120283	90-313 P 90-313 P 50-348 Q 90-313 P 50-313 P	UDALL, M. K. UDMADIA, F. E. UHRIG, R. E. UHRIG, R. E. UHRIG, R. E.	7912130377* 7912180223 7912110199* 7912100453* 7912140527	50-320 U NUREO 50-389 Q 50-335 Q 50-389 Q	VARGA, B. A. VARGA, B. A. VARGA, S. A. VARGA, S. A. VARGA, B.,A.	7912110070 7912110134 7912130125 7912180087 7912180314	50-361 A 50-395 A 50-322 A 50-275 A 50-341 A	
TRIMBLE, D. C. TRIMBLE, D. C. TRIMBLE, D. C, TAIMBLE, D. C. TRIMBLE, D. C.	7912170256 7912170275 7912170312 7912200520 7912200525*	50-313 8 50-348 8 50-348 P 50-313 K 50-313 K	UHRIG; R. E. UHRIG; R. E. UHRIG; R. E. UHRIG; R. E. UHRIG; R. E.	7912310130 7912180353* 7912040276 7912060492 7912070127	REGOD 50-389 6 50-250 P 50-335 P 50-250 P	VARGA, S. A. VARGA, S. A. VARGA, S. A. VARGA, S. A. VARGA, S. A.	7912180323 7912270167 7912170135 7912170145 7912190076	50-358 A 50-364 A 50-358 H 50-358 H 50-358 H	
TRIMBLE, D. C.	7912270409 7912190709 7912170196 7912170231 7912260238	50-313 P 50-313 P 50-348 R 50-313 R 50-348 P	UHRIO, R. E. UHRIO, R. E. UHRIO, R. E. UHRIO, R. E. UHRIO, R. E.	7912110304 7912200004 7912310072* 7912110324 7912130259	50-250 P 50-250 Q 50-389 Q 50-335 P 50-335 P	VARGA, B. A. VARGA, B. A. VARGA, S. A. VARGA, S. A. VARGA, S. A.	7912130048 7912130132 7912130135 7912190157 79122300048	50-526 A 50-526 A 50-526 A 50-387 Q 50-247 P	
TRIMBLE, D. C. TRIMBLE, D. C. TRIMBLE, D. C. TRIMBLE, D. C. TRIMBLE, D. C.	7912270278 7912310456 7912260272 7912310335 7912270133	90-348 R 50-348 P 50-313 B 50-313 P 50-313 P	UHRIG, R. E. UHRIG, R. E. UHRIG, R. E. UHRIG, R. E. UHRIG, R. E.	7912140258 7912160243 7912140246 7912140290 7912200408	TOPREP 50-250 P 50-250 P 50-335 P 50-335 P	VARGA: S. A. VASSALLO: D. B. VASSALLO: D. B. VASSALLO: D. B. VASSALLO: D. B.	7912260086 7912110011 7911280153 7911140152* 7912040143	50-382 H 50-275 A 50-352 A 50-518 A 50-327 A	· ·
TRIMBLE, D. C. TRIMBLE, D. C. TRIPLETT, M. P. TRIPLETT, M. P. TRIPLETT, M. P.	7912310303 7912310471 7912180222* 7912110357* 7912190064*	50-368 8 50-313 F DRO TOPREP DRO	UHRIO, R. E. UHRIO, R. E. UHRIO, R. E. UHRIO, R. E. UHRIO, R. E.	7912200508 7912270391 7912270524 7912270350 7912270429	50-250 P 50-250 P 50-250 P 50-250 P 50-250 F	VASSALLO, D. B. VASSALLO, D. B. VASSALLO, D. B. VASSALLO, D. B. VASSALLO, D. B.	7911270467 7912040471 7912190173* 7912280049 7908070310	50-275 A 50-275 F 50-528 A 50-545 A 50-341 A	! !
TRIPLETT, M. P. TRIPLETT, M. P. TRIPP, R. W. TRIPP, L. E. TRIPP, L. E.	7912310225* 7912310233* 7912200422* 7912030048* 7912040026*	ORG ORG 50-339 A 50-333 Q 50-317 Q	UHRIQ, R. E. UHRIQ, R. E. UHRIQ, R. E. ULLRICH, W. T. ULLRICH, W. T.	7912270513 7912270357 7912280548 7912180010 7912310322	50-250 P 50-335 P 50-250 P 50-276 S 50-277 S	VAUOHN, H. VELAZQUEZBUAREZ VERBAGE, P. A. VETTER, W. E. VIZZINI, J.	7912170155 7912180140* 7912100335 7912190172 7912280422*	71-27 71-340 50-97 J NUREO 50-320 H	
TRIPP, L. E. TRIPP, L. E. TRIPP, L. TRIPP, L. TRIPP, L. TRIPP, L.	7912030056# 7912050010# 7912280342# 7912280392# 7912200167#	50-336 G 50-333 G 50-320 G 50-320 G 50-247 G	ULLRICH W. T. ULLRICH W. T. ULLRICH W. T. ULLRICH W. T. ULLRICH W. T.	7912130180 7912310191 7912130417 7912270393 7912190566	50-278	VOELZKE, D. VOGEL, R. J. VOGEL, R. J. VOGENEDE, J. C. VOOT, J. F.	7912050530 7912200124 7912200140* 7911160314 7912210418	FOIA 71-347 71-349 50-320 P 71-364	•
TRIPP, L. E. TROWKINDINEN, C.	7912200526* 7912200472* 7912210331* 7912260056* 7912310501*	50-423	ULLRICH, W. T. UNDERHILL, D. W. UNGARO, A. R. URCIUGLO, L. R. UTLEY, E. E.	7912270596 7912140517* 7912310356 791217036B 7912040283	50-277 S RES 50-275 A PRM 50-324 Q	VOICT, H. H. VOICT, H. H. VOICT, H. H. VOICT, H. H. VOICT, H. H.	7912200522 7912270034 7912280198 7912130460 7912130460	50-244 0 FOIA 50-244 P PR PR	
TROHK IMOINEN, C. TROHK IMOINEN, C. TROHK IMOINEN, C. TROJANONGKI, R. E TROJANONGKI, R. E	7912310465* 7912310495* 7912310469* 7912100461* 7912120255*	50-155 P 50-255 P 50-155 P 50-335 0 50-327 0	UTLEY, E. E.	7912040340 7912210059 7912120316 7912120360 7912120409	50-261 P NOREQ 50-261 P 50-261 P 50-324 P	VOIOT, H. H. VOIOT, H. H. VOLLMER, R. H. VOLLMER, R. H. VOLLMER, R. H.	7912130460 7912200522 7912040100 7912260309 7912040153	PR 50-244 9 50-320 P 50-289 P 50-289 P	a 5

## PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION MAGNER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	N SUBJA CATE		AUTHOR	ACCESSION		ÉCT .
VOLLMER, R. H. VOLLMER, R. H. VOLLMER, R. H.	791204009 <i>8</i> 7912040151	50-320 н	HATTENBARGER, 8. WEAVER, U. H.	7912040000 7912270156	3 XPORTI		HHITESIDES, C. E.	7912100011	CATEG	DRY
VOLLMER, R. H. VOLLMER, R. H. VOLLMER, R. H.	7912040136 7912110102 7912060440	2 50-289 P 50-289 P	Heaver, H. W. Heaver, J. Hebster, E. H.	791227016: 7912130377 7912130275	l# 50~313 7# 50—320	3 P 3 V	WHITES L. D. WHITE, L. D. WHITE, L. D. WHITE, L. D.	7912140040 7912120289 7912140047 7912170247	RES RES 50-244 50-244 50-244	œ
VOLLMER, R. H. VOLLMER, R. H.	7912040085 7912280324 7912280080	50~320 P	Webster, E. H. Webster, E. H.	791207004 <i>6</i> 791204064 <i>6</i>	50-336 50-336		WHITE, L. D.	7912040048	50-244	-
VOLLHER, R. H. VOTH, M. H. VOTINEN, V. O.	7912210118 7912030082 791200020	50-289 P 71-6058	Webster, E. H. Webster, E. H. Weeks, E. D.	7912070012 7912170407 7912120346	50-395 50-338	B S	WHITE, L. D. WHITE, L. D. WHITE, L. D. WHITE, L. D.	7912260033 7912050494 7912120447 7912120450	50-244 50-244 50-244 50-244	9 P P
WACHTER, L. J. WACHTER, L. J.	7912050671 7912190801	* 50-282 q	MEEKS, J. R. WEHRLE, J. L.	7912180181 791218025 <u>4</u>	# 0A999	_	WHITE, L. D. WHITE, L. D.	7912120445	50~244	Р
WACHTER, L. J. WACHTER, L. J. WACHTER, L. J.	7912280046 7912280053 7912280047	50-263 û 50-263 û	METGAND, J. G. METGAND, J. G. METGAND, J. G.	7912070137 7912060551 7912050353	50-459 50-459 50-458	Q	WHITE, L. D. WHITE, L. D. WHITE, L. D.	7912280022 7912180418 7912180514 7912180527	50~244 50~244 50~244 50~244	O P P
HACHTER, L. J. HAGNER, A. G.	7912280041 7912040260	50-282 Q 50-282 Q * 50-416 Q	WEIDAND, J. G. WEINER, M.	7912210335 7912170140	50-458 * 50-358		WHITE, L. D.	7912190515	50~244	s
WALBRIDGE, W. C. WALBRIDGE, W. C. WALKER, R. S.	7912260229 7912190553	50-312 B 50-312 P	Weiss, R. W. Weiss, J. L. Weiss, E. R.	7912120042 7912170383 7912050003	PROJ PROJ 50-266	0	HHITE, L. D. HHITE, L. D. HHITE, L. D. HHITE, L. D.	7912210390 7912280206* 7912270392 7912280501	50-244	P F P
WALKER, J. V. WALKER, R. D.	79122603134 7912160079 79120500374	XPORTLIC	WEISS, E. R. WEISS, E. R.	79122000&6 7912180422	± 50-289 • 50-3	e	WHITE, L. D.	7912270434	50-244	r Si
WALKER, D. I. WALKER, D. I. WALL, L. S.	7912210428* 7912210424*	FOIA	Weiss, E. R. Weiss, E. R. Weiss, E. R.	7912050606 7912170386 7912200063	TRO FDIA 50-289	6	WHITE, L. D. WHITE, T. J. WHITESIDES, G. E. WHITESIDES, Q. E.	7912310391 7912270262# 7912140467 7912140510	50-244 50-259 RES RES	b E
WALLACE, J. J. WALSH, P.	7912120328 7912140362# 7912060610	20 CW2 M	VEISS, E. R. WEISS, E. R.	79122000664 7912180410	50-289 50-3	e e	HHITE, J. R.	7912190214±	FOIA	
HALSH, P.J. HALSKE.C. HALTERS, D.K.	7912110442 7912130499	PRH NUREO PR	WEISS, E. R. WEISS, E. R. WEISS, J. D.	7912180422± 7912270040 7912200305	50-3 FOIA 70-143	e e	WHITENER, H. L. WHITENER, H. L. WHITENER, H. L. WHITESELL, D. E.	7912060215# 7912060235# 7912310353# 7912050544#	50-269 50-281 90-291 90-291	Q Q Q
WALTON, C. WALTON, O. A.	7912180174* 7912280342*	50-320 a	WEISS, J. D. WEISS, D.	7912260047# 7912270055#			WHITESELL, D. E.	7912130420#	GA999	
HALTON, G. A. HANDKE, N. E. HANDKE, N. E.	7912210331# 7912260056* 7912140431#	50-318 Q 50-289 Q FOIA	HEISS, J. D. HEISS, B. HEITZMAN, P. K.	7912190543 7912190465 7912120193#	71-6206 70-1257 50-346 50-338	s e	WHITESELL, D. E. WHITESELL, D. E. WHITESELL, D. E. WHITESELL, D. E.	7912110128± 7912110506± 7912200196± 7912200499×	Qለዓዋ <del>ታ</del> QAዓዋ <del>ታ</del> QAዓ <del>ዓ</del> ዋ	
WANDKE, N. E. WANDKE, N. E.	7912140452± 7912070418	FOIA 50-295 S	WELLING, S. WELLING, B.	7912130328 7912260297	50-445	Ħ	WHITESELL, D. E.	7912210199*	QA999 QA999	
WANDKE, N.E. WARD, J.E.	7912070453 7912110219 7912210073	50-295 B 50-295 R NUREQ	Welling, S. Wells, K. Wenslawski, F.	7912260297 7912260297 7912170378 7912260016	50~445 50~445 PR 50~344	H H S	HHITLEY, H. D. WHITNEY, G. G. WHITNEY, G. G. WHITNEY, G. G.	7912270577 7912060375# 7912040394#	50-249 50-293 50-293	I R S
HARD, E. C. HARD, K. D. HARD, K. D.	7912070332 7912030257=	50-282 S 50-329 O	HENSLAHSKI, F. A. HENSLAHSKI, F. A.	7912190125#	50-142	e	WHITNEY, G. Q.	7912110313± 7912110377#	50-293	8
WAREHBOURG, D.	7912070062* 7912180509 7912180500	50~341 Q 50~267 R 50~267 R	HENSLAHSKI, F. A. HENSLAHSKI, F. HERLING, J. A.	7912280653± 7912310066 7912060665 7912170182	27-10 50-344 50-344 50-334	S 6	WHITNEY, G. G. WHITNEY, G. G. WICHERS, D. L. WICHERS, D. L.	7912180437* 7912200340* 7912280104	50-293 50-293 50-293 40-8502	s s
WAREMBOURO, D. WAREMBOURO, D. WAREMBOURO, D.	7912040337 7912040296	50-267 S 50-267 S	WERLING, J. A. WERLING, J. A.	7912040522	50-334	8	HIDNER, H. A.	7912310203 7912040007	40-8502	
WAREMBOURG, D. WAREMBOURG, D.	7912040324 7912040332	50-267 S 50-267 S	HERLING, J. A. HERLING, J. A.	7912310385 7912130627	50~334 50–334	s s	WIDNER, W. A. HIDNER, W. A.	7912110055 7912210181#	50-321	0 0
HAREMBOURG, D.	7912040362	50-247 B	HERLING, J. A.	7912130634* 7912150633	50-334 50-334	s s	HIDNER, H. A. HIENCUB, L.	7912210177 7912070246	50-321	Q Q
WAREMBOURG, D. WAREMBOURG, D.	7912040429 7912040320	50-267 S 50-267 S	HERLING, J. A. HERLING, J. A.	7912180439#	50~334	S	HIGGINS, E.	7912200031	FOIA CONTRACT	
WAREMBOURG, D. WAREMBOURG, D. W. WAREMBOURG, D. W.	7912040400 7912120406 7912310074	50-247 S 50-247 P 50-247 P	HERLING, J. A. HERLING, J. A. HERHER, J.	7912270502 7912270506* 7912270520* 7912270398*	50-334 50-334 50-334 50-346	8 8 8	Higgins, E. Higgins, E. Higgins, D. Higgins, D.	7912110179 7912180023 7912040176 7912050054	CONTRACT CONTRACT 50-315	P
WAREMBOURG, D. WAREMBOURG, D.	7912110316 7912120324	50~247 P 50~267 B	WERNER, J. WESCOTT, H. M.	7712270420*	50-346	5	HIGGINTON, D.	7912050034		P -
WAREMBOURG, D. WAREMBOURG, D. WAREMBOURG, D.	7912120338 7912140331 7912180596	50-267 S 50-267 R 50-267 S	HEBST, A. S. HEBT, B. Q.	791226009[# 7912110514# 7912130529 7912140483#	50-461 50-261 PR RES	Q G	NICCINTON, D. NILBORN, L. NILKIN, H. A. NILLIAMB, D. C.	7912190007 7912030228* 7912140309 7912120126	50-334 50-382 RES	P D
WAREMBOURG, D. WAREMBOURG, D. W.	7912210373 7912180413 7912280562	50-267 P 50-267 R	Westerman, T. F. Westerman, T. F.	7912310055 7912310059	50-267	S	WILLIAMSON, T. C.	7912130041	PROJ	
WAREKBOURG, D. WAREKBOURG, D. WARNICK, R. F.	791227042 <u>6</u> 7912310396	50-267 P 50-267 S 50-267 R	NESTERMAN, T. F. NESTERMAN, T. F. NESTERMAN, T. F.	7912310087 7912310073 7912310084 7912050342*		5 5 6	WILLIAMS, C.E. WILLIAMS, H.A. WILLIAMS, E.H. WILLIS, E.	7912270002 7912210197* 7912270185 7912130358*	71-9010 50-219 ( 50-331 )	p
WARNICK, R. F. WARNICK, R. F.	7912200435 7912310066	50-346 S 50~346 S	HESTERHAN, T. F. HESTERMAN, T. F.	7912120204s		Q	WILLIAMS, H. O.	7912310437*	50-324 F 50-298 E	
Harnick, R. F. Harnick, R. F.	7912050019# 7912200564 7912050406#	50-346 Q 50-346 S 50-282 Q	WESTFALL, R. M. WESTFALL, R. M. WESTFALL, R. M.	7912120223* 7912100011 7912140640 7912140467	50-267 RES RES RES	Q	WILLIAMS, D. WILLIAMS, C. C. WILLIAMS, C. C. WILLIAMS, C. C.	7912140453* 7912210055 7912200007	RES 50-440 5 50-440 8	3
HARNICK, R. F. HARNICK, R. F. HARNICK, R. F.	7912050365= 7912260105=	50-346 & 50-282 <b>Q</b>	HESTFALL, R. M. HETMORE, J. S.	7912140510	RES		WILLIAMS, C. C.		50-546 Q	
WARNICK, R. F. WARNICK, R. F.	7912200250* 7912210074* 7912170423	50-346 @ 50-282 @ 50-282 &	HETTERHAIN, M. J. HETTERHAIN, M. J. HETTERHAIN, M. J.	7912040180 7912190085 7912110341 7912130090	50-272 50-358	P C C C	WILLIAMS, C. C. WILLIAMS, C. C. WILLIAMS, C. C. WILLIAMS, C. C.	7912060063± 7912310095 7912070162#	50~454 0 50~456 0 50~295 9 50~373 0	! !
WARNICK, R. F. WARNICK, R. F. WARNICK, R. F.	7912180094 7912180221	50~346 B 50~346 B	HETTERHAHN, H. J. HETTERHAHN, H. J.	7912110361	50-358	0.	HILLIAMS, C. C.		50-373 Q	
HATANABE, H. T. HATANABE, N.	7912110295	50-346 S TOPREP XPORTLIC	HETTERHAIN, H. J. HEZELHAN, J. A. HEARTON, R. J.	7912130090 7912140030 7912190406 7912100352	50-358 ( 50-272 ( FDIA		HILLIAMS, C. C. HILLIAMS, C. HILEON, R. J.	7912100342 7912180234+ 7912130510	50-546 Q 50-546 T 50-440 Q PR	
HATFORD, M. HATHEN, R. P. HATKINS, D.	7912120278+	50-261 R GA799	WHARTON, R. J. WHARTON, R. J.	7912130061	50-361 (	<b>.</b>	WILSON, W. R.		PR 400	
WATSON, K. S. WATSON, A. P.	7912070120	40-8200 50-329 и	HHARTON, R. J. MEELER, R. A.	7912100352 7912130041 7912280574	50-361 ( 50-361 (	2	HILSON, W.R. HILSON, M. R.	7912270048	50-498 M 50-498 M 50-498 M	
TOTAL STREET,	7712110465	RES	MHITAKER, M. B.	79122B0574 7912310026	50-133 ( RECOD		MILSON, J. H.	7912310001	50-498 H 50-445 M (PORTLIC	

## PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR	Y	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	,
								ZARSKY, L.	7912110303#	XPORTLIC	_
₩tuson, B. D.	7912030215	XPORTL IC		WOOD, L. D.	7912180002	XPDRTL.IC	•	ZARSKY, L.	7912110383#		G
WILSON, B. D.	7912200397	XPORTL. I C		MODD, J. C.	7912180654	71-352		ZECH, G.	7912110239	CONTRACT	_ !
HILSON B.	7912200329	XPORTLIC		MODD, J. C.	7912190657*	71-352	8	ZECH, G.	7912060649		P
HILSON, B. D.	7912120551	XPORTLIC		MBOD, E. C.	7912040325	90-309	S	ZEFF, D. W.	7912270051	71~6206	
HILSON, B. D.	7912190412	XPORTL LC		WOOD₄ E. C.	7912140494	50-309	5				
							6	ZEFF, D. W.	7912270058*	71-6206	
HILSON, B. D.	7912140146	XPORTLIC		MODD, E. C.	7912180954	50-309 50-309	8	ZEFF, D. W.	7912280001	70-1201	
WILSON, F. W.	7912260002	NUREG		WOOD, E. C.	7912040389		G	ZENTNER, M. A.	7912200175*	CONTRACT	_
WILSON, R. P.	7912060041	70-1729		UŒDHEAD₁C.P.	7912030113	50~409	Ğ	Z19ULSKY, H.	7912260074*		G
WILSON, R. P.	7912040045	50-491	G	WOODHEAD, C. ₽.	7912100357	50-466 50-483	Ğ	ZIBULSKY, H.	7912200516	70-364	
HILSON, R. P.	7912130319	PR		WOODHEAD, C. P.	7912180204	20-463	•				P
					2010010000	50-409	0	Z I EMANN, D. L.	7712050201	50-29	P
HTLSON, R. P.	7912130320*	PR		HOODHEAD, C. P.	7912260028 7912260085*	27~47	-	ZIEMANN, D. L.	7912180172		F
HILSON, W. R.	7912280118	50-490	М	WOODRUFF, R. L.	7912200002*	27-47		ZIEMANN, D. L.	7912200050		P
WILSON, R.	7912280477	50-289	T	MOODRUFF, R. L.	7912170232	50-334	0	ZIEMANN, D. L.	7912110015	50-237 50-10	P
WILSON, R. F.	7912040104	50-320	P	WOOLEVER, E. J.	7912110348	50-412	Š	ZIEMANN, D. L.	7912110017	90-10	•
WILSON, R. F.	7912310446	50-320	P	WOOLEVER, E. J.	/712110340	00 11-			mm45116016	50-155	P
			_		7912280473	50-412	A	ZIEMANN, D. L.	7912110018	50-255	P
HILSON, R. F.	7912310337	50-320	5	WOOLEVER, E. J.	7912210191*	50-62	G <sub>2</sub>	ZIEMANN D. L.	7912110020	50-213	, P
WILLSON, R. F.	7912180483	50~320	P	WRAY, J. R.	7912190177	40-4492		ZIEMANN, D. L.	7912110023	50-409	P
WILSON, R. F.	7912180428	50-320	P	WRIGHT, K. H.	7912170144*	71-9009		ZIEHANN, D. L.	7912110025	50-219	P
WILSON, R. F.	7912270249	50-320	P	WRIGHT, R. R.	7912070152*	50-471	G	ZIEMANN.D.L.	7912110026	JU 211	•
WILSON.R.F.	7912270343	50-320	P	ผส 1 GHT, F. S.	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				7912110029	50-245	р
			_	WRIGHT, G. C.	7912260364	50-331	5	ZIENANN, D. L.	7912110030	50-244	P
HILSON, R. F.	7912280599	50-320	P	GRIGHT, R. W.	7912070067*	50-390	O.	ZIEMANN, D. L.	7912110032	50-204	P
MILSON, J. N.	7912070084	50-322	Ą	WRIGHT R. W.	7912060594#	50~553	G	Z1EMANN, D. L.	7912110032	50-29	P
WILSON, J. N.	7912140053	50-322	A	URIGHT, R. W.	2912070149	96-439	5	ZIEMANN, D. L.	7912170079	50-244	P
HINEGRAD, O. W.	7912170114	50-317	P	₩υ, в. J. C.	7712110555	TOPREP		ZIEMANN, D. L.	, - 1 R 1 . G 5 .		
Wilzner, D. C.	7912040371*	50-315	5	HD1 D. C. C.				ZIEMANN, D. L.	7912170157	50-10	P
		50-316	9	WULLER, G. E.	7912050483	50-461	A	ZIEMANN, D. L.	7912170192	50-29	P
HIZNER, D. G.	7912070379#	50-316	s	YBARRONDO, L. J.	7912140300	RES		ZIEMANN, D. L.	7912170198	50~206	Р
MI ZNER, D. G.	7912100291*	50-316	S	YIN, 1. T.	7912140545*	QA999		ZIEMANN, D. L.	7912170204	50-237	P
HIZNER, D. G.	7912130322*	50-316	ŝ	YIN, I. T.	7912130067*	50~331	e e	ZIEMANN, D. L.	7712180167	50-213	F
WIZNER, D. C.	7912310350# 7912140048	50-295	Ğ	YIN, I. T.	7912200194#	50-263	u	ZIZIARRIO DI Z.			
HOLF, S. F.	7912140040	30 210	•			NUMBER OF		Z IEMANN, D. L.	7912130092	50~155	P ·
1101 55 5 1	7912060223	50-466	G	YODER, R. C.	7912210337	NUREG 50-289	U	Z IEMANN. D. L.	7912170063 <del>*</del>	50-155	G
WOLFE, S. J. WOLFE, S. J.	7912060220*	50~466	Ğ	YOUNG, J. B.	79122804924	50-267	ŏ	Z TEMANNI D. L.	7912170077	50-219	P
WOLFE, S. J.	7912050025	50-466	o	YOUNGDAHL R. C.	7912130195	50-255	Ğ	ZIEMANN, D. L.	7712170189	50-206	P
WOLFE, S. J.	7912060212	50~466	G	YOUNGDARL R. C.	7912060534 7912130239	50-255	P	ZIEMANN, D. L.	7912180081	50-255	P
MOLFE, S. J.	7912050198	50-466	G	YOUNGDAHL, R. C.	1415120574	,50 200	•			50 JES	p
TICKET ET G. G.					7912070346*	50~245	s	ZIEMANN. D. L.	7912130112	50-155 50-255	Ρ.
WOLFE, S. J.	7912120381	50-466	G	YOUNG, R. H.	7912100304+	50-245	5	ZIENANN, D. L.	7912190202	50-255 50-155	р
MOLFE, B. J.	7912120385	50-466	G	YOUNG, R. H.	7912180365*	50-245		ZIEMANN, D. L.	7912140107	50~155	P
WILLEE'S. J.	7912190396	50-382	C	YOUNG, R.	7912270542*	50-245		ZIEMANN, D. L.	7912210158	50-237	P
WOLFE, S. J.	7912200655	50-466	G	YOUNG, R. H.	7912200182*	CONTRA		ZIEMANN, D. L.	7912270006	30" EU	•
HOLFE, B. J.	7412280662	50-466	G	YTHIER, P.	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				7912210153	50-155	P
				YUHAS, Q. P.	7912190214*	FOIA		Z IEMANN, D. L.	7912270030	50-29	ŕ
MOLFF, T. A.	7912280166*		G I	YUNDT, C. P.	7912110344*	50-344		ZIEMANN, D. L.	7912310009	50-206	F
WOLIVER, J.	7912280682	FOIA	_	YUNDT, C. P.	7912110302	50~344	5	Z 1 EMANN, D. L.	7912180502*	50-275	Ü
MOLLETT, S.	7912180031	CONTRAC		YUNDT, C. P.	7912180627	50-344	5	ZIMMERMAN, A.	7912050633	50-400	a
WEILLETT, S.	7912110028	CONTRAC		YUNDT, C. F.	7912140361	50~344	R	ZIMMERMAN, S. R.	, 11204000-		
₩OLLETT, S.	7912180014	CONTRAC		7011211211				ZIMMERMAN, J. C.	7912140482*	50-331	£
		70-371		ZARAKAS, P.	7912190357*			ZIMMERMAN, J. C.	7912140469*	50-331	S
WOLTNER, E.	7912260046#			ZARAKAS, P.	7912190332*			ZIMMERMAN, J. C.	7912170219*	50-331	5
WOLTNER E	7912070273* 7912200333*			ZARAKAS, P.	7912190318#			ZIMMERMAN, J. C.	7912170231*	50-331	ន
MOLTNER, E.	7912200333	40-277		ZARAKAS, P.	7912190196	FOIA 50-247	, p	ZIMMERMAN, R. P.	7912180274*	50-271	G
HDNG, T.	7912210383*		T:	ZARAKAS, P.	7912270312	30-247		t till lead in the second			
MOOD, N. L.	1415510202	001110						ZIMMERMAN, R. P.	7912180309	50-245	S
								ZIMMERMAN, R. P.	7712050131*	50-333	a
								ZITTEL: H. E.	7912110509	RES	
								ZITTEL, H. E.	7712170422	RES	. '
								ZUEHLKE.J.R.	7912200588	40-B722	•
									7912110256*	50~333	R
								ZUFELT, E.	\415110500a	20 444	



The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered In this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the Index titled "Cross Reference of Enclosures to Principal Documents."

CATEGORY

ACCESSION

AUTHÜR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFFILIATION
ARMCO International, Inc.	7912120083# 7912120098#	GA999 GA999		American Industrial Hygiene Association American Institute of Steel Construction. Inc.
ATCOR	7912070303*	FDIA		1916.
Acme-Cleveland Co., Namco Controls Div.	7912260154*	QA999		American Mining Congress
Advanced Medical Systems, Inc.	7912060081	71-5796		American Nuclear Insurers
	7912070509	71-5796 50-514	B	
Advisory Council on Historic Preservation	7912120320	50-314 50-228	œ.	
Aerotest Operations	7912260134* 7912050464	50~514	Ď	
Agriculture, Dapt. of	7912270554	50-514	ם	American Nuclear Society
Akin, Gump, Hauer & Feld	7912140202	50-445	М	Anaheim, CA
WEID! Gamb' wane, & Leta	7912270084	50~445	М	
Alabaga Power Co.	7912030183	50-348	9 6	Andalman, Adelman & Steiner, P. A.
A depoka 1 bast os.	7912030187*	50-348	8	Appleased
	7912040368	50-348		Appleton Papers, Inc.
	7912040381*	50-348	S	
	79121000B4	71-5026 50-348	5	Argonne Mational Laboratory
	7912110335 7912110336*	50-348	8	· · · · · · · · · · · · · · · · · · ·
	7912110336* 7912110337#	50-348	s	Arizona Public Service Co.
		50-348	8	(11.4
	7912110338* 7912110339*	50-348	š	
	7912110337	50~348	5	Arizona, Univ. of
	7912120433*	50-34B	5	Arkansas Power & Light Co.
	7912120459#	50-340	9.	
	7912130422	50-348 50-348	9 9	
	7912130621	50-348	Ğ.	
	7912140473 7912140531	50-348	ā	
	7912170004	50-364	a	•
	7912180397	50-348	P P	
	7912160405	50-348	P	
	7912160542	50-34B 50-34B	F	
	79121 <b>9</b> 0550 79121 <b>9</b> 0556	50-348	P	
	7912210010	50~348	a	
	7912210170	50-348	G.	
	7912210170	50-348	() E	
	7912270212	50-348 50-348	8	
	7912270228#	30-340	_	+ .
	7912270238*	50~348	5	
•	7912270384	50-346	R	· ·
	7912270389*	50~348	R	
	7912280401	50-348	Н.	·
·.	7912310015	50-364	Q	
	7912310025	50-348	o.	
	7712310274	50-348	Q: R	•
•	7912310424	50~348 50~348	rt Rt	
	7912310426*	50-34B	8	
· ·	7912310448	JU 040	_	
	7912310451#	50-348	8	•
	7912180612	50-224	٥	
Alameda County, CA Alaska, State of	7912170413	PROJ		
Allied - General Nuclear Services	7912110349	REGOD		
American Friends Service Committee	7912070172	FOIA		A Company of the Comp

AFFILIATION	NUMBER	CATEGORY	***
Acendiation	7912040158*	50-320	Н
American Industrial Hygiane Association American Institute of Steel Construction	1. 7912130244	TOPREP	
Inc.	7912180124*	QA999 PROJ	
American Mining Congress	7912120240 7908290525	PDR MISC	
American Nuclear Insurers	\4085405%p	-Dit Tiles	
	7908290534	50-320	J
	7912070462	50~312	J.
	7712180580	50-244	J
	7912310110 7912170179#	REGGD ORG	
American Nuclear Society			
Anaheim, CA	7912050612*	PROJ PROJ	
	7912060016 7912130261	PR	
Andalman, Adelman & Steiner, P. A.	7912260355#	50-373	G
Appleseed Appleton Papers, Inc.	7912190769	XPDRTLIC	
Abbierou Labers, sun-		XPDRTLIC	
	7912190794* 7912050009	NUREG	
Argonne National Laboratory	7912070503	71-6717	
_	7912180276	ACRS	
Arizona Public Service Co.	7912130561	50-528	D
William I posts and	7912180445#	50~528	q
	7912060176*	CONTRACT	•
Arizona, Univ. of	7912040181	50~368	r
Arkansas Power & Light Co.	7912040187	50-369	P
	7912040191	50-313	Р
	7912040195*	50-34B	P
•	7912040197#	50-313	F
	7912040305	50-313	Q P
	7912040499	50-313 50-313	ī
	7912050449	20-214	•
	7912050587*	50-313	Œ
	7912070387	50-313	J
	7912070387	50-313 50-368	P
	7912070424 7912070428*	50-368	þ
			_
A Company of the Comp	7912070446	50~368 50-368	a
	7912070447° 7912120283	50-313	P
•	7912120254	50-313	P
	7912130042	50-392	O
* 4	5040400040	50-313	P
1 N	7912130249 7912130249	50-313	P
	7912140238	50~368	Q.
	7912140327	50-313	þ
	7912140327	50-313	P
	7912170134	50-313	a
	7912170196	50-368	R
	7912170203*	50-368	
•	7912170256	50-313	
	7912170264*	50-313	-
•	7912170269*	50-313	
	7912170275	50-348	
•	7912170279#		
	7912170281	- Ju-Jac	
1 - 1			

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	AUTHOR AFFILIATION	ACCESSION NUMBER	
	7912170312 7912170315 7912170331 7912170335 7912170375 7912190705	50-313 R 50-313 R 50-313 P	Baker & Notts	7912050092 7912050092 7912050092 7912050442 79120504514 7912060040	50-445 M 50-498 Q * 50-549 Q
	7712200520 7712200525 7712210342 7712210342 7712260238	50-313 P 50-313 P 50-368 P		7912100471 7912120056 7912120067# 7912130313 7912140005	50-466 0 50-466 0
	7912260272 7912260274* 7912270153 7912270278 7912270282*	50~368 P 50~313 S 50~313 S 50~313 P 50~368 R		7912140008 7912140168 7912140525 7912170046 7912170246	50-466 G 50-466 G 50-466 G 50-466 G 50-466 G
	7912270409 7912210335 7912310383 7912310384* 7912310393*	50-348 R 50-313 P 50-313 P 50-348 S 50-348 S		7912190041 7912190241 7912260286 7912260357 7912260357	50-478 Q 50-445 M 50-466 Q 50-445 M 50-445 M
	7912310399+ 7912310404+ 7912310409+ 7912310456	50-368 S 50-368 S 50-368 S 50-368 S 50-368 P	Baldwin, W. A. Baltimore Gas & Electric Co.	7912270053 7912280630 7912130176 7912130276 7912040463	50-466 G 50-498 M 50-312 P 50-275 G 50-317 F
Arkansas, State of Army, Dept. of	7912310461* 7912310471 7912310474* 7912110019* 7912190390*	50-368 P 50-313 F 50-313 F CGNTRACT 50-344 P		7912040358 7912040453 7912040454* 7912040449 7912040485*	50-317 q 50-317 s 50-317 s 50-317 s
Asher, T. R., PC  Atlas Industrial Manufacturing Co.	10752197 250002197 250202197 2115020197 250203197	71-5939 XPORTLIC XPORTLIC XPORTLIC XPORTLIC		7912060494 7912060499* 7912110559 7912120269 7912120269	50-317 S 50-317 S RECOD 50-317 P
Atlas Minerals	7912130381* 7912030035 7912030230* 7912170241 7912200162	0A999 40-3453 40-3453 40-3453 40-3453		7912120274 7912120289 7912130541 7912130543#	50-317 P 50-317 P 50-244 P 50-317 S 50-317 S
Atomic Energy of Canada, Ltd. Atomic Industrial Forum	7912280438 7912310162 7912180075 7912030075 7912130499	40-3453 40-3453 PT21 XPDRTLIC PR		7912180454 7912180469* 7912180597 7912180602* 7912180608	50-317 g 50-317 g 50-317 g 50-317 g 50-317 g
Austin, TX  Automated Sciences Group, Inc.	7912210073 7912210243 7912060247	DRQ NUREG PR 50-445 M 50-445 M		7912180619* 7912190364 7912190364 7912190403 7912190403	50-317 g 50-317 p 50-317 p 50-317 p 50-317 p
Automation Industries, Inc. Axelrod, B.M. BDM Corp.	7912190436+ 7912190448+ 7912260042	FOIA FOIA FOIA 71-9004 COMMISSION		7912190497 7912190497 7912190521* 7912190571 7912190571	50-317 P 50-317 P 50-244 8 50-317 Q 50-317 Q
Sabcock & Wilcox Co.	7912040412# 5 7912040417# 5 7912070456 5	FOIA 60-312 P 60-312 P 60-13 P 0-824		7912210276 7912260062 7912260064* 7912260220 7912260300	50-317 s 50-317 s 50-317 s 50-317 F 50-318 q
	7912130009# T 7912170030# T 7912170155 7	OPREP OPREP OPREP 1-27 1-27		7912270416 7912270416 7912280010	50-317 P 50-317 P 50-317 P 50-317 P 50-317 Q
	7912190716# 56 7912190721# 56 7912200030 7	UREG 0-313 P 0-313 P 1-88 1-88		7912280419 7912280523 7912280527* 7912310354	50-317 Q NUREQ 50-318 R 50-318 R 50-317 S
	7912270051 71 7912270058* 71 7912270156* 50	0PREP 1-6206 -6206 1-313 P -313 P		7912310357# ; 7912310388 ; 7912310388 ; 7912310414 ; 7912310414 ;	50-317 8 50-317 F 50-317 F 50-317 R 50-317 R
e e e e e e e e e e e e e e e e e e e	7912310227# AC 7912310239# AC 7912310351 70	120 1 R9 R8 135 346 P		7912310418# 5 7912310418# 5 7912310431# 5 7912310432# 5 7912310482# 5	50-317 R 50-317 R 50-317 F 50-317 F
abcock & Wilcox Co., Nuclear Material Div. abcock & Wilcox Operating Plants Owners Group	7912120106* 70	-255 р -364 -271 р		7912310490* 5 7912310496* 5 7912310502* 5 7912310511* 5	60-317 F 60-317 F 60-317 F 60-317 F
				7912310511# 5	0-317 F 0-317 F

AUTHOR	ACCESSION	BUBJECT CATEGORY		AUTHOR AFFILIATION	NUMBER	TOBLEUS CATEGORY	
	NUMBER 7912310525* 7912310530* 7912310530* 7912310534*	50-317 F 50-317 F 50-317 F 50-317 F 50-317 F	<del>;</del> ; <del>;</del>		7912240278 7912240281* 7912270182 7912270204*	50-293 P 50-293 S 50-293 S 50-293 S 50-293 S	
Battelle Memorial Institute, Columbus	7912310534* 7912310541* 7912310544* 7912310544* 7912120645	50-317 F 50-317 F 50-317 F NUREQ	<del>.</del>		7912270320 7912270321 7912270419	50-273 S 50-273 P 50-273 C 50-273 P 50-273 S	
Laboratories	7912140486	RES			7912310312	50-293 9 50-293 F 50-293 R	
Battella Memorial Institute, Pacific	7912140503* 7912200279 7912040520	REB NUREG			7912310414+ 7912310453	50-293 R 50-293 S	
Northwest Laboratory	7912120157 7912120641	NUREO NUREO		Briggs Engineering & Testing	7912210433 7912210437*	71-363 71-363	
	7912130324* 791214034B 7912140391 7912170320 7912170359	PR RES RES RES RES		Brookhaven National Laboratory	7912040103 7912040112 7912040119 7912040125	RES 1168 868 RES 868	
	7912180158 7912190547 7912190557	REB REB REB			7912040133 7912040383 7912100001	TOPREP RES	
	7912200015# 7912200020# 7912200766	71-6581 71-6581 NUREQ NUREQ			7912100005 7912110555 791212010B 7912120121 7912120129	TOPREP TOPREP TOPREP TOPREP	
Bear Creek Uranium Co.	7912210023 7912210337 7912310035 7912200404	NUREO RES 40-8452	S		7912140076 7912170278 7912180181* 7912100276*	71-9853 50-261 F 50-295 G CONTRACT	
Bechtel Associates Professional Corp. Bechtel Corp.	7912130224* 7912280565* 7912190210* 7912190487*	50-327 50-482 50-255	8 0 P	Brookings Institute Brown & Root Corp. (subs. of Halliburton Corp.)	7912110110# 7912110118#	QA999 QA999	
Bechtel Pawer Corp. (subs. of Bechtel	791228047 <b>7</b> 79120403 <b>5</b> 3#	50-387	s	Brawnsville.TX	7912130483 7912310001 7912310001	50-445 1 50-445 1	M M M N
Carp. }	7912110024* 7912110041* 7912110580 7912210347	GA799 GA999 REGOD TOPREP			7912310001 7912310161 7912310161 7912310161	50-445 50-445 50-445	", H H
Berkeley, CA Berle,Butzel,Kass & Case Black & Veatch	7912210353* 7912180616* 7912050447 7912260193* 7912260202*	TOPREP 50-224 50-547 GA997 GA999	G G	Brush-Weliman, Inc.	7912310161 7912310161 7912310189 7912200588 7912030203	50-445 50-445 40-8722 TOPREP	H H
Glack Hills Alliance Boeing Co.	7912310389 7912120051 7912170348 7912170353*	TOPREP PROJ XPORTLIC XPORTLIC	:	Strish-Wellman, Plants Cuners Group C-E Operating Plants Cuners Group	7912130447 7912180550 7912260017*	TOPREP 50-309 TOPREP TOPREP	P
Boeing Camputer Services, Inc. (subs. o	7912310174 7912310180*	XPORTLIC XPORTLIC CONTRACT	3	C-E Power Systems	7912030205* 7912130563 7912180007 7912190558	TOPREP 71-6078 NUREG	
Boeing Ca.) Bogin, M.B. Bosten Edison Co.	7912030023 7912040259 7912040387	50-574 50-293 50-293	6 P 9 S	California, State of	7912030042 7912030107 7912030112* 7912030117* 7912060166	PROJ 50-312 50-312 50-312 PROJ	G G
	7912040394* 7912050448 7912060375* 7912070126* 7912070390	50-273	R R G S		7912070171 7912070171 7912120446 7912120453*	50-275 50-275 PROJ PROJ PR	G G
	7912070393* 7912070494 7912110311 7912110313* 7912110370	71-9081 50-293 50-293 50-293	6 6		7912130333 7912130530 7912130549 7912130552 7912140054	PR PR PR 50-312	G G
	7912110377* 7912120333 7912120337* 7912120419 7912120440	50-293 \$ 50-293 50-293 50-293	8 P P F		7912170005 7912170012 7912180009 7912180015 7912240359	50-275 PR PR PROJ	G G
	7912140286 7912180489 7912180630 7912180637 7912190154	50-471	0 6 8 9 0	California, Univ. of, Berkeley California, Univ. of, Los Angeles	7912110375 7912050660 7912050661 7912050664 7912050664	)* 50-142 l* 50-142 4* 50-142 8* 50-142	Р Р Р
	7912200353 7912200360 7912200372 7912200373 7912210100	* 50-293 * 50-293 * 50-293 50-471	S R C	Capital Legal Foundation Carolina Power & Light Co.	791213027/ 791203007: 791203017: 791203022: 791204027	3* 50-261 7 50-324 5* 50-324	. G
	7912260065	50-293	Q Q				

AUTHOR AFFILIATION	ACCESSION NUMBER	4000	ECT GDRY	AUTHOR AFFILIATION	ACCESSION		
	7912040283 7912040283 7912040340 7912040340 7912040340	50-32- 50-32- 50-26: 50-26:	4 Q 1 P		NUMBER 7912270301 7912270306 7912270317 7912270325 7912270342	* 50-32 50-32 * 50-32	4 8 5 8 5 8
	7912040428 7912040432; 7912040505 7912050438; 7912050438;	50-324 50-325 50-325	8 9 9 9 9 9		7912270358 7912270380 7912270380 7912270383 7912270406	50-24: 50-32: 50-32:	1 P 4 P 4 P 1 P
	7912050462 7912050470 # 7912050475 7912050480 # 7912050534	50-325 50-325 50-261	9 \$		7912270414 7912270487 7912270490 7912270518 7912270522	* 50-324 50-329	9 8 9 8
	7912050549* 7912050629* 7912050633 7912070160* 7912110306	50-261 50-324 50-400 50-324 50-400			7912270526 7912270528* 7912270529 7912270534 7912270535*	50-324 50-325 50-325 50-241	5 5 P
	7912110378 7912110381* 7912110497* 7912120298 7912120303*	50-325 50-325 50-261 50-324 50-324	8 9 9 8 8		7912270536* 7912270537 7912270541* 7912270548 7912270549	50-324 50-325 50-325 50-324	9 9
	7912120314 7912120340 7912120392 7912120409 7912120409	50-241 50-261 50-400 50-324 50-324	թ 8 8 8		7912270551* 7912270554 7912270558* 7912270589 7912270561*	50-324 50-325 50-325 50-324 50-324 50-324	១ ជាសធាលា
	7912120414 7912130285 7912130288* 7912130354 7912130358*	50-400 50-261 50-261 50-324 50-324	A R R R		7912270563 7912270570* 7912270571* 7912270572 7912270583*	50-325 50-324 50-325 50-325 50-325	8 8 8 8 8
	7912130358# 791213044B 7912130452# 7912130461# 7912130461#	50-324 50-400 50-400 50-400 50-400	8 8 8 8		7912280172 7912280529 7912280529 7912280529 7912280529	50-261 50-261 50-261 50-261 50-261	9 9 9
	7912130461* 7912130461* 7912130472* 7912130539 7912130548	50-400 50-400 50-400 50-325 50-261	8 8 8 8		7912280529 7912280529 7912280546 7912280546 7912280546	50-261 50-261 50-400 50-400 50-400	5 8 A A
	7912130554* 7912130586 7912130586 7912130586 7912130586	50-261 50-261 50-261 50-261	P 8 8 8 8		7912280546 7912280555* 7912310053 7912310149 7912310266	50-400 50-400 50-261 50-400 50-324	A A G G
	7912130586 7912140317# 7912140319# 7912140322# 7912140329#	50-241 FOIA FOIA FOIA FOIA	6		7912310266 7912310262 7912310500 7912310500 7912310507	50-324 50-324 50-324 50-324 50-324	Q Q Q
	7912140332* 7912140337* 7912140346* 7912140445 7912140451*	FOIA FOIA FOIA 50-261 50-261	 9	Catalytic, Inc. (subs. of Air Products & Chemicals, Inc.) Cateroillar Tractor Co		50-324 REGGD 71-349	Q Q
4	7912140504* 7912170142 7912170142 7912170142	50-400	G G	Center for Development Policy	7912200140* 7912030023 7912050211* 7912050343*	71-349 XPORTLIC XPORTLIC XPORTLIC	
	(6) 61	50-400 50-400	0 0 0	Center for Law in the Public Interest 7	7912050343* 7912050046 7912050117 7912140011	50-574 50-275 50-275	Q Q Q
	7 ·	50-324 Fr 254 (	6 5 6	7	912130057 912130337 912130337 912130337	50-445 50-445	о м м м
		8		7 7 7	912130337 912130341* 912130341* 912130341* 912130341*	50-445 50-445 50-445	Н Н Н Н Н
		ž.		7' 7' 7'	712130366* 712130366*	50-445   50-445   50-445	M H H M
				79 79	/12130378# /12130378#	90-445 h 50-445 h 50-445 h 50-445 h	1

	ACCESSION	SUBJECT	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
AUTHOR AFFILIATION	NUMBER	CATEGORY		912040006	50-2B9 G	
Central & Southwest Services 2000 Central Iowa Power Cooperative Central Power & Light Co.	7912270185 7912050683 7912050683	50-445 M 50-331 P 50-445 M 50-445 M 50-445 M	Postponement 7 Coalition for Safe Power 7	912170272 912210185	50-289 G 50-344 G 71-114 71-114	
	7912100300 7912100300 7912100300	50-445 M 50-445 M 50-445 M 50-445 M 50-445 M	Cole: Raywid & Braverman Collins: V.P. MD Colorado State Univ.	7912070231 7912140161 7912310169 7912060030 7912170392	FOIA PR 40-8681 PROJ State Prog	
	7912130337 7912130337 7912130337	50-445 M 50-445 M 50-445 M 50-445 M 50-445 M	Calt Industries, Inc. Calumbia Univ.	7912210091 7912180254* 7912180544 7912210012* 7912210020*	WASTE MOT GA979 50-20B J GA999 OA999	
	7912130341*	50-445 M 50-445 M 50-445 M 50-445 M 50-445 M	Commerce Dept. of. National Bureau of	7912260017* 7912310481* 7912310523* 7912040109	TOPREP 50-255 P 50-255 P 50-320 P	
Chem-Nuclear Systems, Inc.	7912130378* 7912130378* 7912130378* 7912130378* 7907260948	50-445 M 50-445 M 50-445 M TOPREP	of Nursahard	7912050002 7912100262 7912140139 7912260354*	50-184 F 71-9953 50-373 G	
CHEMINATURE DYPINAL DISCHARGE	7912140119*	27-47 71-6275	Committee for Application of Mor Production Principles to US Nuclear Power Production	7912240354* 7912240355*	50-373 G 50-373 G	
Chicago Bridge & Iron Co. Chickering & Gregory	7912180095 7912190703* 7912190707* 7912190352 7912100352	50-217 P 50-219 P 50-361 G 50-361 O	Committee to Bridge the Cap	7912240355* 7912050630 7912190105* 7912190119* 79121901162	50-373 G FDIA 50-142 G 50-142 G 50-249 B	)
Christa-Maria	7912130061 7912130061 7912140142 7912060640 7912070344*	50-361 G 50-361 G 50-361 G 50-155 G 50-155 G	Commonwealth Edison Co.	7912030166* 7912030192 7912030196* 7912040011*	50-249 S 50-237 S 50-237 S 50-10 G 50-10 F	3 6 0
Cincinnati Gas & Electric Co. ,	7912130485 7912130546 7912170415 7912050391 7912110361	PR PR 50-155 0 50-358 F 50-358 0		7912040261 7912040261 7912040285 7912040297 7912040297 7912040297	50-10 F 50-454 F 50-10 F	무 F P P
	7912110376 7912110439 7912130090 791217030B 791220043B	50-358 0 50-358 0 50-358 G 50-358 A 50-358 F		7912040297 7912040297 7912040297 7912040297 7912040485	50-10 50-10 50-10	P P P P
Citizens Against Nuclear Dangers Citizens Against Nuclear Power	7912200440* 7912270336 7912050207 7912040455 7912130117	50-358 F 50-358 A 50-387 0 50-295 0 50-397 G		7912040485 7912040485 7912040485 7912040485 7912050501	50-10 50-10 50-10	የ የ የ
	7912130117 7912130120* 7912130120* 7912130121* 7912130121*	50-599 0 50-599 0 50-599 0 50-599 0 50-599 0		7912060190 7912070417 7912070417 7912070418 7912070422	50-245 50-10 50-10 50-295	0 P 8 8
	7912130128 7912130128 7912130294 7912140295 7912140295	50-599 0 50-599 0 50-599 0 50-599 0		7912070443 7912070450 7912070453 7912070457	50-254 ± 50-254 50-295 ± 50-295	8 8 9 4
Citizans Concerned About Nuclear Powers	7912120071*	50-498 U		7912100313 7912110219		R
Inc.	7912130467 7912170354 7912170354 7912170355*	50-498 Q 50-498 O 50-498 O 50-498 Q		7912110217 7912110223 7912110223 7912110223	50-295 * 50-295 * 50-295	R R R P
Citizens United for Responsible Energy Citizens for Equitable Utilities Citizens for Fair Utility Regulation	7912170355* 7912280469 7912260355* 7912130467 7912050203	50-498 0 FOIA 50-373 0 50-498 0 50-445 0		7912110309 7912110318 7912110318 7912110380 7912110380	50-295 50-295 50-237	6 6 6
Citizens for a Better Environment Civil Systems, Inc.	7912110224 7912050589* 7912050610* 7912050613* 7912190285	OBRUM TOM STRAM TOM STRAM TOM STRAM TOM STRAM		7912110386 791211039 7912110515 7912110515 7912110515	1* 50-237 3* 50-295 3* 50-295	P G G
Cleveland Electric Illuminating Co.	7912190359* 7912040223 7912050519 7912060084* 7912140364	50-440 G 50-440 B		791211051 791211052 791211052 791212001 791212008	8* 50-295 5* 50-295 5* 50-295 4 REGOD	6 6 8
Cleveland-Cliffs Iron Co.	7912140364 7912140371# 7912140371# 7912190275	50-440 S 50-440 S 50-440 S 40-8200		791212035	3 50-10	Р.

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE	ECT 30RY	AUTHOR AFFILIATION	ACCESSIO	N CII	BJECT
	7912120330# 7912120411 7912120411 7912120411 7912120411	50-10 50-10 50-10 50-10 50-10	Р Р Р	 THE STATE OF THE S	NUMBER 791218039 791218041 791218043 791218053	CA 7* 50~2 7 50~2 1* 50~2	TEGORY 249 8 249 8
	7912120411 7912120411 7912120411 7912120425 7912120425	50~10 50~10 50~10 50~10 50~10	թ 8 8		791218053 791218053 791218053 791218053 791218053	50-2 50-2 50-2	237 р 237 р 237 р 237 р
	7912120425 7912120425 7912130215 7912140192 7912140266	50-10 50-10 50-3 50-399 50-10	9 0 0 9		7912190108 7912190115 7912190117 7912190122 7912190126	* FOIA * FOIA * FOIA * FOIA * FOIA	<b>u</b> , L
	7912140266 7912140266 7912140366# 7912140372# 7912140372# 7912140372#	50-10 50-10 FOIA FOIA	P		7912190128 7912190138 7912190139 7912190145 7912190159 7912190159	FOIA FOIA FOIA	
	7912140376# 7912140379# 7912140379# 7912140389#	FOIA FOIA FOIA FOIA			7912190190# 7912190194# 7912190542 7912190542 7912190542	FOIA FOIA 50-23	7 P
	791214039B 7912140400# 7912140400# 7912140402#	FDIA 50-237 FDIA FDIA	8		7912190542 7912190542 7912190542 7912190548* 7912190545*	50-237 50-237 50-237 50-237	7 P 7 P 7 P
	7912140404# 7912140408# 7912140408# 7912140421	FOIA 50-237 FOIA FOIA 50-249	9		7912190545# 7912190545# 7912190545# 7912190545# 7912190542	50-237 50-237 50-237 50-237	6 6 6
	7912140426* F 7912140430* 5 7912140431* F 7912140431* F	01A 01A 0-249 01A 01A	9		7912190626* 7912200404 7912210169 7912210349 7912270200	50-249 50-249 50-245 50-379 50-10 NUREO	ያ የ የ የ
	7912140435# F 7912140439# F 7912140439# F 7912140446# F	DIA DIA DIA			7912270254 79122702654 7912270267 7912270267 7912270275#	50-237 50-237 50-3 50-3 50-3	8 9 P
	7912140452# FC 7912140452# FC 7912140456# FC 7912140456# FC				7912270275* 7912270275* 7912270275* 7912270345 7912270345	50-3 50-3 50-3 50-10 50-10	P P P B
	7912140460# F0 7912140460# F0 7912140462 50 7912140465# F0	IA -237 8 IA			7912270345 7912270394 7912270394 7912270394 7912270459 7912270459	50-10 50-254 50-254 50-237 50-237	8 8 8 8
	7912140469# 50: 7912140472# F01 7912140478# F01 7912140478# F01	-237 8 A A A			7912270464 7912270469 7912270469 7912270469	50-295 50-10 50-10 50-10 50-10	Р Р Р
	7912140481* FOI 7912140485* FOI 7912140485* FOI 7912140490* FOI	A A A			7912270469 7912270469 7912270469 7912270470	50-10 50-10 50-10 50-237	P P P
	7912140491# 50-7912140494# F01/7912140498# F01/7912140498# F01/7912140498# F01/	237 g			7912270470 5 7912270470 5 7912270470 5 7912270470 5	0-237 0-237 0-237 0-237	የ የ የ
	7912140500# FOIA 7912140500# FOIA 7912140500# FOIA 7912140508# FOIA 7912140513# FOIA		•		7912280533 5 7912280533 5 7912280533 5 7912280533 5	0-237 F 0-237 F 0-237 F 0-237 F	• •
	7912140513# F01A 7912180013 50-2: 7912180352 50-2: 7912180370# 50-2: 7912180376 50-24	14 B 14 B			7912280405 50 7912280405 50 7912310348 50 7912310348 50	)-10 H )-10 H )-10 P  -10 P  -10 P	! !
	7912180377 50-10 7912180386* 50-10 7912180386* 50-10 7912180386* 50-10	R R			7912310348 50 7912310348 50 7912310348 50 7912310348 50	-10 P -10 P -10 P -10 P -10 P -10 P	
						P	

AUTHOR AFFILIATION	ACCESBION NUMBER	SUBJECT CATEGO		AUTHOR AFFILIATION	ACCESSION NUMBER	EUDJECT CATEGOR	.Y
Community Supported Television LA.	7912310361 7912310361 7912310370 7912070165	50-10 50-10 50-237 FOIA	P P		7912270190# 7912270232 7912270267 7912270267 7912270267	50-247 50-247 50-3 50-3 50-3	ե ե ե
California Computer Data Systems, Inc.	7912200198*	CONTRAC	τ		7912270275	50-3 50-247	P P
Concerned Citizens Reactor Export Review	7912110383*	50-574	C		7912270312 7912270339	50-3 50-3	Р
Board Connecticut Yankee Atomic Power Co.	7912030173 7912040305 7912040501 7912070400	50-213 50-213 50-213 50-213	P P S P		7912270339 7912280224 7912280224 7912280257*	50-599 50-599 50-599	0
	7912100196* 7912140295 7912170244	50-213 50-213 50-213 50-213	Q Q Q		7912280257* 7912310181 7912310303	50-599 50-3 50-247 50-247	e P
	7912170294 7912170294 7912180248 7912180437	50-213 50-213	P P R	Consumers Pawer Co.	7912310403 7912310404* 7912310410* 7912030155 7912030188	50-247 50-247 50-227 50-329 50-329	5 5 6 0 0
	7912180441+ 7912180476 7912180478	50-213 50-213 50-213	R P P		7912030188 7912030191* 7912030191*	50-329 50-329 50-329 50-329	C C C II
	7912210109 7912210288 7912260116# 7912260262 7912270403	50-213 50-213 50-213 50-213	9 0 8		7912040110 7912040219 7912040286 7912040286	50-259 50-329 50-329	ā A
Conner, Moore & Corber	7912270589 7912110341 7912120361	50-213 50-358 50-416	P G G		7912040447 7912040447 7912050497	50-155 50-155 50-155	J P
	7912130090 7912130115 7912190085 7912210403	50-358 50-395 50-272 50-395	G		7912060015# 7912060210 7912060446 7912060450# 7912060500	50-329 50-255 50-155 50-155 50-155	0 B B
Consolidated Edison Co. of New York	7912260290 7912040465 7912040466	27-39 50-247 50-247	Q P		7912060509 7912060509 7912060509	50-155 50-155 50-155	61 61 14
	7912040470 7912050172# 7912060611 7912120465 7912120469#	50-247 50-247 PRM 50-247 50-247	р 0 8 8		7912060519 7912060520* 7912060534	50-255 50-255 50-255 50-255	G G
	7912130284 7912130284 7912130284 7912130291#	50-3 50-3 50-3 50-3	6 6 6		7912040621 7912040621 7912040621 7912040622*	50-155 50-155 50-155 50-155	ь ь ь
·	7912130291* 7912130291* 7912130306*	50-3 50-3 50-3 50-3	P P P		7912060523# 7912060523# 7912060624# 7912060625#	50-155 50-155 50-155 50-155	Р Р Р
	7912130306* 7912130306* 7912130667 7912140127	50-3 50-247 50-286	P P H		7912080626# 7912080626# 7912080627# 7912080627#	50-155 50-155 50-153 50-153	P P
	7912140158 7912140158 7912140333 7912140410	50-3 50-3 50-247	H R S		7912060628* 7912060628* 7912060627*	50-155 50-155 50-155	P
	7912140411# 7912170186 7912170245 7912170299#	50-247 50-3 50-247 50-247	9 9 8	•	7912050529# 7912050530# 7912050530# 7912050531#	50-155 50-155 50-155	P P
	7912170302 7912170302 7912170302 7912170307=	50-3 50-3 50-3 50-3	R R R		7912060632* 7912060632* 7912060633* 7912060634*	50~155 50-155 50-155	р Р
	7912190525 7912190541 7912190541 7912190194#	50-272 50-3 50-3 FOIA	P P		7912040694+ 7912040694+ 7912040694+ 7912040697+	50-155 50-155 50-155	P P
	7912190204 <del>=</del> 7912190226 <del>=</del> 7912190236=	FOIA FOIA FOIA			7912060641 7912060641	50-155 50-155	i P
	7912190242* 7912190249* 7912190253* 7912190286*	FOIA FOIA FOIA FOIA			7912070120 7912070120 7912070125 7912070125	50-327 50-329 50-158 50-158	H P
	7912190295* 7912190308* 7912190318* 7912190332*	FOIA FOIA FOIA			7912070344 7912070413 7912070414 7912070414	50-150 50-155 50-155	5 P 5 P
	7912190347* 7912190357* 7912190367* 7912190362*	FOIA FOIA FOIA			7912070421 7912070425 7912070429 7912070432	# 50-153 # 50-153 # 50-153	9 P 9 P
	7912270188	50-247	P		7912070435	# 50-15t	5 P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	
	7912070441* 7912070449* 7912070451 7912070458* 7912070465*	50-155 50-155 50-327 50-155 50-155	P P A P	Critical Mass Energy Project Cyprus Mines Corp.	7912310202 7912050343* 7912130332 7912170280 7912200580	NURED XPDATL I PRM HASTE M	MQT
	7912070467+ 7912100374 7912110303 7912110358 7912110365	50-155 50-155 50-255 50-329 50-329	P P S S	Dairyland Power Cooperative	7912040418 7912040423* 7912050493 7912100242 7912100318	50-409 50-409 50-409 50-409	8 P P
	7912110365 7912110373* 7912120180* 7912120397 7912120432	50-329 50-329 50-329 50-329 50-155	8 8 0 A 0		7912110206 7912110209* 7912110240 7912120265 7912130006	50~409 50~409 50~409 50~409 50~409	R R P P
	7912120436* 7912130195 7912130219 7912130239 7912130278	50-155 50-155 50-329 50-255 PR	0 9 8 P		7912130407 7912140416 7912180189 7912180545 7912180577	50-409 50-409 50-409 50-409 50-409	Р Р О
	7912130293 7912130297* 7912130396 7912130544 7912130544	50-255 50-255 PR 50-329 50-329	R R S		7912180590* 7912200427 7912200568 7912200571* 7912210174	50~409 50~409 50~409 50~409 50~409	n P B G
	7912140407 7912140409* 7912140412 7912140413* 7912140415	50-155 50-155 50-155 50-155 50-255	\$ 8 8		7912270388 7912270484 7912280464 7912310497 7912310504*	50-409 50-409 50-409 50-409 50-409	P 8 9 8
	7912170008 7912170058 7912170179 7912170235 7912180174	50-155 50-155 50-155 50-155 50-329	6 6 9 P 8	Dallas Power & Light Co. Dames & Moore DeKalb Area Alliance for Responsible Energy	7912280629 7912110246* 7912190678* 7912260355*	50-445 50-409 50-219 50-373	М Р Р
	7912180176 7912180212	50-329	S		7912260363	50-454	0
	7912180212 7912180508 7912180512*	50-329 50-329 50-255 50-255	M 5 8	Debevoise & Liberman Delaware, State of	7912280627 7912280627 7912280629 7912280629 7912050491*	50-445 50-445 50-445 50-445 50-272	M H H
	7912180514* 7912180517* 7912180526 7912180526 7912180526	50-255 50-255 50-329 50-329 50-155	8 8 8 F	Denver, Univ. of Detroit Edison Co.	7912130463 7912070492* 7912030200* 7912040364 7912040508	PR CONTRACT 50-341 50-341 50-341	T K A
	7912190464 7912200678 7912210146 7912210146 7912210182	50-255 50-255 50-155 50-155 50-155	P G P P		7912120382 7912120437 7912120562* 7912140428	50-341 50-341 50-341 50-341	A B Q A
	7912270193 7912270193 7912270197* 7912270197* 7912280483	50-329 50-329 50-329 50-329 50-329	A A A S		7912180520 7912270448 7912270555 7912270549* 7912310194	50-341 50-341 50-341 50-341 REGOD	A A A
	7912280483 7912280499 7912280522 7912280522 7912280540	50-327 50-255 50-327 50-329 50-329	8 9 8 8	Doggett, S.A.	7912260631 7912310148 7912310170* 7912310178* 7912310183*	50-466 50-466 50-466 50-466 50-466	0 0
	7912310296 7912310344 7912310355	50-329 50-255 50-255 50-155 50-255	5 Q P P 5	Dougherty, J.B. Douglass & Barham Dow Chemical Co. Dresser Industries, Inc. Duke Power Co.	7912180374 7912170088 7912130350* 7912130109	FDIA 50-445 50-264 XPORTLIC	
	7912310417 7912310425* 7912310436	50-255	P 53 53 53 53 53 53 53 53 53 53 53 53 53	SSEE FOREI CO.	7911160464 7912040010 7912040130 7912040293 7912040293	50-369 50-369 50-413 50-269 50-269	8 0 9 9
	7912310458 7912310476 7912310483 7912310491	50-155 50-255 50-155 RECOD	8 8		7912040293 7912040355 7912040415 7912040416 7912040418	50~269 50~269 50~269 50~269 50~269	P P P P
orn Belt Power Cooperative	7912310517*	50-255	F J		7912040434 7912040434	50-269 50-269	Q
ornall Univ. ottar Corp.	7912100335 7912200596	50-97 PROJ	J		7912040434 7912040474 7813040474	50-269 50-269	0 B
ouncil of Energy Resource Tribes ouncil on Environmental Quality	7912060075	NASTE MOT PROJ		· · · · · · · · · · · · · · · · · · ·	7912040476# 7912040479# 7912040512	50~269 50~269 50~369	8 A
exington & Burling	7912210184 F 7912110438	DR MIBC	M		7912040512 7912040516 7912040516 7912040516	50-369 50-269 50-269	A P P
· ·							

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE CATEG		AUTHOR AFF1LIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	7912040518# 7912040518# 7912040518# 7912050503 7912050503	50-269 50-269 50-269 50-369 50-369	P P B S		7912270451 7912270451 7912270451 7912270496 7912270496	50-269 50-269 50-269 50-488 50-488	P P P A
	791205051B 7912050592 7912050592 7912050594= 7912050594=	50-369 50-369 50-369 50-369 50-369	9 8 8 8		7912270496 7912270496 7912270496 7912270496 7912270503	50-488 50-488 50-488 50-488 50-270	A A A B
	7912040188* 7912040502 7912040502 7912040502 7912040549	50-349 50-249 50-249 50-249 50-249	9 7 9 0		7912270509+ 7912270577 7912270577 7912270577 7912270577	50-270 50-269 50-269 50-269 50-269	5 I I I
	7912060549 7912060549 7912070439 7912070442* 7912100165*	50-269 50-269 50-287 50-287 50-269	0 5 8 0		7912270577 7912270577 7912270577 7912280017 7912280017	50-269 50-269 50-269 50-269 50-269	I I Q Q
	7912110229# 7912110230 7912110362 7912110388# 7912110565	50-370 50-409 50-287 50-287 REGOD	0 P S B		7912280017 7912280159 7912280497 7912310005 7912310005	50-269 50-367 50-270 50-269 50-269	0 5 9
· .	7912110584 7912120274 7912120434 7912120434 7912120434	REGOD 50-269 50-269 50-269 50-269	В Р В		7912310005 7912310022 7912310022 7912310022 7912310460	50-269 50-269 50-269 50-269 50-369	() () () ()
	7912130088 7912130411 7912130411 7912130411 7912130419	50-491 50-269 50-269 50-269 50-409	0 8 8 8	Duquesne Light Co.	7912310489 7912310489 7912310493* 7912310493* 7912040105*	50-413 50-413 50-413 50-413 50-334	8 8 8
	7912130430 7912130556 7912140348 7912140348 7912140348	50-287 50-287 50-249 50-249 50-249	8 0 0		7912040289 7912040379 7912040439 7912040443* 7912040522	50-334 50-334 50-334 50-334 50-334	P R R S
	7912170127 7912170127 7912170211 7912170222* 7912170287	50-269 50-269 50-269 50-269 50-409	0 0 0 8		7912050448 7912040205± 7912100224± 7912100305 7912100311±	50-334 50-334 50-334 50-334 50-334	9 0 9 P
	7912170288* 7912180160 7912180161 7912180163* 7912180375	50-409 50-270 50-413 50-270 50-269	8 0 P R		7912110348 7912110353* 7912120312 7912130627 7912130634*	50-412 50-412 50-334 50-334 50-334	5 6 8
	7912180375 7912180375 7912180384* 7912180384* 7912180384*	50-269 50-269 50-269 50-269 50-269	R R R R		7912170164 7912170162 7912170232 7912180362 7912180368*	50-334 50-334 50-334 50-334 50-334	Q Q Q R R
	7912180588 7912180588 7912180593* 7912180593* 7912190710	50-413 50-413 50-413 50-413 50-369	5 5 5		7912180633 7912180639* 7912270354 7912270370 7912270456	50-334 50-334 50-334 50-334 50-334	8 9 P P
	7912190710 7912190790 7912190790 7912190790 7912210075	50-349 50-249 50-249 50-249 50-249	9 9 9		7912270502 7912270506* 7912270520* 7912280002 7912280473	50-334 50-334 50-334 50-334 50-412	9 9 9
	7912210075 7912210075 7912210145# 7912210151 7912210151	50-269 50-269 50-491 50-369 50-369	0 0 0 A A	E. I. du Pont de Nemours & Co., Inc.	7912310343 7912310385 7912100310 7912210434* 7912050157*	50-334 50-334 50-416 71-5467 50-263	1 8 A P
•	7912210171 7912210171 7912210238+ 7912210238+ 7912210248+	50-349 50-349 50-249 50-249 50-249	F G G		7912140296 7912140300 7912140309 7912140314 7912140540	RES RES RES RES	
	7912210248* 7912210248* 7912270246 7912270246 7912270266	50-269 50-269 50-269 50-269 50-269	0 G P P		7912170194 7912180144 7912190066* 7912190567 7912190570	RES RES 50-244 RES RES	P
	7912270327 7912270352 7912270399 7912270399 7912270399	50-367 50-369 50-269 50-269 50-269	A P P	Eaton, R.O., P.E. Ebasco Services, Inc. (subs. of Enserch Corp.)	7912310154# 7912190671# 7912050097 7912110572	50-335 50-219 50-574 REGOD	P

AUTHOR AFFILIATION	ACCESS10	SUBJE CATEG		AUTHOR AFFILIATION	ACCEB9ION NUMBER		JECT EGORY
Eberline Instrument Corp.	7912180334 7912180541 7912210194 7912310034 7912210027	TOPREP 50-466 REGED	. A		7912190599 7912200000 79122000119 79122000299 7912200110	71-65 * 71-65	301 3631 3631
Edgecomb-Hartin County Electric Membership Corp. Edison Electric Institute Edlow International Co.	7912180301 7912130481 7912030218 7912060178 7912100216	PR * XPORTLI XPORTLI	IC IC		7912270124 7912280003 7912280004 7912280222 7912280240	50-24	01 4 P
Electric Power Research Institute	7912140122 7912170369 7912180096 7912180106 7912270373	XPORTLI XPORTLI XPORTLI XPORTLI	IC IC IC	FURGO Consulting Engineers & Goologist Federal American Partners Federal American Partners (Mining)	7912280571* 7912070420* 7912030012 7912180179 7912180184*	50-10 40-449 40-449	92 92 92
Energy Fuels Nuclear, Inc. Energy Incorporated	7912190010 7912310464- 7912310465- 7912310469- 7912310473-	40-8481 50-155 50-155 50-155	l Р Р	Federal Emergency Management Agency	7912310375 7912050571* 7912050573* 7912050578* 7912050581*	State State	Prog Prop Prog
Energy, Dept. of	7912310487: 7912310495: 7912310501: 7912030243 7912030244*	50-255 50-255 50-255 XPDRTLI	P P P C C	Federal Interagency Central Coordinatin Committee Federal Prisons Industries Finland Fischer Controls Co., Inc. (subs. of Monsanto Co.)	7912090945 7912090995 7912210387* 7912280116 7912110111*	State State CONTRA XPORTL QA997	Prog
	7912050458 7912060204 7912110280 7912110284* 7912130154* 7912130450	71-5467 PROJ XPORTLIC XPORTLIC PROJ PR	C	Fleischaker, D. S.	7912050046 7912050117 7912060608 7912100483 7912110432	50-275 50-275 70-262: 50-275 70-262:	6 B A
	7912140112± 7912140116 7912170136 7912180097 7912190130	70-2623 71-6345 71-9009 PR			7912130160 7912130168 7912130168 7912130168 7912140011	50-275 50-275 50-275 50-275 50-275	Q Q
	7912210419 7912210425+ 7912260161 7912280233	71-9953 71-5467 71-5467 XPORTLIC PR		Florida Cities Florida Power & Light Co.	7912270064 7912310457 7912060020 7912200207	50-275 50-275 50-250 50-369	0 M H
inergy,Dept.of. Clinch River Breeder Reactor Plant	7912310247* 7912110554 7912200578	50-320 REGOD	н .		7912030146 7912030149#	50-251	8 9
nergy, Dept. of, Idaho Operations Office	7912310177 7912140309	50-537 REGQD RES	٨		7912030152 7912030140* 7912030211 7912040276	50-250 50-250 50-250 50-250	8 0 8 P
nvironmental Coalition on Nuclear Power	7912060039 7912060082 7912110043 7912120055 7912120063	PROJ PROJ 50-277 PROJ PROJ	0		7912040422 7912040425* 7912040430 7912040444* 7912060492	50-335 50-335 50-335 50-335 50-335	9 9 9 9
	7912130559 7912130562= 7912170095 7912210423 7912280614		0 0		7912070127 7912100453* 7912110199* 7912110304	50-250 50-335 50-250	р 0 0 0
nvironmental Policy Center nvironmental Policy Institute	7912050343± 7912050417 7912050617	XPDRTL1C PRDJ PROJ			7912110304 7912110324 7912110438	50-250 50-335 50-250	р М
nvironmental Protection Agency	7912130292 7912180585# 7912190136#		α		7912130050 7912130259 7912130244*	50-250 50-333 50-335	ե 5 0
	7912190144# 7912190148# 7912190225# 7912190452	40-8727 40-8727 40-8727 HASTE MOT 50-272	P		7912130440 7912130457# 7912130534 7912130536#	50-335 50-335 50-250 50-250	8 8 8
	7912280114 7912280171* 7912280177* 7912280202* 7912280203	PR HASTE HOT HASTE HOT PROJ			7912130632 7912130639 7912130641# 7912130647# 7912130653	50-250 50-335 50-250 50-335 50-250	8 8 8
ropean Communities, Commission of ron Minerals Co., USA	7912280474# 7912210128 7912130403 7912170417 7912190780	27-10 XPORTLIC PROJ PROJ 40-8102			7912130650+ 7912140014 7912140229 7912140246 7912140258	50-250 50-250 50-250 50-250 TOPREP	р В В
ton Nuclear Co., Inc. (subs. of Exzon	7912200169 7912200173± 7912310190 79123100407±	40-8102 40-8102 40-8102 50-3 р			7912140290 7912140527 7912180243 7912180243	50-335 50-389 50-250 50-250	Р О Р
	791210045 <u>6</u> ± 7912120305 7912130475	50-3 р 50- <u>261 р</u> PR				50-089 50-250 50-250	9 B
						50-250 50-250	a a

AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGO!		AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGORY
	7912200408 7912200508 7912270098 7912270380 7912270350	50-335 50-250 50-389 50-250 50-250	P P G P		7912120476* 7912130156 7912130493 7912130496 7912130500*	XPORTLIC 70-1308 50-447 A PR 50-447 A
	7912270357 7912270391 7912270429 7912270429 7912270513	50-335 50-250 50-250 50-250 50-250	P P F F P		7912130538 7912130553 7912130566 7912140243 7912140251	TOPREP 50-271 P TOPREP 50-70 P TOPREP
	7912270513 7912270524 7912280548 7912280548 7912310072*	50-250 50-250 50-250 50-250 50-387	P P P G		7912140365* 7912170017* 7912170108* 7912180156* 7912180523	50-70 P 50-70 G 50-293 P FDIA TOPREP
Florida Power Corp.	7912310130 7912030154 7912030157* 7912040441 7912040499	REGGD 50-302 50-302 50-302 50-302	8 8 P		7912180574 7912190509 7912190568 7912190599 7912200329	TOPREP TOPREP TOPREP NUREO XPORTLIC
	7912040502* 7912060666* 7912070460 7912100114 7912100207	50-302 50-302 50-302 50-302 50-302	P Q P Q Q		7912200381 7912200397 7912260246* 7912270109 7912270292	TOPREP XPORTLIC 50-293 P TOPREP TOPREP
	7912100269 7912100275* 7912110330 7912110331*	50-302 50-302 50-302 50-302	5 5 5	General Electric Co., Nuclear Energy Products Div.	7912280143 7912310182 7912040235*	REGOD REGOD TOPREP
	7912110351	50-302	P _		7912050559 7912120551	TOPREP XPORTLIC
	7912110410 7912110417* 7912120288 7912130201 7912140222	50-302 50-302 50-302 50-302 50-302	Р Р Р Р	General Electric Operating Plant Owners	7912140146 7912190412 7912280547 7912130148	XPORTLIC XPORTLIC TOPREP TOPREP
	7912140239	50-302	P P	Graup	7912130152*	TOPREP
	7912180271 7912180275* 7912180391	50-302 50-302 50-302	P R	General Public Utilities - GPU Service Corp.	7912040087	50-289 I
	7912180398* 7912190268 7912190629	50-302 50-302 50-302	R P J		7912040104 7912040345 7912050511 7912130243	50-320 P 50-289 I 50-289 I 50-289 0
	7912190795 7912260239 7912260243*	50-302 50-302 50-302	Q S S		7912260219 7912280477	50-289 I 50-289 T
	7912260245 7912260254* 7912270575	50-302 50-302 50-302	F P	General Services Administration	7912280479 7912310446 7912040036#	50-289 T 50-320 P 40-341
	7912310010 7912310016 7912310018	50-302 50-302 50-302	a a	Georgia Power Co.	7912280007 7912040007 7912040007 7912040445	40-341 50-321 0 50-321 0 50-424 A
	7912310533 7912310536#	50-302 50-302	F F		7912050150	50-321 P
Florida State Univ.	7912316540* 7912140483*	50-302 RES	F		7912050150 7912050155*	50~321 P 50~321 P 50~321 P
Florida, State of Florida, Univ. of, Gainesville Fox, Farr & Cunningham	7912280218 7912210058* 7912050180	PR 50-83 50-289	g G		7912050155* 7912050440 7912050445*	50-321 P 50-366 S 50-366 S
Franklin Institute/Franklin Research	7912180246 7912120558	50-267 FOIA	Ö		7912050450 7912050457* 7912050533 7912050533	50-321 S 50-321 S 50-321 P 50-321 P
Friends of the Earth	7912100352 7912100352	50-361 50-361	G G		7912070445	50-366 B
	7912130061 7912130061 7912130453	50-361 50-361 PR	G G		7912070448# 7912100139 7912110055 7912110055	50-366 S 50-321 H 50-321 Q 50-321 Q 50-321 S
	7912140425 7912170007* 7912280508	50-224 50-70 50-275	0 0 0		7912110320 7912110323*	50-321 S
Friends of the Filipino People Gage-Babcock Associates, Inc.	7912110350* 7911190530*	50-574 50-322	9		7912110368 7912110372* 7912130384	50-366 9 50-366 9 50-366 8
Ceneral Atomic Co. (subs. of Gulf Dil Co.)	7912070226 7912070360*	71-6300			7912130392* 7912130394	50-366 S 50-366 S
General Electric Co.	7912120012 7912030071 7912030215	FOIA PR 50-574 XPORTLIC	: <sup>A</sup>		7912130400* 7912130400* 7912130408* 7912130412	50-366 6 6 366-05 50-366 8 6 36-366 8
	7912040213 7912060521 7912070391 7912100330* 7912110167*	TOPREP TOPREP TOPREP 50-3 40-7344	P '		7912130421* 7912130424 7912130426 7912130436*	50-366 B 50-321 B 50-321 B 50-321 B
	7912110386*	50-237 50-295	P G		7912140236 7912140236	50-424 A
	7912110532* 7912120048	70-130B	•		7912140236	50-424 A 50-321 P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
erline Instrument Corp.	7912180534 7912180541± 7912210194± 7912310036 7912210027	TOPREP TOPREP 50-446 REGGD XPORTLIC	A :		7912190639 7912200008 7912200011* 7912200029* 7912200110	NUREG 71-6581 71-6581 71-6581 71-6581
gecomb-Martin County Electric lembership Corp. lison Electric Institute  low International Co.	7912180301 7912130481 7912030218± 7912060178	50-339 PR XPORTL IC XPORTL IC			7912270124 7912280003 7912280006* 7912280222* 7912280240*	71-3 71-6581 71-6581 50-244 P 50-244 P
ectric Power Research Institute	7912140122 7912140122 7912170369 7912180096 7912180076	XPORTLIC  XPORTLIC  XPORTLIC  XPORTLIC  XPORTLIC  XPORTLIC		FURGO Consulting Engineers & Geologists Federal American Partners Federal American Partners (Mining)	7912280571* 7912070420* 7912030012 7912180179 7912180184*	50-397 A 50-10 P 40-4492 40-4492 40-4492
ergy Fuels Nuclear, Inc.	7912270373*  7912190010  7912310464*  7912310469*  7912310473*	40-9691 50-155 50-155 50-155 50-155	ե ե ե	Federal Emergency Management Agency	7912310375 7912050571= 7912050573= 7912050578= 7912050581=	40-4472 State Prog State Prog State Prog State Prog
iergų. Dept. of	7912310487* 7912310495* 7912310501* 7912030243 7912030244*	50-255 50-255 50-255 XPORTLIC XPORTLIC	P P	Federal Interagency Central Coordinating Committee Federal Prisons Industries Finland Fischer Controls Co., Inc. (subs. of Monsanto Co.)	7912050565 7912050595 7912210387* 7912280116 7912110111*	State Prog State Prog CONTRACT XPORTLIC GA999
	7912050458 7912060204 7912110260 7912110264* 7912130154*	71-5467 PROJ XPDRTLIC XPDRTLIC PROJ		Fleischaker, D. S.	7912050046 7912050117 7912060608 7912100483 7912110432	50-275 0 50-275 0 70-2623 50-275 A 70-2623
	7912130450 7912140112* 7912140116 7912170134 7912180097	PR 70-2423 71-6345 71-9009 PR			7912130160 7912130168 7912130168 7912140011 7912140011	50-275 0 50-275 0 50-275 0 50-275 0 50-275 0
e en	7912190130 7912210419 7912210425= 7912260161 7912260233	71-9853 71-5467 71-5467 XPORTLIC PR		Florida Cities Florida Power & Light Co.	7912270064 7912310457 7912060020 7912200287	50-275 G 50-275 G 50-250 H 50-389 M
ergy.Dept.of, Clinch River Breeder eactor Plant	7912310247* 7912110554	50-320 RECOD	Н	riorida roser a Light Co.	7912030146 7912030149# 7912030152	50-251 8 50-251 8 50-250 6
ergy.Dept.of, Idaho Operations Office	7912200576 7912310177 7912140309	50-537 REGGD RES	A		7912030160# 7912030211 7912040276	50-250 S 50-250 S 50-250 P
vironmental Coalition on Nuclear Power	7912060039 7912060082 7912110043 7912120055 7912120063	PROJ PROJ 50-277 PROJ PROJ	0		7912040422 7912040425* 7912040438 7912040444* 7912060492	50-335 S 50-335 S 50-335 S 50-335 P
	7912130559 7912130562* 7912170095 7912210423 7912280614		G G		7912070127 7912100453* 7912110199* 7912110304 7912110304	50-250 P 50-335 G 50-389 G 50-250 P 50-250 P
vironmental Policy Center vironmental Policy Institute vironmental Protection Agency	7912050343* 7912050617 7912050617 7912130292 7912130292	XPORTLIC PROJ PROJ PR 50-409	D		7912110324 7912110438 7912130050 7912130259 7912130264*	50-335 P 50-250 H 50-250 0 50-335 P 50-335 P
	7912190136* 7912190144* 7912190148* 7912190225* 7912190452	40-8727 40-8727 40-8727 WASTE HOT 50-272			7912130440 7912130457# 7912130534 7912130536# 7912130632	50-335 S 50-335 S 50-250 S 50-250 S 50-250 S
	7912280114 7912280171* 7912280177* 7912280202* 7912280203	PR WASTE HOT WASTE HOT WASTE HOT PROJ	· ·		7912130639 7912130641* 7912130647* 7912130653 7912130658*	50-335 8 50-250 9 50-335 8 50-250 8 50-250 8
ropman Communities, Commission of con Minerals Co., USA	7912260676# 7912210128 7912130403 7912170417 7912190780	27-10 XPORTLIC PROJ PROJ 40-8102			7912140014 7912140229 7912140246 7912140258 7912140290	50-250 0 50-250 8 50-250 P TOPREP 50-335 P
ton Nuclear Co., Inc. (subs. of Exzon orp.)	7912200169 7912200173* 7912310190 7912100407*		P -		7912140527 7912180243 7912180243 7912180353= 7912190520	50-389 Q 50-250 P 50-250 P 50-389 Q 50-250 S
	7912100456* 7912120305 7912130475		h L		7912190522# 7912200004 7912200004	50-250 B 50-250 Q 50-250 Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGO	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7912200408 7912200508 7912270098 7912270350 7912270350	50-335 50-250 50-369 50-250 50-250	Р Р Р		7912120476* 7912130156 7912130493 7912130496 7912130500*	XPGRTLIC 70-130B 50-447 A PR 50-447 A
	7912270357 7912270391 7912270429 7912270429 7912270429 7912270513	50-335 50-250 50-250 50-250 50-250	P F F P		7912130538 7912130553 7912130566 7912140243 7912140251	TOPREP 50-271 P TOPREP 50-70 P TOPREP
	7912270513 7912270524 7912280548 7912280548 7912310072*	50-250 50-250 50-250 50-250 50-389	P P P Q		7912140365* 7912170017* 7912170108* 7912180156* 7912180523	50-70 P 50-70 0 50-293 P FOIA TOPREP
Florida Power Corp.	7912310130 7912030154 7912030157* 7912040441 7912040499	REGOD 50-302 50-302 50-302 50-302	\$ 8 P		7912180574 7912190509 7912190568 7912190599 7912200329	TOPREP TOPREP TOPREP NUREG XPORTLIC
	7912040502* 7912060666* 7912070460 7912100114 7912100207	50-302 50-302 50-302 50-302 50-302	P Q P Q		7912200381 7912200397 7912260246# 7912270109 7912270292	TOPREP XPORTLIC 50-293 P TOPREP TOPREP
	7912100269 7912100275* 7912110330 7912110331*	50-302 50-302 50-302 50-302	8 8 8	General Electric Co., Nuclear Energy Products Div.	7712260143 7712310162 7712040235*	REGOD REGOD TOPREP
	7912110351	50-302	b b		7912050559 7912120551	TOPREP XPDRTLIC
	7912110410 7912110417* 7912120288 7912130201 7912140222	50-302 50-302 50-302 50-302 50-302	6 6 6	General Electric Operating Plant Gwners	7712140146 7712190412 7712280547 7912130148	XPORTLIC XPORTLIC TOPREP TOPREP
	7912140239 7912180271	50-302 50-302	P	Graup	7912130152*	TOPREP
	7912180275* 7912180391	50-302 50-302	P	General Public Utilities - GPU Service Corp	7912040087	50-289 1
	7912180398* 7912190268 7912190429	50-302 50-302 50-302	R P J		7912040104 7912040345 7912050511 7912130243	50-320 P 50-287 I 50-287 I
	7912190795 7912240239 7912240243* 7912240245	50-302 50-302 50-302	0 8 8		7912260219 7912280477 7912280479 7912310446	50-289 I 50-289 T 50-289 T 50-320 P
	7912260254* 7912270575	50-302 50-302	F P	General Services Administration	7912040036*	40-341
	7912310010 7912310016 791231001B 7912310533	50-302 50-302 50-302 50-302	0 0 0 F	Georgia Power Co.	7912280007 7912040007 7912040007 7912040445 7912050150	40-341 50-321 Q 50-321 Q 50-424 A 50-321 P
Florida State Univ.	7912310536* 7912310540* 7912140483*	50~302 50~302 RES	F		7912050150 7912050155*	50-321 P 50-321 P
Florida, State of Florida, Univ. of, Gainesville Fox, Farr & Cunningham	7912280218 7912210058* 7912210058	PR 50~83 50~287	Q G		7912050155* 7912050440 7912050445*	50-321 P 50-364 S 50-366 S
Franklin Institute/Franklin Research	7912180246 7912120558	50-289 FOIA	ğ		7912050450 7912050457*	50-321 B 50-321 B
Genter Friends of the Earth	7912100352 7912100352	50-361 50-361	0		7912050533 7912050533 7912070445	50-321 P 50-321 P 50-366 B
	7912130061 7912130061 7912130453 7912140425	50-361 50-361 PR 50-224	6		7912070448* 7912100139 7912110055 7912110055 7912110320	50-346 S 50-321 H 50-321 G 50-321 G
Friends of the Filipino People Gage-Babcock Associates, Inc.	7912170007* 791228050B 7912110350* 7911190530*	50-70 50-275 50-574 50-322	6		7912110323* 7912110368 7912110372* 7912130384	50-321 S 50-366 S 50-366 S
General Atomic Co. (subs. of Gulf Gil Go.)	7912070226	71-6300			7912130392*	50-366 S
General Electric Co.	7912070360# 7912120012 7912030071 7912030215	FOIA PR 50-574 XPORTLI	c A		7912130394 7912130400* 7912130404 7912130408* 7912130412	50-366 S 50-366 S 50-366 S 50-366 S 50-366 S
	7912040213 7912060521 7912070391 7912100330* 7912110167*	TOPREP TOPREP TOPREP 50-3 40-7:344	P		7912130421* 7912130424 7912130426 7912130436*	50-344 S 50-321 B 50-321 B 50-321 B
	7912110386# 7912110532#	50-237 50-295	P	· ·	7912140236 7912140236	50-424 A 50-424 A
	7912120048	70-130B			7912140321	50-321 P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7912140321 7912140326# 7912140326#	50-321 50-321 50-321	<del>የ</del> የ የ	Hirata Valve Industry Co., Ltd., Kawaski Div.	7912210201* 7912210210*	GA999 GA999
	7912140382# 7912140382#	50-424 50-424	A	Hirschkop & Orad P.C. Hjelmfelt.D.C. Hodder.M.H.	7912200410* 7912180344 7912270147	50-339 A 50-346 M 50-369 G
	7912140429 7912140436* 7912140441 7912140448* 7912170301	50-321 50-321 50-366 50-366 50-424	8 8 8	Hoke: Inc. Homestake Mining Co. House of Rep.	7912270150* 7912140004 7912120046 7912280100 7912040126#	50-389 G XPORTLIC PROJ WASTE MOT 50-320 U
	7912170301 7912170306 7912170316* 7912170319 7912170321*	50-424 50-321 50-321 50-321 50-321	8 9 9 9 9 9 9		7912070256 7912120066* 7912120233* 7912120250* 7912120526*	50-70 G 50-498 U 50-289 U 50-289 U NUREG
	7912180430 7912180434* 7912180438 7912180443* 7912180635	50-321 50-321 50-366 50-366 50-366	R R R S		7912120535* 7912120546* 7912120574* 7912130206 7912130206	50-320 U PDR MISC 50-155 U 50-275 U 50-275 U
	7912180642* 7912210177 7912210181* 7912210181* 7912210340	50-366 50-321 50-321 50-321 50-424	8 0 0 0 B		7912140528 7912180468 7912180468 7912190107 7912190107	50-3 U 50-275 U 50-275 U 50-3 G 50-3 G
	7912210340 7912210344* 7912260221 7912260224* 7912260247	50-424 50-424 50-366 50-366 50-321	8 8 8		7912190107 7912190114* 7912190114* 7912190114* 7912190114*	50-3 0 50-3 0 50-3 0 50-3 0 50-339 A
	7912260249* 7912260265 7912260269* 7912270472 7912270477*	50-321 50-366 50-366 50-321 50-321	9 9 9 9 9		7912200351* 7912200692* 7912210030 7912210228* 7912270039*	50-339 A 50-367 U 50-275 U 50-275 U PDR MISC
	7912270482 7912270489* 7912270519 7912280485 7912280559	50-321 50-321 50-321 50-424 50-321	9 9 A F	House of Rep., Interior & Insular Affairs Houston Industries,Inc. Houston Lighting & Power Co.	7912280313*	50-320 U 50-320 U 50-498 A 50-445 M 50-445 M
	7912310415 7912310420* 7912310429 7912310430* 7912310432	50-321 50-321 50-321 50-321 50-366	9 9 9 F		7912050442 7912060040 7912060555 7912060560 7912070361	50-498 0 50-498 M 50-498 Q 50-498 A 50-498 A
Georgia. State of	7912310433# 7912310434# 7912310462 7912310468# 7912120168	50-366 50-366 50-366 50-366 PROJ	Я Я 9 8		7912070361 7912070370* 7912070370* 7912100471 7912120056	50-498 A 50-498 A 50-498 A 50-466 Q 50-466 Q
Gibbs & Hill, Inc. (subs. of Dravo Corp.) Gibbstd/Commonwealth Cos.	7912120315 7912120318* 7912120474 7912310136 7912180426*	50-584 50-584 50-584 REGOD 50-244	К К А Р		7912120067* 7912120249 7912120249 7912130313	50-466 0 50-445 M 50-445 M 50-498 M
Gillespie & Jones	7912260318 7912280517 7912280528* 7912120345 7912120352*	REGGD TOPREP TOPREP 50-382 50-382	9 6		7912140008 7912140008 7912140032 7912140148 7912140525	50-466 G 50-466 G 50-466 G 50-466 G 50-466 G
Goldberg, Fieldman & Letham, P.C. Goslin-Birmingham Mfg. Co. Gould, Inc. Greene County, NY Gulf Muclear, Inc.	7912190232 7912040352* 7912120278* 7912050451* 7912310032*	50-348 50-29 94999 50-549 PRM	м Р О		7912170046 7912170246 791221018B 7912210209 7912210211* 7912210286	50-466 G 50-466 A 50-466 B 50-466 B 50-466 G
Gulf Oil Corp. Gulf States Utilities Co.	7912070300* 7912050353 7912050353 7912050368*	FOIA 50-458 50-458 50-458 50-458	A A A	Hauston, Univ. of	7912260357 7912260357 7912270369 7912280630 7912120310*	50-445 M 50-445 M 50-498 A 50-498 M CONTRACT
		50-458 50-458 50-458 71-7033 50-219	g g A P	Huber, Magill, Lawrence & Farrell Hunton & Williams	7912120040 7912060074 7912130317 7912140148 7912140172	50-396 0 50-322 0 PR 50-338 0 50-338 0
		50-219 	P .	Hydro-Engineering ITT Grinnell ITT Grinnell Industrial Piping, Inc. (subs. of ITT Grinnell)	7912170143 7912040333 7912200044 7912240104*	40-2259 71-9035 XPORTLIC QA999
					7912260125* 7912260138*	94999 94999
				Idaho National Engineering Laboratory	7912260141* 7912140461*	GA999 RES
					•	
					1.	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	٧	AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGOR	
	791214046B=	REB		28.04.241. Bept. 01. 0.0. 1400-3	7912140423*	RES	
llinois Power Co.	7912140505# 7912040278 7912050493	RES 50~461 50-461	F A	111 ac. 121 r Day 11 ar	7912190086 7912190170 7912190208	40-1341 50-275 40-8745	A
llinois. State of	7912030024 7912060028	40-2061 50-367	G.	Interior,Dept.of. Bureau of Indian Affairs Interior,Dept.of. Bureau of Land	7912130133	40-8721	
	7912120557 7912120557 7912170180± 7912190217	50-599 50-599 40-2061 40-2061	G G	211001.201.0200.000	7912190212 7912180085 7912310145	40~8745 40~1341 40~8745	Р
	7912310340 7912310340	50-599 50-599	G G	Interior, Dept. of, Geological Survey	7912190791 7912310515	50-206 40-8745	r
n-Situ Consulting ndiana & Michigan Electric Co.	7912190280* 7912040254 7912040404	40-8200 50-314 50-316	p P	International Atomic Energy Agency (Austria)	7912210160+	XPORTLIC	
	7912110308 7912110312 7912110312	50-315 50-315 50-315	P P	lowa Electric Light & Power Co.	7912210173* 7912040350 7912050472 7912050505	XPORTLIC 50-331 50-331 50-331	F
	7912120404 7912120404 7912140043	50-315 50-315 50-315	P P Q		7912060364 7912070141 7912110340	50-331 50-331 50-331 50-331	0 P S Q
	7912140504* 7912170018 7912180390 7912180390	FOIA 50-315 50-315 50-315	P P P		7912130229 7912140470 7912140479	50-331 50-331 50-331	9 9
	7912180436 7912190560 7912200036	50-314 50-315 50-315	P P Q		7912140482# 7912140489# 7912170213 7912170219#	50-331 50-331 50-331	8 8 8
	7912200034 7912200509 7912270258 7912270284	50-315 50-316 50-316 50-316	e P P		7912170224 7912170231* 7912180518 7912180614 7912190398	50-331 50-331 50-331 50-331 50-331	8 8 8 8 R
ndiana & Michigan Pawer Co.	7912270431 7912040257 7912040257 7912040365	50-315 50-315 50-315	P P S		7912190405* 7912200683 7912280611 7912310369	50-331 50-331 50-331 50-331	R G G P
	7912040371* 7912040375 7912040378* 7912040384	50-315 50-316 50-316 50-315	9 9	Iowa Public Interest Research Group	7912130098 7912130098 7912140034	50-599 50-599 50-599	0
	7912040390+ 7912040424 7912040430+ 7912040489	50-315 50-316 50-316 50-315	8 8 9		7912140034 7912170403 7912180123 7912060307	50-599 FOIA FOIA NUREG	•
	7912070109 7912070109 7912070351 7912070356*	50-315 50-315 50-316 50-316	0 9 5	Iowa, State of Isham, Lincoln & Beale	7912030004 7912030539 7912050683 7912110503	50-956 50-456 50-445 50-295	9 H
	7912070371 7912070377* 7912070378	50-315 50-315 50-316	8 8 8		7912130057 7912130278 7912130328 7912130337	50-445 PR 50-445 50-445	۲ ۱
	7912070379* 7912100277 7912100286* 7912100291*	50-316 50-316 50-316 50-316	5 5 5		7912130337 7912130341* 7912130341*	50-445 50-445 50-445	
	7912130312 7912130322* 7912130330 7912130372*	50-316 50-316 50-315 50-315	9 9 9		7912130366# 7912130378# 7912130378#	50-445 50-445 50-445	1
	7912130380* 7912140349* 7912140350*	FOIA FOIA FOIA	9		7912130396 7912140192 7912170008 7912170058	PR 50~599 50-155 50-155	
	7912140354* 7912170238 7912170252* 7912170257*	50-315 50-315 50-315	5 6		7912170179 7912180230 7912190015 7912190162	50-155 50-295 50-295 50-329	
	7912170240 7912170270 7912170271* 7912170274*	50-316 50-315 50-316 50-315	S R S R		7912240297 7912270049 7912270049 7912270101	50-445 50-599 50-498	, . , .
75 71 76	7912200687 7912200687 7912270337 7912270590	50-315 50-315 50-316 50-316			7912270104 7912280226 7912280226	50-445 50-599 50-599	) )
	7912270598* 7912270602* 7912270604	50-316 50-316 50-315	8 8	Isotope Products Laboratories	7912280257* 7912280257* 7912280670 7912310339 7912180003	50-599 50-899 50-443 50-329 XPORTL	? 3 ?
	7912280521 7912280521 7912280524*		R	JI Case Co. Jersey Central Power & Light Co.	7912180059 7911200385 7912030248*	71-206 50-219 50-219	5. ?
Industrial Bio-Test Laboratories, Inc. Institute of Electrical & Electronic Engineers	7912310345 7912310350# 7912190112# 7912310031				7912040327 7912040331* 7912040334*		7

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJEC CATEGO	
	7912040334* 7912040358 7912040506 7912070323 7912070327	50-219 50-219 50-219 50-219 50-219	Р Р 8 Р	LeBoeuf, Lamb, Leiby & MacRae	7912190544 7912210332 7912210343* 7912030198 7912130267	RES 50-206 50-206 50-341 PR	P P K
	7912070326* 7912070333 7912070334 7912070340* 7912070345*	50-219 50-219 50-219 50-219 50-219	8888		7912140147 7912200522 7912270034 7912270345 7912280198	50-244 50-244 FOIA 50-244 50-244	Н 9 Н Р
	7912070350 7912070359 7912070364* 7912070365* 7912070404*	50-219 50-219 50-219 50-219 50-219	8 8 9	League of Women Voters of San Luis Obispo.CA Leed. Robert M.	7912190045* 7912040115 7912040115 7912040125* 7912040125*	50-275 50-522 50-522 50-522 50-522	H G G G G
: :	7912110260 7912110315 7912110317* 7912140209 7912140417	50-219 50-219 50-219 50-219 50-219	5 8 8 8 8	Legal Aid Society of Clermont County,OH Lebigh Univ.	7912110267 7912140025 7912310494 7912280682 7912180165	50-522 50-522 50-522 50-522 FOIA RES	G G 9
	7912140419* 7912180401 7912190564 7912190631 7912190683*	50-219 50-343 50-219 50-219 50-219	P G P P	Levy, Gutman, Goldberg & Maplan Lincoln National Life Insurance Co. Lockheed Missiles & Space Co. (subs. Lockheed Aircraft Corp.)	7912070280 7912070284 7912180255 7912140541	FOIA FOIA FOIA 71-159	
	7912210304 7912210310* 7912210338 7912210354* 7912270384	50-219 50-219 50-219 50-219 50-219	R R S S P	Long Island Lighting Co.	7912060079*  7912120040 7912120181 7912130015 7912130451	50-322 50-576 50-322 50-322 50-322	9 9 9
Jo Daviess County Ad Hoc Committee on Nuclear Energy Information Jonas, Broom & Clifford Justice, Dapt of	7912270544 7912280015 7912130066 7912240097 7912100307	50-219 50-219 50-599 50-133 50-445	P G G H	Los Alamos Scientific Laboratory	7912270517 7912120120 7912140125 7912190113	50-322 PROJ NUREO 70-754	Q Q
	7912100307 7912100307 7912100307 7912100332 7912120043	50-445 50-445 50-445 50-478 50-445	 M M M	Louisiana Consumer's League, Inc. Louisiana Power & Light Co.	7912260213 7912260213 7912260213 7912060561 7912070145	50-382 50-382 50-382 50-382	6 6 8
	7912170068 7912170138 7912190140 7912190140 7912190140	50-445 50-445 50-445 50-445 50-445	ስ1 ለ3 M M M		7912070150 7912070392 7912070455 7912100326 7912170209 7912170217	50-382 50-382 50-382 50-382 50-382 50-362	55 55 65 65
KBI Tube Div.	7912190140 7912270123 7912310137 7912040037 7912130040	50-445 50-445 50-445 XPORTLIC XPORTLIC		Louisiana, State of	7912170357 7912170362 7912270274 7912280140 7912120296 7912110238	50-382 50-382 50-382 50-382 PDR MISO REGOD	G A G
KMC, Inc. Kansas Gas & Electric Co.	7912210053 7912050321 7912040542 7912070140 7912070174	NUREC 50-482 50-482 50-482 50-482	G F S	Lowenstein, Newman, Reis, Axelrad & Toll	7912180011# 7912180579 7911300021 7912030007 7912050092	CONTRACT 50-223 50-445 50-522 50-445	J M O M
Kansas, State of	7912070175* 7912270280 7912180060* 7912180067* 7912260002	50-482 WASTE MOT WASTE MOT NUREG			7912050092 7912100471 7912110439 7912130257 7912130313	50-445 50-466 50-250 50-344 50-478	 0 M 0
Kerr-McGee Chemital Corp. (subs. of Kerr-McGee Corp.) Kerr-McGee Corp. Keystone Center for Continuing Education	7912070009 7912030017 7912030103 7912190131 7912100452*	40-2061 40-8027 PRDJ 40-8727 CONTRACT			7912130481 7912140177 7912140179 7912140184 7912140193	PR 50-387 50-446 50-445 50-446	G G M
Kinetic Research, Inc. Kirshen, A.H.	7912190415 7912050599		G		7912140525 7912170246	50-466 50-466	G G
Knopp & Andrews Kadner, J.L.	7912060612 7912060066 7912130117	50-289	G G		7912180113 7912190072 7912190104	50-344 50-466 50-466	G G
	7912130117 7912130120* 7912130120* 7912130128 7912130128	50-579 50-579 50-579	G G G		7912240284 7912270091 7912280430 7912280449 7912310514	50-444 50-344 50-498 50-445 50-498	0 M M
Korea. Republic of (South Korea) Kudzu Alliance Lakeshore Citizens for Safe Energy	7912140295 7912140295 7912200402 7912120224 7912130478	50-599 XPORTLIC 50-400	е е н	MPR Associates, Inc.	7912310514 7912310519* 7912310819* 7912040537* 7912040019	50-498 50-498 50-498 50-255 50-309	M M Q Q
Lawrence Livermore Laboratory	7912140535 7912050005 7912120139	50-266 Nureg Nureg	G		7912040057 7912040325 7912040328*	50-309 50-309 50-309	G S S

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	,	AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT	<u> </u>
	7912120536 7912130086 7912140016 7912140496 7912140501*	50-309 50-309 50-309	0 0 0 5 8		7912130110 7912130308 7912130367 7912130435 7912130441#	50-267 50-267 50-320 50-320	0 8 P P
	7912170053 7912170202 7912180028 7912180387 7912180389*	50-309 50-309 50-309	G G G R R		7912130479* 7912170220 7912180254 7912180257* 7912180428	50-289 50-289 50-289 50-289 50-320	6 6 6
	7912180470 7912180554 7912180557* 7912280222 7912310472	50-307 50-309 50-309	P 8 6 P Q		7912180483 7912180491* 7912180492* 7912180496 7912180921	50-320 50-320 50-320 50-289 50-289	P P G H
Maine, State of  Marubeni America Corp. (subs. of Marubeni	7912100386* 7912190005 7912190009*		g G		7912180521 7912200365 7912200368 7912200513 7912260100	50-289 50-289 50-289 50-289 50-289	H R R P G
Corp. )	7912120576* 7912130129* 7912260145* 7912260168*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC			7912260293 7912270082 7912270084 7912270202 7912270249	50-287 50-287 50-445 50-320 50-320	0 0 M P P
Maryland, State of  Massachusetts Institute of Technology Massachusetts Wiidlife Federation	7912260174* 7912170116 7912280359 7912060146* 7912120358	50-317 50-320 50-20 50-471	P H Q G		7912270253* 7912270323 7912270328* 7912270343 7912270523	50-320 50-289 50-289 50-320 50-289	P 55 52 P
Massachusetts, State of	7912040481 7912040481 7912070142 7912070146* 7912070152*	50-471 50-471 50-471 50-471 50-471	e e e		7912280437+ 7912280454 7912280459+ 7912280477 7912280599	50-320 50-320 50-320 50-289 50-320	P G G T P
	7912070156* 7912110276 7912110460 7912110477 7912110477	50-471 50-443 50-443 50-443	6 6 6	Miami Valley Power Project	7912310196 7912310337 7912310378 7912310382 7912120002	50-287 50-320 50-287 50-287 50-358	6 8 8 8 6
Mathematical Applications, Inc. Natheson Gas Products Matthews, Nowlin, Macfarlane & Barrett	7912180152 7912180002 7912060088 7912270048 7912280118	RES XPDRTLIC 50-498 50-498	н <b>н</b> н	Michigan, Univ. of	7912130033 7912030158* 7912050034 7912050056 7912110004*	50-358 50-329 REGOD REGOD CONTRACT	e c
Mayer, Brown & Platt McCutchen, Doyle, Brown & Emerson	7912120048 7912130154 7912030118 7912100469 7912100477 7912140009	70-1308 70-1309 PROJ PROJ PROJ		Mid-Hudson Nuclear Opponents, Inc.	7912120266* 7912130079 7912140381 7912200270 7912200276*	CONTRACT REGOD 50-294 50-3 50-3	T J G G
McGrath, E. J. McGraw-Hill Publications Co. McKinley Area Council of Govts, Gallup, N	7912140020# 7912170251 7912280684 7912140171	PROJ PROJ WASTE MG FOIA 40-8725	Ŧ	Miller, Pitt & Feldman, P.C. Minerals Exploration Co. (subs. of Union Oil Co. of California) Minnesota, State of	7912190404 7912170243 7912130582 7912130590* 7912110542*	FOIA 40-8348 PR PR 50-275	ı G
Memphis State Univ.	7912100394* 7912130615 7912130628* 7912210297 7912050599	50-538 50-538 50-538 50-538 50-285	1 8 8 0	Minnesota, Univ. of, Minneapolis Mississippi Power & Light Co.	7912030193 7912030193 7912030194# 7912030194# 7912060497	50-416 50-416 50-416 50-416 50-416	CCCCK
Metropolitan Area Planning Agency Omaha,NE Metropolitan Edison Co.	7912060612 7912030170 7912030174 7912040043	50~285 50~320 50~287 50~287	Ç F P S		7912060497 7912060500* 7912060500* 7912100339 7912130524	50-416 50-416 50-416 50-416 50-416	K K C
	7912040150* 7912050320 7912050325* 7912060340 7912040344	50-320 50-289 50-289 50-289 50-289	P P P P		7912130528 7912130528 7912130532# 7912130532# 7912190555		93 93 94
	7912060349* 7912060355* 7912060653* 7912070136 7912070136	50-289 50-289 50-289 50-320 50-320 50-289	С Е Е Р		7912190503 7912190511 7912190511 7912190533 7912190533	50-416 50-416 50-416 50-416 50-416	8 8
	7912100328 7912100341 7912100341 7912110384 7912120335	50-287 50-289 50-289 50-289	н 6 8 8		7912190702 7912310401 7912310401 7912310408: 7912310408:		K K
	7912120401 7912120401 7912120414 7912130034 7912130085	50-289 50-289 50-289 50-289 50-289	P P G	Mississippians Against Disposal Missouri, State of Missouri, Univ. of, Columbia	7912130261	PR 50~492 50~492	2 0

AUTHOR AFFILIATION	ACCEBBION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Missouri, Univ. of, Rolla	7912040247 7912070459 7912200344 7912200452 7912200458*	50-123 F 50-123 P 50-123 F 50-123 P 50-123 P		Neighbors for the Environment Neutron Products, Inc. Nevada, State of	7912310467* 7912130255 7912200662 7912110170 7912280645*	50-298 B PR 71-6400 PR 27-10
	7912200460# 7912200463#	50-123 P 50-123 P		New England Coalition on Nuclear Pollution	7912130469 7912040367	PR 50~443 H
Mitsubishi International Corp. (subs. of Mitsubishi Corp.)	7912200465* 7912200469* 7912110295	50-123 P 50-123 P XPORTLIC		New Hampshire, State of New Jersey, State of	7912130570 7912130578* 7912050177	PR PR 50-272 0
Mitsvi & Co., Ltd.  Mobil Gil Corp. (subs. Mobil Corp.)	7912110297* 7912030058 7912200283 7912310549 7912120247	XPORTLIC XPORTLIC XPORTLIC XPORTLIC PROJ			7912130279 7912130564 7912130567* 7912140534 7912190109*	PR PR PR 50~320 H 50~363 H
Monsento Co. Morrison Knudsen Co., Inc.	7912120254* 7912310187 7912200310 7912260036 7912260036	PR PROJ XPORTLIC 71-60 71-60		New Mexico, State of	7912050574 7912050580# 7912050585* 7912190350 7912200446	WASTE MOT HASTE MOT HASTE MOT WASTE MOT WASTE MOT
Movement for a Free Philippines Musick, Hillamson, Schwartz, Leavenworth & Cope, P.C.	791224003B* 791224003B* 7912030023 7912180332	71-60 71-60 XPORTLIC 50-338 H		New Paper Providence,RI New York State Electric & Gas Corp. New York. State Univ. of, Buffalo	7912280168* 7912280182* 7912280660 7912120040 7912120144*	WASTE MOT WASTE MOT FDIA 50-596 O 50-57 Q
Myer, Bauman, Stroup & Flack N. Industries, Inc. N. Industries, N. Nuclear Div. NORCA Machinery Co.	7912270418 7912030120 7912270002 7912050544 7912120462#	40-8677 71-7010 XPORTLIC XPORTLIC REGOD		New York, State of	7912040644 7912070319* 7912130089 7912130348 7912130352*	50-3 G FOIA NUREG PR PR
NUS Corp.  Nation Institute National Academy of Public Administration Foundation	7912120023 7912190458 7912210383•	FOIA CONTRACT		Newberry Township, York Haven,PA	7912140018 7912170227 7912260282 7912180246	50-596
National Council on Radiation Protection & Measurement		ACRS		Niagara Mohauk Power Corp.	7912040277	50-220 G
National Evaluation Systems, Inc. National Wildlife Federation	7912170377 7912040603 7912040675	FDIA PROJ PROJ			7912040315 7912040346 7912040462 7912040469	50-220 P 50-220 P 50-220 P 50-220 P
Natrona County.HY Natural Resources Defense Council	7912190484 7912060608 7912110432 7912130398	40-8721 70-2623 70-2623 PR			7912050492 7912100208* 7912130460	50-220 P 50-220 G PR
	7912130510 7912140164	PR FDIA			7912140157 7912140282 7912170168	50-220 Q 50-410 Q 50-220 Q
	7912170140 7912180265 7 <del>9</del> 12270031	FOIA FOIA FOIA			7912180539 7912180547 7912200313*	50-220 F 50-220 P 50-220 0
Navy, Dept. of	7912180187# 7912190251 7912190284# 7912190473 7912190479#	71-356 71-357 71-357 71-358 71-358			7912210179 7912210377 7912260267 7912260268*	50-220 F 50-220 P 50-220 R 50-220 R
New Book of Second Mark	7912200146 7912200154* 7912210429*	71-199 71-199 71-364			7912270259 7912270324 7912270330 7912270379	50-220 S 50-410 A 50-220 P
Navy, Dept. of, Forces Afloat	7912180137 7912180180	71-360 71-358			7912270507 7912280019	50-220 P 50-220 0
Navy, Dept. of, Naval Investigative Service Navy, Dept. of, Naval Nuclear Power Unit Navy, Dept. of, Naval Research Laboratory Rebraska Public Power District	7912180140# 7912210418 7912170024 7912040251	71-360 71-364 NUREQ 50-298 P		Niles Steel Tank	7912310427 7912180654 7912180657*	50-220 0 71-352 71-352
	7912070329 7912120259	50-278 P 50-278 P		North Anna Environmental Coalition North Carolina State Univ.	79121900BB* 7912130432 7912310223	50-280 0 50-111 P 50-297 0
	7912130387 7912130389# 7912130391	50-278 B 50-278 B 50-278 B		North Carolina, State of	7912120446 7912180217*	PROJ 50-488 G
	7912130393* 7912140233	50-298 B 50-298 P		North Carolina, Univ. of Northcutt Ely	7912200362# 7912190552 7912260360	50-337 A RES 50-445 M
' 	791214024B 7912140395 7912140399*	50-278 Q 50-278 R 50-278 R		Northeast Nuclear Energy Co. (subs. of Northeast Utilities)	7712040421	50-336 B
And the second s	7912190150* 7912190549	50-278 P			7912040426* 7912140022 7912140227	50-334 B 50-423 G 50-423 A
	7912200542 7912310435	50-298 P 50-298 B			7912140257 7912140267 7912140267	50-423 G 50-336 G
	7912310437# 7912310438	50-278 B		Northeast Utilities	7912030206 7912040225	50-245 P 50-245 P
	7912310440# 7912310442 7912310444#	50-278 9 50-278 9 50-278 5			7912040396 7912040401# 7912040407	50-336 8 50-336 8 50-336 8
	7912310447 7912310450#	50~298 8	4		7912040413#	50-336 B
	7912310459	50-298 6	4.		7912050502 7912080504	50-334 P 50-245 P

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	7912040505 7912040505 7912070343 7912070344*	50-213 F 50-213 F 50-245 E 50-245 E 50-336 S	• • •		7912180640* 7912190167 7912190354 7912190801 7912200369	50-263 50-263 50-282 50-263	R F G P
	7912100284 7912100284 7912100294*	50-334 S 50-213 F 50-213 F 50-213 F 50-215 S	) )		7912200385 7912200414 7912200432 7912270333 7912270340	50-263 50-282 50-263 50-263	P P 8 P
	7912110305 7912120027 7912120390	50-245 S 50-334 F REGOD 50-213 F 50-213 F	÷ >		7912270444 7912270491 7912270498* 7912270540 7912270545*	50-282 50-263 50-263	8 8 8 P
	7912130321 7912130321 7912130321	50-213 F 50-213 F 50-213 F	P		7912270552* 7912270568 7912270580* 7912280041 7912280046	50-263 50-263 50-263 50-263 50-263	0 8 8
	7912130455 7912130455 7912130459	50-213 5 50-336 5	F		7912280053 7912280067 7912310365 7912310422 7912310428*	50-263 50-282 50-263 50-263 50-263	0 0 F 8 5
	7912170228 7912180279 7912180363	50-213 5 50-245	g P R R	Nuclear Assurance Corp	7912310475 7912310475 7912310478* 7912310478* 7912310488	50-282 50-282 50-282 50-282 71-6698	ខ្លួន
	7912180392 7912180403* 7912180487 7912180597 7912180591*	50-334 50-334 50-334	R R G S S	Nuclear Dynamics	7912120135 7912120137* 7912120150* 7912120153* 7912210112	40-8663 40-8663 40-8663 40-8663 40-8663	
	7912180589		s s	Nuclear Engineering Co., Inc. (subs. of Teledyne, Inc.)	7912130045	71-6144	
	7912180601* 7912190261 7912190261	50-213	P P	Nuclear Engineering Co., Inc., (subs. of Teledyne, Inc.)	7912180444	27-37	
	7912190409 7912190414*	50-336 50-336	P P	ieleddiw. III	7912180448* 7912260290 7912280674*	27-39 27-39 27-48	
	791221014B 7912210187 7912210282 7912260276	50-336 50-336	F p P	Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.)	7912310379 7912060213*	71-6058 50-201 70-143	û
	7912270293 7912270318	50-245 50-213	P P	Nuclear Support Svcs Inc. O'Connor & Hannan	7912260175* 7912200304 7912050466	REGGD FOIA	
	7912270515 7912270542* 7912280004 7912310376	50-245 50-245 50-336 50-245	8 9 P	Oak Ridge National Laboratory	7912110442 7912110465 7912110509 7912120033 7912120190	NUREQ RES RES NUREQ NUREQ	
Northern Indiana Public Service Co.	7912310380 7912310543 7912030184 7912030186 7912110254	50-423 50-336 50-367 50-367	A P R R		7912140186 7912140206 7912140427* 7912140467	NUREG NUREG RES RES	
Northern States Power Co.	7912110364 7912140234 7912310466 7912030197	50-367 50-367 50-367 50-306 50-306	R R R S		7912170167 7912170167 7912170174 7912170422 7912180143	RES RES RES RES	
	7912030202* 7912040201 7912040242 7912040249* 7912050671*	50-282 50-263 50-263 50-282	P P G	Ocean County, NJ	7912180700 7912190546 7912190561 7912130309 7912110108*	ORG RES RES PR ACRS	•
	7912070332 7912070431 7912070434 7912070440* 7912100369	50-282 50-263 50-282 50-282 50-263	\$ F Q <del>Q</del> F	Office of Management & Budget  Ogle Petroleum, Inc.	7912270099# 7912130402 7912200616 7912210186		5 5
	7912110307	50-202 50-263	P P	Ohio Edison Co. Ohio, State of	7912120340 7912130311	50-580 PR	
	7912110310 7912120244 7912120244	50~282 50~282	F F	Omaha Nondestructive & Metallurgical	7912140143	71-160	i
	7912120364 7912120376* 7912140259 7912140367	50-263 50-263 50-263	የ የ የ የ	Testing, Inc. Omaha Public Power District	7912030212 7912070406 7912070410 7912070443	50-285	6 6 5 6 6 P
	7912140374* 7912170304 7912180420	50-263	F R		7912070464 7912110360 7912110366 7912130416	50-285 ≠ 50-285	5 S
	7912180628* 7912180628* 7912180634* 7912180636*	50-282 50-282	R R		7912130460 7912140347	PR	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT		AUTHDR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	
	7912140352* 7912140397 7912170195 7912170363 7912190501	50-265 50-285 50-285 50-265 50-265	R P G G H		7912270245 7912270298 7912270298 7912270308* 7912270308*	50-387 50-387 50-387 50-387 50-387	A 9 9 9 9
	7912190545 7912190588 7912210105 7912270270 7912270376	50-285 50-285 50-285 50-285 50-285	P F G P P	Pennsylvania State Univ. Pennsylvania, State of	7912130489 7912050232 7912130175 7912170368 7912180162	PROJ 50-289 50-289 PRM 50-289	G G
cavage.Mark egon, State of	7912120019 7912120125 7912050525 7912120073* 7912130523	50-250 50-250 50-344 CONTRACT PR	H G P	People Against Nuclear Energy	7912180193 7912060238 7912060242* 7912130026 7912260362	50-289 50-289 50-289 50-289 50-289	0 0 0
stershell Alliance, Inc. C Energy Analysis Co. cific Gas & Electric Co.	7912120345 7912120352* 7912180288 7912030038 7912030118	50-382 50-382 FOIA 50-275 FROJ	G G	Perkins, Coie, Stone, Olsen & Williams	7912030007 7912070355 7912070472* 7912100473 7912170020	50-522 50-522 50-522 50-522 50-522	0 0 0 0
	7912040452 7912040498 7912050347 7912050351* 7912050360*	50-275 50-275 50-133 50-133 50-133	A G G		7912170020 7912170041# 7912170041# 7912170048# 7912170048#	50-522 50-522 50-522 50-522 50-522	0000
	7912050364* 7912050369* 7912060251 7912100469 7912100477	50-133 50-133 50-133 PROJ PROJ	G G	Pharmaco Nuclear, Inc. Philadelphia Electric Co.	7912250039 7912120482 7912040295 7912040405 7912050105*	50-522 FOIA 50-278 50-278 50-277	9 5 5 9
	7912110322 7912110322 7912110371 7912120317 7912120317	50-275 50-275 50-275 50-275 50-275	A A H A		7912060044* 7912070151* 7912070349 7912120325 7912120343	50-277 50-352 50-277 50-277 50-277	0 0 8 P 8
	7912120346 7912120350* 7912130271 7912130280* 7912140009	50-133 50-133 50-275 50-275 PROJ	R R A A		7912120347* 7912120429 7912120435* 7912120511 7912130180	50-277 50-277 50-277 50-352 50-278	8 8 9 9
	7912140020* 7912140497* 7912170251 7912190002* 7912190614	PROJ 50-275 PROJ 50-133 50-275	9 9		7912130417 7912140344 7912140344 7912140359* 7912140359*	50~278 50~277 50~277 50~277 50~277	9 R R R
	7912240280 7912260280 7912260284# 7912260284# 7912270078#	50~275 50~275 50~275 50~275 50~275	К К К С		7912140455 7912140463# 7912170171 7912170240 7912180010	50-277 50-277 50-277 50-277 50-278	9 0 0
ific Legal Foundation American World Airways, Inc ameter, Inc.	7912270276# 7912310184 7912130533 7912200116 7912100105*	5()-344 REGOD PR 71-96 CUNTRACT	F	`	7912180504 7912180546 7912180558 7912180586 7912180591*	50-278 50-278 50-278 50-278 50-278	8 8 8 8
sons, Beble & Latimer Afinder Mines Corp.	7912280479 7912060183 7912070277 7912170282 7912170284	FOIA XPORTLIC PROJ 40-2239 40-2259			7912180606 7912180606 7912180644 7912180644 7912180647#	50-277 50-277 50-277 50-277 50-277	۴ ۹ 8
i Munroe Hydrautics, Inc.	7912280295* 7912280311* 7912280331* 7912080320 7912080327#	40-2259 40-2259 40-2259 XPORTLIC XPORTLIC			7912180647* 7912190566 7912270393 7912270393 7912270497	50-277 50-277 50-277 50-277 50-278	9 9 9
nsylvania Power & Light Co.	7912120205* 7912140118 7912040351 7912040507 7912040507	50-387	9 9 9		7912270510* 7912270596 7912280031 7912280561 7912310191	50-278 50-277 50-277 50-277 50-277	5 9 9 P 8
	7912050506 7912050504 7912120019 7912120384 7912120384	50-387 RECOD 50-387	5 9 K K	Pailippines  Pick Instrument Products Co., Inc.	7912310198 7912310322 7912050392 7912050394* 7912180338	REGGD 50-277 50-574 50-574 71-359	9 G G
	7912120387* 7912120387* 7912130246 7912130347* 7912140265	50-387 ( 50-387 ( 50-387 (	K G B B	Pickard Lowe & Garrick, Inc. Placer Amex.Inc. Plateau Resources, Ltd.	7912180359* 7912280232* 7912280487* 7912130340 7912280082	71-359 50-244 WASTE MG 40-7869 40-8674	P T
	7912140275 7912140275 7912240333* 7912260333* 7912270245	50-387 ( 50-387 (	3 3	Pollution Environmental Problems Porter-Gerti Consultants, Inc. Portland Cement Association	7912280089* 7912280108* 7912180147 7912130338* 7912110036*	40-8674 40-8674 FOIA 50-320 CONTRACT	υ

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEGOR'	Υ
Portland General Electric Co.	79120403B0 791205047B 7912060496 7912070405 7912070452	50-344 50-344 50-344 50-344 50-344	P P F F		7912130291* 7912130449 7912130454* 7912130460 7912130515	50-3 50-333 50-333 PR 50-284	р 5 6
	7912110302 7912110341 7912110342* 7912110344* 7912120319	50-344 50-344 50-344 50-344 50-344	8 8 8		7912130545 7912130547* 7912130550* 7912140293 7912140298	50-333 50-333 50-333 50-286 50-333	P P G
	7912120321* 7912130257 7912140353 7912140361 7912140367*	50-344 50-344 50-344 50-344 50-344	C G P R R		7912140438 7912140449* 7912170176 7912170214 7912170296	50-333 50-333 50-286 50-333 50-286	S 9 0 0 P
	7912180120* 7912180127* 7912180549 7912180618 7912180622	50-344 50-344 50-344 50-344 50-344	6 6 8 8		7912180543 7912180549 7912180571 7912180573 7912180582*	50+286 50-286 50+286 50-333 50-286	P P P S
	/912180627 7912180632* 7912190003* 7912190379 7912210162*	50-344 50-344 50-133 50-344 50-206	8 0 P		7912180594 7912180599* 7912190418 7912190418 7912190513	50-333 50-333 50-286 50-286 50-286	9 H H
	7912210366 7912270181 7912270183 7912270269 7912270439	50-344 50-344 50-344 50-344 50-344	P P P F		7912190572 7912200342 7912200349* 7912210316 7912210322*	50-286 50-286 50-286 50-333 50-333	P R R S
	7912280491 7912280518 7912280525* 7912280535* 7912280478*	50-344 50-344 50-344 50-344 50-344	P P P Q		7912210327 7912210336* 7912260053 7912260057 7912270267	50-333 30-333 50-333 50-333 50-3	5 0 0 P
Potomac Alliance	7912310516 7912310520* 7912310527* 7912120174* 7912120174*	50-344 50-344 50-344 50-338 50-338	P P C G		7912270275* 7912270305 7912270315 7912270335 7912270353	50-3 50-286 50-286 50-286 50-286	የ የ የ የ
	7912120178* 7912120178* 7912120184* 7912120189* 7912120197*	50-338 50-338 50-338 50-338 50-338	G G G G		7912270447* 7912270455* 7912270460* 7912270553 7912270562*	50-286 50-286 50-286 50-286 60-286	9 9 9
Potomac Rosearch, Inc. Power Authority of the State of New York	7912110185* 7912030168 7912030181 7912040200 7912040206*	CONTRACT 50-333 50-286 50-286 50-286	P F P		7912280005 7912280504 7912280504 7912280612 7912310328	50-286 50-286 50-286 50-286 50-286	0 H H P S
	7912040308 7912040313* 7912040319 7912040321* 7919040367	50-333 50-333 50-286 50-286 50-286	5 5 5 5 5	Power Engineering Society President of US & Executive Offices President's Commission on the Accident at Three Mile Island	7912310367 7912280654 7912180253* 7912070006	50-286 RECOD PER MIS 50-320	Q C P G
	7912040369* 7912040388 7912040482 7912040500 7912050084*	50-286 50-286 50-286 50-333 50-333	8 8 8 P 0	Public Interest Law Center of Philade]ph ia Public Interest Research Group Public Law Utilities Group Public Service Co. of Colorado	7912130332 7912200025 7912040216 7912040221*	PRM 50-382 50-267 50-267	G P
	7912060526 7912060528* 7912070397 7912100314 7912110250	50-286 50-286 50-286 50-333 50-333	P P G R		7912040296 791204029B* 7912040320 7912040323* 7912040326	50-247 50-247 50-247 50-247 50-247	១ ១១១១
	7912110256* 7912110277 7912110282* 7912110328 7912110329*	50-333 50-333 50-333 50-333 50-333	R 9 9 9		7912040330* 7912040332 7912040335* 7912040337 7912040341*	50-267 50-267 50-267 50-267 50-267	8 5 8 8 9
	7912110332 7912110333* 7912110343 7912110347* 7912110355	50~284 50-286 50-333 50-333 50-333	8 8 8 8		7912040363* 7912040363* 7912040400 7912040406* 7912040429	50-267 50-267 50-267 50-267 50-267	មា ១១១១១១
	7912110359* 7912120003 7912120128 7912120421 7912120457	50-333 50-333 50-333 50-333 50-333	6 6 7 7		7912040433* 7912110316 7912120324 7912120336* 7912120338	50-247 50-247 50-247 50-267 50-267	9 9 8 9
	7912120460* 7912120461* 7912120504 7912130200 7912130291*	50-333 50-333 50-333 50-333 50-3	P G G P		7912120341* 7912120404 7912140331 7912140335*	50-267 50-267 50-267 50-267	B R R

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	
	7912170201 7912170204 7912180062 7912180045* 7912180246	50-267 50-267 50-267 50-267 50-267	0 9 9 9		7912040511 7912040515* 7912040521 7912040521 7912040524*	50-272 50-272 50-272 50-272 50-272	R R R R
	7912180413 7912180429* 7912180500 7912180503* 7912180509	50-247 50-247 50-247 50-247 50-247	R R R R		7912040524* 7912050422 7912050429* 7912050487 7912050487	50-272 50-272 50-272 50-272 50-272	R 8 F F
	7912180513# 7912180595 7912180596 7912180610# 7912190580	50-267 50-267 50-267 50-267 50-267	8 8 9		7912050488* 7912050488* 7912060318 7912060329* 7912060335*	50-272 50-272 50-272 50-272 50-272	ե Ե Է
	7912210098 7912210373 7912210376* 7912270233 7912270426	50-267 50-267 50-267 50-267 50-267	Q P P S		7912060339* 7912070423 7912110296 7912110296* 7912130296	50-272 50-272 50-272 90-272 PR	6 8 8
	7912270433* 7912280562 7912310074 7912310175 7912310396	50-267 50-267 50-267 50-267 50-267	9 9 9 8		7912130464* 7912140030 7912140267 7912140289 7912140304	50-354 50-272 50-354 50-354 50-272	8 0 0 P
Public Service Co. of Indiana, Inc.	7912310398* 7912050301* 7912050301* 7912050424* 7912060057	50-267 50-546 50-546 50-546 50-546	R G G G		7912140318* 7912140537* 7912170190 7912170234 7912180379	50-272 50-311 50-272 50-354 50-272	Р 8 0 0 R
Public Service Co. of New Hampshire	7912060057 7912070411* 7912070411* 7912120398 7912050070*	50-546 50-546 50-546 50-546 50-443	0 0 A 0		7912180383* 7912180435 7912180472 7912180530 7912190092*	50-272 50-311 50-272 50-311 50-272	R Q Q A G
	7912120464 7912120464 7912120466* 7912120466* 7912120486	50-443 50-443 50-443 50-443 50-443	5 5 5 5		7912190569 7912190877 7912190577 7912200527 7912260032	50-272 50-272 50-272 50-272 50-272	ዘ P P የ
	7912120486 7912120489* 7912120513 7912140231 7912140363	50-443 50-443 50-443 50-443 50-443	5 9 A 5		7912270286 7912270290* 7912270567 7912270584 7912270591*	50-272 50-272 50-354 50-272 50-272	8 8 8 9
Public Service Co. of Oklahoma	7912140343 7912210320 7912030004 7912030015# 7912130337	50-443 50-443 50-554 50-554 50-445	E Q Q M	Puget Sound Power & Light Co.	7912270595 7912270600* 7912280538 7912030007 7912070355	50~272 50~272 50~272 50~522 50~522	5 B P G
	7912130337 7912130337 7912130361* 7912130361* 7912130361*	50-445 50-445 50-445 50-445 50-445	H H H H		7912100473 7912170020 7912170020 7912170041* 7912170041*	50-522 50-522 50-522 50-522 50-522	0 0 0
	7912130366* 7912130366* 7912130366* 7912130378* 7912130378*	50-445 50-445 50-445 50-445 50-445	# # #		7912170048* 7912170048* 7912260039 7912270215 7912270512	50-522 50-522 50-522 50-522 50-522	G G O A H
Public Service Electric & Gas Co. of New Jersey	7912130378* 7912180559 7912180547* 7912030190 7912030195*	50-445 50-554 50-554 50-272 50-272	M A A	Purdue Univ. Putney,L.W. Raytheon Co. Rensselaer Polytechnic Inst. Røuter≕Stokes, Inc.	7912050563 7912180327 7912030222* 7912110541* 7912170371	50-182 50-302 40-1386 CONTRACT XPORTLIC	
	7912030239* 7912040311 7912040317* 7912040338	50-272 50-272 50-272 50-272 50-272	9 9 9 9	Rhode Island, State of	7912200407 7912210139 7912130522 7912130531 7912190590	XPORTLIC XPORTLIC 50-193 50-193 50-193	
			8 8 3	Rickano Corp. Riverside. CA Rochester Committee for Scientific Information	7912180072 7912050414# 7912200522	WASTE MO PROJ 50-244	T G
			9	Rochester Gas & Electric Corp.	7912040049 7912050494	50-244 50-244	G P
					7912120445 7912120447 7912120450 7912130524 7912140047	50-244 50-244 50-244 50-244 50-244	P P P Q
					7912170247 7912180348 7912180351# 7912180418	50-244 50-244 50-244 50-244	G R R P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEODA		AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGORY
	7912180514 7912180527 7912190515 7912200522 7912210380	50-244 50-244 50-244 50-244 50-244		San Diego Gas & Electric Co. San Luis Obispo Mothers for Peace San Luis Obispo Mothers for Peace Sandia Laboratories	7912140142 7912270397* 7912120086* 7912130276 7912140168	50-361 Q 50-361 A CONTRACT 50-275 Q NUREG
	7912260033 7912270392 7912270434 7912270442* 7912270603	50-244 50-244 50-244 50-244 50-244	9 F 8 9		7912140339 7912140453# 7912140499# 7912140524# 7912140526#	NUREG REB REB REB REB
	7912280022 7912280204* 7912280501 7912310391 7912310394*	50-244 50-244 50-244 50-244 50-244	0 P P F F	Sargent & Lundy, Inc.	7912170337 7912180079 7912310153 7912310529 7912100321*	REB XPDRTLIC NUREQ NUREQ BO-409 P
Rocky Mountain Energy Co.	7912120039 7912170267 7912180088 7912180093 7912270252	PROJ 40-8721 40-8721 40-8721 40-8452		Sassafras Audubon Society	7712100324* 7712100331* 7712280151 7712170031* 7712210360	50-409 P 50-409 P REGGD 50-546 A 50-546 9
Rogow, B. Ropes & Gray	7912310200 7912120015 7912120125 7912170053 7912170202	40-8721 50-250 50-250 50-309 50-309	H G G	Schent & Boncher Science Applications, Inc.	7912210364* 7912140307* 7912050601* 7912050604* 7912050607*	SO-546 G FOIA WASTE MGT WASTE MGT WASTE MGT
S. M. Stoller Corp. (subs. of Arthur D. Little, Inc.)	7912180028 7912210100 7912130336 7912030041	50-309 50-471 PR XPORTLE	<b>.</b>	Scientists & Engineers for Secura Energy	7912120132 7912120163 7912130141 7912140536 7912130267	NUREO FDIA FDIA WASTE MOT PR
SPEX Industries, Inc.  Sacramento Municipal Utility District	7912210064 7912030027 7912030034* 7912040392 7912040478	XPORTLIC 50-312 50-312 50-312 50-312		Securities & Exchange Commission Senate	7912130274 7912280479 7912120049* 7912120096 7912120155	PR 50-287 T PDR MISC NUREO 50-320 U
	7912050500 7912070426 7912070430* 7912110319 7912110328	50-312 50-312 50-312 50-312 50-312	J 9 9		7912120279* 7912120563* 7912130022* 7912130171 7912140530	FDIA 50-346 U 50-302 U 50-546 U 50-155 U
	7912110327* 7912140015 7912140023* 7912140033 7912140041*	50-312 50-312 50-312 50-312 50-312	S G G G		7912170395 7912200312 7912200368* 7912210089* 7912210133*	50-250 U 50-339 A 50-339 A 50-358 U 50-275 U
	7912140124 7912140159* 7912140450 7912140457* 7912170277	50-312 50-312 50-312 50-312 50-312	0 S S R		7912210178* 7912210197* 7912210266* 7912270005* 7912280261	50-497 U 50-219 U 50-352 U PDR MISC 50-313 U
	7912170278* 7912180551 7912180555* 7912180407 7912180438	50-312 50-312 50-312 50-312 50-312	R 8 9 9	Sensible Maine Powar	7912280287* 7912110408 7912110418* 7912110425* 7912130316	50-320 V 50-309 0 50-309 0 50-309 0 PR
	7912180641* 791219052* 7912190437 7912190553 7912200505	50-312 50-312 50-312 50-312 50-312	6 P P	Shannon & Wilson, Inc. Shaw, Pittman, Potts & Trowbridge	7912120442 7912310208 7912030027 7912030034* 7912050321	NUREO NUREO 50-312 0 50-312 0 50-482 0
	7912200506* 7912210155* 7912260215 7912260217* 7912260226	50-312 50-204 50-312 50-312 50-312	P G S S F		7912060061 7912060095 7912100326 7912130034 7912130042	50-329 0 50-289 0 50-382 0 50-382 0
	7912260228 7912260229* 7912260230 7912260273 7912260277*	50-312 50-312 50-312 50-312	5 F S S		7912130085 7912130110 7912130308 7912140015 7912140023*	50-287 0 50-289 0 50-289 0 50-312 0 50-312 0
	7912260279 7912260283* 7912270246 7912270329 7912270334*	50-312 50-312 50-312 50-312 50-312	8 0 0		7912140033 7912140041* 7912140124 7912140159* 7912170209	50-312
	7912270462 7912280447 7912280496 7912280575 7912310358	50-312 50-312 50-312 50-312 50-312	P ·		7912170217 7912190029 7912240100 7912240293 7912270082	50-392 0 50-327 0 50-287 0 50-287 0 50-287 0
Safe Hayan, Ltd. San Antonio, TX	7912310348* 7912310452 7912310455* 7912130307 7912270052*	PR	g g		7912270093 7912270096 7912270347 7912280105 7912280140	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE(			AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	
Sheldon, Harmon & Weiss	7912280456 7912280459* 7912310149 7912310196 7912050606	50-320 50-320 50-400 50-289 0RG	0 0 0			7912180529* 7912180532* 7912180572 7912180609 7912180617*	50-361 50-206 50-206 50-206 50-206	S S F S
	791204023B 7912040242* 7912040440 7912130024 7912130449	50-289 50-289 50-155 50-289 PR	G G G			7912190006# 7912190602 7912190602 7912190615# 7912200541	50-133 50-361 50-361 50-361 50-361	9 8 8
	7912130485 7912130546 7912170386 7912180410 7912180410	PR PR FOIA 50-3 50-3	Q Q			7912200541 7912200544# 7912200544# 7912210136# 7912210142	50-361 50-361 50-361 50-206 50-206	8 8 9 0
	7912180410 7912180422* 7912180422* 7912180422* 7912200063	50-3 50-9 50-3 50-9 50-289	6 6 6			7912210369 7912270361 7912270390 7912270397* 7912270504	50-206 50-206 50-361 50-361 50-206	9 A A 9
Sbenandoah Valley Electric Cooperative, Inc. Sierra Club	7912200046* 7912260362 7912270040 7912200586	50-289 50-289 FOIA 50-339	С С Н		Southern California, Univ. of Spex Disc, Inc.	7912270581 7912270587* 7912280502 7912180223 7912280677	50-206 50-206 50-361 NUREQ XPORTLI	S S A
Sigma Chemical Co. (subs. of Sigma	7912130518	PR			Spiegel & McDiarmid	7912030042	PROJ	
Aldrich Corp.)  Sinnissippi Alliance for the Environment	7912030049 7912110166 7912130139 7912260355#	XPORTLI XPORTLI XPORTLI 50~373	С			7912050609 7912060016 7912120446 7912130483	PROJ PROJ PROJ 50-445	м
(SAFE)	7912260363	50-454	Q			7912140226 7912190130	PROJ 50-445	н
Small Business Administration Smell & Wilmer	7912200175* 7912200182* 7912030038	CONTRAC CONTRAC 50-275				7912190227 7912200287 7912260359	50-445 50-389 PROJ	M M
South Carolina Electric & Gas Co.	7912030145 7912030147# 7912040585#	50-395 50-395 50-395	K K		Standardized Nuclear Unit Power Plant	7912310161 7912310169 7912310294 7912060556	50-445 50-445 PROJ 50-482	N M
	7912100463 7912110049	50-395 50-395	Q Q		System	7912120146*	50-482	s
	7912130115 7912130433 7912130568 7912140358	50-395 50-395 50-395 50-395	6 8 8			7912120395 7912180175 7912190197 7912280429	50-482 50-482 50-482 50-482	S 0 0
	7912140360 7912190563 7912210166	50-395 50-395 50-395	5 5 F			7912280429 7912280429 7912280429	50-482 50-482 50-482	A
	7912210167* 7912210403 7912280532 7912280610 7912310026	50-395 50-395 50-395 50-395 REGOD	6 8 8			7912280436* 7912280436* 7912280469	50-482 50-482 50-482	A A F
South Carolina, State of	7912060041 7912060045 7912110002* 7912130319	70-1729 50-491 CONTRACT PR	9		State, Dept. of	7912280469 7912280469 7912280469 7912280593 7912030214	50-462 50-462 50-462 50-462 XPORTLIC	F F S
South Texas Electric Cooperative, Inc.	7912130320#	PR			State Dept. of Bureau of Oceans &	7912100474 7912030097	50-574 XPURTLIC	G
Southern California Edison Co.	7912270084 7912030176 7912040397 7912040408* 7912040468	50-445 50-204 50-206 50-206 50-206	# 6 5 5		Internati. Environ. & Scientific Affairs	7912140111 7912140141 7912140149	XPORTLIC XPORTLIC XPORTLIC	;
	7912040473*	50-204	5		Steel, Hector & Davis	7912130050	50-250	Q
	7912100306 7912100352 7912100352 7912110212	50-206 50-361 50-361 50-264	р 6 8		Stone & Webster Engineering Corp.	7912140014 7912200119 7912280155 7912280185	50-250 71~347 REGOD REGOD	G
<u>.</u> *	7912110215*	50-204	R	!	Guffalk County, NY Gusquebanna Alliance	7912060079# 7912200456	50-322 50-320	G C
	7912120443 7912130061 7912130061 7912130704*	50-206 50-361 50-361 50-361	F 0 0 0		Systems, Sciences & Software Tech/Opa (Tachnical Operations, Inc.)	7912280459# 7912180037# 7912180293	50-320 CONTRACT 71-9028	G
	7912140142 7912140340 7912140484* 7912170292 7912170293*	50-361 50-206 50-361 50-206 50-206	0 P G S S		Technassociates, Inc.	7912200461 7912200619 7912210289 7912200175* 7912200182*	71-9027 71-6144 71-9137 CONTRACT CONTRACT	
	7912170311 7912170314* 7912180515 7912180524 7912180524	50-204 50-206 50-206 50-361 50-361	5 S P S S		Technical Operatums, Inc. Technimet Corp. Technology for Energy Corp. Teknekron, Inc.	7912310012 7912190279 7912110326# 7912120170# 7912130315#	REGOD 50-397 50-335 FOIA FOIA	A P
	7912180528 7912180529*	50-204 50-361	S	1	Teledyne Wah Chang Albany Tennessee Valley Authority	7912040003 7910310325 7910310359#	XPORTLIC 50-327 50-327	S S

AUTHOR AFF IL TATTON	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFFILIAT		ACCESSION NUMBER	SUBJECT CATEGORY	
	7912030199 7912030199 7912040152 7912040301 7912040303*	50-566 50-566 PR 50-259 50-259	5 6 6	 		7912140232 7912140255 7912140273 7912140273 7912140273	50~259 50~259	A P P P
	7912040435 7912040435 7912040435 7912040448 7912040477	50-259 50-259 50-259 50-327 50-260	ք Բ 0 8			7912140384 7912140384 7912140384 7912140393* 7912170313	50-259 50-259 50-259 50-259 50-390	R R R S
	7912040483 7912050071 7912050477 7912050484 7912050484	50-260 50-438 50-390 50-390 50-390	5 A S S			7912170313 7912170317 7912170317 7912170318* 7912170318*	50-370 50-370 50-370 50-370 50-370	8 8 8 8
	7912050507 7912050508 7912050508 7912050508 7912050508	50-327 50-259 50-259 50-259 50-259	0 Р Р			7912170323* 7912170323* 7912170324 7912170324 7912180615	50-370 50-370 50-370 50-370 50-259	90090
	7912050510* 7912050510* 7912050513 7912050513 7912050513 7912050516*	50-259 50-259 50-390 50-390 50-390	P 8 8			7912180623 7912180625* 7912180629* 7912190554 7912190574	50-259 50-259 50-259 50-296 50-327	9 9 9 9
	7912050516* 7912050517 7912050517 7912050522* 7912050522*	50-370 50-438 50-438 50-438 50-438	9 9 9 9			7912190574 7912190575* 7912190675* 7912190578 7912190578	50-327 50-327 50-327 50-566 50-566	8 9 9 8
	7912050524 7912050524 7912050524 7912050530* 7912050530* 7912050541	50-327 50-327 50-327 50-327 50-546	8 8 8 8 8			7912190610* 7912190610* 7912190620 7912190620 7912190692	50-566 50-566 50-390 50-390 50-566	ន ន ន
	7912050541 7912050602* 7912060522 7912060525 7912070506	50-566 50-327 50-327 50-327 71-9079	S G A A			7912190492 7912190498* 7912190498* 7912200003 7912200003	50-546 50-546 50-546 50-370 50-370	9 9 0
	7912100359 7912100359 7912100361* 7912100361* 7912110104*	50-327 50-327 50-327 50-327 ACRB	Ж К К			7912200249 7912200289 7912200503 7912200503 7912210348	REGOD REGOD 50~327 50~327 50~327	Λ Α Α
	7912110202 7912110369 7912110369 7912110369 7912120422 7912120422	50-327 50-327 50-327 50-327 50-327	Q A A S			7912210348 7912210356# 7912270251 7912270251 7912270251	50-327 50-327 50-259 50-259 50-259	A P P
	7912120428* 7912120428* 7912120477 7912120477 7912120481*	50-327 50-327 50-327 50-327 50-327	8888			7912270256* 7912270256* 7912270256* 7912270262* 7912270287	50-259 50-259 50-259 50-259 50-327	Р Р Р К
	7912120491* 7912130258 7912130268* 7912130268* 7912130429	50-327 50-390 50-390 50-390 50-553	5 R R R			7912270289 7912270295* 7912270295* 7912270299 7912270304*	50~327 50~327 50~327 50~260 50~260	K K S S
	7912130429 7912130431* 7912130431* 7912130438 7912130458	50-553 50-553 50-553 50-259 PR	9 9			7912270356 7912270343 7912270363 7912270424 7912270473	50-390 50-327 50-327 50-553 50-327	A A A
	7912130482 7912130482 7912130482 7912130508* 7912130508*	50-259 50-259 50-259 50-259 50-259	թ թ թ			7912270473 7912270475 7912270476* 7912270476* 7912270480	50-327 50-296 50-327 50-327 50-370	ទ ទ ទ
	7912130508* 7912130520 7912130521 7912130581 7912130581	50~259 50~327 50~438 50~518 50~518	P 6 4 9			7912270480 7912270483* 7912270484* 7912270484* 7912270527	50-270 50-276 50-370 50-370 50-257	8 8 9
	7912130581 7912130581 7912130581 7912130581 7912130601*	50-518 50-518 50-518 50-518 50-518	5 5 5 5 5	,	· ·	7912270533 7912270564 7912270574* 7912280027 7912280173	50-327 50-294 50-294 REGOD REGOD	8 8
	7912130601* 7912130601* 7912130601* 7912130601* 7912130601*	50~518 50~518	S 8			7912280499 7912280503 7912280507* 7912280509 7912280513*	50-438 50-274 50-274 50-259 50-259	8 8 8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO			AUTHO AFFILIAT		ACCEBBION NUMBER	SUBJECT	
	7912280544 7912280544 7912280552* 7912280557	50-327 50-327 50-327 50-327 50-438	8 8 8	Toled	io Edison Co.		7912140151 7912170070* 7912270087 7912270111 7912100279	50-287 50-287 50-269 50-289 50-346	0 0 0 8
	7912280581 7912280581 7912280581 7912280581 7912280587	50-327 50-327 50-327 50-327 REGGD	9 8 8				7912100288* 7912100334 7912130210 7912130373 7912130373	50-346 50-346 50-346 50-346 50-346	E H Q R R
	7912280590* 7912280590* 7912280590* 7912280590* 7912280607	50-327 50-327 50-327 50-327 50-518	S S A				7912130474 7912130486* 7912170295 7912170297* 7912170300	50-346 50-346 50-346 50-346 50-346	88869
	7912280407 7912280407 7912280407 7912280413* 7912280413*	50-518 50-518 50-518 50-518 50-518	A A A A				7912170303* 7912170305 7912170309* 7912180505 7912180584	50-346 50-346 50-346 50-346 50-346	5 5 5 P P
	7912280613* 7912280661 7912310008 7912310020 7912310352	50-518 REGOD 50-327 REGOD 50-327	A G A				7912190127 7912190402 7912190433 7912190532* 7912210147*	50-346 50-346 50-346 50-346 50-346	0 P P Q
Yennessee, State of Ferminal Data Corp. Texas A & M Univ. Texas Electric Service Co.	7912310352 7912110009* 7912140294* 7912100303 7912180421*	50-327 CONTRAC CONTRAC 50-59 50-445					7912260234 7912260237* 7912260253 7912260258* 7912270395	50-346 50-346 50-346 50-346 50-346	១១១១១
Texas Instruments, Inc. Texas Nuclear Div. (subs. of Ramsay Eng. Co.)	7912280629 7912040093 7912280656	50-445 70-33 XPORTLI					7912270398# 7912270402 7912270407# 7912270413	50-346 50-346 50-346 50-346	8 8 8
Taxas Power & Light Co.	7912280663* 7912180425*	XPORTLI 50-445	I				7912270420# 7912270594	50-346 50-346	8
Texas Public Interest Research Group	7912280629 7912060002 7912120478 7912140081 7912140091	50-445 50-466 50-466 50-466 50-466	H 0 0 0				7912270599* 7912280643 7912310463 7912310480	50-346 50-346 50-346 50-346	8 Q P
Texas Utilities Generating Co.	7912140188* 7912140218 7912170035 7912180170 7912030040	50-466 50-466 50-466 50-466 50-446	0 0 0 0	Trans	nuclear, Inc.		7912170338 7912170343* 7912170356 7912170363* 7912170364	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	
	7912040595 7912040595 7912040402* 7912040402* 7912140240	50-445 50-445 50-445 50-445 50-445	A A A G			:	7912170346* 7912200284 7912210104 7912260189 7912260196*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	
	7912140264 7912140264 7912140271* 7912140271* 7912170088	50-445 50-445 50-445 50-445 50-445	KKKKG				7912260205 7912260208* 7912260212* 7912270027 7912270029*	XPORTLIC XPORTLIC XPORTLIC 71-250 71-250	:
	7912180412 7912180417* 7912190429 7912190548	50-445 50-445 50-445 50-445	I I A K	Tuskej URBAJi (sub-	s Publishing, Inc. gee Inst. ohn A. Blume & As: s. of URB)		7912180109 7912040491 7912040300	FOIA 50-406 TOPREP	A
	7912190548	50-445	ĸ	Union	74 Minerals Explo Carbide Corp.	SPACION CO.	7912170283 7912030082	40-8584 71-6058	
	7912280627 7912280627 7912280627 7912280629 7912280629	50-445 50-445 50-445 50-445 50-445	M M M				7912050648# 7912070086# 7912070088# 7912100011 7912140040	70-697 70-697 70-697 REB REB	
Teres, State of	7912280629 7912100338 7912110459 7912130342 7912130344*	50-445 50-446 50-445 PR PR	M Q M				7912170144* 7912170286 7912200170 7912260061* 7912310138	71-9009 40-299 71-5957 50-54 40-299	G
	7912190245* 7912190245* 7912190245* 7912190245* 7912190298*	50-445 50-445 50-445 50-445 50-445	н н н	Union	Electric Co. Dil Co. of Califo of Concerned Scie	•	7912180535 7912120253 7912120260* 7912050003 7912180422*	50-483 PROJ PROJ 50-266 50-3	H 0 0
	7912190298* 7912190298*	50-445 50-445	H	Unior	Carbide Corp., Cl	nem, & Plastics	7912200066# 7912040064	50-287 71-9070	Q
	7912170298* 7912170319* 7912190319* 7912280118	50-445 50-445 50-445 50-498	H H H	Div. Unites		itructors, Inc.	7912040049 7912170125 7912170387*	71-9070 71-9070 0A999	
Texas-Louisiana Electric Cooperative, Inc. Three Hile Island Alert	7911300277 7912260360 7912040081	50-445 50-445 50-320	H	(304)	. or kaysnadn çd,	1.1	7912190576 7912270236#	50-286 50-247	P P

AUTHOR AFFILIATION	ACCEBSION NUMBER	SUBJECT CATEGOR	·	AUTHOR AFFILIATIO	DN:	ACCESSION NUMBER	EUB JECT	<u>۲</u>
United Nuclear Corp., UNC Recovery Systems Div.	7912270243* 7912060091*	50-247 70-820	P	**************************************		7912120169 7912120306 7912120311* 7912120438	50-338 50-338 50-338 50-338	6 8 6
aystems biv.	7912120540* 7912180035 7912310299*	70-820 71-4949 70-820				7912120441* 7912120449	50-338 50-338 50-338	Q P P
Uranium Fuel Cycle Group Utah. State of Utility Workers Union of America Valentine. P. C.	7912130317 7912060023 7912310360 7912130176	PR PROJ REGOD 50-312	P			7912120452* 7912130329 7912130329 7912130341*	50-338 50-338 50-338	F F
Vanderbilt Univ. Vermont Vankee Nuclear Power Corp.	7912130276 7912180290 7912030084* 7912110387 7912110382	50-275 ACRB 50-271 50-271 50-271 50-271	G G S S S			7912130341* 7912130434 7912130519 7912140324 7912140324	50-338 50-339 50-338 50-280 50-280	F S R R
	7912110389*  7912110402* 7912130018 7912130379 7912130385*	50-271 50-271 50-271 50-271	8 P 8 8			7912140338* 7912140377 7912140377 7912140386 7912140390*	50-280 50-280 50-338 50-280 50-338	R R B R
	7912140260 7912170310 7912170326 7912170329* 7912170365	50-271 50-271 50-271 50-271 50-271	P ខ ច ប			7912140394* 7912140432 7912140442* 7912140466 7912140477*	50-280 50-280 50-280 50-280 50-280	5 5 5 5
	7912180238 7912180402 7912180407* 7912180433 7912180486	50-271 50-271 50-271 50-271 50-271	P R G S			7912140538 7912180182 7912180182 7912180536 7912180538	50-280 50-280 50-280 50-280 50-339	0 P 0 8
U. J. Obste of	7912180489* 7912270332 7912270338* 7912310341 7912130611	50-271 50-271 50-271 50-271 PR	9 6 9		_	7912180560 7912180564 7912180570# 7912190663 7912190668	50-337 50-338 50-338 50-339 50-338	9 9 9
Vermont, State of  Vet. Admin. Hosp. Lexington, KY  Veterans Administration  Viking Energy Corp.	7912130619* 7912110198 7912200322* 7912130301 7912190175	PR PR 50-337 FOIA FOIA	A			7912200097 7912200097 7912200107 7912200378 7912200378	50-280 50-280 50-338 50-261 50-281	0 0 0
Village Voice Virginia Electric & Power Co.	7912030189 7912030201 7912030201 7912030201 7912030201	50-280 50-280 50-280 50-280 50-290	F የ የ የ			7712200382* 7912200387 7912200387 7912200391 7912200518	50-339 50-404 50-404 50-339 50-280	A 8 8 9
	7912030209 7912030209 7912030210* 7912030210* 7912040312	50-338 50-338 50-338 50-338	P P P B			7912200518 7912200518 7912200518 7912200562 7912200562	50-260 50-280 50-280 50-338 50-338	Р Р Р
•	7912040316* 7912040349 7912040349 7912040376 7912040399	50-338 50-404 50-404 50-338 50-280	s s f f			7912210330 7912260209 7912260209 7912260211 7912260211	50-404 50-338 50-338 50-338 50-338	8 P P P
	7912040487 7912040496 7912040496 7912050356* 7912050452*	50-339 50-338 50-338 50-133 50-280	8 P P G			7912240214 7912240214 7912240218+ 7912240218+ 7912240231	50-338 50-338 50-339 50-339 50-280	P P P Q
	7912050570 7912050576 7912050576 7912060377 7912070191	50-338 50-280 50-280 50-338 50-338	F F 8 F			7912260244 7912260244 7912260251 7912260251 7912260259	50-280 50-280 50-280 50-280 50-337	0 0 0 0 A
	7912070325 7912070326 7912070338 7912070380 7912070386*	50-338 50-339 50-339 50-338 50-338	р Р <b>А</b> В			7912270187 7912270307 7912270311* 7912270348 7912270348	50-338 50-280 50-280 50-338 50-338	P B B P P
:	7912070388* 7912070395 7912070395 7912070407 7912070407*	50-338 50-339 50-338 50-338	8 8 8 8			7912270366 7912270421 7912270441 7912270441 7912270468	50-339 50-338 50-280 50-280 50-338	A Q Q Q B
	7912100250 7912100250 7912100302 7912100302	50-280 50-280 50-280 50-280 50-338	  -  -  -  -  -  -			7912270494 7912270547 7912270560 7912270560 7912270580 7912270580	50-338	8 8
	7912100364 7912100377* 7912110387 7912110390* 7912120059 7912120169	50-338 50-280 50-280 50-338 50-338	P 8 8 8	·		7912270392 7912280490 7912280494 7912280494 7912280344	50-280 50-281 50-280 50-280 50-339	Q Q Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	
	7912310255 7912310255 7912310280 7912310371 7912310374*	50-338 50-338 50-280 50-338 50-338	0 0 P P		7912260291 7912270207* 7912270546 7912280213* 7912280540*	TOPREP NUREG TOPREP 50-244 50-395	 P S
	7912310390 7912310499 7912310499 7912310506* 7912310506*	50-280 50-280 50-280 50-280 50-280	<b>ኮ</b> P <del>P</del> P		7912280548 7912280549 7912280452 7912310114 7912310384#	50-282 TOPREP XPORTL I PR 50-338	s tc o
Virginia Tech Virginia, State of	7912310548 7912100091+ 7912130410	50-338 CONTRAC 50-339	T H	Westinghouse Electric Corp., Nuclear Energy Systems	7912030110	XPORTL1	
	7912130596 7912130603±	PR PR		Westinghouse Electric Corp., PWR Systems Div.	7912050085* 7912030099* 7912040014*	70-1143 70-1143 50-349	
	7912200357 <b>+</b> 7912200370* 7912200585	50-339 50-339 PR	A A		7912040138*	50-413	Q
Virginia, Univ. of	7912310145 7912130041	50-339 NUREC	A	Westinghouse Electric Corp., Wyoming Mineral Corp.	7912050548 7912110188	TOPREP PROJ	
Volpe, Boskey & Lyons H. J. Woolley Co. Wald, Harkrader & Ross Washington Public Power Supply System	7912210038* 7912060036 7912190713* 7912180212 7912030204	50-62 70-1729 50-369 50-329 50-397	о в м о	Westinghouse Operating Plants Cwners Group	7912310193 7912310197 7912180587	40-8502 40-8502 TOPREP	
and the same of th	7912030207*	50-397	a	Wharton, R. J.	7912270601 7912100352 7912130061	TOPREP 50~361 50-361	6
	7912040246 7912040252 7912040476	50-397 50-397 50-460	A A A	Widoff, Reagar, Selkowitz & Adler	7912140151 7912170066	50-289 50-289	9
	7912110471* 7912120413 7912120418* 7912120470	50-440 50-508 50-397 50-397 50-508	A G S S	William Powell Co.	7912170070* 7912270087 7912270111 7912280454 7912180054	50-287 50-287 50-289 50-320 50-414	6 6 8
	7912120473* 7912140357 7912140362* 7912180626	50-509 50-305 50-305 50-460	ร R R A	Williams-Robinetto & Associates, Inc. Wisconsin Electric Power Co.	7912190288 7912030171 7912030171 7912030172	WASTE MG 50-266 50-266 50-266	ե ե ե
	7912280409 7912280566	NUREO 50-397	A		7912040247 7912040419 7912040486	50-244 50-502 50-246	i I
Washington State Univ. Hashington, State of Washington, Univ. of	7912280642* 7912280651* 7912100267 7912310503	50-397 50-397 50-27 50-522	s s f g		7912050087 7912050474 7912070412	50-266 50-266 50-266	G P Si
West Chicago, IL	7912270056* 7912270056* 7912270059* 7912270059* 7912280608	50-522 50-522 50-522 50-522 50-139	6 6 6 8		7912070416* 7912070427 7912070433* 7912110195 7912120230	50-266 50-266 50-266 PR 50-266	ម ម ទ
West Texas Utilities Co	7912130057 7912130337 7912130337 7912130337 7912130361#	40-2061 50-445 50-445 50-445 50-445	н м м		7912120230 7912130295 7912130295 7912130303* 791213060B	50-266 50-266 50-266 50-266 50-266	F F F P
West Virginia Univ.	7912130361* 7912130366* 7912130366* 7912130378* 7912130378*	50-445 50-445 50-445 50-445 50-445	н н н н		7912140369 7912140369 7912140422 7912180446 7912180446	50-266 50-266 50-266 50-266 50-266	Н Н Н Н
Western Nuclear: Inc. (subs. of Phelos	7912040449 7912030032	50-129 40-1162	Р		7912180447# 791218057B	50-246 50-246	R
Dodge Corp.) Western Nuclear, Inc. Westinghouse Electric Corp	7912130376 7912040356	PROJ TOPREP			7912180578 7912190562 7912190562	50-244 50-244 50-244	P P P
	7912050509 7912070341 7912100255*	TOPREP TOPREP 50-87 50-3	P P		7912200027 7912210143 7912210143 7912270191	50-266 50-266 50-266 50-266	9 P P
	7912130AB4* 791217037A 79121B0039	XPORTLIC 50-247 XPORTLIC XPORTLIC	P		7912270191 7912270196* 7912270196* 7912270206	50-266 50-266 50-266	F F P
	7912180049 7912180185* 7912180304	PT21 QA999 71-5395			7912270204 7912270209 7912270220*	50-244 50-244	P P
·	7912190424* 7912190597 7912190601*	TOPREP TOPREP TOPREP TOPREP 70-1143			7712270220# 7712270200 7912270300 7912270300 7912270430	50-266 50-266 50-266 50-266 50-266	6 6 6 6
	7912200338 7912200394	TOPREP 50-545	u B	•	7912270430 7912270492 7912270492 7912270495	50-266 50-266 50-266 50-266	P P F
	7912200584*		Ã	† *	7912270495 7912270499*	50-266 50-266	F P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	łΥ	AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGO	
					7912120366	PROJ	
	7912270499*	50-266	þ	Wyoming Outdoor Council	7912310212	40-8745	
	7912270500*	50-266	F	Hyoming. State of	7912310372	40-8721	
	7912270500 <b>»</b>	50-266	F		7912030175	50-29	P
	7912280154	50-266	Q	Yanker Atomic Electric Co.		50-29	P
	7912280154	50~266	Q		7912040208	30-27	•
			_		7912040348	50-29	P
	7912280550	50-266	P		79120403B9	50-309	s
	7912280554	50-266	P		791204039B*	50-309	S
	7912280554	50-266	P		7912060185	50-27	G.
	7912280601	50-266	P		7912070437	50-27	8
	7912280601	50-266	P		7412070137	30 E	•
		*** 541	р		7912070444*	50-29	S
	7912280606	50-244			7912100292	50~27	8
	7912280650	50-266	Q		7912100298	50-27	S
	79122B0650	50-246	G		7912110297	50-27	5
	7912310139	20~549	G		7912110290#	50-29	6
Wisconsin Public Gervice Corp.	7912040211	50-305	a		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		_
	************	50-305	Р		7912110291	50-29	8
	7912120362	50-300	Ġ		7912110293#	50~29	9
	7912170210	50-305	P		7912110314	50-29	þ
	7912180481		P		7912120218	50-29	G.
	7912180501	50-305	P		7912120299	50-29	b
	7912180621	50-305	•		* * * * * * * * * * * * * * * * * * * *		
•	7912190420	50-305	р		7912130096	50-29	Œ
	7912200089	50-305	Ġ		7912130230	50-27	P
	7912210325	50-305	P		7912140152	PR	
	7912210439	50-300	ė		7912140252	50-29	O)
		20~266	Ġ		7912140370	50~29	þ
Wisconsin's Environmental Decade	7912050091	JU-ALD	4				
	7912100470	50-246	G		7912180150	50~27	P
	7912100472*	50-246	ō		7912180155	50-29	Ъ
	7912190234	50~266	G	·	7912180341	50-29	R
Manager 2 - Marker - 6	7912060610	PRM			7912180345₺	50-29	R
Wisconsin, State of	7912130490	PR			7912180611	50-27	P
	7712130470	•		· ·			_
	7912310085	NUREG			7912200551	50-29	Р
Wiss, Janney, Elstner & Association, Inc.	7912110346*	50-344	S		79122005569	50-27	l.
Wiss, Danney, Elsther & Association, The.	7912190496*	50-255	P		7912270203	50~29	P
Un Mikeles & Association Inc	7912200453*	WASTE M	DТ		7912270454	50~29	p
Wm. Matotan & Associates, Inc. Wyle Laboratories	7912200512#	50-316	P		7912270532	50-27	P
wite Capalatolies						MINGEO	
	7912200515*	50-316	P		7912280121	NUREC	
Wyoming Mineral Corp.	7912120363	PROJ			7912280515	MANEE	Р
adducting transcrate and by	7912130011	40~8502			7912310556	50-29	۲,
	7912170170	40-8502					
	7912190788	40-B304					
	7912200014	40-8502					
	7912210042	40-8502					
	7912270047	40-8502					
	7912280106	40-8502					
	7912310203	40-8502					



#### REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the Index titled "Cross Reference of Enclosures to Principal Documents."

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER	REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
22A43A5 7912040103 7912040112 7912040117 7912040125	7912130500* 7912040103 7912040112 7912040119 7912040125	50-447 / RES RES RES RES	\ \	BWNP-20004 BWNP-20004 CE-1-A CEN-125 CENPD-263-NP	7912190716# 7912310486# 7912310359# 7912310481# 7912030205#	50-313 P 50-346 P 50-10 P 50-255 P TOPREP	69-1106003-00
7912040133 7912100001 7912100005 7912100011 7912110465	7912040133 7912100001 7912100005 7912100011 7912110465	RES RES RES RES RES	BNL-NUREG-24827 BNL-NUREG 24687	DP8PU 79-124-2 0A-D15474 0A1-2074 0A1-TR-106 HSPH/EH9(NUREO)-880	7912210434* 7912040221* 7912180424* 7912280528* 7912140517*	71-5467 50-267 P 50-244 P TOPREP REB	14941
7912110509 7912140040 7912140296 7912140300 7912140309	7912110509 7912140040 7912140296 7912140300 7912140309	RES RES RES RES	ORNL/ED/EIS-107 ORNL/CBD/INF-79 EGG-FM-5035 YBR-197-79 EGG-FM-5034	NEDO-11207-04A NEDO-21660 NEDO-24146 NEDO-24221 NEDO-24224	7912040235* 7912180156* 7912110386* 7912040247* 7912260246*	TDPREP FOIA 50-237 P 50-243 P 50-273 P	
7912140314 7912140368 7912140391 7912140453 7912140467	7912140314 7912140368 7912140391 7912140453* 7912140467	RES RES RES RES RES	EGG-FM-5036 AT(49-24)-018 DRNL/CBD/INF-79	NMWL-13B1-2 NUREO-0002 NUREO-0970 V2 NUREO-0135 V3 N4 NUREO-0306	7912200020* 7912200795 7912050012 7912170003 7912200850	71-4581 NUREO NUREO NUREO NUREO	14897
7912140486 7912140510 7912140540 7912170167 7912170174	7912140486 7912140510 7912140540 7912170167 7912170174	res res res res res	ORNL/CSD/INF-79 EGG-CAPF-5052 DRNL-41-89-95-1 DRNL/MASRD-97	NUREO-0314 V3 N5 NUREO-0330 V3 N5 NUREO-0380 V3 N11 NUREO-0394 NUREO-0503	7912200766 7912130072 7912120099 7912140483* 7912310363	NUREO NUREO NUREO REB NUREO	BNWL-1774
7912170194 7912170320 7912170337 7912170359 7912170422	7912170194 7912170320 7912170337 7912170359 7912170422	RES RES RES RES RES	EGG-SEMI-5018 DRNL/ED/£19-108	NUREO-0523 NUREO-0525 NUREO-0548 NUREO-0596 NUREO-0598	7911090248* 7912130075 7912110521 7912180207 7912130353*	50-3 F NUREQ NUREQ NUREG 50-320 U	
7912180143 7912180146 7912180152 7912180158	7912180143 7912180146 7912180152 7912180158	RES RES RES RES	GRNL/FTR-761	NUREQ-0616 NUREG-0632 NUREO-0632 NUREQ-0650 NUREQ/CR-0030	7912180224 7912120034 7912190292 7912170011 7912140526*	NUREQ NUREQ PDR MIBC NUREG RES	6AND76-587
7912180165 7912190544 7912190546 7912190547 7912190552	7912190165 7912190544 7912190546 7912190547 7912190552 7912190557	RES RES RES RES RES	NRC-04-77-119	NUREO/CR-0150 V2 NUREO/CR-0628 NUREO/CR-0662 NUREO/CR-0717 NUREO/CR-0794	7912110442 7912120157 7912050005 7912120033 7912130089	NUREG NUREG NUREG NUREG NUREG	ORNL/NUREG/TM-1 PNL-2889 UCRL-52702 ORNL/NUREG-59 NYSG8/79-2403
7912190557 7912190541 7912190547 7912190570 7912200279	7912190561 7912190567 7912190570 7912200279 7912310035	RES RES RES RES RES	DE-ACO7-74ID015 DE-ACO7-74ID015 PNL-3084	NUREG/CR-0944 NUREG/CR-0947 NUREG/CR-0955 NUREG/CR-0963 NUREG/CR-0967	7912140339 7912310529 7912060307 7912120139 7912140206	NUREO NUREO NUREO NUREO NUREO	9AND79-1132 9AND79-1399 UCRL-52721 ORNL/NUREG/TM-3
7912310035 BAH-10122A BAH-1384 BAH-1590 BNL-NUREG-26422 BNL-NUREG-26464	7912130009* 7912270156* 7912310513* 7912120108 7912120121	TOPREP 50-313	P P	NUREO/CR-0970 NUREO/CR-0982 NUREO/CR-0987 NUREO/CR-0990 NUREO/CR-0998	7912310153 7912120645 7912140165 7912120641 7912120442	NUREO NUREO NUREO NUREO NUREO	9AND79-1314 BMI-2034 BAND79-0299 PNL-3080
BNL-NUREG-26572 BNL-NUREG-26789 BQ-TOP-1 BVTR-1-0 BHNP-20004	7912120129 7912110555 7912210353* 7912310389 7912040412*	TOPREP	Р	NUREO/CR-1022 NUREO/CR-1040 NUREO/CR-1068 NUREO/CR-1076 NUREO/CR-1076	7912120190 7912090009 7912180223 7912310202 7912050002	NUREG NUREG NUREG NUREG NUREG	ORNL/NUREO/TM 3 ANL-79-43 CREARE TN-906

#### REPORT NUMBER INDEX

REPORT NUMBER	ACCESSION NVMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER	REPORT NUMBER	ACCESSION NUMBER	BUBJECT CATEGORY	OTHER REPORT NUMBER
NUREG/CR-1101 V7 NUREG/CR-1102 V3 NUREG/CR-1144 NUREG/CR-1155 NUREG/CR-1156	7912140186 7912040520 7912260002 7912140125 7912120132	NUREG NUREG NUREG NUREG NUREG	ORNL/NUREG/NSIC FNL-2804 LA-UR-79-2910 SAI 01379-729LJ	RIL-025 RIL-026 RIL-027 RIL-028 RIL-027	7912140454 7912140474 7912140487 7912140495 7912140502	RES RES RES RES	
NUREG/CR-1175 RIL-001 RIL-002 RIL-003 RIL-004	7912310208 7912140418 7912140420 7912140424 7912140433	NUREG RES RES RES RES	NRC-04-76-200	RIL-030 RIL-033 SAND77-2042 SAND78-0724 SECY-79-490	7912140507 7912140522 7912140499* 7912140524* 7912040086*	RE8 RE8 RE9 RE9 50-320 P	
RIL-005 RIL-006 RIL-007 RIL-008 RIL-008	7912140440 7912140447 7912140458 7912140464 7912140512	RES RES RES RES RES		TFBP-TR-164 VI TFBP-TR-194 TFBP-TR-228 V2 TR-3501-1 WARD-D-0050 R3	7912140461* 7912140505* 7912140468* 7912170222* 7912200584*	RES RES RES 50-267 G 50-537 A	IEB-79-02
RIL-009 RIL-010 RIL-011 RIL-012 RIL-013	7912140471 7912140475 7912140480 7912140488 7912140493	RES RES RES RES		HASH-1350 RA HCAP-7800 R5A HCAP-7639 XN-92 XN-FN-499	7912190247* 7912190424* 7912190401* 7912200011* 7912200029*	FOIA TOPREP TOPREP 71-6581 71-6581	14897 14897
RIL-014 RIL-015 RIL-016 RIL-017 RIL-018	7912140504 7912140509 7912140511 7912140514 7912140518	RES RES RES RES RES		XN-NF-103 XN-NF-77-40 XN-NF-79-103	7912280571* 7912280222* 7912280240*	50-397 A 50-244 P 50-244 P	
RIL-019 RIL-020 RIL-021 RIL-023 RIL-024	7912140520 7912140523 7912140515 7912140519 7912140521	RES RES RES RES					

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

Items listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued and the category enables locating the title listing of the enclosure.

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

ACCESSIO	NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEODR	
7809270104	7809270093	78/09/22	50-269	P
7908010163	7912210394	79/12/13	FOIA	
7908080606	7912190530	79/12/03	50-311	G
7908140509 7909180007	7908140497 7909180006	79/07/26 79/08/20	PDR MISC 50-320	
,,0,,10,00,,	,,0,,10000	77700720	30-320	н
7910040491	7910040479	79/08/29	50-324	Q
7910310359	7910310325	79/10/26	50-327	s
7911050268 7911090248	7911050267 7911090108	79/10/15	PRM	р
7911140152	7911140147	79/03/21 79/10/23	50-3 50-518	A
, , , , , , , , , , , , , , , , , , , ,	.,	. / // 10/ 23	20-216	~
7911190354	7912190526	79/12/03	NUREG	
7911190530 7912030015	7911170520	79/10/30	50-322	G
7912030013	7912030011 7912030011	79/11/14 79/11/14	50-554 50-554	Q Q
7712030034	7912030011	79/11/08	50~312	ä
7912030048	7912030045	79/09/26	50~333	G
7912030053	7912030050	79/11/13	50-335	a
7912030056 7912030064	7912030054 7912030059	79/09/26 79/09/27	50-336 50~272	0
7912030065	7912030051	79/10/18	50-327	G
		,		•
7912030073	7912030068	79/11/16	50-261	G.
7912030074	7912030070	79/11/13	50-338	G.
7912030076 7912030079	791203006B 791203006B	79/11/16 79/11/16	50-261	G G
7912030083	7912030068	79/11/16	50-261 50-261	G
7912030086	7912030080	79/10/24	50~271	a
7912030089 7912030092	79120300B0 79120300B0	79/10/24 79/10/24	50-271	g
7912030096	7912030080	79/10/24	50-271 50-271	G G
7912030112	7912030107	79/10/24	50-312	Ğ
7912030117 7912030147	7912030107	79/10/24	50-312	G)
7912030147	7912030145 7912030146	79/11/30 79/10/25	50-395 50-251	X 5
7912030157	7912030154	79/11/27	50~302	8
7912030158	7912030155	79/11/29	50-329	Ċ
7712030140	7912030152	70////05	50 000	_
7712030160	7912030152	79/11/05 79/11/28	50-250 50-249	9 8
7912030187	7912030103	79/11/27	50-348	Š
7912030191	791203018B	79/11/30	50-327	č
7912030194	7912030193	79/11/30	50-416	C
7912030195	7912030190	79/11/10	50-272	8
7912030176	7912030170	79/11/28	50-237	8
7912030200	7912030198	79/11/30	50-341	ĸ
7912030202	7912030197	79/11/30	50~306	8
7912030205	7912030203	79/11/30	TOPREP	
7912030207	7912030204	79/11/28	90-397	g
7912030210	7912030209	79/11/29	50-338	P
7912030218	7912030216	79/11/23	XPORTLIC	
7912030220	7912030219	79/11/07	50~186	G.
7912030222	7912030221	79/11/01	40-1386	

ACCESSIO	N NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE	SUBJECT CATEGOR	
7912030224	7912030221	79/11/01	40-1386	
7912030225	7912030223	79/11/14	50-324	Q.
7912030227	7912030223	79/11/14	50-324	ä
7912030228	7912030226	79/10/26	50-392	ũ
7912030230	7912030229	79/10/29	40-3453	-
7912030231	7912030229	79/10/29	40-3453	
7912030232	7912030229	79/10/29	40-3453	
7912030234	7912030229	79/10/29	40-3453	
7912030235	7912030233	79/11/19	50-331	Р
7712030238	7912030233	79/11/19	50-331	Ь
7912030239	7912030236	79/10/15	50-272	G
7912030240	7912030233	79/11/19	50-331	P
7912030241	7912030236	79/10/15	50272	a
7912030242	7912030236	79/10/15	50-272	Q.
7912030244	7912030243	79/11/02	XPORTLIC	
7912030248	7912030245	79/10/24	50-217	G
7912030251	7912030245	79/10/24	50-219	Q.
7912030252	7912030245	79/10/24	50-217	G
7912030256	7912030245	79/10/24	50-217	a
7912030257	7912030249	79/10/11	50~329	a
7912030262	7912030260	79/10/10	50~327	a
7912030263	7912030240	79/10/10	50-327	G
7912040000	7912040006	79/10/29	50-289	G
7912040011	7712040009	79/11/21	50-10	G
7912040014	7912040010	79/11/07	50-367	Q
7912040015	7912040013	79/10/30	70-925	
7912040016	7912040013	79/10/30	70-925	
7912040023	7912040020	79/11/20	71-6	
7912040030	7912040027	79/11/20	71-9853	
7912040035	7912040032	79/11/20	71-355	
7912040036	7912040031	79/10/30	40-341	
7912040038	7912040031	79/10/30	40-341	
7912040045	7912040031	79/10/30	40-341	
7912040072	7912040071	79/11/20	71~193	
7912040086	7912040084	79/10/22	50-320	P
7912040092	7912040085	79/11/23	50-320	н
7912040105	7912040097	79/10/12	50-334	a
7912040118	7912040107	79/10/03	50-320	Ü
7912040121	7912040097	79/10/12	50-334	a
7912040124	7912040108	79/11/20	50-272	ľ
7912040126	7912040107	79/10/03	50-320	U
7912040128	7912040108	79/11/20	50~272	P
7912040129	7912040097	77/10/12	50-334	Q
7912040137	7912040108	79/11/20	50-272	P
7912040130	7912040130	79/11/07	50-413	0
7912040148	7912040136	79/11/19	50-320	Р
7912040150	7912040136	79/11/19	50-320	P
7912040158	7912040151	79/11/14	50-320	H
7912040179	7912040166	79/10/01	50-320	a
7912040195	7912040187	79/11/19	50-368	þ

ACCESSION NUMBER

					ACCEBBIC	M MOUDEN			
ACCESSION	PRINCIPAL	DATE	SUBJECT		ENCLOSURE	PRINCIPAL DOCUMENT	DATE	BUDJECT CATEGORY	_
ENCLOSURE	DOCUMENT	IBSUED	CATEGORY			7912050074	79/10/18	50-333 (	a
	7912040191	79/11/29	50-313 P		79120500B9 79120500B9	7912050083	79/10/25		3
7912040197 7912040206	7912040200	79/11/28	50-286 P		7912050090	7912050074	79/10/18	50-333 ( 70-1143	a
7912040221	7912040216	79/11/29	50-267 F		7912050095	7912050080	79/10/15 79/10/26		Ġ
7912040235	7912040213	79/11/29 79/11/30	50-243 F	,	7912050094	7912050094	/ 7/ TO/ EG		
7912040249	7912040242	77711700			7912050099	7912050080	79/10/15	70-1143	
7912040298	7912040296	79/11/20	50-247 \$		7912050102	7912050080	79/10/15	70-1143 70-1143	
7712040303	7912040301	79/11/23 79/11/30	50-259 5 50-333 5		7912050104	7912050080 7912050101	79/10/15 79/11/06		G
7912040313	7912040308 7912040312	79/11/29	50-338		7912050105 7912050107	7912050101	79/11/06	50-277	a
7912040316 7912040317	7912040311	79/11/10	50~272 9	3	/41200010/	,,		~~ 4447	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		79/11/28	50~286	3	7912050109	7912050080	79/10/15 79/11/06	70-1143 50-277	G
7912040321	7912040319 7912040320	79/11/29	50~267	8	7912050110 7912050116	7912050101 7912050101	79/11/06	50-277	Q.
7912040323 7912040328	7912040325	79/11/28		5	7912050119	7912050111	79/10/17		()
7912040330	7912040326	79/11/20		B P	7912050127	7912050120	79/10/11	70-135	
7912040331	7912040327	79/11/28	JU-E11		7912050131	7912050074	79/10/18	50-333	G
7912040334	7912040327	79/11/28		թ 9	7912050141	7912050120	79/10/11	70-133	P
7912040335	7912040332	79/11/20 79/11/20		P	7912050151	7912050146	79/11/14 79/11/30	50-263 50-321	P
7912040336	7912040327 7912040337	79/11/16		s	7912050155		79/11/14	50-243	P
7912040341 7912040343	7912040338	79/11/10	50-272	S	7912050157				
		-0444200	50-29	P	7912050173		79/11/06 79/11/13	50-247 50-275	G G
7912040352	7912040349 7912040351	79/11/29 79/11/28		8	7912050170 7912050179		79/11/06	50-247	a
7912040353 7912040357	7912040356	79/11/16	TOPREP		791205018		79/11/06	50-247	G G
7912040360	7912040359	79/11/10		B B	791205019		79/11/06	50-247	u
7912040363	7912040362	79/11/26	50 20,	•	70.005000	7912050197	79/10/18	50-10	Q.
7912040369	7912040367	79/11/28		s	791205020: 791205021:		79/11/21	XPORTLIC	
7912040371	7912040365	79/11/28		5 5	791205023	7912050220	79/10/22	50-409 50-293	Q Q
7912040378	7912040375 7912040368	79/11/28 79/11/30		Š	791205026		79/10/04 79/08/20	50-312	ā
7912040381 7912040390	7912040384	79/11/26	50-315	5	791205028	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			_
		70/11/70	50-293	8	791205029	7912050279	79/10/26 79/10/26	50-271 50-271	P P
7912040374	7912040387 7912040386	79/11/28 79/11/10	50-272	8	791205030	7912050279 7912050290	79/11/27	50-546	Ġ
7912040395 7912040398	7912040389	79/11/21	50-309	5	791205030 791205030		79/11/09	50-329	A
7912040401	7912040396	79/11/27 79/11/29	50-334 50-247	8 5	791205030		79/10/26	50-271	P
7912040406	7912040400	/4/11/2/			791205031	5 7912050073	79/10/22	50-264	0
7912040409	7912040397	79/11/29	50-206	5 8	791205031		79/10/30	50-187	Q P
7912040409	7912040402	79/11/10 79/11/26	50-272 50-312	P	791205032	5 7912050320	79/12/03 79/10/23	50-289 50-313	a
7912040412 7912040413	7912040392 7912040407	79/11/27	50-336	8	791205033 791205033		79/10/25	50-518	G
7912040416	7912040414	79/11/10	50-272	8	771203030	-		50-507	G
	7912040392	79/11/26	50-312	Р	791205034		79/10/24 79/10/23	50-397 50∽313	ō.
7912040417 7912040423	7912040418	79/11/27	50-409	8	791205034 791205034		79/11/19	XPORTL10	
7912040425	7912040422	79/10/17	50-335 50-336	6 8	791203034	3 7912050336	79/11/19	50-574 50-133	G
7912040426	7912040421 7912040424	79/11/28 79/11/28	50-314	g	791205035	1 7912050347	79/10/31	20-100	•
7912040430	7712040424				791205035	4 7912050348	79/10/31	50-346	Qi
7912040432	7912040428	79/11/29	50-261 50-267	\$ 8	791205035	5 7912050346	79/10/22 79/10/31	50-142 50-133	G G
7912040433	7912040429 7912040439	79/11/28 79/11/29	50-334	Ř	791205035		79/10/31	50-133	Ğ
7912040443 7912040444	7912040438	79/10/11	50~335	8	791205036 791205036		79/10/31	50-133	G
7912040473	7912040468	79/11/26	50-206	5			20110131	50~346	Q.
7912040476	7912040474	79/12/04	50-269	5	79120503 79120503			50-45B	Ā
7912040479	7912040474	79/12/04	50-249	E	79120503		79/10/31	50-133	Q
7912040483	7912040477	79/11/30	50-240 50-272	S R	79120503	79 7912050366		50-259 70-1143	0
7912040495	7912040493 7912040499	79/11/26 79/11/27	50-302	P	79120503	93 7912050374	/4/10/14	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
7912040502	, , , , , , , , , , , , , , , , , , , ,			_	79120503	35 7912050380	79/10/24	50-327	Q.
7912040515	7912040511	79/11/08 79/11/20	50-272 50-269	<u>ե</u> 6	79120503				G G
7912040518	7912040516 7912040521	79/11/13	50-272	Ř	79120503				ö
7912040524 7912050004		79/10/15	50-286	Q	79120503 79120504				G
7712050008	7712050006	79/10/04	50-440	a				50-305	a
	7912050007	79/10/16	50-333	a	79120504				ä
7912050010 7912050011			50-440	a	79120504 79120504	29 791205042	79/11/30	50-272	8
7912050018	7912050014			a a	79120504	38 791205043	2 79/11/28 3 79/11/28		8
7912050020 7912050022	7912050013 791205001 <i>6</i>			ä	79120504	45 791205044	) /7/11/AC	au Baa	
/4120000E				^	79120904	51 791205044	7 79/10/24		Q (A
7912050035	7912050028			G G	79120504	52 791205044			Ğ
7912050037 7912050048				P	79120504 79120504			50-321	8
7912050052	7912050040	79/10/19	50-440	Q P	79120504		6 79/11/21		Q.
7912050053	7912050042	2 79/11/27	30-302			67 791205044	6 79/11/21	50-280	Ġ
7912050046	7912050050	79/10/17		a	79120504 79120504		3 79/10/29	50-492	G
791205006	791205006	79/10/24	50-302	· 0:	79120504	70 791205046	2 79/11/20	3 50-325	5 0
791205007				Ğ	7912050	79 791205046			•
7712050073 7712050073				ā	7712050	1/6 /7120304/			
• •			2 50-264	a	7912050				8
791205007 791205007			2 50-443	a	7912050- 7912050-			70-220	5
791205008	4 791205007	4 79/10/16	50-333	G.	7912050	05 791205047	1 79/11/1	70-220	
791205008					7912050		79/11/1	9 50-272	
791205008	- , ,1m00000)								

ACCESSION						ACCESSION				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR'	<u>-</u>		ENCLOSURE	PRINCIPAL DOCUMENT	DATE	SUBJECT CATEGOR	
7912050489 7912050491 7912050510 7912050516 7912050522	7912050486 7912050487 7912050508 7912050513 7912050517	79/10/25 79/11/19 79/11/29 79/11/23 79/11/23	50-327 50-272 50-259 50-390 50-438	0 F 9 8		7912060089 7912060091 7912060096 7912060104 7912060105	7912050077 7912050085 7912050085 7912050090 7912060085	79/10/31 79/11/09 79/11/09 79/10/19 79/11/09	50-566 70-820 70-820 50-275 70-820	Q Q
7912050528 7912050530 7912050531 7912050532 7912050542	7912050518 7912050524 7912050526 7912050518 7912050538	79/11/23 79/11/23 79/10/26 79/11/23 79/10/25	50-369 50-327 50-382 50-369 50-454	9 9 9		7912060110 7912060114 7912060123 7912060125 7912060134	7912060085 7912060100 7912060112 7912060115 7912060121	79/11/09 79/10/30 79/10/15 79/11/05 79/10/31	70-820 50-338 50-344 50-522 50-261	0 0 0
7912050544 7912050549 7912050584 7912050555 7912050571	7912050837 7912050834 7912050538 7912050550 7912050565	79/09/12 79/11/29 79/10/25 79/10/25 79/11/19	GA999 50-261 50-454 50-281 State Pr	9 0 9		7912060146 7912060147 7912060152 7912060153 7912060160	7912040131 7912040140 7912040142 7912040131 7912040151	79/11/06 79/11/26 79/11/27 79/11/06 79/11/26	50-20 71-6 50-325 50-20 71-79	0 0
7912050573 7912050578 7912050580 7912050581 7912050585	7912050865 7912050565 7912050565 7912050565 7912050574	79/11/19 79/11/19 79/10/11 79/11/19 79/10/11	State Pr State Pr WASTE MO State Pr WASTE MO	99 F 99		7912040141 7912040171 7912040174 7912040185 7912040188	7912060131 7912060131 7912060167 7912060177 7912060182	79/11/06 79/11/06 79/11/05 79/11/06 79/11/28	50-20 50-20 CONTRACT 50-29 50-369	a a a
7912050589 7912050594 7912050596 7912050601 7912050602	7912050574 7912050592 7912050562 7912050574 7912050597	79/10/11 79/11/29 79/10/24 79/10/11 79/11/20	WASTE MG 50-369 50-416 WASTE MG 50-327	8 Q		7912060189 7912060192 7912060193 7912060197 7912060200	7912060177 7912060182 7912060177 7912060182 7912060194	79/11/06 79/11/28 79/11/06 79/11/28 79/10/12	50-27 50-367 50-29 50-369 50-387	0 0 0 0
7912050404 7912050405 7912050407 7912050410 7912050412	7912050574 7912050597 7912050574 7912050574 7912050609	79/10/11 79/11/20 79/10/11 79/10/11 79/10/29	WASTE MG 50-327 WASTE MG WASTE MG PROJ	Q T		7912040201 7912040205 7912040213 7912040214 7912040215	7912060177 7912060191 7912060208 7912060191 7912060182	79/11/06 79/10/19 79/11/06 79/10/18 79/11/29	50-29 50-334 50-201 50-334 50-369	9999
7912050413 7912050414 7912050415 7912050418 7912050422	7912050574 7912050609 7912050611 7912050616 7912050621	79/10/11 79/10/29 79/11/05 79/10/24 79/10/25	WASTE MO PROJ 50-498 50-416 50-280	r 0 0		7912060217 7912060218 7912060220 7912060221 7912060222	7912060211 7912060191 7912060212 7912060191 7912060219	79/11/26 79/10/18 79/11/19 79/10/18 79/11/26	71-248 50-334 50-466 50-334 71-5375	0 0
7912050624 7912050625 7912050628 7912050629 7912050631	7912050623 7912050605 7912050597 7912050626 7912050627	79/10/26 79/11/20 79/11/20 79/11/20 79/10/25	50-280 50-327 50-327 50-324 50-327	a a a a		7912060233 7912060235 7912060237 7912060240 7912060242	7912060208 7912060228 7912060208 7912060208 7912060238	79/11/06 79/10/25 79/11/06 79/11/06 79/11/07	50-201 50-280 50-201 50-201 50-289	0 0 0 0
7912050432 7912050434 7912050436 7912050437 7912050438	7912050626 7912050626 7912050633 7912050635 7912050633	79/11/20 79/11/20 79/11/15 79/11/14 79/11/15	50-324 50-324 50-400 50-142 50-400	a a o P		7912060254 7912060259 7912060260 7912060269 7912060279	7912060249 7912060248 7912060255 7912060248 7912060248	79/10/31 79/11/01 79/11/28 79/11/01 79/11/01	50-335 70-1362 50-416 70-1362 70-1362	a a
7912050640 7912050641 7912050646 7912050648 7912050649	7912050435 7912050626 7912050635 7912050642 7912050635	79/11/16 79/11/20 79/11/16 79/10/24 79/11/16	50-142 50-324 50-142 70-697 50-142	р Ф Р		7912060287 7912060291 7912060299 7912060327 7912060329	7912060266 7912060266 7912060266 7912060320 7912060318	79/11/29 79/11/29 79/11/29 79/11/16 79/11/26	50-390 50-390 50-390 XPDRTLIG 50-272	0 0 0 :
7912050451 7912050455 7912050458 7912050440 7912050461	7912050635 7912050642 7912050642 7912050635 7912050635	79/11/16 79/10/24 79/10/24 79/11/16 79/11/16	50-142 70-687 70-687 50-142 50-142	P P		7912060335 7912060339 7912060349 7912060355 7912060375	7912060318 7912060318 7912060340 7912060346 7912050448	79/11/26 79/11/26 79/12/04 79/12/04 79/11/29	50-272 50-272 50-269 50-269 50-293	Р Р Р Rt
7912050662 7912050664 7912050665 7912050666 7912050668	7912050642 7912050635 7912050635 7912050657 7912050635	79/10/24 79/11/16 79/11/16 79/10/24 79/11/16	70-687 50-142 50-142 50-566 50-142	P P Q P		7912060415 7912060450 7912060454 7912060467 7912060485	7912060406 7912060446 7912060453 7912060458 7912060469	79/11/21 79/12/03 79/12/04 79/10/23 79/12/04	50-341 50-155 50-317 50-327 50-317	# 8 0
7912050471 7912050480 7912050487 7912050493 7912040015	7912050667 7912050675 7912050684 7912050691 7912060012	79/11/30 79/11/14 79/11/27 79/10/16 79/11/30	50-282 50-128 50-313 50-94 50-329	0 0 0 0		7912060486 7912060495 7912060499 7912060500 7912060520	791206047 <i>†</i> 7912060490 7912060494 7912060497 791206051 <i>†</i>	79/10/23 79/10/23 79/12/04 79/11/30 79/12/04	50-327 50-280 50-317 50-414 50-255	. a 8 8 4
7912060017 7912060029 7912060026 7912060031 7912060044	7912060003 7912060018 7912060022 7912060021 7912060033	79/09/27 79/10/31 79/09/25 79/10/17 79/10/22	50-309 50-361 50-317 50-147 50-277	@ @ @ @		7912060328 7912060335 7912060537 7912060559 7912060569	7912060526 7912060534 7912060534 7912060558 7912060563	79/12/03 79/11/29 79/11/29 79/11/15 79/11/23	50-286 50-255 50-255 FOIA 50-387	P G A
7912040047 7912040048 7912040049 7912040054 7912040058	7912060035 7912060043 7912060033 7912060033 7912060033	79/11/02 79/10/24 79/10/22 79/10/22 79/10/22	80-528 50-454 50-277 50-277 50-277	0 0 0 0		7912040575 7912040585 7912040587 7912040589 7912040590	7912040548 7912040581 7912040581 7912040581 7912040581	79/11/21 79/11/29 79/11/29 79/11/29 79/11/29	50-514 50-395 50-395 50-395 50-395	D Q Q Q
7912040043 7912040045 7912040074 7912040079 7912040084	7912060043 7912060056 7912060068 7912060074 7912060073	79/10/24 79/11/01 79/09/27 79/11/05 79/11/30	50-456 50-275 50-272 50-322 50-440	G G G		7912040594 7912040401 7912040402 7912040422 7912040423	7912040592 7912040543 7912040595 7912040421 7912040421	79/10/31 79/11/23 79/09/17 79/12/03 79/12/03	50-553 REGOD 50-445 50-155 50-155	Q A P P

ACCESSION NUMBER

## CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER

ACCESSION					ACCESS	ION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	Y	ENCLOBURE		DATE 186UED	CATEGOR	
7912060624 7912060625 7912060626 7912060627 7912060627	7912060621 7912060621 7912060621 7912060621 7912060621	79/12/03 79/12/03 79/12/03 79/12/03 79/12/03	50-155 50-155	P P P P	791207032 791207032 791207033 791207034 791207034	7912070325 8 7912070323 5 7912070263 0 7912070334	79/12/06 79/11/30 79/11/16 79/11/30 79/11/16	50-338 50-219 FOIA 50-219 FOIA	P 8
7912060629 7912060630 7912060631 7912060632 7912060633	7912060621 7912060621 7912060621 7912060621 7912060621	79/12/03 79/12/03 79/12/03 79/12/03 79/12/03	50-155 50-155	P P P P	791207034 791207034 791207034 791207034 791207035	15 7912070333 16 7912070343 17 7912070291	79/11/26 79/12/03 79/12/03 79/11/16 79/11/30	50-155 50-219 50-245 FOIA 50-316	6 8 8
7912060634 7912060636 7912060637 7912060641 7912060653	7912060621 7912060621 7912060621 7912060621 7912060643	79/12/03 79/12/03 79/12/03 79/12/03 79/11/09		P P P 0	771207036 771207036 771207036 771207036 771207037	4 7912070350 5 7912070359 6 7912070263	79/11/16 79/12/03 79/11/30 79/11/16 79/12/05	FOIA 50-217 50-217 FOIA 50-498	S S
7912060656 7912060657 7912060657 7912060658 7912060664	7912040443 7912040451 7912040451 7912040443 7912040443	79/11/09 79/10/22 79/10/22 79/11/09 79/11/09	50-269 50-339 50-399 50-269 50-269	Q Q Q Q	791207037 791207037 791207037 791207037 791207038	76 7912070263 77 7912070371 79 7912070378	79/11/30	50-498 FOIA 50-315 50-316 50-336	A 8 8
7912060666 7912060668 7912060671 7912060673 7912070030	7912040661 7912040661 7912040661 7912040661 7912070004	79/11/20 79/11/20 79/11/20 79/11/20 79/11/08	50-302 50-302 50-302 50-302 50-275	0 0 0 0 A	791207031 791207031 791207031 791207040 791207040	9B 7912070380 79 7912070390 04 7911200385	79/12/04 79/11/30 79/11/16	50-338 50-338 50-293 50-219 50-338	8 8 8
7912070038 7912070055 7912070062 7912070067 7912070072	7912070004 7912070049 7912070049 7912070056 7912070066	79/11/08 79/10/16 79/10/16 79/10/22 79/10/26	50-275 50-341 50-341 50-390 50-346	A G G G	79120704 79120704 79120704 79120704 79120704	11 7912070402 13 7912060621 14 7912060621	79/11/27 79/12/03 79/12/03	50-285 50-544 50-155 50-155 50-266	5 P P S
7912070079 7912070086 7912070088 7912070091 7912070093	7912070066 7912070077 7912070077 7912070089 7912070076	79/10/26 79/10/15 79/10/15 79/10/17 79/11/29	50-346 70~687 70-687 70-2756 50-272	G G	79120704 79120704: 79120704: 79120704: 79120704:	20 7912070417 21 7912060621 22 7912070416	79/11/29 79/12/03 79/11/09	50-155 50-10 50-155 50-275 50-155	P P S P
7912070095 7912070097 7912070098 7912070102 7912070105	7912070077 7912070089 7912070077 7912070076 7912070099	79/10/15 79/10/22 79/10/15 79/11/29 79/10/22	70~697 50-348 70~687 50-188 50~375	Q Q	79120704: 79120704: 79120704: 79120704: 79120704:	29 7912060621 30 7912070424 32 7912060621	79/12/03 79/11/29 79/12/03	50-348 50-155 50-312 50-155 50-266	P 65 P 53
7912070112 7912070113 7912070126 7912070132 7912070134	7912070108 7912070077 7912070123 7912070123 7912070123	79/10/24 79/10/15 79/10/22 79/10/22 79/10/22	50-280 70-487 50-293 50-293 50-293	Q Q Q	79120704 79120704 79120704 79120704 79120704	40 7912070434 41 7912060621 42 7912070439	79/12/04 79/12/03 79/11/30	50-155 50-282 50-155 50-287 50-29	6 8 8 6
7912070139 7912070146 7912070151 7912070152 7912070156	7912070123 7912070142 7912070144 7912070142 7912070142	79/10/22 79/11/05 79/11/15 79/11/05 79/11/05	50-293 50-471 50-352 50-471 50-471	0 0 0 0	79120704 79120704 79120704 79120704 79120704	48 7912070445 49 791206062 50 7912070445	79/11/29 79/12/03 79/11/27	50-368 50-366 50-155 50-254 50-295	0 8 P S
7912070160 7912070162 7912070163 7912070166 7912070167	7912070159 7912070155 7912070159 7912070159 7912070159	79/11/20 79/10/26 79/11/20 79/11/20 79/11/20	50-324 50-373 50-324 50-324 50-324	G G G G	79120704 79120704 79120704 79120704 79120704	64 791207046 65 791206062 67 791206062	79/12/04 1 79/12/03 1 79/12/03	50-155 50-285 50-185 50-155 50-522	6 6 6 6
7912070169 7912070175 7912070186 7912070192 7912070198	7912070164 7912070174 7912070181 7912070192 7912070179	79/11/23 79/09/25 79/11/23 79/11/23 79/10/19	CONTRACT 50-482 FOIA FOIA 50-89	5 G	79120704 79120704 79120704 79120704 79120705	185 791207047 188 791207047 192 791207048	6 79/11/23 6 79/11/23 9 79/10/02	50-273 50-273 50-273 CONTRAC 50-364	е Р Р Т
7912070199 7912070202 7912070203 7912070206 7912070211	7912070181 7912070200 7912070181 7912070181 7912070181	79/11/23 79/09/26 79/11/23 79/11/23 79/11/23	FOIA 50-322 FOIA FOIA FOIA	q	79120705 79120705 79121006 79121006 79121006	508 791207049 )39 791210002 )43 791210002	7 79/11/23 2 79/11/13 2 79/11/13	50-366 50-366 50-286 50-286 50-286	թ 19 19 19
7912070214 7912070218 7912070248 7912070258 7912070270	7912070181 7912070181 7912070243 7912070173 7912070264	79/11/23 79/11/23 79/11/13 79/11/20 79/10/25	FOIA FOIA 50-382 CONTRACT 50-10	G G	79121000 79121000 79121000 79121000 79121000	)56 791210004 )57 791210004 )60 791210004	6 79/11/19 9 79/10/23 6 79/11/19	70-824 70-824 70-820 70-824 50-286	P
7912070273 7912070276 7912070289 7912070299 7912070300	7912070269 7912070263 7912070263 7912070263 7912070291	79/09/26 79/11/16 79/11/16 79/11/16 79/11/16	70-371 FOIA FOIA FOIA FOIA		79121000 79121000 79121000 79121000 79121000	)70 791210004 )79 791210002 )91 791210008	6 79/11/19 2 79/11/13 7 79/10/03	50-286 70-824 50-286 CONTRA CONTRA	
7912070303 7912070305 7912070316 7912070319 7912070321	7912070291 7912070263 7912070291 7912070291 7912070291	79/11/16 79/11/16 79/11/16 79/11/16 79/11/16	FOIA FOIA FOIA FOIA		7912100; 7912100; 7912100; 7912100; 7912100;	143 791210013 147 791210013 153 791210013	7 79/11/09 7 79/11/09 7 79/11/09	CONTRA 50-312 50-312 50-312 50-312	9 9
							The second secon		

ACCESSION				ACCESS	ION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	BUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE 195VED	SUBJECT	_
7912100161 7912100165 7912100196 7912100197 7912100197	7912100137 7912100184 7912100193 7912100193 7912100193	79/11/09 79/11/16 79/10/18 79/10/18 79/10/18	50-312 0 50-269 0 50-213 0 50-213 0 50-213 0	791211012 791211012 791211016 791211016 791211016	7912110107 7912110101 26 7912110038 7912110101	79/11/23 79/11/19 79/11/23 79/11/19 79/11/23	0A999 0A999 50-3 0A999 0A999	G
7912100208 7912100211 7912100215 7912100217 7912100224	7912100205 7912100205 7912100205 7912100210 7912100219	79/10/23 79/10/23 79/10/23 79/11/28 79/11/06	50-220 0 50-220 0 50-220 0 50-244 T 50-334 0	791211015 791211012 791211017 791211017 791211011	57 7912110159 75 7912110159 76 7912110142	79/11/19 79/11/14 79/11/14 79/11/20 79/11/29	9A979 40-7344 40-7344 70-1308 CONTRACT	
7912100236 7912100245 7912100253 7912100254 7912100255	7912100219 7912100219 7912100219 7912100246 7912100189	79/11/05 79/11/05 79/11/06 79/11/13 79/11/09	50-334 G 50-334 G 50-334 G 50-250 P 50-3 P	791211016 791211026 791211026 79121102 79121102	7912110193 7912110206 10 7912110193	79/11/26 79/11/26 79/12/06 79/11/26 79/11/26	50-389 50-409 50-389	G G R G
7912100268 7912100274 7912100275 7912100276 7912100286	7912100266 7912100260 7912100269 7912100270 7912100277	79/11/16 79/10/22 79/12/04 79/11/20 79/12/03	50-348 P 50-335 G 50-302 S CONTRACT 50-316 S	79121102 79121102 79121102 79121102 79121102	23 7912110219 29 7912110220 33 7912110220	79/12/05 79/12/07 79/11/23 79/11/23 79/11/23	50-295 50-370 50-370	R R Q Q
7912100288 7912100291 7912100294 7912100296 7912100304	7912100279 7912100277 7912100284 7912100292 7912100299	79/12/04 79/12/03 79/12/06 79/12/05 79/12/04	50-346 S 50-316 S 50-213 F 50-29 S 50-245 S	79121102 79121102 79121102 79121102 79121102	47 7912110220 56 7912110250 43 7912110257	79/11/29 79/11/23 79/12/07 79/10/24 79/10/24	50-370 50-333 50-315	P G R G
7912100311 7912100321 7912100324 7912100330 7912100331	7912100305 7912100318 7912100318 7912100189 7912100318	79/12/05 79/11/29 79/11/29 79/11/09 79/11/29	50-334 F 50-409 F 50-409 F 50-3 F 50-409 F	79121102 79121102 79121102 79121102 79121102	84 7912110277 84 7912110280 86 7912110261	79/11/21 79/12/04 79/10/31 79/10/25 79/12/06	XPDRTLIC 50-546	5 0 9
7912100348 7912100361 7912100373 7912100377 7912100383	7912100344 7912100359 7912100371 7912100364 7912100380	79/11/09 79/12/07 79/11/30 79/12/06 79/08/24	50-516 0 50-327 P 71-9119 50-338 F	79121102 79121102 79121102 79121103 79121103	97 7912110295 98 7912110296 113 7912110311	79/12/07 79/10/29 79/12/03 79/12/04 79/12/06	XPDRTLIC 50-272 50-293	S S S
7912100384 7912100394 7912100407 7912100409 7912100415	7912100385 7912100390 7912100189 7912100404 7912100412	79/11/30 79/11/30 79/11/09 79/09/26 79/10/22	CONTRACT CONTRACT 50-3 F GA999 GA999	79121103 79121103 79121103 79121103 79121103	123 7912110320 126 7912110324 127 7912110325	79/11/26 79/11/27 79/12/04 79/11/29 79/12/04	50-400 50-321 50-335 50-312 50-333	0 8 P 8 6
7912100427 7912100452 7912100453 7912100455 7912100456	7912100422 7912100449 7912100451 7912100451 7912100189	79/11/19 79/10/25 79/11/27 79/11/27 79/11/09	50-318 F CONTRACT 50-335 C 50-335 C	79121103 79121103 79121103 79121103 79121103	333 7912110332 334 7912110306 336 7912110335	79/12/05 79/12/07 79/11/26 79/12/03 79/12/03	50-302 50-284 50-400 50-348 50-348	\$ 6 8 5
7912100458 7912100461 7912100462 7912100464 7912100466	7912100451 7912100451 7912100460 7912100463 7912100465	79/11/27 79/11/27 79/11/30 79/11/28 79/11/30	50-335 ( 50-335 ( 71~9111 50-395 ( 71-5768	79121101 79121101 79121101 79121101 79121101	339 7912110335 342 7912110341 344 7912110341	79/12/03 79/12/03 79/12/04 79/12/04 79/12/04	50-348 50-348 50-344 50-344 50-344	5555
7912100467 7912100472 7912100482 7912110002 7912110004	7912100463 7912100470 7912100479 7912110001 7912110003	79/11/28 79/11/26 79/11/29 79/11/30 79/11/29	50-395 50-266 50-466 CONTRACT CONTRACT	7912110: 7912110: 7912110: 7912110: 7912110:	350 7912110349 353 7912110348 357 7912110352	79/12/04 79/12/06 79/12/05 79/11/12 79/12/05	50-333 50-574 50-412 TOPREP 50-333	5 6 5
7912110009 7912110019 7912110024 7912110034 7912110036	7912110006 7912110013 7912110016 7912110016 7912110028	79/11/30 79/11/30 79/11/14 79/11/16 79/11/28	CONTRACT CONTRACT GA999 GA999 CONTRACT	7912110 7912110 7912110 7912110 7912110	372 7912110348 373 7912110345 377 7912110370	79/12/05 79/11/30 79/12/14 79/12/06 79/12/06	50-285 50-366 50-329 50-293 50-325	8888
7912110041 7912110042 7912110045 7912110046 7912110052	7912110016 7912110016 7912110040 7912110016 7912110016	79/11/16 79/11/16 79/11/28 79/11/16 79/11/16	QA797 QA777 CONTRACT QA777 QA777	7912110 7912110 7912110 7912110 7912110	383 7912110375 385 7912110382 386 7912110380	79/11/19 79/12/06 79/12/04	50-574 XPORTL10 50-271 50-237 50-297	C 59 P 8
7912110061 7912110062 7912110071 7912110081 7912110088	7912110058 7912110059 7912110065 7912110076 7912110082	79/09/21 79/11/30 79/10/31 79/10/03 79/10/23	QA999 71-6280 QA999 QA999 QA999	7912110 7912110 7912110 7912110 7912110	1391 7912110380 1402 7912110379 1417 7912110410	79/12/04 79/12/04 79/12/04	50-290 50-237 50-271 50-302 50-307	8 p S
7912110089 7912110090 7912110099 7912110104 7912110108	7912110086 7912110085 7912110086 7912110097 7912110105	79/11/28 79/07/04 79/11/28 79/07/13 79/08/09	FOIA ACRB FOIA ACRB ACRB	7912110 7912110 7912110 7912110 7912110	)447 7912110435 )463 7912110435 )471 791211046	79/12/04 79/12/04 79/11/29	50-309 50-454 50-454 50-508 50-454	A A O A
7912110110 7912110111 7912110114 7912110117 7912110118	7912110101 7912110107 7912110101 7912110107 7912110101	79/11/19 79/11/23 79/11/19 79/11/23 79/11/19	GA999 GA999 GA999 GA999 GA999	7912116 7912116 7912116 7912116 7912116	)488 7912110462 )493 7912110462 )497 7912110482	79/11/29 79/11/29 79/11/30	50-508 50-508 50-261 50-261	0 0 0

ACCESSION	NUMBER				ACCEBBION				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE IBBUED	GUBJECT CATEGORY		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	BUBJECT CATEGORY	
7912110505 7912110506 7912110513 7912110514	7912110486 7912110301 7912110503 7912110486	79/11/30 79/10/30 79/11/16 79/11/30	50-261 GA999 50-295	• • •	7912120418 7912120428 7912120433 7912120435	7912120413 7912120422 7912120426 7912120426 7912120429	79/11/30 79/12/05 79/12/07 79/11/29	50-397 5 50-327 5 50-348 5 50-277 5	3 3 3
7912110516 7912110518 7912110525 7912110531	7912110511 7912110503 7912110503 7912110301	79/11/26 79/11/16 79/11/16 79/11/28	9A999 50~295 50~295 71~9113	0	7912120436 7912120441 7912120448 7912120452 7912120453	7912120432 7912120438 7912120431 7912120449 7912120446	79/12/07 79/12/10 79/12/10 79/10/10 79/11/14	50~33B (	a G P
7912110532 7912110541	7912110503 7912110529 7912110503	79/11/16 79/11/16	50~275 CONTRACT 50~275	0	7912120455 7912120459	7912120431	79/12/10	50-516 ( 50-349 (	0 8
7912110542 7912110544 7912120028 7912120044 7912120049	7912110503 7912110536 7912120022 7912120035 7912120035	79/11/16 79/11/01 79/11/20 79/10/22 79/10/22	70-27 PRM PDR M18C PDR M18C		7912120460 7912120461 7912120462 7912120466	7912120457 7912120457 7912120456 7912120464	79/12/06 79/12/06 79/11/19 79/12/06	50-333   XPORTLIC 50-443	P P B
7912120066 7912120067 7912120071 7912120073 7912120083	7912120053 7912120055 7912120053 7912120065 7912120077	79/10/15 79/11/21 79/10/15 79/11/30 79/11/23	50-498 50-466 50-498 Contract 0a999	U 0 U	7912120469 7912120473 7912120476 7912120481 7912120489	7912120465 7912120470 7912120468 7912120477 7912120486	79/12/07 79/12/03 79/11/13 79/12/05 79/12/06	50-508 XPDRTLIC 50-327 50-443	8 8 8 8
7912120085 7912120086 7912120089 7912120098 7912120104	7912120079 7912120078 7912120077 7912120077 7912120077	79/11/21 79/11/28 79/11/23 79/11/23 79/11/23	50-305 CONTRACT GA797 GA797 GA797	· C	7912120505 7912120512 7912120517 7912120521 7912120524	7912120502 7912120910 7912120514 7912120519 7912120520	79/10/23 79/12/04 79/12/04 79/12/04 79/10/12	50-508 71-199 71-347 71-349 NUREQ	<b>Q</b>
7912120106 7912120109 7912120110 7912120115 7912120118	7912120101 7912120077 7912120101 7912120101 7912120077	79/11/09 79/11/23 79/11/09 79/11/09 79/11/23	70-364 GA999 70-364 70-364 GA999		7912120527 7912120532 7912120533 7912120535 7912120540	7912120525 7912120528 7912120529 7912120529 7912120531	79/12/04 79/10/31 79/12/04 79/10/31 79/10/11	71-345	U
7912120197 7912120144 7912120146 7912120147 7912120149	7912120135 7912120141 7912120142 7912120141 7912120141	79/10/19 79/10/17 79/10/15 79/10/17 79/10/17	40-8463 50-57 50-482 50-57 50-57	Q 8 9 0	7912120543 7912120544 7912120546 7912120548 7912120549	7912120538 7912120538 7912120541 7912120538 7912120531	79/11/27 79/11/27 79/10/31 79/11/27 79/10/11	FOIA FOIA PDR MISC FOIA 70-820	
7912120150 7912120153 7912120158 7912120170 7912120174	7912120135 7912120135 7912120141 7912120166 7912120169	79/10/19 79/10/19 79/10/17 79/11/29 79/11/30	40-8663 40-8663 50-57 FOIA 50-338	œ •	7912120554 7912120560 7912120562 7912120563 7912120571	7912120538 7912120531 7912120554 7912120552 7912120568	79/11/27 79/10/11 79/12/03 79/10/23 79/12/03	70-820	0 G U
7912120178 7912120180 7912120184 7912120189 7912120193	7912120169 7912120172 7912120169 7912120169 7912120169	79/11/30 79/11/26 79/11/30 79/11/30 79/11/30	50-338 50-327 50-338 50-338 50-338	a a o o	7912120574 7912120576 7912130009 7912130017 7912130019	7912120570 7912120572 7912130003 7912130014 7912130016	79/10/12 79/11/01 79/11/30 79/10/04 79/12/04	50-155 XPORTLIC TOPREP 50-302 71-225	U
7912120197 7912120204 7912120205 7912120223 7912120233	7912120169 7912120196 7912120203 7912120212 7912120226	79/11/30 79/10/25 79/11/13 79/11/05 79/10/12	50-338 50-382 XPORTLIC 50-247 50-289	e ; a ; u	7912130020 7912130022 7912130028 7912130067 7912130070	7912130014 7912130014 7912130025 7912130064 7912130058	79/10/04 79/10/04 79/10/15 79/11/05 79/11/27	50-302 50-302 PR 50-331 50-275	U Q Q
7912120235 7912120239 7912120250 7912120254 7912120255	7912120229 7912120229 7912120243 7912120247 7912120248	79/11/07 79/11/07 79/10/04 79/10/23 79/11/02	50-148 50-148 50-287 PR 50-327	e g U	7912130071 7912130076 7912130080 7912130091 7912130093	7912130068 7912130068 7912130068 7912130084 7912130086	79/11/17 79/11/17 79/11/17 79/10/12 79/11/29	50-261 50-261 50-261 40-5721 50-491	P P Q
7912120260 7912120266 7912120275 7912120278 7912120279	7912120253 7912120261 7912120264 7912120272 7912120268	79/10/23 79/11/19 79/11/01 79/11/27 79/10/02	PROJ CONTRACT 50-338 GA999 FOIA	T G	7912130100 7912130102 7912130120 7912130121 7912130127	7912130088 7912130087 7912130117 7912130117 7912130123	79/11/29 79/11/13 79/11/26 79/11/26 79/11/13	50-491 XPORTLIC 50-599 50-599 XPORTLIC	G
7912120281 7912120287 7912120293 7912120303 7912120307	7912120272 7912120272 7912120272 7912120298 7912120301	79/11/27 79/11/27 79/11/27 79/12/10 79/10/11	GA799 GA799 GA799 50-324 50-317	S P	7912130133 7912130136 7912130146 7912130152 7912130154	7912130084 7912130131 7912130141 7912130148 7912130149	79/10/12 79/10/23 79/12/03 79/11/30 79/12/04	40~8721 50~546 FOIA TOPREP PROJ	Q
7912120310 7912120311 7912120318 7912120321 7912120327	7912120308 7912120306 7912120315 7912120302 7912120323	79/11/30 79/12/10 79/11/30 79/11/30 79/11/28	CONTRACT 50-338 50-584 50-344 50-10	T B K O C P	7912130163 7912130224 7912130226 7912130264 7912130268	7912130159 7912130219 7912130214 7912130259 7912130258	79/11/21 79/12/10 79/11/02 79/12/07 79/12/05	50-347 50-329 PDR MIBC 50-335 50-390	Q S P R
7912120330 7912120336 7912120337 7912120341 7912120347	7912120323 7912120324 7912120333 7912120336 7912120343	79/11/28 79/12/04 79/12/07 79/12/06 79/11/29	50-10 50-247 50-293 50-247 50-277	P	7912130288 7912130288 7912130291 7912130297 7912130303	7912130271 7912130285 7912130284 7912130293 7912130295	79/12/06 79/12/10 79/12/03 79/12/07 79/12/06	50-275 50-261 50-3 50-255 50-266	A P R F
7912120350 7912120352 7912120353 7912120376 7912120387	7912120345 7912120345 7912120348 7912120364 7912120384	79/12/04 79/11/23 79/10/24 79/12/06 79/12/12	50-133 50-382 70-1143 50-263 50-387	P	7912130306 7912130314 7912130315 7912130320 7912130322	7912130284 7912130241 7912130310 7912130319 7912130312	79/12/03 79/11/21 79/11/30 79/11/20 79/12/07	50-3 50-320 FOIA PR 50-314	۴ ۷ 9

ACCE891DN	MIMDED				ACCESSION	NUMBER			
	PRINCIPAL	DATE	SUBJECT CATEGORY		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT	, . <b>_</b>
ENCLOSURE	DOCUMENT	185UED		-	7912140188	7912140168	79/11/09	50-466 71-3059	G
7912130326 7912130338	7912130324 7912130241	79/11/21 79/11/21		U F	7912140215 7912140271	7912140210 7912140264	79/12/04 79/11/30	50-445 CONTRACT	K
7912130341 7912130344	7912130329 7912130342	79/12/10 79/11/20	PR		7912140294 7912140303	7912140288 7912140297	79/12/06 79/12/06	CONTRACT	
7912130347	7912130335	79/10/22		8	7912140307	7912140302	79/11/02	FOIA	
7912130350 7912130352	7912130346 7912130348	79/11/28 79/11/21	50~264 PR	G 	7912140317 7912140318	7912140312 7912140304	79/11/30 79/12/10	FOIA 50-272	P
7912130353 7912130358	7912130241 7912130354	79/11/21 79/12/10	50-324	V R	7912140319	7912140312 7912140312	79/11/30 79/11/30	FOIA FOIA	
7912130359	7912130356	79/10/29	50-131	a	7912140322	7912140321	79/12/07	50-321	P
7912130361	7912130337 7912130241	79/11/27 79/11/21	50~445 50~320	M U	7912140326 7912140329	7912140312 7912140312	79/11/30 79/11/30	FOIA FOIA	
7912130365 7912130366 7912130371	7912130337 7912130241	79/11/27 79/11/21	50-445 50-320	M U	7912140332 7912140335	7912140331 7912140312	79/12/07 79/11/30	50-267 FOIA	R
7912130371	7912130330	79/12/07	50-315	8	7912140337	7912140324	79/12/12	50-280	R
7912130375	7912130373 7912130241	79/12/07 79/11/21	50~346 50~320	R	7912140338 7912140346	7912140312 7912140312	79/11/30 79/11/30	FOIA FOIA	
7912130377 7912130378	7912130337	79/11/27 79/12/07	50-445 50-315	M S	7912140349 7912140350	7912140312	79/11/30 79/12/07	FOIA 50-285	R
7912130380 7912130381	7912130330 7912130374	79/11/27	QA999		7912140352	7912140347	79/11/30	FOLA	
7912130385	7912130379	79/12/10	50-271 50-298	6 8	7912140354 7912140359	7912140312 7912140344	79/12/10	50-277 50-305	R R
7912130389 7912130392	7912130387 7912130384	79/11/20 79/12/06	50-366 50-298	5	7912140362 7912140365	7912140357 7912140243	79/12/10 79/12/10	50-70 FDIA	P
7912130393 7912130400	7912130391 7912130394	79/11/21 79/12/06	50-366	8	7912140366	7912140312	79/11/30	50~440	9
7912130408	7912130404	79/12/06	50-366	8	7912140371 7912140372	7912140364 7912140312	79/12/07 79/11/30	FOIA	R
7912130421 7912130423	7912130412 7912130374	79/12/06 79/11/27	50-346 0A999	S	7912140374 7912140376	7912140367	79/12/07 79/11/30	50-263 FOIA	
7912130427 7912130428	7912130374 7912130374	79/11/27 79/11/27	0A999 0A999		7912140375		79/11/30	FOTA	
7712130431	7912130429	79/11/15	50-553	8	7912140382 7912140382		79/12/07 79/12/08	50-424 50-344	A R
7912130436 7912130441	7912130424 7912130435	79/12/05 79/12/07	50-321 50-320	8 P	7912140385 7912140395 7912140395	7912140312	79/11/30 79/12/12	FO!A 50-338	R
7912130452	7912130449 7912130449	79/12/05 79/11/28	50-400 50-333	\$ 8	791214039		79/12/10	50-259	R
7912130454	7912130440	79/10/22	50-335	8	791214039	7912140386 7912140395	79/12/12 79/12/07	50-280 50-298	B R
7912130457 7912130461	7912130448	79/12/05 79/10/17	50-400 50-354	8 8	791214039 791214040	7912140312	79/11/30 79/11/30	FOIA FOIA	
7912130464 7912130468	7912130456 7912130459	79/11/28	50-334 50-400	8	791214040 791214040			50-237	9
7912130472	7912130448	79/12/05 79/11/26	50-289	8	771214040	7912140312 9 7912140407	79/11/30 79/12/11	FOIA 50-155	6
7912130479 7912130486	7912130367 7912130476	79/12/06	50-346	S A	791214040 791214041	1 7912140410	79/12/07	50-247 50-155	S 8
7912130500 7912130508	7912130493 7912130482	79/11/30	50-447 50-259	P	791214041 791214041		79/12/11 79/12/11	50-219	P
7912130527	7912130484	79/10/23	70-1151	8	791214042	3 7912140420			
7912130532 7912130536	7912130528 7912130534	79/11/02 79/11/30	50-416 50-250	8	791214042 791214042	7 7912140424	74/08/07	RES	в
7912130543 7912130547	7912130541 7912130545	79/12/10 79/12/06	50-317 50-333	g P	791214045 791214045	0 791214042			
7912130550	7912130545	79/12/06		Ъ	79121404		2 79/11/30		_
7912130552 7912130554		79/11/26 79/12/10		P	79121404 79121404	6 791214042		FOIA	
7912130562 7912130567	7912130359	79/11/26			79121404 79121404 79121404	2 791214043	2 79/12/11	, 50~280 ) FOIA	) 5
7912130578									
7912130590				8	79121404 79121404	791214043	8 79/12/19		
7912130401 7912130403	7912130594	79/11/24	PR		79121404 79121404	52 771214031	2 79/11/3	POIA	
7912130619 7912130628	7912130611 7912130615			8	79121404				
7912130634				Ś	79121404 79121404	57 791214045	0 79/12/0	4 50-31	2 8
7912130441 7912130647	7912130639	79/11/15	5 50-335	6	79121404 79121404	A1 791214045	4 78/03/2	4 REB	7 9
7912130656 7912130684	7912130653 7912130667	79/11/15		P	79121404			_	
791213070		79/11/29			79121404 79121404	48 79121404	ja 78/03/2	4 REB	7 9
7912130706 7912130 <b>7</b> 07	7 7912130700	3 79/11/20	9 50-361	Q	79121404 79121404	72 79121403	2 79/11/3	O FOIA	
7912130713 7912130713	3 791213070				7912140	77 79121404			.u 13
791213072	3 791213070		9 50-341	G. P	7912140 7912140	Bi 79121403	12 79/11/3	O FOIA	
791213072 791214002	6 791213043 0 791214000	7 79/12/0	5 PROJ		7912140 7912140 7912140	82 79121404	70 79/12/1 74 78/04/1	27 REB	
791214002 791214004	3 791214001	5 79/12/0	4 50-312 4 50-312		7912140		76 79/12/		
791214011	2 791214010	8 79/12/0		23	7912140 7912140	489 79121404	79 79/12/	10 50-3	31 8
791214011 791214012	9 791214011 1 791214010	4 79/11/0 2 79/11/2	STEAM 6	том	7912140 7912140 7912140	490 79121403	12 79/11/ 59 79/12/	30 FOIA 04 50-2	37 (
791214014 791214015	4 791214013	7 79/11/1		2 G	7912140			30 FOIA	
,									

ACCESS10	NUMBER					ACCESSION				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	Y		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	SUBJECT CATEGOR	Υ
7912140497 7912140498 7912140499 7912140500 7912140501	7912140492 7912140312 7912140495 7912140312 7912140496	79/12/07 79/11/30 78/05/09 79/11/30 79/12/07	50-275 FOIA RES FOIA 50-309	G S		7912170329 7912170335 7912170343 7912170353 7912170355	7912170326 7912170331 7912170338 7912170348 7912170354	79/12/14 79/12/14 79/11/16 79/11/21 79/11/12	50-271 50-313 XPORTLIC XPORTLIC 50-498	S R
7912140503 7912140504 7912140505 7912140508 7912140513	7912140493 7912140312 7912140502 7912140312 7912140312	77/11/11 79/11/30 78/06/07 79/11/30 79/11/30	RES FOIA RES FOIA FOIA			7912170363 7912170366 7912170384 7912170387 7912170389	7912170356 7912170364 7912170381 7912170382 7912170381	79/11/07 79/11/07 79/11/26 79/11/23 79/11/26	XPORTLIC XPORTLIC 27-47 QA999 27-47	
7912140517 7912140524 7912140526 7912140537 7912140545	7912140515 7912140522 7912140522 7912140533 7912140543	78/03/24 78/08/03 78/08/03 79/10/15 79/10/22	REB RES RES SO-311 GA999	s		7912170391 7912170393 7912170398 7912170399 7912170408	7912170362 7912170362 7912170362 7912170394 7912170401	79/11/23 79/11/23 79/11/23 79/11/30 79/11/30	GA999 GA999 GA999 FOIA CONTRACT	
7912170007 7912170010 7912170014 7912170017 7912170019	7912170004 7912170006 7912170006 7912170013 7912170009	79/09/07 79/11/27 79/11/27 79/09/07 79/11/16	50-70 50-364 50-364 50-70 50-289	0 0 0 0		7912170418 7912170420 7912180011 7912180015 7912180019	7912170415 7912170414 7912180006 7912180009 7912180014	79/10/31 79/11/29 79/11/30 79/11/30 79/11/28	50-155 CONTRACT CONTRACT PR CONTRACT	
7912170026 7912170027 7912170030 7912170031 7912170032	7912170021 7912170023 7912170023 7912170021 7912170029	79/11/27 79/11/21 79/11/21 79/11/27 79/10/29	50+946 TOPREP TOPREP 50-546 50-280	A A P		7912160026 7912180037 7912180058 7912180060 7912180063	7912180023 7912180031 7912180056 7912180053 7912180057	79/12/07 79/11/01 79/11/14 79/10/11 79/11/07	CONTRACT CONTRACT 50-387 WASTE MG 50-317	G
7912170036 7912170037 7912170041 7912170048 7912170063	7912170009 7912170029 7912170020 7912170020 791217005B	79/11/16 79/10/29 79/11/30 79/11/30 79/12/01	50-289 50-280 50-522 50-522 50-155	G P G G		7912180065 7912180067 7912180068 7912180070 7912180077	7912180062 7912180053 7912180059 7912180064 7912180064	79/11/09 79/10/11 79/11/21 79/11/27 79/11/27	50-267 WASTE MG 71-206 50-331 50-331	B T P
7912170070 7912170078 7912170087 7912170108 7912170140	7912170066 7912170075 7912170084 7912170106 7912170135	79/11/13 79/11/19 79/11/09 79/10/30 79/11/26	50~267 40~4940 50~29 50~293 50~358	С Р Р		7912180092 7912180107 7912180120 7912180121 7912180124	7912180086 7912180078 7912180113 7912180114 7912180112	79/11/13 79/11/30 79/12/08 79/11/07 79/12/04	70-754 50-277 50-344 50-302 GA999	H G G
7912170144 7912170162 7912170180 7912170185 7912170199	7912170136 7912170155 7912170177 7912170177 7912170193	79/11/19 79/12/12 79/11/21 79/11/21 79/11/27	71-9009 71-27 40-2061 40-2061 080			7912180127 7912180128 7912180130 7912180132 7912180138	7912180113 7912180117 7912180125 7912180112 7912180112	79/12/08 79/11/13 79/11/07 79/12/04 79/12/04	50-344 50-333 50-327 GA999 GA999	e P G
7912170203 7912170208 7912170212 7912170215 7912170219	7912170194 7912170207 7912170207 7912170207 7912170213	79/12/14 79/12/06 79/12/06 79/12/06 79/12/12	50-368 50-466 50-466 50-466 50-331	R G G G		7912180140 7912180142 7912180145 7912180154 7912180156	7912180137 7912180112 7912180141 7912180149 7912180147	79/11/16 79/12/04 79/11/06 79/11/06 79/12/06	71-360 GA999 50-261 50-327 FOIA	Q Q
7912170221 7912170222 7912170223 7912170225 7912170229	7912170207 7912170211 7912170218 7912170207 7912170218	79/12/06 79/10/29 79/12/07 79/12/06 79/12/07	50-466 50-269 50-344 50-466 50-344	G G G G		7912180159 7912180163 7912180166 7912180169 7912180174	7912180153 7912180160 7912180161 7912180164 7912180166	79/12/04 79/12/13 79/12/05 79/12/04 79/12/05	71-239 50-270 50-413 71-354 50-413	P G
7912170230 7912170231 7912170233 7912170236 7912170237	7912170224 7912170224 7912170218 7912170216 7912170218	79/12/05 79/12/12 79/12/07 79/11/13 79/12/07	27-47 50-331 50-344 50-312 50-344	S C C C		7912180181 7912180184 7912180185 7912180186 7912180187	7912180178 7912180179 7912180177 7912180178 7912180180	79/12/07 79/11/14 79/11/26 79/12/07 79/11/21	50-295 40-4492 GA999 50-295 71-358	G G
7912170242 7912170248 7912170252 7912170257 7912170264	7912170218 7912170218 7912170238 7912170238 7912170256	79/12/07 79/12/07 79/12/11 79/12/11 79/12/06	50~344 50~344 50~315 50~315 50~313	6 8 8 8		7912180188 7912180190 7912180196 7912180209 7912180217	7912180177 7912180177 7912180177 7912180202 7912180211	79/11/26 79/11/26 79/11/26 79/12/03 79/12/05	QA779 QA779 QA799 50-445 50-488	M O
7912170249 7912170271 7912170274 7912170278 7912170279	7912170256 7912170260 7912170270 7912170277 7912170275	79/12/06 79/12/12 79/12/13 79/12/07 79/12/06	50-313 50-316 50-319 50-312 50-368	\$ \$ R R		7912180222 7912180231 7912180234 7912180236 7912180240	7912180219 7912180202 7912180228 7912180224 7912180202	79/11/20 79/12/03 79/11/06 79/11/07 79/12/03	ORG 50-445 50-440 50-295 50-445	M G G M
7912170281 7912170285 7912170288 7912170293 7912170297	7912170275 7912170284 7912170287 7912170292 7912170295	79/12/06 79/11/14 79/12/07 79/12/07 79/12/11	50-369 40-2257 50-409 50-204 50-346	s s s		7912180252 7912180253 7912180256 7912180257 7912180261	7912180202 7912180250 7912180247 7912180254 7912180247	79/12/03 79/11/30 79/12/04 79/12/14 79/12/04	50-445 PDR MISO GA979 50-289 GA999	H P
7912170299 7912170303 7912170307 7912170309 7912170314	7912170245 7912170300 7912170302 7912170305 7912170311	79/12/14 79/12/11 79/12/14 79/12/11 79/12/11	50-247 50-346 50-3 50-346 50-206	R 8 8 8		7912180262 7912180264 7912180268 7912180272 7912180273	7912180202 7912180260 7912180247 7912180202 7912180247	79/12/03 79/09/29 79/12/04 79/12/03 79/12/04	50-445 40-8675 GA999 50-445 GA999	M M
7912170315 7912170316 7912170318 7912170321 7912170323	7912170312 7912170304 7912170313 7912170319 7912170317	79/12/11 79/12/11 79/12/07 79/12/11 79/12/07	50-36B 50-321 50-390 50-321 50-390	P 5 5 5		7912180274 7912180275 7912180281 7912180289 7912180297	7912180270 7912180271 7912180202 7912180202 7912180202	79/10/31 79/12/07 79/12/03 79/12/03 79/12/03	50-271 50-302 50-445 50-445 50-445	е Р М М

ACCEBBION	NUMBER				ACCE99100	NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	SUBJECT	
7912180304 7912180307 7912180311 7912180312 7912180314	7912180202 7912180305 7912180202 7912180305 7912180305	79/12/03 79/11/27 79/12/03 79/11/27 79/11/27	50-445 PDR MISC 50-445 PDR MISC PDR MISC	м	7912180517 7912180517 7912180522 7912180527 7912180532 7912180537	7912180508 7912180497 7912180524 7912180528 7912180533	79/12/14 79/05/12 79/12/12 79/11/29 79/12/07	50-255 ACR8 50-361 50-204 50-324	s s s
7912180320 7912180321 7912180324 7912180325 7912180329	7912180202 7912180305 7912180317 7912180302 7912180202	79/12/03 79/11/27 79/11/13 79/12/10 79/12/03	50~445 PBR MISC 50~249 FBIA 50~445	М Р М	7912180541 7912180545 7912180545 7912180555 7912180555	7912180534 7912180540 7912180549 7912180551 7912180554	79/12/14 79/12/14 79/12/11 79/12/06 79/12/07	TOPREP 50-325 50-325 50-312 50-309	8 8 8
7912180330 7912180336 7912180340 7912180342 7912180343	7912180319 7912170302 7912180202 7912180333 7912180337	79/11/14 79/12/10 79/12/03 79/11/06 79/11/06	50-324 FOIA 50-445 50-373 50-324	P M Q Q	7912180567 7912180570 7912180581 7912180582 7912180583	7912180589 7912180564 7912180575 7912180569 7912180577	79/12/12 79/12/12 79/12/13 79/12/14 79/12/12	90-556 50-338 50-336 50-286 50-409	A 8 8 0
7912180345 7912180349 7912180350 7912180351 7912180353	7912180341 7912180202 7912180346 7912180348 7912180347	79/12/12 79/12/03 79/11/28 79/12/11 79/12/05	50-29 50-445 50-251 50-244 50-389	R M P R G	7912180590 7912180591 7912180593 7912180599 7912180609	7912180577 7912180586 7912180588 7912180594 7912180589	79/12/12 79/12/06 79/12/13 79/12/13 79/12/10	50-409 50-278 50-413 50-333 50-336	D 5 5 6
7912180354 7912180357 7912180358 7912180359 7912180360	7912180346 7912180347 7912180346 7912180338 7912180202	79/11/28 79/12/05 79/11/28 79/11/27 79/12/03	50-251 50-387 50-251 71-357 50-445	P G P	7912180602 7912180610 7912180610 7912180616 7912180617	7912180597 7912180596 7912180603 7912180612 7912180609	79/12/13 79/12/12 79/12/07 79/10/30 79/12/12	50-317 50-267 50-325 50-224 50-206	8 9 8 8
7912180361 7912180364 7912180365 7912180367 7912180368	7912180347 7912180355 7912180363 7912180347 7912180362	79/12/05 79/10/15 79/12/07 79/12/05 79/12/12	50-389 50-335 50-245 50-389 50-334	0 0 R 0 R	7912180619 7912180625 7912180628 7912180629 7912180632	7912180608 7912180615 7912180620 7912180623 7912180627	79/12/13 79/12/11 79/12/12 79/12/12 79/12/03	50-317 50-259 50-282 50-259 50-344	8 8 8 8
7912180370 7912180372 7912180381 7912180382 7912180383	7912180352 7912180202 7912180202 7912180374 7912180379	79/11/30 79/12/03 79/12/03 79/11/15 79/12/10	50-254 50-445 50-445 FOIA 50-272	S M M R	7912180634 7912180636 7912180637 7912180639 7912180640	7912180420 7912180420 7912180430 7912180433 7912180420	79/12/12 79/12/12 79/12/12 79/12/11 79/12/12	50-282 50-282 50-293 50-334 50-282	R S B R
7912180384 7912180386 7912180389 7912180395 7912180398	7912180375 7912180377 7912180387 7912180202 7912180391	79/12/14 79/12/07 79/12/12 79/12/03 79/12/14	50-269 50-10 50-309 50-445 50-302	R A R M	7912180641 7912180642 7912180647 7912180649 7912180651	7912180638 7912180635 7912180644 7912180648 7912180648	79/11/29 79/12/12 79/12/11 79/12/04 79/12/04	50-312 50-346 50-277 FOIA FOIA	8
7912180399 7912180403 7912180404 7912180407 7912180414	7912180376 7912180392 7912180202 7912180402 7912180202	79/12/10 79/12/12 79/12/03 79/12/12 79/12/03	50-249 50-336 50-445 50-271 50-445	8 M R M	7912180453 7912180455 7912180457 7912180458 7912180458	7912180648 7912180648 7912180654 7912180648 7912180648	79/12/04 79/12/04 79/11/20 79/12/04 79/12/04	FOIA FOIA 71-352 FOIA FOIA	
7912180417 7912180421 7912180422 7912180423 7912180423	7912180412 7912180412 7912180410 7912180202 7912180412	79/12/04 79/12/04 79/12/10 79/12/03 79/12/04	50-445 50-445 50-3 50-445 50-445	I G M I	7912180663 7912180664 7912180666 7912180667 7912180667	7912180648 7912180648 7912180648 7912180648 7912180648	79/12/04 79/12/04 79/12/04 79/12/04 79/12/04	FOIA FOIA FOIA FOIA	
7912180426 7912180429 7912180431 7912180434 7912180441	7912180418 7912180413 7912180419 7912180430 7912180437	79/12/12 79/12/14 79/12/06 79/12/10 79/12/12	50-244 50-267 50-249 50-321 50-213	P R S R R	7912180671 7912180672 7912180674 7912180676 7912180677	7912180648 7912180648 7912180648	79/12/04 79/12/04 79/12/04 79/12/04 79/12/04	FOIA FOIA FOIA FOIA	
7912180443 7712180445 7912180448 7912180449 7912180461	7912180438 7912180439 7912180444 7912180446 7912180457	79/12/10 79/12/07 79/11/04 79/12/10 79/03/12	50-366 50-528 27-39 50-266 ACRS	R Q R	7912180678 7912180679 7912180687 7912180687 7912180683	7912180649 7912180649 7912180649	79/12/04 79/12/04 79/12/04 79/12/04 79/12/04	FDIA FOIA FOIA FOIA	
7912180462 7912180467 7912180469 7912180475 7912180480	7912180457 7912180464 7912180456 7912180468 7912180468	79/05/12 79/11/13 79/12/13 79/11/15 79/11/15	ACRS GA999 50-317 50-275 50-275	8 U U	7912180684 7912180685 7912180685 7912180686 7912180685	7912180648 7912180648 7912180648	79/12/04 79/12/04 79/12/04 79/12/04 79/12/04	FOIA FOIA FOIA FOIA	
7912180482 7912180484 7912180488 7912180489 7912180491	7912180477 7912180468 7912180468 7912180486 7912180483	79/12/06 79/11/15 79/11/15 79/12/12 79/12/11	50-324 50-275 50-275 50-271 50-320	8 U U B P	7912180690 7912180691 7912180697 7912180698 7912180698	7912180648 7912180648 7912180648	79/12/04	FOIA FOIA FOIA FOIA	
7912180492 7912180493 7912180498 7912180502 7912180503	7912180483 7912180468 7912180494 7912180468 7912180500	79/12/11 79/11/15 79/12/13 79/11/15 79/10/11	90-320 50-275 50-324 50-275 50-267	P U B U R	7912180692 7912180692 7912180692 7912180692 7912180702	7 7912180648 7912180648 7 7912180648	79/12/04 79/12/04 79/12/04	FOIA FOIA FOIA FOIA	
7912180507 7912180510 7912180512 7912180513 7912180514	7912180468 7912180468 7912180508 7912180509 7912180508	79/11/15 79/11/15 79/12/14 79/09/18 79/12/14	50-275 50-275 50-255 50-267 50-255	U B R 8	791218070; 791218070; 791218070; 791219000; 791219000;	3 7912180648 4 7912180648 2 7912190001	79/12/04 79/12/04 79/12/07	FOIA FOIA FOIA 50-133	

ACCESSIO					ACCESSION NUMBER	
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR		PRINCIPAL DATE ENCLOGURE DOCUMENT ISSUED	BUBJECT CATEGORY
7912190004 7912190009 7912190012 7912190035 7912190045	7912190001 7912190005 7912190008 7912190008 7912190008	79/12/07 79/11/28 79/11/27 79/11/27 79/11/27	50-133 50-309 50-275 50-275 50-275	о н н	7912190319 7912190227 79/11/0 7912190321 7912190274 79/06/1 7912190323 7912190187 79/12/0 7912190325 7912190274 79/06/1 7912190330 7912190274 79/06/1	7 50-445 M 4 ACRS 7 FOIA 4 ACRS
7912190052 7912190062 7912190064 7912190066 7912190077	7912190042 7912190057 7912190051 7912190057 7912190069	79/12/07 79/12/03 79/11/12 79/12/03 79/12/03	50-312 50-244 ORQ 50-244 50-285	G P P	7912190332 7912190187 79/12/0 7912190336 7912190274 79/06/1 7912190338 7912190187 79/12/0 7912190341 7912190274 79/06/1 7912190346 7912190274 79/06/1	6 ACRS 7 FOIA 6 ACRS
7912170088 7912170092 7912170098 7912170105 7912170106	7912190082 7912190085 7912190091 7912190091 7912190096	79/11/29 79/11/14 79/11/30 79/11/30 79/12/05	50-280 50-272 50-142 50-142 FOIA	0	7912190347 7912190187 79/12/0 7912190351 7912190187 79/12/0 7912190352 7912190274 79/06/1 7912190356 7912190274 79/06/1 7912190357 7912190187 79/12/0	7 FOIA 6 ACRS 6 ACRS
7912190109 7912190112 7912190114 7912190115 7912190117	7912190102 7912190096 7912190107 7912190096 7912190096	79/11/28 79/12/05 79/12/17 79/12/05 79/12/05	50-363 FOIA 50-3 FOIA FOIA	<b>С</b>	7912190359 7912190355 79/10/1 7912190360 7912190187 79/12/0 7912190362 7912190274 79/06/1 7912190367 7912190187 79/12/0 7912190373 7912190187 79/12/0	7 FOIA 6 ACRS 7 FOIA
7912190119 7912190122 7912190125 7912190126 7912190128	7912170091 7912170096 7912170091 7912170096 7912170096	79/11/30 79/12/05 79/11/30 79/12/05 79/12/05	50-142 FDIA 50-142 FDIA FOIA	G G	7912190375 7912170274 79/06/1 7912190382 7912190187 79/12/0 7912190390 7912190379 79/12/1 7912190405 7912190398 79/12/1 7912190414 7912190409 79/12/0	7 FOIA 7 50-344 P 4 50-331 R
7912190135 7912190136 7912190139 7912190144 7912190145	7912190096 7912190131 7912190096 7912190131 7912190096	79/12/05 79/11/07 79/12/05 79/11/07 79/12/05	FOIA 40-8727 FOIA 40-8727 FOIA		7912190424 7912190416 79/12/1: 7912190428 7912190422 79/11/3: 7912190436 7912190422 79/11/3: 7912190448 7912190422 79/11/3: 7912190433 7912190422 79/11/3:	D FOIA D FOIA D FOIA
7912190148 7912190150 7912190152 7912190159 7912190166	7912190131 7912190141 7912190096 7912190096 7912190096	79/11/07 79/11/26 79/12/05 79/12/05 79/12/05	40-8727 50-278 FOIA FOIA FOIA	q	7912190474 7912190469 79/12/14 7912190479 7912190473 79/11/14 7912190487 7912190466 79/12/14 7912190496 7912190466 79/12/14 7912190521 7912190515 79/12/14	4 71-358 4 50-255 P 4 50-255 P
7912190171 7912190173 7912190179 7912190183 7912190186	7912190096 7912190165 7912190096 7912190096 7912190165	79/12/05 79/11/29 79/12/05 79/12/05 79/11/29	FOIA 50-528 FOIA FOIA 50-528	A	7912190522 7912190520 79/12/01 7912190531 7912190527 79/11/30 7912190532 7912190402 79/12/01 7912190541 7912190538 79/12/01 7912190545 7912190542 79/12/1	) PDR MISC 5 50-346 P 9 PDR MISC
7912190190 7912190191 7912190194 7912190194 7912190201	7912190096 7912190170 7912190096 7912190187 7912190096	79/12/05 79/12/04 79/12/05 79/12/07 79/12/05	FOIA 50-322 FOIA FOIA FOIA	G	7912190575 7912190574 79/12/15 7912190401 7912190597 79/12/15 7912190410 7912190578 79/11/25 7912190415 7912190402 79/12/15 7912190426 7912190402 79/12/16	TOPREP 50-546 8 50-361 6
7912190204 7912190210 7912190214 7912190222 7912190225	7912190187 7912190197 7912190187 7912190187 7912190184	79/12/07 79/10/05 79/12/07 79/12/07 79/12/02	FOIA 50-482 FOIA FOIA WASTE MOI	G T	7912190659 7912190631 79/12/0 7912190664 7912190631 79/12/0 7912190671 7912190631 79/12/0 7912190678 7912190631 79/12/0 7912190683 7912190631 79/12/0	7 50-219 P 7 50-219 P 7 50-219 P
7912190226 7912190236 7912190237 7912190242 7912190245	7912190187 7912190187 7912190230 7912190230 7912190230	79/12/07 79/12/07 79/11/27 79/11/27 79/11/27	FOIA FOIA 50-275 FDIA 50-275	0 0	7912190698 7912190692 79/11/24 7912190703 7912190631 79/12/07 7912190707 7912190631 79/12/07 7912190713 7912190710 79/11/3 7912190714 7912190705 79/12/15	7 50-219 P 7 50-219 P 0 50-369 S
7912190247 7912190249 7912190253 7912190254 7912190257	7912190187 7912190187 7912190187 7912190251 7912190187	79/12/07 79/12/07 79/12/07 79/11/08 79/12/07	FOIA FOIA FOIA 71-357 FOIA		7912190721 7912190705 79/12/10 7912190775 7912190748 79/11/15 7912190781 7912190748 79/11/15 7912190792 7912190784 79/11/07 7912190794 7912190789 79/11/21	70-1100 70-1100 7 50-255 Q
7912190265 7912190266 7912190269 7912190278 7912190280	7912190227 7912190259 7912190264 7912190274 7912190275		TOM STEAM	M P	7912190797 7912190787 79/10/26 7912190799 7912190786 79/11/07 7912200002 7912200001 79/11/07 7912200011 7912200008 79/11/30 7912200015 7912200008 79/11/30	7 50-255 Q 7 27-47 9 71-4581
7912190282 7912190286 7912190289 7912190289 7912190297	7912190274 7912190197 7912190187 7912190187 7912190274	79/06/16 79/12/07 79/12/07 79/12/07 79/06/16	ACRB FDIA FOIA FOIA ACRB		7912200020 7912200008 79/11/30 7912200029 7912200030 79/11/30 7912200035 7912200030 79/11/16 7912200037 7912200031 79/11/16 7912200046 7912200043 79/11/01	71-6581 71-88 CONTRACT
7912190298 7912190301 7912190302 7912190304 7912190308	7912190227 7912190187 7912190292 7912190274 7912190187	79/11/07 79/12/07 79/12/04 79/06/16 79/12/07	50-445 FOIA PDR MISC ACRS FOIA	м	7912200053 7912200049 79/12/10 7912200054 791220050 79/11/15 7912200057 791220050 79/11/15 7912200064 7912200060 79/12/10 7912200066 7912200063 79/11/30	90-219 F 90-219 F 9 50-320 H
7912190311 7912190313 7912190315 7912190316 7912190316	7912190274 7912190187 7912190274 7912190310 7912190187	79/06/16 79/12/07 79/06/16 79/12/03 79/12/07	ACRS FOIA ACRB 50-155 FOIA	<b>Q</b>	7912200067 7912200054 79/10/80 7912200071 7912200063 79/11/30 7912200072 7912200068 79/11/30 7912200074 7912200068 79/11/30 7912200078 7912200069 79/11/30	90-289 G 50-244 G 50-246 G

	ON NUMBER				ACCESSIO	IN NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT		ENCLOSURE	PRINCIPAL	DATE	SUBJEC	
7912200079 7912200081 7912200084 7912200088 7912200095	7912200048 7912200076 7912200049 7912200076 7912200092	79/11/30 79/11/19 79/11/30 79/11/19 79/11/19	50-246 70-371 PDR MISO 70-371 70-135	Q	791220089 791220089 7912200605 7912200605 7912200621	7912200578 7912200577 7912200403 7912200403 7912200408 7912200417	188UED 79/12/14 79/11/07 79/12/03 79/11/06 79/11/05	CATEGO: 50-537 50-454 50-548 70-27 50-438	A G H
7912200096 7912200100 7912200118 7912200132 7912200140	7912200090 7912200092 7912200114 7912200124 7912200124	79/12/06 79/11/19 79/11/20 79/11/05 79/11/05	50-424 70-135 50-305 71-349 71-349	F	7912200441 7912200445 7912200446 7912200448 7912200451	7912200637 7912200642 7912200637 7912200642 7912200642	79/12/06 79/12/06 79/12/06 79/12/06 79/12/06	50-213 50-329 50-213 50-329 50-329	G G G
7912200154 7912200165 7912200167 7912200168 7912200173	7912200146 7912200162 7912200159 7912200158 7912200169	79/11/08 79/11/15 79/11/01 79/11/27 79/11/09	71-179 40-3453 50-247 50-275 40-8102	Q C	7912200457 7912200460 7912200467 7912200484 7912200492	7912200652 7912200652 7912200652 7912200677 7912200677	79/12/05 79/12/05 79/12/05 79/10/25 79/10/25	50-334 50-334 50-334 50-367 50-367	0 0 U
7912200175 7912200182 7912200183 7912200194 7912200194	7912200149 7912200177 7912200179 7912200189 7912200187	79/11/23 79/11/06 79/12/03 79/11/07 79/11/06	CONTRACT CONTRACT CONTRACT 50-263 GA999		7912210009 7912210012 7912210013 7912210016 7912210017	7912210006 7912210001 7912210008 7912210010 7912210001	79/12/10 79/11/29 79/12/12 79/12/10 79/11/29	50-424 GA999 50-282 50-348 GA999	A P G
7912200198 7912200213 7912200250 7912200276 7912200308	7912200190 7912200206 7912200242 7912200270 7912200296	79/11/27 79/10/31 79/11/13 79/11/27 79/10/26	CONTRACT 50-219 50-346 50-3 70-33	0 0 0	7912210019 7912210020 7912210021 7912210024 7912210029	7912210014 7912210001 7912210010 7912210014 7912210001	79/12/17 79/11/29 79/12/10 79/12/17 79/11/29	50-387 QA779 50-348 50-387 QA779	0 0 0
7912200313 7912200316 7912200318 7912200322 7912200324	7912200303 7912200312 7912200303 7912200312 7912200303	79/11/21 79/11/20 79/11/21 79/11/20 79/11/21	50-220 50-337 50-220 50-337 50-220	Q A Q A Q	7912210031 7912210032 7912210033 7912210036 7912210038	7912210025 7912210001 7912210028 7912210001 7912210034	79/11/16 79/11/29 79/11/09 79/11/29 79/12/12	50-237 QA779 50-483 QA779 50-62	o o o
7912200328 7912200332 7912200333 7912200334 7912200345	7912200312 7912200303 7912200317 7912200312 7912200312	79/11/20 79/11/21 79/10/29 79/11/20 79/11/20	50~337 50-220 70-371 50-339 50-339	A A A	7912210043 7912210046 7912210046 7912210058 7912210061	7912210034 7912210034 7912210034 7912210052 7912210052	79/12/12 79/12/12 79/12/12 79/12/11 79/12/11	50-62 50-62 50-62 50-83 50-83	Q Q Q Q
7912200349 7912200351 7912200357 7912200360 7912200362	7912200342 7912200312 7912200312 7912200353 7912200312	79/12/14 79/11/20 79/11/20 79/12/14 79/11/20	50-286 50-339 50-339 50-293 50-339	R A A B A	7912210063 7912210069 7912210074 7912210078 7912210080	7912210052 7912210052 7912210066 7912210072 7912210075	79/12/11 79/12/11 79/11/16 79/11/23 79/12/10	50-83 50-83 50-292 50-312 50-249	0 0 0
7912200360 7912200370 7912200375 7912200376 7912200382	7912200365 7912200312 7912200372 7912200312 7912200312	79/12/17 79/11/20 79/12/01 79/11/20 79/11/20	50-289 50-339 50-293 50-339 50-339	R A R A	791221008B 7912210089 7912210103 7912210114 7912210114	7912210078 7912210071 7912210096 7912210100 7912210100	79/12/10 79/10/31 79/11/27 79/12/04 79/12/04	50-249 50-358 50-284 27-48 27-48	Ω U Q
7912200388 7912200393 7912200393 7912200399 7912200400	7912200312 7912200312 7912200344 7912200312 7912200396	79/11/20 79/11/20 79/11/07 79/11/20 79/12/18	50-339 50-339 27-47 50-339 50-545	A A B	7912210133 7912210136 7912210145 7912210147 7912210152	7912210124 7912210132 7912210135 7912210140 7912210135	79/10/31 79/12/07 79/12/04 79/12/05 79/12/06	50-275 50-206 50-491 50-346 50-491	U G G
7912200403 7912200410 7912200413 7912200418 7912200422	7912200312 7912200312 7912200312 7912200312 7912200312	79/11/20 79/11/20 79/11/20 79/11/20 79/11/20	50-339 50-339 50-339 50-339 50-339	A A A A	7912210154 7912210155 7912210160 7912210161 7912210162	7912210150 7912210132 7912210141 7912210133 7912210132	79/11/08 79/12/07 79/12/05 79/12/06 79/12/07	50-373 50-206 XPORTLIC 50-491 50-206	0 0 0
7912200424 7912200433 7912200440 7912200453 7912200457	7912200312 7912200426 7912200438 7912200446 7912200449	79/11/20 79/11/19 79/12/17 79/11/28 79/11/02	TOM STRAW	A F O	7912210167 7912210172 7912210178 7912210178 7912210181	7912210166 7912210135 7912210141 7912210164 7912210177	79/12/20 79/12/06 79/12/05 79/10/12 79/12/05	50-395 50-491 XPORTLIC 50-437 50-321	F G U
7912200458 7912200460 7912200463 7912200465 7912200469	7912200452 7912200452 7912200452 7912200452 7912200452	79/12/14 79/12/14 79/12/14 79/12/14 79/12/14	50-123 50-123 50-123	₽ ₽ ₽ ₽	7912210139 7912210191 7912210197 7912210197 7912210197	7912210165 7912210034 7912210168 7912210190 7912210196	79/11/29 79/12/12 79/12/20 79/10/24 79/11/06	71-114 50-62 50-466 50-219 0A999	G A U
7912200472 7912200475 7912200478 7912200499 7912200506	7912200466 7912200474 7912200474 7912200491 7912200505	79/11/01 79/11/16 79/11/16 79/11/16 79/11/06 79/12/17	50-29 50-29 GA999	a Q Q P	7912210201 7912210210 7912210210 7912210212 7912210218	7912210198 7912210198 7912210209 7912210202 7912210203	79/11/29 79/11/29 79/12/20 79/12/05 79/11/09	0A999 0A999 50-466 50-259 50-259	II G G
7912200512 7912200515 7912200516 7912200525 7912200526	7912200509 7912200509 7912200510 7912200520 7912200521	79/12/18 79/12/18 79/11/02 79/12/11 79/10/26	50-316 70-364 50-313	P P K	7912210219 7912210222 7912210228 7912210233 7912210235	7912210198 7912210198 7912210216 7912210198 7912210224	79/11/29 79/11/29 79/10/29 79/11/29 79/11/29	GA999 GA999 50-275 GA999 70-1151	U
7912200534 7912200544 7912200556 7912200571 7912200582	7912200530 7912200541 7912200551 7912200568 7912200577	79/10/29 79/12/14 79/12/10 79/12/07 79/11/07	50-361 50-29 50-409	G 5 5 3	7912210238 7912210248 7912210243 7912210264 7912210277	7912210227 7912210227 7912210227 7912210253 7912210272	79/12/11 79/12/11 79/12/11 79/10/12 79/10/26	50-269 50-269 50-269 50-352 40-8740	0 0 0 V

ACCESSION NUMBER					ACCESSION NUMBER						
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT	Y	ENCLOBU	RE	PRINCIPAL DOCUMENT	DATE IBSUED	SUBJECT CATEGORY	_	
7912210283 7912210286 7912210290 7912210295 7912210296	7912210227 7912210272 7912210272 7912210272 7912210272 7912210273	79/12/11 79/10/26 79/10/26 79/10/26 79/09/18	50-269 40-8748 40-8748 40-8748 71-9932	G.	7912260 7912260 7912260 7912260 7912260	)141 )144 )145 )146	7912260096 7912260140 7912260142 7912260096 7912260096	79/11/29 79/11/16 79/11/09 79/11/29 79/11/29	QA999 30-155 27-47 QA999 QA999	G	
7912210310 7912210312 7912210322 7912210323 7912210324	7912210306 7912210300 7912210316 7912210317 7912210314	79/12/14 79/10/26 79/12/17 79/10/26 79/11/09	50-219 40-8745 50-333 40-8749 50-389	R S T	7912260 7912260 7912260 7912260 7912260	0153 0154 0155	7912240147 7912240148 7912240152 7912240094 7912240152	79/11/16 79/11/16 79/12/10 79/11/29 79/12/10		G G	
7912210328 7912210331 7912210336 7912210343 7912210344	7912210317 7912210319 7912210327 7912210332 7912210340	79/10/26 79/11/01 79/12/17 79/12/06 79/12/10	40-8745 50-318 50-333 50-206 50-424	9 9 P B	7912240 7912240 7912240 7912240 7912240	0159 0144 0145	7912260152 7912260152 7912260131 7912260161 7912260161	79/12/10 79/12/10 79/11/27 79/11/29 79/11/29	XPORTLIC XPORTLIC	Þ	
7912210346 7912210353 7912210354 7912210356 7912210363	7912210341 7912210347 7912210336 7912210346 7912210357	79/12/10 79/12/13 79/12/14 79/12/13 79/11/01	71-5086 TOPREP 50-219 50-327 50-244	S A G	7912260 7912260 7912260 7912260 7912260	0174 0175 0178	7912260167 7912260161 7912260171 7912260171 7912260171	79/11/15 79/11/29 79/12/11 79/12/11 79/12/11	XPDRTLIC 70-143 70-143 70-143	Q	
7912210364 7912210376 7912210383 7912210387 7912210405	7912210340 7912210373 7912210382 7912210385 7912210402	79/12/14 79/12/13 79/11/06 79/11/06 79/12/13	50-546 50-267 CONTRACT CONTRACT FOIA		7912240 7912240 7912240 7912240 7912240	0196 0198 0202	7912260185 7912260189 7912260185 7912260185 7912260185	79/12/12 79/11/29 79/12/12 79/12/12 79/12/12	GA999 XPORTLIC GA999 GA999 GA999		
7912210407 7912210409 7912210411 7912210424 7912210425	7912210402 7912210402 7912210402 7912210402 7912210419	79/12/13 79/12/13 79/12/13 79/12/13 79/12/03	FOIA FOIA FOIA FOIA 71-5467		7912260 7912260 7912260 7912260 7912260	0206 0208 0212	7912240185 7912240185 7912240205 7912240205 7912240210	79/12/12 79/12/12 79/12/04 79/12/04 79/11/13	GA999 GA999 XPORTLIC XPORTLIC 50-362	G	
7912210426 7912210428 7912210429 7912210430 7912210432	7912210402 7912210402 7912210418 7912210402 7912210402	79/12/13 79/12/13 79/11/27 79/12/13 79/12/13	FOIA FOIA 71-364 FOIA FOIA		7912260 7912260 7912260 7912260 7912260	0217 0218 0224	7912260207 7912260215 7912260216 7912260221 7912260228	79/12/04 79/12/11 79/12/19 79/12/14 79/12/10	50-312	P 6 8 8 8	
7912210434 7912210435 7912210437 7912210441 7912210443	7912210419 7912210402 7912210433 7912210438 7912210438	79/12/03 79/12/13 79/11/21 79/12/04 79/12/04	71-5467 FOIA 71-363 50-155 50-155	G G	7912260 7912260 7912260 7912260 7912260	0237 0241 0243	7912260227 7912261234 7912260238 7912260239 7912260242	79/11/19 79/12/15 79/12/17 79/12/10 79/12/12	50-243 50-346 50-368 50-302 50-293	P S P S P	
7912260014 7912260017 7912260038 7912260041 7912260046	7912260011 7912260012 7912260036 7912260040 7912260043	79/12/03 79/11/21 79/12/04 79/12/10 79/11/07	XPORTLIC TOPREP 71-60 71-6078 70-371		7912260 7912260 7912260 7912260 7912260	0254 0258 0268	7912260247 7912260245 7912260253 7912260267 7912260265	79/12/14 79/12/17 79/12/18 79/12/10 79/12/14	50-321 50-302 50-346 50-220 50-366	8 8 8	
7912260047 7912260049 7912260055 7912260056 7912260061	7912260042 7912260045 7912260052 7912260051 7912260054	79/11/15 79/12/10 79/12/06 79/11/07 79/11/19	71-9006 71-9001 71-24 50-289 50-54	Q Q	791226C 791226C 791226C 791226C 791226C	0277 0281 0283	7912260272 7912260273 7912260278 7912260279 7912260280	79/12/18 79/12/13 79/12/17 79/12/12 79/12/18	50-313 50-312 50-273 50-312 50-275	8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	
7912260063 7912260064 7912260068 7912260071 7912260074	7912260059 7912260062 7912260054 7912260066 7912260054	79/11/06 79/11/13 79/11/19 79/11/06 79/11/19	70-820 50-317 50-54 70-1143 50-54	8 0 0	791226( 791226( 791226( 791226( 791226(	0302 0306 0315	7912240294 7912260301 7912260303 7912260309 7912260327	79/11/06 79/11/08 79/11/16 79/12/05 79/12/17	50-352 50-29 50-327 50-289 50-312	G G P O	
7912260078 7912260085 7912260088 7912260091 7912260095	7912260072 7912260072 7912260081 7912260087 7912260092	79/11/08 79/11/08 79/12/14 79/11/09 79/10/26	27-47 27-47 50-445 50-461 50-333	И G G	791226( 791226( 791226( 791226( 791226)	0333 0335 0337	7912260330 7912260332 7912260332 7912260332 7912260332	79/11/02 79/11/23 79/11/23 79/11/23 79/11/23	50-134 50-387 50-387 50-387 50-387	G G G	
7912260098 7912260104 7912260105 7912260106 7912260111	7912260094 7912260096 7912260102 7912260103 7912260096	79/11/09 79/11/29 79/11/06 79/12/11 79/11/29	50-266 GA999 50-282 40-2061 GA999	a a	791226( 791226( 791226( 791226( 791226(	0345 0346 0348	7912260327 7912260327 7912260309 7912260309 7912260347	79/12/17 79/12/17 79/12/05 79/12/05 79/12/04	50-312 50-312 50-289 50-289 50-373	9 9 9 9	
7912260115 7912260116 7912260119 7912260120	7912260109 7912260113 7912260113 7912260109 7912260113	79/11/21 79/11/30 79/11/30 79/11/21 79/11/30	50-277 50-213 50-213 50-277 50-213	0 0 0 0	791224 791224 791225 791224 791227	0354 0355 0375	7912260347 7912260347 7912260347 7912260372 7912270001	79/12/04 79/12/04 79/12/04 79/12/11 79/10/09	50-373 50-373 50-373 50-443 PDR MISC	0	
7912260122 7912260125 7912260130 7912260133 7912260134	7912260113 7912260096 7912260096 7912260129 7912260132	79/11/30 79/11/29 79/11/29 79/10/30 79/12/11	50-213 GA999 GA999 50-329 50-228	Q Q Q	791227 791227 791227 791227 791227	0009 0021 0023	7912270004 7912270004 7912270018 7912270018 7912270018	79/12/06 79/12/06 79/12/07 79/12/07 79/12/07	50-329 50-329 50-315 50-315 50-315	0 P P	
7912260135 7912260136 7912260137 7912260138 7912260139	7912260132 7912260132 7912260129 7912260096 7912260132	79/12/11 79/12/11 79/10/30 79/11/29 79/12/11	50-228 50-228 50-329 GA779 50-228	0 0 0	791227 791227 791227 791227 791227 791227	70039 70052 70055	7912270027 7912270033 7912270648 7912270051 7912270054	79/12/07 79/10/31 79/11/29 79/11/28 79/12/14	71-250 PDR MISC 50-478 71-6206 50-522	M	

ACCESS10	N NUMBER					ACCESSION	NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSVED	SUBJECT CATEGORY			ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	BUBJECT CATEGORY	
7912270058 7912270059 7912270069 7912270077 7912270078	7912270051 7912270054 7912270067 7912270062 7912270072	79/11/28 79/12/14 79/11/26 79/10/12 79/12/07	71-6206 50-522 40-8745 COMMISSIO	0		7912270542 7912270545 7912270551 7912270552 7912270558	7912270515 7912270540 7912270537 7912270540 7912270540	79/12/14 79/12/21 79/12/20 79/12/21 79/12/21	50-263 50-325 50-263	5 F 5 P
7912270085 7912270099 7912270114 7912270117 7912270125	7912270083 7912270097 7912270110 7912270110 7912270122	79/12/03 79/12/07 79/11/30 79/11/30 79/11/28	COMMISSIO COMMISSIO COMMISSIO COMMISSIO COMMISSIO	DN DN DN	•	7912270560 7912270561 7912270562 7912270569 7912270570	7912270547 7912270549 7912270553 7912270555 7912270559	79/12/20 79/12/14 79/12/21 79/12/16 79/12/20	50-324 50-286 50-341	5 6 8 A S
7912270131 7912270135 7912270149 7912270150 7912270152	7912270122 7912270122 7912270122 7912270147 7912270148	79/11/28 79/11/28 79/11/28 79/11/27 79/12/07	COMMISSIC COMMISSIC COMMISSIC 50-387 PDR MISC	ON ON G		7912270571 7912270574 7912270580 7912270583 7912270585	7912270563 7912270564 7912270569 7912270572 7912270577	79/12/19 79/12/19 79/12/19 79/12/20 79/12/20	50-294 50-263 50-325	9 9 9 9 1
7912270154 7912270156 7912270158 7912270160 7912270161	7912270122 7912270153 7912270122 7912270122 7912270153	79/11/28 79/12/20 79/11/28 79/11/28 79/12/20	COMMISSIO COMMISSIO COMMISSIO 50-313	Р ОИ		7912270987 7912270588 7912270591 7912270592 7912270598	7912270581 7912270582 7912270584 7912270547 7912270590	79/12/17 79/12/20 79/12/20 79/12/20 79/12/19	50-338 50-272 50-280	9 6 9 9 9
7912270172 7912270178 7912270180 7912270190 7912270196	7912270167 7912270167 7912270173 7912270188 7912270191	79/11/23 79/11/23 79/11/04 79/12/19 79/12/20	50-364 50-364 70-1143 50-247 50-266	A P F		7912270599 7912270600 7912270602 7912280006 7912280007	7912270594 7912270595 7912270590 7912280003 7912280033	79/12/18 79/12/20 79/12/19 79/11/20 79/12/12	50~272	8 8 8
7912270197 7912270204 7912270207 7912270220 7912270220	7912270193 7912270182 7912270200 7912270206 7912270212	79/12/19 79/12/14 79/12/15 79/12/19 79/12/19	50-329 50-293 NUREG 50-266 50-348	А Б Р Б		7912280038 7912280089 7912280102 7912280108 7912280132	7912280033 7912280082 7912280082 7912280082 7912280124	79/12/12 79/10/31 79/10/31 79/10/31 79/12/05	71-6698 40-8674 40-8674 40-8674 NUREO	
7912270236 7912270238 7912270243 7912270253 7912270255	7912270232 7912270212 7912270232 7912270249 7912270248	79/12/14 79/12/19 79/12/14 79/12/20 79/12/10	50-247 50-348 50-247 50-320 71-358	P S P P		7912280137 7912280139 7912280148 7912280154 7912280157	7912280130 7912280133 7912280133 7912280153 7912280152	79/12/19 79/12/07 79/12/07 79/12/11 79/11/14	50-344 WASTE MGT WASTE MGT XPORTLIC 50-395	
7912270256 7912270262 7912270265 7912270275 7912270276	7912270251 7912270251 7912270254 7912270267 7912270269	79/12/17 79/12/17 79/12/21 79/12/21 79/12/19	50-259 50-259 50-237 50-3 50-344	Р Р Б Р Г		7912280143 7912280148 7912280149 7912280171 7912280174	7912280159 7912280133 7912280133 7912280133 7912280159	79/12/13 79/12/07 79/12/07 79/12/07 79/12/13	50~369 WASTE MGT WASTE MGT WASTE MGT 700~369	F
7912270282 7912270290 7912270295 7912270301 7912270304	7912270278 7912270286 7912270289 7912270279 7912270279	79/12/17 79/12/20 79/12/13 79/12/07 79/12/20	50-368 50-272 50-327 50-324 50-260	R S K S		7912280177 7912280182 7912280192 7912280202 7912280206	7912280133 7912280133 7912280133 7912280133 7912280198	79/12/07 79/12/07 79/12/07 79/12/07 79/12/20	WASTE MOT WASTE MOT WASTE MOT SO-244	r T
7912270308 7912270311 7912270317 7912270328 7912270334	7912270298 7912270307 7912270306 7912270323 7912270329	79/12/17 79/12/20 79/12/17 79/12/11 79/12/12	50-387 50-280 50-325 50-289 50-312	6 8 9		7912280210 7912280213 7912280222 7912280232 7912280232	7912280133 7912280198 7912280198 7912280198 7912280198	79/12/20 79/12/20 79/12/20 79/12/20 79/12/20	WASTE MO' 50-244 50-244 50-244 50-244	T P P P
7912270330 7912270373 7912270389 7912270397 7912270390	7912270332 7912270339 7912270384 7912270390 7912270395	79/12/19 79/12/17 79/12/17 79/12/19 79/12/20	50-271 50-3 50-348 50-341 50-344	9 R A S		7912280257 7912280268 7912280279 7912280281 7912280287	7912280226 7912280264 7912280274 7912280275 7912280253	79/12/10 79/11/30 79/11/30 79/12/12 79/11/15	50-599 50-320 50-320 50-346 50-320	0 H H P U
7912270407 7912270414 7912270420 7912270433 7912270442	7912270402 7912270406 7912270413 7912270426 7912270434	79/12/20 79/12/19 79/12/20 79/12/20 79/12/21	50-346 50-324 50-346 50-267 50-244	9 9 9 9		7912280290 7912280293 7912280295 7912280301 7912280303	7912280275 7912280288 7912280285 7912280286 7912280285	79/12/12 79/11/30 79/11/19 79/09/26 79/11/19	50-346 50-320 40-2259 50-320 40-2259	P H G
7912270447 7912270455 7912270460 7912270476 7912270477	7912270335 7912270335 7912270335 7912270473 7912270472	79/12/10 79/12/18 79/12/18 79/12/18 79/12/17	50-284 50-284 50-284 50-327 50-321	9 9 8 8		7912280304 7912280311 7912280313 7912280316 7912280321	7912280298 7912280285 7912280299 7912280309 7912280320	79/11/30 79/11/19 79/11/15 79/11/30 79/11/30	50-320 40-2259 50-320 50-320 50-320	Н И Н
7912270483 7912270484 7912270489 7912270490 7912270498	7912270475 7912270480 7912270482 7912270487 7912270491	79/12/17 79/12/18 79/12/19 79/12/20 79/12/21	50-296 50-390 50-321 50-326 50-282	8 8 8 9		7912280325 7912280328 7912280329 7912280331 7912280337	7912280285 7912280326 7912280322 7912280285 7912280332	79/11/19 79/11/30 79/11/14 79/11/19 79/11/30	40-2259 50-320 50-498 40-2259 50-320	Н 0
7912270499 7912270500 7912270506 7912270509 7912270510	7912270492 7912270495 7912270502 7912270503 7912270497	79/12/21 79/12/17 79/12/19 79/12/21 79/12/14	50-266 50-266 50-334 50-270 50-278	P B B B		7912280339 7912280342 7912280346 7912280348 7912280360	7912280285 7912280330 7912280285 7912280340 7912280285	79/11/19 79/10/12 79/11/19 79/11/30 79/11/19	40-2259 50-320 40-2259 50-320 40-2259	Q H
7912270520 7912270528 7912270535 7912270536 7912270541	7912270502 7912270518 7912270522 7912270526 7912270529	79/12/19 79/12/20 79/12/19 79/12/14 79/12/19	50-334 50-325 50-325 50-324 50-325	8 8 8		7912280361 7912280373 7912280385 7912280392 7912280393	7912280353 7912280367 7912280378 7912280379 7912280388	79/11/30 79/11/30 79/11/30 79/10/19 79/11/30	50-320 50-320 50-320 50-320 50-320	H H Q H

ACCESSION NUMBER					ACCESSION NUMBER						
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	SUBJECT CATEGOR	,			ENCLOSURE	PRINCIPAL DOCUMENT	DATE 185UED	SUBJECT CATEGOR	
7918280397 7912280406 7912280410 7912280422 7912280436	7912280380 7912280380 7912280399 7912280415 7912280429	79/11/09 79/11/09 79/11/30 79/11/30 79/12/20	50-320 50-320 50-320 50-320 50-482	Р Р Н Н			7912310247 7912310251 7912310257 7912310258 7912310259	7912310240 7912310236 7912310236 7912310236 7912310249	79/12/14 79/12/18 79/12/18 79/12/18 79/12/13	50-320 50-320 50-320 50-320 27-48	H H H
7912280437 7912280439 7912280449 7912280454 7912280456	7912280430 7912280433 7912280445 7912280452 7912280457	79/11/23 79/11/30 79/11/30 79/11/30 79/11/30	50-320 50-320 50-320 50-320 50-320	Р Н Н Н			7912310274 7912310287 7912310288 7912310299 7912310300	7912310270 7912310270 7912310281 7912310291 7912310292	79/11/13 79/11/13 79/11/09 79/11/30 79/11/15	50-438 50-438 50-387 70-820 50-348	g g g
7912280459 7912280461 7912280465 7912280470 7912280476	7912280456 7912280460 7912280462 7912280468 7912280472	79/11/30 79/11/30 79/11/30 79/11/30 79/11/30	50-320 50-320 50-320 50-320 50-320	е н н н			7912310304 7912310311 7912310318 7912310320 7912310331	7912310291 7912310291 7912310307 7912310291 7912310325	79/11/30 79/11/30 79/11/16 79/11/30 79/11/16	70-820 70-820 50-390 70-820 50-395	a Q
7912280480 7912280482 7912280486 7912280487 7912280489	7912280478 7912280481 7912280471 7912280484 7912280471	79/11/30 79/11/30 79/11/29 79/11/30 79/11/29	50-320 50-320 50-287 50-320 50-289	H H U H			7912310333 7912310338 7912310346 7912310350 7912310353	7912310326 7912310336 7912310336 7912310345 7912310349	79/11/16 79/11/16 79/11/16 79/11/14 79/11/14	50-327 50-302 50-302 50-316 50-281	9 9 9 9
7912280492 7912280493 7912280507 7912280513 7912280514	7912280471 7912280471 7912280503 7912280509 7912280510	79/11/29 79/11/29 79/12/21 79/12/21 79/11/30	50-289 50-320 50-276 50-259 50-320	ប ទ ទ អ			7912310357 7912310359 7912310368 7912310374 7912310377	7912310354 7912310348 7912310358 7912310371 7912310366	79/12/20 79/12/20 79/12/12 79/12/28 79/12/12	50-317 50-10 50-312 50-338 50-338	9 P P
7912280524 7912280525 7912280527 7912280528 7912280530	7912280521 7912280518 7912280523 7912280517 7912280516	79/12/20 79/12/24 79/12/19 79/12/18 79/11/30	50-315 50-344 50-316 TOPREP 50-320	R P R H			7912310384 7912310386 7912310393 7912310394 7912310398	7912310383 7912310366 7912310383 7912310391 7912310396	79/12/21 79/12/12 79/12/21 79/12/28 79/12/21	50-348 50-338 50-368 50-244 50-247	8 8 8
7912289535 7912280537 7912280540 7912280551 7912280552	7912280518 7912280534 7912280532 7912280543 7912280544	79/12/24 79/11/30 79/12/19 79/11/30 79/12/14	50-344 50-320 50-395 50-320 50-327	P 0 5 H 5			7912310399 7912310404 7912310406 7912310408 7912310409	7912310383 7912310383 7912310403 7912310401 7912310383	79/12/21 79/12/21 79/12/21 79/12/28 79/12/21	50-368 50-368 50-247 50-416 50-368	5 8 8 8
7912280555 7912280558 7912280545 7912280571 7912280590	7912280546 7912280553 7912280560 7912280566 7912280581	79/12/19 79/11/30 79/12/21 79/12/20 79/12/17	50-400 50-320 50-329 50-397 50-327	A B A S			7912310410 7912310414 7912310418 7912310420 7912310425	7912310403 7912310413 7912310416 7912310415 7912310417	79/12/21 79/12/21 79/12/13 79/12/27 79/12/26	50-247 50-273 50-317 50-321 50-255	8 R R 8
7912280613 7912280641 7912280642 7912280645 7912280646	7912280607 7912280634 7912280636 7912280640 7912280634	79/12/19 79/12/17 79/12/14 79/11/14 79/12/17	50-518 50-317 50-397 27-10 50-317	A P B			7912310426 7912310428 7912310430 7912310431 7912310433	7912310424 7912310422 7912310429 7912310388 7912310432	79/12/17 79/12/28 79/12/20 79/12/27 79/08/08	50-348 50-263 50-321 50-317 50-366	R 8 F R
7912280651 7912280653 7912280658 7912280663 7912280667	7912280636 7912280640 7912280640 7912280656 7912280640	79/12/14 79/11/14 79/11/14 79/11/06 79/11/14	50-397 27-10 27-10 XPORTLIC 27-10	S			7912310434 7912310437 7912310440 7912310441 7912310444	7912310432 7912310435 7912310438 7912310436 7912310442	79/08/08 79/12/06 79/12/12 79/12/26 79/12/10	50-366 50-298 50-298 50-255 50-278	R 9 9
7912280674 7912280676 7912280678 7912280687 7912310004	7912280672 7912280640 7912280671 7912280684 7912310002	79/12/18 79/11/14 79/12/07 79/09/25 79/12/13	27-48 27-10 50-344 Wabte Mo 50-204	g T G			7912310449 7912310450 7912310451 7912310484 7912310455	7912310445 7912310447 7912310448 7912310453 7912310452	79/11/29 79/12/06 79/12/28 79/12/28 79/12/24	40-4492 50-298 50-348 50-293 50-312	9 9 9
7912310006 7912310024 7912310032 7912310047 7912310058	7912310002 7912310014 7912310029 7912310041 7912310054	79/12/13 79/12/12 79/12/17 79/11/09 79/11/09	50-204 TOPREP PRM 50-318 50-322	0 0 0			7912310461 7912310464 7912310465 7912310467 7912310468	7912310456 7912310458 7912310458 7912310459 7912310462	79/12/17 79/12/27 79/12/27 79/12/07 79/12/26	50-368 50-155 50-155 50-298 50-366	P P B B
7912310065 7912310072 7912310076 7912310081 7912310086	7912310040 7912310047 7912310047 7912310047 7912310047	79/11/06 79/12/07 79/12/07 79/12/07 79/12/07	50-219 50-389 50-389 50-389 50-389	0 G G G			7912310469 7912310473 7912310474 7912310478 7912310481	7912310458 7912310458 7912310471 7912310475 7912310476	79/12/27 79/12/27 79/12/28 79/12/26 79/12/27	50-155 50-155 50-313 50-282 50-255	P P F 80 P
7912310100 7912310115 7912310131 7912310152 7912310154	7912310093 7912310107 7912310125 791231014B 791231014B	79/11/08 79/11/08 79/11/05 79/12/07 79/12/07	50-390 50-281 50-286 50-335 50-335	G G P P			7912310482 7912310486 7912310487 7912310490 7912310492	7912310388 7912310480 7912310476 7912310388 7912310483	79/12/27 79/12/27 79/12/27 79/12/27 79/12/26	50-317 50-346 50-255 50-317 50-155	F P P F 9
7912310170 7912310178 7912310180 7912310183 7912310225	7912310168 7912310168 7912310176 7912310168 7912310218	79/12/04 79/12/04 79/11/20 79/12/04 79/12/11	50-466 50-466 XPDRTLIC 50-466 ORO	0 0			7912310493 7912310495 7912310496 7912310501 7912310502	7912310489 7912310476 7912310388 7912310476 7912310388	79/12/26 79/12/27 79/12/27 79/12/27 79/12/27	50-413 50-255 50-317 50-255 50-317	9 P P F
7912310227 - 7912310233 7912310238 7912310239 7912310243	7912310214 7912310210 7912310230 7912310214 7912310236	79/08/23 79/12/11 79/11/19 79/08/23 79/12/18	ACR8 OR0 27-47 ACR8 50-320	н			7912310504 7912310506 7912310508 7912310511 7912310512	7912310497 7912310499 7912310476 7912310388 7912310510	79/12/26 79/12/28 79/12/27 79/12/27 79/12/26	50-409 50-280 50-255 50-317 50-133	8 P P F O

### 453

ACCESSION NUMBER					ACCESSION NUMBER					
ENCLOSUR	PRINCIPAL DOCUMENT	DATE IBBUED	SUBJEC CATEGO		ENCLOSURE	PRINCIPAL DOCUMENT	DATE	SUBJEC1		
79123105		79/12/27	50-255	 Р	7912310525	7912310388	79/12/27	50-317	F	
79123105	17 7912310476	79/12/27	50-255	Р	7912310527	7912310516	79/12/28	50-344	P	
79123105	19 7912310514	79/12/11	50~498	м	7912310530	7912310388	79/12/27	50-317	F	
79123105	20 7912310516	79/12/28	50-344	p	7912310534	7912310388	79/12/27	50-317	F	
79123105	23 7912310476	79/12/27	50-255	P	7912310536	7912310533	79/12/27	50-302	F	
					7912310540	7912310533	79/12/27	50-302	F	
					7912310541	7712310388	79/12/27	50-317	F	
					701001004	7010010000	70 (10 /07	EA 417		



#### APPENDIX A

#### **DEFINITIONS OF DOCKET 50 CATEGORIES**

### A. Application/Construction Stage Documents and Correspondence

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are:

- 1. Correspondence and documents relating to unresolved design and construction issues.
- 2. Meeting announcements and summaries of meeting discussions on issues of item 1.
- 3. Correspondence regarding Preliminary and Final Safety Analysis Reports.
- 4. NRC questions, requests for additional information, and applicant responses.
- 5. Applicant's Quality Assurance Manual.
- 6. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 7. Federal Register notices that do not apply to other categories.
- 8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
- 9. Scheduling of license application submission or review.
- 10. Reports of site visits.
- 11. Backup technical documents (i.e., topical reports) submitted in support of the application.
- 12. Early site review information.
- 13. Construction Permit, amendments and correspondence relating to construction permit.
- 14. Environmental review information.
- 15. Construction permit.

### B. Utility Preliminary Safety Analysis Report (PSAR) and Amendments

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

- 1. Preliminary Safety Analysis Report (PSAR) submitted by the utility.
- 2. Amendments and changes to the PSAR.
- 3. Transmittal letters,
- 4. Letters acknowledging receipt.
- 5. Hazards Summary Report submitted by utility (now designated PSAR).

- 6. Safety Analysis Report submitted by utility (now designated PSAR).
- 7. Certificates of Service of PSAR.

## C. Utility Environmental Report (ER), Amendments and Correspondence

- 1. Environmental Report (ER) submitted by the utility.
- 2. Amendments and supplements to the ER.
- 3. Transmittal letters.
- 4. Information on scheduling of submittal or review of ER.
- 5. NRC questions, requests for additional information, and applicant responses.
- 6. Federal Register notice citing availability of items 1 and 2.
- 7. Correspondence relating to the review of ER.
- 8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

## D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), Supplements and Correspondence

- 1. Draft and Final Environmental (Impact) Statements (DES and FES).
- 2. Supplements to DES and FES.
- 3. Correspondence relating to the DES or FES.
- 4. Comments from other federal, state, and local government agencies.
- 5. Transmittal letters.
- 6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
- 7. Backup technical documents submitted in connection with above.
- 8. Notices of availability of above.
- 9. Draft of detailed statement.

## E. NRC Safety Evaluation Report (SER), Supplements and Correspondence

- 1. Safety Evaluation Report (SER).
- 2. Supplements to SER.
- 3. Correspondence relating to SER.

- 4. Notices advising of the availability of 1 and 2.
- 5. Information on scheduling of SER submittals and review.
- 6. Requests for additional information for use in preparing SER; responses to such requests.
- 7. Meeting announcements or reports of meetings where the primary subject of discussion is the safety review or safety evaluation.
- 8. Transmittal letters.
- 9. Comments from other agencies relative to safety review.
- 10. NRC-AEC Hazard Analysis Reports (now designated SER).

## F. Security, Medical, Emergency, and Fire-Protection Plans

All plans in this category are submitted separately. Information submitted for the PSAR or FSAR is excluded.

- 1. Correspondence relating to plans.
- 2. Supplements, changes, and revisions to plans.
- 3. Fire Hazard Protection Plan and Surveys.

## G. Adjudicatory Correspondence

This category contains all documents on hearings, Atomic Safety and Licensing Board (ASLB) review, and opposition except word-for-word transcripts of ASLB hearings (Category T) and antitrust hearings (Category N).

- 1. ASLB hearing and review documents.
- 2. Correspondence to and from intervenors.
- 3. Correspondence to and from persons writing in opposition to the facility. Those writing for information or in support of the facility are in category H.
- 4. Board orders and decisions.
- 5. Requests to make appearances at hearings.
- 6. Transmittal of supporting documents (i.e., SER, FES) to the board.
- 7. Federal Register notices regarding hearings.
- 8. Requests for a hearing.
- 9. Petitions from participants (including petition for request for extension).
- 10. Corrections to transcripts.
- 11. Professional qualifications, if presented at a hearing.

- 12. Memorandums and orders authorizing issuance of license, changes, and other issuances by the Atomic Safety and Licensing Board.
- 13. Hearing index.

## H. General correspondence

This category includes documents with little or no bearing on the status of the application or license. Items that have no substantive technical content or meaning for the status of the license or application are included.

- 1. Qualification statements of new employees.
- 2. Change of address notifications.
- 3. Changes in organization.
- 4. Changes in service lists, "Certificate of Service" documents (without a document attached).
- 5. NRC requests to applicant for additional copies of documents.
- 6. Correspondence from the public in support of or requesting information about the facility.
- 7. Letters of "concern" (NOT "opposition") and response thereto.
- 8. Correspondence on strictly administrative matters.
- 9. Correspondence regarding the local Public Document Room.
- Memoranda to Public Document Room regarding withholding a document (unaccompanied by that document).
- 11. Press releases from applicant.
- 12. Any other material that fits the criteria given above.
- 13. Professional qualifications (resumes).

#### I. Financial Information

- 1. Company annual reports.
- 2. Separately submitted financial information and related correspondence.

## J. Insurance and Idemnity Information

- 1. All correspondence and documentation regarding indemnity and insurance.
- 2. Endorsements to insurance policies.
- 3. NELPIA Nuclear Energy Liability Property Insurance information.

## K. Utility Final Safety Analysis Report (FSAR) and Amendments

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

- 1. Final Safety Analysis Report (FSAR).
- 2. Amendments and changes to the FSAR.
- 3. Transmittal letters.
- 4. Letters acknowledging receipt of items.
- 5. Hazards Final Summary Report (now designated FSAR).
- 6. Certificates of Service of FSAR.

## L. Limited Work Authorization and Related Correspondence

This category is limited to items issued before the construction permit is granted.

- 1. Limited Work Authorizations.
- 2. Environmental exemptions.
- 3. Correspondence relating to 1 and 2.
- 4. All information concerning site preparation prior to the issuance of a construction permit.

### M. Antitrust Correspondence

- 1. All material concerning antitrust except hearing transcripts (category N)
- 2. All material marked with an A immediately following the docket number. The A signifies antitrust proceedings.

### N. Antitrust Hearing Transcripts

This category contains only word-for-word transcripts of hearings in antitrust matters. In most cases they will be marked with an A following the docket number. Related correspondence falls in category M.

## O. Advisory Committee on Reactor Safeguards (ACRS) Reports and Correspondence

- 1. Correspondence and letter reports relating to ACRS reviews
- 2. Correspondence from ACRS
- 3. Announcements of ACRS meetings

- 4. Transmittal letters to ACRS
- 5. ACRS reports.

## P. Operating License Stage Documents and Correspondence

This file assumes the position of the application file for general technical items dated on or after the issuance of the operating license. It includes:

- 1. Operating license, amendments, proposed amendments, and changes.
- 2. Technical specifications and changes.
- 3. Announcements of issuance of 1 and 2.
- 4. Transmittal letters.
- 5. All general technical correspondence relating to technical specifications or operating license.
- 6. License conditions.
- 7. Operator licenses or administrative information bearing on the licensing of operators.
- 8. Meeting announcements or summaries of discussions where the main subject is technical specifications, operating license, or any technical issue arising after the issuance of the operating license.
- 9. Correspondence regarding codes (ASME), regulations, laws, or changes in policy that may affect plant operation or bear on the operating license.
- 10. Information on the Standard Review Plan (SRP).
- 11. Results of surveys or tests conducted in accordance with the technical specifications (NOT periodic reports, which fall in category R).
- 12. Requests for issuance of operating license.
- 13. Requests for copies of items 1 and 2 and responses.
- 14. Correspondence on generic technical issues.
- 15. Owner's group meeting announcements and reports.
- 16. Orders for modification of license.
- 17. Requests for extension date of license or license modification.
- 18. Quality assurance information.
- 19. Environmental matters (technical).
- 20. Emergency core cooling system.
- 21. Radioactive waste information.

## Q. Inspection Reports, IE Bulletins and Correspondence

- 1. Inspection reports.
- 2. Bulletins and Circulars of NRC Office of Inspection and Enforcement (IE).
- 3. Responses by applicant to IE correspondence.
- 4. Applicant's determination of proprietary nature of inspection reports.
- 5. Letters concerning areas of noncompliance.
- 6. Any correspondence relating to inspection and enforcement that does not specifically relate to incidents as defined in category S.
- 7. In-service inspections.
- 8. Regulatory Operations (RO) Bulletins.

## R. Periodic Operating Reports and Related Correspondence

This category includes periodic reports of a routine nature.

- 1. Monthly, semiannual, or annual reports (other than financial).
- 2. Periodic environmental monitoring, effluent testing, or similar reports.
- 3. Gray Book Information.
- 4. Operational Logbooks:

Logbooks on Environmental Data Logbooks of Radiological Data Operations Log on Plant Systems Core Plant Status Summary Sheets

5. Correspondence or other documents relating to the above listed items.

## S. Reportable Occurrences, LERs and Related Correspondence

This category contains all materials relating to abnormal, unusual, reportable, nonroutine, or 10 CFR 50.55e occurrences. This includes:

- 1. All 24-hour, 10-day, 30-day, interim, final, and followup reports on these events.
- 2. Other related documents.

NOTE: Also called licensee event reports, incident reports, etc.

## T. Hearing Transcripts on Non-Antitrust Matters

This category contains word-for-word transcripts, corrections to the transcript, attachments and Vu-Graphs. Examples of non-antitrust matters include:

- 1. ASLB hearings.
- 2. Commission Meetings.
- 3. Commission Briefings.
- 4. Telephone conversations.

### U. Congressional/Executive Correspondence

- 1. Testimony before Congress.
- 2. Preparatory and backup documents for Congressional testimony.
- 3. Letters to and from Congress and the Executive Branch.
- 4. Responses to letters from members of Congress and the Executive Branch.
- 5. Correspondence to and from the NRC Office of Congressional Affairs.

## V. Operator Examinations

- 1. NRC Examination Results.
- 2. Power Plant Examination Summary Sheet.
- 3. Related correspondence.

## APPENDIX B

## **DEFINITIONS OF NONDOCKETED CATEGORIES**

## 10CFR - Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes:

- 1. Sunshine Act Federal Register notices.
- 2. Full, written explanation of closed meetings.
- 3. Certification of General Counsel on closed meetings.
- 4. Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.
- Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
- Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.
- 7. Staff requirements memoranda for open meetings; memoranda to record; record of votes of Commissioners on items under consideration at meetings.

## ACRS - Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are:

- Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.
- 2. ACRS meeting announcements; description of meeting agendas.
- 3. ACRS-generated reports, memoranda and correspondence that are publicly available.
- 4. ACRS consultant reports, comments and related correspondence.
- ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

#### COMMISSION - NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including:

- 1. Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.
- 2. Travel vouchers, telephone logs and official appointment calendars of individual Commissioners.
- Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE: For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

#### CONTRACT - NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including:

- 1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).
- 2. Solicitations (RFP or IFB) issued by the NRC.
- Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.
- 4. Contractual documents and contract modifications, if any.

#### FOIA - Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include:

- Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year—numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
- 2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
- 3. Records or portions of records released in response to specific requests made under FOIA.

#### GEN TECH IS - Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

- 1. Draft reports of action plans to accomplish generic tasks in the regulatory program.
- Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues.
- 3. Meeting notifications and minutes.
- Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

## I&E - Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

- 1. I&E Circulars, which describe an event at a licensed facility and are informational in nature.
- I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
- I&E Bulletins, which describe an event at a licensed facility and request all recipients to
  perform certain actions as a result of this event.
- 4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance.

NOTE: For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

## MISC - Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other nondocketed categories.

## NUREG - NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

- 1. These reports are normally final work products and are characterized by the following criteria:
  - They are predecisional documents which present information to be considered in Commission licensing and policy decisions.
  - b. They present the results of Commission licensing and policy decisions.
  - c. They present the results of technical research conducted for the Commission.
- Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
- Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

## ORG - Correspondence with Other Organizations

This category contains correspondence with professional organizations and associations; records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development; and emergency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are:

- Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.
- Correspondence between NRC's Office of Standards Development and other government
  agencies in which both parties have joint regulatory responsibility; e.g., EPA has authority
  to control all radioactive pollutants emitted into the air.
- Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
- 4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE: For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

#### PR - Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

- Federal Register notices stating the terms or substance of the proposed rule or a specification
  of the subject and issues involved.
- 2. Text of the Proposed Rule (PR).
- 3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.
- Requests from the nuclear industry, organizations and other parties for written interpretations
  of the PR.

#### PRM - Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

- Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
- 2. Federal Register cause notices of the filing of the petition.
- Correspondence between NRC and the petitioner regarding the status and substance of the petition.
- Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE: For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

#### PROJ - Projects-Predocket Licensing

This category contains records pertaining to two classes of projects: (1) commercial nuclear power plants for which NRC has full licensing responsibilities; and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

1. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

## A. Application/Construction Stage

- 1. Application submitted by the utility.
- 2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
- 3. Applicant's Quality Assurance Manual.
- 4. Early site review information.
- 5. Backup technical documents submitted in support of the application.
- 6. Early site visits.

## B. Utility PSAR and Amendments

- 1. PSARs submitted by the utility.
- 2. Amendments and changes to the PSAR.
- Transmittal letters.
- Letters acknowledging receipt of the PSAR.

#### G. Adjudicatory Correspondence

1. Motions, briefs, orders, et al. pertaining to pre-hearing conferences, if any.

### M. Antitrust Correspondence

1. Submittals and related material pertaining to the antitrust review.

### Q. Inspection Reports

- 1. Inspection reports of the applicant's quality assurance program.
- 2. Notices of deviations.
- 3. Follow-up correspondence resolving deviations cited.

### Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

## PT21 - Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include:

- Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
- Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
- 3. NRC inspection reports of defects cited.
- 4. Correspondence specifying appropriate follow-up actions taken by the Agency,

### QA999 - Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling

criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

- NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
- Notices of deviations.
- 3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

### REGGD - Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC staff for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are:

- 1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
- 2. Revised or newly issued Regulatory Guides.
- 3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
- 4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
- 5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE: For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

## RES - Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

- 1. Project description documents.
- 2. Letter reports of accomplishments and data reports; for example,
  - a. model documentation reports
  - b. code documentation reports
  - c. code verification reports
- 3. Pre-test prediction reports.
- 4. "Quick look" reports.
- 5. Informal experimental data reports and post-irradiation examination analyses.
- 6. Conceptual design descriptions.

- 7. Letter reports of foreign travel and site visits by contractors.
- 8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
- 9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
- 10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

## REVIEW GRP - NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in defined technical areas. They review and comment on research plans and predicted results of major experiments, the validity and applicability of research results, the possible redirection of research projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are:

- 1. Agendas for quarterly review group meetings.
- 2. Summary minutes of review group meetings representing views expressed, including dissenting views.
- 3. Research plans and predicted results of major experiments; presentations by research contractors.
- 4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
- 5. Internal memoranda relating to topics under discussion.

## RM - Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include:

- 1. Designations of the presiding officer and any special directions for the conduct of the hearing.
- 2. Notifications of hearing board meetings.
- 3. Petitions, motions, testimony and statements submitted by parties to the hearings.
- 4. Hearing board orders and rulings.
- 5. Technical reports submitted as evidence in the proceeding.
- 6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

#### SECY - Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

- Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
- 2. Consent Calendar items and Policy Session items.

NOTE: For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

#### STATE PROG - State Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting State and local governments in planning responses to radiological emergencies; and (3) a wide range of liaison and cooperative activities regarding such functions as licensing and siting. It includes:

- Correspondence between and among NRC Office of State Programs and State officials, mostly State liaison officers, regarding:
  - a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.
  - technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
- 2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations; i.e. decommissioning and facility siting.
- 3. State Legislative Reports.
- 4. Agreement State Licensing Statistics Reports.

NOTE: For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

#### TOPREP - Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

- Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.
- 2. Revisions, modifications and amendments to topical reports.
- 3. Correspondence between NRC and vendors pertaining to the review of submittals.

endas, summaries, minutes and correspondence pertinent to vendor activities,

ted by utilities that are written by vendors on their behalf and that cases, see the categories for the Docket 50 series.

#### WASTE MGT - Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

- 1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
- Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.
- Correspondence pertaining to NRC's advisory role in providing DOE with technical assistance in the Waste Isolation Pilot Plan (WIPP) for burial of defense wastes.
- 4. NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories.

#### XPORTLIC - Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

- 1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
- 2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
- 3. Commission letters requesting Executive Branch views.
- 4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
- Correspondence from foreign governments, international organizations, and members of the public.
- Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
- 7. Filings pursuant to hearing requests or intervention petitions, if any.
- 8. Hearing records and decisions.
- Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
- 10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE: For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.



INFIC FORM 355 U.S. NUCLEAR REGULATORY COMMISSION	1. REPO	RT NUMBER (Assigned by DDC		
BIBLIOGRAPHIC DATA SHEET	NUREG	-0540 Vol.1 No. 12		
4. TITLE AND SUBTITLE (Add Volume No., if appropriate)	2. (Leave			
Title List of Documents Made Publicly Available	3. RECIPI	ENT'S ACCESSION NO.		
7. AUTHOR(S)	5, DATE	REPORT COMPLETED		
	MONTH	1 YEAR		
9. PERFORMING ORGANIZATION NAME AND MAILING ADDRESS (Include 2		uary 1980 REPORT ISSUED		
	MONTH	YEAR		
Division of Technical Information and Document (U.S. Nuclear Regulatory Commission Washington, D.C. 20555	Control Feb	ruary 1980 blank)		
	8. (Leave t	olank)		
12. SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include Z Same as #9	ip Code) 10. PROJE	10. PROJECT/T.ASK/WORK UNIT NO.		
Same as ms	11. CONTE	11. CONTRACT NO.		
13. TYPE OF REPORT	PERIOD COVERED (Inclusiva	dates)		
Monthly				
5. SUPPLEMENTARY NOTES	14. (Leave I	blank)		
This document is a monthly publication con information received and generated by the includes (1) docketed material associated plants and other uses of radioactive material received and generated by NRC per regulatory agency. The docketed information merely issued through U.S. DOE's Technical the title Power Reactor Docket Information replaces PRDI, which will no longer be prepersonal Author Index, Corporate Source Information received.	U.S. NRC. This into with civilian nuclei and (2) nondertinent to its role on includes information Center (PRDI). This documented. It is index	formation lear power ocketed e as a ation for- er under ument ked by a		
7. KEY WORDS AND DOCUMENT ANALYSIS 17a.	DESCRIPTORS			
b. IDENTIFIERS/OPEN-ENDED TERMS				
AVAILABILITY OF THE STATE OF TH				
. AVAILABILITY STATEMENT	19. SECURITY CLASS (This Unclassified			
Unlimited	20. SECURITY CLASS (This p	page) 22. PRICE		